



November 19, 1996

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001

ULNRC-03488


Gentlemen:

**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
FACILITY OPERATING LICENSE NPF-30  
SPECIAL REPORT 96-003  
NUMBER OF TUBES PLUGGED DURING THE NINTH  
STEAM GENERATOR TUBE INSERVICE INSPECTION**

This special report is submitted in accordance with Technical Specification (T/S) 4.4.5.5.a, which states:

"Within 15 days following the completion of each inservice inspection of steam generator tubes, the number of tubes plugged in each steam generator shall be reported to the Commission in a Special Report pursuant to Specification 6.9.2."

The Steam Generator (S/G) Inservice Inspection was completed for all 4 S/G's on 11/11/96 to meet the surveillance requirements of T/S 3/4.4.5, "Steam Generators". Forty-eight (48) tubes were plugged and 77 tubes were repaired using the laser welded sleeving method as a result of the inspection. The tubes plugged are identified on page 2, the tubes sleeved are identified on page 3.

  
for R. D. Affolter  
Manager, Callaway

RDA/HDB/TWP/MNF/lmf

9611260198 961119  
PDR ADOCK 05000483  
G PDR

AD4711

## STEAM GENERATOR TUBES PLUGGED IN REFUEL 8

<u>Steam Generator A</u>		<u>Steam Generator B</u>		<u>Steam Generator C</u>		<u>Steam Generator D</u>	
<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>
56	47	21	38 *	10	3	48	42
57	76 *	11	52	2	6	41	51 *
22	82 *	12	53 *	57	48	14	55 *
2	87	11	54	14	59	22	55
		31	87	42	66 *	15	61 *
		1	100 *	14	71 *	15	62 *
		32	110	35	77 *	11	63
		1	119	55	80 *	12	63 *
				17	81	14	63
				30	91 *	13	64 *
				17	100	14	64 *
						16	64 *
						13	65
						24	65 *
						13	66 *
						49	84
						16	86 *
						48	89
						32	94 *
						26	99 *
						14	101
						7	102
						14	102 *
						20	116 *
						24	116 *

\* - Tube stabilized

## TUBES SLEEVED IN REFUEL 8

## Steam Generator A

## Steam Generator C

<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>	<i>Row</i>	<i>Col</i>
29	30	25	71	24	14	15	61
25	42	15	72	15	15	12	62
21	43	19	72	33	34	15	62
19	47	16	75	27	35	41	63
18	48	12	76	24	45	50	67
21	48	18	76	12	46	10	70
22	51	20	77	15	46	31	78
18	52	15	78	10	48	17	86
46	53	54	78	23	51	50	86
14	54	36	79	49	51	37	87
21	54	27	80	14	53	35	90
57	55	23	82	15	53	12	91
17	57	20	83	17	55	19	91
22	57	38	87	28	56	34	95
19	59	41	87	11	59	29	97
16	60	31	90	41	59	26	99
26	61	31	91	12	60		
13	62	31	93				
14	62	12	94				
19	63	31	95				
35	67	27	99				
19	70	8	115				

cc: Mr. L. Joe Callan  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Ms. Kristine M. Thomas (2 copies)  
Licensing Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop 13E16  
Washington, DC 20555-2738

Manager, Electric Department  
Missouri Public Service Commission  
PO Box 360  
Jefferson City, MO 65102

Mr. Thomas A. Baxter  
Shaw, Pittman, Potts, & Trowbridge  
2300 N. Street N.W.  
Washington, DC 20037

ULNRC-03488

**SPECIAL REPORT 96-003**

Page 5

bcc: D. F. Schnell (400)  
G. L. Randolph  
J. V. Laux/G. A. Hughes  
A. C. Passwater/D. E. Shafer (470)  
Z40SR  
G. J. Czeschin  
N. E. Barnett  
Corporate Communications (100)  
WCNOC  
M. P. Barrett (100)  
P. L. Reynolds (470) NSRB  
H. D. Bono  
E210.0001  
Z40ULNRC  
A160.0761  
RDA Chrono

Manager, Plant Support  
Wolf Creek Nuclear Operating Corporation  
PO Box 411  
Burlington, KS 66839