

SAFETY INSPECTION

Page 1 of

1. LICENSEE Jackson Community College		2. REGIONAL OFFICE REGION III U S NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S) 030-01228	4. LICENSE NUMBER(S) SNM-1171	5. DATE OF INSPECTION January 24, 1997	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

<input type="checkbox"/>	1. Within the scope of this inspection, no violations were observed.
<input type="checkbox"/>	2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
<input checked="" type="checkbox"/>	3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF VIOLATION , which is required to be posted in accordance with 10 CFR 19.11.
<input type="checkbox"/>	A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
<input type="checkbox"/>	B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____
<input type="checkbox"/>	C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____
<input type="checkbox"/>	D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
<input type="checkbox"/>	E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____
<input checked="" type="checkbox"/>	F. License Condition 6.A lists the authorized licensed material. Contrary to the above, the licensee possesses for storage only since approximately 1974, one cobalt-60 source decayed to 110 microcuries as of January 1997 that is not listed as an authorized licensed material on the license.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE -- LICENSEE

DATE

SIGNATURE -- NRC INSPECTOR

DATE

9702250152 970221
PDR ADOCK 07001228
C PDR

[Handwritten Signature]

2/21/97