


AUG 17 1966

Form AEC-591
(6/1/65)UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE HARSHAW CHEMICAL COMPANY 1945 EAST 97TH STREET CLEVELAND, OHIO 44106	2. REGIONAL OFFICE REGION III, DIV. OF COMPLIANCE OAKBROOK PROFESSIONAL BLDG. OAK BROOK, ILLINOIS 60523
3. LICENSE NUMBER(S) 34-6558-5 & SNM-427 (10-472)	4. DATE OF INSPECTION AUGUST 10, 1966
5. INSPECTION FINDINGS <ul style="list-style-type: none"> <input checked="" type="checkbox"/> A. No item of noncompliance was found. <input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42 <input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 <input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) <input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) <input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) <input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4) <input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(t) <input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c) <input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) <input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d) <input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 <input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) <input type="checkbox"/> N. Records of inventories were not maintained. 10 CFR 34.26 <input type="checkbox"/> O. Utilization logs were not maintained. 10 CFR 34.27 	
6. LICENSEE'S ACKNOWLEDGMENT <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <p style="text-align: right;">B82</p> <p style="text-align: right;">(Licensee Representative — Title or Position)</p> <p style="text-align: center;">(Date)</p>	



Edgar L. Ashley
 (AEC Compliance Inspector)

9702260130 970218
 PDR FOIA
 BABCOCK96-529 PDR

☐ LICENSEE: ☐ COMPLIANCE REGION: ☒ DIV. OF ST. & LIC. REL.: ☐ DIV. OF COMPLIANCE