

AUG 21 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by A. G. Januska of this office on August 6-9, 1985; of activities at Davis-Besse Nuclear Power Station, Unit 1 authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. Storz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix. The inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this noncompliance is required and we have no further questions regarding this matter at this time.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC's Public Document Room.

IEO6
11

8509100015 850821
PDR ADOCK 05000346
G PDR

Toledo Edison Company

2 AUG 21 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

1. Appendix, Notice
of Violation
2. Inspection Report
No. 50-346/85024(DRSS)

cc w/enclosures:

L. Storz, Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health

RIII

Januska/ld
08/19/85

RIII

Schumacher

RIII

Jackiw

RIII

Shafer