

# WOLF CREEK

NUCLEAR OPERATING CORPORATION

Clay C. Warren  
Chief Operating Officer

February 18, 1997

WO 97-0022

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Stop: P1-137  
Washington, D. C. 20555

Subject: Docket No. 50-482: Changes to Wolf Creek Generating  
Station Radiological Emergency Response Plan and  
Implementing Procedures

Gentlemen:

Enclosed are revision 53 (effective January 22, 1997) and revision 54 (effective January 24, 1997) to Wolf Creek Generating Station (WCGS) Radiological Emergency Response Plan (RERP). Also transmitted are revisions to WCGS Radiological Emergency Response Implementing Procedures.

Effective January 20, 1997:

EPP 02-1.3, Revision 13


Effective February 3, 1997:

EPP 01-7.2, Revision 18

This submittal is in accordance with 10 CFR 50.54(q) and 10 CFR 50, Appendix E.

If you have any questions concerning this submittal, please contact me at (316) 364-8831, extension 4485, or Mr. James D. Weeks at extension 5210.

Very truly yours,



Clay C. Warren

9702270072 970218  
PDR ADOCK 05000482  
F PDR

CCW/jad

Enclosures

250061

cc: L. J. Callan (NRC), w/e (2)  
W. D. Johnson (NRC), w/o  
B. Murray (NRC), w/e  
J. F. Ringwald (NRC), w/o  
J. C. Stone (NRC) w/e

AD45

## CHANGE SUMMARY

DOCUMENT/REV: RERP / 53

TITLE: RADIOLOGICAL EMERGENCY RESPONSE PLAN

Step	Description	Reason for Change
Table 2.2-2, Box 8-SSFM5 on Page 8 of 13	Box 8-SSFM5 changed first bullet from "All SG NR levels are less than 5%" to "All SG NR levels are less than 6%".	EAL was changed due to the EMG level setpoint was changed.
Table 2.2-2, Box 8-SSFM3 on Page 8 of 13	Changed "NO" response line from an "Alert classification" to a "Site Area classification".	Response line from this box was inadvertently changed from the correct Site Area classification to an Alert classification in a revision to the EALs due to the icing event in January of 1996. This correction returns the "NO" response line to the correct classification.