

Commonwealth Edison Company
Zion Generating Station
101 Shiloh Boulevard
Zion, IL 60099-2797
Tel 847-746-2084




February 18, 1997

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

The enclosed Licensee Event Report number 97-002-00, Docket No. 50-295/DPR-39 from Zion Generating Station is being transmitted to pursuant to 10 CFR 50.73(a)(2)(i)(B) which requires a thirty-day written report when any event or condition occurs that is prohibited by the plant's Technical Specifications. Commitments made in this report are:

1. Unit 2 containment isolation valves will be verified tested prior to Unit 2 entering Mode 4 from Z2R14.
2. The Operations Procedures Group will modify associated procedures or create new procedures to ensure that containment isolation valves are tested prior to entering the required mode of applicability.
3. Zion Station IST Group is continuing a review of the IST program to ensure all requirements are met. This review is expected to be completed by March 31, 1997.
4. Zion Station will modify the Technical Specification Amendment implementation process to include required independent verification.

Very truly yours,


W.S. Lacey
Station Manager
Zion Generating Station

JE22/1

WSL/jz

Enclosure: Licensee Event Report

cc: NRC Region III Administrator
NRC Resident Inspector
IDNS Resident Inspector
INPO Record Center
Illinois Department of Nuclear Safety

9702270258 970218
PDR ADOCK 05000295
S PDR

