

December 3, 1996

NOTE TO: Edmund J. Sullivan, Chief
Inservice Inspection Section

FROM: Kenneth J. Karwoski, Materials Engineer
Inservice Inspection Section

SUBJECT: STEAM GENERATOR TUBE CIRCUMFERENTIAL INDICATIONS AT THE COLD LEG
EXPANSION TRANSITION AT BYRON 1

SD-454

As a result of discussions with representatives of the Commonwealth Edison Company, the licensee for Byron 1 and Braidwood 1, telefaxed information concerning eddy current indications located on the cold-leg side of the Byron 1 steam generator tubes. Attached is a copy of the material provided.

Attachment: As stated.

DISTRIBUTION:

PUBLIC

EMCB PF/RF

KKarwoski

TSullivan D Lynch

DOCUMENT NAME: G:\KARWOSKI\BRAIDWD\CL.NOT

*See Previous Concurrence

To receive a copy of this document, indicate in the box: "C" = Copy w/o attachment/enclosure; "E" = Copy with attachment/enclosure; "N" = No copy

OFFICE	EMCB:DE	E	EMCB:DE	
NAME	KKarwoski	✓	TSullivan	✓
DATE	11/27/96		11/11/96	

OFFICIAL RECORD COPY

9612050036 961203
PDR ADOCK 05000454
P PDR

41
DFOI