

AUG 28 1985

Docket No. 50-293

License No. DPR-35

Boston Edison Company M/C Nuclear
ATTN: Mr. William D. Harrington
Senior Vice President, Nuclear
800 Boylston Street
Boston, Massachusetts 02199

Gentlemen:

Subject: Inspection 50-293/81-18 and 81-22

This refers to your letter dated August 7, 1985 in response to our telephone conversation on July 30, 1985.

Thank you for providing a description of your activities and schedule to complete your long term corrective actions for Item of Noncompliance 81-22-01. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

Jacque P. Durr

Stewart D. Ebner, Director
Division of Reactor Safety

cc w/encl:

A. V. Morisi, Manager, Nuclear Management Services Department
C. J. Mathis, Station Manager
Joanne Shotwell, Assistant Attorney General
Paul Levy, Chairman, Department of Public Utilities
W. J. Nolan, Chairman, Plymouth Board of Selectmen
Plymouth Civil Defense Director
Senator Edward P. Kirby
E. R. MacCormack, Senior Regulatory Affairs and Program Engineer (Receives Safeguards Only)
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)

8509110100 850828
PDR ADDCK 05000293
G PDR

OFFICIAL RECORD COPY


RL PILGRIM - 0001.0.0
08/27/85


IE01
11

bcc w/encl:
Region I Docket Room (with concurrences)
Senior Operations Officer (w/o encl)
Section Chief, DRP

RI:DRS
Anderson/ca
8/22/85

Jwe for


RI:DRS
Durr
8/26/85


RI:DRS
Ebnetter
8/26/85

OFFICIAL RECORD COPY

RL PILGRIM - 0002.0.0
08/22/85

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

August 7, 1985
BECO Ltr. #85-142

Mr. Stewart D. Ebnetter, Director
Division of Reactor Safety
U.S. Nuclear Regulatory Commission
Region I - 631 Park Avenue
King of Prussia, PA 19406

License No. DPR-35
Docket No. 50-293

Subject: Followup Information Relating to INC 81-22-01

Reference: Combined NRC Inspections 81-18 and 81-22

Dear Mr. Martin:

Per Boston Edison Company's telephone conversation on 7/30/85 with Mr. Jack Durr of your office, we are providing you with the following information relating to Item of Non-Compliance 81-22-01:

In order to enhance the affected Station operating procedures to the point where those procedures will provide the user adequate technical guidance and Tech. Spec. section references, the below-listed activities will be funded, staffed, and completed as follows:

<u>Activity Description</u>	<u>Scheduled Completion Date</u>
Revise procedures for D4, D5, D6, Y1, Y2, and D19 to more clearly indicate equipment affected by the individual breakers.	12/31/85
Complete E-203 walkdowns and issue Discrepancy packages to the Nuclear Engineering Dept. for disposition.	7/31/86
Revise all affected procedures to include:	9/30/86
1) Applicable Technical Specifications	
2) Walkdown-Observed Configuration Changes	
3) Component Details	

RECEIVED-GENERAL
AUG 14 1985
6-30V 5001

MR

8508150185


47P

BOSTON EDISON COMPANY

Mr. Steward D. Ebnetter
U.S. Nuclear Regulatory Commission
August 7, 1985
Page Two

We trust that this information will provide the details and content required. However, if you have any further questions regarding these issues, please do not hesitate to contact me.

Very truly yours,

A handwritten signature in dark ink, appearing to read "WD Harrington". The signature is written in a cursive, somewhat stylized script.

W. D. Harrington

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

August 7, 1985
BECO Ltr. #85-142

Mr. Stewart D. Ebnetter, Director
Division of Reactor Safety
U.S. Nuclear Regulatory Commission
Region I - 631 Park Avenue
King of Prussia, PA 19406

License No. DPR-35
Docket No. 50-293

Subject: Followup Information Relating to INC 81-22-01

Reference: Combined NRC Inspections 81-18 and 81-22

Dear Mr. Martin:

Per Boston Edison Company's telephone conversation on 7/30/85 with Mr. Jack Durr of your office, we are providing you with the following information relating to Item of Non-Compliance 81-22-01:

In order to enhance the affected Station operating procedures to the point where those procedures will provide the user adequate technical guidance and Tech. Spec. section references, the below-listed activities will be funded, staffed, and completed as follows:

<u>Activity Description</u>	<u>Scheduled Completion Date</u>
Revise procedures for D4, D5, D6, Y1, Y2, and D19 to more clearly indicate equipment affected by the individual breakers.	12/31/85
Complete E-203 walkdowns and issue Discrepancy packages to the Nuclear Engineering Dept. for disposition.	7/31/86
Revise all affected procedures to include:	9/30/86
1) Applicable Technical Specifications	
2) Walkdown-Observed Configuration Changes	
3) Component Details	


RECEIVED-REGION I
AUG 14 1985

BOSTON EDISON COMPANY

Mr. Steward D. Ebnetter
U.S. Nuclear Regulatory Commission
August 7, 1985
Page Two

We trust that this information will provide the details and content required. However, if you have any further questions regarding these issues, please do not hesitate to contact me.

Very truly yours,

A handwritten signature in dark ink, appearing to read "W.D. Harrington". The signature is written in a cursive, somewhat stylized script.

W. D. Harrington