



Partners In Care

DMB COPY

3013396

Scioto Memorial Hospital

1805 27th Street Portsmouth, Ohio 45662-2640
Telephone 614/354-7581

September 5, 1985

D. J. Sreniawski, Chief
Nuclear Materials Safety Section 2
United State Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Re: **License Number 34-15938-02**


Dear Mr. Sreniawski:


In response to your letter of August 12, 1985, to correct the non-compliance relative to the GM Survey Meter, the following steps have been taken:

1. A new survey meter which is felt to meet the requirements was ordered and has now been received. This is a Lydlum Model #3, Probe Model #44-7, Serial #PR 025040.
2. Pursuant with our discussion with Ms. C. C. Casey, it is our intent to utilize our previous GM Survey Meter Victoreen Model #6B, Serial #57500, to fill in that short gap of a couple of weeks when the aforementioned new survey meter is periodically calibrated.

I believe this will fulfill the requirements and it is our understanding that with this change we are in full compliance under our license. If you feel these steps are not satisfactory, please call me as soon as possible.

Sincerely,


George V. Johnson, M.D.
Radiation Safety Officer


Terry L. Vanderhoof
Sr. V.P. & Chief Operating Officer

ps

8509160241 850905
REG3 LIC30
34-15938-02 PDR

IE07 1/0