

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

August 20, 1985

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief  
Licensing Branch No. 4

Subject: McGuire Nuclear Station  
Docket Nos. 50-369 and 50-370  
Commitment to Reroute Instrument Lines

Dear Mr. Denton:

In Licensee Event Report 369/85-03 dated February 20, 1985, Duke Power Company committed to reroute instrument impulse lines and to heat trace and insulate by next winter (December, 1985). Due to design and material lead times, and that the implementation of these modifications during an outage is preferred, the modifications will be delayed until an outage in 1986.

Very truly yours,

*Hal B. Tucker*

Hal B. Tucker

JBD/hrp

cc: Dr. J. Nelson Grace, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. W. T. Orders  
Senior Resident Inspector  
McGuire Nuclear Station

8508230158 850820  
PDR ADCK 05000369  
S PDR

Pool  
1/0