

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

August 6, 1985

RECEIVED
NRC

1985 AUG 13 AM 11:24

SCE

REGION V

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
Licensee Event Report Nos. 82-094 Revision 3 and 82-103 Revision 3
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, Mr. H. B. Ray (SCE) to Mr. R. H. Engelken, (NRC),
dated March 30, 1983, "Licensee Event Report Nos. 82-094
Revision 2 and 82-103 Revision 2"

This letter provides the follow-up to the referenced reports which were made in accordance with Section 6.9.1.13.b of Appendix A to Facility Operating License NPF-10 for San Onofre, Unit 2, for two occurrences involving Limiting Condition for Operation (LCO) 3.6.3. The revision to LER 82-094 is being submitted to delete the reference to LER 82-103 and update the corrective action. The revision to LER 82-103 is being submitted to provide the results of an evaluation into the root cause of the subject failure and the corrective action supporting this evaluation.

If you require any additional information, please so advise.

Sincerely,

HE Morgan

Enclosures: LER 82-094 Revision 3, 82-103 Revision 3

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

U.S. Nuclear Regulatory Commission
Document Control Desk

Institute of Nuclear Power Operations (INPO)

8508260219 850806
PDR ADCK 05000361
S PDR

11 IE-29