

Docket: 50-267

AUG 20 1985

Public Service Company of Colorado  
ATTN: O. R. Lee, Vice President  
Electric Production  
P. O. Box 840  
Denver, Colorado 80201-0840

Gentlemen:

Our consultants at the Los Alamos National Laboratory have completed their review of three tasks for which we had requested their assistance. The results of their review are contained in the enclosed reports:

1. Review of Fuel Rod Metallography on Fort St. Vrain Fuel Element SN 1-2415
2. Post Irradiation Examination of Fort St. Vrain Cracked Fuel Element SN-1-2415.
3. Evaluation of Concrete Creep and Stress Redistribution in the Fort St. Vrain PCRV Following Rupture of Prestressing Tendons.

We are providing you these reports for your information and/or comment.

Since no specific reporting is required, OMB clearance is not required under P.L. 96-511.

If you have any questions on this matter, please contact me.

Sincerely,

/s/

Philip C. Wagner  
Senior Project Manager

Enclosures:  
As stated

cc:  
See next page

RSB/ES *ew*  
PCWagner:gb  
8/15/85

*Ret 8/11/85*  
ES *PCWagner*  
REIreland  
8/15/85

RSB *QW*  
DRHunter  
9/19/85

8508270077XA

CC:

Mr. D. W. Warembourg, Manager  
Nuclear Engineering Division  
Public Service Company of Colorado  
P. O. Box 840  
Denver, Colorado 80201

Mr. David Alberstein, 14/159A  
GA Technologies, Inc.  
P. O. Box 85608  
San Diego, California 92138

Kelley, Stansfield & O'Donnell  
Public Service Company Building  
550 15th Street, Room 900  
Denver, Colorado 80202

Chairman, Board of County Comm.  
of Weld County, Colorado  
Greeley, Colorado 80631

Regional Representative  
Radiation Programs  
Environmental Protection Agency  
1860 Lincoln Street  
Denver, Colorado 80203

Mr. H. L. Brey, Manager  
Nuclear Licensing/Fuels Div.  
Public Service Company of Colorado  
P. O. Box 840  
Denver, Colorado 80201

J. W. Gahm, Manager, Nuclear  
Production Division  
Fort St. Vrain Nuclear Station  
16805 WCR 19 $\frac{1}{2}$   
Platteville, Colorado 80651

L. Singleton, Manager, Quality  
Assurance Division  
(same address)

Colorado Radiation Control Program Director

bcc distrib. by RIV:

RPB	Resident Inspector
RSB	Section Chief, RSB/ES
P. Wagner, RSB/ES	R. Denise, DRSP
RIV Official Reading File	
CPB/NRR	D. Eisenhut, D/DL
K. Heitner, ORB3	J. Taylor, IE

*Kcm*  
R. D. Martin, RA  
EP&RPB  
E. Haycraft, DRSP/LA  
E. Butcher, ORB3  
G. Linaas, DL  
E. Jordan, IE