



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

AUG 16 1985

Report Nos.: 50-413/85-32, 50-414/85-30, 50-369/85-25, 50-370/85-30,
50-269/85-22, 50-270/85-22 and 50-287/85-22

Licensee: Duke Power Company
422 South Church Street
Charlotte, NC 28242

Docket Nos.: 50-413, 50-414, 50-369,
50-370, 50-269, 50-270
and 50-287

License Nos.: NPF-35, CPPR-117
NPF-9, NPF-17,
DPR-38, DPR-47,
and DPR-55

Facility Name: Catawba, Oconee, and McGuire

Inspection Conducted: July 23, 1985

Inspector: W. W. Stansberry
W. W. Stansberry

5 Aug 1985
Date Signed

Approved by: W. E. Cline
for W. E. Cline, Section Chief
Division of Radiation Safety and Safeguards

08/11/85
Date Signed

SUMMARY

Scope: This special, announced inspection involved 5 inspector-hours onsite in the areas of Emergency Preparedness, Emergency Response Facilities, and NRC Response Team Coordination.

Results: Of the three areas inspected, no violations or deviations were identified.

8508290317 850816
PDR ADOCK 05000269
G PDR

REPORT DETAILS

1. Persons Contacted

Licensee Employees

- *M. E. Bolch, Catawba Nuclear Station Emergency Planner
- *C. C. Jennings, Oconee Nuclear Station Emergency Planner
- *J. R. Leonard, McGuire Nuclear Station Emergency Planner
- *R. E. Harris, Duke Power Company System Emergency Planner

*Attended exit interview

2. Exit Interview

The inspection scope and findings were summarized on July 23, 1985, with those persons indicated in paragraph 1 above. The licensee did not identify as proprietary any of the materials provided to or reviewed by the inspector during this inspection.

3. Licensee Action on Previous Enforcement Matters

This subject was not addressed in the inspection.

4. Independent Inspector Effort (92706)

The inspector held discussions with licensee representatives regarding emergency preparedness, emergency response facilities, Region II Incident Response Teams, and NRC-licensee interface during emergencies. Experiences and lessons-learned from the Full Field Exercise of the Federal Radiological Emergency Response Plan at Plant St. Lucie, in March 1984 were discussed. A draft copy of the logistical needs of the Region II Incident Response Teams was presented and discussed. The inspector discussed NRC response team organization, NRC concept of operation, roles and responsibility of the site team, and interface areas between the NRC and licensee response team. The licensee's plans for evaluation of the Crisis Management Center in Charlotte, North Carolina were discussed.

Licensee representative indicated that they would like additional information on the ERF appraisal program. The licensee was advised in a telephone conversation between Mr. W. E. Cline (NRC) and Mr. R. Harris, Duke Power Emergency Preparedness Coordinator that additional information would be provided.