

JAN 16 1986

Docket No. 50-454

Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. H. A. Walker of this office on January 6-10, 1986, of activities at Byron Unit 2 authorized by NRC Construction Permit No. CPPR-131 and to the discussion of our findings with Mr. R. E. Querio and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

ORIGINAL SIGNED BY L. A. REYES

Luis A. Reyes, Chief
Operations Branch

Enclosure: Inspection Report
No. 50-455/86002(DRS)

See Attached Distribution

8601220419 860116
PDR ADOCK 05000455
Q PDR

yes
RIII
HAW
Walker/mab
01/16/86

yes
RIII
1/14
Hawkins

yes
RIII
PRP for
Forney
1/16

RIII
Reyes
1/16/86

1/1
FE01

JAN 16 1986

Distribution

cc w/enclosure:

D. L. Farrar, Director
of Nuclear Licensing
V. I. Schlosser, Project Manager
Gunner Sorensen, Site Project
Superintendent
R. E. Querio, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division
D. W. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE
Steve Lewis, ELD
L. Olshan, NRR LPM
H. S. Taylor, Quality Assurance
Division