



Chevron U.S.A. Inc.
P.O. Box 29789, Honolulu, HI 96820 • Phone (808) 682-5711

M.J. Holmes
Manager
Hawaiian Refinery
Manufacturing Department

RECEIVED
HST

1985 MAY -6 PM 1:42

REGION V HST

May 1, 1985

DOCKET NO.: 030-13317
LICENSE NO.: 53-17787-01
CONTROL NO.: 13830
FILE: 071.

U. S. Nuclear Regulatory Commission
Region V
Materials Radiation Protection Section
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Gentlemen:

Pursuant to the U.S. Nuclear Regulatory Commission Regulatory Guide 10.7, Chevron U.S.A. Inc., Hawaiian Refinery requests an amendment to License Number 53-17787-01 to permit storage of Cobalt-60 radioactive sources. This source is required for gamma ray scanning of columns and pipes to help find anomalies during process operations. The material will be kept in a lead shield container.

Please advise if additional information is needed.

Very truly yours,

M. J. HOLMES

MJH

RLS:tmp

RECEIVED BY LFMB	
Date..	5/13/85
Log.	May 1 I
By..	Brown
Orig	
Action Comp.	6/3/85

Applicant..	12516
Check No.	860/3P
Amount. Fee Category	
Type of Fee	Amendment
Date Check Rec'd	5/28/85
Received By..	Brown

8512030212 851001
REG5 LIC30
53-17787-01 PDR

70190

NOTE TO: License Fee Management Branch, ADM

FROM: Region V

SUBJECT: VOIDED APPLICATION

Control Number 70190

Applicant Chevron U.S.A.

Date Voided 10/1/85

Reason for Void _____

non response to
deficiency letter

Signature fr

Attachment:
Application

OK LFMS
(no refund due)

ML 50

1/1