

MAY 24 1985

Sytec, Inc.  
ATTN: Allison Blackmer  
Radiological Officer  
2525 S. Oneida Street  
Appleton, WI 54915

Dear Ms. Blackmer:

Pursuant to your request, enclosed is Amendment No. 03 to NRC License Number 48-21261-01.

Please note that Condition 18. has been modified to require Sytec representatives to have available for reference a copy of the device manufacturer's operating, maintenance and emergency instructions when servicing generally licensed devices.

Be advised that per your letter dated May 10, 1985, we have not amended your license to include servicing LFE devices located at Gilbert Paper Company. We will continue the review of this request when the concerns expressed in your letter have been resolved.

In view of this amendment, please review your license carefully to assure that you understand and are in compliance with the terms and conditions contained therein. If you have questions, please contact our office by dialing (312) 790-5625.

Sincerely,

*B. J. Holt for*  
Original Signed By  
B.J. Holt  
Materials Licensing Section

Enclosure: Amendment No. 03

RIII

*2-15/24/85*  
Holt/cm  
05/23/85

8509120417 850524  
REG3 LIC30  
48-21261-01 PDR

## CONVERSATION RECORD

TIME

10:20

DATE

5/23/85

TYPE

☐ VISIT☐ CONFERENCE☒ TELEPHONE☐ INCOMING☐ OUTGOING

ROUTING

NAME/SYMBOL

INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

See Below

ORGANIZATION (Office, dept., bureau, etc.)

TELEPHONE NO:

SUBJECT

Sytec Inc.

Control No. 78996

SUMMARY

Regarding request to service NDC System  
Backscatter Gages:

(S.B. Fishman)

I discussed with NDC the method  
used for leak testing the devices and  
for replacing the probe assembly.  
They confirmed Sytec's submitted procedures  
for leak testing and said that the  
probe assembly exchange was a simple  
electrical disconnect. No source  
handling is involved. I also  
contacted the State of CA and they  
confirmed NDC's response. I contacted  
Ted Amberg at Promac and discussed  
with him the training received by Sytec.

ACTION REQUIRED

It appears to be adequate for what they  
want to do. (NDC also confirmed that  
Promac is one of their distributors and that  
Amberg is authorized on their license.)

ACTION TAKEN

None. For Info Only

SIGNATURE

TITLE

DATE

50271-101

© (20) 1981 O - 361-526 (7227)

CONVERSATION RECORD

OPTIONAL FORM 271 (12-76)  
DEPARTMENT OF DEFENSE