

SEP 9 1985

Docket No. 50-454

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. M. Hinds, Jr., P. G. Brochman, B. L. Hansen and R. M. Lerch of this office on August 2 - September 3, 1985, of activities at Byron Station Unit 1, authorized by NRC Operating License NPF-37 and to the discussion of our findings with Mr. R. E. Querio and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure/s will be placed in the NRC Public Document Room.

8509130111 850909
PDR ADOCK 05000454
G PDR

SEP 9 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by R. F. Warnick"

R. F. Warnick, Chief
Reactor Projects Branch 1

Enclosure:

Inspection Report
No. 50-454/85036(DRP)

cc w/encl:

D. L. Farrar, Director
of Nuclear Licensing
V. I. Schlosser, Project Manager
Gunner Sorensen, Byron Project
Construction Manager
R. E. Querio, Station
Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division
D. W. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE
W. Paton, ELD
L. Olshan, NRR LPM

RIII
WA
Lerch/r1
9/9/85

RIII
WA
Forney
9/9

RIII
RFW
Warnick
9/9