

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

September 9, 1985

BECO 85-163

Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch #2
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License DPR-35
Docket 50-293

Dear Sir:

By letter dated July 1, 1985, the NRC provided a Safety Evaluation Report (SER) on the post-accident sampling system (PASS) installed at Pilgrim Nuclear Power Station (PNPS).

That SER requested that Boston Edison submit a revised procedure for estimating reactor core damage for NRC review. To expedite NRC review, BECO provided a copy of PNPS Procedure No. 5.7.5, "Estimating Core Damage, Rev. 1", to Mr. Paul Leech of your office.

We hereby formally submit Procedure 5.7.5, Rev. 1 as an attachment to this letter. Should you wish further information on this issue, please contact us.

Very truly yours,

G. J. O'Brien
for W. D. Harrington

Attachment: PNPS Procedure No. 5.7.5

Pool

8509130247 850909
PDR ADOCK 05000293
PDR