

DMB

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

5N 157B Lookout Place

06 JAN 17 AIO: 24

January 13, 1986

U.S. Nuclear Regulatory Commission
Region II
ATTN: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

5

Dear Dr. Grace:


Please refer to J. A. Domer's letter to you dated October 31, 1985 which provided our response to OIE Inspection Report 85-36 for BFN. We indicated a procedure would be issued for the mechanical maintenance small tool repair and calibration shop that will implement all requirements. That procedure will be issued by January 17, 1986. This was discussed between B. C. Morris at BFN and Floyd Cantrell of your staff on January 10, 1986.

If you have any questions, please get in touch with R. E. Alsup at FTS 858-2725.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


J. W. Hufham
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8601290133 860113
PDR ADOCK 05000259
G PDR