

Docket File 40-8786  
 PDR/DCS  
 DBangart, RIV  
 Swastler  
 URFO r/f  
 WDEQ  
 JHaes, RCPD, WY

40-8786/SLW/85/09/03/0

- 1 -

SEP 10 1985

URFO:SLW  
 Docket No. 40-8786  
 04008786251E  
 04008786271E

Uranium Resources, Inc.  
 ATTN: R. F. Clements, Jr.  
 Vice President - Exploration  
 Suite 735, Promenade Bank Tower  
 1600 Promenade Center  
 Richardson, Texas 75080

Dear Mr. Clements:

This letter is to reiterate the agreements reached between NRC, WDEQ and URI during the August 29, 1985 meeting held at the North Platte site. The purpose of this meeting was to discuss the status of the URI's ground-water sweep program at the North Platte site. As stated during the meeting, the NRC has reviewed the result received to date of the daily and weekly ground-water sampling conducted by URI, WDEQ and NRC and concluded that the ground-water parameters appear to be stabilizing near values representative of background. As a result, the NRC concurred in URI's August 16, 1985 request to discontinue ground-water sweep. Upon receipt of all URI, WDEQ and NRC outstanding ground-water sampling results, the NRC and WDEQ will again review the ground-water sweep program. Should the additional ground-water data support the NRC's conclusions that ground-water parameters have stabilized near values representative of background, then the NRC would proceed with the write off on the restoration and stabilization of the North Platte site. Should the review of the additional ground-water data show some anomalies, the NRC may request that the ground-water sweep program be restarted. URI agreed with the approach as outlined above.

In addition to discussion of the ground-water sweep program, the NRC conducted the annual inspection of Source Material License SUA-1400 for the North Platte site. As a result of the inspection, the following documents, which were located in the Texas office, were to be submitted:

C :	8509190109 PDR	850910 ADOCK	04008786 PDR	:	:	:
ME :	:	:	:	:	:	:
TE :85/09/09	:	:	:	:	:	:

SEP 10 1985

- ° Instrument calibration records as required by License Condition No. 24.
- ° Results of alpha, gamma, Rn-222 or daughters surveys required by License Condition No. 21.
- ° Data on cleaning of MW-4 as required by License Condition No. 33.
- ° Documentation of walkthrough inspections and security checks required by License Condition No. 30.

In order to complete our annual inspection by the end of the fiscal year, the above stated documents must be submitted no later than September 20, 1985. If the documents have not been received by this date, the NRC will issue violations based on a lack of information being available to verify compliance with the above stated license conditions.

Should you have any comments or questions regarding this letter, please contact Sandra L. Wastler of my staff at (303) 236-2811.

Sincerely,  
Original Signed By  
Edward F. Hawkins

Edward F. Hawkins, Chief  
Licensing Branch 1  
Uranium Recovery Field Office  
Region IV

UREO	URFO					
SWastler/lv	EHawkins					
TE : 85/09/09	9/10/85					