

**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791
Fax (203) 444-4277

The Northeast Utilities System

April 3, 1997
Docket No. 50-336
B16294

Re: 10 CFR 50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 96-031-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on October 3, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii). This LER supplement provides an update on the analyses and corrective actions planned for this event.

The following are NNECO's commitments made within this letter.

B16294-01: As a result of this event, corrective actions will be implemented to ensure that the plant response to analyzed events will not result in exceeding the design requirements of the SG. These actions will include any necessary reanalysis and plant modifications. These actions will be completed prior to plant restart from the current outage.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



J. A. Price
Director - Millstone Unit No. 2

1/1
Ierr

cc: see page 2

080081

9704090073 970403
PDR ADDCK 05000336
S PDR



Attachment: LER 96-031-01

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2