

ENCLOSURE

NOTICE OF VIOLATION

William Vasquez Agrait

License No. 52-21368-01

The following violation was identified during an inspection conducted on August 20, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

License Condition 12 requires that licensed material be used by individuals who are directly supervised by certain named people or who have completed specific training courses.

Contrary to the above, licensed material has been used routinely by two individuals who were not supervised as required nor had they completed either of the specified training courses.

This is a Severity Level IV violation (Supplement VI).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: SEP 6 1985

8509190847 850906  
REG2 LIC30  
52-21368-01 PDR