

FEB 02 1986

Docket No. 030-10538

License No. 29-16185-01

U. S. Department of Commerce
NOAA, NMFS, NEFC
ATTN: Mr. John E. O'Reilly
Chief, Chemical Processing Branch
Sandy Hook Facility
Highland, New Jersey 07732

Gentlemen:

Subject: Inspection No. 030-10538/85-02

This refers to the special safety inspection conducted by Marlene J. Taylor of this office on October 25, 1985, of activities authorized by NRC License No. 29-16185-01 and to the discussions of our findings held by Mrs. Taylor with yourself at the conclusion of the inspection.

The area examined during the inspection was the loss of licensed material due to a fire at your facility and is described in the enclosed report. Within this area, the inspection consisted of interviews with personnel, and measurements made by the inspector.

Within the scope of this inspection, no violations were observed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed report will be placed in the Public Document Room.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:
John D. Kinneman

John D. Kinneman, Chief
Nuclear Materials Safety Section A,
Division of Radiation Safety
and Safeguards

Enclosure: NRC Region I Report No. 030-10538/85-02

cc:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
State of New Jersey

OFFICIAL RECORD COPY

IR DOC-85-02 - 0001.0.0
01/16/86

8602070141 860202
REG1 LIC30
29-16185-01 PDR

RETURN ORIGINAL TO
REGION I

1E:07

FEB 02 1986

U.S. Dept. of Commerce

2

bcc:
Region I Docket Room (w/concurrences)

mgT
RI:DRSS
Taylor/ca/mmb

1/28/86

Kinneman
RI:DRSS
Kinneman

1/30/86

OFFICIAL RECORD COPY

IR DOC-85-02 - 0002.0.0
01/16/86