

November 15, 1985

Docket No. 50-346

Mr. Joe Williams, Jr.
Senior Vice President, Nuclear
Toledo Edison Company
Edison Plaza - Stop 712
300 Madison Avenue
Toledo, Ohio 43652

DISTRIBUTION

Docket File

NRC PDR
L PDR
ORB#4 Rdg
HThompson
OELD
EJordan
BGrimes
JPartlow

JRidgely
ACRS-10
RIngram
ADeAgazio
GDick
EBrach
Hornstein
WPaulson
GEdison
OParr

Dear Mr. Williams:

SUBJECT: DAVIS BESSE ROOT CAUSE FINDING REPORT PLAN 1D

On October 30, 1985 we provided Toledo Edison Company with our evaluation of your report related to AFPT overspeed trip throttle valve problems, Plan 1D. The revision of the report which we reviewed indicated that it was Toledo Edison Company's intent to replace the trip spring for the trip and throttle valve on both AFPTs prior to restart of Davis Besse. This recommendation had previously been provided to you in a letter from Terry Turbine on February 3, 1984.

In Revision 3 to Plan 1D, submitted on October 31, 1985 (Serial No. 1202), this commitment has been deleted. It is our position that these springs should be replaced as per manufacturer's recommendations prior to restart; otherwise an acceptable justification should be provided. The report on Plan 1D should be revised to reflect restoration of the commitment or the requested justification for our review. Please provide your revision no later than November 30, 1985.

Sincerely,

"ORIGINAL SIGNED BY

JOHN F. STOLZ"

John F. Stolz, Chief
Operating Reactors Branch #4
Division of Licensing

cc: See next page

ORB#4:DL *me*
ADeAgazio;cr
11/15/85

ORB#4:DL *fd*
JStolz
11/15/85

8512050410 851115
PDR ADOCK 05000346
P PDR

Mr. J. Williams
Toledo Edison Company

Davis-Besse Nuclear Power Station
Unit No. 1

cc:

Donald H. Hauser, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

Ohio Department of Health
ATTN: Radiological Health
Program Director
P. O. Box 118
Columbus, Ohio 43216

Mr. Robert F. Peters
Manager, Nuclear Licensing
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Attorney General
Department of Attorney
General
30 East Broad Street
Columbus, Ohio 43215

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. James W. Harris, Director
Division of Power Generation
Ohio Department of Industrial Relations
2323 West 5th Avenue
P. O. Box 825
Columbus, Ohio 43216

Paul M. Smart, Esq.
Fuller & Henry
300 Madison Avenue
P. O. Box 2088
Toledo, Ohio 43603

Mr. Harold Kohn, Staff Scientist
Power Siting Commission
361 East Broad Street
Columbus, Ohio 43216

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation
Division
Suite 200, 7910 Woodmont Avenue
Bethesda, Maryland 20814

President, Board of
Ottawa County
Port Clinton, Ohio 43452

Resident Inspector
U.S. Nuclear Regulatory Commission
5503 N. State Route 2
Oak Harbor, Ohio 43449

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137