

FEB 02 1986

Docket No. 040-08821

License No. SMB-1419

Resource Engineering, Incorporated  
ATTN: Norman Schapiro  
Vice President  
80 Bacon Street  
Waltham, Massachusetts 02154

Gentlemen:

This refers to the safety closeout inspection conducted by Mr. John J. Miller and Mr. John T. Jensen of this office on November 21, 1985 of activities authorized by NRC License No. SMB-1419 and to the discussions of our findings held by Mr. Miller with you at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspectors, and observations by the inspectors.

Within the scope of this inspection, no violations were observed.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:  
John E. Glenn

John E. Glenn, Ph.D, Chief  
Nuclear Materials Safety Section B,  
Division of Radiation Safety  
and Safeguards

Enclosure: NRC Region I Inspection Report No. 40-08821/85-01

cc w/encl:  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
Commonwealth of Massachusetts

OFFICIAL RECORD COPY

IR RESOURCE 85-01 - 0001.0.0  
01/24/86

8602070195 860202  
PDR ADDCK 04008821  
C PDR

RETURN ORIGINAL TO  
REGION I

IE:07

FEB 02 1986

Resource Engineering Incorporated

2

bcc w/encl:

Region I Docket Room (w/concurrences)

Management Assistant, DRMA (w/o encl)

J. Jensen, RI

J. Miller, RI

RI:DRSS  
JJensen/fi  
01/24/86

RI:DRSS  
JMiller  
01/27/86

RI:DRSS  
JGlenn  
01/30/86

OFFICIAL RECORD COPY

IR RESOURCE 85-01 - 0002.0.0  
01/24/86