

OSK 85-98

November 21, 1985

Manual Holders of
Callaway Plant Security Plans
Docket NO. 50-483
Facility Operating License NPF-30

Recently, Revision 6 to the Security Plan was transmitted under letter ULNRC-1139, dated July 15, 1985, with minor printing and page errors.

To correct printing problems, figures 5.1-1 and ~~5.1-3~~ ^{5.3-1 dpm 11/26/85} are enclosed. Remove and return the above two figures and replace with the enclosed figures. 5.1-1 and 5.1-3 are both Revision 5.

Also enclosed is figure 7.3-1. This figure was inadvertently left out of the transmittal. Remove and return figure 7.3-1, Revision 3 and replace with figure 7.3-1, Revision 4.

G. R. Pendergraff
G. R. Pendergraff

GRP/tfr

Enclosures: The enclosed documents contain SAFEGUARD INFORMATION within the scope of 10 CFR 73.21. Removal of enclosures declassifies this letter.

cc: GRP Chrono
G57.64

8512060096 851121
PDR ADOCK 050004E3
F PDR

* Sool
1/4