

**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

April 4, 1997

Docket No. 50-336

B16346

Re: 10 CFR 50.73(a)(2)(i)(B)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 97-007-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on March 8, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B).

The following are NNECO's commitments made within this letter.

- B16346-01: The Surveillance Procedure, "Reactor Head and Pressurizer Vent Solenoid Valve Operability Test," will be revised to ensure that this surveillance requirement is fulfilled before entering Mode 4 from the current outage.
- B16346-02: Technical Specification surveillance procedures will be reviewed to ensure compliance with Technical Specification surveillance requirements as part of the Millstone Unit No. 2 Operational Readiness Plan. The review will initially focus on Technical Specification surveillance procedures required for Mode 6 and defueled. Surveillance procedures required for subsequent mode changes will be reviewed prior to mode entry. (This commitment was previously sent to the NRC in the response to NOV 336/96-08-07, NNECO Commitment No. B16076-2.)

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



J. A. Price
Director, Millstone Unit No. 2

IE221

9704150032 970404
PDR ADDCK 05000336
S PDR

cc: see page 2



Attachment: LER 97-007-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2