

FEB 11 1986

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

Enclosed is a copy of the revised NRC Form 398. This revised form requires that all information be completed in total with each new, renewal, upgrade, multi-unit, and reapplication license submittal. Applicants requesting a renewal and reapplication will also need to indicate the additional training received since the last application under Item 15. Please note that the training section will no longer be cumulative. Other changes are detailed in Enclosure 2. Enclosure 3 is a set of instructions for the completion of all items on the NRC Form 398.

Please ensure that all applications for licenses received after April 1, 1986, are submitted on this revised form. On that date, the NRC Operator Licensing Tracking System will be modified to reflect these changes, and submittals using the previous form will not be accepted.

Additional copies of the form can be obtained from Vivian Miller, U. S. Nuclear Regulatory Commission, Document Management Branch, Mail Stop W-548, Washington, DC 20555.

A meeting will be held with all Region III licensees in late March or early April to discuss this and other operator licensing matters. You will be notified of the details of this meeting at a later date.

If you have any questions regarding these changes, please call our office.

ORIGINAL SIGNED BY LUIS A. REYES

B602180042 B60211
PDR ADOCK 05000346
V PDR

Luis A. Reyes, Chief
Operations Branch

Enclosures: As stated

See Attached Distribution

RIII

cul
Roxworthy/mab
02/11/86

RIII

JMM
McMillen
2/11/86

RIII

Reyes
2/11/86

IFH2 110

FEB 11 1986

Distribution

cc w/enclosures:

R. Simpkins, Training Department

cc w/o enclosures:

L. Storz, Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Robert H. Quillin, Ohio

Department of Health