

Commonwealth Edison Company
Zion Generating Station
101 Shiloh Boulevard
Zion, IL 60099-2797
Tel 847-746-2084

ComEd


April 10, 1997

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Attachment: (A) List of Regulatory Commitments
(B) License Event Report Number 97-007

The enclosed Licensee Event Report number 97-007-00, Docket No. 50-295/DPR- from Zion Generating Station is being transmitted to you in accordance with the 10CFR50.73(a)(2)(iv), which requires reporting of any event or condition that resulted in a manual or automatic actuation of any engineered safety feature.

Very truly yours,



R. Starkey
Station Manager
Zion Generating Station

RS/jz

Enclosure: (A) List of Regulatory Commitments
(B) Licensee Event Report

cc:NRC Region III Administrator
NRC Resident Inspector
IDNS Resident Inspector
INPO Record Center
Illinois Department of Nuclear Safety

IE221

9704150319 970410
PDR ADDCK 05000295
S PDR

150106



Attachment A

The following table identifies those actions committed to by ComEd in this document. Any other actions discussed in this submittal represent intended or planned actions by ComEd. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify Mr. Robert Godley, Zion Station Regulatory Assurance Manager, of any questions regarding this document or any associated regulatory commitments.

Commitment Scope	Commitment Number
The Unit 2 SAT sudden pressure relay will be replaced prior to going to mode 4. (ER9701610)	NTS# 29518097124501
Repairs to the Unit 1 Safe Shutdown Timer reset function will be performed.	NTS# 29518097124502