

APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION  
REGION IV

NRC Inspection Report: 30-20309/85-02

License: 35-23147-01

Docket: 30-20309

Licensee: Petro-Log  
P. O. Box 337  
Hominy, Oklahoma 74035

Facility Name: Petro-Log

Conference Conducted: December 19, 1985

Report Prepared  
by:

W. L. Holley  
W. L. Holley, Radiation Specialist, Nuclear  
Materials Safety Section

1/31/86  
Date

Approved:

R. J. Everett  
R. J. Everett, Chief, Nuclear Materials  
Safety Section

2/3/86  
Date

Conference Summary

Conference held on December 19, 1985 (Report: 30-20309/85-02)  
(Report 30-20309/85-01)

On December 19, 1985, a representative of Petro-log met with Region IV personnel in Arlington, Texas, to discuss the findings of the NRC inspection performed on October 31 and November 1, 1985. The meeting was held at the request of Region IV.

Results: The NRC presented four violations of NRC requirements and expressed concern regarding control of the licensed program. The licensee representative responded relative to his understanding of the violations and presented no information that would allow deletion or modification of the violations. The licensee described the actions taken or planned to bring the licensed program within full compliance of NRC requirements and prevent similar occurrences in the future. The NRC staff emphasized the enforcement options available. The NRC staff stated that a decision would be made as to the appropriate enforcement action and that the licensee would then be notified.

8602180278 860210  
REG4 LIC30  
35-23147-01 PDR

DETAILSPersons Participating in the ConferencePetro-log

Robin Kidd, Manager

NRC Region IV

R. L. Bangart, Director, Division of Radiation Safety and Safeguards  
R. D. Everett, Chief, Nuclear Materials Safety Section  
G. D. Brown, Radiation Specialist  
W. L. Holley, Radiation Specialist  
D. A. Powers, Enforcement Officer