

FEB 11 1986

License: 36-15657-01
Docket: 30-09530/85-01

Pacific Power & Light Company
920 Southwest Sixth Avenue
Portland, Oregon 97204

Gentlemen:

Enclosed please find NRC Inspection Report 30-09530/85-01 documenting the NRC inspection conducted on November 14, 1985, and the enforcement conference held by telephone on December 12, 1985. The Enforcement Conference was held to review the inspection findings and to obtain your response to these findings. Enforcement correspondence concerning these matters was sent to you under separate cover.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examination of procedures and representative records, interviews of personnel, reenactments of events, independent measurements, and observations by the inspector.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed by:
R. L. BANGART

Ramon E. Hall, Chief
Radiological and Safeguards
Programs Branch

Enclosure:
NRC Inspection Report
30-09530/85-01

cc:
Charles T. McCoy
Bridger Power Plant
P. O. Box 158
Point of Rocks, Wyoming 82942

Wyoming Radiation Control Program Director

bcc:
DMB - Original (IE-07)
RMartin
RBangart
*w/766
D. Weiss, LFMB (AR-2015)
*Inspector
*MIS System
D. Powers
*RIV Files
*NMSS
*RSTS Operator

RIV:NMSS
LRickelson/tw
2/6/86
C:NMSS
RSEverett
2/6/86

C:RASP
REHall
2/10/86
D:DRS
RLBangart
2/10/86

EO
DAPowers
2/7/86

8602180286 860211
REG4 LIC30
36-15657-01 PDR