



Northeast
Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791
Fax (203) 444-4277

The Northeast Utilities System

April 8, 1997
Docket No. 50-336
B16371

Re: 10 CFR 50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 97-008-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on March 10, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i).

The following are NNECO's commitments made within this letter.

- B16371-01: The surveillance procedures for testing the bistables will be revised prior to entry into Mode 4 from the current outage to verify the red status lamps on the bistables.
- B16371-02: The facility Generic Letter 96-01 review, which will verify that all circuits are tested properly from the detector to the Reactor Trip circuit breakers, shall be completed prior to entry into Mode 4 from the current outage.

IE221


9704160134 970408
PDR ADOCK 05000336
S PDR



B16371-03: In the response to NOV 336/96-08-07 (NNECO Commitment No. B16076-2), Millstone Unit No. 2 committed to perform a review of Technical Specification surveillance procedures to ensure compliance with Technical Specification surveillance requirements as part of the Operational Readiness Plan.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

A handwritten signature in cursive script, appearing to read "H. L. Miller for", is written over a horizontal line.

J. A. Price

Director - Millstone Unit No. 2

Attachment: LER 97-008-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2