

FEB 12 1986

Docket No. 50-341

The Detroit Edison Company
ATTN: Frank E. Agosti
Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Mr. L. J. Hueter of this office on January 13-17, 1986, of activities at Fermi 2 authorized by NRC Operating License No. NPF-33 and to the discussion of our findings with F. E. Agosti and other members of your staff at the conclusion of the inspection and by telephone on February 3, and 7, 1986.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection. However, we are concerned that personnel errors were apparently a root cause of all six occurrences involving the area of gaseous and liquid effluents reviewed during this inspection. Specific corrective measures had been instituted in each case. In addition, we understand that two programs, the recently implemented Reactor Operations Improvement Program and Radiological Improvement Plan being developed, are intended to address a generic approach for resolution of the recurring problem of personnel errors. We will monitor the effectiveness of these programs during future inspections.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8602190039 860212
PDR ADDCK 05000341
Q PDR

W. D. Shafer

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Report
No. 50-341/86002(DRSS)

See Attached Distribution
RIII LSH/Hueter/mj
RIII Schumacher

RIII RO
Wright
2/12/86

RIII
Shafer

IEOB
delete
RSH

The Detroit Edison Company

2 FEB 12 1986

Distribution

cc w/enclosure:

L. P. Bregni, Licensing
Engineer

P. A. Marquardt, Corporate
Legal Department

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

Harry H. Voigt, Esq.

Nuclear Facilities and

Environmental Monitoring
Section

Monroe County Office of
Civil Preparedness