

North
Atlantic

North Atlantic Energy Service Corporation
P.O. Box 300
Seabrook, NH 03874
(603) 474-9521

The Northeast Utilities System

April 11, 1997

Docket No. 50-443
NYN-97033

United States Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555


Seabrook Station
Emergency Response Manual Revision 76 and
Radiological Emergency Plan Revision 24

Enclosed, please find Revision 76 to the Seabrook Station Emergency Response Manual (SSER) and Revision 24 to the Seabrook Station Radiological Emergency Plan (SSREP). The revisions were reviewed per the criteria of 10 CFR 50.54(q) and it was determined that they do not decrease the effectiveness of the Seabrook station Radiological Emergency Plan (SSREP). The SSREP continues to meet the standards of 10 CFR 50.47(b) and 10 CFR 50, Appendix E. These changes are submitted per the requirements of 10 CFR 50, Appendix E, and 10 CFR 50.4. The Resident Inspector copies are provided directly through the North Atlantic records management system.

Should you have any questions regarding the enclosed SSER and SSREP revisions, please call Mr. Terry L. Harpster, Director of Licensing, at (603) 773-7765.

Very truly yours,

NORTH ATLANTIC ENERGY SERVICE CORP.


Ted C. Feigenbaum
Executive Vice President and
Chief Nuclear Officer

cc: Hubert J. Miller, Region I Administrator (two copies of SSER and SSREP)
Mr. Albert W. De Agazio, Sr. Project Manager (one copy of SSER)

(without enclosure)

Mr. John B. Macdonald, NRC Senior Resident Inspector

9704170023 970411
PDR ADOCK 05000443
F PDR



A045 1/1