



Department of Energy  
Albuquerque Operations Office  
P.O. Box 5400  
Albuquerque, New Mexico 87185-5400

Rec'd VRB  
04-14-97

April 8, 1997

Mr. Joseph J. Holonich, Chief  
Uranium Recovery Branch  
Office of Nuclear Material Safety  
and Safeguards  
Mail Stop T7J9  
U.S. Nuclear Regulatory Commission  
11545 Rockville Pike  
Rockville, MD 20852-2738

Dear Mr. Holonich:

*Mexican Hat, Utah Uranium Mill Tailings Remedial Action Project*  
Enclosed is one copy of the 1996 Annual Prelicensing Inspection Report. Please replace this report with the one that was previously sent to you on March 11, 1997. The report that was transmitted in March contained a number of errors. Please give me a call at (505) 845-5668 if you have any questions.

Sincerely,

Sharon J. Arp  
Site Manager  
Uranium Mill Tailings Remedial Action Team  
Environmental Restoration Division

Enclosure

cc w/enclosure:  
H. Lefevre, NRC

cc w/o enclosure:  
J. Virgona, GJPO

9704170122 970408  
PDR WASTE  
WM-63 PDR

160039



1/1  
WM-63  
NL04

Recd VRB  
04 14-97

Your copy of the 1996 LTSM Mexican Hat Inspection Report may be incomplete. Please replace it with the attached copy.

March 1997