



PECO NUCLEAR

A Unit of PECO Energy

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
610 718 2000

10CFR50.73

April 11, 1997

Docket Nos. 50-352
50-353
License Nos. NPF-39
NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Units 1 and 2

This LER reports a reduction in the ability to achieve safe shutdown in the event of a fire as provided by the Fire Protection Program. Instrument gas may not be available to operate the main steam relief valves due to postulated fire damage. This resulted in a failure to meet License Conditions for Limerick Generating Station Units 1 and 2 .

Reference:	Docket Nos. 50-352 50-353
Report Number:	1-96-021
Revision Number:	01
Event Date:	October 26, 1984 Unit 1 June 22, 1989 Unit 2
Discovery Date:	December 5, 1996
Report Date:	April 11, 1997
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER revision provides amplification of information provided in the original version regarding the discovery, cause, scope and schedule of corrective actions, and generic implication review of this event. This information is beyond that required by 10CFR50.73 and is provided to assist the NRC in evaluating the enforcement actions related to this event. Changes are indicated by revision bar markers. This LER is being submitted pursuant to the requirements of License Conditions 2.F for Unit 1 and 2.E for Unit 2.

Very truly yours,

170064

Robert W. Boyce

IE221/1

cc: H. J. Miller, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

9704170368 970411
PDR ADOCK 05000352
S PDR

