



DEPARTMENT OF THE ARMY  
HEADQUARTERS, U. S. ARMY MATERIEL COMMAND  
5001 EISENHOWER AVENUE, ALEXANDRIA, VA 22333-0001

25 February 1985

'85 MAR -6 AM 1:10

Director  
Nuclear Material Safety and Safeguards  
ATTN: Radioisotopes Licensing Branch  
US Nuclear Regulatory Commission  
Washington , DC 20555


Reference: AMCSF-P/84-0005

Gentlemen:

Forwarded are four copies of the US Army Aviation Systems Command request for amendment to Source Material License Number STB-1433. The request is to eliminate the requirement that respirators be used during licensed maintenance on aircraft components containing thorium-magnesium alloys.

Please acknowledge receipt of correspondence on enclosed DA Form 209, Mail Reply Card.

Sincerely,

  
DARWIN N. TARAS  
Chief, Health Physics,  
Safety Office

Enclosures

Copies Furnished:  
HQDA (DASG-PSP-E), WASH DC 20310 w/o encl  
Director, AMC FSA, Charlestown, IN 47111 w/encl  
Commander, AVSCOM, ATTN: AMSAV-X, St. Louis, MO 63120

8602190660 851217  
REG3 LIC40  
STB-1433 PDR

24919