

SEP 30 1985

Docket No. 50-29

Yankee Atomic Electric Company
ATTN: Mr. L. H. Heider
Vice President of Operations
1671 Worcester Road
Framingham, Massachusetts 01701

Gentlemen:

Subject: Inspection Report No. 50-29/85-16

A routine safety inspection of the radiation protection program at Yankee Nuclear Power Station was conducted on August 12-16, 1985. Areas inspected included respiratory protection, shipment of spent resin, ALARA, posting of radiation areas, and the procedures revision project.

The inspection report is attached. The inspectors found the allocation of resources to upgrading the radiation protection procedures and improving the quality control program to be commendable. No violations were identified and no reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

Ronald R. Bellamy
Thomas T. Martin, Director
Division of Radiation Safety
and Safeguards

Enclosure: NRC Region I Inspection Report No. 50-29/85-16

cc w/encl:

N. N. St. Laurent, Plant Superintendent
J. E. Tribble, President
G. J. Papanic, Jr., Senior Project Engineer - Licensing
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)

8510040163 850930
PDR ADOCK 05000029
Q PDR

OFFICIAL RECORD COPY

IR YR 85-16 - 0001.0.0
09/24/85

TE06
11

bcc w/encl:
Region I Docket Room (with concurrences)
Senior Operations Officer (w/o encl)
DRP Section Chief
M. McBride, RI, Pilgrim

RI:DRSS/amb
TDragoun

9/25/85

RI:DRSS
MShanbary

9/25/85

RI:DRSS
RBellamy

9/26/85

OFFICIAL RECORD COPY