

ROBERTO BUXEDA, M. D., F.A.C.S., F.I.C.S.

Ashford Medical Center
Ashford Ave. Corner Washington St.,
SANTURCE, PUERTO RICO 00907

November 25, 1985

30-03589

05 DEC 2 P1:57

J. Philip Stohr, Director
Division of Radiation Safety
and Safeguards
U.S. Nuclear Regulatory Commission

Dear Sir:

Subject: Report # 52-11897-01/85-01

(1) I hereby admit the alleged violations.

(2) The only reason I can give for the violations is that they were definitely unintentional and may be attributed to the natural forgetfulness associated with a busy practice of Ophthalmology of the undersigned.

(3) The undersigned Roberto Buxeda, M.D. who is semiretired from the practice of Ophthalmology, will use the licensed material exclusively until my son Roberto M. Buxeda, M.D. obtains his own license. The undersigned will continue performing the leak tests as up to the present.

(4) Further violations will be avoided by posting current copies of Part 19, Part 20, the license, license conditions, documents incorporated into the license, license amendments and operating procedures, or by a notice describing these documents and where they may be examined.

(5) Full compliance should be achieved as of this time.

We are using the Radiation Medical Service for the leak tests. Their address is:

Radiation Medical Service
1310 W. Montgomery Ave.
Sheffield, Alabama 35660

My son is interested in obtaining his own license as Pterygium is a very common pathological condition in Puerto Rico.

8512100181 851125
NMSS LIC30
52-11897-01 PDR

Sincerely yours,

Roberto Buxeda M.D.
Roberto Buxeda, M.D., M.Sc. (Med), F.A.C.S.

P.S. Please, recommend a company specifically authorized by you to perform leak tests.

AB.