

September 30, 1985

*Martin*

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-IV-85-49

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by NRC staff on this date.

FACILITY: Arkansas Power and Light Company Licensee Emergency Classification:  
Arkansas Nuclear One, Unit 2 Notification of Unusual Event  
Russellville, Arkansas Alert  
Docket: 50-368 Site Area Emergency  
General Emergency  
X Not Applicable

SUBJECT: OUTAGE GREATER THAN TWO DAYS

The reactor was shutdown on September 28, 1985, and a cool down was commenced to replace the seal on the 'C' RCP. This seal cartridge had developed a weld crack where the middle cavity seal pressure sensing line joins the cartridge. During the outage, attempts will be made to locate and repair a main condenser tube leak. Startup is scheduled for October 3, 1985.

The licensee does not plan to issue a press release, but will respond to any media inquiries.

This information is current as of 8:00 a.m. (CDT) on September 30, 1985.

The state of Arkansas has been informed.

CONTACT: L. E. Martin, FTS 728-8153.

DISTRIBUTION:

H. ST.	MNBB	Phillips	E/W	Willste	MAIL:
Chmn Palladino	EDO	NRR	IE	NMSS	DOT: Trans Only
Comm. Zech	PA	DCS	OIA	RES	DMB (Original)
Comm. Roberts	MPA		AEOD		
Comm. Asselstine	ELD		VIB		INPO
Comm. Bernthal					NSAC
SECY		Air Rights			
ACRS		SP			
CA					
PDR Regions:					

Licensee: \_\_\_\_\_  
(Reactor Licensees)

*RIV*  
RIV:DRSP  
RPDenise/lk  
9/30/85

*RA*  
RDMartin  
30/9/85

8510040238 850930  
PDR I&E  
PNO-IV-85-049 PDR

1234  
9/1