

DMB

December 5, 1985

Docket No. 50-263

Northern States Power Company
ATTN: Mr. C. E. Larson
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Gentlemen:

This refers to the routine safety inspection conducted by Mr. P. L. Hartmann of this office on September 10 through November 25, 1985, of activities at the Monticello Nuclear Generating Station authorized by NRC Operating License No DPR-22, and to the discussion of our findings with Mr. W. Shamla and members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by N. J. Chrissotimos"

N. J. Chrissotimos, Chief
Reactor Projects Branch 2

8512100221 851205
PDR ADOCK 05000263 PDR
G

Enclosure: Inspection Report
No. 50-263/85023(DRP)

cc w/enclosure:
W. A. Shamla, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Monticello
Resident Inspector, RIII Prairie
Island
John W. Ferman, Ph.D.,
Nuclear Engineer, MPCA

RIII
RWO
Defayette/jlk
12/04/85

RIII
Boyd

RIII
Chrissotimos

LEO1
11