

MATERIALS LICENSE

Pursuant to the Atomic Energy Act of 1954, as amended, the Energy Reorganization Act of 1974 (Public Law 93-438), and Title 10, Code of Federal Regulations, Chapter I, Parts 30, 31, 32, 33, 34, 35, 40 and 70, and in reliance on statements and representations heretofore made by the licensee, a license is hereby issued authorizing the licensee to receive, acquire, possess, and transfer byproduct, source, and special nuclear material designated below; to use such material for the purpose(s) and at the place(s) designated below; to deliver or transfer such material to persons authorized to receive it in accordance with the regulations of the applicable Part(s). This license shall be deemed to contain the conditions specified in Section 183 of the Atomic Energy Act of 1954, as amended, and is subject to all applicable rules, regulations and orders of the Nuclear Regulatory Commission now or hereafter in effect and to any conditions specified below.

Licensee

1. Seatt Corporation
2464 Wisconsin Avenue
Downers Grove, Illinois 60515

In accordance with letter dated
April 23, 1985
3. License number 12-15537-02E is amended in
its entirety to read as follows:

4. Expiration date October 31, 1989

5. Docket or
Reference No. 030-11357

6. Byproduct, source, and/or
special nuclear material

7. Chemical and/or physical
form

8. Maximum amount that licensee
may possess at any one time
under this license

A. Americium 241

A. Foil sources in smoke
detection devices
(Nuclear Radiation
Developments Model
A-001 or Amersham Corp.
Model AMM-1001H)

A. Not applicable
(Refer to
Condition 10.)

9. Authorized use

- A. Pursuant to Section 32.26, 10 CFR Part 32, the licensee is authorized to
distribute smoke detector devices specified in Condition 10. to persons
exempt from the requirements for a license pursuant to Section 30.20, 10
CFR Part 30.

8602200108 851115
NMSS LIC30
12-15537-02E PDR

MLB

Send Copy to Region III

11

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License number

12-15537-02E

Docket or Reference number

030-11357

Amendment No. 14

CONDITIONS

10. Each smoke detector device distributed pursuant to this license shall contain not more than the amount of americium 241 listed in the following table:

<u>Device Model</u>	<u>Maximum-Quantity per Device</u>
100	1.3 microcuries
FXB-1	0.99 microcurie
FXC-1	0.99 microcurie
FXW-1	0.99 microcurie
Montgomery Ward Model 165800	0.99 microcurie
83-7 (FXB-1)	
Anglo-Nordic Model	0.99 microcurie
TYP-9V (FXB-1)	
Radio Shack Model 275-454	0.99 microcurie
(FXB-1)	
FG-1 (FXB-1)	0.99 microcurie
Radio Shack Model 49-454	0.99 microcurie
(FXB-1)	
Sunbeam Model 45-51 (FXB-1)	0.99 microcurie
FX-1014	0.99 microcurie
FX-1020	0.99 microcurie
FX-830	0.99 microcurie
OS-1	0.99 microcurie
FXB-1A	0.99 microcurie
FXW-1A	0.99 microcurie
FXC-1A	0.99 microcurie
Jameson Home Products CD-1	0.99 microcurie
Jameson Home Products CD-2	0.99 microcurie
Jameson Home Products CD-3	0.99 microcurie
Jameson Home Products CD-5	0.99 microcurie
Jameson Home Products CD-23	0.99 microcurie
Jameson Home Products CD-24	0.99 microcurie
Jameson Home Products RS-1	0.99 microcurie

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License number

12-15537-02E

Docket or Reference number

030-11357

Amendment No. 14

CONDITIONS

11. This license does not authorize possession or use of licensed material.
12. Distribution may be made from 2464 Wisconsin Avenue, Downers Grove, Illinois or 21-B Zane Grey, El Paso, Texas.
13. The licensee shall file periodic reports as specified in Section 32.29(c), 10 CFR Part 32.
14. Each device distributed under the license shall be manufactured, tested, and labeled in accordance with the statements, representations and procedures contained in application dated June 9, 1975; letters dated July 24, 1975, September 24, 1975, April 3, 1977, July 29, 1977, September 15, 1978, March 25, 1980, July 9, 1980, November 14, 1980, and October 29, 1980; letter received March 8, 1982; and letters dated April 4, 1983, April 21, 1983, May 12, 1983, July 20, 1983, August 18, 1983, November 4, 1983, December 9, 1983, August 30, 1984, April 23, 1985 and August 19, 1985.

FOR THE U. S. NUCLEAR REGULATORY COMMISSION

Original Signed By

John W. N. Hickey

DATE 15 1985

BY

Material Licensing Branch
Division of Fuel Cycle and
Material Safety
Washington, D. C. 20555

BA
11/2/85

2

OK to change name

Seatt
CORPORATION

April 23, 1985

Mr. John Hickey

UNITED STATES NUCLEAR REGULATORY COMMISSION
Division of Fuel Cycle & Material Safety
Washington, D.C. 20555

Dear Mr. Hickey:

Seatt Corporation, which is the parent company of Firex Corporation, was reorganized effective April 1, 1985.

Seatt Corporation is now the manufacturing unit of all smoke detectors. Firex Corporation will exist as a Sales organization involved with the Sales and distribution of smoke detectors.

Please revise your records to include the above name change.

If you have any further questions, please don't hesitate to ask.

Sincerely,

Tom Barakat

Tom Barakat

TB:sy

CC: Howard Chen
Gene Szymczak

5/1/85
April 1 Hickey
Brown
6/1/85

Applicant	
Check No.	53729 (#350)
Insurance Fee Category	#230-34
Type of Fee	Amendment
Date Check Rec'd	6/6/85
Received By	J. Allen

C.N.
18912
10 for
01

#110
refunded
6/25/85

85 APR 26 P3:12

2464 Wisconsin Avenue
Downers Grove, IL 60515
312/963-1580

~~8509110174~~

18907



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

DATE: 10/22/85

TO: Steve Baggett

SUBJECT: REQUEST FOR ASSISTANCE

RETURN TO: IMAS, MLB, 396-SS

Control No. 019198 (attached)

License No. 12-15537-02E (attached)

Letter No. (attached)

Assistance requested:

- ☐ Custom review
☐ New source review
☐ New device review
☒ Other (see remarks)

Steve: Try to give quick turnaround. Do you need to do anything? Better to be sure. 10/23/85

REMARKS:

- ☐ Catalog has been checked. No information is available on the source/device.
- ☐ We are not aware of any specific license which authorizes possession and use of this device.
- ☐ Manufacturer is located in Agreement State. We have verified that no device review is completed or pending and that a custom review is required.
- ☐ Manufacturer is located in non-Agreement State.
- ☐ Source/device will be imported.
- ☐ If information provided by applicant is inadequate, assistance is required in the form of a letter/standard paragraphs and guides to request additional information from applicant.
- ☒ This case is being recorded in the computer as being assigned to I-5. When it is returned, it will be reassigned to an IMAS reviewer.
- ☒ Other Device amendment

John W. N. Hickey
Requestor