

Douglas R. Gipson
Senior Vice President, Nuclear Generation

Fermi 2
6400 North Dixie Hwy., Newport, Michigan 48166
Tel: 313.586.5201 Fax: 313.586.4172

Detroit Edison



10CFR50.73

April 24, 1997
NRC-97-0048

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington D. C. 20555

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 97-007

Pursuant to 10CFR50.73, Detroit Edison is submitting the enclosed LER No. 97-007 which documents the failure of the Reactor Building Ventilation System (RBHVAC) resulting in a loss of Secondary Containment Integrity during shutdown conditions. This is being reported as a condition prohibited by the Technical Specifications.

The following commitments are being made in this LER:

1. The effectiveness of the quarterly walkdown of non-safety related solenoid valves is being evaluated to determine whether it is sufficient for this application, considering the failure mechanism discovered during post failure examination of the solenoid valve.
2. An evaluation of the exhaust fan no-flow trip function is being made to determine why it did not actuate when damper T41F014 closed.

9704290065 970424
PDR ADOCK 05000341
S PDR




A DTE Energy Company

IE22/1

If you have any questions, please contact Norm Peterson at (313) 457-4258.

Sincerely,

A handwritten signature in dark ink, appearing to read "Norm Peterson", is written above the distribution list.

cc: A. B. Beach
G. A. Harris
M. J. Jordan
A. J. Kugler
M. V. Yudas, Jr.
Region III
Wayne County Emergency Management Division