


BOEING
SERVICES INTERNATIONAL, INC.

Mailing Address:

P.O. Box 10838
PLEASANT HILLS, PA 15236

MINING EQUIPMENT TEST FACILITY
BRUCETON RESEARCH CENTER
Cochrans Mill Road
Bruceton, PA

August 27, 1985
W6200-85-066

Mr. Edwin Weurtz
United States Nuclear Regulatory Commission
Region 1
Nuclear Materials Safety Section B
631 Park Avenue
King of Prussia, PA 19406

MS 16
P9

Subject. NRC Control No. 103839

Dear Mr. Weurtz:

Reference your recent telephone conversation with BSI's METF Radiation Protection Officer, Larry Miller, concerning BSI's application for amendment to byproduct material license No. 37-21292-01. You requested clarification as to whom will service the nuclear gauges and perform the required leak tests.


Regarding servicing the gauges, BSI will not service the gauges. If the Kay-Ray gauges need service, Kay-Ray Inc., of 516 West Campus Drive, Arlington Heights, IL 60004 (312-259-5600), will be contacted for the service. If the SAI gauges need service, Science Applications, Inc., of 4030 Sorrento Valley Blvd., San Diego, CA 92121 (714-452-1720), will be contacted for service.

Regarding leak testing the gauges, the BSI METF Radiation Protection Officer performs the leak tests. Specimens are collected using Applied Health Physics, Inc. Mark V Leak Test Kits. These are returned to Applied Health Physics at 2986 Industrial Blvd., P.O. Box 197, Bethel Park, PA 15102 (412-563-2242) for analysis. Test results are acted on accordingly.

Please contact Larry Miller should you have any other questions or comments.

Sincerely,

BOEING SERVICES INTERNATIONAL, INC.



M.E. Henderson
METF Project Manager

LFM:jah

cc: W.E. Evans (BOM)
A.J. Miscoe (BOM)
P.M. Yavorsky (BOM)

8510300297 850925
REG 1 LIC 30
37-21292-01 PDR

40 2 15 06 00V 500
1 10000-001/000000
03839
"OFFICIAL RECORD COPY"

ML10

AUG 30 1985

DATE 8/15/85
TIME 8:10 ☒ A.M. ☐ P.M.

TELEPHONE OR VERBAL CONVERSATION RECORD

☐ INCOMING CALL

☒ OUTGOING CALL

☐ VISIT

PERSON CALLING

E. Wurtz

OFFICE/ADDRESS

RI

PHONE NUMBER

EXTENSION

PERSON CALLED

Larry Miller, RPO

OFFICE/ADDRESS

Boeing Services International

PHONE NUMBER

EXTENSION

(412) 675-6188

CONVERSATION

SUBJECT

Telephone Deficiency

SUMMARY

- ① Mr. Miller stated that BSI is responsible for the use of the gauges and the radiation safety program and that the Bureau of Mines owns the gauges but is not involved in their use.
- ② Mr. Miller stated that BSI personnel will not service or repair the gauges but this will be done by an outside organization licensed to perform such functions.
- ③ Mr. Miller stated that he performs the leak tests of the sources using a kit from Applied Health Physics.

"OFFICIAL RECORD COPY"

REFERRED TO:

ACTION REQUESTED

Mr. Miller is sending a letter confirming the above information.

ACTION TAKEN

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

INITIALS

DATE