

TEXAS UTILITIES GENERATING COMPANY

P. O. BOX 1002 · GLEN ROSE, TEXAS 76043

Log # TXX-4297  
File # 910.2

September 11, 1984

Mr. B. J. Youngblood, Chief  
Division of Licensing  
Licensing Branch No. 1  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION  
TURBINE DISC CRACKING

Dear Mr. Youngblood:

Enclosed are three (3) copies each of Utility Power Corporation Engineering Reports ER-8401 "Ultrasonic Disk Inspection" and ER-8402 "Probability of Disk Cracking Due to Stress Corrosion" for your advance review prior to the meeting of September 19, 1984.

Should you have any questions in this matter, please contact me directly.

Sincerely,

*Bob Beck*  
For John Beck

JB:pew  
Enclosures  
cc: John Stefano

8512260016 841005  
PDR ADOCK 05000445  
A PDR