

**CONAM INSPECTION**

6106 Rookin Street
Houston, Texas 77074-3792
(713) 774-9657

'85 JUL 12 P3:14

July 9, 1985

3011849

United States Nuclear Regulatory Commission
Division of Fuel Cycle and Material Safety
Radioisotope Licensing Branch
Washington, D.C. 20555

Reference: License # 42-16559-01 Amendment 14

Gentlemen:

Conam Inspection wishes to amend the above referenced license to reflect the following changes.

Add to Item 7C.

... or Tech/Ops Model 866 sealed sources.

Add to Item 9C.

... or Tech/Ops Model 650 source changer for storage and replacement of sources.

Please note that our Operating and Emergency Manual presently includes the operating instructions for the Tech/Ops 650 source changer. Enclosed is our check \$230.00 as required by 10 CFR Part 170, paragraph 170.12c and 170.31.3, 'O'.

If you require further information please contact us.

Sincerely,

[Signature]
Otis C. Gamble
Radiation Safety Officer

cc: J. McClellen
File

July - 2 - IV

Applicant	3/1/80
Check No.	230 (30)
Amount	230.00
Type of Fee	Amendment
Date Check Rec'd	7/17/85
Received By	Jacques

8511070451 850709
NMSS LIC30
42-16559-09 PDR

U.S. N.R.C.
LIC. FEE MGMT. BRANCH

'85 JUL 17 P12...

RECEIVED

ML40

10096



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555



BETWEEN: William O. Miller, Chief
License Fee Management Branch
Office of Administration

Regional License Section
Material Licensing Branch
FCMS, Office of Nuclear Material
Safety & Safeguards

LICENSE FEE TRANSMITTAL

A. REGION TV

1. APPLICATION ATTACHED

Applicant/Licensee: Nuclear Energy Serv. Inc.

Application Dated: 7/9/85

Control No.: 419096

License No.: 42-16559-01

2. FEE ATTACHED

Amount: _____

Check No.: _____

3. COMMENTS

03320

Signed _____

Date _____

B. LICENSE FEE MANAGEMENT BRANCH

1. Fee Category and Amount: 30 - \$230 1/87

2. Correct Fee Paid. Application may be processed for:

Amendment ☒ _____

Renewal _____

License _____

Signed Jackson
Date 7/22/85