

9/21/84

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

12:45

☐ A.M.  
☒ P.M.

☒ INCOMING CALL

☐ OUTGOING CALL

☐ VISIT

PERSON CALLING

Frank Castello

OFFICE/ADDRESS

Region I

PHONE NUMBER

EXTENSION

PERSON CALLED

John Glenn

OFFICE/ADDRESS

Region I

PHONE NUMBER

EXTENSION

CONVERSATION

SUBJECT

Inspection at Radiation Technology, Dover, NJ

SUMMARY

Frank described a problem with the product conveyor system. The interlocks used to prevent inadvertent entry when the irradiator is being run in the continuous mode have been bypassed since April 1984. He indicated that the interlock system was okay when the irradiator was used in the batch mode. Since operation of the irradiator with bypassed interlocks is contrary to NRC regulations, we discussed negotiating an agreement to cease the unauthorized activities. We decided he should proceed with this attempt at the closeout to be followed by a CPH. He will call back after the closeout.

REFERRED TO:

Kinneman and Joyner

ACTION REQUESTED

For discussion and planning.

29-13613-02

29-13613-03

236-97022

236-97046

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

ACTION TAKEN

"OFFICIAL RECORD COPY"

8512260312 840921

REG1 LIC30

29-13613-02

PDR

IE:07

RETURN ORIGINAL TO

REGION I

1/0

INITIALS

DATE