

APPENDIX A

NOTICE OF VIOLATION

New England Pathology Services, Inc.
Woburn, Massachusetts 01801

Docket No. 030-19421
License No. 20-20566-01

As a result of the inspection conducted on June 12, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR 30.34(c) requires that each licensee confine his possession and use of byproduct materials to the locations and purposes authorized by the license.

Item 6 of License No. 20-10566-01 authorized only iodine-125.

Contrary to the above, as of June 12, 1985, millicurie amounts of hydrogen-3 had been used.

This is a Severity Level IV violation. (Supplement VI)

8512270006 851220
REG1 LIC30
20-20566-01 PDR

OFFICIAL RECORD COPY

DL NE PATHOLOGY - 0003.0.0
12/16/85