
Title List of Documents Made Publicly Available

October 1-31, 1985

Office of Administration
U.S. Nuclear Regulatory Commission



8512270359 851231
PDR NUREG
0540 R PDR

Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1985

Date Published: November 1985

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xv
Docket Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	9
Domestic Licensing of Special Nuclear Material — Docket 70	258
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	264
Licensing of Independent Spent Fuel Storage — Docket 72	267
Nondocketed Items	269
10 CFR — Commission Meeting Records	269
ACRS — Advisory Committee on Reactor Safeguards	269
ADVCM — NRC Advisory Committee	270
COMMISSION — NRC Commissioners	270
CONTRACT — NRC Contracts and Modifications	274
FOIA — Freedom of Information Act Requests and Releases	277
GEN TECH IS — Generic Technical Issues	294
I&E — Inspection and Enforcement	296
MISC — Public Document Room Miscellaneous	297
NUREG — NUREG Reports and Related Correspondence	298
ORG — Correspondence with Other Organizations	320
PR — Proposed Rule	320
PRM — Petition for Rulemaking	324
PROJ — Projects - Predocket Licensing	324
PT21 — Noncompliance Reports and Related Correspondence	325
QA999 — Quality Assurance Inspections	325
REGGD — Regulatory Guides	327
RES — Research and Technical Assistance Reports	328
REVIEW GROUP — NRC Research Review Groups	328
SECY — Position Papers Before the Commission	330
STATE PROG — State Programs	330
TOPREP — Vendor Reports and Related Correspondence	333
WASTE MGT — Nuclear Waste Management	336
WASTE RES — Waste Management Research Reports	343
XPORTLIC — Export and Import Licenses	345
Personal Author Index	347
Corporate Source Index	375
Report Number Index	401
Cross Reference of Enclosures to Principal Documents	403
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

- ① P. Operating license stage documents & correspondence

②

③

8411270362 Submits renewed, amended & updated petition under 2.206, urging NRC to require that util provide Commission full disclosure of intended sources & environ consequences prior to issuing full power OL.

④

SUGARMAN, R.J.

⑤

Sugarman, Denworth & Hellegers

⑥

84/11/21

⑦

Denton, H. Office of Nuclear Reactor Regulation, Director

⑧

2pp.

27628:356:27628:357

⑨

⑩

⑪

⑫

⑬

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. This five-digit number is the NRC 48X microfiche designation.
10. The three-digit portion of this entry is the number of the frame on which this document starts.
11. The five-digit portion of this entry is the number of the frame on which this document ends.
12. The three-digit portion of this entry is the number of the frame on which this document ends.
13. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

- 10CFR—Commission Meeting Records
- ACRS—Advisory Committee on Reactor Safeguards
- COMMISSION—NRC Commissioners
- CONTRACT—NRC Contracts and Modifications
- DISCLOSURE—Financial Disclosure Information
- FOIA—Freedom of Information Act Requests and Releases
- GEN TECH IS—Generic Technical Issues

I&E—Inspection and Enforcement
 MISC—Public Document Room Miscellaneous
 NUREG—NUREG Reports and Related Correspondence
 ORG—Correspondence with Other Organizations
 PR—Proposed Rule
 PRM—Petition for Rulemaking
 PROJ—Projects—Predocket Licensing
 PT21—Noncompliance Reports and Related Correspondence
 QA999—Quality Assurance Inspections
 REGGD—Regulatory Guides
 RES—Research and Technical Assistance Reports
 REVIEW GRP—NRC Research Review Groups
 RM—Rulemakings
 SECY—Position Papers Before the Commission
 STATE PROG—State Programs
 TOPREP—Vendor Reports and Related Correspondence
 WASH—Regulatory Publications—Pre-NUREG Series
 WASTE MGT—Nuclear Waste Management
 WASTE RES—Waste Management Research Reports
 XPORTLIC—Exports and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocket category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the documents.

14. This five-digit number is the NRC 49X microfiche designation.
15. This three-digit portion of this entry is the number of the frame on which this document starts.
16. This five-digit number is the microfiche on which this document ends.
17. This three-digit number is the frame on which this document ends.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 487-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings which vary from \$0.05 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703) 941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites - Docket 27			40-8674	PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	8
27-039	SHEFFIELD, IL, U.S. ECOLOGY, INC.	1	40-8681	UMETCO MINERALS CORP., GRAND JUNCTION, CO	8
27-048	RICHLAND, WA, U.S. ECOLOGY, INC.	1	40-8698	PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	8
Domestic Licensing of Source Material - Docket 40			40-8714	CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	8
40-0299	UNION CARBIDE CORP., GRAND JUNCTION, CO	1	40-8724	CHEMETRON CORP., CHICAGO, IL	8
40-0672	NUCLEAR METALS, INC., CONCORD, MA	1	40-8745	OGLE PETROLEUM, INC., CASPER, WY	9
40-1162	WESTERN NUCLEAR, INC., JEFFREY CITY, WY	2	40-8768	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	9
40-1193	BABCOCK & WILCOX CO., APOLLO, PA	2	40-8778	MOLYCORP, INC., LOS ANGELES, CA	9
40-1366	KERR-MCGEE OIL INDUSTRIES, INC., OKLAHOMA CITY, OK	2	40-8781	TETON EXPLORATION DRILLING CO., INC., CASPER, WY	9
40-2038	KERR-MCGEE OIL INDUSTRIES, INC., SHIPROCK, NM	3	40-8783	URANERZ USA, INC., CASPER, WY	9
40-2061	KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL	3	40-8786	URANIUM RESOURCES, INC., RICHARDSON, TX	9
40-2259	PATHFINDER MINES CORP., RIVERTON, WY	3	40-8800	MCGEAN DISPOSAL DUMP, NEWBURGH HEIGHTS, OH	9
40-3392	ALLIED CHEMICAL CORP., MORRISTOWN, NJ	3	40-8820	AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CO	9
40-3453	ATLAS MINERALS, INC., DENVER, CO	3	Domestic Licensing of Production and Utilization Facilities - Docket 50		
40-4492	AMERICAN NUCLEAR CORP., CASPAR, WY	3	50-2	FORD NUCLEAR REACTOR	9
40-6500	ENERGY, DEPT. OF, CANONSBURG, PA	4	50-3	INDIAN POINT STATION, UNIT 1	9
40-6622	PATHFINDER MINES CORP., SHIRLEY BASIN, WY	4	50-5	PENNSYLVANIA STATE UNIV. RESEARCH REACTOR	10
40-6659	GETTY OIL/PETROTOMICS CO., SHIRLEY BASIN, WY	4	50-10	DRESDEN NUCLEAR POWER STATION, UNIT 1	10
40-7455	WHITTAKER METALS, LOS ANGELES, CA	4	50-20	MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	10
40-7604	VISTRON CORP., LIMA, OH	4	50-27	WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)	10
40-8006	KERR-MCGEE CORP., OKLAHOMA CITY, OK	4	50-29	YANKEE-ROWE NUCLEAR POWER STATION	11
40-8027	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	5	50-30	PLUM BROOK RESEARCH REACTOR FACILITY	12
40-8064	EXXON MINERALS CO., USA, HOUSTON, TX	7	50-54	CINTICHEM RESEARCH REACTOR	12
40-8084	RIO ALGOM CORP., MOAB, UT	7	50-57	BUFFALO MATERIALS RESEARCH CENTER	12
40-8102	EXXON CO., USA, HOUSTON, TX	7	50-59	TEXAS A&M UNIV. RESEARCH REACTOR	12
40-8355	AMAX SPECIALTY METALS CORP., PARKERSBURG, WV	7	50-62	UNIV. OF VIRGINIA RESEARCH REACTOR	12
40-8452	BEAR CREEK URANIUM CO., CASPER, WY	7	50-70	GENERAL ELECTRIC TEST REACTOR	13
40-8502	WYOMING MINERAL CORP., LAKEWOOD, CO	7	50-73	GENERAL ELECTRIC NUCLEAR TEST REACTOR	13
40-8584	MINERALS EXPLORATION CO., LOS ANGELES, CA	7	50-77	CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	13
40-8631	ARMY, DEPT. OF, ROCK ISLAND, IL	8			

Docket	Name	Page	Docket	Name	Page
50-83	UNIV. OF FLORIDA TRAINING REACTOR	13	50-238	NUCLEAR SHIP SAVANNAH	26
50-87	WESTINGHOUSE CRITICAL EXPERIMENT	13	50-243	OREGON STATE UNIV. RESEARCH REACTOR	26
50-97	CORNELL UNIV. ZERO POWER REACTOR	13	50-244	ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1	26
50-116	IOWA STATE UNIV. RESEARCH REACTOR	14	50-245	MILLSTONE NUCLEAR POWER STATION, UNIT 1	27
50-123	UNIV. OF MISSOURI RESEARCH REACTOR	14	50-247	INDIAN POINT STATION, UNIT 2	30
50-124	VIRGINIA POLYTECHNIC INSTITUTE TRAINING REACTOR	14	50-249	DRESDEN NUCLEAR POWER STATION, UNIT 3	31
50-128	TEXAS A&M UNIV. RESEARCH REACTOR	14	50-250	TURKEY POINT PLANT, UNIT 3	33
50-133	HUMBOLDT BAY POWER PLANT, UNIT 3	14	50-251	TURKEY POINT PLANT, UNIT 4	34
50-134	WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR	15	50-252	UNIV. OF NEW MEXICO RESEARCH REACTOR	36
50-139	UNIV. OF WASHINGTON RESEARCH REACTOR	15	50-254	QUAD-CITIES STATION, UNIT 1	36
50-142	UCLA TRAINING REACTOR	15	50-255	PALISADES NUCLEAR PLANT	37
50-148	UNIV. OF KANSAS RESEARCH REACTOR	15	50-259	BROWNS FERRY NUCLEAR POWER STATION, UNIT 1	39
50-150	OHIO STATE UNIV. RESEARCH REACTOR	15	50-260	BROWNS FERRY NUCLEAR POWER STATION, UNIT 2	41
50-155	BIG ROCK POINT NUCLEAR PLANT	16	50-261	H.B. ROBINSON PLANT, UNIT 2	43
50-156	UNIV. OF WISCONSIN RESEARCH REACTOR	17	50-262	BRIGHAM YOUNG UNIV. RESEARCH REACTOR	44
50-157	CORNELL UNIV. RESEARCH REACTOR	17	50-263	MONTICELLO NUCLEAR GENERATING PLANT	45
50-160	GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	17	50-264	DOW CHEMICAL CO.	46
50-163	GA TECHNOLOGIES	17	50-265	QUAD-CITIES STATION, UNIT 2	46
50-182	PURDUE UNIV. RESEARCH REACTOR	17	50-266	POINT BEACH NUCLEAR PLANT, UNIT 1	47
50-184	NATIONAL BUREAU OF STANDARDS REACTOR	17	50-267	FORT ST. VRAIN NUCLEAR GENERATING STATION	49
50-185	PLUM BROOK REACTOR - MOCK-UP	18	50-269	OCONEE NUCLEAR STATION, UNIT 1	50
50-186	UNIV. OF MISSOURI RESEARCH REACTOR	18	50-270	OCONEE NUCLEAR STATION, UNIT 2	52
50-188	KANSAS STATE UNIV. RESEARCH REACTOR	18	50-271	VERMONT YANKEE NUCLEAR POWER STATION	53
50-193	RHODE ISLAND & PROVIDENCE PLANTATIONS AEC	18	50-272	SALEM NUCLEAR GENERATING STATION, UNIT 1	54
50-199	MANHATTAN COLLEGE RESEARCH REACTOR	18	50-275	DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1	56
50-206	SAN ONOFRE NUCLEAR STATION, UNIT 1	18	50-277	PEACH BOTTOM ATOMIC POWER STATION, UNIT 2	58
50-213	HADDAM NECK PLANT	20	50-278	PEACH BOTTOM ATOMIC POWER STATION, UNIT 3	60
50-219	OYSTER CREEK NUCLEAR POWER PLANT	22	50-280	SURRY POWER STATION, UNIT 1	61
50-220	NINE MILE POINT NUCLEAR STATION, UNIT 1	23	50-281	SURRY POWER STATION, UNIT 2	63
50-223	UNIV. OF LOWELL RESEARCH REACTOR	24	50-282	PRAIRIE ISLAND NUCLEAR STATION, UNIT 1	64
50-225	RPI CRITICAL EXPERIMENT	24	50-285	FORT CALHOUN STATION, UNIT 1	66
50-237	DRESDEN NUCLEAR POWER STATION, UNIT 2	24	50-286	INDIAN POINT STATION, UNIT 3	67
			50-287	OCONEE NUCLEAR STATION, UNIT 3	68
			50-288	REED COLLEGE RESEARCH REACTOR	69
			50-289	THREE MILE ISLAND NUCLEAR STATION, UNIT 1	69

Docket	Name	Page	Docket	Name	Page
50-293	PILGRIM NUCLEAR POWER STATION, UNIT 1	72	50-335	ST. LUCIE PLANT, UNIT 1	123
50-295	ZION NUCLEAR POWER STATION, UNIT 1	74	50-336	MILLSTONE NUCLEAR POWER STATION, UNIT 2	124
50-296	BROWNS FERRY NUCLEAR POWER STATION, UNIT 3	75	50-338	NORTH ANNA POWER STATION, UNIT 1	125
50-297	NORTH CAROLINA STATE UNIV. PULSTAR REACTOR	77	50-339	NORTH ANNA POWER STATION, UNIT 2	127
50-298	COOPER NUCLEAR STATION	77	50-341	ENRICO FERMI ATOMIC POWER PLANT, UNIT 2	128
50-301	POINT BEACH NUCLEAR PLANT, UNIT 2	78	50-344	TROJAN NUCLEAR PLANT	130
50-302	CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	79	50-346	DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1	132
50-304	ZION NUCLEAR POWER STATION, UNIT 2	81	50-348	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1	136
50-305	KEWAUNEE NUCLEAR POWER PLANT	83	50-352	LIMERICK GENERATING STATION, UNIT 1	138
50-306	PRAIRIE ISLAND NUCLEAR STATION, UNIT 2	84	50-353	LIMERICK GENERATING STATION, UNIT 2	140
50-309	MAINE YANKEE ATOMIC POWER PLANT	85	50-354	HOPE CREEK NUCLEAR STATION, UNIT 1	141
50-311	SALEM NUCLEAR GENERATING STATION, UNIT 2	86	50-358	WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1	143
50-312	RANCHO SECO NUCLEAR GENERATING STATION	88	50-361	SAN ONOFRE NUCLEAR STATION, UNIT 2	143
50-313	ARKANSAS NUCLEAR ONE, UNIT 1	90	50-362	SAN ONOFRE NUCLEAR STATION, UNIT 3	145
50-315	DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1	91	50-364	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2	147
50-316	DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2	93	50-366	EDWIN I. HATCH NUCLEAR PLANT, UNIT 2	148
50-317	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	96	50-368	ARKANSAS NUCLEAR ONE, UNIT 2	149
50-318	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2	97	50-369	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1	151
50-320	THREE MILE ISLAND NUCLEAR STATION, UNIT 2	99	50-370	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2	152
50-321	EDWIN I. HATCH NUCLEAR PLANT, UNIT 1	101	50-373	LASALLE COUNTY STATION, UNIT 1	153
50-322	SHOREHAM NUCLEAR POWER STATION	103	50-374	LASALLE COUNTY STATION, UNIT 2	156
50-323	DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2	106	50-382	WATERFORD GENERATING STATION, UNIT 3	157
50-324	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2	107	50-385	TAKAHAMA, UNIT 1	174
50-325	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	108	50-387	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1	174
50-326	UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	110	50-388	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2	175
50-327	SEQUOYAH NUCLEAR PLANT, UNIT 1	110	50-389	ST. LUCIE PLANT, UNIT 2	177
50-328	SEQUOYAH NUCLEAR PLANT, UNIT 2	112	50-390	WATTS BAR NUCLEAR PLANT, UNIT 1	178
50-329	MIDLAND PLANT, UNIT 1	113	50-391	WATTS BAR NUCLEAR PLANT, UNIT 2	179
50-330	MIDLAND PLANT, UNIT 2	116	50-395	VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1	181
50-331	DUANE ARNOLD ENERGY CENTER	119	50-396	UNIV. OF VIRGINIA CAVALIER REACTOR	182
50-333	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	120	50-397	WPPSS NUCLEAR PROJECT, UNIT 2	182
50-334	BEAVER VALLEY POWER STATION, UNIT 1	122	50-400	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1	184
			50-401	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2	186

Docket	Name	Page	Docket	Name	Page
50-409	LA CROSSE BOILING WATER REACTOR	186	STN-50-499	SOUTH TEXAS PROJECT, UNIT 2	246
50-410	NINE MILE POINT NUCLEAR STATION, UNIT 2	188	STN-50-508	WPPSS NUCLEAR PROJECT, UNIT 3	249
50-412	BEAVER VALLEY POWER STATION, UNIT 2	190	50-513	WPPSS NUCLEAR PROJECT, UNIT 4	250
50-413	CATAWBA NUCLEAR STATION, UNIT 1	191	STN-50-518	HARTSVILLE NUCLEAR PLANT, UNIT 1	250
50-414	CATAWBA NUCLEAR STATION, UNIT 2	192	STN-50-520	HARTSVILLE NUCLEAR PLANT, UNIT 3	250
50-416	GRAND GULF NUCLEAR STATION, UNIT 1	194	50-522	SKAGIT NUCLEAR POWER PROJECT, UNIT 1	250
50-417	GRAND GULF NUCLEAR STATION, UNIT 2	198	50-523	SKAGIT NUCLEAR POWER PROJECT, UNIT 2	250
50-423	MILLSTONE NUCLEAR POWER STATION, UNIT 3	199	STN-50-528	PALO VERDE NUCLEAR STATION, UNIT 1	250
50-424	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1	203	STN-50-529	PALO VERDE NUCLEAR STATION, UNIT 2	253
50-425	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2	205	STN-50-530	PALO VERDE NUCLEAR STATION, UNIT 3	255
50-433	UNIV. OF CALIFORNIA AT SANTA BARBARA RESEARCH REACTOR	207	STN-50-546	MARBLE HILL NUCLEAR STATION, UNIT 1	257
STN-50-437	FLOATING NUCLEAR PLANT	207	STN-50-547	MARBLE HILL NUCLEAR STATION, UNIT 2	257
50-438	BELLEfonte NUCLEAR PLANT, UNIT 1	207	STN-50-566	YELLOW CREEK NUCLEAR PLANT, UNIT 1	258
50-439	BELLEfonte NUCLEAR PLANT, UNIT 2	208	STN-50-567	YELLOW CREEK NUCLEAR PLANT, UNIT 2	258
50-440	PERRY NUCLEAR POWER PLANT, UNIT 1	209	50-601	RESAR SP/90	258
50-441	PERRY NUCLEAR POWER PLANT, UNIT 2	212	50-602	UNIV. OF TEXAS RESEARCH REACTOR	258
50-443	SEABROOK NUCLEAR STATION, UNIT 1	214	Domestic Licensing of Special Nuclear Material - Docket 70		
50-444	SEABROOK NUCLEAR STATION, UNIT 2	216	70-0025	ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA	258
50-445	COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1	217	70-0027	BABCOCK & WILCOX CO., LYNCHBURG, VA	258
50-446	COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	222	70-0036	COMBUSTION ENGINEERING, INC., WINDSOR, CT	258
STN-50-447	GESSAR-238	226	70-0123	PENNSYLVANIA, UNIV. OF, PHILADELPHIA, PA	259
STN-50-454	BYRON STATION, UNIT 1	226	70-0134	WISCONSIN, UNIV. OF, MADISON, WI	259
STN-50-455	BYRON STATION, UNIT 2	228	70-0135	BABCOCK & WILCOX CO., APOLLO, PA	259
STN-50-456	BRAIDWOOD STATION, UNIT 1	230	70-0143	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	259
STN-50-457	BRAIDWOOD STATION, UNIT 2	232	70-0267	NEW YORK, STATE UNIV. OF, BUFFALO, NY	260
50-458	RIVER BEND STATION, UNIT 1	235	70-0364	BABCOCK & WILCOX CO., APOLLO, PA	260
50-459	RIVER BEND STATION, UNIT 2	237	70-0371	UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT	261
50-460	WPPSS NUCLEAR PROJECT, UNIT 1	237	70-0687	CINTICHEM, INC.	261
50-461	CLINTON POWER STATION, UNIT 1	237	70-0698	WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA	261
STN-50-482	WOLF CREEK GENERATING STATION	240	70-0734	GA TECHNOLOGIES, INC., SAN DIEGO, CA	261
STN-50-483	CALLAWAY PLANT, UNIT 1	241			
STN-50-498	SOUTH TEXAS PROJECT, UNIT 1	242			

Docket	Name	Page	Docket	Name	Page
70-0754	GENERAL ELECTRIC CO., PLEASANTON, CA	261	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71		
70-0820	UNITED NUCLEAR CORP., WOOD RIVER JUNCTION, RI	262	71-0005	MAGNAFLUX CORP.	264
70-0824	BABCOCK & WILCOX CO., LYNCHBURG, VA	262	71-0088	BABCOCK & WILCOX CO.	264
70-1068	FLORIDA, UNIV. OF, GAINESVILLE, FL	262	71-0121	NEUTRON PRODUCTS, INC.	264
70-1100	COMBUSTION ENGINEERING, INC., WINDSOR, CT	262	71-0133	NAVY, DEPT. OF	264
70-1113	GENERAL ELECTRIC CO., WILMINGTON, NC	262	71-0135	BABCOCK & WILCOX CO.	264
70-1151	WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA	262	71-0139	TULSA GAMMA RAY, INC.	264
70-1201	BABCOCK & WILCOX CO., LYNCHBURG, VA	262	71-0173	PACIFIC NORTHWEST LABORATORIES	264
70-1257	EXXON NUCLEAR CO., INC., RICHLAND, WA	262	71-0230	BABCOCK & WILCOX CO.	265
70-1308	GENERAL ELECTRIC CO., SAN JOSE, CA	263	71-0240	POWER AUTHORITY OF STATE OF NEW YORK	265
70-1489	GOODYEAR AEROSPACE CORP., AKRON, OH	263	71-0251	WESTINGHOUSE ELECTRIC CORP.	265
70-1549	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	263	71-0363	BALTIMORE GAS & ELECTRIC CO.	265
70-1764	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	263	71-0384	NEW ENGLAND NUCLEAR CORP.	265
70-2322	EDLOW INTERNATIONAL CO., WASHINGTON, DC	263	71-0546	VECTOR CORP.	265
70-2910	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	263	71-0551	SIEMENS MEDICAL SYS, INC.	265
70-2930	FIVE FOUR THREE CO., INC., MORGANTOWN, WV	263	71-0552	OLD DOMINION FABRICATORS	265
70-2947	ILLINOIS POWER CO., DECATUR, IL	263	71-5088	MODEL: D34710-1, D34710-2, ROCKWELL INTERNATIONAL CORP.	265
70-2948	NIAGRA MOHAWK POWER CORP., SYRACUSE, NY	263	71-5507	MODEL: HFIF PENT FUEL ELEMENT SHIPPING CASK, ENERGY,	265
70-2953	CONNECTICUT, UNIV. OF, STORRS, CT	263	71-5607	MODEL: T-2, ENERGY, DEPT. OF	265
70-2984	ARIZONA PUBLIC SERVICE CO., PHOENIX, AZ	263	71-5862	MODEL: SENTINEL-100F, TELEDYNE ENERGY SYSTEMS	265
70-2997	CAROLINA POWER & LIGHT CO., RALEIGH, NC	263	71-5874	MODEL: WAPD-40, ENERGY, DEPT. OF	265
70-3000	COMMONWEALTH EDISON CO., CHICAGO, IL	263	71-5939	MODEL: GE-1500, GENERAL ELECTRIC CO.	266
70-3008	DUQUESNE LIGHT CO., PITTSBURGH, PA	264	71-5942	MODEL: GE-700, GENERAL ELECTRIC CO.	266
70-3013	COMMONWEALTH EDISON CO., CHICAGO, IL	264	71-5984	MODEL: 5984, J.L. SHEPHERD & ASSOCIATES	266
70-3016	HOUSTON LIGHTING & POWER CO., HOUSTON, TX	264	71-6058	MODEL: B-3, U.S. ECOLOGY, INC.	266
70-3018	HOUSTON LIGHTING & POWER CO., SOUTH TEXAS PROJECT, TX	264	71-6206	MODEL: B, BABCOCK & WILCOX CO.	266
70-3020	NUCLEAR ASSURANCE CORP., NORCROSS, GA	264	71-6574	MODEL: HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.	266
70-3027	PUBLIC SERVICE CO. OF NEW HAMPSHIRE, SEABROOK, NH	264	71-6722	MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY	266
			71-9010	MODEL: NLI 1/2, NUCLEAR ASSURANCE CORP.	266
			71-9032	MODEL: 650, TECH/OPS, INC.	266
			71-9071	MODEL: AP-101, ANEFCO, INC.	266
			71-9073	MODEL: OH-142 SERIES & NUS 10-135, NUCLEAR PACKAGING,	266
			71-9079	MODEL: NUPAC 14D-2.0 & HN-100 SERIES 2 & 2A,	266
			71-9080	MODEL: HN-600, NUPAC 100 & CNS 7-100,	266
			71-9089	MODEL: HN-100S, HITTMAN NUCLEAR & DEVELOPMENT CORP.	266

Docket	Name	Page	Docket	Name	Page
71-9133	MODEL: C-10, GAMMA INDUSTRIES	266	71-9200	MODEL: 125-B, ENERGY, DEPT. OF	267
71-9156	MODEL: IR-50, INDUSTRIAL NUCLEAR CO.	266	71-9201	MODEL: ELEKTA TIGER TYPE B(U), NUCLEAR PACKAGING, INC.	267
71-9159	MODEL: NUPAC 14/190L, /190M & /190H, NUCLEAR PKG., INC.	266	71-9202	MODEL: TN-BRP, TRANSNUCLEAR, INC.	267
71-9168	MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC.	266	71-9203	MODEL: DHFT, BABCOCK & WILCOX CO.	267
71-9176	MODEL: NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING, INC.	267	71-9204	MODEL: CNS 10-160B, CHEM-NUCLEAR SYSTEMS, INC.	267
71-9177	MODEL: NUPAC 10/140, NUCLEAR PACKAGING, INC.	267	Licensing of Independent Spent Fuel Storage - Docket 72		
71-9178	MODEL: NUPAC 7/100, NUCLEAR PACKAGING, INC.	267	72-0001	MORRIS OPERATIONS, GENERAL ELECTRIC CO.	267
71-9179	MODEL: NUPAC 6/100L & 6/100H, NUCLEAR PACKAGING, INC.	267	72-0002	VIRGINIA ELECTRIC & POWER CO.	267
71-9192	MODEL: AP-300, ANEFCO, INC.	267	72-0003	CAROLINA POWER & LIGHT CO.	267

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 27			PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	40-8674	8
RICHLAND, WA, U.S. ECOLOGY, INC.	27-048	1	RIO ALGOM CORP., MOAB, UT	40-8084	7
SHEFFIELD, IL, U.S. ECOLOGY, INC.	27-039	1	TETON EXPLORATION DRILLING CO., INC., CASPER, WY	40-8781	9
Domestic Licensing of Source Material - Docket 40			UMETCC MINERALS CORP., GRAND JUNCTION, CO	40-8681	8
ALLIED CHEMICAL CORP., MORRISTOWN, NJ	40-3392	3	UNION CARBIDE CORP., GRAND JUNCTION, CO	40-0299	1
AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CO	40-8820	9	URANERZ USA, INC., CASPER, WY	40-8783	9
AMAX SPECIALTY METALS CORP., PARKERSBURG, WV	40-8355	7	URANIUM RESOURCES, INC., RICHARDSON, TX	40-8786	9
AMERICAN NUCLEAR CORP., CASPAR, WY	40-4492	3	VISTRON CORP., LIMA, OH	40-7604	4
ARMY, DEPT. OF, ROCK ISLAND, IL	40-8631	8	WESTERN NUCLEAR, INC., JEFFREY CITY, WY	40-1162	2
ATLAS MINERALS, INC., DENVER, CO	40-3453	3	WHITTAKER METALS, LOS ANGELES, CA	40-7455	4
BABCOCK & WILCOX CO., APOLLO, PA	40-1193	2	WYOMING MINERAL CORP., LAKEWOOD, CO	40-8502	7
BEAR CREEK URANIUM CO., CASPER, WY	40-8452	7	Domestic Licensing of Production and Utilization Facilities - Docket 50		
CHEMETRON CORP., CHICAGO, IL	40-8724	8	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1	50-424	203
CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	40-8714	8	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2	50-425	205
ENERGY, DEPT. OF, CANONSBURG, PA	40-6500	4	ARKANSAS NUCLEAR ONE, UNIT 1	50-313	90
EXXON CO., USA, HOUSTON, TX	40-8102	7	ARKANSAS NUCLEAR ONE, UNIT 2	50-368	149
EXXON MINERALS CO., USA, HOUSTON, TX	40-8064	7	BEAVER VALLEY POWER STATION, UNIT 1	50-334	122
GETTY OIL/PETROTOMICS CO., SHIRLEY BASIN, WY	40-6659	4	BEAVER VALLEY POWER STATION, UNIT 2	50-412	190
KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL	40-2061	3	BELLEFONTE NUCLEAR PLANT, UNIT 1	50-438	207
KERR-MCGEE CORP., OKLAHOMA CITY, OK	40-8006	4	BELLEFONTE NUCLEAR PLANT, UNIT 2	50-439	208
KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	40-8027	5	BIG ROCK POINT NUCLEAR PLANT	50-155	16
KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	40-8768	9	BRAIDWOOD STATION, UNIT 1	STN-50-456	230
KERR-MCGEE OIL INDUSTRIES, INC., OKLAHOMA CITY, OK	40-1366	2	BRAIDWOOD STATION, UNIT 2	STN-50-457	232
KERR-MCGEE OIL INDUSTRIES, INC., SHIPROCK, NM	40-2038	3	BRIGHAM YOUNG UNIV. RESEARCH REACTOR	50-262	44
MCGEAN DISPOSAL DUMP, NEWBURGH HEIGHTS, OH	40-8800	9	BROWNS FERRY NUCLEAR POWER STATION, UNIT 1	50-259	39
MINERALS EXPLORATION CO., LOS ANGELES, CA	40-8584	7	BROWNS FERRY NUCLEAR POWER STATION, UNIT 2	50-260	41
MOLYCORP, INC., LOS ANGELES, CA	40-8778	9	BROWNS FERRY NUCLEAR POWER STATION, UNIT 3	50-296	75
NUCLEAR METALS, INC., CONCORD, MA	40-0672	1	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	50-325	108
OGLE PETROLEUM, INC., CASPER, WY	40-8745	9	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2	50-324	107
PATHFINDER MINES CORP., RIVERTON, WY	40-2259	3	BUFFALO MATERIALS RESEARCH CENTER	50-57	12
PATHFINDER MINES CORP., SHIRLEY BASIN, WY	40-6622	4	BYRON STATION, UNIT 1	STN-50-454	226
PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	40-8698	8	BYRON STATION, UNIT 2	STN-50-455	228
			CALLAWAY PLANT, UNIT 1	STN-50-483	241

Name	Docket	Page	Name	Docket	Page
CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	50-317	96	GRAND GULF NUCLEAR STATION, UNIT 1	50-416	194
CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2	50-318	97	GRAND GULF NUCLEAR STATION, UNIT 2	50-417	198
CATAWBA NUCLEAR STATION, UNIT 1	50-413	191	H.B. ROBINSON PLANT, UNIT 2	50-261	43
CATAWBA NUCLEAR STATION, UNIT 2	50-414	192	HADDAM NECK PLANT	50-213	20
CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	50-77	13	HARTSVILLE NUCLEAR PLANT, UNIT 1	STN-50-518	250
CINTICHEM RESEARCH REACTOR	50-54	12	HARTSVILLE NUCLEAR PLANT, UNIT 2	STN-50-520	250
CLINTON POWER STATION, UNIT 1	50-461	237	HOPE CREEK NUCLEAR STATION, UNIT 1	50-354	141
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1	50-445	217	HUMBOLDT BAY POWER PLANT, UNIT 3	50-133	14
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	50-446	222	INDIAN POINT STATION, UNIT 1	50-3	9
COOPER NUCLEAR STATION	50-298	77	INDIAN POINT STATION, UNIT 2	50-247	30
CORNELL UNIV. RESEARCH REACTOR	50-157	17	INDIAN POINT STATION, UNIT 3	50-286	67
CORNELL UNIV. ZERO POWER REACTOR	50-97	13	IOWA STATE UNIV. RESEARCH REACTOR	50-116	14
CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	50-302	79	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	50-333	120
DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1	50-346	132	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1	50-348	136
DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1	50-275	56	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2	50-364	147
DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2	50-323	106	KANSAS STATE UNIV. RESEARCH REACTOR	50-188	18
DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1	50-315	91	KEWAUNEE NUCLEAR POWER PLANT	50-305	83
DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2	50-316	93	LA CROSSE BOILING WATER REACTOR	50-409	186
DOW CHEMICAL CO.	50-264	46	LASALLE COUNTY STATION, UNIT 1	50-373	153
DRESDEN NUCLEAR POWER STATION, UNIT 1	50-10	10	LASALLE COUNTY STATION, UNIT 2	50-374	156
DRESDEN NUCLEAR POWER STATION, UNIT 2	50-237	24	LIMERICK GENERATING STATION, UNIT 1	50-352	138
DRESDEN NUCLEAR POWER STATION, UNIT 3	50-249	31	LIMERICK GENERATING STATION, UNIT 2	50-353	140
DUANE ARNOLD ENERGY CENTER	50-331	119	MAINE YANKEE ATOMIC POWER PLANT	50-309	85
EDWIN I. HATCH NUCLEAR PLANT, UNIT 1	50-321	101	MANHATTAN COLLEGE RESEARCH REACTOR	50-199	18
EDWIN I. HATCH NUCLEAR PLANT, UNIT 2	50-366	148	MARBLE HILL NUCLEAR STATION, UNIT 1	STN-50-546	257
ENRICO FERMI ATOMIC POWER PLANT, UNIT 2	50-341	128	MARBLE HILL NUCLEAR STATION, UNIT 2	STN-50-547	257
FLOATING NUCLEAR PLANT	STN-50-437	207	MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	50-20	10
FORD NUCLEAR REACTOR	50-2	9	MIDLAND PLANT, UNIT 1	50-329	113
FORT CALHOUN STATION, UNIT 1	50-285	66	MIDLAND PLANT, UNIT 2	50-330	116
FORT ST. VRAIN NUCLEAR GENERATING STATION	50-267	49	MILLSTONE NUCLEAR POWER STATION, UNIT 1	50-245	27
GA TECHNOLOGIES	50-163	17	MILLSTONE NUCLEAR POWER STATION, UNIT 2	50-336	124
GENERAL ELECTRIC NUCLEAR TEST REACTOR	50-73	13	MILLSTONE NUCLEAR POWER STATION, UNIT 3	50-423	199
GENERAL ELECTRIC TEST REACTOR	50-70	13	MONTICELLO NUCLEAR GENERATING PLANT	50-263	45
GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	50-160	17	NATIONAL BUREAU OF STANDARDS REACTOR	50-184	17
GESSAR-238	STN-50-447	226	NINE MILE POINT NUCLEAR STATION, UNIT 1	50-220	23
			NINE MILE POINT NUCLEAR STATION, UNIT 2	50-410	188
			NORTH ANNA POWER STATION, UNIT 1	50-338	125

Name	Docket	Page	Name	Docket	Page
NORTH ANNA POWER STATION, UNIT 2	50-339	127	SALEM NUCLEAR GENERATING STATION, UNIT 2	50-311	86
NORTH CAROLINA STATE UNIV. PULSTAR REACTOR	50-297	77	SAN ONOFRE NUCLEAR STATION, UNIT 1	50-206	18
NUCLEAR SHIP SAVANNAH	50-238	26	SAN ONOFRE NUCLEAR STATION, UNIT 2	50-361	143
OCONEE NUCLEAR STATION, UNIT 1	50-269	50	SAN ONOFRE NUCLEAR STATION, UNIT 3	50-362	145
OCONEE NUCLEAR STATION, UNIT 2	50-270	52	SEABROOK NUCLEAR STATION, UNIT 1	50-443	214
OCONEE NUCLEAR STATION, UNIT 3	50-287	68	SEABROOK NUCLEAR STATION, UNIT 2	50-444	216
OHIO STATE UNIV. RESEARCH REACTOR	50-150	15	SEQUOYAH NUCLEAR PLANT, UNIT 1	50-327	110
OREGON STATE UNIV. RESEARCH REACTOR	50-243	26	SEQUOYAH NUCLEAR PLANT, UNIT 2	50-328	112
OYSTER CREEK NUCLEAR POWER PLANT	50-219	22	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1	50-400	184
PALISADES NUCLEAR PLANT	50-255	37	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2	50-401	186
PALO VERDE NUCLEAR STATION, UNIT 1	STN-50-528	250	SHOREHAM NUCLEAR POWER STATION	50-322	103
PALO VERDE NUCLEAR STATION, UNIT 2	STN-50-529	253	SKAGIT NUCLEAR POWER PROJECT, UNIT 1	50-522	250
PALO VERDE NUCLEAR STATION, UNIT 3	STN-50-530	255	SKAGIT NUCLEAR POWER PROJECT, UNIT 2	50-523	250
PEACH BOTTOM ATOMIC POWER STATION, UNIT 2	50-277	58	SOUTH TEXAS PROJECT, UNIT 1	STN-50-498	242
PEACH BOTTOM ATOMIC POWER STATION, UNIT 3	50-278	60	SOUTH TEXAS PROJECT, UNIT 2	STN-50-499	246
PENNSYLVANIA STATE UNIV. RESEARCH REACTOR	50-5	10	ST. LUCIE PLANT, UNIT 1	50-335	123
PERRY NUCLEAR POWER PLANT, UNIT 1	50-440	209	ST. LUCIE PLANT, UNIT 2	50-389	177
PERRY NUCLEAR POWER PLANT, UNIT 2	50-441	212	SURRY POWER STATION, UNIT 1	50-280	61
PILGRIM NUCLEAR POWER STATION, UNIT 1	50-293	72	SURRY POWER STATION, UNIT 2	50-281	63
PLUM BROOK REACTOR - MOCK-UP	50-185	18	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1	50-387	174
PLUM BROOK RESEARCH REACTOR FACILITY	50-30	12	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2	50-388	175
POINT BEACH NUCLEAR PLANT, UNIT 1	50-266	47	TAKAHAMA, UNIT 1	50-385	174
POINT BEACH NUCLEAR PLANT, UNIT 2	50-301	78	TEXAS A&M UNIV. RESEARCH REACTOR	50-59	12
PRAIRIE ISLAND NUCLEAR STATION, UNIT 1	50-282	64	TEXAS A&M UNIV. RESEARCH REACTOR	50-128	14
PRAIRIE ISLAND NUCLEAR STATION, UNIT 2	50-306	84	THREE MILE ISLAND NUCLEAR STATION, UNIT 1	50-289	69
PURDUE UNIV. RESEARCH REACTOR	50-182	17	THREE MILE ISLAND NUCLEAR STATION, UNIT 2	50-320	99
QUAD-CITIES STATION, UNIT 1	50-254	36	TROJAN NUCLEAR PLANT	50-344	130
QUAD-CITIES STATION, UNIT 2	50-265	46	TURKEY POINT PLANT, UNIT 3	50-250	33
RANCHO SECO NUCLEAR GENERATING STATION	50-312	88	TURKEY POINT PLANT, UNIT 4	50-251	34
REED COLLEGE RESEARCH REACTOR	50-288	69	UCLA TRAINING REACTOR	50-142	15
RESAR SP/90	50-601	258	UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	50-326	110
RHODE ISLAND & PROVIDENCE PLANTATIONS AEC	50-193	18	UNIV. OF CALIFORNIA AT SANTA BARBARA RESEARCH REACTOR	50-433	207
RIVER BEND STATION, UNIT 1	50-458	235	UNIV. OF FLORIDA TRAINING REACTOR	50-80	13
RIVER BEND STATION, UNIT 2	50-459	237	UNIV. OF KANSAS RESEARCH REACTOR	50-148	15
ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1	50-244	26	UNIV. OF LOWELL RESEARCH REACTOR	50-223	24
RPI CRITICAL EXPERIMENT	50-225	24	UNIV. OF MISSOURI RESEARCH REACTOR	50-186	18
SALEM NUCLEAR GENERATING STATION, UNIT 1	50-272	54	UNIV. OF MISSOURI RESEARCH REACTOR	50-123	14

Name	Docket	Page	Name	Docket	Page
UNIV. OF NEW MEXICO RESEARCH REACTOR	50-252	36	CAROLINA POWER & LIGHT CO., RALEIGH, NC	70-2997	263
UNIV. OF TEXAS RESEARCH REACTOR	50-602	258	CINTICHEM, INC.	70-0687	261
UNIV. OF VIRGINIA CAVALIER REACTOR	50-396	182	COMBUSTION ENGINEERING, INC., WINDSOR, CT	70-0036	258
UNIV. OF VIRGINIA RESEARCH REACTOR	50-62	12	COMBUSTION ENGINEERING, INC., WINDSOR, CT	70-1100	262
UNIV. OF WASHINGTON RESEARCH REACTOR	50-139	15	COMMONWEALTH EDISON CO., CHICAGO, IL	70-3013	264
UNIV. OF WISCONSIN RESEARCH REACTOR	50-156	17	COMMONWEALTH EDISON CO., CHICAGO, IL	70-3000	263
VERMONT YANKEE NUCLEAR POWER STATION	50-271	53	CONNECTICUT, UNIV. OF, STORRS, CT	70-2953	263
VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1	50-395	181	DUQUESNE LIGHT CO., PITTSBURGH, PA	70-3008	264
VIRGINIA POLYTECHNIC INSTITUTE TRAINING REACTOR	50-124	14	EDLOW INTERNATIONAL CO., WASHINGTON, DC	70-2322	263
WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)	50-27	10	EXXON NUCLEAR CO., INC., RICHLAND, WA	70-1257	262
WATERFORD GENERATING STATION, UNIT 3	50-382	157	FIVE FOUR THREE CO., INC., MORGANTOWN, WV	70-2930	263
WATTS BAR NUCLEAR PLANT, UNIT 1	50-390	178	FLORIDA, UNIV. OF, GAINESVILLE, FL	70-1068	262
WATTS BAR NUCLEAR PLANT, UNIT 2	50-391	179	GA TECHNOLOGIES, INC., SAN DIEGO, CA	70-0734	261
WESTINGHOUSE CRITICAL EXPERIMENT	50-87	13	GENERAL ELECTRIC CO., PLEASANTON, CA	70-0754	261
WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1	50-369	151	GENERAL ELECTRIC CO., SAN JOSE, CA	70-1308	263
WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2	50-370	152	GENERAL ELECTRIC CO., WILMINGTON, NC	70-1113	262
WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1	50-358	143	GOODYEAR AEROSPACE CORP., AKRON, OH	70-1489	263
WOLF CREEK GENERATING STATION	STN-50-482	240	HOUSTON LIGHTING & POWER CO., HOUSTON, TX	70-3016	264
WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR	50-134	15	HOUSTON LIGHTING & POWER CO., SOUTH TEXAS PROJECT, TX	70-3018	264
WPPSS NUCLEAR PROJECT, UNIT 1	50-460	237	ILLINOIS POWER CO., DECATUR, IL	70-2947	263
WPPSS NUCLEAR PROJECT, UNIT 2	50-397	182	NEW YORK, STATE UNIV. OF, BUFFALO, NY	70-0267	260
WPPSS NUCLEAR PROJECT, UNIT 3	STN-50-508	249	NIAGRA MOHAWK POWER CORP., SYRACUSE, NY	70-2948	263
WPPSS NUCLEAR PROJECT, UNIT 4	50-513	250	NUCLEAR ASSURANCE CORP., NORCROSS, GA	70-3020	264
YANKEE-ROWE NUCLEAR POWER STATION	50-29	11	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	70-1549	263
YELLOW CREEK NUCLEAR PLANT, UNIT 1	STN-50-566	258	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	70-1764	263
YELLOW CREEK NUCLEAR PLANT, UNIT 2	STN-50-567	258	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	70-0143	259
ZION NUCLEAR POWER STATION, UNIT 1	50-295	74	PENNSYLVANIA, UNIV. OF, PHILADELPHIA, PA	70-0123	259
ZION NUCLEAR POWER STATION, UNIT 2	50-304	81	PUBLIC SERVICE CO. OF NEW HAMPSHIRE, SEABROOK, NH	70-3027	264
Domestic Licensing of Special Nuclear Material - Docket 70			ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA	70-0025	258
ARIZONA PUBLIC SERVICE CO., PHOENIX, AZ	70-2984	263	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	70-2910	263
BABCOCK & WILCOX CO., APOLLO, PA	70-0135	259	UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT	70-0371	261
BABCOCK & WILCOX CO., APOLLO, PA	70-0364	260	UNITED NUCLEAR CORP., WOOD RIVER JUNCTION, RI	70-0820	262
BABCOCK & WILCOX CO., LYNCHBURG, VA	70-1201	262	WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA	70-1151	262
BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0027	258			
BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0824	262			

Name	Docket	Page	Name	Docket	Page
WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA	70-0698	261	MODEL: HN-600, NUPAC 100 & CNS 7-100,	71-9080	266
WISCONSIN, UNIV. OF, MADISON, WI	70-0134	259	MODEL: IR-50, INDUSTRIAL NUCLEAR CO.	71-9156	266
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71			MODEL: NLI 1/2, NUCLEAR ASSURANCE CORP.	71-9010	266
BABCOCK & WILCOX CO.	71-0088	264	MODEL: NUPAC 10/140, NUCLEAR PACKAGING, INC.	71-9177	267
BABCOCK & WILCOX CO.	71-0135	264	MODEL: NUPAC 14/190L, /190M & /190H, NUCLEAR PKG., INC.	71-9159	266
BABCOCK & WILCOX CO.	71-0230	265	MODEL: NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING, INC.	71-9176	267
BALTIMORE GAS & ELECTRIC CO.	71-0383	265	MODEL: NUPAC 14D-2.0 & HN-100 SERIES 2 & 2A,	71-9079	266
MAGNAFLUX CORP.	71-0005	264	MODEL: NUPAC 6/100L & 6/100H, NUCLEAR PACKAGING, INC.	71-9179	267
MODEL: 125-B, ENERGY, DEPT. OF	71-9200	267	MODEL: NUPAC 7/100, NUCLEAR PACKAGING, INC.	71-9178	267
MODEL: 5984, J.L. SHEPHERD & ASSOCIATES	71-5984	266	MODEL: OH-142 SERIES & NUS 10-135, NUCLEAR PACKAGING,	71-9073	266
MODEL: 650, TECH/OPS, INC.	71-9032	266	MODEL: SENTINEL-100F, TELEDYNE ENERGY SYSTEMS	71-5862	265
MODEL: AP-101, ANEFCO, INC.	71-9071	266	MODEL: T-2, ENERGY, DEPT. OF	71-5607	265
MODEL: AP-300, ANEFCO, INC.	71-9192	267	MODEL: TN-B-3P, TRANSNUCLEAR, INC.	71-9202	267
MODEL: B, BABCOCK & WILCOX CO.	71-6206	266	MODEL: WAPD-40, ENERGY, DEPT. OF	71-5874	265
MODEL: B-3, U.S. ECOLOGY, INC.	71-6058	266	NAVY, DEPT. OF	71-0133	264
MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY	71-6722	266	NEUTRON PRODUCTS, INC.	71-0121	264
MODEL: C-10, GAMMA INDUSTRIES	71-9133	266	NEW ENGLAND NUCLEAR CORP.	71-0384	265
MODEL: CNS 10-160B, CHEM-NUCLEAR SYSTEMS, INC.	71-9204	267	OLD DOMINION FABRICATORS	71-0552	265
MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC.	71-9168	266	PACIFIC NORTHWEST LABORATORIES	71-0173	264
MODEL: D34710-1, D34710-2, ROCKWELL INTERNATIONAL CORP.	71-5088	265	POWER AUTHORITY OF STATE OF NEW YORK	71-0240	265
MODEL: DHFT, BABCOCK & WILCOX CO.	71-9203	267	SIEMENS MEDICAL SYS, INC.	71-0551	265
MODEL: ELEKTA TIGER TYPE B(U), NUCLEAR PACKAGING, INC.	71-9201	267	TULSA GAMMA RAY, INC.	71-0139	264
MODEL: GE-1500, GENERAL ELECTRIC CO.	71-5939	266	VECTOR CORP.	71-0546	265
MODEL: GE-700, GENERAL ELECTRIC CO.	71-5942	266	WESTINGHOUSE ELECTRIC CORP.	71-0251	265
MODEL: HFIR SPENT FUEL ELEMENT SHIPPING CASK, ENERGY,	71-5507	265	Licensing of Independent Spent Fuel Storage - Docket 72		
MODEL: HN-100S, HITTMAN NUCLEAR & DEVELOPMENT CORP.	71-9089	266	CAROLINA POWER & LIGHT CO.	72-0003	267
MODEL: HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.	71-6574	266	MORRIS OPERATIONS, GENERAL ELECTRIC CO.	72-0001	267
			VIRGINIA ELECTRIC & POWER CO.	72-0002	267

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U.S. ECOLOGY, INC.

8510280481 Summary of 850730 meeting w/USGS re IDNS request that USGS decommission Sheffield facilities.
SHAFFNER, J. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/01.
STARMER, J. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33228-001-33228-001.

8510240579 Telcon w/M Hamel on 850815 inviting State of IL Dept of Nuclear Safety to join NRC & ORNL 850918-19 site visit to take split samples. Objectives of 8600 HAP methodology & Resources Conservation & Recovery Act procedures discussed.
GOODE, D. NRC - No Detailed Affiliation Given. 85/08/15. 1p. 33183-326-33183-326.

8510090063 Responds to FOIA request for info on J. Neel & D. Gravelly association w/ listed companies re Maxey Flats nuclear disposal area. Forwards App B documents. App A & B documents available in PDF.
FELTON, J.M. Division of Rules and Records. 85/09/26. PIERCE, J.F. Environmental Task Force. 3pp. 32963-314-32963-320.

-8510090067 Authorizes use of Trench 18 for burial of radwaste subj to listed conditions. per 760903 meeting & Jul 1976 rept. LE Stratton 761029 ltr to JN Neel encl.
SINGER, B. Radiotopes Licensing Branch (Pre 790501). 78/09/21. NEEL, J. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 4pp. 32963-317-32963-320.

8510240102 "Trench 18 Monitoring Rept for Jul-Sept 1985." W/851004 ltr.
BOWEN, M.A. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 85/09/30. SHAFFNER, J.J. NRC - No Detailed Affiliation Given. 2pp. 33178-200-33178-202.

8510290559 Trip rept of 850918-19 visit to Sheffield, IL re low level waste disposal at facility.
SHAFFNER, J.A. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33245-342-33245-344.

8510280097 Trip rept of 850918-19 site visit to Sheffield low level waste facility to observe features & groundwater monitoring activities conducted by ORNL.
LEE, R. Geotechnical Branch (Post 831001). 85/10/02. KNAPP, M. Geotechnical Branch (Post 831001). 2pp. 33228-360-33228-361.

8510280512 Requests monthly & quarterly results of environ monitoring for trench sumps, tr series wells & chemical waste disposal facility licensed by IEPA & any results of analyses samples from wells adjacent to unlicensed chemical facility.
SHAFFNER, J.A. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/04. MARTINEZ, E. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 1p. 33199-355-33199-355.

DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC.

8510280431 Comments on proposed groundwater monitoring program for Hanford low level waste disposal field. per SV Wright 850709 ltr. Phased approach to finalizing monitoring plan should be used.
SHAFFNER, J. Low-Level Waste & Uranium Recovery Projects Branch. 85/07/23. STORRI, J. Washington, State of Dept. of Social & Health Services. 2pp. 33196-322-33196-323.

8510280084 Recommends that licensee request for one-time exemption for disposal of solidified low specific activity waste oil be granted if solidification procedure produces free standing monolith that remains intact for 30 days. Details encl.
GRIEVES, J.T. Engineering Branch (Post 831001). 85/07/25. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 6pp. 33241-057-33241-062.

8510280365 Responds to 850708 request for variance from Condition 10(g) of License 16-19204-01. Documentation of mineral process control program assuring production of free-standing monolith required.
HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/07/29. MARTINEZ, E. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 1p. 33196-350-33196-350.

8510280494 Trip rept of 850624-26 visit to Hanford facility to discuss issues re license renewal.
STARMER, R.J., SHAFFNER, J., HUNT, J. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 7pp. 33227-352-33227-358.

8510280429 Responds to J. Shaffner 850703 request for confirmation that NRC views on mixed waste issue restricted to scintillation vials & limited number of miscellaneous wastes.
HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/07. HARRINGTON, A.L. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 2pp. 33196-331-33196-334.

8510280433 Ack receipt of Shaffner 850731 ltr transmitting appl. for renewal of License 16-19204-01. Fee to be assessed upon completion of review ltr addressing specific deficiencies in facility operations manual forthcoming.
HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/09. WRIGHT, S.V. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 1p. 33196-313-33196-320.

-8510280435 Forwards trip rept documenting 850624-26 trip to Hanford low level waste disposal field.
STARMER, R.J., SHAFFNER, J., HUNT, J. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 7pp. 33196-314-33196-320.

8510280090 Notices of 850820 meeting to discuss Hanford license renewal & technical assistance to State of WA re state license.
SHAFFNER, J. Division of Waste Management. 85/08/13. HUNT, J. Division of Waste Management. JUNGLING, T., JAGANNATH, B. Engineering Branch (Post 831001). 2pp. 33241-055-33241-056.

8510300174 Forwards evaluation of US Ecology license exemption request for small quantity of solidified waste oil. Exemption should be granted contingent on listed actions.
GRIEVES, J.T. Engineering Branch (Post 831001). 85/08/21. BELL, M.J. Division of Waste Management. 6pp. 33261-347-33261-352.

8510080308 Monthly TLD results for Aug 1985. W/850930 ltr.
MARTINEZ, E.D. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 85/08/31. SHAFFNER, J.J. NRC - No Detailed Affiliation Given. 2pp. 32923-140-32923-141.

8510290219 Comments on Amend 4 to SNM license & proposed changes in licensing conditions. Condition 23 & supplemental license conditions should read as listed.
LEE, R. Geotechnical Branch (Post 831001). 85/09/05. SHAFFNER, J. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254-224-33254-224.

8510250183 Third Quarter 1985 thyroid results W/850930 ltr.
MARTINEZ, E.D. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 85/09/30. SHAFFNER, J.J. NRC - No Detailed Affiliation Given. 2pp. 33226-087-33226-088.

8510250314 Notices that B&W contacted on 850729 concerns re process control to ensure solidification produces no free standing liquid & that oil poses no hazard.
MARTINEZ, E.D. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 85/10/02. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 4pp. 33226-141-33226-144.

8510250204 Forwards SNM receipt & burial rept for Sept 1985 & rept of isotopic activity W/o encl.
RITTENBERG, R.B. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 85/10/10. BROWNING, R.E. Low-Level Waste Licensing Branch. 1p. 33226-035-33226-035.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP., GRAND JUNCTION, CO

8510170397 Forwards "10CFR40.65 Reporting Requirements for UMETCO Minerals Corp. Gas Hills, WY Mill First Half 1985." No liquid, solid or airborne releases reported.
LYONS, P.J. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 85/08/28. PETTINGILL, H. Uranium Recovery Field Office. 2pp. 33063-174-33063-182.

-8510170406 "10CFR40.65 Reporting Requirements for UMETCO Minerals Corp. Gas Hills, WY Mill First Half 1985." W/one oversize drawing.
* UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 85/06/30. 200pp. 33063-176-33064-064.

8510170212 Clarifies confusion during 850913 telcon re calibr of pneumatic pressure indicator for piezometers due to recent changes in personnel. Pneumatic pressure indicator will be calibr in 1986 before Phase 2 begins.
TRAMMELL, J.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 85/09/13. GARCIA, P. Uranium Recovery Field Office. 1p. 33043-057-33043-057.

8510180460 Forwards Amend 37 to License SUA-648 for Umetco Minerals Corp. incorporating 850812 updated organization chart. Issuance of amend discussed via 851001 telcon between J. Conner & C. Jierree.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. LYONS, P.J. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 2pp. 33077-127-33077-151.

-8510180464 Amend 37 to License SUA-648 for Umetco Minerals Corp. authorizing possession of byproduct mill in form of U waste tailings.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. 21pp. 33077-129-33077-149.

-8510180469 Submits approval of Amend 37 to License SUA-648 for Umetco Minerals Corp. incorporating 850812 revised organization chart.
JIERREE, C.C., PETTINGILL, H.J. Uranium Recovery Field Office. 85/10/02. Uranium Recovery Field Office. 2pp. 33077-150-33077-151.

85-3210300 Discusses environ monitoring data for First Half 1985 at East Gas Hills Mill. per Condition 53 of License SUA-648. Cause of rising parameters in surface waters must be identified.
JIERREE, C.C., PETTINGILL, H.J. Uranium Recovery Field Office. 85/10/07. Uranium Recovery Field Office. 5pp. 33079-034-33079-038.

8510210305 Submits review of UMETCO Minerals Corp 850718 annual technical evaluation of performance of embankments comprising evaporation ponds at East Gas Hills Mill. Embankments functioning as designed.
JIERREE, C.C., PETTINGILL, H.J. Uranium Recovery Field Office. 85/10/07. Uranium Recovery Field Office. 2pp. 33079-039-33079-040.

8510170426 Advises that risk of surveyors sinking into tailings pond will be limited by use of photographs to document locations of ponds. per Condition 53 of License SUA-648.
TRAMMELL, J.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 85/10/08. GARCIA, P. Uranium Recovery Field Office. 1p. 33047-218-33047-218.

DOCKET 40-0672 NUCLEAR METALS, INC., CONCORD, MA

8510160305 Responds to FOIA request for approved operational nuclear license for Nuclear Metals, Inc. Documents listed in encl App A available in PDF.
FELTON, J.M. Division of Rules and Records. 85/09/12. CROOK, M.F. Environmentics. 2pp. 33050-029-33050-294.

2 DOCKETED ITEMS

- 8510160308 Amend 6 to License SMB-179 for Nuclear Metals, Inc., amending license in entirety. WANG, J.C. Materials Licensing Branch. 84/05/23. 2pp. 33050-031-33050-032.
- 8510160310 Forwards corrected Page 11 to 820930 correspondence. Original page should be discarded. VUMBACO, F.J. Nuclear Metals, Inc. 82/11/24. WANG, J.C. Materials Licensing Branch. 3pp. 33050-033-33050-035.
- 8510160313 Application for amend to License SMB-179, incorporating mfg or transfer of industrial production or device containing depleted U. Fee paid. LISCHINSKY, J. Nuclear Metals, Inc. 83/07/26. HICKEY, J. Materials Licensing Branch. 5pp. 33050-036-33050-040.
- 8510160316 Responds to 831109 request for addl info re renewal of License SMB-179. Supplemental instructions for handling & disposition of depleted U sinker bars encl. All transfers will be accompanied by NRC Form 244. VUMBACO, F.J. Nuclear Metals, Inc. 84/03/19. WANG, J.C. Materials Licensing Branch. 7pp. 33050-041-33050-164.
- 8510160317 Application for amend to License SMB-179, incorporating addition to scrap packaging procedure in accordance w/NRC low level waste vol reduction policy & authorizing R&D for reduction of waste generated. LISCHINSKY, J. Nuclear Metals, Inc. 83/12/29. HICKEY, J. Materials Licensing Branch. 3pp. 33050-165-33050-284.

DOCKET 40-1162 WESTERN NUCLEAR, INC., JEFFREY CITY, WY

- 8510180284 Responds to 850719 ltr re reduction of monitoring at Split Rock Mill. All concerns satisfactorily addressed w/exception of Well 14. Recommends that water quality degradation of Well 14 be investigated in more detail. GARLAND, W.L., SHAFFER, R. Wyoming, State of. 85/08/15. COLLINS, R. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 2pp. 33075-073-33075-074.
- 8510210082 Reviews 850830 water monitoring data for Split Rock Mill, Second Quarter 1985. Plume moving in northwest & southwest valleys contaminated by seepage from acid plant cooling pond. Effects will be reviewed in next submittal. KOWINSKI, G.R. Uranium Recovery Field Office. PETTINGILL, H.J. Region 4, Office of the Director. 85/10/01. Uranium Recovery Field Office. 5pp. 33094-273-33094-277.
- 8510180191 Forwards Amend 30 to License SUA-56 for Western Nuclear Inc., modifying groundwater & surface water monitoring program requirements per 850814 request. SMITH, R.D. Uranium Recovery Field Office. 85/10/02. COLLINS, R. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 2pp. 33069-232-33069-253.
- 8510180195 Amend 30 to License SUA-56 for Western Nuclear Inc., authorizing possession of byproduct mill in form of U waste tailings generated by mill operations. SMITH, R.D. Uranium Recovery Field Office. 85/10/02. 15pp. 33069-234-33069-248.
- 8510180200 Submits approval of Amend 30 to License SUA-56 for Western Nuclear Inc., modifying groundwater & surface water monitoring requirements, per licensee 850814 request. JERREE, C.C., PETTINGILL, H.J. Uranium Recovery Field Office. 85/10/02. Uranium Recovery Field Office. 5pp. 33069-249-33069-253.
- 8510220116 Reviews 850823 environ monitoring rept for First Half 1985 for Split Rock Mill. Air particulate monitoring data not available until Second Half 1985 rept. Mill & yellowcake dryer not operating. No licensing action warranted. JERREE, C.C., PETTINGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 4pp. 33098-175-33098-180.

DOCKET 40-1193 BABCOCK & WILCOX CO., APOLLO, PA

- 8510090132 FOIA request for all repts of radioactive effluents discharged to unrestricted areas resulting from work performed under Licenses SMB-502, SNM-414, SNM-145 & 37-04456-03. VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 85/07/29. CROW, W.T. Uranium Fuel Licensing Branch. 1p. 32963-145-32963-145.
- 8510090143 Responds to FOIA requests for all effluent release repts for Licenses SMB-502, SNM-145, SNM-414 & 37-04456-03. Also responds to Category 6 of related FOIA Request 85-552. Forwards requested documents. Addl effluent info available in POR. FELTON, J.M. Division of Rules and Records. 85/09/04. VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 1p. 32963-146-32963-196.
- 8510090155 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1977. W/770829 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-147-32963-152.
- 8510090169 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1977. W/770824 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-153-32963-155.
- 8510090178 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1978. W/780829 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 78/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-156-32963-158.
- 8510090186 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1978. W/790223 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 78/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-159-32963-173.

DOCKET 40-1366 KERR-MCGEE OIL INDUSTRIES, INC., OKLAHOMA CITY, OK

- 8510150142 Response to FOIA request for documents re Licenses SUA-809 & SUA-797. Forwards documents listed in App A & portions of documents in App B. Portions of App B documents withheld (ref FOIA Exemption 6). FELTON, J.M. Division of Rules and Records. 85/09/20. BARNES, C. Affiliation Not Assigned. 8pp. 33033-293-33034-28.
- 8508280083 Followup insp rept on 600712-14. Noncompliance noted: less than adequate analytical results recorded & airborne radioactivity areas not posted. HAWLEY, C.A. Atomic Energy Commission. 60/09/16. 10pp. 33034-190-33034-199.

- 8508280100 Followup insp rept on 611011-1215 & 21 items of noncompliance: records re liquid effluent concentrations of U reported in improper units & environ air surveys conducted improperly. HAWLEY, C.A. Atomic Energy Commission. 62/01/04. 9pp. 33034-177-33034-185.
- 8508280127 Documents B Logan & HR Keil 620416 telcon informing of forthcoming shutdown of U mill. Submittal of written notification of intentions suggested. WALKER, D.I. Atomic Energy Commission. 62/04/19. DUBINSKI, L. Atomic Energy Commission. 4pp. 33034-186-33034-189.
- 8510150153 Compliance insp rept on 580404. Noncompliance noted: survey to determine existence of hazards incident to U core processing not conducted & caution signs in areas containing U in excess of specified limits not posted. WALKER, D.I. Atomic Energy Commission. 58/07/15. 11pp. 33033-301-33033-311.
- 8510150163 Forwards compliance insp rept & recommends licensee furnish plans for conducting survey for determining airborne activity & radiation levels & for posting warnings. Posting regulations discussed w/licensee. WALKER, D.I. Atomic Energy Commission. 58/07/15. MANN, M.M. Atomic Energy Commission. 2pp. 33033-313-33033-314.
- 8510150176 Forwards followup insp rept. Items of noncompliance include exposure of individuals in restricted areas & failure to complete survey for airborne concentrations. Licensee failure to take action noted. WALKER, D.I. Atomic Energy Commission. 59/05/14. PRICE, H.L. Atomic Energy Commission. 3pp. 33033-317-33033-319.
- 8510150201 Followup insp rept on 590325. Noncompliance noted: individuals exposed in restricted areas, surveys for airborne concentrations not made, caution signs, labels & signals not posted & records of radiation surveys not maintained. WALKER, D.I. Atomic Energy Commission. 59/05/14. 9pp. 33033-320-33033-328.
- 8510150214 Suggests transmittal of ltr notifying licensee of noncompliance items discovered during insp & requesting corrective action be sent. Case summary will be included in Ofc of General Manager rept. Atomic Energy Commission. 58/08/31. Atomic Energy Commission. 1p. 33033-361-33033-361.
- 8510150251 Forwards State of ID. Licensee Compliance Div 600916 memo & rept re insp of License R-209. Citation for noncompliance re failure to conduct airborne effluent surveys suggested. Followup insp to be conducted. LOW, L.D. Atomic Energy Commission. 60/09/23. PRICE, H.L. Atomic Energy Commission. 1p. 33034-044-33034-044.
- 8510150272 Informs that, according to licensee 610112 ltr re deficiencies noted during Jul 1980 insp of License R-209, corrective actions completed. No confirmation will be sent. CUNNINGHAM, R.E. Atomic Energy Commission. 61/07/21. DUBINSKI, L. Atomic Energy Commission. 1p. 33034-048-33034-052.
- 8510150299 Forwards 620105 ltr & encl supplementing 611011 insp rept for License R-209. Film badge exposure & airborne natural U sampling of unrestricted areas discussed. WALKER, D.I. Atomic Energy Commission. 62/03/05. DUBINSKI, L. Atomic Energy Commission. 1p. 33034-053-33034-056.
- 8510150344 Forwards summary rept re processes & potential exposures associated w/U ore processing info docs not constitute evaluation of particular mill. Related info encl. DELANEY, J.C. Atomic Energy Commission. 59/01/15. THORNBURG, V. Gunnison Mining Co. 23pp. 33034-154-33034-176.
- 8510150364 Notifies that ltr confirming listed licensee responses to citations for non-compliance will not be forwarded due to time elapsed since responses were received. Related info encl. ROGERS, L.R. Atomic Energy Commission. 59/03/11. MANN, M.M. Atomic Energy Commission. 5pp. 33034-200-33034-204.
- 8510150367 Requests listed correspondence to complete files for mills initially inspected to permit followup insp. Porter Brothers Corp. license expired on 7/11/01. Followup insp requested. Addl initial & followup insps will be conducted. WALKER, D.I. Atomic Energy Commission. 59/01/14. LOW, L.D. Atomic Energy Commission. 2pp. 33034-205-33034-207.
- 8510150370 Forwards Kermac Nuclear Fuels Corp 641110 ltr requesting closeout insp of Gunnison facility. Walker has contracted Davidson for purpose of scheduling insp. HARMON, D.F. Atomic Energy Commission. 64/11/17. PAULUS, R.C. Atomic Energy Commission. 1p. 33034-206-33034-206.
- 8510150373 Requests insp of Gunnison facility required for clearance of sale of facility. List of items exceeding prescribed levels of radiation per survey results forwarded. Prior to survey, cleanup procedures included trash removal & burial. DAVIDSON, J.M. Kerr-McGee Corp. 64/11/10. NUSSBAUMER, D.A. Atomic Energy Commission. 5pp. 33034-209-33034-213.
- 8510150374 Forwards list of items found to be over accepted levels at Gunnison facility per 641113 telcon. DAVIDSON, J.M. Kerr-McGee Corp. 64/11/16. WALKER, D.I. Atomic Energy Commission. 1p. 33034-214-33034-214.
- 8510150378 Submits insp status rept for U & thorium ore processing mills. Status rept not submitted at end of last quarter due to SL-1 incident & subsequent problems. WALKER, D.I. Atomic Energy Commission. 61/11/03. DUBINSKI, L. Atomic Energy Commission. 2pp. 33034-215-33034-218.
- 8510150381 Submits quarterly insp status rept for U ore processing mills 2 months following previous rept, to coincide w/quarterly licensee insp rept submittal. No new developments transpired re Falls City, TX mill operation. WALKER, D.I. Atomic Energy Commission. 60/10/10. LOW, L.D. Atomic Energy Commission. 2pp. 33034-217-33034-218.
- 8510150386 Submits insp status rept for U ore processing mills. Corrections requested. Rept will be updated at first of each month following quarterly rept submittal. Addl mill believed to be under const in Falls City, TX. WALKER, D.I. Atomic Energy Commission. 60/08/02. LOW, L.D. Atomic Energy Commission. 5pp. 33034-219-33034-223.

—85101114 Discusses use of AEC-owned equipment at Rifle Mill discovered during Dept. of Labor insp. Union Carbide Nuclear contacted re equipment. Air samplers presumably left for sample collection. Converters permit use of two prong plugs. JONES, A.E. Atomic Energy Commission. 60/07/22. SHERMAN, J.T. Atomic Energy Commission. 3pp. 33034-225-33034-227.

—8510150404 Forwards survey results for U ore processing mills insp status files. Files determined to be up to date. Copies of correspondence between other AEC offices & licensees requested. WALKER, D.I. Atomic Energy Commission. 60/03/22. LOW, L.D. Atomic Energy Commission. 5pp. 33034-271-33034-275.

—8510150417 Forwards correspondence between Insp. Licensing & Regulation & licensees. Complete correspondence available for Licenses R-102 & R-185. Missing correspondence requested prior to followup insps. License R-205 extended to 581031. WALKER, D.I. Atomic Energy Commission. 58/09/30. LOW, L.D. Atomic Energy Commission. 3pp. 33034-279-33034-281.

DOCKET 40-2038 KERR-MCGEE OIL INDUSTRIES, INC., SHIPROCK, NM

8510010044 FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1975 & Oct 1976 - Mar 1977. BARNES, C. Affiliation Not Assigned. 85/07/22. Division of Rules and Records. 1p. 32830-075-32830-075.

8510010060 Responds to FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1975. Forwards App A & B documents. No records available for Docket 40-2038. FELTON, J.M. Division of Rules and Records. 85/08/29. BARNES, C. Affiliation Not Assigned. 8pp. 32830-076-32830-171.

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL

8510240355 Forwards Reed-Keppler Park & Sewage Treatment Plant "Thorium Removal Program," submitted by Kerr-McGee to City of West Chicago, IL. Rept prepared per consent decree entered by city & Kerr-McGee on 8/5/61. Related correspondence. MESERVE, R.A. Covington & Burling. MESERVE, R.A. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). #485 873. 85/10/21. FRYE, J.H. MORRIS, P.A. CARPENTER, J.H. Atomic Safety and Licensing Board Panel. 300pp. 33153-047-33153-320.

8510150107 Consolidated answer to motions to quash, or in alternative, modify subpoena to Catalytic & Grant. Motions should be denied. HARTIGAN, N.F. Illinois. State of. 85/06/18. Atomic Safety and Licensing Board Panel. 75pp. 33029-030-33029-179.

8510220194 Forwards sediment sampling location drawing & final "Sediment Sample Analyses" rept. Containing methodology for sample collection, analyses & results. Final data confirms preliminary measurements. STAUTER, J.C. Kerr-McGee Corp. 85/07/19. CONSTANTELOS, B. Region 5, Office of Director. 2pp. 33108-001-33108-014.

—8510220200 "Sediment Sample Analysis." * Radiation Management Corp. 85/07/12. 11pp. 33108-003-33108-014.

8510240577 Summarizes 850905 discussions re issues raised by EPA concerning residential property thorium removal program. Remaining residual thorium matrix insignificant. DENNY, J.L. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 85/09/18. CONSTANTELOS, B. Environmental Protection Agency. 7pp. 33183-327-33183-333.

8510240175 Advises that listed ANL personnel will visit Galata, IL mine on 851018. DENNY, J.L. Kerr-McGee Corp. 85/09/27. NIXON, W.A. Uranium Fuel Licensing Branch. 2pp. 33176-352-33176-353.

8510100066 Comments opposing ASLB 850911 suggestion of need to seek Commission waiver to allow for early hearing on draft suppl to FES re decommissioning of Rare Earths Facility at West Chicago, IL. HODGDON, A.P. Hearing Branch 2. #485 681. 85/10/04. Atomic Safety and Licensing Board Panel. 9pp. 32960-146-32960-164.

—8510100075 Affidavit of M Horn re encl rept entitled, "Status of West Chicago Site," based on encl Insp Rept 40-2061/85-01. Certificate of Svc encl. HORN, M. Uranium Fuel Licensing Branch. 85/10/03. 10pp. 32960-155-32960-164.

8510100170 Response supporting Board proposal to begin hearing after issuance of supplemental DES rather than awaiting supplemental FES. Certificate of Svc encl. Related correspondence. MESERVE, R.A. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). MESERVE, R.A. Covington & Burling. #485 683. 85/10/04. Atomic Safety and Licensing Board Panel. 10pp. 32962-202-32962-211.

8510110158 Motion for leave to file instant re State of IL position concerning waiver of 10CFR51 Filing deadline missed due to inability of counsel to prepare position on time. RAPKIN, A. Illinois. State of. #485 725. 85/10/07. Atomic Safety and Licensing Board Panel. 1p. 32972-184-32972-190.

—8510110158 Position re waiver of 10CFR51 to permit hearing after supplemental DES issued. ASLB should await completion of DuPage County trial & issuance of statement re or to decision whether to seek waiver. RAPKIN, A. Illinois. State of. 85/10/07. Atomic Safety and Licensing Board Panel. 6pp. 32972-185-32972-190.

8510240272 Forwards new info potentially relevant & mail to Board proceedings re proposed decommissioning of Kerr-McGee rare earths facility & proposed cleanup of Kress Creek near West Chicago, IL. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/09. FRYE, J.H. Atomic Safety and Licensing Board Panel. 48pp. 33181-323-33182-036.

8510230252 Requests DOE investigate possibility of making land available for disposal of waste from Kerr-McGee facility. Possible sites listed. FES encl. W/o encl. CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director. 85/10/10. VOIGT, W.R. Energy. Dept. of. 3pp. 33108-019-33108-021.

8510180120 Order allowing parties to reply by 851025 to responses re proposition that evidentiary hearing in proceeding take place following issuance of draft suppl to EIS. Served on 851015. FRYE, J.H. Atomic Safety and Licensing Board Panel. #485 803. 85/10/15. Office of the Executive Legal Director. 1p. 33059-355-33059-355.

8510210002 Motion to stay proceeding re Kerr-McGee waste disposal practices in violation of State of IL law until trial completed in related action in State Circuit Court for DuPage County. Related info & Svc List encl. RYAN, H.A. EGGERT, R.R. Illinois. State of. #485 631. 85/10/18. Atomic Safety and Licensing Board Panel. 23pp. 33071-359-33072-019.

8510290005 Order extending time until 851101 for all parties to reply to other parties responses to question on whether evidentiary hearing should take place following issuance of supplemental DES. Served on 851025. FRYE, J.H. Atomic Safety and Licensing Board Panel. #485 927. 85/10/25. Office of the Executive Legal Director. 1p. 33236-168-33236-168.

8510310284 Motion for sanctions & opposition to State of IL motion to stay proceedings re movement of radwaste from facility to unspecified site due to financial demands imposed by state court case. Exhibits A & B & Certificate of Svc encl. NICKLES, P.J. MESERVE, R.A. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). NICKLES, P.J. Covington & Burling. #485 948. 85/10/28. Atomic Safety and Licensing Board Panel. 37pp. 33271-256-33271-290.

8510310341 Forwards Kerr-McGee Chemical Corp motion for sanctions & opposition to state motion to stay proceedings for filing. Related correspondence. MESERVE, R.A. Covington & Burling. MESERVE, R.A. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). #485 982. 85/10/28. Docketing & Services Branch. 1p. 33271-351-33271-351.

DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY

8510180438 Advises that licensee followup & corrective actions re bioassay results in excess of 15 micrograms/liter conform to requirements of Reg Guide 8.22. No licensing action necessary. JIERREE, C.C., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 3pp. 33077-114-33077-116.

8510180451 Advises that licensee land use survey rept dtd 850903 satisfies License Condition 21 of License SUA-672 & no further action required. JIERREE, C.C., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 2pp. 33077-154-33077-155.

8510220102 Reviews 850903 environ monitoring data for Pathfinder Lucky MC for 851011-0603. Reporting of Well T1-9 included for first time. Ra-226 typical of values previously measured. No significant changes from previous rept. JIERREE, C.C., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/07. Uranium Recovery Field Office. 4pp. 33098-193-33098-196.

DOCKET 40-3392 ALLIED CHEMICAL CORP., MORRISTOWN, NJ

8510080190 Requests addl info re 850829 amend request including collection efficiency as function of particle size & proposed fiberglass air sampling filters & clarification of listed items re whole body counting program. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/01. CIPOLLA, A.J. Allied Chemical Corp. 2pp. 32925-240-32925-241.

8510230254 Discusses review of use of Model 48G thin-wall cylinders for transport w/ natural UF6. Requests evaluation of use of cylinders for filling at Allied facility to complete review. COOL, L.A. Uranium Fuel Licensing Branch. 85/10/15. CIPOLLA, A.J. Allied Corp. 1p. 33106-362-33106-362.

DOCKET 40-3453 ATLAS MINERALS, INC., DENVER, CO

8510160309 Forwards surety contracts entered into by Atlas Corp & State of UT Board of Oil Gas & Mining for 21 mines & for mill. Contracts still in effect as written. MAY, K. Utah. State of. 85/09/17. SMITH, R.D. Uranium Recovery Field Office. 17pp. 33028-261-33028-277.

8510210169 Submits review of semiannual ALARA audit for 1984. Minor corrections to program expected. Licensee effort adequate. SHOPEN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 4pp. 33094-203-33094-206.

8510210048 Submits review of First Half 1985 environ monitoring for Moab Mill. dtd 850826. Two sampling stations located in prevailing wind direction from ore pipes & tailings pond had significantly increased radon. SHOPEN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/07. Uranium Recovery Field Office. 4pp. 33094-283-33094-286.

DOCKET 40-4492 AMERICAN NUCLEAR CORP., CASPAR, WY

8510090305 Forwards water monitoring data sheet for Apr 1985 quarterly sampling. per 850726 request for addl info. Sheet gives measuring point elevations for most monitored wells. Recovery Well 1 plumbed into return line to Tailings Pond 1. ANDRUS, N.J. American Nuclear Corp. 85/08/06. PETTENGILL, H.J. Uranium Recovery Field Office. 2pp. 32950-168-32950-168.

—8510090306 Water monitoring data sheet for Apr 1985 quarterly sampling. * American Nuclear Corp. 85/04/30. 2pp. 32950-170-32950-171.

8510150271 Responds to 850829 ltr re testing of tailings cover mats. Plan describes limited sampling program that will only provide rough estimate of relative proportion of unsuitable mat in dump. Samples should be obtained from side slopes. MOXLEY, M. Wyoming. State of. 85/09/04. ANDRUS, N. American Nuclear Corp. 4pp. 33033-031-33033-034.

4 DOCKETED ITEMS

8510090312 Informs that air monitoring will be discontinued at Loco Shop & Puddle Springs Ranch remote stations, effective on 851001 Stations will be decommissioned & sites reclaimed.
ANDRUS, N.J. American Nuclear Corp. 85/09/12. PETTENGILL, H.J. Uranium Recovery Field Office. 1p. 32950-099-32950-099.

8510090267 Ack receipt of Custody Receipt 20413 for US Treasury Bill, CUSIP 912794JA3, Treasury bill accepted as replacement bonding instrument for US Treasury Bill, CUSIP 912794HZ0 which matured on 850919.
BRYAN, V.J. Wyoming, State of. 85/09/19. FERGUSON, J.C. American Nuclear Corp. 3pp. 32948-246-32948-248.

8510180470 Forwards Amend 23 to License SUA-667 for American Nuclear Corp. reissuing license for mill in decommissioning mode. Previous request for source mat'l license withdrawn from consideration per 850613 request.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. ANDRUS, N.J. American Nuclear Corp. 2pp. 33077-285-33077-301.

-8510180473 Amend 23 to License SUA-667 for American Nuclear Corp. authorizing possession of natural U as residual contamination from previously licensed activities.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. 5pp. 33077-288-33077-292.

-8510180476 Submits approval of Amend 23 to License SUA-667 for American Nuclear Corp. reissuing license for mill in decommissioning mode. Previous application for renewal of source mat'l license withdrawn per licensee 850613 request.
GARCIA, P.J., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/02. Uranium Recovery Field Office. 9pp. 33077-293-33077-301.

8510180448 Reviews American Nuclear Corp. First & Second Quarter 1985 environ monitoring data. Joint review of groundwater monitoring program underway by NRC & State of WY, Dept. of Environ. Quality.
KONWINSKI, G.R., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 4pp. 33077-120-33077-123.

DOCKET 40-6500 ENERGY, DEPT. OF, CANONSBURG, PA

8510030251 Submits items of interest. License SUB-1010 renewed on 850920 for receipt, sampling & conversion of yellowcake to UF₆. Canonsburg site toured. Site certification discussed w/DOE. Remedial action will be completed in Nov 1985.
CROW, W.T. Uranium Fuel Licensing Branch. 85/09/26. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 32849-115-32849-115.

8510300236 Trip rept of 850917-18 visit to Canonsburg, PA for dry run certification review of completion of remedial action at UMTRAP site. List of attendees encl.
GNUGNOLL, G.N. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/04. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 14pp. 33261-296-33261-309.

DOCKET 40-6622 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

8510210053 Submits review of semiannual ALARA rept for Pathfinder Mines Corp. Shirley Basin U Mill, dtd 850827 on exchange area only sampling location exceeding 25% of max permissible concentration. Audit acceptable. No further action needed.
KONWINSKI, G.R., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 3pp. 33094-280-33094-282.

8510220081 Submits review of First & Second Quarter 1985 environ monitoring data for Pathfinder Shirley Basin Mill, dtd 850829. Seepage collection & pumpback sys installed downgradient of impoundment.
KONWINSKI, G.R., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 4pp. 33098-246-33098-249.

8510240001 EN-85-073 on 851023, notice of violation & proposed imposition of civil penalties in amount of \$8,000 will be issued. Action based on unauthorized const of three U heap leach piles & failure to comply w/EPA stds.
ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/17. 1p. 33155-322-33155-322.

8510290117 Discusses insp on 850618-19, 0702 & 15 & forwards notice of violation & proposed imposition of civil penalty in amount of \$8,000.
MARTIN, R.D. Region 4, Office of Director. 85/10/24. SIMCHUK, G. Pathfinder Mines Corp. 2pp. 33235-264-33235-271.

-8510290127 Notice of violation & proposed imposition of civil penalty in amount of \$8,000. Violations noted: licensee possessed unauthorized byproduct mat'l from special mine wastes & inadequate environ assessment.
MARTIN, R.D. Region 4, Office of Director. 85/10/23. 4pp. 33235-267-33235-271.

-8510290136 Notice of deviation from insp on 850618-19. Deviation noted: radiation safety officer did not attend refresher training course on U mill health physics since 1981.
MARTIN, R.D. Region 4, Office of Director. 85/10/23. 1p. 33235-271-33235-271.

DOCKET 40-6659 GETTY OIL/PETROTRONIC CO., SHIRLEY BASIN, WY

8510180432 Forwards "Environ Sample Data, First Quarter 1985," "Environ Sample Data, Second Quarter 1985," "Stack Emissions Survey Petrotronics Co U Mill Shirley Basin, WY, Mar 1985" & "Stack Emissions Survey..." per 10CFR40.85 & License Condition 20.
PFAFF, S.J. Petrotronics Co. (formerly Getty/Petrotronics Co.). 85/06/29. PETTENGILL, H.J. Uranium Recovery Field Office. 3pp. 33076-304-33077-113.

-8510180437 Radionuclide liquid effluent release info for First Half 1985.
PFAFF, S.J. Petrotronics Co. (formerly Getty/Petrotronics Co.). 85/06/28. PETTENGILL, H.J. Region 4, Office of Director. 3pp. 33076-306-33076-307.

-8510180439 "Environ Sample Data, First Quarter 1985."
Petrotronics Co. (formerly Getty/Petrotronics Co.). 85/03/31. 24pp. 33076-308-33076-332.

-8510180441 "Environ Sample Data Second Quarter 1985."
Petrotronics Co. (formerly Getty/Petrotronics Co.). 85/06/30. 36pp. 33076-333-33077-007.

-8510180443 "Stack Emissions Survey, Petrotronics Co U Mill, Shirley Basin, WY, Mar 1985."
Western Environmental Services & Testing. 85/03/31. 55pp. 33077-008-33077-062.

-8510180446 "Stack Emission Survey Petrotronics Co U Mill, Shirley Basin, WY, May 1985."
Western Environmental Services & Testing. 85/05/31. 51pp. 33077-063-33077-113.

8510170436 Requests addl info re 850905 submittal concerning radiological survey & cleanup plan, per License Condition 25 D Response requested by 851015.
PETTENGILL, H.J. Uranium Recovery Field Office. 85/09/24. PFAFF, S.J. Petrotronics Co. (formerly Getty/Petrotronics Co.). 2pp. 33047-185-33047-186.

8510210106 Submits review of First & Second Quarter 1985 environ monitoring data for Petrotronics mill. One Th-230 reading 11% of max permissible concentration. No trends in environ monitoring areas identified. No licensing action warranted.
KONWINSKI, G.R., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 4pp. 33094-269-33094-272.

8510170331 Submits results of 850909-12 land survey, per License Condition 19. No change in land use within 5 miles of restricted area boundary around mill in last yr. Mining discontinued north of restricted area.
PFAFF, S.J. Petrotronics Co. (formerly Getty/Petrotronics Co.). 85/10/02. PETTENGILL, H.J. Licensing Branch 2. 1p. 33043-357-33043-357.

DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA

8510310474 Forwards Oak Ridge Associated Univs radiological site assessment program repts, "Confirmatory Radiological Survey, Greenville, PA" & "Followup Survey Findings, Greenville, PA," per 851023 telcon w/o encls.
COOL, D.A. Uranium Fuel Licensing Branch. 85/10/24. TERRILL, J.G. Energy Impact Associates. 1p. 33278-273-33278-273.

DOCKET 40-7604 VISTRON CORP., LIMA, OH

8510210230 Forwards draft "Outline of Proposed Plan to Decommission Vistron Corp. Lima, OH Facility Operated Under NRC Mat'l Byproduct License SUB-908," & "Radiation Detection & Control Plan for ANI Dismantlement," for review w/o encl.
HOUGLAND, J.W. Sohio Chemical Co. (subs. of Standard Oil Co., Ohio). 85/09/23. COOL, D.A. Division of Fuel Cycle & Material Safety. 2pp. 33079-340-33079-357.

-8510210236 Forwards draft "Outline of Proposed Plan to Decommission Vistron Corp. Lima, OH Facility Operated Under NRC Mat'l Byproduct License SUB-908," for review. Requests opportunity to meet w/NRC to discuss plan.
HOUGLAND, J.W. Sohio Chemical Co. (subs. of Standard Oil Co., Ohio). 85/09/04. ADAM, B. Region 3, Office of Director. 17pp. 33079-341-33079-357.

8510110254 Requests that vendor 500612 request to terminate License SUB-908 be placed in Mgt Tracking Sys. Licensee should submit addl info re qualifications of individuals performing decontamination.
AXELSON, W.L. Region 3, Office of Director. 85/09/30. CROW, W.T. Uranium Fuel Licensing Branch. 4pp. 32974-354-32974-357.

DOCKET 40-8006 KERR-MCGEE CORP., OKLAHOMA CITY, OK

8510010044 FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1975 & Oct 1976 - Mar 1977.
BARNES, C. Affiliation Not Assigned. 85/07/22. Division of Rules and Records. 1p. 32830-075-32830-075.

8510010060 Responds to FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1973. Forwards App A & B documents. No records available for Docket 40-2038.
FELTON, J.M. Division of Rules and Records. 85/08/29. BARNES, C. Affiliation Not Assigned. 8pp. 32830-076-32830-085.

-8510010065 Forwards IE Bulletin 75-07, "Exothermic Reaction in Used HEPA Filters," requiring action re NRC licensed activities.
HOWARD, E.M. Region 4, Dallas, Office of the Director. 75/11/26. Kerr-McGee Nuclear Corp. 1p. 32830-084-32830-088.

-8510010081 Forwards application for source mat'l license. Expedited consideration of application appreciated.
HEWLETT, J.P. Kerr-McGee Corp. 69/05/09. NUSSBAUMER, D.A. Atomic Energy Commission. 1p. 32830-093-32830-093.

-8510010089 Application for license, authorizing use of U for calibr & standardization of instruments & in research on radiation measurements.
Kerr-McGee Corp. 69/05/09. 5pp. 32830-094-32830-098.

-8510010103 Forwards License SUB-986. Related info encl.
HARMON, D.F. Atomic Energy Commission. 69/05/20. HEWLETT, J.P. Kerr-McGee Corp. 2pp. 32830-099-32830-100.

-8510010117 License SUB-986 for Kerr-McGee Corp. authorizing use of U.
HARMON, D.F. Atomic Energy Commission. 69/05/20. 1p. 32830-101-32830-101.

-8510010121 Requests interpretation of licensing category for assessment of fee. License could be classified as storage due to burial of mat'l & proper licensing category would be 2B rather than 2A.
HEWLETT, J.P. Kerr-McGee Corp. 71/02/12. PRICE, E. Atomic Energy Commission. 2pp. 32830-102-32830-103.

-8510010127 Application for amend to License SUB-986, revising Item 7 to read "800 lb U."
VALENTINE, A.M. Kerr-McGee Corp. 71/03/30. LAYFIELD, R.L. Atomic Energy Commission. 2pp. 32830-104-32830-105.

-8510010134 Advises of reason for delay in paying invoice L-1557-71. Invoice will be paid upon receipt of opinion from Div of State & License Relations.
HEWLETT, J.P. Kerr-McGee Corp. 71/03/03. Atomic Energy Commission. 1p. 32830-106-32830-106.

-8510010148 Notifies of issuance of Amend 1 to License SUB-986, revising Item 7 to reflect max possession limit of 364 kg source matl.
LAYFIELD, R.L. Atomic Energy Commission, 71/04/23. VALENTINE, A.M. Kerr-McGee Corp. 2pp. 32830:108-32830:109.

-8510010153 Forwards Insp Findings & Licensee Ack on 720526 of License SUB-986.
HYDER, J.E. Atomic Energy Commission, 72/06/01. VALENTINE, A.M. Kerr-McGee Corp. 1p. 32830:110-32830:110.

-8510010160 Insp Findings & Licensee Ack on 720526 of License SUB-986. No non-compliance or unsafe conditions found.
* Region 4, Dallas, Office of the Director. 72/05/26. 1p. 32830:111-32830:111.

-8510010166 Application for amend to License SUB-986, revising Item 6 to reflect use of U & thorium source matl.
ROBERTSON, W.J. Kerr-McGee Corp. 72/09/13. LAYFIELD, R.L. Atomic Energy Commission, Directorate of Licensing. 3pp. 32830:112-32830:114.

-8510010173 Application for amend to License SUB-986, authorizing use of 800 lb U & thorium for development of solvent extraction process for separation & purification of thorium.
* Kerr-McGee Corp. 65/09/05. 3pp. 32830:115-32830:117.

-8510010181 Notifies of issuance of Amend 6 to License SUB-986, revising Items 6 & 8 to reflect use of U & thorium source matl.
LAYFIELD, R.L. Atomic Energy Commission, Directorate of Licensing. 72/09/29. ROBERTSON, W.J. Kerr-McGee Corp. 1p. 32830:118-32830:118.

-8510010224 Forwards application for renewal of License SUB-986. Related documents encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/04/30. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:130-32830:132.

-8510010230 Application for amend to License SUB-986, renewing license to authorize use of thorium matls in solvent extraction process for separation & purification & U matl as radiation sources for experimental work.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/04/30. 2pp. 32830:133-32830:137.

-8510010243 Forwards application for renewal of License SUB-986.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/05/09. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:138-32830:138.

-8510010248 Application for renewal of License SUB-986, authorizing use of thorium matls in solvent extraction process & U matls as radiation sources in experimental work, design & calibr of new instruments. Related documents encl.
* Kerr-McGee Corp. 74/05/09. 5pp. 32830:139-32830:143.

-8510010254 Insp rept of License SUB-986 on 720526. No noncompliance noted. Major areas inspected: scope of licensee program, organization, administrative control, noncompliance & safety items.
* NRC - No Detailed Affiliation Given. 72/07/12. 6pp. 32830:144-32830:153.

-8510010263 Health & safety evaluation insp rept of facility on 700325. No noncompliance noted. Major areas inspected: records review, interview of persons responsible for administration & radiation safety aspects of program.
PAAS, H.L., BROWN, G.D. Atomic Energy Commission, 70/04/10. 9pp. 32830:154-32830:162.

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

8510010044 FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1975 & Oct 1976 - Mar 1977.
BARNES, C. Affiliation Not Assigned. 85/07/22. Division of Rules and Records. 1p. 32830:075-32830:075.

8510010060 Responds to FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1975. Forwards App A & B documents. No records available for Docket 40-2038.
FELTON, J.M. Division of Rules and Records. 85/08/29. BARNES, C. Affiliation Not Assigned. 8pp. 32830:076-32830:171.

-8510010065 Forwards IE Bulletin 75-07, "Exothermic Reaction in Used HEPA Filters," requiring action re NRC licensed activities.
HOWARD, E.M. Region 4, Dallas, Office of the Director. 75/11/26. Kerr-McGee Nuclear Corp. 1p. 32830:084-32830:088.

-8510010126 Insp rept on 740604-06. No violations noted. Major areas inspected: previous insp history, organization & administration, health physics organization, radiological procedures, personnel monitoring & effluents.
MURRAY, B., BROWN, G.D. Region 4, Dallas, Office of the Director. 74/07/12. 14pp. 32830:255-32830:268.

-8510010135 Forwards plan to accomplish objectives re stopping & containing present leakage & preventing occurrence of further leakage in Raffinate Pond 2 at facility per 850925 request.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/10/25. MILLER, J.R. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830:269-32830:275.

-8510010142 Forwards Suppl 3 to "Applicant Environ Rept," presenting cost benefit discussion of alternate methods of raffinate disposal applicable to process considered to be technically feasible.
SHELLEY, W.J. Kerr-McGee Corp. 73/08/01. ROUSE, L.C. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:276-32830:276.

-8510010150 Suppl 3 to "Applicant Environ Rept."
* Kerr-McGee Corp. 73/08/31. 20pp. 32830:277-32830:297.

-8510010159 Forwards response to questions & comments re environ assessment of expansion of UF6 facility capacity. Methods contemplated include returning sludges to Kerr-McGee mill site in State of NM & solidification & burial of sludge.
SHELLEY, W.J. Kerr-McGee Corp. 77/01/03. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 5pp. 32830:298-32830:302.

-8510010164 Permit OK 0000191 for NPDES authority to discharge from facility into headwaters of RS Kerr Reservoir on Arkansas River.
WHITE, J.C. Environmental Protection Agency. 76/07/31. 13pp. 32830:303-32830:315.

-8510010174 Forwards corrected 770111 ltr transmitting suppl to rept for waste retention ponds, correcting date of ltr.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/01/11. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 1p. 32830:316-32830:316.

-8510010183 Responds to 761019 request for info re environ assessment of UF6 facility & forwards rept describing drilling of addl core holes, info gained & data generated from tests conducted w/new holes. W/o encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/01/11. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 3pp. 32830:317-32830:319.

-8510010229 Responds to 761012 request for info re 761008 application for renewal of License SUB-1010. Response replaces 750627 application for license renewal. Frequency in Paragraph 5.7.4 revised to read "semimonthly," in response to Question 26.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/01/12. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 1p. 32830:320-32830:320.

-8510010236 Application for amend to License SUB-1010, authorizing treatment of approx 160 acres of Kerr-McGee Corp land immediately south of facility w/max concentration of ammonium nitrate from treated raffinate.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/03/09. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 21pp. 32830:321-32830:341.

-8510010242 Informs that well mods made during 770328-0405 to prevent leakage of Raffinate Pond 2. Revised monitor well location & well summary table encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/05/31. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 10pp. 32830:342-32830:351.

-8510010247 Confirms 770726 telcon w/GJ Sinke re 770112 application for renewal of License SUB-1010. Addl info requested, including commitment to verify design exhaust vols by actual measurements when determining stack losses.
ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 77/08/01. SHELLEY, W.J. Kerr-McGee Nuclear Corp. 5pp. 32830:352-32830:356.

-8510010256 Forwards draft revised pages to License SUB-1010, incorporating changes discussed in 770726 telcon. Exception authorizing use of GMR canister for protection against combined HF & U particulate hazards requested.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/08/03. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 22pp. 32830:357-32830:016.

-8510010261 Responds to 850520 request for revised dose estimates for expanded facility. Dose estimates for 50-mile radius will be provided promptly upon receipt of info from consultant. Calculated dose estimates encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/08/13. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 9pp. 32831:017-32831:026.

-8510010269 Forwards corrected Page 2 to 770813 submittal re estimated facility doses, correcting erroneous distance of first location.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/08/16. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 2pp. 32831:027-32831:028.

-8510010271 Confirms 720530 telcon w/CR Buchanan re Kerr-McGee Corp application for amend to License SUB-1010, authorizing disposal of liquid wastes from UF6 plant by deep well injection. Comments & recommendations requested.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/06/02. DEBUCHANAN, G. Interior, Dept. of Geological Survey. 2pp. 32830:163-32830:164.

-8510010273 Forwards draft "Calculation of Potential Impact of Releases From Sequoyah UF6 Facility for Year 1976 & 2000." Estimate of data results in considerably lower dose estimate than 1972 calculation.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/09/16. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 1p. 32831:029-32831:029.

-8510010275 Follows up Chitwood 720530 call re application for amend to License SUB-1010, authorizing deep well disposal of wastes from Sequoyah facility. Comments & recommendations re application requested.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/06/02. WARNER, D.L. Missouri, Univ. of Rolla, MO. 2pp. 32830:165-32830:166.

-8510010279 Draft "Calculation of Potential Impact of Releases From Sequoyah UF6 Facility for 1976 & 2000."
* Kerr-McGee Corp. 77/09/16. 31pp. 32831:030-32831:060.

-8510010280 Responds to 720602 request for recommendations & comments re Kerr-McGee Corp application for amend to License SUB-1010, authorizing disposal of liquid waste from UF6 plant by deep well injection. New data does not address brine displaced.
DEBUCHANAN, G. Interior, Dept. of Geological Survey. 72/06/16. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:167-32830:168.

-8510010285 Confirms 770929 request for written notification to State of OK Dept of Health Air Quality Svc, informing of proposed expanded UF6 production & requesting authorization for airborne effluents.
ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 77/09/30. SHELLEY, W.J. Kerr-McGee Corp. 3pp. 32831:061-32831:063.

-8510010289 Advises that time required for review of application for amend to License SUB-1010 will be lengthened due to review of State of OK geological survey work. Review should be completed by end of June.
WARNER, D.L. Missouri, Univ. of Rolla, MO. 72/06/16. BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:169-32830:169.

-8510010294 Forwards 1 Younghein 771001 ltr expressing Citizens Action for Safe Energy concern that EIS for UF6 facility expansion be prepared. Formal ack of concern requested. Related info encl.
SPOTTS, C.B. Environmental Protection Agency. 77/10/25. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 3pp. 32831:064-32831:066.

-8510010296 Ack receipt of 720616 ltr re intended review of State of OK geological study of Kerr-McGee plant site. Any readily available geological info re area should be considered in proposal evaluation.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/07/06. WARNER, D.L. Missouri, Univ. of Rolla, MO. 1p. 32830:170-32830:170.

6 DOCKETED ITEMS

- 8510010300 Forwards updated drawing of 160-acre fertilizer test plot, per 770926 request. SINKE, G.J. Kerr-McGee Nuclear Corp. 77/10/24. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 5pp. 32831-067-32831-071.
- 8510010303 Forwards Kerr-McGee Corp revised "Applicants Environ Rept" & supplemental "Applicants Environ Rept" re UF6 plant. Review of repts & comments requested. ROTHFLEISCH, J. Atomic Energy Commission. 72/08/24. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 1p. 32830-171-32830-171.
- 8510010308 Insp Findings & Licensee Ack on 730409-11 of License SUB-1010. No noncompliance found. Related info encl. * Region 4, Dallas, Office of the Director. 73/04/09. 2pp. 32831-072-32831-073.
- 8510010309 Comments on Kerr-McGee Corp revised & supplemental "Applicant Environ Rept," in response to 720824 request. Environ surveillance program & four air samplers wholly inadequate for job intended. VAN DER HOVEN Commerce, Dept. of Natl. Oceanographic & Atmospheric Administration. 72/09/25. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830-172-32830-173.
- 8510010318 Draft insp rept of License SUB-1010 on 730409-11. No violations noted. Major areas inspected: scope & conditions of license, organization & administration facilities & equipment & radiological safety precautions. HYDER, J.E., BRAUN, G.D. Region 4, Dallas, Office of the Director. 73/05/15. 12pp. 32831-074-32831-085.
- 8510010327 Discusses telcon re attendance at 721120 meeting in Bethesda, MD requested by Kerr-McGee Corp concerning proposal for deep well disposal of wastes from facility. Participation encouraged. BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 72/11/07. DEBUCHANAN, G. Interior, Dept. of Geological Survey. 1p. 32830-177-32830-177.
- 8510010335 Forwards modified version of comments & questions provided of meeting per 721120 discussions. Response to comments & questions requested in order to proceed on schedule w/facility DES. W/o encl. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 72/12/04. SHELLEY, W.J. Kerr-McGee Corp. 1p. 32830-178-32830-178.
- 8510010341 Summarizes 721120 meeting w/Kerr-McGee Corp in Bethesda, MD re proposal for deep well disposal of low level waste. Deep well disposal might be approved for limited period of 5 yrs w/appropriate restrictions & monitoring requirements. BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 72/12/07. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830-179-32830-180.
- 8510010349 Comments on relative merits of subsurface injection & waste holding ponds as two possible methods of handling raffinate waste at facility. Alternative to ponds should be developed. Related correspondence encl. WARNER, D.L. Missouri, Univ. of, Rolla, MO. 72/12/22. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830-181-32830-183.
- 8510010356 Informs that on 721215, Shelley notified Nussbaumer of unfortunate accident resulting in delay of response to 721208 ltr. Response to questions enclosed W/o encl. DUNN, P.S. Kerr-McGee Corp. 72/12/29. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 1p. 32830-184-32830-184.
- 8510010368 Forwards most current ltr sent to Kerr-McGee Corp re denial of proposal to dispose of raffinate wastes from facility by deep well. Related info encl. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 73/02/16. DEBUCHANAN, G. Interior, Dept. of Geological Survey. 10pp. 32830-215-32830-224.
- 8510010372 Requests review of Suppl 2 to environ rept re raffinate pond seepage. Comments requested at earliest opportunity. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 73/03/14. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 1p. 32830-225-32830-225.
- 8510010391 Requests review of Suppl 2 to environ rept re raffinate pond seepage. Comments requested at earliest opportunity. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 73/03/14. WARNER, D.L. Missouri, Univ. of, Rolla, MO. 1p. 32830-226-32830-226.
- 8510010394 Expresses gratitude for courtesy & cooperation extended during 730321-22 plant visit to facility & confirms that add items will be provided, including proposal re solvent extraction raffinate disposal. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 73/03/26. SHELLEY, W.J. Kerr-McGee Corp. 2pp. 32830-227-32830-228.
- 8510010398 Discusses addl info supplied on 730314 re Kerr-McGee EIS. Review concluded that high nitrate levels shown for Monitor Wells 1, 2 & 5 was result of contamination. WARNER, D.L. Missouri, Univ. of, Rolla, MO. 73/03/28. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 1p. 32830-229-32830-229.
- 8510010401 Responds to 730326 request for addl info resulting from Malaro 730321-22 site visit & previous submittals of environ rept. Proposal re short-term treatment & ultimate solution to solvent extraction raffinate disposal encl. SHELLEY, W.J. Kerr-McGee Corp. 73/04/09. ROUSE, L.C. Atomic Energy Commission, Directorate of Licensing. 5pp. 32830-230-32830-234.
- 8510010404 Forwards comments on raffinate pond seepage & air sampling. Review concluded that monitoring plan adequate. Air samplers should be moved out at least 1 mile. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 73/04/19. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830-235-32830-238.
- 8510010408 Forwards review & comments re significance of gross alpha, gross beta, radium & U in groundwater monitoring well samples per 730530 request. Contamination w/soluble U indicated in most seepage wells. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 73/06/15. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 3pp. 32830-239-32830-241.
- 8510010413 Responds to request for fluoride in air & vegetation data in 1973. Revised analytical procedure for determination of fluoride in air & stack gas samples & related info encl. SHELLEY, W.J. Kerr-McGee Corp. 73/07/16. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830-242-32830-249.
- 8510010415 Discusses retention pond leakage noted during 740604-06 routine insp of License SUB-1010. Licensee drilled 10 addl seepage wells to help identify seepage area. BROWN, G.D. Atomic Energy Commission. 74/06/18. THORNBURG, H.D. Atomic Energy Commission, Directorate of Regulatory Operations. 2pp. 32830-250-32830-251.
- 8510010421 Insp Findings & Licensee Ack on 740604-06 of License SUB-1010. No noncompliance or unsafe conditions found. MURRAY, B. Region 4, Dallas, Office of the Director. 74/06/04. 3pp. 32830-252-32830-254.
- 8510010093 Forwards WT Crow 850920 ltr to JC Stauter forwarding renewed License SUB-1010 & related SER finding of no significant impact on quality of human environ & environ assessment (NUREG-1157). Related correspondence. LEWIS, S.H. Hearing Branch 2. #485 679. 85/10/03. FRYE, J.H. Atomic Safety and Licensing Board Panel. 225pp. 32957-238-32958-335.
- 851020235 Forwards Sequoyah Fuels Corp response to petitions re proposed UF6-to-UF4 conversion facility & app. STAUTER, J.C. Kerr-McGee Corp. #485 843. 85/10/18. Docketing & Services Branch. 1p. 33089-077-33089-266.
- 851020241 Response to petitions re proposed UF6-to-UF4 conversion facility W/one oversize drawing Apps & Certificate of Svc encl. STILLE, T. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 85/10/18. Atomic Safety and Licensing Board Panel. 178pp. 33089-078-33089-266.
- 8510100184 Requests to make limited appearance statement at upcoming hearing. LITTELL, A. People's Action for Safe Environment. #485 703. 85/09/10. FRYE, J.H. NRC - No Detailed Affiliation Given. 1p. 32962-108-32962-108.
- 8510020378 Petition of Natl Water Ctr for leave to intervene & request for hearing. Served on 850930. COSTNER, P. National Water Center. #485 650. 85/09/12. NRC - No Detailed Affiliation Given. 5pp. 32824-044-32824-348.
- 8510150071 Forwards revised application for renewal of License SUB-1010, revising Chapters 1-8 to incorporate updated environ matl for 1983 & 1984 & NRC comments. STAUTER, J.C. Kerr-McGee Corp. 85/09/13. CROW, W.T. Uranium Fuel Licensing Branch. 2pp. 33051-130-33051-220.
- 8510150073 Revised application for renewal of License SUB-1010, revising Chapters 1-8 to incorporate updated environ matl for 1983 & 1984 & NRC comments. * Kerr-McGee Corp. 85/08/31. 90pp. 33051-132-33051-220.
- 8510160304 Forwards Aug 1985 rept for controlled industrial waste injection well. No wastes disposed of during period. Annulus pressure monitored & maintained above min 10 psig requirement. STAUTER, J.C. Kerr-McGee Corp. 85/09/13. HENSCH, D.A. Oklahoma, State of. 1p. 33028-278-33028-278.
- 8510160307 "Groundwater Monitoring & Injection Well Data for Aug 1985." * Kerr-McGee Corp. 85/08/31. 4pp. 33028-279-33028-283.
- 8510180337 Response to ASLB 850927 memorandum & order Consolidation of participation w/NACE declined & petition for intervention withdrawn. IKARD, J.A. Cherokee Nation. IKARD, J.A. Ikard, J. #485 818. 85/09/26. Atomic Safety and Licensing Board Panel. 3pp. 33060-267-33060-269.
- 8510020128 Responds to 850830 request for compilation of all violations, contaminations & permits for Sequoyah Fuels Corp facility near Gore, OK. Info can be reviewed at LPOR in Salinas, OK. W/o stated encl. CROW, W.T. Uranium Fuel Licensing Branch. 85/09/27. DICK, G. Cherokee Nation. 1p. 32829-273-32829-274.
- 8510020133 Requests compilation of all violations, contaminations & permits for Sequoyah Fuels Corp facility near Gore, OK, including permit expiration dates & regulations on radwastes. DICK, G. Cherokee Nation. 85/08/30. NRC - No Detailed Affiliation Given. 1p. 32829-274-32829-274.
- 8510100194 Authorizes Natl Water Ctr to petition on author behalf for leave to intervene. GRULKEY, M.W. Affiliation Not Assigned. #485 694. 85/10/01. FRYE, J.H. Atomic Safety and Licensing Board Panel. 1p. 32962-107-32962-107.
- 8510090136 Submits items of interest. On 850926, ASLB admitted listed parties to Sequoyah Fuel Corp hearing on amend request to construct UF6 conversion facility. Sequoyah must respond to petitioner allegations by 851015. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/02. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards Director. 1p. 32951-340-32951-340.
- 8510180172 Errata to ASLB 850926 memorandum & order Served on 851016. FRYE, J.H. Atomic Safety and Licensing Board Panel. #485 793. 85/10/15. 1p. 33063-013-33063-013.
- 8510230044 Requests dismissal of Cherokee Nation &/or Cherokee Tribal Council as party to proceeding due to inability to continue in consolidated position w/Native Americans for Clean Environ Served on 851022. WILCOXEN, J.G. Cherokee Nation. #485 866. 85/10/15. FRYE, J.H. Atomic Safety and Licensing Board Panel. 1p. 33101-359-33101-359.
- 8510310388 Informs that 850422 Sequoyah Fuels Corp environ info adequate to permit preparation of environ assessment. Draft SER & environ assessment will be issued by 851130. LEWIS, S.H. Hearing branch 2. #485 974. 85/10/25. FRYE, J.H. Atomic Safety and Licensing Board Panel. 2pp. 33272-276-33272-276.
- 8510310336 Informs that Sequoyah Fuels Corp response to petitions re proposed UF6-to-UF4 conversion facility addressed to MA Specs returned as undeliverable due to closing of post ofc. Served on 851030. MESERVE, R.A. Covington & Burling. #485 980. 85/10/28. FRYE, J.H. Atomic Safety and Licensing Board Panel. 1p. 33272-048-33272-048.

DOCKET 40-8064 EXXON MINERALS CO., USA, HOUSTON, TX

8510170447 Forwards "Supplemental Rept to Restoration Achievement at Exxon Mineral Co Expanded R&D Pilot in Situ U Mine, Highland U Operations." Requests NRC concurrence so processing of commercial license application can be expedited. MORZENTI, S.P. Everest Minerals Corp. 85/09/10. HAWKINS, E.F. Uranium Recovery Field Office. 1p. 33047-093-33047-181.

-8510170453 "Supplemental Rept to Restoration Achievement at Exxon Mineral Co Expanded R&D Pilot in Situ U Mine, Highland U Operations."
* Everest Minerals Corp. 85/08/19. 86pp. 33047-094-33047-181.

8510180257 Submits results of audit as part of annual insp of License SUA-1064. License Condition 12 requires documentation & maint of file on sampling & monitoring data, subsequent reviews, investigations & corrective actions for at least 5 yrs. HILDENBRAND, P. HAWKINS, E.F. Uranium Recovery Field Office. 85/09/22. Uranium Recovery Field Office. 11p. 33075-075-33075-085.

DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT

8510210176 Submits review of 850712 rept of possible overexposure to personnel working under radiation work permit at Rio Algom Lisbon Mill. Overexposure did not occur according to NRC evaluation. SHOPENN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/09/18. Uranium Recovery Field Office. 2pp. 33094-155-33094-156.

8510090512 Forwards "ALARA Audit of Environ & Radiological Monitoring Program" for 841212-850627.
LAWTON, M.D. Rio Algom Corp. 85/09/25. NRC - No Detailed Affiliation Given. 1p. 32966-154-32966-183.

-8510090513 "ALARA Audit of Environ & Radiological Monitoring Program" for 841212-850627.
* Rio Algom Corp. 85/06/27. 28pp. 32966-156-32966-183.

8510180485 Forwards Amend 7 to License SUA-1119, correcting Amend 6 in which Condition 51 inadvertently substituted for Condition 52.
SMITH, R.D. Uranium Recovery Field Office. 85/10/01. PATTON, R.S. Rio Algom Corp. 33077-320-33077-334.

-8510180486 Amend 7 to License SUA-1119 for Rio Algom Mining Corp. authorizing possession of U waste tailings generated by milling operations.
SMITH, R.D. Uranium Recovery Field Office. 85/10/01. 11pp. 33077-323-33077-333.

-8510180489 Requests fee exemption for issuance of Amend 7 to License SUA-1119. Amend 6 had editorial oversight so Amend 7 issued for NRC convenience.
SHOPENN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. MILLER, W.O. License Fee Management Branch. 1p. 33077-334-33077-334.

8510210070 Submits review of 1985 land use survey for Lisbon Mill. More mobile homes removed, new road constructed, small pond added & restricted area fence extended. No major changes in land use noted. No further action necessary.
SHOPENN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 2pp. 33094-278-33094-279.

8510220084 Submits review of First Half 1985 environ monitoring data for Lisbon Mill, dtd 850830. Chemical data results for wells showing increases & decreases in chemical constituents should be checked in future repts & compared for trends.
SHOPENN, N.M., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 4pp. 33098-232-33098-235.

DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX

8510170409 Forwards revised Page 5-6 of 850806 application for amend to License SUA-1139. Section 5.3 changed to allow contractor training appropriate to task, rather than fixed program given to Exxon & Everest employees.
PATTON, J.D. Exxon Nuclear Co., Inc (subs of Exxon Corp.). 85/09/05. HAWKINS, E.F. Uranium Recovery Field Office. 1p. 33075-018-33075-019.

-8510170413 Revised Page 5-6 of 850806 application for amend to License SUA-1139. Section 5.3 changed to allow contractor training appropriate to task, rather than fixed program given to Exxon & Everest employees.
* Exxon Corp. 85/09/05. 1p. 33075-019-33075-019.

8510180487 Forwards "Airborne Emissions of Principal Radionuclides From Highland Tailings Basin, Jan-June 1985" & "Environ Monitoring Data, Jan-June 1985," per License Condition 12.
RANGE, D.M. Exxon Corp. 85/09/24. Uranium Recovery Field Office. 1p. 33077-350-33078-017.

-8510180490 "Airborne Emissions of Principal Radionuclides From Highland Tailings Basin, Jan-June 1985."
* Exxon Corp. 85/06/30. 1p. 33077-351-33077-351.

-8510180492 "Environ Monitoring Data, Jan-June 1985."
* Exxon Corp. 85/06/30. 28pp. 33077-352-33078-017.

DOCKET 40-8355 AMAX SPECIALTY METALS CORP., PARKERSBURG, WV

8510170019 Responds to FOIA request for documents re investigation of possible unauthorized or unlawful burials of radioactive mat & removal of Nigerian ore or other mat from site info withheld (ref FOIA Exemptions 6 & 7).
FELTON, J.M. Division of Rules and Records. 85/09/27. KOWALSKI, K.M. Squire, Sanders & Dempsey. 8pp. 33048-184-33049-041.

-8510170044 Provides preliminary summary of activities conducted re possible unauthorized burial of low level radioactive waste at site. Recorded radiation level no danger to public health & safety. Activities onsite closely monitored.
ANNAST, M.V. Region 2, Atlanta. Safeguards Branch. 78/05/24. Region 2, Atlanta. Safeguards Branch. 15pp. 33048-217-33048-231.

8510170016 FOIA request for info re AEC or NRC investigation of possible unauthorized or unlawful burials of radioactive mat by Amax, Inc & Carborundum Co & removal of Nigerian ore & other mats from site.
KOWALSKI, K.M. Squire, Sanders & Dempsey. 85/05/18. NRC - No Detailed Affiliation Given. 2pp. 33048-182-33048-183.

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

8510170247 "Environ Sampling Semiannual Rept, Jan-June 1985." W/850826 ltr.
BLOSSOM, J.N. Bear Creek Uranium Co. 85/06/30. 16pp. 33045-111-33045-126.

8510110123 Forwards Rev 1 to App K to Nov 1981 tailings mgt plan, per License Condition 44. App provides erosion analysis that demonstrates proposed reclamation surface hydraulically equivalent to required vegetated slope. Fee paid.
MEDLOCK, R.L. Bear Creek Uranium Co. 85/08/30. SMITH, R.D. Uranium Recovery Field Office. 1p. 33013-027-33013-046.

-8510110132 Rev 1 to App K to Nov 1981 tailings mgt plan W/two oversize drawings.
* Bear Creek Uranium Co. 85/09/01. 18pp. 33013-028-33013-046.

8510110111 Forwards amend fee for 850830 rev to tailings reclamation plan.
MEDLOCK, R.L. Bear Creek Uranium Co. 85/09/11. SMITH, D., PANGBURN, G. Uranium Recovery Field Office. 1p. 33011-344-33011-344.

8510090529 Application for amend to License SUA-1310, allowing disposal of mat from Reno Creek evaporation pond in tailings pond. Approx 1.2 million gallons of slurry containing 1-2% solids will be discharged into tailing pond. Fee paid.
SCOTT, E.Y. Bear Creek Uranium Co. 85/09/12. PANGBURN, G. Uranium Recovery Field Office. 5pp. 32965-089-32965-093.

8510090173 Forwards ltr describing quantity & type of wastes UNC Teton Exploration Drilling, Inc proposes to haul to Bear Creek. Mod of amend allowing disposal of pond wastes from Reno Creek Project at Bear Creek to include UNC waste requested.
NEUMANN, M.R. Rocky Mountain Energy Co. 85/09/17. PANGBURN, G. Uranium Recovery Field Office. 4pp. 32948-197-32948-200.

8510180329 Informs that land use within 5 miles of restricted area boundary remains as described in June 1982 environ rept. No private residences or potable water wells constructed since rept. Grazing remains primary use of land.
BLOSSOM, J.N. Bear Creek Uranium Co. 85/09/26. SMITH, R.D., PANGBURN, G. Uranium Recovery Field Office. 1p. 33068-358-33068-358.

8510180305 Forwards Amend 8 to License SUA-1310, authorizing disposal of U waste mats & slurry.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. BAUMANN, W. Bear Creek Uranium Co. 2pp. 33075-031-33075-062.

-8510180313 Amend 8 to License SUA-1310 for Bear Creek U Co. authorizing possession & disposal of waste tailings generated by milling operations. Related info encl.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. 20pp. 33075-033-33075-060.

-8510180322 Recommends issuance of Amend 8 to License SUA-1310 to change Condition 46 re disposal of synthetic evaporation pond liner mats & other solid & liquid waste resulting from past operations.
* PANGBURN, G.C., HAWKINS, E.F. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 2pp. 33075-061-33075-062.

DOCKET 40-8502 WYOMING MINERAL CORP., LAKEWOOD, CO

8510170430 "Semiannual Activity & Monitoring Rept, Jan-June 1985." W/850821 ltr.
FALLOFF, R.J.R. Westinghouse Electric Corp. 85/06/30. SMITH, R.D. Uranium Recovery Field Office. 8pp. 33047-210-33047-217.

8510130143 Forwards pages inadvertently omitted from 850601 proposed rev to Ingaray Mine application for in situ permit to mine & 850701 rept, "E-Field Restoration Demonstration Program."
RUTLEDGE, C. Westinghouse Electric Corp. 85/09/11. SMITH, R.D. Uranium Recovery Field Office. 11pp. 32849-302-32849-312.

8510170394 Discusses 850710 request for review of "E-Field Restoration Demonstration Program." Expeditious review requested to facilitate coordination of state & federal replies prior to submittal of application for renewal of License SUA-1341.
RUTLEDGE, C. Westinghouse Electric Corp. 85/09/11. SMITH, R.D. Uranium Recovery Field Office. 2pp. 33048-158-33048-159.

8510090269 Discusses review of Westinghouse 850710 request for review of updated Ingaray Permit 478 documents re hydrologic issues.
HOGG, S. Wyoming. State of. 85/09/17. Wyoming. State of. 13pp. 32948-233-32948-245.

8510210039 Reviews Apr-June 1985 rept for Westinghouse Ingaray In Situ Leach facility. Corrective actions pumping of ore zone increased to draw chloride levels down in coal zone. Wells 9R5-64 & 9R5-7a. Overpumping of production zone continued.
HILDENBRAND, P. HAWKINS, E.F. Uranium Recovery Field Office. 85/09/18. Uranium Recovery Field Office. 2pp. 33094-287-33094-288.

8510170191 Forwards post-restoration groundwater stability data from Westinghouse Ingaray 517 test area. Wells 517-6B & 517-3B on data sheets area same wells as 517-6 & 517-3 on area map.
WICHERS, D.L. Donna L. Wichers. 85/10/03. HILDENBRAND, P. Uranium Recovery Field Office. 22pp. 33043-063-33043-084.

DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA

8510170207 Submits summary of reasons for denial of application for permit to construct 85-315 Blue 6 reservoir. Proposed waste & wastewater disposal sys does not provide adequate protection of aquifer.
JARLAND, W.L. Wyoming. State of. 85/09/10. Minerals Exploration Co. (subs of Union Oil Co. of California). 5pp. 33043-058-33043-062.

8510170246 Provides summary of reasons for denial of Water Quality Div Permit 85-315. Proposed design does not adequately protect waters of state.
JARLAND, W.L. Wyoming. State of. 85/09/10. Minerals Exploration Co. (subs of Union Oil Co. of California). 5pp. 33045-127-33045-131.

8510180477 Forwards renewal of License SUA-1350 to continue U milling operations. Environ assessment & SER also and W/o environ assessment or SER.
SMITH, R.D. Uranium Recovery Field Office. 85/10/02. HILL, C. Minerals Exploration Co. (subs of Union Oil Co. of California). 1p. 33077-302-33077-313.

8 DOCKETED ITEMS

-8510180479 Renewal of License SUA-1350 for Minerals Exploration Co., authorizing continued U mill operations.
SMITH,R.D. Uranium Recovery Field Office. 85/10/02. 9pp. 33077-303-33077-311.

-8510180480 Forwards SER prepared in support of renewal of License SUA-1350. W/o end.
KONWINSKI,G.R., PETTENGILL,H.J. Uranium Recovery Field Office. 85/05/29. Uranium Recovery Field Office. 1p. 33077-312-33077-312.

-8510180482 Forwards environ assessment prepared in support of renewal of License SUA-1350. W/o end.
KONWINSKI,G.R., PETTENGILL,H.J. Uranium Recovery Field Office. 85/05/29. Uranium Recovery Field Office. 1p. 33077-313-33077-313.

8510180252 Forwards environ assessment prepared in support of renewal of License SUA-1350 for Minerals Exploration Co Sweetwater U Mill as followup to NRC 841023 ltr W/o end.
PETTENGILL,H.J. Uranium Recovery Field Office. 85/10/03. MARTIN,J.B. Environmental Defense Fund. 1p. 33075-090-33075-090.

8510170474 Requests 851021 meeting to discuss reasons for requiring & denying Permit 85-315 & all areas of disagreement concerning revised tailings plans.
KLEIN,T.J. Union 76 Minerals. 85/10/04. GARLAND,W.C. Wyoming. State of. 1p. 33047-223-33047-223.

8510180259 Forwards Oct 1985 semiannual tailings excursion rept for Sweetwater U project tailings excursion assessment program. Rept will be discussed at 851021 meeting W/o end.
HILL,C.Z. Union 76 Minerals Exploration Co. 85/10/08. GARLAND,W.C. Wyoming. State of. 1p. 33075-086-33075-086.

DOCKET 40-8631 ARMY, DEPT. OF, ROCK ISLAND, IL

8510150077 "Weldon Spring Site Environ Monitoring Rept,CY84." W/850906 ltr.
Bechtel Corp. DOE/OR/20722-58. 84/12/31. 48pp. 33030-303-33030-351.

8510240325 Submits items of interest On 851007-08 meetings held w/LLL re review of model study to evaluate protection against damage in severe accidents afforded by NRC performance criteria On 851008 Comm Ed issued License SNM-1938.
CROW,W.T. Uranium Fuel Licensing Branch. 85/10/10. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards,Director. 2pp. 33182-272-33182-273.

DOCKET 40-8674 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8510170433 "Effluent Monitoring Rept,Jan-June 1985." W/850827 ltr.
REAVEAU,B.K. Plateau Resources, Ltd. 85/06/30. 16pp. 33047-194-33047-209.

8510170393 Application for renewal of License SUA-1326,extending expiration date to 860401 Fee paid.
FISHER,B.O. Plateau Resources, Ltd. 85/09/30. SMITH,R.D. Uranium Recovery Field Office. 1p. 33048-160-33048-160.

DOCKET 40-8681 UMETCO MINERALS CORP., GRAND JUNCTION, CO

8510210118 Forwards notice of final finding of no significant impact re renewal of License SUA-1358 for operation of UMETCO Minerals Corp White Mesa U Mill, San Juan County,UT, for publication in FR.
PETTENGILL,H.J. Uranium Recovery Field Office. 85/09/18. COMBES,T. Office of the Secretary of the Commission. 1p. 33094-264-33094-268.

-8510210125 Notice of final finding of no significant impact re renewal of License SUA-1358 for operation of UMETCO Minerals Corp White Mesa U Mill, San Juan County,UT.
PETTENGILL,H.J. Uranium Recovery Field Office. 85/09/18. 4pp. 33094-265-33094-268.

8510180227 Forwards renewed License SUA-1358,SER & environ assessment. Conditions discussed in 850905 meeting.
SMITH,R.D. Uranium Recovery Field Office. 85/09/26. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 1p. 33075-091-33075-216.

-8510180234 Renewed License SUA-1358 for Umetco Minerals Corp, authorizing possession of U waste tailings & other U byproduct waste generated by milling operations.
SMITH,R.D. Uranium Recovery Field Office. 85/09/26. 10pp. 33075-092-33075-101.

-8510180238 Environ assessment supporting renewal of License SUA-1358 for Umetco Minerals Corp.
GARCIA,P.J., JERREE,C.C., PETTENGILL,H.J. Uranium Recovery Field Office. 85/09/26. 83pp. 33075-102-33075-184.

-8510180243 Forwards SER supporting renewal of License SUA-1358 for Umetco Minerals Corp.
GARCIA,P.J., JERREE,C.C., PETTENGILL,H.J. Uranium Recovery Field Office. 85/09/26. Uranium Recovery Field Office. 1p. 33075-165-33075-216.

-8510180249 SER supporting renewal of License SUA-1358 for Umetco Minerals Corp.
GARCIA,P.J., JERREE,C.C., PETTENGILL,H.J. Uranium Recovery Field Office. 85/09/26. 50pp. 33075-167-33075-216.

8510180250 "NO-IV 85-050 on 850930 10. gallons slurry spilled from door frame weld failure. 20% overflowed onto bldg floor & exited through doorway. Leach tanks will be drained & examined. Welds will be repaired."
PETTENGILL,H. Region 4, Office of Director. 85/10/02. 1p. 32881-133-32881-133.

8510170408 Requests 30-day extension in reporting period for ALARA & effluent repts. Data not received from vendor lab. Repts will be sent upon receipt of data.
SCHEFFMAN,S.L. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 85/10/04. PETTENGILL,H. Uranium Recovery Field Office. 1p. 33043-361-33043-361.

8510180302 Forwards UMETCO Minerals Corp 851018 demand for hearing re Region IV renewal of License SUA-1358.
THOMPSON,A.J. Hamel, Park, McCabe & Saunders. #485 820. 85/10/16. CHALK,S.J. Office of the Secretary of the Commission. 1p. 33062-137-33062-140.

-8510180307 Demands hearing on 850926 renewal of License SUA-1358. Demand should be consolidated w/850812 demand for hearing on 850719 order re issuance of Amend. 29 implementing groundwater detection monitoring program per 40CFR192.32(a)(2).
THOMPSON,A.J. Hamel, Park, McCabe & Saunders. 85/10/16. SMITH,R.D. Uranium Recovery Field Office. 3pp. 33062-138-33062-140.

DOCKET 40-8698 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8510110255 Requests Plateau Resources Ltd application for renewal of License SUA-1371 for interim shutdown.
WRIGHT,C. Utah. State of. 85/09/17. Office of the Executive Legal Director. 1pp. 32974-353-32974-353.

8510170439 Forwards draft environ assessment supporting renewal of Plateau Resources, Ltd License SUA-1371, per request. W/o end.
JERREE,C.C. Uranium Recovery Field Office. 85/09/27. WRIGHT,C. Utah, State of. 1p. 33047-184-33047-184.

8510170444 Submits review of Plateau Resources, Ltd 850909 annual land use survey for Shooting Canyon U Mill. Population decreased by 46 people within 5-mile zone. Rept satisfies License Condition 37 of SUA-1371. No further action required.
JERREE,C.C. Uranium Recovery Field Office. 85/10/01. Uranium Recovery Field Office. 2pp. 33047-182-33047-183.

8510180444 Submits review of licensee semiannual environ monitoring rept for Shooting Canyon U mill processing facility for First Half 1985. Results reflective of nonoperational processing facility.
JERREE,C.C., PETTENGILL,H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 3pp. 33077-117-33077-119.

8510210132 Forwards notice of final finding of no significant impact re renewal of License SUA-1371 for interim shutdown of Shooting Canyon U Processing Mill, Garfield County,UT, for publication in FR.
PETTENGILL,H.J. Uranium Recovery Field Office. 85/10/08. PHILLIPS,J. Office of the Secretary of the Commission. 1p. 33094-259-33094-263.

-8510210135 Notice of final finding of no significant impact re renewal of License SUA-1371 for interim shutdown of Shooting Canyon U Processing Mill, Garfield County,UT.
PETTENGILL,H.J. Uranium Recovery Field Office. 85/10/08. 4pp. 33094-260-33094-263.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8510090222 Informs of approval of 850508 modified reclamation plan leaving bldg, surface road & other mine structures for use of surface owner. F. Brown Approval for abandonment of property pending state & NRC acceptance of wellfields restoration.
MOONEY,G. Wyoming. State of. 85/09/16. LAUDERBACK,T.E. Cleveland-Cliffs Iron Co. 1p. 32949-199-32949-199.

8510170261 Summary of 850913 meeting w/Cleveland Cliffs Iron Co & NRC in Denver, CO re present status of issues concerning in situ operation/reclamation & review of data pursuant to NRC & state sign-off on mine site.
HOGG,S. Wyoming. State of. 85/09/16. SHAFFER,R. Wyoming. State of. 4pp. 33045-051-33045-054.

8510090175 Forwards TH Bartlett ltr defining methods used to analyze selenium, arsenic & mercury in water samples from Collins Draw Project Site, per 850913 discussion.
LAUDERBACK,T.E. Cleveland-Cliffs Iron Co. 85/09/25. WASTLER,S. Uranium Recovery Field Office. HOGG,S. Wyoming. State of. 2pp. 32948-195-32948-196.

8510110262 Application for amend to License SUA-1352, changing monitoring requirements to detect excursion of contaminated groundwater at site during restoration & stabilization to twice per yr. Monitoring results encl. Fee paid.
LAUDERBACK,T.E. Cleveland-Cliffs Iron Co. 85/09/25. WASTLER,S. Uranium Recovery Field Office. SHAFFER,R. Wyoming. State of. 29pp. 33011-156-33011-185.

8510170272 Discusses data re stability of A & B fields, including overage water quality for B-wellfield. Further restoration & followup monitoring to ensure geochemical stability of wellfield recommended.
HOGG,S. Wyoming. State of. 85/09/25. Wyoming. State of. 4pp. 33045-039-33045-042.

8510170336 Informs that revised monitoring plan for Collins Draw Site will be submitted for review. Number of wells monitored will be reduced & excursion indicators increased for some wells.
HOGG,S. Wyoming. State of. 85/09/26. Wyoming. State of. 1p. 33043-358-33043-358.

8510180037 Notifies that NRC cannot concur w/conclusion provided in 850724 submital re groundwater stability data for Wellfields A-1 & B through 850605. New plan to stabilize wellfields requested. Evaluation encl.
HAWKINS,E.F. Uranium Recovery Field Office. 85/10/02. LAUDERBACK,T.E. Cleveland-Cliffs Iron Co. 1p. 33076-166-33076-295.

-8510180042 Concludes that parameter concentration at Cleveland Cliffs Iron Co Wellfields A-1 & B must be reduced & stabilized. Cleveland Cliffs Iron Co should submit plan to stabilize wellfields. Groundwater stability data encl.
WASTLER,S.L. Uranium Recovery Field Office. 85/09/30. Uranium Recovery Field Office. 125pp. 33076-167-33076-295.

DOCKET 40-8724 CHEMETRON CORP., CHICAGO, IL

8510210157 "Rept on Decontamination Activities & Final Confirmatory Survey of McGean-Rohco Properties, Newburg Heights, OH."
Radation Management Corp. 85/09/30. 30pp. 33094-229-33094-258.

DOCKET 40-8745 OGLE PETROLEUM, INC., CASPER, WY

8510170458 "Eighth Semiannual ALARA Audit, Jan-June 1985." W/850911 ltr. BROWN,K.J. Ogle Petroleum, Inc. of California. 85/06/30. 10pp. 33048:161-33048:171.

8510180001 "Annual Land Use Survey, 1984-1985." CATCHPOLE,G.J. Ogle Petroleum, Inc. of California. 85/06/01. PANGBURN,G.C. Uranium Recovery Field Office. 2pp. 33074:271-33074:272.

8510170450 Advises that proposed monitoring plan, outlined in 850712 ltr, acceptable w/ listed exceptions. If monitoring indicates problems, expanded monitoring may again be required. SHAFFER,R. Wyoming. State of. 85/08/19. CATCHPOLE,G.J. Ogle Petroleum, Inc. of California. 1p. 33048:172-33048:173.

8510180299 Summarizes 850930 telcon w/G Catchpole re confidentiality of Catchpole 850712 correspondence & 850919 meeting in Denver between Ogle Petroleum, Inc. & Western Fuels. ENGELMANN,R. Wyoming. State of. 85/09/30. Wyoming. State of. 1p. 33068:357-33068:357.

8510180105 Provides position of Western Fuels, Inc. re restoration & reclamation of lands covered by Permit 504. Position based on review of publicly available documents rather than first hand knowledge of events. BLOOMENTHAL,H. Roath & Brega, P.C. BLOOMENTHAL,H. Western Fuel, Inc. 85/10/07. ERDMANN,J. Wyoming. State of. 4pp. 33069:290-33069:293.

DOCKET 40-8758 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

8510180481 Forwards First Quarter 1985 repts for O-Sand & Q-Sand in situ U R&D projects W/o repts. STAUTER,J.C. Kerr-McGee Corp. 85/06/27. SHAFFER,R. Wyoming. State of. 2pp. 33077:315-33077:315.

8510170332 Application for amend to License S-A-1387, deleting Rn-222 monitoring requirement. Fee paid. FREEMAN,M.D. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 85/09/19. HAWKINS,E., HILDENBRAND,P. Uranium Recovery Field Office. 5pp. 33043:352-33043:356.

DOCKET 40-8778 MOLYCORP, INC., LOS ANGELES, CA

8510220025 Discusses review of Oak Ridge Associated Univs preliminary site assessment rept for facility Rept does not adequately address extent of cleanup required. Requests 90-day extension to define magnitude of cleanup & completion schedule. DAWES,G.W. MolyCorp, Inc. (subs. of Union Oil of California). 85/09/12. KINNEMAN,J.D. Region 1, Office of Director. 2pp. 33098:275-33098:276.

DOCKET 40-8781 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

8510180478 Informs of advanced stage of negotiation w/Central Electricity Generating Board Exploration (America), Inc. for sale of UNC Teton & Nedoc interests in Louenberger project. Background info and W/o encl. TORC,V. Teton Exploration Drilling Co., Inc. (subs. of UNC Resources, Inc.). TOWNSEND,M. Central Electricity Generating Board Exploration, Inc. (London). 85/09/16. SMITH,D. Uranium Recovery Field Office. 1p. 33077:314-33077:314.

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

8510170323 Forwards "Operational Annual ALARA Rept, Jul 1984 - Jul 1985." Rept summarizes all data collected & reported in quarterly repts & contains review by mgmt & radiation safety staff. SOMERVILLE,K.G. Uranerz USA, Inc. 85/09/16. HAWK,J.E., BRICH,R. Uranium Recovery Field Office. 1p. 33044:258-33044:263.

8510170326 "Operational Annual ALARA Rept, Jul 1984 - Jul 1985." SOMERVILLE,K.G., HARTMAN,G.J. Uranerz USA, Inc. 85/07/31. 25pp. 33044:259-33044:283.

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

8510180289 Responds to Pelizza 850911 request re current restoration status of U Resources North Platte R&D project. Current restoration plan is satisfactory for pursuit of final restoration of North Platte site. SPEARS,R.G. Wyoming. State of. 85/09/13. Marsh & McLennan, Inc. 1p. 33068:359-33068:359.

8510170471 Forwards recent alpha, gamma & Rn-222 surveys & documentation of security checks per 850910 request. Alpha probe not recently calibr due to plant inactivity. Probe calibr onsite w/ alpha std prior to surveys. PELIZZA,M.S. Uranium Resources, Inc. 85/09/27. WASTLER,S.L. Uranium Recovery Field Office. 6pp. 33047:224-33047:289.

DOCKET 40-8800 MCGEE DISPOSAL DUMP, NEWBURGH HEIGHTS, OH

8510210157 "Rept on Decontamination Activities & Final Confirmatory Survey of McGee-Rohco Properties, Newburgh Heights, OH." Radiation Management Corp. 85/09/30. 30pp. 33094:229-33094:258.

DOCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CO

8510170019 Responds to FOIA request for documents re investigation of possible unauthorized or unlawful burials of radioactive material & removal of Nigerian ore or other material from site. Info withheld (ref FOIA Exemptions 6 & 7). FELTON,J.M. Division of Files and Records. 85/09/27. KOWALSKI,K.M. Squire, Sanders & Dempsey. 6pp. 33048:184-33048:041.

8510170015 FOIA request for info re AEC or NRC investigation of possible unauthorized or unlawful burials of radioactive material by Amax, Inc. & Carborundum Co. & removal of Nigerian ore or other material from site. KOWALSKI,K.M. Squire, Sanders & Dempsey. 85/05/16. NRC - No Detailed Affiliation Given. 2pp. 33048:182-33048:183.

8510030251 Submits items of interest. License SUB-1010 renewed on 850920 for receipt, sampling & conversion of yellowcake to UF₆. Canonsburg site toured. Site certification discussed w/DOE. Remedial action will be completed in Nov 1985. CROW,W.T. Uranium Fuel Licensing Branch. 85/09/26. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 32849:115-32849:115.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 FORD NUCLEAR REACTOR

P. Operating license stage documents & correspondence

8510250015 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended. HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Michigan, Univ. of, Ann Arbor, MI. 3pp. 33191:356-33191:358.

Q. Inspection reports, IE Bulletins & correspondence

8510310292 Forwards Safety Insp Rept 50-002/85-03 on 851002-04 & notice of violation. SHAFER,W.D. Region 3, Office of Director. 85/10/25. KERR,W. Michigan, Univ. of, Ann Arbor, MI. 1p. 33272:254-33272:262.

8510310293 Notice of violation from insp on 851002-04. SHAFER,W.D. Region 2, Office of Director. 85/10/25. 1p. 33272:255-33272:255.

8510310294 Insp Rept 50-002/85-03 on 851002-04. Violations noted: release of material not readily soluble or dispersible to sanitary sys & failure to complete quarterly effluent repts. NICHOLSON,N.A., GREGER,L.R. Region 3, Office of Director. 85/10/25. 7pp. 33272:256-33272:262.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510180225 Revised emergency procedures document, replacing NUC-1 through 5A-1 through 6, SAE-1 through 6 & GE-1 through 5 w/NUC-1 through 4A-1 through 6 & SAE-1 through 6 in Emergency Procedures Document 1 W/851008 ltr. SELMAN,M. Consolidated Edison Co. of New York, Inc. 85/10/08. MURLEY,T.E. Region 1, Office of Director. 23pp. 33023:149-33023:171.

8510240585 Forwards public version of page changes to emergency procedures document W/851021 release memo. SELMAN,M. Consolidated Edison Co. of New York, Inc. 85/10/11. MURLEY,T.E. Region 1, Office of Director. 3pp. 33185:219-33185:235.

8510240592 Public version of page changes to emergency procedures document. Consolidated Edison Co. of New York, Inc. 85/09/30. 15pp. 33185:221-33185:235.

J. Insurance & indemnity information

8510290372 Forwards Endorsement 142 to NELA Policy NF-100. O'TOOLE,J.D. Consolidated Edison Co. of New York, Inc. 85/10/23. SALTZMAN,J. NRC - No Detailed Affiliation Given. 2pp. 33240:333-33240:334.

G. Advisory Committee on Reactor Safeguards reports & correspondence

8510250179 Presents ACRS position on Indian Point special proceeding. Schedule & plan development recommended to reduce estimated core melt frequency & uncertainty. Detailed containment performance evaluation for particular sites suggested. OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 85/10/12. PALLADINO,N.J. Commissioners. 3pp. 33276:237-33276:239.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc ltr encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32868:282-32868:060.

8509260389 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc ltr encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp. 32868:147-32868:281.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc ltr encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

10 DOCKETED ITEMS

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250302 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Pennsylvania State Univ., University Park, PA. 3pp. 33226-151-33226-153.

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510220166 Forwards revised onsite & offsite maps for Environ Group Procedure 2. Directions for updating procedure listed.
LICARI, K. Commonwealth Edison Co. 85/08/22. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33083-296-33083-297.

8510080506 Revised emergency plan implementing procedures, including Rev 1 to ED-24 re determining recommended offsite protective action response option for general public & Rev 2 to ED-2 re flood prediction sys.
KENEALY, D., BENNETT, C.J. Commonwealth Edison Co. 85/08/31. 150pp. 32943-090-32943-249.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-086.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DIXON Senate. 2pp. 33109-001-33109-002.

8510210064 Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director."
GORDON, J.C. Commonwealth Edison Co. 85/10/15. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33082-282-33083-043.

-8510210073 Revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination." W/two oversize drawings.
KENEALY, D.M., BENNETT, C.J., GOLDEN, J.C. Commonwealth Edison Co. 85/10/15. 120pp. 33082-283-33083-043.

8510240324 Rev 5 to Emergency Plan Implementing Procedure EG-11, "Environ Sample Collection Procedures for Air, Water, Milk, Soil & Vegetation." W/851017 ltr.
KENEALY, D., MOORE, R.D., GOLDEN, J.C. Commonwealth Edison Co. 85/10/17. DENTON, H.R. Record Services Branch (Document Control Desk). 11pp. 33153-327-33153-338.

J. Insurance & indemnity information

8510300064 Forwards unexecuted Amends 23.4 & 5 to Indemnity Agreements B-10, B-97 & B-84, respectively, modifying location descriptions to conform to facility forms.
DINITZ, J. Office of State Programs, Director. 85/10/25. OSTER, J. Commonwealth Edison Co. 4pp. 33261-353-33261-356.

P. Operating license stage documents & correspondence

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

G. Inspection reports, IE Bulletins & correspondence

8510080517 Forwards Insp Repts 50-010/85-14.50-237-35-31 & 50-249/85-27 on 850816-28. No violations noted.
MURELIUS, C.E. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32920-068-32920-074.

-8510080518 Insp Repts 50-010/85-14.50-237/85-31 & 50-249/85-27 on 850816-28. No violations noted. Major areas inspected: licensee prompt & long-term actions in response to 850816 loss of offsite power.
WRIGHT, G.C. Region 3, Office of Director. 85/09/23. 5pp. 32920-070-32920-074.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32868-282-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp. 32868-147-32869-261.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-164.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DIXON Senate. 2pp. 33109-001-33109-002.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

I. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-164.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-001-33109-002.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510210041 Advises that operator & senior operator written & oral exams scheduled for wk of 850127. List of required ref matl & description of requirements for conducting exams encl. License applications required 60 days prior to exam.
REYES, L.A. Region 3, Office of Director. 85/10/15. REED, C. Commonwealth Edison Co. 5pp. 33072-313-33072-317.

DOCKET 50-20 MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250032 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Massachusetts Institute of Technology, Cambridge, MA. 3pp. 33223-359-33223-361.

R. Periodic operating reports & related correspondence

8510170165 MIT Research Reactor Annual Rpt to US NRC for Jul 1984 - June 1985. W/850830 ltr.
CLARK, L. Nuclear Reactor Laboratory. 85/06/30. MURLEY, T.E. Region 1, Office of Director. 26pp. 33052-035-33052-060.

DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)

F. Security, medical, emergency & fire protection plans

- 8510150076** Ack receipt of 850903 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-027/85-02. Referenced portions of current emergency plan implementing procedures manual requested to complete review.
MONTGOMERY, J.L. Region 5, Office of Director. 85/10/07. WILSON, W.E. Washington State Univ., Pullman, WA. 1p. 33010:298-33010:298.
- 8510150082** Responds to NRC 850823 ltr re violations noted in Insp Rept 50-027/85-02. Corrective action-short form security plan procedures manual written on 850805.
WILSON, W.E. Washington State Univ., Pullman, WA. 85/09/03. MONTGOMERY, J.L. Region 5, Office of Director. 1p. 33010:299-33010:299.
- 8510150086** Forwards current physical security plan & new emergency plan procedure covering events listed on Page 14 of plan, per recent physical security insp W/o encl.
WILSON, W.E. Washington State Univ., Pullman, WA. 85/08/05. SCHUSTER, M.D. Region 5, Office of Director. 1p. 33010:300-33010:300.

P. Operating license stage documents & correspondence

- 8510250147** Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Washington State Univ., Pullman, WA. 3pp. 33226:047-33226:049.

Q. Inspection reports, IE Bulletins & correspondence

- 8510080472** Ack receipt of 850919 ltr informing NRC of steps taken to correct violations noted in insp on 850715-17.
SCARANO, R.A. Region 5, Office of Director. 85/10/04. WILSON, W.E. Washington State Univ., Pullman, WA. 1p. 32921:157-32921:163.
- 8510080475** Responds to NRC 850821 ltr re violations noted in insp on 850715-17. Corrective actions: changing of reactor ventilation sys absolute filter added to planned maint schedule & charter for reactor safeguards committee modified.
WILSON, W.E. Washington State Univ., Pullman, WA. 85/09/19. SCARANO, R.A. Region 5, Office of Director. 6pp. 32921:158-32921:163.
- 8510150076** Ack receipt of 850903 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-027/85-02. Referenced portions of current emergency plan implementing procedures manual requested to complete review.
MONTGOMERY, J.L. Region 5, Office of Director. 85/10/07. WILSON, W.E. Washington State Univ., Pullman, WA. 1p. 33010:298-33010:298.
- 8510150082** Responds to NRC 850823 ltr re violations noted in Insp Rept 50-027/85-02. Corrective action-short form security plan procedures manual written on 850805.
WILSON, W.E. Washington State Univ., Pullman, WA. 85/09/03. MONTGOMERY, J.L. Region 5, Office of Director. 1p. 33010:299-33010:299.
- 8510150086** Forwards current physical security plan & new emergency plan procedure covering events listed on Page 14 of plan, per recent physical security insp W/o encl.
WILSON, W.E. Washington State Univ., Pullman, WA. 85/08/05. SCHUSTER, M.D. Region 5, Office of Director. 1p. 33010:300-33010:300.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION**F. Security, medical, emergency & fire protection plans**

- 8510150111** Advises that 850730 Rev 11 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
MARTIN, T.T. Region 1, Office of Director. 85/09/25. HEIDER, L.H. Yankee Atomic Electric Co. 3pp. 33015:095-33015:097.
- 8510030073** Forwards addl info in response to 850731 concerns & Rev 12 to security plan. Encls withheld (ref 10CFR2.793).
PAPANIC, G. Yankee Atomic Electric Co. 85/10/01. MURLEY, T.E. Region 1, Office of Director. 1p. 32843:189-32843:189.
- 8510280175** Forwards responses to interim evaluation rept Section 4 open items re conformance to Reg Guide 1.97 Reg guide guidance superseded by 10CFR50.49. Environ qualification rept contains identified equipment.
PAPANIC, G. Yankee Atomic Electric Co. 85/10/22. ZWOLINSKI, J.A. Operating Reactors Branch 5. 6pp. 33191:087-33191:092.

P. Operating license stage documents & correspondence

- 8510030033** Forwards results of revised assessment of impact of diesel generator bldg heating steam line break on ability to safely shut down; revising 840305 & 850314 submittals.
PAPANIC, G. Yankee Atomic Electric Co. 85/09/26. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32843:077-32843:078.
- 8510070309** Application for amend to License DPR-3, changing Tech Spec 2.2.1 & Tables 2.2.1.3.3.2 & 3.3-3 to increase required setpoint for main steam line isolation trip from 200 psig to 262.5 psig. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/09/30. Office of Nuclear Reactor Regulation, Director. 3pp. 32880:348-32880:354.
- 8510070315** Proposed changes to Tech Spec 2.2.1 & Tables 2.2.1.3.3.2 & 3.3-3, increasing required setpoint for main steam line isolation trip from 200 psig to 262.5 psig.
Yankee Atomic Electric Co. 85/09/30. 4pp. 32880:351-32880:354.
- 8510070430** Application for amend to License DPR-3, revising Tech Specs re radiological environ monitoring. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/09/30. Office of Nuclear Reactor Regulation, Director. 4pp. 32877:129-32877:136.
- 8510070433** Proposed Tech Specs re radiological environ monitoring.
Yankee Atomic Electric Co. 85/09/30. 4pp. 32877:133-32877:136.

8510040260 Forwards Amend 84 to License DPR-3 & safety evaluation. Amend revises Tech Specs for capacity of pressurizer code safety valves & snubbers & adds Tech Specs for degraded grid voltage protection sys & RCS vents.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. PAPANIC, G. Yankee Atomic Electric Co. 4pp. 32851:079-32851:097.

-8510040265 Amend 84 to License DPR-3, revising Tech Specs for capacity of pressurizer code safety valves & snubbers & adds Tech Specs for degraded grid voltage protection sys & RCS vents.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. 12pp. 32851:083-32851:094.

-8510040270 Safety evaluation supporting Amend 84 to License DPR-3.
Office of Nuclear Reactor Regulation, Director. 85/10/01. 3pp. 32851:095-32851:097.

8510080380 Advises of completion of evaluation of consequences of small burnup increase during Cycle 17 operation beyond 15,000 MWD/MTU. Operation can continue until 851019 scheduled shutdown.
HEIDER, L.H. Yankee Atomic Electric Co. 85/10/02. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32919:304-32919:305.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510150333 Forwards safety evaluation supporting util responses to Generic Ltr 83-28, Items 4.2.1 & 4.2.2 re preventive maint program for reactor trip breakers/maint & trending.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/10. PAPANIC, G. Yankee Atomic Electric Co. 2pp. 33013:006-33013:010.

-8510150339 Safety evaluation supporting util responses to Generic Ltr 83-28, Items 4.2.1 & 4.2.2 re reactor trip sys reliability.
Office of Nuclear Reactor Regulation, Director. 85/10/10. 3pp. 33013:008-33013:010.

1510150403 Advises that operation of facility to core burnup of 15,200 MWD/MTU, as indicated in util 851002 ltr, acceptable. Operation at less than 70% power level places facility in compliance w/action statement w/o reaching action level.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/11. PAPANIC, G. Yankee Atomic Electric Co. 2pp. 33000:360-33000:361.

8510210093 Application for amend to License DPR-3, changing Tech Specs re containment pressure monitor, containment water level monitor & instrumentation for detection of inadequate core cooling (ref NUREG-0737, Items II.F.1 & II.F.2). Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 4pp. 33072:142-33072:153.

-8510210099 Proposed Tech Spec changes, revising Table 3.3-4, "Radiation Monitoring Instrumentation," Table 4.3-3, "Radiation Monitoring Instrumentation Surveillance Requirements," & Tech Spec 3.3.3.2, "Instrumentation-In-Core Detection Sys."
Yankee Atomic Electric Co. 85/10/15. 8pp. 33072:146-33072:153.

8510210119 Application for amend to License DPR-3, revising Tech Specs to accommodate mods to RCS vent sys valve power supplies. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 3pp. 33073:303-33073:307.

-8510210120 Proposed Tech Specs, reflecting mods to RCS vent sys valve power supplies.
Yankee Atomic Electric Co. 85/10/15. 2pp. 33073:306-33073:307.

851022002 Application for amend to License DPR-3, adding two containment isolation valves to Table 3.6-1 for compliance w/Tech Spec 3/4.6.2 which requires Type C tests for valves. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 2pp. 33090:262-33090:264.

-8510220027 Proposed Tech Spec Table 3.6-1, adding two containment isolation valves for compliance w/Tech Spec 3/4.6.2 which requires Type C tests for valves.
Yankee Atomic Electric Co. 85/10/15. 1p. 33090:264-33090:264.

8510220140 Requests exemption from requirements of 10CFR50.62 re reduction of risk from ATWS events for light-water-cooled nuclear power plants, per Generic Ltr 85-06, due to small size & remote siting of plant. ATWS risk summary encl. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. 85/10/15. THOMPSON, H.L. Division of Licensing. 11pp. 33090:130-33090:140.

8510220055 Application for amend to License DPR-3, modifying Tech Spec Table 4.3-2, "Engineered Sys Instrumentation Surveillance Requirements," to require monthly test of new second level degraded grid voltage protection for each bus. Fee paid.
HUNTER, D. Yankee Atomic Electric Co. 85/10/16. Office of Nuclear Reactor Regulation, Director. 3pp. 33081:298-33081:302.

-8510220059 Proposed Tech Spec Table 4.3-2, "Engineered Sys Instrumentation Surveillance Requirements," requiring monthly functional test of new second level degraded grid voltage protection for each 480-volt emergency bus.
Yankee Atomic Electric Co. 85/10/16. 2pp. 33081:301-33081:302.

8510290554 Summary of 850808 meeting w/util in Bethesda, MD re proposed revs to ECCS codes & input to assure compliance w/10CFR50.46. Agenda & viewgraphs encl.
CLIFFORD, J.W. Operating Reactors Branch 5. 85/10/22. Operating Reactors Branch 5. 98pp. 33254:113-33254:211.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAME, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

12 DOCKETED ITEMS

8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1, 1. "Post-Trip Review-Program Description & Procedure" for Bellefonte Nuclear Plant. Science Applications International Corp. (formerly Science Applications, Inc.) NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510310207 Forwards "Tornado Cost-Benefit Analysis for Proposed Backfits of Yankee Nuclear Power Station," per 851021 request for addl info re SEP Topics II-2 & III-4.A. HASELTINE, J.D. Yankee Atomic Electric Co. 85/10/24. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 33271-014-33271-179.

8510310215 "Tornado Cost-Benefit Analysis for Proposed Backfits of Yankee Nuclear Power Station." SCHULTZ, S.P., SLIFER, B.C. Yankee Atomic Electric Co. 84/09/30. 164pp. 33271-016-33271-179.

8510310485 Forwards notice of consideration of issuance of amend to License DPR-3 & proposed NSHC & opportunity for hearing, per 851016 request for amend re degraded grid voltage surveillance. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/25. PAPANIC, G. Yankee Atomic Electric Co. 3pp. 33278-318-33278-326.

8510310493 Notice of consideration of issuance of amend to License DPR-3 & proposed NSHC determination & opportunity for hearing on 851016 request re testing second level undervoltage protection on monthly basis. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/25. 6pp. 33278-321-33278-326.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/05/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510040163 Forwards Safety Insp Rept 50-029/85-16 on 850812-16. No violations noted. MARTIN, T.T. Region 1, Office of Director. 85/09/30. HEIDER, L.H. Yankee Atomic Electric Co. 2pp. 32851-147-32851-157.

8510040172 Insp Rept 50-029/85-16 on 850812-16. No noncompliance noted. Major areas inspected: radiation protection program, including respiratory protection, spent resin shipment, ALARA & radiation protection procedures upgrade project. DRAGUNT, T., MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/09/25. 9pp. 32851-149-32851-157.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasitic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010649 Monthly operating rept for Jul 1985 W/850802 ltr. WHIPPLE, S., HEIDER, L.H. Yankee Atomic Electric Co. 85/07/31. 6pp. 32820-187-32820-192.

S. Reportable occurrences, LERs & related correspondence

8510070370 Special report: 850722, fire detection sys & Halon automatic suppression for Battery Rooms 1 & 2 taken out of svc to facilitate const of new battery room roof. Detection & Halon sys should be operable by 850913. ST. LAURENT, N.N. Yankee Atomic Electric Co. 85/09/04. MURLEY, T.E. Region 1, Office of Director. 2pp. 32883-296-32883-297.

8510020274 PNO-I-85-071A on 850927, Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage. STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825-232-32825-232.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510280061 Forwards operator licensing exam schedule for FY86-89, in response to 850927 Generic Ltr 85-18. PAPANIC, G. Yankee Atomic Electric Co. 85/10/22. BOGER, B. NRC - No Detailed Affiliation Given. 3pp. 33191-012-33191-014.

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

H. General correspondence

8510230017 Advises that, effective 851015, NASA initiated listed organizational changes per description in 850726 application for reinstatement of Licenses TR-3 & R-93 to possess-but-not-operate. RICHLEY, E.A. National Aeronautics & Space Admin. 85/10/10. Office of Nuclear Reactor Regulation, Director. 2pp. 33101-038-33101-039.

DOCKET 50-54 CINTICHEM RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250090 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended. HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Cintichem, Inc. (subs. of Medi-Physics, Inc.). 3pp. 33226-092-33226-094.

Q. Inspection reports, IE Bulletins & correspondence

8510280299 Forwards Safety Insp Repts 50-054/85-04 & 70-0687/85-07 on 850819-23 & notice of violation. MARTIN, T.T. Region 1, Office of Director. 85/10/22. MCGOVERN, J.J. Cintichem, Inc. (subs. of Medi-Physics, Inc.). 2pp. 33192-027-33192-041.

8510280302 Notice of violation from insp on 850819-23. * NRC - No Detailed Affiliation Given. 85/10/22. 2pp. 33192-029-33192-030.

8510280305 Insp Repts 50-054/85-04 & 70-0687/85-07 on 850819-23. Violations noted: high radiation areas not posted as required & entry to hazardous areas generated by waste drums not restricted. WEADOCK, A., MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/10/21. 11pp. 33192-041-33192-041.

DOCKET 50-57 BUFFALO MATERIALS RESEARCH CENTER

Q. Inspection reports, IE Bulletins & correspondence

8510250062 Forwards Exam Rept 50-057/85-03 conducted during wk of 850902. WENZINGER, E.C. Region 1, Office of Director. 85/10/17. RENNIE, D.W. New York State Univ. of Buffalo, NY. 2pp. 33171-001-33171-052.

8510250078 Exam Rept 50-057/85-03 on 850904-05. Exam results: one reactor operator candidate failed written exam & one license issued. Some ref matl provided for preparation of exam found outdated. DUDLEY, N.F., KELLER, R.M., KISTER, H.B. Region 1, Office of Director. 85/10/08. 50pp. 33171-003-33171-052.

V. Operator Examinations

8510250062 Forwards Exam Rept 50-057/85-03 conducted during wk of 850902. WENZINGER, E.C. Region 1, Office of Director. 85/10/17. RENNIE, D.W. New York State Univ. of Buffalo, NY. 2pp. 33171-001-33171-052.

8510250078 Exam Rept 50-057/85-03 on 850904-05. Exam results: one reactor operator candidate failed written exam & one license issued. Some ref matl provided for preparation of exam found outdated. DUDLEY, N.F., KELLER, R.M., KISTER, H.B. Region 1, Office of Director. 85/10/08. 50pp. 33171-003-33171-052.

DOCKET 50-59 TEXAS A&M UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510150005 Forwards chronology of Commission approved physical security plan for Texas A&M Univ. AGN-201M reactor facility. THOMAS, C.O. Standardization & Special Projects Branch. 85/10/08. RICHARDSON, H.H. Texas A&M Univ., College Station, TX. 4pp. 33031-182-33031-185.

H. General correspondence

8510310435 Requests that univ president & nuclear engineering dept head be included in distribution list. Author should also be included in future correspondence. RICHARDSON, H.H. Texas A&M Univ., College Station, TX. 85/10/22. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 33280-274-33280-275.

DOCKET 50-62 UNIV. OF VIRGINIA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510110187 Forwards Rev 1 to emergency plan & emergency plan implementing procedures, including EPIP-1 re emergency director controlling procedure & EPIP-6 re notification of emergency response personnel & support organizations. MULDER, R.U. Virginia, Univ. of, Charlottesville, VA. 85/10/04. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 32971:314-32971:352.

-8510110190 Rev 1 to emergency plan for Univ. of Virginia.
* Virginia, Univ. of, Charlottesville, VA. 85/09/30. 18pp. 32971:315-32971:332.

-8510110194 Emergency plan implementing procedures, including EPIP-1 re emergency director controlling procedure & EPIP-6 re notification of emergency response personnel & support organizations.
* Virginia, Univ. of, Charlottesville, VA. 85/09/30. 21pp. 32971:333-32971:352.

P. Operating license stage documents & correspondence

8510250138 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Virginia, Univ. of, Charlottesville, VA. 3pp. 33226:053-33226:055.

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

P. Operating license stage documents & correspondence

8510070270 Forwards modified Tech Specs re storage & disposal of liquid effluents & elimination of area radiation monitors for shutdown of test reactor facility info suppls 850626 submittal of license renewal info.
CUNNINGHAM, G.E. General Electric Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32877:315-32877:322.

-8510070272 Proposed modified Tech Specs re storage & disposal of liquid effluents & elimination of radiation monitors for shutdown of test reactor facility.
* General Electric Co. 85/09/30. 6pp. 32877:317-32877:322.

Q. Inspection reports, IE Bulletins & correspondence

8510170354 Forwards Insp Repts 50-070/85-01 & 50-073/85-02 on 850812-15 & notice of violation.
SCARANO, R.A. Region 5, Office of Director. 85/10/01. DARMITZEL, R.W. General Electric Co. 2pp. 33064:177-33064:191.

-8510170355 Notice of violation from insp on 850812-15.
SCARANO, R.A. Region 5, Office of Director. 85/10/01. 1p. 33064:179-33064:179.

-8510170358 Insp Repts 50-070/85-01 & 50-073/85-02 on 850812-15. Violation noted: failure to conspicuously post radiation area. Unresolved item involving nuclear test reactor licensed operator activities identified.
CILLIS, M. YUHAS, G.P. Region 5, Office of Director. 85/10/01. 12pp. 33064:180-33064:191.

8510150379 Forwards corrected Page 2 to Insp Repts 50-070/85-01 & 50-073/85-02 per 851007 telcon re presence of second individual at facility whenever licensed operator w/medical restrictions is performing licensed activities.
SCARANO, R.A. NRC - No Detailed Affiliation Given. 85/10/08. DARMITZEL, R.W. General Electric Co. 1p. 33010:177-33010:177.

-8510150382 Corrected Page 2 to Insp Repts 50-070/85-01 & 50-073/85-02.
* NRC - No Detailed Affiliation Given. 85/10/08. 1p. 33010:178-33010:178.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P. Operating license stage documents & correspondence

8510250017 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. General Electric Co. 3pp. 33226:217-33226:219.

8510300003 Application for amend to License R-33, changing Tech Specs to clarify staffing requirements when reactor control room manned by operator w/no solo medical restriction. Fee paid.
CUNNINGHAM, G.E. General Electric Co. 85/10/24. BERNARD, H. Standardization & Special Projects Branch. 2pp. 33247:001-33247:003.

-8510300006 Proposed Tech Spec changes clarifying staffing requirements when reactor control room manned by operator w/no solo medical restriction.
* General Electric Co. 85/10/24. 1p. 33247:003-33247:003.

Q. Inspection reports, IE Bulletins & correspondence

8510170354 Forwards Insp Repts 50-070/85-01 & 50-073/85-02 on 850812-15 & notice of violation.
SCARANO, R.A. Region 5, Office of Director. 85/10/01. DARMITZEL, R.W. General Electric Co. 2pp. 33064:177-33064:191.

-8510170355 Notice of violation from insp on 850812-15.
SCARANO, R.A. Region 5, Office of Director. 85/10/01. 1p. 33064:179-33064:179.

-8510170358 Insp Repts 50-070/85-01 & 50-073/85-02 on 850812-15. Violation noted: failure to conspicuously post radiation area. Unresolved item involving nuclear test reactor licensed operator activities identified.
CILLIS, M. YUHAS, G.P. Region 5, Office of Director. 85/10/01. 12pp. 33064:180-33064:191.

8510150379 Forwards corrected Page 2 to Insp Repts 50-070/85-01 & 50-073/85-02 per 851007 telcon re presence of second individual at facility whenever licensed operator w/medical restrictions is performing licensed activities.
SCARANO, R.A. NRC - No Detailed Affiliation Given. 85/10/08. DARMITZEL, R.W. General Electric Co. 1p. 33010:177-33010:177.

-8510150382 Corrected Page 2 to Insp Repts 50-070/85-01 & 50-073/85-02.
* NRC - No Detailed Affiliation Given. 85/10/08. 1p. 33010:178-33010:178.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510240501 Confirms 851001 telcon clarifying transfer of up to 701 g U-235, enriched to 20% UO₂ & embedded in polyethylene, to DOE facilities.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/21. JORDAN, E.D. Catholic Univ. of America, Washington, DC. 3pp. 33182:155-33182:157.

8510280476 Application for amend to License R-31, authorizing possession only status. Approval of request will assure protective storage of reactor & reactor fuel while plans for decommissioning facility finalized.
MURPHY, J.J. Catholic Univ. of America, Washington, DC. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33197:021-33197:051.

-8510280478 Proposed Tech Spec changes, authorizing possession only status.
* Catholic Univ. of America, Washington, DC. 85/10/22. 28pp. 33197:023-33197:051.

DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

F. Security, medical, emergency & fire protection plans

8510080043 Advises that 850606 Rev 6 to physical security plan consistent w/provisions of 10CFR50.54 & acceptable.
WALKER, R.D. Region 2, Office of Director. 85/10/03. DIAZ, N.J. Florida, Univ. of, Gainesville, FL. 2pp. 32922:116-32922:117.

P. Operating license stage documents & correspondence

8510250160 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Florida, Univ. of, Gainesville, FL. 3pp. 33226:038-33226:040.

8510300070 Application for amend to License R-56, changing typo noted in Amend 15.
VERNETSON, W.G. Florida, Univ. of, Gainesville, FL. 85/10/17. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 33256:223-33256:225.

-8510300076 Proposed Tech Specs, correcting typo noted in Amend 15.
* Florida, Univ. of, Gainesville, FL. 85/10/17. 1p. 33256:225-33256:225.

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

8510250155 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Westinghouse Electric Corp. 3pp. 33226:041-33226:043.

V. Operator Examinations

8510240647 Informs that NRC cannot support 851007 request for instructor certification exams at present time. Applicants allowed to instruct until NRC has adequate resources to administer exams listed.
REYES, L.A. Region 3, Office of Director. 85/10/18. SCHOLAND, G.W. Westinghouse Electric Corp. 1p. 33157:219-33157:219.

DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

F. Security, medical, emergency & fire protection plans

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation. Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER, E.C. Region 1, Office of Director. 85/09/18. STREETT, W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted: licensed operator requalification testing not given on annual basis. Unresolved items noted involved annual emergency drill & operations audit.
MEYER, G.W. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

Q. Inspection reports, IE Bulletins & correspondence

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation. Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER, E.C. Region 1, Office of Director. 85/09/18. STREETT, W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230210 Notice of violation from insp on 850422-24.
* Region 1, Office of Director. 85/09/18. 1p. 33101:155-33101:155.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted: licensed operator requalification testing not given on annual basis. Unresolved items noted involved annual emergency drill & operations audit.
MEYER, G.W., MCCABE, E.C. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

14 DOCKETED ITEMS

V. Operator Examinations

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation. Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER, E.C. Region 1, Office of Director. 85/09/18. STREETT, W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted. Licensed operator requalification testing not given on annual basis. Unresolved items noted involved annual emergency drill & operations audit.
MEYER, G.W., MCCABE, E.C. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

DOCKET 50-116 IOWA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510280075 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Iowa State Univ., Ames, IA. 3pp. 33241:119-33241:121.

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR

H. General correspondence

8510010069 Forwards documents re renewal of Univ of Missouri (Rolla) facility, including 850114 license, SER, environ assessment, 850416 amend extending license expiration date & Univ of Missouri (Columbia) license & SER w/o encls.
THOMAS, C.O. Standardization & Special Projects Branch. 85/09/25. DREY, L. Affiliation Not Assigned. 3pp. 32833:157-32833:159.

P. Operating license stage documents & correspondence

8510250091 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Missouri, Univ. of, Rolla, MO. 3pp. 33226:084-33226:086.

DOCKET 50-124 VIRGINIA POLYTECHNIC INSTITUTE TRAINING REACTOR

P. Operating license stage documents & correspondence

8510250143 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Virginia Polytechnic Institute & State Univ., Blacksburg, VA. 3pp. 33226:050-33226:052.

8510280150 Responds to ltr re removal of unirradiated highly enriched U fuel to secure facility. Fuel will be shipped by Proto-Power Bisco to DOE. No fuel will remain at facility by 860101.
FURRAK, Virginia Polytechnic Institute & State Univ., Blacksburg, VA. 85/10/08.
HOYLE, J.C. Office of the Secretary of the Commission. 2pp. 33228:312-33228:313.

DOCKET 50-126 TEXAS A&M UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510150005 Forwards chronology of Commission approved physical security plan for Texas A&M Univ AGN-201M reactor facility.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/08.
RICHARDSON, H.H. Texas A&M Univ., College Station, TX. 4pp. 33031:182-33031:185.

H. General correspondence

8510310435 Requests that univ president & nuclear engineering dept head be included in distribution list. Author should also be included in future correspondence.
RICHARDSON, H.H. Texas A&M Univ., College Station, TX. 85/10/22. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 33280:274-33280:275.

P. Operating license stage documents & correspondence

8510250098 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Texas A&M Univ., College Station, TX. 3pp. 33226:089-33226:091.

S. Reportable occurrences, LERs & related correspondence

8510080058 RO-85-04 on 850912, transient rod followed cylinder cut during positioning of transient rod cylinder. Air solenoid for transient rod sys not functioning as designed. Air solenoid disassembled, cleaned & reassembled.
ANDERSON, D.G. Texas A&M Univ., College Station, TX. 85/09/24. JOHNSON, E. Region 4, Office of Director. 2pp. 32928:258-32928:259.

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8510280400 Forwards Rev 1 to custodial SAFSTOR physical security plan. Rev withheld (ref 10CFR73.21).
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/22. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33192:189-33192:189.

G. Adjudicatory correspondence

8510160282 Provides 15th quarterly status rept in response to ASLB 620216 memorandum & order. Related correspondence.
LOCKER, R.F. Pacific Gas & Electric Co. #485 784. 85/10/07. LAZO, R.M., SCHINK, D.R., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 2pp. 33023:348-33023:349.

8510160287 Motion to terminate proceeding re withdrawal of application for license amend. Submission of decommissioning plan renders amend application & any issue concerning contested application moot. Certificate of Svc encl.
YOUNG, M.A. Hearing Branch 4. #485 776. 85/10/11. Atomic Safety and Licensing Board Panel. 18pp. 33026:231-33026:248.

P. Operating license stage documents & correspondence

8510030271 Forwards 820204 ltr re need for review of proposed bldg, plant staff review committee 821101 minutes, Operating Instruction F-5, "Solid Radwaste Facilities" & Radiation Control Procedure 6.1, per 850906 telcon request. W/o encl.
WEEKS, E.D. Pacific Gas & Electric Co. 85/09/17. YUHAS, G. Region 5, Office of Director. 1p. 32845:247-32845:247.

8510160043 Discusses investigation of shipment of solidified/encapsulated filters for which notification of receipt not received within 20 days after transfer. Caused by personnel change at burial site & change of broker address.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/01. MARTIN, J.B. Region 5, Office of Director. 1p. 33023:357-33023:357.

8510230135 Forwards four State of CA documents supporting util SAFSTOR decommissioning environ plan.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/07. ZWOLINSKI, J.A. Operating Reactors Branch 5. 54pp. 33102:037-33102:090.

Q. Inspection reports, IE Bulletins & correspondence

8510150461 Forwards Insp Rept 50-133/85-04 on 850826-30 & 0918-22. No violations noted.
WENSLAWSKI, F.A. Region 5, Office of Director. 85/09/27. SHIFFER, J.D. Pacific Gas & Electric Co. 1p. 33015:153-33015:166.

-8510150465 Insp Rept 50-133/85-04 on 850826-30 & 0918-22. No violations or deviations noted. Major areas inspected: processing, solidification & classification of radwaste & transportation activities associated w/decommissioning process.
SHERMAN, C.I., YUHAS, G.P. Region 5, Office of Director. 85/09/24. 13pp. 33015:154-33015:166.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010414 Monthly operating rept for Jul 1985. W/850807 ltr.
KWOK, C.C., WEEKS, E.D. Pacific Gas & Electric Co. 85/07/31. 5pp. 32809:055-32809:060.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-134 WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR**P. Operating license stage documents & correspondence**

8510250070 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Worcester Polytechnic Institute, Worcester, MA. 3pp. 33223:338-33223:340.

8510230152 Responds to 850927 ltr to show cause. Std 10 plate element used as spare & other three elements used sporadically in critical experiments constitute irradiated fuel.
WILBUR, L.C. Worcester Polytechnic Institute, Worcester, MA. 85/10/04. Office of the Secretary of the Commission. 3pp. 33108:024-33108:026.

DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR**F. Security, medical, emergency & fire protection plans**

8510080459 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in insp on 850717-19.
SCARANO, R.A. Region 5, Office of Director. 85/10/04. BOWEN, J.R. Washington, Univ. of, Seattle, WA. 1p. 32921:357-32921:358.

-8510080461 Responds to NRC 850904 ltr re violations noted in insp on 850717-19. Corrective actions: evacuation drills will be held annually & written operator exams will be held during Last Quarter 1985.
BOWEN, J.R. Washington, Univ. of, Seattle, WA. 85/09/26. SCARANO, R.A. Region 5, Office of Director. 1p. 32921:358-32921:358.

P. Operating license stage documents & correspondence

8510250127 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Washington, Univ. of, Seattle, WA. 3pp. 33226:059-33226:061.

8510250582 Ack receipt of show cause order to dispose of highly enriched U fuel. Requests extension beyond 120 days, until DOE Richland Operations Ofc can assume possession.
ROBKIN, M.A. Washington, Univ. of, Seattle, WA. 85/10/14. HOYLE, J.C. Office of the Secretary of the Commission. 3pp. 33226:290-33226:292.

Q. Inspection reports, IE Bulletins & correspondence

8510080459 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in insp on 850717-19.
SCARANO, R.A. Region 5, Office of Director. 85/10/04. BOWEN, J.R. Washington, Univ. of, Seattle, WA. 1p. 32921:357-32921:358.

-8510080461 Responds to NRC 850904 ltr re violations noted in insp on 850717-19. Corrective actions: evacuation drills will be held annually & written operator exams will be held during Last Quarter 1985.
BOWEN, J.R. Washington, Univ. of, Seattle, WA. 85/09/26. SCARANO, R.A. Region 5, Office of Director. 1p. 32921:358-32921:358.

V. Operator Examinations

8510080459 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in insp on 850717-19.
SCARANO, R.A. Region 5, Office of Director. 85/10/04. BOWEN, J.R. Washington, Univ. of, Seattle, WA. 1p. 32921:357-32921:358.

-8510080461 Responds to NRC 850904 ltr re violations noted in insp on 850717-19. Corrective actions: evacuation drills will be held annually & written operator exams will be held during Last Quarter 1985.
BOWEN, J.R. Washington, Univ. of, Seattle, WA. 85/09/26. SCARANO, R.A. Region 5, Office of Director. 1p. 32921:358-32921:358.

DOCKET 50-142 UCLA TRAINING REACTOR**F. Security, medical, emergency & fire protection plans**

8510020197 Forwards suppl to 850830 application for amend to License R-71, consisting of Proposed Amend 14 of Tech Specs, eliminating all authorization to possess SNM & need for physical security plan attendant.
WEGST, W.F. California, Univ. of, Los Angeles, CA. 85/09/25. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 32827:196-32827:201.

-8510020201 Suppl to 850830 application for amend to License R-71, consisting of Proposed Amend 14 of Tech Specs, eliminating all authorization to possess SNM & need for physical security plan attendant.
* California, Univ. of, Los Angeles, CA. 85/09/25. 5pp. 32827:197-32827:201.

G. Adjudicatory correspondence

8510150308 Forwards signed stipulation & proposed ASLB order that parties agreed to as settlement of issues re pending license renewal proceedings. Approval of stipulation, issuance of order & termination of proceeding requested W/o encl.
WOODHEAD, C.P. Hearing Branch 4. #485 766. 85/10/10. FRYE, J.H., BRIGHT, G.O., LUEBKE, E.A. Atomic Safety and Licensing Board Panel. 2pp. 33009:087-33009:088.

8510180247 Memorandum & order requesting parties to respond by 851030 to listed questions re 851010 settlement agreement & proposed order terminating proceeding. Served on 851017.
BRIGHT, G.O., LUEBKE, E.A., FRYE, J.H. Atomic Safety and Licensing Board Panel. #485 821. 85/10/16. Office of the Executive Legal Director. 3pp. 33061:128-33061:130.

8510290007 Forwards UCLA 851008 ltr describing dismantlement plan for research reactor on campus. Relate 1 correspondence.
WOODHEAD, C.P. Hearing Branch 4. #485 938. 85/10/23. FRYE, J.H., LUEBKE, E.A., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 33233:282-33233:291.

8510310298 Forwards direct response to Board 851016 order for review, per request. Notification of receipt requested prior to 851030. W/o encl. Related correspondence.
WOODHEAD, C.P. Hearing Branch 4. #485 976. 85/10/25. CORMIER, W.H. California, Univ. of, Los Angeles, CA. HIRSCH, D. Affiliation Not Assigned. 1p. 33273:005-33273:005.

P. Operating license stage documents & correspondence

8510020197 Forwards suppl to 850830 application for amend to License R-71, consisting of Proposed Amend 14 of Tech Specs, eliminating all authorization to possess SNM & need for physical security plan attendant.
WEGST, W.F. California, Univ. of, Los Angeles, CA. 85/09/25. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 32827:196-32827:201.

-8510020201 Suppl to 850830 application for amend to License R-71, consisting of Proposed Amend 14 of Tech Specs, eliminating all authorization to possess SNM & need for physical security plan attendant.
* California, Univ. of, Los Angeles, CA. 85/09/25. 5pp. 32827:197-32827:201.

8510150219 Advises that dismantling & decommissioning of reactor will be done in-house rather than by outside contractor, per review on informal bids. Detailed analysis of radiological status, dismantling plans & organizational charts encl.
WEGST, W.F. California, Univ. of, Los Angeles, CA. 85/10/08. DENTON, H. Office of Nuclear Reactor Regulation, Director. 9pp. 33015:048-33015:056.

DOCKET 50-143 UNIV. OF KANSAS RESEARCH REACTOR**P. Operating license stage documents & correspondence**

8510250084 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Kansas, Univ. of, Lawrence, KS. 3pp. 33226:098-33226:100.

8510280192 Responds to 850927 order to show cause re removal of unirradiated high enriched U fuel rods. B Evans of DOE contacted to facilitate removal of all fuel prior to deadline. Procedures re shipment of fuel requested.
BEARSE, R.C. Kansas, Univ. of, Lawrence, KS. 85/10/04. HOYLE, J.C. Office of the Secretary of the Commission. 2pp. 33228:246-33228:247.

DOCKET 50-150 OHIO STATE UNIV. RESEARCH REACTOR**F. Security, medical, emergency & fire protection plans**

8510280181 Forwards Safety Insp Rept 50-150/85-01 on 850826-28 & notices of violation & deviation.
NORELIUS, C.E. Region 3, Office of Director. 85/09/18. REDMOND, R.F. Ohio State Univ., Columbus, OH. 2pp. 33191:159-33191:160.

-8510280195 Insp Rept 50-150/85-01 on 850826-28. Violation & deviation noted: failure to calibrate radiation instruments at required frequency & failure to follow Procedure IM-05, "Use of RY-4 Jumper," respectively.
RIDGWAY, K.R., SCHWEIBINZ, E.R. Region 3, Office of Director. 85/09/13. 9pp. 33191:162-33191:172.

P. Operating license stage documents & correspondence

8510250150 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Ohio State Univ., Columbus, OH. 3pp. 33226:044-33226:046.

Q. Inspection reports, IE Bulletins & correspondence

8510280181 Forwards Safety Insp Rept 50-150/85-01 on 850826-28 & notices of violation & deviation.
NORELIUS, C.E. Region 3, Office of Director. 85/09/18. REDMOND, R.F. Ohio State Univ., Columbus, OH. 2pp. 33191:159-33191:160.

-8510280187 Notice of violation from insp on 850826-28.
NORELIUS, C.E. Region 3, Office of Director. 85/09/18. 1p. 33191:161-33191:161.

-8510280191 Notice of deviation from insp on 850826-28.
* Region 3, Office of Director. 85/09/18. 1p. 33191:162-33191:162.

-8510280195 Insp Rept 50-150/85-01 on 850826-28. Violation & deviation noted: failure to calibrate radiation instruments at required frequency & failure to follow Procedure IM-05, "Use of RY-4 Jumper," respectively.
RIDGWAY, K.R., SCHWEIBINZ, E.R. Region 3, Office of Director. 85/09/13. 9pp. 33191:162-33191:172.

8510280253 Responds to NRC 850918 ltr re violations noted in safety insp rept. Corrective actions: requirements for calibr of exit radiation survey instrument & pocket dosimeters & list of items requiring notification will be distributed.
REDMOND, R.F. Ohio State Univ., Columbus, OH. 85/10/01. NORELIUS, C.E. Region 3, Office of Director. 2pp. 33191:202-33191:203.

16 DOCKETED ITEMS

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8510040177 Forwards application for amend to License DPR-6, revising Tech Specs by adding operability & surveillance requirements for alternate shutdown sys installed in accordance w/ 10CFR50, App R. Fee paid.
BERRY, K.W. Consumers Power Co. 85/09/30. Office of Nuclear Reactor Regulation, Director. 1p. 32850.273-32850.296.

-8510040181 Application for amend to License DPR-6, adding operability & surveillance requirements for components of alternate shutdown sys installed in accordance w/ 10CFR50, App R.
DEWITT, R.B. Consumers Power Co. 85/09/30. 8pp. 32850.274-32850.282.

-8510040187 Proposed Tech Spec changes, adding operability & surveillance requirements for components of alternate shutdown sys installed in accordance w/ 10CFR50, App R.
* Consumers Power Co. 85/09/30. 13pp. 32850.283-32850.296.

8510080046 Rev 68 to Site Emergency Plan Implementing Procedure 6F, "Emergency Notifications."
* Consumers Power Co. 85/09/30. 14pp. 32922.125-32922.138.

8510080263 Forwards FEMA 850909 Itr & evaluation of 850521 offsite emergency preparedness exercise. No deficiencies affecting public health & safety identified.
SHAFFER, W.D. Region 3, Office of Director. 85/10/02. DEWITT, R.B. Consumers Power Co. 2pp. 32913.226-32913.273.

8510250206 Lists determinations based on review of util 850218 Itr containing positions on use of armed responder for compensatory duties. Although members of response force may have other duties, primary duty must be response.
AXELSON, W.L. Region 3, Office of Director. 85/10/11. BERRY, K.W. Consumers Power Co. 2pp. 32190.261-32190.262.

8510230184 Requests addl clarification indicating how emergency operation facility staff will take over command & responsibility for making protective action recommendations within approx 1.5 h after declaration of site emergency.
SHAFFER, W.D. Region 3, Office of Director. 85/10/18. DEWITT, R.B. Consumers Power Co. 2pp. 33101.133-33101.134.

8510300015 Rev: 79 to Vol 9 of site emergency plan.
* Consumers Power Co. 85/10/21. 75pp. 33247.062-33247.137.

J. Insurance & indemnity information

8510080556 Forwards Endorsement 107 to NELIA Policy NF-117.
FROUNFELKER, R. Consumers Power Co. 85/09/24. SALTZMAN, J. Office of Nuclear Reactor Regulation, Director. 2pp. 32922.325-32922.326.

P. Operating license stage documents & correspondence

8510010319 Forwards revised application for amend to License DPR-6, changing 11 fuel MAPLHGR limits, per 850816 request, in order to implement reactor operating limits for Reload 11 fuel. Fee paid.
BERRY, K.W. Consumers Power Co. 85/09/24. Office of Nuclear Reactor Regulation, Director. 1p. 32801.004-32801.012.

-8510010329 Revised application for amend to License DPR-6, changing 11 fuel MAPLHGR limits, per 850816 request, in order to implement operating limits for Reload 11 fuel.
DEWITT, R.B. Consumers Power Co. 85/09/24. 5pp. 32801.005-32801.009.

-8510010338 Proposed Tech Specs, revising fuel MAPLHGR limits, per 850816 request, in order to implement operating limits for Reload 11 fuel.
* Consumers Power Co. 85/09/24. 3pp. 32801.010-32801.012.

8510020253 Forwards notice of consideration of issuance of amend to License DPR-6 & proposed NSHC determination & opportunity for hearing re 850816 & 0924 requests concerning reactor core Reload 11 fuel design.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/09/26. BERRY, K.W. Consumers Power Co. 2pp. 32824.095-32824.103.

-8510020256 Notice of consideration of amend to License DPR-6 & proposed NSHC determination & opportunity for hearing re 850816 & 0924 requests concerning reactor core Reload 11 fuel design.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/09/26. 7pp. 32824.097-32824.103.

8510040177 Forwards application for amend to License DPR-6, revising Tech Specs by adding operability & surveillance requirements for alternate shutdown sys installed in accordance w/ 10CFR50, App R. Fee paid.
BERRY, K.W. Consumers Power Co. 85/09/30. Office of Nuclear Reactor Regulation, Director. 1p. 32850.273-32850.296.

-8510040181 Application for amend to License DPR-6, adding operability & surveillance requirements for components of alternate shutdown sys installed in accordance w/ 10CFR50, App R.
DEWITT, R.B. Consumers Power Co. 85/09/30. 8pp. 32850.274-32850.282.

-8510040187 Proposed Tech Spec changes, adding operability & surveillance requirements for components of alternate shutdown sys installed in accordance w/ 10CFR50, App R.
* Consumers Power Co. 85/09/30. 13pp. 32850.283-32850.296.

8510040274 Forwards Amend 78 to License DPR-6 & safety evaluation. Amend modifies Tech Specs by implementing definition of operability & incorporating limiting conditions for operation for redundant safety sys.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/02. VANDEWALLE, D.J. Consumers Power Co. 2pp. 32851.163-32851.180.

-8510040277 Amend 78 to License DPR-6, modifying Tech Specs by implementing definition of operability & incorporating limiting conditions for operation for redundant safety sys.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/02. 12pp. 32851.185-32851.178.

-8510040279 Safety evaluation supporting Amend 78 to License DPR-6.
* Office of Nuclear Reactor Regulation, Director. 85/10/02. 4pp. 32851.177-32851.180.

8510150298 Requests withdrawal of portions of 841101 application to amend License DPR-6, revising Tech Specs re calibr of portable high-range gamma measuring instruments. Revised Tech Spec pages encl.
FRISCH, R.R. Consumers Power Co. 85/10/09. Office of Nuclear Reactor Regulation, Director. 2pp. 33009.094-33009.095.

-8510150303 Proposed Tech Specs, revising calibr of portable gamma & neutron dose-rate measuring instruments.
* Consumers Power Co. 85/10/09. 2pp. 33009.096-33009.097.

8510160296 Notifies that 850702 request for exemption from 10CFR50.72 & 50.73 reporting requirements re manual & automatic actuations of reactor protective sys denied. NRC in process of re-evaluating similar requests.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/11. VANDEWALLE, D.J. Consumers Power Co. 5pp. 33026.292-33026.296.

8510180380 Responds to request for proposed implementation schedule for 10CFR50.62 requirements for reduction of risk from ATWS. Exemption from 10CFR50.62(c)(5) requested due to limited benefits of automatic recirculating pump trip.
FRISCH, R.R. Consumers Power Co. 85/10/14. Office of Nuclear Reactor Regulation, Director. 3pp. 33059.359-33059.361.

8510220256 Withdraws 741101 & 850903 Tech Spec change requests to eliminate min control rod withdrawal rate limit.
FRISCH, R.R. Consumers Power Co. 85/10/18. Office of Nuclear Reactor Regulation, Director. 1p. 33087.001-33087.001.

8510290145 Forwards Rev 4 to CPC-2A, "QA Program Description for Operational Nuclear Power Plants," due to organizational changes.
BERRY, K.W. Consumers Power Co. 85/10/18. KEPLER, J.G. Region 3, Office of Director. 1p. 33233.001-33233.126.

-8510290152 Rev 4 to "QA Program Description for Operational Nuclear Power Plants."
* Consumers Power Co. 85/10/18. 115pp. 33233.002-33233.126.

8510290360 Forwards Amend 79 to License DPR-6 & safety evaluation. Amend changes several Tech Spec surveillance frequencies to provide for operation between refueling shutdowns w/o potential surveillance test performance interruptions.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/22. BERRY, K.W. Consumers Power Co. 3pp. 33258.257-33258.281.

-8510290365 Amend 79 to License DPR-6, re changes to several Tech Spec surveillance frequencies to provide for operation between refueling shutdowns w/o potential surveillance test performance interruptions.
* Operating Reactors Branch 5. 85/10/22. 19pp. 33258.260-33258.266.

-8510290370 Safety evaluation supporting Amend 79 to License DPR-6.
* Office of Nuclear Reactor Regulation, Director. 85/10/22. 3pp. 33258.267-33258.281.

Q. Inspection reports, IE Bulletins & correspondence

8510210079 Revises response to violations noted in Insp Rept 50-155/85-03. Change to radiation safety plan surveillance program does not change commitment, per conversation w/ P Lovendale.
JOHNSON, B.D. Consumers Power Co. 85/09/23. KEPLER, J.G. Region 3, Office of Director. 2pp. 33073.289-33073.290.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160031 Forwards Safety Insp Rept 50-155/85-17 on 850909-12. No noncompliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/10/08. DEWITT, R.B. Consumers Power Co. 2pp. 33024.153-33024.161.

-8510160038 Insp Rept 50-155/85-17 on 850909-12. No noncompliance or deviations noted. Major areas inspected: confirmatory measurements program, QC of analytical measurements & licensee actions on previously identified findings.
JANUSKA, A.G., ROZAK, S., SCHUMACHER, M.C. Region 3, Office of Director. 85/10/07. 7pp. 33024.155-33024.161.

8510160264 Requests Itr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023.351-33023.354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/ Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510290051 Forwards Safety Insp Rept 50-155/85-18 on 850909-10,25-26 & 1009-10.No violations noted.
HARRISON,J.J. Region 3, Office of Director. 85/10/24. DEWITT,R.B. Consumers Power Co. 2pp. 33236:136-33236:142.

-8510290066 Insp Rept 50-155/85-18 on 850909-10,25-26 & 1009-10.No violation or deviation noted.Major areas inspected:inservice insp work activities,including Generic Ltr 84-11 insp.
WARD,K.D., DANIELSON,D.H. Region 3, Office of Director. 85/10/24. 5pp. 33236:138-33236:142.

R. Periodic operating reports & related correspondence

8510010491 Monthly operating rept for Jul.W/850802 ltr.
DUGAN,J.S., HOFFMAN,D.P. Consumers Power Co. 85/07/31. 7pp. 32820:171-32820:177.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250120 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Wisconsin, Univ. of, Madison, WI. 3pp. 33226:062-33226:064.

8510250290 Responds to 850927 order to show cause re return of high enriched U.Extension of 120-day limit requested,based on listed reasons,including need for order clarifying which mats require removal to secure facility.
CASHWELL,R.J. Wisconsin, Univ. of, Madison, WI. 85/10/10. Office of the Secretary of the Commission. 3pp. 33226:164-33226:166.

8510250577 Ack receipt of 850927 show cause order to dispose of highly enriched U fuel.Requests extension beyond 120 days to permit shipment of matl to designated receiver.
CASHWELL,R.J. Wisconsin, Univ. of, Madison, WI. 85/10/10. Office of the Secretary of the Commission. 3pp. 33226:313-33226:315.

R. Periodic operating reports & related correspondence

8510290401 Forwards matl balance repts & physical inventory listings for Types E2,E3,E4,50 & 81 for period ending on 850930.
CASHWELL,R.J. Wisconsin, Univ. of, Madison, WI. 85/10/21. Record Services Branch (Document Control Desk). 11pp. 33242:349-33242:359.

DOCKET 50-157 CORNELL UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation.Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER,E.C. Region 1, Office of Director. 85/09/18. STREETT,W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted:licensed operator requalification testing not given on annual basis.Unresolved items noted involved annual emergency drill & operations audit.
MEYER,G.W. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

Q. Inspection reports, IE Bulletins & correspondence

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation.Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER,E.C. Region 1, Office of Director. 85/09/18. STREETT,W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230210 Notice of violation from insp on 850422-24.
* Region 1, Office of Director. 85/09/18. 1p. 33101:155-33101:155.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted:licensed operator requalification testing not given on annual basis.Unresolved items noted involved annual emergency drill & operations audit.
MEYER,G.W., MCCABE,E.C. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

V. Operator Examinations

8510230190 Forwards Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24 & notice of violation.Response to violation should also address corrective actions associated w/emergency drill & operations audit.
WENZINGER,E.C. Region 1, Office of Director. 85/09/18. STREETT,W.B. Cornell Univ., Ithaca, NY. 2pp. 33101:153-33101:163.

-8510230210 Notice of violation from insp on 850422-24.
* Region 1, Office of Director. 85/09/18. 1p. 33101:155-33101:155.

-8510230213 Safety Insp Repts 50-097/85-01 & 50-157/85-01 on 850422-24. Violation noted:licensed operator requalification testing not given on annual basis.Unresolved items noted involved annual emergency drill & operations audit.
MEYER,G.W. Region 1, Office of Director. 85/09/18. 8pp. 33101:156-33101:163.

DOCKET 50-160 GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250013 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Georgia Institute of Technology, Atlanta, GA. 3pp. 33226:241-33226:243.

Q. Inspection reports, IE Bulletins & correspondence

8510180208 Ack receipt of 850909 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-160/85-02.Addl corrective actions include interviewing licensed operators to ensure compliance w/procedures.
WALKER,R.D. Region 2, Office of Director. 85/10/07. KARAM,R.A. Georgia Institute of Technology, Atlanta, GA. 2pp. 33062:275-33062:276.

V. Operator Examinations

8510180208 Ack receipt of 850909 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-160/85-02.Addl corrective actions include interviewing licensed operators to ensure compliance w/procedures.
WALKER,R.D. Region 2, Office of Director. 85/10/07. KARAM,R.A. Georgia Institute of Technology, Atlanta, GA. 2pp. 33062:275-33062:276.

DOCKET 50-163 GA TECHNOLOGIES

P. Operating license stage documents & correspondence

8510010632 Revised application for amend to License R-67,amending Tech Spec 10.2.6(f)(2) to clarify justification & discussion in 850826 application,authorizing routine calibr or maint of radiation monitors during extended operations.
ASMUSSEN,K.E. GA Technologies, Inc./General Atomic Co. 85/09/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32830:048-32830:051.

8510250022 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. GA Technologies, Inc./General Atomic Co. 3pp. 33226:204-33226:206.

8510210181 Forwards Amend 35 to License R-67 & safety evaluation.Amend authorizes substitution of temporary radiation detectors & temporary bypass of certain radiation detector scram functions during calibr & maint on permanent detectors.
THOMAS,C.O. Standardization & Special Projects Branch. 85/10/17. ASMUSSEN,K.E. GA Technologies, Inc./General Atomic Co. 3pp. 33094:167-33094:177.

-8510210183 Amend 35 to License R-67,authorizing substitution of temporary radiation detectors & temporary bypass of certain radiation detector scram functions during calibr & maint on permanent detectors.
THOMAS,C.O. Standardization & Special Projects Branch. 85/10/17. 6pp. 33094:170-33094:175.

-8510210187 Safety evaluation supporting Amend 35 to License R-67.
* Office of Nuclear Reactor Regulation, Director. 85/10/17. 2pp. 33094:176-33094:177.

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250297 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Purdue Univ., West Lafayette, IN. 3pp. 33226:155-33226:157.

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

P. Operating license stage documents & correspondence

8510250009 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Commerce, Dept. of, National Bureau of Standards. 3pp. 33226:253-33226:255.

Q. Inspection reports, IE Bulletins & correspondence

8510080602 Forwards Safety Insp Rept 50-184/85-03 on 850905-06.No violations noted.
WENZINGER,E.C. Region 1, Office of Director. 85/09/25. CARTER,R.S. Commerce, Dept. of, National Bureau of Standards. 2pp. 32927:110-32927:117.

18 DOCKETED ITEMS

-8510080604 Insp Rept 50-184/85-03 on 850905-06 No violations or deviations noted. Major areas inspected: licensee organization, logs & records, reviews & audits, equipment condition, experiments & surveillance activities. TRIMBLE, D.C., MCCABE, E.C. Region 1, Office of Director. 85/09/18. 6pp. 32927:112-32927:117.

DOCKET 50-185 PLUM BROOK REACTOR - MOCK-UP

H. General correspondence

8510230017 Advises that effective 851015, NASA initiated listed organizational changes per description in 850726 application for reinstatement of Licenses TR-3 & R-93 to possess-but-not-operate. RICHLEY, E.A. National Aeronautics & Space Admin. 85/10/10. Office of Nuclear Reactor Regulation, Director. 2pp. 33101:038-33101:039.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510070022 Approves encl modified route from Columbia, MO to Idaho Falls, ID through Omaha, NE per 850910 request. MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/09/30. HULTSCH, R.A. Missouri, Univ. of, Columbia, MO. 11pp. 32901:069-32901:079.

P. Operating license stage documents & correspondence

8510250096 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended. HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Missouri, Univ. of, Columbia, MO. 3pp. 33226:068-33226:070.

8510280091 Consents to 850927 show cause order re allowance of inventory of fuel sufficient for maint of reactor operations. Quantity of fuel will stay within limits set forth in License R-103. BRUGGER, R.M. Missouri, Univ. of, Columbia, MO. 85/10/10. Office of the Secretary of the Commission. 3pp. 33240:359-33240:361.

DOCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

P. Periodic operating reports & related correspondence

8510170386 Annual rept of changes in facility, procedures & experiments, Oct 1984 - Sept 1985. FAW, R.E. Kansas State Univ., Manhattan, KS. 85/10/07. THOMAS, C.O. Standardization & Special Projects Branch. 3pp. 33053:351-33053:353.

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS A

P. Operating license stage documents & correspondence

8510250074 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended. HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Rhode Island, State of. 3pp. 33223:336-33223:337.

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250012 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended. HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Manhattan College, Riverdale, NY. 3pp. 33226:244-33226:246.

R. Periodic operating reports & related correspondence

8510170383 "Facility Operations Rept, Sept 1984 - Aug 1985." W/851010 ltr. BERLIN, R.E. Manhattan College, Riverdale, NY. 85/08/31. 5pp. 33053:284-33053:288.

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510290306 "San Onofre Generating Station Unit 1 Annual Emergency Exercise." * Southern California Edison Co. 85/08/07. 375pp. 33231:024-33232:101.

8510070179 Forwards revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements." Procedure S023-VIII-28.2 should be deleted. ZINTL, W.G. Southern California Edison Co. 85/09/27. MARTIN, J.B. Region 5, Office of Director. 2pp. 32881:084-32881:119.

-8510070185 Revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements" & Temporary Change TCN 3-1 to Rev 3 to S0123-VIII-70.1, "Site Telephone." BENNETT, D.D., HOWELL, T.G., WHARTON, M.A. Southern California Edison Co. 85/09/27. 32pp. 32881:086-32881:119.

8510100092 Requests extension until 851004 to submit info on App R, Section III.G compliance plans & response to Generic Ltr 81-12, per 850919 commitment re fire protection program review. MEDFORD, M.O. Southern California Edison Co. 85/09/30. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 32960:123-32960:123.

8510090007 Forwards "Southern California Edison, Generic Ltr 81-12 Response," "Design Description for Dedicated Safe Shutdown Sys." "Southern California, 10CFR50 App R Exemption Requests" & "San Onofre, Evaluation..." MEDFORD, M.O. Southern California Edison Co. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32943:250-32946:001.

-8510090011 Rev 0 to "Southern California Edison San Onofre Nuclear Generating Station Unit 1 Generic Ltr 81-12 Response." * Southern California Edison Co. 85/09/30. 200pp. 32943:252-32944:049.

-8510090016 "Design Description for Dedicated Safe Shutdown Sys." * Southern California Edison Co. 85/09/30. 30pp. 32944:050-32944:079.

-8510090025 Rev 0 to "Southern California Edison San Onofre Nuclear Generating Station, Unit 1 10CFR50 App R Exemption Requests." * Southern California Edison Co. 85/09/30. 32pp. 32944:080-32944:111.

-8510090033 Rev 0 to "San Onofre Nuclear Generating Station Unit 1 10CFR50 App R, Section III.G Compliance Evaluation." * Impell Corp. 01-0310-1435 R00. 85/09/30. 600pp. 32944:112-32946:025.

8510180493 Expresses appreciation for coordinating 850924 site visit & 850925 emergency operations facility tour. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/15. BASKIN, K.P. Southern California Edison Co. 2pp. 33077:335-33077:336.

8510220174 Forwards Rev 1 to "Progress on Selected Regulatory Projects, San Onofre Unit 1," covering long-term seismic upgrading, fire protection & Suppl 1 to NUREG-0737, per 850919 ltr. MEDFORD, M.O. Southern California Edison Co. 85/10/18. ZWOLINSKI, J.A. Operating Reactors Branch 5. 3pp. 33090:060-33090:062.

8510310277 Revised emergency plan implementing procedures, including Rev 2 to S0123-VIII-0.301, "Offsite/Onsite Communications Test" & Temporary Change Notice 1-3 to Rev 1 to S0123-VIII-0.202, "Assignment of Emergency Response Personnel." W/851025 ltr. ZINTL, W.G. Southern California Edison Co. 85/10/25. MARTIN, J.B. Region 5, Office of Director. 93pp. 33272:161-33272:250.

8510310285 Advises that 850620 & 1023 Revs 5 & 5A to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. Figure 5-1 & const security procedures to be submitted as Rev 5B will be reviewed upon receipt, per 851024 telcon. SCHUSTER, M.D. Region 5, Office of Director. 85/10/29. MORGAN, H.E. Southern California Edison Co. 4pp. 33273:267-33273:271.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510170048 Final response to FOIA request for documents re restart of facility. Forwards App K documents. Documents also available in PDR Apps L & M documents completely or partially withheld (ref FOIA Exemptions 5, 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/26. BELL, N. Nuclear Information & Resource Service. 14pp. 33049:219-33050:027.

-8510170067 Advises that ACRS comments re adequacy of facility seismic design features require more than single meeting & later deadline due to change in approach from context of SEP review to restart decision. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 84/11/14. PALLADINO, N.J. Commissioners. 1p. 33049:238-33049:238.

P. Operating license stage documents & correspondence

8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDR App E documents withheld (ref FOIA Exemptions 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833:002-32833:052.

8510100036 Forwards application & affidavit for withholding proprietary info in Franklin Research Ctr technical evaluation rept concerning SEP Topic III-6, "Seismic Design Considerations," from public disclosure (ref 10CFR2.790). MEDFORD, M.O. Southern California Edison Co. 85/09/20. ZWOLINSKI, J.A. Operating Reactors Branch 5. 5pp. 32960:236-32960:240.

8510160174 Further response to FOIA request for 12 categories of documents re plant. Forwards App E documents. App F documents available in PDR Apps G & H documents withheld (ref FOIA Exemptions 7 & 5). FELTON, J.M. Division of Rules and Records. 85/09/26. ZAELE, D. Sierra Club. 6pp. 33042:331-33042:357.

-8510160183 Proposes course of action re legal & policy considerations concerning util proposal to restart facility, per General Counsel 841105 memo. Decision should be made promptly. ROBERTS, Commissioners. 84/11/08. PALLADINO, ASSELSTINE, BERNTHAL, Commissioners. 2pp. 33042:345-33042:346.

-8510160187 Forwards Asselstine dissenting views on order denying Sierra Club request for hearing & stay of NRC decision re facility, for inclusion w/order prior to issuance. DAVIS, P. Commissioners. 85/02/12. BATES, A. Office of the Secretary of the Commission. 10pp. 33042:347-33042:356.

-8510160193 Affirmation response sheet disapproving SECY-85-39, "Proposed Response to Sierra Club Request for Hearing & Request for Stay" re San Onofre Unit 1. Dissenting views encl. W/o encl. ASSELSTINE, Commissioners. 85/02/12. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33042:357-33042:357.

8510170048 Final response to FOIA request for documents re restart of facility Forwards App K documents. Documents also available in PDR Apps L & M documents completely or partially withheld (ref FOIA Exemptions 5, 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/26. 9ELL, N. Nuclear Information & Resource Service. 14pp. 33049:219-33050:027.

-8510170062 Forwards draft Commission paper re facility restart, including more extensive discussion of procedural issues involved than presented in SECY-84-360, Miller & Chevalier memo & State of CA PUC 840502 interim opinion. W/o encls. CUNNINGHAM, G.H. Office of the Executive Legal Director. 84/10/04. REAMER, W., GUTCHIN, J., DAVIS, P. NRC - No Detailed Affiliation Given. 1p. 33049:237-33049:237.

-8510170070 Advises that Ofc of Investigation inquiry Q5-83-006 closed administratively & changed to Case 5-83-003 on 830927 per BB Hayes direction. Investigation assigned to PV Joukoff. SHACKLETON, O.C. Office of Investigation. 83/09/28. Office of Investigation. 1p. 33049:239-33049:239.

-8510170073 Forwards memo re 830317 discussion of facility. HAYES, B.B. Office of Investigation. 83/04/28. CASE, E.G., KNIGHT, J.P., MIRAGLIA, F. Office of Nuclear Reactor Regulation, Director. 1p. 33049:240-33049:240.

-8510170077 Notices of 830317 meeting at NRR to discuss requested investigation of facility. Meeting attendees listed. JOUKOFF, P. Office of Investigation. 83/04/06. Office of Investigation. 2pp. 33049:241-33049:242.

-8510170060 "Licensing Activities Schedule for Restart of San Onofre Nuclear Generating Station Unit 1." Viewgraphs re status of facility as of 841029 encl. * NRC - No Detailed Affiliation Given. 85/09/26. 11pp. 33049:243-33049:291.

-8510170086 Advises that Commissioners Roberts & Zech do not believe ACRS technical review required prior to restart decision. No comments offered by Commissioner Bernthal. Comments encl. W/o encl. CHILK, S.J. Office of the Secretary of the Commission. 84/11/16. PALLADINO Commissioners. 1p. 33049:292-33049:292.

-8510170093 Forwards Commissioner responses to 841107 memo re restart of facility. Meeting will be held on 841119 to discuss legal & policy issues re facility operation. CHILK, S.J. Office of the Secretary of the Commission. 84/11/15. PALLADINO Commissioners. 1p. 33049:293-33049:294.

-8510170097 Interim decision, concluding that util achieved understanding with NRC re scope & methods of making mods required by NRC for initial restart of facility cost effective. CARLOS, M. California, State of. 84/05/02. 39pp. 33049:295-33050:027.

8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Theien, Marrin, Johnson & Bridges. 2pp. 33049:042-33049:234.

8510100104 Forwards addl response to NRC 831219 request for addl info re performance testing of relief & safety valves per NUREG-0737, Item II.D.1. Pressurizer safety valve discharge piping & valve actuation time history analysis encl. MEDFORD, M.O. Southern California Edison Co. 85/10/01. ZWOLINSKI, J.A. Operating Reactors Branch 5. 8pp. 32955:092-32957:237.

8510100024 Forwards description of actions, schedule & commitments for plant mods resulting from SEP open issues. Rev to Table 4.1 of draft integrated plant safety assessment rept (NUREG-0829) also encl. MEDFORD, M.O. Southern California Edison Co. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 22pp. 32959:178-32959:199.

8510100034 Forwards "Surveillance Guidelines for San Onofre Nuclear Generating Station Unit 1 Intake Structure," per recipient 850424 request. MEDFORD, M.O. Southern California Edison Co. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 32959:160-32959:177.

-8510100040 "Surveillance Guidelines for San Onofre Nuclear Generating Station: Unit 1 Intake Structure." * Bechtel Corp. 85/09/30. 17pp. 32959:161-32959:177.

8510100083 Withdraws request as part of Proposed Change 149 to License DPR-13, removing Valves CV-948 & 949 from Tech Spec Table 3.6.2-1, "Remote Manual (RM) or Automatic Containment Isolation Valve Summary." Revised table encl. MEDFORD, M.O. Southern California Edison Co. 85/10/07. Office of Nuclear Reactor Regulation, Director. 2pp. 32961:112-32961:113.

8510100124 Submits plans & schedule for providing info on NUREG-0737, Item II.F.2 re inadequate core cooling instrumentation, per 821210 request. Evaluation of instrumentation capabilities will be submitted by 860301. MEDFORD, M.O. Southern California Edison Co. 85/10/08. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32960:351-32960:352.

8510160046 Responds to Generic Ltr 85-12, "Automatic Trip of Reactor Coolant Pumps," to extent possible w/o delaying response to Generic Ltr 83-10d. "Evaluation of Reactor Coolant Pump Restart..." encl. Addl info to be submitted by 851202. MEDFORD, M.O. Southern California Edison Co. 85/10/10. ZWOLINSKI, J.A. Operating Reactors Branch 5. 4pp. 33024:171-33024:317.

-8510160054 "Evaluation of Reactor Coolant Pump Restart Criteria for San Onofre Unit 1." * HOLDERBAUM, D.F. Westinghouse Electric Corp. 85/08/31. 150pp. 33024:175-33024:317.

8510170179 Submits proposed schedule & plans for compliance w/10CFR50.62 re reduction of risk from ATWS, per Generic Ltr 85-06 concerning QA guidance for nonsafety-related equipment. MEDFORD, M.O. Southern California Edison Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 2pp. 33036:229-33036:230.

8510180315 Forwards Amend 91 to License DPR-13 & safety evaluation. Amend approves Tech Spec revs re administrative controls, including reporting requirements, min shift crew composition & offsite organization. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/15. BASKIN, K.P. Southern California Edison Co. 4pp. 33060:270-33060:350.

-8510180318 Amend 91 to License DPR-13, approving Tech Spec revs re administrative controls, including reporting requirements, min shift crew composition & offsite organization. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/15. 60pp. 33060:274-33060:333.

-8510180323 Safety evaluation supporting Amend 91 to License DPR-13. * Office of Nuclear Reactor Regulation, Director. 85/10/15. 17pp. 33060:334-33060:350.

8510210024 Informs of plans to submit proposed Tech Spec change to require operation of all reactor coolant pumps in Mode 3 w/reactor trip breakers closed. MEDFORD, M.O. Southern California Edison Co. 85/10/17. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33074:143-33074:143.

8510220174 Forwards Rev 1 to "Progress on Selected Regulatory Projects, San Onofre Unit 1," covering long-term seismic upgrading, fire protection & Suppl 1 to NUREG-0737, per 850919 ltr. MEDFORD, M.O. Southern California Edison Co. 85/10/18. ZWOLINSKI, J.A. Operating Reactors Branch 5. 3pp. 33090:060-33090:062.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5. ADENSAME, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review: Program Description & Procedure' for Bellefonte Nuclear Plant..." * Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510100080 Forwards application fee for NRR review of steam generator insp program, per 850911 request & 840620 rev to 10CFR170. MEDFORD, M.O. Southern California Edison Co. 85/10/04. DIGGS, R.M. License Fee Management Branch. 1p. 32961:061-32961:061.

8510240269 Forwards Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21 No violation noted. KIRSCH, D.F. Region 5, Office of Director. 85/10/04. BASKIN, K.P. Southern California Edison Co. 1p. 33159:060-33159:060.

-8510240281 Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21 No violation or deviation noted. Major areas inspected: QA program & licensee actions on previously identified items. NARBUT, P.P., JOHNSON, P.H. Region 5, Office of Director. 85/10/02. 5pp. 33159:061-33159:065.

8510150172 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations & discrepancies noted in Insp Rept 50-206/85-26. KIRSCH, D.F. Region 5, Office of Director. 85/10/07. BASKIN, K.P. Southern California Edison Co. 1p. 33010:285-33010:285.

-8510150177 Responds to NRC 850828 ltr re violations & discrepancies noted in Insp Rept 50-206/85-26. Corrective actions: corrective actions as result of pump testing recorded on required documentation. BASKIN, K.P. Southern California Edison Co. 85/09/27. MARTIN, J.B. Region 5, Office of Director. 12pp. 33010:286-33010:297.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510100641 Monthly operating rept for Jul 1985. W/850813 ltr. SIACOR, E.R., MORGAN, H.E. Southern California Edison Co. 85/07/31. 6pp. 32820:335-32820:340.

20 DOCKETED ITEMS

S. Reportable occurrences, LEP- & related correspondence

8510010270 PNO-V-85-0628: on 850919, reactor tripped due to failure of steam reheater dump valve to actuate resulting in main turbine overspeed. Caused by lack of lubricating oil in bearing pumps & failure of pressure switch & relay.
JOHNSON, P., HUEY, R. Region 5, Office of Director. 85/09/23. 1p. 32800:185-32800:185.

8510010628 LER 84-009-00 on 841205, load sequencer 31-day surveillance delinquent. Caused by personnel oversight. Personnel counseled & performance of Tech Spec required surveillances in specified manner reemphasized. W/850924 ltr.
MORGAN, H.E. Southern California Edison Co. 85/09/24. 2pp. 32830:046-32830:047.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965:021-32965:047.

8510080482 PNO-V-85-067: on 851002, earthquake of magnitude 5.0 on Richter scale occurred. Epicenter located approx 50 miles north of site. Event minor, not felt by site personnel & did not activate reactor instruments.
JOHNSON, P., HUEY, R. Region 5, Office of Director. 85/10/03. 1p. 32921:164-32921:164.

8510220152 Rev 1 to special rept on 850814, high-range west main steam line radiation monitor R-1258B failed low & removed from svc. Caused by ground loop &/or ac noise induced into coaxial detector input/output cables.
MORGAN, H.E. Southern California Edison Co. 85/10/15. MARTIN, J.B. Region 5, Office of Director. 2pp. 33082:250-33082:251.

8510290133 Special rept on 851007, during routine quarterly surveillance, plant vent stack wide-range gas monitor R-1254 failed. Connections resoldered on printed circuit cards. No addl corrective action planned.
MORGAN, H.E. Southern California Edison Co. 85/10/16. MARTIN, J.B. Region 5, Office of Director. 2pp. 33235:214-33235:215.

8510300224 LER 85-014-00 on 850919, reactor tripped in response to turbine trip. Turbine trip caused by too rapid rate of pressure increase in auxiliary transformer B. Nitrogen addition operations revised. W/851021 ltr.
MORGAN, H.E. Southern California Edison Co. 85/10/21. 7pp. 33257:282-33257:288.

V. Operator Examinations

8509240245 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

8510230131 Forwards addl info re App R review to clarify previous requests for exemptions from Sections III.G & III.O & to support encl request for exemption from Section III.G.2. W/11 oversize drawings. Fee paid.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. 85/09/16. THOMPSON, H.L. Division of Licensing. 125pp. 33102:260-33103:023.

8510030203 Forwards SER re integrated plant safety assessment rept Section 4.1.4(1), "Emergency Procedures - Flooding." Procedure should be revised to initiate flood protection actions at 19 ft instead of 21 ft.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/09/24. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 2pp. 32849:204-32849:205.

-8510030211 SER re integrated plant safety assessment rept Section 4.1.4(1), "Emergency Procedures - Flooding." Procedure should be revised to indicate flood protection actions at 19 ft instead of 21 ft.
* NRC - No Detailed Affiliation Given. 85/09/24. 79pp. 32849:206-32849:285.

8510150113 Advises that 850628 Rev 11 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
MARTIN, T.T. Region 1, Office of Director. 85/09/25. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 3pp. 33015:092-33015:094.

8510100004 Informs that application for amend to Tech Specs re post-accident sampling sys will not be submitted until 851030 due to delays in review process.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. 85/10/01. MURLEY, T.E. Region 1, Office of Director. 1p. 32960:361-32960:361.

8510150247 Revised emergency plan implementing procedures, including Rev 5 to EPIP 1.5-11, "Personnel Injuries" & Rev 7 to EPIP 1.5-22, "Manager of Radiological Consequence Assessment." W/851009 ltr.
* Connecticut Yankee Atomic Power Co. 85/10/09. 21pp. 33009:291-33009:311.

8510150284 Corporate organization for nuclear incidents procedures, including Rev 10 to CONI-4.02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines." W/851009 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Utilities. 85/10/09. 171pp. 33009:113-33009:285.

8510220190 Forwards Amend 69 to License DPR-61 & safety evaluation. Amend modifies Tech Spec by incorporating requirements which restrict vol of flammable liquids in control room to no greater than 1 pint.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/16. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 2pp. 33089:310-33089:318.

-8510220195 Amend 69 to License DPR-61, modifying Tech Spec by incorporating requirements which restrict vol of flammable liquids in control room to no greater than 1 pint.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/16. 5pp. 33089:312-33089:316.

-8510220206 Safety evaluation supporting Amend 69 to License DPR-61.
* Office of Nuclear Reactor Regulation, Director. 85/10/16. 2pp. 33089:317-33089:318.

8510280201 Informs that 850812 amend application denied since Northeast Utils did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

P. Operating license stage documents & correspondence

8510070190 Forwards "Final Rept, Connecticut Yankee Plant Design Change External Review Group," per Jan 1985 program plan re response to NRC order for mod of License DPR-61.
VANDENBURGH, D. Yankee Atomic Electric Co. HARRINGTON, W.D. Boston Edison Co. POINDEXTER, C.H. Baltimore Gas & Electric Co. 85/09/06. MURLEY, T.E. Region 1, Office of Director. 2pp. 32881:122-32881:132.

-8510070193 "Final Rept, Connecticut Yankee Plant Design Change External Review Group."
VANDENBURGH, D. Yankee Atomic Electric Co. HARRINGTON, W.D. Boston Edison Co. POINDEXTER, C.H. Baltimore Gas & Electric Co. 85/09/06. 10pp. 32881:123-32881:132.

8510020101 Notifies that use of "bleed & feed" unacceptable as method for mitigating consequences of DBAs & not permanent alternative to qualification of electrical equipment. Justification for continued operation required.
THOMPSON, H.L. Division of Licensing. 85/09/30. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 3pp. 32824:105-32824:107.

8510170098 Requests extension to 860104 for Haddam Neck re environ qualification of electrical equipment, per Generic Ltr 85-15, 10CFR50.49(g) & Integrated Safety Assessment Program. Further evaluation proposed for Millstone. Fee paid.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. PALLADINO, N.J. Commissioners. 61pp. 33036:118-33036:179.

8510030105 Denies 850913 application for exemptions from 10CFR50.71(e) for submittal of updated FSAR. Comprehensive exemption request must be submitted by 851011.
THOMPSON, H.L. Division of Licensing. 85/10/02. OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 32844:082-32844:084.

8510070379 Summary of 851002 meeting w/util re use of "feed & bleed" core cooling in lieu of qualifying equipment outside containment. Suppl to safety evaluation & Schwencer 770714 ltr forwarding Amend 16 to License DPR-61 encl.
AKSTULEWICZ, F. Operating Reactors Branch 5. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32877:161-32877:183.

-8510070391 Suppl to safety evaluation re licensee 730628 submittals on high energy line failures. Upon completion of scheduled mods, facility can withstand consequences of rupture in any high energy fluid piping outside containment.
* Atomic Energy Commission, Directorate of Licensing. 74/12/27. 7pp. 32877:166-32877:172.

-8510070400 Forwards Amend 16 to License DPR-61 & safety evaluation. Amend changes Tech Specs to incorporate augmented inservice insp for piping components outside containment to control effects of high energy pipe breaks. W/o amend.
SCHWENCER, A. Division of Reactor Licensing (NRR-1975 only). 77/07/14. SWITZER, D.C. Connecticut Yankee Atomic Power Co. 2pp. 32877:173-32877:183.

-8510070416 Safety evaluation supporting Amend 16 to License DPR-61.
* Division of Reactor Licensing (NRR-1975 only). 77/07/14. 4pp. 32877:175-32877:183.

8510080447 Forwards corrected Amend 68 to License DPR-61. Amend approves Tech Specs for radiological effluent monitoring to incorporate requirements of 10CFR50, App I & deletes ETS.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/04. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 3pp. 32921:359-32921:363.

-8510080449 Corrected Amend 68 to License DPR-61, approving Tech Specs for radiological effluent monitoring to incorporate requirements of 10CFR50, App I & deleting ETS.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/04. 2pp. 32921:362-32921:363.

85 0150346 Concur w/NRC that Generic Ltr 85-12 should not apply to Westinghouse reactors which do not utilize Westinghouse Owners Group small break LOCA analysis methodology. No further response forthcoming.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33000:350-33000:350.

8510220158 Submits ATWS rule schedule required by 10CFR50.62(d), per Generic Ltr 85-06. Facilities participating in NRC Integrated Safety Assessment Program. Justification for absence of schedules for Haddam Neck & Millstone Unit 1 provided.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/11. BUTCHER, E.J. Operating Reactors Branch 3. ZWOLINSKI, J.A. Operating Reactors Branch 5. 7pp. 33090:076-33090:082.

8510220186 Requests scheduler exemption to submit updated FSAR by 870331 for Millstone Unit 1 & by 870630 for Haddam Neck Plant (ref 10CFR50.71(e)). Complete adoption of format to Rev 3 to Reg Guide 1.70 not planned.
OPEKA,J.F. Connecticut Yankee Atomic Power Co. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/11. THOMPSON,H.L. Division of Licensing. 3pp. 33090:053-33090:055.

8510180104 Forwards Amend 70 to License DPR-61 & safety evaluation. Amend revises Tech Specs to update pressure/temp curves for hydrostatic & leak rate testing & for heatup & cooldown rates.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/16. OPEKA,J.F. Connecticut Yankee Atomic Power Co. 3pp. 33054:116-33054:131.

-8510180109 Amend 70 to License DPR-61, revising Tech Specs to update pressure/temp curves for hydrostatic & leak rate testing & for heatup & cooldown rates.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/16. 8pp. 33054:119-33054:126.

-8510180110 Safety evaluation supporting Amend 70 to License DPR-61.
* Office of Nuclear Reactor Regulation, Director. 85/10/16. 5pp. 33054:127-33054:131.

8510180365 Forwards safety evaluation re util 831108 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, "Post-Maint Testing (Reactor Trip Sys Components & All Other Safety-Related Components)." Response acceptable.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/16. OPEKA,J.F. Connecticut Yankee Atomic Power Co. 3pp. 33059:240-33059:244.

-8510180370 Se evaluation re util 831108 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, "Post-Maint Testing (Reactor Trip Sys Components & All Other Safety-Related Components)." Response acceptable.
* Office of Nuclear Reactor Regulation, Director. 85/10/16. 2pp. 33059:243-33059:244.

8510220190 Forwards Amend 69 to License DPR-61 & safety evaluation. Amend modifies Tech Spec by incorporating requirements which restrict vol of flammable liquids in control room to no greater than 1 pint.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/16. OPEKA,J.F. Connecticut Yankee Atomic Power Co. 2pp. 33089:310-33089:318.

-8510220195 Amend 69 to License DPR-61, modifying Tech Spec by incorporating requirements which restrict vol of flammable liquids in control room to no greater than 1 pint.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/16. 5pp. 33089:312-33089:316.

-8510220206 Safety evaluation supporting Amend 69 to License DPR-61.
* Office of Nuclear Reactor Regulation, Director. 85/10/16. 2pp. 33089:317-33089:318.

8510250101 Provides PVRC damping curve info to clarify proposed changes to criteria document for safety-related piping analyses under SEP Topic III-6, "Seismic Design Considerations."
OPEKA,J.F., SEARS,C.F. Connecticut Yankee Atomic Power Co. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 2pp. 33172:092-33172:093.

8510220138 Requests info to clarify role of feed & bleed core cooling method in primary design basis, including analysis of primary sys response for transients & accidents relying on feed & bleed as principal means of DHR.
THOMPSON,H.L. Division of Licensing. 85/10/17. OPEKA,J.F. Connecticut Yankee Atomic Power Co. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33082:096-33082:099.

8510280201 Informs that 850812 amend application denied since Northeast Util did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/21. OPEKA,J.F. Connecticut Yankee Atomic Power Co. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possibility: Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070379 Summary of 851002 meeting w/util re use of "feed & bleed" core cooling in lieu of qualifying equipment outside containment. Suppl to safety evaluation & Schwencer 770714 ltr forwarding Amend 16 to License DPR-61 encl.
AKSTULEWICZ,F. Operating Reactors Branch 5. 85/10/04. ZWOLINSKI,J.A. Operating Reactors Branch 5. 2pp. 32877:161-32877:183.

-8510070391 Suppl to safety evaluation re licensee 730628 submittals on high energy line failures. Upon completion of scheduled mods, facility can withstand consequences of rupture in any high energy fluid piping outside containment.
* Atomic Energy Commission, Directorate of Licensing. 74/12/27. 7pp. 32877:166-32877:172.

-8510070400 Forwards Amend 16 to License DPR-61 & safety evaluation. Amend changes Tech Specs to incorporate augmented inservice insp for piping components outside containment to control effects of high energy pipe breaks w/o amend.
SCHWENCER,A. Division of Reactor Licensing (NRR-1975 only). 77/07/14. SWITZER,D.C. Connecticut Yankee Atomic Power Co. 2pp. 32877:173-32877:183.

8510110025 Notification of 851020, 29 & 30 meetings w/util in Berlin, Waterford & East Hampton, CT to discuss & review plant mods in response to IE Bulletin 80-11 on masonry wall design.
AKSTULEWICZ,F. Operating Reactors Branch 5. 85/10/08. ZWOLINSKI,J.A. Operating Reactors Branch 5. 4pp. 32974:016-32974:019.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:001-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:069-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510280201 Informs that 850812 amend application denied since Northeast Util did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/21. OPEKA,J.F. Connecticut Yankee Atomic Power Co. 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

8510310164 Forwards Insp Rept 50-213/85-20 on 850918-23. Insp identified component malfunctions & design deficiencies in automatic auxiliary feedwater actuation sys. Mgt meeting scheduled on 851031 at Region 1 ofc.
STAROSTECKI,R. Region 1, Office of Director. 85/10/25. OPEKA,J.F. Connecticut Yankee Atomic Power Co. 2pp. 33273:226-33273:235.

-8510310167 Insp Rept 50-213/85-20 on 850918-23. Major areas inspected: circumstances & corrective actions re auxiliary feedwater actuation component failure. Mgt meeting scheduled to discuss corrective actions.
SWETLAND,P.D., MCCABE,E.C. Region 1, Office of Director. 85/10/24. 8pp. 33273:228-33273:235.

S. Reportable occurrences, LERs & related correspondence

8510010008 LER 85-023-00: on 850823, determined that fire protection valves FP-V-231 & 234 not properly tested. Caused by misinterpretation of Tech Spec requirements. Surveillance Procedure SUR 5.5-24 revised. W/850920 ltr.
BRANSFIELD,T.J., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/09/20. 3pp. 32809:052-32809:054.

8510090248 LER 85-008-02: on 850320, during test of fire protection sys, actuation of carbon dioxide sys failed to shut off containment cable vault exhaust fan. Caused by wiring error. Exhaust fan rewired. W/850924 ltr.
BRANSFIELD,T.J., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/09/24. 5pp. 32942:336-32942:340.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewpoints encl.
CRITCHFIELD,D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON,H.L. Division of Licensing. 27pp. 32965:021-32965:047.

8510170440 LER 85-024-00: on 850910, during performance of preventive maint procedure, one solenoid-operated valve in auxiliary feedwater sys failed to change state upon deenergization. Cycling initiated until valves replaced. W/851011 ltr.
EVOLA,J.H., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/10/10. 5pp. 33053:238-33053:242.

8510240462 LER 85-009-00: on 850910, one auxiliary feedwater solenoid-operated valve failed to change state upon deenergization. Caused by stuck valve NP-8320A-185E. Periodic cycling will be performed until problem resolved. W/851009 ltr.
EVOLA,J.H., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/10/10. 5pp. 33160:343-33160:347.

8510220043 LER 85-013-00: on 850916, licensee discovered rod misalignment power peaking penalty not imposed on fuel cycle design & safety analysis. Caused by inadequacy of design requirements. Allowable axial offset limit reduced. W/851015 ltr.
DRAGO,J.P., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/10/16. 4pp. 33095:291-33095:294.

8510240635 LER 85-025-00: on 850919, unplanned release of radwaste to environ detected. Caused by isolation valve left open through operator error & ambiguous valve tag numbers. Event reviewed w/operators & valves relabeled clearly. W/851018 ltr.
KASUGA,R.W., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/10/18. 5pp. 33157:254-33157:258.

8510300296 LER 84-017-01: on 841004, degradation of 15-conductor interconnection cable discovered. Caused by aging. Insp for similar problems in other equipment concluded problem isolated incident. Degraded equipment replaced. W/851022 ltr.
TYLINSKI,G.H., GRAVES,R.H. Connecticut Yankee Atomic Power Co. 85/10/22. 4pp. 33258:009-33258:012.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

22 DOCKETED ITEMS

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510160091 Forwards summary description of agreement reached & resulting changes in 850403 submittal of "Fire Hazards Analysis & App R Section III.G Safe Shutdown Evaluation." Info provides basis for NRC to complete SER.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/09. ZWOLINSKI,J. Operating Reactors Branch 5. 8pp. 33027-349-33027-356.

F. Security, medical, emergency & fire protection plans

8510180194 Rev 4 to Emergency Plan implementing Procedure EPIP-26, "Technical Support Ctr." W/851010 ltr.
LEAVITT,J.B., SMITH,W.J., BARTON,J.J. General Public Utilities Corp. - GPU Service Corp. 85/09/20. 17pp. 33062-258-33062-274.

8510080339 Forwards Safeguards Insp Rept 50-219/85-24 on 850722-26.No violation noted.
MARTIN,T.T. Region 1, Office of Director. 85/10/03. FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 32913-205-32913-213.

-8510080346 Physical Security Insp Rept 50-219/85-24 on 850722-26.No noncompliance noted.Major areas inspected:security plan & implementing procedures,mgmt effectiveness,testing & maint, keys & combinations,alarm stations & communications.
DUNLAP,J.M., KEIMIG,R.R. Region 1, Office of Director. 85/10/02. 7pp. 32913-207-32913-213.

8510170149 Forwards Safety Insp Rept 50-219/85-23 on 850701-0818 & notice of violation.
KISTER,H.B. Region 1, Office of Director. 85/10/07. FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33052-077-33052-098.

-8510170153 Insp Rept 50-219/85-23 on 850701-0818.Violations noted: improper closure of containment isolation valve & failure to follow procedures while inerting drywell.
BATEMAN,W.H., WECHSELBERGER, REYNOLDS,S.D. Region 1, Office of Director. 85/10/07. 18pp. 33052-081-33052-098.

8510160091 Forwards summary description of agreement reached & resulting changes in 850403 submittal of "Fire Hazards Analysis & App R Section III.G Safe Shutdown Evaluation." Info provides basis for NRC to complete SER.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/09. ZWOLINSKI,J. Operating Reactors Branch 5. 8pp. 33027-349-33027-356.

8510220421 Forwards SALP Rept 50-219/85-99 for May 1984 - June 1985. Meeting scheduled for 851028 to discuss assessment & plans for performance improvement.
MURLEY,T.E. Region 1, Office of Director. 85/10/11. FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33097-069-33097-131.

-8510220423 SALP Rept 50-219/85-99 for May 1984 - June 1985.
* Region 1, Office of Director. 85/10/11. 61pp. 33097-071-33097-131.

8510250161 Forwards Safety Insp Rept 50-219/85-26 on 850819-0922.No violation noted.
KISTER,H.B. Region 1, Office of Director. 85/10/16. FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33190-028-33190-041.

-8510250171 Insp Rept 50-219/85-26 on 850819-0922.No violation noted. Major areas inspected:plant operations,physical security, radiation control,housekeeping,chemistry.Part 21 repts & status of NUREG-0737 items.
BATEMAN,W.H., WECHSELBERGER, URBAN,R.J. Region 1, Office of Director. 85/10/16. 12pp. 33190-030-33190-041.

P. Operating license stage documents & correspondence

8510250220 Forwards description of proposed utilization of new ASME Code Case in piping criteria.Criteria technically justified & provide more realistic piping design considering thermal & seismic requirements.
WILSON,R.F. General Public Utilities Corp. - GPU Service Corp. 85/09/13. MURLEY,T.E. Region 1, Office of Director. 5pp. 33169-077-33169-081.

8510010209 Summarizes position re mods to containment vent & purge sys, per NUREG-0578 & NUREG-0737.Forwards Rev 1 to Technical Data Rept TDR 266, "Stress Analysis for Demonstration of Operability of Purge & Vent Valves During DBAs."
WILSON,R.F. General Public Utilities Corp. - GPU Service Corp. 85/09/24. ZWOLINSKI,J.A. Operating Reactors Branch 5. 6pp. 32800-249-32800-274.

-8510010214 Rev 1 to "Stress Analysis for Demonstration of Operability of Purge & Vent Valves During DBAs."
MANNING,T.G., SHEU,J., ROCHINO,A.P. General Public Utilities Corp. - GPU Service Corp. TDR 266 R01. 85/05/09. 20pp. 32800-255-32800-274.

8510020064 Notification of 851024 meeting w/utl & State of NJ in Trenton,NJ to discuss facility ETS,App B & to review status of licensing actions.
DONOHEW,J.N. Operating Reactors Branch 5. 85/09/27. ZWOLINSKI,J.A. Operating Reactors Branch 5. 3pp. 32824-112-32824-114.

8510070474 Application for amend to License DPR-16,consisting of Tech Spec Change Request 141, revising Table 4.1.1 to replace two sets of indicating pressure switches w/environmentally qualified nonindicating switches.Fee paid.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/09/30. Office of Nuclear Reactor Regulation, Director. 4pp. 32878-186-32878-193.

-8510070476 Proposed Tech Spec Change Request 141, revising Table 4.1.1 to delete requirement of daily channel check for low reactor water level & lo-lo water level instrument channels.
* General Public Utilities Corp. - GPU Service Corp. 85/09/30. 4pp. 32878-190-32878-193.

8510110066 Forwards Rev 1 to "GPU Nuclear Corp Operational QA Plan for TMI-1 & Oyster Creek." Exception to Reg Guide 1.37 re permissible particle sizes added for consistency w/requirements of ANSI N45.2.1-1980.
LONG,R.L. General Public Utilities Corp. - GPU Service Corp. 85/10/02. MURLEY,T.E. Region 1, Office of Director. 10pp. 32969-033-32969-042.

-8510110072 Rev 1 to 1000-PLN-7200.01, "GPU Nuclear Corp Operational QA Plan for TMI-1 & Oyster Creek."
KAZANAS,N.C., HUKILL,H.D., FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/07/19. 141pp. 32969-043-32969-199.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co,Inc in Bethesda,MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510110214 Forwards justification for continued operation,providing assurance that failure of existing temp elements will not jeopardize plant safety.Environ qualification program identified elements which have been added to master list.
WILSON,R.F. General Public Utilities Corp. - GPU Service Corp. 85/10/04. ZWOLINSKI,J. Operating Reactors Branch 5. 5pp. 32971-356-32971-360.

8510100143 Advises that NRC completed review of utl 841013 response to Generic Ltr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability." Response sufficient. Ltr closes out actions on Generic Ltr 84-15.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/07. FIEDLER,P.B. Gulf States Utilities Co. 2pp. 32961-205-32961-206.

8510160072 Forwards schedule for meeting requirements of 10CFR50.62(c)3 & (c)4 re reduction of risk from ATWS events for light water cooled nuclear power plants.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/09. DENTON,R.F. Office of Nuclear Reactor Regulation, Director. 3pp. 33028-013-33028-015.

8510180073 Application for amend to License DPR-16,consisting of Tech Spec Change Request 142,modifying reactor bldg isolation & gas treatment sys initiation to reflect lo-lo reactor water level not necessarily required.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/11. Office of Nuclear Reactor Regulation, Director. 7pp. 33054-085-33054-094.

-8510180077 Proposed Tech Spec Table 3.1.1,modifying reactor bldg isolation & gas treatment sys initiation to reflect lo-lo reactor water level not required when secondary containment not required.
* General Public Utilities Corp. - GPU Service Corp. 85/10/11. 3pp. 33054-092-33054-094.

8510230136 Forwards info re hydrogen water chemistry test.Test will be performed on three backshifts in Dec 1985 & will establish optimum hydrogen feed rate to achieve max IGSCC mitigation. Dose rate measurements on & offsite will be taken.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/16. ZWOLINSKI,J.A. Operating Reactors Branch 5. 2pp. 33102-034-33102-035.

8510240103 Revised application to amend License DPR-16,consisting of Change Request 142,modifying Tech Spec requirements for reactor water level monitoring to be applicable only for duration of Cycle 10M outage.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/18. Office of Nuclear Reactor Regulation, Director. 6pp. 33155-232-33155-239.

-8510240108 Proposed changes to Tech Specs,modifying requirements for reactor water level monitoring to be applicable only for duration of Cycle 10M outage.
* General Public Utilities Corp. - GPU Service Corp. 85/10/18. 1p. 33155-238-33155-238.

8510250045 Forwards Amend 90 to License DPR-16 & safety evaluation. Amend changes Tech Specs to revise inservice insp & testing requirements in Section 4.3, "Reactor Coolant."
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/18. FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 7pp. 33225-002-33225-022.

-8510250049 Amend 90 to License DPR-16,changing Tech Specs to revise inservice insp & testing requirement in Section 4.3, "Reactor Coolant."
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/18. 10pp. 33225-009-33225-018.

-8510250050 Safety evaluation supporting Amend 90 to License DPR-16.
* Office of Nuclear Reactor Regulation, Director. 85/10/18. 4pp. 33225-019-33225-022.

8510280126 Responds to NRC 850530 requests to include independent onsite safety review group & vice president of each nuclear div in inline LER review.Addl reviewers unnecessary.Review exceeds Generic Ltr 84-43 & Rev 3 to NUREG-0123.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/21. ZWOLINSKI,J.A. Operating Reactors Branch 5. 2pp. 33191-058-33191-059.

8510290252 Forwards Rev 16 to Procedure 116, "Surveillance Test Program," in response to SEP Integrated Plant Safety Assessment Rept (NUREG-0822),Section 4.26.2, "Instrumentation for Reactor Trip Testing."
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/22. ZWOLINSKI,J.A. Operating Reactors Branch 5. 1p. 33236-284-33236-335.

-8510290263 Rev 16 to Procedure 116, "Surveillance Test Program." W/ "Cross-Ref of Surveillance Procedures & Tech Specs."
BIDDLE,R.A., SMITH,W.J. General Public Utilities Corp. - GPU Service Corp. 85/10/03. 51pp. 33236-285-33236-335.

8510290321 Provides supplemental info to Tech Spec Change Request 142 confirming that listed requirements would be met during time period needed to install environmentally qualified level instrumentation & forwards Standing Order 38.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/22. Office of Nuclear Reactor Regulation, Director. 3pp. 33235-027-33235-039.

-8510290327 Rev 2 to Standing Order 38, "Reactor Low Level Alarm Response W/ Yawways Out of Svc."
* General Public Utilities Corp. - GPU Service Corp. 85/10/22. 10pp. 33235-030-33235-039.

8510290172 Informs that nuclear util task action committee vendor equipment technical info program will be implemented in response to Generic Ltr 83-28.Plans & schedules re vendor interface & equipment classification issues encl.
FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/23. ZWOLINSKI,J.A. Operating Reactors Branch 5. 12pp. 33239-073-33239-088.

8510290625 Notification of 851120 meeting w/utl in Bethesda, MD to discuss licensee long-range plan to complete deferments from Cycle 11R outage in Operating Cycle 11.
DONCHEW, J.N. Operating Reactors Branch 5. 85/10/23. ZWOLINSKI, J.A. Operating Reactors Branch 5. 6pp. 33245:347-33245:352.

8510310385 Forwards Science Applications Intl Corp draft technical evaluation rept re utl response to Generic Ltr 83-28, Item 1.2 re S₁ ATWS events. Response incomplete in four areas. Addl info requested to complete review.
ZWOLINSKI, J.A. Operating Reactors Branch 5. NRC-03-82-096. 85/10/24. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 3pp. 33278:180-33278:197.

-8510310390 Draft "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions, ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' for Oyster Creek Nuclear Power Plant," technical evaluation rept.
Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1526 DRFT. 85/07/10. NRC - No Detailed Affiliation Given. 15pp. 33278:183-33278:197.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32863:001-32869:060.

8503260365 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080169 Notification of Significant Licensee Meeting 85-95 on 851011 w/utl in King of Prussia, PA to discuss SALP mgt meeting.
KISTER, H.B. Region 1, Office of Director. 85/10/01. Region 1, Office of Director. 2pp. 32922:084-32922:085.

8510080339 Forwards Safeguards Insp Rept 50-219/85-24 on 850722-26. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/03. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 32913:205-32913:213.

-8510080346 Physical Security Insp Rept 50-219/85-24 on 850722-26. No noncompliance noted. Major areas inspected: security plan & implementing procedures, mgt effectiveness, testing & maint, keys & combinations, alarm stations & communications.
DUNLAP, J.M., KEIMIG, R.R. Region 1, Office of Director. 85/10/02. 7pp. 32913:207-32913:213.

8510170149 Forwards Safety Insp Rept 50-219/85-23 on 850701-0818 & notice of violation.
KISTER, H.B. Region 1, Office of Director. 85/10/07. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33052:077-33052:098.

-8510170150 Notice of violation from Insp on 850701-0818.
* Region 1, Office of Director. 85/10/07. 2pp. 33052:079-33052:080.

-8510170153 Insp Rept 50-219/85-23 on 850701-0818. Violations noted: improper closure of containment isolation valve & failure to follow procedures while inserting drywell.
BATEMAN, W.H., WECHSELBERGER, REYNOLDS, S.D. Region 1, Office of Director. 85/10/07. 18pp. 33052:081-33052:098.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubs. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510220421 Forwards SALP Rept 50-219/85-99 for May 1984 - June 1985. Meeting scheduled for 851028 to discuss assessment & plans for performance improvement.
MURLEY, T.E. Region 1, Office of Director. 85/10/11. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33097:069-33097:131.

-8510220423 SALP Rept 50-219/85-99 for May 1984 - June 1985.
* Region 1, Office of Director. 85/10/11. 61pp. 33097:071-33097:131.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510250161 Forwards Safety Insp Rept 50-219/85-26 on 850819-0922. No violation noted.
KISTER, H.B. Region 1, Office of Director. 85/10/16. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33190:028-33190:041.

-8510250171 Insp Rept 50-219/85-26 on 850819-0922. No violation noted. Major areas inspected: plant operations, physical security, radiation control, housekeeping, chemistry. Part 21 repts & status of NUREG-0737 items.
BATEMAN, W.H., WECHSELBERGER, URBAN, R.J. Region 1, Office of Director. 85/10/16. 12pp. 33190:030-33190:041.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250045 Forwards Amend 90 to License DPR-16 & safety evaluation. Amend changes Tech Specs to revise inservice insp & testing requirements in Section 4.3, "Reactor Coolant."
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/18. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 7pp. 33225:002-33225:022.

-8510250049 Amend 90 to License DPR-16, changing Tech Specs to revise inservice insp & testing requirement in Section 4.3, "Reactor Coolant."
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/18. 10pp. 33225:009-33225:018.

-8510250050 Safety evaluation supporting Amend 90 to License DPR-16.
* Office of Nuclear Reactor Regulation, Director. 85/10/18. 4pp. 33225:019-33225:022.

R. Periodic operating reports & related correspondence

8510020124 Monthly operating rept for Jul 1985. W/850814 ltr.
EMRICH, W.J., FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 85/07/31. 7pp. 32827:082-32827:088.

8510070277 Forwards "Progress Rept for 41st Quarter on Study of Woodborer Populations in Relation to Oyster Creek Nuclear Generating Station," for May-Jul 1985.
FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 85/09/27. MURLEY, T.E. Region 1, Office of Director. 1p. 32900:057-32900:080.

-8510070283 "Progress Rept for 41st Quarter on Study of Woodborer Populations in Relation to Oyster Creek Nuclear Generating Station," for May-Jul 1985.
HILLMAN, R.E., BELMORE, C.I. Battelle New England Marine Research Laboratory. 15298. 85/08/31. 23pp. 32900:059-32900:080.

S. Reportable occurrences, LERs & related correspondence

8510150348 LER 84-031-01 on 841205, during performance of MSIV closure & inservice test, main steam drain valves V-1-106, V-1-107 & V-1-110 failed to operate. Caused by open torque switches preventing operation of valves. W/851002 ltr.
CUSTODIO, D.B., FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/02. 4pp. 33000:342-33000:345.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

U. Congressional/Executive Correspondence

8510220432 Responds to lecture slides described in 850830 ltr. After review completed, Commission will respond to last paragraph of 850830 ltr.
PALLADINO, N.J. Commissioners. 85/10/10. MARKEY, E.J. House of Rep., Energy & Commerce. 2pp. 33099:106-33099:148.

-8510220434 Provides review of certain mats used during training course presented in Fall 1983.
CLARK, P.R. General Public Utilities Corp. - GPU Service Corp. 85/09/03. PALLADINO, N.J. Commissioners. 14pp. 33099:133-33099:146.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510240444 Forwards addl info re 840402 submittal on Section 6 of Suppl 1 to NUREG-0737, "Reg Guide 1.97-Application to Emergency Response Facilities," requested in NRC 850613 ltr. Existing instrumentation meets needs for post-accident monitoring.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/10/18. VASSALLO, D.B. Operating Reactors Branch 2. 25pp. 33149:011-33149:035.

8510280338 Forwards Safety Insp Rept 50-220/85-12 on 850701-0905 & notice of violation.
COLLINS, S.J. Region 1, Office of Director. 85/10/23. MANGAN, C.V. Niagara Mohawk Power Corp. 2pp. 33193:241-33193:253.

-8510280348 Insp Rept 50-220/85-12 on 850701-0906. Violation noted: failure to lock open manual valve in core spray sys when sys restored to svc after maint.
LINVILLE, J.C. Region 1, Office of Director. 85/10/21. 10pp. 33193:244-33193:253.

I. Financial information

8510150083 Informs that financial info submitted for 1985 in 850809 ltr satisfies requirements of 10CFR140.21.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/10/01. RUSHMORE, J.W. Niagara Mohawk Power Corp. 1p. 33042:204-33042:204.

P. Operating license stage documents & correspondence

8510040143 Forwards status of deficiencies/unresolved & open items resulting from Audit 85-13 of equipment qualification program held during wk of 850819.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/09/30. POTAPOVS, U. Director's Office, Office of Inspection and Enforcement. 6pp. 32851:018-32851:023.

24 DOCKETED ITEMS

8510040429 Responds to 850228 request for exemption from 10CFR50.72 & 50.73 requirements re reporting of all manual & automatic actuations of ESF sys. Request will be addressed generically after reevaluation of requirements.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/01. MANGAN, C.V. Niagara Mohawk Power Corp. 2pp. 32859-334-32859-335.

8510070261 Advises that load drop analyses of two remaining load handling devices completed, per util 850805 ltr addressing guidelines of NUREG-0612, Section 5.1.1. Scabbing of intervening floor may occur for certain loads.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 32677-311-32677-311.

8510160218 Submits schedule to meet requirements of 10CFR50.62 re ATWS events for light water cooled nuclear power plants. Alternate rod injection sys will be installed by end of 1988 refueling & maint outage. Util evaluating standby liquid control sys.
LEMPGES, T.E. Niagara Mohawk Power Corp. 85/10/10. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 33023-258-33023-259.

8510120206 Notification of 851016 meeting w/util in Bethesda, MD to discuss topical rept on QA results based on NRC initial review of rept.
ANKRUM, G.T. Quality Assurance Branch. 85/10/11. GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 2pp. 33069-230-33069-231.

8510250418 Forwards application for amend to License DPR-63 & proposed changes to Tech Spec 6.2.2 & Figure 6.2-1, "Mgt Organization Chart." Analyses demonstrating that changes involve NSHC also encl. Fee paid.
DONLON, W.J. Niagara Mohawk Power Corp. 85/10/17. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 33171-303-33171-317.

-8510250426 Application for amend to License DPR-63, revising Tech Spec 6.2.2 & Figure 6.2-1 to reflect change in mgt organization. Supporting info & analyses demonstrating that changes involve NSHC encl.
DONLON, W.J. Niagara Mohawk Power Corp. 85/10/17. 10pp. 33171-304-33171-313.

-8510250431 Proposed Tech Spec 6.2.2 & Table 6.2-1, "Mgt Organization Chart," reflecting change in mgt organization.
* Niagara Mohawk Power Corp. 85/10/17. 4pp. 33171-314-33171-317.

8510280028 Forwards 851017 certification of pollution control facilities, per 850813 request. Abating or controlling atmospheric pollutants of electricity acceptable.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/17. MANGAN, C.V. Niagara Mohawk Power Corp. 6pp. 33241-203-33241-208.

Q. Inspection reports, IE Bulletins & correspondence

8510160078 FOIA request for Investigation Rept I-84-014.
WENNER, R. Meredith Broadcasting/WTWH Television. 85/09/26. FELTON, J. Division of Rules and Records. 1p. 33028-284-33028-284.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160084 Responds to FOIA request for Investigation Rept I-84-014. Forwards 850912 ltr to BP Garde of GAP, provided in response to FOIA Request 85-613 W/o encl.
FELTON, J.M. Division of Rules and Records. 85/10/03. WENNER, R. Meredith Broadcasting/WTWH Television. 1p. 33028-285-33028-285.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230102 Forwards Press Release 84-36 re NRC proposed fine against util for 30 alleged violations. Util ordered to hire consultant firm to evaluate organization.
KAMMERER, C. Office of Congressional Affairs. 84/03/21. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, E. House of Rep. MOYNIHAN, D. Senate. 2pp. 33108-341-33108-343.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280338 Forwards Safety Insp Rept 50-220/85-12 on 850701-0906 & notice of violation.
COLLINS, S.J. Region 1, Office of Director. 85/10/23. MANGAN, C.V. Niagara Mohawk Power Corp. 2pp. 33193-241-33193-253.

-8510280341 Notice of violation from insp on 850701-0906.
* Region 1, Office of Director. 85/10/23. 1p. 33193-243-33193-243.

-8510280348 Insp Rept 50-220/85-12 on 850701-0906. Violation noted: failure to lock open manual valve in core spray sys when sys restored to svc after maint.
LINVILLE, J.C. Region 1, Office of Director. 85/10/21. 10pp. 33193-244-33193-253.

R. Periodic operating reports & related correspondence

8510180236 Monthly operating rept for Sept 1985. W/851004 ltr.
ROMAN, T.W., LEMPGES, T.E. Niagara Mohawk Power Corp. 85/09/30. 5pp. 33068-046-33068-050.

S. Reportable occurrences, LERs & related correspondence

8510030348 Special rept on 850808, fire barrier penetrations I-849 & I-2310 declared inoperable due to maint mods on floor drains. Fire watch patrols performed hourly insps until completion of mods on 850830.
LEMPGES, T.E. Niagara Mohawk Power Corp. 85/09/09. MURLEY, T.E. Region 1, Office of Director. 1p. 32846-072-32846-072.

8510170110 LER 85-015-00 on 850911, personnel informed of three instances of cable routing discrepancies. Operators informed. Mods designed & will be installed in timely manner. W/851011 ltr.
RANDALL, R., LEMPGES, T.E. Niagara Mohawk Power Corp. 85/10/11. 5pp. 33052-118-33052-122.

8510220011 LER 85-012-00 on 850916, reactor cleanup sys isolated due to high area temp. Caused by steam leaking from gland packing on 1-inch vent valve from cleanup nonregenerative HX. Leak repaired. W/851016 ltr.
RANDALL, R., LEMPGES, T.E. Niagara Mohawk Power Corp. 85/10/16. 3pp. 33095-316-33095-318.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230102 Forwards Press Release 84-36 re NRC proposed fine against util for 30 alleged violations. Util ordered to hire consultant firm to evaluate organization.
KAMMERER, C. Office of Congressional Affairs. 84/03/21. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 2pp. 33108-341-33108-343.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250079 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Lowell, Univ. of, Lowell, MA. 3pp. 33226-104-33226-106.

8510240400 Forwards revised Tech Specs in support of request for extension of License R-125.
WALLACE, T.J., HOGAN, W.T. Lowell, Univ. of, Lowell, MA. 85/10/21. Standardization & Special Projects Branch. 62pp. 33154-123-33154-184.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

8510250118 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Rensselaer Polytechnic Institute, Troy, NY. 3pp. 33226-065-33226-067.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510220166 Forwards revised onsite & offsite maps for Environ Group Procedure 2. Directions for updating procedure listed.
LICARI, K. Commonwealth Edison Co. 85/08/22. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33083-296-33083-297.

8510080506 Revised emergency plan implementing procedures, including Rev 1 to ED-24 re determining recommended offsite protective action response option for general public & Rev 2 to ED-2 re flood prediction sys.
KENEALY, D., BENNETT, C.J. Commonwealth Edison Co. 85/08/31. 150pp. 32943-090-32943-249.

8510230018 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114. KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33109:001-33109:002.

8510110008 Forwards "DCRDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." Most requirements of Suppl 1 to NUREG-0737 satisfied. Proposed resolutions to human engineering deficiencies necessary within 120 days of ltr receipt. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 4pp. 32999:183-32999:251.

-8509170394 "DCRDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." * Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. 85/08/30. NRC - No Detailed Affiliation Given. 65pp. 32999:187-32999:251.

8510210064 Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director." GORDON, J.C. Commonwealth Edison Co. 85/10/15. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33082:282-33083:043.

-8510210073 Revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/two oversize drawings. KENEALY, D.M., BENNETT, C.J., GOLDEN, J.C. Commonwealth Edison Co. 85/10/15. 120pp. 33082:283-33083:043.

8510230049 Forwards addl exemption request re structural steel & cold shutdown analyses & fire protection. Util committed to continuing evaluation of all safe shutdown sys & equipment to meet App R Fee paid W/o encls. WOJNAROWSKI, J. Commonwealth Edison Co. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33258:175-33258:256.

8510230125 Ack receipt of FEMA 850910 ltr including revised schedule of corrective actions submitted by State of IL for recommendations identified as result of 850423 exercise. FEMA & Region V determined responses adequate. SHAFFER, W.D. Region 3, Office of Director. 85/10/17. REED, C. Commonwealth Edison Co. 7pp. 33101:046-33101:047.

8510240324 Rev 5 to Emergency Plan Implementing Procedure EG-11, "Environ Sample Collection Procedures for Air Water, Milk, Soil & Vegetation." W/851017 ltr. KENEALY, D., MOORE, R.D., GOLDEN, J.C. Commonwealth Edison Co. 85/10/17. DENTON, H.R. Record Services Branch (Document Control Desk). 11pp. 33153:327-33153:338.

J. Insurance & indemnity information

8510300064 Forwards unexecuted Amends 23.4 & 5 to Indemnity Agreements B-10, B-97 & B-84, respectively, modifying location descriptions to conform to facility forms. DINITZ, J. Office of State Programs, Director. 85/10/25. OSTER, J. Commonwealth Edison Co. 4pp. 33261:353-33261:356.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929:003-32929:070.

-8510080357 Documents conclusions reached during ACRS 122nd meeting re Midland Plant Units 1 & 2 request for exemption to allow certain const & ESF instrumentation for Indian Point 2. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/06/17. MORRIS, P.A. Atomic Energy Commission. 2pp. 32929:359-32929:360.

P. Operating license stage documents & correspondence

8510080445 Forwards safety evaluation for storage & handling of liquid propane gas in response to NRC request for info re 841204 proposed amend to Tech Specs supporting use of mobile vol reduction sys. Diagram of storage configuration encl. WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 12pp. 32922:034-32922:045.

8510080452 Requests approval of proposed alternate methods & criteria for performing seismic evaluation, including criteria described in FSAR. Forwards "Alternate Seismic Evaluation Criteria/Methodology..." Fee paid. WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:327-32921:356.

-8510080456 "Alternate Seismic Evaluation Criteria/Methodology, Quad-Cities Nuclear Station, Units 1 & 2, Dresden Nuclear Station, Units 2 & 3." * Commonwealth Edison Co. 85/09/30. 28pp. 32921:329-32921:356.

8510080514 Forwards Rev 0 to COM-83-042, "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. THOMPSON, H.L. Division of Licensing. 2pp. 32920:134-32920:216.

-8510080515 Rev 0 to "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." ANDERSSON, O., GAVULA, J.A., CRAWFORD, R.M. NUTECH Engineers, Inc. COM-83-042 R00. 85/09/23. 70pp. 32920:136-32920:216.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues. BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes. ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations." * Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC praimplementation review & approval of generic & plant-specific designs for incomplete mods requested. ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33019:332-33019:337.

Q. Inspection reports, IE Bulletins & correspondence

8510080517 Forwards Insp Repts 50-010/85-14, 50-237/85-31 & 50-249/85-27 on 850816-28. No violations noted. NORELIUS, C.E. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32920:068-32920:074.

-8510080518 Insp Repts 50-010/85-14, 50-237/85-31 & 50-249/85-27 on 850816-28. No violations noted. Major areas inspected: licensee prompt & long-term actions in response to 850816 loss of offsite power. WRIGHT, G.C. Region 3, Office of Director. 85/09/23. 5pp. 32920:070-32920:074.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114. KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. PERCY Senate. MADIGAN House of Rep. 2pp. 33109:001-33109:002.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510210218 Forwards Insp Repts 50-237/85-32 & 50-249/85-28 on 850916-19 & notice of violation. REYES, L.A. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33074:091-33074:097.

-8510210220 Notice of violation from insp on 850916-19. REYES, L.A. Region 3, Office of Director. 85/10/16. 1p. 33074:093-33074:093.

-8510210223 Insp Repts 50-237/85-32 & 50-249/85-28 on 850916-19. Violation noted: review of test res ltr of Procedure DTS-300-2, "CRD Scram Testing & Scram Valve Timing Test," not documented. TAYLOR, T.E., HAWKINS, F.C. Region 3, Office of Director. 85/10/15. 4pp. 33074:094-33074:097.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic R00 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230231 Responds to NRC 850918 ltr re violations noted in Insp Repts 50-237/85-29 & 50-249/85-24. Corrective actions: personnel required to receive training on 850605 QA rev trained & training dept will issue reminder memos more frequently. FARRAR, D.L. Commonwealth Edison Co. 85/10/18. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33169:033-33169:034.

R. Periodic operating reports & related correspondence

8510180472 Monthly operating rept for Sept 1985 W/851001 ltr. MAXWELL, D.C., SCOTT, D.J. Commonwealth Edison Co. 85/09/30. 20pp. 33068:228-33068:247.

26 DOCKETED ITEMS

S. Reportable occurrences, LERs & related correspondence

8510040142 RO 15: on 850816, reactor scrambled on low reactor water level due to loss of offsite power. Caused by electrical interference generated from movement of source & intermediate range monitors. Insp scheduled on 850930.
SCOTT, D.J. Commonwealth Edison Co. 85/09/20. KEPPLER, J.G. Region 3, Office of Director. 2pp. 32651:238-32651:239.

8510280423 Amend 1 to Confirmatory Action Ltr. 85-04 re monitoring sys operability/response to strain gauge linear variable differential transformers & replacement of monitoring sys w/ Megatrac computerized sys.
KEPPLER, J.G. Region 3, Office of Director. 85/10/23. REED, C. Commonwealth Edison Co. 2pp. 33194:010-33194:011.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:001-33109:002.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

8510210041 Advises that operator & senior operator written & oral exams scheduled for wk of 860127. List of required ref matl & description of requirements for conducting exams encl. License applications required 60 days prior to exam.
REYES, L.A. Region 3, Office of Director. 85/10/15. REED, C. Commonwealth Edison Co. 5pp. 33072:313-33072:317.

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

P. Operating license stage documents & correspondence

8510080249 Forwards application for renewal/amend to License NS-1 to authorize annual radiation surveys of ship & semiannual environ surveillance by State of SC, Dept of Health & Environ Control.
GUERRY, J.E., LEVINE, Z. South Carolina, State of. 85/08/20. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 32922:141-32922:165.

-8510080254 Application for renewal/amend to License NS-1 to authorize annual radiation surveys of ship & semiannual environ surveillance by State of SC, Dept of Health & Environ Control. "Five-Yr Summary Survey Rept" encl.
* South Carolina, State of. 85/08/20. 5pp. 32922:142-32922:146.

-8510080257 "Five-Yr Summary Survey Rept," including TLD monitoring, direct radiation survey, contamination survey results, environ sample analysis rept & leak deck plans.
* South Carolina, State of. 85/08/20. 19pp. 32922:147-32922:165.

DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250308 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. Oregon State Univ., Corvallis, OR. 3pp. 33226:148-33226:150.

8510280115 Responds to 850927 order to show cause re limits on possession of unirradiated high enriched U fuel at facility. Consents to order. Facility in compliance. No further action required.
SMITH, C.V. Oregon State Univ., Corvallis, OR. 85/10/11. Office of the Secretary of the Commission. 3pp. 33228:326-33228:328.

R. Periodic operating reports & related correspondence

8510290374 "Oregon State Univ Triga Reactor Annual Rept," for reporting period Jul 1984 - June 1985. W/850915 ltr.
ANDERSON, T.V., DODD, B., PRATT, D.S. Oregon State Univ., Corvallis, OR. 85/06/30. 120pp. 33245:177-33245:296.

8510290586 "Changes to Facility, to Facility Procedures & to Reactor Experiments for Jul 1984 - June 1985."
SMITH, C.V. Oregon State Univ., Corvallis, OR. 85/10/04. Region 5, Office of Director. 10pp. 33244:344-33244:353.

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510110231 Forwards final scenario for full-scale exercise scheduled for 850926. per 850807 conversation w/Burke. Submittal incorporates BMNL 850719 comments.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/08/08. COHEN, J. Region 1, Office of Director. 400pp. 32970:198-32971:234.

8510150258 Advises that Class III fee appropriate for 840116 request for exemptions from requirements of 10CFR50, App R Fee remitted by 850109 ltr for 841004 application will be applied to 840116 request. Remaining fee should be remitted.
MILLER, W.O. License Fee Management Branch. 85/10/09. KOBEL, R.W. Rochester Gas & Electric Corp. 1p. 33032:212-33032:212.

8510310242 Forwards fee to cover review of applications re reanalysis of alternate safe shutdown sys. in response to NRC 851009 ltr.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/10/23. MILLER, W.O. License Fee Management Branch. 3pp. 33274:029-33274:031.

J. Insurance & indemnity information

8510310052 Forwards unexecuted Amend 10 to Indemnity Agreement B-38, modifying location description to conform to facility form policies.
DINITZ, J. Office of State Programs, Director. 85/10/25. WHITE, L.D. Rochester Gas & Electric Corp. 2pp. 33277:175-33277:176.

P. Operating license stage documents & correspondence

8510040444 Advises that 831202 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing acceptable Conclusion supported by encl EG&G Idaho, Inc rept.
VARGAS, A. Operating Reactors Branch 1. 85/09/19. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 32859:315-32859:331.

-8509060182 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Ginna, Kewaunee, Point Beach Units 1 & 2 & Prairie Island Units 1 & 2."
HAROLDSEN, R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6001. EA-7000. 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859:317-32859:331.

8510030002 Forwards safety evaluation of util 831104 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint safety-related testing requirements for reactor trip sys. Response acceptable.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. KOBEL, R.W. Rochester Gas & Electric Corp. 2pp. 32842:225-32842:228.

-8510030016 Safety evaluation supporting util 831104 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing of reactor trip sys. No testing requirements identified in existing Tech Specs which degrade safety.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 2pp. 32842:227-32842:228.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510160267 Forwards revised list of safety-related hydraulic snubbers, incorporating changes made since 840720 update, due to continuing seismic upgrade program. Up-to-date listing of mechanical snubbers will be submitted after NRC review.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 4pp. 33021:291-33021:294.

8510100167 Advises that submittal of Tech Spec amend to perform periodic purge/vent valve seal leakage tests not required. Amend would be required if new purge/vent sys not installed.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/08. KOBEL, R.W. Rochester Gas & Electric Corp. 2pp. 32962:194-32962:195.

8510150258 Advises that Class III fee appropriate for 840116 request for exemptions from requirements of 10CFR50, App R Fee remitted by 850109 ltr for 841004 application will be applied to 840116 request. Remaining fee should be remitted.
MILLER, W.O. License Fee Management Branch. 85/10/09. KOBEL, R.W. Rochester Gas & Electric Corp. 1p. 33032:212-33032:212.

8510180132 Forwards proprietary & nonproprietary WCAP-10885, "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture... Using LOFTTR1," per 830830 request. Proprietary rept withheld.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/10/09. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33056:131-33056:205.

-8510180137 Requests withholding of proprietary "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture at RE Ginna Nuclear Power Plant Using LOFTTR1." Affidavit & operator action times encl.
WIESEMANN, R.A. Westinghouse Electric Corp. 85/08/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 33056:132-33056:145.

-8510180142 "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture at RE Ginna Nuclear Power Plant Using LOFTTR1."
BRENNAN, J., RUBIN, K. Westinghouse Electric Corp. WCAP-10885. 85/07/31. 62pp. 33056:146-33056:205.

8510220274 Forwards application for amend to License DPR-18, deleting requirement for operation of auxiliary bldg vent & charcoal filter absorber sys when fuel in spent fuel storage pool decayed 60 days since irradiation. Fee paid.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33087:078-33087:089.

-8510220278 Application for amend to License DPR-18, changing Tech Specs to delete requirement for operation of auxiliary bldg vent & charcoal filter absorber sys when fuel in spent fuel storage pool decayed 60 days since irradiation.
KOBEL, R.W. Rochester Gas & Electric Corp. 85/10/09. 2pp. 33087:079-33087:080.

-8510220283 Proposed Tech Specs re fuel handling in auxiliary bldg & spent fuel pit charcoal absorber sys.
* Rochester Gas & Electric Corp. 85/10/09. 9pp. 33087:081-33087:089.

8510210050 Provides proposed schedule for meeting requirements of ATWS rule & brief description of tentative design being considered, per Generic Ltr 85-06. Util will use design presented in Section 4.0 of WCAP-10858.
KUCER, R.W. Rochester Gas & Electric Corp. 85/10/11. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 33072:308-33072:309.

8510170224 Notification of 851017 meeting w/util in Bethesda, MD to discuss staff recommendations re licenses containment tendon surveillance program.
CLIFFORD, T.W. Operating Reactors Branch 5. 85/10/15. ZWOLINSKI, J.A. Operating Reactors Branch 5. 4pp. 33039:281-33039:284.

8510210127 Forwards application for amend to License DPR-18, revising Tech Specs re containment internal pressure limitations. Fee paid.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33073:308-33073:345.

-8510210130 Application for amend to License DPR-18, revising Tech Specs re containment internal pressure limitations.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/16. 3pp. 33073:309-33073:311.

-8510210134 Proposed Tech Specs re containment internal pressure limitations.
* Rochester Gas & Electric Corp. 85/10/16. 34pp. 33073:312-33073:345.

8510220092 Forwards application for amend to License DPR-18, reflecting recently announced mgt changes. Fee paid.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33081:325-33081:339.

-8510220096 Application for amend to License DPR-18, reflecting recent mgt changes.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/16. 3pp. 33081:327-33081:329.

-8510220099 Proposed Tech Specs reflecting recent mgt changes.
* Rochester Gas & Electric Corp. 85/10/16. 10pp. 33081:330-33081:339.

8510220371 Forwards application for amend to License DPR-18, changing Tech Specs to incorporate new containment mini-purge sys & delete requirements associated w/old 48-inch containment purge sys. Fee paid.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33088:160-33088:175.

-8510220376 Application for amend to License DPR-18, changing Tech Specs to incorporate new containment mini-purge sys & delete requirements associated w/old 48-inch containment purge sys.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/22. 2pp. 33088:161-33088:162.

-8510220379 Proposed Tech Specs, incorporating new containment mini-purge sys & deleting requirements associated w/old 48-inch containment purge sys.
* Rochester Gas & Electric Corp. 85/10/22. 13pp. 33088:163-33088:175.

8510280011 Requests fee for 850911 request for approval to dispose of slightly contaminated oil by burning in house heating boiler.
DIGGS, R.M. License Fee Management Branch. 85/10/22. KOBBER, R.W. Rochester Gas & Electric Corp. 1p. 33241:337-33241:337.

Q. Inspection reports, IE Bulletins & correspondence

8510040425 Responds to violations noted in Insp Rept 50-244/85-04. Corrective actions: Administrative Procedure A-1020 will be revised by 851213 to provide more effective valve preventive maint program.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/09/25. MURLEY, T.E. Region 1, Office of Director. 2pp. 32853:361-32853:362.

8510080030 Forwards Special Team Insp Rept 50-244/85-08 on 850610-14. No violations observed. Areas of concern listed. Description of action taken or planned re possible Eberline SPING-4 sys damage requested within 25 days.
MARTIN, T.T. Region 1, Office of Director. 85/09/27. KOBBER, R.W. Rochester Gas & Electric Corp. 2pp. 32928:131-32928:158.

-8510080032 Safety Insp Rept 50-244/85-08 on 850610-14. No violations identified. Major areas inspected: implementation & status of task actions identified in NUREG-0737, including increased range of noble gas radiation monitors.
WHITE, J.R., PAULINO, R., DRAGOUN, T.D. Region 1, Office of Director. 85/09/25. 25pp. 32928:133-32928:158.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510040202 Forwards Safety Insp Rept 50-244/85-15 on 850801-31. No violations noted.
COLLINS, S.J. Region 1, Office of Director. 85/09/30. KOBBER, R.W. Rochester Gas & Electric Corp. 2pp. 32850:311-32850:328.

-8510040209 Insp Rept 50-244/85-15 on 850801-31. No violations noted. Major areas inspected: routine plant activities, action on previous findings, surveillance testing, review of svc water leak & review of TMI action plan.
LINVILLE, J.C. Region 1, Office of Director. 85/09/25. 16pp. 32850:313-32850:328.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160002 Submits update of improvements in steam generator tubesheet sleeve eddy current insp techniques since initial sleeve installation in 1983. Removal of restriction limiting number of tubesheet sleeves that can be installed requested.
KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 9pp. 33027:093-33027:101.

8510220103 Forwards Safety Insp Rept 50-244/85-14 on 850820-22. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/11. KOBBER, R.W. Rochester Gas & Electric Corp. 2pp. 33095:109-33095:115.

-8510220106 Insp Rept 50-244/85-14 on 850820-22. No violations identified. Major areas inspected: nonradiological chemistry program, including training, measurement control & analytical procedure evaluations.
ZIBULSKY, H., PASCIAK, W.J. Region 1, Office of Director. 85/10/11. 5pp. 33095:111-33095:115.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230233 Forwards Safety Insp Rept 50-244/85-18 on 850903-06 & notice of violation. Violations of QA & QC programs represent example of type of concern expressed in 850225 SALP Rept 50-244/84-99.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. KOBBER, R.W. Rochester Gas & Electric Corp. 2pp. 33103:038-33103:050.

-8510230236 Notice of violation from Insp on 850903-06.
* Region 1, Office of Director. 85/10/18. 2pp. 33103:040-33103:041.

-8510230244 Insp Rept 50-244/85-18 on 850903-06. Violations noted: failure to sample surface water per Tech Specs & failure to establish calibr procedure & calibr frequency.
COFFI, J.A., SHANBAKY, M.M. Region 1, Office of Director. 85/10/11. 9pp. 33103:042-33103:050.

8510280350 Ack receipt of 850925 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-244/85-04.
EBNETER, S.D. Region 1, Office of Director. 85/10/23. KOBBER, R.W. Rochester Gas & Electric Corp. 2pp. 33192:313-33192:316.

R. Periodic operating reports & related correspondence

8510010422 Monthly operating rept for Jul 1985. W/850812 ltr.
DODGE, R.E., SNOW, B.A. Rochester Gas & Electric Corp. 85/07/31. 6pp. 32809:186-32809:191.

S. Reportable occurrences, LERs & related correspondence

8510010032 LER 85-011-01 on 850411. reactor trip occurred during attempts to trip main turbine manually. Caused by low condenser vacuum & reactor power being above P-7. Inquiry re reactor trip train design undertaken. W/850913 ltr.
MEYER, T.A., KOBBER, R.W. Rochester Gas & Electric Corp. 85/09/13. 5pp. 32609:244-32609:248.

8510240248 LER 85-016-00 on 850915. control rod deviation alarm occurred. Caused by intermittent fluctuation in RPI & change in reactor coolant temp. On 850916, control rod indication sys made inoperable to replace power supplies. W/851015 ltr.
EDGAR, E.C., KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/14. 4pp. 33159:075-33159:077.

8510240644 LER 85-017-00 on 850916. rod control sys on bank "C" switch allowed only two rods in each of banks "B" & "D" to move, causing control rod insertion & bank overlap violation. Caused by faulty firing card. Card replaced. W/851015 ltr.
WIDAY, J.A., KOBBER, R.W. Rochester Gas & Electric Corp. 85/10/15. 4pp. 33157:215-33157:218.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.I. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080460 Forwards notice of environ assessment & finding of no significant impact re 820301, 0716, 830415, 841204, 850807 & 23 applications for exemptions from requirements of 10CFR50, App R.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/02. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32921:221-32921:226.

-8510080462 Notice of environ assessment & finding of no significant impact re 820301, 0716, 830415, 841204, 850807 & 23 applications for exemptions from requirements of 10CFR50, App R re main control room & turbine bldg reactor feed pump.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/02. 3pp. 32921:224-32921:226.

8510110074 Forwards FEMA 850829 ltr & rept of 841012 exercise. Category B deficiencies observed at exercise do not detract from public protection. State of CT preparing schedule of corrective actions.
HARPSTER, T.L. Region 1, Office of Director. 85/10/04. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32973:028-32973:117.

28 DOCKETED ITEMS

- 8510110075** Forwards SER re util 840202 & 0316 responses to integrated safety assessment rept (NUREG-0824) sections, including flooding elevation & roofs. Proposed method of safe shutdown acceptable if firehouse blockwalls can resist flood loads. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/07. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33011:305-33011:311.
- 8510110086** SER supporting integrated plant safety assessment rept NUREG-0824 sections, including flooding elevation & roofs, provided fire pump house blockwalls adequate to resist flood loads.
* NRC - No Detailed Affiliation Given. 85/10/07. 4pp. 33011:308-33011:311.
- 8510150284** Corporate organization for nuclear incidents procedures, including Rev 10 to CONI-4.02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines." W/851009 ltr. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Utilities. 85/10/09. 17pp. 33009:113-33009:285.
- 8510160014** Forwards Insp Rept 50-245/85-15 on 850617-28 & notice of violation. EBNETER, S.D. Region 1, Office of Director. 85/10/11. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33027:102-33027:161.
- 8510160024** Notice of violation from insp on 850617-28.
* Region 1, Office of Director. 85/10/11. 10pp. 33027:104-33027:113.
- 8510160037** Insp Rept 50-245/85-15 on 850617-28. Violations noted: failure to provide adequate written procedures for two specific safety-related activities & failure to follow station procedure.
CHUNG, J.W., MURPHY, K.G., PETRONE, C.D. Region 1, Office of Director. 85/09/03. 48pp. 33027:114-33027:161.
- 8510220295** Forwards review of integrated safety assessment program Topic 1.36, "Tech Specs Covered by Generic Ltr 83-36," per 850517 commitment.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/15. GRIMES, C.I. Systematic Evaluation Program Branch. 5pp. 33086:310-33086:314.
- 8510240287** Forwards reviews of integrated safety assessment program, Topics 1.07, "CRDR" & 1.08, "SPDS," per 850517 commitment.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/16. GRIMES, C.I. Systematic Evaluation Program Branch. 8pp. 33151:315-33151:322.
- 8510280203** Submits for review, Integrated Safety Assessment Program Topics 1.16.1, "MP1/MP2 Backfeed," 1.16.2, "Modify CRD Pumps," 1.16.3, "Alternative Cooling for Shutdown Equipment," & 1.16.4, "Power Cold Shutdown Equipment."
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/16. GRIMES, C.I. Systematic Evaluation Program Branch. 14pp. 33191:183-33191:196.
- 8510230219** Forwards sections of State of CT radiological emergency response plan re medical svcs & similar sections from local plans within 10 mile emergency planning zone.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/18. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 150pp. 33100:216-33101:026.
- 8510280201** Informs that 850812 amend application denied since Northeast Utils did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 4pp. 33228:237-33228:243.
- 8510280219** Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.
- P. Operating license stage documents & correspondence**
- 8510020435** Forwards Science Applications Intl Corp draft rept, "Review of Risk Based Evaluation of Integrated Safety Assessment Program (ISAP) issues for Millstone Unit 1." Review & comments requested by 851015.
GRIMES, C.I. Systematic Evaluation Program Branch. 85/09/23. KACICH, R. Northeast Utilities Service Co. (subs. of Northeast Utilities). 2pp. 32827:351-32828:123.
- 8510020438** Draft "Review of Risk Based Evaluation of Integrated Safety Assessment Program (ISAP) issues for Millstone Unit 1."
ATEFI, B., GALLAGHER, D., LE, P.T. Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. 85/09/16. NRC - No Detailed Affiliation Given. 131pp. 32827:353-32828:123.
- 8510030130** Forwards TR UR 85-225, "ASEA-Atom BWR Control Blades for US BWRs," for review & approval. Licensing of Quad Cities Unit 1 Reload 9 & Millstone Unit 1 reload dependent on approval of rept. Fee paid.
TENER, E. ASEA Atom, Inc. 85/09/24. BERNARD, H. NRC - No Detailed Affiliation Given. 2pp. 32878:035-32878:075.
- 8510030140** "ASEA-Atom BWR Control Blades for US BWRs."
CHRISTIANSSON, HAMMARLUND, C.E. ASEA Atom, Inc. TR UR 85-225. 85/10/01. 41pp. 32878:037-32878:075.
- 8510020055** Forwards reviews of integrated safety assessment program, Topics 2.02 & 2.16 re drywell humidity instrumentation & reactor protection trip sys, respectively, per 850731 request.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/26. GRIMES, C.I. Systematic Evaluation Program Branch. 5pp. 32825:268-32825:272.
- 8510070441** Forwards detailed comments on draft SER re revised inservice pump & valve test program for second 10-yr insp interval & Rev 2 to "Inservice Pump & Valve Test Program."
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/26. ZWOLINSKI, J.A. Operating Reactors Branch 5. 31pp. 32918:188-32918:292.
- 8510070447** Rev 2 to "Inservice Pump & Valve Test Program." W/six oversize drawings.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/26. 73pp. 32918:220-32918:292.
- 8510070303** Forwards review of integrated safety assessment program, Topics 2.29, "Feedwater Coolant Injection Assessment Study," 2.30, "MSIV Closure Test Frequency," & 2.31, "LPCI Lube Oil Cooler Test Frequency," per NRC 850731 request.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. GRIMES, C.I. Systematic Evaluation Program Branch. 9pp. 32878:016-32878:024.
- 8510080385** Requests exemption from 10CFR50.49 requirements for six remaining valve motor operators. Physical & administrative controls will ensure that valves accomplish required safety function.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32919:306-32919:311.
- 8510170098** Requests extension to 860104 for Haddam Neck re environ qualification of electrical equipment, per Generic Ltr 85-15, 10CFR50.49(g) & Integrated Safety Assessment Program. Further evaluation proposed for Millstone. Fee paid.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. PALLADINO, N.J. Commissioners. 61pp. 33036:118-33036:179.
- 8510080470** Forwards reviews of integrated safety assessment program, Topics 2.17.2.21 & 2.24 re ventilation duct chase plant distribution protection, load ctr replacement of oil filled breakers & offsite power sys, respectively.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. GRIMES, C.I. Systematic Evaluation Program Branch. 9pp. 32921:228-32921:236.
- 8510030105** Denies 850913 application for exemptions from 10CFR50.71(e) for submittal of updated FSAR. Comprehensive exemption request must be submitted by 851011.
THOMPSON, H.L. Division of Licensing. 85/10/02. OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 32844:082-32844:084.
- 8510110037** Forwards evaluations of integrated safety assessment program, Topic 2.14, "Evaluation & Implementation of NUREG-0577" & Topic 2.15, "Torque Switch Evaluation for Motor-Operated Valves," for review.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/02. GRIMES, C.I. Systematic Evaluation Program Branch. 5pp. 32973:221-32973:225.
- 8510100135** Comments on draft rept on integrated safety assessment program review of operating experience. Rept should be corrected to state that plant operated for 374 consecutive days & set US BWR record.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/03. GRIMES, C.I. Systematic Evaluation Program Branch. 4pp. 32960:090-32960:093.
- 8510150067** Forwards comments on draft SER for conversion of provisional OL (POL) to full-term OL & comments on existing POL in response to 850726 ltr transmitting draft SER.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/03. ZWOLINSKI, J.A. Operating Reactors Branch 5. 16pp. 33008:303-33008:318.
- 8510150369** Application for amend to License DPR-21, revising Tech Specs to consolidate Specs 3.5.F.7 & 3.5.F.8 into one spec, to clarify water level requirements for refuel cavity & modify LPCI/core spray requirements. Fee paid.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/07. ZWOLINSKI, J.A. Operating Reactors Branch 5. 4pp. 33010:009-33010:012.
- 8510150371** Proposed Tech Specs, consolidating Specs 3.5.F.7 & 3.5.F.8 into one spec, clarifying water level requirements for refuel cavity & modifying LPCI/core spray requirements during refuel condition to more closely match STS.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/07. 5pp. 33010:013-33010:017.
- 8510220247** Forwards review of safety assessment program Topic 2.18, "Spent Fuel Storage Racks/Transportation Cask," per 850731 request. Topics 2.13 & 2.19 canceled.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/09. GRIMES, C.I. Systematic Evaluation Program Branch. 5pp. 33087:324-33087:328.
- 8510290388** Forwards review of Integrated Safety Assessment Program Topic 1.25, "Degraded Gnd Voltage Procedures," resulting from review of SEP Topics VIII-1.A & VII-3 per 850517 commitment.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/09. GRIMES, C.I. Systematic Evaluation Program Branch. 8pp. 33239:089-33239:125.
- 8510290390** Rev 4 to OP 342A "480-Volt Electrical Sys Under/Over-Voltage."
SAUER, G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 84/06/27. 10pp. 33239:097-33239:106.
- 8510290392** Rev 13 to OP 341 "4160-Volt Electrical Sys."
LEMKE, J.A. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/03/28. 8pp. 33239:107-33239:114.
- 8510290393** Rev 21 to OP 340, "24 K Electrical Sys."
SAUER, G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 84/10/31. 11pp. 33239:115-33239:125.

8510220158 Submits ATWS rule schedule required by 10CFR50.62(d), per Generic Ltr 85-06 Facilities participating in NRC Integrated Safety Assessment Program. Justification for absence of schedules for Haddam Neck & Millstone Unit 1 provided.

OPEKA,J.F., Connecticut Yankee Atomic Power Co. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/11. BUTCHER,E.J. Operating Reactors Branch 3. ZWOLINSKI,J.A. Operating Reactors Branch 5. 7pp. 33090:076-33090:082.

8510220186 Requests schedule exemption to submit updated FSAR by 870331 for Millstone Unit 1 & by 870630 for Haddam Neck Plant (ref 10CFR50.71(e)). Complete adoption of format to Rev 3 to Reg Guide 1.70 not planned.

OPEKA,J.F., Connecticut Yankee Atomic Power Co. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/11. THOMPSON,H.L. Division of Licensing. 3pp. 33090:053-33090:055.

8510220313 Forwards reviews of integrated safety assessment program, Topic 1.06, "Seismic Qualification of Safety-Related Piping" & Topic 1.13, "BWR Vessel Water Level Instrumentation," per 850517 commitment.

OPEKA,J.F., FEE,W.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/11. GRIMES,C.I. Systematic Evaluation Program Branch. 8pp. 33084:050-33084:057.

8510220295 Forwards review of integrated safety assessment program Topic 1.36, "Tech Specs Covered by Generic Ltr 83-36," per 850517 commitment.

OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/15. GRIMES,C.I. Systematic Evaluation Program Branch. 5pp. 33086:310-33086:314.

8510230031 Forwards review for integrated safety assessment program Topic 1.47, "Containment Emergency Sump Performance," per 850517 ltr. USI A-43 should be resolved for facility.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33101:352-33101:355.

8510240003 Forwards integrated safety assessment program Topic 1.21, "Fault Transfers," Disarming or removal of six remaining automatic bus transfers in 480 volt ac, 120 volt ac & 125 volt dc impractical due to safety function of devices.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 7pp. 33155:199-33155:205.

8510240078 Forwards review of integrated safety assessment program Topic 1.22, "Electrical Isolation," per 850517 commitment.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 5pp. 33155:227-33155:231.

8510240089 Submits integrated safety assessment program Topic 1.48, "Determination of Safety Relief Valve Pool Dynamic Loads." GDC 50, USI A-7, "Long-Term Program" & USI A-39 served as review criteria.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33155:185-33155:188.

8510240335 Forwards review of integrated safety assessment program, Topic 1.41, "Flooding of Compartments by Backflow," per 850517 commitment.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33151:305-33151:308.

8510240373 Forwards review of integrated safety assessment program Topic 1.17, "Replacement of Motor-Operated Valves," per 850731 commitment.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33151:311-33151:314.

8510240382 Forwards review of integrated safety assessment program Topic 1.38, "Expand QA List," per 850731 commitment.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 5pp. 33154:044-33154:048.

8510240410 Forwards reviews of integrated safety assessment program Topics 1.03 re containment isolation, App A mods & 1.14 re containment leakage testing, App J mods.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 6pp. 33153:339-33153:346.

8510240459 Forwards integrated safety assessment program Topics 1.02 & 1.19 re tornado missile protection & integrated structural analysis, respectively, per 850517 commitment.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 5pp. 33155:028-33155:042.

8510290320 Application for amend to License DPR-21, revising Tech Specs to define refuel condition & operability requirements of sys during refuel & shutdown conditions. Fee paid.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. ZWOLINSKI,J.A. Operating Reactors Branch 5. 6pp. 33236:220-33236:247.

-8510290324 Proposed Tech Spec changes, defining refuel condition & clarifying various sys during refuel & shutdown conditions.

* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/16. 22pp. 33236:226-33236:247.

8510290333 Forwards reviews for Integrated Safety Assessment Program Topics 1.40, "Boiling Degradation or Failure" & 1.49, "Reactor Vessel Surveillance Program," per 850517 ltr. Departmental Instruction 1-MPM-12.17 also encl.

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 6pp. 33234:341-33234:358.

-8510290343 Rev 0 to Departmental Instruction 1-MPM-12.17, "Torque & Fasteners."

* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/03/22. 12pp. 33234:347-33234:358.

8510300123 Forwards review of Integrated Safety Assessment Program Topic 1.42, "Main Steam Line Leakage Control Sys."

OPEKA,J.F., SEARS,C.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities).

OPEKA,J.F., Northeast Utilities. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 5pp. 33251:005-33251:009.

8510220033 Provides info re operating experience for ASEA-ATOM control blades, per NRC request. Mechanical & hydraulic compatibility of hafnium tipped blades w/std GE control blades demonstrated in NRC review.

OPEKA,J.F., MROCZKA,E.J., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/17. ZWOLINSKI,J.A. Operating Reactors Branch 5. 4pp. 33090:221-33090:224.

8510310126 Forwards summary of Integrated Safety Assessment Program Topic 1.17, "Replacement of Motor-Operated Valves," which was evaluated for public safety impacts, per 850731 request. Safety impact scores considered preliminary.

OPEKA,J.F., FEE,W.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/10/17. GRIMES,C.I. Systematic Evaluation Program Branch. 19pp. 33273:303-33273:321.

8510230201 Informs that 850812 amend application denied since Northeast Utilis did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21 Safety evaluation encl.

ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/21. OPEKA,J.F., Connecticut Yankee Atomic Power Co. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.

* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

8510310001 Forwards safety evaluation re util 810413, 850322 & 0614 responses to 800101 request to develop action plan for issues concerning anchorage & support of safety-related equipment. Responses acceptable.

ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/24. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33277:098-33277:102.

-8510310002 Safety evaluation accepting util 810413, 850322 & 0614 ltrs re anchorage & support of safety-related equipment. Safety-related gas turbine subsystems & adjacent non-Category I equipment adequately supported.

* Office of Nuclear Reactor Regulation, Director. 85/10/24. 3pp. 33277:100-33277:102.

Q. Inspection reports, IE Bulletins & correspondence

8510030227 Forwards Special Dosimetry Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09. Status of planning during preoperational phase for dosimetry needs reviewed. No violations noted.

MARTIN,T.T. Region 1, Office of Director. 85/09/17. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32845:139-32845:150.

-8510030235 Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09. No violations identified. Major areas inspected: personnel selection, facilities & equipment, dose assessment, QA, documentation & recordkeeping & organization.

CIOFFI,J.A., JANG,J., SHANBAKY,M. Region 1, Office of Director. 85/09/11. 10pp. 32845:141-32845:150.

8510070441 Forwards detailed comments on draft SER re revised inservice pump & valve test program for second 10-yr insp interval & Rev 2 to "Inservice Pump & Valve Test Program."

OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F., Northeast Utilities. 85/09/26. ZWOLINSKI,J.A. Operating Reactors Branch 5. 31pp. 32918:188-32918:292.

8510080593 Ack receipt of 850906 ltr informing NRC of steps taken to correct violations noted in insp Repts 50-245/85-16 & 50-336/85-22.

EBNETER,S.D. Region 1, Office of Director. 85/09/27. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32927:033-32927:036.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510110025 Notification of 851020, 29 & 30 meetings w/utis in Berlin, Waterford & East Hampton, CT to discuss & review plant mods in response to IE Bulletin 80-11 on masonry wall design.

AKSTULEWICZ,F. Operating Reactors Branch 5. 85/10/08. ZWOLINSKI,J.A. Operating Reactors Branch 5. 4pp. 32974:016-32974:019.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.

LOFF,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510160014 Forwards Insp Rept 50-245/85-15 on 850617-28 & notice of violation.

EBNETER,S.D. Region 1, Office of Director. 85/10/11. OPEKA,J.F., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33027:102-33027:161.

-8510160024 Notice of violation from insp on 850617-28.

* Region 1, Office of Director. 85/10/11. 10pp. 33027:104-33027:113.

-8510160037 Insp Rept 50-245/85-15 on 850617-28. Violations noted: failure to provide adequate written procedures for two specific safety-related activities & failure to follow station procedure.

CHUNG,J.W., MURPHY,K.G., PETRONE,C.D. Region 1, Office of Director. 85/09/03. 48pp. 33027:114-33027:161.

30 DOCKETED ITEMS

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series T.D.s." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Sismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280201 Informs that 850812 amend application denied since Northeast Utils did not establish that group performing fire protection audits qualifies as outside firm per Generic Ltr 82-21 Safety evaluation encl. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. App. 33228-237-33228-243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228-241-33228-243.

R. Periodic operating reports & related correspondence

8510020074 Monthly operating rept for Jul 1985. W/850812 ltr. NEWBURGH, G. ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/07/31. 5pp. 32827-328-32827-332.

S. Reportable occurrences, LERs & related correspondence

8510020274 PNO-I-85-071A on 850927, Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status upgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage. STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825-232-32825-232.

8510170245 LER 85-013-01 on 850829, Part 21 form received, recommending design defect evaluation. LER provides results of investigation re reporting timeliness & 1970 design change background in response to NRC 850909 request. W/851009 ltr. SUMMA, J.A., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/09. 4pp. 33051-237-33051-240.

8510240415 LER 85-016-00 on 850916, automatic actuation of ESF occurred. Caused by isolation of reactor bldg ventilation & initiation of standby gas treatment due to steam tunnel high radiation spike. Isolation signal reset. W/851016 ltr. YAPCHANYK, D.J., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/16. 3pp. 33160-032-33160-034.

8510310100 LER 85-017-00 on 850927, reactor scrammed on APRM hi-hi when reactor mode switch changed from "run" to "startup/hot standby." Off-normal procedures followed. Reactor brought to hot shutdown. W/851025 ltr. YAPCHANYK, D.J., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/25. 3pp. 33291-333-33291-335.

8510310502 LER 85-018-00 on 850927, loss of normal power occurred causing various isolations & sys initiations. Caused by Hurricane Gloria. W/851025 ltr. YAPCHANYK, D.J., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/25. 3pp. 33279-341-33279-343.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510040544 Discusses Tech Specs for external flooding conditions. Probable max hydrologic event, including hurricane surge poses significant safety concern. External flooding Tech Specs requested within 60 days. VARGA, S.A. Operating Reactors Branch 1. 85/09/19. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 4pp. 32863-156-32863-159.

8510310174 Forwards Amend 97 to License DPR-26 & safety evaluation. Amend revises Tech Specs to limit overtime for critical shift job positions, changes audit frequency & clarifies QA record retention requirements. NEIGHBORS, J.D. Operating Reactors Branch 1. 85/09/30. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 2pp. 33277-306-33277-316.

-8510310179 Amend 97 to License DPR-26, revising overtime procedure for safety-related positions, changing audit frequency of emergency preparedness program & safety-related contingency plan & clarifying record retention requirements. VARGA, S.A. Operating Reactors Branch 1. 85/09/30. 7pp. 33277-308-33277-314.

8510160225 Revised emergency procedures document, replacing NUC-1 through 5, A-1 through 6, SAE-1 through 6 & GE-1 through 5 w/ NUC-1 through 4, A-1 through 6 & SAE-1 through 6 in Emergency Procedures Document 1. W/851008 ltr. SELMAN, M. Consolidated Edison Co. of New York, Inc. 85/10/08. MURLEY, T.E. Region 1, Office of Director. 23pp. 33023-149-33023-171.

8510220064 Forwards SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985. Meeting scheduled on 851025 to discuss assessments & plans for performance improvement. MURLEY, T.E. Region 1, Office of Director. 85/10/11. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33095-180-33095-228.

-8510220069 SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985.
* Region 1, Office of Director. 85/10/11. 46pp. 33095-182-33095-228.

8510240585 Forwards public version of page changes to emergency procedures document. W/851021 release memo. SELMAN, M. Consolidated Edison Co. of New York, Inc. 85/10/11. MURLEY, T.E. Region 1, Office of Director. 3pp. 33185-219-33185-235.

-8510240592 Public version of page changes to emergency procedures document.
* Consolidated Edison Co. of New York, Inc. 85/09/30. 15pp. 33185-221-33185-235.

8510210155 Forwards Insp Rept 50-247/85-23 on 850901-30. No violation observed. COLLINS, S.J. Region 1, Office of Director. 85/10/17. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33071-128-33071-137.

-8510210156 Insp Rept 50-247/85-23 on 850901-30. No violation identified. Major areas inspected: onsite activities, including operational safety verification, maint, surveillance, review of monthly rept, TMI action items & security event. LIMROTH, D., NORRHOLM, L. Region 1, Office of Director. 85/10/07. 8pp. 33071-130-33071-137.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents. App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-8510080357 Documents conclusions reached during ACRS 122nd meeting re Midland Plant Units 1 & 2 request for exemption to allow certain const & ESF instrumentation for Indian Point 2. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/06/17. MORRIS, P.A. Atomic Energy Commission. 2pp. 32929-359-32929-360.

P. Operating license stage documents & correspondence

8510310174 Forwards Amend 97 to License DPR-26 & safety evaluation. Amend revises Tech Specs to limit overtime for critical shift job positions, changes audit frequency & clarifies QA record retention requirements. NEIGHBORS, J.D. Operating Reactors Branch 1. 85/09/30. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 2pp. 33277-306-33277-316.

-8510310179 Amend 97 to License DPR-26, revising overtime procedure for safety-related positions, changing audit frequency of emergency preparedness program & safety-related contingency plan & clarifying record retention requirements. VARGA, S.A. Operating Reactors Branch 1. 85/09/30. 7pp. 33277-308-33277-314.

-8510310183 Safety evaluation supporting Amend 97 to License DPR-26.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 2pp. 33277-315-33277-316.

8510090299 Discusses discrepancies identified in Mar 1985 edition of NUREG-0020, "Licensed Operating Reactors Status Summary Rept." Error originated in Apr 1984 edition. Excerpts from NUREG-0020 & Apr 1984 monthly operating rept encl. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/02. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 6pp. 32947-107-32947-112.

8510110229 Requests assistance in reviewing encl util 850806 application for amend to License DPR-26 re anticipatory reactor trip upon turbine trip. Completion requested by 851130. THOMPSON, H.L. Division of Licensing. 85/10/02. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33012-186-33012-234.

8510160220 Responds to 850909 ltr transmitting conclusion requiring reactor trip bypass breaker status indication on main control board. Requests justification of human factors implications of ATWS events. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/09. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33022-240-33022-242.

8510180039 Responds to request for addl info re const matls & pressure bearing capability of proposed temporary closure plate. per 850806 request to revise Tech Specs. Capability of 3 psi & use of carbon steel as const matl proposed. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/09. VARGA, S.A. Operating Reactors Branch 1. 1p. 33063-059-33063-059.

8510300033 Forwards request for addl info re util 850719 submittal concerning hydraulic snubber Tech Specs. Justification for deviation from STS should be provided within 60 days. VARGA, S.A. Operating Reactors Branch 1. 85/10/11. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 4pp. 33259-353-33259-356.

8510220226 Discusses proposed schedule for implementing 10CFR50.62 to mitigate consequences of ATWS events. Final design & implementation schedule will be submitted within 6 months following receipt of SER. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/13. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33088-150-33088-151.

8510220118 Forwards supporting info re boron injection tank removal, including methodology to derive pressure/energy relation for dry containment & containment capability study pressure vs steam air internal energy. per 851011 request. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. THOMPSON, H.L. Division of Licensing. 7pp. 33081-357-33081-363.

8510250068 Advises that response to 850909 request for addl info re seismic qualification of auxiliary feedwater sys or schedule will be submitted by 851216. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. VARGA, S.A. Operating Reactors Branch 1. 1p. 33173-145-33173-145.

8510250239 Forwards responses to Questions 2-5 contained in 850424 request for addl info re NUREG-0737, Item I.D.1, "Performance Testing of Relief & Safety Valves." O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. VARGA, S.A. Operating Reactors Branch 1. 12pp. 33172:105-33172:116.

8510250192 Forward: response to 841026 & 850827 questions re inservice testing program summary, proposed changes for Rev 1 to summary for Jul 1984 - June 1994 & new relief requests initiated by util. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/22. VARGA, S.A. Operating Reactors Branch 1. 60pp. 33173:187-33173:248.

8510280292 Notices of 851025 meeting at Region 1 ofc to discuss radiation protection program upgrade, per M. L. telecon w/RR Bellamy. Radiation protection organization successfully met objective: of 850927 order modifying license. MURLEY, T.E. Region 1, Office of Director. 85/10/22. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33192:345-33192:346.

8510290196 Responds to request for addl info re 850806 application for amend to License DPR-26, deleting anticipatory reactor trip upon turbine trip below 35% power. Valves of moderator density & Doppler power coefficients provided. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/24. VARGA, S.A. Operating Reactors Branch 1. 2 pp. 33233:249-33233:250.

Q. Inspection reports, IE Bulletins & correspondence

8510040123 Responds to NRC 850826 ltr re violations noted in Insp Rept 50-247/85-18. Corrective actions: caution tags for Valves SWN-51-1 through 5 reissued & properly logged & latest central control room drawing index posted. SELMAN, M. Consolidated Edison Co. of New York, Inc. 85/09/26. COLLINS, S.J. Region 1, Office of Director. 3pp. 32851:200-32851:202.

8510070544 Forwards Insp Rept 50-247/85-21 on 850801-31. No violations observed. COLLINS, S.J. Region 1, Office of Director. 85/09/27. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 32883:244-32883:250.

8510070550 Insp Rept 50-247/85-21 on 850801-31. No violations identified. Major areas inspected: licensee action on previously identified insp items, operational safety verification, maint. surveillance & review of monthly rept. LIMROTH, D., NORRHOLM, L. Region 1, Office of Director. 85/09/24. 6pp. 32883:246-32883:250.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510180249 Forwards "10-Yr Inservice Insp & Testing Program (Jul 1984 - June 1994). Quality Group A,B & C Components & Supports." First exams will be initiated during next refueling outage scheduled to begin in Jan 1986. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/09/30. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33022:139-33022:140.

8510180251 "10-Yr Inservice Insp & Testing Program (Jul 1984 - June 1994). Quality Group A,B & C Components & Supports." Consolidated Edison Co. of New York, Inc. 85/09/30. 83pp. 33022:141-33022:222.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180498 Notification of 851113-14 meetings w/util in King of Prussia, PA to discuss second 10-yr inservice insp program. SLOSSON, M.M. Operating Reactors Branch 1. 85/10/07. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33079:001-33079:003.

8510220064 Forwards SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985. Meeting scheduled on 851025 to discuss assessments & plans for performance improvement. MURLEY, T.E. Region 1, Office of Director. 85/10/11. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33095:180-33095:228.

8510220069 SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985. * Region 1, Office of Director. 85/10/11. 46pp. 33095:182-33095:228.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510210155 Forwards Insp Rept 50-247/85-23 on 850901-30. No violation observed. COLLINS, S.J. Region 1, Office of Director. 85/10/17. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33071:128-33071:137.

8510210156 Insp Rept 50-247/85-23 on 850901-30. No violation identified. Major areas inspected onsite: activities, including operational safety verification, maint. surveillance, review of monthly rept, TMI action items & security event. LIMROTH, D., NORRHOLM, L. Region 1, Office of Director. 85/10/07. 8pp. 33071:130-33071:137.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230193 Forwards Special Safety Insp Rept 50-247/85-22 on 850917-20. No violations noted. Util will repair cracking in joints of walls in fan house & evaluate need for further actions. EBNETER, S.D. Region 1, Office of Director. 85/10/18. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33101:195-33101:203.

8510230196 Insp Rept 50-247/85-22 on 850917-20. No violation noted. Major areas inspected: licensee actions in response to IE Bulletin 80-11, masonry wall design & verification of work performed in modifying affected blockwalls. VARELA, A.A., WIGGINS, J.T. Region 1, Office of Director. 85/10/10. 7pp. 33101:197-33101:203.

R. Periodic operating reports & related correspondence

8510290622 Forwards monthly operating rept for Sept 1985 & revised monthly operating data rept for Aug 1985. O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 1p. 33245:164-33245:171.

8510290627 Monthly operating rept for Sept 1985. KRIEGER, K. Consolidated Edison Co. of New York, Inc. 85/09/30. 5pp. 33245:165-33245:169.

8510290633 Revised monthly operating rept for Aug 1985. KRIEGER, K. Consolidated Edison Co. of New York, Inc. 85/08/31. 2pp. 33245:170-33245:171.

S. Reportable occurrences, LERs & related correspondence

8510250178 LER 85-013-00 on 851004, leakage into containment from all sources exceeded Tech Spec limit of 10 gpm for combined leakage. Source of leakage traced to tube in fan cooler unit water box. Tubing replaced. W/851018 ltr. ELLWANGER, J.R., O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. 4pp. 33190:203-33190:206.

8510290071 LER 85-009-00 on 850920, short circuit between phases of main transformer caused turbine generator trip. Caused by river water spray from condenser water box exhaust. Changes made to exhaust to eliminate spray. W/851018 ltr. ELLWANGER, J.R., O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. 4pp. 33242:314-33242:317.

8510300030 LER 85-010-00 on 850923, reactor tripped during restart. Caused by operator failure to anticipate steam generator swell at time of synchronization of generator output. Event & measures implemented reviewed. W/851023 ltr. ELLWANGER, J.R., O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/23. 4pp. 33256:242-33256:245.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8510220166 Forwards revised onsite & offsite maps for Environ Group Procedure 2. Directions for updating procedure listed. LICARI, K. Commonwealth Edison Co. 85/08/22. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33083:296-33083:297.

8510080506 Revised emergency plan implementing procedures, including Rev 1 to ED-24 re determining recommended offsite protective action response option for general public & Rev 2 to ED-2 re flood prediction sys. KENEALY, D., BENNETT, C.J. Commonwealth Edison Co. 85/08/31. 150pp. 32943:090-32943:249.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:288.

8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114. KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33109:001-33109:002.

8510110008 Forwards "DCRDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." Most requirements of Suppl 1 to NUREG-0737 satisfied. Proposed resolutions to human engineering deficiencies necessary within 120 days of ltr receipt. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 4pp. 32999:183-32999:251.

8509170394 "DCRDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." * Science Applications International Corp. (formerly Science Applications, Inc.) NRC-03-82-096. 85/08/30. NRC - No Detailed Affiliation Given. 65pp. 32999:187-32999:251.

8510210064 Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/two oversize drawings. KENEALY, D.M., BENNETT, C.J., GOLDEN, J.C. Commonwealth Edison Co. 85/10/15. 120pp. 33082:283-33083:043.

32 DOCKETED ITEMS

8510230049 Forwards addl exemption request re structural steel & cold shutdown analyses & fire protection. Util committed to continuing evaluation of all safe shutdown sys & equipment to meet App R Fee paid. W/o encls.
WOJNAROWSKI, J. Commonwealth Edison Co. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33258-175-33258-256.

8510230125 Ack receipt of FEMA 850910 ltr including revised schedule of corrective actions submitted by State of IL for recommendations identified as result of 850423 exercise. FEMA & Region V determined responses adequate.
SHAFFER, W.D. Region 3, Office of Director. 85/10/17. REED, C. Commonwealth Edison Co. 7pp. 33101-046-33101-047.

8510240324 Rev 5 to Emergency Plan Implementing Procedure EG-11, "Environ Sample Collection Procedures for Air, Water, Milk, Soil & Vegetation." W/851017 ltr.
KENEALY, D., MOORE, R.D., GOLDEN, J.C. Commonwealth Edison Co. 85/10/17. DENTON, H.R. Record Services Branch (Document Control Desk). 11pp. 33153-327-33153-338.

J. Insurance & indemnity information

8510300064 Forwards unexecuted Amends 23.4 & 5 to Indemnity Agreements B-10-B-97 & B-84, respectively, modifying location descriptions to conform to facility forms.
DINITZ, J. Office of State Programs, Director. 85/10/25. OSTER, J. Commonwealth Edison Co. 4pp. 33261-353-33261-356.

P. Operating license stage documents & correspondence

8510030130 Forwards TR UR 85-225, "ASEA-Atom BWR Control Blades for US BWRs," for review & approval. Licensing of Quad Cities Unit 1 Reload 9 & Millstone Unit 1 reload dependent on approval of rept. Fee paid.
TENERZ, E. ASEA Atom, Inc. 85/09/24. BERNARD, H. NRC - No Detailed Affiliation Given. 2pp. 32878-035-32878-075.

8510080445 Forwards safety evaluation for storage & handling of liquid propane gas, in response to NRC request for info re 841204 proposed amend to Tech Specs supporting use of mobile vol reduction sys. Diagram of storage configuration encl.
WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 12pp. 32922-034-32922-045.

8510080452 Requests approval of proposed alternate methods & criteria for performing seismic evaluation, including criteria described in FSAR. Forwards "Alternate Seismic Evaluation Criteria/Methodology..." Fee paid.
WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921-327-32921-356.

-8510080456 "Alternate Seismic Evaluation Criteria/Methodology, Quad-Cities Nuclear Station, Units 1 & 2, Dresden Nuclear Station, Units 2 & 3."
* Commonwealth Edison Co. 85/09/30. 28pp. 32921-329-32921-356.

8510080466 Forwards response to questions re plan to replace recirculation sys piping during Fall 1985 refueling outage. Response to submittal indicating concurrence w/ plan requested.
WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32922-001-32922-005.

8510080514 Forwards Rev 0 to COM-83-042, "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2."
WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. THOMPSON, H.L. Division of Licensing. 2pp. 32920-134-32920-216.

-8510080515 Rev 0 to "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2."
ANDERSSON, O., GAVULA, J.A., CRAWFORD, R.M. NUTEC Engineers, Inc. COM-83-042 R00. 85/09/23. 70pp. 32920-136-32920-216.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-175-33031-150.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

8510150204 Forwards projected schedule for complying w/10CFR50.62 per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

8510310133 Informs that 851003 secondary containment leak rate test results indicate 0.255 inch water negative pressure for atmosphere. Results meet requirement of Tech Spec Section 4.7.C.1.C.
SCOTT, D.J. Commonwealth Edison Co. 85/10/18. KEPPLER, J.G. Region 3, Office of Director. 1p. 33290-350-33290-350.

Q. Inspection reports, IE Bulletins & correspondence

8510080517 Forwards Insp Repts 50-010/85-14, 50-237/85-31 & 50-249/85-27 on 850816-28. No violations noted.
NORELIUS, C.E. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32920-068-32920-074.

-8510080518 Insp Repts: 50-010/85-14, 50-237/85-31 & 50-249/85-27 on 850816-28. No violations noted. Major areas inspected: licensee prompt & long-term actions in response to 850816 loss of offsite power.
WRIGHT, G.C. Region 3, Office of Director. 85/09/23. 5pp. 32920-070-32920-074.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Response to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep. Energy & Commerce. PERCY Senate. MADIGAN House of Rep. 2pp. 33109-001-33109-002.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510210218 Forwards Insp Repts 50-237/85-32 & 50-249/85-28 on 850916-19 & notice of violation.
REYES, L.A. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33074-091-33074-097.

-8510210220 Notice of violation from insp on 850916-19.
REYES, L.A. Region 3, Office of Director. 85/10/16. 1p. 33074-093-33074-093.

-8510210223 Insp Repts 50-237/85-32 & 50-249/85-28 on 850916-19. Violation noted: review of test results of Procedure DTS-300-2, "CRD Scram Testing & Scram Valve Timing Test," not documented.
TAYLOR, T.E., HAWKINS, F.C. Region 3, Office of Director. 85/10/15. 4pp. 33074-094-33074-097.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250231 Responds to NRC 850918 ltr re violations noted in Insp Repts 50-237/85-29 & 50-249/85-24. Corrective actions personnel required to receive training on 850605 QA rev trained & training dept will issue reminder memos more frequently.
FARRAR, D.L. Commonwealth Edison Co. 85/10/18. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33169-033-33169-034.

S. Reportable occurrences, LERs & related correspondence

8510010234 PNO-III 85-084 on 850919, reactor scrambled due to mechanic bumping circuit board. Reactor bldg evacuated due to steam leak & high radiation alarms. Four people slightly contaminated.
WRIGHT, G., CHRISSTIMOS, N. Region 3, Office of Director. 85/09/20. 1p. 32800-187-32800-187.

8510010208 LER 85-016-00 on 850826, equipment attendant observed HPCI room cooler fan breaker emitting smoke. Caused by shorted motor contactor coil. Coil & auxiliary contacts replaced & Maint Procedure DMP 7300-5 performed W/850923 ltr.
WOJNAROWSKI, J., SCOTT, D.J. Commonwealth Edison Co. 85/09/23. 3pp. 32809-201-32809-203.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewpoints encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965-021-32965-047.

8510090381 LER 85-017-00 on 850905, fuel pool Channel B high radiation trip occurred, causing ventilation sys trip & starting gas treatment sys. Caused by chips in water-filled bucket used for cleanup. Bucket immersed in fuel pool W/851003 ltr.
FLAHERTY, J.M., SCOTT, D.J. Commonwealth Edison Co. 85/10/03. 3pp. 32946-131-32946-133.

8510240174 LER 85-018-00 on 850919, unit tripped from APRM hi-hi level scram. Caused by personnel error. Several changes will be made to scram procedure to ensure scram discharge val vent valves remain closed W/851018 ltr.
MCCABE, B., SCOTT, D.J. Commonwealth Edison Co. 85/10/18. 5pp. 33156-335-33156-339.

8510300279 LER 85-019-00 on 850923, observed that reactor not vented at less than 149 F. Caused by failure of shutdown procedure to completely outline conditions to vent reactor. Reactor head vents opened W/851022 ltr.
MOY, M., SCOTT, D.J. Commonwealth Edison Co. 85/10/22. 4pp. 33258-093-33258-096.

8510300304 LER 85-020-00 on 850925, no particulate sample for reactor bldg ventilation sys collected for wk. Caused by failure to replace screen in filter holder after last sample. Signs to be posted in future. W/851024 ltr. WOJCIULEWICZ, T., SCOTT, D.J. Commonwealth Edison Co. 85/10/24. 3pp. 33257:359-33257:361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114. KAMMERER, C. Office of Congressional Affairs. 84/05/10. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DIXON Senate. 2pp. 33109:001-33109:002.

V. Operator Examinations

8508240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

8510210041 Advises that operator & senior operator written & oral exams scheduled for wk of 860127. List of required ref matl & description of requirements for conducting exams encl. License applications required 60 days prior to exam. REYES, L.A. Region 3, Office of Director. 85/10/15. REED, C. Commonwealth Edison Co. 5pp. 33072:313-33072:317.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8510040088 Forwards comments on Rev 2 to safeguards contingency plan, per 850813 ltr. Changes effective immediately. Comments will be included in next rev W/o encl. WILLIAMS, J.W. Florida Power & Light Co. 85/09/23. GRACE, J.N. Region 2, Office of Director. 1p. 32851:191-32851:191.

8510150324 Revised emergency plan implementing procedures, including 1101, "Duties of Emergency Control Officer, Offsite Emergency Organization" & 1102, "Duties of Recovery Manager, Offsite Emergency Organization." W/851004 ltr. WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. GRACE, J.N. Region 2, Office of Director. 51pp. 33009:001-33009:051.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. BROWNLEE, V.L. Region 2, Office of Director. 85/10/04. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33096:332-33096:335.

-8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination. STANSBERRY, W. Region 2, Office of Director. 85/09/26. 2pp. 33096:334-33096:335.

8510160023 Revised "Procedures Generation Package." W/851009 ltr. WILLIAMS, J.W. Florida Power & Light Co. 85/10/09. VARGA, S.A. Operating Reactors Branch 1. 51pp. 33024:102-33024:152.

8510170076 Requests schedule exemptions to 10CFR50.48, App R requirements detailed in Attachment A, per Aug 1985 commitment to submit rept of add'l scope of App R work. W/three oversized drawings. Fee paid. WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. VARGA, S.A. Operating Reactors Branch 1. 24pp. 33036:025-33036:046.

8510250396 Revised emergency plan implementing procedures, including EP-20101 re duties of emergency coordinator & EP-20102 re duties of individual discovering emergency condition. W/851022 ltr. YOUNG, H.T., WILLIAMS, J.W. Florida Power & Light Co. 85/10/22. GRACE, J.N. Region 2, Office of Director. 93pp. 33171:220-33171:301.

G. Adjudicatory correspondence

8510160133 Motion for extension until 851025 to respond to licensee 850920 motion for summary disposition. Certificate of Svc encl. HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Lorion, J. HODDER, M.H. Hodder, M.H. #485 782. 85/10/08. Atomic Safety and Licensing Board Panel. 4pp. 33028:128-33028:131.

8510180140 Motion for 10-day extension of time to respond to licensee 850920 motion for summary disposition of intervenor contention. Served on 851015. Granted for ASLB on 851015 by RA Lazo. HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Hodder, M.H. #485 787. 85/10/15. Atomic Safety and Licensing Board Panel. 3pp. 33058:255-33058:257.

8510180214 Motion to establish schedule for hearings re increased fuel enrichment. Intervenor & NRC support proposed schedule. Certificate of Svc encl. FRANTZ, H.F. Florida Power & Light Co. FRANTZ, H.F. Newman & Holtzinger. #485 798. 85/10/15. Atomic Safety and Licensing Board Panel. 4pp. 33062:297-33062:300.

8510180320 Motion to establish schedule for hearings re spent fuel pool expansion. Motion should be granted. W/Certificate of Svc. FRANTZ, S.P. Florida Power & Light Co. FRANTZ, S.P. Newman & Holtzinger. #485 797. 85/10/15. Atomic Safety and Licensing Board Panel. 4pp. 33060:354-33060:357.

8510180344 Response supporting licensee 850920 second motion for summary disposition of Contention (d) re reduction in DNBR. No genuine issue of matl fact exists. YOUNG, M.A. Hearing Branch 4. #485 789. 85/10/15. Atomic Safety and Licensing Board Panel. 5pp. 33060:126-33060:147.

-8510180347 Affidavit of Yi-Hsiung Hsi addressing Contention (d) re three issues stated in ASLB 850816 order denying licensee motion for summary disposition. HSI, Y. Core Performance Branch. 85/10/15. 10pp. 33060:131-33060:147.

8510310323 Response opposing util 850920 second motion for summary disposition re Contention (d). Util failure to support motion & to show that no genuine issue of matl fact exists should cause motion to be denied. Certificate of Svc encl. HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Lorion, J. HODDER, M.H. Hodder, M.H. #485 972. 85/10/25. Atomic Safety and Licensing Board Panel. 5pp. 33272:049-33272:053.

8510310253 Forwards corrected intervenor response to licensee statement of matl fact as to which no genuine issue to be heard w/respect to intervenor Contention (d) re vessel flux reduction. HODDER, M.H. Hodder, M.H. HODDER, M.H. Center for Nuclear Responsibility. #485 994. 85/10/26. LAZO, R.M., LUEBKE, E.A., COLE, R.F. Atomic Safety and Licensing Board Panel. 1p. 33273:090-33273:096.

-8510310257 Corrected intervenor response to licensee statement of matl fact as to which no genuine issue to be heard w/respect to intervenor Contention (d). Certificate of Svc encl. HODDER, M.H. Center for Nuclear Responsibility. 85/10/25. Atomic Safety and Licensing Board Panel. 6pp. 33273:091-33273:096.

8510310281 Notices of util disagreement w/intervenor request for extension until 851109 to respond to licensee 850920 motion for summary disposition & 851015 supporting response. Certificate of Svc encl. REIS, H.F. Newman & Holtzinger. REIS, H.F. Florida Power & Light Co. #485 959. 85/10/28. HODDER, M.H. Hodder, M.H. 4pp. 33273:236-33273:239.

8510310365 First set of interrogatories, requesting all documents, books, repts & papers intended for use in conducting cross-examination of witnesses testifying on Contention 3.W/ Certificate of Svc. Related correspondence. REIS, H.F. Florida Power & Light Co. REIS, H.F. Newman & Holtzinger. #485 961. 85/10/28. Center for Nuclear Responsibility. 6pp. 33271:319-33271:324.

8510310434 First set of interrogatories to Ctr for Nuclear Responsibility & J Lorion re spent fuel pool expansion. Certificate of Svc encl. Related correspondence. REIS, H.F. Florida Power & Light Co. REIS, H.F. Newman & Holtzinger. #485 962. 85/10/28. Center for Nuclear Responsibility. 11pp. 33273:017-33273:027.

P. Operating license stage documents & correspondence

8510010361 Forwards add'l response to Generic Ltr 83-28, Item 1.2 re post-trip review, data & info capability, per 850815 telcon & NRC 850719 draft technical evaluation rept. Reliability of digital data processing sys also discussed. WILLIAMS, J.W. Florida Power & Light Co. 85/09/27. VARGA, S.A. Operating Reactors Branch 1. 24pp. 32801:208-32801:231.

8510030231 Notification of 851003 meeting w/util in Bethesda, MD to discuss fluence calculational methods used in flux surveillance program. McDONALD, D.G. Operating Reactors Branch 1. 85/09/27. VARGA, S.A. Operating Reactors Branch 1. 3pp. 32849:197-32849:199.

8510180542 Confirms 850924 telcon re 851009 enforcement conference in Atlanta, GA to discuss turbine runback sys mod & reporting. Proposed meeting agenda encl. GRACE, J.N. Region 2, Office of Director. 85/10/08. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33068:272-33068:273.

8510170091 Advises that response to Generic Ltr 85-12 re implementation of TMI Action Item I.K.3.5, "Automatic Trip of Reactor Coolant Pumps" & safety evaluation will be provided by 851220. WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. VARGA, S.A. Operating Reactors Branch 1. 1p. 33036:233-33036:233.

8510180061 Withdraws part of 840402 application for amendments to Licenses DPR-31 & DPR-41, dealing w/operability/surveillance requirements referencing inservice test programs. Revised pages encl. WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. THOMPSON, H.L. Division of Licensing. 18pp. 33054:095-33054:112.

8510180023 Advises of need to evaluate NRC SER impact re Westinghouse Owners Group ATWS mitigating sys actuation circuitry generic design program to determine best logic implementation schedule will be submitted 90 days after SER issuance. WILLIAMS, J.W. Florida Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33054:017-33054:017.

8510230078 Forwards add'l info re Category C-2 steam generator tube insps, completing response to Generic Ltr 85-02. Add'l tubes will be inspected on case-by-case basis. WILLIAMS, J.W. Florida Power & Light Co. 85/10/16. THOMPSON, H.L. Division of Licensing. 2pp. 33102:216-33102:217.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180543 Summarizes 850924 meeting w/util in Atlanta, GA re current status of performance enhancement program. WALKER, R.D. Region 2, Office of Director. 85/10/02. WILLIAMS, J.W. Florida Power & Light Co. 1p. 33068:274-33068:274.

34 DOCKETED ITEMS

8510220387 Forwards Insp Repts 50-250/85-29,50-251/85-29,50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/04. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33096:332-33096:335.

-8510220396 Insp Repts 50-250/85-29,50-251/85-29,50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY,W. CUNNINGHAM,A.L. Region 2, Office of Director. 85/09/26. 2pp. 33096:334-33096:335.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230027 Forwards Press Release 84-16 re proposed civil penalty in amount of \$40,000 against util for alleged violation of radiation protection requirements during 831014 incident.
KAMMERER,C. Office of Congressional Affairs. 84/01/02. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:274-33108:275.

-8510230222 Forwards Press Release 84-91 re NRC proposed civil penalty in amount of \$150,000 against util for failure to identify two auxiliary feedwater pumps out of operation & failure to take compensatory action.
KAMMERER,C. Office of Congressional Affairs. 84/07/20. OTTINGER,R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. CHILES Senate. 2pp. 33109:096-33109:097.

-8510230293 Forwards Press Release 84-141 of NRC mitigation of proposed civil penalty in amount of \$40,000 against util for violations of radiation protection requirements. Two workers entered locked high radiation area.
KAMMERER,C. Office of Congressional Affairs. 84/12/06. OTTINGER,R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. CHILES Senate. 2pp. 33109:119-33109:120.

8510150224 Forwards Safety Sys Functional Insp Repts 50-250/85-32 & 50-251/85-32 on 850826-30 & 0909-13 & summarizes comments & responses re auxiliary feedwater sys made during 850913 exit meeting.
TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 85/10/07. WILLIAMS,J.W. Florida Power & Light Co. 3pp. 33033:255-33033:257.

-8510150228 Safety Sys Functional Insp Repts 50-250/85-32 & 50-251/85-32 on 850826-0913. Ten potential enforcement findings noted during auxiliary feedwater sys insp in areas of maint, operations, surveillance, QA, training & design changes & mod.
CALLAN,L.J., SMITH,J.D., MARTIN,T.O. Division of Inspection Programs (Post 850212). 85/10/01. 33pp. 33033:258-33033:290.

8510310203 Responds to violations noted in Insp Repts 50-250/85-26 & 50-251/85-26. Corrective actions revs to Administrative Procedure 0190.19 will be discussed w/ foremen & supervisors to ensure awareness of work order guidelines.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/09. GRACE,J.N. Region 2, Office of Director. 10pp. 33274:017-33274:026.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510150022 IE Info Notice 85-080. "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510210046 Forwards "1985 Inservice Insp Summary Rept for Turkey Point Nuclear Power Plant Unit 3," per ASME Code. Owner data rept of repairs or replacement & data rept for eddy current exam results included.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/16. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33073:048-33073:208.

-8510210058 "1985 Inservice Insp Summary Rept for Turkey Point Nuclear Power Plant Unit 3."
* Florida Power & Light Co. MCI-PTP-85-300-1. 85/12/31. 150pp. 33073:049-33073:208.

8510230078 Forwards addl info re Category C-2 steam generator tube insps, completing response to Generic Ltr 85-02. Addl tubes will be inspected on case-by-case basis.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/16. THOMPSON,H.L. Division of Licensing. 2pp. 33102:216-33102:217.

8510150025 IE Info Notice 85-081. "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082. "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010477 Monthly operating repts for Jul 1985 W/850814 ltr.
GRANT,N.W. WILLIAMS,J.W. Florida Power & Light Co. 85/07/31. 18pp. 32809:082-32809:099.

S. Reportable occurrences, LERs & related correspondence

8510080333 LER 85-025-00 on 850827 & 30, during App R safe shutdown review, addl circuits that may require protection, rerouting or circuit mods identified. Caused by addl NRC guidance. Fire watch expanded. W/850930 ltr.
TEUTBERG,R.L., WILLIAMS,J.W. Florida Power & Light Co. 85/09/30. 4pp. 33298:197-33298:200.

8510150091 Summary of Operating Reactors Events Meeting 95-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON,H.L. Division of Licensing. 23pp. 33030:243-33030:265.

8510170104 LER 85-026-00 on 850911, boric acid storage tank A found w/ concentration of 22,800 parts per million. Caused by batch of boron added to tank A earlier in day. Tank B lined up to Unit 3 & 200 gallons of water added to tank A. W/851011 ltr.
HART,R.D., WILLIAMS,J.W. Florida Power & Light Co. 85/10/11. 2pp. 33052:067-33052:068.

8510280003 LER 85-030-00 on 850919, Tech Spec monthly internal surveillance for updating target axial flux difference exceeded. Caused by personnel error. New target axial flux difference calculated from measured values. W/851021 ltr.
TEUTBERG,R.L., WILLIAMS,J.W. Florida Power & Light Co. 85/10/21. 2pp. 33194:312-33194:313.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230027 Forwards Press Release 84-16 re proposed civil penalty in amount of \$40,000 against util for alleged violation of radiation protection requirements during 831014 incident.
KAMMERER,C. Office of Congressional Affairs. 84/01/02. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:274-33108:275.

-8510230222 Forwards Press Release 84-91 re NRC proposed civil penalty in amount of \$150,000 against util for failure to identify two auxiliary feedwater pumps out of operation & failure to take compensatory action.
KAMMERER,C. Office of Congressional Affairs. 84/07/20. OTTINGER,R.L. House of Rep., Energy & Commerce. 2pp. 33109:096-33109:097.

-8510230293 Forwards Press Release 84-141 of NRC mitigation of proposed civil penalty in amount of \$40,000 against util for violations of radiation protection requirements. Two workers entered locked high radiation area.
KAMMERER,C. Office of Congressional Affairs. 84/12/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:119-33109:120.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510180520 Informs that operator & senior operator licensing & requalification exam scheduled for wks of 860203 & 10. Encl listed ref matl should be furnished by 851125. Delay necessitates postponement of exam administration.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/02. WILLIAMS,J.W. Florida Power & Light Co. 5pp. 33067:352-33067:356.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

8510040088 Forwards comments on Rev 2 to safeguards contingency plan, per 850813 ltr. Changes effective immediately. Comments will be included in next rev. W/o encl.
WILLIAMS,J.W. Florida Power & Light Co. 85/09/23. GRACE,J.N. Region 2, Office of Director. 1p. 32851:191-32851:191.

8510150324 Revised emergency plan implementing procedures, including 1101, "Duties of Emergency Control Officer, Offsite Emergency Organization" & 1102, "Duties of Recovery Manager, Offsite Emergency Organization." W/851004 ltr.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/04. GRACE,J.N. Region 2, Office of Director. 51pp. 33009:001-33009:051.

8510220387 Forwards Insp Repts 50-250/85-29,50-251/85-29,50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/04. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33096:332-33096:335.

-8510220396 Insp Repts 50-250/85-29,50-251/85-29,50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY,W. Region 2, Office of Director. 85/09/26. 2pp. 33096:334-33096:335.

8510160023 Revised "Procedures Generation Package." W/851009 ltr.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/09. VARGA,S.A. Operating Reactors Branch 1. 51pp. 33024:102-33024:152.

8510170076 Requests schedule exemptions to 10CFR50.48, App R requirements detailed in Attachment A, per Aug 1985 commitment to submit rept of addl scope of App R work. W/three oversize drawings. Fee paid.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/11. VARGA,S.A. Operating Reactors Branch 1. 24pp. 33036:025-33036:046.

8510250396 Revised emergency plan implementing procedures, including EP-20101 re duties of emergency coordinator & EP-20102 re duties of individual discovering emergency condition. W/ 851022 ltr.
YOUNG, H.T., WILLIAMS, J.W. Florida Power & Light Co. 85/10/22. GRACE, J.N. Region 2, Office of Director. 93pp. 33171-220-33171-301.

G. Adjudicatory correspondence

8510160133 Motion for extension until 851025 to respond to licensee 850920 motion for summary disposition. Certificate of Svc encl.
HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Lorion, J. HODDER, M.H. Hodder, M.H. #485 782. 85/10/08. Atomic Safety and Licensing Board Panel. 4pp. 33028-128-33028-131.

8510180140 Motion for 10-day extension of time to respond to licensee 850920 motion for summary disposition of intervenor contention. Served on 851015. Granted for ASLB on 851015 by RA Lazo.
HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Hodder, M.H. #485 787. 85/10/15. Atomic Safety and Licensing Board Panel. 3pp. 33058-255-33058-257.

8510180214 Motion to establish schedule for hearings re increased fuel enrichment. Intervenor's & NRC support proposed schedule. Certificate of Svc encl.
FRANTZ, H.F. Florida Power & Light Co. FRANTZ, H.F. Newman & Holtzinger. #485 796. 85/10/15. Atomic Safety and Licensing Board Panel. 4pp. 33062-297-33062-300.

8510180320 Motion to establish schedule for hearings re spent fuel pool expansion. Motion should be granted w/ Certificate of Svc.
FRANTZ, S.P. Florida Power & Light Co. FRANTZ, S.P. Newman & Holtzinger. #485 797. 85/10/15. Atomic Safety and Licensing Board Panel. 4pp. 33060-354-33060-357.

8510180344 Response supporting licensee 850920 second motion for summary disposition of Contention (d) re reduction in DNBR. No genuine issue of fact exists.
YOUNG, G.M.A. Hearing Branch 4. #485 789. 85/10/15. Atomic Safety and Licensing Board Panel. 5pp. 33060-126-33060-147.

-8510180347 Affidavit of Yi-Hsiung Hsui addressing Contention (d) re three issues stated in ASLB 850816 order denying licensee motion for summary disposition.
HSUI, Y. Core Performance Branch. 85/10/15. 10pp. 33060-131-33060-147.

8510310323 Response opposing until 850920 second motion for summary disposition re Contention (d). Util failure to support motion & to show that no genuine issue of fact exists should cause motion to be denied. Certificate of Svc encl.
HODDER, M.H. Center for Nuclear Responsibility. HODDER, M.H. Lorion, J. HODDER, M.H. Hodder, M.H. #485 972. 85/10/25. Atomic Safety and Licensing Board Panel. 5pp. 33272-049-33272-053.

8510310253 Forwards corrected intervenor response to licensee statement of fact as to which no genuine issue to be heard w/ respect to intervenor Contention (d) re vessel flux reduction.
HODDER, M.H. Hodder, M.H. HODDER, M.H. Center for Nuclear Responsibility. #485 964. 85/10/26. LAZO, R.M., LUEBKE, E.A., COLE, R.F. Atomic Safety and Licensing Board Panel. 1p. 33273-090-33273-096.

-8510310257 Corrected intervenor response to licensee statement of fact as to which no genuine issue to be heard w/ respect to intervenor Contention (d). Certificate of Svc encl.
HODDER, M.H. Center for Nuclear Responsibility. 85/10/25. Atomic Safety and Licensing Board Panel. 6pp. 33273-091-33273-096.

8510310281 Notices of util disagreement w/ intervenor request for extension until 851109 to respond to licensee 850920 motion for summary disposition & 851015 supporting response. Certificate of Svc encl.
REIS, H.F. Newman & Holtzinger. REIS, H.F. Florida Power & Light Co. #485 959. 85/10/28. HODDER, M.H. Hodder, M.H. 4pp. 33273-236-33273-239.

8510310365 First set of interrogatories, requesting all documents, books, repts & papers intended for use in conducting cross-examination of witnesses testifying on Contention 3.W/ Certificate of Svc. Related correspondence.
REIS, H.F. Florida Power & Light Co. REIS, H.F. Newman & Holtzinger. #485 961. 85/10/28. Center for Nuclear Responsibility. 6pp. 33271-319-33271-324.

8510310434 First set of interrogatories to Ctr for Nuclear Responsibility & J Lorion re spent fuel pool expansion. Certificate of Svc encl. Related correspondence.
REIS, H.F. Florida Power & Light Co. REIS, H.F. Newman & Holtzinger. #485 962. 85/10/28. Center for Nuclear Responsibility. 11pp. 33273-017-33273-027.

P. Operating license stage documents & correspondence

8510010361 Forwards addl response to Generic Ltr 83-28, Item 1.2 re post-trip review, data & info capability, per 850815 telcon & NRC 850719 draft technical evaluation rept. Reliability of digital data processing sys also discussed.
WILLIAMS, J.W. Florida Power & Light Co. 85/09/27. VARGA, S.A. Operating Reactors Branch 1. 24pp. 32801-208-32801-231.

8510030231 Notification of 851003 meeting w/ util in Bethesda, MD to discuss fluence calculational methods used in flux surveillance program.
MCDONALD, D.G. Operating Reactors Branch 1. 85/09/27. VARGA, S.A. Operating Reactors Branch 1. 3pp. 32849-197-32849-199.

8510180542 Confirms 850924 telcon re 851009 enforcement conference in Atlanta, GA to discuss turbine runback sys mod & reporting. Proposed meeting agenda encl.
GRACE, J.N. Region 2, Office of Director. 85/10/08. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33068-272-33068-273.

8510170091 Advises that response to Generic Ltr 85-12 re implementation of TMI Action Item IIR 3.5, "Automatic Trip of Reactor Coolant Pumps" & safety evaluation will be provided by 851220.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. VARGA, S.A. Operating Reactors Branch 1. 1p. 33038-233-33038-233.

8510180081 Withdraws part of 840402 application for amendments to Licenses DPR-31 & DPR-41, dealing w/ operability/surveillance requirements referencing inservice test programs. Revised pages encl.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. THOMPSON, H.L. Division of Licensing. 18pp. 33054-095-33054-112.

8510180023 Advises of need to evaluate NRC SER impact re Westinghouse Owners Group ATWS mitigating sys actuation circuitry generic design program to determine best logic implementation schedule will be submitted 90 days after SER issuance.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33054-017-33054-017.

8510230078 Forwards addl info re Category C-2 steam generator tube insps, completing response to Generic Ltr 85-02. Addl tubes will be inspected on case-by-case basis.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/18. THOMPSON, H.L. Division of Licensing. 2pp. 33102-216-33102-217.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180543 Summarizes 850924 meeting w/ util in Atlanta, GA re current status of performance enhancement program.
WALKER, R.D. Region 2, Office of Director. 85/10/02. WILLIAMS, J.W. Florida Power & Light Co. 1p. 33068-274-33068-274.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/04. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33096-332-33096-335.

-8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY, W., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/26. 2pp. 33096-334-33096-335.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230189 Forwards Press Release 85-33 re NRC proposed fine against util for alleged violation of requirements concerning operation of reactor more than 5 days w/o intake CWS being operational.
KAMMERER, C. Office of Congressional Affairs. 85/03/04. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109-085-33109-086.

-8510230222 Forwards Press Release 84-91 re NRC proposed civil penalty in amount of \$150,000 against util for failure to identify two auxiliary feedwater pumps out of operation & failure to take compensatory action.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, House of Rep. CHILES, Senate. 2pp. 33109-096-33109-097.

-8510230293 Forwards Press Release 84-141 of NRC mitigation of proposed civil penalty in amount of \$40,000 against util for violations of radiation protection requirements. Two workers entered locked high radiation area.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, House of Rep. CHILES, Senate. 2pp. 33109-119-33109-120.

8510150224 Forwards Safety Sys Functional Insp Repts 50-250/85-32 & 50-251/85-32 on 850826-30 & 0909-13 & summarizes comments & responses re auxiliary feedwater sys made during 850913 ext meeting.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/07. WILLIAMS, J.W. Florida Power & Light Co. 3pp. 33033-255-33033-257.

-8510150228 Safety Sys Functional Insp Repts 50-250/85-32 & 50-251/85-32 on 850826-0913. Ten potential enforcement findings noted during auxiliary feedwater sys insp in areas of maint, operations, surveillance, QA, training & design changes & mod.
CALLAN, L.J., SMITH, J.D., MARTIN, T.O. Division of Inspection Programs (Post 850212). 85/10/01. 33pp. 33033-258-33033-290.

8510310203 Responds to violations noted in Insp Repts 50-250/85-26 & 50-251/85-26. Corrective actions re: Administrative Procedure 0190.19 will be discussed w/ foremen & supervisors to ensure awareness of work order guidelines.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/09. GRACE, J.N. Region 2, Office of Director. 10pp. 33274-017-33274-026.

8510180264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510230078 Forwards addl info re Category C-2 steam generator tube insps, completing response to Generic Ltr 85-02. Addl tubes will be inspected on case-by-case basis.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/18. THOMPSON, H.L. Division of Licensing. 2pp. 33102-216-33102-217.

36 DOCKETED ITEMS

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010477 Monthly operating repts for Jul 1985 W/850814 ltr.
GRANT,N.W., WILLIAMS,J.W. Florida Power & Light Co. 85/07/31. 18pp. 32809-082-32809-099.

S. Reportable occurrences, LERs & related correspondence

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director/div directors & representatives on events occurring since 850909 meeting list of attendees & viewgraphs encl.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON,H.L. Division of Licensing. 23pp. 33030-243-33030-265.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

8510230189 Forwards Press Release 85-33 re NRC proposed fine against util for alleged violation of requirements concerning operation of reactor more than 5 days w/o intake CWS being operational.
KAMMERER,C. Office of Congressional Affairs. 85/03/04. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-085-33109-086.

8510230222 Forwards Press Release 84-91 re NRC proposed civil penalty in amount of \$150,000 against util for failure to identify two auxiliary feedwater pumps out of operation & failure to take compensatory action.
KAMMERER,C. Office of Congressional Affairs. 84/07/20. OTTINGER,R.L. House of Rep., Energy & Commerce. 2pp. 33109-096-33109-097.

8510230293 Forwards Press Release 84-141 of NRC mitigation of proposed civil penalty in amount of \$40,000 against util for violations of radiation protection requirements. Two workers entered locked high radiation area.
KAMMERER,C. Office of Congressional Affairs. 84/12/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-119-33109-120.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510180520 Informs that operator & senior operator licensing & requalification exam scheduled for wks of 860203 & 10 Encl listed ref mat should be furnished by 851125. Delay necessitates postponement of exam administration.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/02. WILLIAMS,J.W. Florida Power & Light Co. 5pp. 33067-352-33067-356.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510170197 Advises that full implementation of approved emergency plan completed at end of Sept. Implementation included training in new procedures & appropriate posting of procedures.
WOODALL,D.M. New Mexico, Univ. of, Albuquerque, NM. 85/10/11. THOMAS,C.O. Standardization & Special Projects Branch. 1p. 33052-001-33052-001.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510220166 Forwards revised onsite & offsite maps for Environ Group Procedure 2. Directions for updating procedure listed.
LICARI,K. Commonwealth Edison Co. 85/08/22. DENTON,H.R. Record Services Branch (Document Control Desk). 1p. 33083-296-33083-297.

8510040191 Rev 4 to Procedure QEP 520-1, "Training Procedure for Assignment of Personnel to Generating Station Emergency Plan (GSEP) Positions & Associated Training Requirements." & Rev 1 to QEP 520-S2, "GSEP Assignment Request."
TOREN,H. Commonwealth Edison Co. 85/09/26. 7pp. 32851-039-32851-044.

8510080026 Forwards results of onsite audit of DCRDR per Suppl 1 to NUREG-0737. Schedule for implementation of corrective actions satisfactory in light of required supplemental rept.
VASSALLO,D.B. Operating Reactors Branch 2. 85/09/30. FARRAR,D.L. Commonwealth Edison Co. 3pp. 32926-267-32926-338.

8510080375 Revised station emergency procedures including Rev 30 to QEP 310-0, "Notification of Responsible Authorities" & Rev 16 to QEP 310-T3, "Prioritized Notification Listing."
* Commonwealth Edison Co. 85/09/30. 12pp. 32913-157-32913-168.

8510110146 Ack receipt of 850927 ltr re annual meeting w/offsite response agencies. NRC does not normally attend plant annual emergency preparedness training to offsite organizations. Notification of dates of training requested.
SHAFFER,W.D. Region 3, Office of Director. 85/10/08. TOREN,H. Commonwealth Edison Co. 1p. 32972-248-32972-249.

8510110148 Extends invitation to attend 851016 dinner meeting w/emergency plan offsite support agencies in Cordova, IL. Radiation protection & safety training class will be offered on 851017.
KALIVIANAKIS,N. Commonwealth Edison Co. 85/09/27. KEPPLER,J.G. Region 3, Office of Director. 1p. 32972-249-32972-249.

8510160168 Forwards Physical Security Insp Repts 50-254/85-26 & 50-265/85-29 on 850916-19. No noncompliance noted.
AXELSON,W.L. Region 3, Office of Director. 85/10/09. REED,C. Commonwealth Edison Co. 2pp. 33023-126-33023-128.

8510160177 Physical Security Insp Repts 50-254/84-26 & 50-265/85-29 on 850916-19. No noncompliance noted. Areas inspected: security program, testing & maint, locks, keys & combinations, lighting & alarm stations. Details withheld (ref 10CFR73.21).
PIRTLE,G.L., CREED,J.R. Region 3, Office of Director. 85/10/09. 1p. 33023-128-33023-128.

8510210064 Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director."
GORDON,J.C. Commonwealth Edison Co. 85/10/15. DENTON,H.R. Record Services Branch (Document Control Desk). 1p. 33082-282-33083-043.

8510210073 Revised emergency plan implementing procedures including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/two oversize drawings.
KENEALY,D.M. Commonwealth Edison Co. 85/10/15. 120pp. 33082-283-33083-043.

P. Operating license stage documents & correspondence

8510030130 Forwards TR UR 85-225, "ASEA-Atom BWR Control Blades for US BWRs," for review & approval. Licensing of Quad Cities Unit 1 Reload 9 & Millstone Unit 1 reload dependent on approval of rept. Fee paid.
TENERZ,E. ASEA Atom, Inc. 85/09/24. BERNARD,H. NRC - No Detailed Affiliation Given. 2pp. 32878-035-32878-075.

8510080452 Requests approval of proposed alternate methods & criteria for performing seismic evaluation including criteria described in FSAR Forwards "Alternate Seismic Evaluation Criteria/Methodology..." Fee paid.
WOJNAROWSKI,J. Commonwealth Edison Co. 85/09/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921-327-32921-356.

8510080456 "Alternate Seismic Evaluation Criteria/Methodology, Quad-Cities Nuclear Station, Units 1 & 2, Dresden Nuclear Station, Units 2 & 3."
* Commonwealth Edison Co. 85/09/30. 28pp. 32921-329-32921-356.

8510080514 Forwards Rev 0 to COM-83-042, "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2."
WOJNAROWSKI,J. Commonwealth Edison Co. 85/09/30. THOMPSON,H.L. Division of Licensing. 3pp. 32920-134-32920-216.

8510080515 Rev 0 to "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2."
ANDERSSON,O., GAVULA,J.A., CRAWFORD,R.M. NUTECH Engineers, Inc. COM-83-042 R00. 85/09/23. 70pp. 32920-136-32920-216.

8510170094 Forwards list of changes, tests & experiments completed during Sept 1985 summary of safety evaluation reported per 10CFR50.59 Mod M-4-1-81-17 initiated to install add'l supports on CRD insert & withdrawal lines.
TAMLYN,T.K. Commonwealth Edison Co. 85/10/01. CASE,E.G. Office of Nuclear Reactor Regulation, Director. 2pp. 33036-231-33036-232.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER,G.L. Commonwealth Edison Co. 85/10/03. KEPPLER,J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

8510110056 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

8510150204 Forwards projected schedule for complying w/10CFR50.62 per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER,G. Commonwealth Edison Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Main, Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

851000157 Ack receipt of 850923 ltr & fee of \$50,000 in payment of civil penalty imposed by NRC in 850809 order. Corrective actions will be examined during future insps.

AXELRAD, J.A. Director's Office, Office of Inspection and Enforcement. 85/11/04. O'CONNOR, J.J. Commonwealth Edison Co. 2pp. 32925-245-32925-246.

8510160168 Forwards Physical Security Insp Repts 50-254/85-26 & 50-265/85-29 on 850916-19. No noncompliance noted. Areas inspected: security program, testing & maint, locks, keys & combinations, lighting & alarm stations. Details withheld (ref 10CFR73.21).

PIRTLE, G.L., CREED, J.R. Region 3, Office of Director. 85/10/09. 1p. 33023-128-33023-128.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.

LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 72pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250153 Forwards Safety Insp Repts 50-254/85-24 & 50-265/85-27 on 850801-0930. No violation noted. CHRISOTIMOS, N. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33173-176-33173-186.

8510250158 Insp Repts 50-254/85-24 & 50-265/85-27 on 850801-0930. No violation or deviation noted. Major areas inspected: actions on previous insp rept, operation, maint, surveillance, procedures, review of routine & special repts & LER review.

WRIGHT, G.C. Region 3, Office of Director. 85/10/18. 9pp. 33173-178-33173-186.

8510310243 Forwards Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. Weaknesses identified re vendor-provided info & recommendations concerning safety-related sys & components. Items will be referred to Region III for action.

ZECH, G.G. Vendor Program Branch. 85/10/25. REED, C. Commonwealth Edison Co. 3pp. 33278-107-33278-123.

8510310247 Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. No potential enforcement items identified. Major areas inspected: licensee/vendor info interface, including sys for receipt, evaluation & implementation of actions.

PETTIS, R.L., MCINTYRE, R.P., MIEGEL, N.J. Director's Office, Office of Inspection and Enforcement. 85/10/09. 14pp. 33278-110-33278-123.

8510310327 Forwards Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. Potential enforcement finding re inadequate 10CFR21 review & one open item noted. Notification requested if notice of violation not issued within 1 month. W/o encl. GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/10/25. NORELIUS, C.E. Region 3, Office of Director. 1p. 33278-131-33278-131.

R. Periodic operating reports & related correspondence

8510170388 Monthly operating repts for Sept 1985 W/851001 ltr. KRONICH, C.L., TAMLYN, T.K. Commonwealth Edison Co. 85/09/30. 28pp. 33053-289-33053-316.

S. Reportable occurrences, LERs & related correspondence

8510110266 LER 85-016-00 on 850905 reactor bldg ventilation isolated & standby gas treatment initiated following spurious high alarm & fuel pool radiation monitor trip. Probably caused by electrical noise interference to monitor cable W/850924 ltr.

REED, J.L., KALIVIANAKIS, N. Commonwealth Edison Co. 85/09/24. 4pp. 32974-318-32974-321.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1 Rev commitment requested within 45 days.

ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

DOCKET 50-255 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8510010316 Temporary Change EI-85-023, Rev 6 to Emergency Implementing Procedure EI-4.1, "Technical Support Ctr."

* Consumers Power Co. 85/09/18. 3pp. 32802-353-32802-355.

8510150323 Rev 0 to Emergency Plan Implementing Procedure EI-12.2, "Assembly Area Personnel Lists."

* Consumers Power Co. 85/09/18. 2pp. 33009-052-33009-053.

8510150352 Rev 1 to Emergency Implementation Procedure EI-15.2, "Communications Drills."

BRUNET, J.R. Consumers Power Co. 85/09/18. 3pp. 33000-329-33000-332.

8510010128 Forwards Meeting Rept 50-255/85-22 on 850905.

SHAFFER, W.D. Region 3, Office of Director. 85/09/23. DEWITT, R.B. Consumers Power Co. 1p. 32800-202-32800-204.

8510010141 Mgt Meeting Rept 50-255/85-22 on 850905. Major areas discussed: weaknesses in emergency preparedness annual exercise of 850820 & concern w/overall trend & performance of emergency preparedness program.

PATTERSON, J.P., PHILLIPS, M.P. Region 3, Office of Director. 85/09/20. 2pp. 32800-203-32800-204.

8510010407 Temporary Changes EI-85-024 & EI-85-025 to Rev 6 to Procedure EI-7.1, "Post-Accident Sampling."

* Consumers Power Co. 85/09/25. 4pp. 32803-267-32803-271.

8510210071 Suppl 850620 response to NRC 850521 ltr re violations noted in Insp Rept 50-255/85-10. Corrective actions commitment changed to include installation of door lock on Door 168 as alternative to alarm compliance expected by 851030.

JOHNSON, B.D. Consumers Power Co. 85/09/30. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33072-283-33072-284.

8510150380 Rev 3 to Emergency Implementation Procedure EI-13, "Evacuation/Reassembly."

BRUNET, J.R., ROGERS, D.W. Consumers Power Co. 85/10/01. 2pp. 33010-175-33010-176.

8510250251 Public version of revised general ofc response team/emergency operations facility emergency implementing procedures, including Rev 1 to controlled copyholders list & Rev 1 to facility procedures index W/851021 release memo.

* Consumers Power Co. 85/10/03. 16pp. 33226-172-33226-186.

8510160015 Forwards Safety Insp Rept 50-255/85-16 on 850819-22 & 0920. No violation noted. Exercise weaknesses summarized in app. Written statement re corrective actions for Weakness 5 requested within 30 days of ltr date.

SHAFFER, W.D. Region 3, Office of Director. 85/10/08. DEWITT, R.B. Consumers Power Co. 3pp. 33027-058-33027-089.

8510160018 Insp Rept 50-255/85-16 on 850819-22 & 0920. No violation or deviation noted. Major areas inspected: facility emergency preparedness exercise. Six weaknesses identified.

PATTERSON, J., KERS, L., WILLIAMSEN, N. Region 3, Office of Director. 85/10/07. 29pp. 33027-081-33027-089.

8510180235 Rev 11 to Emergency Implementation Procedure EI-1, "Activation of Site Emergency Plan/Emergency Classification."

* Consumers Power Co. 85/10/11. 46pp. 33062-036-33062-081.

8510300002 Rev 3 to Emergency Implementing Procedure EI-6.7, "Plant Site Meteorological Sys."

* Consumers Power Co. 85/10/23. 3pp. 33247-035-33247-036.

8510300009 Rev 12 to Attachment 1 of Emergency Plan Implementing Procedure EI-2.1, "Emergency Actions/Notification/Responsibilities."

* Consumers Power Co. 85/10/23. 2pp. 33247-033-33247-034.

8510300016 Revised list of effective index pages to plan; emergency implementation procedures.

* Consumers Power Co. 85/10/23. 4pp. 33247-138-33247-141.

8510300052 Rev 1 to Emergency Plan Implementing Procedure EI-15.2, "Communications Drills."

* Consumers Power Co. 85/10/23. 6pp. 33247-321-33247-326.

8510300094 Rev 3 to Emergency Implementing Procedure EI-7.1, "Post-Accident Sampling," incorporating Temporary Change EI-85-021.

HAGER, J. Consumers Power Co. 85/10/23. 4pp. 33250-344-33250-347.

8510300130 to Emergency Implementation Procedure EI-4.1, "Technical Support Ctr." incl. Temporary Change EI-85-023.

BRUNET, J. Consumers Power Co. 85/10/23. 8pp. 33250-359-33251-004.

8510300131 Rev 1 to Emergency Implementation Procedure EI-7.5, "Boron Mannitol Titration Method Post-Accident," incorporating Temporary Change EI-85-020.

BRUNET, J.R., HAGER, J. Consumers Power Co. 85/10/23. 3pp. 33250-351-33250-354.

8510300183 Rev 2 to Emergency Implementing Procedure EI-7.2, "Post-Accident Analysis," incorporating Temporary Change EI-85-019.

* Consumers Power Co. 85/10/23. 4pp. 33247-327-33247-330.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510240067 Forwards Rev 1 to updated FSAR for Palisades Plant, reflecting removal of electrohydraulic door closure units from inner door of containment personnel air lock & replacement of auxiliary feedwater sparger sys.

DEWITT, R.B. Consumers Power Co. 85/10/17. Office of Nuclear Reactor Regulation, Director. 2pp. 33149-160-33150-147.

38 DOCKETED ITEMS

—8510240074 Rev 1 to updated FSAR for Palisades Plant W/110 oversize figures.
* Consumers Power Co. 85/10/15. 275pp. 33149.162-33150.147.

P. Operating license stage documents & correspondence

8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDR. App E documents withheld (ref FOIA Exemptions 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833.002-32833.052.

8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049.042-33049.234.

8510080117 Confirms 850930 concurrence that util will supply addl info re TMI Action Plan Item II.D.1, "Performance Testing of Relief & Safety Valves" before end of 1985. Response originally expected within 60 days of 850806 request. KUEMIN, J.L. Consumers Power Co. 85/10/02. Office of Nuclear Reactor Regulation, Director. 1p. 32919.357-32919.357.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues. BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031.135-33031.150.

8510080499 Submits addl info in support of 850802 Tech Spec change request, revising 18-month diesel generator surveillance schedule to each refueling cycle. Insp of Diesel Generator 1-2 showed all parts to be in working order. KUEMIN, J.L. Consumers Power Co. 85/10/04. Office of Nuclear Reactor Regulation, Director. 1p. 32921.110-32921.110.

8510180032 Summarizes long- & short-term plans for spent fuel storage. Present rack configuration in spent fuel pool will accommodate fuel core discharge through Cycle 7. Mod to rerack half of pool to be completed during Cycle 7. KUEMIN, J.L. Consumers Power Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 2pp. 33063.050-33063.051.

8510220253 Forwards application for amend to License DPR-20, revising Tech Spec 6.8 to allow delegation of plant manager procedure approval authority by plant manager to other appropriate members of plant mgt. Fee paid. BERRY, K.W. Consumers Power Co. 85/10/15. Office of Nuclear Reactor Regulation, Director. 1p. 33084.042-33084.046.

—8510220258 Application for amend to License DPR-20, revising Tech Spec 6.8 to allow delegation of plant manager procedure approval authority by plant manager to other appropriate members of plant mgt. DEWITT, R.B. Consumers Power Co. 85/10/15. 3pp. 33084.043-33084.045.

—8510220261 Proposed Tech Spec 6.8, allowing delegation of plant manager procedure approval authority by plant manager to other appropriate members of plant mgt. * Consumers Power Co. 85/10/15. 1p. 33084.046-33084.046.

8510220275 Notifies of 851030 enforcement conference in Glen Ellyn, IL to review events involving failure to complete required equipment environ qualification mod by scheduled date. NOELIUS, C.E. Region 3, Office of Director. 85/10/18. DEWITT, R.B. Consumers Power Co. 1p. 33087.077-33087.077.

8510250100 Notification of significant licensee meeting w/util on 851024 in Covert, MI to discuss maint issues & other items of mutual interest. * Region 3, Office of Director. 85/10/18. Region 3, Office of Director. 2pp. 33173.120-33173.121.

8510290145 Forwards Rev 4 to CPC-2A, "QA Program Description for Operational Nuclear Power Plants," due to organizational changes. BERRY, K.W. Consumers Power Co. 85/10/18. KEPLER, J.G. Region 3, Office of Director. 1p. 33233.001-33233.126.

—8510290152 Rev 4 to "QA Program Description for Operational Nuclear Power Plants." * Consumers Power Co. 85/10/18. 115pp. 33233.002-33233.126.

8510250134 Advises of failure to submit compliance schedule within 180 days of issuance of QA guidance for ATWS equipment not safety-related, per Generic Ltr 85-06. Event considered isolated occurrence. KUEMIN, J.L. Consumers Power Co. 85/10/22. Office of Nuclear Reactor Regulation, Director. 2pp. 33172.071-33172.072.

8510250444 Application for amend to License DPR-20, changing Tech Specs re alternate electronic circuit check surveillance for new environmentally qualified containment high radiation monitors. Fee paid. BERRY, K.W. Consumers Power Co. 85/10/22. Office of Nuclear Reactor Regulation, Director. 3pp. 33172.338-33172.342.

—8510250449 Proposed Tech Spec Table 4.1.2, authorizing alternate electronic circuit check surveillance for new environmentally qualified containment high radiation monitors. * Consumers Power Co. 85/10/22. 2pp. 33172.341-33172.342.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5. ADENSAME, G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262.231-33262.231.

—8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant." * Science Applications International Corp. (formerly Science Applications, Inc.) NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262.232-33262.255.

Q. Inspection reports, IE Bulletins & correspondence

8510040184 Responds to NRC 850417 ltr re violations noted in Insp Rept 50-255/85-03. Corrective actions: all 480-volt safety-related switchgear & load ctrs will be incorporated into preventive maint program. Biennial review completed. VANDEWALLE, D.J. Consumers Power Co. 85/06/03. KEPLER, J.G. Region 3, Office of Director. 14pp. 32850.297-32850.310.

8510010128 Forwards Meeting Rept 50-255/85-22 on 850905. SHAFER, W.D. Region 3, Office of Director. 85/09/23. DEWITT, R.B. Consumers Power Co. 1p. 32800.202-32800.204.

—8510010141 Mgt Meeting Rept 50-255/85-22 on 850905. Major areas discussed: weaknesses in emergency preparedness annual exercise of 850820 & concern w/overall trend & performance of emergency preparedness program. PATTERSON, J.P., PHILLIPS, M.P. Region 3, Office of Director. 85/09/20. 2pp. 32800.203-32800.204.

8510010366 Forwards "Steam Generator Eddy Current Insp Plans for 1985/86 Refueling Outage," per 850514 commitment. KUEMIN, J.L. Consumers Power Co. 85/09/27. Office of Nuclear Reactor Regulation, Director. 2pp. 32801.255-32801.263.

—8510010370 "Steam Generator Eddy Current Insp Plan for 1985/86." * Consumers Power Co. 85/09/27. 7pp. 32801.257-32801.263.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8510210071 Suppl 850620 response to NRC 850521 ltr re violations noted in Insp Rept 50-255/85-10. Corrective actions: commitment changed to include installation of door lock on Door 168 as alternative to alarm. Compliance expected by 851030. JOHNSON, B.D. Consumers Power Co. 85/09/30. KEPLER, J.G. Region 3, Office of Director. 2pp. 33072.283-33072.284.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080499 Submits addl info in support of 850802 Tech Spec change request, revising 18-month diesel generator surveillance schedule to each refueling cycle. Insp of Diesel Generator 1-2 showed all parts to be in working order. KUEMIN, J.L. Consumers Power Co. 85/10/04. Office of Nuclear Reactor Regulation, Director. 1p. 32921.110-32921.110.

8510160015 Forwards Safety Insp Rept 50-255/85-16 on 850819-22 & 0920. No violation noted. Exercise weaknesses summarized in app. Written statement re corrective actions for Weakness 5 requested within 30 days of ltr date. SHAFER, W.D. Region 3, Office of Director. 85/10/08. DEWITT, R.B. Consumers Power Co. 3pp. 33027.058-33027.089.

—8510160018 Insp Rept 50-255/85-16 on 850819-22 & 0920. No violation or deviation noted. Major areas inspected: facility emergency preparedness exercise. Six weaknesses identified. PATTERSON, J., KERS, L., WILLIAMS, N. Region 3, Office of Director. 85/10/07. 29pp. 33027.061-33027.089.

8510160202 Advises that replacement of balance of GE type safety-related HFA relay coils will be completed by end of upcoming refueling outage. Work cannot be completed by 851231 as indicated in 840713 response to IE Bulletin 84-02. KUEMIN, J.L. Consumers Power Co. 85/10/11. Office of Nuclear Reactor Regulation, Director. 1p. 33026.300-33026.300.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510300106 Forwards Insp Rept 50-255/85-21 on 850813-0910. No noncompliance noted. CHRISOTIMOS, N. Region 3, Office of Director. 85/10/24. DEWITT, R.B. Consumers Power Co. 2pp. 33248.003-33248.015.

—8510300114 Insp Rept 50-255/85-21 on 850813-0910. No noncompliance noted. Major areas inspected: maint, operational safety, surveillance, ESF, walkdown, LERs & confirmatory action ltr. HEHL, C.W. Region 3, Office of Director. 85/10/24. 11pp. 33248.005-33248.015.

R. Periodic operating reports & related correspondence

8510150438 Monthly operating rept for Sept 1985. W/851008 ltr. SMITH, P.A., VANDENBERG, D. Consumers Power Co. 85/09/30. 5pp. 33015.170-33015.174.

S. Reportable occurrences, LERs & related correspondence

8510080056 LER 85-016-00: on 850830, reactor trip initiated by generator output protective trip. Caused by personnel physical arrangement of relay cutouts. Incident reviewed w/ personnel. W/850930 ltr. FENECH, R.A. Consumers Power Co. 85/09/30. 3pp. 32928-255-32928-257.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965-021-32965-047.

8510170016 LER 85-017-00: on 850909, determined that engineered safeguards room cooler temp control switches did not meet 10CFR50.49 schedule requirements. Caused by administrative error. Cooler fans placed in manual operation. W/851009 ltr. FENECH, R.A., FRISCH, R.R. Consumers Power Co. 85/10/09. 3pp. 33053-209-33053-211.

8510210294 LER 85-018-00: on 850914, calibr check determined seven pressurizer pressure transmitters outside required range. Caused by personnel miscommunication of dead weight pressures. Correlation techniques reviewed. W/851015 ltr. FENECH, R.A., JOHNSON, B.D. Consumers Power Co. 85/10/10. 4pp. 33095-014-33095-017.

8510250447 PNO-III-85-089: on 851015, RHR shutdown cooling suction isolation valve found leaking in excess of Tech Specs. Caused by failed valve packing. Packing & motor replaced & valve returned to svc on 851019. HEHL, W., CHRISOTIMOS, N. Region 3, Office of Director. 85/10/18. 1p. 33172-353-33172-353.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. * Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510010087 Requests that review of 841031 10CFR50, App R submittal be terminated due to reduction of scope of cable routing mods. New 10CFR50, App R will be submitted by 860115. DOMER, J.A. Tennessee Valley Authority. 85/09/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800-198-32800-199.

8510070335 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized. DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 32878-194-32878-207.

8510030061 Rev 27 to radiological emergency plan W/850930 ltr. HUFHAM, J.W. Tennessee Valley Authority. 85/09/26. GRACE, J.N. Region 2, Office of Director. 150pp. 32844-190-32844-328.

8510210260 Advises that review of Rev 25 to radiological emergency plan dtd 850729 completed. Plan continues to meet 10CFR50.47(b) planning stds & 10CFR50, App E requirements. VERRELLI, D.M. Region 2, Office of Director. 85/10/04. PARRIS, H.G. Tennessee Valley Authority. 1p. 33094-339-33094-339.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill. KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33108-337-33108-338.

8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements. KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. 2pp. 33109-052-33109-053.

8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan. KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33109-124-33109-150.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr. HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. GRACE, J.N. Region 2, Office of Director. 14pp. 33010-272-33010-284.

8510160068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028-094-33028-096.

8510160082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR2.790 & 73.21). TOBIN, W. Region 2, Office of Director. 85/10/07. 1p. 33028-096-33028-096.

8510160242 Revised radiological emergency plan implementing procedures, including BFN-IP-1 re emergency plan classification logic, BFN-IP-2 re notification of unusual event & BFN-IP-10 re medical emergency procedure. W/851011 ltr. MARKS, B.K., HUFHAM, J.W. Tennessee Valley Authority. 85/10/11. GRACE, J.N. Region 2, Office of Director. 51pp. 33022-357-33022-044.

I. Financial information

8510110269 Informs that financial info in 850830 ltr satisfies requirements of 10CFR140.21 that each licensee maintain guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e). SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. DOMER, J.A. Tennessee Valley Authority. 1p. 33011-186-33011-186.

P. Operating license stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr W/o encl. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510090472 Notification of postponement of 851002 meeting to 851010 w/util in Bethesda, MD to discuss integrated schedule for NRC-required mods. CLARK, R.E. Operating Reactors Branch 2. 85/09/23. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 32966-199-32966-200.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr. Followup rept of addl summaries expected by 851031. PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510070336 Application for amends to Licenses DPR-33, DPR-52 & DPR-68, revising Tech Specs to correct inconsistencies & typos. Fee paid. DOMER, J.A. Tennessee Valley Authority. 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32877-262-32877-297.

8510070340 Proposed Tech Specs, deleting Sections 6.9, "Environ Qualification," 6.10, "Integrity of Sys Outside Containment" & 6.11, "Iodine Monitoring" from table of contents. * Tennessee Valley Authority. 85/10/01. 35pp. 32877-264-32877-297.

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949-162-32949-166.

8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested. STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949-167-32949-167.

8510150328 Requests plans & schedule for NRC approved mods for NUREG-0737, Item ILK.3.18 re automatic depressurization sys logic, as specified in 830603 ltr. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-240-33033-242.

8510150383 Forwards info in response to NRC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co. & nuclear safety review staff & line responses to investigation repts. WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001-001-33006-171.

8510160153 Submits schedule to meet requirements of 10CFR50.62(c)(1)-(c)(5) re reduction of risk from ATW.3. Final implementation of mods to meet Paragraphs (c)(3) & (c)(4) scheduled for Unit 1 Cycle 7, Unit 2 Cycle 6 & Unit 3 Cycle 7 outages. SELLER, H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021-183-33021-185.

8510230024 Forwards addl info re plans for modifying plant to address Generic Ltr 84-23, "Reactor Vessel Water Level Instrumentation in BWRs." Util evaluating cost & feasibility of reducing vertical drops of ref legs inside drywell. DOMER, J.A. Tennessee Valley Authority. 85/10/15. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33102-238-33102-240.

8510220185 Responds to 850711 request that Tech Spec amends requested prior to ltr contain provision that amend be effective within 90 days of date of issuance unless otherwise specified. Implementation will be on case-by-case basis. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/16. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33098-131-33098-132.

40 DOCKETED ITEMS

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085-157-33086-052.

8510220119 Notification of 851029 meeting w/util in Bethesda, MD to discuss TVA program to environmentally qualify cable.
CLARK, R.J. Operating Reactors Branch 2. 85/10/17. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 33108-022-33108-023.

8510280331 Forwards response to Quality Technology Co investigation repts. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193-185-33193-237.

Q. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510030068 Forwards rev to 850621 response to violation noted in Insp Repts 50-259/85-25, 50-260/85-25 & 50-296/85-25. Plant Std Practice BF 14.25, "Clearance Procedure," rewritten.
SHELL, R.H. Tennessee Valley Authority. 85/09/18. GRACE, J.N. Region 2, Office of Director. 2pp. 32844-329-32844-330.

8510070335 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-25, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized.
DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 32878-194-32878-207.

8510070037 Forwards Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. No notice of violation issued since violations under consideration for escalated enforcement action pending further NRC review.
WALKER, R.D. Region 2, Office of Director. 85/09/24. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32900-030-32900-041.

-8510070042 Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. Violations noted: inadequate design controls for safety-related cable tray supports & inadequate corrective actions for safety-related cable tray sys.
LIU, W.C., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 10pp. 32900-032-32900-041.

8510070486 Informs that ultrasonic training for response inspectors delayed until 851104, per 851118 telcon re 850819 response to violations noted in Insp Repts 50-259/85-33, 50-260/85-33 & 50-296/85-33.
DOMER, J.A. Tennessee Valley Authority. 85/09/25. GRACE, J.N. Region 2, Office of Director. 1p. 32878-136-32878-136.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. DUTTON, D.E. Southern Co. Services, Inc. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8510180021 Responds to NRC 850807 ltr re violations noted in Insp Repts 50-259/85-36, 50-260/85-36 & 50-296/85-36. Corrective actions: RHR sys Operating Instruction (OI)-74 will be revised to fully incorporate steps to cross tie RHR loops.
SHELL, R.H. Tennessee Valley Authority. 85/09/27. GRACE, J.N. Region 2, Office of Director. 12pp. 33063-014-33063-025.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510180030 Notifies that Item 5.c of 851015 response to EA-84-82 (Insp Rept 84-20) re design criteria for electrical separation will not be completed until 851202 rather than 850930, due to difficulty & time necessary to assemble criteria.
SHELL, R.H. Tennessee Valley Authority. 85/09/30. GRACE, J.N. Region 2, Office of Director. 1p. 33054-009-33054-009.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180069 Responds to NRC 850904 ltr re violations noted in Insp Repts 50-259/85-39, 50-260/85-39 & 50-296/85-39. Corrective actions: heaters tagged out & design change initiated for permanent removal of heaters from standby gas treatment sys.
DOMER, J.A. Tennessee Valley Authority. 85/10/03. GRACE, J.N. Region 2, Office of Director. 5pp. 33054-080-33054-084.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

-8510230055 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DENTON Senate. 2pp. 33108-337-33108-338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. DENTON, HEFLIN Senate. 2pp. 33109-052-33109-053.

-8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DENTON Senate. 2pp. 33109-094-33109-095.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DENTON Senate. 2pp. 33109-124-33109-150.

-8510230337 Forwards Press Release 85-13 re NRC proposed civil penalty in amount of \$100,000 against util as result of 840814 incident concerning overpressurization of safety sys.
KAMMERER, C. Office of Congressional Affairs. 85/01/29. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-158-33109-159.

8510180367 Ack receipt of 850923 ltr informing NRC of steps taken to correct violations in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Response under evaluation.
WALKER, R.D. Region 2, Office of Director. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 1p. 33068-283-33068-283.

8510180068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028-094-33028-096.

-8510180082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR2.790 & 73.21).
TOBIN, W. MCGUIRE, D.R. Region 2, Office of Director. 85/10/07. 1p. 33028-096-33028-096.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout repts.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action, per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191-072-33191-073.

R. Periodic operating reports & related correspondence

8510010487 Monthly operating repts for Jul 1985. W/850814 ltr.
THOM, T., LEWIS, R.L. Tennessee Valley Authority. 85/07/31. 25pp. 32809-120-32809-144.

8510070553 "Discharge Monitoring Rept for Aug 1985."
* Tennessee Valley Authority. 85/08/31. 12pp. 32883-219-32883-230.

8510250293 Forwards revised "Discharge Monitoring Rept for Aug 1985." Original submission indicated: min pH of 7.2 which is incorrect rounding off of true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/10/18. WARR, J.W., PIZNAR, T. Alabama, State of. 1p. 33189-350-33189-351.

-8510250440 Revised "Discharge Monitoring Rept for Aug 1985," correcting typo to reflect true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/08/31. 1p. 33189-351-33189-351.

S. Reportable occurrences, LERs & related correspondence

8510070545 LER 85-041-00 on 850814 sys operational readiness reviews determined that manufacturer multi-yr diesel generator insp recommendations not implemented. Cause unknown. Vendor recommendations will be evaluated. W/850927 ltr.
SMITH, D.L., LEWIS, R.L. Tennessee Valley Authority. 85/09/27. 4pp. 32883-240-32883-243.

8510060020 LER 85-045-00: on 850904, during performance of Technical Instruction-33, emergency equipment cooling water flow verification found inadequate. Possibly caused by silt accumulation, biofouling & corrosion. W/851004 ltr. EBERSOLE, P.N., LEWIS, R.L. Tennessee Valley Authority. 85/10/04. 4pp. 32934-348-32934-351.

8510180387 LER 85-048-00: on 850908, inadvertent scram occurred during weekly surveillance instruction. Cause not determined. Cable & breaker replaced. Surveillance instruction will be revised to add steps to verify half scram fully reset. W/851008 ltr. STEELE, R.C., LEWIS, R.L. Tennessee Valley Authority. 85/10/06. 4pp. 33068-033-33068-036.

8510170370 LER 85-046-00: on 850912, chemical lab technician left continuous air monitor sample hose to turbine bldg ventilation continuous air monitor disconnected. Technician disciplined. Procedure will be revised. W/851011 ltr. SMITH, D.L., LEWIS, R.L. Tennessee Valley Authority. 85/10/11. 3pp. 33053-327-33053-329.

8510290470 LER 85-047-00: on 850111, heat trace tape transformer overloaded. Caused by installation of incorrect tape as result of discrepancy in vendor-supplied info. Tape, w/ proper wattage, to be installed prior to restart. W/851016 ltr. SMITH, D.L., LEWIS, R.L. Tennessee Valley Authority. 85/10/16. 4pp. 33242-121-33242-124.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants. STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078-256-33078-261.

-8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp. 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078-260-33078-361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill. KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108-337-33108-338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements. KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-052-33109-053.

-8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance. KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-094-33109-095.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan. KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-124-33109-150.

-8510230337 Forwards Press Release 85-13 re NRC proposed civil penalty in amount of \$100,000 against util as result of 840814 incident concerning overpressurization of safety sys. KAMMERER, C. Office of Congressional Affairs. 85/01/29. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-158-33109-159.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510010182 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-326/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-326/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510010087 Requests that review of 841031 10CFR50, App R submittal be terminated due to reduction of scope of cable routing mods. New 10CFR50, App R will be submitted by 860115. DOMER, J.A. Tennessee Valley Authority. 85/09/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800-198-32800-199.

8510070335 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized. DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 32878-194-32878-207.

8510030061 Rev 27 to radiological emergency plan. W/850930 ltr. HUFHAM, J.W. Tennessee Valley Authority. 85/09/28. GRACE, J.N. Region 2, Office of Director. 150pp. 32844-190-32844-328.

8510210260 Advises that review of Rev 25 to radiological emergency plan dtd 850729 completed. Plan continues to meet 10CFR50.47(b) planning stds & 10CFR50, App E requirements. VERRELLI, D.M. Region 2, Office of Director. 85/10/04. PARRIS, H.G. Tennessee Valley Authority. 1p. 33094-339-33094-339.

8510230018 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill. KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33108-337-33108-338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements. KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. 2pp. 33109-052-33109-053.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan. KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33109-124-33109-150.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr. HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. GRACE, J.N. Region 2, Office of Director. 14pp. 33010-272-33010-284.

8510160068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028-094-33028-096.

-8510160082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR2.790 & 73.21). TCBIN, W. Region 2, Office of Director. 85/10/07. 1p. 33028-096-33028-096.

8510160242 Revised radiological emergency plan implementing procedures, including BFN-IP-1 re emergency plan classification logic, BFN-IP-2 re notification of unusual event & BFN-IP-10 re medical emergency procedure. W/851011 ltr. MARKS, B.K., HUFHAM, J.W. Tennessee Valley Authority. 85/10/11. GRACE, J.N. Region 2, Office of Director. 51pp. 33022-357-33023-044.

I. Financial information

8510110269 Informs that financial info in 850830 ltr satisfies requirements of 10CFR140.21 that each licensee maintain guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e). SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. DOMER, J.A. Tennessee Valley Authority. 1p. 33011-186-33011-186.

P. Operating license stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr W/o encl. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510090472 Notification of postponement of 851002 meeting to 851010 w/util in Bethesda, MD to discuss integrated schedule for NRC-required mods. CLARK, R.E. Operating Reactors Branch 2. 85/09/23. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 32966-199-32966-200.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 350906 ltr. Follow-up rept of add summaries expected by 851031. PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510070336 Application for amendments to Licenses DPR-33, DPR-52 & DPR-68, revising Tech Specs to correct inconsistencies & typos. Fee paid. DOMER, J.A. Tennessee Valley Authority. 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32877-262-32877-297.

-8510070340 Proposed Tech Specs, deleting Sections 6.9, "Environ Qualification," 6.10, "Integrity of Sys Outside Containment," & 6.11, "Iodine Monitoring," from table of contents.
* Tennessee Valley Authority. 85/10/01. 35pp. 32877-264-32877-297.

42 DOCKETED ITEMS

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing until 850604 backfit claim NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949:162-32949:166.

8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested. STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949:167-32949:167.

8510150328 Requests plans & schedule for NRC approved mods for NUREG-0737, Item II.K.3.18 re automatic depressurization sys logic, as specified in 830603 ltr. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033:240-33033:242.

8510150383 Forwards info in response to NRC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts. WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001:001-33006:171.

8510160153 Submits schedule to meet requirements of 10CFR50.62(c)(1)-(c)(5) re reduction of risk from ATWS. Final implementation of mods to meet Paragraphs (c)(3) & (c)(4) scheduled for Unit 1 Cycle 7, Unit 2 Cycle 6 & Unit 3 Cycle 7 outages. SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021:183-33021:185.

8510230024 Forwards addl info re plans for modifying plant to address Generic Ltr 84-23, "Reactor Vessel Water Level Instrumentation in BWRs." Util evaluating cost & feasibility of reducing vertical drops of ref legs inside drywell. DOMER, J.A. Tennessee Valley Authority. 85/10/15. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33102:238-33102:240.

8510220185 Responds to 850711 request that Tech Spec amends requested prior to ltr contain provision that amend be effective within 90 days of date of issuance unless otherwise specified. Implementation will be on case-by-case basis. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/16. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33098:131-33098:132.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11. WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085:157-33086:052.

8510230119 Notification of 851029 meeting w/util in Bethesda, MD to discuss TVA program to environmentally qualify cable. CLARK, R.J. Operating Reactors Branch 2. 85/10/17. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 33108:022-33108:023.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns. WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193:185-33193:237.

Q. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834:210-32834:349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. * Region 2, Office of Director. 85/09/17. 68pp. 32834:229-32834:349.

8510030068 Forwards rev to 850821 response to violation noted in Insp Repts 50-259/85-25, 50-260/85-25 & 50-296/85-25. Plant Std Practice BF 14.25, "Clearance Procedure," rewritten. SHELL, R.H. Tennessee Valley Authority. 85/09/18. GRACE, J.N. Region 2, Office of Director. 2pp. 32844:329-32844:330.

8510070335 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized. DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 3378:194-32878:207.

8510070037 Forwards Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. No notice of violation issued since violations under consideration for escalated enforcement action pending further NRC review. WALKER, R.D. Region 2, Office of Director. 85/09/24. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32900:030-32900:041.

8510070042 Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. Violations noted: inadequate design controls for safety-related cable tray supports & inadequate corrective actions for safety-related cable tray sys. LIU, W.C., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 10pp. 32900:032-32900:041.

8510070486 Informs that ultrasonic training for response inspectors delayed until 851104, per 851118 telcon re 850819 response to violations noted in Insp Repts 50-259/85-33, 50-260/85-33 & 50-296/85-33. DOMER, J.A. Tennessee Valley Authority. 85/09/25. GRACE, J.N. Region 2, Office of Director. 1p. 32878:136-32878:136.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds. DUTTON, D.E. Nuclear Construction Issues Group. DUTTON, D.E. Southern Co. Services, Inc. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds." * Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510180021 Responds to NRC 850807 ltr re violations noted in Insp Repts 50-259/85-36, 50-260/85-36 & 50-296/85-36. Corrective actions: RHR sys Operating Instruction (OI)-74 will be revised to fully incorporate steps to cross tie RHR loops. SHELL, R.H. Tennessee Valley Authority. 85/09/27. GRACE, J.N. Region 2, Office of Director. 12pp. 33063:014-33063:025.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510180030 Notifies that Item 5.c of 851015 response to EA-84-82 (Insp Rept 84-20) re design criteria for electrical separation will not be completed until 851202 rather than 850930, due to difficulty & time necessary to assemble criteria. SHELL, R.H. Tennessee Valley Authority. 85/09/30. GRACE, J.N. Region 2, Office of Director. 1p. 33054:009-33054:009.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180069 Responds to NRC 850904 ltr re violations noted in Insp Repts 50-259/85-39, 50-260/85-39 & 50-296/85-39. Corrective actions: heaters tagged out & design change initiated for permanent removal of heaters from standby gas treatment sys. DOMER, J.A. Tennessee Valley Authority. 85/10/03. GRACE, J.N. Region 2, Office of Director. 5pp. 33054:080-33054:084.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:088.

8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill. KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33108:337-33108:338.

8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements. KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. FLIPPO House of Rep. 2pp. 33109:052-33109:053.

8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance. KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33109:094-33109:095.

8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan. KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33109:124-33109:125.

8510230312 Ack receipt of 850923 ltr informing NRC of steps taken to correct violations in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Response under evaluation. * Region 2, Office of Director. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33068:283-33068:283.

8510160068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028:094-33028:096.

8510160082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR2.790 & 73.21). TUCKER, W. MCQUIRE, D.R. Region 2, Office of Director. 85/10/07. 1p. 33028:096-33028:096.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closure rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action, per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191:072-33191:073.

R. Periodic operating reports & related correspondence

8510010487 Monthly operating repts for Jul 1985. W/850814 ltr.
THOM, T., LEWIS, R.L. Tennessee Valley Authority. 85/07/31. 25pp. 32809:120-32809:144.

8510070553 "Discharge Monitoring Rept for Aug 1985."
* Tennessee Valley Authority. 85/08/31. 12pp. 32863:219-32863:230.

8510250293 Forwards revised "Discharge Monitoring Rept for Aug 1985." Original submission indicated min pH of 7.2 which is incorrect rounding of true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/10/18. WARR, J.W., PIZNAR, T. Alabama, State of. 1p. 33189:350-33189:351.

-8510250440 Revised "Discharge Monitoring Rept for Aug 1985," correcting typo to reflect true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/08/31. 1p. 33189:351-33189:351.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants.
STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078:256-33078:261.

-8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078:260-33078:361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to Congress re pending or escalated enforcement action against applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. West-ument Service. 7pp. 33108:264-33109:088.

-8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:337-33108:338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:052-33109:053.

-8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post mod testing & monthly surveillance.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:094-33109:095.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:124-33109:150.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-261 H.B. ROBINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070169 Forwards plant-specific info re TMI Action Item II.K.3.5 per Section IV of SER issued w/Generic Ltr 85-12 Reactor coolant subcooling methodology will be used to determine reactor coolant pump setpoint.
ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/30. THOMPSON, H.L. Division of Licensing. 6pp. 32881:196-32881:201.

8510180518 Confirms 850930 telcon re 851008 meeting at Region II ofc concerning proposed changes to physical security plan.
WALKER, R.D. Region 2, Office of Director. 85/10/03. UTLEY, E.E. Carolina Power & Light Co. 1p. 33067:351-33067:351.

8510220404 Forwards Insp Rept 50-261/85-29 on 850909-13. No violation or deviation noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096:346-33096:354.

-8510220406 Insp Rept 50-261/85-29 on 850909-08:13. No violation or deviation noted. Major areas inspected: emergency preparedness.
MARSTON, R.R., CUNNINGHAM, A.L. Region 2, Office of Director. 85/10/01. 7pp. 33096:348-33096:354.

8510180431 Forwards Insp Rept 50-261/85-28 on 850911-1010. No violation or deviation noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/10. UTLEY, E.E. Carolina Power & Light Co. 1p. 33056:319-33056:328.

-8510180435 Insp Rept 50-261/85-28 on 850911-1010. No violation or deviation noted. Major areas inspected: plant tour, operations performance, ROs, housekeeping, site security, surveillance & radiation control activities.
KRUG, H.E., WHITCOMB, H.C., FREDRICKSON, P. Region 2, Office of Director. 85/10/10. 9pp. 33056:320-33056:328.

8510220248 Rev 3 to Plant Emergency Procedure PEP-301, "Initial Dose Projections" & Rev 2 to PEP-304, "Automation of Dose Assessment Using IBM Personal Computer." W/851017 ltr.
MORGAN, R.E. Carolina Power & Light Co. 85/10/17. GRACE, J.N. Region 2, Office of Director. 74pp. 33087:129-33087:202.

8510240385 Forwards Rev 0 to Plant Emergency Procedure PEP-375, "Core Damage Assessment," per util 850624 commitment. Procedure incorporates Westinghouse Owners Group methodology re use of post-accident sampling sys, per TMI Action Item II.B.3.
ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/21. VARGA, S.A. Operating Reactors Branch 1. 1p. 33149:092-33149:159.

-8510240389 Rev 0 to Plant Emergency Procedure PEP-355, "Core Damage Assessment." W/one oversize drawing.
MORROW, M. Carolina Power & Light Co. 85/10/14. 67pp. 33149:093-33149:159.

8510150116 Site specific emergency response plan, "SC Operational Radiological Emergency Response Plan, including Change 4 dtd Aug 1985 W/851007 ltr.
ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/31. VARGA, S.A. Operating Reactors Branch 1. 21pp. 33010:306-33010:326.

P. Operating license stage documents & correspondence

8510040045 Forwards Amend 95 to License DPR-23 & safety evaluation. Amend adds requirements to Tech Specs, per NUREG-0737, Items I.A.1.3 & II.K.3.3 concerning shift manning overtime limits & reporting safety & relief valve failures.
REQUAG, G. Operating Reactors Branch 1. 85/09/12. UTLEY, E.E. Carolina Power & Light Co. 3pp. 32900:274-32900:307.

-8510040078 Amend 95 to License DPR-23, adding requirements to Tech Specs re shift manning overtime limits & reporting safety & relief valve failures, per NUREG-0737, Items I.A.1.3 & II.K.3.3.
VARGA, S.A. Operating Reactors Branch 1. 85/09/12. 6pp. 32900:277-32900:282.

-8510040089 Safety evaluation supporting Amend 95 to License DPR-23.
* Office of Nuclear Reactor Regulation, Director. 85/09/12. 4pp. 32900:283-32900:286.

-8510040100 "Conformance to NRR Generic Ltr 82-16, HB Robinson Steam Electric Plant, Unit 2," technical evaluation rept.
BEAHM, D.M. Idaho National Engineering Laboratory. FIN A-6600. EGG-EA-6437. 83/12/31. NRC - No Detailed Affiliation Given. 20pp. 32868:126-32868:146.

8510080292 Submits info re Exxon Nuclear Co ECCS/LOCA analysis, per 850930 discussion w/NRC. Error found in TOODEE2 code re calculation of thermal response of hot fuel rod peak cladding temp underpredicted. Calculations revised.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32919:109-32919:111.

-8510080301 Notices of error in 10CFR50.46 LOCA analyses performed for facilities. Input error in TOODEE2 code used to calculate fuel rod heatup resulted in rod decay heat power too low & subsequent underpredicted peak cladding temp.
MALODY, C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/09/30. MARTIN, J.B. Region 5, Office of Director. 11pp. 32919:112-32919:122.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co, Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510310552 Forwards safety evaluation of 830812, 841228 & 850624 responses to NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys." Procedure for estimating core damage from fission measurements acceptable on interim basis.
VARGA, S.A. Operating Reactors Branch 1. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 11pp. 33277:043-33277:053.

8510150277 Informs that efforts underway w/Exxon to develop long-term solution for error in TOODEE2 calculation portion of 10CFR50.46 LOCA analysis for Cycle 10. NRC will be advised of schedule when available.
CUTTER, A.B. Carolina Power & Light Co. 85/10/08. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33009:288-33009:290.

8510150109 Application for amend to License DPR-23, changing method for data collection during ex-core symmetrical offset detector calibr w/o incurring reduction in safety fee paid.
CUTTER, A.B. Carolina Power & Light Co. 85/10/09. VARGA, S.A. Operating Reactors Branch 1. 4pp. 33006:315-33006:318.

-8510150112 Proposed Tech Specs, changing method for data collection during ex-core symmetrical offset detector calibr.
* Carolina Power & Light Co. 85/10/09. 8pp. 33006:319-33006:326.

8510180274 Ack receipt of 841005 response to Generic Ltr 84-15 re diesel generator reliability info contained in ltr useful. Item closed for TAC 55897.
VARGA, S.A. Operating Reactors Branch 1. 85/10/09. UTLEY, E.E. Carolina Power & Light Co. 3pp. 33075:087-33075:089.

8510180265 Submits proposed schedule for meeting requirements of 10CFR50.62 re ATWS & provides brief description of tentative design.
CUTTER, A.B. Carolina Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33062:034-33062:035.

44 DOCKETED ITEMS

8510230005 Provides clear description of util operating plans under revised Exxon analyses. High flux trip setpoint will be reset to value allowed by facility Tech Specs. CUTTER, A.B. Carolina Power & Light Co. 85/10/15. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33101:036-33101:037.

8510240337 Requests deletion of App B (environ protection plan) from License DPR-23. Areas addressed in plan within EPA jurisdiction. ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/18. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33151:033-33151:036.

Q. Inspection reports, IE Bulletins & correspondence

8509180255 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. UTLEY, E.E. Carolina Power & Light Co. 11pp. 32854:316-32854:326.

8510070341 Responds to violations noted in Insp Rept 50-261/85-24. Corrective actions: personnel replacing in-core detectors required to wear respirators. MORGAN, R.E. Carolina Power & Light Co. 85/09/26. GRACE, J.N. Region 2, Office of Director. 5pp. 32678:239-32678:243.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Main Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220107 Forwards Insp Rept 50-261/85-30 on 850916-20. No violation noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 1p. 33095:116-33095:124.

8510220112 Insp Rept 50-261/85-30 on 850916-20. No violation or deviation noted. Major areas inspected: plant chemistry & inservice insp of pumps & valves. ROSS, W.J., BLAKE, J.J. Region 2, Office of Director. 85/10/02. 8pp. 33095:117-33095:124.

8510220404 Forwards Insp Rept 50-261/85-29 on 850909-13. No violation or deviation noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096:346-33096:354.

8510220406 Insp Rept 50-261/85-29 on 850909-0913. No violation or deviation noted. Major areas inspected: emergency preparedness. MARSTON, R.R., CUNNINGHAM, A.L. Region 2, Office of Director. 85/10/01. 7pp. 33096:348-33096:354.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

8510230246 Forwards Press Release 84-109 re NRC mitigation of proposed civil penalty in amount of \$30,000 against util for alleged violation of NRC radiation protection requirements due to prompt reporting. KAMMERER, C. Office of Congressional Affairs. 84/09/11. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:105-33109:106.

8510180431 Forwards Insp Rept 50-261/85-28 on 850911-1010. No violation or deviation noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/10. UTLEY, E.E. Carolina Power & Light Co. 1p. 33056:319-33056:328.

8510180435 Insp Rept 50-261/85-28 on 850911-1010. No violation or deviation noted. Major areas inspected: plant tour, operations performance, ROs, housekeeping, site security, surveillance & radiation control activities. KRUG, H.E., WHITCOMB, H.C., FREDRICKSON, P. Region 2, Office of Director. 85/10/10. 9pp. 33056:320-33056:328.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510180348 Forwards Rev 8 to "Inservice Insp Program Interval 2." Rev includes addl requests for relief from certain insp requirements submitted in response to Region II & INPO insp reqs. ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/15. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33060:149-33060:249.

8510180350 Rev 8 to "Inservice Insp Program Interval 2." Carolina Power & Light Co. 85/10/15. 95pp. 33060:152-33060:249.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510180239 Forwards monthly operating rept for Sept 1985 & rev to monthly operating rept for Aug 1985. Rev necessary due to mathematical error in plant log. MORGAN, R.E. Carolina Power & Light Co. 85/10/09. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 1p. 33068:292-33068:296.

8510180242 Monthly operating rept for Sept 1985. SCOTT, A.E. Carolina Power & Light Co. 85/09/30. 3pp. 33068:293-33068:295.

8510180246 Revised monthly operating rept for Aug 1985. SCOTT, A.E. Carolina Power & Light Co. 85/08/31. 1p. 33068:296-33068:296.

S. Reportable occurrences, LERs & related correspondence

8510080065 LER 85-019-00: on 850829, reactor power increased above nine times allowable power level prior to completion of ex-core calibr test, contrary to Tech Spec 3.10.2.9. Calibr Test FMP-011 revised W/850927 ltr. WRIGHT, C.L., MORGAN, R.E. Carolina Power & Light Co. 85/09/27. 3pp. 32928:121-32928:123.

8510090055 LER 85-020-00: on 850911, main transformer fault pressure signal resulted in generator lockout/turbine trip & subsequent reactor trip. Caused by faulty main transformer C supply plug. Plug replaced W/851003 ltr. WRIGHT, C.L., MORGAN, R.E. Carolina Power & Light Co. 85/10/03. 3pp. 32934:345-32934:347.

8510180532 LER 85-021-00: on 850917, reactor trip occurred due to false low reactor coolant flow signal. Caused when bistable for Loop 1 was tripped for testing. No cause for voltage spike found W/851010 ltr. WRIGHT, C.L., MORGAN, R.E. Carolina Power & Light Co. 85/10/10. 3pp. 33068:017-33068:019.

8510300153 LER 85-022-00: on 850928, Exxon Nuclear Corp informed util of error in large break LOCA analysis which resulted in peak clad temp being underpredicted. Reactor power & high flux trip setpoint increased within new limits W/851023 ltr. WRIGHT, C.L., MORGAN, R.E. Carolina Power & Light Co. 85/10/23. 3pp. 33257:151-33257:160.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

8510230246 Forwards Press Release 84-109 re NRC mitigation of proposed civil penalty in amount of \$30,000 against util for alleged violation of NRC radiation protection requirements due to prompt reporting. KAMMERER, C. Office of Congressional Affairs. 84/09/11. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:105-33109:106.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

Y. Dry Cask Independent Spent Fuel Storage Installations

8510250064 Notifies that Drawing RNT162-M-2622, Sheet 1 of 2, missing from 851014 submittal. Application for withholding should be submitted for drawings identified as proprietary (re: 10CFR2.790). ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/21. UTLEY, E.E. Carolina Power & Light Co. 1p. 33191:359-33191:359.

50-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F. Security, medical, emergency & fire protection plans

8510010016 Grants 850625 request for extension of completion dates for Items 2.b.3 & 4 in Commission 840612 order re Suppl 1 to NUREG-0737 Implementation of upgraded emergency procedures should be completed 6 months after Cycle 12 startup. THOMPSON, H.L. Division of Licensing. 85/09/24. MUSOLF, D.M. Northern States Power Co. 3pp. 32833:191-32833:193.

8510080505 Rev 8 to Corporate Nuclear Emergency Implementing Procedure EPIP 1.1.7, "Startup & Operation of Headquarters Emergency Ctr." W/850927 ltr. FEY, F.L. Northern States Power Co. 85/09/27. 22pp. 32920:217-32920:235.

8510070024 Forwards SER re fire protection. Responses to open items identified in 810212 SSER 1 comply w/guidelines in App A to Branch Technical Position ASB 9.5-1 & 10CFR50. App R requirements. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/02. MUSOLF, D.M. Northern States Power Co. 2pp. 32901:092-32901:098.

-8510070026 SER supporting facility fire protection program.
* Office of Nuclear Reactor Regulation, Director. 85/10/02. 5pp. 32901:094-32901:098.

8510100037 Responds to 850905 request for addl info on 850830 submittal re revised control room habitability study sent on 840817. CB Hogg 850926 ltr to util re toxic chemical analysis encl. MUSOLF, D. Northern States Power Co. 85/10/02. Office of Nuclear Reactor Regulation, Director. 4pp. 32960:241-32960:244.

8510080345 Ack receipt of 850710 changes to Rev 8 to emergency plan. Changes consistent w/10CFR50.54(q) requirements & acceptable. Notes that Figure 8-3, "Notifications," added to Section 8.0. SHAFER, W.D. Region 3, Office of Director. 85/10/03. LARSON, C.E. Northern States Power Co. 2pp. 32918:356-32918:357.

8510080389 Ack receipt of 850905 ltr transmitting Rev 5 to emergency plan. Changes consistent w/10CFR50.54(q) & do not decrease effectiveness of plan. Plan changes must be made in accordance w/10CFR50. App E, Section V. SHAFER, W.D. Region 3, Office of Director. 85/10/03. LARSON, C.E. Northern States Power Co. 1p. 32919:312-32919:312.

8510170164 Forwards Amend 33 to License DPR-22 & safety evaluation. Amend revises Tech Spec Section 3.13/4-13, "Fire Suppression Water Sys.," to change term "screen wash pump" to "screen wash/fire pump." AULUCK, R. Operating Reactors Branch 2. 85/10/07. MUSOLF, D.M. Northern States Power Co. 2pp. 33043:098-33043:108.

-8510170170 Amend 33 to License DPR-22, revising Tech Spec Section 3.13/4-13, "Fire Suppression Water Sys.," to change term, "screen wash pump" to "screen wash/fire pump." VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. 7pp. 33043:100-33043:106.

-8510170176 Safety evaluation supporting Amend 33 to License DPR-22.
* Office of Nuclear Reactor Regulation, Director. 85/10/07. 2pp. 33043:107-33043:108.

8510240242 Revised emergency plan implementing procedures, including Rev 6 to EPIP 1.1.1 re corporate emergency response organization & Rev 12 to EPIP 1.1.5 re startup & operation of emergency operations facility W/851007 ltr. FEY, F.L. Northern States Power Co. 85/10/07. 56pp. 33155:266-33155:321.

8510280055 Revised emergency response plan implementing procedures, including Rev 3 to A.2-209 re responsibilities of radiological emergency coordinator & Rev 4 to A.2-301 re emergency evacuation W/851023 ltr. FEY, F.L. Northern States Power Co. 85/10/23. 29pp. 33191:025-33191:053.

I. Financial information

8510310004 Informs that 851008 submittal of financial info for 1985 satisfies requirements of 10CFR140.21 re licensee maint of approved guarantee of payment of deferred premiums for each operating reactor over 100 MWe. SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/10/24. HALL, E.J. Northern States Power Co. 1p. 33277:198-33277:108.

P. Operating license stage documents & correspondence

8510030017 Withdraws previously submitted applications for amends to License DPR-22, including 760130 & 05 requests re compliance w/App J & 780118 request re augmented insp of piping susceptible to stress corrosion cracking. MUSOLF, D. Northern States Power Co. 85/09/18. Office of Nuclear Reactor Regulation, Director. 3pp. 32844:339-32844:341.

8510170164 Forwards Amend 33 to License DPR-22 & safety evaluation. Amend revises Tech Spec Section 3.13/4-13, "Fire Suppression Water Sys.," to change term "screen wash pump" to "screen wash/fire pump." AULUCK, R. Operating Reactors Branch 2. 85/10/07. MUSOLF, D.M. Northern States Power Co. 2pp. 33043:098-33043:108.

-8510170170 Amend 33 to License DPR-22, revising Tech Spec Section 3.13/4-13, "Fire Suppression Water Sys.," to change term, "screen wash pump" to "screen wash/fire pump." VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. 7pp. 33043:100-33043:106.

-8510170176 Safety evaluation supporting Amend 33 to License DPR-22.
* Office of Nuclear Reactor Regulation, Director. 85/10/07. 2pp. 33043:107-33043:108.

8510170359 Forwards Amend 34 to License DPR-22 & safety evaluation. Amend revises Tech Specs to raise Keff limit on spent fuel storage pool & adds infinite multiplication factor less than or equal to 1.13 for new fuel & 1.33 for spent fuel. AULUCK, R. Operating Reactors Branch 2. 85/10/08. MUSOLF, D.M. Northern States Power Co. 2pp. 33048:174-33048:181.

-8510170361 Amend 34 to License DPR-22, revising Tech Specs to raise Keff limit on spent fuel storage pool & adding infinite multiplication factor less than or equal to 1.31 for new fuel & 1.33 for spent fuel assemblies. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/08. 4pp. 33048:176-33048:179.

-8510170362 Safety evaluation supporting Amend 34 to License DPR-22.
* Office of Nuclear Reactor Regulation, Director. 85/10/08. 2pp. 33048:180-33048:181.

8510160252 Submits proposed schedule for compliance w/10CFR50.52, "Requirements for Reduction of Risk From ATWS Events for Light-Water-Cooled Nuclear Power Plants," per Generic Ltr 85-06. MUSOLF, D. Northern States Power Co. 85/10/11. Office of Nuclear Reactor Regulation, Director. 3pp. 33023:217-33023:219.

8510290371 Forwards Rev 1 to 850426 application for amend to License DPR-22, changing Tech Specs re provision for corn & potato sampling if plant releases liquid radioactive effluent, clarifying issues & correcting typos. MUSOLF, D. Northern States Power Co. 85/10/16. Office of Nuclear Reactor Regulation, Director. 3pp. 33240:319-33240:332.

-8510290375 Rev 1 to 850426 application for amend to License DPR-22, changing Tech Specs re provision for corn & potato sampling if plant releases liquid radioactive effluent, clarifying issues & correcting typos. MUSOLF, D. Northern States Power Co. 85/10/16. 5pp. 33240:321-33240:325.

-8510290378 Rev 1 to proposed Tech Specs, providing for corn & potato sampling if plant releases liquid radioactive effluent, clarifying issues & correcting typos.
* Northern States Power Co. 85/10/16. 7pp. 33240:326-33240:332.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5. ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-62-006. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

Q. Inspection reports, IE Bulletins & correspondence

8510030017 Withdraws previously submitted applications for amends to License DPR-22, including 760130 & 05 requests re compliance w/App J & 780118 request re augmented insp of piping susceptible to stress corrosion cracking. MUSOLF, D. Northern States Power Co. 85/09/18. Office of Nuclear Reactor Regulation, Director. 3pp. 32844:339-32844:341.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510220282 Forwards addendum to Insp Rept 50-263/85-14, consisting of Table II re comparisons of beta analyses performed on liquid sample collected at facility during insp on 850506-09. SHAFER, W.D. Region 3, Office of Director. 85/10/15. LARSON, C.E. Northern States Power Co. 1p. 33086:360-33086:361.

-8510220285 Addendum to Insp Rept 50-263/85-14, consisting of Table II re comparisons of beta analyses.
* Region 3, Office of Director. 85/10/15. 1p. 33086:361-33086:361.

8510220361 Forwards "Baseline Insp - Exam Summary, Recirculation Piping Project Monticello Nuclear Generating Plant - Unit 1, 840210-850112, Refueling Outage 10, Insp Period 1, Interval 2." MUSOLF, D. Northern States Power Co. 85/10/18. Office of Nuclear Reactor Regulation, Director. 1p. 33088:001-33088:148.

-8510220363 "Baseline Insp - Exam Summary, Recirculation Piping Project Monticello Nuclear Generating Plant - Unit 1, 840210-850112, Refueling Outage 10, Insp Period 1, Interval 2." DAHLMAN, L.C., KRAUSE, G.T. Northern States Power Co. 85/10/10. 150pp. 33088:002-33088:148.

R. Periodic operating reports & related correspondence

8510020103 Monthly operating rept for Jul 1985. W/850813 ltr. MYRABO, A.L. MUSOLF, D. Northern States Power Co. 85/07/31. 5pp. 32827:019-32827:023.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

46 DOCKETED ITEMS

DOCKET 50-264 DOW CHEMICAL CO.

F. Security, medical, emergency & fire protection plans

- 8510170221** Final response to FOIA request for documents re Dow Chemical Co. Forwards Apps O & P documents. Documents also available in PDR App Q documents withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 85/10/04. KOHN, S. Government Accountability Project. 5pp. 33050:297-33051:057.
- 8510170234** Notifies that reactor room & lab secured to prevent unauthorized entry in response to 780112 ltr. Updated security plan will be submitted after radiation safety committee meets to discuss reactor security. LANGNER, R.R. Dow Chemical Co. 78/01/19. KEPPLER, J.G. Region 3, Chicago, Office of the Director. 1p. 33050:303-33050:303.
- 8510170242** Forwards enforcement ltr & Initial Physical Security Insp Rept 50-264/76-01 on 760115-16. Portions deleted. HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/02/09. ROY, G.W. Office of Inspection & Enforcement, Office of the Director. 2pp. 33050:304-33050:305.
- 8510170252** Forwards Physical Protection Insp Rept 50-264/76-01 on 760115-16 & notice of violation. HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/02/10. DELINE, R.D. Dow Chemical Co. 2pp. 33050:306-33050:307.
- 8510170260** Notice of violation from physical protection insp on 760115-16. Portions deleted. * NRC - No Detailed Affiliation Given. 76/02/10. 1p. 33050:308-33050:308.
- 8510170263** Physical Protection Insp Rept 50-264/76-01 on 760115-16. Noncompliance noted re communications & access control. Portions withheld (ref 10CFR2.790). BELANGER, J.L. Region 3, Chicago, Office of the Director. 76/02/06. 9pp. 33050:309-33050:317.
- 8510170268** Forwards comments re 760224 ltr informing NRC of steps taken to correct noncompliance noted in 760210 ltr. Comments withheld (ref 10CFR2.790). HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/04/09. DELINE, R.D. Dow Chemical Co. 18pp. 33050:318-33050:335.
- 8510170270** Discusses insp on 780110-12, per 780113 telcon re positive access controls. Enforcement correspondence will be forwarded upon completion of review of insp findings. Analysis of proposed civil penalty encl. Portions deleted. KEPPLER, J.G. Region 3, Chicago, Office of the Director. 78/01/13. LANGNER, R. Dow Chemical Co. 11pp. 33050:336-33050:346.
- 8510170322** Discusses noncompliance from security insp. Issuance of civil penalty recommended. W/o 780113 immediate action ltr & licensee reply. Draft insp rept & notice of violation encl. Portions deleted (ref 10CFR2.790). KEPPLER, J.G. Region 3, Chicago, Office of the Director. 78/03/02. HALLER, N.M. Division of Safeguards Inspections. 24pp. 33051:010-33051:033.
- 8510170327** Forwards Insp Rept 50-264/78-01 on 780110-12 & notice of violation. HIND, J.A. Region 3, Chicago, Safeguards Branch. 78/07/12. HANES, J.H. Dow Chemical Co. 2pp. 33051:034-33051:035.
- 8510170329** Notice of violation from insp on 780110-12. Portions deleted (ref 10CFR2.790). * NRC - No Detailed Affiliation Given. 78/07/12. 1p. 33051:036-33051:036.
- 8510170334** Insp Rept 50-264/78-01 on 780110-12. Noncompliance noted re security organization & access controls. Portions deleted (ref 10CFR2.790). Written statement in reply to notice of violation encl. MADEDA, T.J., DUNLEAVY, J.J., HIND, J.A. Region 3, Chicago, Office of the Director. 78/07/11. 14pp. 33051:037-33051:057.

Q. Inspection reports, IE Bulletins & correspondence

- 8510170221** Final response to FOIA request for documents re Dow Chemical Co. Forwards Apps O & P documents. Documents also available in PDR App Q documents withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 85/10/04. KOHN, S. Government Accountability Project. 5pp. 33050:297-33051:057.
- 8510170234** Notifies that reactor room & lab secured to prevent unauthorized entry in response to 780112 ltr. Updated security plan will be submitted after radiation safety committee meets to discuss reactor security. LANGNER, R.R. Dow Chemical Co. 78/01/19. KEPPLER, J.G. Region 3, Chicago, Office of the Director. 1p. 33050:303-33050:303.
- 8510170242** Forwards enforcement ltr & Initial Physical Security Insp Rept 50-264/76-01 on 760115-16. Portions deleted. HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/02/09. ROY, G.W. Office of Inspection & Enforcement, Office of the Director. 2pp. 33050:304-33050:305.
- 8510170252** Forwards Physical Protection Insp Rept 50-264/76-01 on 760115-16 & notice of violation. HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/02/10. DELINE, R.D. Dow Chemical Co. 2pp. 33050:306-33050:307.
- 8510170260** Notice of violation from physical protection insp on 760115-16. Portions deleted. * NRC - No Detailed Affiliation Given. 76/02/10. 1p. 33050:308-33050:308.
- 8510170263** Physical Protection Insp Rept 50-264/76-01 on 760115-16. Noncompliance noted re communications & access control. Portions withheld (ref 10CFR2.790). BELANGER, J.L. Region 3, Chicago, Office of the Director. 76/02/06. 9pp. 33050:309-33050:317.
- 8510170268** Forwards comments re 760224 ltr informing NRC of steps taken to correct noncompliance noted in 760210 ltr. Comments withheld (ref 10CFR2.790). HIND, J.A. Region 3, Chicago, Safeguards Branch. 76/04/09. DELINE, R.D. Dow Chemical Co. 18pp. 33050:318-33050:335.
- 8510170270** Discusses insp on 780110-12, per 780113 telcon re positive access controls. Enforcement correspondence will be forwarded upon completion of review of insp findings. Analysis of proposed civil penalty encl. Portions deleted. KEPPLER, J.G. Region 3, Chicago, Office of the Director. 78/01/13. LANGNER, R. Dow Chemical Co. 11pp. 33050:336-33050:346.
- 8510170322** Discusses noncompliance from security insp. Issuance of civil penalty recommended. W/o 780113 immediate action ltr & licensee reply. Draft insp rept & notice of violation encl. Portions deleted (ref 10CFR2.790). KEPPLER, J.G. Region 3, Chicago, Office of the Director. 78/03/02. HALLER, N.M. Division of Safeguards Inspections. 24pp. 33051:010-33051:033.
- 8510170327** Forwards Insp Rept 50-264/78-01 on 780110-12 & notice of violation. HIND, J.A. Region 3, Chicago, Safeguards Branch. 78/07/12. HANES, J.H. Dow Chemical Co. 2pp. 33051:034-33051:035.
- 8510170329** Notice of violation from insp on 780110-12. Portions deleted (ref 10CFR2.790). * NRC - No Detailed Affiliation Given. 78/07/12. 1p. 33051:036-33051:036.
- 8510170334** Insp Rept 50-264/78-01 on 780110-12. Noncompliance noted re security organization & access controls. Portions deleted (ref 10CFR2.790). Written statement in reply to notice of violation encl. MADEDA, T.J., DUNLEAVY, J.J., HIND, J.A. Region 3, Chicago, Office of the Director. 78/07/11. 14pp. 33051:037-33051:057.
- 5. Reportable occurrences, LERs & related correspondence**
- 8510170221** Final response to FOIA request for documents re Dow Chemical Co. Forwards Apps O & P documents. Documents also available in PDR App Q documents withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 85/10/04. KOHN, S. Government Accountability Project. 5pp. 33050:297-33051:057.
- 8510170273** PNS-III-78-004 on 780110, during physical security insp. Lack of positive access controls to reactor bldg discovered. Portions deleted (ref 10CFR2.790). Related draft documents encl. DONAHUE, J.F. Region 3, Chicago, Office of the Director. 78/01/16. 25pp. 33050:347-33051:009.
- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2**
- F. Security, medical, emergency & fire protection plans**
- 8510220166** Forwards revised onsite & offsite maps for Environ Group Procedure 2. Directions for updating procedure listed. LICARI, K. Commonwealth Edison Co. 85/08/22. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33083:296-33083:297.
- 8510040191** Rev 4 to Procedure QEP 520-1, "Training Procedure for Assignment of Personnel to Generating Station Emergency Plan (GSEP) Positions & Associated Training Requirements" & Rev 1 to QEP 520-S2, "GSEP Assignment Request." TOREN, H. Commonwealth Edison Co. 85/09/26. 7pp. 32851:039-32851:044.
- 8510080026** Forwards results of onsite audit of DCRDR, per Suppl 1 to NUREG-0737. Schedule for implementation of corrective actions satisfactory in light of required supplemental rept. VASSALLO, D.B. Operating Reactors Branch 2. 85/09/30. FARRAR, D.L. Commonwealth Edison Co. 3pp. 32926:267-32926:338.
- 8510080375** Revised station emergency procedures, including Rev 30 to QEP 310-0, "Notification of Responsible Authorities" & Rev 16 to QEP 310-T3, "Prioritized Notification Listing." * Commonwealth Edison Co. 85/09/30. 12pp. 32913:157-32913:168.
- 8510110146** Ack receipt of 850927 ltr re annual meeting w/offsite response agencies. NRC does not normally attend plant annual emergency preparedness training to offsite organizations. Notification of dates of training requested. SHAFFER, W.D. Region 3, Office of the Director. 85/10/08. TOREN, H. Commonwealth Edison Co. 1p. 32972:248-32972:249.
- 8510110148** Extends invitation to attend 851016 dinner meeting w/emergency plan offsite support agencies in Cordova, IL. Radiation protection & safety training class will be offered on 851017. KALIVIANAKIS, N. Commonwealth Edison Co. 85/09/27. KEPPLER, J.G. Region 3, Office of the Director. 1p. 32972:249-32972:249.
- 8510160168** Forwards Physical Security Insp Repts 50-254/85-26 & 50-265/85-29 on 850916-19. No noncompliance noted. AXELSON, W.L. Region 3, Office of the Director. 85/10/09. REED, C. Commonwealth Edison Co. 2pp. 33023:126-33023:128.
- 8510160177** Physical Security Insp Repts 50-254/85-26 & 50-265/85-29 on 850916-19. No noncompliance noted. Areas inspected: security program, testing & maint. locks, keys & combinations, lighting & alarm stations. Details withheld (ref 10CFR2.790). PIRTLE, G.L. Region 3, Office of the Director. 85/10/09. 1p. 33023:128-33023:128.
- 8510210064** Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/two oversize drawings. KENEALY, D.M. Commonwealth Edison Co. 85/10/15. 120pp. 33082:263-33083:043.
- 8510210073** Revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environs Group Activities by Environs Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/two oversize drawings. KENEALY, D.M. Commonwealth Edison Co. 85/10/15. 120pp. 33082:263-33083:043.

P. Operating license stage documents & correspondence

- 8510080452** Requests approval of proposed alternate methods & criteria for performing seismic evaluation, including criteria described in FSAR. Forwards "Alternate Seismic Evaluation Criteria/Methodology..." Fee paid. WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921-327-32921-356.
- 8510080456** "Alternate Seismic Evaluation Criteria/Methodology, Quad-Cities Nuclear Station, Units 1 & 2, Dresden Nuclear Station, Units 2 & 3." * Commonwealth Edison Co. 85/09/30. 28pp. 32921-329-32921-356.
- 8510080514** Forwards Rev 0 to COM-83-042, "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." WOJNAROWSKI, J. Commonwealth Edison Co. 85/09/30. THOMPSON, H.L. Division of Licensing. 2pp. 32920-134-32920-216.
- 8510080515** Rev 0 to "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." ANDERSSON, O. NUTECH Engineers, Inc. COM-83-042 R00. 85/09/23. 70pp. 32920-136-32920-216.
- 8510170094** Forwards list of changes, tests & experiments completed during Sept 1985. Summary of safety evaluation reported per 10CFR50.59 Mod M-4-1-81-17 initiated to install add'l supports on CRD insert & withdrawal lines. TAMLYN, T.K. Commonwealth Edison Co. 85/10/01. CASE, E.G. Office of Nuclear Reactor Regulation, Director. 2pp. 33036-231-33036-232.
- 8510170036** Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes. ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.
- 8510170058** Rev 38 to "QA Program for Nuclear Generating Stations." * Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.
- 8510150204** Forwards projected schedule for complying w/10CFR50.62 per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested. ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

Q. Inspection reports, IE Bulletins & correspondence

- 8510090037** Forwards Rev 1 to CEC-20-013, "Evaluation & Disposition of Flaws at Quad-Cities Nuclear Power Plant Unit 2" & summary of Spring 1985 inservice insp results per NRC 850516 request for add'l info for completion of SER. WOJNAROWSKI, J. Commonwealth Edison Co. 85/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32941-344-32942-038.
- 8510090042** Rev 1 to "Evaluation & Disposition of Flaws at Quad-Cities Nuclear Power Plant Unit 2." FROELICH, C.H., WENNER, T.J., BUCHHOLZ, R.H. NUTECH Engineers, Inc. CEC-20-013 R01. 85/07/15. 53pp. 32941-347-32942-038.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510160168** Forwards Physical Security Insp Repts 50-254/85-26 & 50-265/85-29 on 850916-19. No noncompliance noted. AXELSON, W.L. Region 3, Office of Director. 85/10/09. REED, C. Commonwealth Edison Co. 2pp. 33023-126-33023-128.
- 8510160177** Physical Security Insp Repts 50-254/84-26 & 50-265/85-29 on 850916-19. No noncompliance noted. Areas inspected: security program, testing & maint, locks, keys & combinations, lighting & alarm stations. Details withheld (rel 10CFR73.21). PIRTLE, G.L., CREED, J.R. Region 3, Office of Director. 85/10/09. 1p. 33023-128-33023-128.
- 8510160284** Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.
- 8510250153** Forwards Safety Insp Repts 50-254/85-24 & 50-265/85-27 on 850801-0930. No violation noted. CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33173-176-33173-186.

-8510250158 Insp Repts 50-254/85-24 & 50-265/85-27 on 850801-0930. No violation or deviation noted. Major areas inspected: actions on previous insp rept, operation, maint, surveillance, procedures, review of routine & special repts & LER review. WRIGHT, G.C. Region 3, Office of Director. 85/10/18. 9pp. 33173-178-33173-186.

8510210243 Forwards Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. Weaknesses identified re vendor-provided info & recommendations concerning safety-related sys & components. Items will be referred to Region III for action. ZECH, G.G. Vendor Program Branch. 85/10/25. REED, C. Commonwealth Edison Co. 3pp. 33278-107-33278-123.

-8510310247 Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. No potential enforcement items identified. Major areas inspected: licensee/vendor info interface, including sys for receipt, evaluation & implementation of actions. PETTIS, R.L., MCINTYRE, R.P., MIEGEL, N.J. Director's Office, Office of Inspection and Enforcement. 85/10/09. 14pp. 33278-110-33278-123.

8510310327 Forwards Insp Repts 50-254/85-20 & 50-265/85-22 on 850610-14. Potential enforcement finding re inadequate 10CFR21 review & one open item noted. Notification requested if notice of violation not issued within 1 month. W/o encl. GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/10/25. NORELIUS, C.E. Region 3, Office of Director. 1p. 33278-131-33278-131.

R. Periodic operating reports & related correspondence

8510170388 Monthly operating repts for Sept 1985. W/851001 ltr. KRONICH, C.L., TAMLYN, T.K. Commonwealth Edison Co. 85/09/30. 28pp. 33053-289-33053-316.

S. Reportable occurrences, LERs & related correspondence

- 8510090388** LER 85-019-00 on 850908. MSIV closure times failed to meet Tech Spec requirement & shutdown commenced. Caused by incorrect control valve adjustment on hydraulic control cylinder Valves readjusted. W/850924 ltr. MEDULAN, K., KALIVIANAKIS, N. Commonwealth Edison Co. 85/09/24. 3pp. 32946-134-32946-136.
- 8510220009** LER 85-020-00 on 850916. All high level pump trip switches taken out of svc w/o considering Tech Spec requirements to remove broken pencil inside 3-ft level alarm switch. Caused by personnel error. W/851010 ltr. KRONICH, C., KALIVIANAKIS, N. Commonwealth Edison Co. 85/10/10. 5pp. 33095-319-33095-323.

V. Operator Examinations

- 8509240248** Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.
- 8510030083** Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8510070223** Approves 850823 revs to emergency plan. Effectiveness of plan not downgraded. SHAFER, W.D. Region 3, Office of Director. 85/09/30. FAY, C.W. Wisconsin Electric Power Co. 1p. 32878-011-32878-011.
- 8510100006** Forwards Safety Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No noncompliance noted. Response to exercise weaknesses identified during insp & noted in encl app, requested within 45 days. SHAFER, W.D. Region 3, Office of Director. 85/10/04. FAY, C.W. Wisconsin Electric Power Co. 3pp. 32961-009-32961-024.
- 8510100018** Insp Rep's 50-266/85-12 & 50-301/85-12 on 850909-11. No deficiencies, noncompliance or deviation noted. Major areas inspected: emergency preparedness exercise. One weakness noted re notification of unusual event. SNELL, W., WILLIAMSEN, N., BROWN, G. Region 3, Office of Director. 85/10/03. 13pp. 32961-012-32961-024.
- 8510150314** Informs that alternatives for providing alternate shutdown capability for 4,160-volt switchgear room being evaluated. Evaluation should be completed by Nov 1985. BRITT, R.W. Wisconsin Electric Power Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 1p. 33000-324-33000-324.
- 8510280439** Grants extension of completion date until Mar 1986 for compliance w/ Commission 840702 order re submission of DCDR summary rept & proposed implementation schedule per 850521 request. THOMPSON, H.L. Division of Licensing. 85/10/16. FAY, C.W. Wisconsin Electric Power Co. 3pp. 33196-303-33196-305.
- 8510230105** Responds to 851003 ltr re changes in procedures for contacting NRC operations officer following activation of facility emergency plan. Revised procedures adequately meet all NRC concerns. Meeting unnecessary. SHAFER, W.D. Region 3, Office of Director. 85/10/18. FAY, C.W. Wisconsin Electric Power Co. 1p. 33101-250-33101-252.

48 DOCKETED ITEMS

-8510230111 Clarifies procedure until will use when making emergency notifications to NRC. Procedures re collection of all pertinent info needed by NRC being revised. Changes & training of personnel will be completed by 860101.
FAY, C.W. Wisconsin Electric Power Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33101:251-33101:252.

P. Operating license stage documents & correspondence

8510040444 Advises that 831202 response to Generic Ltr 83-26, Items 3.1.3 & 3.2.3 re post-maint testing acceptable. Conclusion supported by encl EG&G Idaho, Inc. rept.
VARGA, S.A. Operating Reactors Branch 1. 85/09/19. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 32859:315-32859:331.

-8509060182 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Ginna, Kewaunee Point Beach Units 1 & 2 & Prairie Island Units 1 & 2."
HAROLDSEN, R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6001. EA-7000. 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859:317-32859:331.

8510040251 Ack receipt of 841119 & 850701 submittals of Rev 3 changes to QA program description. Rev acceptable.
PAPERIELLO, C.J. Region 3, Office of Director. 85/09/30. FAY, C.W. Wisconsin Electric Power Co. 1p. 32851:160-32851:160.

8510080369 Provides proposed schedule for meeting requirements of 10CFR50.62 re reduction of risk from ATWS events for light-water cooled nuclear plants. Brief description of tentative design for PWR listed.
FAY, C.W. Wisconsin Electric Power Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 2pp. 32918:308-32918:309.

8510150165 Informs that complete response to Generic Ltr 85-12 re TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," will be submitted by 851206.
BRITT, R.W. Wisconsin Electric Power Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 2pp. 33010:301-33010:302.

8510170078 Forwards Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively & safety evaluation. Amends define limiting conditions for operation & surveillance requirements for radioactive liquid & gaseous effluent monitoring.
COLBURN, T.G. Operating Reactors Branch 3. 85/10/03. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33043:234-33043:300.

-8510170083 Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively, defining limiting conditions for operation & surveillance requirements for radioactive liquid & gaseous effluent monitoring.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/03. 56pp. 33043:236-33043:291.

-8510170087 Safety evaluation supporting Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/03. 9pp. 33043:292-33043:300.

-8506050540 "Radiological Effluent Tech Specs (RETS) Implementation - Point Beach Nuclear Plant."
SERRANO, W. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6459. EGG-PBS-6863. 85/05/31. NRC - No Detailed Affiliation Given. 32pp. 33043:301-33043:332.

8510150138 Discusses history of qualification effort on pressurizer safety valve direct position indicators (refs NUREG-0578 & NUREG-0737, Item II.D.3.1), per NRC 850927 telcon request.
BRITT, R.W. Wisconsin Electric Power Co. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 5pp. 33013:001-33013:005.

8510160006 Informs of change in plans & current status of rod cluster control assemblies (RCCA), per 830818 & 840627 results of exams. Twelve Unit 1 and six Unit 2 RCCAs replaced.
FAY, C.W. Wisconsin Electric Power Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 3pp. 33027:090-33027:092.

8510280297 Accepts 831107 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing of reactor trip sys components & other safety-related equipment. Safety evaluation encl.
BUTCHER, E.J. Operating Reactors Branch 5. 85/10/18. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33228:179-33228:193.

-8510280300 Safety evaluation accepting until 831107 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing.
* Office of Nuclear Reactor Regulation, Director. 85/10/18. 1p. 33228:181-33228:193.

8510290043 Notifies of completion of evaluation re 850423 ltr concerning time necessary for NRC inspectors to gain initial access to licensed facilities. List of tasks necessary to gain unrestricted plant access encl.
FAY, C.W. Wisconsin Electric Power Co. 85/10/23. KEPPLER, J.G., NORELIUS, C. Region 3, Office of Director. 5pp. 33236:159-33236:163.

Q. Inspection reports, IE Bulletins & correspondence

8510010154 Forwards Safety Insp Repts 50-266/85-17 & 50-301/85-17 on 850903-06. No noncompliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/09/25. FAY, C.W. Wisconsin Electric Power Co. 2pp. 32801:353-32801:362.

-8510010180 Insp Repts 50-266/85-17 & 50-301/85-17 on 850903-06. No violation or deviation noted. Major areas inspected: radiation protection program, including organization & mgmt controls, posting & access controls, contamination control & training.
PAUL, R.A., GREGER, L.R. Region 3, Office of Director. 85/09/24. 8pp. 32801:355-32801:362.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080393 Forwards Safety Insp Rept 50-266/85-18 on 850909-13. No violation noted.
HARFISON, J.J. Region 3, Office of Director. 85/10/02. FAY, C.W. Wisconsin Electric Power Co. 2pp. 32919:284-32919:285.

-8510080398 Insp Rept 50-266/85-18 on 850909-13. No violation or deviation noted. Major areas inspected: core power distribution limits, control rod worth measurements & axial flux difference measurements.
MCCORMICK-BARGE, RING, M.A. Region 3, Office of Director. 85/10/02. 8pp. 32919:286-32919:293.

8510100006 Forwards Safety Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No noncompliance noted. Response to exercise weaknesses identified during insp & noted in encl app, requested within 45 days.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. FAY, C.W. Wisconsin Electric Power Co. 3pp. 32961:009-32961:024.

-8510100018 Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No deficiencies, noncompliance or deviation noted. Major areas inspected: emergency preparedness exercise. One weakness noted re notification of unusual event.
SNELL, W., WILLIAMS, N., BROWN, G. Region 3, Office of Director. 85/10/03. 13pp. 32961:012-32961:024.

8510250271 Forwards Safety Insp Repts 50-266/85-15 & 50-301/85-15 on 850801-0930 & notice of violation.
CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/10. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33173:098-33173:107.

-8510250276 Notice of violation from insp on 850801-0930.
CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/10. 1p. 33173:100-33173:100.

-8510250282 Insp Repts 50-266/85-15 & 50-301/85-15 on 850801-0930. Violation noted: three subcritical spent fuel assemblies moved to positions adjacent to spent fuel pit east wall.
* Region 3, Office of Director. 85/10/10. 7pp. 33173:101-33173:107.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510180502 Monthly operating repts for Sept 1985. W/851010 ltr.
KRAUSE, C.W., FAY, C.W. Wisconsin Electric Power Co. 85/09/30. 9pp. 33067:339-33067:347.

S. Reportable occurrences, LERs & related correspondence

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available.
ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905:053-32905:157.

-8510070192 Provides daily staff notes for 850611. Final rule amending 10CFR9 approved. Events at facilities discussed.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/12. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 21pp. 32911:022-32911:081.

8510100128 LER 85-006-00: on 850903, turbine runback occurred. Caused by voltage spike on red instrument bus, resulting in momentary downward spike on nuclear instrumentation sys. Red inverter inspected & returned to svc. All sys normal. W/851003 ltr.
FAY, C.W. Wisconsin Electric Power Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32960:353-32960:355.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

8510220439 LER 85-007-00: on 850911, turbine runback from 100 to 80% power noted. Caused by momentary interruption of power to instrumentation bus inverter. Unit returned to 100% & conduit packing process stopped. W/851010 ltr.
FAY, C.W. Wisconsin Electric Power Co. 85/10/10. KEPPLER, J.G. Region 3, Office of Director. 3pp. 33096:210-33096:212.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

8510080007 Advises that Div of Disaster Emergency Svcs of State of CO will not participate in full scale emergency exercise until 1987. Decision based on IE Info Notice 85-055.
GAHM, J.W. Public Service Co. of Colorado. 85/09/24. HUNTER, D. Region 4, Office of Director. 1p. 32927-345-32927-345.

8510170171 Informs of status of mods committed to in 850401 ltr (per App R) & forwards changed pages to Repts 3 & 4. Mod proposed to install disconnect switches to interrupt potential faults that could cause Valves FV-2205 & FV-2206 to close.
LEE, O.R. Public Service Co. of Colorado. 85/09/26. HUNTER, D. Region 4, Office of Director. 10pp. 33051-311-33051-320.

8510180168 Revised radiological emergency response plan implementing procedures, including Issue 6 to REPR-CR re control room procedure & Issue 26 to REPR-PHONE LISTS re radiological emergency response plan phone lists. W/851009 ltr.
GAHM, J.W. Public Service Co. of Colorado. 85/10/09. 213pp. 33055-053-33055-266.

8510310566 Clarifies commitment dates in util 850401 ltr re proposed mods per 10CFR50, App R fire protection evaluation. Remaining mods expected to be completed during refueling outage.
WAREMBOURG, D.W. Public Service Co. of Colorado. 85/10/14. HUNTER, D. Region 4, Office of Director. 3pp. 33280-011-33280-013.

P. Operating license stage documents & correspondence

8510090537 Requests interim evaluation re acceptability of automatic & manual control of emergency electrical power sys by 850607, per 850516 meeting w/util. Summary of meeting encl. W/o encl.
LAINAS, G.C. Assistant Director for Operating Reactors. 85/05/28. RUBENSTEIN, L.A. Assistant Director for Core & Plant Systems. 2pp. 32965-084-32965-085.

8510110089 Forwards updated safety evaluation accepting util commitments re tendon surveillance as basis for restart. Util will incorporate modified tendon surveillance program into Tech Specs & provide results 6 months after restart.
THOMPSON, H.L. Division of Licensing. 85/07/02. DENISE, R.P. Region 4, Office of Director. 1p. 33011-315-33011-318.

-8510110109 Safety evaluation accepting util tendon surveillance proposal. Proposal will lead to maintaining structural integrity of reactor vessel. Plant structurally ready for restart.
* Office of Nuclear Reactor Regulation, Director. 85/07/02. 3pp. 33011-316-33011-318.

8510080005 Clarifies commitment in statement of Page 7 of GA Co Document 907785, "NDE of 62 Fuel & Reflector Elements From Fort St Vrain Core Segment 3," per 850321 submittal. Statement made in ref to DOE reporting commitment.
BREY, H.L. Public Service Co. of Colorado. 85/09/18. HUNTER, D. Region 4, Office of Director. 1p. 32927-346-32927-346.

8510010010 Requests 60-day extension for response to SSER & NRC 850708 request for revised procedure for estimating extent of core damage per NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys."
GAHM, J.W. Public Service Co. of Colorado. 85/09/20. HUNTER, D.R. Region 4, Office of Director. 2pp. 32809-211-32809-212.

8510080001 Identifies revised submittal date for draft Tech Specs for helium circulators, steam generators & PCRV liner cooling sys. Due to demands associated w/ plant restart & environ qualification, specs will not be available until 850930.
BREY, H.L. Public Service Co. of Colorado. 85/09/20. HUNTER, D.R. Region 4, Office of Director. 1p. 32927-351-32927-351.

8510090353 Notices of change to one of mods provided in 850312 ltr re helium circulator auxiliary sys. Mod designed to mitigate PCRV moisture ingress. Thermal dispersion type flow elements removed for evaluation by manufacturer.
WAREMBOURG, D.W. Public Service Co. of Colorado. 85/09/20. HUNTER, D. Region 4, Office of Director. 1p. 32947-155-32947-155.

8510080219 Informs of current status & future plans re NRC concerns over beta radiation in radioactive liquid effluents. Util evaluating effectiveness of reactor bldg sump drain mapping & identification program to assure compliance w/ 10CFR20.
GAHM, J.W. Public Service Co. of Colorado. 85/09/25. HUNTER, D. Region 4, Office of Director. 2pp. 32927-355-32927-356.

8510040460 Forwards safety evaluation based on util 850830, 0910, 11 & 23 requests for authorization to operate at max 8% power for up to 45 days, to remove moisture from RCS. Authorization granted, subj to listed commitments.
MARTIN, R.D. Region 4, Office of Director. 85/09/30. LEE, O.R. Public Service Co. of Colorado. 3pp. 32854-187-32854-194.

-8510040463 Safety evaluation supporting util 850830, 0910, 11 & 23 requests for authorization to operate at max 8% power for up to 45 days, to remove moisture from RCS.
* NRC - No Detailed Affiliation Given. 85/09/30. 5pp. 32854-190-32854-194.

8510090149 Forwards draft Tech Specs for helium circulators, steam generators & PCRV liner cooling sys for review & comment. Specs address concerns expressed during 850722-26 meetings re sys operability.
BREY, H.L. Public Service Co. of Colorado. 85/09/30. HUNTER, D.R. Region 4, Office of Director. 34pp. 32943-047-32943-081.

8510090154 Requests extension until 860101 for submitting programmed feedwater flow-low helium circulator allowable value & trip setpoint to plant protective sys Tech Specs. Analysis value review of helium circulator will be completed by 851001.
BREY, H.L. Public Service Co. of Colorado. 85/09/30. HUNTER, D.R. Region 4, Office of Director. 2pp. 32941-259-32941-260.

8510090201 Provides update on util environ qualification of post-accident monitoring equipment. Util unable to file documentation by 850930. Qualification will continue pending NRC response on acceptability of parameters & equipment.
WAREMBOURG, D.W. Public Service Co. of Colorado. 85/09/30. HUNTER, D. Region 4, Office of Director. 2pp. 32942-138-32942-139.

8510110113 Requests transmittal to util of encl responses to issues raised during 850722-26 meetings re Tech Spec upgrade program for guidance in preparing next draft of Tech Specs. Emergency diesel generator Tech Specs also encl.
THOMPSON, H.L. Division of Licensing. 85/09/30. DENISE, R.P. Region 4, Office of Director. 11pp. 33012-133-33012-182.

8510090296 Forwards comments on proposed fuel surveillance program submitted by 850503 ltr. Response to comments & revised program should be submitted within 60 days of ltr receipt. Problems must be corrected prior to program approval.
HUNTER, D.R. Region 4, Office of Director. 85/10/02. LEE, O.R. Public Service Co. of Colorado. 5pp. 32947-098-32947-102.

8510160075 Requests extension of submittal date for final draft of upgraded Tech Specs to 851130. Final draft will include operations personnel review per Action Item 16 of NRC 850822 ltr.
BREY, H.L. Public Service Co. of Colorado. 85/10/08. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33028-011-33028-012.

8510170464 Forwards table re status of operating plants for which licensees requested extensions beyond 851130 environ qualification deadline. Fort St Vrain presently constrained by confirmatory action ltr re operation prior to 851130.
THOMPSON, H.L. Division of Licensing. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33046-359-33046-362.

8510160173 Forwards resubmittal of draft Tech Specs for helium circulators, steam generators & PCRV liner cooling sys. Tech Specs include surveillance requirements for Spec 3.5.1.1 & Figures 3.5.1-1, 3.5.1-2 & 3.5.1-3.
BREY, H.L. Public Service Co. of Colorado. 85/10/11. BUTCHER, E.J. Operating Reactors Branch 3. 40pp. 33021-203-33021-242.

8510250011 Forwards request for addl info on 850924 request for special consideration & schedule extension to equipment qualification rule, 10CFR50.49. Info requested within 7 days of ltr receipt.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/11. LEE, O.R. Public Service Co. of Colorado. 6pp. 33226-247-33226-252.

8510170117 Forwards "Heavy Load Analysis Rept. Phase II" & revised "Heavy Load Analysis Rept. Phase I," per 841205 request to reevaluate control of heavy loads of 1 ton or more. Action items identified from repts listed.
WAREMBOURG, D.W. Public Service Co. of Colorado. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33039-050-33039-155.

-8510170123 Revised "Heavy Load Analysis Rept. Phase I."
* Sargent & Lundy, Inc. 85/10/15. 60pp. 33039-052-33039-109.

-8510170127 "Heavy Load Analysis Rept. Phase II."
* Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 47pp. 33039-110-33039-155.

8510230093 Responds to Generic Ltr 85-06 re QA guidance for nonsafety-related ATWS equipment. Facility not covered by 10CFR50.62. Util will meet w/NRC if necessary to discuss applicability of rule.
BREY, H.L. Public Service Co. of Colorado. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33101-151-33101-152.

8510290352 "Fort St Vrain Nuclear Generating Station Heavy Load Analysis, Phase II."
* Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 46pp. 33240-015-33240-060.

8510290366 "Fort St Vrain Nuclear Generating Station Heavy Load Analysis Phase I."
* Sargent & Lundy, Inc. 85/10/15. 58pp. 33240-260-33240-317.

8510220237 Notices that draft proposed rev to Tech Spec Limiting Condition for Operation 4.1.9 re core region temp rise will be submitted for review by 851122.
BREY, H.L. Public Service Co. of Colorado. 85/10/17. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33087-204-33087-205.

8510230052 Forwards response to 851011 request for addl info re 850924 request for schedule extension for environ qualification program under 10CFR50.49 from 851130 to 860331.
LEE, O.R. Public Service Co. of Colorado. 85/10/21. BUTCHER, E.J. Operating Reactors Branch 3. 24pp. 33101-063-33101-086.

8510290546 Forwards response to NRC action items resulting from Tech Spec upgrade program, per 850722-26 meetings & 850814 telcon. North Anna emergency diesel generator Tech Specs also encl for guidance.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/22. LEE, O.R. Public Service Co. of Colorado. 12pp. 33254-297-33254-347.

Q. Inspection reports, IE Bulletins & correspondence

8510080007 Advises that Div of Disaster Emergency Svcs of State of CO will not participate in full scale emergency exercise until 1987. Decision based on IE Info Notice 85-055.
GAHM, J.W. Public Service Co. of Colorado. 85/09/24. HUNTER, D. Region 4, Office of Director. 1p. 32927-345-32927-345.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510040134 Forwards Insp Rept 50-267/85-23 on 850826-30. No violation or deviation noted.
JOHNSON, E.H. Region 4, Office of Director. 85/09/30. LEE, O.R. Public Service Co. of Colorado. 2pp. 32850-352-32850-356.

-8510040139 Insp Rept 50-267/85-23 on 850826-30. No violation or deviation noted. Major areas inspected: maint, operational safety verification & periodic & special repts.
SKOW, M.E., JAUDON, J.P. Region 4, Office of Director. 85/09/20. 3pp. 32850-354-32850-356.

50 DOCKETED ITEMS

8510090077 Summarizes current status of efforts concerning reevaluation of control/distribution of controlled drawings per 850522 request & nuclear performance enhancement program. Three add'l locations provided w/complete controlled drawings. GAHM,J.W. Public Service Co. of Colorado. 85/09/30. HUNTER,D.R. Region 4, Office of Director. 2pp. 32941.283-32941.284.

8510090251 Ack receipt of 850910 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-267/85-16. JOHNSON,E.H. Region 4, Office of Director. 85/09/30. LEE,O.R. Public Service Co. of Colorado. 1p. 32946.223-32946.225.

-8510090263 Responds to NRC 850813 ltr re violations noted in Insp Rept 50-267/85-16. Corrective actions design for new storage ctr initiated. WAREMBOURG,D.W. Public Service Co. of Colorado. 85/09/10. JOHNSON,E.H. Region 4, Office of Director. 2pp. 32946.224-32946.225.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510090070 Forwards staff evaluation re response to Oct 1984 assessment rept,NUS mgt audit & systematic evaluation of licensee performance rept for 1984. Info should be provided in third quarterly status rept on performance enhancement program. HUNTER,D.R. Region 4, Office of Director. 85/10/03. LEE,O.R. Public Service Co. of Colorado. 2pp. 32941.285-32941.336.

-8510090074 "Staff Evaluation of State of CO PSC Plans to Enhance Mgt of Fort St Vrain Activities." Svc list encl. * NRC - No Detailed Affiliation Given. 85/10/03. 50pp. 32941.287-32941.336.

8510150139 Forwards Safety Insp Rept 50-267/85-26 on 850819-28 NRC will focus increased insp attention on maint & maint-related activities until improved performance achieved. Unresolved items identified in rept will be disposed of by Region IV. PARTLOW,J.G. Division of Inspection Programs (Post 850212). 85/10/08. LEE,O.R. Public Service Co. of Colorado. 2pp. 33030.359-33031.027.

-8510150146 Safety Insp Rept 50-267/85-26 on 850819-28. Three potential enforcement findings & three open items identified. Major areas inspected plant operations, surveillance programs & maint. WHEELER,L.L., DYER,J.E., WHITNEY,L.E. Operating Reactor Program Branch. 85/10/04. 13pp. 33030.361-33031.027.

8510160108 Confirms L. Brey 851011 visit to Region IV to discuss progress on performance enhancement program. JOHNSON,E.H. Region 4, Office of Director. 85/10/09. LEE,O.R. Public Service Co. of Colorado. 1p. 33023.355-33023.355.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510290122 Forwards status rept for performance enhancement program for 850603-0930 per SALP 850529 meeting commitment. BREY,H.L. Public Service Co. of Colorado. 85/10/21. JOHNSON,E.H. Region 4, Office of Director. 46pp. 33235.216-33235.260.

8510310296 Ack receipt of 850904 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-267/85-14. MARTIN,L.E. Region 4, Office of Director. 85/10/25. LEE,O.R. Public Service Co. of Colorado. 1p. 33270.135-33270.138.

-8510310307 Responds to NRC 850802 ltr re violations noted in Insp Rept 50-267/85-14. Corrective actions interim rev to controlled work procedure manual issued to correct Section 5.3.1.3 re use of checklists. GAHM,J.W. Public Service Co. of Colorado. 85/09/04. JOHNSON,E.H. Region 4, Office of Director. 3pp. 33270.136-33270.138.

8510310444 Ack receipt of 850923 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-267/85-07. MARTIN,L.E. Region 4, Office of Director. 85/10/25. LEE,O.R. Public Service Co. of Colorado. 1p. 33276.015-33276.025.

-8510310532 Responds to NRC 850821 ltr re violations noted in Insp Rept 50-267/85-07. Corrective actions: SMAP-1 revised to direct operators on how to correctly fill out surveillance procedures & work packages reviewed. GAHM,J.W. Public Service Co. of Colorado. 85/09/23. JOHNSON,E.H. Region 4, Office of Director. 10pp. 33276.016-33276.025.

R. Periodic operating reports & related correspondence

8510220407 Monthly operating rept for Sept 1985 W/851011 ltr. NOVACHEK,F., GAHM,J.W. Public Service Co. of Colorado. 85/09/30. 9pp. 33096.355-33096.363.

S. Reportable occurrences, LERs & related correspondence

8510170457 LER 85-009-01 on 850803. Loop 1 automatic shutdown initiated by plant protective sys. Caused by short of intermodular connections between two loop trouble logic modules. Connections repaired W/851003 ltr. EGGBROTEN,J., GAHM,J.W. Public Service Co. of Colorado. 85/10/03. HUNTER,D. Region 4, Office of Director. 6pp. 33053.221-33053.228.

8510170462 LER 85-015-00 on 850903. Circulator A trip on high buffer-mid-buffer differential pressure occurred. Caused by abnormal cycling of bearing water main drain control valve. Valve positioner replaced W/851003 ltr. EGGBROTEN,J., GAHM,J.W. Public Service Co. of Colorado. 85/10/03. HUNTER,D. Region 4, Office of Director. 5pp. 33053.229-33053.233.

8510220436 LER 85-016-00 on 850913. Helium circulation A tripped on buffer-mid-buffer differential. Caused by bearing water entry into mid-buffer sense line. Water removed by helium "blow down" method W/851011 ltr. EGGBROTEN,J., HILL,J., GAHM,J.W. Public Service Co. of Colorado. 85/10/11. JOHNSON,E.H. Region 4, Office of Director. 6pp. 33096.204-33096.209.

8510240156 LER 85-017-00 on 850916. Unplanned actuation of plant protective sys occurred during surveillance testing. Caused by personnel error. Operations Order 85-19 issued to clarify reportability requirements W/851016 ltr. EGGBROTEN,J., GAHM,J.W. Public Service Co. of Colorado. 85/10/16. 5pp. 33156.347-33156.351.

8510310165 LER 85-018-00 on 850925. Automatic actuation of plant protective sys reactor scram circuitry occurred. Caused by personnel error while troubleshooting circulator D inlet temp. Personnel counseled W/851016 ltr. EGGBROTEN,J., HEIN,G., GAHM,J.W. Public Service Co. of Colorado. 85/10/25. 4pp. 33291.314-33291.317.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-239 OCONEE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080335 Requests withdrawal of 831111 application for exemption from Section III G.2 of 10CFR50.48. App R Mock-up of fire barrier wall separating east & west penetration rooms demonstrated compliance w/fire endurance requirements. TUCKER,H.B. Duke Power Co. 85/09/30. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. STOLZ,J.F. Operating Reactors Branch 4. 3pp. 32913.197-32913.199.

8510020243 Summary of 850212-14 meetings w/util in Seneca, SC re review of util response to NUREG-0737 Item III D.3.4, "Control Room Habitability Requirements" & status of open items concerning emergency feedwater sys. Attendance list encl. NICOLARAS,H. Operating Reactors Branch 4. 85/10/01. Operating Reactors Branch 4. 6pp. 32846.252-32846.266.

8510080165 Rev 85-8 to emergency plan implementing procedures. Vol B, Chemistry Manual 5.1, "Emergency Responses" & health physics manual. Section 11.1, "Health Physics Emergency Response." W/851001 ltr. TUCKMAN,M.S., TUCKER,H.B. Duke Power Co. 85/10/01. GRACE,J.N. Region 2, Office of Director. 33pp. 32950.358-32950.358.

8510210067 Rev 85-9 to Vol B of emergency plan implementing procedure manual, "Health Physics Emergency Response." W/851010 ltr. TUCKMAN,M.S., TUCKER,H.B. Duke Power Co. 85/10/10. GRACE,J.N. Region 2, Office of Director. 17pp. 33073.211-33073.227.

8510210075 Rev 85-6 to Vol C of emergency plan implementing procedures, including Procedure RP/O/B/1000/15, "Offsite Communicator," emergency telephone numbers & table of contents. TUCKMAN,M.S., TUCKER,H.B. Duke Power Co. 85/10/10. GRACE,J.N. Region 2, Office of Director. 34pp. 33072.090-33072.125.

8510240384 Forwards Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21). GRACE,J.N. Region 2, Office of Director. 85/10/17. TUCKER,H.B. Duke Power Co. 2pp. 33151.336-33151.338.

-8510240392 Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06. Violation noted: inadequate procedure for documentation of vital area barrier insp. Details withheld (ref 10CFR2.790(d) & 73.21). PERNY,C.D. Region 2, Office of Director. 85/10/02. 1p. 33151.338-33151.338.

I. Financial information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept." including financial forecast for 1985-1987 & interim financial statements for 850630. TUCKER,H.B. Duke Power Co. 85/10/17. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. 3pp. 33246.245-33246.310.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements. TUCKER,H.B. Duke Power Co. 85/03/01. GRACE,J.N. Region 2, Office of Director. 3pp. 32865.148-32865.239.

-8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-IX withheld. * Duke Power Co. 85/03/01. 46pp. 32865.194-32865.239.

8510040565 Summary of 841107 meeting w/util in Washington, DC re cost/benefit evaluation of reactor vessel coolant inventory tracking sys. Viewgraphs, meeting agenda & list of attendees encl. NICOLARAS,H. Operating Reactors Branch 4. 85/07/24. Operating Reactors Branch 4. 45pp. 32861.249-32861.293.

8510090075 Forwards Amends 142,142 & 139 to Licenses DPR-38,DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to support operation of Unit 3 at full rated power during Cycle 9.
NICOLARAS,H. Operating Reactors Branch 4. 85/09/19. TUCKER,H.B. Duke Power Co. 2pp. 32963:342-32964:008.

-8510090080 Amends 142,142 & 139 to Licenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to support operation of Unit 3 at full rated power during Cycle 9 in area of core protection safety limits.
STOLZ,J.F. Operating Reactors Branch 4. 85/09/19. 20pp. 32963:344-32964:001.

-8510090088 Safety evaluation supporting Amends 142,142 & 139 to Licenses DPR-38,DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/19. 7pp. 32964:002-32964:008.

8510010259 Application for amends to Licenses DPR-38,DPR-47 & DPR-55, revising Tech Specs to delete ref to reload fuel assembly & rod enrichment requirements. Fee paid.
TUCKER,H.B. Duke Power Co. 85/09/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 3pp. 32802:227-32802:236.

-8510010262 Proposed Tech Specs, deleting ref to reload fuel assembly & rod enrichment requirements.
* Duke Power Co. 85/09/24. 7pp. 32802:230-32802:236.

8510070263 Submits verification results for serial numbers on each IRVSP capsule in Lynchburg Research Ctr storage pool, per Rev 2 to BAW-1543.
TAYLOR,J.H. Babcock & Wilcox Co. 85/10/01. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32877:312-32877:313.

8510090319 Forwards topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
STOLZ,J.F. Operating Reactors Branch 4. 85/10/01. TUCKER,H.B. Duke Power Co. 2pp. 32949:176-32949:185.

-8510090321 Topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 8pp. 32949:178-32949:185.

85100100155 Forwards response to NRC 850603 request for addl info on NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves." PORV control circuit components located in cable room & not subj to harsh environ.
TUCKER,H.B. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 43pp. 32962:223-32962:266.

8510160278 Advises that due to delay in issuance of B&W Owners Group QA guidance for final design info on diverse scram sys/ATWS mitigation sys actuation circuitry sys will be submitted 60 days after review of design basis document.
TUCKER,H.B. Duke Power Co. 85/10/09. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 2pp. 33026:249-33026:250.

8510210074 Forwards addl info re util 850610 waste vol reduction incinerator license submittal, in response to NRC 350906 request. Revised submittal will be forwarded by 851122, in response to Questions A-2,B-1,-2,-3,-4 & -5.
TUCKER,H.B. Duke Power Co. 85/10/09. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 61pp. 33073:228-33073:288.

8510210189 Forwards Amends 143,143 & 140 to Licenses DPR-38,DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak tests.
NICOLARAS,H. Operating Reactors Branch 4. 85/10/09. TUCKER,H.B. Duke Power Co. 2pp. 33094:140-33094:154.

-8510210194 Amends 143,143 & 140 to Licenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak test of connected sys.
STOLZ,J.F. Operating Reactors Branch 4. 85/10/09. 11pp. 33094:142-33094:152.

-8510210197 Safety evaluation supporting Amends 143,143 & 140 to Licenses DPR-38,DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/09. 2pp. 33094:153-33094:154.

8510180512 Forwards safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1. Reviews & other actions accepted. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
STOLZ,J.F. Operating Reactors Branch 4. 85/10/11. TUCKER,H.B. Duke Power Co. 3pp. 33077:196-33077:205.

-8510180517 Safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1, accepting reviews & other actions. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
* Office of Nuclear Reactor Regulation, Director. 85/10/11. 5pp. 33077:201-33077:205.

8510300188 Forwards Amends 144,144 & 141 to Licenses DPR-38,DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to delineate need for administrative controls to limit hours for staff performing safety-related functions.
NICOLARAS,H. Operating Reactors Branch 4. 85/10/21. TUCKER,H.B. Duke Power Co. 2pp. 33261:332-33261:346.

-8510300193 Amends 144,144 & 141 to Licenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to delineate need for administrative controls to limit working hours for station staff performing safety-related functions.
STOLZ,J.F. Operating Reactors Branch 4. 85/10/21. 8pp. 33261:334-33261:341.

-8510300211 Safety evaluation supporting Amends 144,144 & 141 to Licenses DPR-38,DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 5pp. 33261:342-33261:346.

8510310248 Submits addl info re NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves." New middle ring setting for Unit 1 will be changed to -50 during end of Cycle 10 refueling outage scheduled to begin on 8/09/92.
TUCKER,H.B. Duke Power Co. 85/10/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 1p. 33273:241-33273:241.

Q. Inspection reports, IE Bulletins & correspondence

8510030296 Forwards Exam Rept 50-269/OL-85-02 for exam administered on 850819. BROWNLEE,V.L. Region 2, Office of Director. 85/09/25. TUCKER,H.B. Duke Power Co. 2pp. 32846:142-32846:251.

-8510030298 Exam Rept 50-269/OL-85-02 on 850819-22 Exam results: 12 candidates passed written exam & 13 candidates passed simulator & oral exams.
LAWYER,S., WILSON,B.A. Region 2, Office of Director. 85/09/23. 108pp. 32846:144-32846:251.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON,D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT,J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510070466 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-269/85-20, 50-270/85-20 & 50-287/85-20. Corrective actions: program developed to ensure proper station responsibility assignments for surveillance, maint & reporting.
TUCKER,H.B. Duke Power Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 9pp. 32878:345-32878:353.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510180527 Responds to 840409 denial of violation from Insp Repts 50-269/83-34, 50-270/83-34 & 50-287/83-34 re posting of chemical treatment pond as radioactive waste area. Agrees no violation occurred.
GRACE,J.N. Region 2, Office of Director. 85/09/30. TUCKER,H.B. Duke Power Co. 1p. 33068:009-33068:009.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070465 Forwards Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06 & notice of violation.
WALKER,R.D. Region 2, Office of Director. 85/10/01. TUCKER,H.B. Duke Power Co. 2pp. 32878:115-32878:126.

-8510070497 Notice of violation from Insp on 850903-06.
* Region 2, Office of Director. 85/10/01. 2pp. 32878:117-32878:118.

-8510070500 Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06. Violations noted: failure to use qualified weld procedures & to obtain final QA approval on reactor coolant pump replacement bolts prior to startup.
ECONOMOS,N., BLAKE,J.J. Region 2, Office of Director. 85/09/24. 8pp. 32878:119-32878:126.

8510070505 Forwards Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13. No violations or deviations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/01. TUCKER,H.B. Duke Power Co. 1p. 32878:102-32878:114.

-8510070513 Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13. No violation or deviation noted. Major areas inspected: QA program review, QA/QC administration, procurement, receipt, storage & handling & previous findings.
RUNYAN,M.F., MOORMAN,J.H., BELISLE,G.A. Region 2, Office of Director. 85/09/26. 12pp. 32878:103-32878:114.

8510160017 Forwards response to 850722 request for addl info re inservice insp relief requests for second 10-yr interval.
TUCKER,H.B. Duke Power Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. STOLZ,J.F. Operating Reactors Branch 4. 15pp. 33029:001-33029:015.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510240384 Forwards Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
GRACE,J.N. Region 2, Office of Director. 85/10/17. TUCKER,H.B. Duke Power Co. 2pp. 33151:336-33151:338.

-8510240392 Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06. Violation noted: inadequate procedure for documentation of vital area barrier Insp Details withheld (ref 10CFR2.790(d) & 73.21).
PERNY,C.D., MASNYK,O.M., MCGUIRE,D.R. Region 2, Office of Director. 85/10/02. 1p. 33151:338-33151:338.

52 DOCKETED ITEMS

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510170185 Forwards "Environ Radiological Monitoring Program Annual Operating Rept, 1984." W/o encl.
TUCKER, H.B. Duke Power Co. 85/07/30. GRACE, J.N. Region 2, Office of Director. 1p. 33051-328-33051-356.

8510220094 Monthly operating repts for Sept 1985. W/851015 ltr.
REAVIS, J.A., TUCKER, H.B. Duke Power Co. 85/09/30. 17pp. 33095-130-33095-146.

S. Reportable occurrences, LERs & related correspondence

8510010231 LER 85-012-00 on 850819, determined that several reactor bldg tendon insps not performed & insp repts not sent to NRC on time. Caused by misinterpretation of Tech Specs. Administrative directives revised. W/850919 ltr.
GODWIN, S.G., TUCKER, H.B. Duke Power Co. 85/09/19. 4pp. 32809-236-32809-239.

8510180086 PNO-II-85-094 on 851007, unit shut down due to steam generator tube leak. Leakage amounted to 0.15 gallon per minute & increasing. Generator isolated. Shutdown expected for 10-12 days.
BURGER, C., PANCIERA, V., Region 2, Office of Director. 85/10/08. 1p. 33062-155-33062-155.

8510180014 Notification of 851021-24 site visits to discuss operating experience associated w/loss of safety function events due to personnel actions on wrong train of redundant sys or wrong unit of multi-unit facilities.
HOOD, D.S. Licensing Branch 4. 85/10/11. ADENSAM, E.G. Licensing Branch 4. 5pp. 33069-354-33069-358.

V. Operator Examinations

8510030296 Forwards Exam Rept 50-269/OL-85-02 for exam administered on 850819.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. TUCKER, H.B. Duke Power Co. 2pp. 32846-142-32846-251.

-8510030296 Exam Rept 50-269/OL-85-02 on 850819-22. Exam results: 12 candidates passed written exam & 13 candidates passed simulator & oral exams.
LAWYER, S., WILSON, B.A. Region 2, Office of Director. 85/09/23. 108pp. 32846-144-32846-251.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510080335 Requests withdrawal of 831111 application for exemption from Section III.G.2 of 10CFR50.48. App R. Mock-up of fire barrier wall separating east & west penetration rooms demonstrated compliance w/fire endurance requirements.
TUCKER, H.B. Duke Power Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 32913-197-32913-199.

8510020243 Summary of 850212-14 meetings w/util in Seneca, SC re review of util response to NUREG-0737, Item III.D.3.4, "Control Room Habitability Requirements" & status of open items concerning emergency feedwater sys. Attendance list encl.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/01. Operating Reactors Branch 4. 6pp. 32846-252-32846-286.

8510080165 Rev 85-8 to emergency plan implementing procedures, Vol B, Chemistry Manual 5.1, "Emergency Responses" & health physics manual, Section 11.1, "Health Physics Emergency Response." W/851001 ltr.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/01. GRACE, J.N. Region 2, Office of Director. 33pp. 32950-358-32950-358.

8510210067 Rev 85-9 to Vol B of emergency plan implementing procedure manual, "Health Physics Emergency Response." W/851010 ltr.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/10. GRACE, J.N. Region 2, Office of Director. 17pp. 33073-211-33073-227.

8510210075 Rev 85-6 to Vol C of emergency plan implementing procedures, including Procedure RP/O/B/1000/15, "Offsite Communicator," emergency telephone numbers & table of contents.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/10. GRACE, J.N. Region 2, Office of Director. 34pp. 33072-090-33072-125.

8510240384 Forwards Insp Repts 50-269/85-26, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
GRACE, J.N. Region 2, Office of Director. 85/10/17. TUCKER, H.B. Duke Power Co. 2pp. 33151-336-33151-338.

-8510240392 Insp Repts 50-269/85-26, 50-270/85-28 & 50-287/85-28 on 850903-06. Violation noted: inadequate procedure for documentation of vital area barrier insp. Details withheld (ref 10CFR2.790(d) & 73.21).
PERNY, C.D. Region 2, Office of Director. 85/10/02. 1p. 33151-336-33151-338.

I. Financial Information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept," including financial forecast for 1985-1987 & interim financial statements for 850630.
TUCKER, H.B. Duke Power Co. 85/10/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33246-245-33246-310.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER, H.B. Duke Power Co. 85/03/01. GRACE, J.N. Region 2, Office of Director. 3pp. 32865-148-32865-239.

-8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-X withheld.
* Duke Power Co. 85/03/01. 46pp. 32865-194-32865-239.

8510040565 Summary of 841107 meeting w/util in Washington, DC re cost/benefit evaluation of reactor vessel coolant inventory tracking sys. Viewgraphs, meeting agenda & list of attendees encl.
NICOLARAS, H. Operating Reactors Branch 4. 85/07/24. Operating Reactors Branch 4. 45pp. 32861-249-32861-293.

8510090075 Forwards Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to support operation of Unit 3 at full rated power during Cycle 9.
NICOLARAS, H. Operating Reactors Branch 4. 85/09/19. TUCKER, H.B. Duke Power Co. 2pp. 32963-342-32964-008.

-8510090080 Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to support operation of Unit 3 at full rated power during Cycle 9 in area of core protection safety limits.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/19. 20pp. 32963-344-32964-001.

-8510090088 Safety evaluation supporting Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/19. 7pp. 32964-002-32964-008.

8510010259 Application for amends to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs to delete ref to reload fuel assembly & rod enrichment requirements. Fee paid.
TUCKER, H.B. Duke Power Co. 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 32802-227-32802-236.

-8510010262 Proposed Tech Specs, deleting ref to reload fuel assembly & rod enrichment requirements.
* Duke Power Co. 85/09/24. 7pp. 32802-230-32802-236.

8510070263 Submits verification results for serial numbers on each IRVSP capsule in Lynchburg Research Ctr storage pool, per Rev 2 to BAW-1543.
TAYLOR, J.H. Babcock & Wilcox Co. 85/10/01. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 32877-312-32877-313.

8510090319 Forwards topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/01. TUCKER, H.B. Duke Power Co. 2pp. 32949-176-32949-185.

-8510090321 Topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 8pp. 32949-178-32949-185.

8510010155 Forwards response to NRC 850603 request for addl info on NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves." PORV control circuit components located in cable room & not subj to harsh environ.
TUCKER, H.B. Duke Power Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 43pp. 32962-223-32962-266.

8510080175 "Oconee 2, Cycle 8 Startup Test Rept, Part I, Zero Power Physics Testing, Part II, Power Escalation Testing." W/851002 ltr.
PARSONS, C.H., TUCKER, H.B. Duke Power Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 18pp. 32920-001-32920-018.

8510160278 Advises that due to delay in issuance of B&W Owners Group QA guidance ltr, final design info on diverse scram sys/ATWS mitigation sys actuation circuitry sys will be submitted 60 days after review of design basis document.
TUCKER, H.B. Duke Power Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33026-249-33026-250.

8510210074 Forwards addl info re util 850610 waste vol reduction incinerator license submittal, in response to NRC 850906 request. Revised submittal will be forwarded by 851122 in response to Questions A-2-B-1, -2, -3, -4 & -5.
TUCKER, H.B. Duke Power Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 61pp. 33073-228-33073-288.

8510210189 Forwards Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak tests.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/09. TUCKER, H.B. Duke Power Co. 2pp. 33094-140-33094-154.

-8510210194 Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak test of connected sys.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/09. 11pp. 33094-142-33094-152.

-8510210197 Safety evaluation supporting Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/09. 2pp. 33094-153-33094-154.

8510180512 Forwards safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1 Reviews & other actions accepted. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/11. TUCKER, H.B. Duke Power Co. 3pp. 33077:199-33077:205.

-8510180517 Safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1, accepting reviews & other actions. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
* Office of Nuclear Reactor Regulation, Director. 85/10/11. 5pp. 33077:201-33077:205.

8510300188 Forwards Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to delineate need for administrative controls to limit hours for staff performing safety-related functions.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/21. TUCKER, H.B. Duke Power Co. 2pp. 33261:332-33261:346.

-8510300193 Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to delineate need for administrative controls to limit working hours for station staff performing safety-related functions.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/21. 8pp. 33261:334-33261:341.

-8510300211 Safety evaluation supporting Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 5pp. 33261:342-33261:346.

8510310248 Submits addl info re NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves." New middle ring setting for Unit 1 will be changed to -50 during end of Cycle 10 refueling outage scheduled to begin on 870920.
TUCKER, H.B. Duke Power Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33273:241-33273:241.

G. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510070466 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-269/85-20, 50-270/85-20 & 50-287/85-20. Corrective actions: program developed to ensure proper station responsibility assignments for surveillance, maint & reporting.
TUCKER, H.B. Duke Power Co. 85/09/27. GRACE, J.N. Region 2, Office of Director. 9pp. 32878:345-32878:353.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510180527 Responds to 840409 denial of violation from Insp Repts 50-269/83-34, 50-270/83-34 & 50-287/83-34 re posting of chemical treatment pond as radioactive materials area. Agrees no violation occurred.
GRACE, J.N. Region 2, Office of Director. 85/09/30. TUCKER, H.B. Duke Power Co. 1p. 33068:009-33068:009.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070495 Forwards Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06 violations noted failure to use qualified weld procedures & to obtain final QA approval on reactor coolant pump replacement bolts prior to startup.
WALKER, R.D. Region 2, Office of Director. 85/10/01. TUCKER, H.B. Duke Power Co. 2pp. 32878:115-32878:126.

-8510070497 Notice of violation from insp on 850903-06.
* Region 2, Office of Director. 85/10/01. 2pp. 32878:117-32878:118.

-8510070500 Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06 violations noted failure to use qualified weld procedures & to obtain final QA approval on reactor coolant pump replacement bolts prior to startup.
ECONOMOS, N., BLAKE, J.J. Region 2, Office of Director. 85/09/24. 8pp. 32878:119-32878:126.

8510070505 Forwards Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13 No violation or deviation noted. Major areas inspected: QA program review, QA/QC administration, procurement, receipt, storage & handling & previous findings.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/01. TUCKER, H.B. Duke Power Co. 1p. 32878:102-32878:114.

-8510070513 Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13 No violation or deviation noted. Major areas inspected: QA program review, QA/QC administration, procurement, receipt, storage & handling & previous findings.
RUYAN, M.F., MOORMAN, J.H., BELISLE, G.A. Region 2, Office of Director. 85/09/26. 12pp. 32878:103-32878:114.

8510160017 Forwards response to 850722 request for addl info re inservice insp relief requests for second 10-yr interval.
TUCKER, H.B. Duke Power Co. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 15pp. 33029:001-33029:015.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510240384 Forwards Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
GRACE, J.N. Region 2, Office of Director. 85/10/17. TUCKER, H.B. Duke Power Co. 2pp. 33151:336-33151:338.

-8510240392 Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 Violation noted: inadequate procedure for documentation of vital area barrier insp Details withheld (ref 10CFR2.790(d) & 73.21).
PERNY, C.D., MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/02. 1p. 33151:338-33151:338.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510170185 Forwards "Environ Radiological Monitoring Program Annual Operating Rept, 1984." W/o encl.
TUCKER, H.B. Duke Power Co. 85/07/30. GRACE, J.N. Region 2, Office of Director. 1p. 33051:328-33051:356.

8510220094 Monthly operating rpts for Sept 1985 W/851015 ltr.
REAVIS, J.A., TUCKER, H.B. Duke Power Co. 85/09/30. 17p. 33095:130-33095:146.

S. Reportable occurrences, LERs & related correspondence

8510180014 Notification of 851021-24 site visits to discuss operating experience associated w/loss of safety function events due to personnel actions on wrong train of redundant sys or wrong unit of multi-unit facilities.
HOOD, D.S. Licensing Branch 4. 85/10/11. ADENSAM, E.G. Licensing Branch 4. 5pp. 33069:354-33069:358.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8510080198 Advises that emergency plan revised to incorporate use of new emergency operations facility located adjacent to corporate ofc bldg. Revised plan will go into effect on 850916.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/12. MARTIN, T.T. Region 1, Office of Director. 1p. 32921:041-32921:041.

8510080352 Responds to region 850703 meeting requests re util 1985 emergency exercise. Authority & responsibility of key managers will be evaluated & changes will be incorporated in plan before next annual exercise.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/12. MARTIN, T.T. Region 1, Office of Director. 24pp. 32919:315-32919:338.

8510110097 Responds to 850918 telcon request for info re installation of carpet over vinyl tile floor as part of control room upgrade program. Carpet installation represents human factors enhancement.
CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 85/10/08. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32973:309-32973:310.

8510250215 Forwards Physical Security Insp Rept 50-271/85-31 on 850924-26 Apparent violations re access control & compensatory measurements identified. Enforcement conference scheduled on 851021 Rept withheld (ref 10CFR73.21 & 2.790).
MARTIN, T.T. Region 1, Office of Director. 85/10/11. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 33190:042-33190:043.

8510250456 Forwards Safety Insp Rept 50-271/85-28 on 850923-27 No violation or deviation noted Weaknesses noted re radiation protection program.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 33173:019-33173:035.

-8510250458 Insp Rept 50-271/85-28 on 850923-27 No violation or deviation noted Major areas inspected: radiation protection program, including previously identified items, changes, planning & preparation, training & qualification & ALARA.
BICEHOUSE, H., PASCIAK, W. Region 1, Office of Director. 85/10/18. 15pp. 33173:021-33173:035.

8510290567 Notification of Significant Licensee Meeting 85-104 on 851021 w/util in King of Prussia, PA to discuss Insp Rept 50-271/85-31 re unauthorized entry into protected area.
TRIPP, L. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 2pp. 33245:345-33245:346.

8510310211 Forwards addl info in response to NRC 850819 request on 841030 response to Generic Ltr 82-33 re conformance to Rev 3 to Reg Guide 1.97, Suppl 1 to NUREG-0737.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/10/25. VASSALLO, D.B. Operating Reactors Branch 2. 10pp. 33273:163-33273:172.

54 DOCKETED ITEMS

P. Operating license stage documents & correspondence

- 8510180068** Submits schedule for meeting requirements of 10CFR50.62, Paragraphs (c)(1) through (c)(5) per Generic Ltr 85-06. Util alternate rod insertion sys & recirculation pump trip sys described in Attachment 1.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33063.118-33063.121.
- 8510150334** Requests plans & schedule for NRC approved mods for NUREG-0737, Item II K.3.18 re automatic depressurization sys logic, as specified in 830603 ltr.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 3pp. 33033.243-33033.245.
- 8510220212** Application for amend to License DPR-28, consisting of Proposed Change 130, revising Tech Spec Pages 51, 109, 110 & 124 to delete sections requiring valves in equalizer piping be closed during operation. Fee paid.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33090.023-33090.030.
- 8510220217** Proposed Change 130, revising Tech Spec Pages 51, 109, 110 & 124 to delete sections requiring valves in equalizer piping be closed during reactor operation.
* Vermont Yankee Nuclear Power Corp. 85/10/09. 4pp. 33090.027-33090.030.
- 8510250610** Forwards draft technical evaluation rept re licensee response to Generic Ltr 83-28, Item 1.2, "Post-Trip Review: Data & Info Capabilities." Addl info required in order to complete review & preserve present review schedule.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/15. CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 2pp. 33226.271-33226.286.
- 8510250613** Draft "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Ltr 83-28, Item 1.2 'Post-Trip Review: Data & Info Capabilities' for Vermont Yankee Nuclear Power Station)."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-21. DRFT. 85/10/15. NRC - No Detailed Affiliation Given. 14pp. 33226.273-33226.286.
- 8510240320** Discusses scram sys design hydraulic control unit support mod installation schedule. Work on remaining mod to insert & withdrawal line pipe supports will be completed within 5 months following return to normal power operation.
CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 85/10/21. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 33151.309-33151.310.
- 8510280161** Requests meeting to discuss commitment of resources necessary to ensure timely completion of licensee review of RELAP5/LOCA code for LWR sys thermal hydraulic analysis.
HUNTER, D. Vermont Yankee Nuclear Power Corp. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33191.069-33191.071.

Q. Inspection reports, IE Bulletins & correspondence

- 8510080390** Responds to NRC 850718 ltr re violations noted in Insp Rept 50-271/84-11 Existing high radiation monitor locations meet requirements of NUREG-0737, Item II F.1.3. Request for technical deviation from criterion will be sent by 851130.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/26. MARTIN, T.T. Region 1, Office of Director. 2pp. 32919.313-32919.314.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510080223** Forwards Insp Rept 50-271/85-26 on 850903-06. No violation noted. Corrective actions stated in 850425.0531 & 0820 ltrs examined. Reexam of completed actions will be conducted during future insp.
EBNETER, S.D. Region 1, Office of Director. 85/10/01. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 32913.325-32913.341.
- 8510080236** Insp Rept 50-271/85-26 on 850903-06. No violation noted. Major areas inspected QA program implementation in audits, first-level insp of work, offsite safety review committee, procurement & shelf-life controls.
EAPEN, P.K., NAPUDA, G., PRELL, J. Region 1, Office of Director. 85/09/27. 15pp. 32913.327-32913.341.
- 8510160264** Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023.351-33023.354.
- 8510250215** Forwards Physical Security Insp Rept 50-271/85-31 on 850924-26. Apparent violations re access control & compensatory measurements identified. Enforcement conference scheduled on 851021. Rept withheld (ref 10CFR73.21 & 2.790).
MARTIN, T.T. Region 1, Office of Director. 85/10/11. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 33190.042-33190.043.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.241.
- 8510240413** EN-85-070 on 851021 notice of violation & proposed imposition of civil penalties in amount of \$50,000 will be issued to util. Action based on radiological incident re personnel exposure.
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/16. 1p. 33154.122-33154.122.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510250456 Forwards Safety Insp Rept 50-271/85-28 on 850923-27. No violation or deviation noted. Weaknesses noted re radiation protection program.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 2pp. 33173.019-33173.035.

-8510250458 Insp Rept 50-271/85-28 on 850923-27. No violation or deviation noted. Major areas inspected radiation protection program, including previously identified items, changes, planning & preparation, training & qualification & ALARA.
BICEHOUSE, H., PASCIAK, W. Region 1, Office of Director. 85/10/18. 15pp. 33173.021-33173.035.

8510290567 Notification of Significant Licensee Meeting 85-104 on 851021 w/ util in King of Prussia, PA to discuss Insp Rept 50-271/85-31 re unauthorized entry into protected area.
TRIPP, L. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 2pp. 33245.345-33245.346.

8510310166 Discusses Insp 50-271/85-21 on 850809 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000. Incident on 850808 re unplanned occupational radiation exposure of 1.3 rem also discussed.
MURLEY, T.E. Region 1, Office of Director. 85/10/22. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 4pp. 33277.300-33277.305.

-8510310170 Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violation noted: technician given approval to enter restricted area to perform surveys w/o adequate guidance to minimize exposure.
MURLEY, T.E. Region 1, Office of Director. 85/10/22. 2pp. 33277.304-33277.305.

R. Periodic operating reports & related correspondence

- 8510290399** "Semiannual Effluent Release Rept, Jan-June 1985." W/850830 ltr.
CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 85/06/30. MURLEY, T.E. Region 1, Office of Director. 21pp. 33242.328-33242.348.
- 8510220048** Monthly operating rept for Sept 1985. W/851002 ltr.
BURGER, F.J., MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/30. 7pp. 33095.282-33095.288.

S. Reportable occurrences, LERs & related correspondence

8510020274 PNO-I-85-071A on 850927. Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage.
STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825.232-32825.232.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8510020214** Responds to 850830 request for approval to hold one emergency medical assistance drill on 851106 to meet criteria to test medical response capability for emergency plans. Proposal acceptable.
MURLEY, T.E. Region 1, Office of Director. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 1p. 32827.214-32827.215.
- 8510020226** Requests approval to hold one, instead of two, emergency medical assistance drills. Annual drill scheduled for 851106. Drills involve same teams of onsite & offsite personnel & would meet redundant requirement.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/08/30. MURLEY, T.E. Region 1, Office of Director. 1p. 32827.215-32827.215.
- 8510030087** Rev 85-10 to emergency plan procedures manual, including Rev 23 to index, Rev 9 to Addendum 1 re index & Rev 2 to Addendum 2 re event classification guide, distribution list W/850926 ltr.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/09/26. VARGA, S.A. Operating Reactors Branch 1. 38pp. 32844.085-32844.121.
- 8510090375** Trip rept of 850925 site visit re emergency operating procedures (EOPs) audit per Supp 1 to NUREG-0737. Licensee not generating EOPs per procedures generation package & TMI Action Plan Item I.C.1. Attendance list encl.
CLAYTON, H.B. Procedures & Systems Review Branch. 85/10/02. ZIEMANN, D.L. Division of Human Factors Safety. 4pp. 32965.058-32965.061.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33108.088.
- 8510230150** Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/ emergencies.
KAMMERER, C. Office of Congressional Affairs. 85/03/26. MARKEY, E. House of Rep., Energy & Commerce. HUGHES House of Rep. 3pp. 33109.065-33109.067.

8510170161 Notification of 851010 meeting w/utl in Bethesda, MD to discuss emergency operating procedure audit re procedure generation packages.
FISCHER, D.C. Operating Reactors Branch 1. 85/10/07. DENTON, H., EISENHUT, D., LYONS, J. NRC - No Detailed Affiliation Given. 2pp. 33043:109-33043:110.

8510160226 Forwards Safety Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Significant progress in improving emergency preparedness program noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/09. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33023:247-33023:257.

8510160231 Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Major areas inspected: emergency preparedness program w/emphasis on review of deficient areas noted in Insp Repts 50-272/84-39 & 50-311/84-38.
VITO, D.J., AMATO, C.G., COHEN, J. Region 1, Office of Director. 85/10/07. 9pp. 33023:249-33023:257.

8510220316 Forwards proprietary "Responses to Design Info Questionnaire for IAEA." Encl withheld.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/11. THOMPSON, H.L. Division of Licensing. 1p. 33067:293-33067:293.

8510220353 Application for amend to License DPR-70, revising Tech Specs to incorporate fire detection instruments. Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33086:326-33086:330.

8510220354 Proposed Tech Specs incorporating fire detection instrument operability.
* Public Service Electric & Gas Co. of New Jersey. 85/10/16. 2pp. 33086:329-33086:330.

H. General correspondence

8510150286 Forwards "Cancer Mortality & Morbidity (Incidence) Around TMI" & "Assessment of Cancer Mortality Survey in Three TMI Areas..." in response to K Bloudin 850709 ltr. Actions taken as result of Feb 1983 Salem ATWS events also discussed.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/10/09. CRANSTON, A. Senate. 10pp. 33032:202-33032:211.

8510150291 "Cancer Mortality & Morbidity (Incidence) Around TMI."
TOKUHATA, G.K., DIGON, E. Pennsylvania, Commonwealth of. 85/09/30. 52pp. 33032:101-33032:153.

8510150295 "Assessment of Cancer Mortality Survey in Three TMI Areas Selected by Local Residents."
* Pennsylvania, Commonwealth of. 85/09/30. 22pp. 33032:154-33032:201.

8510150300 Requests response to encl K Bloudin 850709 concerns re Salem ATWS event & TMI accident.
CRANSTON, A. Senate. 85/08/30. Office of Congressional Affairs. 10pp. 33032:202-33032:211.

J. Insurance & indemnity information

8510090261 Forwards Endorsement 80 to NELIA Policy NF-230 & Endorsement 65 to MAELU Policy MF-90.
MURAT, A. Marsh & McLennan, Inc. 85/10/03. DINITZ, J. Assistant Director for State & Licensee Relations. 3pp. 32943:031-32943:033.

8510160199 Forwards Secondary Financial Protection Certificates NELIA N-104 & MAELU M-104.
MURAT, A. Marsh & McLennan, Inc. 85/10/08. DINITZ, J. Assistant Director for State & Licensee Relations. 14pp. 33026:37-33026:316.

P. Operating license stage documents & correspondence

8510170382 Forwards Vols 1 & 2 of App 1, "Methods, Mats & Rationale," to "Salem Generating Station 316(b) Demonstration," re Clean Water Act. Microfiche also encl.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/07/03. MURLEY, T.E. Region 1, Office of Director. 2pp. 33064:192-33067:338.

8510170387 Vols 1 & 2 of App 1, "Methods, Mats & Rationale," to "Salem Generating Station 316(b) Demonstration."
* Public Service Electric & Gas Co. of New Jersey. 85/04/30. 1,200pp. 33064:194-33067:338.

8510040518 Forwards Amends 67 & 42 to Licenses DPR-70 & DPR-75, respectively & safety evaluation. Amends add Tech Specs incorporating post-accident sampling program requirements.
FISCHER, D. Operating Reactors Branch 1. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32863:134-32863:147.

8510040522 Amends 67 & 42 to Licenses DPR-70 & DPR-75, respectively, adding Tech Specs to incorporate post-accident sampling program requirements.
VARGA, S.A. Operating Reactors Branch 1. 85/09/16. 10pp. 32863:136-32863:145.

8510040528 Safety evaluation supporting Amends 67 & 42 to Licenses DPR-70 & DPR-75, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/16. 2pp. 32863:146-32863:147.

8510070023 Forwards Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively & safety evaluation. Amends change Tech Specs to add surveillance requirement re testing of safety injection pumps.
FISCHER, D. Operating Reactors Branch 1. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32901:080-32901:091.

8510070027 Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively, adding Tech Spec surveillance requirement re testing of safety injection pumps.
VARGA, S.A. Operating Reactors Branch 1. 85/09/16. 8pp. 32901:082-32901:089.

8510070032 Safety evaluation supporting Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/16. 2pp. 32901:090-32901:091.

8510080108 Responds to NRC 850628 request for add info re TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," per Generic Ltr 85-12. RCS pressure less than 1,450 psig selected as basic criterion for tripping pumps.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/04. THOMPSON, H.L. Division of Licensing. 12pp. 32913:214-32913:225.

8510220270 Submits clarification re Paragraphs 17.2.2 & 17.2.5 of QA program, per R Winters 850926 telcon request. Clarification reviewed & approved on 851004 & will be incorporated in next updated FSAR change.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/08. MURLEY, T.E. Region 1, Office of Director. 3pp. 33083:360-33083:361.

8510220068 Provides proposed schedule for meeting requirements of ATWS rule & brief description of tentative design being considered to meet requirements of 10CFR50.62(c)(1).
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/11. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33081:309-33081:310.

8510240649 Informs that radiation protection/chemistry managers for facilities duly authorized representatives to sign all State of NJ pollution discharge elimination sys related correspondence & repts.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/15. CAPORALE, G. New Jersey, State of. 1p. 33157:214-33157:214.

8510220050 Forwards response to NRC 850722 request for add info on Generic Ltr 83-28, Item 4.5.3 re intervals for online testing. Testing frequencies in 851017 application for Tech Spec change will be used.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33081:296-33081:297.

8510220262 Application for amends to Licenses DPR-70 & DPR-75, changing Tech Specs re analog rod position indication sys. Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33087:090-33087:128.

8510220265 Proposed Tech Spec changes, improving method of calibr of analog rod position indication sys. Significant hazards consideration evaluation encl.
* Public Service Electric & Gas Co. of New Jersey. 85/10/16. 36pp. 33087:093-33087:128.

8510220320 Application for amend to License DPR-70, revising Tech Spec 3.4.9.1, "Pressure/Temp Limits-RCS" & replacing 841015 amend request, based on Capsule "Y." Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33084:128-33084:141.

8510220326 Proposed Tech Spec 3.4.9.1 updating RCS pressure/temp limits & replacing present heatup limit curves.
* Public Service Electric & Gas Co. of New Jersey. 85/10/16. 11pp. 33084:131-33084:141.

8510220353 Application for amend to License DPR-70, revising Tech Specs to incorporate fire detection instruments. Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33086:326-33086:330.

8510220354 Proposed Tech Specs incorporating fire detection instrument operability.
* Public Service Electric & Gas Co. of New Jersey. 85/10/16. 2pp. 33086:329-33086:330.

8510250081 Application for amend to Licenses DPR-70 & DPR-75, adding specs per Generic Ltr 83-28, Item 4.3, "Reactor Trip Breaker Automatic Shunt Trip." Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/17. VARGA, S.A. Operating Reactors Branch 1. 8pp. 33173:129-33173:144.

8510250092 Proposed Tech Specs adding specs per Generic Ltr 83-28, Item 4.3, "Reactor Trip Breaker Automatic Shunt Trip."
* Public Service Electric & Gas Co. of New Jersey. 85/10/17. 8pp. 33173:137-33173:144.

G. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:268.

8510230150 Forwards Press Release 85-51 re NRC proposed fine against utl for two alleged violations concerning program for dealing w/emergencies.
KAMMERER, C. Office of Congressional Affairs. 85/03/26. MARKEY, E. House of Rep. Energy & Commerce. BRADLEY, LAUTENBERG Senate. 3pp. 33109:065-33109:067.

8510110166 Forwards Mgt Meeting Repts 50-272/85-22 & 50-311/85-25 on 850925.
STAROSTECKI, R. Region 1, Office of Director. 85/10/07. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32973:118-32973:153.

8510110171 Mgt Meeting Repts 50-272/85-22 & 50-311/85-25 on 850925. Major areas discussed: status & closeout of utl action plan, submitted in Aug 1985 for improvement of nuclear dept operations & performance indicators of upward trend.
LIMOTH, D.F., NORRHOLM, L.J. Region 1, Office of Director. 85/10/02. 34pp. 32973:120-32973:153.

56 DOCKETED ITEMS

8510160226 Forwards Safety Insp Repts 50-272/85-16 & 50-311/85-18 on 85070-11. No violation noted. Significant progress in improving emergency preparedness program noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/09. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33023-247-33023-257.

8510160231 Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Major areas inspected: emergency preparedness program w/emphasis on review of deficient areas noted in Insp Repts 50-272/84-39 & 50-311/84-38.
VITO, D.J., AMATO, C.G., COHEN, J. Region 1, Office of Director. 85/10/07. 9pp. 33023-249-33023-257.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510220177 Forwards Safety Insp Repts 50-272/85-20 & 50-311/85-22 on 850901-30 & notice of violation.
COLLINS, S.J. Region 1, Office of Director. 85/10/17. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33087-294-33087-308.

8510220181 Notice of violation from insp on 850922.
* Region 1, Office of Director. 85/10/17. 1p. 33087-296-33087-296.

8510220192 Insp Repts 50-272/85-20 & 50-311/85-22 on 850901-30. Violation noted: failure to provide adequate procedural guidance re calculating reactor coolant inventory balance (leak-rate).
LIMROTH, D.F., NORRHOLM, L.J. Region 1, Office of Director. 85/10/10. 12pp. 33087-297-33087-308.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250493 Forwards Safety Insp Repts 50-272/85-21 & 50-311/85-23 on 850909-13. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/21. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33172-271-33172-278.

8510250497 Safety Insp Repts 50-272/85-21 & 50-311/85-23 on 850909-13. No violation or deviation noted. Major areas inspected: routine radiological surveys & area postings, organization & staffing & whole body counting program.
DRAGON, T., SHANBAKY, M. Region 1, Office of Director. 85/10/18. 6pp. 33172-273-33172-278.

R. Periodic operating reports & related correspondence

8510180471 Forwards "Artificial Island Radiological Environ Monitoring Program, 1984 Radiological Rept."
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey. 85/03/26. MURLEY, T.E. Region 1, Office of Director. 2pp. 33068-064-33068-227.

8510180474 "Artificial Island Radiological Environ Monitoring Program, 1984 Radiological Rept."
* PSE&G Research Corp. RTL-ENV-85-01. 84/12/31. 167pp. 33068-066-33068-227.

8510080066 Forwards "NPDES Discharge Monitoring Rept for Aug 1985."
TREJO, J. Public Service Electric & Gas Co. of New Jersey. 85/09/17. RADOW, E. Trenton, NJ. 3pp. 32928-091-32928-111.

8510080091 "NPDES Discharge Monitoring Rept for Aug 1985."
* Public Service Electric & Gas Co. of New Jersey. 85/08/31. 18pp. 32928-094-32928-111.

8510090185 Forwards corrected monthly operating repts for Jul & Aug 1985. Yr-to-date & cumulative gross thermal energy generated values corrected.
ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/23. Director's Office, Office of Inspection and Enforcement. 1p. 32947-175-32947-177.

8510090190 Corrected monthly operating rept for Aug 1985.
RONAFALVY, J.P. Public Service Electric & Gas Co. of New Jersey. 85/08/31. 1p. 32947-176-32947-176.

8510090192 Corrected monthly operating rept for Jul 1985.
RONAFALVY, J.P. Public Service Electric & Gas Co. of New Jersey. 85/07/31. 1p. 32947-177-32947-177.

8510240396 Monthly operating rept for Sept 1985. W/851010 ltr.
WHITE, P., RONAFALVY, J., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/30. 11pp. 33160-044-33160-054.

8510240108 Forwards "NPDES Discharge Monitoring Rept for Sept 1985." Rept presents observed results obtained in accordance w/approved methods for sampling & monitoring.
TREJO, J. Public Service Electric & Gas Co. of New Jersey. 85/10/11. RADOW, E. New Jersey, State of. 3pp. 33156-278-33156-298.

8510240116 "NPDES Discharge Monitoring Rept for Sept 1985."
* Public Service Electric & Gas Co. of New Jersey. 85/09/30. 18pp. 33156-281-33156-298.

8510220315 Forwards "Nuclear Oversight Committee Eighth Quarterly Rept." dtd 851014. Response to rept will be submitted within 30 days.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/18. VARGA, S.A. Operating Reactors Branch 1. 1p. 33086-283-33086-290.

8510220319 "Nuclear Oversight Committee Eighth Quarterly Rept."
* Public Service Electric & Gas Co. of New Jersey. 85/10/14. 7pp. 33086-284-33086-290.

S. Reportable occurrences, LERs & related correspondence

8510020274 PNO-I-85-071A on 850927. Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage.
STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825-232-32825-232.

8510090238 PNO-I-85-075 on 851006. Plant tripped. Caused by condensation in condenser vacuum sensing line reaching sensor causing turbine trip w/automatic reactor trip. Plant in cold shutdown for maint & mod to condenser.
NORRHOLM, L., KENNY, T. Region 1, Office of Director. 85/10/07. 1p. 32942-341-32942-341.

8510220119 LER 85-009-00 on 850913. Fire watch left post while automatic actuation feature for diesel low pressure fire suppression sys defeated for diesel maint. Caused by poor coordination between maint & operations shift supervisors W/851011 ltr.
RUPP, J.L., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 85/10/11. 4pp. 33095-105-33095-108.

8510240050 LER 85-010-00 on 850919. Discovered that inservice waste gas decay tank not being continuously sampled for oxygen content as required by Tech Specs. Caused by incorrect valve lineup on 850915 due to personnel error W/851018 ltr.
RUPP, J.L., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 85/10/18. 6pp. 33155-206-33155-211.

8510290527 LER 85-011-00 on 850922. Unidentified RCS leakage exceeded allowable Tech Spec limit. Caused by operator error & lack of procedure. Steam leaks repaired, new procedure developed & personnel counseled W/851022 ltr.
RUPP, J.L., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey. 85/10/22. 6pp. 33242-239-33242-244.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

8510230150 Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/emergencies.
KAMMERER, R.C. Office of Congressional Affairs. 85/03/26. MARKEY, J. House of Rep. Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109-065-33109-067.

V. Operator Examinations

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.

8510010428 Power plant exam results summary sheets info deleted.
* Public Service Electric & Gas Co. of New Jersey. * Pennsylvania Power & Light Co. * Commonwealth Edison Co. 85/09/20. 9pp. 32832-355-32833-001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510160151 Inform of review completion of inservice testing program documented in SSER 31. Further discussions required to clarify NRC evaluations of Items 3.4 & 13 in Section 5.2.8.1. Meeting requested for 851104-05 in Bethesda, MD.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/11. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33021-186-33021-192.

F. Security, medical, emergency & fire protection plans

8510010239 Forwards physical security plan change notification. Encl withheld (ref 10CFR73.21).
SHIFFER, J.D. Pacific Gas & Electric Co. 85/09/23. MARTIN, J.B. Region 5, Office of Director. 1p. 32802-239-32802-239.

8510070076 Inform of team insp scheduled for 851118-22 to ensure compliance w/Sections III G, J, L & O of App R to 10CFR50. Info will be requested during next several wks to support insp effort.
KIRSCH, D.F. Region 5, Office of Director. 85/09/30. SHIFFER, J.D. Pacific Gas & Electric Co. 2pp. 32881-015-32881-016.

8510180139 Forwards public version of revised emergency plan implementing procedures, including Rev 9 to EP R-6 re radiological fire & Rev 11 to EP M-6 re radiological fire.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/04. MARTIN, J.B. Region 5, Office of Director. 1p. 33075-217-33076-165.

-8510180143 Public version of revised emergency plan implementing procedures, including Rev 9 to EP R-6 re radiological fire & Rev 11 to EP M-6 re non-radiological fire. W/JM Felton 851015 transmittal memo.
* Pacific Gas & Electric Co. 85/10/04. 150pp. 33075-218-33076-165.

8510240497 Notification of 851106 & 07 meetings w/utl in Bethesda, MD to discuss status of licensee DCRDR.
SCHIERLING, H. Licensing Branch 3. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-160-33182-163.

8510300057 Ack receipt of 850830 ltr w/scenario manual for 1985 emergency preparedness exercise to be held on 851030. Minor changes to original 850726 submittal deemed adequate to meet exercise objectives.
FISH, R.F. Region 5, Office of Director. 85/10/23. SHIFFER, J.D. Pacific Gas & Electric Co. 1p. 33249-218-33249-218.

G. Adjudicatory correspondence

851110202 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
HASSELL, D.F. Hearing Branch 2. #485 737. 85/10/09. 3pp. 32574-030-32974-032.

J. Insurance & indemnity information

8510170275 Forwards Endorsement 46 to NELIA Policy NF-228 & Endorsement 17 to MALEU Policy MF-103.
CRANE, P.A. Pacific Gas & Electric Co. 85/10/10. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 33039-290-33039-292.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510020043 Forwards Rev 1 to updated FSAR & instruction sheets. Rev reflects status of Unit 1 through 850322. Lists changes not submitted to Commission.
SHIFFER, J.D., CRANE, P.A. Pacific Gas & Electric Co. 85/09/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32991-001-32991-001.

-8510020046 Rev 1 to updated FSAR for Diablo Canyon, Units 1 & 2. W/17 oversize figures.
* Pacific Gas & Electric Co. 85/09/30. 3,058pp. 32991-005-32991-182.

P. Operating license stage documents & correspondence

8504250409 Forwards draft "Preliminary Rept on Design Interface Review of Seismic Reverification Program."
CLOUD, R.L. Robert L. Cloud Associates, Inc. 81/10/21. ROCCA, J. Pacific Gas & Electric Co. 2pp. 30027-204-30027-274.

-8504250410 Draft "Preliminary Rept on Design Interface Review of Seismic Reverification Program."
* Robert L. Cloud Associates, Inc. 81/10/31. 69pp. 30027-206-30027-274.

8510180201 FOIA request for documents re Ofc of Inspector & Auditor charges that NRC responded improperly to allegations of possible QA & safety violations by whistleblowers at plant.
DEVINE, T. Government Accountability Project. 85/08/20. Office of Administration. 2pp. 33028-359-33028-360.

8510010064 Responds to FOIA request for correspondence NRC received from Barnes, Byron, Mathias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDR. Forwards documents listed on app.
FELTON, J.M. Division of Rules and Records. 85/09/04. DEZUBE, D. Montgomery County Sentinel. 3pp. 32831-087-32831-116.

-8510010172 Forwards Washington Post 840712 article entitled, "NRC Engineer Resigns From Diablo Task Force." Info requested on NRC role in safety investigations.
BARNES, M.D. House of Rep. 84/07/12. PALLADINO, N.J. Commissioners. 2pp. 32831-121-32831-122.

-8510010186 Ack receipt of ltr requesting info re status of licensing for facility. Forwards Chairman Palladino & H Denton statements. Results of ACRS review also encl. W/o encl.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. BARNES, M.D. House of Rep. 1p. 32831-123-32831-123.

8510180205 Responds to FOIA request for documents re Ofc of Inspector & Auditor inquiry into char's that NRC responded improperly to allegation by whistleblowers. Documents withheld (ref FOIA Exemptions 5 & 7(a)).
FELTON, J.M. Division of Rules and Records. 85/10/03. DEVINE, T. Government Accountability Project. 2pp. 33028-361-33028-362.

8510180506 Notification of 851021 meeting w/utl in Bethesda, MD to discuss long term seismic program on soil-structure interaction.
SCHIERLING, H. Licensing Branch 3. 85/10/08. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33077-193-33077-197.

8510180020 Advises that licensee will implement 10CFR50.62 requirements for reduction of risk from ATWS events by completion of second refueling outage, per Generic Ltr 85-06, "QA Guidance for Nonsafety-Related ATWS Equipment."
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33054-007-33054-008.

8510280362 Advises that investigations in response to Allegations 1722, 1723, 1724 & 1725 forwarded on 850905 still in progress. Responses will be submitted by 851101.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/14. MARTIN, J.B. Region 5, Office of Director. 1p. 33192-063-33192-063.

8510240506 Notification of 851104-05 meetings w/utl in Bethesda, MD to discuss in-service testing & insp.
SCHIERLING, H. Licensing Branch 3. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-149-33182-152.

8510300065 Informs that reactor coolant conductivity will be deleted as acceptance criteria from Rev 3 of STP G-14, "Operability Determination of Post-Accident Sampling Program," per review of SENTRY post-accident sampling sys.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 1p. 33250-348-33250-348.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262-231-33262-231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510290059 Forwards application for amends to Licenses DPR-80 & DPR-82, modifying loose parts detection sys instrumentation, RCS relief valves, RCS pressure/temp limits & administrative controls for startup repts. Fee paid.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33236-116-33236-134.

-8510290062 Application for amends to Licenses DPR-80 & DPR-82, modifying loose parts detection instrumentation, RCS relief valves, RCS pressure/temp limits & administrative controls for startup repts.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/24. 1p. 33236-117-33236-117.

-8510290069 Proposed Tech Specs, modifying loose parts detection sys, requirements for PORV, revising spec re pressure/temp limits & clarifying trial & subsequent startup repl requirements.
* Pacific Gas & Electric Co. 85/10/24. 17pp. 33236-118-33236-134.

8510290267 Forwards application for amends to Licenses DPR-80 & DPR-82, changing Tech Specs to reduce excessive testing of diesel generators & provide preventive maint times, per Generic Ltr 84-15. Fee paid.
MANEATIS, G.A. Pacific Gas & Electric Co. 85/10/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235-005-33235-024.

-8510290276 Application for amends to Licenses DPR-80 & DPR-82, changing Tech Specs to reduce excessive testing of diesel generators & provide maint times consistent w/manufacture recommendations & previous experience, per Generic Ltr 84-15.
MANEATIS, G.A. Pacific Gas & Electric Co. 85/10/25. 8pp. 33235-006-33235-013.

-8510290285 Proposed Tech Specs, reducing excessive testing of diesel generators & providing maint times for diesel generators consistent w/manufacture recommendations & previous maint & repair experience, per Generic Ltr 84-15.
* Pacific Gas & Electric Co. 85/10/25. 11pp. 33235-014-33235-024.

Q. Inspection reports, IE Bulletins & correspondence

8510030265 Forwards Insp Repts 50-275/85-30 & 50-323/85-28 on 850826-30. No violations noted.
WENSI, AWSKI, F.A. Region 5, Office of Director. 85/09/16. SHIFFER, J.D. Pacific Gas & Electric Co. 1p. 32845-317-32845-323.

-8510030268 Insp Repts 50-275/85-30 & 50-323/85-28 on 850826-30. No violation or deviation noted. Major areas inspected: ALARA, licensee organization & mgt, facility tour & followup on IE info notices.
CILLIS, M., HOOKER, C.A., YUHAS, G.P. Region 5, Office of Director. 85/09/13. 6pp. 32845-318-32845-323.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint, Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070076 Informs of team insp scheduled for 851118-22 to ensure compliance w/Sections III, G, J, L & O of App R to 10CFR50. Info will be requested during next several wks to support insp effort.
KIRSCH, D.F. Region 5, Office of Director. 85/09/30. SHIFFER, J.D. Pacific Gas & Electric Co. 2pp. 32881-015-32881-016.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230173 Forwards Press Release 84-58 re NRC proposed fine against utl for alleged violation of NRC requirements during preoperational testing.
KAMMERER, C. Office of Congressional Affairs. 84/05/17. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. WILSON Senate. 3pp. 33109-005-33109-007.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510240506 Notification of 851104-05 meetings w/utl in Bethesda, MD to discuss in-service testing & insp.
SCHIERLING, H. Licensing Branch 3. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-149-33182-152.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

58 DOCKETED ITEMS

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010612 Monthly operating repts for Jul 1985. W/850802 ltr.
KANICK, B., THORNBERRY, R.C. Pacific Gas & Electric Co. 85/07/31. 8pp. 32830-010-32830-017.

8510070324 Advises that 850829 semiannual radioactive effluent release rept did not include results of dose assessment. Understands that dose assessment results will be submitted within 30 days, per 850924 telcon.
WENSLAWSKI, F.A. Region 5, Office of Director. 85/09/30. SHIFFER, J.D. Pacific Gas & Electric Co. 1p. 32878-354-32878-354.

S. Reportable occurrences, LERs & related correspondence

8510150185 Special Rept SR 85-08 on 850828, diesel generator 1-1 failed to obtain required speed during performance of surveillance test. Caused by failure of diode in governor motor operator speed potentiometer. Diode replaced.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/09/23. MARTIN, J.B. Region 5, Office of Director. 2pp. 33006-358-33006-359.

8510010644 LER 85-030-00 on 850827, lo-to steam generator level reactor trip occurred. Caused by loose termination on main feedwater pump local manual trip button. Loose termination tightened. Local manual trip connections inspected. W/850926 ltr.
SISK, D.P., SHIFFER, J.D. Pacific Gas & Electric Co. 85/09/26. 2pp. 32820-178-32820-179.

8510210286 LER 85-032-00 on 850912, QA insp disclosed absence of nuts on embedded plate for main feedwater piping snubber support. Caused by const & engineering misunderstandings of design details. Nuts installed & plate stiffened. W/851014 ltr.
SISK, D.P., SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/14. 4pp. 33095-061-33095-064.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.

-8510230173 Forwards Press Release 84-58 re NRC proposed fine against util for alleged violation of NRC requirements during preoperational testing.
KAMMERER, C. Office of Congressional Affairs. 84/05/17. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109-005-33109-007.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510010386 Informs that 841114 rev to Chapter 9 of physical security plan re control of access to containment, consistent w/provisions of 10CFR50.54(p) & acceptable. Rev submitted on 841228 unacceptable.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/24. BAUER, E.G. Philadelphia Electric Co. 3pp. 32833-320-32833-322.

8510160318 Forwards public version of revs to emergency plan implementing procedures, including Rev 14 to EP-101 re classification of emergencies & Rev 11 to EP-102 re unusual event response. JM Felton release memo encl.
COONEY, M.J. Philadelphia Electric Co. 85/09/26. MURLEY, T.E. Region 1, Office of Director. 5pp. 33034-299-33035-299.

-8510160319 Public version of revs to emergency plan implementing procedures, including Rev 14 to EP-101 re classification of emergencies, Rev 11 to EP-102 re unusual event response & Rev 13 to EP-209 App D-5 re security team.
* Philadelphia Electric Co. 85/09/18. 375pp. 33034-299-33035-299.

8510090521 Forwards Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively & safety evaluation. Amends correct errors, establish consistency in reactor water level setpoint values & revise audit frequency of emergency plan & procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. BAUER, E.G. Philadelphia Electric Co. 2pp. 32965-129-32965-169.

-8510090528 Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively, correcting errors, establishing consistency in reactor water level setpoint values & revising audit frequency of emergency plan & implementing procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. 34pp. 32965-131-32965-164.

8510080072 Forwards Safety Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. No violations observed. Concerns re mgt & reporting of maint & repair activities for RHR Valve MO-2-10-154A discussed.
STAROSTECKI, R. Region 1, Office of Director. 85/10/03. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32918-312-32918-313.

-8510080080 Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. Major areas inspected: operational safety, radiation protection, physical security, control room activities, licensee events, surveillance testing & Unit 3 refueling/outage activities.
BEALL, J.E., GALLO, R.M. Region 1, Office of Director. 85/10/01. 28pp. 32918-314-32918-341.

8510180144 Forwards payment of fee requested in 850911 ltr re 850722 application concerning control room upgrade.
BRADLEY, E.J. Philadelphia Electric Co. 85/10/11. DIGGS, R.M. License Fee Management Branch. 1p. 33055-033-33055-033.

8510250132 Ack receipt of 850412 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-40 & 50-278/84-19.
EBNETER, S.D. Region 1, Office of Director. 85/10/15. DALTROFF, S.L. Philadelphia Electric Co. 1p. 33223-026-33223-030.

-8510250146 Responds to NRC 850308 ltr re violations noted in Insp Repts 50-277/84-40 & 50-278/84-19. Corrective actions: fire patrol established until maint on problem doors corrected.
DALTROFF, S.L. Philadelphia Electric Co. 85/04/12. EBNETER, S.D. Region 1, Office of Director. 4pp. 33223-027-33223-030.

8510210065 Revs to emergency plan implementing procedures, including Rev 7 to EP-207, "Personnel Safety Team Activation" & Rev 2 to EP-316A, "Reading Rapid Dose Assessment II Program into TI-50." W/851016 ltr.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/16. MURLEY, T.E. Region 1, Office of Director. 17pp. 33072-286-33072-302.

P. Operating license stage documents & correspondence

8510090521 Forwards Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively & safety evaluation. Amends correct errors, establish consistency in reactor water level setpoint values & revise audit frequency of emergency plan & procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. BAUER, E.G. Philadelphia Electric Co. 2pp. 32965-129-32965-169.

-8510090528 Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively, correcting errors, establishing consistency in reactor water level setpoint values & revising audit frequency of emergency plan & implementing procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. 34pp. 32965-131-32965-164.

-8510090533 Safety evaluation supporting Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/02. 5pp. 32965-165-32965-169.

8510150110 Forwards util & Westinghouse proprietary response to NRC 850905 request for addl info re 850613 request for approval of new spent fuel storage racks. Westinghouse response withheld (ref 10CFR2.790).
COONEY, M.J. Philadelphia Electric Co. 85/10/09. STOLZ, J.F. Operating Reactors Branch 4. 15pp. 33000-305-33000-319.

8510220251 Responds to NRC 850710 ltr re Generic Ltr 83-28, Item 1.2, "Post-Trip Review Data & Info Capability." Process computer upgrade will incorporate "good practices" recommendations.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/16. STOLZ, J.F. Operating Reactors Branch 4. 6pp. 33086-304-33086-309.

8510210146 Submits schedule for compliance w/10CFR50.62, "Requirements for Reduction of Risk From ATWS for Light Water Cooled Nuclear Plants." Design of recirculation pump trip described in detail in encl util 761008 & 780714 ltrs.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33071-274-33071-282.

-8510210147 Forwards addl info on use of recirculation pump trip to mitigate consequences of ATWS, in response to NRC 780515 request.
BRADLEY, E.J. Philadelphia Electric Co. 78/07/14. IPPOLITO, T. Operating Reactors Branch 3 (Pre 790625). 5pp. 33071-276-33071-280.

-8510210151 Forwards info re recirculation pump trip circuit design, in response to NRC 760901 request. Tech Specs for pump trip setpoints & surveillance requirements contained in Specs 3.2.5 & 4.2.5.
HANKINS, J.L. Philadelphia Electric Co. 76/10/08. STELLO, V. Division of Operating Reactors. 2pp. 33071-281-33071-282.

8510280306 Notification of Significant Licensee Meeting 85-106 on 851023 w/util in King of Prussia, PA to discuss maint activities.
GALLO, R.M. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 2pp. 33196-360-33196-361.

8510310397 Concurs w/850703 assessment that rev to Tech Specs for max closing time not required since Table 3.7.1 requires 5 s stroke time limitation. Surveillance Tech Specs for purge/vent valves unnecessary.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/24. BAUER, E.G. Philadelphia Electric Co. 2pp. 33278-200-33278-201.

Q. Inspection reports, IE Bulletins & correspondence

8510250401 Responds to NRC 850519 ltr re unresolved items noted in Insp Rept 50-277/85-04. Radiograph comparisons & tensile test show that diffraction patterns on radiographs do not indicate weld integrity problem.
MOSKOWITZ, J. Philadelphia Electric Co. 85/06/12. EBNETER, S.D. Region 1, Office of Director. 3pp. 33172-231-33172-233.

8510200444 Forwards Safety Insp Repts 50-277/85-34 & 50-278/85-14 on 850617-19 & 0812-16. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/09/17. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32827-333-32827-344.

-8510020050 Insp Repts 50-277/85-34 & 50-278/85-14 on 850617-19 & 0812-16. No violation noted. Major areas inspected: program for detection of IGSCC progression per Generic Ltr 84-11 & mods & insp of nitrogen inerting sys.
GRAY, E.H., KORTAS, A.J., MCBREARTY, R.A. Region 1, Office of Director. 85/09/06. 10pp. 32827-335-32827-344.

8510010324 Forwards Rev 0 to NCIQ-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.F. Division of Engineering. 4pp. 32803-095-32803-125.

-8510010378 Rev 0 to NCIQ-02. "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8510080274 Responds to NRC 840215 ltr re violations noted in Insp Repts 50-277/84-02 & 50-278/84-02. Corrective actions 232 of 425 mod packages closed out. Outstanding mod packages will be closed out by 860630 due to heavy workload.
DALTROFF, S.L. Philadelphia Electric Co. 85/09/27. EBNETER, S.D. Region 1, Office of Director. 2pp. 32913-323-32913-324.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080416 Forwards Safety Insp Repts 50-277/85-33 & 50-278/85-30 on 850812-16. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/01. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32921-308-32921-326.

-8510080421 Safety Insp Repts 50-277/85-33 & 50-278/85-30 on 850812-16. No non-compliance or deviation noted. Major areas inspected: administrative controls, preventive & corrective maint programs & implementation of electrical maint.
CHUNG, J.W., BISSETT, P., PHELAN, P. Region 1, Office of Director. 85/09/16. 17pp. 32921-310-32921-326.

8510080072 Forwards Safety Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. No violations observed. Concerns re mgt & reporting of maint & repair activities for RHR V-1e MO-2-10-154A discussed.
STAROSTI, K.L.R. Region 1, Office of Director. 85/10/03. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32918-312-32918-313.

-8510080080 Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. Major areas inspected: operational safety, radiation protection, physical security, control room activities, licensee events, surveillance testing & Unit 3 refueling/outage activities.
BEALL, J.E., GALLO, R.M. Region 1, Office of Director. 85/10/01. 18pp. 32918-314-32918-341.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces.
KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. SCHULZE, BORSKI House of Rep. 3pp. 33109-047-33109-049.

-8510230191 Forwards Press Release 84-75 re NRC proposed fine against util for five alleged violations of Tech Specs.
KAMMERER, C. Office of Congressional Affairs. 84/06/19. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109-010-33109-012.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rpt.
LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510250132 Ack receipt of 850412 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-40 & 50-278/84-19.
EBNETER, S.D. Region 1, Office of Director. 85/10/15. DALTROFF, S.L. Philadelphia Electric Co. 1p. 33223-026-33223-030.

-8510250146 Responds to NRC 850308 ltr re violations noted in Insp Repts 50-277/84-40 & 50-278/84-19. Corrective actions: fire patrol established until maint on problem doors corrected.
DALTROFF, S.L. Philadelphia Electric Co. 85/04/12. EBNETER, S.D. Region 1, Office of Director. 4pp. 33223-027-33223-030.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280336 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-02 & 50-278/84-02. Revised date for completion of mod closeout project acceptable.
EBNETER, S.D. Region 1, Office of Director. 85/10/23. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 33193-001-33193-004.

R. Periodic operating reports & related correspondence

8510210299 Monthly operating repts for Sept 1985 W/851015 ltr.
ALDEN, W.M., LOGUE, R.H. Philadelphia Electric Co. 85/09/30. 12pp. 33095-001-33095-012.

S. Reportable occurrences, LERs & related correspondence

8510010286 PNO-I-85-068 on 850923, chemistry technician determined to be missing & possibly drowned after being sent to obtain environ water grab sample from discharge canal. Search by util & state police unsuccessful.
JOHNSON, T., GALLO, R. Region 1, Office of Director. 85/09/24. 1p. 32802-352-32802-352.

8510010642 LER 85-008-01 on 850725, determined that fire barrier penetrations containing ceramic fiber-polyurethane foam unacceptable. Caused by incorrect results from tests performed on 831103. Barriers upgraded W/850919 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/09/19. 4pp. 32820-341-32820-344.

8510010618 Forwards LERs 85-015-00 & 85-016-00.
ULLRICH, W.T. Philadelphia Electric Co. 85/09/20. Record Services Branch (Document Control Desk). 1p. 32830-031-32830-037.

-8510010629 LER 85-015-00 on 850822, full scram & primary containment isolation sys Groups II & III initiated due to reactor low level signal. Caused by pressure transmitter PT-53 block valve leak. Block valve replaced.
BIRELY, W.C. Philadelphia Electric Co. 85/09/20. 3pp. 32830-032-32830-034.

-8510010633 LER 85-016-00 on 850826, full scram & primary containment isolation sys Groups II & III initiated due to reactor low level signal. Caused by failure to ensure that pressure transmitter returned to svc from 850822 event.
BIRELY, W.C. Philadelphia Electric Co. 85/09/20. 3pp. 32830-035-32830-037.

8510010215 LER 85-014-00 on 850820, scram signal & Groups II & III isolation occurred due to low reactor water level. Caused by slow response of controller LIC-8091 & employee error. Controller tuned & tested W/850924 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/09/24. 4pp. 32809-207-32809-210.

8510040087 LER 85-017-00 on 850825, suppression pool vol in torus dropped below Tech Spec limit. Caused by use of torus water filter pump to reduce torus water vol. Condensate storage tank water used to restore torus vol W/850924 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/09/24. 4pp. 32867-181-32867-184.

8510150250 LER 85-013-00 on 850812 & 19, Loop A RHR sys outboard injection valve declared inoperable. Caused by mechanical interference & binding in valve yoke assembly. Assembly rebuilt following each event W/851007 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/07. 12pp. 33015-108-33015-119.

8510170416 LER 85-018-00 on 850912, reactor water cleanup sys inboard & outboard suction valves closed due to high flow isolation signal. Caused by too rapid opening of demineralizer outlet valve. Operator instructed on proper procedures W/851011 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/11. 4pp. 33053-354-33053-357.

8510210102 PNO-I-85-080 on 851017, plant tripped on low level due to loss of all three turbine-driven main feed pumps. Cause unstated. Reactor vessel level recovered by HPCI & RCIC injection.
GALLO, R.M., JOHNSON, T. Region 1, Office of Director. 85/10/17. 1p. 33072-280-33072-280.

8510300242 LER 85-019-00 on 850919, RHR pump declared inoperable due to reduced performance of pump in low head region. Cause undetermined. Pump reassembled & tested W/851018 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/18. 5pp. 33257-263-33257-267.

8510300253 LER 85-020-00 on 850924, low level scram occurred due to operator error. Level automatically restored to normal by reactor feedwater level control sys. Operator counseled. W/851021 ltr.
BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/21. 4pp. 33258-121-33258-124.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces.
KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-047-33109-049.

-8510230191 Forwards Press Release 84-75 re NRC proposed fine against util for five alleged violations of Tech Specs.
KAMMERER, C. Office of Congressional Affairs. 84/06/19. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-010-33109-012.

60 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8510010386 Informs that 841114 rev to Chapter 9 of physical security plan re control of access to containment, consistent w/provisions of 10CFR50.54(p) & acceptable. Rev submitted on 841228 unacceptable.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/24. BAUER, E.G. Philadelphia Electric Co. 3pp. 32833-320-32833-322.

8510160318 Forwards public version of revs to emergency plan implementing procedures, including Rev 14 to EP-101 re classification of emergencies & Rev 11 to EP-102 re unusual event response. JM Felton release memo encl.
COONEY, M.J. Philadelphia Electric Co. 85/09/26. MURLEY, T.E. Region 1, Office of Director. 5pp. 33034-293-33035-299.

8510160319 Public version of revs to emergency plan implementing procedures, including Rev 14 to EP-101 re classification of emergencies, Rev 11 to EP-102 re unusual event response & Rev 13 to EP-209 App D-5 re security team.
* Philadelphia Electric Co. 85/09/18. 375pp. 33034-299-33035-299.

8510090521 Forwards Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively & safety evaluation. Amends correct errors, establish consistency in reactor water level setpoint values & revise audit frequency of emergency plan & procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. BAUER, E.G. Philadelphia Electric Co. 2pp. 32965-129-32965-169.

8510090528 Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively, correcting errors, establishing consistency in reactor water level setpoint values & revising audit frequency of emergency plan & implementing procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. 34pp. 32965-131-32965-164.

8510080072 Forwards Safety Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. No violations observed. Concerns re mgt & reporting of maint & repair activities for RHR Valve MO-2-10-154A discussed.
STAROSTECKI, R. Region 1, Office of Director. 85/10/03. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32918-312-32918-313.

8510080080 Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. Major areas inspected: operational safety, radiation protection, physical security, control room activities, licensee events, surveillance testing & Unit 3 refueling/outage activities.
BEALL, J.E. Region 1, Office of Director. 85/10/01. 28pp. 32918-314-32918-341.

8510180144 Forwards payment of fee requested in 850911 ltr re 850722 application concerning control room upgrade.
BRADLEY, E.J. Philadelphia Electric Co. 85/10/11. DIGGS, R.M. License Fee Management Branch. 1p. 33055-033-33055-033.

8510250132 Ack receipt of 850412 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-40 & 50-278/84-19.
EBNETER, S.D. Region 1, Office of Director. 85/10/15. DALTROFF, S.L. Philadelphia Electric Co. 1p. 33223-026-33223-030.

8510250146 Responds to NRC 850308 ltr re violations noted in Insp Repts 50-277/84-40 & 50-278/84-19. Corrective actions: fire patrol established until maint on problem doors corrected.
DALTROFF, S.L. Philadelphia Electric Co. 85/04/12. EBNETER, S.D. Region 1, Office of Director. 4pp. 33223-027-33223-030.

8510210065 Revs to emergency plan implementing procedures, including Rev 7 to EP-207, "Personnel Safety Team Activation" & Rev 2 to EP-316A, "Reading Rapid Dose Assessment II Program into TI-59." W/851016 ltr.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/16. MURLEY, T.E. Region 1, Office of Director. 17pp. 33072-286-33072-302.

P. Operating license stage documents & correspondence

8510090521 Forwards Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively & safety evaluation. Amends correct errors, establish consistency in reactor water level setpoint values & revise audit frequency of emergency plan & procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. BAUER, E.G. Philadelphia Electric Co. 2pp. 32965-129-32965-169.

8510090528 Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively, correcting errors, establishing consistency in reactor water level setpoint values & revising audit frequency of emergency plan & implementing procedures.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/02. 34pp. 32965-131-32965-164.

8510090533 Safety evaluation supporting Amends 111 & 115 to Licenses DPR-44 & DPR-56, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/02. 5pp. 32965-165-32965-169.

8510150110 Forwards util & Westinghouse proprietary response to NRC 850905 request for add info re 850613 request for approval of new spent fuel storage racks. Westinghouse response withheld (ref 10CFR2.790).
COONEY, M.J. Philadelphia Electric Co. 85/10/09. STOLZ, J.F. Operating Reactors Branch 4. 15pp. 33000-305-33000-319.

8510170417 Summary of 851001 meeting w/util & GE in Bethesda, MD re cracking identified in 316 L grade stainless steel recirculation outlet safe ends. Proprietary viewgraphs encl. Viewgraphs withheld (ref 10CFR2.790).
HERMANN, R.A. Operating Reactors Branch 2. 85/10/09. Operating Reactors Branch 2. 2pp. 33045-132-33045-133.

8510220251 Responds to NRC 850710 ltr re Generic Ltr 83-26, Item 1.2, "Post-Trip Review Data & Info Capability." Process computer upgrade will incorporate "good practices" recommendations.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/16. STOLZ, J.F. Operating Reactors Branch 4. 6pp. 33086-304-33086-309.

8510210146 Submits schedule for compliance w/10CFR50.62, "Requirements for Reduction of Risk From ATWS for Light Water Cooled Nuclear Plants." Design of recirculation pump trip described in detail in encl util 761008 & 780714 ltrs.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33071-274-33071-282.

8510210147 Forwards add info on use of recirculation pump trip to mitigate consequences of ATWS, in response to NRC 780515 request.
BRADLEY, E.J. Philadelphia Electric Co. 78/07/14. IPPOLITO, T. Operating Reactors Branch 3 (Pre 790625). 5pp. 33071-276-33071-280.

8510210151 Forwards info re recirculation pump trip circuit design, in response to NRC 760901 request. Tech Specs for pump trip setpoints & surveillance requirements contained in Specs 3.2.5 & 4.2.5.
HANKINS, J.L. Philadelphia Electric Co. 76/10/08. STELO, V. Division of Operating Reactors. 2pp. 33071-281-33071-282.

8510280306 Notification of Significant Licensee Meeting 85-106 on 851023 w/util in King of Prussia, PA to discuss maint activities.
GALLO, R.M. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 2pp. 33196-360-33196-361.

8510310397 Concurs w/850703 assessment that rev to Tech Specs for max closing time not required since Table 3.7.1 requires 5 s stroke time limitation. Surveillance Tech Specs for purge/vent valves unnecessary.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/24. BAUER, E.G. Philadelphia Electric Co. 2pp. 33278-200-33278-201.

8510300266 Notification of 851031 meeting w/util & GE to discuss N-1 safe ends. Meeting location not yet selected.
GEARS, G. Operating Reactors Branch 4. 85/10/25. DENTON, H., EISENHUT, D., LYONS, J. NRC - No Detailed Affiliation Given. 2pp. 33259-344-33259-346.

Q. Inspection reports, IE Bulletins & correspondence

8510020044 Forwards Safety Insp Repts 50-277/85-34 & 50-278/85-14 on 850617-19 & 0812-16. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/09/17. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32827-333-32827-344.

8510020050 Insp Repts 50-277/85-34 & 50-278/85-14 on 850617-19 & 0812-16. No violation noted. Major areas inspected: program for detection of IGSCC progression per Generic Ltr 84-11 & mods & insp of nitrogen inerting sys.
GRAY, E.H., KORTAS, A.J., MCBREARY, R.A. Region 1, Office of Director. 85/09/06. 10pp. 32827-335-32827-344.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform, technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8510080274 Responds to NRC 840215 ltr re violations noted in Insp Repts 50-277/84-02 & 50-278/84-02. Corrective actions: 232 of 425 mod packages closed out. Outstanding mod packages will be closed out by 860630 due to heavy workload.
DALTROFF, S.L. Philadelphia Electric Co. 85/09/27. EBNETER, S.D. Region 1, Office of Director. 2pp. 32913-323-32913-324.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080416 Forwards Safety Insp Repts 50-277/85-33 & 50-278/85-30 on 850812-16. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/01. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32921-308-32921-326.

8510080421 Safety Insp Repts 50-277/85-33 & 50-278/85-30 on 850812-16. No non-compliance or deviation noted. Major areas inspected: administrative controls, preventive & corrective maint programs & implementation of electrical maint.
CHUNG, J.W., BISSETT, P., PHELAN, P. Region 1, Office of Director. 85/09/16. 17pp. 32921-310-32921-326.

8510080072 Forwards Safety Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. No violations observed. Concerns re mgt & reporting of maint & repair activities for RHR Valve MO-2-10-154A discussed.
STAROSTECKI, R. Region 1, Office of Director. 85/10/03. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 32918-312-32918-313.

8510080080 Insp Repts 50-277/85-30 & 50-278/85-27 on 850727-0906. Major areas inspected: operational safety, radiation protection, physical security, control room activities, licensee events, surveillance testing & Unit 3 refueling/outage activities.
BEALL, J.E., GALLO, R.M. Region 1, Office of Director. 85/10/01. 28pp. 32918-314-32918-341.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces. KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. SCHULZE, BORSKI House of Rep. 3pp. 33109:047-33109:049.

-8510230191 Forwards Press Release 84-75 re NRC proposed fine against util for five alleged violations of Tech Specs. KAMMERER, C. Office of Congressional Affairs. 84/06/19. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109:010-33109:012.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510230028 Provides plans for returning unit to power w/recirculation inlet safe-end crack indications & forwards proprietary NEDC-31086-P, "Evaluation of Crevice Cracking in Peach Bottom. Recirculation Inlet Safe-Ends." Rept withheld. DALTROFF, S.L. Philadelphia Electric Co. 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 7pp. 33103:295-33103:301.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510250132 Ack receipt of 850412 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-40 & 50-278/84-19. EBNETER, S.D. Region 1, Office of Director. 85/10/15. DALTROFF, S.L. Philadelphia Electric Co. 1p. 33223:026-33223:030.

-8510250146 Responds to NRC 850308 ltr re violations noted in Insp Repts 50-277/84-40 & 50-278/84-19. Corrective actions fire patrol established until maint on problem doors corrected. DALTROFF, S.L. Philadelphia Electric Co. 85/04/12. EBNETER, S.D. Region 1, Office of Director. 4pp. 33223:027-33223:030.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510290418 Informs that util 840604 & 1005 submittals re pipe insp program in response to Generic Ltr 84-11 acceptable w/ exception of proposed sample expansion logic when cracks found, per IE Bulletin 83-02. STOLZ, J.F. Operating Reactors Branch 4. 85/10/22. BAUER, E.G. Philadelphia Electric Co. 3pp. 33254:271-33254:273.

8510280336 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-277/84-02 & 50-278/84-02. Revised date for completion of mod closeout project acceptable. EBNETER, S.D. Region 1, Office of Director. 85/10/23. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 33193:001-33193:004.

R. Periodic operating reports & related correspondence

8510210299 Monthly operating repts for Sept 1985. W/851015 ltr. ALDEN, W.M., LOGUE, R.H. Philadelphia Electric Co. 85/09/30. 12pp. 33095:001-33095:012.

S. Reportable occurrences, LERs & related correspondence

8510010286 PNO-1-85-068 on 850923, chemistry technician determined to be missing & possibly drowned after being sent to obtain environ water grab sample from discharge canal. Search by util & state police unsuccessful. JOHNSON, T., GALLO, R. Region 1, Office of Director. 85/09/24. 1p. 32802:352-32802:352.

8510040076 LER 85-014-00 on 850826, during in-vessel inservice insp program, crack indication on 240 degree azimuth core spray supply junction box discovered. Caused by intergranular stress corrosion Brackets installed W/850925 ltr. BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/09/25. 4pp. 32867:232-32867:235.

8510070542 LER 85-011-02 on 850620, discovered that required fire watch not established for fire barriers between MSIV & torus room. Caused by administrative oversight. Hourly fire watch established & penetrations sealed W/851001 ltr. BIRELY, W.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/01. 5pp. 32883:252-32883:256.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965:021-32965:047.

8510090437 Summary of 850905 & 17 meetings w/util in Bethesda, MD re recent detection of IGSCC on recirculation & RHR sys piping & cracks on core spray line, respectively. List of participants & presentation encl. GEARS, G.E. Operating Reactors Branch 4. 85/10/03. Operating Reactors Branch 4. 104pp. 32964:144-32964:248.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces. KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:047-33109:049.

-8510230191 Forwards Press Release 84-75 re NRC proposed fine against util for five alleged violations of Tech Specs. KAMMERER, C. Office of Congressional Affairs. 84/06/19. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:010-33109:012.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510070360 Rev 3 to "Corporate Emergency Response Plan." for Third Quarter 1985. W/850927 ltr. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/08/29. GRACE, J.N. Region 2, Office of Director. 90pp. 32875:036-32875:125.

8510040137 Forwards Revs 8 & 9 to security personnel training & qualification programs for North Anna & Surry, respectively & response to NRC 850724 comments. Encls withheld (ref 10CFR73.21). STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32851:208-32851:209.

8510040348 Forwards Rev 13 to security program. Rev withheld (ref 10CFR73.21). STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 1p. 32853:274-32853:274.

8510100086 Rev 1 to Emergency Plan Implementing Procedure EPIP-4.07, "Protective Measures." Revised index also encl W/851007 ltr. GRODY, W.D., MILLER, H.L. Virginia Power (Virginia Electric & Power Co.). 85/10/07. GRACE, J.N. Region 2, Office of Director. 16pp. 32961:096-32961:111.

8510290086 Revised emergency plan implementing procedures, including Rev 15 to EPIP-3.01, "Callout of Emergency Response Personnel" & Rev 1 to EPIP-4.14, "In-Plant Monitoring." W/851021 ltr. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. GRACE, J.N. Region 2, Office of Director. 19pp. 33236:017-33236:035.

J. Insurance & indemnity information

8510080180 Forwards Endorsements 79 & 80 to NELIA Policy NF-186 & MAELU Policy MF-57, respectively. INGLES, J.M. Marsh & McLennan, Inc. 85/09/25. DINITZ, I. Office of Nuclear Reactor Regulation, Director. 3pp. 32922:076-32922:078.

P. Operating license stage documents & correspondence

8510180540 Forwards request for addl info re 850830 updated QA Topical Rept VEP 1-4A necessary for completion of evaluation of program changes. WALKER, R.D. Region 2, Office of Director. 85/10/01. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 33068:253-33068:256.

8510080360 Forwards addl info for Items 3.1.1, 3.1.2, 3.2.1 & 3.2.2 of Generic Ltr 83-28, per 850708 request. Administrative Procedure A-13 re functional testing of safety-related equipment prior to restoration revised. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 4pp. 32922:118-32922:121.

8510100113 Forwards corrected Tech Spec Page 4.1-8 re limiting conditions for operation & surveillance requirements for reactor trip bypass breakers & undervoltage & shunt trip logic contained in 850412 & 0909 ltrs. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32960:344-32960:346.

-8510100122 Corrected Tech Spec Page 4.1-8 re limiting conditions for operation & surveillance requirements for reactor trip bypass breakers & undervoltage & shunt trip logic. * Virginia Power (Virginia Electric & Power Co.). 85/10/07. 1p. 32960:346-32960:346.

62 DOCKETED ITEMS

8510170074 Forwards VEP-NE-2, "Statistical DNBR Evaluation Methodology." Rept describes methodology for statistically treating several important uncertainties in DNBR analysis & replaces deterministic methodology. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/08.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 2pp. 33036:252-33036:320.

-8510170079 "Statistical DNBR Evaluation Methodology."
ANDERSON, R.C. BASEHORE, K.L. BERRYMAN, R.M. Virginia Power (Virginia Electric & Power Co.). VEP-NE-2. 85/07/31. 67pp. 33036:254-33036:320.

8510180151 Advises that proposed schedule for meeting requirements for ATWS mitigation sys. per 10CFR50.62(d) & Generic Ltr 85-06, will be completed by end of First Quarter 1986. ATWS mitigation sys. of vendors under evaluation.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/11.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 3pp. 33055:035-33055:037.

8510310022 Forwards request for addl info. within 30 days, re proposed Tech Spec changes for snubber surveillance requirements provided in 850809 ltr. Final determination of ASME O&M-4 std will not occur prior to review of published document.
VARGA, S.A. Operating Reactors Branch 1. 85/10/11. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 5pp. 33277:132-33277:136.

8510290047 Notices that revised schedule for submittal of info requested in Generic Ltr 85-12 re Section IV of safety evaluation for Westinghouse Owners Group reactor coolant pump trip will be submitted by 851206.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 2pp. 33236:157-33236:158.

8510290109 Requests permission to use damping values given in ASME Code Case N-411 as recommended in NUREG-1061. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33235:294-33235:295.

8510310353 Application for amend to Licenses DPR-32 & DPR-37, revising Tech Specs re increase in max K-effective allowable during refueling conditions from 0.90 to 0.95. Safety evaluation encl. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/28.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33271:336-33271:350.

-8510310357 Proposed Tech Specs increasing max K-effective allowable during refueling conditions from value of 0.90 to 0.95. Safety evaluation encl.
* Virginia Power (Virginia Electric & Power Co.). 85/10/28. 12pp. 33271:339-33271:350.

Q. Inspection reports, IE Bulletins & correspondence

8509180313 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 11pp. 32854:338-32854:348.

8510070069 Ack receipt of 850724 & 0912 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-280/85-19 & 50-281/85-19.
WALKER, R.D. Region 2, Office of Director. 85/09/24. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 32900:056-32900:056.

8510010090 Confirms QA program insp at corporate ofcs during wk of 850930 & at plant during wk of 851021 per 850921 telcon.
ZECH, G.G. Vendor Program Branch. 85/09/26. HARDWICKER, Virginia Power (Virginia Electric & Power Co.). 2pp. 32802:177-32802:178.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230234 Forwards Press Release 84-94 re NRC proposed imposition of civil penalty in amount of \$40,000 against util for allegedly assuming that all hydraulic snubbers rebuilt during steam generator replacement projects.
KAMMERER, C. Office of Congressional Affairs. 84/07/31. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. WARNER Senate. 2pp. 33109:100-33109:101.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. WARNER, TRIBBLE Senate. 2pp. 33109:155-33109:157.

8510160284 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 "Loss of Fuel Element Transfer Tubes." Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010643 Monthly operating repts for Jul 1985. W/850815 ltr.
JONES, V., STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/07/31.
BEEBE, M.R. Office of Resource Management, Director. 43pp. 328:0245-32820:288.

S. Reportable occurrences, LERs & related correspondence

8510040367 NPDES noncompliance notification on 850907, chlorine residual at Outfall 011 at sewage treatment plant exceeded effluent limitations. Subsequent test results within limitations. No corrective action planned.
MARSHALL, B.M. Virginia Power (Virginia Electric & Power Co.). 85/09/25.
JENKINS, R.R. Virginia, Commonwealth of. 1p. 32866:345-32866:345.

8510030014 PNO-II 85-092 on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown. Unit 2 shut down & Surry 1 & 2 at full power.
CUNNINGHAM, A. Region 2, Office of Director. 85/09/26. 2pp. 32844:335-32844:336.

8510150173 NPDES noncompliance notification, flow for Outfall 011 sewage treatment plant estimated for Sept rather than reflecting recorded results. On 850928, sample taken from Outfall 002 oil tank diked area discharge exceeded limits.
MARSHALL, B.M. Virginia Power (Virginia Electric & Power Co.). 85/10/04.
JENKINS, R.R. Virginia, Commonwealth of. 2pp. 33015:061-33015:062.

8510280032 LER 85-017-00 on 850911, following reactor trip, I-131 level exceeded Tech Spec limit. Caused by fuel element defects in reactor core. Dose equivalent monitored until less than 1.0 uCi/cc. W/851014 ltr.
SAUNDERS, R.F. Virginia Power (Virginia Electric & Power Co.). 85/10/14. 5pp. 33194:351-33194:355.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230234 Forwards Press Release 84-94 re NRC proposed imposition of civil penalty in amount of \$40,000 against util for allegedly assuming that all hydraulic snubbers rebuilt during steam generator replacement projects.
KAMMERER, C. Office of Congressional Affairs. 84/07/31. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:100-33109:101.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:155-33109:157.

V. Operator Examinations

8510150041 Submits addl info re training of personnel performing fuel handling & cask handling for dry cask ISFSI. Cask handling & fuel loading operations performed by licensed operators or under direct supervision of senior licensed personnel.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/09.
CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 3pp. 33031:298-33031:300.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

Y. Dry Cask Independent Spent Fuel Storage Installations

8510150041 Submits addl info re training of personnel performing fuel handling & cask handling for dry cask ISFSI. Cask handling & fuel loading operations performed by licensed operators or under direct supervision of senior licensed personnel.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/09.
CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 3pp. 33031:298-33031:300.

8510180033 Forwards topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys. Inc." Rept acceptable for referencing in licensing applications subj to encl limitations.
ROUSEL, C. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30.
BARNHART, V.J. General Nuclear Systems, Inc. 6pp. 33074:176-33074:270.

-8510180038 Topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys. Inc."
* Office of Nuclear Material Safety & Safeguards, Director. 85/09/30. 89pp. 33074:182-33074:270.

8510180539 Requests analysis & evaluation of cause of cracking found in fuel basket of CASTOR V/21 cask used in dry spent fuel storage cooperative demonstration program. Revs necessary to topical SAR also requested.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/14.
BARNHART, V.J. General Nuclear Systems, Inc. 1p. 33077-280-33077-280.

8510220028 Requests reassessment of use of CASTOR V/21 cask at ISFSI & rept of findings along w/ necessary license application changes per recent discovery of cracks in cask fuel basket.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/15.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33098-281-33098-282.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070360 Rev 3 to "Corporate Emergency Response Plan," for Third Quarter 1985. W/850927 ltr.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/08/29. GRACE, J.N. Region 2, Office of Director. 90pp. 32875-036-32875-125.

8510040137 Forwards Revs 8 & 9 to security personnel training & qualification programs for North Anna & Surry, respectively & response to NRC 850724 comments. Encls withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32851-208-32851-209.

8510040348 Forwards Rev 13 to security program. Rev withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 1p. 32853-274-32853-274.

8510100086 Rev 1 to Emergency Plan Implementing Procedure EPIP-4.07, "Protective Measures." Revised index also encl. W/851007 ltr.
GRODY, W.D., MILLER, H.L. Virginia Power (Virginia Electric & Power Co.). 85/10/07. GRACE, J.N. Region 2, Office of Director. 16pp. 32961-096-32961-111.

8510290066 Revised emergency plan implementing procedures, including Rev 15 to EPIP-3.01, "Callout of Emergency Response Personnel" & Rev 1 to EPIP-4.14, "In-Plant Monitoring." W/851021 ltr.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. GRACE, J.N. Region 2, Office of Director. 19pp. 33236-017-33236-035.

J. Insurance & indemnity information

8510080180 Forwards Endorsements 79 & 80 to NELIA Policy NF-186 & MAELU Policy MF-57, respectively.
INGLES, J.M. Marsh & McLennan, Inc. 85/09/25. DINITZ, I. Office of Nuclear Reactor Regulation, Director. 3pp. 32922-076-32922-078.

P. Operating Branches & documents & correspondence

8510040374 Forwards W/850925, "Steam Generator Girth Weld 6 Repair Rept."
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/27.
THOMPSON, H.L. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32853-014-32853-104.

8510040379 "Steam Generator Girth Weld 6 Repair Rept."
* Westinghouse Electric Corp. WCAP-10925. 85/08/31. 90pp. 32853-016-32853-104.

8510180540 Forwards request for addl info re 850830 updated QA Topical Rept VEP 1-A necessary for completion of evaluation of program changes.
WALKER, R.D. Region 2, Office of Director. 85/10/01. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 33068-253-33068-256.

8510080360 Forwards addl info for Items 3.1.1.3.1, 3.2.2.1 & 3.2.2 of Generic Ltr 83-28, per 850708 request. Administrative Procedure A-13 re functional testing of safety-related equipment prior to restoration revised.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/02.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 4pp. 32922-118-32922-121.

8510100113 Forwards corrected Tech Spec Page 4.1-8 re limiting conditions for operation & surveillance requirements for reactor trip bypass breakers & undervoltage & shunt trip logic contained in 850412 & 0909 ltrs.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/07.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32960-344-32960-346.

8510100122 Corrected Tech Spec Page 4.1-8 re limiting conditions for operation & surveillance requirements for reactor trip bypass breakers & undervoltage & shunt trip logic.
* Virginia Power (Virginia Electric & Power Co.). 85/10/07. 1p. 32960-346-32960-346.

8510170074 Forwards VEP-NE-2, "Statistical DNBR Evaluation Methodology." Rept describes methodology for statistically treating several important uncertainties in DNBR analysis & replaces deterministic methodology. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/08.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 2pp. 33036-252-33036-320.

8510170079 "Statistical DNBR Evaluation Methodology."
ANDERSON, R.C., BASEHORE, K.L., BERRYMAN, R.M. Virginia Power (Virginia Electric & Power Co.). VEP-NE-2. 85/07/31. 67pp. 33036-254-33036-320.

8510180151 Advises that proposed schedule for meeting requirements for ATWS mitigation sys. per 10CFR50.62(d) & Generic Ltr 85-06, will be completed by end of First Quarter 1986. ATWS mitigation sys of vendors under evaluation.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/11.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 3pp. 33055-035-33055-037.

8510310022 Forwards request for addl info, within 30 days, re proposed Tech Spec changes for snubber surveillance requirements provided in 850809 ltr. Final determination of ASME O&M-4 std will not occur prior to review of published document.
VARGA, S.A. Operating Reactors Branch 1. 85/10/11. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 5pp. 33277-132-33277-136.

8510290047 Notifies that revised schedule for submittal of info requested in Generic Ltr 85-12 re Section IV of safety evaluation for Westinghouse Owners Group reactor coolant pump trip will be submitted by 851206.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 2pp. 33236-157-33236-158.

8510290109 Requests permission to use damping values given in ASME Code Case N-411 as recommended in NUREG-1061. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33235-294-33235-295.

8510310353 Application for amend to Licenses DPR-32 & DPR-37, revising Tech Specs re increase in max K-effective allowable during refueling conditions from 0.90 to 0.95. Safety evaluation encl. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/28.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 3pp. 33271-336-33271-350.

8510310357 Proposed Tech Specs, increasing max K-effective allowable during refueling conditions from value of 0.90 to 0.95. Safety evaluation encl.
* Virginia Power (Virginia Electric & Power Co.). 85/10/28. 12pp. 33271-339-33271-350.

Q. Inspection reports, IE Bulletins & correspondence

8509180313 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 11pp. 32854-338-32854-348.

8510070069 Ack receipt of 850724 & 0912 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-280/85-19 & 50-281/85-19.
WALKER, R.D. Region 2, Office of Director. 85/09/24. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 32900-056-32900-056.

8510010090 Confirms QA program inop at corporate otrs during wk of 850930 & at plant during wk of 851021, per 850921 telcon.
ZECH, G.G. Vendor Program Branch. 85/09/26. HARDWICKE, R. Virginia Power (Virginia Electric & Power Co.). 2pp. 32802-177-32802-178.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

8510230234 Forwards Press Release 84-94 re NRC proposed imposition of civil penalty in amount of \$40,000 against utility for allegedly assuming that all hydraulic snubbers rebuilt during steam generator replacement projects.
KAMMERER, C. Office of Congressional Affairs. 84/07/31. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. WARNER Senate. 2pp. 33109-106-33109-101.

8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against utility for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. WARNER, TRIBBLE Senate. 2pp. 33109-155-33109-157.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Implementation needed for IE Bulletin 78-08 closeout rept.
LOF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510180183 Requests assistance in conducting review of encl 850919 request for relief from certain ASME Code Section XI inservice insp requirements. SER & SALP input expected by 851130.
THOMPSON, H.L. Division of Licensing. 85/10/11. WALKER, R.D. Region 2, Office of Director. 3pp. 33069-254-33069-266.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

64 DOCKETED ITEMS

8510150080 IE Info Notice 85-062, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010643 Monthly operating repts for Jul 1985. W/850815.1r.
JONES, V. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/07/31. BEEBE, M.R. Office of Resource Management, Director. 43pp. 32820-245-32820-288.

S. Reportable occurrences, LERs & related correspondence

8510040367 NPDES noncompliance notification on 850907, chlorine residual at Outfall 011 at sewage treatment plant exceeded effluent limitations. Subsequent test results within limitations. No corrective action planned.
MARSHALL, B.M. Virginia Power (Virginia Electric & Power Co.). 85/09/25. JENKINS, R.R. Virginia, Commonwealth of. 1p. 32866-345-32866-345.

8510030014 PNO-II-85-092 on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown, Unit 2 shut down & Surry 1 & 2 at full power.
CUNNINGHAM, R. Region 2, Office of Director. 85/09/26. 2pp. 32844-335-32844-336.

8510150173 NPDES noncompliance notification flow for Outfall 011 sewage treatment plant estimated for Sept rather than reflecting recorded results. On 850928, sample taken from Outfall 002 oil tank diked area discharge exceeded limits.
MARSHALL, B.M. Virginia Power (Virginia Electric & Power Co.). 85/10/04. JENKINS, R.R. Virginia, Commonwealth of. 2pp. 33015-061-33015-062.

8510170442 LER 85-018-00 on 850911, turbine trip/reactor trip occurred due to low condenser vacuum signal. Caused by operator inadvertently closing four condenser inlet valves while throttling four condenser outlet valves. W/851101.1r.
SAUNDERS, R.F. Virginia Power (Virginia Electric & Power Co.). 85/10/11. 4pp. 33053-234-33053-237.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.

-8510230234 Forwards Press Release 84-84 re NRC proposed imposition of civil penalty in amount of \$40,000 against utility for allegedly assuming that all hydraulic snubbers rebuilt during steam generator replacement projects.
KAMMERER, C. Office of Congressional Affairs. 84/07/31. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON, R. Senate. UDALL, House of Rep. 2pp. 33109-100-33109-101.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against utility for alleged violations of requirements concerning failure to assure operability of reactor vessel vent system.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep. Energy & Commerce. SIMPSON, R. Senate. UDALL, House of Rep. 2pp. 33109-155-33109-157.

V. Operator Examinations

8510150041 Submits add info re training of personnel performing fuel handling & cask handling for dry cask (ISFSI) cask handling & fuel loading operations performed by licensed operators or under direct supervision of senior licensed personnel.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/09. CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 3pp. 33031-298-33031-300.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

Y. Dry Cask Independent Spent Fuel Storage Installations

8510150041 Submits add info re training of personnel performing fuel handling & cask handling for dry cask (ISFSI) cask handling & fuel loading operations performed by licensed operators or under direct supervision of senior licensed personnel.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/09. CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 3pp. 33031-298-33031-300.

8510180033 Forwards topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys., Inc." Rept acceptable for referencing in licensing applications sub to encl limitations.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30. BARNHART, V.J. General Nuclear Systems, Inc. 6pp. 33074-176-33074-270.

-8510180038 Topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys., Inc."
Office of Nuclear Material Safety & Safeguards, Director. 85/09/30. 89pp. 33074-182-33074-270.

8510180539 Requests analysis & evaluation of cause of cracking found in fuel basket of CASTOR V/21 cask used in dry spent fuel storage cooperative demonstration program. Revs necessary to topical SAR also requested.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/14. BARNHART, V.J. General Nuclear Systems, Inc. 1p. 33077-280-33077-280.

8510220028 Requests reassessment of use of CASTOR V/21 cask at ISFSI & rept of findings along w/necessary license application changes, per recent discovery of cracks in cask fuel basket.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/15. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33098-281-33098-282.

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080505 Rev 8 to Corporate Nuclear Emergency Implementing Procedure EPIP 1.1.7, "Startup & Operation of Headquarters Emergency Ctr." W/850927.1r.
FEY, F.L. Northern States Power Co. 85/09/27. 22pp. 32920-217-32920-235.

8510080345 Ack receipt of 850710 changes to Rev 8 to emergency plan. Changes consistent w/10CFR50.54(g) requirements & acceptable. Notes that Figure 8-3, "Notifications," added to Section 8.0.
SHAFER, W.D. Region 3, Office of Director. 85/10/03. LARSON, C.E. Northern States Power Co. 2pp. 32918-356-32918-357.

8510160181 Resubmits 850916 revs to listed emergency plan implementing procedures, including Rev 35 to Procedure F3, "Table of Contents," & Rev 4 to Procedure F3-9, "Emergency Evacuation," due to error in printing process.
FEY, F.L. Northern States Power Co. 85/10/03. Region 3, Office of Director. 2pp. 33021-254-33021-286.

8510240242 Revised emergency plan implementing procedures, including Rev 6 to EPIP 1.1.1 re corporate emergency response organization & Rev 12 to EPIP 1.1.5 re startup & operation of emergency operations facility W/851007.1r.
FEY, F.L. Northern States Power Co. 85/10/07. 55pp. 33155-266-33155-321.

8510160179 Ack receipt of FEMA findings re evaluation of State of MN & local emergency plans. Plans adequate.
SHAFER, W.D. Region 3, Office of Director. 85/10/08. LARSON, C.E. Northern States Power Co. 2pp. 33021-287-33021-289.

-8510160189 Advises that state & local plans for radiological emergencies adequate subj to criteria of App 3, Rev 1 to NUREG-0654/FEMA-REP-1 & FEMA-43, "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants."
SPECK, S.W. Federal Emergency Management Agency. 85/09/24. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33021-289-33021-289.

8510280443 Forwards safety evaluation & EG&G technical evaluation rept accepting 830415, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/Rev 2 to Reg Guide 1.97.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF, D.M. Northern States Power Co. 3pp. 33196-270-33196-295.

-8510280448 Safety evaluation accepting util 830415, 0915, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/Rev 2 to Reg Guide 1.97.
Office of Nuclear Reactor Regulation, Director. 85/10/18. 2pp. 33196-273-33196-295.

-8510280451 "Conformance to Reg Guide 1.97, Prairie Island Nuclear Generating Plant, Units 1 & 2."
UDY, A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6483. 85/08/31. Division of Systems Integration (post 811005). 21pp. 33196-275-33196-295.

8510310304 Revised emergency plan implementing procedures, including Rev 5 to F3-7 re activation & operation of operational support ctr & Rev 8 to F3-15 re responsibilities of radiation survey teams W/851023.1r.
FEY, F.L. Northern States Power Co. 85/10/23. 91pp. 33272-277-33272-004.

I. Financial Information

8510310004 Informs that 851008 submittal of financial info for 1985 satisfies requirements of 10CFR140.21 re licensee maint of approved guarantee of payment of deferred premiums for each operating reactor over 100 MWe.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/10/24. HALLE, E.J. Northern States Power Co. 1p. 33277-108-33277-108.

P. Operating license stage documents & correspondence

8510010299 Provides confirmation of willingness to assist in resolution of Generic Issue 77 per NRC 850806 request. Util will provide requested drainage sys info by 851130.
MUSOLF, D. Northern States Power Co. 85/09/18. Office of Nuclear Reactor Regulation, Director. 1p. 32804-096-32804-096.

8510040444 Advises that 831202 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing acceptable. Conclusion supported by encl EG&G Idaho, Inc. rept.
VARGA, S.A. Operating Reactors Branch 1. 85/09/19. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 32859-315-32859-316.

-8509060182 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Ginna, Kewaunee, Point Beach Units 1 & 2 & Prairie Island Units 1 & 2."
HAROLDSEN, R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6001. EA-7000. 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859-317-32859-331.

8510090209 Provides add info re NUREG-0737, Item II.D.1, "Performance Testing of Relief & Safety Valves," in response to NRC 850214 request.
MUSOLF, D. Northern States Power Co. 85/09/28. Office of Nuclear Reactor Regulation, Director. 12pp. 32942-140-32942-335.

-8510090216 "Pressurizer Safety & Relief Line Evaluation Summary Rept - Prairie Island Nuclear Generating Station, Unit 1."
VALASEK, L.M. ANTAKI, G.A. Westinghouse Electric Corp. 84/02/29. 78pp. 32942-153-32942-230.

—8510090221 "Pressurizer Safety & Relief Line Evaluation Summary Rept - Prairie Island Nuclear Generating Station, Unit 2." VALASEK, L.M., ANTA, G.A. Westinghouse Electric Corp. 84/02/29. 78pp. 32942-231-32942-306.

—8510090227 "Summary Rept for Evaluation of Pipe Supports for Pressurizer Safety & Relief Line." DYKSTRA, P., DICKERSON, B., BARTHOLOMEW, G. Fluor Corp. 85/08/15. 27pp. 32942-309-32942-335.

8510040592 IN-PLANT SOURCE TERM MEASUREMENTS AT PRAIRIE ISLAND NUCLEAR GENERATING STATION. MANDLER, J.W., STALKER, A.C., CRONEY, S.T. EG&G Idaho, Inc. (subs. of EG&G, Inc.). PIN A-6075. NUREG/CR-4397. 85/09/30. Division of Engineering Technology. 250pp. 32863-172-32865-016.

8510070449 Forwards response to Generic Ltr 85-12, "Implementation of TMI Action Item ILK.3.5 re Automatic Trip of Reactor Coolant Pumps." MUSOLF, D. Northern States Power Co. 85/10/01. Office of Nuclear Reactor Regulation, Director. 6pp. 32875-282-32878-287.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues. BLAK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510170463 Forwards Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively & safety evaluations. Proprietary safety evaluation withheld. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/11. MUSOLF, D.M. Northern States Power Co. 3pp. 33045-134-33045-164.

—8510170466 Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively, modifying Tech Specs to allow tube sleeving method for repairing steam generator tubes. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/11. 12pp. 33045-137-33045-148.

—8510170467 Nonproprietary safety evaluation supporting Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively. Office of Nuclear Reactor Regulation, Director. 85/10/11. 16pp. 33045-149-33045-164.

8510180053 Provides proposed schedule for compliance w/requirements of 10CFR50.62(d) & Generic Ltr 85-06 re reduction of risk from ATWS events for light water-cooled plants & QA guidance for ATWS equipment that is not safety-related, respectively. MUSOLF, D. Northern States Power Co. 85/10/11. Office of Nuclear Reactor Regulation, Director. 2pp. 33063-085-33063-086.

8510280409 Forwards safety evaluation re util 850422 & 0830 ltrs concerning removal of rod cluster control guide tube thimble plugs. Plan acceptable. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF, D.M. Northern States Power Co. 2pp. 33228-121-33228-139.

—8510280412 Safety evaluation re util 850422 & 0830 ltrs concerning removal of rod cluster control guide tube thimble plugs. Plan acceptable. Office of Nuclear Reactor Regulation, Director. 85/10/18. 17pp. 33228-123-33228-139.

8510290437 Accepts 831104 response to Generic Ltr 83-25, Items 3.1.3 & 3.2.3 re post-maint testing requirements that degrade rather than enhance safety. No degradation of post-maint testing requirements found. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF, D.M. Northern States Power Co. 2pp. 33254-48-33254-349.

8510310366 Responds to REG-0737, Item II.F.2, "Inadequate Core Cooling Instrumentation." Add info re core exit thermocouple backup display & model reactor vessel level indication sys draft Tech Specs encl. MUSOLF, D. Northern States Power Co. 85/10/22. Office of Nuclear Reactor Regulation, Director. 5pp. 33271-314-33271-318.

Q. Inspection reports, IE Bulletins & correspondence

8510010101 Forwards Safety Insp Repts 50-282/85-17 & 50-306/85-14 on 850828-29. No violation noted. HARRISON, J.J. Region 3, Office of Director. 85/09/25. LARSON, C.E. Northern States Power Co. 2pp. 32800-072-32800-079.

—8510010112 Insp Repts 50-282/85-17 & 50-306/85-14 on 850828-29. No violation or deviation noted. Major areas inspected: radiation protection program during Unit 2 refueling activities & Unit 1 operational activities re solid radwaste. GUTAM, A.S., TANI, K., WILLIAMS, C.C. Region 3, Office of Director. 85/09/24. 6pp. 32800-074-32800-079.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080101 Submits steam generator tube plugging info per Tech Spec 4.12.E.1. Results of inservice insp: 19 tubes plugged, including 7 tubes in Steam Generator 21 & 12 tubes in Steam Generator 22 (1.6% & 3.2% respectively). MUSOLF, D. Northern States Power Co. 85/10/02. Office of Nuclear Reactor Regulation, Director. 1p. 32918-342-32918-342.

8510180114 Forwards Insp Repts 50-282/85-20 & 50-306/85-16 on 850916-20. No non-compliance noted. SHAFFER, W.D. Region 3, Office of Director. 85/10/10. LARSON, C.E. Northern States Power Co. 2pp. 33024-084-33024-094.

—8510180125 Insp Repts 50-282/85-20 & 50-306/85-16 on 850916-20. No violation or deviation noted. Major areas inspected: radiation protection program during Unit 2 refueling activities & Unit 1 operational activities re solid radwaste. GRANT, W.B., GREGER, L.R. Region 3, Office of Director. 85/10/10. 9pp. 33024-086-33024-094.

8510220002 Forwards Safety Insp Repts 50-282/85-19 & 50-306/85-18 on 850917-19 & 1001 & notice of violation. SHAFFER, W.D. Region 3, Office of Director. 85/10/10. LARSON, C.E. Northern States Power Co. 2pp. 33095-339-33095-349.

—8510220003 Notice of violation from insp on 850917-19, 26 & 1001. SHAFFER, W.D. Region 3, Office of Director. 85/10/10. 2pp. 33095-341-33095-342.

—8510220004 Insp Repts 50-282/85-19 & 50-306/85-18 on 850917-19, 26 & 1001. Violation noted: failure to follow procedures associated w/restoration of liquid radwaste sys following maint & w/subsequent liquid radwaste release. HUETER, L.J., OESTMANN, M.J., SCHUMACHER, M.C. Region 3, Office of Director. 85/10/09. 7pp. 33095-343-33095-349.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Sufficiently Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510310137 Responds to NRC 850920 ltr re violations noted in Insp Repts 50-282/85-15 & 50-306/85-12. Corrective actions: program of steam generator snubber insp & testing underway. LER procedures implemented & Westinghouse reviewing specs. LARSEN, C.E. Northern States Power Co. 85/10/18. HARRISON, J.J. Region 3, Office of Director. 2pp. 33274-058-33274-059.

8510250129 Forwards Safety Insp Repts 50-282/85-18 & 50-306/85-15 on 850926-27. No violation or deviation noted. HARRISON, J.J. Region 3, Office of Director. 85/10/21. LARSON, C.E. Northern States Power Co. 2pp. 33172-073-33172-080.

—8510250137 Insp Repts 50-282/85-18 & 50-306/85-15 on 850926-27. No violation or deviation noted. Major areas inspected: large capacity snubbers installed on steam generators. YIN, L.T., DANIELSON, D.H. Region 3, Office of Director. 85/10/21. 6pp. 33172-075-33172-080.

8510280296 Forwards addendum to Insp Repts 50-282/84-14 & 50-306/84-16, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sampler collected during insp. SHAFFER, W.D. Region 3, Office of Director. 85/10/22. LARSON, C.E. Northern States Power Co. 1p. 33194-008-33194-009.

—8510280304 Addendum to Insp Repts 50-282/84-14 & 50-306/84-16, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sampler collected during insp. Region 3, Office of Director. 85/10/22. 1p. 33194-009-33194-009.

R. Periodic operating reports & related correspondence

8510010650 Monthly operating repts for Jul 1985. W/850805 ltr. DUGSTAD, D., MUSOLF, D. Northern States Power Co. 85/07/31. 9pp. 32820-193-32820-201.

8510230121 Forwards revised Pages 6-8 & Attachment 1 to: "Semiannual Effluent & Waste Disposal Rept for Jan-June 1985," incorporating Fe-55 analysis results. FEY, F.L. Northern States Power Co. 85/10/01. Region 3, Office of Director. 1p. 33108-167-33108-171.

—8510230124 Revised Pages 6-8 & Attachment 1 to: "Semiannual Effluent & Waste Disposal Rept for Jan-June 1985," incorporating Fe-55 analysis results. Northern States Power Co. 85/06/30. 4pp. 33108-168-33108-171.

S. Reportable occurrences, LERs & related correspondence

8510010306 Preliminary Part 21 rept re 3.5-inch crack on snubber ball bearing. Vendor attempting to have bearing returned for exam & evaluation by SKF Industries. Next rept will be submitted when significant info available. LAURENSON, A. (ITT Grinnell Corp. (subs. of ITT Corp.)). 85/09/26. Director's Office, Office of Inspection and Enforcement. 2pp. 32801-274-32801-275.

8510210276 LER 85-012-00 on 850915, reactor tripped due to voltage transient during troubleshooting. Caused by unfamiliarity w/regulator. Event will be discussed in licensed operator requalification program W/851015 ltr. HUNSTAD, A.A., MUSOLF, D. Northern States Power Co. 85/10/15. 3pp. 33094-328-33094-330.

8510220062 Second preliminary Part 21 rept re hairline crack in bearing. Bearing will not be returned for exam. Bearing sent to Westinghouse. LAURENSON, A. (ITT Grinnell Corp. (subs. of ITT Corp.)). 85/10/15. Director's Office, Office of Inspection and Enforcement. 1p. 33090-154-33090-154.

8510220157 LER 85-013-00 on 850915, feeder breaker to motor control ctr 1KA2 tripped due to electrical fault in motor operator for valve MV-32024. Caused by overheating during repeated attempts to open valve. Motor replaced W/851015 ltr. HUNSTAD, A.A., MUSOLF, D. Northern States Power Co. 85/10/15. 4pp. 33095-096-33095-099.

66 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32862-049-32862-075.

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510240398 Forwards descriptions of objectives & scope of 1985 emergency preparedness exercise in response to NRC 840209 request.
JONES, W.C. Omaha Public Power District. 85/05/02. MARTIN, R.D. Region 4, Office of Director. 4pp. 33154-049-33154-052.

8510280009 Forwards comments re 850502 submittal of objectives for full scale emergency preparedness exercise scheduled for Jul 1985. Addl development needed re demonstration of corrective actions for weaknesses identified in previous exercises.
HUNTER, D.R. Region 4, Office of Director. 85/05/21. ANDREWS, R.L. Omaha Public Power District. 4pp. 33194-323-33194-326.

8510250307 Forwards description of exercise scenario for 1985 emergency preparedness exercise, anticipated licensee actions, complete controller packages w/info to be supplied to observers of exercise & source term data, per NRC 840209 request.
JONES, W.C. Omaha Public Power District. 85/06/07. MARTIN, R.D. Region 4, Office of Director. 150pp. 33170-186-33170-341.

8510240403 Responds to 850624 request for addl info re exercise scenario for 1985. Util unable to provide info due to quantity of data requested & short time before exercise. Scenario submitted to FEMA on 850612 meets NRC requirements.
ANDREWS, R.L. Omaha Public Power District. 85/07/05. MARTIN, R.D. Region 4, Office of Director. 2pp. 33151-323-33151-324.

8510100059 Forwards payment of civil penalty in amount of \$21,425 for security violations. Corrective actions to resolve violations noted in 840820-24 insp encl Encl withheld (ref 10CFR73.21).
ANDREWS, R.L. Omaha Public Power District. 85/08/29. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 2pp. 32961-025-32961-026.

8510010426 Forwards revised plans & calculations re control room habitability (NUREG-0737, Item III D.3.4) Design verification for VA-65 ductwork in progress. Relocation expected prior to restart after Fall 1985 outage.
ANDREWS, R.L. Omaha Public Power District. 85/09/23. BUTCHER, E.J. Operating Reactors Branch 3. 24pp. 32804-099-32804-122.

8510230099 Forwards Physical Security Event Rept 85-29. Rept withheld (ref 10CFR73.21).
ANDREWS, R.L. Omaha Public Power District. 85/10/04. DENISE, R.P. Region 4, Office of Director. 1p. 33102-212-33102-212.

8510170226 Changes to Section E & table of contents of radiological emergency response plan. W/851010 ltr.
ANDREWS, R.L. Omaha Public Power District. 85/10/10. MARTIN, R.D. Region 4, Office of Director. 38pp. 33043-001-33043-038.

8510280060 Forwards safety evaluation & Science Applications Intl Corp technical evaluation rept re 850401,0502 & 0615 submittals for DCDRDCDRDCDR incomplete. Submittal of listed info for review & approval required within 60 days of ltr receipt.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/17. ANDREWS, R.L. Omaha Public Power District. 3pp. 33241-137-33241-196.

-8510280069 Safety evaluation re util 850401,0502 & 0615 submittals for DCDRDCDRDCDR incomplete. Listed activities must be completed to satisfy requirements of Suppl 1 to NUREG-0737. Preimplementation audit may be necessary.
* Office of Nuclear Reactor Regulation, Director. 85/10/17. 12pp. 33241-140-33241-151.

-8510280074 "Technical Evaluation of DCDRDCDR for Ft Calhoun Station."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. 85/08/28. Division of Human Factors Safety. 45pp. 33241-152-33241-196.

8510240293 Forwards Insp Rept 50-285/85-15 on 850701-0831 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/18. ANDREWS, R.L. Omaha Public Power District. 2pp. 33151-016-33151-032.

-8510240334 Notice of violation from insp on 850701-0831.

* Region 4, Office of Director. 85/10/18. 2pp. 33151-016-33151-019.

-8510240343 Insp Rept 50-285/85-15 on 850701-0831 Violations noted: failure to establish document control procedures, meet licensing requirements re storage of flammable matl & implement surveillance requirements for toxic gas monitors.
YANDELL, A. MARTIN, L.E. Region 4, Office of Director. 85/10/01. 13pp. 33151-020-33151-032.

8510290208 Revised table of contents for emergency plan implementing procedure.
"Reentry & Recovery Organization." W/851023 ltr.
ANDREWS, R.L. Omaha Public Power District. 85/10/23. MARTIN, R.D. Region 4, Office of Director. 5pp. 33233-253-33233-257.

8510290240 Revised emergency plan implementing procedures, including table of contents & Section J, "Protective Response." W/851023 ltr.
ANDREWS, R.L. Omaha Public Power District. 85/10/23. MARTIN, R.D. Region 4, Office of Director. 63pp. 33230-323-33231-023.

I. Financial information

8510150495 Advises that financial info submitted for 1985 in 850715 ltr satisfies requirements of 10CFR140.21.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. ANDREWS, R.L. Omaha Public Power District. 1p. 33033-134-33033-134.

P. Operating license change documents & correspondence

8510080147 Requests extension of response date until 850927 to respond to NRC 850722 request for info re policy for use of Procedure OP-10, "Abnormal Condition Procedure." per 850920 telcon.
ANDREWS, R.L. Omaha Public Power District. 85/09/23. JOHNSON, E.H. Region 4, Office of Director. 1p. 32918-355-32918-355.

8510080044 Forwards addl info re 850524 response to Generic Ltr 83-28, Item 2.2, including discussion & schedule for completion of Phases II & III of vendor manual control project indexing will be completed by 860228 for manuals received by 850601.
ANDREWS, R.L. Omaha Public Power District. 85/09/26. BUTCHER, E.J. Division of Licensing. 2pp. 32918-310-32918-311.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510160062 Forwards proposed schedule for validation completion & use of CECOR re core reload methodology on ERF computer NRC to be notified when validation of mini-CECOR/BASSS sys complete.
ANDREWS, R.L. Omaha Public Power District. 85/10/04. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33027-207-33027-208.

8510230021 Submits schedule for meeting requirements of 10CFR50.62 per Generic Ltr 85-06 re ATWS implementation. C-E Owners Group preparing submittal for portion addressing diversity in auxiliary feedwater actuation.
ANDREWS, R.L. Omaha Public Power District. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33102-237-33102-237.

8510230026 Forwards revised request for exemption from inservice insp testing of inaccessible sections of containment recirculation piping buried in concrete.
ANDREWS, R.L. Omaha Public Power District. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 7pp. 33102-241-33102-247.

Q. Inspection reports, IE Bulletins & correspondence

8510100059 Forwards payment of civil penalty in amount of \$21,425 for security violations. Corrective actions to resolve violations noted in 840820-24 insp encl Encl withheld (ref 10CFR73.21).
ANDREWS, R.L. Omaha Public Power District. 85/08/29. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 2pp. 32961-025-32961-026.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070572 Ack receipt of 850829 ltr & \$21,425 in payment of civil penalties imposed by 850730 order. Corrective actions will be examined during future insps.
AXELRAD, J.A. Enforcement Staff. 85/10/04. Omaha Public Power District. 2pp. 32900-358-32900-359.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510230026 Forwards revised request for exemption from inservice insp testing of inaccessible sections of containment recirculation piping buried in concrete.
ANDREWS, R.L. Omaha Public Power District. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 7pp. 33102-241-33102-247.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series FLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510240293 Forwards Insp Rept 50-285/85-15 on 850701-0831 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/18. ANDREWS, R.L. Omaha Public Power District. 2pp. 33151-016-33151-032.

-8510240334 Notice of violation from insp on 850701-0831.

* Region 4, Office of Director. 85/10/18. 2pp. 33151-016-33151-019.

-8510240343 Insp Rept 50-285/85-15 on 850701-0831 Violations noted: failure to establish document control procedures, meet licensing requirements re storage of flammable matl & implement surveillance requirements for toxic gas monitors.
YANDELL, A. MARTIN, L.E. Region 4, Office of Director. 85/10/01. 13pp. 33151-020-33151-032.

R. Periodic operating reports & related correspondence

8510230313 Monthly operating rept for Sept 1985. W/851011 ltr.
MATTHEWS, T.P. ANDREWS, R.L. Omaha Public Power District. 85/09/30. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 8pp. 33109-243-33109-257.

S. Reportable occurrences, LERs & related correspondence

8510080275 PNO-IV-85-053 on 85092R reactor shut down in preparation for planned refueling outage. Outage expected to last 3 months. State of NE informed. No press release planned.
MARTIN, L.E. Region 4, Office of Director. 85/10/04. 1p. 32913:343-32913:343.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32862-049-32862-075.

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

A. Application/construction stage documents & correspondence

8510080218 Informs of installation of safety-related seismic Category I qualified valve on auxiliary feedwater sys downstream from Valve LCV-1158, per Generic Ltr 81-14. Condensate storage tank setpoint being returned to original value.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/02. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32922:109-32922:110.

F. Security, medical, emergency & fire protection plans

8510090316 Informs that continued shutdown not required pending action on 850910 request not to install funds associated w/NUREG-0737, Item III.D.3.4, "Control Room Habitability" & forthcoming license amend to modify scheduler requirement.
THOMPSON, H.L. Division of Licensing. 85/09/30. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 6pp. 32949:172-32949:175.

8510220001 Revised emergency plan implementing procedures, including Rev 13 to EP Book II, Rev 7 to IP-1001, "Determining Magnitude of Release," Rev 4 to IP-1025, "Repair & Corrective Action Teams" & Rev 1 to IP-1057.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. 57pp. 33090:265-33090:322.

8510220330 Forwards application for amend to License DPR-64, extending completion date for 830318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Fee paid.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/17. VARGA, S.A. Operating Reactors Branch 1. 4pp. 33093:071-33093:074.

8510220337 Application for amend to License DPR-64, requesting extension of completion date for 830318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Safety evaluation encl.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/17. 6pp. 33093:075-33093:080.

8510220340 "Dose Rates Inside Indian Point 3 Control Room."
GOLSHUNI, M., SIMON, S. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 85/04/25. 14pp. 33093:081-33093:088.

8510250259 Notification of Licensee Meeting 85-10th on 851030 w/utl in King of Prussia, PA to discuss licensee action re NUREG-0737, Item III.D.3.4, "Control Room Habitability."
NORRHOLM, L.J. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 1p. 33170:360-33170:360.

P. Operating license stage documents & correspondence

8510030071 Provides method & frequency for functional testing of steam generator snubbers prior to startup from Cycle 4/5 refueling outage, per 840813 commitment. Representative sample of 10% will be selected to perform test.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/09/27. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32843:005-32843:008.

8510080218 Informs of installation of safety-related seismic Category I qualified valve on auxiliary feedwater sys downstream from Valve LCV-1158, per Generic Ltr 81-14. Condensate storage tank setpoint being returned to original value.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/02. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32922:109-32922:110.

8510080313 Forwards response to 850701 ltr & supplemental safety evaluation re NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys (PASS)." Encl discusses PASS capability in post-accident water chemistry environ.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/02. VARGA, S.A. Operating Reactors Branch 1. 10pp. 32919:001-32919:010.

8510100120 Forwards application for amend to License DPR-64, revising Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737 items. Fee paid.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/04. VARGA, S.A. Operating Reactors Branch 1. 3pp. 32961:181-32961:197.

8510100136 Application for amend to License DPR-64, revising Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737 items.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/04. 1p. 32961:184-32961:184.

8510100147 Proposed Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737, Items II.B.1, II.F.1.1, II.F.1.5 & II.F.1.6. Safety evaluation encl.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/04. 13pp. 32961:185-32961:197.

8510180059 Submits proposed schedule for meeting 10CFR50.62, "Requirements for Reduction of Risk From ATWS Events for Light Water Cooled Nuclear Power Plants." Design description will be submitted within 3 months of NRC SER issuance.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33054:051-33054:052.

8510220330 Forwards application for amend to License DPR-64, extending completion date for 830318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Fee paid.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/17. VARGA, S.A. Operating Reactors Branch 1. 4pp. 33093:071-33093:074.

8510220337 Application for amend to License DPR-64, requesting extension of completion date for 830318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Safety evaluation encl.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/17. 6pp. 33093:075-33093:080.

8510220340 "Dose Rates Inside Indian Point 3 Control Room."
GOLSHUNI, M., SIMON, S. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 85/04/25. 14pp. 33093:081-33093:088.

Q. Inspection reports, IE Bulletins & correspondence

8510030213 Forwards Insp Rept 50-286/85-19 on 850716-0831. No violations noted.
COLLINS, S.J. Region 1, Office of Director. 85/09/18. JOSIGER, W. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 32846:123-32846:138.

8510030225 Insp Rept 50-286/85-19 on 850716-0831. No violations noted. Major areas inspected: onsite regular & backfit insp of operations, including shift logs & records, operational safety verification & status of TMI action items.
KOLTAY, P.S., NORRHOLM, L.J. Region 1, Office of Director. 85/09/17. 14pp. 32846:125-32846:138.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080184 Forwards Safety Insp Rept 50-286/85-21 on 850909-13. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/02. JOSIGER, W. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 32921:047-32921:054.

8510080189 Insp Rept 50-286/85-21 on 850909-13. No violation noted. Major areas inspected: inservice insp activities, including NDE procedures, inservice insp data & steam generator augmented ultrasonic exam.
MCBREARTY, R.A., WIGGINS, J.T. Region 1, Office of Director. 85/09/27. 9pp. 32921:049-32921:054.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510310178 Forwards Safety Insp Rept 50-286/85-20 on 850903-06. No violation noted. Need for continued improvement in radiochemical lab QC noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/25. JOSIGER, W. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 33273:255-33273:263.

8510310182 Insp Rept 50-286/85-20 on 850903-06. No noncompliance noted. Major areas inspected: radioactive liquid & gaseous effluents control program, including mgmt control, training, audits & radioactive effluent release records.
STRUCKMEYER, R., MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/10/24. 7pp. 33273:257-33273:263.

R. Periodic operating reports & related correspondence

8510290476 Monthly operating rept for Sept 1985 W/851015 ltr.
KELLY, J., JOSIGER, W.A. New York Power Authority (formerly Power Authority of the State of New York). 85/09/30. 10pp. 33242:128-33242:137.

68 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing, 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32862-049-32862-075.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8510080335 Request withdrawal of 831111 application for exemption from Section III G.2 of 10CFR50.48, App R Mock-up of fire barrier wall separating east & west penetration rooms demonstrated compliance w/fire endurance requirements.
TUCKER, H.B. Duke Power Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 32913-197-32913-199.

8510020243 Summary of 850212-14 meetings w/util in Seneca, SC re review of util response to NUREG-0737, Item III 7.3.4, "Control Room Habitability Requirements" & status of open items concerning emergency feedwater sys Attendance list encl.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/01. Operating Reactors Branch 4. 6pp. 32846-252-32846-286.

8510080165 Rev 85-8 to emergency plan implementing procedures, Vol 6, Chemistry Manual 5.1, "Emergency Responses" & health physics manual, Section 11.1, "Health Physics Emergency Response" W/851001 ltr.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/01. GRACE, J.N. Region 2, Office of Director. 33pp. 32950-358-32950-358.

8510210067 Rev 85-9 to Vol B of emergency plan implementing procedure manual, "Health Physics Emergency Response" W/851010 ltr.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/10. GRACE, J.N. Region 2, Office of Director. 17pp. 33073-211-33073-227.

8510210075 Rev 85-6 to Vol C of emergency plan implementing procedures, including Procedure RP/O/B/1000/15, "Offsite Communicator," emergency telephone numbers & table of contents.
TUCKMAN, M.S., TUCKER, H.B. Duke Power Co. 85/10/10. GRACE, J.N. Region 2, Office of Director. 34pp. 33072-090-33072-125.

8510240384 Forwards Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
GRACE, J.N. Region 2, Office of Director. 85/10/17. TUCKER, H.B. Duke Power Co. 2pp. 33151-336-33151-338.

8510240392 Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 Violation noted: inadequate procedure for documentation of vital area barrier insp Details withheld (ref 10CFR2.790(d) & 73.21).
PERNY, C.D. Region 2, Office of Director. 85/10/02. 1p. 33151-338-33151-338.

I. Financial information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept," including financial forecast for 1985-1987 & interim financial statements for 850630.
TUCKER, H.B. Duke Power Co. 85/10/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33246-245-33246-310.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 6 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER, H.B. Duke Power Co. 85/03/01. GRACE, J.N. Region 2, Office of Director. 3pp. 32865-148-32865-239.

8510040542 Revised Vol 1 to "Process Control Program," Sections I-V, Sections VI-IX withheld.
* Duke Power Co. 85/03/01. 46pp. 32865-194-32865-239.

8510040565 Summary of 841107 meeting w/util in Washington, DC re cost/benefit evaluation of reactor vessel coolant inventory tracking sys. Viewgraphs, meeting agenda & list of attendees encl.
NICOLARAS, H. Operating Reactors Branch 4. 85/07/24. Operating Reactors Branch 4. 45pp. 32861-249-32861-293.

8510090075 Forwards Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to support operation of Unit 3 at full rated power during Cycle 9.
NICOLARAS, H. Operating Reactors Branch 4. 85/09/19. TUCKER, H.B. Duke Power Co. 2pp. 32963-342-32964-008.

8510090080 Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to support operation of Unit 3 at full rated power during Cycle 9 in area of core protection safety limits.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/19. 20pp. 32963-344-32964-001.

8510090088 Safety evaluation supporting Amends 142, 142 & 139 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/19. 7pp. 32964-002-32964-008.

8510010259 Application for amends to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs to delete ref to reload fuel assembly & rod enrichment requirements. Fee paid.
TUCKER, H.B. Duke Power Co. 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 32802-227-32802-236.

8510010262 Proposed Tech Specs, deleting ref to reload fuel assembly & rod enrichment requirements.
* Duke Power Co. 85/09/24. 7pp. 32802-230-32802-236.

8510070263 Submits verification results for serial numbers on each IRVSP capsule in Lynchburg Research Ctr storage pool, per Rev 2 to BAW-1543.
TAYLOR, J.H. Babcock & Wilcox Co. 85/10/01. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 32877-312-32877-313.

8510090319 Forwards topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/01. TUCKER, H.B. Duke Power Co. 2pp. 32949-176-32949-185.

8510090321 Topical rept evaluation of Technical Rept DPC-NE-1002, "Oconee Nuclear Station Reload Design Methodology II." Revised methodology acceptable means for calculation of facility licensing submittals.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 8pp. 32949-178-32949-185.

8510100155 Forwards response to NRC 850603 request for addl info on NUREG-0737, Item III D.1, "Performance Testing of Relief & Safety Valves." PCHV control circuit components located in cable room & not subj to harsh environ.
TUCKER, H.B. Duke Power Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 43pp. 32962-223-32962-266.

8510160278 Advises that due to delay in issuance of B&W Owners Group QA guidance ltr, final design info on diverse scram sys/ATWS mitigation sys actuation circuitry sys will be submitted 60 days after review of design basis document.
TUCKER, H.B. Duke Power Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33026-249-33026-250.

8510210074 Forwards addl info re util 850610 waste vol reduction incinerator license submittal in response to NRC 850906 request. Revised submittal will be forwarded by 851122 in response to Questions A-2-B-1, -2, -3, -4 & -5.
TUCKER, H.B. Duke Power Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 61pp. 33073-228-33073-288.

8510210189 Forwards Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak tests.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/09. TUCKER, H.B. Duke Power Co. 2pp. 33094-140-33094-154.

8510210194 Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to allow use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during leak test of connected sys.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/09. 11pp. 33094-142-33094-152.

8510210197 Safety evaluation supporting Amends 143, 143 & 140 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/09. 2pp. 33094-153-33094-154.

8510180512 Forwards safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1 Reviews & other actions accepted. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/11. TUCKER, H.B. Duke Power Co. 3pp. 33077-198-33077-205.

8510180517 Safety evaluation re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1, 3.2.2, 4.1 & 4.5.1, accepting reviews & other actions. Written confirmation of completion of Items 3.1.1 & 3.2.2 & actions on Item 4.1 requested.
* Office of Nuclear Reactor Regulation, Director. 85/10/11. 5pp. 33077-201-33077-205.

8510300188 Forwards Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation. Amends revise Tech Specs to delineate need for administrative controls to limit hours for staff performing safety-related functions.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/21. TUCKER, H.B. Duke Power Co. 2pp. 33261-332-33261-345.

8510300193 Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to delineate need for administrative controls to limit working hours for station staff performing safety-related functions.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/21. 8pp. 33261-334-33261-341.

8510300211 Safety evaluation supporting Amends 144, 144 & 141 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 5pp. 33261-342-33261-346.

8510310248 Submits addl info re NUREG-0737, Item III D.1, "Performance Testing of Relief & Safety Valves." New middle ring setting for Unit 1 will be changed to -50 during end of Cycle 10 refueling outage scheduled to begin on 870920.
TUCKER, H.B. Duke Power Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33273-241-33273-241.

Q. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8510070466 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-269/85-20, 50-270/85-20 & 50-287/85-20. Corrective actions: program developed to ensure proper station responsibility assignments for surveillance, maint & reporting.
TUCKER, H.B. Duke Power Co. 85/09/27. GRACE, J.N. Region 2, Office of Director. 9pp. 32878-345-32878-353.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510180527 Responds to 840409 denial of violation from Insp Repts 50-269/83-34, 50-270/83-34 & 50-287/83-34 re posting of chemical treatment pond as radioactive matts area. Agrees no violation occurred.
GRACE, J.N. Region 2, Office of Director. 85/09/30. TUCKER, H.B. Duke Power Co. 1p. 33068-009-33068-009.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070495 Forwards Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/01. TUCKER, H.B. Duke Power Co. 2pp. 32878-115-32878-126.

-8510070497 Notice of violation from Insp on 850903-05.
* Region 2, Office of Director. 85/10/01. 2pp. 32878-117-32878-118.

-8510070500 Insp Repts 50-269/85-27, 50-270/85-27 & 50-287/85-27 on 850903-06. Violations noted: failure to use qualified weld procedures & to obtain final QA approval on reactor coolant pump replacement bolts prior to startup.
ECONOMOS, N., BLAKE, J.J. Region 2, Office of Director. 85/09/24. 8pp. 32878-119-32878-126.

8510070505 Forwards Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13. No violations or deviations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/01. TUCKER, H.B. Duke Power Co. 1p. 32878-102-32878-114.

-8510070513 Insp Repts 50-269/85-29, 50-270/85-29 & 50-287/85-29 on 850909-13. No violation or deviation noted. Major areas inspected: QA program review, QA/QC administration, procurement, receipt, storage & handling & previous findings.
RUNYAN, M.F., MOORMAN, J.H., BELISLE, G.A. Region 2, Office of Director. 85/09/26. 12pp. 32878-103-32878-114.

8510160017 Forwards response to 850722 request for addl info re inservice Insp relief requests for second 10-yr interval.
TUCKER, H.B. Duke Power Co. 85/10/06. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 15pp. 33029-001-33029-015.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510240384 Forwards Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
GRACE, J.N. Region 2, Office of Director. 85/10/17. TUCKER, H.B. Duke Power Co. 2pp. 33151-336-33151-338.

-8510240392 Insp Repts 50-269/85-28, 50-270/85-28 & 50-287/85-28 on 850903-06. Violation noted: inadequate procedure for documentation of vital area barrier Insp. Details withheld (ref 10CFR2.790(d) & 73.21).
PERNY, C.D., MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/02. 1p. 33151-336-33151-338.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510170185 Forwards "Environ Radiological Monitoring Program Annual Operating Rept, 1984." W/o encl.
TUCKER, H.B. Duke Power Co. 85/07/30. GRACE, J.N. Region 2, Office of Director. 1p. 33051-326-33051-356.

8510220094 Monthly operating repts for Sept 1985. W/851015 ltr
REAVIS, J.A., TUCKER, H.B. Duke Power Co. 85/09/30. 17pp. 33095-130-33095-146.

S. Reportable occurrences, LERs & related correspondence

8510090535 LER 85-002-00 on 850828, fault pressure relay on startup transformer CT-3 actuated, initiating lockout & resulting in loss of ac power. Cause undeterminable. Load ctr transformer feeder breakers reset W/850930 ltr.
GODWIN, S.G., TUCKER, H.B. Duke Power Co. 85/09/30. 4pp. 32946-041-32946-044.

8510180014 Notification of 851021-24 site visits to discuss operating experience associated w/loss of safety function events due to personnel actions on wrong train of redundant sys or wrong unit of multi-unit facilities.
HOOD, D.S. Licensing Branch 4. 85/10/11. ADENSAME, E.G. Licensing Branch 4. 5pp. 33069-354-33069-358.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8510040111 Forwards App A to emergency plan, containing agreement ltrs w/offsite support organizations. App B will be submitted by 851015.
KAY, M.A. Reed College, Portland, OR. 85/09/24. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 32851-192-32851-199.

-8510040114 App A to emergency response plan.
HARRINGTON, P.E. Reed College, Portland, OR. 85/09/24. 7pp. 32851-193-32851-199.

8510220228 Forwards App B to 850915 emergency plan, "Reed Reactor Facility Emergency Implementation Procedures." Submission of revised emergency plan complete.
KAY, M.A. Reed College, Portland, OR. 85/10/18. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 33090-007-33090-022.

-8510220232 "Reed Reactor Facility Emergency Implementation Procedures."
* Reed College, Portland, OR. 85/10/15. 15pp. 33090-008-33090-022.

P. Operating license stage documents & correspondence

8510080489 Application for amend to License R-112, changing Tech Specs to incorporate listed changes re reactor safety committee.
KAY, M.A., CROLYN, M.W. Reed College, Portland, OR. 85/09/30. DORSIA, J. Office of Nuclear Reactor Regulation, Director. 3pp. 32921-192-32921-213.

-8510080491 Revised "Administrative Procedures."
* Reed College, Portland, OR. 85/05/31. 19pp. 32921-195-32921-213.

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080173 Rev 14 to Emergency Planning Implementing Procedure 1004.4, "Callout of Duty Roster Personnel."
BEVELAQUA, J.J. General Public Utilities Corp. - GPU Service Corp. 85/09/30. 16pp. 32922-086-32922-101.

8510150362 Temporary Change Notice 1-85-0158 to Rev 14 to Procedure 1004.2 re emergency direction, Temporary Change Notice 1-85-0157 to Rev 15 to Procedure 1004.3 re emergency offsite notifications & canceling Temporary Change Notice 1-85-0115.
* General Public Utilities Corp. - GPU Service Corp. 85/10/08. 43pp. 33010-025-33010-067.

8510250180 Forwards Safety Insp Rept 50-289/85-21 on 850802-0916 & notice of violation. Discusses operationally significant 850821 & 0907 events.
KANE, W.F. Region 1, Office of Director. 85/10/15. HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 5pp. 33190-207-33190-245.

-8510250186 Notice of violation from Insp on 850802-0916. Portions deleted (ref 10CFR2.790(a)).
* Region 1, Office of Director. 85/10/15. 1p. 33190-212-33190-212.

-8510250193 Safety Insp Rept 50-289/85-21 on 850802-0916. Violations noted: failure to conduct complete search of escorted individual. Portions deleted (ref 10CFR2.790(a)).
CONTER, Region 1, Office of Director. 85/10/14. 33pp. 33190-213-33190-245.

8510250354 Forwards control room emergency HVAC sys repts & test results, per 850404 meeting & 850603 ltr re NUREG-0737, Item III D.3.4, "Control Room Habitability." Results indicate control room habitable.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33166-304-33167-166.

-8510250359 "TMI-1 Control Room Habitability Study Analysis of Radiological & Chemical Accidents for Abnormal Flow Paths to Control Room," final rept.
FENSTERMACHER, Pickard, Lowe & Garlick, Inc. PLG-0433. 85/08/28. 70pp. 33166-307-33167-058.

-8510250364 Rev 0 to "Evaluation of Capability of Control Bldg HVAC Sys to Maintain Post-Accident Habitable Environ in Control Room," technical data rept.
SANFORD, M. General Public Utilities Corp. - GPU Service Corp. TDR 728 R00. 85/10/14. 43pp. 33167-015-33167-058.

-8510250375 Rev 0 to "Control Bldg 'Delta-P' Test Single Mode Failure (Postulated) of Dampers (AH-D-37, 41A & 28) & Airflow Measurements."
TOOLE, R.J. General Public Utilities Corp. - GPU Service Corp. STP 141/13 R00. 85/10/18. 100pp. 33167-059-33167-166.

G. Adjudicatory correspondence

8510100048 Response to Mr Lewis 850919 petition for new leak rate contention. Board has no jurisdiction to consider petitioner contention.
TROWBRIDGE, G.F. General Public Utilities Corp. - GPU Service Corp.
TROWBRIDGE, G.F. Shaw, Pittman, Potts & Trowbridge. #485 682. 85/10/04. Atomic Safety and Licensing Board Panel. 6pp. 32960-079-32960-084.

70 DOCKETED ITEMS

- 851010020** Advises that author will present oral argument on behalf of NRC re appeal of ASLB 850503 partial initial decision on licensed operator training in response to ASLB 850905 order. Related correspondence.
YAGNER, M.E. Hearing Branch 4. #485 721. 85/10/07. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32973:276-32973:276.
- 8510110156** Withdraws appeal of ASLB Partial Initial Decision LBP-85-30 on remanded Deckamp mailgram issue due to inability to continue funding. Certificate of Svc encl.
DOROSHOW, J. Three Mile Island Alert. #485 733. 85/10/06. EDLES, G.J., KOHL, C.N., JOHNSON, W.R. Atomic Safety and Licensing Appeal Panel. 14pp. 32972:131-32972:180.
- 8510150347** Notice of withdrawal of 850503 appeal of LBP-85-15. Certificate of Svc encl.
WEISS, E.R. Union of Concerned Scientists. WEISS, E.R. Harmon, Weiss & Jordan. #485 769. 85/10/08. 4pp. 33000:346-33000:349.
- 8510110129** Advises that time to review ASLB Decision ALAB-815 expired. NRC declined review. Decision made final agency action on 851008. Served on 851009.
CHILK, S.J. Office of the Secretary of the Commission. #485 727. 85/10/09. Office of the Executive Legal Director. 1p. 32974:020-32974:020.
- 8510180120** Informs of intention to present oral argument on 851024 on intervenor appeal from 850503 partial initial decision re licensed operator training (LBP-85-15). W/svc list. Related correspondence.
BAUSER, D.B. Shaw, Pittman, Potts & Trowbridge. BAUSER, D.B. General Public Utilities Corp. - GPU Service Corp. #485 772. 85/10/09. SHOEMAKER, C.J. Atomic Safety and Licensing Board Panel. 3pp. 33022:308-33022:310.
- 8510160280** Answer to Mi Lewis 850919 petition for new or expanded contention re Hartman leak rate allegations. Petition should be denied in entirety.
FINKELSTEIN, L. Hearing Branch 4. #485 777. 85/10/09. Atomic Safety and Licensing Board Panel. 14pp. 33024:318-33024:338.
- 8510160284** Affidavit of L.H. Bettenhausen re allegations raised by Mi Lewis 850919 petition for new or expanded contention concerning Hartman leak rate allegations. Certificate of Svc encl.
BETTENHAUSEN, L. Region 1, Office of Director. 85/10/07. 7pp. 33024:332-33024:338.
- 8510180287** Response opposing licensee 851004 response to petition for new leak rate contention. ASLB should find litigation of new leak rate contention in best interest of all concerned. Prehearing conference re contention should be called.
LEWIS, M.I. Lewis, M. #485 791. 85/10/11. Atomic Safety and Licensing Board Panel. 3pp. 33062:084-33062:086.
- 8510180164** Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
BAUSER, D.B. Shaw, Pittman, Potts & Trowbridge. #485 800. 85/10/15. 3pp. 33055:267-33055:269.
- 8510180185** Order denying Mi Lewis 850919 petition for new or expanded contention re Hartman leak rate allegations. Ruling referred to Appeal Board. Served on 851016.
WOLFE, S.J., LINENBERGER, G., SMITH, J.W. Atomic Safety and Licensing Board Panel. #485 801. 85/10/15. Lewis, M. 5pp. 33059:336-33059:340.
- 8510210003** Forwards notices of appearance of MW Maupin & MC Henaley. Certificate of Svc encl.
MAUPIN, M.W. Hutton & Williams. #485 841. 85/10/16. Docketing & Services Branch. 4pp. 33074:128-33074:131.
- 8510240675** Petition of L. Bradford for leave to intervene & request for hearing re C. Husted integrity & suitability to serve as licensed operator instructor or training supervisor. Certificate of Svc encl.
BRADFORD, L. Three Mile Island Alert. #485 889. 85/10/20. Commissioners. 4pp. 33161:026-33161:029.
- 8510230039** Notices of withdrawal of appeal of ASLB Partial Initial Decision LBP-85-15 re remanded training issues due to inability to continue funding. Svc list encl.
DOROSHOW, J. Three Mile Island Alert. #485 871. 85/10/21. EDLES, G.J., KOHL, C.N., JOHNSON, W.R. Atomic Safety and Licensing Appeal Panel. 3pp. 33101:060-33101:062.
- 8510230087** Order cancelling 851024 oral argument based on UCS & TMI Alert withdrawal of appeals of ASLB 850503 & 8519 partial initial decisions re licensed operator training & Deckamp mailgram, respectively. Served on 851022.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 870. 85/10/21. 2pp. 33102:182-33102:183.
- 8510230128** Notice of cancellation of scheduled 851024 oral argument on TMI Alert, Inc & UCS appeals from ASLB 850503 partial initial decision re licensed operator training (LBP-85-15) in Bethesda, MD. ASLB 851021 order. Served on 851022.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 869. 85/10/21. 1p. 33102:036-33102:036.
- 8510240666** Notifies Commission that Commonwealth of PA will not participate in hearing noticed on 850906. Withdrawal of representation for Husted by Shaw, Pittman, Potts & Trowbridge renders licensee motion to disqualify moot. Svc list encl.
AU, T.Y. Pennsylvania, Commonwealth of. #485 890. 85/10/21. Docketing & Services Branch. 2pp. 33161:013-33161:014.
- 8510240673** Petition of DB Bauser for leave to intervene. Certificate of Svc encl.
BAUSER, D.B. General Public Utilities Corp. - GPU Service Corp. BAUSER, D.B. Shaw, Pittman, Potts & Trowbridge. #485 888. 85/10/21. Atomic Safety and Licensing Board Panel. 3pp. 33161:023-33161:025.
- 8510280516** Forwards 851003 ltr re schedule for delivery of Singer Link replica simulator for TMI-1. Svc list encl. Related correspondence.
BAUSER, D.B. Shaw, Pittman, Potts & Trowbridge. BAUSER, D.B. General Public Utilities Corp. - GPU Service Corp. #485 931. 85/10/24. EDLES, G.J., JOHNSON, W.R., KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 5pp. 33227:303-33227:307.
- 8510310337** Forwards HD Hukill 851003 ltr to NRC reporting on current schedule for delivery of Singer Link replica simulator for facility. Encl updates 850731 notification to ASLB & parties. Svc list encl. Related correspondence.
BAUSER, D.B. Shaw, Pittman, Potts & Trowbridge. BAUSER, D.B. General Public Utilities Corp. - GPU Service Corp. #485 965. 85/10/24. EDLES, G.J., JOHNSON, W.R., KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 5pp. 33271:352-33271:356.
- 8510280517** Order dismissing petition re Hartman allegations on erroneous leak rate measurement. Served on 851025.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 928. 85/10/25. LEWIS, M.I. Lewis, M. 6pp. 33227:297-33227:302.

H. General correspondence

8510150286 Forwards "Cancer Mortality & Morbidity (Incidence) Around TMI" & "Assessment of Cancer Mortality Survey in Three TMI Areas..." in response to K Bloudin 850709 ltr. Actions taken as result of Feb 1983 Salem ATWS events also discussed.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/10/09. CRANSTON, A. Senate. 19pp. 33032:082-33032:211.

-8510150291 "Cancer Mortality & Morbidity (Incidence) Around TMI"
TOKUHATA, G.K., DIGONE, E. Pennsylvania, Commonwealth of. 85/09/30. 52pp. 33032:101-33032:153.

-8510150295 "Assessment of Cancer Mortality Survey in Three TMI Areas Selected by Local Residents."
Pennsylvania, Commonwealth of. 85/09/30. 22pp. 33032:154-33032:201.

-8510150300 Requests response to encl K Bloudin 850709 concerns re Salem ATWS event & TMI accident.
CRANSTON, A. Senate. 85/08/30. Office of Congressional Affairs. 10pp. 33032:202-33032:211.

I. Financial information

8510160247 Forwards util 850425 Ltr 5211-85-2080/4410-85-L-0094, per NRC 851003 ltr info demonstrates util payment capabilities required by 10CFR140.21.
MORRELL, M.P. General Public Utilities Corp. - GPU Service Corp. 85/10/09. STOLZ, J.F. Office of State Programs, Director. 1p. 33022:223-33022:226.

P. Operating license stage documents & correspondence

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force report available.
ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905:053-32905:157.

-8405010072 Forwards comparison of emergency feedwater sys at TMI-1 & other B&W operating plants to acceptance criteria of SRP Section 10.4.9. Schedules established for implementation of necessary mods at each B&W plant.
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 84/04/17. LAINAS, G.C. Assistant Director for Operating Reactors. 13pp. 32908:119-32908:197.

8510010118 Notifies that meeting to discuss inservice testing of pumps & valves, originally scheduled for 850820 & 21, rescheduled for 850904-05 in Bethesda, MD due to util request for addl preparation time. Related correspondence.
STOLZ, J.F. Operating Reactors Branch 4. #385 070. 85/07/29. HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 4pp. 32833:309-32833:312.

8510010064 Responds to FOIA request for correspondence NRC received from Barnes, Byron, Mathias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDR. Forwards documents listed on app.
FELTON, J.M. Division of Rules and Records. 85/09/04. DEZUBE, D. Montgomery County Sentinel. 3pp. 32831:087-32831:196.

-8406210273 Responds to 840524 ltr to Chairman Palladino re constituent LW Bussert concerns on licensing delays & impact on utils. Minimized delays key in NRC decision-making process.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/06/12. SARBANES, P.S. Senate. 4pp. 32831:117-32831:117.

-8510010143 Forwards correspondence received from JC Morris re concerns about investigations on restart of TMI-1. Review of matter & response requested.
SARBANES, P.S. Senate. 84/05/30. Office of Congressional Affairs. 2pp. 32831:118-32831:119.

-8510010157 Ack receipt of ltr on behalf of constituent, JC Morris, inquiry as to status of Commission decision on restart of TMI-1. On 840601, Commission issued encl order requesting parties comments on subj question by 840615. W/o encl.
KAMMERER, C. Office of Congressional Affairs. 84/06/04. SARBANES, P. Senate. 1p. 32831:120-32831:120.

-8510010210 Forwards correspondence received from J Merryman re serious concerns about delay of restart of TMI-1. Response requested.
SARBANES, P.S. Senate. 84/10/11. KAMMERER, C. Office of Congressional Affairs. 2pp. 32831:131-32831:132.

-8510010213 Ack receipt of inquiry on behalf of J Merryman re status of restart proceeding. Commission will undertake & complete review of ALAB-772. Forwards Commission 840911 orders & Commissioner Asseltine dissenting views. W/o encl.
KAMMERER, C. Office of Congressional Affairs. 84/10/18. SARBANES, P.S. Senate. 1p. 32831:133-32831:133.

-8510010344 Forwards correspondence received from CF Jones re concerns about restart of TMI-1. Response requested.
SARBANES, P.S. Senate. 85/03/25. PALLADINO, N.J. Commissioners. 2pp. 32831:180-32831:181.

-8510010362 Ack receipt of ltr re status of NRC deliberations on whether to lift immediate effectiveness of orders directing that TMI-1 remain shut down pending further order of Commission. No date set for public meeting.
KAMMERER, C. Office of Congressional Affairs. 85/04/17. SARBANES, P.S. Senate. 1p. 32831:182-32831:182.

8510020371 Resume of AN Fasano.
FASANO, A.N. TMI Program Office. 85/09/27. 12pp. 32983:067-32983:078.

8510030056 Discusses proposal to Commonwealth of PA Dept of Environ Resources to use preoperational chemical cleaning basins as disposal facility for site-generated filter cake Phase I & II submittals encl.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/27. STOLZ, J.F. Operating Reactors Branch 4. 100pp. 32844-342-32845-079.

8510040445 Forwards application for amend to License DPR-50, consisting of Rev 1 to Change Request 143, revising Tech Specs re operability conditions for CRD trip breakers & diverse trip devices. Fee paid.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/30. STOLZ, J.F. Operating Reactors Branch 4. 1p. 32853-345-32853-355.

8510040448 Application for amend to License DPR-50, consisting of Rev 1 to Change Request 143, revising Tech Specs re operability conditions for CRD trip breakers & diverse trip devices.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/30. 4pp. 32853-346-32853-349.

8510040450 Proposed Tech Specs re operability conditions for CRD trip breakers & diverse trip devices.
* General Public Utilities Corp. - GPU Service Corp. 85/09/30. 6pp. 32853-350-32853-355.

8510070210 Suppl 1 to 850528 application to amend License DPR-50, consisting of Tech Spec Change Request 144, revising Figure 6-2 re organizational chart. Rev adds box labeled "Plant Engineering Managers TMI-1."
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/30. STOLZ, J.F. Operating Reactors Branch 4. 1p. 32878-086-32878-087.

8510070218 Revised proposed Tech Specs re Figure 6-2 concerning organizational chart.
* General Public Utilities Corp. - GPU Service Corp. 85/09/30. 1p. 32878-087-32878-087.

8510090315 Ack receipt of 841017 response to Generic Ltr 84-15 re reduction of diesel generator fast starts. Response acceptable. No further action required.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/30. HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 4pp. 32950-078-32950-081.

8510070263 Submits verification results for serial numbers on each IRVSP capsule in Lynchburg Research Ctr storage pool. Per Rev 2 to BAW-1543.
TAYLOR, J.H. Babcock & Wilcox Co. 85/10/01. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 32877-312-32877-313.

8510070426 Application for amend to License DPR-50, consisting of Tech Spec Change Request 104, Rev 3, replacing current reactor vessel matl surveillance requirements w/ BAW-1543, "Integrated Reactor Vessel Matl Surveillance Program."
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/02. STOLZ, J.F. Operating Reactors Branch 4. 4pp. 32878-331-32878-338.

8510070432 Proposed Tech Spec Change Request 104, Rev 3, replacing current reactor vessel matl surveillance requirements w/ BAW-1543, "Integrated Reactor Vessel Matl Surveillance Program."
* General Public Utilities Corp. - GPU Service Corp. 85/10/02. 4pp. 32878-335-32878-338.

8510080212 Ack receipt of NRC 851002 ltr authorizing operation of TMI-1. Startup will proceed in accordance w/ approved power ascension schedule.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32918-352-32918-352.

8510090334 Informs that Commission Order CLI-85-9, dtd 850329, lift suspension upheld on appeal by US Court of Appeals. Facility authorized to operate subj to compliance w/ encl list of conditions imposed during restart proceeding.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/02. HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 11pp. 32950-190-32950-200.

8510110066 Forwards Rev 1 to "GPU Nuclear Corp Operational QA Plan for TMI-1 & Oyster Creek." Exception to Reg Guide 1.37 re permissible particle sizes added for consistency w/ requirements of ANSI N45.2.1-1980.
LONG, R.L. General Public Utilities Corp. - GPU Service Corp. 85/10/02. MURLEY, T.E. Region 1, Office of Director. 10pp. 32969-033-32969-042.

8510110072 Rev 1 to 1000-PLN-7200.01, "GPU Nuclear Corp Operational QA Plan for TMI-1 & Oyster Creek."
KAZANAS, N.C., HUKILL, H.D., FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 85/07/19. 141pp. 32969-043-32969-199.

8510080078 Forwards projected milestones remaining for Singer Link replica simulator project, indicating delivery by Aug 1986. Initial simulator training lesson plans will be developed by delivery date.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/03. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32919-360-32919-361.

8510150398 Forwards plans & schedules re Generic Ltr 83-28, "Vendor Interface." NUTAC vendor equipment technical info program will be implemented for safety-related components.
WILSON, R.F. General Public Utilities Corp. - GPU Service Corp. 85/10/04. STOLZ, J.F. Operating Reactors Branch 4. 4pp. 33000-320-33000-323.

8510160080 Forwards schedule for meeting requirements of 10CFR 50.62(c)(1) & (c)(2) re ATWS events for light water cooled nuclear power plants.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33028-004-33028-005.

8510150376 Advises that submittal of Rev 1 to TSCR 143 completes response to Generic Ltr 85-10, requiring rev to Tech Specs to address Generic Ltr 83-28, Items 4.3 & 4.4 re shunt & undervoltage trip attachments.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/09. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33006-357-33006-357.

8510180442 Further response to FOIA request for documents re TMI. Forwards App H documents App H & I documents available in PDR. Apps J & K documents withheld partially or in entirety (ref FOIA Exemptions 5 & 7).
FELTON, J.M. Division of Rules and Records. 85/10/09. BERNABELL, Government Accountability Project. 7pp. 33077-156-33077-190.

8510180500 "Summary of Order Before Commission for Affirmation (SECY-84-475A)." * NRC - No Detailed Affiliation Given. 85/02/14. 2pp. 33077-187-33077-188.

8510280378 Requests exemption from local leak rate testing schedule requirements in order to prevent forced outage to perform tests planned for Mar 1986 eddy current outage, due to delays in facility operating schedule. Fee paid.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33192-144-33192-148.

8510290088 Discusses delay in mod schedule for fuel handling bldg crane interlocks. Delay due to vol of restart work. Mod completion rescheduled for Dec 1985.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/24. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33236-016-33236-018.

8510290160 Forwards application for amend to License DPR-50, consisting of Tech Spec Change Request 141, clarifying conditions which allow feedwater pump & main turbine trip defeat during physics tests. Fee paid.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/24. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33236-192-33236-197.

8510290175 Application for amend to License DPR-50, consisting of Tech Spec Change Request 141, clarifying conditions which allow feedwater pump & main turbine trip defeat during physics tests. Fee paid.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/24. 3pp. 33236-194-33236-196.

8510290182 Proposed Tech Spec change, clarifying conditions which allow feedwater pump & main turbine trip defeat during physics tests.
* General Public Utilities Corp. - GPU Service Corp. 85/10/24. 1p. 33236-197-33236-197.

8510310445 Summary of 851009 meeting w/ util & impell in Middletown, PA re detailed design review of auxiliary feedwater sys automatic initiation circuitry to be installed during Cycle 6 refueling outage. Attendee list encl.
THOMAS, J. Operating Reactors Branch 4. 85/10/24. Operating Reactors Branch 4. 5pp. 33278-226-33278-230.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

8510230065 Forwards Press Release 84-26 re NRC proposed fine against util for 12 alleged violations of Tech Specs while performing work at facility.
KAMMERER, C. Office of Congressional Affairs. 84/02/29. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33108-332-33108-334.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF, R.A. Parametric, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Genic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510250180 Forwards Safety Insp Rept 50-289/85-21 on 850802-0916 & notice of violation. Discusses operationally significant 850821 & 0907 events.
KANE, W.F. Region 1, Office of Director. 85/10/15. HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 5pp. 33190-207-33190-245.

8510250186 Notice of violation from insp on 850802-0916. Portions deleted (ref 10CFR 2.790(a)).
* Region 1, Office of Director. 85/10/15. 1p. 33190-212-33190-212.

8510250193 Safety Insp Rept 50-289/85-21 on 850802-0916. Violations noted: failure to conduct complete search of escorted individual. Portions deleted (ref 10CFR 2.790(a)).
CONTE, R. Region 1, Office of Director. 85/10/14. 33pp. 33190-213-33190-245.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

72 DOCKETED ITEMS

8510250322 Ack receipt of util 850415 ltr responding to 830722 notice of violation & proposed imposition of civil penalty. Characterization of violation in Item A re JR Floyd certification of 830722 notice as willful is correct.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/21. CLARK, P.R. General Public Utilities Corp. - GPU Service Corp. 3pp. 33226:128-33226:130.

R. Periodic operating reports & related correspondence

8510310596 Monthly operating rept for Sept 1985 W/851015 ltr.
SMYTH, C.W., HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/30. McDONALD, W.C. Record Services Branch (Document Control Desk) 5pp. 33279:349-33279:354.

S. Reportable occurrences, LERs & related correspondence

8510070371 RO on 850821, make-up auto power failure resulted in partial loss of instrumentation & control sys/non-nuclear instrumentation power. Caused by shortage due to worn insulation on coiled connector cable. Cable replaced.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/09/18. MURLEY, T.E. Region 1, Office of Director. 4pp. 32883:298-32883:301.

8510010062 PNO-I-85-067 on 850923, malfunction of one reactor protection sys ac breaker caused small electrical fire. Operator deenergized breaker from feeder bus & fire extinguished. Spare breaker installed.
CONTER, R., KANE, W. Region 1, Office of Director. 85/09/24. 1p. 32800:064-32800:064.

8510090457 LER 85-002-00 on 850907, reactor manually tripped due to fire in CRD transfer switch. Caused by failure of relay K171 which shorted Groups 5 & 6 rod select contacts. Failed components replaced W/851003 ltr.
HASSLER, D.V., HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/03. 5pp. 32946:094-32946:098.

8510250226 Documents commitments to remedy problems resulting in lifting emergency feedwater pump EF-P1 turbine main steam inlet relief valves MS-V22A/B during automatic starting of EF-P1 as part of Startup Test Procedure TP 700/2.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 85/10/11. MURLEY, T.E. Region 1, Office of Director. 2pp. 33169:075-33169:076.

8510210098 PNO-I-85-079 on 851016, steam leak identified on drain line from associated main turbine control valve header. Caused by through-wall crack in weld associated w/pipe elbow. Power reduced from 40% to make repairs.
STROSNIDER, J. Region 1, Office of Director. 85/10/16. 1p. 33072:279-33072:279.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:268.

-8510230065 Forwards Press Release 84-26 re NRC proposed fine against util for 12 alleged violations of Tech Specs while performing work at facility.
KAMMERER, C. Office of Congressional Affairs. 84/02/29. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33108:332-33108:334.

V. Operator Examinations

8510010064 Responds to FOIA request for correspondence NRC received from Barnes, Byron, Mathias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDR. Forwards documents listed on app.
FELTON, J.M. Division of Rules and Records. 85/09/04. DEZUBE, D. Montgomery County Sentinel. 3pp. 32831:087-32831:116.

-8510010362 Ack receipt of ltr re status of NRC deliberations on whether to lift immediate effectiveness of orders directing that TMI-1 remain shut down pending further order of Commission. No date set for public meeting.
KAMMERER, C. Office of Congressional Affairs. 85/04/17. SARBANES, P.S. Senate. 1p. 32831:182-32831:182.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510020192 Ack receipt of 850815 ltr informing NRC of steps taken to correct violations & deviations noted in Insp Rept 50-293/85-13. Rept clarified util use of procedural steps as health physics.
MARTIN, T.T. Region 1, Office of Director. 85/09/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827:273-32827:278.

8510020242 Forwards Safety Insp Rept 50-293/85-20 on 850716-0819 & notice of violation.
WENZINGER, E.C. Region 1, Office of Director. 85/09/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827:001-32827:018.

-8510020260 Insp Rept 50-293/85-20 on 850716-0819. Violation noted: failure to maintain trip level settings for two main steam line high radiation monitors consistent w/ Tech Spec limits.
MCBRIDE, M., MEYER, G., CASELLA, F. Region 1, Office of Director. 85/09/12. 15pp. 32827:004-32827:018.

8510020238 Forwards Enforcement Conference Rept 50-293/85-25 on 850827 discussing Special Inps 50-293/85-21 & 50-293/85-24. Meeting included identification of degraded vital area barrier & lack of timely corrective actions.
STAROSTECKI, R. Region 1, Office of Director. 85/09/18. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827:187-32827:192.

-8510020244 Enforcement Conference Rept 50-293/85-25 on 850827 re findings of Special Inps 50-293/85-21 & 50-293/85-24, including concerns of timely corrective action for abnormal surveillance test findings & degraded vital area barrier.
MCBRIDE, M., SMITH, G., TRIPP, L. Region 1, Office of Director. 85/09/12. 4pp. 32827:189-32827:192.

8510110149 Provides info to close remaining open issues re NUREG-0737, Item ID.2 concerning SPDS. Complete list of radiation monitors which will be used in SPDS for monitoring radioactivity control safety provided.
HARRINGTON, W.D. Boston Edison Co. 85/10/07. VASSALLO, D.B. Operating Reactors Branch 2. 4pp. 32972:127-32972:130.

8510220277 Forwards Safety Insp Rept 50-293/85-26 on 850820-0923 & notice of violation.
WENZINGER, E.C. Region 1, Office of Director. 85/10/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 33085:136-33085:156.

-8510220284 Insp Rept 50-293/85-26 on 850820-0923. Violation noted: failure to take corrective action to ensure that reactor operator overtime properly authorized.
MCBRIDE, M., TRIPP, L. Region 1, Office of Director. 85/10/10. 18pp. 33085:139-33085:156.

8510230109 Forwards Safety Insp Rept 50-293/85-19 on 850904-06. No violation noted. Concern expressed re lack of evaluation & control of radiation exposures to in-plant personnel involved in simulated emergency.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. HARRINGTON, W.D. Boston Edison Co. 2pp. 33102:219-33102:225.

-8510230113 Insp Rept 50-293/85-19 on 850904-06. No violation noted. Major areas inspected: 850905 annual full participation exercise. Concerns identified re evaluation of radiation exposure to reentry teams.
LAZARUS, W., HARPSTER, T. Region 1, Office of Director. 85/10/11. 5pp. 33102:221-33102:225.

G. Adjudicatory correspondence

8510210007 Advises that time for Commission to review ALAB-816 expired. Commission declined review. Decision became final agency action on 851015. Served on 851018.
CHILK, S.J. Office of the Secretary of the Commission. #485 836. 85/10/18. Atomic Safety and Licensing Board Panel. 1p. 33072:021-33072:021.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510080201 Forwards eight pages inadvertently omitted from 850719 Rev 5 to updated FSAR, including QA program description.
HARRINGTON, W.D. Boston Edison Co. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32921:031-32921:040.

-8510080215 Eight pages inadvertently omitted from 850719 Rev 5 to updated FSAR, including QA program description.
* Boston Edison Co. 85/10/08. 9pp. 32921:032-32921:040.

P. Operating license stage documents & correspondence

8510030288 Advises that revised procedure for estimating core damage, submitted w/ 850908 ltr reviewed & meets Criterion 2 of NUREG-0737, Item II.B.3.
VASSALLO, D.B. Operating Reactors Branch 2. 85/09/30. HARRINGTON, W.D. Boston Edison Co. 3pp. 32849:081-32849:083.

8510010112 Corrects undated ltr re annual update to FSAR. Date should be 851004.
HARRINGTON, W.D. Boston Edison Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32960:104-32960:104.

8510150100 Informs of organizational changes affecting Tech Spec Figures 6.2.1 & 6.2.2. Application for amend will be submitted after final organizational change complete.
HARRINGTON, W.D. Boston Edison Co. 85/10/07. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 33010:347-33010:348.

8510150181 Provides schedule to implement requirements of final ATWS rule (10CFR50.62).
HARRINGTON, W.D. Boston Edison Co. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33012:360-33012:361.

8510150326 Requests plans & schedule for NRC approved mods for NUREG-0737, Item II.K.3.18 re automatic depressurization sys logic as specified in 830603 ltr.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. HARRINGTON, W.D. Boston Edison Co. 2pp. 33033:238-33033:239.

8510170249 Forwards Amend 90 to License DPR-35 & safety evaluation. Amend revises Tech Specs by changing reactor low water level trip requirement to 307 inches above vessel zero.
LEECH, P.H. Operating Reactors Branch 2. 85/10/09. HARRINGTON, W.D. Boston Edison Co. 2pp. 33045:055-33045:062.

-8510170253 Amend 90 to License DPR-35, revising Tech Specs to change reactor low water level trip requirement to 307 inches above vessel zero.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/09. 4pp. 33045:057-33045:060.

-8510170255 Safety evaluation supporting Amend 90 to License DPR-35.
* Office of Nuclear Reactor Regulation, Director. 85/10/09. 2pp. 33045:061-33045:062.

8510180026 Responds to 850618,0725 & 0807 requests for addl info re Generic Ltr 84-09 concerning 10CFR50.44(c)(3) requirements & supls 850521 commitments. Svc air connecting valve, re-wrapped & added to Procedure 8.C.13 on 850626. HARRINGTON, W.D. Boston Edison Co. 85/10/11. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33054.004-33054.006.

8510310240 Forwards Rev 2 to TR-6121-4, "Fluid Analysis To Determine if Standby Gas Treatment Sys Purge... Overpressurized During DBA LOCA," technical rept, per 850629 request for addl info. Supporting calculations also encl. HARRINGTON, W.D. Boston Edison Co. 85/10/23. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33271.180-33271.255.

-8510310244 Rev 2 to "Fluid Analysis To Determine if Standby Gas Treatment Sys Purge & Vent Line Duct Work Overpressurized During DBA LOCA," technical rept. * Teledyne Engineering Services. TR-6121-4 R02. 85/10/31. 73pp. 33271.183-33271.255.

8510310450 Forwards Rev 1A to "Inservice Testing Program for Pumps & Valves, Pilgrim Nuclear Power Station," in response to request for addl info. Util disposition of open items also encl. W/21 oversize drawings. HARRINGTON, W.D. Boston Edison Co. 85/10/24. VASSALLO, D.B. Operating Reactors Branch 2. 14pp. 33293.001-33293.133.

-8510310453 Rev 1A to "Inservice Testing Program for Pumps & Valves, Pilgrim Nuclear Power Station." * Boston Edison Co. 85/10/24. 150pp. 33293.015-33293.133.

Q. Inspection reports, IE Bulletins & correspondence

8510020192 Ack receipt of 850815 ltr informing NRC of steps taken to correct violations & deviations noted in Insp Rept 50-293/85-13. Rept clarified util use of procedural steps as health physics. MARTIN, T.T. Region 1, Office of Director. 85/09/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827.273-32827.278.

8510020242 Forwards Safety Insp Rept 50-293/85-20 on 850716-0819 & notice of violation. WENZINGER, E.C. Region 1, Office of Director. 85/09/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827.001-32827.018.

-8510020249 Notice of violation from insp on 850716-0819. * Region 1, Office of Director. 85/09/17. 1p. 32827.003-32827.003.

-8510020260 Insp Rept 50-293/85-20 on 850716-0819. Violation noted: failure to maintain trip level settings for two main steam line high radiation monitors consistent w/ Tech Spec limits. MCBRIDE, M., MEYER, G., CASELLA, F. Region 1, Office of Director. 85/09/12. 15pp. 32827.004-32827.018.

8510020238 Forwards Enforcement Conference Rept 50-293/85-25 on 850827 discussing Special Insp 50-293/85-21 & 50-293/85-24. Meeting included identification of degraded vital area barrier & lack of timely corrective actions. STAROSTECKI, R. Region 1, Office of Director. 85/09/18. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827.187-32827.192.

-8510020244 Enforcement Conference Rept 50-293/85-25 on 850827 re findings of Special Insp 50-293/85-21 & 50-293/85-24, including concerns of timely corrective action for abnormal surveillance test findings & degraded vital area barrier. MCBRIDE, M., SMITH, G., TRIPP, L. Region 1, Office of Director. 85/09/12. 4pp. 32827.189-32827.192.

8510030260 Discusses Insp Rept 50-293/85-21 on 850716-30 & forwards notice of violation. Violation re failure to take action to maintain secondary containment integrity classified as Severity Level IV. STAROSTECKI, R. Region 1, Office of Director. 85/09/20. HARRINGTON, W.D. Boston Edison Co. 3pp. 32845.312-32845.316.

-8510030261 Notice of violation from insp on 850716-30. Violation noted: Diesel Generator A inoperable due to water & sediment content in fuel tank & remaining generator low pressure core & containment cooling subsystem not tested until 850726. * Region 1, Office of Director. 85/09/20. 2pp. 32845.315-32845.316.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33108.088.

-8510230134 Forwards Press Release 84-50 re NRC proposed fine against util for failure to implement adequate radiological controls during maint. KAMMERER, C. Office of Congressional Affairs. 84/04/18. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108.359-33108.361.

8510110040 Forwards Radiological Safety Insp Rept 50-293/85-22 on 850819-23. No violations noted. Addl mgt attention warranted for review of radiological controls preparation & planning for upcoming fuel pool work. MARTIN, T.T. Region 1, Office of Director. 85/10/07. HARRINGTON, W.D. Boston Edison Co. 2pp. 32973.194-32973.220.

-8510110047 Insp Rept 50-293/85-22 on 850819-23. No violation noted. Major areas inspected: implementation of radiological improvement program commitments, previously identified items & review of unmonitored releases. NIMTZ, R.L., PASCIAK, W. Region 1, Office of Director. 85/10/02. 25pp. 32973.196-32973.220.

8510180264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023.351-33023.354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510240406 EN-85-072 on 851021, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to util. Action based on multiple examples of openings in vital area barrier. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/16. 1p. 33154.198-33154.198.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510220277 Forwards Safety Insp Rept 50-293/85-26 on 850820-0923 & notice of violation. WENZINGER, E.C. Region 1, Office of Director. 85/10/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 33085.136-33085.156.

-8510220281 Notice of violation from insp on 850820-0923. * Region 1, Office of Director. 85/10/17. 1p. 33085.138-33085.138.

-8510220284 Insp Rept 50-293/85-26 on 850820-0923. Violation noted: failure to take corrective action to ensure that reactor operator overtime properly authorized. MCBRIDE, M., TRIPP, L. Region 1, Office of Director. 85/10/10. 18pp. 33085.139-33085.156.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510230109 Forwards Safety Insp Rept 50-293/85-19 on 850904-06. No violation noted. Concern expressed re lack of evaluation & control of radiation exposures to in-plant personnel involved in simulated emergency. MARTIN, T.T. Region 1, Office of Director. 85/10/18. HARRINGTON, W.D. Boston Edison Co. 2pp. 33102.219-33102.225.

-8510230113 Insp Rept 50-293/85-19 on 850904-06. No violation noted. Major areas inspected: 850905 annual full participation exercise. Concerns identified re evaluation of radiation exposure to reentry teams. LAZARUS, W., HARPSTER, T. Region 1, Office of Director. 85/10/11. 5pp. 33102.221-33102.225.

8510250260 Forwards Safety Insp Rept 50-293/85-29 on 850928-1002. No violation noted. EBNETER, S.D. Region 1, Office of Director. 85/10/13. HARRINGTON, W.D. Boston Edison Co. 2pp. 33170.342-33170.359.

-8510250273 Insp Rept 50-293/85-29 on 850928-1002. No violation noted. Major areas inspected: licensee activities re movement of spent fuel within spent fuel pool & condition of refueling equipment. BRIGGS, L., SMITH, G., JOHNSON, J. Region 1, Office of Director. 85/10/17. 16pp. 33170.344-33170.359.

R. Periodic operating reports & related correspondence

8510180523 Monthly operating rept for Sept 1985. W/851011 ltr. HAMILTON, P., HARRINGTON, W.D. Boston Edison Co. 85/09/30. 8pp. 33068.001-33068.008.

8510300004 Forwards "Radiological Improvement Plan Implementation Progress Rept" for Third Quarter 1985, contained in EH Deacon 851016 memo. HARRINGTON, W.D. Boston Edison Co. 85/10/17. MURLEY, T.E. Region 1, Office of Director. 17pp. 33256.287-33256.303.

S. Reportable occurrences, LERs & related correspondence

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available. ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905.053-32905.157.

-8510070192 Provides daily staff notes for 850611. Final rule amending 10CFR9 approved. Events at facilities discussed. DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/12. PALLADINO Commissioners. 21pp. 32911.022-32911.081.

8510020208 LER 85-024-00 on 850602, surveillance test of station 250-volt batteries missed. Caused by procedural deficiency. Procedure revised & batteries retested. W/850925 ltr. HAMILTON, P.J., HARRINGTON, W.D. Boston Edison Co. 85/09/25. 2pp. 32827.207-32827.208.

8510020209 LER 85-023-00 on 850827, HPCI turbine control valve failed to operate properly. Caused by leaking nipple due to personnel inadvertently stepping on oil supply line to HPCI hydraulic control valve. Nipple repaired. W/850925 ltr. BELMONT, G., HARRINGTON, W.D. Boston Edison Co. 85/09/25. 3pp. 32827.209-32827.211.

8510020274 PNO-85-071A on 850927, Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage. STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825.232-32825.232.

74 DOCKETED ITEMS

8510020383 PNS-I-85-013a on 850927, bent mast on refueling bridge over spent fuel pool discovered. Cause unknown. No fuel damage apparent. Licensee conducting tests & insp to assure operability.
TRIPP, L., JOYNER, J. Region 1, Office of Director. 85/09/27. 2pp. 32624-340-32924-341.

8510070029 LER 85-026-00 on 850830, during QA audit of operations, failure to perform instrument check of 28-volt control rod position indicating lights indicated. Caused by inadequate surveillance procedure. Procedure modified W/850927 ltr.
BELMONT, G., HARRINGTON, W.D. Boston Edison Co. 85/09/27. 3pp. 32900-024-32900-026.

8510070034 LER 85-025-00 on 850901, reactor scram occurred when insulator in switchyard arced to ground & disintegrated. Caused by salt buildup resulting from storm. Insulator replaced & washdown procedures reviewed W/850927 ltr.
HAMILTON, P.J., HARRINGTON, W.D. Boston Edison Co. 85/09/27. 3pp. 32900-027-32900-029.

8510080183 PNS-I-85-013a on 850928, insp team conducted review on licensee investigative/followup actions & independent evaluation to determine probable cause of damaged spent fuel handling equipment. No evidence of attempted sabotage.
TRIPP, L., KEIMIG, R. Region 1, Office of Director. 85/10/03. 2pp. 32921-063-32921-064.

8510250232 LER 85-027-00 on 850919, LPCI injection valve would not open during testing. Caused by failed motor in valve motor operator. Motor replaced W/851018 ltr.
HAMILTON, P., HARRINGTON, W.D. Boston Edison Co. 85/10/18. 3pp. 33190-170-33190-172.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-085.

-8510230134 Forwards Press Release 84-50 re NRC proposed fine against util for failure to implement adequate radiological controls during maint.
KAMMERER, C. Office of Congressional Affairs. 84/04/18. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33108-359-33108-361.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510160248 Forwards Mgt Meeting Repts 50-295/35-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026-219-33026-222.

-8510160277 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026-221-33026-222.

8510160256 Ack receipt of 850924 ltr re annual meeting w/offsite response agencies. Requests to be informed of dates for plant annual emergency preparedness training to offsite organizations.
SHAFFER, W.D. Region 3, Office of Director. 85/10/09. NYKIEL, A. Commonwealth Edison Co. 1p. 33022-322-33022-324.

-8510160259 Extends invitation to visit plant on 851023 to discuss emergency plan. Radiological training or retraining will be offered to NRC personnel. Response requested by 851010.
PLIML, G.J. Commonwealth Edison Co. 85/09/24. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33022-323-33022-324.

8510280170 Forwards Rev 16 to security plan. Rev withheld (ref 10CFR73.21).
FARRAR, D.L. Commonwealth Edison Co. 85/10/21. KEPPLER, J.G. Region 3, Office of Director. 1p. 33191-002-33191-002.

8510310318 Advises that 851021 Rev 16 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
AXELSON, W.L. Region 3, Office of Director. 85/10/25. FARRAR, D.L. Commonwealth Edison Co. 2pp. 33272-084-33272-085.

J. Insurance & indemnity information

8510080148 Forwards Endorsements 75 & 76 to NEIA Policy NF-201 & Endorsements 63 & 64 to MAELU Policy MF-64.
OSTER, J. Commonwealth Edison Co. 85/09/23. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 32913-303-32913-307.

P. Operating license stage documents & correspondence

8510010155 Application for amends to Licenses DPR-39 & DPR-48 re proposed changes to specimen capsule withdrawal schedule. Forwards WCAP-10902, "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
LEBLOND, P.C. Commonwealth Edison Co. 85/09/13. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 32800-001-32800-063.

-8510010161 "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
ANDERSON, S.L., LAU, F.L. Westinghouse Electric Corp. WCAP-10902. 85/08/31. 55pp. 32800-010-32800-063.

8510070519 Notification of 851017 meeting w/Z Reytblatt w/ Glen Elynn, IL to discuss 850703 Emergency Relief Decision DD-85-10.
SHAPAKER, J.W. Containment Systems Branch. 85/09/30. KUDRICK, J. Containment Systems Branch. 2pp. 32901-038-32901-039.

8510310542 Notifies that Tech Spec Page 217a should be deleted from 850827 Amend 9G to License DPR-39 & Amend 80 to License DPR-48, per 850910 request.
NORRIS, J.A. Operating Reactors Branch 1. 85/09/30. FARRAR, D.L. Commonwealth Edison Co. 2pp. 33277-041-33277-042.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

8510310561 Forwards safety evaluation of 851105 response to Generic Ltr 83-28. Post-trip review data & info capabilities re item 1.2 do not meet guidelines. Response to recommendations requested.
VARGA, S.A. Operating Reactors Branch 1. 85/10/03. FARRAR, D.L. Commonwealth Edison Co. 12pp. 33277-054-33277-066.

-8510310573 Safety evaluation re review of util response to Generic Ltr 83-28. Post-trip review data & info capabilities re item 1.2 may be inadequate for diagnosing causes of unscheduled reactor shutdowns & for evaluating safety-related equipment.
* Office of Nuclear Reactor Regulation, Director. 85/10/03. 11pp. 33277-056-33277-066.

8510220304 Revised application for amends to Licenses DPR-39 & DPR-48, changing Tech Spec Section 1.0, "Definitions," for inclusion in 850625 proposed amend.
LEBLOND, P.C. Commonwealth Edison Co. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33084-017-33084-041.

-8510220308 Proposed Tech Spec changes to Section 1.0, "Definitions," for inclusion in 850625 submittal.
* Commonwealth Edison Co. 85/10/07. 23pp. 33084-019-33084-041.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

8510310595 Forwards safety evaluation identifying concerns re NUREG-0737, item II.F.2 on final inadequate core cooling instrumentation sys. per util 840824 & 850305 responses to 840530 ltr. Further clarification required.
VARGA, S.A. Operating Reactors Branch 1. 85/10/17. FARRAR, D.L. Commonwealth Edison Co. 9pp. 33277-083-33277-091.

8510290081 Informs that State of IL Dept of Nuclear Safety reviewed proposed Tech Spec amend involving radiological effluent Tech Spec Section 1.0 re definitions. No adverse findings noted.
PARKER, M.C. Illinois, State of. 85/10/22. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 33236-036-33236-036.

Q. Inspection reports, IE Bulletins & correspondence

8510090156 Forwards Safety Insp Repts 50-295/85-30 & 50-304/85-31 on 850820-23 & 27-29 & notice of violation.
SHAFFER, W.D. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32946-175-32946-185.

-8510090161 Notice of violation from insp on 850820-23 & 27-28.
SHAFFER, W.D. Region 1, Office of Director. 85/09/27. 1p. 32946-177-32946-185.

-8510090171 Insp Repts 50-295/85-30 & 50-304/85-31 on 850820-23 & 27-28. Violation noted: failure to implement written Procedure ZCP 531-7, "Performance Test for Eberline Model SAC-4 Scintillation Alpha Counter."
JANUSKA, A.G., SCHUMACHER, M.C. Region 3, Office of Director. 85/09/27. 8pp. 32946-178-32946-185.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026-219-33026-222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A., KERS, L.L., SMITH, M.J. Region 3, Office of Director. 85/10/04. 2pp. 33026-221-33026-222.

8510220414 Forwards Safety Insp Repts 50-295/85-34 & 50-304/85-36 on 850917-19 & 26 & notice of violation.
SHAFFER, W.D. Region 3, Office of Director. 85/10/08. REED, C. Commonwealth Edison Co. 2pp. 33097-057-33097-068.

-8510220417 Notice of violation from insp on 850917-19 & 26.
SHAFFER, W.D. Region 3, Office of Director. 85/10/08. 1p. 33097-059-33097-059.

-8510220420 Insp Repts 50-295/85-34 & 50-304/85-36 on 850917-19 & 26. Violation noted: failure to make required rept when 7 Ci released from site via liquid radwaste during Third Quarter 1984.
NICHOLSON, N.A., LOVENDALE, P.C., GREGER, L.R. Region 3, Office of Director. 85/10/08. 9pp. 33097-060-33097-068.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-06 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510160272 Forwards Safety Insp Repts 50-295/85-33 & 50-304/85-34 on 850913-30. No violations or deviations noted.
REYES, L.A. Region 3, Office of Director. 85/10/10. REED, C. Commonwealth Edison Co. 2pp. 33024-339-33024-346.

-8510160274 Insp Repts 50-295/85-33 & 50-304/85-34 on 850913-30. No violations or deviations noted. Major areas inspected: Unit 2 containment integrated leak rate test (CILRT), Unit 1 CILRT rept & resolution of Unit 1 violations & open items.
MAURA, F., GULDEMOND, W.G. Region 3, Office of Director. 85/10/09. 6pp. 33024-341-33024-346.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510310262 Forwards Safety Insp Repts 50-295/85-32 & 50-304/85-33 on 850918-20, 23-26, 30 & 1001-03. No violations noted.
REYES, L.A. Region 3, Office of Director. 85/10/25. REED, C. Commonwealth Edison Co. 2pp. 33274-033-33274-042.

-8510310265 Insp Repts 50-295/85-32 & 50-304/85-33 on 850918-20, 23-26, 30 & 1001-03. No violations or deviations noted. Major areas inspected: QA program implementation, QA/QC administration & calibr activities.
SUTPHIN, R.N., HAWKINS, P. Region 3, Office of Director. 85/10/25. 8pp. 33274-035-33274-042.

R. Periodic operating reports & related correspondence

8510100101 Monthly operating rpts for Sept 1985 W/851004 ltr.
AUSTIN, G., PLIML, G.J. Commonwealth Edison Co. 85/09/30. 12pp. 32960-332-32960-343.

S. Reportable occurrences, LERs & related correspondence

8510210069 PNO-III-85-087 on 851007, concrete finisher killed after falling 45 ft while working on interim radwaste storage facility. No contamination involved.
HEHL, W., CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/08. 1p. 33072-285-33072-285.

8510150499 LER 85-032-00 on 850909, while performing Periodic Test PT-10, "Safetyguards Actuation Unit 1," six containment isolation Phase A valves inadvertently stroked closed. Caused by improper test component reset W/851009 ltr.
ROHDE, J.E., PLIML, G.J. Commonwealth Edison Co. 85/10/09. 4pp. 33015-136-33015-139.

8510180522 LER 85-033-00 on 850913, manual quadrant power tilt ratio (QPTR) calculations not performed w/QPTR alarm inoperable. Caused by personnel error. Channel returned to normal Shift meetings held W/851011 ltr.
BLESS, A., PLIML, G.J. Commonwealth Edison Co. 85/10/11. 4pp. 33067-357-33067-360.

8510240057 LER 85-034-00 on 850920, temporary procedure change written for hydro-test of s/w water piping to & from containment fan coolers not reviewed onsite within 14 days of initiation. Appropriate signatures obtained W/851018 ltr.
BERCZYNSKI, S., PLIML, G.J. Commonwealth Edison Co. 85/10/18. 3pp. 33156-255-33156-257.

V. Operator Examinations

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510030083 Forwards SER supporting 830807 rept, "Re-qualification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1 Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510010087 Requests that review of 841031 10CFR50, App R submittal be terminated due to reduction of scope of cable routing mods. New 10CFR50, App R will be submitted by 860115.
DOMER, J.A. Tennessee Valley Authority. 85/09/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800-198-32800-199.

8510070335 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized.
DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 32678-194-32678-207.

8510030061 Rev 27 to radiological emergency plan W/850930 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/26. GRACE, J.N. Region 2, Office of Director. 150pp. 32844-190-32844-328.

8510210260 Advises that review of Rev 25 to radiological emergency plan dtd 850729 completed. Plan continues to meet 10CFR50.47(b) planning stds & 10CFR50, App E requirements.
VERRELLI, D.M. Region 2, Office of Director. 85/10/04. PARRIS, H.G. Tennessee Valley Authority. 1p. 33094-339-33094-339.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

-8510230085 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33108-337-33108-338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. 2pp. 33109-052-33109-053.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. 2pp. 33109-124-33109-150.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. GRACE, J.N. Region 2, Office of Director. 14pp. 33010-272-33010-284.

8510160068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028-094-33028-096.

-8510160082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR2.790 & 73.21).
TOBIN, W. Region 2, Office of Director. 85/10/07. 1p. 33028-096-33028-096.

8510160242 Revised radiological emergency plan implementing procedures, including BFN-IP-1 re emergency plan classification logic, BFN-IP-2 re notification of unusual event & BFN-IP-10 re medical emergency procedure W/851011 ltr.
MARKS, B.K., HUFHAM, J.W. Tennessee Valley Authority. 85/10/11. GRACE, J.N. Region 2, Office of Director. 51pp. 33022-357-33022-044.

I. Financial information

8510110269 Informs that financial info in 850830 ltr satisfies requirements of 10CFR140.21 that each licensee maintain guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e).
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. DOMER, J.A. Tennessee Valley Authority. 1p. 33011-186-33011-186.

P. Operating license stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr W/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510090472 Notification of postponement of 851002 meeting to 851010 w/util in Bethesda, MD to discuss integrated schedule for NRC-required mods.
CLARK, R.E. Operating Reactors Branch 2. 85/09/23. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 32966-199-32966-200.

76 DOCKETED ITEMS

- 8510030424** Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848.077-32848.081.
- 8510060442** Forwards first interim rpt summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906. It follows up rpt of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.
- 8510070336** Application for amends to Licenses DPR-33, DPR-52 & DPR-68, revising Tech Specs to correct inconsistencies & typos. Fee paid.
DOMER, J.A. Tennessee Valley Authority. 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32877.262-32877.297.
- 8510070340** Proposed Tech Specs, deleting Sections 6.9, "Environ Qualification," 6.10, "Integrity of Sys Outside Containment" & 6.11, "Iodine Monitoring" from table of contents.
* Tennessee Valley Authority. 85/10/01. 35pp. 32877.264-32877.297.
- 8510090340** Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed. NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949.162-32949.166.
- 8509030152** Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/ Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949.167-32949.167.
- 8510150328** Requests plans & schedule for NRC approved mods for NUREG-0737, Item II.K.3.18 re automatic depressurization sys logic, as specified in 830603 ltr.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033.240-33033.242.
- 8510150383** Forwards info in response to NRC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts.
WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001.001-33006.171.
- 8510160153** Submits schedule to meet requirements of 10CFR50.62(c)(1)-(c)(5) re reduction of risk from ATWS. Final implementation of mods to meet Paragraphs (c)(3) & (c)(4) scheduled for Unit 1 Cycle 7, Unit 2 Cycle 6 & Unit 3 Cycle 7 outages.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021.183-33021.185.
- 8510230024** Forwards addl info re plans for modifying plant to address Generic Ltr 84-23, "Reactor Vessel Water Level Instrumentation in BWRs." Util evaluating cost & feasibility of reducing vertical drops of ref legs inside drywell.
DOMER, J.A. Tennessee Valley Authority. 85/10/15. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33102.238-33102.240.
- 8510220185** Responds to 850711 request that Tech Spec amends requested prior to ltr contain provision that amend be effective within 90 days of date of issuance unless otherwise specified. Implementation will be on case-by-case basis.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/16. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33098.131-33098.132.
- 8510220374** Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085.157-33086.052.
- 8510230119** Notification of 851029 meeting w/util in Bethesda, MD to discuss TVA program to environmentally qualify cable.
CLARK, R.J. Operating Reactors Branch 2. 85/10/17. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 33108.022-33108.023.
- 8510280331** Forwards response to Quality Technology Co investigation rpt. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193.185-33193.237.
- Q. Inspection re: ors, IE Bulletins & correspondence**
- 8510010162** Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834.210-32834.349.
- 8510010246** SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834.229-32834.349.
- 8510030068** Forwards rev to 850821 response to violation noted in Insp Repts 50-259/85-25, 50-260/85-25 & 50-296/85-25. Plant Std Practice BF 14.25, "Clearance Procedure," rewritten.
SHELL, R.H. Tennessee Valley Authority. 85/09/18. GRACE, J.N. Region 2, Office of Director. 2pp. 32844.329-32844.330.
- 8510070335** Responds to NRC 850624 ltr re violations noted in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Corrective actions: misaligned high pressure fire header valve corrected & responsible personnel disciplined & penalized.
DOMER, J.A. Tennessee Valley Authority. 85/09/23. GRACE, J.N. Region 2, Office of Director. 14pp. 32878.194-32878.207.
- 8510070037** Forwards Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. No notice of violation issued since violations under consideration for escalated enforcement action pending further NRC review.
WALKER, R.D. Region 2, Office of Director. 85/09/24. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32900.030-32900.041.
- 8510070042** Insp Repts 50-259/85-41, 50-260/85-41 & 50-296/85-41 on 850812-16. Violations noted: inadequate design controls for safety-related cable tray supports & inadequate corrective actions for safety-related cable tray sys.
LIU, W.C., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 10pp. 32900.032-32900.041.
- 8510070486** Informs that ultrasonic training for response inspectors delayed until 851104. per 851118 telcon re 850819 response to violations noted in Insp Repts 50-259/85-33, 50-260/85-33 & 50-296/85-33.
DOMER, J.A. Tennessee Valley Authority. 85/09/25. GRACE, J.N. Region 2, Office of Director. 1p. 32878.136-32878.136.
- 8510103234** Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803.095-32803.125.
- 8510010378** Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803.099-32803.125.
- 8510180021** Responds to NRC 850807 ltr re violations noted in Insp Repts 50-259/85-36, 50-260/85-36 & 50-296/85-36. Corrective actions: RHR sys Operating Instruction (OI)-74 will be revised to fully incorporate steps to cross tie RHR loops.
SHELL, R.H. Tennessee Valley Authority. 85/09/27. GRACE, J.N. Region 2, Office of Director. 12pp. 33063.014-33063.025.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32860.001-32869.060.
- 8510180030** Notifies that Item 5.c of 851015 response to EA-84-82 (Insp Rept 84-20) re design criteria for electrical separation will not be completed until 851202 rather than 850930, due to difficulty & time necessary to assemble criteria.
SHELL, R.H. Tennessee Valley Authority. 85/09/30. GRACE, J.N. Region 2, Office of Director. 1p. 33054.009-33054.009.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510180069** Responds to NRC 850904 ltr re violations noted in Insp Repts 50-259/85-39, 50-260/85-39 & 50-296/85-39. Corrective actions: heaters tagged out & design change initiated for permanent removal of heaters from standby gas treatment sys.
DOMER, J.A. Tennessee Valley Authority. 85/10/03. GRACE, J.N. Region 2, Office of Director. 5pp. 33054.080-33054.084.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in FDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.254-33108.268.
- 8510230041** Forwards Press Release 85-99 re NRC proposed civil penalty in amount of \$150,000 against util for violation of requirements concerning reactor vessel water level instruments.
KAMMERER, C. Office of Congressional Affairs. 85/07/23. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109.025-33109.026.
- 8510230085** Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33108.337-33108.338.
- 8510230097** Forwards Press Release 85-0 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E.J. House of Rep., Energy & Commerce. FLIPPO House of Rep. 2pp. 33109.052-33109.053.
- 8510230197** Forwards Press Release 85-157 re NRC proposed civil penalty in amount of \$150,000 against util for alleged violation of requirements concerning improper startup procedures.
KAMMERER, C. Office of Congressional Affairs. 85/02/27. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109.087-33109.088.
- 8510230220** Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33109.094-33109.095.
- 8510230312** Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. HEFLIN Senate. FLIPPO House of Rep. 2pp. 33109.124-33109.150.
- 8510180367** Ack receipt of 850923 ltr informing NRC of steps taken to correct violations in Insp Repts 50-259/85-28, 50-260/85-28 & 50-296/85-28. Response under evaluation.
WALKER, R.D. Region 2, Office of Director. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 1p. 33068.283-33068.283.

8510160068 Forwards Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations or deviations noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/10. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33028.094-33028.096.

-8510160082 Safeguards Insp Repts 50-259/85-46, 50-260/85-46 & 50-296/85-46 on 850924-27. No violations noted. Major areas inspected: power supply & access controls. Details withheld (ref 10CFR 2.790 & 73.21).
TOBIN, W., MCGUIRE, D.R. Region 2, Office of Director. 85/10/07. 1p. 33028.096-33028.096.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023.351-33023.354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191.072-33191.073.

R. Periodic operating reports & related correspondence

8510010487 Monthly operating repts for Jul 1985 W/850814 ltr.
THOM, T., LEWIS, R.L. Tennessee Valley Authority. 85/07/31. 25pp. 32809.120-32809.144.

8510070553 "Discharge Monitoring Rept for Aug 1985."
* Tennessee Valley Authority. 85/08/31. 12pp. 32883.219-32883.230.

8510250293 Forwards revised "Discharge Monitoring Rept for Aug 1985." Original submission indicated min pH of 7.2 which is incorrect rounding off of true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/10/18. WARR, J.W., PIZNAR, T. Alabama, State of. 1p. 33189.350-33189.351.

-8510250440 Revised "Discharge Monitoring Rept for Aug 1985," correcting typo to reflect true min pH of 7.62.
RIVERS, M.E. Tennessee Valley Authority. 85/08/31. 1p. 33189.351-33189.351.

S. Reportable occurrences, LERs & related correspondence

8510040479 LER 85-009-00 on 850320 during investigation of motor noise, RHR pump motor 3D failed. Caused by failure of lower radial guide bearing resulting in failure of stator winding. On 850218, unrelated RHR pump motor also failed W/850926 ltr.
SMITH, D.L., LEWIS, R.L. Tennessee Valley Authority. 85/09/20. 3pp. 32865.240-32865.242.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants.
STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078.256-33078.361.

-8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078.260-33078.361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230041 Forwards Press Release 85-99 re NRC proposed civil penalty in amount of \$150,000 against util for violation of requirements concerning reactor vessel water level instruments.
KAMMERER, C. Office of Congressional Affairs. 85/07/23. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109.025-33109.026.

-8510230085 Forwards Press Release 84-28 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER, C. Office of Congressional Affairs. 84/03/07. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, House of Rep. DENTON, Senate. 2pp. 33108.337-33108.338.

-8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 85/05/17. MARKEY, E. House of Rep., Energy & Commerce. DENTON, HEFLIN, Senate. 2pp. 33109.052-33109.053.

-8510230197 Forwards Press Release 85-157 re NRC proposed civil penalty in amount of \$150,000 against util for alleged violation of requirement: concerning improper startup procedures.
KAMMERER, C. Office of Congressional Affairs. 85/02/27. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109.087-33109.088.

-8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, House of Rep. DENTON, Senate. 2pp. 33109.094-33109.095.

-8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan.
KAMMERER, C. Office of Congressional Affairs. 84/12/06. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, House of Rep. DENTON, Senate. 2pp. 33109.124-33109.150.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR

P. Operating license stage documents & correspondence

8510250312 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. North Carolina State Univ., Raleigh, NC. 3pp. 33226.145-33226.147.

8510220462 Responds to 850927 order to show cause re possession of highly enriched U onsite. Facility not licensed to possess highly enriched U as of 850909 amend to License R-120. Amend 9 encl.
POULTON, B.R. North Carolina State Univ., Raleigh, NC. 85/10/08. Office of the Secretary of the Commission. 1p. 33099.092-33099.099.

DOCKET 50-298 COOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

8510240247 Notifies that next annual emergency preparedness exercise scheduled for 851016. Further details re exercise will be forwarded in accordance w/nestones outlined in 840209 ltr.
PILANT, J.M. Nebraska Public Power District. 85/04/09. MARTIN, R.D. Region 4, Office of Director. 2pp. 33154.305-33154.306.

8510240331 Forwards objectives for 1985 emergency preparedness exercise scheduled for 851016. Objectives developed in conjunction w/status of NE & MO Joint agency meeting scheduled for 850820.
PILANT, J.M. Nebraska Public Power District. 85/08/01. MARTIN, R.D. Region 4, Office of Director. 12pp. 33151.339-33151.350.

8510240414 Forwards detailed description of exercise sequence of events & "Cooper Nuclear Station 1985 Annual Emergency Preparedness Exercise," per 840209 commitment. Comments requested by 850213 W/o detailed description.
PILANT, J.M. Nebraska Public Power District. 85/08/26. MARTIN, R.D. Region 4, Office of Director. 201pp. 33150.148-33151.015.

8510070244 Addresses App R mod schedule & interim compensatory measures. Majority of mods requiring plant shutdown scheduled to be completed during 1986 refueling outage. Fire doors w/rating less than 3 h will be installed.
PILANT, J.M. Nebraska Public Power District. 85/09/26. JOHNSON, E.H. Region 4, Office of Director. 2pp. 32878.082-32878.083.

8510080168 Forwards Rev 13 to physical security plan, incorporating restructuring of security organization. Rev withheld (ref 10CFR 73.21).
PILANT, J.M. Nebraska Public Power District. 85/09/26. MARTIN, R.D. Region 4, Office of Director. 1p. 32922.102-32922.102.

8510280012 Ack receipt & review of scenario for annual emergency preparedness exercise scheduled for Oct 1985. Addl info needed re channel numbers & controller instructions to ensure that data sheets not used for trending.
JOHNSON, E.H. Region 4, Office of Director. 85/10/01. PILANT, J.M. Nebraska Public Power District. 4pp. 33194.327-33194.330.

8510160040 Notifies of plans to ship via Burlington Northern Railroad, low level radioactive waste that will encounter state boundary. Shipment info encl.
PILANT, J.M. Nebraska Public Power District. 85/10/04. MARTIN, R.D. Region 4, Office of Director. 3pp. 33024.164-33024.166.

P. Operating license stage documents & correspondence

8510020034 Revised application for expedited amend to License DPR-46 revising 850920 Tech Spec changes re single loop operation. Revs incorporate all amends to OL up to & including Amend 93 issued on 830603.
PILANT, J.M. Nebraska Public Power District. 85/09/23. VASSALLO, D.W. Operating Reactors Branch 2. 1p. 32824.180-32824.215.

-8510020037 Proposed Tech Specs, revising 850920 Tech Spec change request re single loop operation.
* Nebraska Public Power District. 85/09/23. 35pp. 32824.181-32824.215.

78 DOCKETED ITEMS

8510040001 Requests withdrawal of single loop operation Tech Spec changes requested in 800805, 820506 & 28 & 831202 submittals. Proposed changes superseded by 850923 & 25 requests.
PILANT, J.M. Nebraska Public Power District. 85/09/27. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32851-158-32851-159.

8510180043 Submits mods to be completed after 1986 outage to meet ATWS (i.e. requirements in 10CFR50.62 & Generic Ltr 85-06 re QA guidance for nonsafety-related ATWS equipment.
PILANT, J.M. Nebraska Public Power District. 85/10/14. THOMPSON, H.L. Division of Licensing. 1p. 33054-050-33054-050.

8510280274 Forwards notice of withdrawal of 800805 application for amend to License DPR-46. Amend authorized operation of reactor at power levels up to 50% of rated thermal power w/one recirculation loop out of svc.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/18. PILANT, J.M. Nebraska Public Power District. 2pp. 33228-212-33228-214.

8510280361 Notice of withdrawal of application for amend to License DPR-46.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/18. 1p. 33228-214-33228-214.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32861-001-32869-060.

8510090297 Ack receipt of 850731 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-298/85-16.
JOHNSON, E.H. Region 4, Office of Director. 85/09/30. PILANT, J.M. Nebraska Public Power District. 1p. 32947-103-32947-106.

8510090300 Responds to NRC 850702 ltr re violations noted in Insp Rept 50-298/85-16. Corrective actions: QA Instructions QAI-4, QAI-5 & QAI-10 will be revised to identify proper distribution & contractor will review NDE documentation.
PILANT, J.M. Nebraska Public Power District. 85/07/31. JOHNSON, E.H. Region 4, Office of Director. 3pp. 32947-104-32947-106.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

8510230325 Forwards Press Release 85-22 re NRC proposed fine against util for several alleged violations of regulations concerning failure to conduct surveillance tests for unit batteries.
KAMMERER, C. Office of Congressional Affairs. 85/02/14. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-153-33109-154.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LCV, P.A. Parametec, Inc. (NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510220460 Forwards Insp Rept 50-298/85-18 on 850601-0731. No violations or deviation noted.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. PILANT, J.M. Nebraska Public Power District. 2pp. 33096-235-33096-265.

8510220464 Insp Rept 50-298/85-18 on 850601-0731. No violation or deviation noted. Major areas inspected: operational safety verification, monthly surveillance & maint observations, licensed operator training & IE info notices.
DUBOIS, D.L., JAUDON, J.P. Region 4, Office of Director. 85/10/08. 29pp. 33096-237-33096-265.

8510240424 Ack receipt of 850923 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-298/85-20.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. PILANT, J.M. Nebraska Public Power District. 1p. 33159-358-33159-360.

8510240426 Responds to NRC 850829 ltr re violations noted in Insp Rept 50-298/85-20. Corrective actions: revs will be issued to Purchase Orders 231236 & 236067 to reflect 10CFR21 applicability & QAI-9 refresher training given.
PILANT, J.M. Nebraska Public Power District. 85/09/23. JOHNSON, E.H. Region 4, Office of Director. 2pp. 33159-359-33159-360.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510290194 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-298/85-19.
JOHNSON, E.H. Region 4, Office of Director. 85/10/23. PILANT, J.M. Nebraska Public Power District. 1p. 33233-197-33233-200.

8510290202 Responds to NRC 850821 ltr re violations noted in Insp Rept 50-298/85-19. Corrective actions: CNS Procedure 3.8, "Drawing Control Procedure," will be revised & implemented to control use of safety-related drawings.
PILANT, J.M. Nebraska Public Power District. 85/09/20. JOHNSON, E.H. Region 4, Office of Director. 3pp. 33233-198-33233-200.

R. Periodic operating reports & related correspondence

8510010492 Monthly operating rept for Jul 1985. W/850805 ltr.
SALISBURY, J.K., THOMASON, P.V. Nebraska Public Power District. 85/07/31. 5pp. 32820-152-32820-156.

S. Reportable occurrences, LERs & related correspondence

8510090107 PNO-IV-85-054 on 851005 reactor manually tripped due to sudden increase in vibration of low pressure turbine elements in main turbine condensate activity. Caused by possible damage to condenser tubes. State of NE informed.
JAUDON, J.P. Region 4, Office of Director. 85/10/07. 1p. 32941-264-32941-264.

8510290379 NPDES noncompliance notification on 851014, increased flows & flow surges to treatment plant occurred. Cause not stated.
COOPER, L.J. Nebraska Public Power District. 85/10/18. VARNER, D. Nebraska, State of. 2pp. 33242-318-33242-319.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

8510230325 Forwards Press Release 85-22 re NRC proposed fine against util for several alleged violations of regulations concerning failure to conduct surveillance tests for unit batteries.
KAMMERER, C. Office of Congressional Affairs. 85/02/14. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-153-33109-154.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510220460 Forwards Insp Rept 50-298/85-18 on 850601-0731. No violations or deviation noted.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. PILANT, J.M. Nebraska Public Power District. 2pp. 33096-235-33096-265.

8510220464 Insp Rept 50-298/85-18 on 850601-0731. No violation or deviation noted. Major areas inspected: operational safety verification, monthly surveillance & maint observations, licensed operator training & IE info notices.
DUBOIS, D.L., JAUDON, J.P. Region 4, Office of Director. 85/10/08. 29pp. 33096-237-33096-265.

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070223 Approves 850823 revs to emergency plan. Effectiveness of plan not downgraded.
SHAFFER, W.D. Region 3, Office of Director. 85/09/30. FAY, C.W. Wisconsin Electric Power Co. 1p. 32678-011-32678-011.

8510100006 Forwards Safety Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No noncompliance noted. Response to exercise weaknesses identified during insp & noted in encl app, requested within 45 days.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. FAY, C.W. Wisconsin Electric Power Co. 3pp. 32961-009-32961-024.

8510100018 Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No deficiencies, noncompliance or deviation noted. Major areas inspected: emergency preparedness exercise. One weakness noted re notification of unusual event.
SNELL, W., PHILLIPS, M. Region 3, Office of Director. 85/10/03. 13pp. 32961-012-32961-024.

8510150314 Informs that alternatives for providing alternate shutdown capability for 4160-volt switchgear room being evaluated. Evaluation should be completed by Nov 1985.
BRITT, R.W. Wisconsin Electric Power Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 1p. 33000-324-33000-324.

8510280439 Grants extension of completion date until Mar 1986 for compliance w/ Commission 840702 order re submission of DCDR summary rept & proposed implementation schedule per 850521 request.
THOMPSON, H.L. Division of Licensing. 85/10/16. FAY, C.W. Wisconsin Electric Power Co. 3pp. 33196-303-33196-305.

8510230105 Responds to 851003 ltr re changes in procedures for contacting NRC operations officer following activation of facility emergency plan. Revised procedures adequately meet all NRC concerns. Meeting unnecessary.
SHAFFER, W.D. Region 3, Office of Director. 85/10/18. FAY, C.W. Wisconsin Electric Power Co. 1p. 33101-250-33101-252.

—8510230111 Clarifies procedure util will use when making emergency notifications to NRC. Procedures re collection of all pertinent info needed by NRC being revised. Changes & training of personnel will be completed by 850101.
FAY, C.W. Wisconsin Electric Power Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33101-251-33101-252.

P. Operating license stage documents & correspondence

8510040444 Advises that 831202 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing acceptable. Conclusion supported by encl EG&G Idaho, Inc. rept. VARGA, S.A. Operating Reactors Branch 1. 85/09/19. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 32859-315-32859-316.

—8509060182 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Ginna, Kewaunee, Point Beach Units 1 & 2 & Prairie Island Units 1 & 2."
HAROLDSEN, R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6001, EA-7000. 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859-317-32859-331.

8510040251 Ack receipt of 841119 & 850701 submittals of Rev 3 changes to QA program description. Rev acceptable.
PAPERIELLO, C.J. Region 3, Office of Director. 85/09/30. FAY, C.W. Wisconsin Electric Power Co. 1p. 32851-160-32851-160.

8510080369 Provides proposed schedule for meeting requirements of 10CFR50.62 re reduction of risk from ATWS events for light-water cooled nuclear plants. Brief description of tentative design for PWR listed.
FAY, C.W. Wisconsin Electric Power Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 2pp. 32918-308-32918-309.

8510150165 Informs that complete response to Generic Ltr 85-12 re TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," will be submitted by 851206.
BRITT, R.W. Wisconsin Electric Power Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 2pp. 33010-301-33010-302.

8510170078 Forwards Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively & safety evaluation. Amends define limiting conditions for operation & surveillance requirements for radioactive liquid & gaseous effluent monitoring.
COLBURN, T.G. Operating Reactors Branch 3. 85/10/03. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33043-234-33043-300.

—8510170083 Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively, defining limiting conditions for operation & surveillance requirements for radioactive liquid & gaseous effluent monitoring.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/03. 56pp. 33043-236-33043-291.

—8510170087 Safety evaluation supporting Amends 97 & 101 to Licenses DPR-24 & DPR-27, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/03. 9pp. 33043-292-33043-300.

—8506050540 "Racine" Effluent Tech Specs (RETS) Implementation - Point Beach Nuclear Plant.
SERRANO, W.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6459. EGG-PBS-6863. 85/05/31. NRC - No Detailed Affiliation Given. 32pp. 33043-301-33043-332.

8510150138 Discusses history of qualification effort on pressurizer safety valve direct position indicators (refs NUREG-0578 & NUREG-0737, Item 3.D.3.1) per NRC 850927 telcon request.
BRITT, R.W. Wisconsin Electric Power Co. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 5pp. 33013-091-33013-095.

8510160006 Informs of change in plans & current status of rod cluster control assemblies (RCCA) per 830818 & 840627 results of exams. Twelve Unit 1 and six Unit 2 RCCAs replaced.
FAY, C.W. Wisconsin Electric Power Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 3pp. 33027-090-33027-092.

8510280297 Accepts 831107 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing of reactor trip sys components & other safety-related equipment. Safety evaluation encl.
BUTCHER, E.J. Operating Reactors Branch 5. 85/10/18. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33228-179-33228-193.

—8510280300 Safety evaluation accepting util 831107 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing.
* Office of Nuclear Reactor Regulation, Director. 85/10/18. 1p. 33228-181-33228-193.

8510290043 Notifies of completion of evaluation re 850423 ltr concerning time necessary for NRC inspectors to gain initial access to licensed facilities. List of tasks necessary to gain unrestricted plant access encl.
FAY, C.W. Wisconsin Electric Power Co. 85/10/23. KEPPLER, J.G., NORELIUS, C. Region 3, Office of Director. 5pp. 33236-159-33236-163.

Q. Inspection reports, IE Bulletins & correspondence

8510010154 Forwards Safety Insp Repts 50-266/85-17 & 50-301/85-17 on 850903-06. No noncompliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/09/25. FAY, C.W. Wisconsin Electric Power Co. 2pp. 32801-353-32801-362.

—8510010180 Insp Repts 50-266/85-17 & 50-301/85-17 on 850903-06. No violation or deviation noted. Major areas inspected: radiation protection program including organization & mgt controls, posting & access controls, contamination control & training.
PAUL, R.A., GREGER, L.R. Region 3, Office of Director. 85/09/24. 8pp. 32801-355-32801-362.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510100006 Forwards Safety Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No noncompliance noted. Response to exercise weaknesses identified during insp & noted in encl app, requested within 45 days.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. FAY, C.W. Wisconsin Electric Power Co. 3pp. 32961-009-32961-024.

—8510100018 Insp Repts 50-266/85-12 & 50-301/85-12 on 850909-11. No deficiencies, noncompliance or deviation noted. Major areas inspected: emergency preparedness exercise. One weakness noted re notification of unusual event.
SNELL, W., WILLIAMS, N., BROWN, G. Region 3, Office of Director. 85/10/03. 13pp. 32961-012-32961-024.

8510250271 Forwards Safety Insp Repts 50-266/85-15 & 50-301/85-15 on 850801-0930 & notice of violation.
CHRISTOTIMOS, N. Region 3, Office of Director. 85/10/10. FAY, C.W. Wisconsin Electric Power Co. 2pp. 33173-098-33173-107.

—8510250276 Notice of violation from insp on 850801-0930.
CHRISTOTIMOS, N. Region 3, Office of Director. 85/10/10. 1p. 33173-100-33173-100.

—8510250282 Insp Repts 50-266/85-15 & 50-301/85-15 on 850801-0930. Violation noted three subcritical spent fuel assemblies moved to positions adjacent to spent fuel pit east wall.
* Region 3, Office of Director. 85/10/10. 7pp. 33173-101-33173-107.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLCs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510180502 Monthly operating repts for Sept 1985. W/851010 ltr.
KRAUSE, C.W., FAY, C.W. Wisconsin Electric Power Co. 85/09/30. 9pp. 33067-333-33067-347.

S. Reportable occurrences, LERs & related correspondence

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8510310218 Revised emergency plan implementing procedures, consisting of Rev 33 to EM-206, "Emergency Plan Roster & Notification" & Rev 4 to VP-580, "Plant Safety Verification Procedure."
* Florida Power Corp. (subs. of Florida Progress Corp.). 85/03/09. 39pp. 33272-086-33272-125.

8510080423 Rev 2 to Procedure AP-601, "TGF M Annunciator Response."
WITTMAN, R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/11. 6pp. 32919-294-32919-299.

8510020285 Forwards Insp Rept 50-302/85-30 on 850729-0802. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 32825-205-32825-231.

—8510020290 Insp Rept 50-302/85-30 on 850729-0802. No violation or deviation noted. Major areas inspected: fire protection & licensee action re implementation of requirements of 10CFR50, App R, Sections III G, III J, III L, & III O.
MILLER, W.H., WISEMAN, G.R., MELLEN, L.S. Region 2, Office of Director. 85/09/20. 25pp. 32825-207-32825-231.

8510080351 Forwards Insp Rept 50-302/85-38 on 850826-30. No violation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/27. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32928-005-32928-016.

80 DOCKETED ITEMS

-8510080363 Insp Rept 50-302/85-38 on 850826-30. No violation or deviation noted. Major areas inspected: licensee commitment in tracking of regulatory requirements.
SMITH, C.F., BELISLE, G.A. Region 2, Office of Director. 85/09/26. 11pp. 32928-006-32928-016.

8510180458 Forwards Insp Rept 50-302/85-36 on 850823. No violation noted.
BROWN, L.E.V. Region 2, Office of Director. 85/10/01. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 33068-059-33068-062.

-8510180463 Insp Rept 50-302/85-36 on 850823. No violation or deviation noted. Major areas inspected: emergency preparedness, emergency response facilities, NRC Response Team coordination & NRC hurricane response procedures.
STANSBERRY, W.W., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/26. 2pp. 33068-061-33068-062.

8510220219 Forwards Insp Rept 50-302/85-35 on 850811-15 & 22-23 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
WALKER, R.D. Region 2, Office of Director. 85/10/03. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 33089-307-33089-309.

-8510220229 Insp Rept 50-302/85-35 on 850811-15 & 22-23. Violation noted: failure to provide positive access control to protected area. Details withheld (ref 10CFR2.790(d) & 73.21).
TILLMAN, A., MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/01. 1p. 33089-309-33089-309.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.

-8510230342 Forwards Press Release 85-4 re NRC proposed civil penalty in amount of \$50,000 against utility for alleged violation of security requirements concerning protection of vital equipment.
KAMMERER, C. Office of Congressional Affairs. 85/01/11. House of Rep., Energy & Commerce. MARKEY House of Rep. CHILES Senate. 2pp. 33109-160-33109-161.

8510150133 Notification of 851024 meeting w/Util & Science Applications Intl Corp in Bethesda, MD to discuss NRC concerns re DCDR summary rept. Agenda encl.
SILVER, H. Operating Reactors Branch 4. 85/10/08. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33031-031-33031-034.

8510290206 Rev 11 to "Activation & Notification of Corporate Emergency Support Plan."
* Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/18. 32pp. 33233-201-33233-232.

8510310534 Submits implementation rept re NUREG-0737, Item II.F.2, "Inadequate Core Cooling Instrumentation" per NRC 830906 ltr. Saturation margin meters installed before Refuel III & operational Pressure-temp display added to SPDs.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/23. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33280-043-33280-045.

H. General correspondence

8510250027 Responds to 850911 request re constituent GL Rausch ltr on safety of plant during hurricane. Design of plant protects against winds up to 140 mph & associated tides & waves.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/10/18. CHILES, L. Senate. 7pp. 33224-353-33224-362.

-8510250030 Requests review of encl GL Rausch ltr re safety of plant in hurricane.
CHILES, L. Senate. 85/09/11. KAMMERER, C. Office of Congressional Affairs. 3pp. 33224-360-33224-362.

I. Financial Information

8510290440 Informs that 851007 financial info submitted for 1985 satisfies requirements of 10CFR40, Section 140.21 re guarantee of payment of deferred premiums for each partially or wholly owned operating reactor over 100 MWe.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/10/24. GREENE, G.E. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 33254-350-33254-350.

P. Operating license stage documents & correspondence

8510040327 Forwards Amend 81 to License DPR-72 & safety evaluation. Amend permits triaxial peak accelograph on top of reactor vessel head to be inoperable during Modes 5 & 6.
SILVER, H. Operating Reactors Branch 4. 85/09/18. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 32860-102-32860-112.

-8510040339 Amend 81 to License DPR-72, permitting triaxial peak accelograph on top of reactor head to be inoperable during Modes 5 & 6.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/18. 7pp. 32860-104-32860-110.

-8510040344 Safety evaluation supporting Amend 81 to License DPR-72.
* Operating Reactors Branch 4. 85/09/18. 2pp. 32860-111-32860-112.

8510040350 Forwards Amend 82 to License DPR-72 & safety evaluation. Amend changes Tech Specs to update reactor pressure-temp limits to 8 EFYs per analysis of first surveillance capsule.
SILVER, H. Operating Reactors Branch 4. 85/09/23. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 32860-056-32860-075.

-8510040356 Amend 82 to License DPR-72, updating reactor pressure-temp limits to 8 EFYs.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/23. 14pp. 32860-058-32860-071.

-8510040362 Safety evaluation supporting Amend 82 to License DPR-72.
* Office of Nuclear Reactor Regulation, Director. 85/09/23. 4pp. 32860-072-32860-075.

8510010100 Responds to Generic Ltr 85-06 re QA guidance for ATWS nonsafety-related equipment. Util will install equipment per "Design Requirements for Diverse Scram Sys & ATWS..." Document will be submitted by 851001.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/26. THOMPSON, H.L. Division of Licensing. 1p. 32800-105-32800-105.

8510010050 Forwards response to NRC 850826 request for addl info for 5 of 11 criteria summarized in interim safety evaluation re post-accident sampling sys (NUREG-0737, Item II.B.3).
SIMPSON, E.C. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/27. STOLZ, J.F. Operating Reactors Branch 4. 75pp. 32802-277-32802-350.

8510010347 Forwards "Safety Balance Assessment for Elimination of RCS Main Loop Pipe Break Protective Devices," per 850201 request for exemption from 10CFR50, App A, GDC 4 Meeting arranged in late Oct 1985 w/B&W to discuss NRC review.
SIMPSON, E.C. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32803-001-32803-019.

-8510010352 "Safety Balance Assessment for Elimination of RCS Main Loop Pipe Break Protective Devices."
* Babcock & Wilcox Co. 51-1159048-00. 85/09/12. 17pp. 32803-003-32803-019.

8510090162 Forwards Amend 84 to License DPR-72 & safety evaluation. Amend corrects errors & inconsistencies & clarifies certain radiological effluent Tech Specs.
SILVER, H. Operating Reactors Branch 4. 85/09/30. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 32950-359-32950-360.

-8510090166 Amend 84 to License DPR-72, correcting errors & inconsistencies & clarifying certain radiological effluent Tech Specs.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/30. 19pp. 32950-361-32951-017.

-8510090172 Safety evaluation supporting Amend 84 to License DPR-72.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 3pp. 32951-018-32951-020.

8510150316 Forwards Amend 83 to License DPR-72 & safety evaluation. Amend changes Tech Specs, deleting Surveillance Requirement 4.8.1.1.a.2 re verification of sump pump operability.
SILVER, H. Operating Reactors Branch 4. 85/09/30. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 33033-246-33033-254.

-8510150317 Amend 83 to License DPR-72, changing Tech Specs to delete Surveillance Requirement 4.8.1.1.a.2 re verification of sump pump operability in tunnel containing dc control supply to 230 kV switchgear.
STOLZ, J.F. Operating Reactors Branch 4. 85/09/30. 5pp. 33033-248-33033-252.

-8510150319 Safety evaluation supporting Amend 83 to License DPR-72.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 2pp. 33033-253-33033-254.

8510040171 Revises commitment re qualifications & duties of shift technical advisor (STA). STA training will be performed per NUREG-0737, Item I.A.1.1 & Tech Specs, as specified within ltr Refs applicable to STA issue listed.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/01. THOMPSON, H.L. Division of Licensing. 3pp. 32851-045-32851-047.

8510040257 Withdraws Tech Spec Change Request 53 & Rev 1 to Change Request 53, dtd 791120 & 821119 respectively. Overly restrictive allowable outage time addressed generically by Tech Spec Improvement Program & AIF.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32851-161-32851-162.

8510150149 Notification of 851031 meeting w/Util & B&W in Bethesda, MD to discuss NRC concerns re review of GDC 4 exemption request for reactor coolant pump restraints.
SILVER, H. Operating Reactors Branch 4. 85/10/04. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33031-109-33031-111.

8510150147 Responds to 850830 request for confirmatory info re NUREG-0737, Item II.K.3.30, "Small Break LOCA Methods" & use of CRAFT-2 code. Util concurs w/B&W position on NUREG-0565 concerning noncondensable gases.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/08. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33006-355-33006-356.

8510160085 Submits response to 850826 request for addl info re Generic Ltr 83-28, Items 4.2.1 & 4.2.2. Preventive Maint Procedure PM-118 will be performed on 12-month basis per B&W Owners Group ATWS committee recommendations.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33028-002-33028-003.

8510170055 Informs that response to 850826 request for addl info on NUREG-0737, Item II.D.1 re adequacy of relief & safety valves installed on pressurizer will be provided on or before 860115.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/14. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33036-349-33036-349.

8510210077 Informs that licensee in final stages of PRA evaluation of emergency feedwater sys (EFS) per 841218 ltr. Schedule for submittal of evaluation will be provided after review of NRC generic ltr re EFS reliability for PWRs.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/16. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33072-282-33072-282.

8510310191 Forwards ltr re actions taken in pursuit of excellence in plant safety & operation. Ltr illustrates aggressive activities in emergency feedwater sys reliability.
WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33274-044-33274-052.

-8510310197 Summarizes programs & improvements to emergency feedwater sys for facility Sys installed which can automatically start & control emergency feedwater sys & prevent overheating.
WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 8pp. 33274-045-33274-052.

Q. Inspection reports, IE Bulletins & correspondence

8510070372 Forwards supplemental response to violations noted in Insp Rept 50-302/85-15. Corrective action memo issued clarifying unresolved QA audit finding extension & escalation.
WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/17. GRACE, J.N. Region 2, Office of Director. 3pp. 32878.292-32878.294.

8510070063 Ack receipt of 850912 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/85-29.
WALKER, R.D. Region 2, Office of Director. 85/09/24. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32900.055-32900.055.

8510070320 Responds to violations noted in Insp Rept 50-302/85-33. Corrective actions action statement logged & grab samples commenced on 24 h frequency, SP-135B performed satisfactorily on 850724 & Valve EFV-7 placed in open position.
WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/24. GRACE, J.N. Region 2, Office of Director. 5pp. 32880.302-32880.306.

8510020285 Forwards Insp Rept 50-302/85-30 on 850729-0802. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 32825.205-32825.231.

8510020290 Insp Rept 50-02/85-30 on 850729-0802. No violation or deviation noted. Major areas inspected: fire protection & licensee action re implementation of requirements of 10CFR50, App R, Sections III.G, III.J, III.L & III.O.
MILLER, W.H., WISEMAN, G.R., MELLEN, L.S. Region 2, Office of Director. 85/09/20. 25pp. 32825.207-32825.231.

8510040535 Forwards Insp Rept 50-302/85-39 on 850910-13. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32866.050-32866.056.

8510040539 Insp Rept 50-302/85-39 on 850910-13. No violation or deviation noted. Major areas inspected: post-critically tests performed following refueling outage.
BURNETT, P.T., JAFÉ, F. Region 2, Office of Director. 85/09/23. 6pp. 32866.051-32866.056.

8510080351 Forwards Insp Rept 50-302/85-38 on 850826-30. No violation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/27. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32928.005-32928.016.

8510080363 Insp Rept 50-302/85-38 on 850826-30. No violation or deviation noted. Major areas inspected: licensee commitment in tracking of regulatory requirements.
SMITH, C.F., BELISLE, G.A. Region 2, Office of Director. 85/09/26. 11pp. 32928.006-32928.016.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 143pp. 32869.001-32869.060.

8509260309 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180458 Forwards Insp Rept 50-302/85-36 on 850823. No violation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/01. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 33068.059-33068.062.

8510180463 Insp Rept 50-302/85-36 on 850823. No violation or deviation noted. Major areas inspected: emergency preparedness, emergency response facilities, NRC Response Team coordination & NRC hurricane response procedures.
STANSBERRY, W.W., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/26. 2pp. 33068.061-33068.062.

8510220219 Forwards Insp Rept 50-302/85-35 on 850811-15 & 22-23 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
WALKER, R.D. Region 2, Office of Director. 85/10/03. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 2pp. 33089.307-33089.309.

8510220229 Insp Rept 50-302/85-35 on 850811-15 & 22-23. Violation noted: failure to provide positive access control to protected area. Details withheld (ref 10CFR2.790(d) & 73.21).
TILLMAN, A., MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/01. 1p. 33089.309-33089.309.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33108.088.

8510230342 Forwards Press Release 85-4 re NRC proposed civil penalty in amount of \$50,000 against util for alleged violation of security requirements concerning protection of vital equipment.
KAMMERER, C. Office of Congressional Affairs. 85/01/11. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109.160-33109.161.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

R. Periodic operating reports & related correspondence

8510150353 Forwards monthly operating rept for Sept 1985 & two corrected pages to monthly operating rept for Aug 1985.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/08. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 1p. 33010.188-33010.188.

8510150356 Two corrected pages to monthly operating rept for Aug 1985.
STEWART, S.A. Florida Power Corp. (subs. of Florida Progress Corp.). 85/08/31. 2pp. 33010.189-33010.190.

8510150357 Monthly operating rept for Sept 1985.
GRAHAM, D., STEWART, S.A. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/30. 4pp. 33010.191-33010.194.

S. Reportable occurrences, LERs & related correspondence

8510010640 LER 85-016-00 on 850820. RCS high pressure trip occurred due to RCS pressure & temp perturbations. Caused by sluggish main feedwater control response & improper settings on reactor control module. Control module replaced w/850926 ltr.
BANDHAUER, W.K., WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/26. 4pp. 32820.331-32820.334.

8510020193 LER 85-017-00 on 850830. Unusual event declared due to threat of Hurricane Elena. Watertight flood control doors closed & plant staff augmented w/addl personnel w/850927 ltr.
BANDHAUER, W.K., WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/09/27. 3pp. 32827.193-32827.195.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030.243-33030.265.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33108.088.

8510230342 Forwards Press Release 85-4 re NRC proposed civil penalty in amount of \$50,000 against util for alleged violation of security requirements concerning protection of vital equipment.
KAMMERER, C. Office of Congressional Affairs. 85/01/11. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109.160-33109.161.

V. Operator Examinations

8510030426 Responds to GR Westafér 850903 request for exam of seven operators. Earliest date available for exam administration is mid-Jan 1986 due to limited manpower. S. Lawyer should be contacted re date finalization.
GRACE, J.N. Region 2, Office of Director. 85/09/25. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32846.005-32846.005.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

8510040171 Revises commitment re qualifications & duties of shift technical advisor (STA). STA training will be performed per NUREG-0737, Item I.A.1.1 & Tech Specs, as specified within ltr Rrfs applicable to STA issue listed.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/11/01. THOMPSON, H.L. Division of Licensing. 3pp. 32851.045-32851.047.

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510160248 Forwards Mgt Meeting Repts 50-295/85-35-50-304/85-37, 50-373/85-31, 50-374/85-32-50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026.219-33026.222.

8510160270 Mgt Meeting Repts 50-295/85-35-50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026.221-33026.222.

8510160256 Ack receipt of 850924 ltr re annual meeting w/offsite response agencies. Requests to be informed of dates for plant annual emergency preparedness training to offsite organizations.
SHAFFER, W.D. Region 3, Office of Director. 85/10/09. NYKIELA, Commonwealth Edison Co. 1p. 33022.322-33022.324.

82 DOCKETED ITEMS

-8510160259 Extends invitation to visit plant on 851023 to discuss emergency plan. Radiological training or retraining will be offered to NRC personnel. Response requested by 851010.
PLIML,G.J. Commonwealth Edison Co. 85/09/24. KEPLER,J.G. Region 3, Office of Director. 2pp. 33022-323-33022-324.

F510280170 Forwards Rev 16 to security plan. Rev withheld (ref 10CFR73.21).
FARRAR,D.L. Commonwealth Edison Co. 85/10/21. KEPLER,J.G. Region 3, Office of Director. 1p. 33191-002-33191-002.

8510310318 Advises that 851021 Rev 16 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
AXELSON,W.L. Region 3, Office of Director. 85/10/25. FARRAR,D.L. Commonwealth Edison Co. 2pp. 33272-084-33272-085.

P. Operating license stage documents & correspondence

8510010155 Application for amends to Licenses DPR-39 & DPR-48 re proposed changes to specimen capsule withdrawal schedule. Forwards WCAP-10902, "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
LEBLOND,P.C. Commonwealth Edison Co. 85/09/13. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 32800-001-32800-063.

-8510010161 "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
ANDERSON,S.L. LAU,F.L. Westinghouse Electric Corp. WCAP-10902. 85/10/25. 55pp. 32800-010-32800-063.

8510310542 Notifies that Tech Spec Page 217a should be deleted from 850827 / Rev 90 to License DPR-39 & Amend 80 to License DPR-48, per 850910 request.
NORRIS,J.A. Operating Reactors Branch 1. 85/09/30. FARRAR,D.L. Commonwealth Edison Co. 2pp. 33277-041-33277-042.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER,G.L. Commonwealth Edison Co. 85/10/03. KEPLER,J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

8510310561 Forwards safety evaluation of 851105 response to Generic Ltr 83-28. Post-trip review data & info capabilities re item 1.2 do not meet guidelines. Response to recommendations requested.
VARGA,S.A. Operating Reactors Branch 1. 85/10/03. FARRAR,D.L. Commonwealth Edison Co. 12pp. 33277-054-33277-066.

-8510310573 Safety evaluation re review of util response to Generic Ltr 83-28. Post-trip review data & info capabilities re item 1.2 may be inadequate for diagnosing causes of unscheduled reactor shutdowns & for evaluating safety-related equipment.
Office of Nuclear Reactor Regulation, Director. 85/10/03. 11pp. 33277-056-33277-066.

8510220304 Revised application for amends to Licenses DPR-39 & DPR-48, changing Tech Spec Section 1.0, "Definitions," for inclusion in 850625 proposed amend.
LEBLOND,P.C. Commonwealth Edison Co. 85/10/07. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33084-017-33084-041.

-8510220308 Proposed Tech Spec changes to Section 1.0, "Definitions," for inclusion in 850625 submittal.
Commonwealth Edison Co. 85/10/07. 23pp. 33084-019-33084-041.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER,G. Commonwealth Edison Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

8510310595 Forwards safety evaluation identifying concerns re NUREG-0737, item II.F.2 on final inadequate core cooling instrumentation sys. per util 840824 & 850305 responses to 840530 ltr. Further clarification required.
VARGA,S.A. Operating Reactors Branch 1. 85/10/17. FARRAR,D.L. Commonwealth Edison Co. 9pp. 33277-063-33277-091.

8510290081 Informs that State of IL Dept of Nuclear Safety reviewed proposed Tech Spec amend involving radiological effluent Tech Spec Section 1.0 re definitions. No adverse findings noted.
PARKER,M.C. Illinois, State of. 85/10/22. DENTON,H. Office of Nuclear Reactor Regulation, Director. 1p. 33236-036-33236-036.

Q. Inspection reports, IE Bulletins & correspondence

8510070358 Forwards response to NRC 850415 ltr re violations noted in Insp Rept 50-304/85-06. Corrective actions: plastic shipping caps removed from affected valve operators & junction boxes & Limitorque valve operator installed.
DELGEORGE,L.O. Commonwealth Edison Co. 85/09/20. KEPLER,J.G. Region 3, Office of Director. 12pp. 32878-247-32878-258.

8510090156 Forwards Safety Insp Repts 50-295/85-30 & 50-304/85-31 on 850820-23 & 27-28 & notice of violation.
SHAHER,W.D. Region 3, Office of Director. 85/09/27. REED,C. Commonwealth Edison Co. 2pp. 32946-175-32946-185.

-8510090161 Notice of violation from insp on 850820-23 & 27-28.
SHAHER,W.D. Region 1, Office of Director. 85/09/27. 1p. 32946-177-32946-185.

-8510090171 Insp Repts 50-295/85-30 & 50-304/85-31 on 850820-23 & 27-28. Violation noted: failure to implement written Procedure ZCP 531-7, "Performance Test for Eberline Model SAC-4 Scintillation Alpha Counter."
JANIUSKA,A.G. SCHUMACHER,M.C. Region 3, Office of Director. 85/09/27. 8pp. 32946-178-32946-185.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAHER,W.D. Region 3, Office of Director. 85/10/04. REED,C. Commonwealth Edison Co. 2pp. 33026-219-33026-222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN,G.A., KERS,L.L., SMITH,M.J. Region 3, Office of Director. 85/10/04. 2pp. 33026-221-33026-222.

8510220414 Forwards Safety Insp Repts 50-295/85-34 & 50-304/85-36 on 850917-19 & 26 & notice of violation.
SHAHER,W.D. Region 3, Office of Director. 85/10/08. REED,C. Commonwealth Edison Co. 2pp. 33097-057-33097-068.

-8510220417 Notice of violation from insp on 850917-19 & 26.
SHAHER,W.D. Region 3, Office of Director. 85/10/08. 1p. 33097-059-33097-059.

-8510220420 Insp Repts 50-295/85-34 & 50-304/85-36 on 850917-19 & 26. Violation noted: failure to make required repl when 7 Ci released from site via liquid radwaste during Third Quarter 1984.
NICHOLSON,N.A., LOVENDALE,P.C., GREGER,L.R. Region 3, Office of Director. 85/10/08. 9pp. 33097-060-33097-068.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closout rept.
LOFF,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510160272 Forwards Safety Insp Repts 50-295/85-33 & 50-304/85-34 on 850913-30. No violations or deviations noted.
REYES,L.A. Region 3, Office of Director. 85/10/10. REED,C. Commonwealth Edison Co. 2pp. 33024-339-33024-346.

-8510160274 Insp Repts 50-295/85-33 & 50-304/85-34 on 850913-30. No violations or deviations noted. Major areas inspected: Unit 2 containment integrated leak rate test (CILRT), Unit 1 CILRT rept & resolution of Unit 1 violations & open items.
MAURA,F., GULDEMOND,W.G. Region 3, Office of Director. 85/10/09. 6pp. 33024-341-33024-346.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510230055 Forwards proposed Rev 5 to inservice insp program for first 10-yr interval, deferring specific hydrostatic pressure test under IWO-5000 to next refueling outage after receipt of replacement isolation boundary valves.
LEBLOND,P.C. Commonwealth Edison Co. 85/10/13. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33102-246-33102-250.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasitic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510310262 Forwards Safety Insp Repts 50-295/85-32 & 50-304/85-33 on 850918-20, 23-26, 30 & 1001-03. No violations noted.
REYES,L.A. Region 3, Office of Director. 85/10/25. REED,C. Commonwealth Edison Co. 2pp. 33274-033-33274-042.

-8510310265 Insp Repts 50-295/85-32 & 50-304/85-33 on 850918-20, 23-26, 30 & 1001-03. No violations or deviations noted. Major areas inspected: QA program implementation, QA/QC administration & calibr activities.
SUTPHIN,R.N., HAWKINS,P. Region 3, Office of Director. 85/10/25. 8pp. 33274-035-33274-042.

R. Periodic operating reports & related correspondence

8510100101 Monthly operating repts for Sept 1985 W/851004 ltr.
AUSTIN,G., PLIML,G.J. Commonwealth Edison Co. 85/09/30. 12pp. 32960-332-32960-343.

S. Reportable occurrences, LERs & related correspondence

8510090450 LER 85-018-00 on 850930, discovered that four Limitorque valve operators had jumper wires different from wires tested by vendor in environ qualification program. Cause not stated. Adequacy of valve documentation reviewed W/851004 ltr.
BAILEY,M.W., PLIML,G.J. Commonwealth Edison Co. 85/10/04. 3pp. 32946-099-32946-101.

8510210069 PNO-III-85-087 on 851007, concrete finisher killed after falling 45 ft while working on interim radwaste storage facility. No contamination involved.
HEHL,W., CHRISOTIMOS,N. Region 3, Office of Director. 85/10/08. 1p. 33072-285-33072-285.

8510150444 LER 85-017-00 on 850909, purge valves tripped shut. Caused by workers inadvertently actuating high radiation protection circuitry. Mod initiated to remove necessity of installing jumpers to start fans. W/851009 ltr.
HUTSEBAUT, J., PLIML, G.J. Commonwealth Edison Co. 85/10/09. 4pp. 33015-175-33015-178.

8510180266 LER 85-019-00 on 850911, high particulate alarm occurred during venting of containment to atmosphere. Cause suspected to be defect in alarm circuitry on radiation monitor 2RT-PR09C. Personnel counseled. W/851011 ltr.
PETROWSKI, K., PLIML, G.J. Commonwealth Edison Co. 85/10/11. 2pp. 33068-289-33068-291.

8510310545 LER 85-012-01 on 850728, high radiation signal caused closure of purge valves. Caused by procedure deficiency resulting in high alarm setpoint being set below necessary value. Procedure rev implemented on 850827. W/851015 ltr.
KUECHLE, C., PLIML, G.J. Commonwealth Edison Co. 85/10/15. 4pp. 33280-039-33280-042.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, item 1.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8510310056 Requests 851004 meeting re DCDR summary rept submitted to NRC on 850628. Encl meeting agenda identifies concerns to be discussed & resolved. Meeting notice will be issued after date agreed upon.
VARGA, S.A. Operating Reactors Branch 1. 85/10/09. HINTZ, D.C. Wisconsin Public Service Corp. 5pp. 33277-177-33277-181.

8510290339 Radiological emergency response plan implementing procedures, including Rev F to EP-ENV-1, "Environ Team Organization & Responsibilities" & Rev F to EP-ENV-2, "SAF Activation for Emergency Mgt Team." W/841025 ltr.
HINTZ, D.C. Wisconsin Public Service Corp. 85/10/25. 59pp. 33239-167-33239-225.

P. Operating license stage documents & correspondence

8510040444 Advises that 831202 response to Generic Ltr 83-28, items 3.1.3 & 3.2.3 re post-maint testing acceptable. Conclusion supported by encl EG&G Idaho, Inc. rept.
VARGA, S.A. Operating Reactors Branch 1. 85/09/19. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 32859-315-32859-331.

-8509060182 "Conformance to Generic Ltr 83-28, items 3.1.3 & 3.2.3, Ginna, Kewaunee, Point Beach Units 1 & 2 & Prairie Island Units 1 & 2."
HAROLDSEN, R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.) FIN D-6001. EA-7000. 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859-317-32859-331.

8510040228 Forwards current description of Rev 5a to "Operational QA Program Description." Rev clarifies commitments & strengthens program.
HINTZ, D.C. Wisconsin Public Service Corp. 85/09/20. KEPPLER, G. Region 3, Office of Director. 4pp. 32851-112-32851-146.

-8510040232 Rev 5a to "Operational QA Program Description."
* Wisconsin Public Service Corp. 85/09/20. 31pp. 32851-116-32851-146.

8510010282 Application for Amend 69 to License DPR-43, revising Tech Specs to remove limiting condition for operation on North Appleton line contingent upon completing proposed mods to routing of offsite power sources. Fee paid.
GIESLER, C.W. Wisconsin Public Service Corp. 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32800-338-32800-347.

-8510010291 Proposed Tech Spec, removing limiting condition for operation on North Appleton line contingent upon completing proposed mods to routing of offsite power sources.
* Wisconsin Public Service Corp. 85/09/24. 6pp. 32800-342-32800-347.

8510040178 Informs that Rev 5a to QA program description acceptable. Correction in Rev 5a re stop work authority for operational activities meets requirements of ANSI N18.7-1976, Section 3.2, per 850913 request for change to Rev 5.
PAPERIELLO, C.J. Region 3, Office of Director. 85/09/30. HINTZ, D.C. Wisconsin Public Service Corp. 1p. 32851-029-32851-029.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510080247 Forwards XN-NF 85-98, "Kewaunee Limiting Break K(z) LOCA/ECCS Analysis."
HINTZ, D.C. Wisconsin Public Service Corp. 85/10/03. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32918-130-32918-187.

-8510080252 "Kewaunee Limiting Break K(z) LOCA/ECCS Analysis."
ADES, M.J., VALENTINE, P.J., HOLM, J.S. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-85-98. 85/09/30. 60pp. 32918-132-32918-187.

8510150281 Advises that util will propose schedule to meet requirements of 10CFR50.62(c)(1), per Generic Ltr 85-06, within 90 days of receiving NRC SER on ATWS mitigation sys actuation circuitry design described in WCAP-10858.
HINTZ, D.C. Wisconsin Public Service Corp. 85/10/09. THOMPSON, H.L. Division of Licensing. 2pp. 33009-286-33009-287.

8510150392 Revised application for amend to License DPR-43, revising 850924 administrative changes to Tech Specs 3.7.a.8 & 3.7.b.4, Pages 3.7-1 & 3.7-2, respectively. Revis do not affect significant hazards analysis.
GIESLER, C.W. Wisconsin Public Service Corp. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33006-352-33006-353.

-8510150397 Proposed Tech Specs, revising 850924 request for Tech Spec administrative changes.
* Wisconsin Public Service Corp. 85/10/09. 3pp. 33006-354-33006-356.

8510310023 Forwards safety evaluation accepting licensee post-trip review program & procedures, based on 850830 submittal re Generic Ltr 83-28, item 1.1. Review of TAC 52767 completed.
VARGA, S.A. Operating Reactors Branch 1. 85/10/09. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 33277-137-33277-143.

-8510310025 Safety evaluation accepting licensee post-trip review program & procedures, based on 850830 response re Generic Ltr 83-28, item 1.1.
* Office of Nuclear Reactor Regulation, Director. 85/10/09. 5pp. 33277-139-33277-143.

8510310034 Forwards Amend 66 to License DPR-43 & safety evaluation. Amend develops consistency between Tech Specs & 10CFR50 App J re containment air lock surveillance testing.
FAIRFAX, M.B. Operating Reactors Branch 1. 85/10/15. HINTZ, D.C. Wisconsin Public Service Corp. 3pp. 33277-161-33277-170.

-8510310037 Amend 66 to License DPR-43, developing consistency between Tech Specs & 10CFR50 App J re containment air lock surveillance testing.
VARGA, S.A. Operating Reactors Branch 1. 85/10/15. 5pp. 33277-164-33277-168.

-8510310038 Safety evaluation supporting Amend 66 to License DPR-43.
* Office of Nuclear Reactor Regulation, Director. 85/10/15. 2pp. 33277-169-33277-170.

8510250452 Application for amend to License DPR-43, allowing steam generator tube repair & plugging in order to isolate unacceptable tube degradation. Explanation of Tech Spec revs & safety evaluations provided. Fee paid.
GIESLER, C.W. Wisconsin Public Service Corp. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 33170-107-33170-126.

-8510250455 Proposed Tech Specs differentiating repaired from unrepaired tubes when applying sample selection criteria & adding repaired tubes to reporting requirements.
* Wisconsin Public Service Corp. 85/10/23. 11pp. 33170-116-33170-126.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/13. Consolidated Edison Co. of New York, Inc. 13pp. 33177-205-33177-241.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250087 Forwards Safety Insp Rept 50-305/85-13 on 850816-1015. No violation noted.
CHRISTOTIMOS, N. Region 3, Office of Director. 85/10/21. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 33173-122-33173-128.

-8510250095 Insp Rept 50-305/85-13 on 850816-1015. No violation or deviation noted. Major areas inspected previous insp findings, operational safety, surveillance & maint.
JACKWILL, N. Region 3, Office of Director. 85/10/21. 5pp. 33173-124-33173-128.

R. Periodic operating reports & related correspondence

8510210292 Monthly operating rept for Sept 1985. W/851010 ltr.
RUITER, G.H. HINTZ, D.C. Wisconsin Public Service Corp. 85/09/30. 5pp. 33095-077-33095-081.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510070295 Advises that written & oral operator & senior operator licensing exams scheduled for wk of 851216. Listed ref mail requested by 851115.
REYES, L.A. Region 3, Office of Director. 85/10/03. STEINHARDT, C.R. Wisconsin Public Service Corp. 5pp. 32878-088-32878-092.

84 DOCKETED ITEMS

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8510080505** Rev 8 to Corporate Nuclear Emergency Implementing Procedure EPIP 1.1.7, "Startup & Operation of Headquarters Emergency Ctr." W/850927 ltr. FEY,F.L. Northern States Power Co. 85/09/27. 22pp. 32920:217-32920:235.
- 8510080345** Ack receipt of 850710 changes to Rev 8 to emergency plan. Changes consistent w/10CFR50.54(q) requirements & acceptable. Notes that Figure 8-3, "Notifications," added to Section 8.0. SHAFER,W.D. Region 3, Office of Director. 85/10/03. LARSON,C.E. Northern States Power Co. 2pp. 32918:356-32918:357.
- 8510160181** Resubmits 850916 revs to listed emergency plan implementing procedures, including Rev 35 to Procedure F3, "Table of Contents," & Rev 4 to Procedure F3-9, "Emergency Evacuation," due to error in printing process. FEY,F.L. Northern States Power Co. 85/10/03. Region 3, Office of Director. 2pp. 33021:254-33021:286.
- 8510240242** Revised emergency plan implementing procedures, including Rev 6 to EPIP 1.1.1 re corporate emergency response organization & Rev 12 to EPIP 1.1.5 re startup & operation of emergency operations facility W/851007 ltr. FEY,F.L. Northern States Power Co. 85/10/07. 56pp. 33155:266-33155:321.
- 8510160179** Ack receipt of FEMA findings re evaluation of State of MN & local emergency plans. Plans adequate. SHAFER,W.D. Region 3, Office of Director. 85/10/08. LARSON,C.E. Northern States Power Co. 2pp. 33021:287-33021:289.
- 8510160189** Advises that state & local plans for radiological emergencies adequate sub. to criteria of App 3, Rev 1 to NUREG-0654/FEMA-REP-1 & FEMA-43, "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants." SPECK,S.W. Federal Emergency Management Agency. 85/09/24. DIRCKS,W.J. Office of the Executive Director for Operations. 1p. 33021:289-33021:289.
- 8510280443** Forwards safety evaluation & EG&G technical evaluation rept accepting 830415, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/Rev 2 to Reg Guide 1.97. BUTCHER,E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF,D.M. Northern States Power Co. 3pp. 33196:270-33196:295.
- 8510280448** Safety evaluation accepting util 830415, 0915, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/Rev 2 to Reg Guide 1.97. * Office of Nuclear Reactor Regulation, Director. 85/10/18. 2pp. 33196:273-33196:295.
- 8510280451** "Conformance to Reg Guide 1.97, Prairie Island Nuclear Generating Plant, Units 1 & 2." UDY,A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.) FIN A-6483. 85/08/31. Division of Systems Integration (post 811005). 21pp. 33196:275-33196:295.
- 8510310304** Revised emergency plan implementing procedures, including Rev 5 to F3-7 re activation & operation of operational support ctr & Rev 8 to F3-15 re responsibilities of radiation survey teams W/851023 ltr. FEY,F.L. Northern States Power Co. 85/10/23. 91pp. 33272:277-33272:304.

I. Financial information

- 8510310004** Informs that 851008 submittal of financial info for 1985 satisfies requirements of 10CFR140.21 re licensee maint of approved guarantee of payment of deferred premiums for each operating reactor over 100 MW. SALTZMAN,J. Assistant Director for State & License Relations. 85/10/24. HALL,E.J. Northern States Power Co. 1p. 33277:108-33277:108.

P. Operating license stage documents & correspondence

- 8510010299** Provides confirmation of willingness to assist in resolution of Generic issue 77 per NRC 850806 request. Util will provide requested drainage sys info by 851130. MUSOLF,D. Northern States Power Co. 85/09/18. Office of Nuclear Reactor Regulation, Director. 1p. 32804:096-32804:096.
- 8510040444** Advises that 831202 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing acceptable. Conclusion supported by encl EG&G Idaho, Inc rept. VARGA,S.A. Operating Reactors Branch 1. 85/09/19. HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 32859:315-32859:316.
- 8509060182** "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Ginna, Kewaunee Point Beach Units 1 & 2 & Prairie Island Units 1 & 2." HAROLDSEN,R.O. EG&G Idaho, Inc. (subs. of EG&G, Inc.) FIN D-6001, EA-700\ 85/07/31. NRC - No Detailed Affiliation Given. 15pp. 32859:317-32859:331.
- 8510090209** Provides addl info re NUREG-0737, Item I.D.1, "Performance Testing of Relief & Safety Valves," in response to NRC 850214 request. MUSOLF,D. Northern States Power Co. 85/09/26. Office of Nuclear Reactor Regulation, Director. 12pp. 32942:140-32942:335.
- 8510090221** "Pressurizer Safety & Relief Line Evaluation Summary Rept - Prairie Island Nuclear Generating Station, Unit 2." VALASEK,L.M., ANTAKI,G.A. Westinghouse Electric Corp. 84/02/29. 78pp. 32942:231-32942:308.
- 8510090227** "Summary Rept for Evaluation of Pipe Supports for Pressurizer Safety & Relief Line." DYKSTRA,P., DICKERSON,B., BARTHOLOMEW,G. Fluor Corp. 85/08/15. 27pp. 32942:309-32942:335.
- 8510040592** IN-PLANT SOURCE TERM MEASUREMENTS AT PRAIRIE ISLAND NUCLEAR GENERATING STATION. MANDLER,J.W., STALKER,A.C., CRONEY,S.T. EG&G Idaho, Inc. (subs. of EG&G, Inc.) FIN A-6075. NUREG/CR-4397. 85/09/30. Division of Engineering Technology. 250pp. 32863:172-32865:016.

8510070449 Forwards response to Generic Ltr 85-12, "Implementation of TMI Action Item II.K.3.5 re Automatic Trip of Reactor Coolant Pumps." MUSOLF,D. Northern States Power Co. 85/10/01. Office of Nuclear Reactor Regulation, Director. 6pp. 32878:282-32878:287.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues. BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510170463 Forwards Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively & safety evaluations. Proprietary safety evaluation withheld. BUTCHER,E.J. Operating Reactors Branch 3. 85/10/11. MUSOLF,D.M. Northern States Power Co. 3pp. 33045:134-33045:164.

-8510170466 Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively, modifying Tech Specs to allow tube sleeving method for repairing steam generator tubes. BUTCHER,E.J. Operating Reactors Branch 3. 85/10/11. 12pp. 33045:137-33045:148.

-8510170467 Nonproprietary safety evaluation supporting Amends 76 & 69 to Licenses DPR-42 & DPR-60, respectively. * Office of Nuclear Reactor Regulation, Director. 85/10/11. 16pp. 33045:149-33045:164.

8510180063 Provides proposed schedule for compliance w/requirements of 10CFR50.62(d) & Generic Ltr 85-06 re reduction of risk from ATWS events for light water-cooled plants & QA guidance for ATWS equipment that is not safety-related, respectively. MUSOLF,D. Northern States Power Co. 85/10/11. Office of Nuclear Reactor Regulation, Director. 2pp. 33063:085-33063:086.

8510280409 Forwards safety evaluation re util 850422 & 0830 ltrs concerning removal of rod cluster control guide tube thimble plugs. Plan acceptable. BUTCHER,E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF,D.M. Northern States Power Co. 2pp. 33228:121-33228:139.

-8510280412 Safety evaluation re util 850422 & 0830 ltrs concerning removal of rod cluster control guide tube thimble plugs. Plan acceptable. * Office of Nuclear Reactor Regulation, Director. 85/10/18. 17pp. 33228:123-33228:139.

8510290437 Accepts 831104 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing requirements that degrade rather than enhance safety. No degradation of post-maint testing requirements found. BUTCHER,E.J. Operating Reactors Branch 3. 85/10/18. MUSOLF,D.M. Northern States Power Co. 2pp. 33254:348-33254:349.

8510310366 Responds to NUREG-0737, Item IIF.2, "Inadequate Core Cooling Instrumentation." Addl info re core exit thermocouple backup display & model reactor vessel level indication sys draft Tech Specs encl. MUSOLF,D. Northern States Power Co. 85/10/22. Office of Nuclear Reactor Regulation, Director. 5pp. 33271:314-33271:318.

Q. Inspection reports, IE Bulletins & correspondence

8510010101 Forwards Safety Insp Repts 50-282/85-17 & 50-306/85-14 on 850823-29. No violation noted. HARRISON,J.J. Region 3, Office of Director. 85/09/25. LARSON,C.E. Northern States Power Co. 2pp. 32800:072-32800:079.

-8510010112 Insp Repts 50-282/85-17 & 50-306/85-14 on 850823-29. No violation or deviation noted. Major areas inspected: licensee actions on previous insp findings. GAUTAM,A.S., TANI,K., WILLIAMS,C.C. Region 3, Office of Director. 85/09/24. 6pp. 32800:074-32800:079.

8509260122 IE info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080101 Submits steam generator tube plugging info, per Tech Spec 4.12 E.1. Results of in-service insp 19 tubes plugged, including 7 tubes in Steam Generator 21 & 12 tubes in Steam Generator 22 (1.6% & 3.2%, respectively). MUSOLF,D. Northern States Power Co. 85/10/02. Office of Nuclear Reactor Regulation, Director. 1p. 32918:342-32918:342.

8510160114 Forwards Insp Repts 50-282/85-20 & 50-306/85-18 on 850916-20. No non-compliance noted. SHAFER,W.D. Region 3, Office of Director. 85/10/10. LARSON,C.E. Northern States Power Co. 2pp. 33024:084-33024:094.

-8510160125 Insp Repts 50-282/85-20 & 50-306/85-18 on 850916-20. No violation or deviation noted. Major areas inspected: radiation protection program during Unit 2 refueling activities & Unit 1 operational activities re solid radwaste. GRANT,W.B., GREGER,L.R. Region 3, Office of Director. 85/10/10. 9pp. 33024:086-33024:094.

8510220002 Forwards Safety Insp Repts 50-282/85-19 & 50-306/85-18 on 850917-19 & 1001 & notice of violation. SHAFER,W.D. Region 3, Office of Director. 85/10/10. LARSON,C.E. Northern States Power Co. 2pp. 33095:339-33095:349.

-8510220003 Notice of violation from insp on 850917-19, 26 & 1001. SHAFER,W.D. Region 3, Office of Director. 85/10/10. 2pp. 33095:341-33095:342.

-8510220004 Insp Repts 50-282/85-19 & 50-306/85-18 on 850917-19,26 & 1001. Violation noted: failure to follow procedures associated w/ restoration of liquid radwaste sys following maint & w/ subsequent liquid radwaste release.
HUEYER, L.J., OESTMANN, M.J., SCHUMACHER, M.C. Region 3, Office of Director. 85/10/09. 7pp. 33095:343-33095:349.

8510240589 Forwards safety evaluation of 850809 relief request from inservice insp requirements re hydrostatic pressure testing of pipe section in charging sys & surface exam of valve pressure boundary. Relief granted.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/11. MUSOLF, D.M. Northern States Power Co. 2pp. 33185:209-33185:214.

-8510240601 Safety evaluation re 850809 inservice insp of components Relief Requests 29 & 66. Alternative acceptable & relief should be granted.
Office of Nuclear Reactor Regulation, Director. 85/10/11. 4pp. 33185:211-33185:214.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510310137 Responds to NRC 850920 ltr re violations noted in Insp Repts 50-282/85-15 & 50-306/85-12. Corrective actions program of steam generator snubber insp & testing underway. LER procedures implemented & Westinghouse reviewing specs.
LARSEN, C.E. Northern States Power Co. 85/10/18. HARRISON, J.J. Region 3, Office of Director. 2pp. 33274:058-33274:059.

8510250129 Forwards Safety Insp Repts 50-282/85-18 & 50-306/85-15 on 850926-27. No violation or deviation noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/21. LARSON, C.E. Northern States Power Co. 2pp. 33172:073-33172:080.

-8510250137 Insp Repts 50-282/85-18 & 50-306/85-15 on 850926-27. No violation or deviation noted. Major areas inspected: large capacity snubbers installed on steam generators.
YIN, I.T., DANIELSON, D.H. Region 3, Office of Director. 85/10/21. 6pp. 33172:075-33172:080.

8510260298 Forwards addendum to Insp Repts 50-282/84-14 & 50-306/84-16, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sampler collected during insp.
SHAFFER, W.D. Region 3, Office of Director. 85/10/22. LARSON, C.E. Northern States Power Co. 1p. 33194:008-33194:009.

-8510260304 Addendum to Insp Repts 50-282/84-14 & 50-306/84-16, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sampler collected during insp.
Region 3, Office of Director. 85/10/22. 1p. 33194:009-33194:009.

8510280385 Forwards Safety Insp Rept 50-306/85-17 on 850916-18 & 1001. No violations noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/22. LARSON, C.E. Northern States Power Co. 1p. 33192:156-33192:167.

-8510280386 Safety Insp Rept 50-306/85-17 on 850916-18 & 1001. No violations or deviations noted. Major areas inspected: inservice safety activities & auxiliary feedwater sys mod.
WARD, K.D., DANIELSON, D.H. Region 3, Office of Director. 85/10/21. 6pp. 33192:157-33192:162.

R. Periodic operating reports & related correspondence

8510010650 Monthly operating reports for Jul 1985 W/850805 ltr.
DUGSTAD, D., MUSOLF, D. Northern States Power Co. 85/07/31. 9pp. 32820:193-32820:201.

8510230121 Forwards revised Pages 6-8 & Attachment 1 to "Semiannual Effluent & Waste Disposal Rept for Jan-June 1985," incorporating Fe-55 analysis results.
FEY, F.L. Northern States Power Co. 85/10/01. Region 3, Office of Director. 1p. 33108:167-33108:171.

-8510230124 Revised Pages 6-8 & Attachment 1 to "Semiannual Effluent & Waste Disposal Rept for Jan-June 1985," incorporating Fe-55 analysis results.
Northern States Power Co. 85/06/30. 4pp. 33108:168-33108:171.

S. Reportable occurrences, LERs & related correspondence

8510010306 Preliminary Part 21 rept re 3.5-inch crack on snubber ball bearing. Vendor attempting to have bearing returned for exam & evaluation by SKF Industries. Next rept will be submitted when significant info available.
LAURENSEN, A.S. ITT Grinnell Corp. (subs. of ITT Corp.). 85/09/26. Director's Office, Office of Inspection and Enforcement. 2pp. 32801:274-32801:275.

8510220062 Second preliminary Part 21 rept re hairline crack in bearing. Bearing will not be returned for exam. Bearing sent to Westinghouse.
LAURENSEN, A.S. ITT Grinnell Corp. (subs. of ITT Corp.). 85/10/15. Director's Office, Office of Inspection and Enforcement. 1p. 33090:154-33090:154.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

8510250244 Public version of Rev 11 to Emergency Plan Implementing Procedure 2.50.17, "Emergency Notification." W/851021 release memo.
Maine Yankee Atomic Power Co. 85/10/03. 15pp. 33226:187-33226:201.

8510170061 Forwards resolutions to questions re DCRDR & final draft "Control Panel Enhancement Stds," per telcon. Util provided human factors training to plant engineering staff. Expertise of qualified consultant available.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 7pp. 33036:321-33036:348.

-8510170075 Final draft "Control Panel Enhancement Stds."
Maine Yankee Atomic Power Co. 85/08/17. 21pp. 33036:328-33036:348.

8510250229 Revised emergency plan implementing procedures, including Rev 9 to 2.50.1 re notification of unusual event & Rev 7 to 2.50.12 re emergency offsite radiation monitoring procedure.
Maine Yankee Atomic Power Co. 85/10/21. 40pp. 33169:035-33169:074.

P. Operating license stage documents & correspondence

8510080097 Forwards Amend 85 to License DPR-36 & safety evaluation. Amend modifies Tech Specs to reflect Cycle 9 power distributions, insertion limits & peaking factors & describes max reactor inlet temp used in modified safety analyses.
SEARS, P.M. Operating Reactors Branch 3. 85/09/30. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 32926:011-32926:047.

-8510080102 Amend 85 to License DPR-36, modifying Tech Specs to reflect Cycle 9 power distributions, insertion limits & peaking factors & describe max reactor inlet temp used in modified safety analyses.
BUTCHER, E.J. Operating Reactors Branch 3. 85/09/30. 20pp. 32926:013-32926:032.

-8510080106 Safety evaluation supporting Amend 85 to License DPR-36.
Office of Nuclear Reactor Regulation, Director. 85/09/30. 15pp. 32926:033-32926:047.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510170133 Forwards topical rept evaluation supporting YAE-1447, "Application of RETRAN-3D/MOD 02 & BIRP to Analysis of Main Steam Line Break Accident at Maine Yankee Atomic Power Co."
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/02. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 33043:166-33043:170.

-8510170137 Topical rept evaluation supporting YAE-1447, "Application of RETRAN-3D/MOD 02 & BIRP to Analysis of Main Steam Line Break Accident at Maine Yankee Atomic Power Co."
Office of Nuclear Reactor Regulation, Director. 85/10/02. 3pp. 33043:168-33043:170.

8510070268 Application for amend to License DPR-36, consisting of Suppl 1 to Proposed Change 120, replacing pages of Tech Specs re turbine-driven auxiliary feedwater pump.
RANDAZZA, J.B. Maine Yankee Atomic Power Co. 85/10/03. Office of Nuclear Reactor Regulation, Director. 2pp. 32877:328-32877:332.

-8510070282 Suppl 1 to Proposed Change 120, replacing Pages 3.8-2 & 3.8-3 w/3.8-2.3.8-3 & 3.8-4 re turbine-driven auxiliary feedwater pump.
Maine Yankee Atomic Power Co. 85/10/03. 3pp. 32877:330-32877:332.

8510080551 Requests remittance of fee for 850807 application requesting relief from certain ASME Code requirements re inservice testing.
DIGGS, R.M. License Fee Management Branch. 85/10/03. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 1p. 32923:157-32923:157.

8510110031 Application for amend to License DPR-36, consisting of Proposed Change 114, Suppl 1, changing Tech Spec Pages 3.11-2 & 3.11-5 re containment isolation valves under administrative controls.
RANDAZZA, J.B. Maine Yankee Atomic Power Co. 85/10/07. Record Services Branch (Document Control Desk). 3pp. 32973:226-32973:230.

-8510110035 Proposed Change 114, Suppl 1, revising Tech Spec Pages 3.11-2 & 3.11-5 re containment isolation valves under administrative controls.
Maine Yankee Atomic Power Co. 85/10/07. 2pp. 32973:229-32973:230.

8510150387 Submits info supporting util belief that 850423 Proposed Change 114 to Tech Specs re repositioning of certain manual containment isolation valves does not involve significant hazard consideration. Valves not active components of RCS.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/07. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33010:154-33010:155.

8510220160 Application for amend to License DPR-36, consisting of Proposed Change 121, deleting & revising Tech Spec requirement for emergency diesel generator testing in event that auxiliary component in one train of cooling sys inoperable. Fee paid.
RANDAZZA, J.B. Maine Yankee Atomic Power Co. 85/10/16. Record Services Branch (Document Control Desk). 2pp. 33082:258-33082:260.

86 DOCKETED ITEMS

-8510220165 Proposed Tech Spec deleting present requirement for emergency diesel generator testing in event that any component in one train of cooling sys becomes inoperable.
* Maine Yankee Atomic Power Co. 85/10/16. 1p. 33082:260-33082:260.

8510240301 Forwards "Comparison of Maine Yankee Atomic Power Plant W/Seismic Qualification Util Group Seismic Experience Data Base," per 841029 request. Work will continue towards resolution of Generic Issue A-46.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/18. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33151:176-33151:304.

-8510240310 "Comparison of Maine Yankee Atomic Power Plant W/Seismic Qualification Util Group Seismic Experience Data Base."
* EQE, Inc. 85/09/30. 150pp. 33151:178-33151:304.

8510280263 Accepts 831104 response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 re post-maint testing of reactor trip sys & all other safety-related equipment. No post-maint test requirements identified in Tech Specs that degrade safety.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/21. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 33228:235-33228:236.

Q. Inspection reports, IE Bulletins & correspondence

8510030037 Forwards Safety Insp Rept 50-309/85-23 on 850826-30. No violations noted.
EBNETER, S.D. Region 1, Office of Director. 85/09/18. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 32846:088-32846:094.

-8510030053 Insp Rept 50-309/85-23 on 850826-30. No violations noted. Major areas inspected: inservice insp program, NDE procedure review, observation of work in progress & review of inservice insp data.
MCBREARTY, R.A. WIGGINS, J.T. Region 1, Office of Director. 85/09/11. 5pp. 32846:090-32846:094.

8510030095 Submits addl info on review of turbine bldg Elevation 21 ft masonry wall adjacent to HX E-4A, in response to NRC 840918-19 site insp. per IE Bulletin 80-11 re masonry wall design. Sketches encl.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/09/24. BUTCHER, E.J. Operating Reactors Branch 3. 4pp. 32842:209-32842:212.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070068 Forwards Safety Insp Rept 50-309/85-21 on 850819-23. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/01. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 32881:057-32881:066.

-8510070073 Insp Rept 50-309/85-21 on 850819-23. No violation noted. Major areas discussed: radiochemical measurements program using NRC's Mobile Radiological Measurements Lab & DOE lab assistance.
STRUCKMEYER, R. TUCCINARDI, E. SHANBAKY, M.M. Region 1, Office of Director. 85/09/26. 8pp. 32881:059-32881:066.

8510080119 Forwards Enforcement Conference Rept 50-309/85-25 on 850909. Conference convened to discuss results of investigation into isolation of nine steam generator pressure transmitters.
STAROSTECKI, R. Region 1, Office of Director. 85/10/03. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 32951:150-32951:194.

-8510080121 Enforcement Conference Rept 50-309/85-25 on 850909. Areas discussed: isolation of nine steam generator pressure transmitters & inoperability of Channel A low steam generator trip function. Viewgraphs encl.
ELSASSER, T.C. WENZINGER, E.C. Region 1, Office of Director. 85/09/26. 23pp. 32919:013-32919:035.

8510080179 Advises that listed steam generator tubes plugged during insp on 850920-24. Addl info will be included in inservice insp rpt scheduled for submittal in Jan 1986.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/03. BUTCHER, E.J. Operating Reactors Branch 3. 1p. 32922:075-32922:075.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230034 Forwards Safety Insp Rept 50-309/85-26 on 850910-13. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 33101:054-33101:059.

-8510230047 Safety Insp Rept 50-309/85-26 on 850910-13. No violation noted. Major areas inspected: radiation protection program during outage, including external dosimetry, outstanding items, training, surveys & exposure control.
CLEMONS, P. SHANBAKY, M. Region 1, Office of Director. 85/10/17. 4pp. 33101:056-33101:059.

8510280369 Advises that review of util files indicated that actions required to closeout IE Bulletin 79-04 accomplished, contrary to NUREG/CR-4003. Weight discrepancies subsequently found acceptable as part of bulletin review.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/22. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33194:006-33194:007.

R. Periodic operating reports & related correspondence

8510010637 Monthly operating rpt for Jul 1985 W/850809 ltr.
TAYLOR, J.M. WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/07/31. 5pp. 32820:325-32820:329.

S. Reportable occurrences, LERs & related correspondence

8510020274 PNO-I-85-071A on 850927. Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage.
STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825:232-32825:232.

8510090417 LER 85-010-00 on 850903. Low steam generator pressure trip Channel A found inoperable. Caused by installation of subcooling margin monitors resulting in erroneous output signal. Monitor circuitry will be redesigned W/851003 ltr.
MCDOUGOLD, D.P. WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/03. 3pp. 32946:154-32946:156.

8510240640 LER 85-011-00 on 850916. ECCS partially activated. Caused by accidental displacement of safety injection signal blocking devices. Addl devices installed to prevent subsequent activation W/851016 ltr.
MCGRATH, R.S. WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/16. 3pp. 33157:220-33157:222.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510240418 Forwards operator licensing exam schedule requested in NRC 850927 ltr re Generic Ltr 85-18.
WHITTIER, G.D. Maine Yankee Atomic Power Co. 85/10/16. SOGER, B. Assistant Director for Operating Reactors. 3pp. 33151:117-33151:120.

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510020214 Responds to 850830 request for approval to hold one emergency medical assistance drill on 851106 to meet criteria to test medical response capability for emergency plans. Proposal acceptable.
MURLEY, T.E. Region 1, Office of Director. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 1p. 32827:214-32827:215.

-8510020226 Requests approval to hold one instead of two emergency medical assistance drills. Annual drill scheduled for 851108. Drills involve same teams of onsite & offsite personnel & would meet redundant requirement.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/08/36. MURLEY, T.E. Region 1, Office of Director. 1p. 32827:215-32827:215.

8510030087 Rev 85-10 to emergency plan procedures manual, including Rev 23 to index. Rev 9 to Addendum 1 re index & Rev 2 to Addendum 2 re event classification guide. Distribution list W/850926 ltr.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/09/26. VARGA, S.A. Operating Reactors Branch 1. 38pp. 32844:085-32844:121.

8510060375 Trip rpt of 850925 site visit re emergency operating procedures (EOPs) audit per Suppl 1 to NUREG-0737. Licensee not generating EOPs per procedures generation package & TMI Action Plan Item 1.C.1. Attendance list encl.
CLAYTON, H.B. Procedures & Systems Review Branch. 85/10/02. ZIEMANN, D.L. Division of Human Factors Safety. 4pp. 32965:058-32965:061.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:088.

-8510230150 Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/emergencies.
KAMMERER, C. Office of Congressional Affairs. 85/03/26. MARKEY, E. House of Rep., Energy & Commerce. HUGHES House of Rep. 3pp. 33109:065-33109:067.

8510170161 Notification of 851010 meeting w/util in Bethesda, MD to discuss emergency operating procedure audit re procedure generation packages.
FISCHER, D.C. Operating Reactors Branch 1. 85/10/07. DENTON, H., EISENHUT, D., LYONS, J. NRC - No Detailed Affiliation Given. 2pp. 33043:109-33043:110.

8510160226 Forwards Safety Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Significant progress in improving emergency preparedness program noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/09. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33023:247-33023:257.

-8510160231 Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Major areas inspected: emergency preparedness program w/emphasis on review of deficient areas noted in Insp Repts 50-272/84-39 & 50-311/84-38.
VITO, D.J., GORDON, C.Z., HARPSTER, T.L. Region 1, Office of Director. 85/10/07. 9pp. 33023:249-33023:257.

J. Insurance & indemnity information

- 8510090261 Forwards Endorsement 80 to NELIA Policy NF-230 & Endorsement 35 to MAELU Policy MF-90.
MURATA, Marsh & McLennan, Inc. 85/10/03. DINITZ, J. Assistant Director for State & License Relations. 3pp. 32943:031-32943:033.

P. Operating license stage documents & correspondence

- 8510170382 Forwards Vols 1 & 2 of App 1, "Methods, Mats & Rationale," to "Salem Generating Station 316(b) Demonstration," re Clean Water Act. Microfiche also encl. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/07/03. MURLEY, T.E. Region 1, Office of Director. 2pp. 33064:192-33067:338.
- 8510170387 Vols 1 & 2 of App 1, "Methods, Mats & Rationale," to "Salem Generating Station 316(b) Demonstration."
* Public Service Electric & Gas Co. of New Jersey. 85/04/30. 1,200pp. 33064:194-33067:338.
- 8510040518 Forwards Amends 67 & 42 to Licenses DPR-70 & DPR-75, respectively & safety evaluation. Amends add Tech Specs incorporating post-accident sampling program requirements.
FISCHER, D. Operating Reactors Branch 1. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32863:134-32863:147.
- 8510040522 Amends 67 & 42 to Licenses DPR-70 & DPR-75, respectively, adding Tech Specs to incorporate post-accident sampling program requirements.
VARGAS, A. Operating Reactors Branch 1. 85/09/16. 10pp. 32863:136-32863:145.
- 8510040528 Safety evaluation supporting Amends 67 & 42 to Licenses DPF & DPR-75, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/16. 2pp. 32863:146-32863:147.
- 8510040533 Forwards Amend 40 to License DPR-75 & safety evaluation. Amend revises Tech Spec Section 3.1.2.1 to correct typo.
FISCHER, D. Operating Reactors Branch 1. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32863:148-32863:155.
- 8510040537 Amend 40 to License DPR-75, revising Tech Spec Section 3.1.2.1 re surveillance requirements for boron injection sys to correct typo.
VARGAS, A. Operating Reactors Branch 1. 85/09/16. 4pp. 32863:150-32863:153.
- 8510040541 Safety evaluation supporting Amend 40 to License DPR-75.
* Office of Nuclear Reactor Regulation, Director. 85/09/16. 2pp. 32863:154-32863:155.
- 8510070023 Forwards Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively & safety evaluation. Amends change Tech Specs to add surveillance requirement re testing of safety injection pumps.
FISCHER, D. Operating Reactors Branch 1. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32901:080-32901:091.
- 8510070027 Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively, adding Tech Spec surveillance requirement re testing of safety injection pumps.
VARGAS, A. Operating Reactors Branch 1. 85/09/16. 8pp. 32901:082-32901:089.
- 8510070032 Safety evaluation supporting Amends 66 & 41 to Licenses DPR-70 & DPR-75, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/16. 2pp. 32901:090-32901:091.
- 8510080108 Responds to NRC 850628 request for addl info re TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," per Generic Ltr 85-12.RCS pressure less than 1,450 psig selected as basic criterion for tripping pumps.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/04. THOMPSON, H.L. Division of Licensing. 12pp. 32913:214-32913:225.
- 8510220270 Submits clarification re Paragraphs 17.2.2 & 17.2.5 of QA program, per R Winters 850926 telcon request. Clarification reviewed & approved on 851004 & will be incorporated in next updated FSAR change.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/08. MURLEY, T.E. Region 1, Office of Director. 3pp. 33083:360-33083:361.
- 8510220068 Provides proposed schedule for meeting requirements of ATWS rule & brief description of tentative design being considered to meet requirements of 10CFR50.62(c)(1).
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/11. VARGAS, A. Operating Reactors Branch 1. 2pp. 33081:309-33081:310.
- 8510240649 Informs that radiation protection/chemistry managers for facilities duly authorized representatives to sign all State of NJ pollution discharge elimination sys related correspondence & repts.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/15. CAPOALE, G. New Jersey, State of. 1p. 33157:214-33157:214.
- 8510220050 Forwards response to NRC 850722 request for addl info on Generic Ltr 83-28, Item 4.5.3 re intervals for online testing. Testing frequencies in 851017 application for Tech Spec change will be used.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGAS, A. Operating Reactors Branch 1. 2pp. 33081:296-33081:297.
- 8510220262 Application for amends to Licenses DPR-70 & DPR-75, changing Tech Specs re analog rod position indication sys. Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGAS, A. Operating Reactors Branch 1. 3pp. 33087:090-33087:128.
- 8510220265 Proposed Tech Spec changes, improving method of calibr of analog rod position indication sys. Significant hazards consideration evaluation encl.
* Public Service Electric & Gas Co. of New Jersey. 85/10/16. 36pp. 33087:093-33087:128.
- 8510250081 Application for amend to Licenses DPR-70 & DPR-75, adding specs per Generic Ltr 83-28, Item 4.3, "Reactor Trip Breaker Automatic Shunt Trip." Fee paid.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/17. VARGAS, A. Operating Reactors Branch 1. 8pp. 33173:129-33173:144.

- 8510250092 Proposed Tech Specs adding specs per Generic Ltr 83-28, Item 4.3, "Reactor Trip Breaker Automatic Shunt Trip."
* Public Service Electric & Gas Co. of New Jersey. 85/10/17. 8pp. 33173:137-33173:144.

Q. Inspection reports, IE Bulletins & correspondence

- 8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.
- 8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230150 Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/emergencies.
KAMMERER, C. Office of Congressional Affairs. 85/03/26. MARKEY, E. House of Rep., Energy & Commerce. BRADLEY, LAUTENBERG Senate. 3pp. 33109:065-33109:067.
- 8510110166 Forwards Mgt Meeting Repts 50-272/85-22 & 50-311/85-25 on 850925. STAROSTECKI, R. Region 1, Office of Director. 85/10/07. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 32973:118-32973:153.
- 8510110171 Mgt Meeting Repts 50-272/85-22 & 50-311/85-25 on 850925. Major areas discussed: status & closeout of util action plan, submitted in Aug 1985, for improvement of nuclear dept operations & performance indicators of upward trend.
LIMROTH, D.F., NORRHOLM, L.J. Region 1, Office of Director. 85/10/02. 34pp. 32973:120-32973:153.
- 8510160226 Forwards Safety Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Significant progress in improving emergency preparedness program noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/09. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33023:247-33023:257.
- 8510160231 Insp Repts 50-272/85-16 & 50-311/85-18 on 850708-11. No violation noted. Major areas inspected: emergency preparedness program w/emphasis on review of deficient areas noted in Insp Repts 50-272/84-39 & 50-311/84-38.
VITO, D.J., AMATO, C.G., COHEN, J. Region 1, Office of Director. 85/10/07. 9pp. 33023:249-33023:257.
- 8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:295-33177:341.
- 8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLMs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:301-33177:368.
- 8510220177 Forwards Safety Insp Repts 50-272/85-20 & 50-311/85-22 on 850901-30 & notice of violation.
COLLINS, S.J. Region 1, Office of Director. 85/10/17. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33087:294-33087:308.
- 8510220192 Insp Repts 50-272/85-20 & 50-311/85-22 on 850901-30. Violation noted: failure to provide adequate procedural guidance re calculating reactor coolant inventory balance (leak-rate).
LIMROTH, D.F., NORRHOLM, L.J. Region 1, Office of Director. 85/10/10. 12pp. 33087:297-33087:308.
- 8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.
- 8510250493 Forwards Safety Insp Repts 50-272/85-21 & 50-311/85-23 on 850909-13. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/21. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 33172:271-33172:278.
- 8510250497 Safety Insp Repts 50-272/85-21 & 50-311/85-23 on 850909-13. No violation or deviation noted. Major areas inspected: routine radiological surveys & area postings, organization & staffing & whole body counting program.
DRAGOUN, T., SHANBAKY, M. Region 1, Office of Director. 85/10/18. 6pp. 33172:273-33172:278.

R. Periodic operating reports & related correspondence

- 8510180471 Forwards "Artificial Island Radiological Environ Monitoring Program, 1984 Radiological Rept."
LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey. 85/03/26. MURLEY, T.E. Region 1, Office of Director. 2pp. 33068:064-33068:227.
- 8510180474 "Artificial Island Radiological Environ Monitoring Program, 1984 Radiological Rept."
* PSE&G Research Corp. RTL-ENV-85-01. 84/12/31. 167pp. 33068:066-33068:227.

88 DOCKETED ITEMS

8510080086 Forwards "NPDES Discharge Monitoring Rept for Aug 1985."
TREJO,J. Public Service Electric & Gas Co. of New Jersey. 85/09/17. RADOW,E.
Trenton, NJ. 3pp. 32928-091-32928-111.

-8510080091 "NPDES Discharge Monitoring Rept for Aug 1985."
* Public Service Electric & Gas Co. of New Jersey. 85/08/31. 18pp. 32928-094-32928-111.

8510080206 Forwards corrected monthly operating repts for Jul & Aug. 1985.Yr-to-date & cumulative gross thermal energy generated values corrected.
ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/23. Director's Office, Office of Inspection and Enforcement. 1p. 32928-071-32928-073.

-8510080209 Corrected monthly operating rept for Aug 1985.
RONAFALVY,J.P. Public Service Electric & Gas Co. of New Jersey. 85/08/31. 1p. 32928-072-32928-072.

-8510080260 Corrected monthly operating rept for Jul 1985.
RONAFALVY,J.P. Public Service Electric & Gas Co. of New Jersey. 85/07/31. 1p. 32928-073-32928-073.

8510240387 Monthly operating rept for Sept 1985.W/851010 ltr.
WHITE,P., RONAFALVY,J.P., ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/30. 10pp. 33180-055-33180-064.

8510240106 Forwards "NPDES Discharge Monitoring Rept for Sept 1985." Rept presents observed results obtained in accordance w/approved methods for sampling & monitoring.
TREJO,J. Public Service Electric & Gas Co. of New Jersey. 85/10/11. RADOW,E. New Jersey, State of. 3pp. 33156-278-33156-298.

-8510240116 "NPDES Discharge Monitoring Rept for Sept 1985."
* Public Service Electric & Gas Co. of New Jersey. 85/09/30. 18pp. 33156-281-33156-298.

8510220315 Forwards "Nuclear Oversight Committee,Eighth Quarterly Rept." dtd 851014.Response to rept will be submitted within 30 days.
MCNEILL,C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/16. VARGA,S.A. Operating Reactors Branch 1. 1p. 33086-283-33086-290.

-8510220319 "Nuclear Oversight Committee,Eighth Quarterly Rept."
* Public Service Electric & Gas Co. of New Jersey. 85/10/14. 7pp. 33086-284-33086-290.

S. Reportable occurrences, LERs & related correspondence

8510010608 LER 85-019-00:on 850911,containment sump in-leakage rate exceeded 1 gallon per minute.Caused by leak from pipe nipple on containment fan coil unit vent line.New nipple installed. W/850925 ltr.
RUPP,J.L., ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/25. 5pp. 32830-005-32830-009.

8510080074 LER 85-018-00:on 850827,component cooling water HX svc water outlet valve (22SW356) [B] failed to closed position. Caused by vibration problems.Valve actuator 22SW356 replaced W/850926 ltr.
RUPP,J.L., ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 85/09/26. 5pp. 32928-113-32928-117.

8510240185 LER 85-020-00:on 850921,manual reactor trip initiated due to pressurizer pressure control problem.Caused by pressurizer spray valve 2P5S off seat.Transducer replaced & spring tension adjusted W/851018 ltr.
RUPP,J.L., ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 85/10/18. 6pp. 33155-242-33155-247.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 841011.Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Wa n Document Service. 7pp. 33108-264-33109-088.

-8510230150 Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/emergencies.
KAMMERER,C. Office of Congressional Affairs. 85/03/26. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-065-33109-087.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER,S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants.Forwards summary sheets for five plants.Portions deleted.Summary sheets for stated plants destroyed.
FELTON,J.M. Division of Rules and Records. 85/09/20. HANAUER,S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.

-8510010428 Power plant exam results summary sheets info deleted.
* Public Service Electric & Gas Co. of New Jersey. * Pennsylvania Power & Light Co. * Commonwealth Edison Co. 85/09/20. 9pp. 32832-355-32833-001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON,H.L. Division of Licensing. 8/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

8510110218 Requests approval of safeguards info records mgt vault that does not specifically meet requirements of 10CFR73.2. Container provides security protection equal to or greater than requirements.
MOORE,R.C. Sacramento Municipal Utility District. 85/07/15. NRC - No Detailed Affiliation Given. 1p. 32971-362-32971-362.

8510030241 Advises that changes to emergency plan submitted by 850702.11 & 17 ltrs compatible w/provisions of 10CFR50.47, App E to 10CFR50 & criteria of Rev 1 to NUREG-0654.Items needing adjusting discussed w/R Myers during 850924 telcon.
FISH,R.F. Region 5, Office of Director. 85/09/25. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 1p. 32845-311-32845-311.

8510080208 Provides cost estimate to install addl circuit in emergency operations facility & requests permission to use certain util property for contingency telecommunications in response to 850719 ltr.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/25. WENSLAWSKI,F.A. Region 5, Office of Director. 1p. 32913-342-32913-342.

8510040240 Forwards addl clarifying info to 850712 response to Generic Ltr 81-12 re alternative shutdown capability for computer & control room.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/27. THOMPSON,H.L. Division of Licensing. 7pp. 32851-059-32851-065.

8510070180 Revised emergency plan implementing procedures,including Rev 18 to AP 500, "Emergency Measures," Rev 2 to AP 580, "Training," Rev 1 to AP 528, "Protective Action Guidance" & Rev 2 to AP 585, "Emergency Assignment Verification."
* Sacramento Municipal Utility District. 85/09/27. 57pp. 32881-137-32881-195.

8510080305 Requests unescorted access of NRC & NRC contractor employees for insp activities on 850930-1004 individuals listed in encl should be provided w/site-specific training in radiological protection,emergency response & security.
MARTIN,J.B. Region 5, Office of Director. 85/09/27. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 2pp. 32928-159-32928-160.

8510080203 Forwards schedule for installation of instrumentation per Reg Guide 1.97 & Suppl 1 to NUREG-0737 during Cycles 8 & 9 startup.Items include core exit temp,coolant inventory & steam generator level.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/30. THOMPSON,H.L. Division of Licensing. 6pp. 32920-254-32920-259.

8510080507 Ack receipt of 850826 ltr informing NRC of steps taken to correct violations in 850815 notice of violation.
MONTGOMERY,J.L. Region 5, Office of Director. 85/10/04. HAMMOND,W.J. Sacramento Municipal Utility District. 1p. 32920-078-32920-078.

851240127 Notifies that review of technical assistance contractor evaluation of 850628 alert & notification sys design addendum will be provided by 851011,per 850911 request. Meeting to be held 851009 to discuss 851026 siren sounding.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/06. VICKERS,R.L. Federal Emergency Management Agency. 1p. 33155-239-33155-239.

8510180524 Responds to 850715 request for approval of record mgt vault for storage of safeguards info.Vault as described meets requirements for storage in protected area.
STOLZ,J.F. Operating Reactors Branch 4. 85/10/16. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 3pp. 33077-221-33077-223.

8510250093 Revs to emergency plan manual.(NUREG-0654) including Pages 20 & 21 of Rev 18 to AP 500 re offsite emergency organization & Rev 2 to AP 526, "Sabotage or Civil Disturbance."
* Sacramento Municipal Utility District. 85/10/16. 13pp. 33220-071-33226-083.

G. Adjudicatory correspondence

8510290151 Forwards D Kaplan ltr to N Isokawa forwarding summons & complaint in Akins vs SMUD.
NISHIMURA,J. Sacramento Municipal Utility District. 85/10/09. MARTIN,J. Region 5, Office of Director. 22pp. 33233-132-33233-153.

J. Insurance & indemnity information

8510080125 Forwards Endorsements 65 & 64 to MAELU Policy MF-75 & Endorsements 76 & 75 to NELIA Policy NF-212.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/23. SALTZMAN,J.D. NRC - No Detailed Affiliation Given. 5pp. 32918-303-32918-307.

P. Operating license stage documents & correspondence

8508270323 Forwards safety evaluation accepting licensee 831104 response to Generic Ltr 83-28,Items 3.1.1 & 3.1.2 re post-maint testing of reactor trip sys components.
STOLZ,J.F. Operating Reactors Branch 4. 85/08/19. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 2pp. 32472-047-32472-050.

-8509040194 Safety evaluation accepting util 831104 & 850621 responses to Generic Ltr 83-28,Items 3.1.1 & 3.1.2 re post-maint testing of reactor trip sys components.
* NRC - No Detailed Affiliation Given. 85/08/19. 2pp. 32472-049-32472-050.

8510080255 Forwards handouts from 850923 meeting re details of discussion concerning results of INPO progress check of plant.Improvements noted in areas previously evaluated as weaknesses.Util proceeding w/startup based on findings.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/23. MARTIN,J.B. Region 5, Office of Director. 102pp. 32920-271-32921-010.

8510080047 Forwards Rev 21 to "Status of LRS Recommendations," per J Eckhardt request. Rept should be used as internal tracking sys for current status of resolution of LRS recommendations.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/24. MARTIN,J.B. Region 5, Office of Director. 1p. 32913:274-32913:293.

-8510080048 Rev 21 to "Status of LRS Recommendations."
* Sacramento Municipal Utility District. 85/09/16. 19pp. 32913:275-32913:293.

8510040002 Discusses licensee participation in B&W integrated reactor vessel mat's surveillance program. Results of second surveillance capsule indicate that present Tech Spec remains valid. Continued operation acceptable.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/30. STOLZ,J.F. Operating Reactors Branch 4. 2pp. 32851:076-32851:077.

8510070157 Forwards SER addressing licensing action re low temp overpressure protection sys. SALP input, draft ltr to licensee, license amend & revised Tech Specs also encl. TAC 59325 closed.
KIRSCH,D.F. Region 5, Office of Director. 85/09/30. THOMPSON,H.L. Division of Licensing. 3pp. 32880:355-32881:014.

8510070278 Submits justification for util living schedule process re ATWS rule requiring licensee to submit schedule for meeting requirements of 10CFR50.62. Mods required can be completed during Cycle 9 refueling outage.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/30. THOMPSON,H.L. Division of Licensing. 2pp. 32877:348-32877:349.

8510080039 Advises that safety evaluation for proposed Amend 102 to License DPR-54 will be provided by 851018, per NRC 850911 request for justification.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/30. THOMPSON,H.L. Division of Licensing. 1p. 32918:297-32918:297.

8510080112 Forwards Amend 76 to License DPR-54 & safety evaluation. Amend revises Tech Specs to provide conformance w/ regulations governing inservice insp & insp of steam generator tubes set forth in 10CFR50.55a(g).
MINER,S. Operating Reactors Branch 4. 85/09/30. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 2pp. 32925:320-32926:010.

-8510080116 Amend 76 to License DPR-54, revising Tech Specs to provide conformance w/ regulations governing inservice insp & insp of steam generator tubes set forth in 10CFR50.55a(g).
STOLZ,J.F. Operating Reactors Branch 4. 85/09/30. 39pp. 32951:107-32951:149.

-8510080120 Safety evaluation supporting Amend 76 to License DPR-54.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 13pp. 32925:361-32926:010.

8510070263 Submits verification results for serial numbers on each IRVSP capsule in Lynchburg Research Ctr storage pool, per Rev 2 to BAW-1543.
TAYLOR,J.H. Babcock & Wilcox Co. 85/10/01. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32877:312-32877:313.

8510210019 Submits fee for review of 850809 submittal re use of new ASME Code Case N-411 on damping valves, per 850911 request.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/14. DIGGS,R.M. License Fee Management Branch. 2pp. 33072:039-33072:040.

8510210059 Rev 2 to proposed Amend 110 to License DPR-54, deleting all refs to current reactor vessel mat's surveillance requirements from Tech Specs.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/14. THOMPSON,H.L. Division of Licensing. 3pp. 33072:063-33072:070.

-8510210066 Tech Spec changes, consisting of Rev 2 to Proposed Change 110, deleting all refs to current reactor vessel mat's surveillance requirements.
* Sacramento Municipal Utility District. 85/10/14. 5pp. 33072:056-33072:070.

8510230116 Advises that response to NRC 850906 questions re Generic Issue 77, "Flooding of Safety Equipment Compartments by Backflow Through Floor Drains," will be provided by 860215.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/18. THOMPSON,H.L. Division of Licensing. 1p. 33102:226-33102:226.

8510280121 Application for amend to License DPR-54, consisting of Proposed Amend 136, changing offsite & onsite organization charts. Fee paid.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/18. THOMPSON,H.L. Division of Licensing. 3pp. 33191:060-33191:068.

-8510280128 Proposed Tech Specs, changing offsite & onsite organization charts.
* Sacramento Municipal Utility District. 85/10/18. 6pp. 33191:063-33191:068.

Q. Inspection reports, IE Bulletins & correspondence

8510080256 EN-85-065 on 850926, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to licensee. Action based on lack of adequate seismic supports for nitrogen supply & vent header sys.
POINDEXTER,T., AXELRAD,J. Director's Office, Office of Inspection and Enforcement. 85/09/23. 1p. 32913:348-32913:348.

8510010481 Advises that several typos & editorial errors in SALP Rept 50-312/85-18 identified during 850916 meeting. Errata sheets & corrected pages encl.
KIRSCH,D.F. Region 5, Office of Director. 85/09/25. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 1p. 32809:100-32809:106.

-8510010483 Corrected Pages 11 & 21 to SALP Rept 50-312/85-18, correcting typos & editorial errors re performance analysis.
* Region 5, Office of Director. 85/09/25. 6pp. 32809:101-32809:106.

8510090324 Discusses insp on 850623-0809 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.
MARTIN,J.B. Region 5, Office of Director. 85/09/26. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 3pp. 32947:118-32947:124.

-8510090328 Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violations noted design basis for Quality Class 1, Seismic Class 1 portion of reactor coolant vent sys not correctly translated into design specs.
MARTIN,J.B. Region 5, Office of Director. 85/09/26. Sacramento Municipal Utility District. 4pp. 32947:121-32947:124.

8510080305 Requests unescorted access of NRC & NRC contractor employees for insp activities on 850930-1004. Individuals listed in encl should be provided w/ site-specific training in radiological protection, emergency response & security.
MARTIN,J.B. Region 5, Office of Director. 85/09/27. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 2pp. 32928:159-32928:160.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Main Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510070157 Forwards SER addressing licensing action re low temp overpressure protection sys. SALP input, draft ltr to licensee, license amend & revised Tech Specs also encl. TAC 59325 closed.
KIRSCH,D.F. Region 5, Office of Director. 85/09/30. THOMPSON,H.L. Division of Licensing. 3pp. 32880:355-32881:014.

8510080112 Forwards Amend 76 to License DPR-54 & safety evaluation. Amend revises Tech Specs to provide conformance w/ regulations governing inservice insp & insp of steam generator tubes set forth in 10CFR50.55a(g).
MINER,S. Operating Reactors Branch 4. 85/09/30. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 2pp. 32925:320-32926:010.

-8510080116 Amend 76 to License DPR-54, revising Tech Specs to provide conformance w/ regulations governing inservice insp & insp of steam generator tubes set forth in 10CFR50.55a(g).
STOLZ,J.F. Operating Reactors Branch 4. 85/09/30. 39pp. 32951:107-32951:149.

-8510080120 Safety evaluation supporting Amend 76 to License DPR-54.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 13pp. 32925:361-32926:010.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080507 Ack receipt of 850826 ltr informing NRC of steps taken to correct violations in 850815 notice of violation.
MONTGOMERY,J.L. Region 5, Office of Director. 85/10/04. HAMMOND,W.J. Sacramento Municipal Utility District. 1p. 32920:078-32920:078.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:058.

8510290286 Comments on SALP Board rept & responds to Category 3 functional areas per 850925 request. Weaknesses in area of radiological controls recognized & procedural improvements implemented.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/17. MARTIN,J.B. Region 5, Office of Director. 3pp. 33236:258-33236:270.

8510150386 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510090266 Forwards discharger self-monitoring rept for Aug 1985, per J Stolz 830311 ltr re NPDES permit.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/20. MARTIN,J.B. Region 5, Office of Director. 1p. 32974:324-32974:327.

8510280007 Monthly operating rept for Sept 1985. W/851018 ltr.
COLOMBO,R. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/30. 9pp. 33194:314-33194:322.

8510290138 Forwards "NPDES Discharge Self-Monitoring Rept for Sept 1985," in response to J Stolz 830311 request. G Coward 851007 ltr forwarding rept to State of CA also encl.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/07. MARTIN,J.B. Region 5, Office of Director. 3pp. 33236:198-33236:203.

-8510290146 "NPDES Discharge Self-Monitoring Rept for Sept 1985."
* Sacramento Municipal Utility District. 85/09/30. 3pp. 33236:201-33236:203.

8510290356 Forwards "NPDES Discharge Self-Monitoring Rept for Sept 1985," in response to J Stolz 830311 request. G Coward 851007 ltr to State of CA also encl.
RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/10/07. STOLZ,J.R. Operating Reactors Branch 4. 3pp. 33239:226-33239:231.

S. Reportable occurrences, LERs & related correspondence

8510020030 LER 85-017-00 on 850906, leakage flow path reported in filtration unit of Auxiliary Bldg A ventilation unit. Caused by omission of seal plate during mfg. Steel plate welded over bypass opening W/850926 ltr.
COLOMBO,R.W. RODRIGUEZ,R.J. Sacramento Municipal Utility District. 85/09/17. MARTIN,J.B. Region 5, Office of Director. 3pp. 32827:345-32827:347.

90 DOCKETED ITEMS

8510080221 Special Rept 85-11: updates list of nonfunctional fire barriers reported in 850812 Special Rept 85-10. Nonfunctional fire barriers detected since last rept but not restored to functional status within 7 days listed.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/09/19. MARTIN, J.B. Region 5, Office of Director. 13pp. 32919-036-32919-048.

8510080501 Submits actions completed to date & schedule for completion of long-term items arising from 850623 high point vent leak. Items required for plant startup completed.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/09/21. MARTIN, J.B. Region 5, Office of Director. 6pp. 32921-104-32921-109.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510070331 PNO-V-85-064 on 850928 reactor achieved criticality. Plant in cold shutdown since 850623 due to 1-inch diameter hot leg vent piping failure. Exams of other piping sys & supports completed. Plant at 40% power.
MILLER, L., ECKHARDT, J.H. Region 5, Office of Director. 85/10/01. 1p. 32877-261-32877-261.

8510080052 PNO-V-85-066 on 851002 loss of main feedwater event occurred. Plant being maintained in hot shutdown condition pending determination of exact scenario, causes & appropriate corrective action. Region evaluating response.
ECKHARDT, J., MILLER, L. Region 5, Office of Director. 85/10/02. 1p. 32919-362-32919-362.

8510150243 Confirmatory action ltr re 851004 telcon concerning return of facility to power operations after 851002 reactor trip. Util must first conduct root cause analysis of trip & provide briefing to NRC before return to power.
MARTIN, J.B. Region 5, Office of Director. 85/10/04. RODRIGUEZ, R.J. Sacramento Municipal Utility District. 1p. 33009-312-33009-312.

8510170348 LER 85-018-00 on 850907 emergency diesel generator A breaker locked out in open position due to simultaneous trip & close signals. Caused by generator voltage exceeding bus trip voltage W/851007 ltr.
COLOMBO, R.W., RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/10/04. MARTIN, J.B. Region 5, Office of Director. 4pp. 33053-317-33053-320.

8510153091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewpoints encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

8510160240 PNO-V-85-071 on 851007 one of two auxiliary feedwater pumps declared inoperable due to failure of pump thrust bearing. Caused by disintegrated thrust bearing due to inadequate lubrication. Bearing replaced.
MYERS, C., ECKHARDT, J. Region 5, Office of Director. 85/10/09. 1p. 33023-235-33023-235.

8510220088 Notification of significant meeting on 851016 w/ util onsite to discuss root cause assessment & readiness for resumption of power operations following 851002 reactor trip.
* Region 5, Office of Director. 85/10/11. Region 5, Office of Director. 1p. 33081-324-33081-324.

8510220173 Forwards action list providing util plan to resolve concerns stemming from 851002 transient, per 851010-11 meetings. Listed commitments scheduled for completion p.k. to restart. Schedule for long-term items will be submitted by 851118.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/10/14. THOMPSON, H.L. Division of Licensing. 13pp. 33090-003-33090-075.

8510220266 Forwards supplemental info re 851002 transient, per NRC request during 851016 meeting. Info includes main feed pump trip determination, HPI, "A" flow anomaly, no shutdown of RCS, cooldown rate, Tech Specs & revised action list.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/10/18. THOMPSON, H.L. Division of Licensing. 22pp. 33085-075-33085-096.

8510240378 Special Rept 85-12 re nonfunctional fire barriers reported in 850919 Special Rept 85-11. Appropriate fire watch established. Schedules provided in Rept 85-11 unchanged. Updated list of barriers encl.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. 85/10/18. MARTIN, J.B. Region 5, Office of Director. 8pp. 33151-328-33151-335.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F. Security, medical, emergency & fire protection plans

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053-256-33053-272.

8510170375 Notice of violation from Insp on 850801-31.
* Region 4, Office of Director. 85/10/03. 2pp. 33053-258-33053-259.

8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D., HARRELL, P.H., MARTIN, L.E. Region 4, Office of Director. 85/10/01. 13pp. 33053-260-33053-272.

8510170402 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-15 & 50-368/85-16.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33053-332-33053-334.

8510170410 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-313/85-15 & 50-368/85-16. Corrective actions: Procedure 2203.09, "Fire Protection Sys Annunciator Corrective Action," Rev 0 revised.
ENOS, J.T. Arkansas Power & Light Co. 85/06/23. DENISE, R.P. Region 4, Office of Director. 2pp. 33053-333-33053-334.

8510160056 Ack receipt of 850429 & 0723 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-12 & 50-368/85-12. Replies responsive to violations w/ exception of meeting 10CFR73.55 requirements re physical security.
JOHNSON, E.H. Region 4, Office of Director. 85/10/09. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33028-132-33028-133.

8510220031 Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098-257-33098-274.

8510180294 Rev 2 to Emergency Plan Implementing Procedure 1903.34, "Emergency Operations Facility Evacuation."
* Arkansas Power & Light Co. 85/10/11. 19pp. 33062-087-33062-105.

8510220322 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-20 & 50-368/85-21.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33088-185-33088-187.

8510220332 Responds to NRC 850822 ltr re deviations noted in Insp Repts 50-313/85-20 & 50-368/85-21. Corrective actions: all ltrs of agreement between util & outside support groups/agencies will be completed by 870101.
ENOS, J.T. Arkansas Power & Light Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 33088-186-33088-187.

8510220120 Revised emergency plan implementing procedures, including Rev 18 to 1903.10, "Emergency Action Level Response/ Notifications," Rev 2 to 1903.13, "Notification of Little Rock Corporate Official" & Rev 9 to 1903.50.
LEVINE, J.M. Arkansas Power & Light Co. 85/10/15. 100pp. 33082-001-33082-094.

8510240328 Forwards addl info re schedules for corrective actions of human engineering discrepancies noted during onsite audit of DCRDR program. Detailed justification & schedule for excepted discrepancies will be provided by 860418.
ENOS, J.T. Arkansas Power & Light Co. 85/10/18. THOMPSON, H.L. Division of Licensing. 8pp. 33151-351-33151-358.

8510250413 Ack receipt of 850728 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-10 & 50-368/85-10.
JOHNSON, E.H. Region 4, Office of Director. 85/10/18. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33172-226-33172-228.

8510250421 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-313/85-10 & 50-368/85-10. Corrective actions: radiological protection procedures stressed in radiological emergency response training for field monitoring teams.
ENOS, J.T. Arkansas Power & Light Co. 85/07/28. MARTIN, R.D. Region 4, Office of Director. 2pp. 33172-227-33172-228.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510220031 Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098-257-33098-274.

P. Operating license stage documents & correspondence

8510160253 Reissues response to 841207 request for addl info re util response to Generic Ltr 83-28. Author 850408 Amend 1 to Generic Ltr 83-28 response, per B&W Owners Group activities, applicable to util.
ENOS, J.T. Arkansas Power & Light Co. 85/04/23. THOMPSON, H. Division of Licensing. 5pp. 33023-212-33023-216.

8510080356 Responds to NRC 850805 request for voluntary participation in efforts re Generic Issue 77 concerning flooding of safety equipment compartments by backflow through floor drains. Request declined due to demands on engineering resources.
ENOS, J.T. Arkansas Power & Light Co. 85/09/20. STOLZ, J.F. Operating Reactors Branch 4. 1p. 32922-122-32922-122.

8510220046 Provides ATWS (10CFR50.62) implementation schedule. Installation of ATWS mods will be completed prior to criticality following refueling outage (1RB) currently scheduled for Dec 1987.
ENOS, J.T. Arkansas Power & Light Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 33090-155-33090-156.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080415 Forwards Exam Rept 50-313/OL 85-03 administered during wk of 850902. Candidate successfully completed exam & license issued.
JOHNSON, E.H. Region 4, Office of Director. 85/10/01. CAMPBELL, T.G. Arkansas Power & Light Co. 2pp. 32921-269-32921-307.

—8510080419 Exam Rept 50-313/OL 85-03 of retake exam administered on 850905. Exam results: candidate successfully completed written exam & issued appropriate license.
PELLET, J.L., COOLEY, R.A. Region 4, Office of Director. 85/09/25. 37pp. 32921:271-32921:307.

8510160066 Comments on 850903 SALP rept for July 1984 - June 1985. Rept comprehensive & objective. Portions of recommendations made by task force to evaluate design change process implemented. Process significantly improved & will continue to improve.
ENOS, J.T. Arkansas Power & Light Co. 85/10/03. MARTIN, R.D. Region 4, Office of Director. 3pp. 33023:358-33023:360.

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053:258-33053:272.

—8510170375 Notice of violation from insan on 850801-31.
* Region 4, Office of Director. 85/10/03. 2pp. 33053:258-33053:259.

—8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted: failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D., HARRELL, P.H., MARTIN, L.E. Region 4, Office of Director. 85/10/01. 13pp. 33053:260-33053:272.

8510170402 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-15 & 50-368/85-16.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33053:332-33053:334.

—8510170410 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-313/85-15 & 50-368/85-16. Corrective actions: Procedure 2203.09, "Fire Protection Sys. Annunciator Corrective Action," Rev 0 revised.
ENOS, J.T. Arkansas Power & Light Co. 85/08/23. DENISE, R.P. Region 4, Office of Director. 2pp. 33053:333-33053:334.

8510160056 Ack receipt of 850429 & 0723 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-12 & 50-368/85-12. Replies responsive to violations w/exception of meeting 10CFR73.55 requirements re physical security.
JOHNSON, E.H. Region 4, Office of Director. 85/10/09. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33028:132-33028:133.

8510220322 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-20 & 50-368/85-21.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33088:185-33088:187.

—8510220332 Responds to NRC 850822 ltr re deviations noted in Insp Repts 50-313/85-20 & 50-368/85-21. Corrective actions: all ltrs of agreement between util & outside support groups/agencies will be completed by 8/7/01.
ENOS, J.T. Arkansas Power & Light Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 33088:186-33088:187.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 900 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250413 Ack receipt of 850728 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-10 & 50-368/85-10.
JOHNSON, E.H. Region 4, Office of Director. 85/10/18. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33172:226-33172:228.

—8510250421 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-313/85-10 & 50-368/85-10. Corrective actions: radiological protection procedures stressed in radiological emergency response training for field monitoring teams.
ENOS, J.T. Arkansas Power & Light Co. 85/07/28. MARTIN, R.D. Region 4, Office of Director. 2pp. 33172:227-33172:228.

R. Periodic operating reports & related correspondence

8510010479 Monthly operating rept for Jul 1985 W/850815 ltr.
CONVERSE, W.E., ENOS, J.T. Arkansas Power & Light Co. 85/07/31. BASSETT, H.S. Division of Automated Information Services. 6pp. 32809:107-32809:112.

S. Reportable occurrences, LERs & related correspondence

8510020081 LER 85-008-00 on 850819, speed of main feedwater pump (P-18) increased & then tripped in overspeed. Caused by loose screw on turbine speed control governor drive shaft wearing drive shaft coupling. Parts replaced W/850919 ltr.
ROGERS, P.C., ENOS, J.T. Alabama Power Co. 85/09/19. 2pp. 32827:326-32827:327.

8510170034 LER 85-010-00 on 850902 reactor trip resulting from trip of main feedwater pump B occurred. Caused by broken speed control governor drive shaft. Governor shaft & drive shaft replaced W/851003 ltr.
ROGERS, P.C., ENOS, J.T. Arkansas Power & Light Co. 85/10/03. 2pp. 33052:065-33052:066.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510080415 Forwards Exam Rept 50-313/OL 85-03 administered during wk of 850902. Candidate successfully completed exam & license issued.
JOHNSON, E.H. Region 4, Office of Director. 85/10/01. CAMPBELL, T.G. Arkansas Power & Light Co. 2pp. 32921:269-32921:307.

—8510080419 Exam Rept 50-313/OL 85-03 of retake exam administered on 850905. Exam results: candidate successfully completed written exam & issued appropriate license.
PELLET, J.L., COOLEY, R.A. Region 4, Office of Director. 85/09/25. 37pp. 32921:271-32921:307.

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053:258-33053:272.

—8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted: failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D. Region 4, Office of Director. 85/10/01. 13pp. 33053:260-33053:272.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510070314 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-315/85-13 & 50-316/85-13. Corrective actions: plant walkdown will be initiated to identify & seal conduits open at both ends that penetrate fire barrier.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/13. KEPPLER, J.G. Region 3, Office of Director. 5pp. 32880:343-32880:347.

8510040108 Responds to 850812 concerns re SPDS per NUREG-0737, Item II.F.2. Narrow-range water level indications available to diagnose tube rupture in steam generator.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32850:347-32850:350.

8510070082 Forwards Rev 4 to emergency plan. Rev includes changes to descriptions & organization charts of emergency response organizations. Effectiveness of emergency plan not decreased by Rev 4.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/30. Record Services Branch (Document Control Desk). 2pp. 32876:001-32876:331.

—8510070086 Rev 4 to emergency plan W/two oversize maps encl.
* Indiana & Michigan Electric Co. * American Electric Power Service Corp. 85/09/30. 150pp. 32876:003-32876:331.

8510070062 Requests addl time to complete mods to final status rept on Reg Guide 1.97 compliance. Rept expected by 851015.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32878:361-32878:361.

8510080520 Forwards seminar progress rept re overall view & comparison of status of DCDRR w/status presented on 850327. Significant slippage in overall schedule not anticipated. Program summary rept will be submitted by 861231.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32920:075-32920:076.

8510210101 Responds to NRC 850904 ltr re violations noted in Safeguards Insp Repts 50-315/85-23 & 50-316/85-23. Corrective actions withheld (ref 10CFR73.21).
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/02. KEPPLER, J.G. Region 3, Office of Director. 1p. 33072:274-33072:274.

8510160227 Rev 5 to Emergency Plan Procedure PMP 2080 EPP.001, "Emergency Plan Activation & Condition Classification."
* Indiana & Michigan Power Co. * Indiana & Michigan Electric Co. 85/10/09. 5pp. 33021:249-33021:253.

8510160041 Submits status of testing performed on control room ionization smoke detectors. Addl detectors installed & addl test completed on 830915. Item 23 of Table 1 of fire protection safety evaluation satisfied.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33024:167-33024:167.

8510220139 Rev 16 to emergency plan procedures App A, "Emergency Telephone Numbers."
LOOPE, D. Indiana & Michigan Electric Co. 85/10/14. 31pp. 33090:089-33090:119.

8510220249 Forwards status rept, "Implementation Plan of Reg Guide 1.97, Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," in response to 840612 licensing order. Rept reflects final plan for disposition of &/or compliance w/reg guide.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33083:329-33083:359.

—8510220255 "Implementation Plan of Reg Guide 1.97, Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," status rept.
* Indiana & Michigan Electric Co. 85/10/15. 29pp. 33083:331-33083:359.

8510250380 Change Sheet 2 to Rev 2 to Plant Manager Procedure PMP 2081 EPP.009, "Health Physics Mgt for Operations Staging Area," adding Step 3.3.5 to comply w/NUREG-0737 requirements, NRC confirming order & PMI-4030 attachment.
* Indiana & Michigan Electric Co. 85/10/16. 4pp. 33172:179-33172:182.

8510180180 Rev 3 to Plant Manager Procedure PMP 2081 EPP.014, "Offsite Dose Assessment."
* Indiana & Michigan Electric Co. 85/10/18. 52pp. 33062:323-33062:012.

92 DOCKETED ITEMS

P. Operating license stage documents & correspondence

- 8510070189** Responds to Generic Ltr 83-37 re containment pressure monitor Tech Specs required by NUREG-0737, Item II.F.1.4. Current Tech Specs 3.3-11.3.3-10.4.3-7 & 4.3-10 adequately meet NUREG-0737 requirements.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32881.135-32881.136.
- 8510080292** Submits info re Exxon Nuclear Co ECCS/LOCA analysis, per 850930 discussion w/NRC. Error found in TOODEE2 code re calculation of thermal response of hot fuel rod Peak cladding temp underpredicted. Calculations revised.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32919.109-32919.111.
- 8510080301** Notices of error in 10CFR50.46 LOCA analyses performed for facilities. Input error in TOODEE2 code used to calculate fuel rod heatup resulted in rod decay heat power too low & subsequent underpredicted peak cladding temp.
MALODY,C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/09/30. MARTIN,J.B. Region 5, Office of Director. 11pp. 32919.112-32919.122.
- 8510150021** Notification of 851011 meeting w/Exxon Nuclear Co, Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 16pp. 33031.135-33031.150.
- 8510110159** Notices that refund for 850628 application will be used as fee for 850911 application for approval to move trolley over spent fuel pool at plant.
DIGGS,R.M. License Fee Management Branch. 85/10/07. DOLAN,J. American Electric Power Service Corp. 1p. 33012.039-33012.039.
- 8510160047** Forwards corrected "Hydrogen Combustion Modeling Assumptions," originally submitted w/850909 ltr. Error on Page 4 corrected. W/o encl.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33028.127-33028.127.
- 8510160160** Application for amend to Licenses DPR-58 & DPR-74, changing Tech Spec Tables 3.3-11.4.3-7.3.3-10 & 4.3-10 re vessel level instrumentation sys & core exit thermocouples. Requests that changes go into effect on listed dates. Fee paid.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 33023.131-33023.148.
- 8510160167** Proposed Tech Specs, changing Tables 3.3-11.4.3-7.3.3-10 & 4.3-10 re vessel level instrumentation sys & core exit thermocouples. Related info encl.
* Indiana & Michigan Electric Co. 85/10/11. 11pp. 33023.138-33023.148.
- 8510310059** Forwards safety evaluation accepting 851002 correction to TOODEE 2 code input error which resulted in increase in peak cladding temp. Facility continues to satisfy performance requirements of 10CFR50.46.
VARGA,S.A. Operating Reactors Branch 1. 85/10/11. DOLAN,J. Indiana & Michigan Electric Co. DOLAN,J. American Electric Power Service Corp. 3pp. 33277.162-33277.169.
- 8510310062** SER accepting revised submittal re LOCA/ECCS analysis. Facility can be operated w/o undue risk to public health & safety.
* NRC - No Detailed Affiliation Given. 85/10/11. 5pp. 33277.185-33277.189.
- 8510220236** Forwards schedule for revising procedures to inservice test (IST) program for pumps & valves in response to NRC 850904 SER. Insertion of encl revised pages into IST requested.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 16pp. 33082.266-33082.281.
- 8510310028** Forwards "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Action Based on Generic Implications of Salem ATWS Events)..." technical evaluation rpt. Responses incomplete. Add info requested.
VARGA,S.A. Operating Reactors Branch 1. 85/10/17. DOLAN,J. Indiana & Michigan Electric Co. DOLAN,J. American Electric Power Service Corp. 2pp. 33277.144-33277.160.
- 8510310032** Review of Licensee Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.2, "Post-Trip Review Data & Info Capabilities" for DC Cook..." technical evaluation rpt.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-4. 85/10/17. NRC - No Detailed Affiliation Given. 15pp. 33277.146-33277.160.
- 8510250391** Responds to 851019 request for add info re amends to Licenses DPR-58 & DPR-74, revising Tech Specs re containment isolation valves. Footnote added to Page 3/4 6-1 requesting exemption from valve insp.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33172.283-33172.285.
- 8510300164** Proposes schedule for meeting 10CFR50.62 requirements re ATWS rule & provides brief description of design. Util expects to implement ATWS mitigating sys activation circuitry during refueling outage in early 1987.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33250.342-33250.343.
- Q. Inspection reports, IE Bulletins & correspondence**
- 8510070314** Responds to NRC 850826 ltr re violations noted in Insp Repts 50-315/85-13 & 50-316/85-13. Corrective actions/plant walkdown will be initiated to identify & seal conduits open at both ends that penetrate fire barrier.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/13. KEPPLER,J.G. Region 3, Office of Director. 5pp. 32880.343-32880.347.
- 8510080210** EN-85-084 on 850925, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee. Action based on multiple failures to maintain control over access to vital areas.
ROBINSON,P., AXELRAD,J. Director's Office, Office of Inspection and Enforcement. 85/09/20. 1p. 32913.349-32913.349.
- 8510010191** Forwards Safety Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation noted.
CHRISTOTIMOS,N. Region 3, Office of Director. 85/09/24. DOLAN,J.E. American Electric Power Service Corp. DOLAN,J.E. Indiana & Michigan Electric Co. 2pp. 32800.291-32800.301.
- 8510010201** Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation or deviation noted. Major areas inspected: previous insp findings, operational safety verification, refueling, surveillance, maint & Region III requests.
SUERMANN,J.F. Region 3, Office of Director. 85/09/20. 9pp. 32800.293-32800.301.
- 8510040136** Responds to NRC 850729 ltr re violations noted in Insp Repts 50-315/85-16 & 50-316/85-16. Corrective actions: battery tie rod placement corrected per approved drawing & method of scoping design changes will be revised.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/28. KEPPLER,J.G. Region 3, Office of Director. 3pp. 32851.210-32851.212.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510210101** Responds to NRC 850904 ltr re violations noted in Safeguards Insp Repts 50-315/85-23 & 50-316/85-23. Corrective actions withheld (ref 10CFR73.21).
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/02. KEPPLER,J.G. Region 3, Office of Director. 1p. 33072.274-33072.274.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108.264-33108.088.
- 8408010318** Responds to 840620 ltr re investigation involving mail false statement. NRC policy of levying civil penalties on licensee instead of individual elucidated. Violations addressed in D Alabach 840606 ltr under consideration for enforcement.
DIRCKS,W.J. Office of the Executive Director for Operations. 84/07/17. HILLIS,E.H. House of Rep. 2pp. 33109.089-33109.093.
- 8408010320** Forwards constituent D Alabach 840606 ltr questioning fines imposed on licensee for mail false statements.
HILLIS,E.H. House of Rep. 84/06/20. KAMMERER,C. Office of Congressional Affairs. 3pp. 33109.091-33109.093.
- 8510230283** Forwards Press Release 84-51 re NRC proposed fine against util for violations of safety requirements, including improper control valve setting on auxiliary feedwater pump.
KAMMERER,C. Office of Congressional Affairs. 84/12/03. OTTINGER,R.L. House of Rep. Energy & Commerce. MARKEY House of Rep. LEVIN Senate. 2pp. 33109.117-33109.118.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.
- 8510210173** Forwards special Safety Insp Repts 50-315/85-26 & 50-316/85-26 on 850904-20 & notice of violation.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/16. DOLAN,J.E. American Electric Power Service Corp. DOLAN,J.E. Indiana & Michigan Electric Co. 2pp. 33071.112-33071.123.
- 8510210180** Notice of violation from insp on 850904-20.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/16. 2pp. 33071.114-33071.115.
- 8510210186** Insp Repts 50-315/85-26 & 50-316/85-26 on 850904-20. Violations noted: failure to properly store special process records, to provide proper corrective action & to provide adequate control over design changes & mods.
WALKER,H.A. HAWKINS,F.C. Region 3, Office of Director. 85/10/16. 8pp. 33071.116-33071.123.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.
- 8510230160** Forwards Safety Insp Repts 50-315/85-25 & 50-316/85-25 on 850814-0905 & notice of violation. Concerns re containment temp survey requirements & corrective action taken on excessively leaking containment isolation valves identified.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/18. DOLAN,J.E. American Electric Power Service Corp. DOLAN,J.E. Indiana & Michigan Electric Co. 2pp. 33101.135-33101.150.
- 8510230165** Notice of violation from insp on 850814-0905.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/21. 1p. 33101.137-33101.137.
- 8510230169** Insp Repts 50-315/85-25 & 50-316/85-25 on 850814-0905. Violation noted: failure to control calor condition of flowmeter used for supplemental verification test.
HARE,S.M. GULDEMOND,W.G. Region 3, Office of Director. 85/10/18. 13pp. 33101.138-33101.150.
- 8510250391** Responds to 851019 request for add info re amends to Licenses DPR-58 & DPR-74, revising Tech Specs re containment isolation valves. Footnote added to Page 3/4 6-1 requesting exemption from valve insp.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33172.283-33172.285.

8510250410 Confirms 851017 telcon re 851113 enforcement conference in Glen Ellyn, IL to discuss problems w/mtg controls over testing activities described in Insp Repts 85027-85029. Notification encl.
NÖRELIUS, C.E. Region 3, Office of Director. 85/10/22. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33172-229-33172-230.

8510280307 Forwards addendum consisting of confirmatory measurements program data sheet to Insp Repts 50-315/84-21 & 50-316/84-23. Open items 50-315/84-21-05 & 50-316/84-23-05 complete.
SHAHER, W.D. Region 3, Office of Director. 85/10/22. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33193-073-33193-075.

-8510280316 Addendum consisting of confirmatory measurements program data sheet to Insp Repts 50-315/84-21 & 50-316/84-23.
* Region 3, Office of Director. 85/10/22. 1p. 33193-075-33193-075.

8510290023 Forwards payment of insp fee described in Invoice 1612V.
HERING, R.F. Indiana & Michigan Electric Co. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235-040-33235-040.

R. Periodic operating reports & related correspondence

8510010496 Monthly operating rept for Jul 1985. W/850809 ltr.
CLIMER, SMITH, W.G. Indiana & Michigan Electric Co. 85/07/31. 8pp. 32820-157-32820-164.

8510080520 Forwards semiannual progress rept re overall view & comparison of status of DCFDR w/status presented on 850327. Significant slippage in overall schedule not anticipated. Program summary rept will be submitted by 861231.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32920-075-32920-076.

S. Reportable occurrences, LERs & related correspondence

8510080577 NPDES noncompliance notification on 850817, high pH occurred when Steam Generator 23 on Unit 2 NSSS drained. Caused by addition of ammonia during outage to prevent steam generator degradation.
SMITH, W.G. Indiana & Michigan Electric Co. 85/09/20. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32927-048-32927-050.

8510080596 Responds to 850730 ltr informing NRC of intent to rescind commitment in LER 82-016/03X-2 to initiate condition rept each time piece of Tech Spec-related equipment out of svc. Proposed change acceptable.
NÖRELIUS, C.E. Region 3, Office of Director. 85/09/27. SMITH, W.G. American Electric Power Service Corp. SMITH, W.G. Indiana & Michigan Electric Co. 1p. 32927-078-32927-082.

8510090520 NPDES noncompliance notification on 850901, blowdown sample from heating boiler placed in use on 850716, contained iron concentration of 3.9 ppm. Caused by chemical shock.
SMITH, W.G. Indiana & Michigan Electric Co. 85/09/27. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32946-057-32946-059.

8510090374 Forwards LERs 85-042-00 & 85-043-00.
SMITH, W.G. Indiana & Michigan Electric Co. 85/05/30. Record Services Branch (Document Control Desk). 1p. 32946-122-32946-126.

-8510090378 LER 85-042-00 on 850829, control room emergency air intake damper HV-ACRDA-2 discovered improperly positioned. Caused by incorrect damper adjustment made as result of Surveillance Procedure 12 THP 4030 STP.229. Damper correctly adjusted.
BLIND, A.A. Indiana & Michigan Electric Co. 85/09/30. 3pp. 32946-123-32946-125.

-8510090382 LER 85-043-00 on 850830, review of Tech Spec surveillances re calibr & time response testing of process sensors disclosed deficiencies in areas of in-core thermocouples used as backup to saturation monitor & dew point hygrometer.
GIBSON, L.S. Indiana & Michigan Electric Co. 85/09/30. 1p. 32946-126-32946-126.

8510070548 Forwards LERs 85-017-01 & 85-019-01.
SMITH, W.G. Indiana & Michigan Electric Co. 85/10/01. Record Services Branch (Document Control Desk). 1p. 32883-231-32883-234.

-8510070549 LER 85-017-01 on 850417, accumulated leakage exceeded Tech Spec limits found while performing Type B & C leak rate tests. Cause unknown. Penetrations repaired.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/01. 1p. 32883-232-32883-232.

-8510070552 LER 85-019-01 on 850420, ice inventory within ice condenser determined to be below Tech Spec limits. Cause unknown. Ice weight of deficient rows increased by ice replenishment program.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/01. 2pp. 32883-233-32883-234.

8510090246 LER 83-131/99X-1 on 831231, fire hoses exceeded 3-yr surveillance test frequency. Caused by use of two test frequencies, inadvertent interchange of hoses during fire drills & incorrect entry into Tech Spec sys. W/851001 ltr.
BARFELZ, M.E. SMITH, W.G. Indiana & Michigan Electric Co. 85/10/01. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32946-220-32946-222.

8510090176 Forwards LERs 85-042-01 & 85-044-00.
SMITH, W.G. Indiana & Michigan Electric Co. 85/10/02. Record Services Branch (Document Control Desk). 1p. 32946-186-32946-191.

-8510090179 LER 85-042-01 on 850829, Unit 2 control room emergency air intake damper found improperly positioned for approx 14 days. Unit 1 affected due to sys interdependency. Caused by incorrect damper adjustment.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/02. 3pp. 32946-187-32946-189.

-8510090184 LER 85-044-00 on 850902 & 07, steam line isolation signal generated ESF actuation. Caused by solid-state protection sys design change installation & valving out instrumentation lines, respectively. No corrective action taken.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/02. 2pp. 32946-190-32946-191.

8510220067 NPDES noncompliance notification, blowdown sample taken on 851001 from heating boiler contained iron concentration of 1.48 ppm due to chemical shock.
MENGE, R.C. Indiana & Michigan Electric Co. 85/10/03. ZUGGER, P.D. Michigan, State of. 2pp. 33095-178-33095-179.

8510090370 LER 85-045-00 on 850905, improper attachments to steel liner plates forming integral part of pressurizer & steam generator encls identified. Cause not stated. Mod program initiated to ensure seismic qualifications met. W/851004 ltr.
STIETZEL, J.F. SMITH, W.G. Indiana & Michigan Electric Co. 85/10/04. 2pp. 32946-120-32946-121.

8510170049 LER 85-046-00 on 850907, ESF reactor trip signals & loss of RHR pumps occurred due to loss of power to control room instrument circuits. Caused by personnel error. Operator counseled. W/851007 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/07. 3pp. 33052-131-33052-133.

8510170022 LER 85-036-01 on 850806, ESF ventilation sys charcoal absorber 1-HV-AES-1 determined inoperable. On 850823, carbon settling occurred in absorber 1-HV-AES-1. Caused by inadequate functioning of absorber bank. W/851008 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/08. 5pp. 33053-212-33053-216.

8510240183 LER 85-047-00 on 850916, listed equipment not calibr at Tech Spec required frequency. Caused by not including instruments in plant nuclear test schedule. Calibr completed & added to schedule. W/851016 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/16. 2pp. 33156-325-33156-326.

8510280455 LER 85-048-00 on 850917, incorrect trip & throttle valve solenoids found installed on turbine driven auxiliary feedwater pumps. Error discovered during design change considerations. Correct solenoids installed. W/851018 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/18. 2pp. 33194-102-33194-103.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33106-264-33109-088.

-8408010318 Responds to 840620 ltr re investigation involving matl false statement. NRC policy of levying civil penalties on licensee instead of individual elucidated. Violations addressed in D Alabach 840606 ltr under consideration for enforcement.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/07/17. HILLIS, E.H. House of Rep. 2pp. 33109-089-33109-093.

-8408010320 Forwards constituent D Alabach 840606 ltr questioning fines imposed on licensee for matl false statements.
HILLIS, E.H. House of Rep. 34/06/20. KAMMERER, C. Office of Congressional Affairs. 3pp. 33109-091-33109-093.

-8510230283 Forwards Press Release 84-51 re NRC proposed fine against util for violations of safety requirements, including improper control valve setting on auxiliary feedwater pump.
KAMMERER, C. Office of Congressional Affairs. 84/12/03. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109-117-33109-118.

V. Operator Examinations

8510010191 Forwards Safety Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation noted.
CHRISTOS, TIMOS, N. Region 3, Office of Director. 85/09/24. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 32800-291-32800-301.

-8510010201 Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation or deviation noted. Major areas inspected: previous insp findings, operational safety verification, refueling, surveillance, maint & Region III requests.
SUERMANN, J.F. Region 3, Office of Director. 85/09/20. 9pp. 32800-293-32800-301.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070314 Responds to NRC 850626 ltr re violations noted in Insp Repts 50-315/85-13 & 50-316/85-13. Corrective actions plant walkdown will be initiated to identify & seal conduits open at both ends that penetrate fire barrier.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/13. KEPPLER, J.G. Region 3, Office of Director. 5pp. 32880-343-32880-347.

8510040108 Responds to 850812 concerns re SPOS per NUREG-0737, Item ILF 2. Narrow-range water level indications available to diagnose tube rupture in steam generator.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32850-347-32850-350.

8510070082 Forwards Rev 4 to emergency plan. Rev includes changes to descriptions & organization charts of emergency response organizations. Effectiveness of emergency plan not decreased by Rev 4.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/09/30. Record Services Branch (Document Control Desk). 2pp. 32876-001-32876-031.

94 DOCKETED ITEMS

—8510070086 Rev 4 to emergency plan w/two oversize maps encl.
* Indiana & Michigan Electric Co. * American Electric Power Service Corp. 85/09/30. 150pp. 32876:003-32876:331.

8510070062 Requests add'l time to complete mods to final status rept on Reg Guide 1.97 compliance. Rept expected by 851015.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32878:361-32878:361.

8510080520 Forwards semiannual progress rept re overall view & comparison of status of DCRDR w/status presented on 850327. Significant slippage in overall schedule not anticipated. Program summary rept will be submitted by 861231.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32920:075-32920:076.

8510210101 Responds to NRC 850904 ltr re violations noted in Safeguards Insp Repts 50-315/85-23 & 50-316/85-23. Corrective actions withheld (ref 10CFR73.21).
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/02. KEPPLER,J.G. Region 3, Office of Director. 1p. 33072:274-33072:274.

8510160227 Rev 5 to Emergency Plan Procedure PMP 2080 EPP.001, "Emergency Plan Activation & Condition Classification."
* Indiana & Michigan Power Co. * Indiana & Michigan Electric Co. 85/10/09. 5pp. 33021:249-33021:253.

8510220139 Rev 16 to emergency plan procedures App A, "Emergency Telephone Numbers."
LOOPE,D. Indiana & Michigan Electric Co. 85/10/14. 31pp. 33090:089-33090:119.

8510220249 Forwards status rept, "Implementation Plan of Reg Guide 1.97 Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," in response to 840612 licensing order Rept reflects final plan for disposition of &/or compliance w/reg guide.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33083:329-33083:359.

—8510220255 "Implementation Plan of Reg Guide 1.97 Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," status rept.
* Indiana & Michigan Electric Co. 85/10/15. 29pp. 33083:331-33083:359.

8510250380 Change Sheet 2 to Rev 2 to Plant Manager Procedure PMP 2081 EPP.009, "Health Physics Mgt for Operations Staging Area," adding Step 3.3.5 to comply w/ NUREG-0737 requirements, NRC confirming order & PMI-4030 attachment.
* Indiana & Michigan Electric Co. 85/10/16. 4pp. 33172:179-33172:182.

8510180180 Rev 3 to Plant Manager Procedure PMP 2081 EPP.014, "Offsite Dose Assessment."
* Indiana & Michigan Electric Co. 85/10/18. 52pp. 33062:323-33062:012.

P. Operating license stage documents & correspondence

8510070163 Forwards 850930 request to Palladino re extension of environ qualification for License DPR-74 until 860226. Fee paid by using credit from check dtd 850326 per NRC 850911 request.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32881:071-32881:083.

—8510070170 Requests extension of environ qualification of electrical equipment until no later than 860228.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/30. PALLADINO,N.J. Commissioners. 12pp. 32881:072-32881:083.

8510070189 Responds to Generic Ltr 83-37 re containment pressure monitor Tech Specs required by NUREG-0737, Item II.F.1.4. Current Tech. Specs 9.3-11, 3.3-10, 4.3-7 & 4.3-10 adequately meet NUREG-0737 requirements.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32881:135-32881:136.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510070200 Forwards proprietary "N-NF-85-68(P), "DC Cook Unit 2 Limiting Break LOCA/ECCS Analysis, 10% Steam Generator Tube Plugging & K(Z) Curve." Affidavit encl. Rept withheld (ref 10CFR2.790).
COPELAND,R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/10/03. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32873:228-32873:232.

8510110159 Notifies that refund for 850628 application will be used as fee for 850911 application for approval to move trolley over spent fuel pool at plant.
DIGGS,R.M. License Fee Management Branch. 85/10/07. DOLAN,J. American Electric Power Service Corp. 1p. 33012:039-33012:039.

8510160009 Informs that Exxon Nuclear Co. 851003 XN-NF-85-68(P), "DC Cook Unit 2 Limiting Break LOCA/ECCS Analysis," & related submittals constitute basis for Cycle 6 reload licensing.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027:162-33027:163.

8510160047 Forwards corrected "Hydrogen Combustion Modeling Assumptions," originally submitted w/850909 ltr Error on Page 4 corrected w/o encl.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33028:127-33028:127.

8510160160 Application for amend to Licenses DPR-58 & DPR-74, changing Tech Spec Tables 3.3-11, 4.3-7, 3.3-10 & 4.3-10 re vessel level instrumentation sys & core exit thermocouples. Requests that changes go into effect on listed dates. Fee paid.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 33023:131-33023:148.

—8510160167 Proposed Tech Specs, changing Tables 3.3-11, 4.3-7, 3.3-10 & 4.3-10 re vessel level instrumentation sys & core exit thermocouples. Related info encl.
* Indiana & Michigan Electric Co. 85/10/11. 11pp. 33023:138-33023:148.

8510170289 Forwards XN-NF-85-28, "DC Cook Unit 2, Cycle 6 SAR" & proprietary Suppl 1 to XN-NF-85-28(P), "DC Cook Unit 2, Cycle 6 SAR-Disposition of SRP...". Proprietary suppl withheld (ref 10CFR2.790(b)).
COPELAND,R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33039:156-33039:194.

—8510170292 Nonproprietary XN-NF-85-28, "DC Cook Unit 2, Cycle 6 SAR."
WIMPY,P.D., ADAMS,F.T., SKOGEN,F.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-85-28. 85/07/31. 34pp. 33039:161-33039:194.

8510220236 Forwards schedule for revising procedures to inservice test (IST) program for pumps & valves, in response to NRC 850904 SER. Insertion of encl revised pages into IST requested.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 16pp. 33082:266-33082:281.

8510310028 Forwards "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Action Based on Generic Implications of Salem ATWS Events)..." technical evaluation rept Responses incomplete. Add'l info requested.
VARGA,S.A. Operating Reactors Branch 1. 85/10/17. DOLAN,J. Indiana & Michigan Electric Co. DOLAN,J. American Electric Power Service Corp. 2pp. 33277:144-33277:160.

—8510310032 "Review of Licensee Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review: Data & Info Capabilities' for DC Cook..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-4. 85/10/17. NRC - No Detailed Affiliation Given. 15pp. 33277:146-33277:160.

8510250391 Responds to 851019 request for add'l info re amends to Licenses DPR-58 & DPR-74, revising Tech Specs re containment isolation valves. Footnote added to Page 3/4 6-1 requesting exemption from valve insp.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33172:283-33172:285.

8510290139 Informs that Exxon Nuclear Co. transmitted XN-NF-85-28 re Cycle 6 SAR & Suppl 1 to XN-NF-85-28(P) re Cycle 6 SAR & disposition of SRP Chapter 15 events to NRC by 851015 ltr. Transient analysis will be submitted by 851022.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33236:169-33236:170.

8510300164 Proposes schedule for meeting 10CFR50.62 requirements re ATWS rule & provides brief description of design. Util expects to implement ATWS mitigating sys actuation circuitry during refueling outage in early 1987.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33250:342-33250:343.

Q. Inspection reports, IE Bulletins & correspondence

8510070314 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-315/85-13 & 50-316/85-13. Corrective actions plant shutdown will be initiated to identify & seal conduits open at both ends that penetrate fire barrier.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/13. KEPPLER,J.G. Region 3, Office of Director. 5pp. 32880:345-32880:347.

8510080210 EN-85-064 on 850925 notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee. Action based on multiple failures to maintain control over access to vital areas.
ROBINSON,P., AXELRAD,J. Director's Office, Office of Inspection and Enforcement. 85/09/20. 1p. 32913:349-32913:349.

8510010191 Forwards Safety Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation noted.
CHRISTOTIMOS,N. Region 3, Office of Director. 85/09/24. DOLAN,J.E. American Electric Power Service Corp. DOLAN,J.E. Indiana & Michigan Electric Co. 2pp. 32800:291-32800:301.

—8510010201 Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902. No violation or deviation noted. Major areas inspected previous insp findings, operational safety verification, refueling, surveillance, maint & Region III requests.
SUERMANN,J.F. Region 3, Office of Director. 85/09/20. 9pp. 32800:293-32800:301.

8510040136 Responds to NRC 850729 ltr re violations noted in Insp Repts 50-315/85-16 & 50-316/85-16. Corrective actions battery tie rod placement corrected per approved drawing & method of scoping design changes will be revised.
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/09/28. KEPPLER,J.G. Region 3, Office of Director. 3pp. 32851:210-32851:212.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210101 Responds to NRC 850904 ltr re violations noted in Safeguards Insp Repts 50-315/85-23 & 50-316/85-23. Corrective actions withheld (ref 10CFR73.21).
ALEXICH.M.P. Indiana & Michigan Electric Co. 85/10/02. KEPPLER,J.G. Region 3, Office of Director. 1p. 33072:274-33072:274.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33108:288.

-8408010318 Responds to 840620 ltr re investigation involving mail false statement. NRC policy of levying civil penalties on licensee instead of individual elucidated. Violations addressed in D Alabach 840606 ltr under consideration for enforcement.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/07/17. HILLIS, E.H. House of Rep. 2pp. 33109-089-33109-093.

-8408010320 Forwards constituent D Alabach 840606 ltr questioning fines imposed on licensee for mail false statements.
HILLIS, E.H. House of Rep. 84/06/20. KAMMERER, C. Office of Congressional Affairs. 3pp. 33109-091-33109-093.

-8510230283 Forwards Press Release 84-51 re NRC proposed fine against utility for violations of safety requirements, including improper control valve setting on auxiliary feedwater pump.
KAMMERER, C. Office of Congressional Affairs. 84/12/03. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. LEVIN Senate. 2pp. 33109-117-33109-118.

8510170218 Forwards Safety Insp Rept 50-316/85-27 on 850906.19-20 & 25-26. No violations noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/08. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33051-221-33051-229.

-8510170224 Insp Rept 50-316/85-27 on 850906.26. No violations or deviations noted. Major areas inspected: procedures, work activities, NDE personnel certifications & data re leakage evaluation & eddy current exam of steam generators.
JONES, D.E., DANIELSON, D.H. Region 3, Office of Director. 85/10/07. 7pp. 33051-223-33051-229.

8510160021 Informs of program & course of action taken re steam generator work during recent forced outages. Final rept being prepared to detail tube indication data, tube sheet indication mapping & comparison of data from previous insp.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 33027-029-33027-042.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510210173 Forwards special Safety Insp Repts 50-315/85-26 & 50-316/85-26 on 850904-20 & notice of violation.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/16. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33071-112-33071-123.

-8510210180 Notice of violation from insp on 850904-20.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/16. 2pp. 33071-114-33071-115.

-8510210186 Insp Repts 50-315/85-26 & 50-316/85-26 on 850904-20. Violations noted: failure to properly store special process records, to provide proper corrective action & to provide adequate control over design changes & mods.
WALKER, H.A., HAWKINS, F.C. Region 3, Office of Director. 85/10/16. 8pp. 33071-116-33071-123.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510230160 Forwards Safety Insp Repts 50-315/85-25 & 50-316/85-25 on 850814-0905 & notice of violation. Concerns re containment temp survey requirements & corrective action taken on excessively leaking containment isolation valves identified.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/18. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33101-135-33101-150.

-8510230169 Insp Repts 50-315/85-25 & 50-316/85-25 on 850814-0905. Violation noted: failure to control calibr condition of flowmeter used for supplemental verification test.
HARE, S.M., GULDEMOND, W.G. Region 3, Office of Director. 85/10/18. 13pp. 33101-138-33101-150.

8510250391 Responds to 851019 request for addl info re amends to Licenses DPR-58 & DPR-74, revising Tech Specs re containment isolation valves. Footnote added to Page 3/4 6-1 requesting exemption from valve insp.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33172-283-33172-285.

8510250410 Confirms 851017 telcon re 851113 enforcement conference in Glen Ellyn, IL to discuss problems w/mgmt controls over testing activities described in Insp Repts 85027-85029. Notification encl.
NOELIUS, C.E. Region 3, Office of Director. 85/10/22. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33172-229-33172-230.

8510280307 Forwards addendum consisting of confirmatory measurements program data sheet to Insp Repts 50-315/84-21 & 50-316/84-23. Open items 50-315/84-21-05 & 50-316/84-23-05 complete.
SHAFFER, W.D. Region 3, Office of Director. 85/10/22. DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 2pp. 33193-073-33193-075.

-8510280316 Addendum consisting of confirmatory measurements program data sheet to Insp Repts 50-315/84-21 & 50-316/84-23.

* Region 3, Office of Director. 85/10/22. 1p. 33193-075-33193-075.

8510290350 Forwards insp fee per invoice 1613V.

HERING, R.F. Indiana & Michigan Electric Co. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33239-361-33239-361.

R. Periodic operating reports & related correspondence

8510010493 Monthly operating rept for Jul 85: W/850809 ltr.
CLIMER, SMITH, W.G. Indiana & Michigan Electric Co. 85/07/31. 11pp. 32820-141-32820-151.

8510080520 Forwards semiannual progress rept re overall view & comparison of status of DCRDF w/status presented on 850327. Significant slippage in overall schedule not anticipated. Program summary rept will be submitted by 861231.
ALEXICH, M.P. Indiana & Michigan Electric Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32920-075-32920-076.

S. Reportable occurrences, LERs & related correspondence

8510080577 NPDES noncompliance notification: on 850817, high pH occurred when Steam Generator 23 on Unit 2 NSSS drained. Caused by addition of ammonia during outage to prevent steam generator degradation.
SMITH, W.G. Indiana & Michigan Electric Co. 85/09/20. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32927-048-32927-050.

8510010110 Forwards LERs 85-022-00 & 85-023-00.
SMITH, W.G. Indiana & Michigan Electric Co. 85/09/24. Record Services Branch (Document Control Desk). 1p. 32809-198-32809-200.

-8510010120 LER 85-023-00 on 850823, discovered that incorrect essential svc water sample point being used to fulfill Table 3.3-12 of Tech Spec 3.3.3.9. Procedure 12 THP 6020 LAB.037 revised to list specific sample points.
BLIND, A.A. Indiana & Michigan Electric Co. 85/09/24. 1p. 32809-199-32809-199.

-8510010129 LER 85-022-00 on 850825, grab sample of essential svc water sys not obtained at proper time. Caused by technician error. Technician disciplined.
BLIND, A.A. Indiana & Michigan Electric Co. 85/09/24. 1p. 32809-200-32809-200.

8510080596 Responds to 850730 ltr informing NRC of intent to rescind commitment in LER 82-016/03X-2 to initiate condition rept each time piece of Tech Spec-related equipment out of svc. Proposed change acceptable.
NOELIUS, C.E. Region 3, Office of Director. 85/09/27. SMITH, W.G. American Electric Power Service Corp. SMITH, W.G. Indiana & Michigan Electric Co. 1p. 32927-078-32927-082.

8510090520 NPDES noncompliance notification: on 850901, blowdown sample from heating boiler placed in use on 850716, contained iron concentration of 3.9 ppm. Caused by chemical shock.
SMITH, W.G. Indiana & Michigan Electric Co. 85/09/27. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32946-057-32946-059.

8510220067 NPDES noncompliance notification: blowdown sample taken on 851001 from heating boiler contained iron concentration of 1.48 ppm due to chemical shock.
MENGES, R.C. Indiana & Michigan Electric Co. 85/10/03. ZUGGER, P.D. Michigan, State of. 2pp. 33095-178-33095-179.

8510170040 Forwards LERs 85-024-00 & 85-025-00.
SMITH, W.G. Indiana & Michigan Electric Co. 85/10/07. Record Services Branch (Document Control Desk). 1p. 33052-126-33052-130.

-8510170042 LER 85-024-00 on 850906, automatic ESF actuation occurred, resulting in reactor trip signal. Caused by simultaneous tripping of two of three steam generator 2 level channel bistables. No corrective action taken.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/07. 2pp. 33052-127-33052-128.

-8510170045 LER 85-025-00 on 850906, discovered that reactor trip instrumentation Surveillance Requirements 4.3.1.1.1, Items 18B & 20 inadequate. Cause not determined. Items added to computerized nuclear test schedule for reactor startup.
BLIND, A.A. Indiana & Michigan Electric Co. 85/10/07. 2pp. 33052-129-33052-130.

8510170025 LER 85-026-00 on 850903, discovered that charcoal absorber banks inadvertently exposed to fire protection water. On 850908, determined that absorbers possibly incurred damage. Caused by spray header leakage W/851008 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/08. 5pp. 33052-134-33052-138.

8510170445 LER 84-032-01 between 841206 & 17, nine events occurred involving inability to perform hourly insp of inoperable fire assemblies. Caused by coordination problems w/ implementation of fire watch program W/851009 ltr.
STIETZEL, J.F., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/09. 3pp. 33053-249-33053-251.

8510170448 LER 85-027-00 on 850911, determined that fire rating of wall separating Unit 1 & 2 essential svc water pump rooms not consistent w/App A requirements. Caused by open penetrations. Fire watch established & penetrations sealed W/851010 ltr.
BLIND, A.A., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/10. 2pp. 33053-243-33053-244.

8510240219 LER 85-028-00 on 850915, spray additive tank vol exceeded Tech Spec 3.6.2.2. Caused by procedural deficiencies. Tank drained to meet specs & returned to operable status W/851015 ltr.
BAKER, K.R., SMITH, W.G. Indiana & Michigan Electric Co. 85/10/15. 4pp. 33157-354-33157-357.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-288.

96 DOCKETED ITEMS

-8408010318 Responds to 840620 ltr re investigation involving matl false statement/NRC policy of levying civil penalties on licensee instead of individual eluded/Violations addressed in D Alabach 840606 ltr under consideration for enforcement.
DIRCKS,W.J. Office of the Executive Director for Operations. 84/07/17. HILLIS,E.H. House of Rep. 2pp. 33109:089-22 33109:093.

-8408010320 Forwards const... J Alabach 840606 ltr questioning fines imposed on licensee for matl false statements.
HILLIS,E.H. House of Rep. 84/06/20. KAMMERER,C. Office of Congressional Affairs. 3pp. 33109:091-33109:093.

-8510230283 Forwards Press Release 84-51 re NRC proposed fine against util for violations of safety requirements,including improper control valve setting on auxiliary feedwater pump.
KAMMERER,C. Office of Congressional Affairs. 84/12/03. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:117-33109:118.

V. Operator Examinations

8510010191 Forwards Safety Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902 No violation noted.
CHRISSTIMOS,N. Region 3, Office of Director. 85/09/24. DOLAN,J.E. American Electric Power Service Corp. 2pp. 32800:291-32800:301.

-8510010201 Insp Repts 50-315/85-22 & 50-316/85-22 on 850723-0902 No violation or deviation noted.Major areas inspected:previous insp findings,operational safety verification,refueling, surveillance,maint & Region III requests.
SUEFARMAN,J.F. Region 3, Office of Director. 85/09/20. 9pp. 32800:293-32800:301.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080544 Rev 9 to Emergency Response Plan Implementation Procedure ERPIP 5.0, "Preparation & Control of Emergency Response Plan & Implementation Procedures."
RUSSELL,J.B. Baltimore Gas & Electric Co. 85/09/20. 12pp. 32920:049-32920:060.

8510160146 Rev 6 to emergency response plan.
WOOD,J. RUSSELL,J.B. Baltimore Gas & Electric Co. 85/09/25. 68pp. 33021:087-33021:182.

8510080418 Revised emergency response plan implementation procedures, including Rev 3 to ERPIP 4.4.7.5 re post-accident containment atmosphere sampling & Rev 4 to ERPIP 4.4.7.6 re post-accident sample sys & analysis.
* Baltimore Gas & Electric Co. 85/09/30. 57pp. 32922:259-32922:315.

8510080400 Rev 0 to Emergency Response Plan Implementing Procedure ERPIP 4.1.22.2, "Dedicated Communicator."
* Baltimore Gas & Electric Co. 85/10/01. 15pp. 32919:269-32919:283.

8510080476 Change 2 to Rev 10 to Emergency Response Plan Implementing Procedure ERPIP 5.1, "Communications."
* Baltimore Gas & Electric Co. 85/10/01. 9pp. 32922:052-32922:060.

8510080516 Rev 0 to Emergency Response Plan Implementation Procedure ERPIP 4.1.8.1, "Circulating Water Sampling." Procedure 4.3.3, "Liquid Effluent Sampling & Analysis," canceled.
FORGETTE,T.E. Baltimore Gas & Electric Co. 85/10/02. 7pp. 32920:061-32920:067.

8510220268 Rev 0 to Emergency Response Plan Implementation Procedure ERPIP 4.1.32, "Chemistry."
DENTON,R.E. Baltimore Gas & Electric Co. 85/10/02. 6pp. 33087:071-33087:076.

8510090038 Forwards Rev 15 to security plan.Rev withheld (ref 10CFR73.21).
BOWMAKER,N.J. Baltimore Gas & Electric Co. 85/10/03. MURLEY,T.E. Region 1, Office of Director. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32943:045-32943:048.

8510250429 Rev 4 to ERPIP 4.4.7.6, "Dilute Sample."
* Baltimore Gas & Electric Co. 85/10/08. 4pp. 33172:235-33172:238.

8510250474 Emergency response plan implementation procedures,including Rev 13 to table of contents,Rev 9 to ERPIP 4.1.3 re technical support ctr roster & Rev 9 to ERPIP 4.1.4 re operational support ctr roster.
* Baltimore Gas & Electric Co. 85/10/09. 8pp. 33169:323-33169:329.

8510220307 Revised emergency response plan implementation procedures, including Change 2 to Rev 3 to ERPIP 4.4.7.5,deleting syringe sys isolation valve & Rev 2 to ERPIP 4.1.29, "Emergency Operations Facility Director."
* Baltimore Gas & Electric Co. 85/10/14. 27pp. 33085:109-33085:135.

8510230158 Forwards Safety Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11 No violations noted.
BELLAMY,R.R. Region 1, Office of Director. 85/10/18. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 33101:097-33101:108.

-8510230163 Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11.No violation noted.Major areas inspected:emergency preparedness & observation of full-scale annual exercise on 850910.
VITO,D. BORCHARDT,R.W. HAWKHURST,J.J. Region 1, Office of Director. 85/10/15. 10pp. 33101:099-33101:108.

8510250420 Forwards Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930.No violation noted.
WENZINGER,E.C. Region 1, Office of Director. 85/10/21. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 33173:001-33173:018.

-8510250435 Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930.No violation noted.Major areas inspected:control room,plant structures,plant operations,radiation protection,physical security,maint,surveillance & emergency preparedness.
FOLEY,T., TRIMBLE,D.C., ELSASSER,T.C. Region 1, Office of Director. 85/10/17. 16pp. 33173:003-33173:018.

P. Operating license stage documents & correspondence

8510080388 Forwards FR notice of environ assessment & finding of no significant impact.
* Operating Reactors Branch 3. 85/09/26. Division of Rules and Records. 1p. 32927:013-32927:018.

-8510080405 Forwards notice of environ assessment & finding of no significant impact re 850815 application for exemption from certain scheduler requirements of 10CFR50,App J for integrated leak rate tests.
BUTCHER,E.J. Operating Reactors Branch 3. 85/09/26. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 32927:014-32927:015.

-8510080414 Notice of environ assessment & finding of no significant impact supporting proposed exemption from scheduler requirements of App J to 10CFR50 Section III.D.1(a) re integrated leak rate test during insp outage.
LAINAS,G.C. Assistant Director for Operating Reactors. 85/09/26. 3pp. 32927:016-32927:018.

8510070173 Provides supplemental info to 850426 request for amends to Licenses DPR-53 & DPR-69,clarifying surveillance requirements for tendon end anchorages & adjacent concrete surfaces,including concrete surface insps.
DENTON,R. Baltimore Gas & Electric Co. 85/09/30. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 32881:120-32881:121.

8510040468 Forwards corrected "Summary of Startup Testing for Cycle 8." Previous transmittal consisted of two copies of Tables 3 & 4 but no Table 5.
STANLEY,J.E. Baltimore Gas & Electric Co. 85/10/09. Director's Office, Office of Inspection and Enforcement. 1p. 33015:140-33015:150.

-8510150469 Forwards "Summary of Startup Testing for Cycle 8." Testing completed on 850903.
LUNDVALL,E.A. Baltimore Gas & Electric Co. 85/10/08. MURLEY,T.E. Region 1, Office of Director. 1p. 33015:141-33015:141.

-8510150473 Corrected "Summary of Startup Testing for Cycle 8."
* Baltimore Gas & Electric Co. 85/10/08. 9pp. 33015:142-33015:150.

8510240648 Advises that methodology described in 840907 ltr re proprietary CENPD-269-P,Rev 1-P,acceptable for referencing in actions involving calculations for extended burnup designs.Safety evaluation encl.
BUTCHER,E.J. Operating Reactors Branch 3. 85/10/10. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 33185:006-33185:032.

-8510240652 Safety evaluation re extended burnup of C-E PWR fuel. Methodologies acceptable for extended burnup application.
* Office of Nuclear Reactor Regulation, Director. 85/10/10. 25pp. 33185:008-33185:032.

8510280339 Submits proposed schedule for compliance w/10CFR50.62 re ATWS final rule.Final implementation date for Unit 1 extended beyond second refueling outage due to long lead time to schedule major work items.
LUNDVALL,E.A. Baltimore Gas & Electric Co. 85/10/16. BUTCHER,E. Operating Reactors Branch 3. 2pp. 33193:239-33193:240.

8510310044 Forwards response to 850709 request for addl info re performance testing of safety & relief valves,per TMI Action Item II.D.1.
LUNDVALL,E.A. Baltimore Gas & Electric Co. 85/10/23. BUTCHER,E.J. Operating Reactors Branch 3. 37pp. 33273:342-33274:015.

Q. Inspection reports, IE Bulletins & correspondence

8510250414 Confirms 850815 telcon granting extension from 30 days to 60 days to respond to violations noted in Insp Repts 50-317/85-16 & 50-318/85-14,due to complex technical issues involved.
TIERNAN,J.A. Baltimore Gas & Electric Co. 85/08/16. MURLEY,T.E. Region 1, Office of Director. 1p. 33172:317-33172:317.

8509180248 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course.Deceptive insp practices not condoned by industry.
TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. LUNDVALL,E.A. Baltimore Gas & Electric Co. 11pp. 32854:349-32854:359.

8510040408 Forwards safety evaluation granting relief from radiographic & visual insp of reactor coolant pump casings required by ASME Boiler Pressure Vessel Code,Section XI Proposed alternate form of exam acceptable.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/09/18. LUNDVALL,E.A. Baltimore Gas & Electric Co. 4pp. 32860:037-32860:046.

-8510040412 Safety evaluation granting relief from radiographic & visual insp of reactor coolant pump casings.
* Office of Nuclear Reactor Regulation, Director. 85/09/18. 6pp. 32860:041-32860:046.

8510080031 EN-85-066 on or about 850926,notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to licensee.Action based on failure to implement & maintain installed upgraded post-accident sampling sys.
KLINGLER,G. AXELRAD,J. Director's Office, Office of Inspection and Enforcement. 85/09/23. 1p. 32918:293-32918:293.

8510030090 Notification of Significant Licensee Meeting 85-97 on 851015 w/utl in King of Prussia,PA for presentation of ultrasonic data recording & processing sys in support of inservice insp.
ELSASSER,T. Region 1, Office of Director. 85/09/25. Region 1, Office of Director. 2pp. 32849:327-32849:328.

8510110110 Forwards Exam Repts 50-317/85-23 & 50-318/85-23 of exam administered during wk of 850819.
WENZINGER,E.C. Region 1, Office of Director. 85/09/25. LUNDVALL,A.E. Baltimore Gas & Electric Co. 2pp. 32974-215-32974-316.

-8510110112 Exam Repts 50-317/85-23 & 50-318/85-23 on 850820-23.Exam results:one reactor operator & three senior reactor operator licenses will be issued.One senior reactor operator failed written exam.
DUDLEY,N.F., KELLER,R.M., KISTER,H.B. Region 1, Office of Director. 85/09/20. 100pp. 32974-217-32974-316.

8510040243 Discusses Special Team Insp Repts 50-317/85-16, 50-318/85-14,50-317/85-18 & 50-318/85-16 on 850624-28 & 0715-19 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.
MURLEY,T.E. Region 1, Office of Director. 85/09/26. LUNDVALL,E.A. Baltimore Gas & Electric Co. 3pp. 32860-114-32860-121.

-8510040253 Notice of violation & proposed imposition of civil penalty in amount of \$50,000 Violation noted:failure to implement & upgrade post-accident sampling sys per NUREG-0737.
* Region 1, Office of Director. 85/09/26. 5pp. 32860-117-32860-121.

8510080388 Forwards FR notice of environ assessment & finding of no significant impact.
* Operating Reactors Branch 3. 85/09/26. Division of Rules and Records. 1p. 32927-013-32927-018.

-8510080414 Notice of environ assessment & finding of no significant impact supporting proposed exemption from scheduler requirements of App J to 10CFR50 Section III.D.1(a) re integrated leak rate test during insp outage.
LAJNAS,G.C. Assistant Director for Operating Reactors. 85/09/26. 3pp. 32927-016-32927-018.

8509260122 IE Info Notice 85-079. "Inadequate Communications Between Maint.Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070173 Provides supplemental info to 850426 request for amends to Licenses DPR-53 & DPR-69,clarifying surveillance requirements for tendon end anchorages & adjacent concrete surfaces,including concrete surface insps.
DENTON,R. Baltimore Gas & Electric Co. 85/09/30. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 32881-120-32881-121.

8509260369 Suppl 1 to IE Info Notice 85-017. "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210140 Responds to NRC 850808 ltr re violations noted in Insp Repts 50-317/85-16 & 50-318/85-14 Corrective actions:mods to post-accident sampling sys being evaluated to reduce maint problems,including installation of manual valves.
LUNDVALL,E.A. Baltimore Gas & Electric Co. 85/10/08. MURLEY,T.E. Region 1, Office of Director. 7pp. 33071-352-33071-358.

8510150022 IE Info Notice 85-080. "Timely Declaration of Emergency Class,Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510180056 Clarifies alternate exams in 850918 SER re inservice insp program:Page 6 of SER restated part of proposed exams incorrectly:Reactor coolant pumps will be examined per ASME Code Section XI 1974 Edition during hydrostatic test.
DENTON,R.E. Baltimore Gas & Electric Co. 85/10/15. JAFFE,D.H. Operating Reactors Branch 3. 2pp. 33059-344-33059-345.

8510150025 IE Info Notice 85-081. "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082. "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510230158 Forwards Safety Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11 No violations noted.
BELLAMY,R.R. Region 1, Office of Director. 85/10/18. LUNDVALL,A.E. Baltimore Gas & Electric Co. 2pp. 33101-097-33101-108.

-8510230163 Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11.No violation noted.Major areas inspected:emergency preparedness & observation of full-scale annual exercise on 850910.
VITO,D., BORCHARDT,R.W., HAWKHURST,J.J. Region 1, Office of Director. 85/10/15. 10pp. 33101-099-33101-108.

8510250420 Forwards Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930.No violation noted.
WENZINGER,E.C. Region 1, Office of Director. 85/10/21. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 33173-001-33173-018.

-8510250435 Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930.No violation noted.Major areas inspected:control room,plant structures,plant operations,radiation protection,physical security,maint,surveillance & emergency preparedness.
FOLEY,T., TRIMBLE,D.C., ELSASSER,T.C. Region 1, Office of Director. 85/10/17. 16pp. 33173-003-33173-018.

R. Periodic operating reports & related correspondence

8510220089 Monthly operating repts for Sept 1985.W/851007 ltr.
PORTER,R.J., RUSSELL,J.B. Baltimore Gas & Electric Co. 85/09/30. 11pp. 33095-152-33095-162.

S. Reportable occurrences, LERs & related correspondence

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director,div directors & representatives on events occurring since 850909 meeting.List of attendees & viewgraphs encl.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON,H.L. Division of Licensing. 23pp. 33030-243-33030-265.

8510160128 PNO-I-85-076 on 851009,reactor shut down after unsuccessful attempt to identify cause of 1.5 gpm leak from reactor coolant pump 11A controlled bleed off line.Cause by cracked weld.
FOLEY,T., ELSASSER,T. Region 1, Office of Director. 85/10/10. 1p. 33022-131-33022-131.

V. Operator Examinations

8510110110 Forwards Exam Repts 50-317/85-23 & 50-318/85-23 of exam administered during wk of 850819.
WENZINGER,E.C. Region 1, Office of Director. 85/09/25. LUNDVALL,A.E. Baltimore Gas & Electric Co. 2pp. 32974-215-32974-316.

-8510110112 Exam Repts 50-317/85-23 & 50-318/85-23 on 850820-23.Exam results:one reactor operator & three senior reactor operator licenses will be issued.One senior reactor operator failed written exam.
DUDLEY,N.F., KELLER,R.M., KISTER,H.B. Region 1, Office of Director. 85/09/20. 100pp. 32974-217-32974-316.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510080544 Rev 9 to Emergency Response Plan Implementation Procedure ERPIP 5.0. "Preparation & Control of Emergency Response Plan & Implementation Procedures."
RUSSELL,J.B. Baltimore Gas & Electric Co. 85/09/20. 12pp. 32920-049-32920-060.

8510160146 Rev 6 to emergency response plan.
WOOD,J., RUSSELL,J.B. Baltimore Gas & Electric Co. 85/09/25. 68pp. 33021-087-33021-182.

8510080418 Revised emergency response plan implementation procedures, including Rev 3 to ERPIP 4.4.7.5 re post-accident containment atmosphere sampling & Rev 4 to ERPIP 4.4.7.6 re post-accident sample sys & analysis.
* Baltimore Gas & Electric Co. 85/09/30. 57pp. 32922-259-32922-315.

8510080400 Rev 0 to Emergency Response Plan Implementing Procedure ERPIP 4.1.22.2. "Dedicated Communicator."
* Baltimore Gas & Electric Co. 85/10/01. 15pp. 32919-269-32919-283.

8510080476 Change 2 to Rev 10 to Emergency Response Plan Implementing Procedure ERPIP 5.1. "Communications."
* Baltimore Gas & Electric Co. 85/10/01. 9pp. 32922-052-32922-080.

8510080516 Rev 0 to Emergency Response Plan Implementation Procedure ERPIP 4.1.8.1. "Circulating Water Sampling." Procedure 4.3.3. "Liquid Effluent Sampling & Analysis." canceled.
FORGETTE,T.E. Baltimore Gas & Electric Co. 85/10/02. 7pp. 32920-061-32920-067.

8510220268 Rev 0 to Emergency Response Plan Implementation Procedure ERPIP 4.1.32. "Chemistry."
DENTON,R.E. Baltimore Gas & Electric Co. 85/10/02. 6pp. 33087-071-33087-076.

8510090038 Forwards Rev 15 to security plan.Rev withheld (ref 10CFR73.21).
BOWMAKER,N.J. Baltimore Gas & Electric Co. 85/10/03. MURLEY,T.E. Region 1, Office of Director. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32943-045-32943-046.

8510250429 Rev 4 to ERPIP 4.4.7.6. "Dilute Sample."
* Baltimore Gas & Electric Co. 85/10/08. 4pp. 33172-235-33172-238.

8510250474 Emergency response plan implementation procedures,including Rev 13 to table of contents,Rev 9 to ERPIP 4.1.3 re technical support ctr roster & Rev 9 to ERPIP 4.1.4 re operational support ctr roster.
* Baltimore Gas & Electric Co. 85/10/09. 8pp. 33169-323-33169-329.

8510220307 Revised emergency response plan implementation procedures, including Change 2 to Rev 3 to ERPIP 4.4.7.5,deleting syringe sys isolation valve & Rev 2 to ERPIP 4.1.29. "Emergency Operations Facility Director."
* Baltimore Gas & Electric Co. 85/10/14. 27pp. 33085-109-33085-135.

8510230158 Forwards Safety Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11.No violations noted.
BELLAMY,R.R. Region 1, Office of Director. 85/10/18. LUNDVALL,A.E. Baltimore Gas & Electric Co. 2pp. 33101-097-33101-108.

-8510230163 Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11.No violation noted.Major areas inspected:emergency preparedness & observation of full-scale annual exercise on 850910.
VITO,D., KENNY,T.J., LYNCH,T. Region 1, Office of Director. 85/10/15. 10pp. 33101-099-33101-108.

8510250420 Forwards Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930.No violation noted.
WENZINGER,E.C. Region 1, Office of Director. 85/10/21. LUNDVALL,E.A. Baltimore Gas & Electric Co. 2pp. 33173-001-33173-018.

98 DOCKETED ITEMS

—8510250435 Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930. No violation noted. Major areas inspected: control room, plant structures, plant operations, radiation protection, physical security, maint. surveillance & emergency preparedness. FOLEY, T. Region 1, Office of Director. 85/10/17. 16pp. 33173-003-33173-018.

P. Operating license stage documents & correspondence

8510080388 Forwards FR notice of environ assessment & finding of no significant impact.
* Operating Reactors Branch 3. 85/09/26. Division of Rules and Records. 1p. 32927-013-32927-018.

—8510080405 Forwards notice of environ assessment & finding of no significant impact re 850815 application for exemption from certain scheduler requirements of 10CFR50, App J for integrated leak rate tests.
BUTCHER, E.J. Operating Reactors Branch 3. 85/09/26. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 32927-014-32927-015.

—8510080414 Notice of environ assessment & finding of no significant impact supporting proposed exemption from scheduler requirements of App J to 10CFR50 Section III.D.1(a) re integrated leak rate test during insp outage.
LAINAS, G.C. Assistant Director for Operating Reactors. 85/09/26. 3pp. 32927-016-32927-018.

8510070173 Provides supplemental info to 850426 request for amends to Licenses DPR-53 & DPR-69, clarifying surveillance requirements for tendon end anchorages & adjacent concrete surfaces, including concrete surface insps.
DENTON, R. Baltimore Gas & Electric Co. 85/09/30. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 32881-120-32881-121.

8510240648 Advises that methodology described in 840907 ltr re proprietary CENPD-269-P, Rev 1-P, acceptable for referencing in actions involving calculations for extended burnup designs. Safety evaluation encl.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/10. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 33185-006-33185-032.

—8510240652 Safety evaluation re extended burnup of C-E PWR fuel. Methodologies acceptable for extended burnup application.
* Office of Nuclear Reactor Regulation, Director. 85/10/10. 25pp. 33185-008-33185-032.

8510280339 Submits proposed schedule for compliance w/10CFR50.62 re ATWS final rule. Final implementation date for Unit 1 extended beyond second refueling outage due to long lead time to schedule major work items.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 85/10/16. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33193-239-33193-240.

8510310044 Forwards response to 850709 request for add'l info re performance testing of safety & relief valves, per TMI Action Item ILD.1.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 85/10/23. BUTCHER, E.J. Operating Reactors Branch 3. 37pp. 33273-342-33274-015.

Q. Inspection reports, IE Bulletins & correspondence

8510250414 Confirms 850815 telcon granting extension from 30 days to 60 days to respond to violations noted in Insp Repts 50-317/85-16 & 50-318/85-14, due to complex technical issues involved.
TIERNAN, J.A. Baltimore Gas & Electric Co. 85/08/16. MURLEY, T.E. Region 1, Office of Director. 1p. 33172-317-33172-317.

8509180248 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection & Enforcement. 85/09/13. LUNDVALL, A.E. Baltimore Gas & Electric Co. 11pp. 32854-349-32854-359.

8510040408 Forwards safety evaluation granting relief from radiographic & visual insp of reactor coolant pump casings required by ASME Boiler Pressure Vessel Code, Section XI Proposed alternate form of exam acceptable.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/18. LUNDVALL, A.E. Baltimore Gas & Electric Co. 4pp. 32860-037-32860-046.

—8510040412 Safety evaluation granting relief from radiographic & visual insp of reactor coolant pump casings.
* Office of Nuclear Reactor Regulation, Director. 85/09/18. 6pp. 32860-041-32860-046.

8510080031 EN-85-066 on or about 850924, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to licensee. Action based on failure to implement & maintain installed upgraded post-accident sampling sys.
KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection & Enforcement. 85/09/23. 1p. 32918-293-32918-293.

8510030090 Notification of Significant Licensee Meeting 85-97 on 851015 w/util in King of Prussia, PA for presentation of ultrasonic data recording & processing sys in support of inservice insp.
ELSASSER, T. Region 1, Office of Director. 85/09/25. Region 1, Office of Director. 2pp. 32849-327-32849-328.

8510110110 Forwards Exam Repts 50-317/85-23 & 50-318/85-23 of exam administered during wk of 850819.
WENZINGER, E.C. Region 1, Office of Director. 85/09/25. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 32974-215-32974-216.

—8510110112 Exam Repts 50-317/85-23 & 50-318/85-23 on 850820-23. Exam results: one reactor operator & three senior reactor operator licenses will be issued. One senior reactor operator failed written exam.
DUDLEY, N.F., KELLER, R.M., KISTER, H.B. Region 1, Office of Director. 85/09/20. 100pp. 32974-217-32974-316.

8510040243 Discusses Special Team Insp Repts 50-317/85-16, 50-318/85-14, 50-317/85-18 & 50-318/85-16 on 850624-28 & 0715-19 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.
MURLEY, T.E. Region 1, Office of Director. 85/09/26. LUNDVALL, A.E. Baltimore Gas & Electric Co. 3pp. 32860-114-32860-121.

—8510040253 Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violation noted: failure to implement & upgrade post-accident sampling sys per NUREG-0737.
* Region 1, Office of Director. 85/09/26. 5pp. 32860-117-32860-121.

8510080388 Forwards FR notice of environ assessment & finding of no significant impact.
* Operating Reactors Branch 3. 85/09/26. Division of Rules and Records. 1p. 32927-013-32927-018.

—8510080414 Notice of environ assessment & finding of no significant impact supporting proposed exemption from scheduler requirements of App J to 10CFR50 Section III.D.1(a) re integrated leak rate test during insp outage.
LAINAS, G.C. Assistant Director for Operating Reactors. 85/09/26. 3pp. 32927-016-32927-018.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070173 Provides supplemental info to 850426 request for amends to Licenses DPR-53 & DPR-69, clarifying surveillance requirements for tendon end anchorages & adjacent concrete surfaces, including concrete surface insps.
DENTON, R. Baltimore Gas & Electric Co. 85/09/30. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 32881-120-32881-121.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210140 Responds to NRC 850808 ltr re violations noted in Insp Repts 50-317/85-16 & 50-318/85-14. Corrective actions: mods to post-accident sampling sys being evaluated to reduce maint problems, including installation of manual valves.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 85/10/08. MURLEY, T.E. Region 1, Office of Director. 7pp. 33071-352-33071-358.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510180056 Clarifies alternate exams in 850918 SER re inservice insp program. Page 6 of SER restated part of proposed exams incorrectly. Reactor coolant pumps will be examined per ASME Code Section XI 1974 Edition during hydrostatic test.
DENTON, R. Baltimore Gas & Electric Co. 85/10/15. JAFFE, D.H. Operating Reactors Branch 3. 2pp. 33059-344-33059-345.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510230158 Forwards Safety Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11. No violations noted.
BELLAMY, R.R. Region 1, Office of Director. 85/10/18. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 33101-097-33101-108.

—8510230163 Insp Repts 50-317/85-25 & 50-318/85-22 on 850909-11. No violation noted. Major areas inspected: emergency preparedness & observation of full-scale annual exercise on 850910.
VITO, D., BORCHARDT, R.W., HAWKHURST, J.J. Region 1, Office of Director. 85/10/15. 10pp. 33101-099-33101-108.

8510250420 Forwards Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930. No violation noted.
WENZINGER, E.C. Region 1, Office of Director. 85/10/21. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 33173-001-33173-018.

—8510250435 Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930. No violation noted. Major areas inspected: control room, plant structures, plant operations, radiation protection, physical security, maint. surveillance & emergency preparedness.
FOLEY, T., TRIMBLE, D.C., ELSASSER, T.C. Region 1, Office of Director. 85/10/17. 16pp. 33173-003-33173-016.

R. Periodic operating reports & related correspondence

8510220089 Monthly operating repts for Sept 1985. W/851007 ltr.
PORTER, R.J., RUSSELL, J.B. Baltimore Gas & Electric Co. 85/09/30. 11pp. 33095-152-33095-162.

S. Reportable occurrences, LERs & related correspondence

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

V. Operator Examinations

- 8510110110 Forwards Exam Repts 50-317/85-23 & 50-318/85-23 of exam administered during wk of 850819.
WENZINGER,E.C. Region 1, Office of Director. 85/09/25. LUNDVALL,A.E. Baltimore Gas & Electric Co. 2pp. 32974.215-32974.316.
- 8510110112 Exam Repts 50-317/85-23 & 50-318/85-23 on 850820-23 Exam results: one reactor operator & three senior reactor operator licenses will be issued. One senior reactor operator failed written exam.
DUDLEY,N.F. Region 1, Office of Director. 85/09/20. 100pp. 32974.217-32974.316.
- 8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams."
Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8510070575 Requests addl info re program for controlling use of respirators & plans for personnel accessing control room during emergency in order to complete review of Tech Spec & recovery operations plan change requests.
TRAVERS,W.D. TMI Program Office. 85/10/02. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 32900.360-32900.361.
- 8510150310 Temporary Change Notice 4000-1300 85 257 to Rev 0-00 to Emergency Plan Implementing Procedure 4000-IMP-1300.04, "Callout of Duty Roster Personnel."
BEAVER,J.R., MILLER,A., BEVELACQUA,J.J. General Public Utilities Corp. - GPU Service Corp. 85/10/04. 20pp. 33009.066-33009.086.
- 8510150377 Rev 0-00 to Emergency Plan Implementing Procedure 4000-IMP-1300.16, "Contaminated Injuries/Radiation Exposure in Excess of Guidelines," replacing Rev 3 to Procedure 1054.16 Table of contents also encl.
PERKINS,C., BEVELACQUA,J.J. General Public Utilities Corp. - GPU Service Corp. 85/10/08. 15pp. 33009.321-33009.335.
- 8510250219 Ack receipt of 850716 response to NRC 850619 ltr re Insp Rept 50-320/85-10 Apparent security violation remains as written Response, providing measures for preventing similar violations in future, required in 30 days.
MARTIN,T.T. Region 1, Office of Director. 85/10/10. STANDERFER,F. General Public Utilities Corp. - GPU Service Corp. 2pp. 33190.044-33190.045.
- 8510280174 Temporary change notices to Emergency Plan Implementing Procedures 4000-IMP-1300.01, 4000-IMP-1300.02 & 4000-IMP-1300.03 re emergency classification, emergency direction & emergency offsite notifications, respectively.
* General Public Utilities Corp. - GPU Service Corp. 85/10/23. 66pp. 33191.093-33191.158.

G. Adjudicatory correspondence

- 8510020265 Response to NRC motion to conform proposed Tech Specs per 850920 correction to amend of order Requests ASLB issue order notifying all parties that proposed Tech Specs revised per 850920 order. Certificate of Svc encl.
RIDGWAY,D.A. General Public Utilities Corp. - GPU Service Corp. RIDGWAY,D.A. Shaw, Pittman, Potts & Trowbridge. #485 647. 85/09/27. Atomic Safety and Licensing Board Panel. 4pp. 32824.248-32824.251.
- 8510180258 Order granting NRC 850923 motion to conform proposed Tech Specs per NRR 850920 correction to amend of 850808 order. Served on 851016.
WOLFE,S.J., PARIS,O.H., SHON,F.J. Atomic Safety and Licensing Board Panel. #485 794. 85/10/15. Office of the Executive Legal Director. 2pp. 33062.001-33062.002.
- 8510240318 Forwards joint stipulation & motion to approve stipulation re settlement of Environ Coalition on Nuclear Power (ECNP) proposed contentions. Dismissal of proceeding & ECNP as petitioner requested based on resolution of contentions.
CHANDLER,L.J. Hearings Division. #485 880. 85/10/22. WOLFE,S.J., PARIS,O.H., SHON,F.J. Atomic Safety and Licensing Board Panel. 2pp. 33154.258-33154.267.
- 8510240323 Joint stipulation re settlement of Environ Coalition on Nuclear Power proposed contentions.
CHANDLER,L.J. Hearings Division. JOHNSRUD,J. Environmental Coalition on Nuclear Power. RIDGWAY,D.A. General Public Utilities Corp. - GPU Service Corp. 85/10/22. 2pp. 33154.260-33154.261.
- 8510240329 Joint motion to approve joint stipulation re settlement of Environ Coalition on Nuclear Power proposed contentions. Proposed order encl W/Certificate of Svc.
CHANDLER,L.J. Hearings Division. JOHNSRUD,J. Environmental Coalition on Nuclear Power. RIDGWAY,D.A. General Public Utilities Corp. - GPU Service Corp. 85/10/22. Atomic Safety and Licensing Board Panel. 6pp. 33154.262-33154.267.
- 8510240375 Notice of issuance of 851018 amend of Director's 800211 order & motion to conform proposed Tech Specs w/requirements contained in Generic Ltr 83-43 Formal amend of license awaits action by ASLB Svc list encl.
CHANDLER,L.J. Hearings Division. #485 879. 85/10/22. Atomic Safety and Licensing Board Panel. 5pp. 33151.121-33151.175.
- 8510240379 Amend of Director's 800211 order to modify proposed Tech Specs to conform w/requirements contained in Generic Ltr 83-43 Amend of order effective 851122 Certificate of Svc encl.
EISENHUT,D.G. Office of Nuclear Reactor Regulation, Director. 85/10/18. General Public Utilities Corp. - GPU Service Corp. 50pp. 33151.126-33151.175.

H. General correspondence

- 8510150286 Forwards "Cancer Mortality & Morbidity (Incidence) Around TMI" & "Assessment of Cancer Mortality Survey in Three TMI Areas..." in response to K Bloudin 850709 ltr. Actions taken as result of Feb 1983 Salem ATWS events also discussed.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/10/09. CRANSTON,A. Senate. 19pp. 33032.082-33032.211.

- 8510150291 "Cancer Mortality & Morbidity (Incidence) Around TMI."
TOKUHATA,G.K., DIGON,E. Pennsylvania, Commonwealth of. 85/09/30. 52pp. 33032.101-33032.153.

- 8510150295 "Assessment of Cancer Mortality Survey in Three TMI Areas Selected by Local Residents."
* Pennsylvania, Commonwealth of. 85/09/30. 22pp. 33032.154-33032.201.

- 8510150300 Requests response to encl K Bloudin 850708 concerns re Salem ATWS event & TMI accident.
CRANSTON,A. Senate. 85/08/30. Office of Congressional Affairs. 10pp. 33032.202-33032.211.

- 8510180084 Forwards transcript of TMI-2 Advisory Panel meeting in Annapolis, MD re status of util processing of accident water. W/o encl.
MASNIK,M.T. TMI Program Office. 85/10/10. BURNS,P. Affiliation Not Assigned. 1p. 33069.339-33069.339.

- 8510180085 Requests info on status of processed water resulting from 1979 incident.
BURNS,P. Affiliation Not Assigned. 85/10/03. MASNIK,M.T. Office of Nuclear Reactor Regulation, Director. 1p. 33069.340-33069.340.

I. Financial information

- 8510180247 Forwards util 850425 Ltr 5211-85-2080/4410-85-L-0094 per NRC 851003 ltr. Info demonstrates util payment capabilities required by 10CFR140.21.
MORRELL,M.P. General Public Utilities Corp. - GPU Service Corp. 85/10/09. DINITZ,I. Office of State Programs, Director. 1p. 33022.223-33022.226.

F. Operating license stage documents & correspondence

- 7905290232 Forwards NUREG-0557 "Staff Safety Evaluation of Long-Term Post-Accident Cooling of TMI-2."
MATTSON,R.J. Division of Systems Safety. 79/05/09. FRALEY,R. ACRS - Advisory Committee on Reactor Safeguards. 1p. 33013.249-33013.249.

- 7905230274 "Evaluation of Long-Term Post-Accident Core Cooling of TMI-2."
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. NUREG-0557. 79/04/30. 212pp. 33013.250-33013.035.

- 8510040351 Forwards correction to 850808 amend to order, correcting editorial errors & typo in modified proposed Tech Specs re mini-DHR sys & flood protection.
SNYDER,B.J. TMI Program Office. 85/09/20. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 32860.047-32860.055.

- 8510040357 Correction to 850808 amend to order, correcting editorial errors re failure to remove Section 3.7.3.2 from Page 3-7-2 & typo in Section 3/4.7.6 of Tech Specs concerning mini-DHR sys & flood protection.
EISENHUT,D.G. Office of Nuclear Reactor Regulation, Director. 85/09/20. General Public Utilities Corp. - GPU Service Corp. 7pp. 32860.049-32860.055.

- 8510010094 Forwards Rev 3 to "TMI-2 Recovery Program Estimate." Program cost & schedule not significantly changed from Rev 2 or "TMI Defueling Study." Activities to defuel reactor vessel & associated sys will be completed in Sept 1988.
STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 85/09/23. SNYDER,B.J. TMI Program Office. 1p. 32803.032-32803.094.

- 8510010102 Rev 3 to "TMI-2 Recovery Program Estimate."
SANTEE,L.G., STANDERFER,F.R., KINTNER,E.E. General Public Utilities Corp. - GPU Service Corp. 85/08/31. 62pp. 32803.033-32803.094.

- 8510070105 Forwards safety evaluation of util 850208 SER re reactor bldg decontamination & dose reduction activities. Planned activity safe & should meet goal of providing work environ consistent w/ALARA concept.
SNYDER,B.J. TMI Program Office. 85/09/25. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 32901.199-32901.206.

- 8510070109 Safety evaluation re util 850208 SER concerning reactor bldg decontamination & dose reduction activities. Licensee meets programmatic ALARA goals.
* Office of Nuclear Reactor Regulation, Director. 85/09/25. 6pp. 32901.201-32901.206.

- 8510020371 Resume of AN Fasano.
FASANO,A.N. TMI Program Office. 85/09/27. 12pp. 32983.067-32983.078.

- 8510040141 Forwards Rev 7 to "Defueling Water Cleanup (DWC) Sys." technical evaluation rept, revised sys descriptions for DWC reactor vessel cleanup sys & DWC fuel transfer canal/spent fuel pool cleanup sys & applicable drawings.
STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 85/09/27. SNYDER,B.J. TMI Program Office. 1p. 32882.334-32883.047.

- 8510040148 Rev 7 to "Defueling Water Cleanup (DWC) Sys." technical evaluation rept.
BOLDT,G.K., SMITH,E.T. General Public Utilities Corp. - GPU Service Corp. 15737-2-G03-106 R07. 85/09/10. 20pp. 32882.335-32882.354.

- 8510040152 Rev 4 to Sys Description 15737-2-M72-DWC01, "Defueling Water Cleanup Reactor Vessel Cleanup Sys."
BOLDT,G.K., MAYS,R.L., RIDER,R.L. General Public Utilities Corp. - GPU Service Corp. 85/09/06. 24pp. 32882.355-32883.016.

- 8510040155 Rev 4 to Sys Description 15737-2-M72-DWC02, "Defueling Water Cleanup Fuel Transfer Canal/Spent Fuel Pool Cleanup Sys." Applicable drawings, including two oversize drawings, encl.
BOLDT,G.K., MAYS,R.L., RIDER,R.L. General Public Utilities Corp. - GPU Service Corp. 85/09/06. 27pp. 32883.017-32883.047.

- 8510040293 Forwards Rev 2 to 4430-84-007R, "Hazards Analysis Potential for Boron Dilution of RCS," in response to 850806 approval of defueling water cleanup sys technical evaluation rept.
STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 85/09/27. SNYDER,B.J. TMI Program Office. 1p. 32854.019-32854.181.

100 DOCKETED ITEMS

- 8510040296 Rev 2 to "Hazards Analysis Potential for Boron Dilution of RCS."
* General Public Utilities Corp. - GPU Service Corp. 4430-84-007R R02. 85/09/30. 150pp. 32854-020-32854-181.
- 8510040299 Forwards response to 850729 comments re seismic design criteria analysis transmitted in 850416 Itr Waste storage areas, discussed in Section 3.1.2.10, located in reactor bldg, auxiliary bldg & fuel handling bldg.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/09/27. TRAVERS, W.D. TMI Program Office. 5pp. 32853-187-32853-191.
- 8510060139 Notification of contract execution: "Correlation of Radioiodine Resuspension W/Temp at TMI-2," awarded to Daniel & Assoc, Inc.
MACE, M. Technical Assistance Contracts Branch. FIN D-1647. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. CHAN, L. NRC - No Detailed Affiliation Given. 1p. 32925-223-32925-237.
- 8510080146 Contract: "Correlation of Radioiodine Resuspension W/Temp at TMI-2," awarded to Daniel & Assoc, Inc.
DANIEL, J.A. Daniel & Associates, Inc. THOMPSON, R.D. Division of Contracts. FIN D-1647. 85/09/30. 14pp. 32925-224-32925-237.
- 8510040309 Advises that annual review of sys description for processing water storage & recycle sys performed, per NRC 820204 Itr No update required.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/01. SNYDER, B.J. TMI Program Office. 1p. 32854-227-32854-227.
- 8510070271 Confirms appearance at Advisory Panel for Decontamination of TMI-2 851016 meeting in Lancaster, PA to present results of cancer mortality & morbidity studies. List of panel members, map & tentative agenda encl.
MASNIK, M.T. Advisory Council for Decontamination of TMI Unit 2. 85/10/03. MULLER, H.A. Pennsylvania, Commonwealth of. 5pp. 32901-215-32901-219.
- 8510080457 Forwards responses to NRC comments on early defueling SER transmitted by NRC 850729 & 0613 Itrs. Addl input being prepared to respond to NRC question re onsite testing of canisters.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/03. SNYDER, B.J. TMI Program Office. 21pp. 32922-006-32922-026.
- 8510150008 Notification of Significant Licensee Meeting 85-101 on 851009 w/utl in King of Prussia, PA to discuss inaccurate Sr-90 calculations.
COWGILL, C.J. Region 1, Office of Director. 85/10/04. Region 1, Office of Director. 1p. 33031-181-33031-181.
- 8510160039 Research Info Ltr 144, "Effect of Hydrogen Gas on Downcomer Fluid Temps During TMI Accident." Forwards "Cooldown Aspects of TMI-2 Accident," based on TG Theofanous study of fluid mixing in thermally stratified flows.
MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33028-168-33028-171.
- 8510090412 "Cooldown Aspects of TMI-2 Accident."
THEOFANOUS, T.G. Purdue Univ., West Lafayette, IN. 85/08/31. 84pp. 33028-172-33028-256.
- 8510180442 Further response to FOIA request for documents re TMI. Forwards App H documents, App H & I documents available in PDR, Apps J & K documents withheld partially or in entirety (ref FOIA Exemptions 5 & 7).
FELTON, J.M. Division of Rules and Records. 85/10/09. BERNABE, L. Government Accountability Project. 7pp. 33077-156-33077-190.
- 8510180500 "Summary of Order Before Commission for Affirmation (SECY-84-475A)."
* NRC - No Detailed Affiliation Given. 85/02/14. 2pp. 33077-187-33077-188.
- 8510160096 Forwards Rev 4 to "SER for Early Defueling of TMI-2 Reactor Vessel." SER revised to incorporate responses to NRC comments & to reflect boration of defueling sys hydraulic fluid.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/10. SNYDER, B.J. TMI Program Office. 1p. 33024-001-33024-079.
- 8510160102 Rev 4 to "SER for Early Defueling of TMI-2 Reactor Vessel."
* General Public Utilities Corp. - GPU Service Corp. 15737-2-G07-108 R04. 85/09/30. 79pp. 33024-002-33024-079.
- 8510180160 Summarizes 850912 meeting w/NRC re program to ensure that filter canisters, mfg by Nuclear Energy Svc (NES), will meet design specs. Rept describing established GPU/Bechtel QA surveillance program & application to NES encl.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/10. SNYDER, B.J. TMI Program Office. 154pp. 33058-265-33058-058.
- 8510220149 Forwards Rev 4 to 1000-PLN-7200-02, "GPU Nuclear Corp Recovery QA Plan for TMI Unit 2." Rev notes changes in organizational structure & incorporates 840613 commitments.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/14. MURLEY, T.E. Region 1, Office of Director. 2pp. 33082-110-33082-246.
- 8510220153 Rev 4 to "GPU Nuclear Corp Recovery QA Plan for TMI Unit 2."
KAZANAS, N.C. General Public Utilities Corp. - GPU Service Corp. 85/07/17. 131pp. 33082-112-33082-246.
- 8510180074 Submits status of auxiliary & fuel handling bldg decontamination schedule for Third Quarter 1985, per 840307 request. Update lists only areas where Tech Spec surveillance not being performed due to ALARA consideration.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/15. SNYDER, B.J. TMI Program Office. 2pp. 33054-113-33054-114.
- 8510220037 Forwards Rev 0 to "Safety Evaluation Summary for Relocation of Missile Shields." Proposed relocation can be accomplished w/o undue risk to health & safety of public. Fee paid.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/17. SNYDER, B.J. TMI Program Office. 1p. 33090-214-33090-220.
- 8510220042 Rev 0 to "Safety Evaluation Summary for Relocation of Missile Shields."
SMITH, M.O., BERRY, H. General Public Utilities Corp. - GPU Service Corp. 4340-3100-85-0156 R0. 85/10/14. 6pp. 33090-215-33090-220.
- 8510230259 Forwards exemption from requirements of 10CFR30.51.40.61, 70.51(d) & 70.53 re record keeping, inventorying & reporting of core SNM, source & byproduct matts, per 840418 request. No exemption from 10CFR70.54 necessary.
SNYDER, B.J. TMI Program Office. 85/10/17. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 3pp. 33106-347-33106-361.
- 8510230262 Exemption from 10CFR30.51.40.61, 70.51(d) & 70.53 requirements, per 850418 request. Exemption from 10CFR70.53 shall expire following completion of defueling effort, including assessment of fuel fines & debris within plant.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/17. General Public Utilities Corp. - GPU Service Corp. 6pp. 33106-350-33106-355.
- 8510230264 Environ assessment & notice of finding of no significant environ impact re exemption from inventory recordkeeping & reporting requirements of 10CFR30.51.40.61, 70.51(d) & 70.53 for core SNM, source & byproduct matts.
SNYDER, B.J. TMI Program Office. 85/10/17. 6pp. 33106-356-33106-361.
- 8510250008 Forwards list of questions resulting from review of 851010 summary of utl/Bechtel QA program for first four filter canisters. Response requested in writing, including explanation of implementation of program.
TRAVERS, W.D. TMI Program Office. 85/10/17. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 6pp. 33226-256-33226-261.
- 8510250025 Requests addl info in order to complete review & evaluation & respond to utl 850911 request re Rev 2 to SER for heavy load handling inside containment, including plans for meeting keff criterion.
TRAVERS, W.D. TMI Program Office. 85/10/18. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 1p. 33226-034-33226-034.
- 8510280083 Informs that encl amend to 800211 order issued in response to 850412 & 0618 Tech Spec Change Requests 48 & 50, respectively, re conformance to Generic Ltr 83-43 concerning recovery operations plan. Requests acceptable.
SNYDER, B.J. TMI Program Office. 85/10/18. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 4pp. 33241-063-33241-114.
- 8510280088 Amend to 800211 order approving 850412 & 0618 requests to modify proposed Tech Specs to conform to Generic Ltr 83-43 & STS concerning recovery operations plan.
EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/10/18. General Public Utilities Corp. - GPU Service Corp. 5pp. 33241-067-33241-071.
- 8510280096 Safety evaluation approving utl 850412 & 0618 requests to modify proposed Tech Specs to conform to Generic Ltr 83-43 & STS concerning recovery operations plan. Modified Tech Specs & transmittal memo for FR notice encl.
* Office of Nuclear Reactor Regulation, Director. 85/10/18. 44pp. 33241-072-33241-114.
- 8510250565 Forwards Amend 25 to License DPR-73 & safety evaluation. Amend changes Section 2.1.2 re gaseous effluents of App B Tech Specs. Epithet used to describe testing of radiation vent monitors changed to "instrument functional test."
SNYDER, B.J. TMI Program Office. 85/10/21. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 3pp. 33240-335-33240-344.
- 8510250591 Amend 25 to License DPR-73, changing Section 2.1.2 re gaseous effluents of App B Tech Specs. Epithet used to describe testing of radiation vent monitors changed to "instrument functional test" to achieve consistency in Tech Specs.
SNYDER, B.J. TMI Program Office. 85/10/21. 4pp. 33240-338-33240-341.
- 8510250594 Safety evaluation supporting Amend 25 to License DPR-73.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33240-342-33240-344.
- 8510300017 Forwards SER supporting Recovery Operations Plan Change Requests 29 & 32 & Change Approval 31. Affected pages encl.
SNYDER, B.J. TMI Program Office. 85/10/21. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 33262-282-33262-281.
- 8510300027 SER supporting Recovery Operations Plan Change Requests 29 & 32.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 18pp. 33262-264-33262-281.
- 8510290212 Forwards addl info re QA surveillance program at Joseph Oat Corp & B&W in response to NRC Question 14 on early defueling SER implementation of programs provides required assurance that canisters meet design specs.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/23. SNYDER, B.J. TMI Program Office. 4pp. 33236-164-33236-167.
- 8510290218 Advises that preliminary defueling activities necessary prior to loading of core debris into defueling canisters & sampling of core debris for analysis by INEL to further knowledge of damaged core, will begin during wk of 851028.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/10/24. SNYDER, B.J. TMI Program Office. 3pp. 33236-336-33236-338.
- 8510300088 Forwards exemption from 10CFR61.55 re waste classification of EPICOR II resin liners. Exemption from 10CFR20.311 unnecessary.
SNYDER, B.J. TMI Program Office. 85/10/24. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 33261-281-33261-295.
- 8510300093 Exemption from 10CFR61.55 re waste classification of EPICOR II resin liners.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/24. General Public Utilities Corp. - GPU Service Corp. 6pp. 33261-283-33261-288.
- 8510300098 Environ assessment & notice of finding of no significant impact re exemption from 10CFR61.55 concerning waste classification of EPICOR II waste liners.
SNYDER, B.J. TMI Program Office. 85/10/24. 7pp. 33261-289-33261-295.

Q. Inspection reports, IE Bulletins & correspondence

- 8510250463 Informs that revs to Protection Plan 1000-PLN-4010.01 re ALARA implementation per Insp Rept 50-320/84-04 will not be implemented before end of 1985 due to unforeseen delays in review process for corporate level document.
STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 85/09/27. MURLEY, T.E. Region 1, Office of Director. 2pp. 33169-330-33169-331.
- 8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510060238 Confirmatory Action Ltr 85-16 re corrective actions on inaccuracies in Sr-90 analyses found during Special Insp 50-320/85-20 on 850930-1002 Assurance that procedures for strontium analysis clear & accurate expected by 851011.
MARTIN,T.T. Region 1, Office of Director. 85/10/02. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 32918-353-32918-354.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230032 Forwards Press Release 85-106 re proposed fine for util alleged violation of NRC requirements concerning employee discrimination in cleanup program.
KAMMERER,C. Office of Congressional Affairs. 85/08/12. MARKEY,E. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-023-33109-024.

8510170143 Forwards Insp Rept 50-320/85-20 on 850930-1002 re 850920 identification of error in Sr-90 analysis procedure using beta spectrometer Enforcement conference scheduled for 851009 at Region 1.
MARTIN,T.T. Region 1, Office of Director. 85/10/07. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 33052-070-33052-076.

-8510170147 Insp Rept 50-320/85-20 on 850930-1002 Violations noted: failure to properly indicate Sr-90 content on radioactive mail shipping papers, resulting in improper classification of waste.
KOTTAN,J.J., COLLINS,D.J., COWGILL,C.J. Region 1, Office of Director. 85/10/07. 5pp. 33052-072-33052-076.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510250219 Ack receipt of 850716 response to NRC 850619 ltr re Insp Rept 50-320/85-10. Apparent security violation remains as written. Response, providing measures for preventing similar violations in future, required in 30 days.
MARTIN,T.T. Region 1, Office of Director. 85/10/10. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 2pp. 33190-044-33190-045.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510240061 Responds to 850812 notice of violation & proposed imposition of civil penalty (EA-84-137), per 10CFR2.201. Allegations re discrimination & harassment of RD Parks denied. Civil penalty protested.
CLARK,P.R. General Public Utilities Corp. - GPU Service Corp. 85/10/21. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 8pp. 33155-191-33155-198.

8510250322 Ack receipt of util 850415 ltr responding to 830722 notice of violation & proposed imposition of civil penalty. Characterization of violation in Item A re JR Floyd certification of 830722 notice as willful is correct.
TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 85/10/21. CLARK,P.R. General Public Utilities Corp. - GPU Service Corp. 3pp. 33226-128-33226-130.

R. Periodic operating reports & related correspondence

8510020005 Submits TMI Program Ofc weekly status rept for wk of 850916-22.
TRAVERS,W.D. TMI Program Office. 85/09/23. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 5pp. 32829-307-32829-311.

8510040041 Submits TMI Program Ofc weekly status rept for wk of 850923-30.
TRAVERS,W.D. TMI Program Office. 85/09/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 4pp. 32860-311-32860-314.

8510150439 Submits TMI Program Ofc weekly status rept for wk of 850930-1006.
TRAVERS,W.D. TMI Program Office. 85/10/07. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 5pp. 33033-200-33033-204.

8510170381 Submits TMI Program Ofc weekly status rept for wk of 851007-11.
TRAVERS,W.D. TMI Program Office. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 5pp. 33048-021-33048-025.

8510280013 Submits TMI Program Ofc weekly status rept for wk of 851012-20.
TRAVERS,W.D. TMI Program Office. 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. SNYDER,B.J. TMI Program Office. 5pp. 33241-332-33241-336.

S. Reportable occurrences, LERs & related correspondence

8510310132 PNO-TMI-85-010 on 851028, initial phase of defueling damaged reactor core will begin. Defueling will involve manipulation of partial fuel assemblies in preparation for loading into canisters. Press release issued.
MOSLAK,T., COWGILL,C., TRAVERS,W. TMI Program Office. 85/10/28. 1p. 33274-028-33274-028.

T. Hearing transcripts on non-antitrust matters

8510290178 Transcript of Advisory Panel on Decontamination of TMI-2 851016 meeting in Lancaster, PA. Pp 1-132.
* Advisory Council for Decontamination of TMI Unit 2. 85/10/16. 136pp. 33230-186-33230-322.

U. Congressional/Executive Correspondence

8510010506 Forwards insert of Page 39, Line 827 of 850417 hearing record on NRC budget. Insert provides addl views on estimate of crude cumulative probability of core melt accident.
KAMMERER,C. Office of Congressional Affairs. 85/09/16. MARKEY,E. House of Rep. Energy & Commerce. 7pp. 32832-060-32832-116.

-8510010590 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident."
ROBERTS,T.M. Commissioners. 85/09/19. ROTH,W.V. Senate, Governmental Affairs. BROOKS,J. House of Rep., Government Operations. SIMPSON,A. Senate, Environment & Public Works. 6pp. 32832-110-32832-116.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230032 Forwards Press Release 85-106 re proposed fine for util alleged violation of NRC requirements concerning employee discrimination in cleanup program.
KAMMERER,C. Office of Congressional Affairs. 85/08/12. MARKEY,E. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-023-33109-024.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 2'pp. 32882-049-32882-075.

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510070471 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-321/85-23 & 50-366/85-23. Corrective actions, operations & shift supervisors retrained in role of emergency director. Procedure 63EP-EIP-073-0 replaced in manual.
GUCWALT, Georgia Power Co. 85/09/24. GRACE,J.N. Region 2, Office of Director. 4pp. 32878-208-32878-211.

8510180169 Discusses violation noted in Insp Repts 50-321/83-15 & 50-366/83-15 re several locked-open valves, including fire protection valve observed unlocked. Violation applied only to Unit 1. Change in administrative controls stated.
GUCWALT, Georgia Power Co. 85/09/30. GRACE,J.N. Region 2, Office of Director. 2pp. 33059-332-33059-333.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522.
KAMMERER,C. Office of Congressional Affairs. 84/07/11. OTTINGER,R.L. House of Rep. Energy & Commerce. NUNN Senate. ROWLAND House of Rep. 2pp. 33109-019-33109-020.

8510150296 Forwards Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/08. KELLY,R.J. Georgia Power Co. 2pp. 33009-098-33009-099.

-8510150304 Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted. Major areas inspected: program audit, records & repts, testing & maint, locks & keys. Details withheld (ref 10CFR2.790(d) & 73.21).
MASNYK,O.M., MCGUIRE,D.R. Region 2, Office of Director. 85/10/02. 1p. 33009-100-33009-100.

8510250250 Forwards amend to security plan. Amend withheld (ref 10CFR73.21 & 2.790).
BECKHAM,J.T. Georgia Power Co. 85/10/10. GRACE,J.N. Region 2, Office of Director. 1p. 33172-270-33172-270.

8510250448 Revised emergency plan implementing procedures, including Rev 1 to 62RP-RAD-008-OS, "Radiation & Contamination Surveys" & Rev 1 to 62HI-OCB-047-OS, "HP Well Counter Sys." W/851021 ltr.
ZAVADOSKI,R.W., SORRELLE,E.C. Georgia Power Co. 85/10/21. 45pp. 33173-046-33173-090.

102 DOCKETED ITEMS

I. Financial information

8510170029 Advises that financial info submitted for 1985 in 850726 ltr satisfies requirements of 10CFR140.21.
SALTZMAN, J. Assistant Director for State & License Relations. 85/10/01.
COOK, L.A. Georgia Power Co. 1p. 33043-222-33043-222.

P. Operating license stage documents & correspondence

8510040138 Informs that justification in 850719 submittal adequately supports proposed schedule for completing ATWS mods. Proposal to implement ATWS mods by end of third refueling outage following effective ATWS 840726 rule acceptable.
THOMPSON, H.L. Division of Licensing. 85/09/19. BECKHAM, J.T. Georgia Power Co. 3pp. 32860-175-32860-177.

8510010098 Responds to 850607 request for info re Generic Ltr 83-28, Item 1.1 re post-trip review. Forwards Rev 0 to Engineering Svc Procedure 42EN-ENG-011-OS, "Scram/Transient Reporting." Fee paid.
GUCWALT, T. Georgia Power Co. 85/09/23. STOLZ, J.F. Operating Reactors Branch 4. 7pp. 32800-208-32800-239.

-8510010114 Rev 0 to Engineering Svc Procedure 42FN-ENG-011-OS, "Scram/Transient Reporting."
* Georgia Power Co. 85/08/23. 25pp. 32800-215-32800-239.

8510150289 Informs that util 850620 ltr on purge & vent mods contained proposed Tech Spec requirements more restrictive than those reviewed by plant review board. Board will review requirements by 8/10/10.
GUCWALT, T. Georgia Power Co. 85/10/04. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33009-110-33009-110.

8510150338 Forwards addl info re 841120 & 850506 responses to Generic Ltr 84-23, "Reactor Water Level Instrumentation in BWRs." Plant capable of effectively compensating for reactor water level indication errors caused by drywell heatup.
GUCWALT, T. Georgia Power Co. 85/10/07. STOLZ, J.F. Operating Reactors Branch 4. 16pp. 33013-011-33013-026.

8510280301 Forwards latest chronological update of util correspondence w/NRR to which written response expected, per util 850815 ltr. Expedient resolution of listed priority items in support of upcoming outage requested.
GUCWALT, T. Georgia Power Co. 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 4pp. 33193-254-33193-258.

8510280420 Discusses status of cable tray support verification program. All supports modified to bring calculated stresses within allowable values.
GUCWALT, T. Georgia Power Co. 85/10/15. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33194-014-33194-016.

8510300217 Forwards Amend 116 to License DPR-57 & safety evaluation. Amend corrects Tech Specs by replacing text inadvertently deleted from Section 4.5.D.2 on Page 3.5-7.
RIVENBARK, G.W. Operating Reactors Branch 4. 85/10/15. BECKHAM, J.T. Georgia Power Co. 2pp. 33261-325-33261-331.

-8510300222 Amend 116 to License DPR-57, correcting Tech Specs by replacing text inadvertently deleted from Section 4.5.D.2 on Page 3.5-7 re RCIC sys & surveillance w/inoperable components.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/15. 4pp. 33261-327-33261-330.

-8510300223 Safety evaluation supporting Amend 116 to License DPR-57.
* Office of Nuclear Reactor Regulation, Director. 85/10/15. 1p. 33261-331-33261-331.

Q. Inspection reports, IE Bulletins & correspondence

8510010277 Forwards, for NRC approval, reestablished license requalification program in response to Exam Rept 50-321/OL-84-01 & deficiencies identified in Insp Repts 50-321/85-07 & 50-366/85-07.
GUCWALT, T. Georgia Power Co. 85/09/24. STOLZ, J.F. Operating Reactors Branch 4. 8pp. 32800-177-32800-184.

8510070471 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-321/85-23 & 50-366/85-23. Corrective actions: operations & shift supervisors retrained in role of emergency director. Procedure 63EP-EIP-073-0 replaced in manual.
GUCWALT, T. Georgia Power Co. 85/09/24. GRACE, J.N. Region 2, Office of Director. 4pp. 32878-208-32878-211.

8510010324 Forwards Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510180169 Discusses violation noted in Insp Repts 50-321/83-15 & 50-366/83-15 re several locked-open valves, including fire protection valve observed unlocked. Violation applied only to Unit 1. Change in administrative controls stated.
GUCWALT, T. Georgia Power Co. 85/09/30. GRACE, J.N. Region 2, Office of Director. 2pp. 33059-332-33059-333.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220413 Forwards Insp Repts 50-321/85-26 & 50-366/85-26 on 850909-13 & notice of violation.
BROWNLEE, L.L. Region 2, Office of Director. 85/10/03. KELLY, R.J. Georgia Power Co. 2pp. 33097-038-33097-056.

-8510220415 Notice of violation from Insp on 850909-13.
* Region 2, Office of Director. 85/10/03. 2pp. 33097-040-33097-041.

-8510220418 Insp Repts 50-321/85-26 & 50-366/85-26 on 850909-13. Violation noted: failure to follow Insp program for Class 2 tubing welds.
CROWLEY, B.R., BLAKE, J.J. Region 2, Office of Director. 85/10/01. 15pp. 33097-042-33097-056.

8510180378 Ack receipt of 850924 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/85-23 & 50-366/85-23. Requirements of 10CFR2.201 met.
WALKER, R.D. Region 2, Office of Director. 85/10/04. KELLY, R.J. Georgia Power Co. 1p. 33068-275-33068-275.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-086.

-8510230042 Forwards response to JR Bass 840102 request for info re 831227 imposition of civil penalty in amount of \$100,000.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. NUNN, S. Senate. 1p. 33108-276-33108-276.

-8510230048 Forwards response to JR Bass 840102 request for info re 831227 proposed civil penalty in amount of \$100,000. Listed documentation, including NRC 831227 proposed civil penalty & computer printout describing violations, encl.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. THOMAS, L. House of Rep. 4pp. 33108-277-33108-286.

-8510230058 Requests response to encl JR Bass 840102 ltr re proposed fine against util.
THOMAS, L. House of Rep. 84/02/01. KAMMERER, C. Office of Congressional Affairs. 2pp. 33108-330-33108-331.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522.
KAMMERER, C. Office of Congressional Affairs. 84/07/11. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. MATTINGLY Senate. 2pp. 33109-019-33109-020.

8510150296 Forwards Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted.
BROWNLEE, L.L. Region 2, Office of Director. 85/10/08. KELLY, R.J. Georgia Power Co. 2pp. 33009-098-33009-099.

-8510150304 Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted. Major areas inspected: program audit, records & repts, testing & maint. locks & keys. Details withheld (ref 10CFR2.790(d) & 73.21).
MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/02. 1p. 33009-100-33009-100.

8510180373 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/85-22 & 50-366/85-22. Requirements of 10CFR2.201 met.
WALKER, R.D. Region 2, Office of Director. 85/10/09. KELLY, R.J. Georgia Power Co. 1p. 33068-280-33068-280.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510180536 Monthly operating repts for Sept 1985 W/851010 ltr.
KOEBER, G.M., KANIPE, L.M., NIX, H.C. Georgia Power Co. 85/09/30. 13pp. 33068-020-33068-032.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all Insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L., HENDERSON, T. Government Accountability Project. 32pp. 32884-005-32884-001.

-8510020245 Part 21 rept re pump diaphragm failures, initially reported on 800403. Caused by closure of containment isolation valves w/o pump shutdown. Bypass kit available to limit pump pressure. Defects not reportable per 10CFR21.
ROBINSON, A. Comsnp, Inc. 81/04/08. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 3pp. 32890-158-32890-160.

8510016220 LER 85-090-00 on 850827, during preparation for maint on emergency diesel generator A, generator C inadvertently started. Caused by unlicensed personnel entering wrong diesel room. Diesel preventive maint procedure revised. W/850924 ltr. TIPPES, S.B., NIX, H.C. Georgia Power Co. 85/09/24. 3pp. 32809:240-32809:242.

8510180510 LER 85-032-00 on 850918, quarterly surveillance test for drywell main exhaust inboard isolation valve T48-F319 not performed per Tech Specs. Caused by personnel error. Limiting condition for operation initiated. W/851011 ltr. TIPPES, S.B., NIX, H.C. Georgia Power Co. 85/10/11. 3pp. 33067:348-33067:350.

8510250051 LER 85-031-00 on 850920, reactor water cleanup valve isolated & water sample could not be obtained. On 850921, full reactor protection sys logic actuation occurred. Caused by blown seal, sediment blockage & pressure spike. W/851014 ltr. TIPPES, S.B., NIX, H.C. Georgia Power Co. 85/10/14. 4pp. 33190:358-33190:361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBSON, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230042 Forwards response to JR Bass 840102 request for info re 831227 imposition of civil penalty in amount of \$100,000. DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. NUNN, S. Senate. 1p. 33108:276-33108:276.

-8510230048 Forwards response to JR Bass 840102 request for info re 831227 proposed civil penalty in amount of \$100,000. Listed documentation, including NRC 831227 proposed civil penalty & computer printout describing violations, encl. DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. THOMAS, L. House of Rep. 4pp. 33108:277-33108:286.

-8510230058 Requests response to encl JR Bass 840102 ltr re proposed fine against util. THOMAS, L. House of Rep. 84/02/01. KAMMERER, C. Office of Congressional Affairs. 2pp. 33108:330-33108:331.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522. KAMMERER, C. Office of Congressional Affairs. 84/07/11. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL House of Rep. 2pp. 33109:019-33109:020.

V. Operator Examinations

8510010277 Forwards, for NRC approval, reestablished license requalification program in response to Exam Rept 50-321/OL-84-01 & deficiencies identified in Insp Repts 50-321/85-07 & 50-366/85-07. GUCWALT, T. Georgia Power Co. 85/09/24. STOLZ, J.F. Operating Reactors Branch 4. 8pp. 32800:177-32800:184.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8510010506 Forwards insert of Page 39, Line 827 of 850417 hearing record on NRC budget. Insert provides addl views on estimate of crude cumulative probability of core melt accident. KAMMERER, C. Office of Congressional Affairs. 85/09/16. MARKI, E. House of Rep., Energy & Commerce. 7pp. 32832:060-32832:116.

-8510010512 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review. PALLADINO, N.J. Commissioners. 85/09/17. MARKEY, E. House of Rep., Energy & Commerce. 3pp. 32832:067-32832:069.

-8510010525 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review. PALLADINO, N.J. Commissioners. 85/09/17. DOWNEY, T.J. House of Rep. 3pp. 32832:070-32832:072.

-8510010532 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review. PALLADINO, N.J. Commissioners. 85/09/17. MRAZEK, R.J. House of Rep. 3pp. 32832:073-32832:075.

-8510010536 Discusses NRC 850620 request that FEMA conduct emergency preparedness exercise at facility. No useful purpose served by exercise that fails to include full & active participation of state & local govts. MRAZEK, R.J., DOWNEY, T.J. House of Rep. MARKEY, E.J. House of Rep., Energy & Commerce. 85/08/05. PALLADINO, N.J. Commissioners. 3pp. 32832:076-32832:078.

8510080451 Forwards Physical Security Insp Rept 50-322/85-25 on 850611-14. No violation noted. MARTIN, T.T. Region 1, Office of Director. 85/10/03. LEONARD, J.D. Long Island Lighting Co. 4pp. 32921:214-32921:220.

-8510080453 Physical Security Insp Rept 50-322/85-25 on 850611-14. No noncompliance noted. Major areas inspected: onsite review of Rev 10 proposed changes to physical security plan & personnel training & qualification. MARTIN, W.G., KEIMIG, R.R. Region 1, Office of Director. 85/10/02. 3pp. 32921:218-32921:220.

8510100056 Forwards evaluation of "LILCO Transition Plan for Shoreham - Rev 5." Six inadequacies identified, including concerns re legal basis for plan authority & written agreements re operations concept. SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 32959:316-32960:031.

-8510100061 "LILCO Transition Plan for Shoreham - Rev 5." Concerns re legal authority identified during regional assistance committee review of Revs 3, 4 & 5 encl. * Federal Emergency Management Agency. 85/09/23. 73pp. 32959:319-32960:031.

8510210040 Decision ALAB-818 affirming ASLB conclusions in LBP-85-12 re util legal authority to implement features of emergency plan. Served on 851018. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 829. 85/10/18. 47pp. 33073:001-33073:047.

8510250385 Forwards response to WR Butler 850819 ltr re review of EG&G evaluation of implementation of Rev 2 to Reg Guide 1.97 concerning emergency response capability. LEONARD, J.D. Long Island Lighting Co. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33172:158-33172:162.

8510290351 Forwards corrected Page 49 to evaluation of Rev 5 of LILCO transition plan for offsite emergency preparedness at facility. Error noted in section dealing w/ NUREG-0654, Element J 12. KRIMM, R.W. Federal Emergency Management Agency. 85/10/24. JORDAN, W.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 4pp. 33236:355-33236:358.

G. Adjudicatory correspondence

8510100042 Forwards State of NY Supreme Court order to show cause why Nassau County, NY county executive should not cease & desist from offering use of facilities or personnel for facility evacuation plan. Related correspondence. PALOMINO, F.G. New York, State of. #485 684. 85/10/01. NRC - No Detailed Affiliation Given. 15pp. 32960:263-32960:277.

85100100140 Submits status rept on State of NY court litigation on emergency planning-related issues per request at 850926 oral argument. Util views re request by Suffolk County & State of NY forwarded w/ Certificate of Svc. Related correspondence. IRWIN, D.P. Hunton & Williams. IRWIN, D.P. Long Island Lighting Co. #485 675. 85/10/02. ROSENTHAL, A.S., EDLES, G.J., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 8pp. 32960:199-32960:206.

8510040361 Order confirming 850515 order denying Suffolk County & State of NY motion for enlargement of existing limitation of length of brief in support of appeal from 850417 partial initial decision. Served on 851003. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 665. 85/10/03. Suffolk County, NY. 2pp. 32853:267-32853:268.

8510100087 Responds to request for rept re status of State of NY court litigation & Hunton & Williams 851002 filing on behalf of util. Permanent injunction against offsite emergency test or review stands. Related correspondence. LATHAM, S. Twomey, Latham & Shea. LATHAM, S. Southampton, NY. #485 687. 85/10/04. ROSENTHAL, A.S., EDLES, G.J., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 10pp. 32960:313-32960:322.

8510110004 Advises that written motion to extend time to file brief on emergency planning will be made during wk of 851009. Extension to filing date for brief on coliseum issue requested. Certificate of Svc encl. KELLEY, E.R. Suffolk County, NY. #485 734. 85/10/04. ROSENTHAL, A.S., EDLES, G.J., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 4pp. 32969:200-32969:203.

8510100081 Order extending time for filing Suffolk County, State of NY & Town of Southampton briefs on appeals from Board 850826 concluding partial initial decision on emergency planning until 851015. Served on 851007. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 690. 85/10/07. New York, State of. 2pp. 32961:059-32961:060.

8510110057 Brief opposing Board 850826 concluding partial initial decision on emergency planning. Requirement to anticipate number of people to be monitored in emergency impossible to meet & should be reversed. Certificate of Svc encl. CHRISTMAN, J.N. Long Island Lighting Co. CHRISTMAN, J.N. Hunton & Williams. #485 730. 85/10/07. Atomic Safety and Licensing Appeal Panel. 37pp. 32999:262-32999:298.

8510110180 Motion for extension of time until 851023 for filing emergency planning appeal brief for 850417 decision & until 851106 for 850826 decision. Certificate of Svc encl. KELLEY, E.R. Suffolk County, NY. PALOMINO, F.G. New York, State of. #485 743. 85/10/08. Atomic Safety and Licensing Appeal Panel. 7pp. 32972:351-32972:357.

8510110196 Motion for extension of time for filing emergency planning appeal briefs. Extension of filing deadline to 851023 for brief re 850417 decision & to 851106 for brief re 850826 decision requested. Certificate of Svc encl. KELLEY, E.R. Suffolk County, NY. PALOMINO, F.G. New York, State of. #485 749. 85/10/08. Atomic Safety and Licensing Appeal Panel. 8pp. 32972:333-32972:340.

8510110237 Response to Suffolk County & State of NY 851007 motion for extension of time until 851023 for filing emergency planning appeal briefs. Staff does not object to 8-day extension for filing brief supporting appeal. BORDENICK, B.M. Hearing Branch 3. #485 742. 85/10/09. Atomic Safety and Licensing Appeal Panel. 7pp. 32974:180-32974:186.

8510150365 Response opposing motion of Suffolk County & State of NY for further emergency planning briefing extensions. Certificate of Svc encl. Related correspondence. IRWIN, D.P. Long Island Lighting Co. IRWIN, D.P. Hunton & Williams. #485 765. 85/10/09. Atomic Safety and Licensing Appeal Panel. 7pp. 33010:018-33010:024.

8510210040 Decision ALAB-818 affirming ASLB conclusions in LBP-85-12 re util legal authority to implement features of emergency plan. Served on 851018. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 829. 85/10/18. 47pp. 33073:001-33073:047.

104 DOCKETED ITEMS

8510220201 Motion for amend to svc lists to add N Bredes & M Schneider. Notice of withdrawal of counsel & Certificate of Svc encl.
DOUGHERTY,J.B. Shoreham Opponents Coalition. DOUGHERTY,J.B. North Shore Committee Against Nuclear & Thermal Pollution. #485 864. 85/10/18. Atomic Safety and Licensing Appeal Panel. 4pp. 33087.313-33087.316.

8510220314 Forwards notice of withdrawal from all aspects of licensing proceeding.Svc list should be revised.W/o notice. Certificate of Svc encl.
DOUGHERTY,J.B. Dougherty, J.B. DOUGHERTY,J.B. Shoreham Opponents Coalition. DOUGHERTY,J.B. North Shore Committee Against Nuclear & Thermal Pollution. #485 863. 85/10/18. Office of the Secretary of the Commission. 3pp. 33084.047-33084.049.

8510280519 Suffolk County,State of NY & Town of Southampton brief on appeal from ASLR 850417 partial initial decision on emergency planning.Certificate of Svc encl.
KELLEY,E.R. Suffolk County. NY. PALOMINO,F.G. New York. State of. LATHAM,S.B. Southampton, NY. #485 925. 85/10/23. Atomic Safety and Licensing Appeal Panel. 108pp. 33227.001-33227.112.

8510290002 Response expressing no objection to Shoreham Opponents Coalition & North Shore Committee Against Nuclear & Thermal Pollution 851018 motion to amend svc list to reflect withdrawal of JB Dougherty Certificate of Svc encl.
BORDENICK,B.M. Hearing Branch 3. #485 912. 85/10/25. Atomic Safety and Licensing Appeal Panel. 4pp. 33236.206-33236.209.

J. Insurance & indemnity information

8510290189 Forwards Endorsement 4 to MAELU Certificate M-82,Endorsement 4 to NELIA Certificate N-82,Endorsement 11 to MAELU Policy MF-115 & Endorsement 19 to NELIA Policy NF-269.
HOFFMAN,J. Marsh; & McLennan, Inc. 85/10/21. DINIZ,I. Office of State Programs, Director. 5pp. 33233.127-33233.131.

P. Operating license stage documents & correspondence

8510020006 Staff requirements memo re 850917 affirmation/discussion & vote in Washington,DC re SECY-85-295 on review of ALAB-800 (Shoreham vital equipment) & SECY-85-178.
CHILK,S.J. Office of the Secretary of the Commission. 85/09/30. DIRCKS,W.J. Office of the Executive Director for Operations. PLAINE,H.H. Office of the General Counsel. 1p. 32829.306-32829.306.

8510150372 Outlines scheduling plan for compliance to final rule 10CFR50.62 on ATWS.Schedule includes work on recirculation pump trip,alternate rod insertion & standby liquid control sys.
LEONARD,J.D. Long Island Lighting Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33010.005-33010.008.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28,Item 1.2 re Salem ATWS events.Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044.010-33044.257.

-8510170159 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-3. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.013-33044.027.

-8507150361 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1522. 85/07/10. NRC - No Detailed Affiliation Given. 14pp. 33044.028-33044.041.

-8510170169 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1517-1. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.042-33044.056.

-8510170174 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-1. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044.057-33044.068.

-8510170178 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-23. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044.069-33044.084.

-8510170180 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1517-5. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.085-33044.099.

-8510170184 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1517-3. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044.100-33044.113.

-8510170187 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-4. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044.114-33044.125.

-8510170190 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-17. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044.126-33044.140.

-8510170193 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-4. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044.141-33044.156.

-8510170199 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/3092. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044.157-33044.170.

-8510170202 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-22. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.171-33044.185.

-8510170205 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1520. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.186-33044.200.

-8510170211 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-8. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044.201-33044.214.

-8510170213 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-1. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044.215-33044.230.

-8510170215 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-12. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044.231-33044.245.

-8510170217 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review>Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-6. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044.246-33044.257.

8510230074 Forwards application for amend to License NPF-36,consisting of Change Request 1,revising Tech Specs re conversion of reactor bldg standby ventilation sys low-range noble gas radiation monitor to vent stack monitor.Fee paid.
LEONARD,J.D. Long Island Lighting Co. 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33101.253-33101.263.

-8510230082 Application for amend to License NPF-36,consisting of Change Request 1,revising Tech Specs re conversion of reactor bldg standby ventilation sys low-range noble gas radiation monitor to vent stack low-range gas radiation monitor.
LEONARD,J.D. Long Island Lighting Co. 85/10/21. 6pp. 33101.255-33101.260.

-8510230086 Proposed Tech Specs re conversion of reactor bldg standby ventilation sys low-range noble gas radiation monitor to vent stack low-range noble gas radiation monitor.
* Long Island Lighting Co. 85/10/21. 3pp. 33101.261-33101.263.

Q. Inspection reports, IE Bulletins & correspondence

8510020016 Ack receipt of undated ltr informing NRC of steps taken to correct violations re post-accident sampling & monitoring sys noted in Insp Rept 50-322/85-04. MARTIN,T.T. Region 1, Office of Director. 85/09/25. LEONARD,J.D. Long Island Lighting Co. 4pp. 32824.216-32824.225.

-8510020019 Responds to NRC 850731 ltr re violations noted in Insp Rept 50-322/85-04.Corrective actions implementation of Station Mods 85-071 & 85-134 re post-accident sampling & monitoring sys will be accomplished by 851001 & 30,respectively.
LEONARD,J.D. Long Island Lighting Co. 85/10/01. MURLEY,T.E. Region 1, Office of Director. 6pp. 32824.220-32824.225.

8510070254 Forwards Safety Insp Rept 50-322/85-31 on 850729-0812 & notice of violation.
EBNETER,S.D. Region 1, Office of Director. 85/09/26. LEONARD,J.D. Long Island Lighting Co. 2pp. 32883.343-32883.358.

-8510070256 Notice of violation from insp on 850729-0812.

* Region 1, Office of Director. 85/09/26. 4pp. 32883-345-32883-348.

-8510070260 Insp Rept 50-322/85-31 on 850729-0812 Violation noted: failure of test personnel to implement governing startup test procedures for activities affecting quality.

FLOREK,D., KUCHARSKI,S., ESELGROTH,P. Region 1, Office of Director. 85/09/18. 10pp. 32883-349-32883-358.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint.Operations & Security Personnel." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080451 Forwards Physical Security Insp Rept 50-322/85-25 on 850611-14 No violation noted.

MARTIN,T.T. Region 1, Office of Director. 85/10/03. LEONARD,J.D. Long Island Lighting Co. 4pp. 32921-214-32921-220.

-8510080453 Physical Security Insp Rept 50-322/85-25 on 850611-14.No noncompliance noted.Major areas inspected:onsite review of Rev 10 proposed changes to physical security plan & personnel training & qualification.

MARTIN,T.T., KEIMIG,R.R. Region 1, Office of Director. 85/10/02. 3pp. 32921-218-32921-220.

8510170254 Forwards Safety Insp Rept 50-322/85-35 on 850830-0913.No violations noted.

EBNETER,S.D. Region 1, Office of Director. 85/10/07. LEONARD,J.D. Long Island Lighting Co. 4pp. 33051-241-33051-250.

-8510170257 Insp Rept 50-322/85-35 on 850830-0913.No violations noted. Major areas inspected:startup test program,activities & licensee investigation of reactor water level indication problems & unplanned reactor scrams.

PETRONE,C., JOHNSON,J. Region 1, Office of Director. 85/10/02. 6pp. 33051-245-33051-250.

8510210219 Forwards Safety Insp Rept 50-322/85-32 on 850812-30.No violation noted.

EBNETER,S.D. Region 1, Office of Director. 85/10/10. LEONARD,J.D. Long Island Lighting Co. 4pp. 33094-312-33094-324.

-8510210228 Insp Rept 50-322/85-32 on 850812-30.No violations noted. Major areas inspected:startup test program during test condition heatup,including startup test witnessing,results evaluation,procedure review & technical review committee.

CAPHTON,D., FLOREK,D., PETRONE,C. Region 1, Office of Director. 85/10/04. 9pp. 33094-316-33094-324.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class,Implementation of Emergency Plan & Emergency Notifications." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.

JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510020100 Monthly operating rept for Jul 1985 W/850812 ltr.

KELLY,D., STEIGER,W.E. Long Island Lighting Co. 85/07/31. 5pp. 32827-317-32827-321.

8510170003 Monthly operating rept for Sept 1985 W/851004 ltr.

KELLY,D., STEIGER,W.E. Long Island Lighting Co. 85/09/30. 4pp. 33053-199-33053-202.

S. Reportable occurrences, LERs & related correspondence

8510010013 LER 85-033-00 on 850825, inadvertent split of reactor bldg closed loop cooling water into accident mode occurred.Caused by personnel error due to reproductive quality of drawing. Drawings reviewed for clarity W/850924 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/09/24. 2pp. 32809-213-32809-214.

8510030376 LER 85-034-00 on 850826,hinged cap on svc water standpipe found wedged shut.Cause unknown.Wedge & temporary scaffolding removed to prevent immediate access to standpipe W/850926 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/09/26. 3pp. 32846-066-32846-068.

8510030412 LER 85-035-00 on 850831,operator manually initiated reactor protection sys after receiving scram pilot valve air header pressure low & control rod drift alarms.Caused by clogging of instrument air dryer afterfilter W/850926 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/09/26. 4pp. 32846-026-32846-032.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.

LAITY,W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER,C. Division of Licensing. 26pp. 32824-280-32824-305.

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets.Insp for Callaway Unit 1 postponed until next refueling outage (probably A/c 1986).No cracks discovered during insp at Wolf Creek.

SCHREIBER,H. Louis-Allis Co. 85/09/30. NAIDU,K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851-100-32851-107.

8510040315 PNO-I-85-072:advising that current util contract w/YOH Security guards expires on 851001.Contingency security guard force assembled.Strike not expected to affect plant operations.

STROSNIDER Region 1, Office of Director. 85/09/30. 1p. 32853-251-32853-251.

8510090101 LER 85-037-00 on 850906,low Level 3 scram occurred.Caused by technician valving transmitter back into svc & not detecting pressure perturbation traveling through instrument line to variable leg info tags hung on instruments.W/851003 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/03. 4pp. 32948-014-32948-017.

8510090287 LER 85-036-00 on 850903,25.27 & 1001,reactor water cleanup inboard isolations occurred due to high delta flow trips. Isolations attributed to problems w/flow sensing circuitry sys & returned to normal.W/851003 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/03. 3pp. 32947-088-32947-090.

8510170363 LER 85-039-00 on 850909 & 18,while performing surveillance procedure on reactor bldg standby ventilation sys filter trains,control room air conditioning initiations occurred due to low differential pressure condition W/851008 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/08. 3pp. 33053-337-33053-339.

8510180154 LER 85-040-00 on 850909,reactor bldg standby ventilation sys/control room air conditioning initiation occurred due to undervoltage condition.Caused by decrease in 138-kV offsite power due to lightning storm.W/851008 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/08. 2pp. 33068-341-33068-342.

8510180179 LER 85-038-00 on 850908,water level indicator associated w/ref leg B read high & diverged from water level indicators associated w/ref leg A.Caused by excess condensate accumulation in steam line.W/851008 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/08. 3pp. 33068-346-33068-348.

8510170368 LER 85-042-00 on 850912,low level reactor trip occurred during Operational Condition 2.Caused by operator opening & closing test valve,producing pressure oscillation in narrow range variable leg A.Operator counseled W/851011 ltr.

RHOADS,G.G., STEIGER,W.E. Long Island Lighting Co. 85/10/11. 2pp. 33053-335-33053-338.

8510220007 LER 85-043-00 on 850917,full reactor trip occurred due to low level signal.Caused by hydraulic oscillation when instrument test equipment valved in.Procedures to be revised W/851016 ltr.

GRUNSEICH,B., STEIGER,W.E. Long Island Lighting Co. 85/10/16. 4pp. 33095-325-33095-328.

8510250026 LER 85-044-00 on 850920,reactor water cleanup isolation occurred.Caused by personnel error.Sys replaced in svc. Incident reviewed w/personnel involved.Walkdown completed. Several panels examined W/851017 ltr.

GRUNSEICH,B., STEIGER,W.E. Long Island Lighting Co. 85/10/17. 3pp. 33190-300-33190-302.

8510300306 Forwards PNL-5336, "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Shoreham Nuclear Power Station Unit 1," technical evaluation rept.

LAITY,W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/10/17. BERLINGER,C. Division of Licensing. 1p. 33262-001-33262-128.

-8510300314 "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Shoreham Nuclear Power Station Unit 1," technical evaluation rept.

LAITY,W.W., RICHMOND,W.D. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2963. PNL-5336. 85/10/31. BERLINGER,C.H. Division of Licensing. 125pp. 33262-002-33262-128.

T. Hearing transcripts on non-antitrust matters

8510010194 Transcript of 850926 oral argument in Bethesda,MD Pp 1-67.

* Atomic Safety and Licensing Appeal Panel. 85/09/26. 69pp. 32800-108-32800-176.

U. Congressional/Executive Correspondence

8510010506 Forwards insert of Page 39,Line 827 of 850417 hearing record on NRC budget.Insert provides addl views on estimate of crude cumulative probability of core melt accident.

KAMMERER,C. Office of Congressional Affairs. 85/09/16. MARKEY,E. House of Rep., Energy & Commerce. 7pp. 32832-060-32832-116.

-8510010512 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility.Commission position has not changed during course of facility licensing review.

PALLADINO,N.J. Commissioners. 85/09/17. MARKEY,E. House of Rep., Energy & Commerce. 3pp. 32832-067-32832-069.

-8510010525 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility.Commission position has not changed during course of facility licensing review.

PALLADINO,N.J. Commissioners. 85/09/17. DOWNEY,T.J. House of Rep. 3pp. 32832-070-32832-072.

-8510010532 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility.Commission position has not changed during course of facility licensing review.

PALLADINO,N.J. Commissioners. 85/09/17. MRAZEK,R.J. House of Rep. 3pp. 32832-073-32832-075.

106 DOCKETED ITEMS

—8510010536 Discusses NRC 850620 request that FEMA conduct emergency preparedness exercise at facility No useful purpose served by exercise that fails to include full & active participation of state & local govts.
MRAZEK, H.J., DOWNEY, T.J., House of Rep. MARKEY, E.J., House of Rep., Energy & Commerce. 85/08/05. PALLADINO, N.J. Commissioners. 3pp. 32832-076-32832-078.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L., Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

E. NRC Safety Evaluation Report (SER), suppis & correspondence

8510160151 Informs of review completion of inservice testing program documented in SSER 31 Further discussions required to clarify NRC evaluations of Items 3, 4 & 13 in Section 5.2.8.1. Meeting requested for 851104-05 in Bethesda, MD.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/11. KNIGHTON, G.W., Licensing Branch 3. 7pp. 33021-186-33021-192.

F. Security, medical, emergency & fire protection plans

8510090348 Forwards Insp Rept 50-323/85-27 on 850810-16 & 0904. No noncompliance noted.
KIRSCH, D.F., Region 5, Office of Director. 85/09/19. SHIFFER, J.D., Pacific Gas & Electric Co. 1p. 32947-147-32947-154.

—8510090350 Insp Rept 50-323/85-27 on 850810-16 & 0904. No violation noted. Major areas inspected: status of fire detection/alarms sys for one fire zone & procedures used to identify operational status of equipment in need of repair & maint.
CREWS, J.L., JOHNSON, A.D., HUEY, R.F., Region 5, Office of Director. 85/09/19. 7pp. 32947-148-32947-154.

8510010239 Forwards physical security plan mode change notification. Encl withheld (ref 10CFR73.21).
SHIFFER, J.D., Pacific Gas & Electric Co. 85/09/23. MARTIN, J.B., Region 5, Office of Director. 1p. 32802-239-32802-239.

8510070076 Informs of team insp scheduled for 851118-22 to ensure compliance w/ Sections III, G, J, L & O of App R to 10CFR50. Info will be requested during next several wks to support insp effort.
KIRSCH, D.F., Region 5, Office of Director. 85/09/30. SHIFFER, J.D., Pacific Gas & Electric Co. 2pp. 32881-015-32881-016.

8510180139 Forwards public version of revised emergency plan implementing procedures, including Rev 9 to EP R-6 re radiological fire & Rev 11 to EP M-6 re non-radiological fire.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/04. MARTIN, J.B., Region 5, Office of Director. 1p. 33015-217-33015-165.

—8510180143 Public version of revised emergency plan implementing procedures, including Rev 9 to EP R-6 re radiological fire & Rev 11 to EP M-6 re non-radiological fire. W/JM Felton 851015 transmittal memo.
* Pacific Gas & Electric Co. 85/10/04. 150pp. 33075-216-33075-216.

8510240497 Notification of 851106 & 07 meetings w/util in Bethesda, MD to discuss status of licensee DCRDR.
SCHIERLING, H., Licensing Branch 3. 85/10/15. KNIGHTON, G.W., Licensing Branch 3. 4pp. 33182-160-33182-163.

G. Adjudicatory correspondence

851019202 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
HAS, T.L.D.F., Hearing Branch 2. #485 737. 85/10/09. 3pp. 32574-030-32974-032.

J. Insurance & indemnity information

8510170275 Forwards Endorsement 46 to NELIA Policy NF-228 & Endorsement 17 to MALEU Policy MF-103.
CRANE, P.A., Pacific Gas & Electric Co. 85/10/10. SALTZMAN, J., Assistant Director for State & Licensee Relations. 3pp. 33039-290-33039-292.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510020043 Forwards Rev 1 to updated FSAR & instruction sheets. Rev reflects status of Unit 1 through 850322. Lists changes not submitted to Commission.
SHIFFER, J.D., CRANE, P.A., Pacific Gas & Electric Co. 85/09/20. DENTON, H.R., Office of Nuclear Reactor Regulation, Director. 2pp. 32991-001-32996-001.

—8510020046 Rev 1 to updated FSAR for Diablo Canyon, Units 1 & 2. W/17 oversize figures.
* Pacific Gas & Electric Co. 85/09/30. 3,058pp. 32991-005-32999-182.

P. Operating license stage documents & correspondence

8510180201 FOIA request for documents re Ofc of Inspector & Auditor charges that NRC responded improperly to allegations of possible QA & safety violations by whistleblowers at plant.
DEVINE, T., Government Accountability Project. 85/08/20. Office of Administration. 2pp. 33028-359-33028-360.

8510010064 Responds to FOIA request for correspondence NRC received from Barnes, Byron, Methias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDR. Forwards documents listed on app.
FELTON, J.M., Division of Rules and Records. 85/09/04. DEZUBE, D., Montgomery County Sentinel. 3pp. 32831-087-32831-116.

—8510010172 Forwards Washington Post 840712 article entitled, "NRC Engineer Resigns From Diablo Task Force." Info requested on NRC role in safety investigations.
BARNES, M.D., House of Rep. 84/07/12. PALLADINO, N.J., Commissioners. 2pp. 32831-121-32831-122.

—8510010186 Ack receipt of ltr requesting info re status of licensing for facility. Forwards Chairman Palladino & H. Denton statements. Results of ACRS review also encl. W/o encl.
KAMMERER, C., Office of Congressional Affairs. 84/07/20. BARNES, M.D., House of Rep. 1p. 32831-123-32831-123.

8510090408 Ack receipt of 850719 ltr providing info for request not to perform loss of offsite power test w/turbine trip during startup program review. Request denied. Test coincident w/turbine trip must be performed.
KNIGHTON, G.W., Licensing Branch 3. 85/10/02. SHIFFER, J.D., Pacific Gas & Electric Co. 3pp. 32964-324-32964-326.

8510160205 Responds to FOIA request for documents re Ofc of Inspector & Auditor inquiry into charges that NRC responded improperly to allegation by whistleblowers. Documents withheld (ref FOIA Exemptions 5 & 7(a)).
FELTON, J.M., Division of Rules and Records. 85/10/03. DEVINE, T., Government Accountability Project. 2pp. 33028-361-33028-362.

8510180506 Notification of 851021 meeting w/util in Bethesda, MD to discuss long term seismic program on soil-structure interaction.
SCHIERLING, H., Licensing Branch 3. 85/10/08. KNIGHTON, G.W., Licensing Branch 3. 5pp. 33077-193-33077-197.

8510180020 Advises that licensee will implement 10CFR50.62 requirements for reduction of risk from ATWS events by completion of second refueling outage, per Generic Ltr 85-06, "QA Guidance for Nonsafety-Related ATWS Equipment."
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/14. DENTON, H.R., Office of Nuclear Reactor Regulation, Director. 2pp. 33054-007-33054-008.

8510280362 Advises that investigations in response to Allegations 1722, 1723, 1724 & 1725 forwarded on 850905 still in progress. Responses will be submitted by 851101.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/14. MARTIN, J.B., Region 5, Office of Director. 1p. 33192-063-33192-063.

8510240506 Notification of 851104-05 meetings w/util in Bethesda, MD to discuss inservice testing & insp.
SCHIERLING, H., Licensing Branch 3. 85/10/15. KNIGHTON, G.W., Licensing Branch 3. 4pp. 33182-149-33182-152.

8510300065 Informs that reactor coolant conductivity will be deleted as acceptance criteria from Rev 3 of STP G-14, "Operability Determination of Post-Accident Sampling Program," per review of SENTRY post-accident sampling sys.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/22. KNIGHTON, G.W., Licensing Branch 3. 1p. 33250-348-33250-348.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G., Licensing Branch 4. 85/10/22. FOSTER, D.O., Georgia Power Co. 1p. 33262-231-33262-231.

—8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.), NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510290059 Forwards application for amends to Licenses DPR-80 & DPR-82, modifying loose parts detection sys instrumentation, RCS relief valves, RCS pressure/temp limits & administrative controls for startup repts. Fee paid.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/24. DENTON, H.R., Office of Nuclear Reactor Regulation, Director. 1p. 33236-116-33236-134.

—8510290062 Application for amends to Licenses DPR-80 & DPR-82, modifying loose parts detection instrumentation, RCS relief valves, RCS pressure/temp limits & administrative controls for startup repts.
SHIFFER, J.D., Pacific Gas & Electric Co. 85/10/24. 1p. 33236-117-33236-117.

—8510290069 Proposed Tech Specs, modifying loose parts detection sys, operability requirements for PORV, revising spec re pressure/temp limits & clarifying & revising initial & subsequent startup rept requirements.
* Pacific Gas & Electric Co. 85/10/24. 17pp. 33236-118-33236-134.

8510290267 Forwards application for amends to Licenses DPR-80 & DPR-82, changing Tech Specs to reduce excessive testing of diesel generators & provide preventive maint times, per Generic Ltr 84-15. Fee paid.
MANEATIS, G.A., Pacific Gas & Electric Co. 85/10/25. DENTON, H.R., Office of Nuclear Reactor Regulation, Director. 1p. 33235-005-33235-024.

—8510290276 Application for amends to Licenses DPR-80 & DPR-82, changing Tech Specs to reduce excessive testing of diesel generators & provide maint times consistent w/manufacture recommendations & previous experience, per Generic Ltr 84-15.
MANEATIS, G.A., Pacific Gas & Electric Co. 85/10/25. 8pp. 33235-006-33235-013.

—8510290285 Proposed Tech Specs, reducing excessive testing of diesel generators & providing maint times for diesel generators consistent w/manufacture recommendations & previous maint & repair experience, per Generic Ltr 84-15.
* Pacific Gas & Electric Co. 85/10/25. 11pp. 33235-014-33235-024.

Q. Inspection reports, IE Bulletins & correspondence

8510030265 Forwards Insp Repts 50-275/85-30 & 50-323/85-28 on 850826-30. No violations noted.
WENSLAWSKI, F.A., Region 5, Office of Director. 85/09/16. SHIFFER, J.D., Pacific Gas & Electric Co. 1p. 32845-317-32845-323.

—8510030268 Insp Repts 50-275/85-30 & 50-323/85-28 on 850826-30. No violation or deviation noted. Major areas inspected. ALARA, licensee organization & mgt./facility tour & followup on IE info notices.
CILLIS, M., HOOKER, C.A., YUHAS, G.P. Region 5, Office of Director. 85/09/13. 6pp. 32845-318-32845-323.

8510090348 Forwards Insp Rept 50-323/85-27 on 850810-16 & 0904. No noncompliance noted.
KIRSCH, D.F. Region 5, Office of Director. 85/09/19. SHIFFER, J.D. Pacific Gas & Electric Co. 1p. 32947-147-32947-154.

—8510090350 Insp Rept 50-323/85-27 on 850810-16 & 0904. No violation noted. Major areas inspected. Status of fire detection/alarm sys for one fire zone & procedures used to identify operational status of equipment in need of repair & maint.
CREWS, J.L., JOHNSON, A.D., HUEY, R.F. Region 5, Office of Director. 85/09/19. 7pp. 32947-148-32947-154.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070078 Informs of team insp scheduled for 851118-22 to ensure compliance w/ Sections III, G, J, L & O of App R to 10CFR50. Info will be requested during next several wks to support insp effort.
KIRSCH, D.F. Region 5, Office of Director. 85/09/30. SHIFFER, J.D. Pacific Gas & Electric Co. 2pp. 32881-015-32881-016.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

—8510230173 Forwards Press Release 84-58 re NRC proposed fine against util for alleged violation of NRC requirements during preoperational testing.
KAMMERER, C. Office of Congressional Affairs. 84/05/17. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. WILSON Senate. 3pp. 33109-005-33109-007.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510240506 Notification of 851104-05 meetings w/util in Bethesda, MD to discuss in-service testing & insp.
SCHIERLING, H. Licensing Branch 3. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-149-33182-152.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Sexmically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010612 Monthly operating repts for Jul 1985. W/850802 ltr.
KANICK, B., THORNBERRY, R.C. Pacific Gas & Electric Co. 85/07/31. 8pp. 32830-010-32830-017.

S. Reportable occurrences, LERs & related correspondence

8510040112 LER 85-007-00 on 850829, reactor trip on low steam generator level coincident w/steam flow/feed flow mismatch occurred. Caused by personnel error. Operator counseled on significance of understanding abnormal plant conditions. W/850930 ltr.
HINDS, J.R., SHIFFER, J.D. Pacific Gas & Electric Co. 85/09/30. 3pp. 32867-127-32867-129.

8510080396 LER 85-008-00 on 850913, while unit in cold shutdown, automatic isolation of containment ventilation sys occurred. Investigation continuing. Alarm reset & gaseous radiation monitor isolation valves returned to position. W/851004 ltr.
SISK, D.P., SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/04. 2pp. 32919-300-32919-301.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

—8510230173 Forwards Press Release 84-58 re NRC proposed fine against util for alleged violation of NRC requirements during preoperational testing.
KAMMERER, C. Office of Congressional Affairs. 84/05/17. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-005-33109-007.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510220394 Forwards Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation noted.
WALKER, R.D. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096-336-33096-342.

—8510220398 Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation or deviation noted. Major areas inspected: emergency preparedness.
KREH, J.L., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/27. 5pp. 33096-338-33096-342.

8510160320 Summary of 850912 meeting w/util re DCRDR program plan & implementation. List of meeting attendees & agenda encl.
GROTHUIS, M. Operating Reactors Branch 2. 85/10/10. Operating Reactors Branch 2. 4pp. 33028-172-33028-260.

G. Adjudicatory correspondence

8510040338 Requests to present oral arguments supporting request for extension to environ qualification compliance date for facility during Commission 850917 meeting. Alternate date requested if presentation unable to be scheduled.
SMITH, S.H. Carolina Power & Light Co. 85/09/13. PALLADINO, N.J. Commissioners. 1p. 32854-230-32854-230.

P. Operating license stage documents & correspondence

8510040391 Submits addl info re 850709 request for extension for full compliance w/ environ qualification of electrical equipment to 860330 for Unit 2. Extension would allow Unit 1 outage info to be incorporated into Unit 2 outage activities.
SMITH, S.H. Carolina Power & Light Co. 85/09/10. PALLADINO, N.J., ASSELSTINE, J.K., BERNTHAL, F.M. Commissioners. 2pp. 32854-255-32854-256.

8510160057 Submits info per 10CFR50.62(d) re implementation of ATWS mitigating sys. Alternate rod injection sys will be installed. Util evaluating options to meet equivalent injection rate requirement.
CUTTER, A.B. Carolina Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027-198-33027-199.

8510240503 Staff requirements memo re 851009 meeting w/util in Washington, DC re environ qualification exemption request.
CHILK, S.J. Office of the Secretary of the Commission. 85/10/18. Office of the Secretary of the Commission. 1p. 33182-154-33182-154.

8510290423 Forwards safety evaluation re util 831107 & 850828 responses to Generic Ltr 83-28, Items 3.1.2 & 3.2.1 & 850701 request for addl info. Responses acceptable.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/23. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33254-277-33254-281.

—8510290427 Safety evaluation re util 831107 & 850828 responses to Generic Ltr 83-28, Items 3.1.2 & 3.2.1 & 850701 request for addl info. Responses re vendor & engineering test guidance & testing requirements after maint acceptable.
* Office of Nuclear Reactor Regulation, Director. 85/10/23. 3pp. 33254-279-33254-281.

8510300014 Requests exemption from Type C testing requirements of 10CFR50, App J, for primary containment isolation valves. Description of affected valves & justification for exemptions listed. Approval requested by 851130. Fee paid.
CUTTER, A.B. Carolina Power & Light Co. 85/10/25. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 33248-073-33248-075.

Q. Inspection reports, IE Bulletins & correspondence

8509180255 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. UTLEY, E.E. Carolina Power & Light Co. 11pp. 32854-316-32854-328.

8510040505 Forwards Insp Repts 50-324/85-27 & 50-325/85-27 on 850801-31 & notice of violation.
VERRELLI, D.M. Region 2, Office of Director. 85/09/23. UTLEY, E.E. Carolina Power & Light Co. 2pp. 32865-272-32865-285.

—8510040506 Notice of violation from insp on 850801-31.
* Region 2, Office of Director. 85/09/23. 1p. 32865-274-32865-274.

—8510040510 Insp Repts 50-324/85-27 & 50-325/85-27 on 850801-31. Violation noted: bolts replaced on hydraulic control units w/type other than specified on drawings.
GARNER, L.W., HICKS, T.E., FREDRICKSON, P. Region 2, Office of Director. 85/09/20. 11pp. 32865-275-32865-285.

8510040618 Ack receipt of 850912 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/85-22 & 50-325/85-22. Response to item 1 meets requirements of 10CFR2.201. Response to item 2 requested by 851022.
VERRELLI, D.M. Region 2, Office of Director. 85/09/25. UTLEY, E.E. Carolina Power & Light Co. 1p. 32866-071-32866-071.

108 DOCKETED ITEMS

- 8510070355** Responds to violations noted in Insp Repts 50-324/85-24 & 50-325/85-24. Corrective actions. Administrative Instruction AI-59 revised to more accurately reflect intent of review of jumpers/wire removal procedure.
DIETZ, C.R. Carolina Power & Light Co. 85/09/25. GRACE, J.N. Region 2, Office of Director. 8pp. 32877-238-32877-245.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510070460** Forwards Insp Repts 50-324/85-30 & 50-325/85-30 on 850903-06. No violation noted.
VERRELLI, D.M. Region 2, Office of Director. 85/10/01. UTLEY, E.E. Carolina Power & Light Co. 1p. 32878-272-32878-279.
- 8510070463** Insp Repts 50-324/85-30 & 50-325/85-30 on 850903-06. No violation or deviation noted. Major areas inspected: previous enforcement items, followup items & review of ultrasonic data for automated exams of weld overlay repairs.
COLEY, J.L., BLAKE, J.J. Region 2, Office of Director. 85/09/27. 7pp. 32878-273-32878-279.
- 8510220394** Forwards Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation noted.
WALKER, R.D. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096-336-33096-342.
- 8510220398** Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation or deviation noted. Major areas inspected: emergency preparedness.
KREH, J.L., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/27. 5pp. 33096-338-33096-342.
- 8510160264** Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-06 closeout rept.
LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023-351-33023-354.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.
- 8510310171** Advises that completion date for maint surveillance test procedure program revised to 860131, in response to Insp Repts 50-324/84-31 & 50-325/84-31. Commitment schedule encl.
DIETZ, C.R. Carolina Power & Light Co. 85/10/15. GRACE, J.N. Region 2, Office of Director. 3pp. 33273-107-33273-109.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-301-33177-068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.
- R. Periodic operating reports & related correspondence**
- 8510160321** Monthly operating reports for Sept 1985. W/851004 ltr.
HARRISON, F., DIETZ, C.R. Carolina Power & Light Co. 85/09/30. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 14pp. 33029-016-33029-029.
- S. Reportable occurrences, LERs & related correspondence**
- 8510030014** PNO-II-85-092 on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown. Unit 2 shut down & Surry 1 & 2 at full power.
CUNNINGHAM, A. Region 2, Office of Director. 85/09/26. 2pp. 32844-335-32844-336.
- 8510030052** PNO-II-85-093 on 850926, Unit 2 shut down & on 850927, Unit 1 shut down due to Hurricane Gloria w/35-40 miles per hour winds. Unit 1 expected to restart on 850927. Unit 2 will remain shut down for 2 wks for repair of LPSI valves.
CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/09/27. 2pp. 32845-080-32845-081.
- 8510090342** LER 85-006-00 on 850906, HPCI rendered inoperable due to auto-closing of sys primary containment inboard isolation valve E41-F002. Caused by alligator clip from test equipment leads slipping off terminal screw W/851002 ltr.
PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/02. 2pp. 32947-144-32947-145.
- 8510030039** PNO-II-85-091. Region II dispatched emergency response specialist to plant to set up high frequency radio communications as result of Hurricane Gloria. Unit 1 in shutdown for refueling.
CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/10/03. 1p. 32845-112-32845-112.
- 8510090027** LER 85-005-00 on 850904, reactor scram manually initiated due to multiple control rod drift indications resulting from inadvertent isolation of air supply to control rod scram air header. Caused by personnel error W/851004 ltr.
PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/04. 4pp. 32943-041-32943-044.
- 8510310227** RO on 850927 during surveillance testing. MSIVs 2-B21-F028A, F028C & F022C failed to fast close. Caused by disc-to-seat sticking of ASCO Model 8323A36E double solenoid valves. Addl info expected by 851025.
HOWE, P.W. Carolina Power & Light Co. 85/10/15. GRACE, J.N. Region 2, Office of Director. 2pp. 33272-159-33272-160.
- 8510310065** LER 85-006-00 on 850927, MSIVs F028A, F022C & F028C did not fast close during surveillance testing. Caused by disc-to-seat sticking of valve operator double solenoid valves. Double solenoid valves will be replaced. W/851025 ltr.
PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/25. 6pp. 33291-327-33291-332.
- T. Hearing transcripts on non-antitrust matters**
- 8510170372** Transcript of Commission 851010 public meeting in Washington, DC w/util re environ qualification exemption request for facility Pp 1-88.
* Commissioners. 85/10/09. 114pp. 33046-034-33046-142.
- V. Operator Examinations**
- 8509240248** Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1**
- F. Security, medical, emergency & fire protection plans**
- 8510220394** Forwards Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation noted.
WALKER, R.D. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096-336-33096-342.
- 8510220398** Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation or deviation noted. Major areas inspected: emergency preparedness.
KREH, J.L. Region 2, Office of Director. 85/09/27. 5pp. 33096-338-33096-342.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.
- 8510230018** Forwards Press Release 84-4 re NRC proposed civil penalty in amount of \$40,000 against util for failure to post continuous firewatch while both trains of stand-by gas treatment sys fire suppression sys inoperable.
KAMMERER, C. Office of Congressional Affairs. 84/01/10. OTTINGER, R.L. House of Rep. Energy & Commerce. MARKEY House of Rep. EAST Senate. 3pp. 33108-271-33108-273.
- 8510160320** Summary of 850912 meeting w/util re DCRDR program plan & implementation. List of meeting attendees & agenda encl.
GROTEHUIS, M. Operating Reactors Branch 2. 85/10/10. Operating Reactors Branch 2. 4pp. 33028-172-33028-260.
- P. Operating license outage documents & correspondence**
- 8510040391** Submits addl info re 850709 request for extension for full compliance w/ environ qualification of electrical equipment to 860330 for Unit 2. Extension would allow Unit 1 outage info to be incorporated into Unit 2 outage activities.
SMITH, S.N. Carolina Power & Light Co. 85/09/10. PALLADINO, N.J., ASSELSTINE, J.K., BERNTHAL, F.M. Commissioners. 2pp. 32854-255-32854-256.
- 8510160057** Submits info per 10CFR50.62(d) re implementation of ATWS mitigating sys. Alternate rod injection sys will be installed. Util evaluating options to meet equivalent injection rate requirement.
CUTTER, A.B. Carolina Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027-198-33027-199.
- 8510240503** Staff requirements memo re 851009 meeting w/util in Washington, DC re environ qualification exemption request.
CHILK, S.J. Office of the Secretary of the Commission. 85/10/18. Office of the Secretary of the Commission. 1p. 33182-154-33182-154.
- 8510290423** Forwards safety evaluation re util 831107 & 850828 responses to Generic Ltr 83-28, Items 3.1.2 & 3.2.1 & 850701 request for addl info. Responses acceptable.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/23. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33254-277-33254-281.
- 8510290427** Safety evaluation re util 831107 & 850828 responses to Generic Ltr 83-28, Items 3.1.2 & 3.2.1 & 850701 request for addl info. Responses re vendor & engineering test guidance & testing requirements after maint acceptable.
* Office of Nuclear Reactor Regulation, Director. 85/10/23. 3pp. 33254-279-33254-281.
- Q. Inspection reports, IE Bulletins & correspondence**
- 8509180255** Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. UTLEY, E.E. Carolina Power & Light Co. 11pp. 32854-316-32854-326.
- 8510040505** Forwards Insp Repts 50-324/85-27 & 50-325/85-27 on 850801-31 & notice of violation.
VERRELLI, D.M. Region 2, Office of Director. 85/09/23. UTLEY, E.E. Carolina Power & Light Co. 2pp. 32865-272-32865-285.

—8510040510 Insp Repts 50-324/85-27 & 50-325/85-27 on 850801-31. Violation noted: bolts replaced on hydraulic control units w/type other than specified on drawings. GARNER, L.W., HICKS, T.E., FREDRICKSON, P. Region 2, Office of Director. 85/09/20. 11pp. 32865.275-32865.285.

8510040618 Ack receipt of 850912 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/85-22 & 50-325/85-22. Response to item 1 meets requirements of 10CFR2.201. Response to item 2 requested by 851022. VERRELLI, D.M. Region 2, Office of Director. 85/09/25. UTLEY, E.E. Carolina Power & Light Co. 1p. 32866.071-32866.071.

8510070355 Responds to violations noted in Insp Repts 50-324/85-24 & 50-325/85-24. Corrective actions: Administrative Instruction AI-59 revised to more accurately reflect intent of review of jumpers/wire removal procedure. DIETZ, C.R. Carolina Power & Light Co. 85/09/25. GRACE, J.N. Region 2, Office of Director. 8pp. 32877.238-32877.245.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070460 Forwards Insp Repts 50-324/85-30 & 50-325/85-30 on 850903-06. No violation noted. VERRELLI, D.M. Region 2, Office of Director. 85/10/01. UTLEY, E.E. Carolina Power & Light Co. 1p. 32878.272-32878.279.

—8510070463 Insp Repts 50-324/85-30 & 50-325/85-30 on 850903-06. No violation or deviation noted. Major areas inspected: previous enforcement items, followup items & review of ultrasonic data for automated exams of weld overlay repairs. COLEY, J.L., BLAKE, J.J. Region 2, Office of Director. 85/09/27. 7pp. 32878.273-32878.279.

8510220394 Forwards Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation noted. WALKER, R.D. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33096.336-33096.342.

—8510220396 Insp Repts 50-324/85-32 & 50-325/85-32 on 850909-13. No violation or deviation noted. Major areas inspected: emergency preparedness. KREH, J.L., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/27. 5pp. 33096.338-33096.342.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33106.264-33106.288.

—8510230018 Forwards Press Release 84-4 re NRC proposed civil penalty in amount of \$40,000 against util for failure to post continuous firewatch while both trains of stand-by gas treatment sys fire suppression sys inoperable. KAMMERER, C. Office of Congressional Affairs. 84/01/10. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108.271-33108.273.

8510160050 Forwards summary of NRC requests & util responses to 851001 conference call re IGSCC insp performed during current Reload 4 outage. ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/10. VASSALLO, D.B. Operating Reactors Branch 2. 6pp. 33027.184-33027.189.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept. LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023.351-33023.354.

8510170293 Advises of acceptability of info re IGSCC insp of recirculation & reactor water cleanup sys. Detailed safety evaluation providing basis for conclusion will be transmitted under separate cover. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/11. UTLEY, E.E. Carolina Power & Light Co. 2pp. 33044.295-33044.296.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510310171 Advises that completion date for maint surveillance test procedure program revised to 860131 in response to Insp Repts 50-324/84-31 & 50-325/84-31. Commitment schedule encl. DIETZ, C.R. Carolina Power & Light Co. 85/10/15. GRACE, J.N. Region 2, Office of Director. 3pp. 33273.107-33273.109.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasitic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

R. Periodic operating reports & related correspondence

8510160321 Monthly operating repts for Sept 1985. W/851004 ltr. HARRISON, F., DIETZ, C.R. Carolina Power & Light Co. 85/09/30. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 14pp. 33029.016-33029.029.

S. Reportable occurrences, LERs & related correspondence

8510040540 Special Rept 1-SR-85-9 on 850824 & 27.7-day specified time frames of fire burner limiting conditions for operation for Fire Doors 203 & 303, respectively, exceeded. Caused by preventive maint. Fire watches in reactor bldg maintained. DIETZ, C.R. Carolina Power & Light Co. 85/09/19. GRACE, J.N. Region 2, Office of Director. 1p. 32866.057-32866.057.

8510020086 LER 85-047-00 on 850826, LOCA signal caused auto-initiation of core spray 1A & B & auto-start of diesel generators 1-4. Caused by residual pressure from test equipment vented into reactor level instruments sensing leg. W/850925 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/09/25. 3pp. 32827.126-32827.128.

8510030014 PNO-II-85-092 on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown. Unit 2 shut down & Surry 1 & 2 at full power. CUNNINGHAM, A. Region 2, Office of Director. 85/09/26. 2pp. 32844.335-32844.336.

8510030052 PNO-II-85-093 on 850926, Unit 2 shut down & on 850927, Unit 1 shut down due to Hurricane Gloria w/35-40 miles per hour winds. Unit 1 expected to restart on 850927. Unit 2 will remain shut down for 2 wks for repair of LPSI valves. CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/09/27. 2pp. 32845.080-32845.081.

8510080537 LER 85-039-01 on 850730, automatic initiation of core spray 1A & autostart of diesel generators 1, 3 & 4 occurred due to LOCA signal. Caused by installation of incorrect relay type under plant mod instruction revised W/850930 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/09/30. 5pp. 32927.132-32927.136.

8510080529 LER 85-048-00 on 850903, automatic start signals to control bldg emergency air filtration sys initiated by bldg fire detection sys. Caused by computer room air conditioner leaking on room fire detector. Leak repaired. W/851002 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/02. 2pp. 32927.157-32927.158.

8510030039 PNO-II-85-091. Region II dispatched emergency response specialist to plant to set up high frequency radio communications as result of Hurricane Gloria. Unit 1 in shutdown for refueling. CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/10/03. 1p. 32845.112-32845.112.

8510090018 LER 85-049-00 on 850905, inadequacy of main steam line tunnel temp switch response test & primary containment isolation valve circuitry response time test discovered. Surveillance tests under rev. W/851003 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/03. 3pp. 32937.359-32937.361.

8510310227 RO on 850927, during surveillance testing, MSIVs 2-B21-F028A, F028C & F022C failed to fast close. Caused by disc-to-seat sticking of ASCO Model 8323A3EE double solenoid valves. Add info expected by 851025. HOWE, P.W. Carolina Power & Light Co. 85/10/15. GRACE, J.N. Region 2, Office of Director. 2pp. 33272.159-33272.160.

8510250198 LER 85-051-00 on 850921, reactor power intermediate range monitor trip occurred resulting in automatic trip of reactor protection sys logic Channels A & B. Caused by bump to LPRM signal cable. Trip signal reset. W/851018 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/18. 2pp. 33190.257-33190.258.

8510280077 LER 85-052-00 on 850924, primary containment Group 6 isolation & auto start of reactor bldg standby gas treatment sys occurred when foreman manually tapped power supply while investigating downscale-inoperative alarm. W/851018 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/18. 2pp. 33194.138-33194.139.

8510280261 LER 85-016-00 on 850923, nonquantifiable leakage noted in primary containment isolation valves 6-1-E11-F020A, B & 1-E21-F031B. Caused by faulty seats, jacking & discs. Valves repaired & returned to svc. W/851018 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/18. 5pp. 33195.217-33195.221.

8510280440 LER 85-050-00 on 850918, six automatic isolations of control bldg HVAC sys occurred. Caused by spurious sys air intake chlorine alarms. Functional tests of chlorine detectors performed & HVAC sys returned to svc. W/851018 ltr. PASTVA, M.J., DIETZ, C.R. Carolina Power & Light Co. 85/10/18. 3pp. 33195.035-33195.037.

T. Hearing transcripts on non-antitrust matters

8510170372 Transcript of Commission 851010 public meeting in Washington, DC w/util re environ qualification exemption request for facility. Pp 1-88. * Commissioners. 85/10/09. 114pp. 33048.034-33048.142.

U. Congressional/Executive Correspondence

8510230018 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33106.264-33106.288.

—8510230018 Forwards Press Release 84-4 re NRC proposed civil penalty in amount of \$40,000 against util for failure to post continuous firewatch while both trains of stand-by gas treatment sys fire suppression sys inoperable. KAMMERER, C. Office of Congressional Affairs. 84/01/10. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108.271-33108.273.

110 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-326 UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

8510170298 Forwards Insp Rept 50-326/85-01 on 850903-06 & notice of violation.
SCARANO, R.A. Region 5, Office of Director. 85/09/30. LILLYMAN, W.J. California, Univ. of Irvine, CA. 2pp. 33051-277-33051-291.

-8510170301 Notice of violation from insp on 850903-06.
SCARANO, R.A. Region 5, Office of Director. 85/09/30. 1p. 33051-279-33051-279.

-8510170304 Insp Rept 50-326/85-01 on 850903-06. Violations noted: failure of reactor operation committee to conduct quarterly meetings & implement licensed operators requalification program.
CILLIS, M., YUHAS, G.P. Region 5, Office of Director. 85/09/27. 12pp. 33051-280-33051-291.

V. Operator Examinations

8510170298 Forwards Insp Rept 50-326/85-01 on 850903-06 & notice of violation.
SCARANO, R.A. Region 5, Office of Director. 85/09/30. LILLYMAN, W.J. California, Univ. of Irvine, CA. 2pp. 33051-277-33051-291.

-8510170301 Notice of violation from insp on 850903-06.
SCARANO, R.A. Region 5, Office of Director. 85/09/30. 1p. 33051-279-33051-279.

-8510170304 Insp Rept 50-326/85-01 on 850903-06. Violations noted: failure of reactor operation committee to conduct quarterly meetings & implement licensed operators requalification program.
CILLIS, M., YUHAS, G.P. Region 5, Office of Director. 85/09/27. 12pp. 33051-280-33051-291.

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510290296 "State of GA Radiological Emergency Plan, Annex G, U.S. TVA - Sequoyah Nuclear Plant." W/851024 ltr.
* Georgia, State of. DOMER, J.A. Tennessee Valley Authority. 85/09/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 56pp. 33235-159-33235-213.

8510150080 Rev 22 to radiological emergency plan. W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. SON-REP R22. 85/09/30. GRACE, J.N. Region 2, Office of Director. 152pp. 33008-117-33008-268.

8510070326 Forwards Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32880-313-32880-334.

-8510070343 Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905. Violations noted: failure to follow procedure during surveillance testing of emergency diesel generator & failure to adequately perform NDE.
JENISON, K.M., WATSON, L.J., IGNATONIS, A. Region 2, Office of Director. 85/09/27. 18pp. 32880-317-32880-334.

8510080243 Forwards Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
VERRELL, D.M. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32913-296-32913-298.

-8510080264 Physical Security Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06. Violation noted: compensatory measures. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS, J.D., MCGUIRE, D.R. Region 2, Office of Director. 85/09/27. 1p. 32913-298-32913-298.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. 14pp. 33010-272-33010-284.

8510290331 Forwards surveillance instruction test results for intrusion Detection Sys FPS-2, per 850529 response to TM Novak. 850412 request for info. Test results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 2pp. 33235-025-33235-026.

8510310184 Forwards physical security plan, including test procedures, test data & results, alarm logs, daily environ conditions, guard/sys interaction data & sensitivity changes of fence-mounted sys. Encls withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 3pp. 33273-264-33273-266.

I. Financial Information

8510110269 Informs that financial info in 850830 ltr satisfies requirements of 10CFR140.21 that each licensee maintain guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e).
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. DOMER, J.A. Tennessee Valley Authority. 1p. 33011-186-33011-186.

P. Operating license stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse Ltr to be used as ref in response to NRC 850917 ltr W/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510010048 Forwards response to NUREG-0737, Item II.K.3.30 & NRC 701 ltr verifying util participation in Westinghouse Owners Group & use of h. MP in small-break LOCA analysis. Analysis for Item II.K.3.31 will be provided by 860602.
DOMER, J.A. Tennessee Valley Authority. 85/09/25. ADENSAM, E. Licensing Branch 4. 3pp. 32800-311-32800-313.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510030045 Requests extension to schedule for final environ qualification of electrical cables, per Generic Ltr 85-15, for continued operation up to & beyond 851130.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 16pp. 32842-313-32842-328.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510090130 Application for amends supplementing 841002 application for amends to Licenses DPR-77 & DPR-79, changing radiological effluent Tech Specs. Revised pages clarify original amend & enhance conformance w/NRC std.
SHELL, R.H. Tennessee Valley Authority. 85/09/27. ADENSAM, E. Licensing Branch 4. 2pp. 32934-093-32934-133.

-8510090134 Revised pages to proposed radiological effluent Tech Specs, per 841002 application for amends to Licenses DPR-77 & DPR-79.
* Tennessee Valley Authority. 85/09/27. 39pp. 32934-095-32934-133.

8510090200 Forwards "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 1, "Plant-Level Models," & Vol 2, "App - Sys-Level Detailed Models," final rept, per License Condition 2 F.
SHELL, R.H. Tennessee Valley Authority. 85/10/02. ADENSAM, E. Licensing Branch 4. 2pp. 32952-277-32952-091.

-8510090212 "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 1, "Plant-Level Models," final rept.
RAABE, P.H., RENEY, D.A., FLEMING, K.N. Pickard, Lowe & Garlick, Inc. EPRI NP-4128 V01. 85/07/31. 175pp. 32952-279-32953-286.

-8510090220 "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 2, "App - Sys-Level Detailed Models," final rept.
RAABE, P.H., RENEY, D.A., FLEMING, K.N. Pickard, Lowe & Garlick, Inc. EPRI NP-4128 V02. 85/07/31. 200pp. 32953-287-32955-091.

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949-162-32949-166.

-8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949-167-32949-167.

8510150106 Discusses status of environ qualification program review, per 851002 telcon. Review of program during wk of 851004 requested. Request for extension to schedule requirements for open issues re electrical equipment encl.
DOMER, J.A. Tennessee Valley Authority. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33008-298-33008-300.

8510150383 Forwards info in response to NRC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts.
WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001-001-33006-171.

8510160200 Informs that ATWS mitigating sys actuation circuitry will be installed at facility based on generic functional design developed by Westinghouse Owners Group in efforts to meet requirements of 10CFR50.62.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021-083-33021-085.

8510160265 Forwards sketches of diesel generator configurations omitted from 850201 application for amends to Licenses DPR-77 & DPR-79. Amends change Tech Specs to allow use of fifth standby diesel generator.
DOMER, J.A. Tennessee Valley Authority. 85/10/11. ADENSAM, E. Licensing Branch 2. 4pp. 33022-311-33022-314.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 25pp. 33085.157-33086.052.

8510280331 Forwards response to Quality Technology Co investigation repts. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193.185-33193.237.

8510290159 Application for amendments to Licenses DPR-77 & DPR-79, consisting of Change 1 to raise spent fuel pool radiation monitor setpoint & Change 2 to modify neutron flux rate reactor trip setpoint. Fee paid.
DOMER, J.A. Tennessee Valley Authority. 85/10/22. ADENSAM, E. Licensing Branch 2. 2pp. 33236.171-33236.190.

8510290166 Proposed Tech Spec changes, consisting of Change 1 to raise spent fuel pool radiation monitor setpoint & Change 2 to modify power range flux rate trip setpoint.
* Tennessee Valley Authority. 85/10/22. 18pp. 33236.173-33236.190.

G. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834.210-32834.349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834.229-32834.349.

8510020351 Ack receipt of 850909 ltr revising response to Violations 50-327/83-31-01 & 50-328/83-31-01 noted in Insp Repts 50-327/83-31 & 50-328/83-31.
WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 1p. 32825.008-32825.008.

8510040118 Ack receipt of 850906 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/85-24 & 50-328/85-24. Addl info re ice removal & surveillance testing requested per 850913 telcon.
WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32867.125-32867.126.

8510020270 Ack receipt of 850828 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/85-17 & 50-328/85-17. Response to Item 2 contradictory & incorrect. Corrective action addresses issue. No response required.
WALKER, R.D. Region 2, Office of Director. 85/09/26. PARRIS, H.G. Tennessee Valley Authority. 1p. 32824.104-32824.104.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070326 Forwards Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32880.313-32880.334.

8510070333 Notice of violation from Insp on 850806-0905.
* Region 2, Office of Director. 85/10/01. 2pp. 32880.315-32880.316.

8510070343 Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905. Violations noted: failure to follow procedure during surveillance testing of emergency diesel generator & failure to adequately perform NDE.
JENISON, K.M. WATSON, L.J., IGNATONIS, A. Region 2, Office of Director. 85/09/27. 18pp. 32880.317-32880.334.

8510080243 Forwards Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
VERRELLI, D.M. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32913.296-32913.298.

8510080264 Physical Security Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06. Violation noted: compensatory measures. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS, J.D., MCGUIRE, D.R. Region 2, Office of Director. 85/09/27. 1p. 32913.298-32913.298.

8510180048 Suppls response to NRC 850807 ltr re violations noted in Insp Repts 50-327/85-24 & 50-328/85-24. Corrective actions: ice removed from intermediate deck door & Surveillance Requirement 4.6.5.2.b being prepared.
DOMER, J.A. Tennessee Valley Authority. 85/10/04. GRACE, J.N. Region 2, Office of Director. 4pp. 33063.060-33063.063.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

8510230126 Forwards Press Release 85-66 re NRC proposed imposition of civil penalty in amount of \$112,500 against TVA for alleged noncompliance w/requirements concerning 840419 event when tube used to insert instrumentation ejected.
KAMMERER, C. Office of Congressional Affairs. 85/05/09. MARKEY, E.J. House of Rep., Energy & Commerce. GORE, SASSER Senate. 2pp. 33109.058-33109.059.

8510310233 Revises 850826 response to NRC 850730 ltr re violations noted in Insp Repts 50-327/85-17 & 50-328/85-17. QC inspector restructured in proper procedures to follow in event that protective clothing lost or damaged during work.
DOMER, J.A. Tennessee Valley Authority. 85/10/09. GRACE, J.N. Region 2, Office of Director. 2pp. 33273.161-33273.162.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.001-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.204-33177.204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191.073-33191.074.

R. Periodic operating reports & related correspondence

8510020108 Monthly operating repts for Jul 1985. W/850813 ltr.
WILBOURN, G.R., HOLLOMON, T.J., WALLACE, P.R. Tennessee Valley Authority. 85/07/31. 30pp. 32827.024-32827.053.

8510240043 Forwards repts to "NPDES Discharge Monitoring Rept for Apr 1985." Revs correct figure reported for reservoir temp rise & provides previously omitted data on downstream temp.
RIVERS, M.E. Tennessee Valley Authority. 85/10/18. MARLAR, J. Environmental Protection Agency. 1p. 33156.195-33156.197.

8510240045 Revised pages to "NPDES Discharge Monitoring Rept for Apr 1985."
* Tennessee Valley Authority. 85/04/30. 2pp. 33156.196-33156.197.

S. Reportable occurrences, LERs & related correspondence

8510010617 LER 85-035-00 on 850829, control power for diesel generator 2B-B lost for several seconds. Caused by personnel error resulting in loose connector from test rig to breaker lugs. Suction valves returned to normal. W/850924 ltr.
DUGGIN, G., WALLACE, P.R. Tennessee Valley Authority. 85/09/24. 3pp. 32830.028-32830.030.

8510020220 LER 85-036-00 on 850825, 26.28 & 0913, hourly fire watch not performed within 1 h. Caused by improper shift relief or inaccessibility to areas. Fire watches reestablished as soon as practical. W/850926 ltr.
ORMSBY, D.P., WALLACE, P.R. Tennessee Valley Authority. 85/09/25. 4pp. 32827.054-32827.057.

8510030355 LER 85-034-00 on 850827, diesel generator 2B-B performed incorrectly during surveillance. Caused by loose electrical connector between control panel & hydraulic actuator on engine governor. Connector tightened. W/850926 ltr.
DUGGIN, G., WALLACE, P.R. Tennessee Valley Authority. 85/09/26. 3pp. 32846.069-32846.071.

8510040102 LER 85-037-00 on 850906, main control room ventilation isolation occurred due to spike on radiation monitor (RM) RM-90-125. Caused by RM controller either placed in TRIP REF mode or momentary loss of power. W/850930 ltr.
DUGGIN, G., WALLACE, P.R. Tennessee Valley Authority. 85/09/27. 3pp. 32867.130-32867.132.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of reactor div directors & representatives on events occurring since 850909 meeting. List of attendees & viewpoints encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030.243-33030.265.

8510150455 LER 85-038-00 on 850908, auxiliary bldg ventilation isolation occurred due to spike on spent fuel pool (SFP) radiation monitor. Caused by increase in radiation level due to removal of SFP filter from svc. W/851004 ltr.
DUGGIN, G., WALLACE, P.R. Tennessee Valley Authority. 85/10/07. 3pp. 33015.167-33015.169.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants.
STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078.256-33078.361.

8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078.260-33078.361.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

112 DOCKETED ITEMS

—8510230126 Forwards Press Release 85-66 re NRC proposed imposition of civil penalty in amount of \$112,500 against TVA for alleged noncompliance w/requirements concerning 840419 event when tube used to insert instrumentation ejected.
KAMMERER, C. Office of Congressional Affairs. 85/05/09. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109.058-33109.059.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

—8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8510290296 "State of GA Radiological Emergency Plan, Annex G, U.S. TVA - Sequoyah Nuclear Plant." W/851024 ltr.
* Georgia, State of. DOMER, J.A. Tennessee Valley Authority. 85/09/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 56pp. 33235-159-33235-213.

8510150060 Rev 22 to radiological emergency plan. W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. SQN-REP R22. 85/09/30. GRACE, J.N. Region 2, Office of Director. 152pp. 33008-117-33008-268.

8510070326 Forwards Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32880-313-32880-334.

—8510070343 Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905. Violations noted: failure to follow procedure during surveillance testing of emergency diesel generator & failure to adequately perform NDE.
JENISON, K.M. Region 2, Office of Director. 85/09/27. 18pp. 32880-317-32880-334.

8510080243 Forwards Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21).
VERRELLI, D.M. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32913-298-32913-298.

—8510080264 Physical Security Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06. Violation noted: compensatory measures. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS, J.D. Region 2, Office of Director. 85/09/27. 1p. 32913-298-32913-298.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. 14pp. 33010-272-33010-284.

8510290331 Forwards surveillance instruction test results for Intrusion Detection Sys FPS-2, per 850529 response to TM Novak 850412 request for info. Test results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 2pp. 33235-025-33235-026.

8510310184 Forwards physical security plan, including test procedures, test data & results, alarm logs, daily environ conditions, guard/sys interaction data & sensitivity changes of fence-mounted sys. Encls withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 3pp. 33273-264-33273-266.

I. Financial information

8510110268 Informs that financial info in 850830 ltr satisfies requirements of 10CFR140.21 that each licensee maintain guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e).
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/09/30. DOMER, J.A. Tennessee Valley Authority. 1p. 33011-186-33011-186.

P. Operating license stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr. W/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510010048 Forwards response to NUREG-0737 Item H.K.3.30 & NRC 850701 ltr verifying util participation in Westinghouse Owners Group & use of NOTRUMP in small-break LOCA analysis. Analysis for Item H.K.3.31 will be provided by 860602.
DOMER, J.A. Tennessee Valley Authority. 85/09/25. ADENSAM, E. Licensing Branch 4. 3pp. 32800-311-32800-313.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510030045 Requests extension to schedule for final environ qualification of electrical cables per Generic Ltr 85-15, for continued operation up to & beyond 851130.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 16pp. 32842-313-32842-328.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff per commitment in util 850906 ltr. Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510090130 Application for amends supplementing 841002 application for amends to Licenses DPR-77 & DPR-79, changing radiological effluent Tech Specs. Revised pages clarify original amend & enhance conformance w/NRC std.
SHELL, R.H. Tennessee Valley Authority. 85/09/27. ADENSAM, E. Licensing Branch 4. 2pp. 32934-093-32934-133.

—8510090134 Revised pages to proposed radiological effluent Tech Specs, per 841002 application for amends to Licenses DPR-77 & DPR-79.
* Tennessee Valley Authority. 85/09/27. 39pp. 32934-095-32934-133.

8510090200 Forwards "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 1, "Plant-Level Models" & Vol 2, "App - Sys-Level Detailed Models," final rept, per License Condition 2 F.
SHELL, R.H. Tennessee Valley Authority. 85/10/02. ADENSAM, E. Licensing Branch 4. 2pp. 32952-277-32952-091.

—8510090212 "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 1, "Plant-Level Models," final rept.
RAABE, P.H., REND, D.A., FLEMING, K.N. Pickard, Lowe & Garck, Inc. EPRI NP-4128 V01. 85/07/31. 175pp. 32952-279-32952-286.

—8510090220 "Full-Scale Plant Safety & Availability Assessment: Demonstration of GO Sys Analysis Methodology," Vol 2, "App - Sys-Level Detailed Models," final rept.
RAABE, P.H., REND, D.A., FLEMING, K.N. Pickard, Lowe & Garck, Inc. EPRI NP-4128 V02. 85/07/31. 200pp. 32953-287-32953-091.

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949-162-32949-166.

—8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949-167-32949-167.

8510150106 Discusses status of environ qualification program review, per 851002 teicon. Review of program during wk of 851004 requested. Request for extension to schedule requirements for open issues re electrical equipment encl.
DOMER, J.A. Tennessee Valley Authority. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33008-298-33008-300.

8510150383 Forwards info in response to NRC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts.
WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001-001-33001-171.

8510160200 Informs that ATWS mitigating sys actuation circuitry will be installed at facility based on generic functional design developed by Westinghouse Owners Group in efforts to meet requirements of 10CFR50.62.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021-083-33021-085.

8510160265 Forwards sketches of diesel generator configurations omitted from 850201 application for amends to Licenses DPR-77 & DPR-79. Amends change Tech Specs to allow use of fifth standby diesel generator.
DOMER, J.A. Tennessee Valley Authority. 85/10/11. ADENSAM, E. Licensing Branch 2. 4pp. 33022-311-33022-314.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085-157-33086-052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193-185-33193-237.

8510290159 Application for amends to Licenses DPR-77 & DPR-79, consisting of Change 1 to raise spent fuel pool radiation monitor setpoint & Change 2 to modify neutron flux rate reactor trip setpoint. Fee paid.
DOMER, J.A. Tennessee Valley Authority. 85/10/22. ADENSAM, E. Licensing Branch 2. 2pp. 33236-171-33236-190.

—8510290166 Proposed Tech Spec changes, consisting of Change 1 to raise spent fuel pool radiation monitor setpoint & Change 2 to modify power range flux rate trip setpoint.
* Tennessee Valley Authority. 85/10/22. 18pp. 33236-173-33236-190.

G. Inspection reports, IE Bulletins & correspondence

- 8510010162** Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.
- 8510010246** SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable. * Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.
- 8510020351** Ack receipt of 850909 ltr revising response to Violations 50-327/83-31-01 & 50-328/83-31-01 noted in Insp Repts 50-327/83-31 & 50-328/83-31. WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 1p. 32825-008-32825-008.
- 8510040118** Ack receipt of 850906 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/85-24 & 50-328/85-24. Add info re ice removal & surveillance testing requested per 850913 telcon. WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32867-125-32867-126.
- 8510020270** Ack receipt of 850828 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/85-17 & 50-328/85-17. Response to item 2 contradictory & incorrect. Corrective action addresses issue. No response required. WALKER, R.D. Region 2, Office of Director. 85/09/26. PARRIS, H.G. Tennessee Valley Authority. 1p. 32825-104-32825-104.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510070326** Forwards Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905 & notice of violation. WALKER, R.D. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32880-313-32880-334.
- 8510070333** Notice of violation from insp on 850806-0905. * Region 2, Office of Director. 85/10/01. 2pp. 32880-315-32880-316.
- 8510070343** Insp Repts 50-327/85-27 & 50-328/85-28 on 850806-0905. Violations noted failure to follow procedure during surveillance testing of emergency diesel generator & failure to adequately perform NDE. JENISON, K.M., WATSON, L.J., IGNATONIS, A. Region 2, Office of Director. 85/09/27. 18pp. 32880-317-32880-334.
- 8510080243** Forwards Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06 & notice of violation. Notice of violation withheld (ref 10CFR2.790(d) & 73.21). VERRELLI, D.M. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32913-296-32913-298.
- 8510080264** Physical Security Insp Repts 50-327/85-30 & 50-328/85-30 on 850903-06. Violation noted: compulsory measures. Details withheld (ref 10CFR2.790(d) & 73.21). ENNIS, J.D., MCGUIRE, D.R. Region 2, Office of Director. 85/09/27. 1p. 32913-298-32913-298.
- 8510180048** Suppls response to NRC 850807 ltr re violations noted in Insp Repts 50-327/85-24 & 50-328/85-24. Corrective actions: ice removed from intermediate deck door & Surveillance Requirement 4.6.5.2.b being prepared. DOMER, J.A. Tennessee Valley Authority. 85/10/04. GRACE, J.N. Region 2, Office of Director. 4pp. 33063-060-33063-063.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.
- 8510230126** Forwards Press Release 85-66 re NRC proposed imposition of civil penalty in amount of \$112,500 against TVA for alleged noncompliance w/requirements concerning 840419 event when tube used to insert instrumentation ejected. KAMMERER, C. Office of Congressional Affairs. 85/05/09. MARKEY, E.J. House of Rep., Energy & Commerce. GORE, SASSER Senate. 2pp. 33109-058-33109-059.
- 8510310233** Revises 850828 response to NRC 850730 ltr re violations noted in Insp Repts 50-327/85-17 & 50-328/85-17. QC inspector instructed in proper procedures to follow in event that protective clothing lost or damaged during work. DOMER, J.A. Tennessee Valley Authority. 85/10/09. GRACE, J.N. Region 2, Office of Director. 3pp. 33273-161-33273-162.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action, per NRC 850917 suggestion. DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191-073-33191-074.

R. Periodic operating reports & related correspondence

- 8510020106** Monthly operating repts for Jul 1985. W/850813 ltr. WILBOURN, G.R., HOLLOMON, T.J., WALLACE, P.R. Tennessee Valley Authority. 85/07/31. 30pp. 32827-024-32827-053.
- 8510240043** Forwards revs to "NPDES Discharge Monitoring Rept for Apr 1985." Revs correct figure reported for reservoir temp rise & provides previously omitted data on downstream temp. RIVERS, M.E. Tennessee Valley Authority. 85/10/18. MARLAR, J. Environmental Protection Agency. 1p. 33156-195-33156-197.
- 8510240045** Revised pages to "NPDES Discharge Monitoring Rept for Apr 1985." * Tennessee Valley Authority. 85/04/30. 2pp. 33156-196-33156-197.

S. Reportable occurrences, LERs & related correspondence

- 8510010283** Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABE, L.L., HENDERSON, T. Government Accountability Project. 32pp. 32884-005-32884-001.
- 8510010388** Forwards 10CFR50.55(e)/Part 21 rept from TVA re generic problem w/ hydrogen detection sys integrity. Followup on generic aspects w/AE/vendor requested. Supporting documentation encl. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15. Region 4, Dallas, Vendor Inspection Branch. 327pp. 32884-241-32885-206.
- 8510150091** Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

T. Hearing transcripts on non-antitrust matters

- 8510180495** Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants. STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078-256-33078-361.
- 8510180503** Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100. * NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078-260-33078-361.

U. Congressional/Executive Correspondence

- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.
- 8510230126** Forwards Press Release 85-66 re NRC proposed imposition of civil penalty in amount of \$112,500 against TVA for alleged noncompliance w/requirements concerning 840419 event when tube used to insert instrumentation ejected. KAMMERER, C. Office of Congressional Affairs. 85/05/09. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-058-33109-059.

V. Operator Examinations

- 8510010355** FOIA request for power plant exam results summary sheets for listed plants. HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.
- 8510010387** Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed. FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.
- 8509240248** Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8510080037** FOIA request for ACRS documents re facility. BRUNNER, J.E. Consumers Power Co. 85/08/23. Office of Administration. 2pp. 32929-071-32929-072.
- 8510010225** Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDR. App E documents withheld (ref FOIA Exemptions 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833-002-32833-052.

114 DOCKETED ITEMS

-**8510010237** Summary of 820915 meeting w/utl in Chicago, IL re proposed utl investigation into GAP allegations concerning facilities. Utl agreed to delay investigation until RACI P.E. Office of Investigation. 82/09/20. Office of Investigation. 26pp. 32933-022-32933-049.

8510160279 Forwards Bechtel nonconformance repts, quality action requests, mgt corrective action repts & quality audit findings written or closed during Aug 1985, per condition of Memorandum & Order ALAB-106.
COOK, J.W. Consumers Power Co. 85/09/25. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 7pp. 33026-223-33026-229.

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents, App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32929-092.

-**8208030689** Recommends that design & const audit recommended by ACRS be performed by competitor to assure highest possible degree of objectivity & independence.
STAMIRIS, B. Stamiris, B. 82/07/28. TEDESCO, R.L. Assistant Director for Licensing. 1p. 32930-075-32930-075.

-**8510080033** Forwards project status rept for ACRS Subcommittee on Midland Plant 820602 meeting in Washington, DC to review application for OL. Related info encl.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/28.
OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 57pp. 32929-014-32929-070.

-**8510080045** Forwards summary of 700312 meeting w/utl & JT Wilson in Bethesda, MD re subsidence problem under site. General subsidence could occur, but not abrupt offset. Abrupt offset or scarping could not be tolerated.
MCKINLEY, J.C. Atomic Energy Commission. 70/03/19. SQUIRES, L. Atomic Energy Commission. 11pp. 32929-075-32929-085.

-**8510080055** Summarizes meeting w/utl re Dow Chemical Co solution mining of salt. Calculations of stress levels at or near surface of bedrock required.
WILSON, J.T. Affiliation Not Assigned. 70/03/16. MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-088-32929-088.

-**8510080073** Summary of 700422 meeting w/utl & Dow Chemical Co re radioactivity of process steam to be exported to Dow. FDA recommended detector to continuously monitor activity of steam. Related info encl.
MCKINLEY, J.C. Atomic Energy Commission. 70/04/23. SQUIRES, L. Atomic Energy Commission. 5pp. 32929-111-32929-115.

-**8510080127** Forwards 10CFR30-36 & 150, for info in connection w/review of Midland W/o encls.
FRALEY, R.F. Atomic Energy Commission. 70/04/28. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-144-32929-144.

-**8510080132** Summary of briefing of ACRS Subcommittee Chairman L. Squires on AEC requirements/plans re licensing of Midland &/or Dow Chemical Co for use of secondary steam from facility.
FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/05/01. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32929-145-32929-150.

-**8510080262** Discusses 820407 telcon re ACRS subcommittee 840429 meeting on soils matters. Discussion will focus on remedy rather than cause of soil problem.
HOOD, D. Licensing Branch 4. 82/04/07. FISCHER, D. NRC - No Detailed Affiliation Given. 10pp. 32929-230-32929-239.

-**8510080277** Notification of 760521 meeting w/utl in Bethesda, MD to discuss criteria to be used for analysis of high energy line breaks. Related info encl.
CROCKER, L.P. NRC - No Detailed Affiliation Given. 76/05/01. KNIEL, K. NRC - No Detailed Affiliation Given. 5pp. 32929-310-32929-314.

-**8510080373** Forwards statement of B. Stamiris before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of utl application for OL. Statement addresses misrepresented or overlooked issues re soil settlement.
STAMIRIS, B. Stamiris, B. 82/05/20. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930-002-32930-005.

-**8510080409** Urges serious consideration of const problems at plant site, rated one of five worst nuclear plants in country per W. Dircks May 1981 testimony before Congress. Utl should be held accountable for public safety.
GARDE, B.P. Government Accountability Project. 83/01/11. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. SIESS, C. Illinois, Univ. of, Urbana, IL. 8pp. 32930-050-32930-057.

-**8510080438** Forwards project status rept for ACRS Subcommittee on Midland 820429 meeting in Washington, DC to discuss utl remedial action on soils & structural settlement issues.
FISCHER, D. NRC - No Detailed Affiliation Given. 82/04/21. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 14pp. 32930-100-32930-119.

8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland, Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049-042-33049-234.

8510110011 Board Notification 85-086, supps Board Notifications 82-117, 83-102 & 85-045 re welding-related allegations at Midland 1 & 2. H. Wahl (Bechtel) 850916 summary of developments in suit filed re E. Kent allegations & 850509 ltr encl.
MOVAK, T.M. Assistant Director for Licensing. 85/10/07. ROSENTHAL, A., MOORE, T. Atomic Safety and Licensing Appeal Panel. 4pp. 33056-121-33056-130.

-**8510180161** Discusses EE Kent allegations re plant, per encl 850509 ltr. Decision reflected in NRC 850809 ltr should be reconsidered. B. Garde & T. Devine of GAP unwilling to testify for Kent Kent & counsel unable to produce expert witnesses.
WAHL, H.W. Bechtel Corp. 85/09/16. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33056-125-33056-130.

-**8510180175** Discusses EE Kent allegations re quality of engineering & const at plant. Region III could quickly dispose of matters held open in NRC 850322 ltr. Meeting to facilitate closure suggested.
WAHL, H.W. Bechtel Corp. 85/05/09. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33056-128-33056-130.

8510230132 Informs that utl will submit schedule for meeting requirements of 10CFR50.62(d) per Generic Ltr 85-06 re QA guidance for ATWS nonsafety-related equipment when & if project reactivated.
COOK, J.W. Consumers Power Co. 85/10/14. THOMPSON, H.L. Division of Licensing. 1p. 33102-091-33102-091.

E. NRC Safety Evaluation Report (SER), supps & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents, App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-**8204120124** Forwards branch SER input. Sections 2.5.5 re stability of slopes & 2.5.6 re embankment & dams, essentially complete. Section 2.5.4 re stability of subsurface mats & foundations, remains open & impacted by ASLB hearings.
LEAR, G. Hydrologic & Geotechnical Engineering Branch. 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 17pp. 32929-213-32929-229.

-**8204210531** Forwards Structural Engineering Branch SER input re FSAR Chapter 3 on design of Category I structures. Evaluation will be completed upon submittal of info re soil remedial actions & new site-specific response spectra.
KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/05. TEDESCO, R.L. Assistant Director for Licensing. 2pp. 32929-161-32929-162.

-**8204290608** Forwards geological & seismological input to SER for OL.
KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 26pp. 32929-185-32929-212.

-**8510080248** SER input re design of Category 1 structures & remedial actions. Completion of SER controlled by utl response to NRC request for info re soil remedial actions.
* Structural Engineering Branch. 82/04/05. 22pp. 32929-163-32929-184.

-**8510080272** Forwards SER input. Outstanding issues listed, including flood protection of settled structures & adequacy of dewatering sys. Related info encl.
LEAR, G. Hydrologic & Geotechnical Engineering Branch. 85/09/30. ADENSAME, E. Licensing Branch 4. 6pp. 32929-242-32929-309.

F. Security, medical, emergency & fire protection plans

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents, App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-**8510080038** Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Chicago, IL to discuss radioactive matl in process steam, potential for subsidence, seismic design criteria, emergency plans & flood protection level.
MCKINLEY, J.C. Atomic Energy Commission. 70/04/15. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929-073-32929-074.

-**8510080049** Submits agenda for ACRS Subcommittee on Midland Plant 700324 meeting in Washington, DC to discuss items, including emergency plans, adequacy of ESF & protection sys, control room design & ECCS initiations signals.
MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/03/18. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-086-32929-086.

-**8510080051** Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Washington, DC to discuss emergency plans, adequacy of ESF & protection sys, containment design, siting of ECCS reservoir & steam purity & monitoring.
MCKINLEY, J.C. Atomic Energy Commission. 70/02/12. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-087-32929-087.

-**8510080061** Submits schedule & agenda for ACRS Subcommittee on Midland Plant 690204 meeting to discuss meteorology, dose calculations, containment leakage rates, containment iodine removing sys & evacuation procedures. Related info encl.
HARD, J.E. Atomic Energy Commission. 69/01/29. MULLER, D. Atomic Energy Commission. 22pp. 32929-089-32929-110.

-**8510080391** Forwards tentative schedule for ACRS Subcommittee on Midland Plant 820602 meeting to continue review of application for OL. Topics include fire protection, control room habitability & items from 820520-21 meetings.
FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930-010-32930-015.

-**8510080403** Forwards tentative schedule for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL. Discussion topics include quality of design & const, alternate shutdown, seismic criteria & PRA mgt.
FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/12. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930-042-32930-049.

G. Adjudicatory correspondence

8510110217 Informs of plans to physically disable equipment installed in & about evaporator bldg to serve process steam to Dow Chemical Co, per 850925 resolution. Equipment & structures abandoned are non-Q. Related correspondence.
MILLER, M.I. Isham, Lincoln & Beale. #485 747. 85/10/08. ROSENTHAL, A.S., MOORE, T.S. Atomic Safety and Licensing Board Panel. App. 32972-359-32972-362.

8510110166 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
HASSELL, D.F. Hearing Branch 2. #485 740. 85/10/09. 3pp. 32977-348-32972-350.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents, App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

- 820920126 Requests info on factors entering into cost of adding safety-grade high level trip on each steam generator.
FISCHER,D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/06/28.
HERNAN,R. NRC - No Detailed Affiliation Given. 17pp. 32930:058-32930:074.
- 8510080033 Forwards project status rept for ACRS Subcommittee on Midland Plant 820602 meeting in Washington,DC to review application for OL Related info encl.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/28.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 57pp. 32929:014-32929:070.
- 8510080038 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Chicago,IL to discuss radioactive mail in process steam,potential for subsidence,seismic design criteria, emergency plans & flood protection level.
MCKINLEY,J.C. Atomic Energy Commission. 70/04/15. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:073-32929:074.
- 8510080048 Submits agenda for ACRS Subcommittee on Midland Plant 700324 meeting in Washington,DC to discuss items,including emergency plans,adequacy of ESF & protection sys,control room design & ECCS initiation signals.
MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/03/18. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:086-32929:086.
- 8510080051 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Washington,DC to discuss emergency plans,adequacy of ESF & protection sys,containment design,siting of ECCS reservoir & steam purity & monitoring.
MCKINLEY,J.C. Atomic Energy Commission. 70/02/12. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:087-32929:087.
- 8510080073 Summary of 700422 meeting w/util & Dow Chemical Co re radioactivity of process steam to be exported to Dow/FDA recommended detector to continuously monitor activity of steam.Related info encl.
MCKINLEY,J.C. Atomic Energy Commission. 70/04/23. SQUIRES,L. Atomic Energy Commission. 5pp. 32929:111-32929:115.
- 8510080088 Forwards draft FR notice re ACRS Subcommittee 820429 meeting Portions of meeting may be closed.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/04/07.
HOYLE,J.C. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 32929:117-32929:119.
- 8510080094 Forwards ACRS 761118 supplemental rept & attached mail for in camera review by ASLB & parties to Midland hearing,per 761130 request.
FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 76/12/01.
HEAD,D.M. Atomic Safety and Licensing Board Panel. 2pp. 32929:120-32929:121.
- 8510080100 Forwards 770126 request for addl info re ACRS 761201 supplemental rept on Midland Supplemental rept encl. Discussion in 770210-12 meeting & possible action during Mar 1977 full committee meeting planned.
LIBARKIN,M.W. ACRS - Advisory Committee on Reactor Safeguards. 77/02/04. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32961:026-32961:026.
- 8510080132 Summary of briefing re ACRS Subcommittee Chairman L. Squires on AEC requirements/plans re licensing of Midland &/or Dow Chemical Co for use of secondary steam from facility.
FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/05/01. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32929:145-32929:150.
- 8510080143 Forwards schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington,DC to discuss util remedial action re soils & structural settlement issues.
FISCHER,D. NRC - No Detailed Affiliation Given. 82/04/14. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929:151-32929:154.
- 8510080239 Forwards for review,seismic site-specific spectra info,per telcon & request by D Okrent,Comments will determine discussion topics at ACRS Subcommittee on Midland 820520-21 meetings.
FISCHER,D.C. NRC - No Detailed Affiliation Given. 82/04/09. POMEROY,P. TRIFUNJAC,M. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:159-32929:160.
- 8510080284 Summary of 760521 meeting w/util in Bethesda,MD re proposed high energy line break analysis Agenda encl.
MULLER,R. ACRS - Advisory Committee on Reactor Safeguards. 76/05/24. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929:315-32929:318.
- 8510080295 Requests copies of ACRS documents re Midland be forwarded to Chairman Okrent & other ACRS members.
STAMIRIS,B. Stamiris, B. 82/05/30. FISCHER ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:319-32929:319.
- 8510080302 Statement before ACRS Subcommittee on Midland Nuclear Plant re alleged QC problems,Public confidence in licensing process lost.
SINCLAIR,M. Affiliation Not Assigned. 82/06/04. 21pp. 32929:320-32929:340.
- 8510080309 Advises that ACRS concurred w/proposed staff position re diverse reactor trip signal during 127th meeting.
FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/11/18.
PRICE,H.L. Atomic Energy Commission. 2pp. 32929:341-32929:342.
- 8510080329 Forwards summary of info from Category B repts ACRS action unwarranted.
MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/07/13.
SQUIRES,L. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:343-32929:344.
- 8510080337 Notices of ACRS Subcommittee on Midland Plant 700914 meeting in Washington,DC to discuss containment design pressure change,tertiary steam sys & ternary steam generator design,Related info encl.
MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/08/28. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929:345-32929:348.
- 8510080341 Notices of ACRS Subcommittee on Midland Plant 700610 meeting in Washington,DC to discuss ATWS design approaches, addl primary sys safety valve capacity & process steam purity & monitoring.
MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/14. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:349-32929:349.
- 8510080449 Forwards summary of info in Category B repts ACRS action unwarranted,Related info encl.
MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/20.
SQUIRES,L. BUSH,S.H. ACRS - Advisory Committee on Reactor Safeguards. 9pp. 32929:350-32929:358.
- 8510080357 Documents conclusions reached during ACRS 122nd meeting re Midland Plant Units 1 & 2 request for exemption to allow certain const & ESF instrumentation for Indian Point 2.
FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/06/17.
MORRIS,P.A. Atomic Energy Commission. 2pp. 32929:319-32929:360.
- 8510080386 Forwards written statement of C Anderson,MP Sinclair & B Stamiris submitted for ACRS subcommittee 820520-21 meetings,C Anderson statement includes Addenda 1 & 2.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. ACRS - Advisory Committee on Reactor Safeguards. DENTON,H. Office of Nuclear Reactor Regulation, Director. EISENHUT,D. Division of Licensing. 1p. 32930:009-32930:009.
- 8510080391 Forwards tentative schedule for ACRS Subcommittee on Midland Plant 820602 meeting to continue review of application for OL Topics include fire protection,control room habitability & items from 820520-21 meetings.
FISCHER,D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930:010-32930:015.
- 8510080394 Forwards proposed summary for ACRS Subcommittee on Midland Plant 820520-21 meetings to review application for OL List of attendees & meeting highlights,agreements & requests included.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/08/21.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 10pp. 32930:016-32930:025.
- 8510080397 Forwards project status rept for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL Rept summarizes ACRS review to date,open items,ACRS actions required & requests for public participation.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/17.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 16pp. 32930:026-32930:041.
- 8510080403 Forwards tentative schedule for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL Discussion topics include quality of design & siting, seismic criteria & PRA mgt.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/12.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930:042-32930:049.
- 8510080420 Forwards proposed summary of ACRS Subcommittee on Midland 820602 meeting review of application for OL for review & comment Corrections & additions will be included in minutes of meeting.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/08/11.
OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 32930:076-32930:080.
- 8510080426 Forwards Midland Hearing Board request for further elaboration of 700618 committee rept re LWR problems. Comments on behalf of util arguing that other problems should be considered as items of rept encl.
LIBARKIN,M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/11/10. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32930:081-32930:081.
- 8510080429 Provides info re necessity of further explication of ACRS rept concerning "catch-all" paragraph on problems about LWRs Related info encl.
LIBARKIN,M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/08/06. ACRS - Advisory Committee on Reactor Safeguards. 7pp. 32930:083-32930:089.
- 8510080431 Summary of ACRS Ad Hoc Subcommittee on Midland 820429 meeting w/util & consultants in Washington,DC re foundation problems & remedial action.
SIESS,C.P. ACRS - Advisory Committee on Reactor Safeguards. 85/09/30. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930:090-32930:097.
- 8510080435 Forwards M Sinclair statement for ACRS Subcommittee on Midland 820429 meeting.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/04.
DENTON,H. Office of Nuclear Reactor Regulation, Director. EISENHUT,D. Division of Licensing. MATTSON,R. Division of Systems Integration. (post 811005). 2pp. 32930:096-32930:099.
- 8510080441 Forwards revised schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington,DC to discuss util remedial action re soils & structural settlement issues. Related info encl.
FISCHER,D.C. NRC - No Detailed Affiliation Given. 82/04/26. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930:120-32930:123.
- 8510080444 Discusses upcoming ACRS 820429 meeting in Washington,DC to discuss soil sediment problems at facility Related info encl.
SINCLAIR,M. Sinclair, M. 82/04/26. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. 27pp. 32930:124-32930:149.
- 8510080448 Forwards proposed FR notice of ACRS Subcommittee on Midland 820520 & 21 meetings in Midland,MI Portions of meeting may be closed for reasons stated in attachment. Requests that notice be published by 820504 Related info encl.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/04/27.
HOYLE,J.C. ACRS - Advisory Committee on Reactor Safeguards. 29pp. 32930:150-32930:192.

Q. Inspection reports, IE Bulletins & correspondence

- 8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint.Operations & Security Personnel" Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

116 DOCKETED ITEMS

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR.
FELTON,J.M. Division of Rules and Records. 85/09/30. BRUNNER,J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-8510080158 Confirms conversation re 820426 meeting in Jackson,MI to discuss SALP SALP Board finding encl.
HIND,J.A. Division of Emergency Preparedness & Operational Support. 82/04/20. COOK,J.W. Consumers Power Co. App. 32951.021-32951.023.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210254 Forwards CJ Holloway 840409 memo discussing regional & IE activity codes included & excluded from OL reviews.
DIGGS,R.M. License Fee Management Branch. 85/10/11. BIRD,W. Consumers Power Co. 1p. 33079-329-33079-334.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class/Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasonic 600 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510080090 Submits Quarterly Rept 49,per ALAB-106.No new individuals assigned to quality-related duties.Const at plant shut down on 840716.No const projected for Fourth Quarter 1985.Next quarterly rept will be submitted by end of Dec 1985.
COOK,J.W. Consumers Power Co. 85/09/30. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 1p. 32920-253-32920-253.

8510290345 Forwards monthly rept for Sept 1985,per Memorandum & Order ALAB-106 & Amend 1 to CP,including Bechtel nonconformance rept,quality action requests,mgt corrective action repts, quality audit findings & B&W repts of nonconformity.
COOK,J.W. Consumers Power Co. 85/10/25. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 43pp. 33241-001-33241-043.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY,W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER,C. Division of Licensing. 26pp. 32824-260-32824-305.

8510220408 Interim deficiency rept re Limtorque motor-operated butterfly valves not opening electrically after closed manually.Initially reported on 850912.No corrective actions will be taken unless facility reactivated.
COOK,J.W. Consumers Power Co. 85/10/08. KEPPLER,J.G. Region 3, Office of Director. 4pp. 33097-001-33097-004.

8510220411 Interim deficiency rept re loose set screws on Anchor Darling swing check valves & disc nut pin problems causing inoperability.Initially reported on 850912.No further corrective action will be taken unless facility reactivated.
COOK,J.W. Consumers Power Co. 85/10/08. KEPPLER,J.G. Region 3, Office of Director. 4pp. 33097-034-33097-037.

8510220090 Interim deficiency rept re larger than anticipated util movement where freewall crossed safety-related utils at Monitoring Pits 1,2,3 & 4.Initially reported on 850917.No action will be taken.
COOK,J.W. Consumers Power Co. 85/10/09. KEPPLER,J.G. Region 3, Office of Director. 4pp. 33095-148-33095-151.

T. Hearing transcripts on non-antitrust matters

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR.
FELTON,J.M. Division of Rules and Records. 85/09/30. BRUNNER,J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-8510080367 Statement of C Anderson before ACRS subcommittee 820520-21 meetings re review of application for OL Statement addresses soil/structure interaction problems.Addenda 1 & 2 encl.
ANDERSON,C. A A Engineering. 82/05/20. 3pp. 32929-361-32930-001.

-8510080379 Statement of MP Sinclair before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of application for OL Statement addresses plant design & qualification deficiencies.
SINCLAIR,M.P. Sinclair, M. 82/05/20. 3pp. 32930-006-32930-008.

V. Operator Examinations

8509240246 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510080037 FOIA request for ACRS documents re facility.
BRUNNER,J.E. Consumers Power Co. 85/08/23. Office of Administration. 2pp. 32929-071-32929-072.

8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities.Forwards App D documents.Documents also available in PDR App E documents withheld (ref FOIA Exemptions 6 & 7).
FELTON,J.M. Division of Rules and Records. 85/09/20. RILLO,C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833-002-32833-052.

-8510010237 Summary of 820915 meeting w/util in Chicago,IL re proposed util investigation into GAP allegations concerning facilities.Util agreed to delay investigation until NRC completes investigation.Related info encl.
BACI,P.E. Office of Investigation. 82/09/20. Office of Investigation. 28pp. 32833-022-32833-049.

8510010279 Forwards Bechtel nonconformance repts,quality action requests,mgt corrective action repts & quality audit findings written or closed during Aug 1985,per condition of Memorandum & Order ALAB-106.
COOK,J.W. Consumers Power Co. 85/09/25. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 7pp. 33026-223-33026-229.

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR.
FELTON,J.M. Division of Rules and Records. 85/09/30. BRUNNER,J.E. Consumers Power Co. 11pp. 32929-003-32934-092.

-8208030689 Recommends that design & const audit recommended by ACRS be performed by competitor to assure highest possible degree of objectivity & independence.
STAMIRIS,B. Stamiris, B. 82/07/28. TEDESCO,R.L. Assistant Director for Licensing. 1p. 32930-075-32930-075.

-8510080033 Forwards project status rept for ACRS Subcommittee on Midland Plant 820602 meeting in Washington,DC to review application for OL.Related info encl.
FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/28. OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 57pp. 32929-014-32929-070.

-8510080045 Forwards summary of 700312 meeting w/util & JT Wilson in Bethesda,MD re subsidence problem under site.General subsidence could occur,but not abrupt offset.Abrupt offset or scarping could not be tolerated.
MCKINLEY,J.C. Atomic Energy Commission. 70/03/19. SQUIRES,L. Atomic Energy Commission. 11pp. 32929-075-32929-085.

-8510080055 Summarizes meeting w/util re Dow Chemical Co solution mining of salt Calculations of stress levels at or near surface of bedrock required.
WILSON,J.T. Affiliation Not Assigned. 70/03/16. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-088-32929-088.

-8510080073 Summary of 700422 meeting w/util & Dow Chemical Co re radioactivity of process steam to be exported to Dow.FDA recommended detector to continuously monitor activity of steam.Related info encl.
MCKINLEY,J.C. Atomic Energy Commission. 70/04/23. SQUIRES,L. Atomic Energy Commission. 5pp. 32929-111-32929-115.

-8510080127 Forwards 10CFR30-36 & 150,for info in connection w/review of Midland,W/o encl.
FRALEY,R.F. Atomic Energy Commission. 70/04/28. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-144-32929-144.

-8510080132 Summary of briefing of ACRS Subcommittee Chairman L Squires on AEC requirements/plans re licensing of Midland &/or Dow Chemical Co for use of secondary steam from facility.
FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/05/01. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32929-145-32929-150.

-8510080262 Discusses 820407 telcon re ACRS subcommittee 840429 meeting on soils matters.Discussion will focus on remedy rather than cause of soil problem.
HOOD,D. Licensing Branch 4. 82/04/07. FISCHER,D. NRC - No Detailed Affiliation Given. 10pp. 32929-230-32929-239.

-8510080277 Notification of 760521 meeting w/util in Bethesda,MD to discuss criteria to be used for analysis of high energy line breaks.Related info encl.
CROCKER,L.P. NRC - No Detailed Affiliation Given. 76/05/01. KNIEL,K. NRC - No Detailed Affiliation Given. 5pp. 32929-310-32929-314.

-8510080373 Forwards statement of B Stamiris before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of util application for OL.Statement addresses misrepresented or overlooked issues re soil settlement.
STAMIRIS,B. Stamiris, B. 82/05/20. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930-002-32930-005.

-8510080409 Urges serious consideration of const problems at plant site, rated one of five worst nuclear plants in country per W Dircks May 1981 testimony before Congress.Util should be held accountable for public safety.
GARDE,B.P. Government Accountability Project. 83/01/11. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. SIESS,C. Illinois, Univ. of, Urbana, IL. 8pp. 32930-050-32930-057.

-8510080436 Forwards project status rept for ACRS Subcommittee on Midland 820429 meeting in Washington,DC to discuss util remedial action on soils & structural settlement issues.
FISCHER,D. NRC - No Detailed Affiliation Given. 82/04/21. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. 14pp. 32930-100-32930-119.

8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland,Palisades & San Onofre nuclear power plants.Forwards App F documents, App F documents also placed in PDR.
FELTON,J.M. Division of Rules and Records. 85/09/30. RILLO,C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049-042-33049-234.

851010011 Board Notification 85-066 supps Board Notifications 82-117, 83-102 & 85-045 re welding-related allegations at Midland 1 & 2 H. Wahl (Bechtel) 850916 summary of developments in suit filed re E Kent allegations & 850509 ltr encl. NOVAK, T.M. Assistant Director for Licensing. 85/10/07. ROSENTHAL, A.S., MOORE, T. Atomic Safety and Licensing Appeal Panel. 4pp. 33056:121-33056:130.

-8510180161 Discusses EE Kent allegations re plant, per encl 850509 ltr. Decision reflected in NRC 850809 ltr should be reconsidered. B. Garde & T. Devine of GAP unwilling to testify for Kent, Kent & counsel unable to produce expert witnesses. WAHL, H.W. Bechtel Corp. 85/09/16. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33056:125-33056:130.

-8510180175 Discusses EE Kent allegations re quality of engineering & const at plant. Region III could quickly dispose of matters held open in NRC 850322 ltr. Meeting to facilitate closure suggested. WAHL, H.W. Bechtel Corp. 85/05/09. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33056:128-33056:130.

8510230132 Informs that util will submit schedule for meeting requirements of 10CFR50.62(d) per Generic Ltr 85-06 re QA guidance for ATWS nonsafety-related equipment when & if project reactivated. COOK, J.W. Consumers Power Co. 85/10/14. THOMPSON, H.L. Division of Licensing. 1p. 33102:091-33102:091.

E. NRC Safety Evaluation Report (SER), supps & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929:003-32929:070.

-8204120124 Forwards branch SER input. Sections 2.5.5 re stability of slopes & 2.5.6 re embankment & dams, essentially complete. Section 2.5.4 re stability of subsurface mats & foundations, remains open & impacted by ASLB hearings. LEAR, G. Hydrologic & Geotechnical Engineering Branch. 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 17pp. 32929:213-32929:229.

-8204210531 Forwards Structural Engineering Branch SER input re FSAR Chapter 3 on design of Category I structures. Evaluation will be completed upon submittal of info re soil remedial actions & new site-specific response spectra. KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/05. TEDESCO, R.L. Assistant Director for Licensing. 2pp. 32929:161-32929:162.

-8204290608 Forwards geological & seismological input to SER for OL. KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 28pp. 32929:185-32929:212.

-8510080248 SER input re design of Category I structures & remedial actions. Completion of SER controlled by util response to NRC request for info re soil remedial actions. * Structural Engineering Branch. 82/04/05. 22pp. 32929:163-32929:184.

-8510080272 Forwards SER input. Outstanding issues listed, including flood protection of settled structures & adequacy of dewatering sys. Related info encl. LEAR, G. Hydrologic & Geotechnical Engineering Branch. 85/09/30. ADENSAME, L. Licensing Branch 4. 69pp. 32929:242-32929:309.

F. Security, medical, emergency & fire protection plans

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929:003-32929:070.

-8510080038 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Chicago, IL, to discuss radioactive matl in process steam, potential for subsidence, seismic design criteria, emergency plans & flood protection level. MCKINLEY, J.C. Atomic Energy Commission. 70/04/15. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:073-32929:074.

-8510080049 Submits agenda for ACRS Subcommittee on Midland Plant 700324 meeting in Washington, DC to discuss items, including emergency plans, adequacy of ESF & protection sys, control room design & ECCS initiation signals. MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/03/18. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:086-32929:086.

-8510080051 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Washington, DC to discuss emergency plans, adequacy of ESF & protection sys, containment design, siting of ECCS reservoir & steam purity & monitoring. MCKINLEY, J.C. Atomic Energy Commission. 70/02/12. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:087-32929:087.

-8510080061 Submits schedule & agenda for ACRS Subcommittee on Midland Plant 690204 meeting to discuss meteorology, dose calculations, containment leakage rates, containment iodine removing sys & evacuation procedures. Related info encl. HARD, J.E. Atomic Energy Commission. 69/01/29. MULLER, D. Atomic Energy Commission. 22pp. 32929:089-32929:110.

-8510080391 Forwards tentative schedule for ACRS Subcommittee on Midland Plant 8206/2 meeting to continue review of application for OL. Topics include fire protection, control room habitability & items from 820520-21 meetings. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930:010-32930:015.

-8510080403 Forwards tentative schedule for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL. Discussion topics include quality of design & const, alternate shutdown, seismic criteria & PRA mgt. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/12. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930:042-32930:049.

G. Adjudicatory correspondence

8510110217 Informs of plans to physically disable equipment installed in & about evaporator bldg to serve process steam to Dow Chemical Co. per 850925 resolution. Equipment & structures abandoned are non-Q. Related correspondence. MILLER, M.I. Isham, Lincoln & Beale. #485 747. 85/10/08. ROSENTHAL, A.S., MOORE, T.S. Atomic Safety and Licensing Board Panel. 4pp. 32972:359-32972:362.

8510110168 Notice of withdrawal of appearance in proceeding Certificate of Svc encl. HASSELL, D.F. Hearing Branch 2. #485 740. 85/10/09. 3pp. 32972:348-32972:350.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929:003-32929:070.

-8209020126 Requests info on factors entering into cost of adding safety-grade high level trip on each steam generator. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/06/28. HERNAN, R. NRC - No Detailed Affiliation Given. 17pp. 32930:058-32930:074.

-8510080033 Forwards project status rept for ACRS Subcommittee on Midland Plant 820602 meeting in Washington, DC to review application for OL. Related info encl. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/28. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 57pp. 32929:014-32929:070.

-8510080038 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Chicago, IL, to discuss radioactive matl in process steam, potential for subsidence, seismic design criteria, emergency plans & flood protection level. MCKINLEY, J.C. Atomic Energy Commission. 70/04/15. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:073-32929:074.

-8510080049 Submits agenda for ACRS Subcommittee on Midland Plant 700324 meeting in Washington, DC to discuss items, including emergency plans, adequacy of ESF & protection sys, control room design & ECCS initiation signals. MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/03/18. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:086-32929:086.

-8510080051 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Washington, DC to discuss emergency plans, adequacy of ESF & protection sys, containment design, siting of ECCS reservoir & steam purity & monitoring. MCKINLEY, J.C. Atomic Energy Commission. 70/02/12. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:087-32929:087.

-8510080073 Summary of 700422 meeting w/ util & Dow Chemical Co re radioactivity of process steam to be exported to Dow. FDA recommended detector to continuously monitor activity of steam. Related info encl. MCKINLEY, J.C. Atomic Energy Commission. 70/04/23. SQUIRES, L. Atomic Energy Commission. 5pp. 32929:111-32929:115.

-8510080088 Forwards draft FR notice re ACRS Subcommittee 820429 meeting. Portions of meeting may be closed. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/04/07. HOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 32929:117-32929:119.

-8510080094 Forwards ACRS 761118 supplemental rept & attached matl for in camera review by ASLB & parties to Midland hearing, per 761130 request. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 76/12/01. HEAD, D.M. Atomic Safety and Licensing Board Panel. 2pp. 32929:120-32929:121.

-8510080100 Forwards 770128 request for addl info re ACRS 761201 supplemental rept on Midland. Supplemental rept encl. Discussion in 770210-12 meeting & possible action during Mar 1977 full committee meeting planned. LIBARKIN, M.W. ACRS - Advisory Committee on Reactor Safeguards. 77/02/04. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32951:026-32951:026.

-8510080132 Summary of briefing of ACRS Subcommittee Chairman L. Squires on AEC requirements/plans re licensing of Midland &/or Dow Chemical Co for use of secondary steam from facility. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/05/01. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32929:145-32929:150.

-8510080143 Forwards schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington, DC to discuss util remedial action re soils & structural settlement issues. FISCHER, D.C. NRC - No Detailed Affiliation Given. 82/04/14. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929:151-32929:154.

-8510080239 Forwards, for review, seismic site-specific spectra info, per telcon & request by D. Okrent. Comments will determine discussion topics at ACRS Subcommittee on Midland 820520-21 meetings. FISCHER, D.C. NRC - No Detailed Affiliation Given. 82/04/09. POMEROY, P., TRIFUNAC, M. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929:159-32929:160.

-8510080284 Summary of 760521 meeting w/ util in Bethesda, MD re proposed high energy line break analysis. Agenda encl. MULLER, D. ACRS - Advisory Committee on Reactor Safeguards. 76/05/24. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929:315-32929:318.

-8510080295 Requests copies of ACRS documents re Midland be forwarded to Chairman Okrent & other ACRS members. STAMIRIS, B. Stamiris, B. 82/05/30. FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929:319-32929:319.

-8510080302 Statement before ACRS Subcommittee on Midland Nuclear Plant re alleged QC problems. Public confidence in licensing process lost. SINCLAIR, M. Affiliation Not Assigned. 82/06/04. 21pp. 32929:320-32929:340.

118 CLOCKETED ITEMS

-851008039 Advises that ACRS concurred w/proposed staff position re diverse reactor trip signal during 127th meeting.
FRALEY, I.F. ACRS - Advisory Committee on Reactor Safeguards. 70/11/18. PRICE, H. Atomic Energy Commission. 2pp. 32929-341-32929-342.

-851008039 Forwards summary of info from Category B repts. ACRS action unwarranted.
MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/07/13. SQUIRES, J.C. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929-343-32929-344.

-8510080337 Notices of ACRS Subcommittee on Midland Plant 700914 meeting in Washington, DC to discuss containment design pressure change, tertiary steam sys & tertiary steam generator design. Related info encl.
MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/08/28. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929-345-32929-348.

-8510080341 Notices of ACRS Subcommittee on Midland Plant 700610 meeting in Washington, DC to discuss ATWS design approaches, add primary sys safety valve capacity & process steam purity & monitoring.
MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/14. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-349-32929-349.

-8510080349 Forwards summary of info in Category B repts. ACRS action unwarranted. Related info encl.
MCKINLEY, J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/20. SQUIRES, J.C. ACRS - Advisory Committee on Reactor Safeguards. 9pp. 32929-350-32929-358.

-8510080357 Documents conclusions reached during ACRS 122nd meeting re Midland Plant Units 1 & 2 request for exemption to allow certain const & ESF instrumentation for Indian Point 2.
FRALEY, I.F. ACRS - Advisory Committee on Reactor Safeguards. 70/06/17. MORRIS, P.A. Atomic Energy Commission. 2pp. 32929-359-32929-360.

-8510080386 Forwards written statement of C Anderson, MP Sinclair & B Stamiris submitted for ACRS subcommittee 820520-21 meetings. C Anderson statement includes Addenda 1 & 2.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. ACRS - Advisory Committee on Reactor Safeguards. DENTON, H. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. Division of Licensing. 1p. 32930-009-32930-009.

-8510080391 Forwards tentative schedule for ACRS Subcommittee on Midland Plant 820602 meeting to continue review of application for OL. Topics include fire protection, control room habitability & items from 820520-21 meetings.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930-010-32930-015.

-8510080394 Forwards proposed summary for ACRS Subcommittee on Midland Plant 820520-21 meetings to review application for OL. List of attendees & meeting highlights, agreements & requests included.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/08/21. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 10pp. 32930-016-32930-025.

-8510080397 Forwards project status report for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL. Rept summarizes ACRS review to date, open items, ACRS actions required & requests for public participation.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/17. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 16pp. 32930-026-32930-041.

-8510080403 Forwards tentative schedule for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL. Discussion topics include quality of design & const, alternate shutdown, seismic criteria & PRA mgt.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/12. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930-042-32930-049.

-8510080420 Forwards proposed summary of ACRS Subcommittee on Midland 820602 meeting review of application for OL, for review & comment. Corrections & additions will be included in minutes of meeting.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/08/11. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 32930-076-32930-080.

-8510080426 Forwards Midland Hearing Board request for further elaboration of 700618 committee report re LWR problems. Comments on behalf of util arguing that other problems should be considered as items of report encl.
LIBARKIN, M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/11/10. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32930-081-32930-081.

-8510080429 Provides info re necessity of further explication of ACRS report concerning "catch-all" paragraph on problems about LWRs. Related info encl.
LIBARKIN, M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/08/06. ACRS - Advisory Committee on Reactor Safeguards. 7pp. 32930-083-32930-089.

-8510080431 Summary of ACRS Ad Hoc Subcommittee on Midland 820429 meeting w/ util & consultants in Washington, DC re foundation problems & remedial action.
SIESS, C.P. ACRS - Advisory Committee on Reactor Safeguards. 85/09/30. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930-090-32930-097.

-8510080435 Forwards M Sinclair statement for ACRS Subcommittee on Midland 820429 meeting.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/04. DENTON, H. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. Division of Licensing. MATTSO, R. Division of Systems Integration (post 811005). 2pp. 32930-098-32930-099.

-8510080441 Forwards revised schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington, DC to discuss util remedial action re soils & structural settlement issues. Related info encl.
FISCHER, D. ACRS - No Detailed Affiliation Given. 82/04/26. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930-120-32930-123.

-8510080444 Discusses upcoming ACRS 820429 meeting in Washington, DC to discuss soil sediment problems at facility. Related info encl.
SINCLAIR, M. Sinclair, M. 82/04/26. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 27pp. 32930-124-32930-149.

-8510080448 Forwards proposed FR notice of ACRS Subcommittee on Midland 820520 & 21 meetings in Midland, MI. Portions of meeting may be closed for reasons stated in attachment. Requests that notice be published by 820504. Related info encl.
FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/04/27. HOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 29pp. 32930-150-32930-192.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510080023 Responds to FOIA request for ACRS documents re f. Forwards App B documents. App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNING, J.E. Consumers Power Co. 11pp. 32929-003-32929-070.

-8510080107 Forwards Special Insp Rept 50-330/77-02 on 770228 & 0301.
HEISHMAN, R.F. Region 3, Office of Director. 77/03/15. HOWELL, S.H. Consumers Power Co. 2pp. 32929-124-32929-125.

-8510080113 Const Insp Rept 50-330/77-02 on 770228-0301 Noncompliance noted failure to retest bulge deficiency per 10CFR50.55(e)(2). Related info encl.
YIN, J.T., HAYES, D.W. Region 3, Office of Director. 77/03/15. 18pp. 32929-126-32929-143.

-8510080158 Confirms conversation re 820426 meeting in Jackson, MI to discuss SALP SALP Board finding encl.
HIND, J.A. Division of Emergency Preparedness & Operational Support. 82/04/20. COOK, J.W. Consumers Power Co. 4pp. 32951-021-32951-023.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210254 Forwards CJ Holloway 840409 memo discussing regional & IE activity codes included & excluded from OL reviews.
DIGGS, R.M. License Fee Management Branch. 85/10/11. BIRD, W. Consumers Power Co. 1p. 33079-329-33079-334.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510080090 Submits Quarterly Rept 49, per ALAB-106. No new individuals assigned to quality-related duties. Const at plant shut down on 840716. No const projected for Fourth Quarter 1985. Next quarterly report will be submitted by end of Dec 1985.
COOK, J.W. Consumers Power Co. 85/09/30. TAYLOR, J. Director's Office, Office of Inspection and Enforcement. 1p. 32920-253-32920-253.

8510290345 Forwards monthly report for Sept 1985, per Memorandum & Order ALAB-106 & Amend 1 to CP, including Bechtel nonconformance report, quality action requests, mgt corrective action repts, quality audit findings & B&W repts of nonconformity.
COOK, J.W. Consumers Power Co. 85/10/25. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 43pp. 33241-001-33241-043.

S. Reports re occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510220408 Interim deficiency report re Limitorque motor-operated butterfly valves not opening electrically after closed manually. Initially reported on 850912. No corrective actions will be taken unless facility reactivated.
COOK, J.W. Consumers Power Co. 85/10/08. KEPPLER, J.G. Region 3, Office of Director. 4pp. 33097-001-33097-004.

8510220411 Interim deficiency report re loose set screws on Anchor Darling swing check valves & disc nut pin problems causing inoperability. Initially reported on 850912. No further corrective action will be taken unless facility reactivated.
COOK, J.W. Consumers Power Co. 85/10/08. KEPPLER, J.G. Region 3, Office of Director. 4pp. 33097-034-33097-037.

8510220090 Interim deficiency rept re larger than anticipated util movement where freeze wall crossed safety-related util at Monitoring Pitts 1,2,3 & 4. Initially reported on 8/5/91. No action will be taken.
COOK, J.W. Consumers Power Co. 85/10/09. KEPPLER, J.G. Region 3, Office of Director. 4pp. 33095:148-33095:151.

T. Hearing transcripts on non-antitrust matters

8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents. App A & B documents available in PCR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929:003-32929:070.

-8510080367 Statement of C Anderson before ACRS subcommittee 820520-21 meetings re review of application for OL. Statement addresses soil/structure interaction problems. Addenda 1 & 2 encl.
ANDERSON, C. A A Engineering. 82/05/20. 3pp. 32929:361-32930:001.

-8510080379 Statement of MP Sinclair before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of application for OL. Statement addresses plant design & qualification deficiencies.
SINCLAIR, M.P. Sinclair, M. 82/05/20. 3pp. 32930:006-32930:008.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

8510070286 Rev 2 to Corporate Plan Implementing Procedure CIP-1.4, "Release of Emergency-Related Info" & Rev 3 to CIP-2.1, "Dose Assessment & Protective Action Recommendations." Revised index encl. W/850920 ltr.
WILSON, D.L. Iowa Electric Light & Power Co. 85/09/20. 180pp. 32874:210-32875:019.

8510080050 Advises that 850829 Rev 5 to emergency plan consistent w/provisions of 10CFR50.54(a) & acceptable.
SHAFFER, W.D. Region 3, Office of Director. 85/10/03. LIU, L. Iowa Electric Light & Power Co. 2pp. 32919:358-32919:359.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PCR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230098 Forwards Press Release 84-34 re NRC proposed imposition of civil penalty in amount of \$20,000 against util for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 84/03/16. OTTINGER, R.L. House of Rep. Energy & Commerce. MARKEY House of Rep. GRASSLEY Senate. 2pp. 33108:339-33108:340.

8510100027 Forwards Safety Insp Rept 50-331/85-21 on 850723-0916 & notice of violation.
CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/07. LIU, L. Iowa Electric Light & Power Co. 2pp. 32959:203-32959:224.

-8510100039 Notice of violation from insp on 850723-0916.
CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/07. 2pp. 32959:205-32959:206.

-8510100051 Insp Rept 50-331/85-21 on 850723-0916. Violation noted: fire watch not established since 850719 & plant operated for approx 7 h w/o establishing base line APRM noise levels on 850802.
WIEBE, J.S., MILBROT, W.E., HILAND, P.L. Region 3, Office of Director. 85/10/03. 18pp. 32959:207-32959:224.

8510250210 Lists determinations based on review of util 850507 response to 850305 safeguards insp rept re use of armed responder for compensatory duties. Although members of response force may have other duties, primary duty must be response.
AXELSON, W.L. Region 3, Office of Director. 85/10/11. LIU, L. Iowa Electric Light & Power Co. 2pp. 33190:076-33190:077.

8510210149 Submits schedule for upgrades to plant instrumentation per requirements of Suppl 1 to NUREG-0737 Rev 2 to Reg Guide 1.97 & Generic Ltr 84-23. Mods will not be fully implemented until 1988 Cycle 9/10 refueling outage.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/16. DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 33071:142-33071:144.

8510280353 Forwards security & guard training & qualification plans. Plans withheld (ref 10CFR73.21).
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/18. KEPPLER, J.G. Region 3, Office of Director. 2pp. 33192:064-33. 92:065.

8510250394 Provides written notification of change in Schedule B item, "Detailed (Suppl 1) CRDR - Supplemental DCRDR," due to underestimation of increased scope of work. Item will be completed by 851103.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/22. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 33171:302-33171:302.

P. Operating license stage documents & correspondence

8510100019 Forwards info re NRC split sample audit of Aug 1985, including memo concerning Kr-85M activity calculated for offgas pretreatment split sample & Gamma 2 search analysis for gamma spectrophotometer.
MINECK, D.L. Iowa Electric Light & Power Co. 85/08/29. HOLTZMAN, R. Region 3, Office of Director. 8pp. 32960:221-32960:228.

8510160344 Forwards Amend 126 to License DPR-49 & safety evaluation. Amend revises Tech Specs incorporating restrictions required by NUREG-0737, Item I.A.1.3.1 re overtime for plant operators.
THADANI, M.C. Operating Reactors Branch 2. 85/10/10. LIU, L. Iowa Electric Light & Power Co. 2pp. 33028:294-33028:301.

-8510160345 Amend 126 to License DPR-49, revising Tech Specs to incorporate restrictions re overtime for plant operators.
VASSALLO, D.B. Operating Reactors Branch 2. 85/10/10. 4pp. 33028:296-33028:299.

-8510160347 Safety evaluation supporting Amend 126 to License DPR-49.
* Office of Nuclear Reactor Regulation, Director. 85/10/10. 2pp. 33028:300-33028:301.

8510150332 Forwards corrected Table 1.1 re power sources for post-trip review recorders, submitted w/850826 response to request for add info concerning Generic Ltr 83-28, Item 1.2. Panel 1C09 will be modified during Cycle 9/10 refueling outage.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/11. DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 33010:354-33010:356.

8510170281 Supplemental application for amend to License DPR-49, clarifying footnotes & correcting typos in Tech Spec Tables 3.2-H & 4.2-H re accident monitoring instrumentation, per Generic Ltr 83-36, "NUREG-0737 Tech Specs."
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/11. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 33043:047-33043:053.

-8510170353 Proposed Tech Spec clarifying footnotes & correcting typos in Tech Spec Tables 3.2-H & 4.2-H re accident monitoring instrumentation, per Generic Ltr 83-36, "NUREG-0737 Tech Specs."
* Iowa Electric Light & Power Co. 85/10/11. 6pp. 33043:048-33043:053.

8510210020 Forwards proposal for satisfying ATWS rule (10CFR50.62). Areas addressed include alternate rod injection, standby liquid control & reactor coolant recirculation pump trip. Mods will be completed prior to Cycle 9 startup.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/14. DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 33074:105-33074:107.

8510310140 Provides results of startup test program conducted at beginning of Cycle 8, per Tech Spec 6.11.1. Listing of surveillances performed & status of startup while test performed encl.
MINECK, D.L. Iowa Electric Light & Power Co. 85/10/18. KEPPLER, J.G. Region 3, Office of Director. 6pp. 33290:351-33290:356.

Q. Inspection reports, IE Bulletins & correspondence

8510040255 Responds to violations noted in Insp Rept 50-331/85-15. Corrective actions/repairs made to outside control panel to restore & protect alarms & fusion change package work request initiated.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/09/06. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32851:108-32851:110.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint./Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510100181 Forwards Safety Insp Rept 50-331/85-28 on 850911-16 & notice of violation.
REYES, L.A. Region 3, Office of Director. 85/10/04. LIU, L. Iowa Electric Light & Power Co. 2pp. 32962:126-32962:137.

-8510100186 Notice of violation from insp on 850911-16.
REYES, L.A. Region 3, Office of Director. 85/10/04. 2pp. 32962:128-32962:129.

-8510100190 Insp Rept 50-331/85-28 on 850911-16. Violations noted: failure to adequately test containment penetration, control containment boundary & implement technically adequate procedures.
GULDEMOND, W.G., REYES, L.A. Region 3, Office of Director. 85/10/04. 8pp. 32962:130-32962:137.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PCR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACC 35, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230098 Forwards Press Release 84-34 re NRC proposed imposition of civil penalty in amount of \$20,000 against util for alleged violation of security requirements.
KAMMERER, C. Office of Congressional Affairs. 84/03/16. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:339-33108:340.

8510280001 Responds to violations noted in Insp Rept 50-331/85-24. Corrective actions/test procedures for six pumps temporarily revised & five potentially deficient tests successfully completed.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. 85/10/04. KEPPLER, J.G. Region 3, Office of Director. 3pp. 33194:301-33194:303.

8510100015 Confirms 851004 telcon re 851016 info meeting w/util in Glen Elyn, IL to address concerns expressed in recent insp repts on maint & personnel error problems at facility.
NORELIUS, C.E. Region 3, Office of Director. 85/10/07. LIU, L. Iowa Electric Light & Power Co. 1p. 32961:001-32961:001.

8510100027 Forwards Safety Insp Rept 50-331/85-21 on 850723-0916 & notice of violation.
CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/07. LIU, L. Iowa Electric Light & Power Co. 2pp. 32959:203-32959:224.

120 DOCKETED ITEMS

-8510100039 Notice of violation from insp on 850723-0916.
CHRISTOSIMOS,N. Region 3, Office of Director. 85/10/07. 2pp. 32959-205-32959-206.

-8510100051 Insp Rept 50-331/85-21 on 850723-0916 Violation noted fire watch not established since 850718 & plant operated for approx 7 h w/o establishing base line APRM noise levels on 850802.
WIEBE,J.S., MILBROT,W.E., HILAND,P.L. Region 3, Office of Director. 85/10/03. 18pp. 32959-207-32959-224.

8510160004 Forwards Safety Insp Rept 50-331/85-25 on 850909-20 & notice of violation.
HARRISON,J.J. Region 3, Office of Director. 85/10/09. LIU,L. Iowa Electric Light & Power Co. 2pp. 33027-164-33027-175.

-8510160007 Notice of violation from insp on 850909-20.
HARRISON,J.J. Region 3, Office of Director. 85/10/09. 1p. 33027-166-33027-166.

-8510160011 Insp Rept 50-331/85-25 on 850909-20 Violation noted failure to properly implement 8 h surveillance requirement & failure to meet intent of Tech Spec limiting control rod pattern requirements.
RESCHESKE,P.R., RING,M.A. Region 3, Office of Director. 85/10/09. 9pp. 33027-167-33027-175.

8510160264 Requests Rtr stating that listed facilities do not have fuel element transfer tubes Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineer in Charge, Generic Communications Branch. 4pp. 33023-351-33023-354.

8510280384 Responds to violations noted in Insp Rept 50-331/85-22. Corrective actions:radioactivity released to river estimated & personnel informed of correct interpretation of Paragraph 5 of App B to 10CFR20.
MCGAUGHY,R.W. Iowa Electric Light & Power Co. 85/10/10. KEPPLER,J.G. Region 3, Office of Director. 3pp. 33192-163-33192-165.

8510250210 Lists determinations based on review of util 850507 response to 850305 safeguards insp rept re use of armed responder for compensatory duties.Although members of response force may have other duties,primary duty must be response.
AXELSON,W.L. Region 3, Office of Director. 85/10/11. LIU,L. Iowa Electric Light & Power Co. 2pp. 33190-076-33190-077.

8510150022 IE Info Notice 85-080. "Timely Declaration of Emergency Class,Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081. "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082. "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510230144 Forwards Safety Insp Rept 50-331/85-17 on 850610-1003 & notice of violation.Concerns re corrective actions taken on excessively leaking containment isolation valves identified in rept.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/18. LIU,L. Iowa Electric Light & Power Co. 2pp. 33101-266-33101-277.

-8510230148 Notice of violation from insp on 850610-1003.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/18. 1p. 33101-268-33101-268.

-8510230154 Insp Rept 50-331/85-17 on 850610-1003.Violation noted: failure to perform as-found Type A test to determine containment structure.
HARE,S.M., GULDEMOND,W.G. Region 3, Office of Director. 85/10/17. 9pp. 33101-269-33101-277.

8510290078 Forwards Safety Insp Rept 50-331/85-26 on 850916-20 & 1007-10 & notice of violation.Response should include discussion of unresolved item re operational readiness or condition of equipment in plant.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/24. LIU,L. Iowa Electric Light & Power Co. 2pp. 33236-037-33236-056.

-8510290082 Notice of violation from insp on 850916-20 & 1007-10.
PAPERIELLO,C.J. Region 3, Office of Director. 85/10/24. 2pp. 33236-039-33236-040.

-8510290089 Insp Rept 50-331/85-26 on 850916-20 & 1007-10.Violations noted:failure to correct deficient flow transmitter & failure to control test equipment used to determine component operability.
ENG,P.L., GULDEMOND,W.G. Region 3, Office of Director. 85/10/23. 7pp. 33236-041-33236-056.

R. Periodic operating reports & related correspondence

8510310513 Forwards amend to semiannual effluent release rept for Jan-June 1985,consisting of changes for 850531 liquid release.
MINECK,D.L. Iowa Electric Light & Power Co. 85/09/27. KEPPLER,J. Region 3, Office of Director. 1p. 33279-344-33279-346.

-8510310519 Amend to semiannual effluent release rept for Jan-June 1985.
* Iowa Electric Light & Power Co. 85/06/30. 2pp. 33279-345-33279-346.

8510210289 Monthly operating rept for Sept 1985.W/851015 ltr.
THOMAS,B. MINECK,D.L. Iowa Electric Light & Power Co. 85/09/30. 8pp. 33095-082-33095-089.

S. Reportable occurrences, LERs & related correspondence

8510090283 LER 85-035-00 on 850904,RCIC sys declared inoperable when RCIC turbine tripped during manual start.Cause:by worn mechanical overspeed trip linkage sys.New turbine governor control box ordered.
PROBST,J.R., MINECK,D.L. Iowa Electric Light & Power Co. 85/10/02. 4pp. 32947-080-32947-083.

8510150432 LER 85-038-00 on 850906,both airlock doors inadvertently opened,violating secondary containment.On 850912,both standby gas treatment room doors opened simultaneously.Both events caused by inoperative solenoids.W/851004 ltr.
THOMAS,B. MINECK,D.L. Iowa Electric Light & Power Co. 85/10/04. 3pp. 33015-180-33015-182.

8510280396 LER 85-039-00 on 850918,RCIC-to-vessel inject valve BN-20-2512 failed to open on demand.Possibly caused by unnecessarily high setting of valve torque switch.Switch placed at lower setting.W/851018 ltr.
THOMAS,B. MINECK,D.L. Iowa Electric Light & Power Co. 85/10/18. 3pp. 33194-116-33194-118.

8510290405 LER 85-028-01 on 850720,RCIC sys tripped on overspeed while auto-starting during monthly/quarterly testing.Cause:by faulty flow controller & ramp generator operation.W/851018 ltr.
PROBST,J.R., MINECK,D.L. Iowa Electric Light & Power Co. 85/10/18. 4pp. 33243-001-33243-004.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-085.

-8510230098 Forwards Press Release 84-34 re NRC proposed imposition of civil penalty in amount of \$20,000 against util for alleged violation of security requirements.
KAMMERER,C. Office of Congressional Affairs. 84/03/16. OTTINGER,R.L. House of Rep. Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108-339-33108-340.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510210042 Notifies that written & oral exams for operator & senior operator licenses scheduled for wk of 851104.Requirements for administering exams encl.Applications should be submitted 60 days prior to first exam.
REYES,L.A. Region 3, Office of Director. 85/10/15. LIU,L. Iowa Electric Light & Power Co. 3pp. 33074-102-33074-104.

8510220279 Advises that 850930 request for certification exams for instructors cannot be supported at present.Persons that may be allowed to instruct until exams administered listed.
REYES,L.A. Region 3, Office of Director. 85/10/18. MCGAUGHY,R.W. Iowa Electric Light & Power Co. 1p. 33087-346-33087-346.

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8510010340 Responds to NRC 850821 ltr re violations noted in Insp Rept 50-333/85-20 Corrective actions:spare conduit penetrations in fire-rated barriers of control room cable spreading room & relay room sealed w/fire-rated seal not less than 3 h.
CONVERSE,J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/09/20. EBNETER,S. Region 1, Office of Director. 6pp. 32801-266-32801-271.

8510220105 Rev 1 to Emergency Plan Implementing Procedure SAP-10. "Meteorological Monitoring Sys Surveillance."
MULCAHEY,E. New York Power Authority (formerly Power Authority of the State of New York). 85/10/09. 17pp. 33081-340-33081-356.

8510220191 Forwards response to questions raised during 850905 telcon re util 851206 proposed changes to Tech Specs,per NUREG-0737.Justification of discrepancies between proposal & guidance of Generic Ltr 83-36 provided.
BRONS,J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/18. VAISALLO,D.B. Operating Reactors Branch 2. 5pp. 33087-317-33087-321.

8510310019 Grants extension of completion date for submittal of NUREG-0737,Suppl 1,Item 2.b re DCRDR summary rept,from 851115 to 860228,per 850807 request.Extension will not impact overall completion schedule.
THOMPSON,H.L. Division of Licensing. 85/10/23. BRONS,J.C. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 33277-130-33277-131.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510210164 Summary of ACRS Class 9 Accidents Subcommittee 850314 meeting w/ PASNY & Risk Mgt Assoc in Washington,DC re recent source term assessment under severe accident conditions.

* ACRS - Advisory Committee on Reactor Safeguards. 85/03/31. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 33094-210-33094-213.

P. Operating license stage documents & correspondence

8510010012 Forwards exemption from requirements of 10CFR50, App J, Paragraph III.D.2(b)(ii) re performance of seal leakage test in lieu of full pressure test prior to restoring containment integrity when airlock doors opened.
VASSALLO, D.B. Operating Reactors Branch 2. 85/09/18. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 32833:194-32833:199.

8510010014 Exemption from requirements of 10CFR50, App J, Paragraph III.D.2(b)(ii) re performance of seal leakage test in lieu of full pressure test prior to restoring containment integrity when airlock doors opened.
THOMPSON, H.L. Division of Licensing. 85/09/18. New York Power Authority (formerly Power Authority of the State of New York). 4pp. 32833:196-32833:199.

8510030018 Forwards "Piping Analysis/Pipe Support Design, Third-Party Review for JA Fitzpatrick Nuclear Power Plant," final rept. Rept prepared to investigate allegations re adequacy of pipe supports.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 3pp. 32842:330-32842:333.

8510030026 "Piping Analysis/Pipe Support Design, Third-Party Review for JA Fitzpatrick Plant," final rept.
BARTON, R.W. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 85/08/30. 28pp. 32842:333-32843:003.

8510040213 Forwards application for amend to License DPR-59, changing Tech Spec Section 6.5 to clarify fact that plant operating review committee is review group, not audit & review group. Fee paid.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 32851:050-32851:057.

8510040221 Application for amend to License DPR-59, changing Tech Spec Section 6.5 to clarify fact that plant operating review committee performs review, not audit function.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/01. 1p. 32851:052-32851:052.

8510040226 Proposed Tech Spec Section 6.5, clarifying fact that plant review committee is review group, not audit group.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/01. 5pp. 32851:053-32851:057.

8510180310 Submits plan & implementation schedule in accordance w/ 10CFR50.62, "Requirements for Reduction of Risk From ATWS Events for Light-Water-Cooled Nuclear Power Plants." Detailed description of conceptual design encl.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. VASSALLO, D.B. Operating Reactors Branch 2. 9pp. 33060:358-33061:004.

8510220347 Forwards application for amend to License DPR-59, changing Tech Specs to permit reactor operation w/ single recirculation loop in svc.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 33084:182-33084:231.

8510220349 Application for amend to License DPR-59, changing Tech Specs to permit reactor operation w/ single recirculation loop in svc.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. 1p. 33084:184-33084:184.

8510220352 Proposed Tech Spec changes, allowing reactor operation w/ single recirculation loop in svc.
* New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. 48pp. 33084:185-33084:231.

8510220191 Forwards response to questions raised during 850905 telcon re util 851206 proposed changes to Tech Specs per NUREG-0737. Justification of discrepancies between proposal & guidance of Generic Ltr 83-36 provided.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/18. VASSALLO, D.B. Operating Reactors Branch 2. 5pp. 33087:317-33087:321.

8510240177 Requests extensions until 851115 & 1201 for submitting inservice test program for second 10-yr interval & response to safety evaluation, respectively, due to outage-related work which must be completed before program.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/10/21. VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 33155:240-33155:241.

Q. Inspection reports, IE Bulletins & correspondence

8510010340 Responds to NRC 850821 ltr re violations noted in Insp Rept 50-333/85-20. Corrective actions: spare conduit penetrations in fire-rated barriers of control room cable spreading room & relay room sealed w/ fire-rated seal not less than 3 h.
CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 85/09/20. EBNETER, S. Region 1, Office of Director. 6pp. 32801:266-32801:271.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510040149 Forwards Safety Insp Rept 50-333/85-22 on 850715-0831. No violation noted.
COLLINS, S.J. Region 1, Office of Director. 85/09/30. CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 32851:002-32851:018.

8510040161 Insp Rept 50-333/85-22 on 850715-0831. No violation noted. Major areas inspected: LER review, operations; safety verification, surveillance observations, maint observations & followup on plan. tips.
LINVILLE, J.C. Region 1, Office of Director. 85/09/28. 13pp. 32851:004-32851:016.

8510040464 Forwards Safety Insp Rept 50-333/85-24 on 850819-23. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/09/30. CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 32854:002-32854:013.

8510040466 Insp Rept 50-333/85-24 on 850819-23. No violations noted. Major areas inspected: radwaste mgmt program & improvements to post-accident sampling sys, including mgmt control, training & liquid waste processing.
MILLER, M.T., HOLSOPE, K., PASCIAK, W. Region 1, Office of Director. 85/09/24. 10pp. 32854:004-32854:013.

8510100033 Forwards Rev 0 to "Inservice Insp Program for Welds & Supports, Second Interval" & piping weld & support listing. Program applicable for 10-yr interval beginning 850728. W/36 oversize drawings.
BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85/09/30. VASSALLO, D.B. Operating Reactors Branch 2. 4pp. 32967:168-32968:127.

8510100046 Rev 0 to "Inservice Insp Program for Welds & Supports, Second Interval." Piping weld & support listing for inservice insp program encl.
PERRY, R., SANCIC, D., DOUGHERTY, T. New York Power Authority (formerly Power Authority of the State of New York). 85/08/16. 350pp. 32967:173-32968:127.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFF, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510180010 Forwards Insp Rept 50-333/85-23 on 850910-12. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/11. CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 33177:330-33177:333.

8510180018 Insp Rept 50-333/85-23 on 850910-12. No violations noted. Major areas inspected: nonradiological chemistry program, including measurement control & analytical procedure evaluations.
ZIBULSKY, H., PASCIAK, W.J. Region 1, Office of Director. 85/10/08. 5pp. 33026:329-33026:333.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250162 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-333/85-20.
EBNETER, S.D. Region 1, Office of Director. 85/10/18. CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 33173:168-33173:175.

R. Periodic operating reports & related correspondence

8510150038 "Radiological Environ Surveillance Rept" for 1984 W/850328 ltr.
GLOVER, H.A. New York Power Authority (formerly Power Authority of the State of New York). 84/12/31. MURLEY, T.E. Region 1, Office of Director. 173pp. 33014:228-33015:039.

8510150312 Monthly operating rept for Sept 1985. W/851007 ltr.
COOK, J., CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 85/09/30. 10pp. 33009:056-33009:065.

S. Reportable occurrences, LERs & related correspondence

8510280151 LER 85-020-01 on 850725. HPCI sys inoperable due to isolation of HPCI steam line. Caused by high ambient temps that shut down & isolated normal reactor bldg ventilation sys. Temp setpoint increased. Procedure reviewed W/851016 ltr.
WALZ, V.M., CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 85/10/15. 4pp. 33194:226-33194:229.

8510280403 Forwards corrected LER 85-024-00. Ltr dtd 851011 incorrectly referenced LER 85-023-00.
CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 85/10/15. Record Services Branch (Document Control Desk). 1p. 33194:104-33194:107.

8510280404 LER 85-024-00 on 850913. Containment analyzers A & B appeared beyond Tech Specs in nonconservative direction. Caused by misleading surveillance procedure. Sample gas method discontinued in favor of software data point analysis.
FLAHERTY, J.P. New York Power Authority (formerly Power Authority of the State of New York). 85/10/11. 3pp. 33194:105-33194:107.

122 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510020105 "1985 Annual Emergency Preparedness Exercise" on 850918-20.
SIEBER, J.D. Duquesne Light Co. 85/09/18. 618pp. 32839-253-32841-150.

8510180184 Forwards comments re review of util public info brochures. Info packet reviewed against NUREG-0654 requirements & determined to meet guidelines.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/06. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33021-243-33021-245.

8510210239 Forwards review comments re info packet, "Important Emergency Info." Info packet adequately meets requirements of NUREG-0654/FEMA REP-1 Rev 1.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/06. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33079-337-33079-339.

8510230009 Forwards "Updated Fire Protection App R Review." Vols 1 & 2. Correspondence summary listing also encl.
CAREY, J.J. Duquesne Light Co. 85/10/16. VARGA, S.A. Operating Reactors Branch 1. 4pp. 33145-188-33149-010.

-8510230011 "Updated Fire Protection App R Review." Vols 1 & 2 W/48 oversize figures.
* Duquesne Light Co. 85/09/30. 120pp. 33145-192-33149-010.

8510220124 Forwards Insp Rept 50-334/85-19 on 850917-20. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. CAREY, J.J. Duquesne Light Co. 2pp. 33090-141-33090-148.

-8510220133 Insp Rept 50-334/85-19 on 850917-20. No violation noted. Major areas inspected: status of changes to emergency program & participation in 850919 emergency exercise.
VITO, D.J., SMITH, R.H., HARPSTER, T.L. Region 1, Office of Director. 85/10/15. 6pp. 33090-143-33090-148.

P. Operating license stage documents & correspondence

8510310083 Forwards safety evaluation accepting 850617 response to Salem ATWS items 4.2.1 & 4.2.2 re 18-month surveillance frequency for reactor trip breakers.
VARGA, S.A. Operating Reactors Branch 1. 85/10/08. CAREY, J.J. Duquesne Light Co. 3pp. 33277-294-33277-298.

-8510310092 Safety evaluation accepting util 850617 response to Generic Ltr 83-28, Items 4.2.1 & 4.2.2 re 18-month preventive maint frequency for reactor trip breakers.
* Office of Nuclear Reactor Regulation, Director. 85/10/08. 2pp. 33277-297-33277-298.

8510310088 Forwards supplemental safety evaluation accepting 850114 & 0510 responses to Generic Ltr 83-28, Item 4.3 on proposed design mods for automatic shunt trip Tech Spec changes should be submitted.
VARGA, S.A. Operating Reactors Branch 1. 85/10/09. CAREY, J.J. Duquesne Light Co. 4pp. 33277-294-33277-290.

-8510310087 Supplemental safety evaluation accepting 850510 response to Generic Ltr 83-28, Item 4.3 re design for automatic actuation of reactor trip breaker shunt trip attachments. Proposed Tech Specs requested per Generic Ltr 85-09.
* NRC - No Detailed Affiliation Given. 85/10/09. 3pp. 33277-288-33277-290.

8510240002 Requests extension for providing addl info requested in 850822 ltr on NUREG-0737, Item I.D.1, "Testing of Safety Relief Valves." Response to Questions 1-6 will be provided by 851115.
CAREY, J.J. Duquesne Light Co. 85/10/14. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33155-189-33155-190.

8510310007 Forwards draft "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, Item 12, 'Post-Trip Review Data & Info Capabilities' for Beaver Valley Power Station Unit 1," technical evaluation rept addl info required.
VARGA, S.A. Operating Reactors Branch 1. 85/10/17. CAREY, J.J. Duquesne Light Co. 3pp. 33277-112-33277-129.

-8510310011 Draft "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2 'Post-Trip Review Data...' technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-1. DRFT. 85/10/17. NRC - No Detailed Affiliation Given. 15pp. 33277-115-33277-129.

Q. Inspection reports, IE Bulletins & correspondence

8509180247 Requests "hat listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. CAREY, J.J. Duquesne Light Co. 11pp. 32854-327-32854-337.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230182 Forwards Press Release 85-43 re NRC proposed fine against util concerning alleged failure to maintain integrity of sys that prevents release of radioactivity into environ.
KAMMERER, C. Office of Congressional Affairs. 85/03/20. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109-082-33109-084.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510240058 Remits insp fee assessed for period of 841223-850330, in accordance w/ 850923 Invoice 1602V.
VASSELLO, J.V. Duquesne Light Co. 85/10/17. Division of Accounting & Finance. 1p. 33155-257-33155-257.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510220124 Forwards Insp Rept 50-334/85-19 on 850917-20. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. CAREY, J.J. Duquesne Light Co. 2pp. 33090-141-33090-148.

-8510220133 Insp Rept 50-334/85-19 on 850917-20. No violation noted. Major areas inspected: status of changes to emergency program & participation in 850919 emergency exercise.
VITO, D.J., SMITH, R.H., HARPSTER, T.L. Region 1, Office of Director. 85/10/15. 6pp. 33090-143-33090-148.

8510250454 Forwards Safety Insp Rept 50-334/85-21 on 850923-27. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. CAREY, J.J. Duquesne Light Co. 2pp. 33173-038-33173-045.

-8510250465 Insp Rept 50-334/85-21 on 850923-27. No violations identified. Major areas inspected: radiation safety program, including mgt controls, training, instrument calibr & maint, posting, labeling & control of areas & QA audits.
MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/10/18. 8pp. 33173-038-33173-045.

8510290050 Responds to 850913 ltr re General Physics Corp training course that appeared to condone practices that could be misleading to NRC insp program. Suggested actions implemented. Util policy statement encl.
CAREY, J.J. Duquesne Light Co. 85/10/23. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 14pp. 33236-143-33236-156.

R. Periodic operating reports & related correspondence

8510620239 Monthly operating rept for Jul 1985 W/850806 ltr.
SMITH, P.A., CAREY, J.J. Duquesne Light Co. 85/07/31. 7pp. 32827-171-32827-177.

8510010476 "NPDES Discharge Monitoring Rept for Aug 1985." W/850927 ltr.
DEVOS, D.H. Duquesne Light Co. 85/08/31. VARGA, S. Operating Reactors Branch 1. 23pp. 32809-148-32809-170.

S. Reportable occurrences, LERs & related correspondence

8510150221 LER 85-015-00 on 850829, safety injection actuation & reactor trip occurred. Caused by loss of station instrument air pressure resulting from failed solder fitting on instrument air sys. Equipment repaired W/850926 ltr.
DRUGA, R.J., LACEY, W.S. Duquesne Light Co. 85/09/26. MURLEY, T.E. Region 1, Office of Director. 6pp. 33015-042-33015-047.

8510170452 LER 85-013-01 on 850706, reactor trip on lo-lo steam generator level occurred. Caused by fault in steam dump control circuitry. Faulted component replaced W/851003 ltr.
DRUGA, R.J., LACEY, W.S. Duquesne Light Co. 85/10/03. MURLEY, T.E. Region 1, Office of Director. 4pp. 33053-245-33053-248.

8510240254 Potential Part 21 rept re pipe snubber brackets mfg from matts less than specified by design drawings. Brackets shipped to facility. SAW requested to return brackets. Investigation incomplete.
FISHER, R.C. Paul-Munroe Hydraulics, Inc. 85/10/09. YOUNG, T. Region 1, Office of Director. 1p. 33154-304-33154-304.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

—8510230182 Forwards Press Release 85-43 re NRC proposed fine against utility concerning alleged failure to maintain integrity of sys that prevents release of radioactivity into environ.
KAMMERER, C. Office of Congressional Affairs. 85/03/20. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109-082-33109-084.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510250454 Forwards Safety Insp Rept 50-334/85-21 on 850923-27 No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/18. CAREY, J.J. Duquesne Light Co. 2pp. 33173-036-33173-045.

—8510250465 Insp Rept 50-334/85-21 on 850923-27 No violations identified. Major areas inspected: radiation safety program, including mgt controls, training, instrument calibr & maint, posting, labeling & control of areas & QA audits.
MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/10/18. 8pp. 33173-036-33173-045.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080279 Forwards Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20 No deviations or violations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/03. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 32918-359-32918-360.

—8510080288 Physical Security Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20 No violations noted. Major areas inspected: mgt effectiveness & security program. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS, J.D., MCGUIRE, D.R. Region 2, Office of Director. 85/10/01. 1p. 32918-361-32918-361.

8510150324 Revised emergency plan implementing procedures, including 1101, "Duties of Emergency Control Officer, Offsite Emergency Organization" & 1102, "Duties of Recovery Manager, Offsite Emergency Organization." W/851004 ltr.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. GRACE, J.N. Region 2, Office of Director. 51pp. 33009-001-33009-051.

8510150385 Rev 5 to Emergency Plan Implementing Procedure 3100034E, "Maintaining Emergency Preparedness - Radiological Emergency Plan Training." W/851004 ltr.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. GRACE, J.N. Region 2, Office of Director. 9pp. 33010-156-33010-164.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21 No violations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/04. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33096-332-33096-335.

—8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21 No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY, W. Region 2, Office of Director. 85/09/26. 2pp. 33096-334-33096-335.

8510180426 Forwards Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923 No violations or deviations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/09. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33056-329-33056-338.

—8510180429 Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923 No violation or deviation noted. Major areas inspected: Tech Spec compliance, operator performance, QA practices & site security procedures.
CRILENIAK, R.V., BIBB, H.E., ELROD, S.A. Region 2, Office of Director. 85/10/08. 8pp. 33056-331-33056-338.

P. Operating license stage documents & correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982 per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L. Government Accountability Project. 32pp. 32884-005-32884-234.

—8510020191 Rev 0 to Procedure 753-ET-1, "Environ Test Plan for Device Qualification to IEEE 323-1971."
MARROW, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/09/15. 6pp. 32890-035-32890-040.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co. Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031-135-33031-150.

8510100108 Requests approval to use alternative insp technique to satisfy inservice pressure testing requirements of ASME Code. Instrumented insp technique can be implemented on listed sys.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. THOMPSON, H.L. Division of Licensing. 2pp. 32960-105-32960-106.

8510180087 Forwards response to 850429 request for addl info on Generic Ltr 83-28, item 1.1 re post-trip review. Revised procedures re post-trip review & responsibilities of shift technical advisor encl.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/11. BUTCHER, E.J. Operating Reactors Branch 3. 3pp. 33063-122-33063-155.

—8510180090 Rev 2 to Operating Procedure 0030119, "Post-Trip Review."
BARROW, J.H., SAGER, D.A. Florida Power & Light Co. 85/06/26. 13pp. 33063-125-33063-137.

—8510180096 Rev 6 to Procedure 0005725, "Duties & Responsibilities of Shift Technical Advisor."
BARROW, J.H., SAGER, D.A. Florida Power & Light Co. 85/07/03. 19pp. 33063-138-33063-155.

8510180070 Informs that utility will provide NRC w/compliance schedule for ATWS rule 90 days after NRC review of C-E Owners Group approach.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33063-093-33063-093.

8510230123 Forwards addl info in response to Generic Ltr 85-02 re Category C-2 steam generator tube insp. insp program in compliance w/expanded insp requirements of C-2 Addl tubes inspected on case-by-case basis.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/16. THOMPSON, H.L. Division of Licensing. 2pp. 33102-210-33102-211.

8510230019 Application for amend to License DPR-67, changing linear heat rate limiting condition for operation from constant value to represent axially dependent limit for all fuel in core. Fee paid.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/17. THOMPSON, H.L. Division of Licensing. 7pp. 33101-278-33101-290.

—8510230022 Proposed Tech Specs, changing linear heat rate limiting condition for operation from constant value to represent axially dependent limit for all fuel in core.
* Florida Power & Light Co. 85/10/17. 6pp. 33101-285-33101-290.

8510240173 Advises that utility will provide response to NRC 850621 & 0711 requests for info re relief & safety valve test requirements per TMI item I.D.1 by 860315.
WILLIAMS, J.N. Florida Power & Light Co. 85/10/18. BUTCHER, E.J. Operating Reactors Branch 3. 1p. 33155-265-33155-265.

8510290307 Application for amend to License DPR-67, changing Tech Specs to support installation of safety-grade automatic feedwater sys during upcoming refueling outage. Fee paid.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/22. THOMPSON, H.L. Division of Licensing. 3pp. 33236-249-33236-267.

—8510290314 Proposed Tech Specs supporting installation of safety-grade automatic feedwater sys during upcoming refueling outage.
* Florida Power & Light Co. 85/10/22. 16pp. 33236-252-33236-267.

8510310523 Advises of completion of review of utility 831108 response to Generic Ltr 83-28, items 3.13 & 3.2.3. Post-maint test requirement reviews should be factored into future Tech Spec changes to assure level of safety not degraded.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/25. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33278-352-33278-353.

Q. Inspection reports, IE Bulletins & correspondence

8510180091 Forwards Insp Repts 50-335/85-23 & 50-389/85-23 on 850826-30 No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/20. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33054-134-33054-142.

—8510180103 Insp Repts 50-335/85-23 & 50-389/85-23 on 850826-30 No violation or deviation noted. Major areas inspected: plant chemistry & inservice testing of pumps & valves.
ROSS, W.J., BLAKE, J.J. Region 2, Office of Director. 85/09/17. 7pp. 33054-136-33054-142.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080279 Forwards Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20 No deviations or violations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/03. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 32918-359-32918-360.

—8510080288 Physical Security Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20 No violations noted. Major areas inspected: mgt effectiveness & security program. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS, J.D., MCGUIRE, D.R. Region 2, Office of Director. 85/10/01. 1p. 32918-361-32918-361.

8510100108 Requests approval to use alternative insp technique to satisfy inservice pressure testing requirements of ASME Code. Instrumented insp technique can be implemented on listed sys.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. THOMPSON, H.L. Division of Licensing. 2pp. 32960-105-32960-106.

8510180178 Responds to NRC ltr re violations noted in Insp Repts 50-335/85-20 & 50-389/85-20. Corrective actions engineering requested to examine circuit changes which allow ground chucks w/o effect on plant operations.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/04. GRACE, J.N. Region 2, Office of Director. 2pp. 33059-342-33059-343.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21 No violations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/04. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33096-332-33096-335.

—8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21 No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY, W., CUNNINGHAM, A.L. Region 2, Office of Director. 85/09/26. 2pp. 33096-334-33096-335.

124 DOCKETED ITEMS

8510180426 Forwards Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violations or deviations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/09. WILLIAMS, J.W. Florida Power & Light Co. 2pp. 33056:329-33056:338.

-8510180429 Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violation or deviation noted. Major areas inspected: Tech Spec compliance, operator performance, QA practices & site security procedures.
CRLENJAK, R.V., BIBB, I.E., ELROD, S.A. Region 2, Office of Director. 85/10/08. 8pp. 33056:331-33056:338.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510230123 Forwards addl info in response to Generic Ltr 85-02 re Category C-2 steam generator tube insps. Insp program in compliance w/expanded insp requirements of C-2 Addl tubes inspected on case-by-case basis.
WILLIAMS, J.W. Florida Power & Light Co. 85/10/16. THOMPSON, H.L. Division of Licensing. 2pp. 33102:210-33102:211.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010477 Monthly operating repts for Jul 1985. W/850814 ltr.
GRANT, N.W., WILLIAMS, J.W. Florida Power & Light Co. 85/07/31. 18pp. 32809:082-32809:099.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510100163 Rev to 850528 application to amend License DPR-65, adding continuous or hourly fire watch patrol until temporary or inoperable fire barrier permanently repaired. Determinations re 10CFR50, App R still applicable.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. MILLER, J.R. Operating Reactors Branch 3. 2pp. 32962:005-32962:009.

-8510100174 Proposed rev to Tech Spec 3/4.7.10, adding continuous or hourly fire watch patrol until temporary or inoperable fire barrier permanently repaired.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. 3pp. 32962:007-32962:009.

8510110074 Forwards FEMA 850829 ltr & rept of 841012 exercise. Category B deficiencies observed at exercise do not detract from public protection. State of CT preparing schedule of corrective actions.
HARPSTER, T.L. Region 1, Office of Director. 85/10/04. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32973:028-32973:117.

8510150284 Corporate organization for nuclear incidents procedures, including Rev 10 to CONI-4.02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines." W/851009 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Utilities. 85/10/09. 171pp. 33009:113-33009:285.

8510230219 Forwards sections of State of CT radiological emergency response plan re medical svcs & similar sections from local plans within 10 mile emergency planning zone.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/18. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 150pp. 33100:216-33100:026.

8510280201 Informs that 850812 amend application denied since Northeast Utils did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

P. Operating license stage documents & correspondence

8510100163 Rev to 850528 application to amend License DPR-65, adding continuous or hourly fire watch patrol until temporary or inoperable fire barrier permanently repaired. Determinations re 10CFR50, App R still applicable.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. MILLER, J.R. Operating Reactors Branch 3. 2pp. 32962:005-32962:009.

-8510100174 Proposed rev to Tech Spec 3/4.7.10, adding continuous or hourly fire watch patrol until temporary or inoperable fire barrier permanently repaired.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. 3pp. 32962:007-32962:009.

8510100166 Advises that required submittal of summary technical rept of containment bldg leak rate test delayed until 851101 due to consideration of implications of IE Info Notice 85-71, "Containment Integrated Leak Rate Test."
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. BUTCHER, E.J. Operating Reactors Branch 3. 1p. 32962:222-32962:222.

8510080558 Forwards Amend 105 to License DPR-65 & safety evaluation. Amend corrects typo on Figure 3.2.2a of Tech Specs.
OSBORNE, D.B. Operating Reactors Branch 3. 85/10/03. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32925:213-32925:221.

-8510080560 Amend 105 to License DPR-65, correcting typo on Figure 3.2.2a of Tech Specs re axial shape index vs fraction of allowable power level.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/03. 5pp. 32925:215-32925:218.

-8510080562 Safety evaluation supporting Amend 105 to License DPR-65.
* Office of Nuclear Reactor Regulation, Director. 85/10/03. 3pp. 32925:219-32925:221.

8510090507 Forwards Structural & Geotechnical Engineering Branch request for addl info to complete review of 850724 application to modify Tech Specs re spent fuel storage capacity expansion.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/03. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 7pp. 32966:188-32966:194.

8510280370 Forwards "Startup Test Rept, Cycle 7." Criticality achieved on 850630 & 100% power reached on 850711 following end-of-cycle 6 refueling outage.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/04. MURLEY, T.E. Region 1, Office of Director. 1p. 33192:096-33192:112.

-8510280375 "Startup Test Rept, Cycle 7."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/31. 16pp. 33192:097-33192:112.

8510220158 Submits ATWS rule schedule required by 10CFR50.62(d), per Generic Ltr 85-06. Facilities participating in NRC Integrated Safety Assessment Program. Justification for absence of schedules for Haddam Neck & Millstone Unit 1 provided.
OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/11. BUTCHER, E.J. Operating Reactors Branch 3. ZWOLINSKI, J.A. Operating Reactors Branch 5. 7pp. 33090:076-33090:082.

8510290300 Forwards Change 1, Rev 5 to Procedure OF2347B, "Normal Station Svc Transformer 15G-2S (NSST)." Encl change suppls 841204 submittal re procedures for degraded grid voltage.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/16. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33239:145-33239:166.

-8510290308 Change 1 to Rev 5 to Procedure OP2347B, "Normal Station Svc Transformer 15G-2S (NSST)."
KEENAN, J.S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/08/15. 20pp. 33239:147-33239:166.

8510280201 Informs that 850812 amend application denied since Northeast Utils did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33228:237-33228:243.

-8510280219 Safety evaluation denying util 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228:241-33228:243.

Q. Inspection reports, IE Bulletins & correspondence

8510030227 Forwards Special Dosimetry Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09 Status of planning during operational phase for dosimetry needs reviewed. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/09/17. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32845:139-32845:150.

-8510030235 Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09. No violations identified. Major areas inspected: personnel selection, facilities & equipment, dose assessment, QA, documentation & recordkeeping & organization.
CIOFFI, J.A., JANG, J., SHANBAKY, M. Region 1, Office of Director. 85/09/11. 10pp. 32845:141-32845:150.

8510080593 Ack receipt of 850906 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-245/85-16 & 50-336/85-22.
EBNETER, S.D. Region 1, Office of Director. 85/09/27. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32927:033-32927:036.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510100166 Advises that required submittal of summary technical rept of containment bldg leak rate test delayed until 851101 due to consideration of implications of IE Info Notice 85-71, "Containment Integrated Leak Rate Test."
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. BUTCHER, E.J. Operating Reactors Branch 3. 1p. 32962-222-32962-222.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510230138 Forwards Safety Insp Rept 50-336/85-29 on 850819-23 No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/18. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33102-016-33102-033.

-8510230143 Insp Rept 50-336/85-29 on 850819-23 No noncompliance identified. Major areas inspected: startup testing following refueling of Cycle 7, including test program, pre-critical tests, low power physics tests & power ascension tests.
WEN, P.C., CHEH, U., ESELGROTH, P.W. Region 1, Office of Director. 85/10/09. 16pp. 33102-018-33102-033.

8510280201 Informs that 850812 amend application denied since Northeast Utilis did not establish that group performing fire protection audits qualifies as outside firm, per Generic Ltr 82-21. Safety evaluation encl.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/21. OPEKA, J.F. Connecticut Yankee Atomic Power Co. 4pp. 33228-237-33228-243.

-8510280219 Safety evaluation denying until 850812 application to amend Tech Specs to permit qualified offsite licensee personnel or independent consultant to perform fire protection audit. Generic Ltr 82-21 should be utilized.
Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33228-241-33228-243.

R. Periodic operating reports & related correspondence

8510020078 Monthly operating rept for Jul 1985. W/850814 ltr.
NERON, G., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/07/31. 17pp. 32827-279-32827-295.

S. Reportable occurrences, LERs & related correspondence

8510020274 PNO-I-85-071A on 850927, Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage.
STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825-232-32825-232.

8510080042 PNO-I-85-073 on 851001, unit placed in cold shutdown after ground fault found in reactor coolant pump motor Pump motor will be removed to allow unit & GE to determine whether fault accessible.
SHEDLOSKEY, J.T., MCCABE, E.C. Region 1, Office of Director. 85/10/02. 1p. 32913-294-32913-294.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

8510170051 LER 84-012-01 on 841112, reactor tripped to protect turbine from water due to steady rise in level in feedwater heater 5A. Caused by leak in heater Check valves 2FW-5A & 2FW-5B inspected & reworked during refueling outage. W/851007 ltr.
BRINKMAN, S., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/07. 3pp. 33052-123-33052-125.

8510310402 LER 85-014-00 on 850927, orderly shutdown commenced as precautionary measure due to Hurricane Gloria. Grounding problems caused unit to divorce from off-site power. Unit returned to normal hot shutdown condition W/851025 ltr.
MCNATT, E.M., ROMBERG, W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). ROMBERG, W.D. Northeast Utilities. 85/10/25. 4pp. 33280-297-33280-300.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510070360 Rev 3 to "Corporate Emergency Response Plan," for Third Quarter 1985. W/850927 ltr.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/08/29. GRACE, J.N. Region 2, Office of Director. 90pp. 32875-036-32875-125.

8510040082 Forwards Rev 14 to security program. Encl withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 1p. 32851-024-32851-024.

8510040137 Forwards Revs 8 & 9 to security personnel training & qualification programs for North Anna & Surry, respectively & response to NRC 850724 comments. Encls withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32851-208-32851-209.

8510150249 Requests assistance in reviewing encl until 841102, 850505 & 0919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively.
THOMPSON, H.L. Division of Licensing. 85/10/04. WALKER, R.D. Region 2, Office of Director. 2pp. 33032-236-33032-299.

8510160094 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-338/85-20 & 50-339/85-20.
GRACE, J.N. Region 2, Office of Director. 85/10/11. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 33027-359-33027-360.

-8510160104 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. Corrective actions withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/26. GRACE, J.N. Region 2, Office of Director. 1p. 33027-360-33027-360.

8510210122 Requests extension to complete commitments for Reg Guide 1.97 & Suppl 1 to NUREG-0737 re SPDS, in response to 840614 confirmatory order. Several items cannot be completed before resuming power operation.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 6pp. 33072-243-33072-248.

8510280372 Advises of mod of 840914 request for schedular exemption from 10CFR50, App R, changing completion dates for encl mods from 1985 refueling outages to next refueling outage.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 3pp. 33192-113-33192-115.

G. Adjudicatory correspondence

8510110028 Order stating that ASLB 850903 initial decision authorizing NRR to amend OL to permit receipt & storage of spent fuel should not be deemed final, pending further order. Served on 851009.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 722. 85/10/09. 2pp. 32973-231-32973-232.

8510110152 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
HASSELL, D.F. Hearing Branch 2. #485 738. 85/10/09. 3pp. 32999-347-32999-349.

8510220240 Forwards notice of withdrawal of appearance in proceeding. Requests svc list be revised to include client under listed address. W/o encl.
DOUGHERTY, J.B. Dougherty, J.B. DOUGHERTY, J.B. Concerned Citizens of Louisiana County. #485 846. 85/10/18. Office of the Secretary of the Commission. 1p. 33087-203-33087-203.

8510220264 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
DOUGHERTY, J.B. Concerned Citizens of Louisiana County. #485 861. 85/10/18. 2pp. 33085-097-33085-098.

J. Insurance & indemnity information

8510080180 Forwards Endorsements 79 & 60 to NELIA Policy NF-186 & MAELU Policy MF-57, respectively.
INGLES, J.M. Marsh & McLennan, Inc. 85/09/25. DINITZ, I. Office of Nuclear Reactor Regulation, Director. 3pp. 32922-076-32922-078.

P. Operating license stage documents & correspondence

8510010451 Application for amends to Licenses NPF-4 & NPF-7, changing Tech Spec Section 4.7.10 re surveillance requirements for snubbers. Change would modify portions of visual insp acceptance criteria. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 3pp. 32804-079-32804-092.

-8510010456 Proposed changes to Tech Spec Section 4.7.10 re surveillance requirements for snubbers, modifying portions of visual insp acceptance criteria.
Virginia Power (Virginia Electric & Power Co.). 85/09/24. 11pp. 32804-082-32804-092.

8510070361 Grants interim relief from inservice testing requirements of ASME Code pending completion of detailed review, per 841231 request for interim approval re inservice insp & testing for pumps & valves.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 32901-275-32901-278.

126 DOCKETED ITEMS

- 85100540** Forwards request for addl info re 850830 updated QA Topical Rept VEP-1-4A necessary for completion of evaluation of program changes. WALKER,R.D. Region 2, Office of Director. 85/10/01. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 33068:253-33068:256.
- 8510080153** Forwards response to 850624 request for addl info re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1 & 3.2.2. Administrative procedure will have step to ack that review performed to determine if post-maint testing required. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 5pp. 32922:079-32922:083.
- 8510150249** Requests assistance in reviewing encl util 841102, 850505 & 0919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively. THOMPSON,H.L. Division of Licensing. 85/10/04. WALKER,R.D. Region 2, Office of Director. 2pp. 33032:236-33032:299.
- 8510180015** Requests encl notice of consideration of issuance of amendments to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing re 850919 application be forwarded for FR publication. ENGLE,L.B. Operating Reactors Branch 3. 85/10/04. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33069:344-33069:345.
- 8510180016** Notice of consideration of issuance of amendments to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing. Amend adds statement to Surveillance Requirement 4.7.10 re early insp of snubbers. ENGLE,L.B. Operating Reactors Branch 3. 85/10/04. 8pp. 33069:346-33069:353.
- 8510170074** Forwards VEP-NE-2, "Statistical DNBR Evaluation Methodology." Rept describes methodology for statistically treating several important uncertainties in DNBR analysis & replaces deterministic methodology. Fee paid. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON,H.L. Division of Licensing. 2pp. 33036:252-33036:320.
- 8510170079** "Statistical DNBR Evaluation Methodology." ANDERSON,R.C., BASEHORE,K.L., BERRYMAN,R.M. Virginia Power (Virginia Electric & Power Co.). VEP-NE-2. 85/07/31. 67pp. 33036:254-33036:320.
- 8510180151** Advises that proposed schedule for meeting requirements for ATWS mitigation sys per 10CFR50.62(d) & Generic Ltr 85-06, will be completed by end of First Quarter 1986. ATWS mitigation sys of vendors under evaluation. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON,H.L. Division of Licensing. 3pp. 33055:035-33055:037.
- 8510280324** Forwards core surveillance rept containing specific power distribution limits applicable for Cycle 6 operation. No unreviewed safety question will exist as result of Cycle 6 reload core. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 6pp. 33193:085-33193:090.
- 8510280118** Advises that analysis data vs plant performance data re 11 motor-operated valves rerate procedures incomplete & 30-day rule not met. Mods to 11 motor-operated valves rescheduled during refueling outage to begin on 870501. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON,H.R., BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33191:010-33191:011.
- 8510280326** Forwards revised response to Generic Ltr 83-28, Item 3.1.2 re reactor trip sys & corresponding commitment data. Approx 75 working level procedures, instead of previously reported 800 procedures, will require addl review. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33192:361-33192:362.
- 8510290197** Application for amendments to Licenses NPF-4 & NPF-7, revising FSAR damping values used for seismic analysis of piping to be consistent w/ASME Code Case N-411 damping values recommended in NUREG-1061. Fee paid. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33236:204-33236:205.
- 8510290257** Confirms 851001 telcon commitment to supply details of updated reactor vessel mat surveillance program for facility by 860415. Programmatic review of vessel mat surveillance programs underway. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33236:353-33236:354.
- Q. Inspection reports, IE Bulletins & correspondence**
- 8509180313** Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 11pp. 32854:338-32854:348.
- 8510070378** Responds to NRC 850719 ltr re violations noted in Insp Repts 50-338/85-16 & 50-339/85-16 & forwards addl responses to Insp Repts 50-338/85-18 & 50-339/85-18, per 850819 telcon. Corrective action personnel trained in operating procedures. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/19. GRACE,J.N. Region 2, Office of Director. 9pp. 32878:295-32878:303.
- 8510010451** Application for amendments to Licenses NPF-4 & NPF-7, changing Tech Spec Section 4.7.10 re surveillance requirements for snubbers. Change would modify portions of visual insp acceptance criteria. Fee paid. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER,E.J. Operating Reactors Branch 3. 3pp. 32804:079-32804:092.
- 8510010456** Proposed changes to Tech Spec Section 4.7.10 re surveillance requirements for snubbers, modifying portions of visual insp acceptance criteria. * Virginia Power (Virginia Electric & Power Co.). 85/09/24. 11pp. 32804:082-32804:092.
- 8510070361** Grants interim relief from inservice testing requirements of ASME Code pending completion of detailed review, per 841231 request for interim approval re inservice insp & testing for pumps & valves. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 32901:275-32901:278.
- 8510070328** Responds to NRC 850813 ltr re violations noted in Insp Repts 50-338/85-19 & 50-339/85-19. Corrective actions: monthly review to check periodic waste gas holdup sys test schedule & accuracy will be performed. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/27. GRACE,J.N. Region 2, Office of Director. 6pp. 32877:255-32877:260.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510150249** Requests assistance in reviewing encl util 841102, 850505 & 0919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively. THOMPSON,H.L. Division of Licensing. 85/10/04. WALKER,R.D. Region 2, Office of Director. 2pp. 33032:236-33032:299.
- 8510180015** Requests encl notice of consideration of issuance of amendments to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing re 850919 application be forwarded for FR publication. ENGLE,L.B. Operating Reactors Branch 3. 85/10/04. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33069:344-33069:345.
- 8510180016** Notice of consideration of issuance of amendments to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing. Amend adds statement to Surveillance Requirement 4.7.10 re early insp of snubbers. ENGLE,L.B. Operating Reactors Branch 3. 85/10/04. 8pp. 33069:346-33069:353.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTC J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service, Inc. 7pp. 33108:264-33108:268.
- 8510230327** Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys. KAMMERER,C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. 2pp. 33109:155-33109:157.
- 8510180094** Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. GRACE,J.N. Region 2, Office of Director. 85/10/11. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 33027:359-33027:360.
- 8510160104** Responds to NRC 850828 ltr re violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. Corrective actions withheld (ref 10CFR73.21). STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/26. GRACE,J.N. Region 2, Office of Director. 1p. 33027:360-33027:360.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.
- 8510150025** IE Info Notice 85-081 "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.
- R. Periodic operating reports & related correspondence**
- 8510020071** Monthly operating repts for Jul 1985. W/850815 ltr. GARNER,B., STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/07/31. BEEBE,M.R. Office of Resource Management, Director. 12pp. 32827:129-32827:140.
- S. Reportable occurrences, LERs & related correspondence**
- 8510030116** Part 21 rept re defective electronically coded vinyl key cards. Pyrotronics Model 1310, used for security electronic access control sys. Initially reported on 850913. Five defective cards destroyed. New cards will be tested. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/16. GRACE,J.N. Region 2, Office of Director. 3pp. 32842:231-32842:233.
- 8510010603** LER 85-001-01: on 850503, semiannual functional test on seismic triaxial response-spectrum recorders not performed. Caused by inaccessibility during power operation. Change in surveillance test requirement requested. W/850925 ltr. HARRELLE,W. Virginia Power (Virginia Electric & Power Co.). 85/09/25. 3pp. 32820:360-32820:362.

8510080397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewpoints encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965-021-32965-047.

8510090407 LER 85-016-00 on 850911, RCS Loop B bypass line motor-operated valve leak exceeded Tech Spec limits. Cause unstated. Maint performed on 850913 resulting in acceptable leak rate. W/851002 ltr.
HARRELLE, W. Virginia Power (Virginia Electric & Power Co.). 85/10/02. 3pp. 32946-145-32946-147.

8510150166 LER 85-018-00 on 850917, expiration of reactor operator license discovered. Caused by administrative error. Administrative controls for license expiration date tracking sys will be reviewed & revised as required. W/851004 ltr.
HARRELLE, W. Virginia Power (Virginia Electric & Power Co.). 85/10/04. 3pp. 33015-063-33015-065.

8510240560 LER 85-011-00 on 850918, emergency diesel generator 1J tripped on high crankcase pressure & repairs not completed within 72 h, causing cold shutdown on 850921. Caused by cracked cylinder liner. Liner replaced. W/851016 ltr.
HARRELLE, W. Virginia Power (Virginia Electric & Power Co.). 85/10/16. 3pp. 33157-332-33157-334.

8510250182 LER 85-017-00 on 850917, reactor & turbine trips manually initiated due to four Control Bank D, Group 1 control rods dropping into core. Caused by three faulty alarm circuit cards. Cards replaced on 850918. W/851016 ltr.
HARRELLE, W. Virginia Power (Virginia Electric & Power Co.). 85/10/16. 4pp. 33190-246-33190-249.

8510180376 Notification of 851018 meeting w/util in Bethesda, MD to discuss 851008 failure of Emergency Diesel Generator 2H.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/17. DENTON, H., EISENHUT, D., THOMPSON, H. NRC - N.J. Detailed Affiliation Given. 2pp. 33078-254-33078-255.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. SLAUGHTER, S. SISKY House of Rep. 2pp. 33109-155-33109-157.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070360 Rev 3 to "Corporate Emergency Response Plan," for Third Quarter 1985. W/850927 ltr.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/08/29. 90pp. 32875-036-32875-125.

8510040082 Forwards Rev 14 to security program. Encl withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 1p. 32851-024-32851-024.

8510040137 Forwards Revs 8 & 9 to security personnel training & qualification programs for North Anna & Surry, respectively & response to NRC 850724 comments. Encls withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32851-208-32851-209.

8510150249 Requests assistance in reviewing encl util 841102, 850505 & 850919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively.
THOMPSON, H.L. Division of Licensing. 85/10/04. WALKER, R.D. Region 2, Office of Director. 2pp. 33032-236-33032-299.

8510160094 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. Corrective actions withheld (ref 10CFR73.21).
GRACE, J.N. Region 2, Office of Director. 85/10/11. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 33027-360-33027-360.

-8510160104 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. Corrective actions withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/26. GRACE, J.N. Region 2, Office of Director. 1p. 33027-360-33027-360.

G. Adjudicatory correspondence

8510110028 Order stating that ASLB 850903 initial decision authorizing NRR to amend OL to permit receipt & storage of spent fuel should not be deemed final, pending further order. Served on 851009.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 722. 85/10/09. 2pp. 32973-231-32973-232.

8510110152 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
HASSELL, D.F. Hearing Branch 2. #485 738. 85/10/09. 3pp. 32999-347-32999-349.

8510220240 Forwards notice of withdrawal of appearance in proceeding. Requests svc list be revised to include client under listed address. W/o encl.
DOUGHERTY, J.B. Dougherty, J.B. DOUGHERTY, J.B. Concerned Citizens of Louisa County. #485 846. 85/10/18. Office of the Secretary of the Commission. 1p. 33087-203-33087-203.

8510220264 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
DOUGHERTY, J.B. Concerned Citizens of Louisa County. #485 861. 85/10/18. 2pp. 33085-097-33085-098.

J. Insurance & indemnity information

8510080180 Forwards Endorsements 79 & 80 to NELIA Policy NF-186 & MAELU Policy MF-57, respectively.
INGLES, J.M. Marsh & McLennan, Inc. 85/09/25. DINI, T.I. Office of Nuclear Reactor Regulation, Director. 3pp. 32922-076-32922-078.

P. Operating license stage documents & correspondence

8510010451 Application for amends to Licenses NPF-4 & NPF-7, changing Tech Spec Section 4.7.10 re surveillance requirements for snubbers. Change would modify portions of visual insp acceptance criteria. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 3pp. 32804-079-32804-092.

-8510010456 Proposed changes to Tech Spec Section 4.7.10 re surveillance requirements for snubbers, modifying portions of visual insp acceptance criteria.
* Virginia Power (Virginia Electric & Power Co.). 85/09/24. 11pp. 32804-082-32804-092.

8510030013 Application for amend to License NPF-7, changing Tech Specs by providing addl operating flexibility during return to power after trips near end of cycle. Approval requested by 850201. Core surveillance rept encl. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 3pp. 32844-122-32844-164.

-8510030020 Proposed Tech Spec changes providing addl operating flexibility during return to power after trips near end of cycle.
* Virginia Power (Virginia Electric & Power Co.). 85/09/26. 39pp. 32844-125-32844-164.

8510070361 Grants interim relief from inservice testing requirements of ASME Code pending completion of detailed review. per 841231 request for interim approval re inservice insp & testing for pumps & valves.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 32901-275-32901-278.

8510180540 Forwards request for addl info re 850830 updated QA Topical Rept VEP 1-4A necessary for completion of evaluation of program changes.
WALKER, R.D. Region 2, Office of Director. 85/10/01. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 33068-253-33068-256.

8510080153 Forwards response to 850624 request for addl info re Generic Ltr 83-28, Items 3.1.1, 3.1.2, 3.2.1 & 3.2.2. Administrative procedure will have step to ack that review performed to determine if post-maint testing required.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 5pp. 32922-079-32922-083.

8510150249 Requests assistance in reviewing encl util 841102, 850505 & 850919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively.
THOMPSON, H.L. Division of Licensing. 85/10/04. WALKER, R.D. Region 2, Office of Director. 2pp. 33032-236-33032-299.

8510180015 Requests encl notice of consideration of issuance of amend to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing re 850919 application be forwarded for FR publication.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/04. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33069-344-33069-345.

-8510180016 Notice of consideration of issuance of amends to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing. Amend adds statement to Surveillance Requirement 4.7.10 re early insp of snubbers.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/04. 8pp. 33069-346-33069-353.

8510170074 Forwards VEP-NE-2, "Statistical DNBR Evaluation Methodology." Rept describes methodology for statistically treating several important uncertainties in DNBR analysis & replaces deterministic methodology. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33036-252-33036-320.

-8510170079 "Statistical DNBR Evaluation Methodology."
ANDERSON, R.C. Virginia Power (Virginia Electric & Power Co.). VEP-NE-2. 85/07/31. 67pp. 33036-254-33036-320.

8510180151 Advises that proposed schedule for meeting requirements for ATWS mitigation sys, per 10CFR50.62(d) & Generic Ltr 85-06, will be completed by end of First Quarter 1986. ATWS mitigation sys of vendors under evaluation.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33055-035-33055-037.

8510280326 Forwards revised response to Generic Ltr 83-28, Item 3.1.2 re reactor trip sys & corresponding commitment date. Approx 75 working level procedures instead of previously reported 800 procedures. Will require addl review.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33192-361-33192-362.

128 DOCKETED ITEMS

8510290197 Application for amends to Licenses NPF-4 & NPF-7, revising FSAR damping values used for seismic analysis of piping to be consistent w/ASME Code Case N-411 damping values recommended in NUREG-1061. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33236:204-33236:205.

8510290253 Confirms 851001 telcon commitment to supply details of updated reactor vessel matts surveillance program for facility by 860415. Programmatic review of vessel matts surveillance programs underway.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/10/21.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33236:353-33236:354.

Q. Inspection reports, IE Bulletins & correspondence

8509180313 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 11pp. 32854:338-32854:348.

8510070378 Responds to MRC 850719 ltr re violations noted in Insp Repts 50-338/85-16 & 50-339/85-16 & forwards addl responses to Insp Repts 50-338/85-18 & 50-339/85-18, per 850819 telcon. Corrective action: personnel trained in operating procedures.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/19. GRACE, J.N. Region 2, Office of Director. 9pp. 32878:295-32878:303.

8510010451 Application for amends to Licenses NPF-4 & NPF-7, changing Tech Spec Section 4.7.10 re surveillance requirements for snubbers. Change would modify portions of visual insp acceptance criteria. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/24.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32804:079-32804:092.

-8510010456 Proposed changes to Tech Spec Section 4.7.10 re surveillance requirements for snubbers, modifying portions of visual insp acceptance criteria.
* Virginia Power (Virginia Electric & Power Co.). 85/09/24. 11pp. 32804:082-32804:092.

8510070361 Grants interim relief from interservice testing requirements of ASME Code pending completion of detailed review, per 841231 request for interim approval re service insp & testing for pumps & valves.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 32901:275-32901:278.

8510070328 Responds to NRC 850813 ltr re violations noted in Insp Repts 50-338/85-19 & 50-339/85-19. Corrective actions: monthly review to check periodic waste gas holdup sys test schedule & accuracy will be performed.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/27. GRACE, J.N. Region 2, Office of Director. 6pp. 32877:255-32877:260.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150249 Requests assistance in reviewing encl util 841102, 850505 & 0919 applications to amend Licenses NPF-4 & NPF-7 re organization changes, entries to airlock for door repair & visual insp of snubbers, respectively.
THOMPSON, H.L. Division of Licensing. 85/10/04. WALKER, R.D. Region 2, Office of Director. 2pp. 33032:236-33032:299.

8510180015 Requests encl notice of consideration of issuance of amends to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing re 850919 application be forwarded for FR publication.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/04. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33069:344-33069:345.

-8510180010 Notice of consideration of issuance of amends to Licenses NPF-4 & NPF-7 & proposed NSHC determination & opportunity for hearing. Amend adds statement to Surveillance Requirement 4.7.10 re early insp of snubbers.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/04. Encl. 33069:346-33069:353.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. 2pp. 33109:155-33109:157.

8510160094 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-325/85-20 & 50-339/85-20.
GRACE, J.N. Region 2, Office of Director. 85/10/11. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 33027:359-33027:360.

-8510160104 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-338/85-20 & 50-339/85-20. Corrective actions withheld (ref 10CFR73.21).
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/26. GRACE, J.N. Region 2, Office of Director. 1p. 33027:360-33027:360.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510020071 Monthly operating repts for Jul 1985 W/850815 ltr.
GARNER, B. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/07/31.
BEEBE, M.R. Office of Resource Management, Director. 12pp. 32827:129-32827:140.

S. Reportable occurrences, LERs & related correspondence

8510030116 Part 21 rept re defective electronically coded vinyl key cards, Pyrotronics Model 1310, used for security electronic access control sys. Initially reported on 850913. Five defective cards destroyed. New cards will be tested.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/16. GRACE, J.N. Region 2, Office of Director. 3pp. 32842:231-32842:233.

8510180376 Notification of 851018 meeting w/util in Bethesda, MD to discuss 851008 failure of Emergency Diesel Generator 2H.
ENGLE, L.B. Operating Reactors Branch 3. 85/10/17. DENTON, H. EISENHUT, D., THOMPSON, H. NRC - No Detailed Affiliation Given. 2pp. 33078:254-33078:255.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys.
KAMMERER, C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. SLAUGHTER, SISKY House of Rep. 2pp. 33109:155-33109:157.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832:352-32832:353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832:354-32832:355.

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510030001 Application for amend to License NPF-43, revising Tech Specs re alternate shutdown sys. Technical justification encl. Fee paid.
JENS, W.H. Detroit Edison Co. 85/09/27. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32842:236-32842:249.

-8510030007 Proposed Tech Specs re instrumentation, controls & surveillance requirements for alternate shutdown sys.
* Detroit Edison Co. 85/09/27. 9pp. 32842:241-32842:249.

8510070057 Forwards Reg Guide 1.97 compliance rpt, providing description of requirements & method of complying w/ requirements for each post-accident variable identified in Table 1 of guide.
JENS, W.H. Detroit Edison Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 130pp. 32875:126-32875:258.

8510220243 Requests meeting w/NRC to review proposed Tech Specs re alternate shutdown program. Meeting would allow util opportunity to explain basis for proposed specs & answer questions.
JENS, W.H. Detroit Edison Co. 85/10/16. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33087:323-33087:323.

8510280352 Forwards Safety Insp Rept 50-341/85-41 on 851001-03. No violation noted. Exercise weakness identified re protective action decisionmaking.
SHAFFER, W.D. Region 3, Office of Director. 85/10/22. JENS, W.H. Detroit Edison Co. 3pp. 33192:317-33192:342.

8510280359 Insp Rept 50-341/85-41 on 851001-03.No violation or deviation noted.Exercise weakness identified re protective action decisionmaking.Scope,objectives & simulations for FERMEX 85 encl. SNELL,W., WILLIAMSEN,N., PHILLIPS,M. Region 3, Office of Director. 85/10/21. 23pp. 33192-320-33192-342.

8510290014 Forwards Safeguards Insp Rept 50-341/85-44 on 850930-1004. No non-compliance noted. HIND,J.A. Region 3, Office of Director. 85/10/24. JENS,W.H. Detroit Edison Co. 2pp. 33235-148-33235-151.

8510290017 Physical Security Insp Rept 50-341/85-44 on 850930-1004.No noncompliance noted.Major areas inspected:mgt effectiveness, security organization,testing & maint & security program. Details withheld (ref 10CFR73.21). MADEDA,T.J., PIRTLE,G.L., CREED,J.R. Region 3, Office of Director. 85/10/24. 2pp. 33235-150-33235-151.

8510290380 Forwards Safety Insp Rept 50-341/85-37 on 850701-0930 & notice of violation.Appropriate corrective action taken for Violation 2 & no response required. CHRISSOTIMOS,N. Region 3, Office of Director. 85/10/25. JENS,W.H. Detroit Edison Co. 2pp. 33239-126-33239-144.

8510290387 Insp Rept 50-341/85-37 on 850701-0930.Violation noted: inadequate procedure for preventive maint of diesel generator & failure to perform intermediate-range monitor Tech Spec surveillance testing. WRIGHT,G.C. Region 3, Office of Director. 85/10/25. 16pp. 33239-129-33239-144.

G. Adjudicatory correspondence

8510020168 Advises that time for Commission to review Director's Decision DD-85-13 expired.Commission declined review. Decision became final agency action on 850927.Served on 850930.

HOYLE,J.C. Office of the Secretary of the Commission. #485 642. 85/09/30. NIEBUTZ,S. Affiliation Not Assigned. 1p. 32824-319-32824-319.

P. Operating license stage documents & correspondence

8510030010 Forwards revs to inservice testing program for pumps & valves,to be implemented to support startup program.Revs will be incorporated into Rev 2 to inservice testing program. JENS,W.H. Detroit Edison Co. 85/09/20. YOUNGBLOOD,B.J. Licensing Branch 1. 23pp. 32844-165-32844-189.

8510030001 Application for amend to License NPF-43,revising Tech Specs re alternative shutdown sys.Technical justification encl. Fee paid. JENS,W.H. Detroit Edison Co. 85/09/27. YOUNGBLOOD,B.J. Licensing Branch 1. 5pp. 32842-236-32842-249.

8510030007 Proposed Tech Specs re instrumentation,controls & surveillance requirements for alternate shutdown sys. * Detroit Edison Co. 85/09/27. 9pp. 32842-241-32842-249.

8510160119 Application for amend to License NPF-23,changing Tech Spec 3.10.5 to delay inerting of containment until 120 EFPDs achieved.Fee paid. JENS,W.H. Detroit Edison Co. 85/10/09. YOUNGBLOOD,B.J. Licensing Branch 1. 4pp. 33022-266-33022-270.

8510160123 Proposed Tech Spec 3.10.5,delaying inerting of containment until 120 EFPDs achieved. * Detroit Edison Co. 85/10/09. 1p. 33022-270-33022-270.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28,Item 1.2 re Salem ATWS events.Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies. CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

8510170169 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events).Item 1.2, "Post-Trip Review>Data & Info Capabilities"... technical evaluation rpt. * Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85-1517-1. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044-042-33044-056.

8510160071 Discusses implementation schedule for ATWS compliance before startup following second refueling outage.Alternate rod insertion sys designed to mitigate potential consequences of ATWS installed & operational. JENS,W.H. Detroit Edison Co. 85/10/12. YOUNGBLOOD,B.J. Licensing Branch 1. 2pp. 33028-125-33028-126.

Q. Inspection reports, IE Bulletins & correspondence

8510080473 Responds to weaknesses noted in Insp Rept 50-341/85-31. Corrective actions,around-the-clock coverage provided to process urgent work promptly in development of maint work package. JENS,W.H. Detroit Edison Co. 85/09/05. KEPPLER,J.G. Region 3, Office of Director. 6pp. 32922-046-32922-051.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070325 Forwards Change 1 to Procedure NE-5.6-ISI-NDE, "Inservice Insp-NDE (ISI-NDE) Program (Plan) for Fermi 2 Power Plant." V.44 oversize drawings. JENS,W.H. Detroit Edison Co. 85/09/30. YOUNGBLOOD,B. Licensing Branch 1. 1p. 32911-307-32912-013.

8510070329 Change 1 to Procedure NE-5.6-ISI-NDE, "Inservice Insp-NDE (ISI-NDE) Program (Plan) for Fermi 2 Power Plant." SHEFFEL,B.J., SHOUDY,A.A., COLBERT,W.F. Detroit Edison Co. 85/09/26. 400pp. 32911-309-32913-011.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510100150 Forwards corrected Page 2 to Insp Rept 50-341/85-29 due to ty. "RC tracking number incorrectly identified as 341/84003-06.Correct designation is 341/84043-06. NORELIUS,C.E. Region 3, Office of Director. 85/10/04. JENS,W.H. Detroit Edison Co. 1p. 32961-203-32961-204.

8510100157 Corrected Page 2 to Insp Rept 50-341/85-29,changing tracking number to 341/84043-06. * Region 3, Office of Director. 85/10/04. 1p. 32961-204-32961-204.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class,Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280352 Forwards Safety Insp Rept 50-341/85-41 on 851001-03.No violation noted.Exercise weakness identified re protective action; decisionmaking. SHAFFER,W.D. Region 3, Office of Director. 85/10/22. JENS,W.H. Detroit Edison Co. 3pp. 33192-317-33192-342.

8510280359 Insp Rept 50-341/85-41 on 851001-03.No violation or deviation noted.Exercise weakness identified re protective action decisionmaking.Scope,objectives & simulations for FERMEX 85 encl. SNELL,W., WILLIAMSEN,N., PHILLIPS,M. Region 3, Office of Director. 85/10/21. 23pp. 33192-320-33192-342.

8510290014 Forwards Safeguards Insp Rept 50-341/85-44 on 850930-1004. No non-compliance noted. HIND,J.A. Region 3, Office of Director. 85/10/24. JENS,W.H. Detroit Edison Co. 2pp. 33235-148-33235-151.

8510290017 Physical Security Insp Rept 50-341/85-44 on 850930-1004.No noncompliance noted.Major areas inspected:mgt effectiveness, security organization,testing & maint & security program. Details withheld (ref 10CFR73.21). MADEDA,T.J., PIRTLE,G.L., CREED,J.R. Region 3, Office of Director. 85/10/24. 2pp. 33235-150-33235-151.

8510290380 Forwards Safety Insp Rept 50-341/85-37 on 850701-0930 & notice of violation.Appropriate corrective action taken for Violation 2 & no response required. CHRISSOTIMOS,N. Region 3, Office of Director. 85/10/25. JENS,W.H. Detroit Edison Co. 2pp. 33239-126-33239-144.

8510290384 Notice of violation from insp on 850701-0930. CHRISSOTIMOS,N. Region 3, Office of Director. 85/10/25. 1p. 33239-128-33239-128.

8510290387 Insp Rept 50-341/85-37 on 850701-0930.Violation noted: inadequate procedure for preventive maint of diesel generator & failure to perform intermediate-range monitor Tech Spec surveillance testing. WRIGHT,G.C. Region 3, Office of Director. 85/10/25. 16pp. 33239-129-33239-144.

R. Periodic operating reports & related correspondence

8510010417 Monthly operating rept for Jul 1985 W/850814 ltr. BREGNI,L., LENART,R.S. Detroit Edison Co. 85/07/31. 4pp. 32809-182-32809-185.

S. Reportable occurrences, LERs & related correspondence

8510020203 LER 85-054-00:on 850827,HPCI sys isolated.Caused by personnel selecting wrong module inside panel.Diagrams showing locations & identification of switch modules from rear or panel added to surveillance procedures W/850924 ltr. BREGNI,L.P., LENART,R.S. Detroit Edison Co. 85/09/24. 3pp. 32834-190-32834-192.

8510020160 LER 85-055-00:on 850828,HPCI sys isolation logic Train A tripped.Caused by incorrect output due to poor connection between amplifier card & pins.Amplifier board retested securely W/850927 ltr. BREGNI,L.P., LENART,R.S. Detroit Edison Co. 85/09/27. 3pp. 32827-270-32827-272.

8510070374 LER 85-057-00:on 850829,during radiological emergency response preparedness drill,h roving fire watch missed. Cause unstated.Fire watch duties reviewed w/all personnel assigned W/850927 ltr. BREGNI,L.P., LENART,R.S. Detroit Edison Co. 85/09/27. 3pp. 32883-302-32883-304.

8510090182 LER 85-058-00:on 850831,Div 1 emergency equipment cooling water sys & associated svc water sys automatically started. Cause unknown.Recorder installed to track differential pressure in closed cooling water sys W/850927 ltr. BREGNI,L.P., LENART,R.S. Detroit Edison Co. 85/09/27. 3pp. 32946-194-32946-196.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923.List of attendees & viewgraphs encl. CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON,H.L. Division of Licensing. 27pp. 32965-021-32965-047.

8510090376 LER 85-059-00:on 850903,Group 1 isolation initiated high pressure trip.Caused by exceeding condenser high pressure setpoint during sensing line refill.Condenser pressure instruments recalled.Lines will be monitored W/851003 ltr. BREGNI,L.P., LENART,R.S. Detroit Edison Co. 85/10/03. 4pp. 32946-127-32946-130.

130 DOCKETED ITEMS

8510090083 LER 85-056-00 on 850826, determined that leak rate test not performed after maint on Div II thermal recombiner on 850620. Leak test on 850829 indicated excessive leakage. Caused by damaged gasket. Gasket replaced. W/851004 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/04. 6pp. 32941:265-32941:270.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl. CRUTCHFIELD, D.D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

8510240004 LER 85-062-00 on 850909, intermediate range monitor Channels B & D inoperable due to weekly channel functional test not completed on time. Caused by staff not being aware of surveillance time limit. Test completed. W/851016 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/16. 5pp. 33156:267-33156:271.

8510250289 LER 85-006-01 on 850407, standby gas treatment sys Div 1 & associated carbon dioxide fire protection sys inoperable. Caused by failure to align both sys after minor mods. Procedure revised. W/851017 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/17. 4pp. 33189:358-33189:361.

8510280071 LER 85-063-00 on 850920, reactor water cleanup sys isolated on high differential flow signal. Caused by pump discharge flow transmitter not holding calibr. Transmitter replaced & sys placed in bypass. W/851021 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/21. 4pp. 33194:134-33194:137.

8510290067 LER 85-025-01 on 850614, reactor water cleanup sys isolated w/plant in Operational Condition 4. Caused by spurious electrical signals associated w/steam leak detection fuse reinstallation. Circuitry delay in design stage. W/851021 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/21. 3pp. 33242:311-33242:313.

8510310404 LER 85-061-00 on 850924, reactor water cleanup sys isolated. Caused by incorrect module leads being lifted, simulating high temp signal. Sys isolated again on high differential flow signal due to flow problems. W/851022 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/22. 4pp. 33280:301-33280:304.

8510310015 LER 85-066-00 on 850927, reactor protection sys tripped on high pressure due to west turbine bypass valve closing. Caused by noise picked up by turbine speed pickup & seen as speed signal. Gain level adjusted. W/851025 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/25. 4pp. 33291:240-33291:243.

8510310057 LER 85-067-00 on 850928, reactor trip occurred while returning jet pump developed head transmitter to svc. Caused by spurious low reactor vessel water Level 3 signal. Common leg instruments added to valving procedure. W/851025 ltr. BREGNI, L.P., LENART, R.S. Detroit Edison Co. 85/10/25. 4pp. 33291:296-33291:299.

U. Congressional/Executive Correspondence

8510090380 Responds to 850823 request for investigation into 850702 premature criticality event. Investigation expected to be completed within 60 days. Rept will be forwarded. Briefing can be arranged by request. PALLADINO, N.J. Commissioners. 85/10/01. DINGELL, J.D. House of Rep., Energy & Commerce. 1p. 33011:301-33011:304.

8510090385 Requests investigation of operational procedures & credentials of employees carrying out procedures at Fermi 2 on 850702. Ltr from Monroe County Commissioners, describing events, encl. DINGELL, J.D. House of Rep., Energy & Commerce. 85/08/23. PALLADINO, N.J. Commissioners. 3pp. 33011:302-33011:304.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510290014 Forwards Safeguards Insp Rept 50-341/85-44 on 850930-1004. No non-compliance noted. HIND, J.A. Region 3, Office of Director. 85/10/24. JENS, W.H. Detroit Edison Co. 2pp. 33235:148-33235:151.

8510290017 Physical Security Insp Rept 50-341/85-44 on 850930-1004. No non-compliance noted. Major areas inspected: mgt effectiveness, security organization, testing & maint & security program. Details withheld (ref 10CFR73.21). MADEIRA, T.J., PIRTELL, G.L., CREED, J.R. Region 3, Office of Director. 85/10/24. 2pp. 33235:150-33235:151.

DOCKET 50-344 TROJAN NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8510080095 Forwards Rev 11 to security program, deleting position of supervisor, nuclear security operations, w/appropriate shifts in responsibilities & adding two vital areas. Rev withheld (ref 10CFR73.21). WITHERS, B.D. Portland General Electric Co. 85/09/30. MARTIN, J.B. Region 5, Office of Director. 2pp. 32913:132-32913:133.

8510070177 Requests that NRC & NRC contractor personnel be granted unescorted access to observe annual emergency exercise on 851014-18. List of participating personnel encl. MARTIN, J.B. Region 5, Office of Director. 85/10/01. WITHERS, B.D. Portland General Electric Co. 2pp. 32878:315-32878:316.

8510070199 Ack receipt of 850829 ltr re scenario & licensee actions for annual emergency exercise on 851016. Changes to scenario discussed w/J Thale of util on 850924 acceptable & meet exercise objectives contained in 850726 submittal. FISH, R.F. Region 5, Office of Director. 85/10/01. WITHERS, B.D. Portland General Electric Co. 1p. 32881:134-32881:134.

8510090230 Revised radiological emergency response plan implementing procedures including Rev 2 to EP-22, "Public Relations Dept" & Rev 0 to EP-22.1, "Emergency Operating Facility Public Info Representative." * Portland General Electric Co. 85/10/04. 71pp. 32952:223-32952:276.

8510220091 Forwards Safeguards Insp Rept 50-344/85-27 on 850826.0923. No non-compliance noted. Rept withheld (ref 10CFR73.21 & 2.790). MONTGOMERY, J.L. Region 5, Office of Director. 85/10/11. WITHERS, B.D. Portland General Electric Co. 1p. 33095:147-33095:147.

8510300228 Forwards safety evaluation accepting util 840731 & 850306 proposed revised Sections III.G.3 & III.L of 10CFR50, App R re alternate shutdown capability w/identified mods & compensatory measures. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/15. WITHERS, B.D. Portland General Electric Co. 2pp. 33261:310-33261:317.

8510300233 Safety evaluation concluding that util proposed post-fire alternate shutdown design meets requirements of 10CFR50, App R, Sections III.G.3 & III.L w/proposed mods & interim measures acceptable. * Office of Nuclear Reactor Regulation, Director. 85/10/15. 6pp. 33261:312-33261:317.

J. Insurance & indemnity information

8510090014 Forwards Endorsement 71 to NELIA Policy NF-225 & Endorsement 59 to MAELU Policy MF-86. ASHBURN, D.J. Marsh & McLennan, Inc. 85/10/04. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 32943:034-32943:036.

P. Operating license stage documents & correspondence

8510150192 Forwards Rev 11 to QA program. Rev includes statement that nuclear safety & regulation dept reviews safety evaluations as nuclear operations board staff function. WITHERS, B.D. Portland General Electric Co. 85/09/16. KIRSCH, D.F. Region 5, Office of Director. 4pp. 33010:338-33010:341.

8510030104 Forwards Rev 1 to License Change Application 117, requesting amend to License NPF-1, modifying Tech Specs to revise reactor trip sys & ESFAS instrumentation requirements. Certificate of Svc encl. WITHERS, B.D. Portland General Electric Co. 85/09/23. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 32843:012-32843:070.

8510030112 Rev 1 to License Change Application 117, modifying Tech Specs to rectify inconsistencies w/installed instrumentation not in agreement w/Rev 4 to NUREG-0452 & to remove unnecessary numerals from spec numbers. WITHERS, B.D. Portland General Electric Co. 85/09/23. 16pp. 32843:014-32843:029.

8510030117 Proposed Tech Specs, rectifying inconsistencies w/installed instrumentation not in agreement w/Rev 4 to NUREG-0452 & removing unnecessary numerals from spec numbers. * Portland General Electric Co. 85/09/23. 41pp. 32843:030-32843:070.

8510010139 Ack receipt of addl info requested in 850703 ltr re Rev 10 to nuclear QA program. Rev 10 continues to satisfy 10CFR50, App B requirements & acceptable. KIRSCH, D.F. Region 5, Office of Director. 85/09/26. WITHERS, B.D. Portland General Electric Co. 2pp. 32800:080-32800:081.

8510240536 Forwards Amend 107 to License NPF-1 & safety evaluation. Amend revises Tech Specs to reduce frequency of diesel generator testing & allow engine to be warmed up for most tests before increasing speed. LAZOL, Operating Reactors Branch 3. 85/10/04. WITHERS, B.D. Portland General Electric Co. 2pp. 33177:356-33177:005.

8510240549 Amend 107 to License NPF-1, revising Tech Specs to reduce frequency of diesel generator testing & allow engine to be warmed up for most tests before increasing speed. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/04. 7pp. 33177:358-33177:002.

8510240558 Safety evaluation supporting Amend 107 to License NPF-1. * Office of Nuclear Reactor Regulation, Director. 85/10/04. 3pp. 33178:003-33178:005.

8510180102 Forwards safety evaluation supporting util response to Generic Ltr 83-28, Item 4.1, concerning reactor trip sys reliability (vendor-related mods). Actions specified by Item 4.1 satisfactorily completed. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/10. WITHERS, B.D. Portland General Electric Co. 2pp. 33069:294-33069:297.

8510180107 Safety evaluation re util response to Generic Ltr 83-28, Item 4.1, concerning reliability of reactor trip sys. Actions specified by Item 4.1 satisfactorily completed, based on licensee review of sources of vendor-recommended mods. * Operating Reactors Branch 3. 85/10/10. 2pp. 33069:296-33069:297.

8510240570 Forwards safety evaluation addressing request to change test parameters used in leak testing Valve MO-8812. Changing test medium for valve from gas to water & 33.6 psi differential pressure acceptable. BUTCHER, E.J. Operating Reactors Branch 3. 85/10/10. WITHERS, B.D. Portland General Electric Co. 2pp. 33184:014-33184:018.

8510240578 Safety evaluation re leak test parameters for Valve MO-8812. Changing test medium for valve from gas to water & 33.6 psi differential pressure acceptable. * Office of Nuclear Reactor Regulation, Director. 85/10/10. 3pp. 33184:016-33184:018.

8510160053 Forwards application for amend to License NPF-1, consisting of License Change Application 131, modifying Tech Specs to clarify surveillance requirement for containment ventilation isolation sys. Fee paid. WITHERS, B.D. Portland General Electric Co. 85/10/11. BUTCHER, E.J. Operating Reactors Branch 3. 1p. 33027:202-33027:206.

8510160060 Application for amend to License NPF-1, consisting of License Change Application 131, modifying Tech Specs to clarify surveillance requirement for containment ventilation isolation sys. Certificate of Svc encl. WITHERS, B.D. Portland General Electric Co. 85/10/11. 2pp. 33027:203-33027:204.

8510160064 Proposed Tech Specs, clarifying surveillance requirement for containment ventilation isolation sys. Certificate of Svc encl. * Portland General Electric Co. 85/10/11. 2pp. 33027:205-33027:206.

8510160299 Provides response & schedule for satisfying 10CFR50.62(d) requirements re ATWS justification for implementing generic design after second refueling outage given.
WITHERS,B.D. Portland General Electric Co. 85/10/11. Office of Nuclear Reactor Regulation, Director. 3pp. 33026:289-33026:291.

8510180141 Forwards safety evaluation re util response to Generic Ltr 83-28, Items 3.1.1 & 3.1.2 concerning post-maint testing to verify operability & guidance for reactor trip sys components. Util satisfied actions requested by item 3.1.2.
BUTCHER,E.J. Operating Reactors Branch 3. 85/10/11. WITHERS,B.D. Portland General Electric Co. 2pp. 33069:267-33069:271.

8510180145 Safety evaluation re util response to Generic Ltr 83-28, Items 3.1.1 & 3.1.2 concerning post-maint testing to verify operability & guidance for reactor trip sys components. Licensee acceptably satisfied actions requested by items.
Office of Nuclear Reactor Regulation, Director. 85/10/11. 3pp. 33069:269-33069:271.

8510220151 Forwards addl info re Generic Ltr 83-28, Position 3.2.2, "Review of Test Recommendations & Guidance." Util commits to revise Nuclear Div Procedure NDP-100-3 to require review of applicable safety-related procedures when required.
WITHERS,B.D. Portland General Electric Co. 85/10/17. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33087:353-33087:354.

8510280286 Forwards safety evaluation accepting util 850313 decision to discontinue annual radiography of Loop A charging line thermal sleeve attachment weld & preferential use of alternate charging line.
BUTCHER,E.J. Operating Reactors Branch 3. 85/10/18. WITHERS,B.D. Portland General Electric Co. 2pp. 33228:194-33228:196.

8510280290 Safety evaluation accepting licensee 850313 decision to discontinue annual radiographic exam of 3-inch Loop A charging line thermal sleeves & restricted use of normal charging line.
Office of Nuclear Reactor Regulation, Director. 85/10/18. 3pp. 33228:196-33228:198.

8510290169 Forwards Rev 0 to 01-0300-1395, "Leak-Before-Break Evaluation of Reactor Coolant Loop," final rept.
WITHERS,B.D. Portland General Electric Co. 85/10/25. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33233:157-33233:196.

8510290174 Rev 0 to "Leak-Before-Break Evaluation of Reactor Coolant Loop," final rept.
EMERSON,R., BAK,W.R., GRUBB,R.L. Impell Corp. 01-0300-1395 R00. 85/06/30. 3pp. 33233:159-33233:196.

Q. Inspection reports, IE Bulletins & correspondence

8510020224 Forwards Insp Rept 50-344/85-29 on 850826-30. No violation noted.
KIRSCH,D.F. Region 5, Office of Director. 85/09/12. WITHERS,B.D. Portland General Electric Co. 1p. 32827:108-32827:114.

8510020230 Insp Rept 50-344/85-29 on 850826-30. No violation or deviation noted. Major areas inspected: IE bulletins, notices, outstanding open items & implementation of selected TMI action items.
KANOW,L.R., YOUNG,T. Region 5, Office of Director. 85/09/11. 6pp. 32827:109-32827:114.

8510090235 Forwards Insp Rept 50-344/85-21 on 850702-0830. No violation noted. Errors associated w/technical efforts identified over past yr appear to indicate need to reinforce adequacy of review of technical work.
KIRSCH,D.F. Region 5, Office of Director. 85/09/18. WITHERS,B.D. Portland General Electric Co. 2pp. 32946:164-32946:174.

8510090245 Insp Rept 50-344/85-21 on 850702-0830. No violation or deviation noted. Major areas inspected: startup testing program & 10CFR21 reporting activities. Info re quality of engineering reviews presented to mgt for consideration.
RICHARDS,S.A., KELLUND,G.C., DODDS,R.I. Region 5, Office of Director. 85/09/16. 9pp. 32946:166-32946:174.

8510020251 Ack receipt of 850819 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-344/85-16.
KIRSCH,D.F. Region 5, Office of Director. 85/09/23. WITHERS,B.D. Portland General Electric Co. 1p. 32827:178-32827:181.

8510150012 Forwards Insp Rept 50-344/85-25 on 850809 & 12-16. No violation noted. Four unresolved items require addl info before further action can be taken.
ZECH,G.G. Vendor Program Branch. 85/09/26. WITHERS,B.D. Portland General Electric Co. 2pp. 33031:158-33031:177.

8510150015 Insp Rept 50-344/85-25 on 850809 & 12-16. Major areas inspected: effectiveness of info exchange between vendors of safety-related equipment & util. Potential violations noted in areas of procurement of safety-related equipment.
MERSCHOFF,E.W., BAKER,E.T., MCINTYRE,R.P. Director's Office, Office of Inspection and Enforcement. 85/09/25. 18pp. 33031:160-33031:177.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint, Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080041 Forwards response to Encl 2 of Generic Ltr 85-02 re steam generator tube integrity Mod to existing steam generator integrity Tech Specs re Category 2 steam generators unnecessary.
WITHERS,B.D. Portland General Electric Co. 85/10/02. THOMPSON,H.L. Division of Licensing. 3pp. 32918:300-32918:302.

8510080188 Forwards request for relief from certain inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code for review & approval. Fee paid.
WITHERS,B.D. Portland General Electric Co. 85/10/03. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 32918:350-32918:351.

8510280342 Forwards inservice insp rept performed during 1985 refueling outage. Rept submitted per Subsection IWA-6220 of Section XI of ASME Boiler & Pressure Vessel Code. No findings of significant nature noted during exam. W/o encl.
WITHERS,B.D. Portland General Electric Co. 85/10/04. MARTIN,J.B. Region 5, Office of Director. 1p. 33193:238-33193:238.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY,R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER,R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510280155 Forwards Insp Rept 50-344/85-30 on 850909-13 & 23-27. No violation noted.
KIRSCH,D.F. Region 5, Office of Director. 85/10/10. WITHERS,B.D. Portland General Electric Co. 1p. 33194:230-33194:239.

8510280159 Insp Rept 50-344/85-30 on 850909-13 & 23-27. No noncompliance or deviations noted. Major areas inspected: requalification training program, facility mod program, implementation of audit program & QC program review.
PEREIRA,D.B., DODDS,R.T. Region 5, Office of Director. 85/10/08. 9pp. 33194:231-33194:239.

8510220091 Forwards Safeguards Insp Rept 50-344/85-27 on 850826-0923. No noncompliance noted. Rept withheld (ref 10CFR73.21 & 2.790).
MONTGOMERY,J.L. Region 5, Office of Director. 85/10/11. WITHERS,B.D. Portland General Electric Co. 1p. 33095:147-33095:147.

8510310228 Forwards response to Vendor Program Branch Insp Rept 50-344/85-25 on 850809-16. Clarification of commercial grade items needed to resolve differing interpretations of regulations.
WITHERS,B.D. Portland General Electric Co. 85/10/14. MARTIN,J.B. Region 5, Office of Director. 9pp. 33292:022-33292:030.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010601 Monthly operating rept for Jul 1985. W/850807 ltr.
ULMER,F.J., ORSER,W.S. Portland General Electric Co. 85/07/31. 7pp. 32820:348-32820:355.

S. Reportable occurrences. LERs & related correspondence

8510010190 PNO-V-85-063 on 850924, reactor tripped due to loss of main feedwater pump. Caused by work on condensate demineralizer sys resulting in flow oscillations. Reactor will be taken to Mode 5 to repair pressurizer safety valves.
DODDS,R., RICHARDS,S. Region 5, Office of Director. 85/09/24. 1p. 32800:207-32800:207.

8510070013 LER 85-011-00 on 850828, incorrect calibr of pressurizer pressure transmitters, discovered in June 1985, determined reportable. Caused by noncompliance w/low pressure reactor trip setpoint requirement. W/850926 ltr.
BAUER,S.A., ORSER,W.S. Portland General Electric Co. 85/09/27. 5pp. 32900:011-32900:015.

8510160238 PNO-V-85-070 on 851008, two plant mod personnel received first & second degree burns on hands & arms due to fire in motor control ctr. Caused by short circuiting of bus bar by hand-held cordless drill.
PEREIRA,D., RICHARDS,S. Region 5, Office of Director. 85/10/08. 1p. 33023:236-33023:236.

8510280214 Special rept on 850919, during const, portions of masonry used for fire protection on structural steel removed from two support columns. Protective encasement will be restored by 851115.
ORSER,W.S. Portland General Electric Co. 85/10/11. MARTIN,J.B. Region 5, Office of Director. 1p. 33191:001-33191:001.

8510300300 LER 85-012-00 on 850924, reactor trip occurred due to lo-lo water level in steam generator D. Caused by personnel error resulting in sys flow oscillations. Training info bulletin prepared. W/851021 ltr.
BAUER,S.A., ORSER,W.S. Portland General Electric Co. 85/10/21. 4pp. 33258:005-33258:008.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

132 DOCKETED ITEMS

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8510070080** Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force report available. ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905:053-32905:157.
- 8407130320** Provides info in response to 810330 memo re Performance Appraisal Section 801027-31, 801101:03-07 & 17-21 insp. KEPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/22. SNIEZEK, J.H. Region 3, Chicago, Office of the Director. 2pp. 32911:169-32911:173.
- 8506270129** Forwards table of B&W plants comparing selected TMI actions from NUREG-1066, incomplete TMI items for facility listed per NUREG-0737, NUREG-0737 & Suppl 1 active items re post-implementation reviews also listed. THOMPSON, H.L. Division of Licensing. 85/06/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32910:274-32910:279.
- 8510070106** Forwards info to suppl 831216 submittal, including purchase order & 1983 annual fire protection & loss prevention program insp & audit report. HAVERLY, J.S. Toledo Edison Co. 83/12/29. LITTLE, W.S. Region 3, Office of Director. 19pp. 32906:228-32906:246.
- 8510070117** "Annual Fire Protection Audit of Davis-Besse Nuclear Power Station Unit 1." * Professional Loss Control, Inc. 81/07/31. 31pp. 32906:247-32906:356.
- 8510070214** Forwards description of 800419 event. Probably caused by breaker bumped by const workers in area. Sequence of events & summary of physical security insps encl. KEPLER, J.G. Region 3, Chicago, Office of the Director. 80/04/23. MOSELEY, N.C. Division of Reactor Operations Inspections. 10pp. 32911:096-32911:131.
- 8510160301** Reissued Rev 18 to Health Physics Procedure HP 1602.01, "External Personnel Radiation Exposure Monitoring." SCOTT, R., TAPLEY, J., BRIDEN, D.W. Toledo Edison Co. 85/09/13. 28pp. 33026:252-33026:279.
- 8510150391** Revised emergency plan implementing procedures, including Rev 9 to EI 1300.02 re unusual event & Rev 8 to EI 1300.07 re technical support ctr activation. REED, G.J., WELLS, C.E. Toledo Edison Co. 85/09/20. 32pp. 33010:240-33010:271.
- 8510310313** Responds to violations noted in Insp Rept 50-346/85-19 dtd 850806. Corrective actions: Administrative Procedure 1827.12, "Protective Action Guidelines" & Emergency Action Level EI 1300.01, "Emergency Plan Activation" to be reviewed. WILLIAMS, J. Toledo Edison Co. 85/09/20. HIND, J.A. Region 3, Office of Director. 2pp. 33271:291-33271:292.
- 8510040453** Rev 5 to Administrative Procedure AD 1827.04, "Overexposure/ Internal Contamination." * Toledo Edison Co. 85/09/24. 9pp. 32853:331-32853:339.
- 8510150393** Rev 12 to Emergency Plan Supporting Procedure AD 1827.02, "Medical Treatment of Injuries." PETERS, B., MURRAY, T.D. Toledo Edison Co. 85/09/24. 24pp. 33010:216-33010:239.
- 8510010331** Forwards list of facility change requests re fire protection scheduled for completion at end of fifth refueling outage to begin in Sept/Oct 1986. List prioritized 25 most important to nuclear safety. WILLIAMS, J. Toledo Edison Co. 85/09/26. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32801:272-32801:273.
- 8510280406** Provides status update on emergency plan training of shift technical advisors. Staff receiving same training as emergency duty officers. Staff will no longer automatically assume emergency duty officer function from supervisor. WILLIAMS, J. Toledo Edison Co. 85/09/30. SHAFER, W. Region 3, Office of Director. 1p. 33192:205-33192:205.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or enacted enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230268** Forwards Press Release 84-134 re NRC proposed fine against util for five alleged violations, including inadvertent shutdown of control room emergency ventilation sys. KAMMERER, C. Office of Congressional Affairs. 84/11/28. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, E. House of Rep. GLENN, J. Senate. 3pp. 33109:112-33109:114.
- 8510310234** Advises that Emergency Plan Procedure EI 1300.11 will be changed to allow implementation of recovery plan at classification above unusual event, in response to T Ploski 850925 request. WILLIAMS, J. Toledo Edison Co. 85/10/07. SHAFER, W. Region 3, Office of Director. 2pp. 33273:155-33273:156.
- 8510150198** Responds to 850909 ltr urging NRC to take necessary steps to improve safety & reliability at plant, based on 850609 loss of feedwater event. NRC reviewing util submittal & will issue SER. PALLADINO, N.J. Commissioners. 85/10/08. CELESTE, R.F. Ohio, State of. 6pp. 33030:212-33030:219.
- 8510280317** Revised emergency plan implementing procedures, including Rev 10 to EI 1300.04, "Site Area Emergency" & Rev 10 to EI 1300.05, "General Emergency." REED, G.J., WELLS, C.E. Toledo Edison Co. 85/10/15. 41pp. 33193:029-33193:070.
- 8510210152** Forwards Safeguards Insp Rept 50-346/85-26 on 850909-12 & notice of violation. Rept details & notice of violation withheld (ref 10CFR73.21). AXELSON, W.L. Region 3, Office of Director. 85/10/16. WILLIAMS, J. Toledo Edison Co. 2pp. 33071:138-33071:141.

-8510210153 Safeguards Insp Rept 50-346/85-26 on 850909-12. Noncompliance noted: intrusion detection sys coverage in some areas inadequate. Details withheld (ref 10CFR73.21). MAEDA, T.J., CHRISTOFFER, G., DROUIN, B. Region 3, Office of Director. 85/10/16. 2pp. 33192:140-33071:141.

8510280284 Temporary Mod Requests T-9673 & T-9664 for Procedures EI 1300.01.9, "Emergency Plan Activation" & EI 1300.06.7, "Operations Support Ctr Activation," respectively. GORDON, D.J., WASILK, J.S., BRIDEN, D.W. Toledo Edison Co. 85/10/16. 4pp. 33192:349-33192:352.

8510280368 Ack receipt of Jul 1985 Rev 9 to emergency plan. Rev consistent w/ 10CFR50.54(q) requirements. Commitment that util will notify govt agencies following declaration of emergency must be stated in next rev. SHAFER, W.D. Region 3, Office of Director. 85/10/21. WILLIAMS, J. Toledo Edison Co. 2pp. 33192:077-33192:078.

8510310325 Forwards Safety Insp Rept 50-346/85-34 on 851010-11. No violation noted. SHAFER, W.D. Region 3, Office of Director. 85/10/25. WILLIAMS, J. Toledo Edison Co. 2pp. 33272:038-33272:047.

-8510310330 Insp Rept 50-346/85-34 on 851010-11. No violation or deviation noted. Major areas inspected: emergency preparedness program, licensee procedures & training program for licensed operators re reporting of events to operations ctr. PLOSKI, T., PHILLIPS, M. Region 3, Office of Director. 85/10/24. 8pp. 33272:040-33272:047.

8510160055 Revised emergency plan supporting procedures, including Rev 3 to Administrative Procedure AD 1850.8, "Emergency Technical Assessment" & Temporary Mod T-9627 to Rev 7 to AD 1827.11.7, "Assembly, Accountability & Evacuation." * Toledo Edison Co. 85/10/31. 17pp. 33028:098-33028:122.

8510210072 Rev 9 to Emergency Plan Implementing Procedure EI 1300.03, "Alert." BRIDEN, D.W. Toledo Edison Co. 85/10/31. 14pp. 33072:071-33072:089.

8510280408 Temporary Mod Request T-9643 to Rev 10 to Emergency Plan Implementing Procedure EI 1300.08.10, "Emergency Control Ctr Activation." Section 6.2.4.2 re location of util emergency monitoring instructions changed. GORDON, D.J., SCOTT, WASLIK, J., BRIDEN, D.W. Toledo Edison Co. 85/10/31. 2pp. 33192:223-33192:224.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510220390 Summarizes ACRS ECCS Subcommittee 850827 meeting in Washington, DC re hydrodynamic loads in Mark I-III containment; resolution of USI A-43 on sump performance & feed & bleed calculations for Davis-Besse event. TIEN, C. California, Univ. of Berkeley, CA. TIEN, C. ACRS - Advisory Committee on Reactor Safeguards. 85/09/09. BOEHNER, P.A. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 33099:147-33099:148.

P. Operating license stage documents & correspondence

8510230117 Forwards application for amend to License NPF-3, revising Tech Specs re water source for auxiliary feedwater pumps, safety grade flow indication for flow verification & bases. WILLIAMS, J. Toledo Edison Co. 85/08/29. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33102:227-33102:238.

-8510230120 Application for amend to License NPF-3, identifying water source for auxiliary feedwater pumps, safety grade flow indication for flow verification & bases. WILLIAMS, J. Toledo Edison Co. 85/08/29. 5pp. 33102:229-33102:233.

-8510230122 Proposed Tech Spec changes, identifying water source for auxiliary feedwater pumps, safety grade flow indication used for flow verification & bases. * Toledo Edison Co. 85/08/29. 3pp. 33102:234-33102:236.

8510010086 Forwards Rev 9 to "Safety-Related Piping Sys Support & Hanger Discrepancies," summary rept. WILLIAMS, J. Toledo Edison Co. 85/09/20. KEPLER, J.G. Region 3, Office of Director. 1p. 32802:240-32802:276.

-8510010088 Rev 9 to "Safety-Related Piping Sys Support & Hanger Discrepancies," summary rept. * Toledo Edison Co. 85/09/17. 36pp. 32802:241-32802:276.

8510090039 Partial response to FOIA request for specified documents re facility App A documents available in PDR. Notice of charges & procedures for obtaining records from PDR encl W/o encl. FELTON, J.M. Division of Rules and Records. 85/09/26. WEBB, R.E. Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law). 3pp. 32964:019-32964:021.

8510010196 Informs that resubmittal of integrated living schedule program plan license amend request will be delayed due to commitments made in 850910 submittal. Meeting requested to discuss 850625 concerns re Generic Ltr 85-07. WILLIAMS, J. Toledo Edison Co. 85/09/30. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32800:106-32800:107.

8510040250 Advises that 850716 Rev 3 to Chapter 17.0 re QA program consistent w/ provisions of 10CFR50.54(2) & acceptable. Review assessed changes, including reduction in commitment re records storage & minor changes outlined in 841203 ltr. PAPERIELLO, C.J. Region 3, Office of Director. 85/09/30. WILLIAMS, J. Toledo Edison Co. 1p. 32851:111-32851:111.

8510040285 Forwards BAW-1882, "Analysis of Capsule TE1-A, Davis-Besse Nuclear Power Station, Unit 1, Reactor Vessel Matt Surveillance Program." Revised pressure-temp curves will be submitted prior to limit of 5 EFYs. WILLIAMS, J. Toledo Edison Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32852:287-32853:013.

-8510040289 "Analysis of Capsule TE1-A, Davis-Besse Nuclear Power Station, Unit 1, Reactor Vessel Matt Surveillance Program." * Babcock & Wilcox Co. 85/09/30. 89pp. 32852:288-32853:013.

8510080035 Forwards response to Question 2 of 850719 request for addl info re NUREG-0737, Item II.B.1 concerning expected blowdowns at current ring settings. Actual percent blowdown of safety valves has no adverse effect upon core cooling.
WILLIAMS, J. Toledo Edison Co. 85/10/01. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32918.295-32918.296.

8510160325 Summary of 850925 meeting w/Util, Delian Corp & Impell Corp at facility site re auxiliary feedwater sys improvements & reliability analyses. Viewgraphs & list of meeting attendees encl.
MCCRACKEN, C. Operating Reactors Branch 4. 85/10/09. Operating Reactors Branch 4. 30pp. 33035.300-33035.329.

8510160065 Informs that procedures re subcooling margin will be revised & approved prior to restart per 850715 ltr. Due to 850609 event, resources heavily allocated for completion of related investigations & corrective actions.
WILLIAMS, J. Toledo Edison Co. 85/10/10. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33027.212-33027.212.

8510160203 Identifies util actions to satisfy Generic Ltr 83-28, Items 3.2.2 & 3.2.3 requirements re ATWS, including 831107 initial response, 850610 addl info/schedule for implementation & 850910 summary of sys review & test program.
WILLIAMS, J. Toledo Edison Co. 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33026.301-33026.302.

8510160209 Advises that design work to satisfy 10CFR50.62 requirements re reduction of risks from ATWS events will be implemented by end of fifth refueling outage, pending NRC concurrence w/ B&W Owners Group Sept 1985 generic design requirements.
WILLIAMS, J. Toledo Edison Co. 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33021.295-33021.295.

8510280343 Forwards Rev 12 to "Seismic Category I Piping Sys Support & Hanger Discrepancies, Summary Rept."
WILLIAMS, J. Toledo Edison Co. 85/10/11. KEPLER, J.G. Region 3, Office of Director. 1p. 33193.111-33193.184.

-8510280346 Rev 12 to "Seismic Category I Piping Sys Support & Hanger Discrepancies, Summary Rept."
* Toledo Edison Co. 85/10/08. 73pp. 33193.112-33193.184.

8510170422 Notification of 851016 meeting w/Util in Bethesda, MD to discuss reliability analyses for auxiliary feedwater sys.
DE AGAZIO, A. Operating Reactors Branch 4. 85/10/15. DENTON, H., EISENHUT, D., EDISON, G. NRC - No Detailed Affiliation Given. 2pp. 33047.221-33047.222.

8510250018 Advises that 830714 request to dispose of dredgings from onsite settling basins on company-owned land acceptable. Environ assessment & finding of no significant impact encl.
LAINAS, G.C. Assistant Director for Operating Reactors. 85/10/15. CROUSE, R.P. Toledo Edison Co. 2pp. 33226.207-33226.216.

-8510250024 Environ assessment & finding of no significant impact re 830714 request for disposal of low level radwaste. Proposed action will have no significant impact on human environ.
LAINAS, G.C. Assistant Director for Operating Reactors. 85/09/30. 8pp. 33226.209-33226.216.

8510180005 Requests remittance of fee for 850910 application. Fee required prior to authorization of restart.
DIGGS, R.M. License Fee Management Branch. 85/10/16. WILLIAMS, J. Toledo Edison Co. 1p. 33075.067-33075.067.

8510220036 Forwards Rev 3 to findings, corrective actions & generic implications rept, "Toledo Edison - Main Steam Header Pressure." Rev 2 to course of action list also encl.
WILLIAMS, J. Toledo Edison Co. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 10pp. 33090.159-33090.213.

-8510220040 Rev 3 to findings, corrective actions & generic implications rept, "Toledo Edison - Main Steam Header Pressure."
HUSTON, L. Toledo Edison Co. MOISIDIS, N. CYGNA Energy Services. 85/10/03. 45pp. 33090.169-33090.213.

8510230025 Responds to 850930 request for addl info re Action Plan 16 contained in 850910 course of action. Bore size on inlet piping will not impair main steam safety valve performance. Flow testing will be performed.
WILLIAMS, J. Toledo Edison Co. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 4pp. 33101.348-33101.351.

8510250371 Requests approval to use alternative insp technique to satisfy inservice pressure testing requirements of ASME Code, Section XI, per 10CFR50.55a(a)(3). Details of technique explained in H.A.F.A. Intl, Inc Rept HAF A 135(P)(A).
WILLIAMS, J. Toledo Edison Co. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33172.183-33172.184.

8510300294 Grants request for withdrawal of 840815 inservice test relief request re testing of DHR sys Line Valves DH-11 & DH-12. Test Procedure ST 5051.03 modified to include visual insp & leakage measurement of DHR sys line.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/18. WILLIAMS, J. Toledo Edison Co. 2pp. 33259.347-33259.348.

8510310420 Forwards marked-up draft SAIC-85/1524-3, "Review of Licensee & Applicant Responses to Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2," technical evaluation rept.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/24. WILLIAMS, J. Toledo Edison Co. 17pp. 33278.207-33278.223.

8510290217 Requests withdrawal of application for amend to License NPF-3 to delete auxiliary feedwater pump turbine inlet steam pressure interlocks due to decision to retain switch interlocks within main steam lines.
WILLIAMS, J. Toledo Edison Co. 85/10/25. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33236.339-33236.339.

Q. Inspection reports, IE Bulletins & correspondence

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available.
ROBERTS, T.M. Commissioners. 85/07/17. MAF/KEY, E.J. House of Rep., Energy & Commerce. 1p. 32905.053-32905.157.

-8103190865 Forwards evaluation of IE insp program & assessment of regional implementation program. Div of Program Development & Appraisal will review concerns re insp program.
MOSELEY, N.C. Division of Program Development & Appraisal. 81/03/03. STELLO, V. Director's Office, Office of Inspection and Enforcement. 14pp. 32911.142-32911.155.

-8312230206 Forwards IE Insp Rept 50-346/83-23 describing meeting re regulatory improvement program.
DIRCKS, W.J. Office of the Executive Director for Operations. 83/12/12. GILINSKY, V. Commissioners. 1p. 32908.316-32909.045.

-8312230212 Forwards proposed transmittal memo & insp rept re regulatory improvement program. W/o encl.
DAVIS, A.B. Region 3, Office of Director. 83/12/07. REHM, T.A. Office of the Executive Director for Operations. 2pp. 32907.020-32907.027.

-8407130274 Forwards IE Mgt Meeting Rept 50-346/81-03 on 810303 re Performance Appraisal Section insp on 801027-31, 1101.03-07 & 17-21, notices of violation & deviation & related info.
KEPLER, J.G. Region 3, Chicago, Office of the Director. 81/05/01. MOSELEY, N.C. Division of Program Development & Appraisal. 1p. 32911.156-32911.173.

-8407130282 Forwards IE Mgt Meeting Rept 50-346/81-03 & notices of violation & deviation re Performance Appraisal Section Insp Rept 50-346/80-03 on 801027-31, 1101.03-07 & 17-21. App B withheld (ref 10CFR2.790).
KEPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/17. CROUSE, R.P. Toledo Edison Co. 2pp. 32911.157-32911.168.

-8407130287 Notice of violation from insp on 801027-31, 1101.03-07 & 17-21.
KEPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/17. 5pp. 32911.159-32911.163.

-8407130313 Notice of deviation from insp on 801027-31, 1101.03-07 & 17-21.
* Region 3, Chicago, Office of the Director. 81/04/17. 1p. 32911.164-32911.164.

-8407130317 IE Mgt Meeting Rept 50-346/81-03 on 810303. Major areas discussed: Performance Appraisal Section Insp Rept 50-346/80-03 on 801027-31, 1101.03-07 & 17-21. Portions withheld (ref 10CFR2.790).
REYES, L.A., ROGERS, W.G., WARNICK, R.F. Region 3, Chicago, Office of the Director. 81/04/17. 4pp. 32911.165-32911.168.

-8407130320 Provides info in response to 810330 memo re Performance Appraisal Section 801027-31, 801101.03-07 & 17-21 insp.
KEPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/22. SNIJEK, J.H. Region 3, Chicago, Office of the Director. 2pp. 32911.169-32911.173.

-8411210152 Forwards 22 potential enforcement findings referenced as unresolved items in Insp Rept 50-346/84-19. Requests followup on findings assigned preliminary classification Severity Level IV violations due to potential for reclassification.
GRACE, J.N. Division of QA, Safeguards & Insp Programs (830103-850212). 84/11/15. NORELIUS, C.E. Region 3, Office of Director. 28pp. 32909.275-32909.315.

-8501030255 Extends response date for Insp Rept 50-346/84-15 to 850115.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 84/12/26. WILLIAMS, J.P. Toledo Edison Co. 1p. 32909.241-32909.274.

-8502190399 Responds to 850102 memo recommending close monitoring of training program as test case of INPO accreditation program. SALP rept of 841204 indicates numerous training problems. Addl review of improvements will be conducted.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/02/12. ASSELSTINE Commissioners. 3pp. 32909.066-32909.068.

-8502190411 Suggests that facility training program be closely monitored as test case of INPO accreditation program.
ASSELSTINE, J.K. Commissioners. 85/01/02. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 32910.019-32910.020.

-8502190413 Informs that Commission wishes to include listed elements in policy statement on training. General course re enforcement action described.
CHILK, S.J. Office of the Secretary of the Commission. 84/11/28. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 32909.316-32909.318.

-8510070106 Forwards info to suppl 831216 submittal, including purchase order & 1983 annual fire protection & loss prevention program insp & audit rept.
HAVERLY, J.S. Toledo Edison Co. 83/12/29. LITTLE, W.S. Region 3, Office of Director. 19pp. 32906.228-32906.246.

-8510070108 Forwards JP Williamson 850204 ltr re SALP response. Views on meeting w/Util will be discussed during next trip.
KEPLER, J.G. Region 3, Office of Director. 85/02/08. DIRCKS, W.J. Office of the Executive Director for Operations. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 1p. 32909.046-32909.064.

-8510070115 Forwards draft documents proposing civil penalty action under general policy & procedure for NRC enforcement actions, submitted for review & concurrence.
SCHULTZ, W.H. Region 3, Office of Director. 85/06/18. AXELRAD, J.A. Enforcement Staff. 11pp. 32909.319-32909.359.

-8510070120 Forwards V Stello revised proposed memo to Commissioner Assestine re regulatory performance based on V Stello 850605 comments.
KEPLER, J.G. Region 3, Office of Director. 85/06/11. DIRCKS, W.J. Office of the Executive Director for Operations. 9pp. 32909.360-32910.008.

-8510070130 Forwards WJ Dircks draft memo to Commissioner Assestine, per request to provide update on status of regulatory performance.
KEPLER, J.G. Region 3, Office of Director. 85/06/05. DIRCKS, W.J. Office of the Executive Director for Operations. 10pp. 32910.009-32910.018.

134 DOCKETED ITEMS

-8510070131 Trip rept of 850207-08 site visit re status of licensee performance enhancement program & status of action plan being used to improve overall training effort.
SHAHER, W.D. Region 3, Office of Director. 85/02/26. NORELIUS, C.E. NRC - No Detailed Affiliation Given. 65pp. 32909:069-32909:133.

-8510070138 Informs of regulatory performance in connection w/plant & NPC actions to improve performance. Special attention will be devoted to licensee effectiveness in strengthening training & improving control room behavior.
KEPPLER, J.G. Region 3, Office of Director. 85/01/09. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 32909:134-32909:135.

-8510070161 Forwards info re status of performance enhancement program. Integrated implementation schedule expected to be developed by 840901.
PETERS, R.F. Toledo Edison Co. 84/07/20. SHAHER, W.D. Region 3, Office of Director. 38pp. 32907:035-32907:072.

-8510070214 Forwards description of 800419 event. Probably caused by breaker bumped by const workers in area. Sequence of events & summary of physical security insps encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 80/04/23. MOSELEY, N.C. Division of Reactor Operations Inspections. 10pp. 32911:096-32911:131.

-8510070220 Provides observations during recent Performance Appraisal Branch insps.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 80/12/08. HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 1p. 32911:132-32911:141.

-8510070269 Ack importance of recent insp finding of borated water storage tank over-temp condition by L. Reyes. Timely identification of safety related concerns beneficial in reaffirming on broad level resident insp program.
KEPPLER, J.G. Region 3, Chicago, Office of the Director (81/03/01). 82/01/20. SPESSARD, R.L. Division of Resident & Project Inspection. 1p. 32911:187-32911:194.

-8510070278 Requests assistance in inspecting QA program on priority basis since QA modules more than 6 months overdue. Licensee auditing staff cannot meet audit workload.
NORELIUS, C.E. Region 3, Office of Director. 83/07/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32911:209-32911:213.

8510310313 Responds to violations noted in Insp Rept 50-346/85-19 dtd 850806. Corrective actions: Administrative Procedure 1827.12, "Protective Action Guidelines" & Emergency Action Level E1 1300.01, "Emergency Plan Activation" to be reviewed.
WILLIAMS, J. Toledo Edison Co. 85/09/20. HIND, J.A. Region 3, Office of Director. 2pp. 33271:291-33271:292.

8510160112 Revises 850726 response to violations noted in Insp Rept 50-346/85-09 Administrative Procedure AD-1838.02, "Performance of Surveillance & Periodic Tests," will be revised by 851018.
WILLIAMS, J. Toledo Edison Co. 85/09/24. NORELIUS, C.E. Region 3, Office of Director. 2pp. 33023:228-33023:229.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:088.

-8510230045 Forwards notice of violation issued to util based on 850409-0531 insp.
KAMMERER, C. Office of Congressional Affairs. 85/07/16. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 1p. 33109:027-33109:038.

-8510230051 Forwards Press Release 85-95 re NRC proposed fine against util for alleged violations of safety requirements during Apr 1985.
KAMMERER, C. Office of Congressional Affairs. 85/07/15. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 3pp. 33109:039-33109:041.

-8510230268 Forwards Press Release 84-134 re NRC proposed fine against util for five alleged violations, including inadvertent shutdown of control room emergency ventilation sys.
KAMMERER, C. Office of Congressional Affairs. 84/11/28. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 3pp. 33109:112-33109:114.

-8510230274 Forwards Press Release 84-52 re NRC proposed fine against util for alleged safety violations, including failure to follow approved procedures during operation of startup feedwater pump.
KAMMERER, C. Office of Congressional Affairs. 84/12/03. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 2pp. 33109:115-33109:116.

8510150198 Responds to 850909 ltr urging NRC to take necessary steps to improve safety & reliability at plant based on 850809 loss of feedwater event. NRC reviewing util submittal & will issue SER.
PALLADINO, N.J. Commissioners. 85/10/06. CELESTER, R.F. Ohio, State of. 6pp. 33030:212-33030:219.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510210152 Forwards Safeguards Insp Rept 50-346/85-26 on 850909-12 & notice of violation. Rept details & notice of violation withheld (ref 10CFR73.21).
AXELSON, W.L. Region 3, Office of Director. 85/10/16. WILLIAMS, J. Toledo Edison Co. 2pp. 33071:138-33071:141.

-8510210153 Safeguards Insp Rept 50-346/85-26 on 850909-12. Noncompliance noted: intrusion detection sys coverage in some areas inadequate. Details withheld (ref 10CFR73.21).
MADEIRA, T.J., CHRISTOFFER, G., DROUIN, B. Region 3, Office of Director. 85/10/16. 2pp. 33071:140-33071:141.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510220323 Confirmatory Action Ltr CAL-RIII-85-13 re piping sys support insps/walkdowns, resulting engineering evaluations & corrective actions. Notification requested if plans differ from listed corrective actions.
KEPPLER, J.G. Region 3, Office of Director. 85/10/17. WILLIAMS, J. Toledo Edison Co. 3pp. 33084:125-33084:127.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250165 Forwards Safety Insp Rept 50-346/85-31 on 850909-18 & notice of violation.
HARRISON, J.J. Region 3, Office of Director. 85/10/18. WILLIAMS, J. Toledo Edison Co. 2pp. 33172:212-33172:225.

-8510250169 Notice of violation from insp on 850909-18.
HARRISON, J.J. Region 3, Office of Director. 85/10/18. 1p. 33172:214-33172:214.

-8510250173 Insp Rept 50-346/85-31 on 850909-18. Violations noted: failure to establish procedure to delineate IE Bulletin 79-14 design interface between Bechtel & ITT-Ginnell Corp & to implement facility change request sys.
YIN, I.T., DANIELSON, D.H. Region 3, Office of Director. 85/10/11. 11pp. 33172:215-33172:225.

8510250171 Requests approval to use alternative insp technique to satisfy inservice pressure testing requirements of ASME Code, Section XI, per 10CFR50.55(a)(3). Details of technique explained in H.A.F.A. Intl, Inc Rept H.A.F.A. 135(P)(A).
WILLIAMS, J. Toledo Edison Co. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33172:183-33172:184.

8510300294 Grants request for withdrawal of 840815 inservice test relief request re testing of DHR sys Line Valves DH-11 & DH-12. Test Procedure ST 5051.03 modified to include visual insp & leakage measurement of DHR sys line.
STOLZ, J.F. Operating Reactors Branch 4. 85/10/18. WILLIAMS, J. Toledo Edison Co. 2pp. 33259:347-33259:348.

8510310325 Forwards Safety Insp Rept 50-346/85-34 on 851010-11. No violation noted.
SHAHER, W.D. Region 3, Office of Director. 85/10/25. WILLIAMS, J. Toledo Edison Co. 2pp. 33272:038-33272:047.

-8510310330 Insp Rept 50-346/85-34 on 851010-11. No violation or deviation noted. Major areas inspected: emergency preparedness program, licensee procedures & training program for licensed operators re reporting of events to operations ctr.
PLOSKE, T., PHILLIPS, M. Region 3, Office of Director. 85/10/24. 8pp. 33272:040-33272:047.

R. Periodic operating reports & related correspondence

8510010410 Monthly operating rept for Jul 1985. W/850809 ltr.
KHAZAR, M., STORZ, L.F. Toledo Edison Co. 85/07/31. HALLER, N. Office of Resource Management, Director. 20pp. 32809:062-32809:081.

8510240023 State of OH EPA discharge monitoring rept for Sept 1985. W/ 851016 ltr.
WILLIAMS, J., STORZ, L.F. Toledo Edison Co. 85/09/30. 7pp. 33156:129-33156:135.

8510240039 Forwards wastewater rept for Sept 1985. Electric power to sampling station lost due to damage in structure circuitry panel. Power restored & sampling reinstated on 850930.
STORZ, L.F. Toledo Edison Co. 85/10/16. Ohio, State of. 1p. 33156:078-33156:084.

-8510240040 Wastewater rept for Sept 1985.
STORZ, L.F. Toledo Edison Co. 85/09/30. 6pp. 33156:079-33156:084.

S. Reportable occurrences, LERs & related correspondence

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available.
ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905:053-32905:216.

-8010010643 Summarizes status of util intentions re addl diverse powered auxiliary feedwater pump & recommends reserved judgment pending proposal submittal.
GARNER, D. Operating Reactors Branch 4. 80/09/11. NOVAK, T.M. Assistant Director for Operating Reactors. 2pp. 32907:103-32907:138.

-8302090513 Forwards evaluation of reliability study for auxiliary feedwater sys (AFS) based on BNL reliability analysis of upgraded AFS.
THADANI, A. Reliability & Risk Assessment Branch. 83/02/04. PARR, O. Auxiliary Systems Branch. 7pp. 32907:201-32907:216.

-8309060463 Forwards SER on TMI Action Item ILE 1.1, "Auxiliary Feedwater Sys Evaluation." Evaluation closes five open items identified in 820426 status rept.
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 83/08/29. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32908:019-32908:043.

- 8311290156 Comments on util performance & improvement program supporting util 831028 response to NRC 831017 ltr. Util safety responsive & safety conscious. RICE, C.M. LRS Consultants. 83/11/21. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 32906.227-32906.227.
- 8311290219 Responds to concerns expressed in 831017 ltr re util performance & improvement program, in connection w/831005 site visit & meeting. WILLIAMSON, J.P. Toledo Edison Co. 83/10/28. GILINSKY, V. Commissioners. 3pp. 32907.028-32907.030.
- 8311290224 Expresses concern re util performance, in connection w/831005 site visit & meeting. GILINSKY, V. Commissioners. 83/10/17. WILLIAMSON, J. Toledo Edison Co. 1p. 32911.214-32911.216.
- 8312010439 Provides evaluation of licensee 811231 auxiliary feedwater reliability study performed by BNL. Unavailability of auxiliary feedwater sys exceeds numerical criterion presented in SRP. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 83/11/16. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32908.069-32908.076.
- 8404170570 Encourages NRR preparation of CRGR package on safety-related electric auxiliary feedwater pump at facility. Interest heightened by 840302 stuck open safety valve event. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/04/09. EISENHUT, D.G. Division of Licensing. 1p. 32908.118-32908.118.
- 8406250404 Provides status of third auxiliary feedwater pump & diesel generator. Util initiated PRA study of auxiliary feedwater sys (AFS). Reliability of AFS in low range does not meet SRP Section 10.49 criteria. DE AGAZIO, A. Operating Reactors Branch 4. 84/06/20. LAINAS, G.C. Assistant Director for Operating Reactors. 2pp. 32909.137-32909.240.
- 8407250135 Requests special meeting w/util re diversity in auxiliary feedwater pump drives compliance w/TMI Action Item II.E.1.1, "Auxiliary Feedwater Sys." RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 84/07/18. LAINAS, G.C. Assistant Director for Operating Reactors. 2pp. 32908.198-32908.199.
- 8410150611 Discusses backfit issue on several serious safety concerns re auxiliary feedwater sys design, including lack of diverse pump drive & high unreliability of sys. Addition of electric motor driven pump would improve reliability. DE AGAZIO, A. Operating Reactors Branch 4. 84/10/09. LAINAS, G.C. Assistant Director for Operating Reactors. 3pp. 32908.204-32908.219.
- 8411290581 Forwards Auxiliary Sys Branch SER input re continued operation of start-up feedwater pump until installation of new sys completed. Limited interim use of existing startup feedwater pump acceptable. SALP evaluation also encl. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 84/11/20. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32910.035-32910.046.
- 8503220113 Discusses licensee 851121 ltr re conceptual design for adding motor driven startup feedwater pump (SUFP). Design mods listed. Licensee proposed Tech Specs for SUFP sys operability requested. PARR, O.D. Auxiliary Systems Branch. 85/03/12. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32910.047-32910.181.
- 8504030276 Informs that cooperation & support provided during recent mgt visit appreciated. Discussions & facility tour very informative. BRACHE, W. Regional Operations & Generic Requirements. 85/03/25. ROGERS, W.G. NRC - No Detailed Affiliation Given. 1p. 32911.74-32911.175.
- 8506260560 Forwards chronology re third diverse powered auxiliary feedwater pump per H Denton 850613 request. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 85/06/18. LAINAS, G.C. Assistant Director for Operating Reactors. 5pp. 32910.260-32910.264.
- 8506260595 Forwards Congressman Markey 85017 ltr re facility 850609 incident. Answers to assigned questions requested by C.O.B. 850621. Breakdown of responsibility for each question & response format also encl. THOMPSON, H.L. Division of Licensing. 85/06/19. KEPLER, J.G. Region 3, Office of Director. 2pp. 32910.265-32910.273.
- 8506260600 Expresses concern re 850609 incident at facility. Requests briefing on 850617 to subcommittee re facility incident & related matters. MARKEY, E.J. House of Rep., Energy & Commerce. 85/06/17. PALLADINO, N.J. Commissioners. 9pp. 32910.267-32910.273.
- 8506260705 Responds to 850617 verbal request for estimate of mean annual population dose from feedwater interruptions. Core melt caused by loss-of-feedwater could result in conditional mean person-rem of 12,000 w/range of 3,000-20,000. HULMAN, L.G. Accident Evaluation Branch. 85/06/18. MINNERS, W. Safety Program Evaluation Branch. 1p. 32910.259-32910.259.
- 8510070099 Provides recommendation on NUREG-0611 auxiliary feedwater reliability study re addition of third, qualified, motor driven emergency feedwater pump. ROWSOME, F.H. Division of Safety Technology. 83/03/01. PARR, O. THANDANIA, I. TSAO, J. NRC - No Detailed Affiliation Given. 1p. 32907.200-32907.200.
- 8510070102 Forwards revised responses to questions in Congressman Markey 850617 ltr re 850609 incident at facility. Rept of task force investigation of incident will be completed & made available by 850724. DIRCKS, W.J. Office of the Executive Director for Operations. 85/07/05. PALLADINO, N.J. Commissioners. 103pp. 32905.054-32905.157.
- 8510070123 Forwards operating procedures modified re 790517 order. Matrix itemizing procedures also encl. ROE, L.E. Toledo Edison Co. 79/05/23. RIED, R.N. Operating Reactors Branch 4. 4pp. 32905.334-32905.337.
- 8510070125 Forwards requested info & documentation summary re effort put forth to meet requirements of 10CFR50.48 & App R to 10CFR50.48 & Kaowool wraps, committed to in 820429 component cooling water pump room exemption request. CROUSE, R.P. Toledo Edison Co. 83/12/16. KEPLER, J.G. Region 3, Office of Director. 22pp. 32906.357-32907.018.
- 8510070133 Responds to 790508 request for info re overall reliability of auxiliary feedwater (AFW) sys w/regard to operating history & design improvements & 790504 commitment to verify adequacy of AFW sys capacity. ROE, L.E. Toledo Edison Co. 79/05/23. RIED, R.N. Operating Reactors Branch 4. 15pp. 32905.338-32906.183.
- 8510070155 Forwards notes & action items representing agreements w/util based on 831104 meeting. Response requested by 831114. DAVIS, A.B. Region 3, Office of Director. 83/11/07. SHAFFER, W. NRC - No Detailed Affiliation Given. 2pp. 32907.031-32907.034.
- 8510070167 Trip rept of 840703 site visit re training organization & programs. Program not implemented due to lack of senior mgt support. SHAFFER, W.D. Region 3, Office of Director. 84/07/05. NOELIUS, C.E. NRC - No Detailed Affiliation Given. 7pp. 32907.073-32907.102.
- 8510070184 Submits daily highlight. On 850609 reactor tripped when RCS temp & pressure increased due to Main Feedwater Pump 1 trip. Sequence of events provided. DE AGAZIO, A. Operating Reactors Branch 4. 85/06/11. DENTON, H. EISENHUT, D. EDISON, G. NRC - No Detailed Affiliation Given. 3pp. 32910.182-32910.258.
- 8510070192 Provides daily staff notes for 850611. Final rule amending 10CFR9 approved. Events at facilities discussed. DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/12. PALLADINO, N.J. ROBERTS, ASSELSTINE Commissioners. 21pp. 32911.022-32911.081.
- 8510070202 Forwards updated status of ten areas of corrective actions to improve mgt controls & plant operation. TAMBUNG, T.N. Region 3, Chicago, Office of the Director. 80/02/13. HEISHMAN, R.F. Region 3, Chicago, Office of the Director. 5pp. 32911.082-32911.095.
- 8510070214 Forwards description of 800419 event. Probably caused by breaker bumped by const workers in area. Sequence of events & summary of physical security insps encl. KEPLER, J.G. Region 3, Chicago, Office of the Director. 80/04/23. MOSELEY, N.C. Division of Reactor Operations Inspections. 10pp. 32911.096-32911.131.
- 8510070227 Discusses establishment of Region III study group due to 850609 loss of feedwater transient. Based on expanded roll of group, no time limit placed on longevity. Related info encl. NOELIUS, C.E. Region 3, Office of Director. 85/06/21. KEPLER, J.G. Region 3, Office of Director. 102pp. 32910.280-32911.021.
- 8510070262 Confirms discussion between T Tambung, J Smith & L Reyes on 810706-08. As result of evaluations of inadvertent 810624 reactor trip, listed corrective action plans initiated. CROUSE, R.P. Toledo Edison Co. 81/07/08. KEPLER, J.G. Region 3, Chicago, Office of the Director (81/03/01). 4pp. 32911.176-32911.186.
- 8510070273 Discusses 850612 & 13 telcons w/R Udell re incident on 850609. Facility only PWR which cannot be adequately protected w/HPCI alone. DAVIS, A.B. Region 3, Office of Director. 85/06/17. KEPLER, J.G. Region 3, Office of Director. 2pp. 32911.195-32911.208.
- 8510090031 FOIA request for documentation re 850609 event at facility, including Items 2.3 & 4 referenced in NUREG-1154, NUREG/CR-3530, NUREG-0737, Tech Specs per FSAR Chapter 16 & OL. WEBB, R.E. Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law). 85/08/29. FELTON, J.M. Division of Rules and Records. 3pp. 32964.016-32964.018.
- 8510010178 PNO-III-85-086 on 850923 & 24, seven of eight main steam safety valves failed to meet criteria during testing at Wylie Labs. Four valves leaked after reseating & lift setpoints of three lower than specs. Valves will be reset. BURGESS, B. CHRISSOTIMOS, N. Region 3, Office of Director. 85/09/26. 1p. 32800.104-32800.104.
- 8510110143 Forwards Rev 10 to "Safety-Related Piping Sys Support & Hanger Discrepancies," summary rept. "Disposition" column enhanced to provide brief description of discrepancy based on engineering evaluation. WILLIAMS, J. Toledo Edison Co. 85/09/26. KEPLER, J.G. Region 3, Office of Director. 1p. 32999.299-32999.346.
- 8510110144 Rev 10 to "Safety-Related Piping Sys Support & Hanger Discrepancies," summary rept. * Toledo Edison Co. 85/09/24. 46pp. 32999.300-32999.346.
- 8510070516 Forwards documents re NRC response to 850609 Davis-Besse incident, per 850920 request. IE & Region III documents will be forwarded upon receipt. Documents should be withheld from public disclosure, pending review completed on 851001. PALLADINO, N.J. Commissioners. 85/09/30. MARKEY, E. House of Rep., Energy & Commerce. 4pp. 32901.026-32901.029.
- 8510070518 Forwards documents re Representative Markey 850920 request. Region III & IE supporting documents will be forwarded upon receipt. Documents also re-processed to Udall 850919 request w/exception of rept of maint insps available in late Oct. REHM, T. Office of the Executive Director for Operations. 85/09/26. FAY, E. Office of Congressional Affairs. 8pp. 32901.030-32901.037.
- 8510070504 Forwards matl applicable to Representative Markey 850930 request, including only documents in NRR files. Transcript of Commission 850918 & 19 briefings by util & Chairman Palladino 850828 memo unavailable. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/09/25. REHM, T. Office of the Executive Director for Operations. 3pp. 32901.020-32901.037.
- 8510070506 Discusses Udall requests for matl in preparation for Markey Subcommittee hearing, including project manager responses re operating nuclear power plants where corrective action outstanding for extended period. DELMEDICO, J. NRC - No Detailed Affiliation Given. 85/09/19. REHM, T. NRC - No Detailed Affiliation Given. 2pp. 32901.023-32901.024.
- 8510070511 Requests listed documents in preparation for Subcommittee on Energy Conservation & Power upcoming hearing on Davis-Besse incident, including all documents generated in response to WJ Dircks 850905 memo to Commission. MARKEY, E.J. House of Rep., Energy & Commerce. 85/09/20. PALLADINO, N.J. Commissioners. 1p. 32901.025-32901.025.
- 8510030229 Staff requirements memo re 850918 continued briefing in Washington, DC on 850609 event. Plant maint suggested topic of discussion for next meeting w/Nuclear Util Mgt & Human Resources Committee. CHILK, S.J. Office of the Secretary of the Commission. 85/10/01. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 32849.200-32849.201.

136 DOCKETED ITEMS

8510090009 Rev 1 to "Davis-Besse Course of Action." W/51001 ltr. WILLIAMS, J. Toledo Edison Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 96pp. 32934.244-32934.339.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965.021-32965.047.

8510090008 LER 85-017-00 on 850906, during auxiliary steam testing of auxiliary feed pump 1-1, steam generator 1-1 pressurized to more than 237 psig w/secondary fluid temp less than 110 F. Caused by personnel error. Personnel counseled. W/851004 ltr. MICHAELIS, J., STORZ, L.F. Toledo Edison Co. 85/10/04. 4pp. 32934.353-32934.358.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030.243-33030.265.

8510150198 Responds to 850909 ltr urging NRC to take necessary steps to improve safety & reliability at plant, based on 850609 loss of feedwater event. NRC reviewing util submittal & will issue SER. PALLADINO, N.J. Commissioners. 85/10/08. CELESTE, R.F. Ohio, State of. 6pp. 33030.212-33030.219.

8510150206 Expresses concerns re 850609 event at plant which resulted in loss of all feedwater. Deficiencies cited must be fully corrected before plant returns to operation. NRC urged to take necessary steps. CELESTE, R.F. Ohio, State of. 85/09/09. PALLADINO, N.J. Commissioners. 2pp. 33030.218-33030.219.

8510150421 Forwards comments re Incident Investigation Program improvement for future team efforts, in response to 850822 memo. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/09. HELTEMES, C.J. AEDD, Director's Office. 8pp. 33033.206-33033.237.

8507090487 Requests Commission approval of plans to improve existing program for investigation of significant operational events. DIRCKS, W.J. Office of the Executive Director for Operations. SECY-85-208. 85/06/10. 8pp. 33033.227-33033.234.

8510150425 Expresses concern w/SECY-85-208 re Incident Investigation Program. SECY-85-208 would not ensure adequate investigation of events & may create unfavorable impression of NRC. HAYES, B.B. Office of Investigation. 85/07/05. CHILK, S.J. Office of the Secretary of the Commission. 3pp. 33033.235-33033.237.

8510220368 Forwards "Independent Mgt Assessment of Toledo Edison Davis-Besse QA Program" & "Rept of Assessment of Actions at Davis-Besse Resulting From 850609 Loss of Feedwater Event." WILLIAMS, J. Toledo Edison Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33084.276-33085.074.

8510220370 "Independent Mgt Assessment of Toledo Edison Davis-Besse QA Program." RAMSETT, L., KISHBAUGH, T. CER Corp. 85/10/04. 63pp. 33084.277-33084.342.

8510220373 "Rept of Assessment of Actions at Davis-Besse Resulting From 850609 Loss of Feedwater Event." * Basic Energy Technology Associates. 85/08/30. 94pp. 33084.343-33085.074.

8510230013 Forwards B&W evaluation of 850906 pressurization of Once-Through Steam Generator 1.1. Event had no adverse structural effect & steam generator remains acceptable for continued operation at full power conditions. WILLIAMS, J. Toledo Edison Co. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 22pp. 33101.109-33101.130.

8510290357 Forwards Rev 13 to "Seismic Category I Piping Sys Support & Hanger Discrepancies, Summary Rept." Rept updated weekly to notify of any new discrepancies. WILLIAMS, J. Toledo Edison Co. 85/10/21. KEPPLER, J.G. Region 3, Office of Director. 1p. 33234.001-33234.096.

8510290359 "Seismic Category I Piping Sys Support & Hanger Discrepancies." * Toledo Edison Co. 85/10/15. 95pp. 33234.002-33234.096.

8510290073 Discusses 851105 meeting w/NRC to discuss actions planned re 850609 facility transient. Topics will include description of timetable, illustration of types of actions planned & special task force action. TUCKER, H.B. Babcock & Wilcox Operating Plants Owners Group. 85/10/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 2pp. 33236.114-33236.115.

T. Hearing transcripts on non-antitrust matters

8510100164 Transcript of ACRS Subcommittee on Davis-Besse 851004 meeting in Oak Harbor, OH re review of course of action prior to restart of plant. Pp 1-117. * ACRS - Advisory Committee on Reactor Safeguards. 85/10/04. 118pp. 32961.230-32961.349.

U. Congressional/Executive Correspondence

8510070516 Forwards documents re NRC response to 850609 Davis-Besse incident, per 850920 request. IE & Region III documents will be forwarded upon receipt. Documents should be withheld from public disclosure, pending review completed on 851001. PALLADINO, N.J. Commissioners. 85/09/30. MARKEY, E. House of Rep., Energy & Commerce. 4pp. 32901.026-32901.029.

8510070518 Forwards documents re Representative Markey 850920 request. Region III & IE supporting documents will be forwarded upon receipt. Documents also responsive to Udall 850919 request w/exception of rept of maint insp available in late Oct. REHM, T.A. Office of the Executive Director for Operations. 85/09/26. FAY, E. Office of Congressional Affairs. 8pp. 32901.030-32901.037.

8510070504 Forwards mail applicable to Representative Markey 850930 request, including only documents in NRR files. Transcript of Commission 850918 & 19 briefings by util & Chairman Palladino 850828 memo unavailable. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/09/25. REHM, T. Office of the Executive Director for Operations. 3pp. 32901.020-32901.037.

8510070508 Discusses Udall requests for matts in preparation for Markey Subcommittee hearing, including project manager responses re operating nuclear power plants where corrective action outstanding for extended period. DELMEDICO, J. NRC - No Detailed Affiliation Given. 85/09/19. REHM, T. NRC - No Detailed Affiliation Given. 2pp. 32901.023-32901.024.

8510070511 Requests listed documents in preparation for Subcommittee on Energy Conservation & Power upcoming hearing on Davis-Besse incident, including all documents generated in response to WJ Dircks 850905 memo to Commission. MARKEY, E.J. House of Rep., Energy & Commerce. 85/09/20. PALLADINO, N.J. Commissioners. 1p. 32901.025-32901.025.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rule and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

8510230045 Forwards notice of violation issued to util based on 850409-0531 insp. KAMMERER, C. Office of Congressional Affairs. 85/07/16. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 1p. 33109.027-33109.038.

8510230051 Forwards Press Release 85-95 re NRC proposed fine against util for alleged violations of safety requirements during Apr 1985. KAMMERER, C. Office of Congressional Affairs. 85/07/15. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 3pp. 33109.039-33109.041.

8510230266 Forwards Press Release 84-134 re NRC proposed fine against util for five alleged violations, including inadvertent shutdown of control room emergency ventilation sys. KAMMERER, C. Office of Congressional Affairs. 84/11/28. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 3pp. 33109.112-33109.114.

8510230274 Forwards Press Release 84-52 re NRC proposed fine against util for alleged safety violations, including failure to follow approved procedures during operation of startup feedwater pump. KAMMERER, C. Office of Congressional Affairs. 84/12/03. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 2pp. 33109.115-33109.116.

8510150198 Responds to 850909 ltr urging NRC to take necessary steps to improve safety & reliability at plant, based on 850609 loss of feedwater event. NRC reviewing util submittal & will issue SER. PALLADINO, N.J. Commissioners. 85/10/08. CELESTE, R.F. Ohio, State of. 6pp. 33030.212-33030.219.

8510150206 Expresses concerns re 850609 event at plant which resulted in loss of all feedwater. Deficiencies cited must be fully corrected before plant returns to operation. NRC urged to take necessary steps. CELESTE, R.F. Ohio, State of. 85/09/09. PALLADINO, N.J. Commissioners. 2pp. 33030.218-33030.219.

V. Operator Examinations

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available. ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905.053-32905.157.

8502190399 Responds to 850102 memo recommending close monitoring of training program as test case of INPO accreditation program. SALP rept of 841204 indicates numerous training problems. Addl review of improvements will be conducted. DIRCKS, W.J. Office of the Executive Director for Operations. 85/02/12. ASSELSTINE, Commissioners. 3pp. 32909.066-32909.068.

8502190413 Informs that Commission wishes to include listed elements in policy statement on training. General course re enforcement action described. CHILK, S.J. Office of the Secretary of the Commission. 84/11/28. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 32909.316-32909.318.

8510070112 Forwards Dircks 850212 memo to Commissioner Assestine suggesting that NRC closely monitor training program. KEPPLER, J.G. Region 3, Office of Director. 85/02/19. NORELIUS, C.E. NRC - No Detailed Affiliation Given. 1p. 32909.065-32909.065.

8510070142 Trip rept of 850315 site visit re presentation of licenses to senior reactor operators & reactor operators. Subs discussed during visit stated. DAVIS, A.B. Region 3, Office of Director. 85/03/15. KEPPLER, J.G. Region 3, Office of Director. 1p. 32909.136-32909.136.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8509110513 Forwards monthly operating repts for June 1985. Rev 1 to offsite dose calculation manual, including all monitoring & sampling stations at plant, also encl. W/O Rev 1. McDONALD, R.P. Alabama Power Co. 85/07/15. Office of Resource Management, Director. 1p. 33036.100-33036.117.

—8510160195 Rev 1 to FNP-0-M-011, "Offsite Dose Calculation Manual."
* Alabama Power Co. 85/05/21. 15pp. 33036:103-33036:117.

8510090036 Rev 10 to emergency plan W/850924 ltr.
HUDSPETH,J.B. Alabama Power Co. 85/09/24. MCKNIGHT,J. Record Services Branch (Document Control Desk). 1,100pp. 32936:001-32941:256.

8510150124 Rev 38 to Emergency Implementing Procedure FNP-0-EIP-8, "Emergency Communications." W/851008 ltr.
HUDSPETH,J.B. Alabama Power Co. 85/10/08. MCKNIGHT,J. Record Services Branch (Document Control Desk). 36pp. 33008:319-33008:354.

8510160246 Forwards attachment to Procedure FNP-85-1072 re on-call schedules & requests that old revs be discarded. Requests transmittal form be signed & returned to listed address.
HUDSPETH,J.B. Alabama Power Co. 85/10/11. MCKNIGHT,J. Record Services Branch (Document Control Desk). 2pp. 33024:347-33024:354.

—8510160276 Attachment to Procedure FNP-85-1072 re on-call schedules concerning both plant & nuclear generation personnel. Schedules effective 851001.
WOODARD,J.D. Alabama Power Co. 85/10/11. 6pp. 33024:349-33024:354.

8510280034 Forwards Technical Support Ctr SPDS display implementation plan, per 841130 commitment.
MCDONALD,R.P. Alabama Power Co. 85/10/16. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 33191:015-33191:016.

8510250236 Forwards revised 10CFR50, App R fire protection exemption requests as result of NRC audit during wk of 850719 of util 850313,0626 & 0719 exemption requests. Mode will be completed no later than Second Quarter 1986.
MCDONALD,R.P. Alabama Power Co. 85/10/18. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 145pp. 33168:238-33169:022.

8510250428 Forwards revised requests for exemption from requirements of 10CFR50, App R for fire areas. Revs deemed necessary based on NRC audit during wk of 850819.
MCDONALD,R.P. Alabama Power Co. 85/10/18. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 100pp. 33170:008-33170:106.

H. General correspondence

8510150188 Provides rev to distribution lists for all correspondence. JD Woodard should be added to list.
MCDONALD,R.P. Alabama Power Co. 85/10/04. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 1p. 33008:297-33008:297.

P. Operating license stage documents & correspondence

8510040125 Rev 18 to Emergency Plan Implementing Procedure FNP-0-EIP-9, "Radiation Exposure Estimation & Classification of Emergencies." W/850923 ltr.
HUDSPETH,J.B. Alabama Power Co. 85/09/23. MCKNIGHT,J. Record Services Branch (Document Control Desk). 5pp. 32851:203-32851:207.

8510150285 Informs that util will finalize plans for ATWS mitigating scram actuation circuitry implementation & develop detailed schedule within 90 days of tentatively scheduled Nov 1985 issuance of SER.
MCDONALD,R.P. Alabama Power Co. 85/10/04. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 33009:111-33009:112.

8510160081 Forwards fee for application for inservice testing of refueling water storage tank check valves, in response to 850923 request.
MCDONALD,R.P. Alabama Power Co. 85/10/08. DIGGS,R.M. Office of Nuclear Reactor Regulation, Director. 1p. 33028:006-33028:006.

8510180134 Forwards proposed schedule for completion of 1985/1986 licensing items, including inservice insp code relief for 10-yr reactor vessel exam, administrative offsite & onsite organizational changes & removal of rod bow penalty.
MCDONALD,R.P. Alabama Power Co. 85/10/14. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 33055:049-33055:052.

8510310222 Requests assistance in reviewing encl util 850919 proposed administrative Tech Spec change, implementing listed mgt changes. SER & SALP input requested by 851031.
THOMPSON,H.L. Division of Licensing. 85/10/21. WALKER,R.D. Region 2, Office of Director. 2pp. 33277:317-33277:344.

Q. Inspection reports, IE Bulletins & correspondence

8510070349 Responds to violations noted in Insp Repts 50-348/85-33 & 50-364/85-33. Corrective actions: engineering evaluation will be performed to determine acceptability of welding activities performed on listed maint work requests.
MCDONALD,R.P. Alabama Power Co. 85/09/26. VERRELLI,D.M. Region 2, Office of Director. 4pp. 32877:248-32877:251.

8510070490 Responds to violations noted in Insp Repts 50-348/85-34 & 50-364/85-34. Corrective actions: 84 drums of sludge lance filters buried following collection & solidification of all free standing water approved.
MCDONALD,R.P. Alabama Power Co. 85/09/26. VERRELLI,D.M. Region 2, Office of Director. 5pp. 32878:128-32878:132.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070365 Ack receipt of 850816 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-348/85-25 & 50-364/85-25. Requests that responses to Violations 1b, 2a, 3 & 4 be resubmitted within 30 days.
GRACE,J.N. Region 2, Office of Director. 85/10/01. MCDONALD,R.P. Alabama Power Co. 6pp. 32878:259-32878:264.

8510180342 Ack receipt of 850926 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-348/85-33.
WALKER,R.D. Region 2, Office of Director. 85/10/07. MCDONALD,R.P. Alabama Power Co. 1p. 33061:290-33061:290.

8510180134 Forwards proposed schedule for completion of 1985/1986 licensing items, including inservice insp code relief for 10-yr reactor vessel exam, administrative offsite & onsite organizational changes & removal of rod bow penalty.
MCDONALD,R.P. Alabama Power Co. 85/10/14. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 33055:049-33055:052.

8510180359 Forwards three addl requests for relief from inservice insp program for ASME Code Class 1, 2 & 3 components re reactor vessel flange ligaments & visual exam of reactor coolant pump casing pressure boundary surfaces. Fee paid.
MCDONALD,R.P. Alabama Power Co. 85/10/14. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 6pp. 33062:244-33062:250.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510180334 Forwards fee inadvertently omitted from encl util 851014 request for relief from certain requirements of ASME Code, Section XI.
Alabama Power Co. 85/10/15. NRC - No Detailed Affiliation Given. 1p. 33062:148-33062:154.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8509110513 Forwards monthly operating repts for June 1985. Rev 1 to offsite dose calculation manual, including all monitoring & sampling stations at plant, also encl. W/0 Rev 1.
MCDONALD,R.P. Alabama Power Co. 85/07/15. Office of Resource Management, Director. 1p. 33036:100-33036:117.

—8510160195 Rev 1 to FNP-0-M-011, "Offsite Dose Calculation Manual."
* Alabama Power Co. 85/05/21. 15pp. 33036:103-33036:117.

8510010635 Monthly operating rept for Jul 1985 W/850812 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/07/31. 5pp. 32820:240-32820:244.

8510220101 Monthly operating rept for Sept 1985 W/851017 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/09/30. 5pp. 33095:125-33095:129.

S. Reportable occurrences, LERs & related correspondence

8510020001 LER 85-014-00 on 850828, ESF equipment actuation occurred when diesel generator 2C started automatically. Caused by technician accidentally bumping manual operator of emergency start relay. Technician counseled W/850923 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/09/23. 2pp. 32827:349-32827:350.

8510170401 LER 85-016-00 on 851002, plant experienced electrical shorts between conductors in GE Series 100 low voltage control electrical containment penetration modules. Caused attributed to separated adjacent connectors.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/10/09. 5pp. 33053:279-33053:283.

8510300307 LER 85-015-00 on 850925, determined that positive & negative rate trip settings existing before 850619 outside Tech Spec tolerance. Caused by incorrect interpretation of vendor info. Procedure revised W/851014 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/10/14. 4pp. 33258:001-33258:004.

8510300248 LER 85-001-01 on 850214, gaps along portions of tops of two fire walls not sealed within 7 days as required by Tech Spec 3.7.12. Firewatch patrols established. Design changes developed & implemented for sealing gaps. W/851021 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/10/21. 3pp. 33258:125-33258:127.

8510300313 LER 85-012-01 on 850623, reactor trip occurred due to high negative flux rate. Caused by shutdown bank & control rods E-11 & L-11 dropping into core due to electrical short. Fuses replaced & cables reterminated. Module ordered W/851025 ltr.
WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 85/10/25. 2pp. 33258:172-33258:173.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 2pp. 32862:049-32862:075.

8510280294 Forwards operator licensing & requalification exam schedules for FY86-FY89, per Generic Ltr 85-18, in response to 850927 request.
MCDONALD,R.P. Alabama Power Co. 85/10/21. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 3pp. 33192:066-33192:068.

138 DOCKETED ITEMS

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppl & correspondence

8510290367 Forwards "Preservice Insp Summary Rpt for Reactor Pressure Vessel," as partial response to NUREG-0991, Confirmatory Issue 12 (Sections 5.2.4.3 & 6.6.3). KEMPER, J.S. Philadelphia Electric Co. 85/10/22. BUTLER, W.R. Licensing Branch 2. 2pp. 33234-097-33234-333.

F. Security, medical, emergency & fire protection plans

8510170007 Advises that portions of 850402 rev to physical security plan consistent w/ provisions of 10CFR50.54(p) & acceptable. Plan should be modified & corrected page revs submitted for unacceptable portions within 30 days of ltr receipt. MARTIN, T.T. Region 1, Office of Director. 85/09/24. BAUER, E.G. Philadelphia Electric Co. 4pp. 33053-217-33053-220.

8510070243 Responds to util 850912 request for review of existing ltr of agreement between Region 1 & util, dtd 840912. Criteria of Region 1 incident response suppl to NUREG-0845 cited as basis for activities during incidents. MURLEY, T.E. Region 1, Office of Director. 85/09/30. COONEY, M.J. Philadelphia Electric Co. 4pp. 32878-076-32878-081.

-8510070247 Forwards current agreement re NRC emergency response to nuclear incidents for review, per NUREG-0654, Rev 1. T.E. Murley 850926 signature to statement that 840912 agreement shall remain in effect appended. COONEY, M.J. Philadelphia Electric Co. 85/09/12. MURLEY, T.E. Region 1, Office of Director. 2pp. 32878-080-32878-081.

8510080268 Forwards revs to plant security personnel training & qualification plan. Revs withheld (ref 10CFR73.21 & 2.790). BRADLEY, E.J. Philadelphia Electric Co. 85/10/01. Region 1, Office of Director. 4pp. 32913-308-32913-311.

8510150069 Forwards correspondence & documentation re emergency planning among applicant, NRC, Commonwealth of PA & other responsible governmental agencies, per ASLB 820601 order. Related correspondence. CULLEN, E.J. Philadelphia Electric Co. #485 717. 85/10/04. ZITZER, P. Ecology Action of Pottstown. 450pp. 33029-180-33030-210.

8510160048 Forwards Safety Insp Rpt 50-352/85-33 on 850808 No violation noted. MARTIN, T.T. Region 1, Office of Director. 85/10/08. DALTROFF, S.L. Philadelphia Electric Co. 4pp. 33027-176-33027-183.

-8510160051 Insp Rpt 50-352/85-33 on 850808 No violation noted. Major areas inspected: emergency preparedness training program for security force at site. VITO, D.J., AMATO, C.G., HARPSTER, T.L. Region 1, Office of Director. 85/10/07. 4pp. 33027-180-33027-183.

8510290076 Revised emergency plan implementing procedures, including Rev 9 to EP-102 re unusual event response, Rev 12 to EP-103 re alert response & Rev 11 to EP-104 re site emergency response. W/851024 ltr. DALTROFF, S.L. Philadelphia Electric Co. 85/10/24. MURLEY, T.E. Region 1, Office of Director. 56pp. 33236-057-33236-113.

G. Adjudicatory correspondence

8510030005 Informs that HJ McGurran will appear at 851011 oral argument. Related correspondence. MCGURRAN, H.J. Hearing Branch 1. #485 658. 85/09/27. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32843-194-32843-195.

8510100106 Motion to reopen record re gross alpha, Ra-226 & Ra-228 levels found in well water near reactor, based on new Commonwealth of PA Div of Environ Resources regulations. ROMANO, F.R. Air and Water Pollution Patrol. #485 674. 85/09/27. Atomic Safety and Licensing Board Panel. 3pp. 32960-107-32960-109.

8510020150 Forwards RL Anthony 850926 postcard re 851011 oral argument on ASLB third partial initial decision. Served on 851001. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 651. 85/09/30. CLEMENTS, W.L. Docketing & Services Branch. 1p. 32824-330-32824-331.

-8510020155 Expresses appreciation for opportunity to present oral argument on 851011 re ASLB third partial initial decision. ANTHONY, R.L. Anthony, R.L. 85/09/26. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32824-331-32824-331.

8510030011 Informs of appearance to present oral argument on 851011 re appeals of third partial initial decision in proceeding, per 850829 order. Related correspondence. RADER, R.M. Conner & Wetterhahn. RADER, R.M. Philadelphia Electric Co. #485 653. 85/09/30. SHOEMAKER, J. Atomic Safety and Licensing Appeal Panel. 1p. 32844-334-32844-334.

8510110017 Petition to require util to comply w/requirements of License NPF-39 & withdraw applications to Delaware River Basin Commission to Lower Schuylkill river flow restraint & permit releases from Beechwood pit. ANTHONY, R.L. Anthony, R.L. Friends of the Earth. #485 732. 85/10/01. Docketing & Services Branch. 2pp. 32973-277-32973-278.

8510100189 Notice of receipt of encl 850927 Air & Water Pollution Patrol motion to reopen record on new Commonwealth of PA, Div of Environ Resources regulations re gross alpha, Ra-226 & Ra-228. Served on 851006. HOYT, H.F. Atomic Safety and Licensing Board Panel. #485 688. 85/10/04. 1p. 32962-120-32962-123.

-8510100202 Motion for NRC to reopen record based on new Commonwealth of PA, Div of Environ Resources regulations re gross alpha, Ra-226 & Ra-228. ROMANO, F.R. Air and Water Pollution Patrol. 85/09/27. Atomic Safety and Licensing Board Panel. 3pp. 32962-121-32962-123.

8510150349 Informs that P Zitzer & D Stone will represent Limerick Ecology Action, Inc at 851011 oral argument in response to ASLB 850829 order. ZITZER, P. Limerick Ecology Action. #485 762. 85/10/04. SHOEMAKER, C.J. Atomic Safety and Licensing Board Panel. 1p. 33000-341-33000-341.

8510110063 Response to Graterford Inmates 850725 & Air & Water Pollution Patrol 850726 appeals from Appeal Board 850612 order & fourth partial initial decision. W/ Certificate of Svc. HASSELL, D.F. Hearing Branch 2. MCGURRAN, H.J. Hearing Branch 1. #485 718. 85/10/08. Atomic Safety and Licensing Appeal Panel. 57pp. 32972-051-32972-107.

8510110219 Notice of withdrawal of appearance in proceeding Certificate of Svc encl. HASSELL, D.F. Hearing Branch 2. #485 736. 85/10/09. 3pp. 32972-279-32972-281.

8510110157 Order denying Graterford Inmates & R Anthony/Friends of the Earth requests that Commission stay NRC orders authorizing issuance of full power license. Served on 851010. CHILK, S.J. Office of the Secretary of the Commission. #485 752. 85/10/10. Graterford Inmates. 3pp. 32972-245-32972-247.

8510210038 Response opposing Air & Water Pollution Patrol (AWPP) 850927 motion to reopen record to admit previously denied contention re drinking water monitoring requirements. AWPP failed to meet three criteria for reopening closed record. CONNER, T.B. Philadelphia Electric Co. CONNER, T.B. Conner & Wetterhahn. #485 832. 85/10/17. Atomic Safety and Licensing Appeal Panel. 16pp. 33072-324-33072-339.

8510230255 Decision ALAB-819 affirming ASLB Second Partial Initial Decision LBP-84-31, except insofar as ASLB decision approves util onsite emergency plan medical arrangements. Issue reversed & remanded. Served on 851023. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 872. 85/10/22. 101pp. 33103-051-33103-151.

8510240279 Forwards Commonwealth of PA court decision finding Bucks County & Neshaminy Water Resources Authority obligated to complete Point Pleasant project. Related correspondence. CONNER, T.B. Conner & Wetterhahn. CONNER, T.B. Philadelphia Electric Co. #485 876. 85/10/22. CHILK, S.J. Office of the Secretary of the Commission. 38pp. 33154-268-33154-303.

8510290001 Response opposing Air & Water Pollution Patrol (AWPP) 851002 motion to reopen record. AWPP failed to state contention w/basis & specificity & satisfy regulations for admitting late-filed contention. Certificate of Svc encl. HODGDON, A.P. Hearing Branch 2. #485 940. 85/10/22. Atomic Safety and Licensing Appeal Panel. 15pp. 33233-233-33233-248.

8510310319 Forwards Commonwealth of PA Emergency Mgt Svcs Act, Pamphlet Law 1322, in response to ASLB 851011 request during aural or oral argument. W/o encl. Related correspondence. FERKIN, Z.G. Pennsylvania, Commonwealth of. #485 971. 85/10/23. KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 1p. 33272-064-33272-064.

8510290008 Order scheduling 851204 oral argument in Bethesda, MD on Graterford Inmates & Air & Water Pollution Patrol appeals of ASLB 850722 Fourth Partial Initial Decision LBP-85-25. Served on 851024. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 944. 85/10/24. Office of the Executive Legal Director. 2pp. 33236-351-33236-352.

8510310195 Confirms recent telcon re need for filing answers to discovery requests w/ Ofc of Secretary. Judges Kohl & Hoyt agree that answers should not be filed w/ Secretariat if answers not delivered to Boards. Related correspondence. CLEMENTS, W.L. Docketing & Services Branch. #485 977. 85/10/28. CULLEN, E.J. Philadelphia Electric Co. 1p. 33274-043-33274-043.

8510310359 Order directing licensee to submit proposal to resolve remanded issue re back-up medical arrangements necessary to satisfy requirements for onsite emergency plan medical arrangements for onsite personnel. Served on 851026. HOYT, H.F. Atomic Safety and Licensing Board Panel. #485 968. 85/10/28. Office of the Executive Legal Director. 2pp. 33271-334-33271-335.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510070232 Forwards Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing. Rev 44 to FSAR also encl. BRADLEY, E.J. Philadelphia Electric Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32876-332-32877-128.

-8510070248 Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing. BOYER, V.S. Philadelphia Electric Co. 85/10/03. 5pp. 32876-334-32876-338.

-8510070257 Rev 44 to FSAR for Limerick Generating Station Units 1 & 2. * Philadelphia Electric Co. 85/10/03. 200pp. 32876-339-32877-128.

8510180017 Forwards Affidavit of Svc re distribution of Rev 44 to FSAR. BRADLEY, E.J. Philadelphia Electric Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33068-316-33068-318.

P. Operating license stage documents & correspondence

8510020031 "Rpt of Initial Plant Startup, Dec 1984." W/850923 ltr. ALDEN, W.M. Philadelphia Electric Co. 85/09/30. MURLEY, T.E. Region 1, Office of Director. 124pp. 32822-072-32822-195.

8510070232 Forwards Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing. Rev 44 to FSAR also encl. BRADLEY, E.J. Philadelphia Electric Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32876-332-32877-128.

-8510070248 Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing. BOYER, V.S. Philadelphia Electric Co. 85/10/03. 5pp. 32876-334-32876-338.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044.010-33044.027.

-8510170193 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities'," technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-4. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044.141-33044.156.

8510210283 Staff requirements memo re 851010 affirmation/discussion & vote in Washington, DC on SECY-85-305 re facility motions & SECY-85-324 re hearing request on denial of senior operator license.
CHILK, S.J. Office of the Secretary of the Commission. 85/10/18. PLAINE, H.H. Office of the General Counsel. 2pp. 33079.077-33079.078.

8510290150 Advises that Startup Test Program (STP) Test-37, "Main Steam Sys & Turbine Performance & Plant Dynamic Response Verifications," deleted from testing program. Test requirements being met by other startup tests.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/22. BUTLER, W.R. Licensing Branch 2. 2pp. 33233.154-33233.155.

Q. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803.095-32803.125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803.099-32803.125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces.
KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. KOSTMAYER, WALKER House of Rep. 3pp. 33109.047-33109.049.

8510160048 Forwards Safety Insp Rept 50-352/85-33 on 850808. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/08. DALTROFF, S.L. Philadelphia Electric Co. 4pp. 33027.176-33027.183.

-8510160051 Insp Rept 50-352/85-33 on 850808. No violation noted. Major areas inspected: emergency preparedness training program for security force at site.
VITO, D.J., AMATO, C.G., HARPSTER, T.L. Region 1, Office of Director. 85/10/07. 4pp. 33027.180-33027.183.

8510220010 Forwards Safety Insp Rept 50-352/85-35 on 850811-23. No violations noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/11. DALTROFF, S.L. Philadelphia Electric Co. 4pp. 33095.300-33095.315.

-8510220017 Insp Rept 50-352/85-35 on 850811-23. No violations noted. Major areas inspected: startup program during Test Condition TC-1, including startup test procedure review, witnessing, results evaluation & plateau review.
FLOREK, D., BLUMBERG, N., ESELGROTH, P. Region 1, Office of Director. 85/10/04. 12pp. 33095.304-33095.315.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510230201 Forwards Safety Insp Rept 50-352/85-37 on 850903-20. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/18. DALTROFF, S.L. Philadelphia Electric Co. 2pp. 33101.204-33101.217.

-8510230206 Insp Rept 50-352/85-37 on 850903-20. No violation noted. Major areas inspected: startup program during Test Condition TC-2, QA/QC interferences, independent measurements, calculations, verifications & tours of facility.
FLOREK, D., CAPTON, D., KUCHARSKI, S. Region 1, Office of Director. 85/10/16. 12pp. 33101.206-33101.217.

8510230192 Forwards Safety Insp Repts 50-352/85-30 & 50-353/85-07 on 850701-0922. No violation noted.
COLLINS, S.J. Region 1, Office of Director. 85/10/21. DALTROFF, S.L. Philadelphia Electric Co. 4pp. 33101.164-33101.194.

-8510230195 Insp Repts 50-352/85-30 & 50-353/85-07 on 850701-0922. No violation noted. Major areas inspected: followup on outstanding items & license conditions, plant tours & maint & surveillance observation.
BEALL, J.E., GALLO, R.M. Region 1, Office of Director. 85/10/17. 27pp. 33101.168-33101.194.

8510290367 Forwards "Preservice Insp Summary Rept for Reactor Pressure Vessel," as partial response to NUREG-0991, Confirmatory Issue 12 (Sections 5.2.4.3 & 6.6.3).
KEMPER, J.S. Philadelphia Electric Co. 85/10/22. BUTLER, W.R. Licensing Branch 2. 2pp. 33234.097-33234.333.

-8510290376 "Preservice Insp Summary Rept for Reactor Pressure Vessel."
* Philadelphia Electric Co. 85/09/25. 200pp. 33234.099-33234.333.

8510290341 Forwards Rev 1 to 8031-P-500, "First 10-Yr Interval Augmented Inservice Insp Program" & Rev 1 to 8031-P-500, "First 10-Yr Interval Inservice Insp Program." W/31 oversize drawings.
KEMPER, J.S. Philadelphia Electric Co. 85/10/23. BUTLER, W.R. Licensing Branch 2. 2pp. 33247.145-33247.146.

-8510290344 Rev 1 to 8031-P-501, "First 10-Yr Interval Augmented Inservice Insp Program."
* Bechtel Corp. 85/10/18. 12pp. 33247.147-33247.158.

-8510290347 Rev 1 to 8031-P-500, "First 10-Yr Interval Inservice Insp Program." W/31 oversize drawings.
* Bechtel Corp. 85/10/18. 150pp. 33247.159-33247.320.

S. Reportable occurrences, LERs & related correspondence

8510010606 LER 85-071-00: on 850824, reactor water cleanup sys isolated when inboard isolation valve received spurious signal from differential temp switch TDTS-44-1N602E. Caused by loose switch connection. Connector cleaned W/850919 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/09/19. 4pp. 32830.001-32830.004.

8510150241 LER 85-072-00: on 850907, while valving reactor water cleanup (RWCU) filter/demineralizer into svc, RWCU sys isolated on high differential flow. Caused by failure of outlet vent valve to fully close. Decontamination initiated W/851007 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/07. 5pp. 33015.120-33015.124.

8510170407 LER 85-073-00: on 850911, reactor scrambled on low level due to feedwater pump trip on low suction pressure & isolation signal occurred. Caused by loss of condensate pump B. Reactor stabilized using Trip Procedures T-99 & 100 W/851010 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/10. 6pp. 33053.273-33053.278.

8510300244 LER 85-074-00: on 850919, technician inadvertently caused fuse to blow resulting in automatic isolation of nuclear steam supply shutoff sys components & initiation of standby gas treatment sys. Fuse replaced W/851018 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/18. 5pp. 33258.128-33258.132.

8510280434 LER 85-077-00: on 850926, while performing HPCI steam line differential pressure timer functional surveillance test, spurious Div IV trip signal received. Caused by loose connection to power supply W/851021 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/21. 5pp. 33195.058-33195.062.

8510310161 LER 85-077-01: on 850926, spurious Div IV trip signals received resulting in load shedding in anticipation of diesel generator loading. Caused by loose connection in power panel. Connection tightened W/851024 ltr.
NAGLE, J.C., ULLRICH, W.T. Philadelphia Electric Co. 85/10/24. 5pp. 33273.250-33273.254.

T. Hearing transcripts on non-antitrust matters

8510160063 Transcript of 851011 hearing in Bethesda, MD. Pp 1-106.
* Atomic Safety and Licensing Board Panel. 85/10/11. 109pp. 33027.241-33027.348.

8510180240 Lists misspellings & errors in transcript of author 851011 oral argument before ASLAP re third partial initial decision.
RADER, R.M. Conner & Wetterhahn. RADER, R.M. Philadelphia Electric Co. #485 819. 85/10/16. KOHL, C.N., EDLES, G.J., GOTCHY, R.L. Atomic Safety and Licensing Appeal Panel. 2pp. 33062.082-33062.083.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces.
KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. HEINZ, SPECTER Senate. 3pp. 33109.047-33109.049.

140 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510070232 Forwards Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing Rev 44 to FSAR also encl.
BRADLEY, E.J. Philadelphia Electric Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32876-332-32877-128.

-8510070248 Amend 80 to applications for License NPF-39 & CPPR-107, changing FSAR Chapter 15 & automatic depressurization sys logic drawing.
BOYER, V.S. Philadelphia Electric Co. 85/10/03. 5pp. 32876-334-32876-338.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. MCVAK, T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

-8510170193 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), item 1.2, 'Post-Trip Review Data & Info Capabilities'..." technical evaluation rept.
Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-4. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044-141-33044-156.

F. Security, medical, emergency & fire protection plans

8510080268 Forwards revs to plant security personnel training & qualification plan. Revs withheld (ref 10CFR73.21 & 2.790).
BRADLEY, E.J. Philadelphia Electric Co. 85/10/01. Region 1, Office of Director. 4pp. 32913-308-32913-311.

8510150069 Forwards correspondence & documentation re emergency planning among applicant, NRC, Commonwealth of PA & other responsible governmental agencies, per ASLB 820601 order. Related correspondence.
CULLEN, E.J. Philadelphia Electric Co. #485 717. 85/10/04. ZITZER, P. Ecology Action of Pottstown. 450pp. 33029-180-33030-210.

8510290076 Revised emergency plan implementing procedures, including Rev 9 to EP-102 re unusual event response, Rev 12 to EP-103 re alert response & Rev 11 to EP-104 re site emergency response. W/851024 ltr.
DALTROFF, S.L. Philadelphia Electric Co. 85/10/24. MURLEY, T.E. Region 1, Office of Director. 56pp. 33236-057-33236-113.

G. Adjudicatory correspondence

8510060005 Informs that HJ McGurren will appear at 851011 oral argument. Related correspondence.
MCGURREN, H.J. Hearing Branch 1. #485 658. 85/09/27. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32843-194-32843-195.

8510100106 Motion to reopen record re gross alpha, Ra-226 & Ra-228 levels found in well water near reactor, based on new Commonwealth of PA Div of Environmental Resources regulations.
ROMANO, F.R. Air and Water Pollution Patrol. #485 674. 85/09/27. Atomic Safety and Licensing Board Panel. 3pp. 32960-107-32960-109.

8510020150 Forwards RL Anthony 850926 postcard re 851011 oral argument on ASLB third partial initial decision. Served on 851001.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 651. 85/09/30. CLEMENTS, W.L. Docketing & Services Branch. 1p. 32824-330-32824-331.

-8510020155 Expresses appreciation for opportunity to present oral argument on 851011 re ASLB third partial initial decision.
ANTHONY, R.L. Anthony, R.L. 85/09/26. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32824-331-32824-331.

8510030011 Informs of appearance to present oral argument on 851011 re appeals of third partial initial decision in proceeding per 850829 order. Related correspondence.
RADER, R.M. Conner & Wetterhahn. RADER, R.M. Philadelphia Electric Co. #485 653. 85/09/30. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 1p. 32844-334-32844-334.

8510110017 Petition to require util to comply w/requirements of License NPF-39 & withdraw applications to Delaware River Basin Commission to Lower Schuylkill river flow restraint & permit releases from Beechwood pit.
ANTHONY, R.L. Anthony, R.L. ANTHONY, R.L. Friends of the Earth. #485 732. 85/10/01. Docketing & Services Branch. 2pp. 32973-277-32973-278.

8510100189 Notice of receipt of encl 850927 Air & Water Pollution Patrol motion to reopen record on new Commonwealth of PA, Div of Environmental Resources regulations re gross alpha, Ra-226 & Ra-228. Served on 851008.
HOYT, H.F. Atomic Safety and Licensing Board Panel. #485 688. 85/10/04. 1p. 32962-120-32962-123.

-8510100202 Motion for NRC to reopen record based on new Commonwealth of PA, Div of Environmental Resources regulations re gross alpha, Ra-226 & Ra-228.
ROMANO, F.R. Air and Water Pollution Patrol. 85/09/27. Atomic Safety and Licensing Board Panel. 3pp. 32962-121-32962-123.

8510150349 Informs that P Zitzer & D Stone will represent Limerick Ecology Action, Inc at 851011 oral argument in response to ASLB 850829 order.
ZITZER, P. Limerick Ecology Action. #485 762. 85/10/04. SHOEMAKER, C.J. Atomic Safety and Licensing Board Panel. 1p. 33000-341-33000-341.

8510110063 Response to Graterford inmates 850725 & Air & Water Pollution Patrol 850726 appeals from Appeal Board 850612 order & fourth partial initial decision. W/ Certificate of Svc.
HASSELL, D.F. Hearing Branch 2. MCGUIRE, R.H. Hearing Branch 1. #485 718. 85/10/08. Atomic Safety and Licensing Appeal Panel. 57pp. 32972-051-32972-107.

8510110219 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl.
HASSELL, D.F. Hearing Branch 2. #485 736. 85/10/09. 3pp. 32972-279-32972-281.

8510110157 Order denying Graterford inmates & R Anthony/Friends of the Earth requests that Commission stay NRC orders authorizing issuance of full power license. Served on 851010.
CHILK, S.J. Office of the Secretary of the Commission. #485 752. 85/10/10. Graterford inmates. 3pp. 32972-245-32972-247.

8510210038 Response opposing Air & Water Pollution Patrol (AWPP) 850927 motion to reopen record to admit previously denied contention re drinking water monitoring requirements. AWPP failed to meet three criteria for reopening closed record.
CONNER, T.B. Philadelphia Electric Co. CONNER, T.B. Conner & Wetterhahn. #485 832. 85/10/17. Atomic Safety and Licensing Appeal Panel. 16pp. 33072-324-33072-339.

8510230255 Decision ALAB-819 affirming ASLB Second Partial Initial Decision LBP-84-31, except insofar as ASLB decision approves util onsite emergency plan medical arrangements. Issue reversed & remanded. Served on 851023.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 872. 85/10/22. 101pp. 33103-051-33103-151.

8510240279 Forwards Commonwealth of PA court decision finding Bucks County & Neshaminy Water Resources Authority obligated to complete Point Pleasant project. Related correspondence.
CONNER, T.B. Conner & Wetterhahn. CONNER, T.B. Philadelphia Electric Co. #485 876. 85/10/22. CHILK, S.J. Office of the Secretary of the Commission. 36pp. 33154-268-33154-303.

8510290001 Response opposing Air & Water Pollution Patrol (AWPP) 851002 motion to reopen record. AWPP failed to state contention w/basis & specificity & satisfy regulations for admitting late-filed contention. Certificate of Svc encl.
HODGDON, A.P. Hearing Branch 2. #485 940. 85/10/22. Atomic Safety and Licensing Appeal Panel. 15pp. 33233-233-33233-248.

8510310319 Forwards Commonwealth of PA Emergency Mgt Svcs Act. Pamphlet Law 1322 in response to ASLB 851011 request during author oral argument. W/o encl. Related correspondence.
FERKIN, Z.G. Pennsylvania, Commonwealth of. #485 971. 85/10/23. KOHL, C.N. Atomic Safety and Licensing Appeal Panel. 1p. 33272-064-33272-064.

8510290008 Order scheduling 851204 oral argument in Bethesda, MD on Graterford inmates & Air & Water Pollution Patrol appeals of ASLB 850722 Fourth Partial Initial Decision LBP-85-25. Served on 851024.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 944. 85/10/24. Office of the Executive Legal Director. 2pp. 33236-351-33236-352.

8510310195 Confirms recent telcon re need for filing answers to discovery requests w/ Ofc of Secretary Judges Kohl & Hoyt agree that answers should not be filed w/ Secretariat if answers not delivered to Boards. Related correspondence.
CLEMENTS, W.L. Docketing & Services Branch. #485 977. 85/10/28. CULLEN, E.J. Philadelphia Electric Co. 1p. 33274-043-33274-043.

8510310359 Order directing licensee to submit proposal to resolve remanded issue re back-up medical arrangements necessary to satisfy requirements for onsite emergency plan medical arrangements for onsite personnel. Served on 851028.
HOYT, H.F. Atomic Safety and Licensing Board Panel. #485 968. 85/10/28. Office of the Executive Legal Director. 2pp. 33271-334-33271-335.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510070232 Forwards Amend 80 to applications for License NPF-39 & CPPR-137, changing FSAR Chapter 15 & automatic depressurization sys logic drawing Rev 44 to FSAR also encl.
BRADLEY, E.J. Philadelphia Electric Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32876-332-32877-128.

-8510070257 Rev 44 to FSAR for Limerick Generating Station Units 1 & 2.
Philadelphia Electric Co. 85/10/03. 200pp. 32876-339-32877-128.

8510180017 Forwards Affidavit of Svc re distribution of Rev 44 to FSAR.
BRADLEY, E.J. Philadelphia Electric Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33068-316-33068-318.

Q. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

-8510010378 Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds."
Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces. KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. KOSTMAYER, WALKER House of Rep. 3pp. 33109:047-33109:049.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230192 Forwards Safety Insp Repts 50-352/85-30 & 50-353/85-07 on 850701-0922 No violation noted. COLLINS, S.J. Region 1, Office of Director. 85/10/21. DALTROFF, S.L. Philadelphia Electric Co. 4pp. 33101:164-33101:194.

-8510230195 Insp Repts 50-352/85-30 & 50-353/85-07 on 850701-0922 No violation noted. Major areas inspected/followup on outstanding items & license conditions, plant tours & maint & surveillance observation. BEALL, J.E., GALLO, R.M. Region 1, Office of Director. 85/10/17. 27pp. 33101:168-33101:194.

8510290341 Forwards Rev 1 to 8031-P-501, "First 10-Yr Interval Augmented Inservice Insp Program" & Rev 1 to 8031-P-500, "First 10-Yr Interval Inservice Insp Program." W/31 oversize drawings. KEMPER, J.S. Philadelphia Electric Co. 85/10/23. BUTLER, W.R. Licensing Branch 2. 2pp. 33247:145-33247:146.

T. Hearing transcripts on non-antitrust matters

8510160063 Transcript of 851011 hearing in Bethesda, MD. Pp 1-106. * Atomic Safety and Licensing Board Panel. 85/10/11. 109pp. 33027:241-33027:348.

8510180240 Lists misspellings & errors in transcript of author 851011 oral argument before ASLAP re third partial initial decision. RADER, R.M. Conner & Wetterhahn. RADER, R.M. Philadelphia Electric Co. #485 819. 85/10/16. KOHL, C.N., EDLES, G.J., GOTCHY, R.L. Atomic Safety and Licensing Appeal Panel. 2pp. 33062:082-33062:083.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces. KAMMERER, C. Office of Congressional Affairs. 85/06/03. MARKEY, E.J. House of Rep., Energy & Commerce. HEINZ, SPECTER Senate. 3pp. 33109:047-33109:049.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510250446 Notifies that GE "Nuclear Energy Business Operations QA Program Description" referenced in PSAR Vendor Program Branch approved FSAR Rev 5 in 850419 ltr Program will be in effect for remaining GE const activities at facility. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/07/17. MURLEY, T.E. Region 1, Office of Director. 1p. 33172:234-33172:234.

8510020195 Forwards "Simplification of Power Ascension Test 20, Pressure Regulator" & "Simplification of Power Ascension Feedwater Sys Response Testing - Test 21A," for NRC expedited review. Marked-up FSAR pages re test mods encl. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/09/30. BUTLER, W. Licensing Branch 2. 4pp. 32824:263-32824:279.

-8510020200 "Simplification of Power Ascension Test 20, Pressure Regulator." Modified Test 20 encl. ATKINSON, C.G., LAMBERT, C.W. Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-020. 85/09/25. 6pp. 32824:267-32824:272.

-8510020205 "Simplification of Power Ascension Feedwater Sys Response Testing - Test 21A." Modified Test 21A encl. JOHNSON, R.W., LAMBERT, C.W. Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-014. 85/09/25. 7pp. 32824:273-32824:279.

8510030040 Confirms that all electrical equipment important to safety will be environmentally qualified prior to fuel load, per NRC 850828 ltr re compliance w/10CFR50.49 & Generic Ltr 85-15. No extensions to deadline anticipated. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/09/30. BUTLER, W. Licensing Branch 2. 1p. 32843:076-32843:076.

8510030148 Comments on draft environ protection plan submitted by NRC 850726 ltr Salt drift monitoring program will be implemented in plant vicinity. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/01. BUTLER, W. Licensing Branch 2. 2pp. 32842:229-32842:230.

8510110005 Forwards RB Hubbard 850927 analysis of facility IDVP, per 851001 conversation w/GT Ankrum & conversation w/R Hubbard. Sargent & Lundy audit failed to confirm adequacy of current util design activities. THURBER, J.P. New Jersey, State of. 85/10/01. MILHOAN, J. NRC - No Detailed Affiliation Given. 10pp. 32999:252-32999:261.

8510160032 Requests addl info re nonmetallic mats used for E sys snubbers & RCIC turbines, documents in public domain concerning nonmetallic mat capabilities & confirmation of replacement intervals. BUTLER, W.R. Licensing Branch 2. 85/10/02. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 4pp. 33028:134-33028:137.

8510170156 Forwards "Audit of Pump & Valve Operability Assurance Program for Hope Creek Generating Station." BUTLER, W.R. Licensing Branch 2. 85/10/02. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 5pp. 33043:111-33043:115.

-8510030411 "Audit of Pump & Valve Operability Assurance Program for Hope Creek Generating Station." KIDO, C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6415. EGG-EA-8901. 85/09/30. NRC - No Detailed Affiliation Given. 46pp. 33043:116-33043:161.

8510080422 Forwards Tests 28B, "Recirculation Pump Trip Test," & 28D, "Recirculation Pump Runback Test," per attached power ascension test mods, for expedited review. Safety evaluation & marked-up FSAR pages also encl. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/04. BUTLER, W. Licensing Branch 2. 3pp. 32921:255-32921:268.

-8510080424 Test 28B, "Recirculation Pump Trip - Two Pumps in Conjunction W/Test 25." OPASL, P.O., SINGH, S., CHURCHMAN, C.W. Public Service Electric & Gas Co. of New Jersey. 85/10/01. 3pp. 32921:258-32921:260.

-8510080428 "Deletion of Test Number 28B, Two Pump Recirculation Pump Trip Test at Test Condition 3," safety evaluation. OPASL, P.O., SINGH, S., CHURCHMAN, C.W. Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-019. 85/10/01. 8pp. 32921:261-32921:268.

8510080566 Forwards proof & review Tech Specs. Identification of sections which do not accurately reflect FSAR or "as-built" plant requested. BUTLER, W.R. Licensing Branch 2. 85/10/04. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 250pp. 32924:064-32925:211.

8510150222 Requests permission to procure replacement svc water spray water pump w/o "N" stamp from Hayward Tyler Pump will meet all ASME Section III requirements, including all QA requirements, w/exception of "N" stamp. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/10. BUTLER, W. Licensing Branch 2. 2pp. 33008:276-33008:277.

8510240649 Informs that radiation protection/chemistry managers for facilities duty authorized representatives to sign all State of NJ pollution discharge elimination sys related correspondence & repts. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/10/15. CAPOREALE, G. New Jersey, State of. 1p. 33157:214-33157:214.

8510280098 Forwards proof & review environ protection plan, revised to incorporate util 851001 comments. Review of encl & notification of addl changes or concurrence requested. BUTLER, W.R. Licensing Branch 2. 85/10/16. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 18pp. 33228:342-33228:359.

8510250481 Forwards detailed justifications & safety evaluations for power ascension test mods, including Test 10 re APRM Calibr, Test 23A re MSIV functional tests, Test 23B re MSIV full isolation & Test 24 re relief valves. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/17. BUTLER, W. Licensing Branch 2. 5pp. 33171:139-33171:219.

-8510250482 "Safety Evaluation: Replace Power Ascension Test Program APRM Calibr Procedure W/Tech Spec Surveillance Procedures & Delete APRM Calibr During Heatup." * Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-007. 85/10/09. 4pp. 33171:144-33171:147.

-8510250483 "Safety Evaluation: Simplification of Test 23A, MSIV Functional Test." * Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-015. 85/10/15. 5pp. 33171:148-33171:152.

-8510250484 "Safety Evaluation: MSIV Full Isolation, Test 23B - Expansion of Test Window." MUSSEL, W. Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-018. 85/10/07. 3pp. 33171:153-33171:176.

-8510250486 "Safety Evaluation: Simplification of Test 24, Relief Valves." * Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-025. 85/10/15. 5pp. 33171:177-33171:181.

-8510250487 "Safety Evaluation: Simplification of Test 28E, Recirculation Sys Cavitation." * Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-022. 85/10/15. 6pp. 33171:182-33171:187.

142 DOCKETED ITEMS

—8510250488 "Safety Evaluation: Simplification of Drywell Piping Vibration Test 31."
* Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-016. 85/10/11. 10pp. 33171:186-33171:197.

—8510250490 "Safety Evaluation: Simplification of Test 32 Reactor Water Cleanup Sys."
* Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-023. 85/10/15. 19pp. 33171:198-33171:216.

—8510250492 "Safety Evaluation: Deletion of Test 28D, Recirculation Pump Runback Test at Test Condition 3."
* Public Service Electric & Gas Co. of New Jersey. PSE-SE-Z-021. 85/10/01. 3pp. 33171:217-33171:219.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510030103 Responds to SER Outstanding Issue 1, "Riverborne Missiles," per 850923 telcon. Review of svc water pump (SWP) flange seal & bearing assembly design complete SWPs seismically qualified to 0.2g acceleration.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/01. BUTLER, W. Licensing Branch 2. 2pp. 32842:234-32842:235.

8510170148 Advises that sufficient info submitted to resolve SER Open Item 3 re pre-service insp program. Results of NRC review will be in SSER 3. Relief requests from preservice insp requirements of ASME Code should be submitted by 851017.
BUTLER, W.R. Licensing Branch 2. 85/10/02. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 4pp. 33043:162-33043:165.

8510160025 Advises that revised process control program acceptable for use in process of Class A wastes. Proposed license will not be changed until process control program revised to include solidification of Class B & C wastes.
BUTLER, W.R. Licensing Branch 2. 85/10/04. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 6pp. 33026:138-33026:143.

8510220329 Forwards "Hope Creek Generating Station Rept of Evaluation of Effects of Radio Frequency Interference on Digital Solid State Sys." for review. Rept closes SER Outstanding Issue 5 re solid state logic modules.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/17. BUTLER, W. Licensing Branch 2. 2pp. 33084:058-33084:124.

—8510220334 "Hope Creek Generating Station Rept of Evaluation of Effects of Radio Frequency Interference on Digital Solid State Sys."
VAN STAVEREN, D. Public Service Electric & Gas Co. of New Jersey. 85/10/02. 65pp. 33084:060-33084:124.

8510280295 Forwards elementary diagrams of automatic depressurization sys showing completed installation of manual switch in response to SER Confirmatory item 37 W/ four oversize drawings.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/18. BUTLER, W. Licensing Branch 2. 1p. 33192:001-33192:003.

F. Security, physical, emergency & fire protection plans

8510020214 Responds to 850830 request for approval to hold one emergency medical assistance drill on 851106 to meet criteria to test medical response capability for emergency plans. Proposal acceptable.
MURLEY, T.E. Region 1, Office of Director. 85/09/16. MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 1p. 32827:214-32827:215.

—8510020226 Requests approval to hold one, instead of two, emergency medical assistance drills. Annual drill scheduled for 851106. Drills involve same teams of onsite & offsite personnel & would meet redundant requirement.
MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey. 85/08/30. MURLEY, T.E. Region 1, Office of Director. 1p. 32827:215-32827:215.

8510010027 Requests formal confirmation that offsite emergency plans include list of local or regional medical facilities & commitment to full compliance w/ NRC response to GUARD remain in order for NRC to issue license.
BUTLER, W. Licensing Branch 2. 85/09/26. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 8pp. 32833:173-32833:180.

8510030031 Responds to 850904 request for add'l info re loss of control room ventilation. Analyses performed on effect of loss of ventilation & cooling to control room & electrical equipment room. Initial conditions based on normal operating temps.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/01. BUTLER, W. Licensing Branch 2. 3pp. 32842:266-32842:268.

8510160336 Advises that encl draft comments on Rev 0 to offsite dose calculation manual forwarded to util. Comments not representative of manual comments to be issued in near future.
BUTLER, W.R. Licensing Branch 2. 85/10/10. Licensing Branch 2. 10pp. 33028:316-33028:326.

8510220209 Forwards info addressing request to consider add'l SPDS display parameter & verification & validation process. per 850827-28 au tit exit meeting.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/14. BUTLER, W. Licensing Branch 2. 36pp. 33087:213-33087:248.

8510220164 Forwards SPDS audit rept detailing results of 850827-28 audit for review. Audit identified areas needing mod for compliance w/ regulatory requirements. Response to each identified concern requested.
BUTLER, W.R. Licensing Branch 2. 85/10/15. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 4pp. 33098:139-33098:165.

8510310089 Revised emergency procedures, including EP I-2, "Alert," EP I-3A, "Site Area Emergency, Senior Shift Supervisor (SNSS)," & EP I-3B, "Site Area Emergency, Emergency Duty Officer (EDO)."
ADAMS, C., SALVESEN, R.S. Public Service Electric & Gas Co. of New Jersey. 85/10/17. 310pp. 33264:144-33265:158.

8510310180 Rev 1 to emergency event classification guide.
* Public Service Electric & Gas Co. of New Jersey. 85/10/17. 300pp. 33267:126-33268:021.

8510310413 Advises that Rev 4 to security plan & Rev 1 to security contingency plan consistent w/ regulatory requirements. Chronology of evolution of various NRC-approved security plans encl.
BUTLER, W.R. Licensing Branch 2. 85/10/21. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 5pp. 33278:202-33278:206.

8510290373 Forwards Rev 9 to emergency plan, revising listed sections. Questions generated in emergency preparedness appraisal during wk of 850812 addressed. Next rev will be submitted on 851115.

MITTL, R.L., DOUGLAS, R.P. Public Service Electric & Gas Co. of New Jersey. 85/10/25. Office of Nuclear Reactor Regulation, Director. BUTLER, W. Licensing Branch 2. 3pp. 33240:061-33240:259.

—8510290377 Rev 9 to emergency plan.
* Public Service Electric & Gas Co. of New Jersey. 85/10/15. 200pp. 33240:064-33240:259.

8510300179 Forwards info re NRC policy statement on Emergency Planning Std 10CFR50.47(b)(12) & interim guidance concerning Guard vs NRC court decision, per 850926 request. Info in States of NJ & DE radiological emergency response plans encl.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/25. BUTLER, W. Licensing Branch 2. 21pp. 33249:219-33249:239.

8510310176 Corrected Page 32 to Rev 1 to Emergency Plan Implementing Procedure EP IV-107, consisting of Attachment 8 re dose calculation nomogram using drywell (primary containment) high range monitor.
* Public Service Electric & Gas Co. of New Jersey. 85/10/31. 2pp. 33274:056-33274:057.

J. Insurance & indemnity information

8510090261 Forwards Endorsement 80 to NELIA Policy NF-230 & Endorsement 65 to MAELU Policy MF-90.
MURAT, A. Marsh & McLennan, Inc. 85/10/03. DINITZ, J. Assistant Director for State & Licensee Relations. 3pp. 32943:031-32943:033.

8510160199 Forwards Secondary Financial Protection Certificates NELIA N-104 & MAELU M-104.
MURAT, A. Marsh & McLennan, Inc. 85/10/08. DINITZ, J. Assistant Director for State & Licensee Relations. 14pp. 33026:303-33026:316.

K. Utility Final Safety Analysis Report (FSAR) & amends

8509250119 Forwards Amend 12 to FSAR for Hope Creek Generating Station. Amend includes text changes due to resolution of SER open items & updated functional control diagrams & instrument electrical diagrams in Section 7.0.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/09/21. BUTLER, W. Licensing Branch 2. 13pp. 32739:233-32744:152.

—8509250123 Amend 12 to FSAR for Hope Creek Generating Station. W/235 oversize drawings.
* Public Service Electric & Gas Co. of New Jersey. 85/09/30. 1,707pp. 32739:246-32744:152.

Q. Inspection reports, IE Bulletins & correspondence

8510090219 Forwards Meeting Rept 50-354/85-43 on 850801 re cold operator licensing exams conducted in Jul 1985. All issues resolved. Second set of exams will be conducted during wks of 851014 & 21 W/o encl.
STAROSTECKI, R. Region 1, Office of Director. 85/09/23. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 32947:191-32947:192.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510170148 Advises that sufficient info submitted to resolve SER Open Item 3 re pre-service insp program. Results of NRC review will be in SSER 3. Relief requests from preservice insp requirements of ASME Code should be submitted by 851017.
BUTLER, W.R. Licensing Branch 2. 85/10/02. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 4pp. 33043:162-33043:165.

8510210108 Responds to NRC 850905 ltr re noncompliance noted in Insp Rept 50-354/85-35. Corrective actions: facility test review board trained & requirements that each preoperational test procedure quality product reemphasized.
MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/10/09. MURLEY, T.E. Region 1, Office of Director. 3pp. 33072:271-33072:273.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510210150 Forwards Exam Rept 50-354/OL-85-29 on 850708-17.
KISTER, H.B. Region 1, Office of Director. 85/10/15. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 1p. 33071:145-33071:272.

—8510210154 Exam Rept 50-354/OL-85-29 on 850708-17. Exam results: 8 reactor operators, 11 senior reactor operators & 1 instructor certification candidate passed oral & written exams. Three candidates failed simulator exam.
BERRY, J., KELLER, R.M., KISTER, H.B. Region 1, Office of Director. 85/10/12. 150pp. 33071:146-33071:272.

8510180292 Responds to 851002 ltr re preservice insp (PSI) program relief requests. Util currently identifying & properly justifying all impractical ASME Code requirements discovered while conducting PSI program.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510210086 Forwards Preoperational Safety Insp Rept 50-354/85-44 on 850910-13. No violations or deviations noted. Several weaknesses noted & discussed within rept.
MARTIN, T.J. Region 1, Office of Director. 85/10/17. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 33072-126-33072-141.

-8510210090 Insp Rept 50-354/85-44 on 850910-13. No violations or deviations noted. Major areas inspected: preoperational radiation protection, chemistry & radwaste programs, including in-house training & procedural development.
BICEHOUSE, H., KOTTAN, J., MILLER, M. Region 1, Office of Director. 85/10/15. 14pp. 33072-128-33072-141.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280356 Forwards Insp Rept 50-354/85-42 on 850812-0923 & notice of violation.
KISTER, H.B. Region 1, Office of Director. 85/10/21. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 33192-206-33192-222.

-8510280357 Notice of violation from insp on 850812-0923.
* Region 1, Office of Director. 85/10/21. 3pp. 33192-208-33192-210.

-8510280360 Insp Rept 50-354/85-42 on 850812-0923. Violation noted: inadequate design control for 125-volt dc control power alarm circuits.
BLOUGH, A.R., CHAUDHARY, S.K., LYASH, J.J. Region 1, Office of Director. 85/10/17. 12pp. 33192-211-33192-222.

8510250442 Forwards Safety Insp Rept 50-354/85-41 on 850819-30. No violation noted. Permission to receive & store fuel per License SNM-1953 granted.
EBNETER, S.D. Region 1, Office of Director. 85/10/22. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 33170-144-33170-165.

-8510250445 Insp Rept 50-354/85-41 on 850819-30. No violation noted. Major areas inspected: fuel handling procedures, polar crane preoperational testing, fuel handling & rigging equipment & radiation protection program.
BIGGS, L., BAILEY, R., BISSETT, P. Region 1, Office of Director. 85/10/08. 20pp. 33170-146-33170-165.

S. Reportable occurrences, LERs & related correspondence

8510030422 Significant const deficiency rept re heat buildup in emergency diesel generator cabinets. Initially reported on 850403. Design Change Package 7079 prepared to increase & redirect airflow. Next rept will be submitted by 851101.
MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/09/13. MURLEY, T.E. Region 1, Office of Director. 2pp. 32846-013-32846-014.

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets. Insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.
SCHREIBER, H. Louis-Allis Co. 85/09/30. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851-100-32851-107.

8510170236 Interim significant const deficiency rept re performance of Ruskin Model NIBD-23 spring closure fire dampers. Initially reported on 841224. Testing program delayed due to HVAC sys problems. Final rept will be provided by 851115.
MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/10/02. MURLEY, T.E. Region 1, Office of Director. 2pp. 33051-230-33051-231.

8510500101 Final const deficiency rept re misoperation of Bailey Controls Co 862 sys logic module logic memories during environ qualification testing. Initially reported on 850909. Gap in circuit board pads increased & area cleaned.
MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/10/10. MURLEY, T.E. Region 1, Office of Director. 2pp. 33256-358-33256-359.

8510300126 Final const deficiency rept re missing lock welds on Anchor/Darling swing check valves. Initially reported on 850911. Set screws staked during insp & disc nut pins peened as alternative to lock welding.
MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 85/10/11. MURLEY, T.E. Region 1, Office of Director. 3pp. 33257-171-33257-173.

V. Operator Examinations

8510090219 Forwards Meeting Rept 50-354/85-43 on 850801 re cold operator licensing exams conducted in Jul 1985. All issues resolved. Second set of exams will be conducted during wks of 851014 & 21. W/o encl.
STAROSTECKI, R. Region 1, Office of Director. 85/09/23. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 2pp. 32947-191-32947-192.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510210150 Forwards Exam Rept 50-354/OL-85-29 on 850708-17.
KISTER, H.B. Region 1, Office of Director. 85/10/15. MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey. 1p. 33071-145-33071-272.

-8510210154 Exam Rept 50-354/OL-85-29 on 850708-17. Exam results: 8 reactor operators, 11 senior reactor operators & 1 instructor certification candidate passed oral & written exams. Three candidates failed simulator exam.
BERRY, J., KELLER, R.M., KISTER, H.B. Region 1, Office of Director. 85/10/12. 150pp. 33071-146-33071-272.

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070179 Forwards revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements." Procedure S023-VIII-28.2 should be deleted.
ZINTL, W.G. Southern California Edison Co. 85/09/27. MARTIN, J.B. Region 5, Office of Director. 2pp. 32881-084-32881-119.

-8510070185 Revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements" & Temporary Change TCN 3-1 to Rev 3 to S0123-VIII-70.1, "Site Telephone." BENNETT, D.D., HOWELL, T.G., WHARTON, M.A. Southern California Edison Co. 85/09/27. 32pp. 32881-086-32881-119.

8510180493 Expresses appreciation for coordinating 850924 site visit & 850925 emergency operations facility tour.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/15. BASKIN, K.P. Southern California Edison Co. 2pp. 33077-335-33077-336.

8510310277 Revised emergency plan implementing procedures, including Rev 2 to S0123-VIII-0.301, "Offsite/Onsite Communications List" & Temporary Change Notice 1-3 to Rev 1 to S0123-VIII-0.202, "Assignment of Emergency Response Personnel." W/851025 ltr.
ZINTL, W.G. Southern California Edison Co. 85/10/25. MARTIN, J.B. Region 5, Office of Director. 93pp. 33272-161-33272-250.

8510310285 Advises that 850620 & 1023 Revs 5 & 5A to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. Figure 5-1 & const security procedures to be submitted as Rev 5B will be reviewed upon receipt, per 851024 telcon.
SCHUSTER, M.D. Region 5, Office of Director. 85/10/29. MORGAN, H.E. Southern California Edison Co. 4pp. 33273-267-33273-271.

P. Operating license stage documents & correspondence

8510010073 Forwards Suppl II to "San Onofre Nuclear Generating Station Unit 2 Initial Startup Rept." addressing testing from issuance of low power OL through completion of startup testing, per Tech Specs.
HAYNES, J.G. Southern California Edison Co. 83/10/21. MARTIN, J.B. Region 5, Office of Director. 1p. 32834-350-32834-194.

-8510010079 Suppl II to "San Onofre Nuclear Generating Station Unit 2 Initial Startup Rept." HERRING, T., WRIGHT, L.A., PHOENIX, W.C. Southern California Edison Co. 83/10/05. 564pp. 32834-351-32834-194.

8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDR App E documents withheld (ref FOIA Exemptions 6 & 7).
FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833-002-32833-052.

8510070097 Forwards Amendments 34 & 23 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec 3/4.8.1.1, "Electrical Power Sys - AC Sources - Operating," re onsite electrical power sources.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 32901-179-32901-198.

144 DOCKETED ITEMS

- 8510070104** Amends 34 & 23 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Spec 3/4.8.1.1, "Electrical Power Sys - AC Sources - Operating," re onsite electrical power sources.
KNIGHTON, G.W. Licensing Branch 3. 85/09/25. 14pp. 32901:182-32901:195.
- 8510070111** Safety evaluation supporting Amends 34 & 23 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/09/25. 2pp. 32901:196-32901:198.
- 8510110081** Forwards Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec 3.2.6, "Reactor Coolant Cold Leg Temp," at power levels less than 70%.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33011:003-33011:018.
- 8510110094** Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Spec 3.2.6, "Reactor Coolant Cold Leg Temp," re cold leg temp limits at power levels less than 70%.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. 10pp. 33011:006-33011:015.
- 8510110268** Safety evaluation supporting Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/09/25. 10pp. 33011:016-33011:018.
- 8510160174** Further response to FOIA request for 12 categories of documents re plant. Forwards App E documents. App F documents available in PDR. Apps G & H documents withheld (ref FOIA Exemptions 7 & 5).
FELTON, J.M. Division of Rules and Records. 85/09/26. ZAEKE, D. Sierra Club. 6pp. 33042:331-33042:357.
- 8510110232** Forwards Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Specs re operability of post-accident cleanup filter sys., boric acid tank storage shutdown & boric acid tank storage.
KNIGHTON, G.W. Licensing Branch 3. 85/09/30. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33011:353-33012:015.
- 8510110235** Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs 3/4.9.12, "Fuel Handling Bldg Post-Accident Cleanup Filter Sys," 3.1.2.7, "Borated Water Source - Shutdown" & 3.1.2.8 re boric acid storage tanks.
KNIGHTON, G.W. Licensing Branch 3. 85/09/30. 16pp. 33011:357-33012:011.
- 8510110236** Safety evaluation supporting Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 4pp. 33012:012-33012:015.
- 8510170085** Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049:042-33049:234.
- 8510170092** Rev 7 to Spec CS-P207, "Pipe Support Field Fabrication & Installation."
* Bechtel Corp. 85/04/18. 39pp. 33049:046-33049:218.
- 8510040287** Forwards response to 850508 request for addl info re Generic Ltr 83-28, "Generic Implications of Salem ATWS Event."
MEDFORD, M.O. Southern California Edison Co. 85/10/02. KNIGHTON, G.W. Licensing Branch 3. 6pp. 32853:181-32853:186.
- 8510110105** Forwards, for review & approval, proposed Rev 1 to "Snubber Reduction Program for Nuclear Piping Sys." Rev replaces original submitted on 850709. Fee paid.
MEDFORD, M.O. Southern California Edison Co. 85/10/09. KNIGHTON, G.W. Licensing Branch 3. 3pp. 32972:032-32972:050.
- 8510110108** Rev 1 to QUAD-7-85-023, "Snubber Reduction Program for Nuclear Piping Sys."
* Southern California Edison Co. 85/10/31. 16pp. 32972:035-32972:050.
- 8510170090** Forwards Amend Applications 32 & 18 to Licenses NPF-10 & NPF-15, respectively to revise Tech Specs for max enrichment limit for reload fuel assemblies. Fee paid.
BASKIN, K.P. Southern California Edison Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33037:039-33037:265.
- 8510170101** Application for amends to Licenses NPF-10 & NPF-15 to revise Tech Specs for max enrichment limit for reload fuel assemblies & increasing range of boric acid concentration for refueling water storage tank.
BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. HOYT, G.W. Anaheim, CA. 85/10/09. 17pp. 33037:041-33037:057.
- 8510170106** Proposed Tech Specs revising max enrichment limit for reload fuel assemblies, increasing range of boric acid concentration for refueling water storage tank & reducing max boric acid concentration in boric acid makeup tank.
* Southern California Edison Co. 85/10/09. 175pp. 33037:058-33037:265.
- 8510150141** Requests expedited review by 851218 of 850220 application to revise Tech Specs re RCS pressure/temp limits & component cyclic or transient limits. Expedited review will accommodate return to Mode 3 operation.
MEDFORD, M.O. Southern California Edison Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 1p. 33010:303-33010:303.
- 8510150199** Forwards "Technical Data Mgt Ctr Computer Code Data Collections, Scale 2, Modular Code Sys for Performing Standardized Computer Analyses for Licensing Evaluation." Calculations support 850823 Proposed Change NPF-10/15-199.
MEDFORD, M.O. Southern California Edison Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 1p. 33000:001-33000:001.
- 8510150203** "Technical Data Mgt Ctr Computer Code Data Collections, Scale 2, Modular Code Sys for Performing Standardized Computer Analyses for Licensing Evaluation."
* Oak Ridge National Laboratory. CCC-450. 85/10/10. 293pp. 33000:0-2-33000:296.
- 8510240411** Forwards Amends 37 & 26 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec "Containment Structural Integrity" & License Condition 2.c(4), "Containment Tendon Surveillance."
KNIGHTON, G.W. Licensing Branch 3. 85/10/11. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33182:206-33182:228.
- 8510240417** Amends 37 & 26 to License NPF-10 & NPF-15, respectively, modifying Tech Spec "Containment Structural Integrity" & License Condition 2.c(4), "Containment Tendon Surveillance."
THOMPSON, H.L. Division of Licensing. 85/10/11. 14pp. 33182:210-33182:223.
- 8510240420** Safety evaluation supporting Amends 37 & 26 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/10/11. 5pp. 33182:224-33182:228.
- 8510170267** Submits proposed schedule for meeting requirements of 10CFR50.62, per Generic Ltr 85-06 re QA guidance for nonsafety-related ATWS equipment. Diverse scram sys will be installed during first refueling outage after 870601.
MEDFORD, M.O. Southern California Edison Co. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33039:293-33039:294.
- 8510180167** Forwards revised Proposed Change NPD-10/15-199 (PCN-199) to Tech Spec 5.3.1, "Fuel Assemblies," clarifying 851010 calculations supporting 850823 application to amend Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33059:347-33059:349.
- 8510180173** Revs to Proposed Change NPD-10/15-199 (PCN-199) for Tech Spec 5.3.1, "Fuel Assemblies" & Tech Spec 5.6.1, "Fuel Storage-Criticality."
* Southern California Edison Co. 85/10/16. 5pp. 33059:350-33059:354.
- 8510180328** Submits addl info & requests minor mods to util 840125 & 0427 Proposed Change Notices 8 & 97, revising Tech Specs re containment isolation valves & hydrogen monitors, respectively, to Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 12pp. 33061:251-33061:287.
- 8510180336** Proposed revs to Tech Specs, restructuring Table 3.6-1, "Containment Isolation Valves" & revising Surveillance Requirement 4.6.3.1 to ref Spec 4.0.5, "In-service Insp," as basis for determining valve operability.
* Southern California Edison Co. 85/10/16. 25pp. 33061:263-33061:287.
- 8510280419** Supplemental application for amends to Licenses NPF-10 & NPF-15, withdrawing previously submitted Proposed Change Notice 84 & inserting encl rev.
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33194:017-33194:022.

Q. Inspection reports, IE Bulletins & correspondence

- 8510170053** Forwards Special Team Insp Repts 50-361/85-22 & 50-362/85-21 on 850812-23. No noncompliance noted. Control over preparation for mod work & use of work instructions w/o approved maint procedures marginally acceptable.
KIRSCH, D.F. Region 5, Office of Director. 85/09/25. BASKIN, K.P. Southern California Edison Co. 4pp. 33052:099-33052:117.
- 8510170054** Insp Repts 50-361/85-22 & 50-362/85-21 on 850812-23. No violation or deviation noted. Major areas inspected: mgt controls re procedures, policies & administrative orders & mgt involvement in implementation as applied to operation.
ALBERT, W.G., BOSTED, C., CREWS, J. Region 5, Office of Director. 85/09/19. 14pp. 33052:103-33052:117.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510240269** Forwards Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21. No violation or deviation noted. Major areas inspected: QA program & licensee actions on previously identified items.
KIRSCH, D.F. Region 5, Office of Director. 85/10/04. BASKIN, K.P. Southern California Edison Co. 1p. 33159:060-33159:060.
- 8510240281** Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21. No violation or deviation noted. Major areas inspected: QA program & licensee actions on previously identified items.
NARBUT, P.P., JOHNSON, P.H. Region 5, Office of Director. 85/10/02. 5pp. 33159:061-33159:065.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.
- 8510180328** Submits addl info & requests minor mods to util 840125 & 0427 Proposed Change Notices 8 & 97, revising Tech Specs re containment isolation valves & hydrogen monitors, respectively, to Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 12pp. 33061:251-33061:287.
- 8510180336** Proposed revs to Tech Specs, restructuring Table 3.6-1, "Containment Isolation Valves" & revising Surveillance Requirement 4.6.3.1 to ref Spec 4.0.5, "In-service Insp," as basis for determining valve operability.
* Southern California Edison Co. 85/10/16. 25pp. 33061:263-33061:287.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510260285 Responds to 841212 request for addl info re consistency between inservice insp interval start dates & ASME Boiler & Pressure Vessel Code Units 1 & 2 start dates were 830818 & 840401, respectively.
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33192:347-33192:348.

R. Periodic operating reports & related correspondence

8510020113 Forwards monthly operating repts for Jul 1985. Revised Unit 3 June 1985 shutdown & power reductions sheet encl due to numbering error. Revised Unit 2 June 1985 operating status rept encl due to error in hours generator on-line.
MORGAN, H.E. Southern California Edison Co. 85/06/15. Office of Resource Management, Director. 1p. 32827:069-32827:081.

-8510020114 Monthly operating repts for Jul 1985.
MAISEL, R.J. Southern California Edison Co. 85/07/31. 10pp. 32827:070-32827:079.

-8510020119 Revised Unit 2 operating status rept & Unit 3 unit shutdown & power reductions sheet from monthly operating repts for June 1985.
MAISEL, R.J. Southern California Edison Co. 85/06/30. 2pp. 32827:080-32827:081.

8510280296 Forwards auxiliary feedwater sys monthly outage rept for 850816-0915, per License Condition 2.C(26).
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33192:343-33192:344.

S. Reportable occurrences, LERs & related correspondence

8510020212 LER 85-044-00 on 850910, Train A containment purge isolation sys spuriously actuated due to electrical noise spike on containment area radiation monitor investigation underway. Containment purge isolation sys reset. W/850924 ltr.
MORGAN, H.E. Southern California Edison Co. 85/09/24. 2pp. 32827:212-32827:213.

8510090183 LER 85-043-00 on 850831, toxic gas isolation sys Train A actuated. Caused by electrical failure in ammonia analyzer channel. Power supply, balance potentiometer & motor source assembly components replaced. W/850927 ltr.
MORGAN, H.E. Southern California Edison Co. 85/09/27. 2pp. 32947:173-32947:174.

8510080482 PNO-V-85-067 on 851002, earthquake of magnitude 5.0 on Richter scale occurred. Epicenter located approx 50 miles north of site. Event minor, not felt by site personnel & did not activate recording instruments.
JOHNSON, P., HUEY, R. Region 5, Office of Director. 85/10/03. 1p. 32921:164-32921:164.

8510170455 LER 85-045-00 on 850909, discovered that position verification not performed at scheduled time for control element assembly calculator 2 on 850815. Caused by personnel error. Notation included i. surveillance log W/851007 ltr.
MORGAN, H.E. Southern California Edison Co. 85/10/07. 2pp. 33053:252-33053:253.

8510170365 LER 85-048-00 on 850915, w/unit in Mode 3, containment purge initiated, requiring collection of iodine & particulate sample. Sample collected late due to failure of chemistry technician to follow direction. W/851010 ltr.
MORGAN, H.E. Southern California Edison Co. 85/10/10. 2pp. 33053:254-33053:255.

8510220127 Followup rept of inoperable fire-rated assemblies found during Sept 1985 surveillances per util 850910 ltr. Compensatory fire watches established. Continuing corrective actions to upgrade door latches & closure mechanisms cited.
MORGAN, H.E. Southern California Edison Co. 85/10/10. MARTIN, J.B. Region 5, Office of Director. 10pp. 33090:120-33090:129.

8510210290 LER 85-046-00 on 850912, reactor trip occurred in response to turbine loss of load signal due to loss of field on generator. Caused by generator exciter fire. Slip rings refinished. Alarm detection sys enhanced. W/851015 ltr.
MORGAN, H.E. Southern California Edison Co. 85/10/15. 5pp. 33095:039-33095:043.

8510310549 LER 85-039-01 on 850722, toxic gas isolation sys Train B actuated when hydrocarbon analyzer malfunctioned. Control room emergency air cleanup sys actuated as required. Toxic gas isolation sys reset. W/851025 ltr.
MORGAN, H.E. Southern California Edison Co. 85/10/25. 2pp. 33280:019-33280:020.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832:352-32832:353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832:354-32832:001.

-8510010428 Power plant exam results summary sheets. Info deleted.
* Public Service Electric & Gas Co. of New Jersey. 85/09/20. 9pp. 32832:355-32832:001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8510070179 Forwards revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements." Procedure S023-VIII-28.2 should be deleted.
ZINTL, W.G. Southern California Edison Co. 85/09/27. MARTIN, J.B. Region 5, Office of Director. 2pp. 32881:084-32881:119.

-8510070185 Revised emergency plan implementing procedures, including Temporary Change TCN 2-2 to Rev 2 to S0123-VIII-30.2, "Emergency Public Address Announcements" & Temporary Change TCN 3-1 to Rev 3 to S0123-VIII-70.1, "Site Telephone."
BENNETT, D.D., HOWELL, T.G., WHARTON, M.A. Southern California Edison Co. 85/09/27. 32pp. 32881:086-32881:119.

8510180493 Expresses appreciation for coordinating 850924 site visit & 850925 emergency operations facility tour.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/15. BASKIN, K.P. Southern California Edison Co. 2pp. 33077:335-33077:336.

8510310277 Revised emergency plan implementing procedures, including Rev 2 to S0123-VIII-0.301, "Offsite/Onsite Communications Test" & Temporary Change Notice 1-3 to Rev 1 to S0123-VIII-0.202, "Assignment of Emergency Response Personnel." W/851025 ltr.
ZINTL, W.G. Southern California Edison Co. 85/10/25. MARTIN, J.B. Region 5, Office of Director. 93pp. 33272:161-33272:250.

8510310285 Advises that 850620 & 1023 Revs 5 & 5A to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. Figure 5-1 & const security procedures to be submitted as Rev 5B will be reviewed upon receipt, per 851024 telcon.
SCHUSTER, M.D. Region 5, Office of Director. 85/10/29. MORGAN, H.E. Southern California Edison Co. 4pp. 33273:267-33273:271.

P. Operating license stage documents & correspondence

8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDR App E documents withheld (ref FOIA Exemptions 6 & 7).
FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 3pp. 32833:002-32833:052.

8510070097 Forwards Amends 34 & 23 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec 3/4.8.1.1, "Electrical Power Sys - AC Sources - Operating," re onsite electrical power sources.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 32901:179-32901:198.

-8510070104 Amends 34 & 23 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Spec 3/4.8.1.1, "Electrical Power Sys - AC Sources - Operating," re onsite electrical power sources.
KNIGHTON, G.W. Licensing Branch 3. 85/09/25. 14pp. 32901:182-32901:195.

-8510070111 Safety evaluation supporting Amends 34 & 23 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/09/25. 2pp. 32901:196-32901:198.

8510110088 Forwards Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec 3.2.6, "Reactor Coolant Cold Leg Temp," at power levels less than 70%.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33011:003-33011:018.

-8510110094 Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Spec 3.2.6, "Reactor Coolant Cold Leg Temp," re cold leg temp limits at power levels less than 70%.
KNIGHTON, G.W. Licensing Branch 3. 85/09/24. 10pp. 33011:006-33011:015.

-8510110268 Safety evaluation supporting Amends 35 & 24 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/09/25. 10pp. 33011:016-33011:018.

8510160174 Further response to FOIA request for 12 categories of documents re plant. Forwards App E documents. App F documents available in PDR. Apps G & H documents withheld (ref FOIA Exemptions 7 & 5).
FELTON, J.M. Division of Rules and Records. 85/09/26. ZAEKE, D. Sierra Club. 6pp. 33042:331-33042:357.

8510110232 Forwards Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Specs re operability of post-accident cleanup filter sys, borated water source shutdown & boric acid tank storage.
KNIGHTON, G.W. Licensing Branch 3. 85/09/30. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33011:353-33011:015.

-8510110235 Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs 3/4.9.12, "Fuel Handling Bldg Post-Accident Cleanup Filter Sys," 3.1.2.7, "Borated Water Source - Shutdown" & 3.1.2.8 re boric acid storage tanks.
KNIGHTON, G.W. Licensing Branch 3. 85/09/30. 16pp. 33011:357-33011:011.

-8510110236 Safety evaluation supporting Amends 36 & 25 to Licenses NPF-10 & NPF-15, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 4pp. 33012:012-33012:015.

8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland, Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049:042-33049:234.

146 DOCKETED ITEMS

-8510170092 Rev 7 to Spec CS-P207, "Pipe Support Field Fabrication & Installation."
* Bechtel Corp. 80/04/18. 39pp. 33049-046-33049-218.

851004C267 Forwards response to 850508 request for addl info re Generic Ltr 83-28, "Generic Implications of Salem ATWS Event."
MEDFORD, M.O. Southern California Edison Co. 85/10/02. KNIGHTON, G.W. Licensing Branch 3. 6pp. 32853-181-32853-186.

8510110105 Forwards, for review & approval, proposed Rev 1 to "Snubber Reduction Program for Nuclear Piping Sys." Rev replaces original submitted on 850709. Fee paid.
MEDFORD, M.O. Southern California Edison Co. 85/10/09. KNIGHTON, G.W. Licensing Branch 3. 3pp. 32972-032-32972-050.

-8510110108 Rev 1 to QUAD-7-85-023, "Snubber Reduction Program for Nuclear Piping Sys."
* Southern California Edison Co. 85/10/31. 16pp. 32972-035-32972-050.

8510170090 Forwards Amend Applications 32 & 18 to Licenses NPF-10 & NPF-15, respectively, to revise Tech Specs for max enrichment limit for reload fuel assemblies. Fee paid.
BASKIN, K.P. Southern California Edison Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33037-039-33037-265.

-8510170101 Application for amends to Licenses NPF-10 & NPF-15 to revise Tech Specs for max enrichment limit for reload fuel assemblies & increasing range of boric acid concentration for refueling water storage tank.
BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. HOYT, G.W. Anaheim, CA. 85/10/09. 17pp. 33037-041-33037-057.

-8510170106 Proposed Tech Specs revising max enrichment limit for reload fuel assemblies, increasing range of boric acid concentration for refueling water storage tank & reducing max boric acid concentration in boric acid makeup tank.
* Southern California Edison Co. 85/10/09. 175pp. 33037-058-33037-265.

8510150141 Requests expedited review by 851218 of 850220 application to revise Tech Specs re RCS pressure/temp limits & component cyclic or transient limits. Expedited review will accommodate return to Mode 3 operation.
MEDFORD, M.O. Southern California Edison Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 1p. 33010-303-33010-303.

8510150199 Forwards "Technical Data Mgt Ctr Computer Code Data Collections, Scale 2, Modular Code Sys for Performing Standardized Computer Analyses for Licensing Evaluation." Calculations support 850823 Proposed Change NPF-10/15-199.
MEDFORD, M.O. Southern California Edison Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 1p. 33000-001-33000-001.

-8510150203 "Technical Data Mgt Ctr Computer Code Data Collections, Scale 2, Modular Code Sys for Performing Standardized Computer Analyses for Licensing Evaluation."
* Oak Ridge National Laboratory. CCC-450. 85/10/10. 293pp. 33000-002-33000-296.

8510240411 Forwards Amends 37 & 26 to Licenses NPF-10 & NPF-15, respectively & safety evaluation. Amends modify Tech Spec "Containment Structural Integrity" & License Condition 2.c(4), "Containment Tendon Surveillance."
KNIGHTON, G.W. Licensing Branch 3. 85/10/11. BASKIN, K.P. Southern California Edison Co. HOLCOMBE, J.C. San Diego Gas & Electric Co. 4pp. 33182-206-33182-228.

-8510240417 Amends 37 & 26 to License NPF-10 & NPF-15, respectively, modifying Tech Spec "Containment Structural Integrity" & License Condition 2.c(4), "Containment Tendon Surveillance."
THOMPSON, H.L. Division of Licensing. 85/10/11. 14pp. 33182-210-33182-223.

-8510240420 Safety evaluation supporting Amends 37 & 26 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given. 85/10/11. 5pp. 33182-224-33182-226.

8510170267 Submits proposed schedule for meeting requirements of 10CFR50.62, per Generic Ltr 85-06 re QA guidance for non-safety-related ATWS equipment. Diverse scram sys will be installed during first refueling outage after 870601.
MEDFORD, M.O. Southern California Edison Co. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33039-293-33039-294.

8510180167 Forwards revised Proposed Change NPD-10/15-199 (PCN-199) to Tech Spec 5.3.1, "Fuel Assemblies," clarifying 851010 calculations supporting 850823 application to amend Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33059-347-33059-349.

-8510180173 Revs to Proposed Change NPD-10/15-199 (PCN-199) for Tech Spec 5.3.1, "Fuel Assemblies" & Tech Spec 5.6.1, "Fuel Storage-Criticality."
* Southern California Edison Co. 85/10/16. 5pp. 33059-350-33059-354.

8510180328 Submits addl info & requests minor mods to util 840125 & 0427 Proposed Change Notices 8 & 97, revising Tech Specs re containment isolation valves & hydrogen monitors, respectively, to Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 12pp. 33061-251-33061-287.

-8510180336 Proposed revs to Tech Specs, restructuring Table 3.6-1, "Containment Isolation Valves" & revising Surveillance Requirement 4.6.3.1 to ref Spec 4.0.5, "In-service Insp," as basis for determining valve operability.
* Southern California Edison Co. 85/10/16. 25pp. 33061-263-33061-287.

8510280419 Supplemental application for amends to Licenses NPF-10 & NPF-15, withdrawing previously submitted Proposed Change Notice 84 & inserting encl rev.
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33194-017-33194-022.

G. Inspection reports, IE Bulletins & correspondence

8510170053 Forwards Special Team Insp Repts 50-361/85-22 & 50-362/85-21 on 850812-23. No noncompliance noted. Control over preparation for mod work & use of work instructions w/o approved maint procedures marginally acceptable.
KIRSCH, D.F. Region 5, Office of Director. 85/09/25. BASKIN, K.P. Southern California Edison Co. 4pp. 33052-099-33052-117.

-8510170054 Insp Repts 50-361/85-22 & 50-362/85-21 on 850812-23. No violation or deviation noted. Major areas inspected: mgt controls re procedures, policies & administrative orders & mgt involvement in implementation as applied to operation.
ALBERT, W.G., BOSTED, C., CREWS, J. Region 5, Office of Director. 85/09/19. 14pp. 33052-103-33052-117.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

-8510230164 Forwards Press Release V-1484 re NRC proposed fine against util for disabling facility safety sys.
KAMMERER, C. Office of Congressional Affairs. 84/05/16. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-003-33109-004.

-8510230250 Forwards Press Release 84-113 re NRC reduction in proposed civil penalty in amount of \$250,000 by 50% due to prompt & extensive corrective action by util. Containment spray sys subsystem inoperable on 840304-17.
KAMMERER, C. Office of Congressional Affairs. 84/09/25. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-107-33109-108.

8510240269 Forwards Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21. No violation noted.
KIRSCH, D.F. Region 5, Office of Director. 85/10/04. BASKIN, K.P. Southern California Edison Co. 1p. 33159-060-33159-060.

-8510240281 Insp Repts 50-206/85-31, 50-361/85-30 & 50-362/85-29 on 850916-21. No violation or deviation noted. Major areas inspected: QA program & licensee actions on previously identified items.
NARBUT, P.P., JOHNSON, P.H. Region 5, Office of Director. 85/10/02. 5pp. 33159-061-33159-065.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510180328 Submits addl info & requests minor mods to util 840125 & 0427 Proposed Change Notices 8 & 97, revising Tech Specs re containment isolation valves & hydrogen monitors, respectively, to Licenses NPF-10 & NPF-15.
MEDFORD, M.O. Southern California Edison Co. 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 12pp. 33061-251-33061-287.

-8510180336 Proposed revs to Tech Specs, restructuring Table 3.6-1, "Containment Isolation Valves" & revising Surveillance Requirement 4.6.3.1 to ref Spec 4.0.5, "In-service Insp," as basis for determining valve operability.
* Southern California Edison Co. 85/10/16. 25pp. 33061-263-33061-287.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-049-33177-204.

8510280285 Responds to 841212 request for addl info re consistency between in-service insp interval start dates & ASME Boiler & Pressure Vessel Code Units 1 & 2 start dates were 830818 & 840401, respectively.
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33192-347-33192-348.

R. Periodic operating reports & related correspondence

8510020113 Forwards monthly operating repts for Jul 1985. Revised Unit 3 June 1985 shutdown & power reductions sheet encl due to numbering error. Revised Unit 2 June 1985 operating status rept encl due to error in hours generator on-line.
MORGAN, H.E. Southern California Edison Co. 85/08/15. Office of Resource Management, Director. 1p. 32827-069-32827-081.

-8510020114 Monthly operating repts for Jul 1985.
MAISEL, R.J. Southern California Edison Co. 85/07/31. 10pp. 32827-070-32827-079.

-8510020119 Revised Unit 2 operating status rept & Unit 3 unit shutdown & power reductions sheet from monthly operating repts for June 1985.
MAISEL, R.J. Southern California Edison Co. 85/06/30. 2pp. 32827-080-32827-081.

8510280296 Forwards auxiliary feedwater sys monthly outage rept for 850816-0915, per License Condition 2.C(26).
MEDFORD, M.O. Southern California Edison Co. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33192-343-33192-344.

S. Reportable occurrences, LERs & related correspondence

- 8510080482** PNO-V-85-067 on 851002, earthquake of magnitude 5.0 on Richter scale occurred. Epicenter located approx 50 miles north of site. Event minor, not felt by site personnel & did not activate recording instruments. JOHNSON, P. Region 5, Office of Director. 85/10/03. 1p. 32921:164-32921:164.
- 8510180358** LER 85-024-00 on 850905, 16 & 1004, spurious fuel handling isolation sys actuations occurred. Caused by radiation monitor sensitivity to random electrical noise. Sys reset. Potential design deficiency being investigated. W/851007 ltr. MORGAN, H.E. Southern California Edison Co. 85/10/07. 2pp. 33068:284-33068:285.
- 8510220127** Followup rept of inoperable fire-rated assemblies found during Sept 1985 surveillances, per util 850910 ltr. Compensatory fire watches established. Continuing corrective actions to upgrade door latches & closure mechanisms cited. MORGAN, H.E. Southern California Edison Co. 85/10/10. MARTIN, J.B. Region 5, Office of Director. 10pp. 33090:120-33090:129.
- 8510290355** Special rept on 850914, RCS specific activity exceeded 1.0 uCi/g dose equivalent I-131. Caused by iodine spiking. Info required by Tech Spec 3.4.7. Action Statement d provided. MORGAN, H.E. Southern California Edison Co. 85/10/15. MARTIN, J.B. Region 5, Office of Director. 3pp. 33239:070-33239:072.
- 8510250568** LER 85-025-00 on 850916, containment purge isolation sys A spuriously actuated by signal from containment area radiation monitor. Cause not determined. Completion of ground sys study scheduled for 851101. W/851016 ltr. MORGAN, H.E. Southern California Edison Co. 85/10/16. 2pp. 33189:251-33189:252.
- 8510300165** LER 85-027-00 on 850920, during main purge, containment airborne radiation monitor 3RE-7804 reached alarm setpoint & initiated Train A containment purge isolation sys. Caused by movement of stagnant air into purge exhaust. W/851017 ltr. MORGAN, H.E. Southern California Edison Co. 85/10/17. 2pp. 33257:314-33257:355.
- 8510310591** LER 85-028-00 on 850925, fuel handling isolation sys Train A actuated w/ no fuel in spent fuel pool. Caused by increase in airborne activity. Fuel handling isolation sys reset. W/851025 ltr. MORGAN, H.E. Southern California Edison Co. 85/10/25. 2pp. 33280:001-33280:002.
- 8510310596** LER 85-029-00 on 850927, w/18-month snubber surveillance in progress, mechanical Pacific Scientific snubber failed due to installation damage. All deficient snubbers replaced. W/851025 ltr. MORGAN, H.E. Southern California Edison Co. 85/10/25. 2pp. 33279:347-33279:348.

U. Congressional/Executive Correspondence

- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230164** Forwards Press Release V-1484 re NRC proposed fine against util for disabling facility safety sys. KAMMERER, C. Office of Congressional Affairs. 84/05/16. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:003-33109:004.
- 8510230250** Forwards Press Release 84-113 re NRC reduction in proposed civil penalty in amount of \$250,000 by 50% due to prompt & extensive corrective action by util. Containment spray sys subsystem inoperable on 840304-17. KAMMERER, C. Office of Congressional Affairs. 84/09/25. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:107-33109:108.

V. Operator Examinations

- 8509240248** Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32682:049-32682:075.

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2**F. Security, medical, emergency & fire protection plans**

- 8509110513** Forwards monthly operating repts for June 1985. Rev 1 to offsite dose calculation manual, including all monitoring & sampling stations at plant, also encl W/O Rev 1. MCDONALD, R.P. Alabama Power Co. 85/07/15. Office of Resource Management, Director. 1p. 33036:100-33036:117.
- 8510180195** Rev 1 to FNP-0-M-011, "Offsite Dose Calculation Manual." * Alabama Power Co. 85/05/21. 15pp. 33036:103-33036:117.
- 8510090036** Rev 10 to emergency plan W/850924 ltr. HUDSPETH, J.B. Alabama Power Co. 85/09/24. MCKNIGHT, J. Record Services Branch (Document Control Desk). 1,100pp. 32938:001-32941:258.
- 8510150124** Rev 38 to Emergency Implementing Procedure FNP-0-EIP-8, "Emergency Communications." W/851008 ltr. HUDSPETH, J.B. Alabama Power Co. 85/10/08. MCKNIGHT, J. Record Services Branch (Document Control Desk). 36pp. 33006:319-33008:354.
- 8510160246** Forwards attachment to Procedure FNP-85-1072 re on-call schedules & requests that old revs be discarded. Requests transmittal form be signed & returned to listed address. HUDSPETH, J.B. Alabama Power Co. 85/10/11. MCKNIGHT, J. Record Services Branch (Document Control Desk). 2pp. 33024:347-33024:354.
- 8510160276** Attachment to Procedure FNP-85-1072 re on-call schedules concerning both plant & nuclear generation personnel. Schedules effective 851001. WOODARD, J.D. Alabama Power Co. 85/10/11. 6pp. 33024:349-33024:354.

- 8510280034** Forwards Technical Support Ctr SPDS display implementation plan, per 841130 commitment. MCDONALD, R.P. Alabama Power Co. 85/10/16. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 33191:015-33191:018.

- 8510250236** Forwards revised 10CFR50, App R fire protection exemption requests as result of NRC audit during wk of 850719 of util 850313, 0626 & 0719 exemption requests. Mods will be completed no later than Second Quarter 1986. MCDONALD, R.P. Alabama Power Co. 85/10/18. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 145pp. 33168:238-33169:022.

H. General correspondence

- 8510150188** Provides rev to distribution lists for all correspondence. JD Woodard should be added to list. MCDONALD, R.P. Alabama Power Co. 85/10/04. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 1p. 33008:297-33008:297.

P. Operating license stage documents & correspondence

- 8510030146** Forwards "Containment 5-Yr Tendon Surveillance Rept." Vols 1 & 2, per Tech Spec 3/4.6.1.6. Rept includes description of tendon & concrete condition, insp procedure & tolerances. Post-tensioning sys shows no signs of abnormal degradation. MCDONALD, R.P. Alabama Power Co. 85/09/16. GRACE, J.N. Region 2, Office of Director. 1p. 32841:156-32842:208.

- 8510030152** "Containment 5-yr Tendon Surveillance Rept." Vols 1 (rept) & 2 (data). * Alabama Power Co. 85/09/16. 412pp. 32841:157-32842:208.

- 8510040125** Rev 18 to Emergency Plan Implementing Procedure FNP-0-EIP-9, "Radiation Exposure Estimation & Classification of Emergencies." W/850923 ltr. HUDSPETH, J.B. Alabama Power Co. 85/09/23. MCKNIGHT, J. Record Services Branch (Document Control Desk). 5pp. 32851:203-32851:207.

- 8510110210** Application for amend to License NPF-8, changing Tech Spec Table 4.4-5 re reactor vessel matl surveillance program withdrawal schedule. Figures 3.4-2 & 3.4-3 re RCS heatup & cooldown curves & Bases 3/4.4.10. Fee paid. MCDONALD, R.P. Alabama Power Co. 85/09/30. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 32974:041-32974:111.

- 8510110245** Proposed Tech Specs, changing Table 4.4-5 re reactor vessel matl surveillance program withdrawal schedule. Figures 3.4-2 & 3.4-3 re RCS heatup & cooldown curves & Bases 3/4.4.10. * Alabama Power Co. 85/09/30. 44pp. 32974:043-32974:086.

- 8510110246** "Heatup & Cooldown Limit Curves for Alabama Power Co, JM Farley Unit 2 Reactor Vessel." KAISER, W.T., CONGEDO, T.V., YANICHKO, S.E. Westinghouse Electric Corp. WCAP-10910. 85/08/31. 25pp. 32974:087-32974:111.

- 8510150285** Informs that util will finalize plans for ATWS mitigating scram actuation circuitry implementation & develop detailed schedule within 90 days of tentatively scheduled Nov 1985 issuance of SER. MCDONALD, R.P. Alabama Power Co. 85/10/04. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 33009:111-33009:112.

- 8510160081** Forwards fee for application for inservice testing of refueling water storage tank check valves in response to 850923 request. MCDONALD, R.P. Alabama Power Co. 85/10/08. DIGGS, R.M. Office of Nuclear Reactor Regulation, Director. 1p. 33028:006-33028:006.

- 8510180134** Forwards proposed schedule for completion of 1985/1986 licensing items, including inservice insp code relief for 10-yr reactor vessel exam, administrative offsite & onsite organizational changes & removal of rod bow penalty. MCDONALD, R.P. Alabama Power Co. 85/10/14. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 33055:049-33055:052.

- 8510310222** Requests assistance in reviewing encl util 850919 proposed administrative Tech Spec change, implementing listed mgt changes. SER & SALP input requested by 851031. THOMPSON, H.L. Division of Licensing. 85/10/21. WALKER, R.D. Region 2, Office of Director. 2pp. 33277:317-33277:344.

Q. Inspection reports, IE Bulletins & correspondence

- 8510030146** Forwards "Containment 5-Yr Tendon Surveillance Rept." Vols 1 & 2, per Tech Spec 3/4.6.1.6. Rept includes description of tendon & concrete condition, insp procedure & tolerances. Post-tensioning sys shows no signs of abnormal degradation. MCDONALD, R.P. Alabama Power Co. 85/09/16. GRACE, J.N. Region 2, Office of Director. 1p. 32841:156-32842:208.

- 8510030152** "Containment 5-yr Tendon Surveillance Rept." Vols 1 (rept) & 2 (data). * Alabama Power Co. 85/09/16. 412pp. 32841:157-32842:208.

- 8510070349** Responds to violations noted in Insp Repts 50-348/85-33 & 50-364/85-33. Corrective actions: engineering evaluation will be performed to determine acceptability of welding activities performed on listed maint work requests. MCDONALD, R.P. Alabama Power Co. 85/09/26. VERRELLI, D.M. Region 2, Office of Director. 4pp. 32877:248-32877:251.

- 8510070490** Responds to violations noted in Insp Repts 50-348/85-34 & 50-364/85-34. Corrective actions: 64 drums of sludge lance filters buried following collection & solidification of all free standing water approved. MCDONALD, R.P. Alabama Power Co. 85/09/26. VERRELLI, D.M. Region 2, Office of Director. 5pp. 32878:128-32878:132.

- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

148 DOCKETED ITEMS

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070365 Ack receipt of 850816 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-348/85-25 & 50-364/85-25. Requests that responses to Violations 1b,2a, 3 & 4 be resubmitted within 30 days.
GRACE,J.N. Region 2, Office of Director. 85/10/01. McDONALD,R.P. Alabama Power Co. 6pp. 32878.259-32878.264.

8510180134 Forwards proposed schedule for completion of 1985/1986 licensing items,including inservice insp code relief for 10-yr reactor vessel exam,administrative offsite & onsite organizational changes & removal of rod bow penalty.
McDONALD,R.P. Alabama Power Co. 85/10/14. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 33055-049-33055.052.

8510180359 Forwards three addl requests for relief from inservice insp program for ASME Code Class 1,2 & 3 components re reactor vessel flange ligaments & visual exam of reactor coolant pump casing pressure boundary surfaces.Fee paid.
McDONALD,R.P. Alabama Power Co. 85/10/14. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 6pp. 33062-244-33062.250.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class,Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 152pp. 33177.205-33177.341.

8510180334 Forwards fee inadvertently omitted from encl util 851014 request for relief from certain requirements of ASME Code, Section XI.
* Alabama Power Co. 85/10/15. NRC - No Detailed Affiliation Given. 1p. 33062-148-33062.154.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

R. Periodic operating reports & related correspondence

8510010495 Monthly operating rept for Jul 1985.W/850812 ltr.
WOODARD,J.D., McDONALD,R.P. Alabama Power Co. 85/07/31. 5pp. 32820-136-32820.140.

8510220054 Monthly operating rept for Sept 1985.W/851017 ltr.
WOODARD,J.D., McDONALD,R.P. Alabama Power Co. 85/09/30. 5pp. 33095.269-33095.273.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER,S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832.353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants.Forwards summary sheets for five plants.Portion deleted Summary sheets for stated plants destroyed.
FELTON,J.M. Division of Rules and Records. 85/09/20. HANAUER,S.H. Technical Analysis Corp. 1p. 32832-354-32833.001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list er
THOMPSON,L.H. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882.075.

8510280294 Forwards operator licensing & requalification exam schedules for FY86-FY89,per Generic Ltr 85-18,in response to 850927 request.
McDONALD,R.P. Alabama Power Co. 85/10/21. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 3pp. 33192-066-33192.068.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510070471 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-321/85-23 & 50-366/85-23.Corrective actions:operations & shift supervisors retrained in role of emergency director. Procedure 63EP-EIP-073-0 replaced in manual.
GUCWALT,T. Georgia Power Co. 85/09/24. GRACE,J.N. Region 2, Office of Director. 4pp. 32878.208-32878.211.

8510180189 Discusses violation noted in Insp Repts 50-321/83-15 & 50-366/83-15 re several locked-open valves,including fire protection valve observed unlocked.Violation applied only to Unit 1.Change in administrative controls stated.
GUCWALT,T. Georgia Power Co. 85/09/30. GRACE,J.N. Region 2, Office of Director. 2pp. 33059-332-33059.333.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108.264-33109.086.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522.
KAMMERER,C. Office of Congressional Affairs. 84/07/11. OTTINGER,R.L. House of Rep. Energy & Commerce. NUNN Senate. ROWLAND House of Rep. 2pp. 33109.019-33109.020.

8510150296 Forwards Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20.No violations or deviations noted.
BROWN,LEE,V.L. Region 2, Office of Director. 85/10/08. KELLY,R.J. Georgia Power Co. 2pp. 33009.098-33009.099.

-8510150304 Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20.No violations or deviations noted.Major areas inspected:program audit,records & repts,testing & maint,locks & keys.Details withheld (ref 10CFR2.790(d) & 73.21).
MASNYK,O.M. Region 2, Office of Director. 85/10/02. 1p. 33009.100-33009.100.

8510250250 Forwards amend to security plan.Amend withheld (ref 10CFR73.21 & 2.790).
BECKHAM,J.T. Georgia Power Co. 85/10/10. GRACE,J.N. Region 2, Office of Director. 1p. 33172-270-33172.270.

8510250448 Revised emergency plan implementing procedures,including Rev 1 to 62RP-RAD-008-OS, "Radiation & Contamination Surveys" & Rev 1 to 62H-OCB-047-OS, "HP Well Counter Sys." W/851021 ltr.
ZAVADOSKI,R.W., SORRELL,E.C. Georgia Power Co. 85/10/21. 45pp. 33173.046-33173.090.

I. Financial information

8510170029 Advises that financial info submitted for 1985 in 850726 ltr satisfies requirements of 10CFR140.21.
SALTZMAN,J. Assistant Director for State & Licensee Relations. 85/10/01. COOK,L.A. Georgia Power Co. 1p. 33043.222-33043.222.

P. Operating license stage documents & correspondence

8510010098 Responds to 850607 request for info re Generic Ltr 83-28, Item 1.1 re post-trip review.Forwards Rev 0 to Engineering Svc Procedure 42EN-ENG-011-OS, "Scram/Transient Reporting." Fee paid.
GUCWALT,T. Georgia Power Co. 85/09/23. STOLZ,J.F. Operating Reactors Branch 4. 7pp. 32800.208-32800.239.

-8510010114 Rev 0 to Engineering Svc Procedure 42EN-ENG-011-OS, "Scram/ Transient Reporting."
* Georgia Power Co. 85/08/23. 25pp. 32800.215-32800.239.

8510150289 Informs that util 850820 ltr on purge & vent mods contained proposed Tech Spec requirements more restrictive than those reviewed by plant review board.Board will review requirements by 851010.
GUCWALT,T. Georgia Power Co. 85/10/04. STOLZ,J.F. Operating Reactors Branch 4. 1p. 33009.110-33009.110.

8510150338 Forwards addl info re 841120 & 850506 responses to Generic Ltr 84-23, "Reactor Water Level Instrumentation in BWRs." Plant capable of effectively compensating for reactor water level indication errors caused by drywell heatup.
GUCWALT,T. Georgia Power Co. 85/10/07. STOLZ,J.F. Operating Reactors Branch 4. 16pp. 33013.011-33013.026.

8510280301 Forwards latest chronological update of util correspondence w/NRR to which written response expected,per util 850815 ltr Expedited resolution of listed priority items in support of upcoming outage requested.
GUCWALT,T. Georgia Power Co. 85/10/11. STOLZ,J.F. Operating Reactors Branch 4. 4pp. 33193.254-33193.258.

8510210142 Submits schedule for completing required ATWS mods,per 10CFR50.62.Mods will be implemented by end of third refueling outage after ATWS rule effective date.
GUCWALT,T. Georgia Power Co. 85/10/14. STOLZ,J.F. Operating Reactors Branch 4. 3pp. 33071.349-33071.351.

8510280420 Discusses status of cable tray support verification program.All supports modified to bring calculated stresses within allowable values.
GUCWALT,T. Georgia Power Co. 85/10/15. STOLZ,J.F. Operating Reactors Branch 4. 3pp. 33194.014-33194.016.

Q. Inspection reports, IE Bulletins & correspondence

8510010277 Forwards,for NRC approval,reestablished license requalification program,in response to Exam Rept 50-321/OL-84-01 & deficiencies identified in Insp Repts 50-321/85-07 & 50-366/85-07.
GUCWALT,T. Georgia Power Co. 85/09/24. STOLZ,J.F. Operating Reactors Branch 4. 8pp. 32800.177-32800.184.

8510070471 Responds to NRC 850826 ltr re violations noted in Insp Repts 50-321/85-23 & 50-366/85-23.Corrective actions:operations & shift supervisors retrained in role of emergency director. Procedure 63EP-EIP-073-0 replaced in manual.
GUCWALT,T. Georgia Power Co. 85/09/24. GRACE,J.N. Region 2, Office of Director. 4pp. 32878.208-32878.211.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance.Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON,D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT,J.P. Division of Engineering. 4pp. 32803.095-32803.125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803.099-32803.125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint,Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8510180169 Discusses violation noted in Insp Repts 50-321/83-15 & 50-366/83-15 re several locked-open valves including fire protection valve observed unlocked. Violation applied only to Unit 1 Change in administrative controls stated.
GUCWALT, Georgia Power Co. 85/09/30. GRACE, J.N. Region 2, Office of Director. 2pp. 33059:332-33059:333.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220413 Forwards Insp Repts 50-321/85-26 & 50-366/85-26 on 850909-13 & notice of violation.
BROWNLEE, L.L. Region 2, Office of Director. 85/10/03. KELLY, R.J. Georgia Power Co. 2pp. 33097:038-33097:056.

-8510220418 Insp Repts 50-321/85-26 & 50-366/85-26 on 850909-13. Violation noted: failure to follow insp program for Class 2 tubing welds.
CROWLEY, B.R., BLAKE, J.J. Region 2, Office of Director. 85/10/01. 15pp. 33097:042-33097:056.

8510180378 Ack receipt of 850924 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/85-23 & 50-366/85-23. Requirements of 10CFR2.201 met.
WALKER, R.D. Region 2, Office of Director. 85/10/04. KELLY, R.J. Georgia Power Co. 1p. 33068:275-33068:275.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:088.

-8510230042 Forwards response to JR Bass 840102 request for info re 831227 imposition of civil penalty in amount of \$100,000.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. NUNN, S. Senate. 1p. 33108:276-33108:276.

-8510230048 Forwards response to JR Bass 840102 request for info re 831227 proposed civil penalty in amount of \$100,000. Listed documentation, including NRC 831227 proposed civil penalty & computer printout describing violations, encl.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. THOMAS, L. House of Rep. 4pp. 33108:277-33108:286.

-8510230054 Forwards corrected Page 2 to 831227 proposed imposition of civil penalties based on violations noted in Insp Rept 50-366/83-23 re improper shutdown. Correction due to administrative oversight.
O'REILLY, J.P. Region 2, Office of Director. 84/01/06. KELLY, R.J. Georgia Power Co. 3pp. 33108:287-33108:329.

-8510230058 Requests response to encl JR Bass 840102 ltr re proposed fine against util.
THOMAS, L. House of Rep. 84/02/01. KAMMERER, C. Office of Congressional Affairs. 2pp. 33108:330-33108:331.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522.
KAMMERER, C. Office of Congressional Affairs. 84/07/11. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. MATTINGLY Senate. 2pp. 33109:019-33109:020.

8510150296 Forwards Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/08. KELLY, R.J. Georgia Power Co. 2pp. 33009:098-33009:099.

-8510150304 Insp Repts 50-321/85-29 & 50-366/85-29 on 850916-20. No violations or deviations noted. Major areas inspected: program audit, records & repts, testing & maint, locks & keys. Details withheld (ref 10CFR2.790(d) & 73.21).
MASNYK, O.M., MCGUIRE, D.R. Region 2, Office of Director. 85/10/02. 1p. 33009:100-33009:100.

8510180373 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/85-22 & 50-366/85-22. Requirements of 10CFR2.201 met.
WALKER, R.D. Region 2, Office of Director. 85/10/09. KELLY, R.J. Georgia Power Co. 1p. 33068:280-33068:280.

8510160264 Requests ltr stating that listed facilities do not have fuel element transfer tubes. Documentation needed for IE Bulletin 78-08 closeout rept.
LOFY, R.A. Parameter, Inc. NRC-05-85-157-02. 85/10/10. BAER, R.L. Engineering & Generic Communications Branch. 4pp. 33023:351-33023:354.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510180536 Monthly operating repts for Sept 1985. W/851010 ltr.
KOEBER, G.M., KANIPE, L.M., NIX, H.C. Georgia Power Co. 85/09/30. 13pp. 33068:020-33068:032.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L. Government Accountability Project. 32pp. 32884:005-32884:234.

-8510020245 Part 21 rept re pump diaphragm failures initially reported on 800403. Caused by closure of containment isolation valves w/o pump shutdown. Bypass kit available to limit pump pressure. Defects not reportable per 10CFR21.
ROBINSON, A. Comsip, Inc. 81/04/08. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 3pp. 32890:158-32890:160.

8510080085 LER 85-027-00 on 850904, during test, fuse blew, resulting in automatic isolation of inboard reactor water cleanup primary containment isolation valve. Caused by jumper coming off one relay terminal. Fuse replaced. W/850927 ltr.
TIPPS, S.B., NIX, H.C. Georgia Power Co. 85/09/27. 3pp. 32928:207-32928:209.

8510180377 LER 85-031-00 on 850913, reactor water cleanup pump inboard suction isolation valve isolated. Caused by nonlicensed staff not completely closing strainer backwash valves prior to svc. Instructions placed next to valves. W/851007 ltr.
TIPPS, S.B., NIX, H.C. Georgia Power Co. 85/10/07. 3pp. 33068:276-33068:278.

8510250564 LER 85-021-01 on 850707, reactor water cleanup pump inboard & outboard suction isolation valves isolated on high sys differential flow. Caused by incompletely closed valves due to misaligned indicators. Valves closed. W/851018 ltr.
TIPPS, S.B., NIX, H.C. Georgia Power Co. 85/10/18. 3pp. 33189:300-33189:302.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:088.

-8510230042 Forwards response to JR Bass 840102 request for info re 831227 imposition of civil penalty in amount of \$100,000.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. NUNN, S. Senate. 1p. 33108:276-33108:276.

-8510230048 Forwards response to JR Bass 840102 request for info re 831227 proposed civil penalty in amount of \$100,000. Listed documentation, including NRC 831227 proposed civil penalty & computer printout describing violations, encl.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/02/28. THOMAS, L. House of Rep. 4pp. 33108:277-33108:286.

-8510230058 Requests response to encl JR Bass 840102 ltr re proposed fine against util.
THOMAS, L. House of Rep. 84/02/01. KAMMERER, C. Office of Congressional Affairs. 2pp. 33108:330-33108:331.

-8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522.
KAMMERER, C. Office of Congressional Affairs. 84/07/11. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:019-33109:020.

V. Operator Examinations

8510010277 Forwards, for NRC approval, reestablished license requalification program, in response to Exam Rept 50-321/OL-84-01 & deficiencies identified in: Insp Repts 50-321/85-07 & 50-366/85-07.
GUCWALT, Georgia Power Co. 85/09/24. STOLZ, J.F. Operating Reactors Branch 4. 8pp. 32800:177-32800:184.

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-366 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053:256-33053:272.

-8510170375 Notice of violation from insp on 850801-31.
* Region 4, Office of Director. 85/10/03. 2pp. 33053:258-33053:259.

-8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted: failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D. Region 4, Office of Director. 85/10/01. 13pp. 33053:260-33053:272.

8510170402 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-15 & 50-368/85-16.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33053:332-33053:334.

-8510170410 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-313/85-15 & 50-368/85-16. Corrective actions. Procedure 2203.09, "Fire Protection Sys Annunciator Corrective Action," Rev 0 revised.
ENOS, J.T. Arkansas Power & Light Co. 85/08/23. DENISE, R.P. Region 4, Office of Director. 2pp. 33053:333-33053:334.

150 DOCKETED ITEMS

8510160056 Ack receipt of 850429 & 0723 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-12 & 50-368/85-12. Replies responsive to violations w/exception of meeting 10CFR73.55 requirements re physical security. JOHNSON, E.H. Region 4, Office of Director. 85/10/09. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33028:132-33028:133.

8510220031 Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098:257-33098:274.

8510180294 Rev 2 to Emergency Plan Implementing Procedure 1903.34, "Emergency Operations Facility Evacuation."
* Arkansas Power & Light Co. 85/10/11. 19pp. 33062:087-33062:105.

8510220322 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-20 & 50-368/85-21.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33088:185-33088:187.

-8510220332 Responds to NRC 850622 ltr re deviations noted in Insp Repts 50-313/85-20 & 50-368/85-21. Corrective actions: all ltrs of agreement between util & outside support groups/agencies will be completed by 870101.
ENOS, J.T. Arkansas Power & Light Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 33088:186-33088:187.

8510220120 Revised emergency plan implementing procedures, including Rev 18 to 1903.10, "Emergency Action Level Response/ Notifications," Rev 2 to 1903.13, "Notification of Little Rock Corporate Official" & Rev 9 to 1903.50.
LEVINE, J.M. Arkansas Power & Light Co. 85/10/15. 100pp. 33082:001-33082:094.

8510250413 Ack receipt of 850728 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-10 & 50-368/85-10.
JOHNSON, E.H. Region 4, Office of Director. 85/10/12. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33172:226-33172:228.

-8510250421 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-313/85-10 & 50-368/85-10. Corrective actions: radiological protection procedures stressed in radiological emergency response training for field monitoring teams.
ENOS, J.T. Arkansas Power & Light Co. 85/07/28. MARTIN, R.D. Region 4, Office of Director. 2pp. 33172:227-33172:228.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510220031 Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098:257-33098:274.

P. Operating license stage documents & correspondence

8510160253 Reissues response to 841207 request for addl info re util response to Generic Ltr 83-28. Author 850408 Amend 1 to Generic Ltr 83-28 response, per B&W Owners Group activities, applicable to util.
ENOS, J.T. Arkansas Power & Light Co. 85/04/23. THOMPSON, H. Division of Licensing. 5pp. 33023:212-33023:216.

8510070237 Forwards addl info, comments & clarifications re certain difficulties/discrepancies noted during review of SER concerning inservice testing program, per 850620 request.
ENOS, J.T. Arkansas Power & Light Co. 85/09/30. BUTCHER, E.J. Operating Reactors Branch 3. 10pp. 32878:001-32878:010.

8510170129 Advises that based on review of 841210 response & info obtained in 850313 meeting re TMI Item II.K.3.25, operator action to reinstate seal cooling acceptable. NRC believes automatic reinitiation of seal cooling preferable.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/07. GRIFFIN, J.M. Arkansas Power & Light Co. 7pp. 33043:171-33043:177.

8510240610 Forwards Amend 69 to License NPF-6 & safety evaluation. Amend changes Tech Spec Table 3.6-1 re containment electrical penetration conductor overcurrent protective devices.
LEER, Operating Reactors Branch 3. 85/10/11. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33185:097-33185:118.

-8510240619 Amend 69 to License NPF-6; revising Tech Spec Table 3.6-1 re containment electrical penetration conductor overcurrent protective devices.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/11. 15pp. 33185:099-33185:115.

-8510240627 Safety evaluation supporting Amend 69 to License NPF-6.
* Office of Nuclear Reactor Regulation, Director. 85/10/11. 3pp. 33185:116-33185:118.

8510220203 Advises of intention to complete ATWS mods prior to criticality following third refueling outage scheduled for Sept 1987. Plant-specific design will be submitted when available following C-E Owners Group concurrence.
ENOS, J.T. Arkansas Power & Light Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33087:311-33087:312.

8510280218 Forwards addl info re 850830 Tech Spec change request concerning CPC sys response to CEA inward deviation, in response to NRC questions. COLSS monitors DNB limiting conditions for operation.
ENOS, J.T. Arkansas Power & Light Co. 85/10/22. BUTCHER, E.J. Operating Reactors Branch 3. 5pp. 33191:197-33191:201.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510160066 Comments on 850903 SALP rept for July 1984 - June 1985. Rept comprehensive & objective. Portions of recommendations made by task force to evaluate design change process implemented. Process significantly improved & will continue to improve.
ENOS, J.T. Arkansas Power & Light Co. 85/10/03. MARTIN, R.D. Region 4, Office of Director. 3pp. 33023:358-33023:360.

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053:256-33053:272.

-8510170375 Notice of violation from insp on 850801-31.
* Region 4, Office of Director. 85/10/03. 2pp. 33053:258-33053:259.

-8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted: failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D., HARRELL, P.H., MARTIN, L.E. Region 4, Office of Director. 85/10/01. 13pp. 33053:260-33053:272.

8510170402 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-15 & 50-368/85-16.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33053:332-33053:334.

-8510170410 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-313/85-15 & 50-368/85-16. Corrective actions: Procedure 2203.09, "Fire Protection Sys Annunciator Corrective Action," Rev 0 revised.
ENOS, J.T. Arkansas Power & Light Co. 85/08/23. DENISE, R.P. Region 4, Office of Director. 2pp. 33053:333-33053:334.

8510160056 Ack receipt of 850429 & 0723 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-12 & 50-368/85-12. Replies responsive to violations w/exception of meeting 10CFR73.55 requirements re physical security.
JOHNSON, E.H. Region 4, Office of Director. 85/10/09. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33028:132-33028:133.

8510220322 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-20 & 50-368/85-21.
JOHNSON, E.H. Region 4, Office of Director. 85/10/11. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33088:185-33088:187.

-8510220332 Responds to NRC 850622 ltr re deviations noted in Insp Repts 50-313/85-20 & 50-368/85-21. Corrective actions: all ltrs of agreement between util & outside support groups/agencies will be completed by 870101.
ENOS, J.T. Arkansas Power & Light Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 33088:186-33088:187.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 860 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:065-33177:204.

8510250410 Ack receipt of 850728 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-313/85-10 & 50-368/85-10.
JOHNSON, E.H. Region 4, Office of Director. 85/10/18. GRIFFIN, J.M. Arkansas Power & Light Co. 1p. 33172:226-33172:228.

-8510250421 Responds to NRC 850624 ltr re violations noted in Insp Repts 50-313/85-10 & 50-368/85-10. Corrective actions: radiological protection procedures stressed in radiological emergency response training for field monitoring teams.
ENOS, J.T. Arkansas Power & Light Co. 85/07/28. MARTIN, R.D. Region 4, Office of Director. 2pp. 33172:227-33172:228.

R. Periodic operating reports & related correspondence

8510010482 Monthly operating rept for Jul 1985. W/850815 ltr.
HARRISON, D.F., ENOS, J.T. Arkansas Power & Light Co. 85/07/31. BASSETT, H.S. Division of Automated Information Services. 7pp. 32809:113-32809:119.

S. Reportable occurrences, LERs & related correspondence

8510010645 LER 84-010-01 on 840207, C-E notified util of incorrect pin-to-box factors incorporated into CEOR computer code, affecting Fxy calculations. Caused by inadequate review of geometry input. Review of checklist initiated. W/850920 ltr.
ROGERS, P.C., ENOS, J.T. Arkansas Power & Light Co. 85/09/20. 3pp. 32820:180-32820:182.

8510040238 PNO-IV 85-049 on 850928, cooldown commenced to replace seal on reactor coolant pump C. Seal cartridge developed crack where middle cavity seal pressure sensing line joins cartridge. Startup scheduled for 851003.
MARTIN, L.E. Region 4, Office of Director. 85/09/30. 1p. 32851:058-32851:058.

8510220036 LER 85-006-01 on 850221, fire watch door found open. Caused by failure to label door per new fire barrier & penetration marking program requirements. Door labeled & closed. Surveillance verified proper labeling. W/851011 ltr.
ROGERS, P.C., ENOS, J.T. Arkansas Power & Light Co. 85/10/11. 2pp. 33095-259-33095-260.

8510250189 LER 85-019-00 on 850913, main steam isolation sys actuated on low steam generator pressure during plant cooldown. Caused by personnel error. Sys restored to preactuation condition. Personnel counseled. W/851013 ltr.
JOHNSON, D.J., ENOS, J.T. Arkansas Power & Light Co. 85/10/13. 2pp. 33190-255-33190-256.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510170371 Forwards Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/03. GRIFFIN, J.M. Arkansas Power & Light Co. 2pp. 33053-256-33053-272.

8510170378 Insp Repts 50-313/85-22 & 50-368/85-23 on 850801-31. Violations noted: failure to verify fire water valves in correct position & two fire doors found open.
JOHNSON, W.D. Region 4, Office of Director. 85/10/01. 13pp. 33053-260-33053-272.

DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER, R.D. Region 2, Office of Director. 85/10/10. TUCKER, H.B. Duke Power Co. 1p. 33026-280-33026-282.

8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER, H.B. Duke Power Co. 85/09/27. GRACE, J.N. Region 2, Office of Director. 2pp. 33026-281-33026-282.

8510230070 Provides info re fire suppression pumps. Any pump can be loaded on Diesel 1E Pump A powered from 6,900-volt Switchgear 2TB. Pump B loaded from 6,900 Switchgear 1TD & Pump C powered from 44-kV substation. Diagrams encl.
TUCKER, H.B. Duke Power Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 6pp. 33102-251-33102-256.

8510300209 Responds to concern re adequacy of preoperational test to measure flow velocity distribution of auxiliary bldg filtered ventilation sys. Engineering evaluation concluded that ventilation sys operable.
TUCKER, H.B. Duke Power Co. 85/10/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 33247-331-33248-002.

8510300214 Confirmation of action ltr re control room & auxiliary bldg ventilation sys filter testing. Actions to be taken listed.
GRACE, J.N. Region 2, Office of Director. 85/10/23. TUCKER, H.B. Duke Power Co. 1p. 33247-333-33247-333.

8510310039 Responds to 851023 confirmation of action ltr, Item 3 re testing of control room ventilation sys. Past testing records & results of review submitted. Since ventilation sys contains only one HEPA filter, test unnecessary.
TUCKER, H.B. Duke Power Co. 85/10/29. GRACE, J.N. Region 2, Office of Director. 2pp. 33273-112-33273-113.

I. Financial Information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept," including financial forecast for 1985-1990 & interim financial statements for 850630.
TUCKER, H.B. Duke Power Co. 85/10/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33248-245-33248-310.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER, H.B. Duke Power Co. 85/03/01. GRACE, J.N. Region 2, Office of Director. 3pp. 32865-148-32865-239.

8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-IX withheld.
* Duke Power Co. 85/03/01. 46pp. 32865-194-32865-239.

8510010389 Forwards request for exemption from 10CFR50, App J requirement to leak test mechanical penetrations for ice condenser refrigeration sys. using air or N as test medium across valve sealing surface. Fee paid.
TUCKER, H.B. Duke Power Co. 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 4pp. 32803-277-32803-280.

8510070534 Forwards Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends change Tech Spec surveillance requirements re inservice insp program for snubbers.
ADENSAM, E.G. Licensing Branch 4. 85/09/30. TUCKER, H.B. Duke Power Co. 3pp. 32900-328-32900-344.

8510070541 Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs surveillance requirements re inservice insp program for snubbers.
ADENSAM, E.G. Licensing Branch 4. 85/09/30. 11pp. 32900-331-32900-341.

8510070547 Safety evaluation supporting Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 3pp. 32900-342-32900-344.

8510080359 Forwards "McGuire Nuclear Station Safety Analysis for Upper Head Injection Elimination," based on 850509 commitment to provide results of confirmatory studies to support proposed Tech Spec changes.
TUCKER, H.B. Duke Power Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 9pp. 32913-012-32913-131.

8510080364 "McGuire Nuclear Station Safety Analysis for Upper Head Injection Elimination."
* Duke Power Co. 85/09/30. 111pp. 32913-021-32913-131.

8510150090 Proposes schedule of proposed implementation of QA guidance provided by Generic Ltr 85-06. Implementation schedule will not occur during 1986 refueling outages.
TUCKER, H.B. Duke Power Co. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 33008-301-33008-302.

8510230153 Supplemental application for amends to Licenses NPF-9 & NPF-17, revising Tech Specs to delete requirement to maintain upper head injection sys.
TUCKER, H.B. Duke Power Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 33101-089-33101-093.

8510230157 Proposed Tech Specs, deleting requirement to maintain upper head injection sys.
* Duke Power Co. 85/10/14. 3pp. 33101-091-33101-093.

8510180003 Forwards request for add info regarding turbine overspeed protection to complete review of util 850830 ltr re proposed Tech Spec changes. Response requested within 60 days of ltr date.
ADENSAM, E.G. Licensing Branch 4. 85/10/15. TUCKER, H.B. Duke Power Co. 3pp. 33075-070-33075-072.

8510180076 Requests add info re 850820 application for changes to Tech Spec 3.6.1.2 to increase allowed containment integrated leak rate. Info required within 30 days.
ADENSAM, E.G. Licensing Branch 4. 85/10/15. TUCKER, H.B. Duke Power Co. 3pp. 33069-341-33069-343.

8510250218 Forwards application to eliminate arbitrary intermediate pipe breaks in high energy lines. Review & concurrence requested prior to upcoming refueling outages. Marked-up Tech Specs also encl. Fee paid.
TUCKER, H.B. Duke Power Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 5pp. 33169-082-33169-136.

8510300209 Responds to concern re adequacy of preoperational test to measure flow velocity distribution of auxiliary bldg filtered ventilation sys. Engineering evaluation concluded that ventilation sys operable.
TUCKER, H.B. Duke Power Co. 85/10/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 33247-331-33248-002.

8510300214 Confirmation of action ltr re control room & auxiliary bldg ventilation sys filter testing. Actions to be taken listed.
GRACE, J.N. Region 2, Office of Director. 85/10/23. TUCKER, H.B. Duke Power Co. 1p. 33247-333-33247-333.

8510300221 Procedure TT/1/A/9100/101A, "Auxiliary Bldg Ventilation Sys Air Flow Distribution Measurements I."
ROBERSON, P.W., JOHANSEN, R.C. Duke Power Co. 85/10/23. 7pp. 33247-334-33247-340.

8510300226 Procedure TT/1/A/9100/101B, "Auxiliary Bldg Ventilation Sys Air Flow Distribution Measurements II."
ROBERSON, P.W., JOHANSEN, R.C. Duke Power Co. 85/10/23. 8pp. 33247-341-33247-348.

8510300230 Procedure MCC-1211.00-00-0096, "Auxiliary Bldg Ventilation Sys Acceptance Criteria for Supplemental Filter Testing."
RICHARDSON, J., SMITH, H.A., WEIDLER, R.R. Duke Power Co. 85/10/23. 16pp. 33247-349-33248-002.

Q. Inspection reports, IE Bulletins & correspondence

8510070437 Responds to NRC 850808 ltr re violations noted in Insp Repts 50-369/84-28 & 50-370/84-25. Corrective actions in-depth technical analysis will be performed. Add response to Violation IV will be submitted by 851028.
TUCKER, H.B. Duke Power Co. 85/09/24. GRACE, J.N. Region 2, Office of Director. 1p. 32878-271-32878-271.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510070534 Forwards Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends change Tech Spec surveillance requirements re inservice insp program for snubbers.
ADENSAM, E.G. Licensing Branch 4. 85/09/30. TUCKER, H.B. Duke Power Co. 3pp. 32900-328-32900-344.

8510070541 Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs surveillance requirements re inservice insp program for snubbers.
ADENSAM, E.G. Licensing Branch 4. 85/09/30. 11pp. 32900-331-32900-341.

8510070547 Safety evaluation supporting Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 3pp. 32900-342-32900-344.

152 DOCKETED ITEMS

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070492 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-23 & 50-370/85-24.
WALKER,R.D. Region 2, Office of Director. 85/10/02. TUCKER,H.B. Duke Power Co. 1p. 32878:127-32878:127.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230323 Forwards Press Release 85-28 re NRC proposed civil penalty in amount of \$50,000 against util for alleged noncompliance w/requirements concerning upper head injection accumulator sys.
KAMMERER,C. Office of Congressional Affairs. 85/02/21. House of Rep., Energy & Commerce. EAST, HELMS Senate. 2pp. 33109:151-33109:152.

8510180456 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-10 & 50-370/85-31. Denial of portion of alleged Violation B.4 accepted. Requirements of 10CFR2.201 met.
GRACE,J.N. Region 2, Office of Director. 85/10/07. TUCKER,H.B. Duke Power Co. 1p. 33068:058-33068:058.

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER,R.D. Region 2, Office of Director. 85/10/10. TUCKER,H.B. Duke Power Co. 1p. 33026:280-33026:282.

-8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER,H.B. Duke Power Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 2pp. 33026:281-33026:282.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510210285 Monthly operating repts for Sept 1985. W/851015 ltr.
REAVIS,J.A., TUCKER,H.B. Duke Power Co. 85/09/30. 12pp. 33095:065-33095:076.

S. Reportable occurrences, LERs & related correspondence

8510090022 LER 85-025-00 on 850909, train chillers & air handling unit for control ventilation area sys tripped. Caused by design deficiency allowing both chillers to become inoperable due to blown fuse. Fuse replaced. Wiring reviewed. W/851004 ltr.
DAY,J., TUCKER,H.B. Duke Power Co. 85/10/04. 4pp. 32943:037-32943:040.

8510170259 LER 85-027-00 on 850911, pressurizer heater group 1B inoperable while diesel generator 1A inoperable. Caused by personnel error. Generator returned to operable. Rept will be reviewed w/personnel. W/851011 ltr.
DAY,J.B., TUCKER,H.B. Duke Power Co. 85/10/11. 4pp. 33051:251-33051:254.

8510180014 Notification of 851021-24 site visits to discuss operating experience associated w/loss of safety function events due to personnel actions on wrong train of redundant sys or wrong unit of multi-unit facilities.
HOOD,D.S. Licensing Branch 4. 85/10/11. ADENSAM,E.G. Licensing Branch 4. 5pp. 33069:354-33069:358.

8510280397 LER 85-026-00 on 850911, vendor-employed minor exposed in excess of quarterly dose limit of 125 mrem. Caused by individual misrepresenting age to work in radiation control area. Birth dates will be verified. W/851011 ltr.
DAY,J., TUCKER,H.B. Duke Power Co. 85/10/11. 5pp. 33194:111-33194:115.

8510290464 LER 85-028-00 on 850919, environmentally sealed Valcor Model 526 inside containment valve failed. Caused by ruptured seal as result of improper installation. Four valves resealed & returned to svc. New design being studied. W/851018 ltr.
DAY,J., TUCKER,H.B. Duke Power Co. 85/10/18. 5pp. 33242:113-33242:117.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230323 Forwards Press Release 85-28 re NRC proposed civil penalty in amount of \$50,000 against util for alleged noncompliance w/requirements concerning upper head injection accumulator sys.
KAMMERER,C. Office of Congressional Affairs. 85/02/21. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:151-33109:152.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER,S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832:352-32832:353.

8510010287 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON,J.M. Division of Rules and Records. 85/09/20. HANAUER,S.H. Technical Analysis Corp. 1p. 32832:354-32833:001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER,R.D. Region 2, Office of Director. 85/10/10. TUCKER,H.B. Duke Power Co. 1p. 33026:280-33026:282.

-8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER,H.B. Duke Power Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 2pp. 33026:281-33026:282.

8510230070 Provides info re fire suppression pumps. Any pump can be loaded on Diesel 1E. Pump A powered from 6,900-volt Switchgear 2TB. Pump B loaded from 6,900 Switchgear 1TD & Pump C powered from 44-kV substation. Diagrams encl.
TUCKER,H.B. Duke Power Co. 85/10/14. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 6pp. 33102:251-33102:256.

8510300209 Responds to concern re adequacy of preoperational test to measure flow velocity distribution of auxiliary bldg filtered ventilation sys. Engineering evaluation concluded that ventilation sys operable.
TUCKER,H.B. Duke Power Co. 85/10/28. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33247:331-33247:333.

-8510300214 Confirmation of action ltr re control room & auxiliary bldg ventilation sys filter testing. Actions to be taken listed.
GRACE,J.N. Region 2, Office of Director. 85/10/23. TUCKER,H.B. Duke Power Co. 1p. 33247:333-33247:333.

8510310039 Responds to 851023 confirmation of action ltr. Item 3 re testing of control room ventilation sys. Past testing records & results of review submitted. Since ventilation sys contains only one HEPA filter, test unnecessary.
TUCKER,H.B. Duke Power Co. 85/10/29. GRACE,J.N. Region 2, Office of Director. 2pp. 33273:112-33273:113.

I. Financial information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept." including financial forecast for 1985-1987 & interim financial statements for 850630.
TUCKER,H.B. Duke Power Co. 85/10/17. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33246:245-33246:310.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER,H.B. Duke Power Co. 85/03/01. GRACE,J.N. Region 2, Office of Director. 3pp. 32865:148-32865:239.

-8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-IX withheld.
* Duke Power Co. 85/03/01. 46pp. 32865:194-32865:239.

8510010389 Forwards request for exemption from 10CFR50, App J requirement to leak test mechanical penetrations for ice condenser refrigeration sys. using air or N as test medium across valve sealing surface. Fee paid.
TUCKER,H.B. Duke Power Co. 85/09/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 4pp. 32803:277-32803:280.

8510070534 Forwards Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends change Tech Spec surveillance requirements re inservice insp program for snubbers.
ADENSAM,E.G. Licensing Branch 4. 85/09/30. TUCKER,H.B. Duke Power Co. 3pp. 32900:328-32900:344.

-8510070541 Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs surveillance requirements re inservice insp program for snubbers.
ADENSAM,E.G. Licensing Branch 4. 85/09/30. 11pp. 32900:331-32900:341.

-8510070547 Safety evaluation supporting Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 3pp. 32900:342-32900:344.

8510080359 Forwards "McGuire Nuclear Station Safety Analysis for Upper Head Injection Elimination," based on 850509 commitment to provide results of confirmatory studies to support proposed Tech Spec changes.
TUCKER,H.B. Duke Power Co. 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 9pp. 32913:012-32913:131.

-8510080364 McGuire Nuclear Station Safety Analysis for Upper Head Injection Elimination.
* Duke Power Co. 85/09/30. 111pp. 32913:021-32913:131.

8510150090 Proposes schedule of proposed implementation of QA guidance provided by Generic Ltr 85-06. Implementation schedule will not occur during 1986 refueling outages.
TUCKER,H.B. Duke Power Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33008:301-33008:302.

8510230153 Supplemental application for amendments to Licenses NPF-9 & NPF-17, revising Tech Specs to delete requirement to maintain upper head injection sys.
TUCKER,H.B. Duke Power Co. 85/10/14. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33101:080-33101:093.

-8510230157 Proposed Tech Specs, deleting requirement to maintain upper head injection sys.
* Duke Power Co. 85/10/14. 3pp. 33101:091-33101:093.

8510180003 Forwards request for addl info regarding turbine overspeed protection to complete review of util 850830 ltr re proposed Tech Spec changes. Response requested within 60 days of ltr date.
ADENSAM,E.G. Licensing Branch 4. 85/10/15. TUCKER,H.B. Duke Power Co. 3pp. 33075:070-33075:072.

8510180076 Requests addl info re 850820 application for changes to Tech Spec 3.6.1.2 to increase allowed containment integrated leak rate. Info required within 30 days.
ADENSAM,E.G. Licensing Branch 4. 85/10/15. TUCKER,H.B. Duke Power Co. 3pp. 33069:341-33069:343.

8510250218 Forwards application to eliminate arbitrary intermediate pipe breaks in high energy lines. Review & concurrence requested prior to upcoming refueling outages. Marked-up Tech Specs also encl. Fee paid.
TUCKER,H.B. Duke Power Co. 85/10/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E. Licensing Branch 4. 55pp. 33169:082-33169:136.

8510300209 Responds to concern re adequacy of preoperational test to measure flow velocity distribution of auxiliary bldg filtered ventilation sys. Engineering evaluation concluded that ventilation sys operable.
TUCKER,H.B. Duke Power Co. 85/10/28. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33247:331-33248:002.

-8510300221 Procedure TT/1/A/9100/101A, "Auxiliary Bldg Ventilation Sys Air Flow Distribution Measurements I."
ROBERSON,P.W., JOHANSEN,R.C. Duke Power Co. 85/10/23. 7pp. 33247:334-33247:340.

-8510300226 Procedure TT/1/A/9100/101B, "Auxiliary Bldg Ventilation Sys Air Flow Distribution Measurements II."
ROBERSON,P.W., JOHANSEN,R.C. Duke Power Co. 85/10/23. 8pp. 33247:341-33247:348.

-8510300230 Procedure MCC-1211.00-00-0096, "Auxiliary Bldg Ventilation Sys Acceptance Criteria for Supplemental Filter Testing."
RICHARDSON,J., SMITH,H.A., WEIDLER,R.R. Duke Power Co. 85/10/23. 16pp. 33247:349-33248:002.

Q. Inspection reports, IE Bulletins & correspondence

8510070437 Responds to NRC 850808 ltr re violations noted in Insp Repts 50-369/84-28 & 50-370/84-25. Corrective actions in-depth technical analysis will be performed. Addl response to Violation IV will be submitted by 851028.
TUCKER,H.B. Duke Power Co. 85/09/24. GRACE,J.N. Region 2, Office of Director. 1p. 32878:271-32878:271.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON,D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT,J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510070534 Forwards Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends change Tech Spec surveillance requirements re inservice insp program for snubbers.
ADENSAM,E.G. Licensing Branch 4. 85/09/30. TUCKER,H.B. Duke Power Co. 3pp. 32900:328-32900:344.

-8510070541 Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs surveillance requirements re inservice insp program for snubbers.
ADENSAM,E.G. Licensing Branch 4. 85/09/30. 11pp. 32900:331-32900:341.

-8510070547 Safety evaluation supporting Amends 46 & 27 to Licenses NPF-9 & NPF-17, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/09/30. 3pp. 32900:342-32900:344.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070492 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-23 & 50-370/85-24.
WALKER,R.D. Region 2, Office of Director. 85/10/02. TUCKER,H.B. Duke Power Co. 1p. 32878:127-32878:127.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230323 Forwards Press Release 85-28 re NRC proposed civil penalty in amount of \$50,000 against util for alleged noncompliance w/requirements concerning upper head injection accumulator sys.
KAMMERER,C. Office of Congressional Affairs. 85/02/21. House of Rep., Energy & Commerce. EAST, HELMS Senate. 2pp. 33109:151-33109:152.

8510180456 Ack receipt of 850913 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-10 & 50-370/85-11. Denial of portion of alleged Violation B.4 accepted. Requirements of 10CFR2.201 met.
GRACE,J.N. Region 2, Office of Director. 85/10/07. TUCKER,H.B. Duke Power Co. 1p. 33068:058-33068:058.

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER,R.D. Region 2, Office of Director. 85/10/10. TUCKER,H.B. Duke Power Co. 1p. 33026:280-33026:282.

-8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER,H.B. Duke Power Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 2pp. 33026:281-33026:282.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510210285 Monthly operating repts for Sept 1985 W/851015 ltr.
REAVIS,J.A., TUCKER,H.B. Duke Power Co. 85/09/30. 12pp. 33095:065-33095:076.

S. Reportable occurrences, LERs & related correspondence

8510180014 Notification of 851021-24 site visits to discuss operating experience associated w/loss of safety function events due to personnel actions on wrong train of redundant sys or wrong unit of multi-unit facilities.
HOOD,D.S. Licensing Branch 4. 85/10/11. ADENSAM,E.G. Licensing Branch 4. 5pp. 33069:354-33069:358.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230323 Forwards Press Release 85-28 re NRC proposed civil penalty in amount of \$50,000 against util for alleged noncompliance w/requirements concerning upper head injection accumulator sys.
KAMMERER,C. Office of Congressional Affairs. 85/02/21. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:151-33109:152.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510080408 Responds to NRC 850905 ltr re violations noted in Insp Repts 50-373/85-25 & 50-374/85-26. Corrective actions on-site dumping no longer permitted. Cleanup of onsite dump will be completed by 851001.
FARRAR,D.L. Commonwealth Edison Co. 85/09/26. KEPPLER,J.G. Region 3, Office of Director. 4pp. 32919:234-32919:237.

8510090494 Forwards Safety Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906 & notice of violation.
NOELIUS,C.E. Region 3, Office of Director. 85/09/27. REED,C. Commonwealth Edison Co. 2pp. 32946:064-32946:082.

-8510090501 Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906. Violation noted: failure to follow Procedure LIP-GM-09 when returning instrument to svc, causing Unit 1 to trip & failure to have adequate document control.
WRIGHT,G.C. Region 3, Office of Director. 85/09/26. 15pp. 32946:068-32946:082.

154 DOCKETED ITEMS

- 8510080064** Forwards Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER, W.R. Licensing Branch 2. 85/10/02. FARRAR, D.L. Commonwealth Edison Co. 6pp. 32926:192-32926:260.
- 8510080069** Amends 26 & 14 to Licenses NPF-11, NPF-18, respectively, revising method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER, W.R. Licensing Branch 2. 85/10/02. 55pp. 32926:197-32926:251.
- 8510080076** Safety evaluation supporting Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively.
* NRC - No Detailed Affiliation Given. 85/10/02. 8pp. 32926:252-32926:260.
- 8510090002** Forwards response to concerns re Rev 21 to vital areas identified in security plan. Response withheld.
FARRAR, D.L. Commonwealth Edison Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32934:352-32934:352.
- 8510100043** Forwards Rev 22 to station security plan. Rev withheld (ref 10CFR73.21).
FARRAR, D.L. Commonwealth Edison Co. 85/10/02. KEPPLER, J.G. Region 3, Office of Director. 1p. 32960:278-32960:278.
- 8510160248** Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on P-09020. Major areas discussed: items re exercise scheduling for FY86 exercises.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REFD, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.
- 8510160270** Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on P-09020. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.
- 8510160106** Advises that 851002 Rev 22 to security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
AXELSON, W.L. Region 3, Office of Director. 85/10/09. FARRAR, D.L. Commonwealth Edison Co. 2pp. 33022:305-33022:306.
- 8510210064** Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environments Group Activities by Environments Director."
GORDON, J.C. Commonwealth Edison Co. 85/10/15. DENTON, H.R. Record Services Branch (Document Control Desk). 1p. 33082:282-33082:043.
- 8510210073** Revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environments Group Activities by Environments Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." W/twc. oversize drawings.
KENEALY, D.M. Commonwealth Edison Co. 85/10/15. 120pp. 33082:283-33082:043.
- 8510220250** Rev 5 to Procedure LSP-1550-9, "Special TLD Locations."
* Commonwealth Edison Co. 85/10/15. 7pp. 33087:329-33087:335.
- 8510250566** Forwards SER conditionally supporting response to procedures generation package. Items re primary containment pressure limit for venting guidance & OCRDR must be addressed.
BUTLER, W.R. Licensing Branch 2. 85/10/18. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33226:349-33226:358.
- 8510250574** SER conditionally supporting response to procedures generation package.
* NRC - No Detailed Affiliation Given. 85/10/18. 7pp. 33226:352-33226:358.
- 8510250270** Forwards Safety Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted.
CHRISSTIMOS, N. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33173:108-33173:119.
- 8510250283** Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings, operational safety, surveillance, maint & interim radwaste storage.
WRIGHT, G.C. Region 3, Office of Director. 85/10/21. 10pp. 33173:110-33173:119.
- 8510310781** Forwards Amend 27 to License NPF-11 & safety evaluation. Amend revises Tech Specs to incorporate instruments for suppression pool water level & instrumentation at remote shutdown panel.
BUTLER, W.R. Licensing Branch 2. 85/10/22. FARRAR, D.L. Commonwealth Edison Co. 9pp. 33277:067-33277:082.
- 8510310586** Amend 27 to License NPF-11, revising Tech Specs to incorporate instruments for suppression pool water level & instrumentation at remote shutdown panel.
BUTLER, W.R. Licensing Branch 2. 85/10/22. 5pp. 33277:076-33277:080.
- 8510310590** Safety evaluation supporting Amend 27 to License NPF-11.
* Office of Nuclear Reactor Regulation, Director. 85/10/22. 2pp. 33277:081-33277:082.
- J. Insurance & Indemnity Information**
- 8510170306** Forwards Endorsements 36 & 19 to NELIA Policy NF-253 & MAELU Policy MF-104, respectively.
OSTER, J. Commonwealth Edison Co. 85/10/08. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 33042:146-33042:148.
- 8510300064** Forwards unexecuted Amends 23, 4 & 5 to Indemnity Agreements B-10, B-97 & B-84, respectively, modifying location descriptions to conform to facility forms.
DINITZ, J. Office of State Programs, Director. 85/10/25. OSTER, J. Commonwealth Edison Co. 4pp. 33261:353-33261:356.
- P. Operating license stage documents & correspondence**
- 8510070317** Forwards leakage data rept & corrective maint performed as result of leakage, per NUREG-0578, Item 2.1.6.9 & FSAR Section L.77.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/16. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32880:335-32880:337.
- 8510010052** Application for amends to Licenses NPF-11 & NPF-18, changing Tech Specs to defer one 18-month interval surveillance requirement for each unit to allow Unit 1 to continue operation past 850927.
MASSIN, H.L. Commonwealth Edison Co. 85/09/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32800:065-32800:071.
- 8510010055** Proposed Tech Specs re waiver of 18-month interval surveillance requirement for ECCS.
* Commonwealth Edison Co. 85/09/23. 4pp. 32800:068-32800:071.
- 8510040247** Advises that State of IL Dept of Nuclear Safety review of util emergency Tech Spec amends to Licenses NPF-11 & NPF-18 re waiver of 18-month surveillance interval, revealed no adverse findings.
PARKER, M.C. Illinois, State of. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32851:078-32851:078.
- 8510080490** Informs that mod of Comp. Inc hydrogen-oxygen analyzer will not be completed by 851130. Analyzer will be installed later as manpower & scheduling permits.
MASSIN, H.L. Commonwealth Edison Co. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 32921:165-32921:171.
- 8510080126** Forwards Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise Tech Specs 4.5.1.c & 4.8.1.2.d to extend one-time-only waiver of 18-month interval surveillance requirement.
BUTLER, W.R. Licensing Branch 2. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 7pp. 32951:195-32951:301.
- 8510080133** Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively, revising Unit 1 Tech Spec 4.5.1.c & Unit 2 Tech Spec 4.8.1.2.d to extend waiver of 18-month interval surveillance requirement for Diesel Generator 1A.
BUTLER, W.R. Licensing Branch 2. 85/10/01. 8pp. 32951:239-32951:301.
- 8510080138** Safety evaluation supporting Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 3pp. 32925:290-32925:295.
- 8510080064** Forwards Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER, W.R. Licensing Branch 2. 85/10/02. FARRAR, D.L. Commonwealth Edison Co. 6pp. 32926:192-32926:260.
- 8510080069** Amends 26 & 14 to Licenses NPF-11, NPF-18, respectively, revising method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER, W.R. Licensing Branch 2. 85/10/02. 55pp. 32926:197-32926:251.
- 8510080076** Safety evaluation supporting Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively.
* NRC - No Detailed Affiliation Given. 85/10/02. 8pp. 32926:252-32926:260.
- 8510100082** Application for amend to License NPF-11, changing Tech Specs re vent & purge isolation valve mod. Fee paid.
MASSIN, H.L. Commonwealth Edison Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32960:302-32960:312.
- 8510100119** Proposed Tech Specs re vent & purge isolation valve mod.
* Commonwealth Edison Co. 85/10/02. 8pp. 32960:305-32960:312.
- 8510110036** Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Station." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.
- 8510110058** Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.
- 8510110141** Advises that no adverse findings identified based on review of proposed amends to Licenses NPF-11 & NPF-18, changing Tech Specs re diesel generator lube oil mod.
PARKER, M.C. Illinois, State of. 85/10/09. DENTON, H. Office of Nuclear Reactor Regulation, Director. 2pp. 32999:351-32999:352.
- 8510230053** Suppls 850927 submittal re Generic Ltr 85-15 & responds to telco questions. Protective devices consist of ITE circuit breakers for control circuits & Klockner-Moeller molded-case circuit breakers for power feeds.
MASSIN, H.L. Commonwealth Edison Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33101:087-33101:088.
- 8510150204** Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010:332-33010:337.
- 8510230036** Application for amend to License NPF-11, revising Tech Specs to remove ECCS/RCIC testable check bypass valves. Fee paid.
MASSIN, H.L. Commonwealth Edison Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33102:001-33102:007.
- 8510230043** Proposed Tech Spec Table 3.6.3-1, reflecting removal of ECCS/RCIC testable check bypass valves.
* Commonwealth Edison Co. 85/10/11. 3pp. 33102:005-33102:007.
- 8510230238** Application for amends to Licenses NPF-11 & NPF-13, revising Tech Specs to allow count rate on source range monitor channels below required counts per second when four or less fuel assemblies in quadrant & adjacent. Fee paid.
MASSIN, H.L. Commonwealth Edison Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33103:152-33103:164.
- 8510230242** Proposed Tech Specs, allowing count rate on source range monitor channels below required counts per second when four or less fuel assemblies in quadrant or adjacent. Significant hazards consideration encl.
* Commonwealth Edison Co. 85/10/11. 9pp. 33103:156-33103:164.

8510290188 Informs of review of application for amend to License NPF-11 re proposed changes to Tech Specs concerning vent & purge isolation valve mods. No adverse findings determined.
PARKER, M.C. Illinois, State of. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33233:156-33233:156.

8510290231 Advises that Dept of Nuclear Safety completed review of proposed amend to Tech Specs re ECCS/RCIC testable check bypass valves. No adverse findings identified.
PARKER, M.C. Illinois, State of. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235:004-33235:004.

8510310581 Forwards Amend 27 to License NPF-11 & safety evaluation. Amend re/ises Tech Specs to incorporate instruments for suppression pool water level & instrumentation at remote shutdown panel.
BUTLER, W.R. Licensing Branch 2. 85/10/22. FARRAR, D.L. Commonwealth Edison Co. 9pp. 33277:067-33277:082.

-8510310586 Amend 27 to License NPF-11, revising Tech Specs to incorporate instruments for suppression pool water level & instrumentation at remote shutdown panel.
BUTLER, W.R. Licensing Branch 2. 85/10/22. 5pp. 33277:076-33277:080.

-8510310590 Safety evaluation supporting Amend 27 to License NPF-11.
* Office of Nuclear Reactor Regulation, Director. 85/10/22. 2pp. 33277:081-33277:082.

8510290055 Notifies that no adverse findings determined based on review of 851011 proposed Tech Spec amend re source range monitor operability.
PARKER, M.C. Illinois, State of. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33236:135-33236:135.

Q. Inspection reports, IE Bulletins & correspondence

8510080222 Responds to NRC 850813 ltr re violations noted in Insp Repts 50-373/85-19 & 50-374/85-21. Corrective actions: temporary sys change installed to defeat isolation signal. RHR sys restarted.
FARRAR, D.L. Commonwealth Edison Co. 85/09/10. KEPLER, J.G. Region 3, Office of Director. 4pp. 32913:299-32913:302.

8510010067 Forwards final summary from Structural Integrity Assoc. Inc. documenting results of independent evaluation of induction heating stress improvement re inservice insp. ltr. supports 850719 submittal. Continued technical review requested.
MASSIN, H.L. Commonwealth Edison Co. 85/09/13. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32801:286-32801:291.

8510080160 EN-85-067 notice of violation & proposed imposition of civil penalty in amount of \$125,000 will be issued on or about 850927. Action due to three failures to ensure that mods performed on safety-related sys adequately controlled.
BEACH, B., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/24. 1p. 32922:066-32922:066.

8510080408 Responds to NRC 850905 ltr re violations noted in Insp Repts 50-373/85-25 & 50-374/85-26. Corrective actions: onsite dumping no longer permitted. Cleanup of onsite dump will be completed by 851001.
FARRAR, D.L. Commonwealth Edison Co. 85/09/26. KEPLER, J.G. Region 3, Office of Director. 4pp. 32919:234-32919:237.

8510010175 Discusses Insp Repts 50-373/85-23 & 50-374/85-19 on 850610-0724 & forwards notice of violation & proposed imposition of civil penalty in amount of \$125,000.
KEPLER, J.G. Region 3, Office of Director. 85/09/27. O'CONNER, J.J. Commonwealth Edison Co. 5pp. 32800:082-32800:103.

-8510010182 Notice of violation & proposed imposition of civil penalty in amount of \$125,000. Violation noted: inoperable ECCS actuation instrumentation channel not placed in tripped condition within 1 hr & three ECCS divs inoperable.
KEPLER, J.G. Region 3, Office of Director. 85/09/27. 5pp. 32800:087-32800:103.

8510090494 Forwards Safety Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906 & notice of violation.
NOELIUS, C.E. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32946:064-32946:082.

-8510090499 Notice of violation from insp on 850725-0906.
NOELIUS, C.E. Region 3, Office of Director. 85/09/27. 2pp. 32946:066-32946:067.

-8510090501 Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906. Violation noted: failure to follow Procedure LIP-GM-09 when returning instrument to svc, causing Unit 1 to trip & failure to have adequate document control.
WRIGHT, G.C. Region 3, Office of Director. 85/09/26. 15pp. 32946:068-32946:082.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510110012 Responds to violations noted in Insp Repts 50-373/85-27 & 50-374/85-28. Corrective actions: ltr written to dept heads emphasizing compliance w/out-of-svc procedure. Posting operator at control device discontinued.
FARRAR, D.L. Commonwealth Edison Co. 85/10/01. KEPLER, J.G. Region 3, Office of Director. 2pp. 32968:357-32968:358.

8510080484 Suppl 840604 response to Generic Ltr 84-11 re augmented inservice insp. plan. Min sample of 33 welds will be required to be inspected during outage.
MASSIN, H.L. Commonwealth Edison Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:131-32921:132.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A., KERS, L.L., SMITH, M.J. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250270 Forwards Safety Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted.
CHRISOTIMOS, N. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33173:108-33173:119.

-8510250283 Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings, operational safety, surveillance, maint & interim radwaste storage.
WRIGHT, G.C. Region 3, Office of Director. 85/10/21. 10pp. 33173:110-33173:119.

8510310267 Forwards addendum to Insp Repts 50-373/85-03 & 50-374/85-03 transmitted by 850221 ltr. Addendum consists of comparisons of analyses performed on liquid sample collected during insp.
SHAFFER, W.D. Region 3, Office of Director. 85/10/24. REED, C. Commonwealth Edison Co. 1p. 33273:097-33273:098.

-8510310278 Addendum to Insp Repts 50-373/85-03 & 50-374/85-03, consisting of comparisons of analyses of liquid sample collected during insp. Results of gross beta comparison verify agreement. Three other comparisons not usable.
* Region 3, Office of Director. 85/10/24. 1p. 33273:098-33273:098.

... Periodic operating reports & related correspondence

8510010638 Monthly operating repts for Jul 1985. W/850810 ltr.
ROHRER, R.J., DIEDERICH, G.J. Commonwealth Edison Co. 85/07/31. 35pp. 32820:289-32820:324.

8510080171 Forwards errata to Part 2 of "Rept of Radioactive Effluents, Jul-Dec 1984."
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/24. KEPLER, J.G. Region 3, Office of Director. 1p. 32913:312-32913:322.

-8510080174 Errata to Part 2 of "Rept of Radioactive Effluents, Jul-Dec 1984."
* Commonwealth Edison Co. 84/12/31. 10pp. 32913:313-32913:322.

8510170166 Monthly operating repts for Sept 1985. W/851010 ltr.
PETERS, J.P., DIEDERICH, G.J. Commonwealth Edison Co. 85/09/30. 33pp. 33052:002-33052:034.

S. Reportable occurrences, LERs & related correspondence

8510020004 Special rept on 850820, determined that 173 F temp limit for safety relief valve solenoids misinterpreted as ambient air temp when intended as metal housing temp. Attempts will be made to return temps to limits.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/17. KEPLER, J.G. Region 3, Office of Director. 1p. 32827:064-32827:064.

8510080269 NPDES noncompliance notification on 850831, 30-day average limit exceeded due to one discharge which contained 28 ppm total suspended solids. Composite sample repaired.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/27. KEPLER, J.G. Region 3, Office of Director. 3pp. 32928:124-32928:126.

8510170047 LER 84-054-01 on 840921, RCIC turbine trip occurred & RCIC Channel A steam line high flow isolation received. Caused by dirty &/or contaminated lubrication oil. Work Requests L41160, L44599 & L46377 generated. W/851001 ltr.
LYON, D., DIEDERICH, G.J. Commonwealth Edison Co. 85/10/01. 4pp. 33052:061-33052:064.

8510310198 Confirms 851101 meeting in Glen Ellyn, IL to discuss actions & plans concerning high ambient temps detected in drywells & related Tech Specs & procedures.
NOELIUS, C.E. Region 3, Office of Director. 85/10/29. REED, C. Commonwealth Edison Co. 1p. 33274:027-33274:027.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832:352-32832:353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832:354-32832:001.

-8510010428 Power plant exam results summary sheets. Info deleted.
* Public Service Electric & Gas Co. of New Jersey. * Southern California Edison Co. * South Carolina Electric & Gas Co. 85/09/20. 9pp. 32832:355-32832:001.

156 DOCKETED ITEMS

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510030083 Forwards SER supporting 830807 rept. "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1 Rev commitment requested within 45 days.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/01. FARRAR,D.L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

8510210014 Informs that operator & senior operator written & oral exams scheduled for wk of 851118. Description of requirements for conducting exams encl. License applications requested 60 days prior to first exam date.
REYES,L.A. Region 3, Office of Director. 85/10/15. REED,C. Commonwealth Edison Co. 3pp. 33074-108-33074-110.

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510080408 Responds to NRC 850905 ltr re violations noted in Insp Repts 50-373/85-25 & 50-374/85-26. Corrective actions: onsite dumping no longer permitted. Cleanup of onsite dump will be completed by 851001.
FARRAR,D.L. Commonwealth Edison Co. 85/09/26. KEPPLER,J.G. Region 3, Office of Director. 4pp. 32919-234-32919-237.

8510090494 Forwards Safety Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906 & notice of violation.
NOELIUS,C.E. Region 3, Office of Director. 85/09/27. REED,C. Commonwealth Edison Co. 2pp. 32946-064-32946-082.

-8510090501 Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906. Violation noted: failure to follow Procedure LIP-GM-09 when returning instrument to svc, causing Unit 1 to trip & failure to have adequate document control.
WRIGHT,G.C. Region 3, Office of Director. 85/09/26. 15pp. 32946-068-32946-082.

8510080064 Forwards Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER,W.R. Licensing Branch 2. 85/10/02. FARRAR,D.L. Commonwealth Edison Co. 6pp. 32926-192-32926-260.

-8510080069 Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively, revising method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER,W.R. Licensing Branch 2. 85/10/02. 55pp. 32926-197-32926-251.

-8510080076 Safety evaluation supporting Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively.
* NRC - No Detailed Affiliation Given. 85/10/02. 8pp. 32926-252-32926-260.

8510070002 Forwards response to concerns re Rev 21 to vital areas identified in security plan. Response withheld.
MASSIN,H.L. Commonwealth Edison Co. 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32934-352-32934-352.

8510100043 Forwards Rev 22 to station security plan. Rev withheld (ref 10CFR73.21).
FARRAR,D.L. Commonwealth Edison Co. 85/10/02. KEPPLER,J.G. Region 3, Office of Director. 1p. 32960-278-32960-278.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
SHAFFER,W.D. Region 3, Office of Director. 85/10/04. REED,C. Commonwealth Edison Co. 2pp. 33026-219-33026-222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN,G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026-221-33026-222.

8510160106 Advises that 851002 Rev 22 to security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
AXELSON,W.L. Region 3, Office of Director. 85/10/09. FARRAR,D.L. Commonwealth Edison Co. 2pp. 33022-305-33022-306.

8510210064 Forwards revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environments Group Activities by Environments Director."
GORDON,J.C. Commonwealth Edison Co. 85/10/15. DENTON,H.R. Record Services Branch (Document Control Desk). 1p. 33082-282-33082-043.

-8510210073 Revised emergency plan implementing procedures, including Rev 5 to EG-1, "Coordination of Environments Group Activities by Environments Director" & Rev 3 to EG-10, "Offsite Personnel & Vehicle Decontamination..." w/two oversize drawings.
KENNEDY,D.M. Commonwealth Edison Co. 85/10/15. 120pp. 33082-283-33082-043.

8510220250 Rev 5 to Procedure LEP-1550-9, "Special TLD Locations."
* Commonwealth Edison Co. 85/10/15. 7pp. 33067-329-33067-335.

8510250566 Forwards SER conditionally supporting response to procedures generation package. Items re primary containment pressure limit for venting guidance & DCRDR must be addressed.
BUTLER,W.R. Licensing Branch 2. 85/10/18. FARRAR,D.L. Commonwealth Edison Co. 3pp. 33226-349-33226-358.

-8510250574 SER conditionally supporting response to procedures generation package.
* NRC - No Detailed Affiliation Given. 85/10/18. 7pp. 33226-352-33226-358.

8510250270 Forwards Safety Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted.
CHRISTOTIMOS,N. Region 3, Office of Director. 85/10/21. REED,C. Commonwealth Edison Co. 2pp. 33173-108-33173-119.

-8510250283 Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings, operational safety surveillance, maint & interim radwaste storage.
WRIGHT,G.C. Region 3, Office of Director. 85/10/21. 10pp. 33173-110-33173-119.

J. Insurance & indemnity information

8510300064 Forwards unexecuted Amends 23.4 & 5 to Indemnity Agreements B-10, B-97 & B-84, respectively, modifying location descriptions to conform to facility forms.
DINITZ,I. Office of State Programs, Director. 85/10/25. OSTER,J. Commonwealth Edison Co. 4pp. 33261-353-33261-356.

P. Operating license stage documents & correspondence

8510010052 Application for amends to Licenses NPF-11 & NPF-18, changing Tech Specs to defer one 18-month interval surveillance requirement for each unit to allow Unit 1 to continue operation past 850927.
MASSIN,H.L. Commonwealth Edison Co. 85/09/23. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32800-065-32800-071.

-8510010055 Proposed Tech Specs re waiver of 18-month interval surveillance requirement for ECCS.
* Commonwealth Edison Co. 85/09/23. 4pp. 32800-068-32800-071.

8510040247 Advises that State of IL Dept of Nuclear Safety review of util emergency Tech Spec amends to Licenses NPF-11 & NPF-18 re waiver of 18-month surveillance interval, revealed no adverse findings.
PARKER,M.C. Illinois, State of. 85/09/25. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32851-078-32851-078.

8510080490 Informs that mod of Comsisp, Inc hydrogen-oxygen analyzer will not be completed by 851130. Analyzer will be installed later as manpower & scheduling permits.
MASSIN,H.L. Commonwealth Edison Co. 85/09/27. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 32921-165-32921-171.

8510080126 Forwards Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise Tech Specs 4.5.1.c & 4.8.1.1.2.d to extend one-time-only waiver of 18-month interval surveillance requirement.
BUTLER,W.R. Licensing Branch 2. 85/10/01. FARRAR,D.L. Commonwealth Edison Co. 7pp. 32951-195-32951-301.

-8510080133 Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively, revising Unit 1 Tech Spec 4.5.1.c & Unit 2 Tech Spec 4.8.1.1.2.d to extend waiver of 18-month interval surveillance requirement for Diesel Generator 1A.
BUTLER,W.R. Licensing Branch 2. 85/10/01. 8pp. 32951-239-32951-301.

-8510080138 Safety evaluation supporting Amends 25 & 13 to Licenses NPF-11 & NPF-18, respectively.
* Office of Nuclear Reactor Regulation, Director. 85/10/01. 3pp. 32925-290-32925-295.

8510080064 Forwards Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively & safety evaluation. Amends revise method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER,W.R. Licensing Branch 2. 85/10/02. FARRAR,D.L. Commonwealth Edison Co. 6pp. 32926-192-32926-260.

-8510080069 Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively, revising method of calculating kW capacity for electric heaters in control room emergency air makeup train.
BUTLER,W.R. Licensing Branch 2. 85/10/02. 55pp. 32926-197-32926-251.

-8510080076 Safety evaluation supporting Amends 26 & 14 to Licenses NPF-11 & NPF-18, respectively.
* NRC - No Detailed Affiliation Given. 85/10/02. 8pp. 32926-252-32926-260.

8510080404 Responds to NRC 850923 request for addl info re 850828 request for Tech Spec change supporting diesel generator lube oil mod. Due to extensive changes to lube oil sys & seismic analysis & testing of piping, 30-day outage required.
MASSIN,H.L. Commonwealth Edison Co. 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32919-239-32919-241.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER,G.L. Commonwealth Edison Co. 85/10/03. KEPPLER,J.G. Region 3, Office of Director. 1p. 32973-333-32974-006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973-334-32974-006.

8510110141 Advises that no adverse findings identified based on review of proposed amends to Licenses NPF-11 & NPF-18, changing Tech Specs re diesel generator lube oil mod.
PARKER,M.C. Illinois, State of. 85/10/09. DENTON,H. Office of Nuclear Reactor Regulation, Director. 2pp. 32999-351-32999-352.

8510230053 Suppls 850927 submittal re Generic Ltr 85-15 & responds to telcon questions. Protective devices consist of ITE circuit breakers for control circuits & Klockner-Moeller molded-case circuit breakers for power feeds.
MASSIN,H.L. Commonwealth Edison Co. 85/10/09. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33101-087-33101-088.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER,G. Commonwealth Edison Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010-332-33010-337.

8510230236 Application for amends to Licenses NPF-11 & NPF-18, revising Tech Specs to allow count rate on source range monitor channels below required counts per second when four or less fuel assemblies in quadrant & adjacent. Fee paid.
MASSIN,H.L. Commonwealth Edison Co. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33103-152-33103-164.

-8510230242 Proposed Tech Specs, allowing count rate on source range monitor channels below required counts per second when four or less fuel assemblies in quadrant or adjacent. Significant hazards consideration encl.
* Commonwealth Edison Co. 85/10/11. 9pp. 33103:156-33103:164.

8510290055 Notices that no adverse findings determined based on review of 851011 proposed Tech Spec amend re source range monitor operability.
PARKER, M.C. Illinois, State of. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33236:135-33236:135.

Q. Inspection reports, IE Bulletins & correspondence

8510080222 Responds to NRC 850813 ltr re violations noted in Insp Repts 50-373/85-19 & 50-374/85-21. Corrective actions: temporary sys change installed to defeat isolation signal. RHR sys restarted.
FARRAR, D.L. Commonwealth Edison Co. 85/09/10. KEPPLER, J.G. Region 3, Office of Director. 4pp. 32913:299-32913:302.

8510010067 Forwards final summary from Structural Integrity Assoc. Inc documenting results of independent evaluation of induction heating stress improvement re inservice insp info suppls 850719 submittal. Continued technical review requested.
MASSIN, H.L. Commonwealth Edison Co. 85/09/13. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32801:286-32801:291.

8510080160 EN-85-067: notice of violation & proposed imposition of civil penalty in amount of \$125,000 will be issued on or about 850927. Action due to three failures to ensure that mods performed on safety-related sys adequately controlled.
BEACH, B., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/24. 1p. 32922:066-32922:066.

8510080408 Responds to NRC 850905 ltr re violations noted in Insp Repts 50-373/85-25 & 50-374/85-26. Corrective actions: onsite dumping no longer permitted. Cleanup of onsite dump will be completed by 851001.
FARRAR, D.L. Commonwealth Edison Co. 85/09/26. KEPPLER, J.G. Region 3, Office of Director. 4pp. 32919:234-32919:237.

8510010175 Discusses Insp Repts 50-373/85-23 & 50-374/85-19 on 850610-0724 & forwards notice of violation & proposed imposition of civil penalty in amount of \$125,000.
KEPPLER, J.G. Region 3, Office of Director. 85/09/27. O'CONNER, J.J. Commonwealth Edison Co. 5pp. 32800:082-32800:103.

-8510010182 Notice of violation & proposed imposition of civil penalty in amount of \$125,000. Violation noted: inoperable ECCS actuation instrumentation channel not placed in tripped condition within 1 h & three ECCS divs inoperable.
KEPPLER, J.G. Region 3, Office of Director. 85/09/27. 5pp. 32800:087-32800:103.

8510090494 Forwards Safety Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906 & notice of violation.
NORELIUS, C.E. Region 3, Office of Director. 85/09/27. REED, C. Commonwealth Edison Co. 2pp. 32946:064-32946:082.

-8510090499 Notice of violation from insp on 850725-0906.
NORELIUS, C.E. Region 3, Office of Director. 85/09/27. 2pp. 32946:066-32946:067.

-8510090501 Insp Repts 50-373/85-24 & 50-374/85-25 on 850725-0906. Violation noted: failure to follow Procedure LIP-GM-09 when returning instrument to svc, causing Unit 1 to trip & failure to have adequate document control.
WRIGHT, G.C. Region 3, Office of Director. 85/09/26. 15pp. 32946:068-32946:082.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510110012 Responds to violations noted in Insp Repts 50-373/85-27 & 50-374/85-28. Corrective actions: ltr written to dept heads emphasizing compliance w/out-of-svc procedure. Posting operator at control device discontinued.
FARRAR, D.L. Commonwealth Edison Co. 85/10/01. KEPPLER, J.G. Region 3, Office of Director. 2pp. 32968:357-32968:358.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAHER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250270 Forwards Safety Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted.
CHRISTOSIMOS, N. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33173:106-33173:119.

-8510250283 Insp Repts 50-373/85-30 & 50-374/85-31 on 850907-30. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings, operational safety, surveillance, maint & interim radwaste storage.
WRIGHT, G.C. Region 3, Office of Director. 85/10/21. 10pp. 33173:110-33173:119.

8510310267 Forwards addendum to Insp Repts 50-373/85-03 & 50-374/85-03 transmitted by 850221 ltr. Addendum consists of comparisons of analyses performed on liquid sample collected during insp.
SHAHER, W.D. Region 3, Office of Director. 85/10/24. REED, C. Commonwealth Edison Co. 1p. 33273:097-33273:098.

-8510310278 Addendum to Insp Repts 50-373/85-03 & 50-374/85-03, consisting of comparisons of analyses of liquid sample collected during insp. Results of gross beta comparison verify agreement. Three other comparisons not usable.
* Region 3, Office of Director. 85/10/24. 1p. 33273:098-33273:098.

R. Periodic operating reports & related correspondence

8510010638 Monthly operating repts for Jul 1985. W/850810 ltr.
ROHMER, R.J., DIEDERICH, G.J. Commonwealth Edison Co. 85/07/31. 35pp. 32820:289-32820:324.

8510080171 Forwards errata to Part 2 of "Rept of Radioactive Effluents, Jul-Dec 1984."
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/24. KEPPLER, J.G. Region 3, Office of Director. 1p. 32913:312-32913:322.

-8510080174 Errata to Part 2 of "Rept of Radioactive Effluents, Jul-Dec 1984."
* Commonwealth Edison Co. 84/12/31. 10pp. 32913:313-32913:322.

8510170166 Monthly operating repts for Sept 1985. W/851010 ltr.
PETERS, J.P., DIEDERICH, G.J. Commonwealth Edison Co. 85/09/30. 33pp. 33052:002-33052:034.

S. Reportable occurrences, LERs & related correspondence

8510080036 Special rept re ambient air temp between 150 & 155F between 840930 & 1202 in excess of Tech Specs limit. High temp corrected by adjustments in drywell airflow. Reporting requirements being clarified.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/25. KEPPLER, J.G. Region 3, Office of Director. 1p. 32928:130-32928:130.

8510080269 NPDES noncompliance notification: on 850831, 30-day average limit exceeded due to one discharge which contained 28 ppm total suspended solids. Composite sampler repaired.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/27. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32928:124-32928:126.

8510310198 Confirms 851101 meeting in Glen Ellyn, IL, to discuss actions & plans concerning high ambient temps detected in drywells & related Tech Specs & procedures.
NORELIUS, C.E. Region 3, Office of Director. 85/10/29. REED, C. Commonwealth Edison Co. 1p. 33274:027-33274:027.

V. Operator Examinations

8509240248 Genenc ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

8510210014 Informs that operator & senior operator written & oral exams scheduled for wk of 851118. Description of requirements for conducting exams encl. License applications requested 60 days prior to first exam date.
REYES, L.A. Region 3, Office of Director. 85/10/15. REED, C. Commonwealth Edison Co. 3pp. 33074:108-33074:110.

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A. Application/construction stage documents & correspondence

8510010266 Responds to 840712 ltr refusing to process FOIA 84-206 due to lack of specificity. Records requested documenting problems w/subcontractors work & corrective actions taken.
BERNABEI, L. Government Accountability Project. 84/08/06. FELTON, J.M. Division of Rules and Records. 2pp. 32884:001-32884:004.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8510020279 Draft 1 of Allegation Investigation Rept 4-83-A-88/5 re Allegations A-53 & A-93 concerning unidentified & uncorrected nonconformances. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. 84/04/11. 2pp. 32982:111-32982:112.

8510020298 Draft 2 of Allegation Investigation Rept 4-84-A-06/39 re Allegations A-144, A-154, A-179 & A-114 concerning clam shell filter blanket record deficiencies. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. 84/04/13. 1p. 32982:155-32982:155.

158 DOCKETED ITEMS

- 8510010565** Draft 5 of Allegation Investigation Rept 4-84-A-06/151 re Allegations A-269,A-112,A-113,A-129,A-131,A-137,A-158 & A-272 concerning cancellation of concrete records review. Insp of issues essentially completed prior to 840402.
* NRC - No Detailed Affiliation Given. 84/05/21. 2pp. 32977.047-32977.048.
- 8510040058** Requests statement explaining unauthorized procurement commitment & action taken to prevent recurrence. D Crutchfield response re svcs & equipment procured to support Waterford 3 Task Force encl. HAGAN,T.F. Division of Contracts. 84/05/22. FUNCHES,J.L. NRC - No Detailed Affiliation Given. 2pp. 32987.270-32987.271.
- 8510070091** Forwards requisition for costs incurred from Waterford 3 Task Force effort.Costs incurred by using util equipment justified due to cost benefit advantage over contracting svcs commercially.
FUNCHES,J.L. Planning & Program Analysis Staff. 84/05/04. REBELLO,J. Administrative Contracts Branch. 3pp. 32990.309-32990.311.
- 8510020020** Rev 0 to Allegation Investigation Rept 4-84-A-06/118 re Allegation A-230 concerning disclosing incomplete Mercury documents & drawings not matching as-built plant configuration during Startup Sys 52B, "Reactor Coolant."
* NRC - No Detailed Affiliation Given. 84/05/23. 9pp. 32978.195-32978.203.
- 8510020175** Draft 1 of Allegation Investigation Repts 4-83-A-88/2c, 1,3A1 & 4-84-A-06/18 re Allegations A-49,A-78,A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that subsequent QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. 84/05/24. 6pp. 32981.050-32981.056.
- 8510040430** Rev 0 to Allegation Investigation Rept 4-84-A-06-40 on Allegation A-145 re location plots for some in-place density tests for soil backfill not falling within fill identified on test rept validity of insp of backfill questioned.
* NRC - No Detailed Affiliation Given. 84/05/24. 5pp. 32988.104-32988.108.
- 8510020390** Draft 2 to Allegation Investigation Rept 4-84-A-06-42 of Allegation A-147 re cadwell test repts created to replace lost records w/forged signatures or initials.Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/05/30. 4pp. 32583.130-32983.133.
- 8510020026** Draft 2 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301 Violations noted: lack of adequate procedures for processing deficiency repts, per 10CFR50,App B,Criterion V & ASME Code.
* NRC - No Detailed Affiliation Given. 84/06/03. 10pp. 32978.238-32978.247.
- 8510010026** Forwards evaluation of J Gagliardo & L Shao performance on Waterford 3 team.
CRUTCHFIELD,D. NRC - No Detailed Affiliation Given. 84/06/06. EISENHUT,D. NRC - No Detailed Affiliation Given. 3pp. 32976.096-32976.098.
- 8510010198** Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65 re Allegation A-06,alleging that Ebasco Svcs,Inc QA reviewers have not completed on-the-job training requirements.No potential violations identified.
* NRC - No Detailed Affiliation Given. 84/06/06. 2pp. 32976.329-32976.330.
- 8510010223** Rev 0 to Allegation Investigation Rept 4-84-A-06-27 on Allegation A-132 re JA Jones Const Co use of "speed ltrs" to rept info which should have been reported in deficiency notices.Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. 84/06/06. 5pp. 32976.280-32976.284.
- 8510010293** Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65, re Allegation A-09,alleging that contractor QA people conducting document reviews laid off & Ebasco Svcs,Inc engineers moved into QA positions.
* NRC - No Detailed Affiliation Given. 84/06/06. 2pp. 32976.251-32976.252.
- 8510010353** Marked-up Rev 1 to Allegation Investigation Repts 4-83-A-48/2,4-84-A-06/96 & 4-84-A-06/156 re Allegations A-02,A-208 & A-274,alleging that Mercury Const Co QC inspectors improperly certified.Potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/06. 7pp. 32976.234-32976.240.
- 8510010498** Rev 0 to Allegation Investigation Rept 4-84-A-06/170b.No violations noted.Major areas investigated:Allegation A-289b re inadequate review of QA documentation of Sys 60 (safety injection) due to unqualified reviewers.
* NRC - No Detailed Affiliation Given. 84/06/06. 4pp. 32977.004-32977.007.
- 8510010514** Rev 0 to Allegation Investigation Rept 4-84-A-06-142(1) of Allegation A-258 re CB&I not maintaining matl traceability on certain seismic Category 1 structural components in containment vessel.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/06. 13pp. 32975.301-32975.313.
- 8510010524** Rev 1 to Allegation Investigation Rept 4-83-A-88 re Allegation A-92 on unqualified Ebasco clerks closing out document deficiency repts.No potential violations noted.
ROSS,D. NRC - No Detailed Affiliation Given. 84/06/06. 6pp. 32975.227-32975.232.
- 8510010586** Draft 6 of Allegation Investigation Rept 4-84-A-06/151 re Allegations A-269,A-112,A-113,A-129,A-131,A-135,A-137,A-158 & A-272 concerning concrete records canceled during partial review.
* NRC - No Detailed Affiliation Given. 84/06/06. 9pp. 32977.161-32977.169.
- 8510010589** Rev 0 to Allegation Investigation Rept 4-84-A-06-27 of Allegation A-132 re JA Jones Const Co use of "speed ltrs" to rept info that should have been reported in deficiency notices.No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/06. 18pp. 32977.136-32977.155.
- 8510020057** Rev 1 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/protective coatings & matl traceability for inside of containment vessel.Violation noted:failure to establish QA program.
* NRC - No Detailed Affiliation Given. 84/06/06. 22pp. 32978.287-32978.307.
- 8510020129** Rev 1 to Allegation Investigation Rept 4-84-A-06-8 re Allegations A-113,A-135 & A-137 concerning concrete placement record problems that should have been identified on nonconformance repts.Allegation unsubstantiated.
* NRC - No Detailed Affiliation Given. 84/06/06. 5pp. 32980.221-32980.225.
- 8510020130** Marked-up Rev 0 to Allegation Investigation Rept 4-84-A-06-6 re Allegation A-111 concerning specs & procedures used as acceptance criteria for concrete work frequently ignored by JA Jones personnel.
* NRC - No Detailed Affiliation Given. 84/06/06. 6pp. 32980.126-32980.132.
- 8510020355** Rev 0 to Allegation Investigation Rept 4-84-A-06-6 re Allegation A-111 concerning acceptance criteria for concrete work.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/06. 4pp. 32983.023-32983.026.
- 8510020523** Rev 0 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/protective coatings & matl traceability for inside of containment. Violation noted:failure to establish QA program.
* NRC - No Detailed Affiliation Given. 84/06/06. 13pp. 32985.040-32985.052.
- 8510010533** Rev 1 to Allegation Investigation Rept 4-83-A-88/15 of Allegation A-63 re equipment improperly aligned or leveled at installation.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/07. 5pp. 32976.031-32976.035.
- 8510010583** Rev 1 to Allegation Investigation Repts 4-83-A-88/16, 4-83-A-88/17,4-83-A-88/18 & 4-84-A-12 re Allegations A-64,A-65,A-66 & A-322 concerning unacceptable Mercury insp activities.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/07. 7pp. 32976.347-32976.353.
- 8510010587** Draft 3 to Allegation Investigation Repts 4-84-A-06/120,123, 124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13, 14,15,16,17,18,4-84-A-31,including Allegations A-232,A-234, A-237,A-238,A-243,A-244,A-245,A-311,A-312,A-313 & A-316.
* NRC - No Detailed Affiliation Given. 84/06/07. 5pp. 32977.156-32977.160.
- 8510010600** Draft 3 of Allegation Investigation Rept 4-84-A-06/7 re Allegations A-112,A-131 & A-269 on concrete placement packages.No evidence of significant deviations from project specs found.Some laxness in record keeping noted.
* NRC - No Detailed Affiliation Given. 84/06/07. 6pp. 32977.081-32977.086.
- 8510020292** Draft 3 to Allegation Investigation Rept 4-84-A-06-07 re Allegations A-112,A-131 & A-269 concerning concrete placement & tampered placement packages & insp of packages. Violation noted:failure to maintain concrete curing log.
CHOKSHI,N.C. NRC - No Detailed Affiliation Given. 84/06/07. 7pp. 32982.143-32982.149.
- 8510020415** Rev 1 to Allegation Investigation Rept 4-83-A-81-A7 of Allegation A-26 re nonconforming conditions improperly identified & corrected by Ebasco.No potential violations noted.
MORGANT,N. NRC - No Detailed Affiliation Given. 84/06/07. 2pp. 32983.194-32983.195.
- 8510020456** Rev 0 to Allegation Investigation Rept 4-84-A-06-34 & 4-84-A-06-35 on Allegations A-139 & A-140 re poor concrete placement practices during const of basement in violation of ACI stds leading to cracks found in 1983.
* NRC - No Detailed Affiliation Given. 84/06/07. 19pp. 32984.083-32984.102.
- 8510020460** Draft 2 to Allegation Investigation Rept 4-84-A-06-36 on Allegation A-141 re whether discrepancy notices written during review of 70 concrete placement packages considered in quality review.No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/07. 20pp. 32984.129-32984.150.
- 8510020474** Rev 0 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 re Allegations A-156,A-106,A-108 & A-133 re forged signatures & initials in JA Jones daily cadwell insp repts.
* NRC - No Detailed Affiliation Given. 84/06/07. 10pp. 32984.238-32984.249.
- 8510040080** Rev 1 to Allegation Investigation Rept 4-83-A-81-9 re Allegation A-35 concerning inadequate documentation & failure to verify that piping sys completed per ASME Code.
* NRC - No Detailed Affiliation Given. 84/06/07. 3pp. 32987.280-32987.282.
- 8510010192** Marked-up Draft 3 of Allegation Investigation Rept 4-83-A-65/1 re Allegation A-03,alleging that Ebasco Svcs,Inc QA personnel used speed ltrs instead of deficiency notices to identify sys turnover documentation package problems.
* NRC - No Detailed Affiliation Given. 84/06/08. 6pp. 32976.331-32976.336.
- 8510010232** Draft 2 to Allegation Investigation Rept 4-84-A-06/145 on Allegation A-263 on Mercury Const superintendent not agreeing w/audit findings & refusing to correct problems re tubing w/o encl caps.Corrective action taken.
* NRC - No Detailed Affiliation Given. 84/06/08. 8pp. 32976.253-32976.260.
- 8510010557** Rev 1 to Allegation Investigation Rept 4-84-A-06/81d re Allegation A-186(a) concerning Ebasco QA surveillance not monitoring contractor work activity.Review concluded Ebasco surveillance program meets intent of Ebasco QA program.
* NRC - No Detailed Affiliation Given. 84/06/08. 3pp. 32977.044-32977.046.
- 8510040040** Draft 2 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13,A-14,A-15,A-16 & A-17 re identified electrical seismic support documentation deficiencies not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. 84/06/08. 5pp. 32987.265-32987.269.
- 8510010021** Press release re NRC receiving pressure from congressional delegation concerning facility licensing.NRC 840609 handwritten notes encl.
RIDENHOUR,R. Gambit Publications, Inc., New Orleans, LA. 84/06/09. 4pp. 32977.029-32977.032.
- 8510010043** Marked-up Draft 6 of Allegation Investigation Repts 4-83-A-65/2,5,4-83-A-88/34,4-84/06/175 & 4-84-A-06/170b re Allegations A-06,A-09,A-92,A-294 & A-289b,alleging inadequate training & layoffs of QA personnel.
* NRC - No Detailed Affiliation Given. 84/06/09. 4pp. 32977.118-32977.121.
- 8510010238** Marked-up Draft 6 of Allegation Investigation Rept 4-83-A-48/3 on Allegation A-03 re disclosure of exam answers.Major areas to be investigated:Mercury certification program & previous Mercury inspectors.
* NRC - No Detailed Affiliation Given. 84/06/09. 1p. 32976.261-32976.261.
- 8510010636** Draft 5 to Allegation Investigation Repts 4-84-A-06/173,174, 178,60 & 61 of Allegations A-292,A-293,A-297,A-298,A-299, A-300,A-165 & A-166 re problems w/ Ebasco vendor QA personnel & records.
* NRC - No Detailed Affiliation Given. 84/06/09. 2pp. 32976.224-32976.225.
- 8510020116** Rev 1 to Allegation Investigation Rept 4-84-A-12-9.No violations noted.Major areas investigated:Allegation A-319 re nonconformance repts on instrumentation weld support deficiencies.Draft Rev 0 dtd 840523 encl.
JOHNSON,C. NRC - No Detailed Affiliation Given. 84/06/09. 5pp. 32979.347-32979.352.

- 8510020231** Draft 6 to Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12-4 re Allegations A-57 & A-314 concerning Mercury Level III examiners having no site certifications.
* NRC - No Detailed Affiliation Given. 84/06/09. 1p. 32981:350-32981:350.
- 8510020259** Draft 5 of Allegation Investigation Repts 4-84-A-06/173,174, 178,60 & 81 re Allegations A-165,A-186,A-292,A-293,A-297, A-298,A-299 & A-300 concerning problems w/Ebasco vendor QA people & records.
* NRC - No Detailed Affiliation Given. 84/06/09. 2pp. 32982:018-32982:019.
- 8510020269** Rev 0 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance notification.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/09. 6pp. 32982:097-32982:102.
- 8510020271** Draft 2 of Allegation Investigation Rept 4-83-A-88/2c,1,3A1 & 4-84-A-06/18 re Allegations A-49,A-78,A-87 & A-123 concerning individuals prevented from writing nonconformance repts & QA documentation that may be falsified.
* NRC - No Detailed Affiliation Given. 84/06/09. 15pp. 32981:116-32981:129.
- 8510020305** Draft 6 to Allegation Investigation Rept 4-83-A-88/3A4 re Allegation A-92 concerning inadequate indoctrination & training.Document reviews by improperly or untrained personnel may affect acceptability of safety-related sys.
* NRC - No Detailed Affiliation Given. 84/06/09. 1p. 32982:170-32982:170.
- 8510020306** Draft 2 of Allegation Investigation Rept 4-84-A-06/9 re Allegations A-114,A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 re claim shell filter blanket.
* NRC - No Detailed Affiliation Given. 84/06/09. 3pp. 32982:171-32982:173.
- 8510020326** Allegation Investigation Rept 4-84-A-06-80 re Allegation A-185 concerning existence of written procedure for joint Mercury/Ebasco review of sys turnover documentation.Adequate guidance provided.
* NRC - No Detailed Affiliation Given. 84/06/09. 3pp. 32982:267-32982:269.
- 8510020333** Draft 2 to Allegation Investigation Rept 4-84-A-06/39 re Allegations A-114,A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 re claim shell filter blanket.Violation of ANSI N45.2.6 noted.
* NRC - No Detailed Affiliation Given. 84/06/09. 3pp. 32982:283-32982:285.
- 8510020360** Marked-up Draft 6 to Allegation investigation Rept 4-83-A-85/5,Allegation A-09 re QA personnel lay offs & non-QA engineer replacements.Investigation of Ebasco indoctrination & training program in progress.
* NRC - No Detailed Affiliation Given. 84/06/09. 1pp. 32983:036-32983:036.
- 8510030186** Draft 3 to Allegation Investigation Rept 4-83-A-74-1 re Allegations A-13,A-14,A-15,A-16 & A-17 concerning identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. 84/06/09. 5pp. 32986:157-32986:161.
- 8510040095** Rev 2 to Allegation Investigation Repts 4-83-A-86-4 & 4-83-A-87-3 re Allegations A-39 & A-42 concerning failure to perform nitrogen purge on piping sys prior to welding.
* NRC - No Detailed Affiliation Given. 84/06/09. 6pp. 32987:289-32987:294.
- 8510040525** Rev 0 to Allegation Investigation Rept 4-84-A-06-02 re Allegation A-107 concerning false document generated to replace missing records re cadweld activities.
* NRC - No Detailed Affiliation Given. 84/06/09. 7pp. 32988:223-32988:229.
- 8510010037** Rev 1 to Allegation Investigation Repts 4-84-A-06-108, 4-84-A-06-121 & 4-84-A-06-122 re Allegations A-220,A-233, A-235 & A-236.One nonconformance rept improperly closed in violation of Criterion XVI of 10CFR50,App B.
* NRC - No Detailed Affiliation Given. 84/06/11. 17pp. 32976:108-32976:124.
- 8510010516** Rev 1 to Allegation Investigation Rept 4-84-A-06-146 of Allegation A-264-1 re lack of accurate matl traceability on instrument tube track.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 5pp. 32975:314-32975:318.
- 8510010517** Rev 1 to Allegation Investigation Rept 4-84-A-06/11 of Allegation A-22 re documentation discrepancies between field const & QC package.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 5pp. 32976:067-32976:081.
- 8510010543** Rev 1 to Allegation Investigation Rept 4-83-A-88-6 re Allegation A-54 on failure by Ebasco & site contractor to implement procedures.Site procedure implementation verified as adequate.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 4pp. 32976:060-32976:066.
- 8510020225** Draft 1 of Allegation Investigation Repts 4-84-A-06-136 & 4-84-A-06-143 re Allegations A-250 & A-261 that Mercury personnel changed matl heat & welder numbers w/o proper justification.No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 3pp. 32981:347-32981:349.
- 8510020234** Draft 4 of Allegation Investigation Repts 4-83-A-88/2c, 1,3A1,4-84-A-06/18 & 76 re Allegations A-49,A-78,A-87,A-123, A-181 & A-283 concerning personnel not free to write nonconformance repts.
* NRC - No Detailed Affiliation Given. 84/06/11. 2pp. 32981:073-32981:074.
- 8510020289** Marked-up Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143,Draft 1 re Allegations A-250 & A-261 concerning Mercury personnel changing matl heat numbers & welder identification numbers w/o proper justification.
* NRC - No Detailed Affiliation Given. 84/06/11. 2pp. 32982:141-32982:142.
- 8510020328** Rev 2 to Allegation Investigation Rept 4-83-A-81/2 of Allegation A-28 re falsified resumes & inadequate verification of previous experience of QC inspectors. Violation noted.unqualified inspectors used to perform insp.
WESTBERG,R. NRC - No Detailed Affiliation Given. 84/06/11. 2pp. 32982:274-32982:275.
- 8510020373** Draft 2 to Allegation Investigation Repts 4-84-A-06-41,50, 5,10,25,43 & 52 on Allegations A-146,A-157,A-155,A-110, A-115,A-130 & A-148 re deficiencies in cadweld splicing records improperly dispositioned.Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 20pp. 32983:079-32983:098.
- 8510040004** Rev 1 to Allegation Investigation Rept 4-84-A-06/24 on Allegation A-129 re installation,insp & acceptance of waterstop splicing activities performed by uncertified JA Jones Const Co personnel.
* NRC - No Detailed Affiliation Given. 84/06/11. 9pp. 32987:156-32987:164.
- 8510040006** Rev 1 to Allegation Investigation Repts 4-84-A-06/38,45,57 & 58 on Allegations A-143,A-150,A-162 & A-163 re util,Ebasco & contractors not performing adequate reviews of QA records.No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/11. 5pp. 32987:167-32987:172.
- 8510030243** Draft "Executive Summary - Instrumentation Issues."
* NRC - No Detailed Affiliation Given. 84/06/12. 11pp. 32986:135-32986:145.
- 8510030362** Draft 2 of "Executive Summary - Civil/Structural Issues."
* NRC - No Detailed Affiliation Given. 84/06/12. 10pp. 32987:104-32987:113.
- 8510010255** Draft 3 to Allegation Investigation Rept 4-84-06/145 on Allegation A-263 on Mercury Const superintendent not agreeing w/audit finding & refusing to correct problems identified re tubing w/o end caps.Corrective actions taken.
* NRC - No Detailed Affiliation Given. 84/06/13. 4pp. 32976:270-32976:273.
- 8510010438** Rev 0 to Allegation Investigation Repts 4-84-A-06/105,106 & 107 re Allegations A-217,A-218 & A-219 that Mercury QA manager tried to free employee because employee alleged QA did not follow procedures.No potential violations noted.
STEARNS,J.D. NRC - No Detailed Affiliation Given. 84/06/13. 2pp. 32976:243-32976:244.
- 8510010452** Final Rev 2 to Allegation Investigation Rept 4-83-A-86-6 re Allegation A-54 on Ebasco & site subcontractor failure to implement procedures.Site procedural implementation verified as adequate.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32977:115-32977:117.
- 8510010475** Rev 2 to Allegation Investigation Repts 4-84-A-06-108,121 & 122 re Allegations A-220,A-233,A-235 & A-236 that non-safety matl used in safety-related sys & nonconformance repts improperly dispositioned.
THATCHER,D.F. NRC - No Detailed Affiliation Given. 84/06/13. 7pp. 32975:187-32975:191.
- 8510010497** Marked-up Allegation Investigation Rept 4-84-A-06-4,Rev 0 re Allegation A-109 that Ebasco Svcs,Inc QA personnel stopped record reviewers when "wholesale" irregularities found in 70 of 1,200 concrete placement packages.
DEVERS,J.K., CHOKSHI,N.C., SHEWMAKER,R.E. NRC - No Detailed Affiliation Given. 84/06/13. 4pp. 32977:014-32977:017.
- 8510010510** Draft 2 to Allegation Investigation Rept 484A06142(3) of Allegation A-259 re Class D matl used by CB&I in fabrication of nonpressure bearing structural components not welded w/traceable weld rod.Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 20pp. 32977:058-32977:077.
- 8510010523** Rev 0 to Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21,22,23a,23c & 167 re Allegations A-100-A-103, A-127,A-128a,A-128c & A-285a concerning Mercury traceability problems.Mercury weld records difficult to follow.
* NRC - No Detailed Affiliation Given. 84/06/13. 8pp. 32976:082-32976:089.
- 8510010537** Allegation Investigation Rept 4-83-A-88/11 re Allegation Draft 3 of A-59 concerning Ebasco failure to place hold tags on field items.
* NRC - No Detailed Affiliation Given. 84/06/13. 4pp. 32976:092-32976:095.
- 8510010540** Rev 0 to Allegation Investigation Rept 4-84-A-06-4 re Allegation A-109 on Ebasco QA personnel stopping records & reviewers when wholesale irregularities found.Potential violation noted re failure to maintain concrete records.
* NRC - No Detailed Affiliation Given. 84/06/13. 19pp. 32976:042-32976:059.
- 8510010551** Marked-up Draft 1 of Allegation Investigation Repts 4-84-A-06/103,109,126,144 & 184 re Allegations A-215,A-175, A-240,A239 & A-306i concerning destruction of deficiency rept.Violation noted:incomplete & incorrect records.
* NRC - No Detailed Affiliation Given. 84/06/13. 17pp. 32976:128-32976:145.
- 8510010574** Rev 2 to Allegation Investigation Rept 4-84-A-06-146 of Allegation A-264-1 re failures to provide accurate matl traceability on instrument tube track.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 2pp. 32976:165-32976:166.
- 8510010592** Rev 1 to Allegation Investigation Rept 4-83-A-88-11 re Allegation A-59 concerning Ebasco failure to place hold tags on field items.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 6pp. 32977:108-32977:113.
- 8510010607** Rev 0 to Allegation Investigation Rept 4-84-A-06/7 re Allegations A-112,A-131 & A-269 concerning concrete placement packages.Potential violation noted:failure to maintain concrete curing log for Placement 593501U74FAA.
* NRC - No Detailed Affiliation Given. 84/06/13. 5pp. 32976:208-32976:222.
- 8510010615** Rev 1 to Allegation Investigation Repts 4-83-A-88/Ad & 4-83-A-88/Ad re Allegations A-81 & A-82 of changes made to N-5 packages w/o knowledge of authorized nuclear inspector. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32977:226-32977:226.
- 8510020011** Rev 1 to Allegation Investigation Rept 4-84-A-06-10 re Allegations A-115 & A-155 concerning concerns on Cadweld splice tensile test failure rates exceeding 1 in 15 consecutive test samples.No potential violations noted.
YANG,L. NRC - No Detailed Affiliation Given. 84/06/13. 8pp. 32978:162-32978:169.
- 8510020017** Draft 3 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301 Violations noted lack of adequate procedures for processing deficiency repts, per 10CFR50,App B Criterion V & ASME Code.
* NRC - No Detailed Affiliation Given. 84/06/13. 5pp. 32978:190-32978:194.
- 8510020039** Rev 2 to Allegation Investigation Rept 4-84-A-06/11 re Allegation A-223 concerning documentation discrepancies between field const & QC packages.No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 2pp. 32978:265-32978:265.
- 8510020042** Rev 1 to Allegation Investigation Rept 4-84-A-06/118 of Allegation A-230 re Ebasco review of Startup Sys 52B(RFS) that found Mercury documents incomplete & red-lined on drawings which did not match as-built plant.
* NRC - No Detailed Affiliation Given. 84/06/13. 6pp. 32978:271-32978:276.
- 8510020062** Rev 2 to Allegation Investigation Rept 4-84-A-06-113 re Allegation A-225 concerning whether guidelines provided in Reg Guide 1.29 were considered during instrument & piping & tubing design.
* NRC - No Detailed Affiliation Given. 84/06/13. 13pp. 32978:314-32978:327.

160 DOCKETED ITEMS

- 8510020084** Rev 0 to Allegation Investigation Repts 4-84-A-06-139, 4-84-A-06-140A & 4-84-A-06-141 re Allegations A-253, A-254 & A-257 concerning use of unqualified vendor reviewers & poorly maintained vendor records. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 8pp. 32979:078-32979:085.
- 8510020086** Rev 1 to Allegation Investigation Repts 4-84-A-06/67 & 4-84-A-06/69 of Allegations A-172 & A-174 re falsified Tompkins-Beckwith heat number records.
* NRC - No Detailed Affiliation Given. 84/06/13. 4pp. 32979:238-32979:241.
- 8510020091** Rev 1 to Allegation Investigation Repts 4-84-A-06-55 & 56 of Allegations A-160 & A-161 re mats lacking heat number traceability & welds done by unqualified welder & inspected by unqualified inspectors.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. 84/06/13. 11pp. 32979:251-32979:261.
- 8510020142** Rev 1 to Allegation Rept 4-84-A-06-63 of Allegation A-168 re poor QC by American Bridge. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 7pp. 32980:245-32980:252.
- 8510020156** Rev 1 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re performance of documentation reviews by unqualified Ebasco personnel. No violations noted. Marked-up Rev 1 encl.
WESTBERG, R. NRC - No Detailed Affiliation Given. 84/06/13. 7pp. 32980:333-32980:339.
- 8510020173** Rev 2 to Allegation Investigation Rept 4-84-A-06/8 re Allegations A-113, A-135 & A-137 concerning concrete placement records. Allegation has neither safety significance nor generic implications.
* NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32980:123-32980:125.
- 8510020177** Rev 0 to Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76. No violations noted. Major areas investigated: Allegations A-283 & A-181 re nonconformance repts. Draft Rev 0 & Draft 4 dtd 840611 encl.
* NRC - No Detailed Affiliation Given. 84/06/13. 7pp. 32981:136-32981:142.
- 8510020179** Draft 3 of Allegation Investigation Rept 4-84-A-06/39 re Allegations A-144, A-154 & A-114 concerning clam shell filter blanket record deficiencies. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. 84/06/13. 2pp. 32981:148-32981:149.
- 8510020206** Rev 3 to Allegation Investigation Rept 4-83-A-81/2 of Allegation A-28 re falsified resumes & inadequate experience of QA inspectors. Violation noted: unqualified inspectors incorrectly certified due to inadequate procedure.
WESTBERG, R. NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32981:259-32981:262.
- 8510020246** Rev 2 to Allegation Investigation Repts 4-84-A-06-78(a) & 4-84-A-06-79 of Allegations A-183(a) & A-184 re generic deficiencies in Mercury documentation of OCR record packages. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 15pp. 32982:001-32982:015.
- 8510020264** Draft 3 of Allegation Investigation Rept 4-83-A-88/2c, 1, 3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. 84/06/13. 17pp. 32981:099-32981:115.
- 8510020306** Rev 0 to Allegation Investigation Rept 484A06/5 re Allegations A-110, A-130 & A-148 on 17 inspectors from Ebasco, JA Jones & Fegles Power Svcs not meeting requirements of ANSI N45.2.6, "Qualification of Insp Exam...".
* NRC - No Detailed Affiliation Given. 84/06/13. 16pp. 32982:174-32982:190.
- 8510020339** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/2. Allegations A-02, A-208 & A-274 re improper certification of Mercury Const Co QC inspectors. Twelve certifications found questionable.
* NRC - No Detailed Affiliation Given. 84/06/13. 12pp. 32982:306-32982:318.
- 8510020353** Marked-up Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167. Rev 0 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning Mercury Const Co mat traceability problems.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. 84/06/13. 4pp. 32983:019-32983:022.
- 8510020383** Rev 0 to Allegation Investigation Rept 4-84-A-06-9 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket. Violation of ANSI N45.2.6 noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32983:041-32983:043.
- 851020513** Rev 0 to Allegation Investigation Rept 4-84-A-06-9 re Allegations A-114, A-144 & A-154 concerning disposition of Nonconformance Rept W3-5997 concerning clam shell filter blanket under plant. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32985:037-32985:039.
- 8510030050** Marked-up Allegation Investigation Repts 4-83-A-88/Ad & Ad, Rev 1 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o authorized nuclear inspector approval.
FARREN, J. NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32985:086-32985:088.
- 8510040009** Rev 0 to Allegation Investigation Repts 4-84-A-06-53 & 54 on Allegations A-138 & A-159 re deficiencies found in Ebasco backfill operation. Corrective actions must be completed before fuel load.
* NRC - No Detailed Affiliation Given. 84/06/13. 14pp. 32987:192-32987:205.
- 8510040217** Marked-up Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a. Rev 1 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability.
SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. 84/06/13. 3pp. 32987:319-32987:321.
- 8510040434** Rev 2 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern that piping supports not in compliance w/Reg Guide 1.29. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 5pp. 32988:109-32988:114.
- 8510040553** Rev 2 to Allegation Investigation Rept 4-84-A-06/11 of Allegation A-223 re documentation discrepancies between field const & QA packages & missing test repts on operational control records. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/13. 2pp. 32989:204-32989:205.
- 8510010199** Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-48/1 re Allegation A-01 alleging that employment records of Mercury Const Co QA personnel not verified. Rept findings: QA inspectors certified w/o verifying previous employment.
* NRC - No Detailed Affiliation Given. 84/06/14. 15pp. 32976:314-32976:328.
- 8510010228** Rev 1 to Allegation Investigation Rept 4-84-A-06-152(3) on Allegation A-260 re lack of traceability of mats used in nonpressure retaining components in containment vessels. Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. 84/06/14. 2pp. 32976:278-32976:279.
- 8510010241** Rev 1 to Allegation Investigation Rept 4-84-A-06-142(3) on Allegation A-260 re lack of traceability of mats used in nonpressure retaining components in containment vessel. Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. 84/06/14. 6pp. 32976:262-32976:269.
- 8510010564** Draft 2 to Allegation Investigation Rept 4-84-A-06-31 of Allegation A-136 re difficulty of Ebasco personnel to get approval to initiate formal nonconformance rept between 1975 & 1977 in civil/structural area. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/14. 5pp. 32975:206-32975:210.
- 8510020029** Rev 1 to Allegation Investigation Rept 4-84-A-06/102 re Allegation A-214 concerning 1981 Mercury QC weld data repts containing incorrect filler matl certification. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/14. 7pp. 32978:252-32978:257.
- 8510020121** Draft 2 to Allegation Investigation Repts 4-84-A-06/103, 109, 144, 126 & 184 re Allegations A-215, A-175, A-239, A-240 & A-306i concerning destroying deficiency rept on welder qualification & questionable quality of welding.
* NRC - No Detailed Affiliation Given. 84/06/14. 38pp. 32980:049-32980:086.
- 8510020218** Draft 2 of Allegation Investigation Repts 4-84-A-06-136 & 4-84-A-06-143 re Allegations A-250 & A-261 that Mercury personnel changed matl heat & welder identification numbers w/o proper justification. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/14. 6pp. 32981:320-32981:325.
- 8510020248** Rev 0 to Allegation Investigation Rept 4-83-A-88/2c, 1, 3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. 84/06/14. 10pp. 32981:075-32981:084.
- 8510020313** Rev 1 to Allegation Investigation Rept 4-84-A-06-12 re Allegations A-117 & A-120 concerning falsified Mercury & Tompkins-Beckwith records. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/14. 8pp. 32982:216-32982:223.
- 8510020391** Draft 3 to Allegation Investigation Rept 4-84-A-06-42 of Allegation A-147 re cadweld test repts created to replace lost records w/forged signatures or initials. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/14. 8pp. 32983:134-32983:141.
- 8510020468** Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re forged signatures & initials in JA Jones daily cadweld insp repts.
* NRC - No Detailed Affiliation Given. 84/06/14. 4pp. 32984:209-32984:212.
- 8510030196** Marked-up Rev 0 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59. Allegations A-18 & A-164 re inadequate nonconformance control by Ebasco Svcs Intl where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. 84/06/14. 3pp. 32986:109-32986:111.
- 8510040427** Rev 1 to Allegation Investigation Rept 4-84-A-06-40 of Allegation A-145 re location plots for some in-place density tests for soil backfill not falling within fill identified on test rept. Validity of insp questioned.
* NRC - No Detailed Affiliation Given. 84/06/14. 8pp. 32988:096-32988:103.
- 8510040515** Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re possibility of forged signatures & initials on JA Jones daily cadweld insp repts.
* NRC - No Detailed Affiliation Given. 84/06/14. 6pp. 32989:287-32989:298.
- 8406260464** Discusses encl 840602 article re review team members under intense pressure to either gloss over or forewarn util of allegations. Each member should remain uninfluenced by calls, comments & pressure.
EISENHUT, D.G. Division of Licensing. 84/06/15. NRC - No Detailed Affiliation Given. 3pp. 32981:162-32981:178.
- 8510010222** Rev 0 to Allegation Investigation Rept 4-84-A-06/145 on Allegation A-263 re Mercury Const superintendent not agreeing w/audit findings & refusing to correct problems re tubing w/c and caps. Corrective actions taken.
* NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32976:285-32976:286.
- 8510010539** Rev 1 to Allegation Investigation Rept 4-84-A-06-02 re Allegation A-107 that false documents generated to replace missing records concerning cadweld activities. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32976:090-32976:091.
- 8510010595** Draft 3 of Allegation Investigation Rept 4-84-A-06-11 re Allegation A-116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 3pp. 32977:105-32977:107.
- 8510010597** Rev 1 to Allegation Investigation Rept 4-83-A-88-10 re Allegation A-58 concerning improper maint practices of util & contractors. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 10pp. 32977:090-32977:099.
- 8510010619** Rev 4 to Allegation Investigation Repts 4-84-A-06/60, 61, 173, 174 & 178 of Allegations A-165, A-166, A-292, A-293, A-297, A-299 & A-300 re activities of Ebasco vendor QA personnel & inadequate QA records.
NALEZNY, C. NRC - No Detailed Affiliation Given. 84/06/15. 10pp. 32976:337-32976:346.
- 8510010621** Rev 2 to Allegation Investigation Repts 4-83-A-88/16, 4-83-A-88/17 & 4-83-A-88/18 re Allegations A-64, A-65 & A-66 concerning unacceptable Mercury insp activities. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32977:222-32977:223.

- 8510020014** Rev 2 to Allegation Investigation Repts 4-84-A-06/182, 4-84-3 & 4-84-A-06/167 re Allegations A-304, A-305 & A-285b on unqualified person making changes to QA documentation which affect acceptability of safety-related piping sys.
* NRC - No Detailed Affiliation Given. 84/06/15. 10pp. 32978:178-32978:187.
- 8510020015** Rev 1 to Allegation Investigation Rept 4-84-A-06/95 re Allegation A-207 concerning Mercury QA personnel throwing away documents after copies made. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32978:188-32978:189.
- 8510020021** Rev 1 to Allegation Investigation Rept 4-84-A-06/91 re Allegation A-196 concerning Ebasco document control supervisor being unqualified for position. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 4pp. 32978:204-32978:207.
- 8510020025** Rev 1 to Allegation Investigation Rept 4-84-A-06/97 re Allegation A-209 concerning review of Mercury weld records identifying welds not fit-up or final-inspected. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 9pp. 32985:056-32985:062.
- 8510020051** Rev 1 to Allegation Investigation Rept 4-84-A-06/135 re Allegation A-249 concerning improperly processed Ebasco Discrepancy notices. No violation noted.
FRED, B.L. NRC - No Detailed Affiliation Given. 84/06/15. 3pp. 32985:053-32985:055.
- 8510020078** Rev 0 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301. Potential violation noted: lack of adequate procedure for disposition of corrective action documents. Draft 3 encl.
* NRC - No Detailed Affiliation Given. 84/06/15. 14pp. 32978:348-32978:361.
- 8510020107** Rev 2 to Allegation Investigation Repts 4-84-A-06/92, 93, 94, 101 & 104 re Allegations A-197 through A-206, A-213 & A-216 concerning inadequate documentation of corrective actions for problems w/ QC weld record data sheets.
* NRC - No Detailed Affiliation Given. 84/06/15. 19pp. 32979:311-32979:327.
- 8510020152** Rev 0 to Allegation Investigation Repts 4-84-A-06/117 & 184g re Allegations A-229 & A-306g concerning inadequate reviews of turnover documentation packages which affect acceptability of safety-related sys.
* NRC - No Detailed Affiliation Given. 84/06/15. 21pp. 32980:305-32980:326.
- 8510020153** Draft of Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 5, 7, 8, 10, 11, 13, 14, 15, 16, 17, 18 & 4-84-A-31 re Allegations A-232, A-234, A-238, A-243, A-244, A-245, A-262, A-311, A-312, A-313, A-316 & A-317.
* NRC - No Detailed Affiliation Given. 84/06/15. 44pp. 32980:166-32980:211.
- 8510020165** Rev 0 to Allegation Investigation Rept 4-84-A-06/115 re Allegation A-227 concerning Ebasco inadequate nonconformance sys & nonconformances not properly identified & dispositioned.
* NRC - No Detailed Affiliation Given. 84/06/15. 26pp. 32980:358-32981:021.
- 8510020266** Draft 3 to Allegation Investigation Rept 4-84-A-06-11 re Allegation 116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 11pp. 32982:024-32982:034.
- 8510020267** Marked-up Allegation Investigation Rept 4-84-A-06-135, Rev 1 re Allegation A-249 concerning Ebasco Svcs, Inc discrepancy notices falsified by subcontractors. No potential violations found.
FRED, B.L. NRC - No Detailed Affiliation Given. 84/06/15. 3pp. 32982:021-32982:023.
- 8510020284** Rev 1 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. Missing & voided nonconformance repts violate Criterion IXI of App B.
* NRC - No Detailed Affiliation Given. 84/06/15. 6pp. 32982:120-32982:125.
- 8510020320** Rev 2 to Allegation Investigation Rept 4-83-A-81-A7 of Allegation A-26 re nonconforming conditions improperly identified & corrected by Ebasco. No potential violations noted.
MORGAN, T. NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32982:241-32982:242.
- 8510020384** Draft 3 of Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re improperly dispositioned cadweld records. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 8pp. 32983:119-32983:126.
- 8510020424** Final Rev 2 to Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12 re Allegations A-64-A-66 & A-322 concerning Ebasco Svcs, Inc site ltrs which imply that Mercury insp activities unacceptable.
MORGAN, T. NRC - No Detailed Affiliation Given. 84/06/15. 3pp. 32983:241-32983:243.
- 8510030205** Draft 3 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re cadweld record deficiencies, uncertified inspectors & implementation of cadweld sampling procedures.
* NRC - No Detailed Affiliation Given. 84/06/15. 7pp. 32986:128-32986:134.
- 8510030350** Rev 0 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13, A-14, A-15, A-16 & A-17 re identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. 84/06/15. 4pp. 32987:063-32987:066.
- 8510040007** Rev 0 to Allegation Investigation Rept 4-84-A-06-31 on Allegation A-136 re difficulty for Ebasco QA personnel to get approval to initiate formal nonconformance repts between 1975 & 1977 in civil/structural area.
* NRC - No Detailed Affiliation Given. 84/06/15. 9pp. 32987:173-32987:181.
- 8407100682** Provides info re potentially significant safety issues at facility, including backfill soil density, cadwelds, welding instrumentation, calineel support & insp records. DIRCKS, W.J. Office of the Executive Director for Operations. SECY-84-239. 84/06/18. 7pp. 32975:005-32975:084.
- 8510010049** Draft 3 of Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 on use of unqualified matl on safety-related sys. Purchase, spec & orders will be reviewed for safety status.
* NRC - No Detailed Affiliation Given. 84/06/18. 12pp. 32977:122-32977:133.
- 8510010521** Provides executive summary of results of interview & review of individual 'X' files. HS Philips assigned to assist Ofc of Investigation per 840601 request. Individual contacted during task force effort.
PHILLIPS, H.S. Region 4, Office of Director. 84/06/18. Region 4, Office of Director. 42pp. 32975:321-32975:362.
- 8510010528** Draft 3 of Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 concerning unqualified matl adaptors used on safety-related sys.
* NRC - No Detailed Affiliation Given. 84/06/18. 3pp. 32976:004-32976:006.
- 8510010563** Rev 3 to Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 that nonsafety matl used in safety-related sys & nonconformance repts improperly dispositioned.
THATCHER, D.F. NRC - No Detailed Affiliation Given. 84/06/18. 10pp. 32975:278-32975:287.
- 8510010631** Rev 1 to Allegation Investigation Repts 4-84-A-06/83, 85, 86 & 88 re Allegations A-188, A-190, A-191 & A-193 concerning Mercury procedures for review of QA records & inadequate documentation packages.
* NRC - No Detailed Affiliation Given. 84/06/18. 10pp. 32977:206-32977:215.
- 8510020069** Rev 1 to Allegation Investigation Rept 4-83-A-88-4A re Allegation A-94-A-99 concerning improper reporting & corrective action of nonconformance repts & missing QA records. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/18. 4pp. 32990:312-32990:315.
- 8510020137** Marked-up Allegation Investigation Rept 4-84-A-06-142(3) re Allegation A-259 concerning Class D matl used by Chicago Bridge & Iron in fabrication of nonpressure bearing structural components not welded w/ traceable weld rod.
* NRC - No Detailed Affiliation Given. 84/06/18. 5pp. 32980:229-32980:233.
- 8510020186** Rev 1 to Allegation Investigation Repts 4-83-A-81/81, 4-84-A-06/161, 4-84-A-06/169, 4-84-A-06/162, 4-84-A-06/164 & 4-84-A-06/166 re Allegations A-279, A-280, A-282, A-284, A-286 & A-27. Violations noted re separation criteria.
SUMMERS, D.L., FARREN, J.W., WENZEL, V.L. NRC - No Detailed Affiliation Given. 84/06/18. 4pp. 32981:198-32981:199.
- 8510040521** Rev 2 to Allegation Investigation Rept 4-84-A-06-37 re Allegation A-142 on American Bridge failure to provide documentation for over 30% of work & documented work not reflecting true status.
* NRC - No Detailed Affiliation Given. 84/06/18. 6pp. 32988:211-32988:222.
- 8510010509** Rev 2 to Allegation Investigation Repts 4-84-A-06/83, 85, 86 & 88 re Allegations A-188, A-190, A-191 & A-193 that Mercury procedures for review of QA records & documentation packages inadequate. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 10pp. 32975:137-32975:145.
- 8510010522** Rev 2 to Allegation Investigation Rept 4-84-A-06/81b re Allegation A-186(b) that Ebasco records reviewer stamped off 1,600 civil records (concrete) in 8 h work day. No potential violations noted.
WENZEL, V. NRC - No Detailed Affiliation Given. 84/06/19. 3pp. 32975:224-32975:226.
- 8510010548** Rev 2 to Allegation Investigation Rept 4-84-A-06/81b re Allegation A-186(b) concerning Ebasco records reviewer allegedly stamping off 1,600 civil records in 8 h day in Sept 11982. Stamping was to account for & collate records.
* NRC - No Detailed Affiliation Given. 84/06/19. 5pp. 32976:125-32976:129.
- 8510010560** Rev 1 to Allegation Investigation Rept 4-8-A-06-27 of Allegation A-132 re JA Jones Const Co use of communication called "speed ltrs" to repts info that should have been reported in deficiency notices. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 14pp. 32975:192-32975:205.
- 8510010610** Rev 2 to Allegation Investigation Rept 4-84-A-06/118 re Allegation A-230 concerning Ebasco review of startup sys 52B RCS finding many Mercury documents incomplete & red-lined on drawings that do not match as-built plant configuration.
* NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32976:204-32976:207.
- 8510020024** Rev 1 to Allegation Investigation Rept 4-84-A-06-142(1) of Allegation A-258 re CB&I not maintaining matl traceability on certain seismic Category 1 structural components in containment vessel. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 25pp. 32978:211-32978:237.
- 8510020047** Rev 1 to Allegation Investigation Repts 4-84-A-06/82a,b & c re Allegation A-187 concerning incorrect Mercury instrumentation drawings due to unincorporated field changes.
* NRC - No Detailed Affiliation Given. 84/06/19. 7pp. 32978:278-32978:283.
- 8510020079** Rev 3 to Allegation Investigation Rept 4-84-A-45 re Allegation A-335. Violations noted: failure to follow Ebasco Spec LOU-1564.472, Section II re insp of concrete curing on dome Rev 1 dtd 840609 & Rev 2 dtd 840618 encl.
DEYERS, J. NRC - No Detailed Affiliation Given. 84/06/19. 16pp. 32979:001-32979:048.
- 8510020082** Rev 2 to Allegation Investigation Rept 4-84-A-47a of Allegation A-336 re failure of Tompkins-Backwith to account for skewed angles in weld size spec for pipe supports. No violations noted. Rev 1 dtd 840609 encl.
TAPIA, J.I. NRC - No Detailed Affiliation Given. 84/06/19. 12pp. 32979:049-32979:077.
- 8510020088** Rev 2 to Allegation Investigation Rept 4-84-A-06/158 re Allegation A-276. Violation noted: certification of unqualified inspector Rev 1 encl.
* NRC - No Detailed Affiliation Given. 84/06/19. 9pp. 32979:242-32979:250.
- 8510020110** Rev 1 to Allegation Investigation Repts 4-84-A-40/1, 4-84-A-40/2 & 4-84-A-40/3. No violations noted. Major areas inspected: Allegations A-332, A-333 & A-334 re inadequate DCN-MP-920 & questionable welder certification.
BERG, V. NRC - No Detailed Affiliation Given. 84/06/19. 3pp. 32979:328-32979:330.
- 8510020111** Draft 3 to Allegation Investigation Rept 4-84-A-06-72 of Allegation A-177 re Ebasco QA inspector malfeasance in dispositioning nonconformance repts on American Bridge Co work. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 13pp. 32979:331-32979:343.

162 DOCKETED ITEMS

- 8510020117** Rev 0 to Allegation Investigation Rept 4-84-A-06-178b. No violations noted. Major areas investigated: Allegation A-298 re inadequate Ebasco QC reviews of structural items. Marked-up Rev 0 dtd 840607 encl.
* NRC - No Detailed Affiliation Given. 84/06/19. 13pp. 32979-353-32980-006.
- 8510020138** Rev 2 to Allegation Investigation Rept 4-84-A-06/77 of Allegation A-182 re failure to inspect welding done by JA Jones Const Co. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 5pp. 32980-157-32980-161.
- 8510020167** Rev 0 to Allegation Investigation Rept 4-84-A-06-150. No violations noted. Major areas investigated: Allegation A-268 re ungrouted surface-mounted base plates. Draft 1 dtd 840531 & Draft 2 dtd 840614 encl.
* NRC - No Detailed Affiliation Given. 84/06/19. 14pp. 32981-022-32981-035.
- 8510020169** Rev 1 to Allegation Investigation Rept 4-84-A-06-152. No violations noted. Major areas investigated: Allegation A-270 re common foundation basement, Block 2 concerns in Ebasco 751215 rept. Draft Rev 1 encl.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/06/19. 6pp. 32981-036-32981-041.
- 8510020247** Rev 0 to Allegation Investigation Rept 4-84-A-06/170(b). No violations noted. Major areas investigated: Allegation A-289(b) re inadequate review of QA documentation of Sys 60, Draft 6 to "Waterford Open Issue," dtd 850609 encl.
* NRC - No Detailed Affiliation Given. 84/06/19. 12pp. 32981-351-32981-361.
- 8510020273** Draft 3 to Allegation Investigation Repts 4-83-A-88/2a, 2b, 2c, 3 & 4-84-A-12-5 re Allegations A-88, A-89, A-90, A-91 & A-315 concerning failure of contractor to provide pipe hydrostatic test results & faulty test documentation.
* NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32982-126-32982-129.
- 8510020273** Draft 3 to Allegation Investigation Repts 4-83-A-88/2a, 2b, 2c, 3 & 4-84-A-12-5 re Allegations A-88, A-89, A-90, A-91 & A-315 concerning failure of contractor to provide pipe hydrostatic test results & faulty test documentation.
* NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32982-126-32982-129.
- 8510020300** Draft 3 of Allegation Investigation Rept 4-84-A-06/177 re Allegation A-296 concerning contractor failure to provide pipe hydrostatic test results.
* NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32982-156-32982-159.
- 8510020303** Rev 1 to Allegation Investigation Rept 4-84-A-06-6 re Allegation A-111 concerning specs & procedures used as acceptance criteria for concrete work frequently ignored by JA Jones personnel. No potential violations.
* NRC - No Detailed Affiliation Given. 84/06/19. 7pp. 32982-163-32982-169.
- 8510020310** Rev 0 to Allegation Investigation Repts 4-84-A-06-44, 46, 47 & 48 for Allegations A-149, A-151, A-152 & A-153 re nonconformance repts signed by QC inspectors performing work prior to being certified. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 10pp. 32982-191-32982-200.
- 8510020314** Draft 5 to Allegation Investigation Rept 4-84-A-06 (114) re Allegation A-226 that traceability requirements of permanent mat welded to Class 1 & 2 piping pressure boundaries not satisfactorily resolved. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 8pp. 32982-224-32982-231.
- 8510020318** Draft 7 of Allegation Investigation Rept 4-84-A-06 re Allegation A-296. Potential violation noted: lack of confirmation that shop welds inspected for leaks during hydrostatic tests per ASME Code.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32982-237-32982-240.
- 8510020343** Marked-up Rev 0 to Allegation Investigation Rept 4-83-A-74/7, Allegation A-19 re record deficiencies for 186 separate Fisch & Moore documents.
* NRC - No Detailed Affiliation Given. 84/06/19. 4pp. 32982-327-32982-330.
- 8510020369** Draft 3 to Allegation Investigation Repts 4-84-A-06/23d, 100 & 157 on Allegations A-128d, A-212 & A-275 re undersized welds in Mercury work.
* NRC - No Detailed Affiliation Given. 84/06/19. 6pp. 32983-061-32983-066.
- 8510020381** Rev 0 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re improperly dispositioned cadweld splicing records. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/19. 5pp. 32983-105-32983-118.
- 8510020413** Draft 2 of Allegation Investigation Rept 4-83-A-81/A6 of Allegation A-25 re CB&I QA record deficiencies on containment penetration welds. No potential violations noted.
TAPIA, J.I. NRC - No Detailed Affiliation Given. 84/06/19. 3pp. 32983-185-32983-187.
- 8510020458** Rev 1 to Allegation Investigation Repts 4-84-A-06-34 & 4-84-A-06-35 on Allegations A-139 & A-140 re instances of poor concrete placement practices during const of basement in violation of spec & ACI stds.
* NRC - No Detailed Affiliation Given. 84/06/19. 14pp. 32984-110-32984-123.
- 8510020467** Marked-up Allegation Investigation Rept 4-84-A-06-140c, Rev 2 re Allegation A-256 concerning Chicago Bridge & Iron Co problems w/protective coatings & mat traceability for inside containment vessel.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. 84/06/19. 5pp. 32984-204-32984-208.
- 8510030008** Allegation Investigation Rept 4-84-A-06/158, Rev 2 re Allegation A-276 concerning Mercury Const Co resume fraud. Potential violations of 10CFR50, App B & ANSI N45.2.6 noted.
WESTBERG, R. NRC - No Detailed Affiliation Given. 84/06/19. 3pp. 32985-063-32985-065.
- 8510030022** Rev 2 to Allegation Investigation Rept 4-83-A-81-B4 re Allegation A-30 concerning as-built drawings of main steamline restraint framing not reflecting actual conditions in field.
* NRC - No Detailed Affiliation Given. 84/06/19. 6pp. 32986-112-32986-124.
- 8510030154** Marked-up Allegation Investigation Rept 4-84-A-06-152, Rev 1 re Allegation A-270 concerning Ebasco Svcs, Inc QC rept on Block 2 common foundation base mat. No potential violations noted.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/06/19. 2pp. 32986-058-32986-059.
- 8510030295** Rev 2 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/protective coatings & mat traceability for inside of containment vessel. Violation noted: failure to establish QA program.
* NRC - No Detailed Affiliation Given. 84/06/19. 5pp. 32987-004-32987-008.
- 8510030390** Rev 0 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re deficiencies in cadweld splicing records identified in Nonconformance Rept W3-6234 not properly dispositioned.
* NRC - No Detailed Affiliation Given. 84/06/19. 17pp. 32987-120-32987-136.
- 8510040070** Marked-up Allegation Investigation Rept 4-84-A-06/170b, Rev 0 re Allegation A-289(b) concerning QA Sys 60 documentation inadequately reviewed due to unqualified Ebasco Svcs, Inc reviewers. No potential violations noted.
ROSS, D. NRC - No Detailed Affiliation Given. 84/06/19. 3pp. 32987-274-32987-276.
- 8510010531** Rev 1 to Allegation Investigation Repts 4-84-A-06/110 & 119 re Allegations A-222 & A-231 re insufficiency of Mercury concrete expansion anchor installation & insp procedure. Allegation may have some safety significance.
MARINI, W.S. NRC - No Detailed Affiliation Given. 84/06/20. 5pp. 32975-233-32975-236.
- 8510010556** Rev 0 to Allegation Investigation Rept 4-84-A-06-11 re Allegation A-116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/20. 6pp. 32976-159-32976-164.
- 8510020013** Rev 1 to Allegation Investigation Rept 4-84-A-06/147 re Allegation A-265. Potential violations noted: initial insp records failed to provide evidence of as-built conditions, per 10CFR50, App B, Criterion XVII.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. 84/06/20. 10pp. 32978-170-32978-177.
- 8510020147** Draft 2 to Allegation Investigation Rept 4-84-A-47b of Allegation A-337 re performance of tube track welding to requirements of AWS Welding Spec D1.3 rather than Spec D1.1. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/20. 7pp. 32980-291-32980-297.
- 8510020151** Draft 4 to Allegation Investigation Rept 4-84-A-06-181 of Allegation 303a re failure of Thompkins-Beckwith to provide documentation to verify compatibility between welding backing rings & mat. No violations noted.
SPAULDING, W. NRC - No Detailed Affiliation Given. 84/06/20. 8pp. 32980-298-32980-305.
- 8510020282** Draft 4 to Allegation Investigation Rept 4-84-A-06-149. No violation noted. Major areas investigated: Allegation A-267 re falsification of documentation concerning nonsafety-related pipe hangers placed in safety-related areas.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/20. 6pp. 32980-352-32980-357.
- 8510020280** Draft 2 to Allegation Investigation Rept 4-84-A-06-03 re Allegation A-252 that Ebasco Ltr W3-QA-23661 issued to cover up problems discovered by documentary review group. Allegation unsupported.
* NRC - No Detailed Affiliation Given. 84/06/20. 6pp. 32982-130-32982-135.
- 8510020325** Draft 2 of Allegation Investigation Rept 4-84-A-06 re Allegations A-126 & A-291 concerning failure to maintain mat traceability on supplemental steel used w/pipes hangers & supports. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/20. 8pp. 32982-259-32982-266.
- 8510020334** Draft 6 to Allegation Investigation Rept 4-84-A-06/23D on Allegation A-128d, A-212 & A-275 re undersized welds discovered in Mercury socket weld fittings. Allegation has no safety significance or generic implications.
* NRC - No Detailed Affiliation Given. 84/06/20. 4pp. 32982-286-32982-289.
- 8510030069** Allegation Investigation Rept 4-84-A-06/147, Rev 1 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
* NRC - No Detailed Affiliation Given. 84/06/20. 3pp. 32985-096-32985-098.
- 8510010486** Rev 1 to Allegation Investigation Repts 4-84-A-06/44, 4-84-A-06/46, 4-84-A-06/47 & 4-84-A-06/48 re Allegations A-149, A-151, A-152 & A-153. Violation noted re nonconformance repts. Draft Rev 1 encl.
CROSSMAN, W.A. NRC - No Detailed Affiliation Given. 84/06/21. 10pp. 32976-354-32977-001.
- 8510010535** Draft 3 of Allegation Investigation Repts 4-84-A-06/136 & 143 re Allegations A-250 & A-261 concerning Mercury Personnel changing mat heat numbers & welder identification numbers on QA documentation w/o proper justification.
* NRC - No Detailed Affiliation Given. 84/06/21. 6pp. 32976-036-32976-041.
- 8510010580** Rev 1 to Allegation Investigation Rept 4-84-A-06-178b of Allegation A-298 re inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/21. 6pp. 32976-184-32976-189.
- 8510010634** "Review of Waterford III Basement Analysis."
* Brookhaven National Laboratory. 84/06/21. 34pp. 32977-172-32977-205.
- 8510020085** Forwards addl info re installation of Chicago Bridge & Iron piece Numbers 55-2 welded to 55-4 & applicable attachments to Nonconformance Rept W3-6224.
DOBSON, D.E. Louisiana Power & Light Co. 84/06/21. STROSNIDER, J. Materials Engineering Branch. 152pp. 32979-086-32979-237.
- 8510020126** Allegation Investigation Repts 4-84-A-06-9, 39 & 49, Rev 0 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. 84/06/21. 3pp. 32978-332-32978-334.
- 8510020178** Allegation Investigation Repts 4-84-A-06-10 & 50, Rev 2 re Allegations A-115 & A-155 concerning deficiencies in tensile testing rates of cadweld splice when compared to Ebasco cadweld spec. No violation noted.
YANG, L. NRC - No Detailed Affiliation Given. 84/06/21. 5pp. 32981-143-32981-147.
- 8510020425** Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 6-18 & 4-84-A-31, Draft 4 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. 84/06/21. 13pp. 32983-214-32983-226.
- 8510020451** Draft 2 to Allegation Investigation Rept 4-84-A-06 re Allegation A-170 concerning improperly dispositioned Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. 84/06/21. 8pp. 32984-071-32984-078.

- 8510030174 Rev 1 to Allegation Investigation Rept 4-83-A-74-1 re Allegations A-13, A-14, A-15, A-16 & A-17 concerning identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. 84/06/21. 3pp. 32986:154-32986:156.
- 8510030320 Rev 1 to Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76 re Allegations A-283 & A-181 concerning Ebasco Svcs, Inc inadequate nonconformance reports. No potential violations noted.
WHITTEMORE, J. NRC - No Detailed Affiliation Given. 84/06/21. 8pp. 32987:036-32987:043.
- 8510030341 Rev 2 to Allegation Investigation Rept 4-84-A-06-142(3). No violations noted. Major area investigated: Allegation A-260 re lack of traceability of mats used in nonpressure retaining components in containment vessel. Rev 1 encl.
* NRC - No Detailed Affiliation Given. 84/06/21. 4pp. 32987:055-32987:058.
- 8510010567 Rev 1 to Allegation Investigation Repts 4-84-A-06-171 & 179 re Allegations A-290 & A-301 concerning inadequate corrective action documents & incorrectly made changes to QA records. Items potential ASME Code violation.
* NRC - No Detailed Affiliation Given. 84/06/22. 8pp. 32977:033-32977:040.
- 8510020099 Rev 1 to Allegation Investigation Rept 4-84-A-51-2. No violation noted. Major areas investigated: Allegation A-341 re alteration of deformed cable trays in order to install cable tray covers. Rev 0 encl.
* NRC - No Detailed Affiliation Given. 84/06/22. 13pp. 32979:298-32979:310.
- 8510020187 Rev 2 to Allegation Investigation Repts 4-84-A-40/1, 4-84-A-40/2 & 4-84-A-40/3. No violation noted. Major areas investigated: Allegations A-332, A-333 & A-334 re Design Change DCN-MP-920. Revs 1 & 0 encl.
* NRC - No Detailed Affiliation Given. 84/06/22. 9pp. 32981:188-32981:195.
- 8510020287 Rev 2 to Allegation Investigation Rept 4-84-A-06-135 re Allegation A-249 concerning Ebasco Svcs, Inc discrepancy notices falsified by subcontractors. No potential violations found. Marked-up Rev 2 encl.
FREED, B.L. NRC - No Detailed Affiliation Given. 84/06/22. 5pp. 32982:136-32982:140.
- 8510020321 Allegation Investigation Rept A-83-A-88-10, Rev 2 re Allegation A-58 concerning improper maint of permanent plant items by subcontractors, Ebasco Svcs Inc or util. No potential violations found.
JOHNSON, C., FARRELL, R. NRC - No Detailed Affiliation Given. 84/06/22. 10pp. 32982:249-32982:258.
- 8510020423 Allegation Investigation Rept 4-83-A-88-11, Rev 2 re Allegation A-59 concerning Ebasco Svcs Inc poor control over nonconforming conditions. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/06/22. 6pp. 32983:235-32983:240.
- 8510020476 Rev 2 to Allegation Investigation Rept 4-84-A-06-66 of Allegation A-171 re quality of Ebasco cadweld splicing. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/22. 13pp. 32984:262-32984:275.
- 8510020477 Marked-up Allegation Investigation Rept 4-84-A-06-65, Rev 0 re Allegation A-170 concerning improperly disposed Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. 84/06/22. 16pp. 32984:276-32984:292.
- 8510030060 Allegation Investigation Repts 4-83-A-88/Ac & Ad, Rev 2 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o knowledge of authorized nuclear inspector. No potential violations found.
FARREN, J. NRC - No Detailed Affiliation Given. 84/06/22. 7pp. 32985:089-32985:095.
- 8510030338 Rev 1 to Allegation Investigation Rept 4-84-A-06/145. No violation noted. Major area investigated: Allegation A-263 re refusal of Mercury const superintendent to correct problems identified in Internal Audit 12-1-82. Rev 0 dtd 840615 encl.
* NRC - No Detailed Affiliation Given. 84/06/22. 5pp. 32987:049-32987:054.
- 8510040363 Rev 2 to Allegation Investigation Rept 4-84-A-06-97 re Allegation A-209 concerning missed insps that could cause quality of installation to be in question.
* NRC - No Detailed Affiliation Given. 84/06/22. 6pp. 32987:337-32987:342.
- 8510040392 Rev 2 to Allegation Investigation Rept 4-84-A-06-97 re Allegation A-209 concerning re view of Mercury weld records identifying welds not fit-up or final-inspected.
* NRC - No Detailed Affiliation Given. 84/06/22. 2pp. 32988:019-32988:020.
- 8510040520 Allegation Investigation Rept 4-84-A-06-150, Rev 1 re Allegation A-268 concerning Ebasco Svcs, Inc not placing grout under base plates for instrument stands & tubing supports. No potential violations noted.
SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. 84/06/22. 5pp. 32988:206-32988:210.
- 8510010264 Rev 0 to Allegation Investigation Rept 4-84-A-06-181. No potential violations noted. Major area investigated: Allegation A-303a re documentation to verify compatibility backing rings & weld base mat.
SPAULDING, W. NRC - No Detailed Affiliation Given. 84/06/25. 4pp. 32976:274-32976:277.
- 8510010562 Marked-up Allegation Investigation Rept 4-84-A-06/181 Rev 0, re Allegation A-303a concerning Tompkins-Beckwith not providing documentation to verify that welding backing rings & base mat compatible. No potential violations noted.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. 84/06/25. 4pp. 32975:253-32975:256.
- 8510010609 Rev 3 to Allegation Investigation Repts 4-84-A-06/55 & 56 re Allegations A-160 & 161 concerning fabrication of support structures for instrumentation cabinets mounted on grating inside reactor containment bldg.
* NRC - No Detailed Affiliation Given. 84/06/25. 17pp. 32976:190-32976:203.
- 8510020028 Rev 1 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. 84/06/25. 4pp. 32978:248-32978:251.
- 8510020364 Rev 0 to Allegation Investigation Rept 4-84-A-06 for Allegations A-296, A-306a, A-306b, A-306c & A-306m re Tompkins-Beckwith failing to visually examine shop pipe welds for leaks. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/25. 4pp. 32983:044-32983:047.
- 8510020464 Allegation Investigation Rept 4-84-A-06-140c, Rev 3 re Allegation A-256 concerning Chicago Bridge & Iron Co problems w/protective coating & mat traceability for inside containment vessel.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. 84/06/25. 13pp. 32984:161-32984:173.
- 8510020503 Allegation Investigation Rept 4-84-A-06/152, Rev 2 re Allegation A-270 concerning Ebasco Svcs, Inc QC rept on Block 2 common foundation base mat. No potential violations noted.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/06/25. 3pp. 32985:034-32985:036.
- 8510030196 Marked-up Allegation Investigation Rept 4-84-A-06, Rev 0 re Allegation A-252 concerning Ebasco Svcs, Inc 830304 Interfc Ltr W3-QA-23661 as example of correspondence written to cover up problems in documentary review group.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/25. 3pp. 32986:125-32986:127.
- 8510030245 Allegation Investigation Rept 4-84-A-06, Rev 0 re Allegation A-252 concerning Ebasco Svcs, Inc 830301 Interfc Ltr W3-QA-23661 as example of correspondence written to cover up problems discovered in documentary review group.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/25. 3pp. 32986:146-32986:148.
- 8510040086 Rev 0 to Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184d & 184p re Allegations A-226, A-306b, A-306c & A-306p concerning traceability requirements of permanent attachment mat welded to Class 1 & 2 piping.
* NRC - No Detailed Affiliation Given. 84/06/25. 6pp. 32987:283-32987:288.
- 8510040107 Allegation Investigation Rept 4-84-A-06/170b, Rev 1 re Allegation A-289(b) concerning QA Sys 60 documentation inadequately reviewed due to unqualified Ebasco Svcs, Inc reviewers. No potential violations noted.
ROSS, D. NRC - No Detailed Affiliation Given. 84/06/25. 3pp. 32987:295-32987:297.
- 8510040109 Rev 1 to Allegation Investigation Repts A-84-A-06/117 & 184g re Allegations A-229 & A-306g concerning turnover of operational control records packages before sys review completed.
* NRC - No Detailed Affiliation Given. 84/06/25. 7pp. 32987:298-32987:305.
- 8510040370 Rev 3 to Allegation Investigation Rept 4-84-A-06/77 re Allegation A-182 concerning insp of welding performed on structural items such as pipe hangers or supports for HVAC sys.
* NRC - No Detailed Affiliation Given. 84/06/25. 11pp. 32988:001-32988:011.
- 8510040461 Allegation Investigation Rept 4-84-A-06/149, Rev 0 re Allegation A-267 concerning falsification of documents stating that Mercury nonsafety-related pipe hangers placed in safety-related areas. No violations noted.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/25. 6pp. 32988:130-32988:135.
- 8510010216 Rev 3 to Allegation Investigation Repts 4-84-A-06/186 & 4-84-A-06/184. No violations noted. Major areas investigated: Allegations A-308 & A-306f re inadequate piping sys documentation required to verify compliance w/ASME Code.
* NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32976:290-32976:293.
- 8510010274 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/1 re Allegation A-01, alleging that Mercury Const Co QA personnel employment records not verified. Rept findings: QA personnel certified w/o verifying previous employment.
* NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32976:247-32976:250.
- 8510010604 Allegation Investigation Repts 4-84-A-06/9, 39 & 49, Rev 1 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. 84/06/26. 3pp. 32977:078-32977:080.
- 8510020115 Allegation Investigation Repts 4-84-A-06-9, 39 & 49, Rev 1 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. 84/06/26. 3pp. 32979:344-32979:346.
- 8510020118 Marked-up Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167, Rev 1 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning listed Mercury Const Co mat traceability problems.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. 84/06/26. 3pp. 32980:007-32980:009.
- 8510020120 Rev 2 to Allegation Investigation Repts 4-84-A-06-33 & 4-84-A-06-54 re Allegations A-138 & A-159. Violation noted: validity of placement, compaction & insp of backfill mat questionable. Rev 1 & Draft 1 encl.
DEVERS, J.F. NRC - No Detailed Affiliation Given. 84/06/26. 37pp. 32980:010-32980:048.
- 8510020123 Rev 2 to Allegation Investigation Repts 4-84-A-06/41 & 4-84-A-06-52 re Allegations A-146 & A-157. Violations noted re Procedure W-SITP-4 & Reg Guide 1.10 guidelines. Rev 1, draft Revs 1 & 2 & Drafts 1 & 2 encl.
YANG, L. NRC - No Detailed Affiliation Given. 84/06/26. 26pp. 32980:087-32980:112.
- 8510020176 Marked-up Allegation Investigation Rept 4-84-A-06-11, Rev 1 re Allegation A-116 concerning unauthorized changes to JA Jones concrete placement records by unknown personnel. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/06/26. 3pp. 32981:130-32981:135.
- 8510020204 Rev 2 to Allegation Investigation Rept 4-84-A-51-1. No violation noted. Major areas investigated: Allegation A-340 re cable tray cleanliness. Revs 0 & 1 & Drafts 1, 2 & 3 encl.
* NRC - No Detailed Affiliation Given. 84/06/26. 33pp. 32981:226-32981:258.
- 8510020263 Commends RE Shewmaker effort during allegation investigations. RE Shewmaker demonstrated outstanding technical knowledge & mgt skills.
SHAO, L.C. Division of Engineering Technology. 84/06/26. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 32982:020-32982:020.
- 8510020282 Rev 2 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/26. 2pp. 32982:113-32982:119.

164 DOCKETED ITEMS

- 8510020312** Rev 0 to Allegation Investigation Repts 4-84-A-06/184u & 4-84-A-06/184z. No violations noted. Major areas investigated: Allegations A-306u & A-306z re control of measuring & test equipment. Drafts 2 & 3 encl.
FARREN, J. NRC - No Detailed Affiliation Given. 84/06/26. 11pp. 32982-205-32982-215.
- 8510020317** Rev 1 to Allegation Investigation Repts 4-84-A-06/177, 184a, 184k, 184l & 184m of Allegations A-296, A-306a, A-306k, A-306l, & A-306m re Thompsons-Beckwith failing to visually examine shop pipe welds for leaks. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32982-233-32982-236.
- 8510020331** Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12. Draft 4 re Allegations A-64 through 66 & 322 concerning unacceptable insp work activities, per Site Ltrs F6-3724E, F6-1895E & F6-1147E.
* NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32982-276-32982-279.
- 8510020332** Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12. Rev 3 re Allegations A-64-A-66 & A-322 concerning Ebasco Svcs, Inc site ltrs which imply Mercury insp activities unacceptable. Marked-up Rev 3 encl.
* NRC - No Detailed Affiliation Given. 84/06/26. 5pp. 32983-031-32983-035.
- 8510020418** Allegation Investigation Rept 4-83-A-88-4A. Rev 2 re Allegation A-94 through A-99 concerning problems w/stainless steel piping & tubing noted in unidentified 830909 nonconformance rept.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32983-205-32983-208.
- 8510020427** Allegation Investigation Rept 4-83-A-88-4A. Rev 2 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance rept addressing various problems w/stainless steel piping & tubing.
* NRC - No Detailed Affiliation Given. 84/06/26. 6pp. 32983-246-32983-251.
- 8510020454** Allegation Investigation Repts 4-84-A-06-139, 140a & 141. Rev 1 re Allegations A-253, A-254 & A-257 concerning unqualified vendor records reviews & bad vendor records, including Bergen-Patterson Pipe Support Co records.
NALEZNY, C.L. NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32984-079-32984-082.
- 8510020475** Rev 2 to Allegation Investigation Rept 4-84-A-06-40 re Allegation A-145. Violations noted: incorrect test locations on records cast doubt on validity of backfill insp. Draft 1 dtd 840717 & Draft 2 dtd 840718 encl.
DEVERS, J. NRC - No Detailed Affiliation Given. 84/06/26. 12pp. 32984-250-32984-261.
- 8510030165** Rev 1 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-18 & A-164 concerning inadequate nonconformance control by Ebasco Svcs, Inc where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. 84/06/26. 3pp. 32986-151-32986-153.
- 8510030351** Final Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167. Rev 1 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning Mercury Const Co traceability problems w/listed mats.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. 84/06/26. 4pp. 32987-067-32987-070.
- 8510010484** Marked-up Allegation Investigation Rept 4-84-A-06-4. Rev 1 re Allegation A-109 that Ebasco Svcs, Inc QA personnel stopped record reviewers when "wholesale" irregularities found in 7 of 1,200 concrete placement packages.
DEVERS, J.K., CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. 84/06/27. 4pp. 32977-021-32977-024.
- 8510010489** Final Allegation Investigation Rept 4-84-A-06-4. Rev 1 re Allegation A-109 that Ebasco Svcs, Inc QA personnel stopped record reviewers when "wholesale" irregularities found in 7 of 1,200 concrete placement packages.
DEVERS, J.K., CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. 84/06/27. 12pp. 32975-155-32975-166.
- 8510010507** Rev 2 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re unqualified Ebasco reviewers performing documentation reviews in short period.
* NRC - No Detailed Affiliation Given. 84/06/27. 3pp. 32975-170-32975-172.
- 8510010518** Allegation Investigation Repts 4-84-A-06/7, 26 & 151. Rev 1 re Allegations A-112, A-131 & A-269 concerning incomplete JA Jones Const Co concrete placement packages. Violation noted: failure to maintain concrete curing log.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/06/27. 5pp. 32977-053-32977-057.
- 8510010584** Final Allegation Investigation Repts 4-84-A-06/7, 26 & 151. Rev 1 re Allegations A-112, A-131 & A-269 concerning complete JA Jones Const Co concrete placement packages. Violation noted: failure to maintain concrete curing log.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/06/27. 5pp. 32975-296-32975-300.
- 8510020161** Marked-up Allegation Investigation Repts 4-84-A-06/5, 25 & 43. Rev 1 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. 84/06/27. 12pp. 32980-340-32980-351.
- 8510020184** Allegation Investigation Repts 4-84-A-06-10 & 50. Rev 3 re Allegations A-115 & A-155 concerning deficiencies in Cadweld spice, tensile testing rates as compared to Ebasco/Cadweld spec. No violation noted.
YANG, L. NRC - No Detailed Affiliation Given. 84/06/27. 3pp. 32981-150-32981-152.
- 8510020301** Marked-up Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143. Rev 0 re Allegations A-250 & A-261 concerning Mercury personnel changing matl heat numbers & welder identification numbers on QA documentation.
* NRC - No Detailed Affiliation Given. 84/06/27. 3pp. 32982-180-32982-182.
- 8510020316** Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184g & 184p. Draft 2 re Allegations A-226, A-306b, A-306f, A-306g & A-306p concerning safety-related sys designed as nonsafety-related.
* NRC - No Detailed Affiliation Given. 84/06/27. 1p. 32982-232-32982-232.
- 8510020346** Rev 0 to Allegation Investigation Rept 4-83-A-81/A1. Allegations A-20, A-21 & A-22 re recordkeeping problems including improper drawing changes, incorrect identification of heat codes & welds & improper dates for welds.
* NRC - No Detailed Affiliation Given. 84/06/27. 15pp. 32983-001-32983-015.
- 8510020347** Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172. Rev 0 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/06/27. 4pp. 32982-351-32982-354.
- 8510020398** Allegation Investigation Repts 4-84-A-06-21 & 172. Rev 0 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/06/27. 5pp. 32983-152-32983-156.
- 8510020401** Marked-up Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 6-18 & 4-84-A-31. Rev 0 re listed allegations concerning Mercury & Ebasco Svcs, Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. 84/06/27. 26pp. 32983-159-32983-184.
- 8510020417** Allegation Investigation Rept 4-83-A-88-13 re Allegation A-61 concerning NRC review of Ebasco Svcs, Inc Nonconformance Rept W3-4504. No potential violations found. Marked-up Rev 0 encl.
* NRC - No Detailed Affiliation Given. 84/06/27. 6pp. 32983-199-32983-204.
- 8510020449** Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157. Rev 0 re Allegations A-128d, A-212 & A-275 concerning undersized welds in Mercury Const Co work.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. 84/06/27. 4pp. 32984-067-32984-070.
- 8510020461** Allegation Investigation Rept 4-84-A-06/155. Draft 3 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted. Marked-up draft encl.
MARINI, W.S. NRC - No Detailed Affiliation Given. 84/06/27. 6pp. 32984-151-32984-156.
- 8510030098** Draft 3 of Allegation Investigation Rept 4-83-A-81-A4c re Allegation A-23C concerning Tompkins-Beckwith welding procedures & techniques used in ASME Code Class 1-3 piping sys inadequately installed. No potential violations noted.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/27. 5pp. 32985-103-32985-107.
- 8510030161** Allegation Investigation Repts 4-83-A-88 & 4-84-A-12. Rev 0 re Allegations A-18 through A-91 & A-315 concerning problems w/hydrostatic testing required by ASME Code for instrumentation & control tubing sys.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/06/27. 7pp. 32986-071-32986-077.
- 8510030376** Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157. Rev 0 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. 84/06/27. 4pp. 32987-114-32987-117.
- 8510040130** Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a. Rev 2 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability. No violations noted.
SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. 84/06/27. 5pp. 32987-314-32987-318.
- 8510040447** Marked-up Draft 2 to Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184g & 184p of Allegations A-226, A-306b, A-306f, A-306g & A-306p re nonsafety instrument air piping & tubings in reactor, auxiliary & fuel handling bldgs.
* NRC - No Detailed Affiliation Given. 84/06/27. 2pp. 32986-123-32986-124.
- 8407090263** Requests listed changes be made to Contract NRC-05-82-249, increasing work requirements & extending period of performance to 840706.
CRUTCHFIELD, D. Operating Reactors Branch 5 NRC-05-82-249. 84/06/28. BLAHA, J.L. Program Support & Analysis Staff. 2pp. 32975-085-32975-086.
- 8510010029** Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65/1 re Ebasco QA personnel use of speed ltrs instead of deficiency notes to identify problems on sys turnover documentation packages. QA Instruction 9 acceptable.
* NRC - No Detailed Affiliation Given. 84/06/28. 6pp. 32976-099-32976-103.
- 8510010206** Forwards NRR 840623 request to util re items resulting from task force review of SSEs. Items discussed at 840615 & 22 meetings w/util SSEs will be signed at future meeting.
SHEWMAKER, NRC - No Detailed Affiliation Given. 84/06/28. CHOKSHI, N., DEVERS, J., JOHNSON, C. NRC - No Detailed Affiliation Given. 1p. 32976-296-32976-313.
- 8510010541** Rev 2 to Allegation Investigation Rept 4-84-A-06-02 re Allegation A-107 concerning generation of false documents to replace missing cadweld activity records. No potential violations found.
DEVERS, J. NRC - No Detailed Affiliation Given. 84/06/28. 6pp. 32975-181-32975-186.
- 8510010547** Rev 1 to Allegation Investigation Rept 4-84-A-06-168 & 170a of Allegations A-286 & A-289a re falsification of heat numbers to demonstrate adequate traceability. No violations noted.
DEVERS, J. NRC - No Detailed Affiliation Given. 84/06/28. 3pp. 32977-018-32977-020.
- 8510020171** Allegation Investigation Rept 4-84-A-06-6. Rev 2 re Allegation A-111 concerning JA Jones personnel ignoring specs & procedures used as acceptance criteria for concrete work. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/06/28. 7pp. 32980-113-32980-119.
- 8510020495** Allegation Investigation Rept 4-84-A-06/158. Rev 3 re Allegation A-276 concerning Mercury Const Co resume fraud. Potential violations of 10CFR50, App B & ANSI N45.2.6 noted. Marked-up Rev 3 encl.
WESTBERG, R. NRC - No Detailed Affiliation Given. 84/06/28. 5pp. 32985-019-32985-023.
- 8510020500** Marked-up Allegation Investigation Rept 4-84-A-06/155. Rev 0 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted.
MARINI, W.S. NRC - No Detailed Affiliation Given. 84/06/28. 6pp. 32985-028-32985-033.

- 8510030141** Rev 0 to Allegation Investigation Repts 4-84-A-06/180,185, 184s & 184x for Allegations A-302,A-307,A-303b,A-306s & A-306x re lower tier corrective action document not upgraded to nonconformance repts.
* NRC - No Detailed Affiliation Given. 84/06/28. 14pp. 32986:020-32986:053.
- 8510040072** Discusses current Waterford 3 Task Force assignment & forthcoming Comanche Peak assignment. Training Ctr director duties to be assumed commensurate w/Comanche Peak assignment.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 84/06/28. GAGLIARDI,J.E. Technical Training Center (830103-850212). 3pp. 32987:277-32987:279.
- 8407090045** Discusses receipt of FOIA requests re work performed by Waterford team at facility. Press release dtd 840208 re obligations under FOIA encl.
CRUTCHFIELD,D. NRC - No Detailed Affiliation Given. 84/06/29. NRC - No Detailed Affiliation Given. 4pp. 32975:001-32975:004.
- 8510010559** Allegation Investigation Rept 4-84-A-06/181,Rev 1 re Allegation A-303a concerning Tompkins-Beckwith not providing documentation to verify that welding backing rings & weld base mat compatible. No potential violations noted.
SPAULDING,W.H. NRC - No Detailed Affiliation Given. 84/07/01. 6pp. 32975:247-32975:252.
- 8510020144** Rev 1 to Allegation Investigation Rept 4-84-A-06/142(3) re Allegation A-259. Violations noted: inability to produce QA records for welds in safety-related structures. Marked-up Rev 0 dtd 840622 & Draft 3 dtd 840621 encl.
* NRC - No Detailed Affiliation Given. 84/07/01. 34pp. 32980:255-32980:290.
- 8510020336** Allegation Investigation Rept 4-84-A-06,Rev 1 re Allegation A-252 that Ebasco Svcs, Inc Interfco Ltr W3-QA-23661 written to cover up problems in documentary review group. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/07/01. 7pp. 32982:290-32982:301.
- 8510020392** Marked-up Allegation Investigation Rept 4-84-A-06,Rev 1 re Allegation A-252 concerning Ebasco Svcs, Inc 830304 Ltr W3-QA-23661 as example of correspondence to cover up problems discovered in documentary review group.
* NRC - No Detailed Affiliation Given. 84/07/01. 3pp. 32983:142-32983:144.
- 8510020446** Rev 1 to Allegation Investigation Rept 4-84-A-06/36. No violations noted. Major areas investigated: Allegation A-141 re consideration of Ebasco discrepancy notices in QA review. Rev 0 dtd 840622 & Draft 4 dtd 840621 encl.
* NRC - No Detailed Affiliation Given. 84/07/01. 52pp. 32984:015-32984:066.
- 8510020459** Allegation Investigation Rept 4-84-A-06/155,Rev 1 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted.
MARINI,W.S. NRC - No Detailed Affiliation Given. 84/07/01. 5pp. 32984:124-32984:128.
- 8510020466** Rev 1 to Allegation Investigation Rept 4-84-A-06/181 re Allegation A-303a concerning Tompkins-Beckwith not providing documentation necessary to verify that welding backing rings & weld base mat compatible.
* NRC - No Detailed Affiliation Given. 84/07/01. 4pp. 32984:361-32985:003.
- 8510030147** Allegation Investigation Rept 4-84-A-06/155,Rev 1 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted.
MARINI,W.S. NRC - No Detailed Affiliation Given. 84/07/01. 3pp. 32986:054-32986:056.
- 8510040401** Rev 1 to Allegation Investigation Rept 4-84-A-06/99 re Allegation A-211 concerning Mercury Const Co program for maintaining identification of instrumentation tubing hangers & supports during rework.
* NRC - No Detailed Affiliation Given. 84/07/01. 40pp. 32988:025-32988:064.
- 8510040420** Allegation Investigation Rept 4-84-A-06/149,Rev 1 re Allegation A-267 concerning falsification of documents stating that Mercury nonsafety-related pipe hangers were placed in safety-related areas. No violations noted.
HUBBARD,R.W. NRC - No Detailed Affiliation Given. 84/07/01. 13pp. 32988:073-32988:087.
- 8510020483** Marked-up Allegation Investigation Rept 4-84-A-06-146 re Allegation A-264-1 concerning inability to provide accurate mat traceability on instrument tube track. No potential violation found.
* NRC - No Detailed Affiliation Given. 84/07/02. 1p. 32984:356-32984:357.
- 8510030201** Handwritten memo forwarding JM Cain (Louisiana Power & Light) 840628 response to NRC 840613 ltr re resolution of relicensing issues. Comments re util program plan for issue resolution due by 850706.
CRUTCHFIELD,D. NRC - No Detailed Affiliation Given. 84/07/02. HARRISON,J. Region 3, Office of Director. SHAO,L. THATCHER,D. NRC - No Detailed Affiliation Given. 1p. 32986:162-32986:267.
- 8510020132** Advises that written communications from GAP should be promptly provided to EDO for further action assignments & EDO should be advised if verbal communication received.
REHM,T.A. Office of the Executive Director for Operations. 84/07/03. DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. DENTON,H.R. Office of Nuclear Reactor Regulation. Director. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 32980:226-32980:228.
- 8510040064** Denies receiving pressure to alter results of Waterford 3 special review team insp conducted w/M Good per description in 840615 ltr & R Ridenhour 840602 "Gambit" article. Insp conducted per NRC procedures.
HAUGHNEY,C.J. Comex Corp. 84/07/07. EISENHUT,D.G. Division of Licensing. 2pp. 32987:272-32987:273.
- 8510010034** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65/1 re Ebasco QA personnel use of speed ltrs instead of deficiency notes to identify problems on sys turnover documentation packages. QA Instruction-9 acceptable.
* NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32976:104-32976:107.
- 8510010508** Allegation Investigation Repts 4-84-A-06/5,23 & 43,Rev 2 re Allegations A-110,A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6. "Qualification of Insp Exam & Testing Personnel..."
DEVERS,J.K. YANG,L. NRC - No Detailed Affiliation Given. 84/07/10. 5pp. 32975:211-32975:215.
- 8510010530** Rev 3 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re unqualified Ebasco reviewers performing documentation reviews in short period given. No violation noted.
* NRC - No Detailed Affiliation Given. 84/07/10. 6pp. 32975:175-32975:180.
- 8510010534** Rev 3 to Allegation Investigation Rept 4-84-A-06/153 of Allegation A-271 re improper consideration given to upgrading process & coating interior of containment vessel. Potential violation noted.
* NRC - No Detailed Affiliation Given. 84/07/10. 2pp. 32977:134-32977:135.
- 8510010545** Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 1 re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining mat traceability on supplemental steel. No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32975:240-32975:243.
- 8510020032** Rev 2 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32978:258-32978:261.
- 8510020038** Allegation Investigation Repts 4-84-A-06/177,184a,184k,184l & 184m, Draft 4 re Allegations A-296,A-306a,A-306k,A-306l & A-306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds.
* NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32978:270-32978:270.
- 8510020038** Allegation Investigation Repts 4-84-A-06/177,184a,184k,184l & 184m, Draft 4 re Allegations A-296,A-306a,A-306k,A-306l & A-306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds.
* NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32978:270-32978:272.
- 8510020038** Allegation Investigation Repts 4-84-A-06/177,184a,184k,184l & 184m, Draft 4 re Allegations A-296,A-306a,A-306k,A-306l & A-306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds.
* NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32978:270-32978:272.
- 8510020154** Allegation Investigation Repts 4-84-A-06/5,25 & 43,Rev 2 re Allegations A-110,A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Eagles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. 84/07/10. 2pp. 32980:327-32980:332.
- 8510020196** Rev 1 to Allegation Investigation Rept 4-84-A-476. No violations noted. Major areas investigated: Allegation A-337 re mercury instrumentation & control tube track welding. Rev 0 & Draft 2 encl.
* NRC - No Detailed Affiliation Given. 84/07/10. 26pp. 32981:200-32981:225.
- 8510020223** Rev 1 to Allegation Investigation Repts 4-84-A-52 & 4-84-A-88 re Allegations A-347,A-072,A-076 & A-077. Violations noted re Procedure PCP-2030 traceability requirements. Rev 0 encl.
* NRC - No Detailed Affiliation Given. 84/07/10. 20pp. 32981:326-32981:346.
- 8510020241** Allegation Investigation Repts 4-84-A-06/120,123,124,129, 130,131,144,4-84-A-12/3(a),(b),(c),6-18 & 4-84-A-31,Rev 0 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. 84/07/10. 44pp. 32982:035-32982:078.
- 8510020255** Rev 1 to Allegation Investigation Rept 4-83-A-88/2c,1,3A1 & 4-84-A-06/18 re Allegations A-49,A-78,A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. 84/07/10. 14pp. 32981:085-32981:098.
- 8510020342** Rev 2 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-18 & A-164 concerning inadequate nonconformance control by Ebasco Svcs Intl & six nonconformance repts w/o numbers.
* NRC - No Detailed Affiliation Given. 84/07/10. 2pp. 32982:322-32982:326.
- 8510020345** Rev 4 to Allegation Investigation Repts 4-84-A-06/186 & 4-84-A-06/184. No violations noted. Major areas investigated: Allegations A-306,A-306j & A-306r re inadequate piping sys documentation. Revs 2 & 3 encl.
WENCZEL,V. NRC - No Detailed Affiliation Given. 84/07/10. 20pp. 32982:331-32982:350.
- 8510020357** Draft 4 to Allegation Investigation Repts 4-84-A-06/177, 184a,184k,184l & 184m for Allegations A-296,A-306a,A-306k, A-306l & A-306m re Tompkins-Beckwith failing to visually examine shop pipe welds for leaks during hydrostatic tests.
* NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32983:027-32983:030.
- 8510020377** Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157,Rev 1 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING,W.H. NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32983:101-32983:104.
- 8510020386** Allegation Investigation Repts 4-84-A-06/23d,4-84-A-06/100 & 4-84-A-06/157,Rev 1 re Allegations A-128d,A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
* NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32983:127-32983:129.
- 8510020419** Allegation Investigation Rept 4-83-A-88/13a, Draft 2 re Allegation A-61a concerning NRC review of Ebasco Svcs, Inc Nonconformance Rept W3-4504.
SHAO NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32983:209-32983:211.
- 8510020421** Allegation Investigation Rept 4-83-A-88/13a, Rev 1 re Allegation A-61a concerning NRC review of Ebasco Svcs Inc Nonconformance Rept W3-4504 regarding repair of threads. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/07/10. 8pp. 32983:227-32983:234.
- 8510020432** Allegation Investigation Rept 4-83-A-88 & 4-84-A-12,Rev 1 re Allegations A-88,A-89,A-90,A-91 & A-315 concerning hydrostatic testing for instrumentation & control tubing sys installed by Mercury Const Co.
HUBBARD,R.W. NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32983:269-32983:272.
- 8510020466** Rev 1 to Allegation Investigation Repts 4-84-A-06/180, 185,181b & 184s of Allegations A-302,A-307,A-303b,A-306s & A-306x re lower tier corrective action documents not upgraded to nonconformance repts.
* NRC - No Detailed Affiliation Given. 84/07/10. 27pp. 32984:177-32984:203.

166 DOCKETED ITEMS

- 8510020492** Allegation Investigation Rept 4-84-A-06-65, Rev 1 re Allegation A-170 concerning improperly disposed Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg. No potential violations found.
KIM, S.B. NRC - No Detailed Affiliation Given. 84/07/10. 7pp. 32985:007-32985:013.
- 8510030183** Rev 3 to Allegation Investigation Repts 4-84-A-06/53 & A-84-A-06/154 re Allegations A-158 & A-272. Potential violation noted: missing or incomplete QA/QC documentation. Rev 2 & Drafts 1 & 2 encl.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. 84/07/10. 25pp. 32986:084-32986:108.
- 8510030299** Rev 3 to Allegation Investigation Rept 4-84-A-06-146. No violations noted. Major area investigated: Allegation A-264-1 re accurate matl traceability on instrument tube track.
MARINI, W.S. NRC - No Detailed Affiliation Given. 84/07/10. 3pp. 32987:031-32987:033.
- 8510030323** Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76, Rev 2 re Allegations A-283 & A-181 concerning Ebasco Svcs, Inc inadequate nonconformance repts. No potential violations noted. Marked-up Rev 2 encl.
WHITTEMORE, J. NRC - No Detailed Affiliation Given. 84/07/10. 5pp. 32987:044-32987:048.
- 8510030345** Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 1 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32987:059-32987:062.
- 8510030359** Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157, Rev 1 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. 84/07/10. 4pp. 32987:097-32987:100.
- 8510040024** Allegation Investigation Rept 4-84-A-06-65, Rev 1 re Allegation A-170 concerning improper disposition of Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. 84/07/10. 2pp. 32987:206-32987:216.
- 8510040477** Rev 1 to Allegation Investigation Repts 4-84-A-06/103, 109, 144, 126 & 184 re Allegations A-215, A-175, A-239, A-240 & A-306i concerning unqualified welders performing welding on safety-related sys.
* NRC - No Detailed Affiliation Given. 84/07/10. 56pp. 32988:136-32988:191.
- 8510010542** Marked-up Allegation Investigation Repts 4-84-A-06/21, 172, Rev 2, re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/07/11. 3pp. 32975:237-32975:239.
- 8510010581** Allegation Investigation Repts 4-84-A-06/177, 184a, 184k, 184l & 184m, Rev 2, re Allegations A-296, A-306a, 306k, 306l & 306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds for leaks.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. 84/07/11. 8pp. 32975:267-32975:274.
- 8510010598** Marked-up Allegation Investigation Repts A-84-A-06/8, 30 & 32 re Allegations A-113, A-135 & A-137 concerning need for review of concrete placement records, based on Ebasco Svcs, Inc 821209 memo.
* NRC - No Detailed Affiliation Given. 84/07/11. 1p. 32977:089-32977:089.
- 8510020098** Marked-up Allegation Investigation Rept 4-84-A-06/27, Rev 3 re Allegation A-132 concerning JA Jones Const Co use of speed ltrs to rept info that should be reported in deficiency notices & nonconformance repts.
* NRC - No Detailed Affiliation Given. 84/07/11. 4pp. 32979:265-32979:297.
- 8510020140** Rev 3 to Allegation Investigation Rept 4-84-A-06-142(1) re Allegation A-258. Violations noted: Ebasco failed to identify deviations from design bases in CBAI design documents re matl traceability. Marked-up Rev 2 dtd 840627 encl.
* NRC - No Detailed Affiliation Given. 84/07/11. 10pp. 32980:235-32980:244.
- 8510020210** Rev 2 to Allegation Investigation Rept 4-84-A-06-42 re Allegation A-147. Violations noted: fabrication of Caldwell test repts to replace lost records. Revs 1 & 0 & Drafts 4 & 2 encl.
* NRC - No Detailed Affiliation Given. 84/07/11. 40pp. 32981:263-32981:303.
- 8510020442** Rev 3 to Allegation Investigation Rept 4-84-A-06/184c. No violations noted. Major areas inspected: Allegation A-306c re lack of Ebasco documents for traceability of bolts 1-inch or less. Revs 1 & 2 encl.
SUMMERS, D. NRC - No Detailed Affiliation Given. 84/07/11. 12pp. 32983:327-32983:338.
- 8510030209** Rev 0 to Allegation Investigation Rept 4-83-A-81-A4c re Allegation A-23c concerning inadequate welding procedures & techniques used by Tompkins-Beckwith in ASME Code Classes 1, 2 & 3 piping sys in six specific areas.
* NRC - No Detailed Affiliation Given. 84/07/11. 5pp. 32986:268-32986:272.
- 8510030277** Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 2 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/07/11. 1p. 32987:001-32987:003.
- 8510020135** Handwritten Allegation Investigation Repts 4-84-A-06-5, 25 & 43 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. 84/07/12. 1p. 32980:234. * 980:234.
- 8510020174** Rev 3 to Allegation Investigation Repts 4-83-A-81/b, -83-A-88/2d, 4-84-A-88/2A1, 4-83-A-88/2A2, 4-83-A-88/2A3, 4-83-A-88/2A4, 4-84-A-06/16, 4-84-A-06/16, 4-84-A-06/23b, 4-84-A-06/163 & 4-84-A-51/7.
* NRC - No Detailed Affiliation Given. 84/07/12. 8pp. 32981:042-32981:049.
- 8510020436** Rev 2 to Allegation Investigation Rept 4-84-A-06-184i. No violations noted. Major areas inspected: Allegation A-306i re noncertified document reviewers making changes to QA documentation. Revs 0 & 1 & questions re items 14 & 15 encl.
ROSS, D. NRC - No Detailed Affiliation Given. 84/07/12. 18pp. 32983:277-32983:294.
- 8510020470** Marked-up Allegation Investigation Repts 4-83-A-81/A1, A2 & A3, Rev 1 re Allegations A-20, A-21 & A-22 concerning recordkeeping problems for Penetrations 38 & 65. No potential violations found.
* NRC - No Detailed Affiliation Given. 84/07/12. 10pp. 32984:222-32984:231.
- 8510030102** Rev 2 to Allegation Investigation Rept 4-83-A-81-A4a re Allegation A-23A concerning problems involving Fischbach & Moore installation, removal & rework of conduit fire seals for electrical penetrations. No potential violations noted.
THATCHER, D. NRC - No Detailed Affiliation Given. 84/07/12. 6pp. 32985:108-32985:113.
- 8510030266** Allegation Investigation Rept 4-84-A-06-24 re Allegation A-129 concerning installation, insp & acceptance of waterstop splicing activities performed by unqualified JA Jones Const Co personnel.
SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/12. 1p. 32986:351-32986:351.
- 8510030316** Allegation Investigation Repts 4-84-A-06/139 & 140a-141, Draft 2 re Allegations A-253, A-254 & A-257 concerning "heat treat" records of Berger-Patterson, Dreboth or Dravo & CB&I.
* NRC - No Detailed Affiliation Given. 84/07/12. 2pp. 32987:034-32987:035.
- 8510010582** Draft 6 to Allegation Investigation Repts 4-84-A-06/173, 174, 178, 60 & 61 re Allegations A-165, 166, 292, 293, 297, 298, 299 & 300 concerning vendor documentation possibly containing deficiencies not identified & corrected.
* NRC - No Detailed Affiliation Given. 84/07/13. 4pp. 32977:049-32977:052.
- 8510020092** Allegation Investigation Rept 4-84-A-06/24, Draft 2 re Allegation A-129 concerning JA Jones installation, insp & acceptance of waterstop splicing activities by unqualified personnel.
SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/13. 3pp. 32979:262-32979:264.
- 8510020134** Allegation Investigation Repts 4-84-A-06-10 & 50, Draft 2 re Allegations 115 & 155 concerning deficiencies in cadweld splice tensile testing rates as compared to Ebasco cadweld spec & inadequate closure of nonconformance rept.
SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/13. 3pp. 32980:133-32980:136.
- 8510020143** Allegation Investigation Repts 4-84-A-06-5, 25 & 43, Draft 2 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/13. 2pp. 32980:253-32980:254.
- 8510020473** Allegation investigation rept, Rev 2 re Allegation A-265 concerning altered data entries made on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. 84/07/13. 3pp. 32984:235-32984:237.
- 8510020478** Allegation Investigation Rept 4-84-A-06/147, Rev 3 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. 84/07/13. 3pp. 32984:293-32984:295.
- 8510020485** Allegation Investigation Rept 4-84-A-06/147, Rev 2 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W.S. NRC - No Detailed Affiliation Given. 84/07/13. 2pp. 32984:358-32984:360.
- 8510030272** Allegation Investigation Rept 4-84-A-06-24, Draft 2 re Allegation A-129 concerning JA Jones Const Co personnel performing installation, insp & acceptance of waterstop splicing activities w/o certification.
SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/13. 2pp. 32986:352-32986:353.
- 8510040378** Draft 3 to Allegation Investigation Rept 4-84-A-06-78(a) re Allegations A-183(a) & A-184 concerning Mercury documentation of generic deficiencies. Partial breakdown in QA program noted.
* NRC - No Detailed Affiliation Given. 84/07/13. 2pp. 32988:012-32988:013.
- 8510020430** Allegation Investigation Rept 4-84-A-06-128, Rev 2 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents. Violations found: hydrostatic tests not performed per 10CFR50, App B.
* NRC - No Detailed Affiliation Given. 84/07/16. 4pp. 32983:263-32983:266.
- 8510020463** Draft 1 to Allegation Investigation Rept 4-84-A-06-178b of Allegation A-298 re QC not checking structural items for defects.
* NRC - No Detailed Affiliation Given. 84/07/16. 4pp. 32984:157-32984:160.
- 8510030108** Rev 1 to Allegation Investigation Rept 4-83-A-81 (A4b) re Allegation A-23B concerning piping installation procedures of Tompkins-Beckwith not assuring that supports & hangers maintained in design-verified condition.
LENARDSON, J.D. NRC - No Detailed Affiliation Given. 84/07/16. 14pp. 32985:114-32985:127.
- 8510030170** Allegation Investigation Rept 4-84-A-06-128, Rev 2 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents & adequacy of instrument tubing installations. Potential violations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. 84/07/16. 5pp. 32986:079-32986:083.
- 8510010217** Marked-up Draft 7 of Allegation Investigation Rept 4-83-A-48/3 re Allegation A-03 concerning disclosure of exam answers before exam. Investigation in progress. Major areas to be investigated: Mercury certification program.
* NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32976:287-32976:289.
- 8510010515** Draft 7 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re inadequate indoctrination & training & QA reviewers not completing on-the-job training requirements. Approach to resolution listed.
* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32975:173-32975:174.
- 8510010526** Allegation Investigation Repts 4-84-A-06/7, 26 & 51, Draft 7 re Allegations A-112, A-131 & A-269 concerning incomplete JA Jones Const Co concrete placement packages. Allegation could impact assessment of concrete structure capability.
* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32975:149-32975:150.

8510010529 Draft 1 of introduction to SSER 7 re proposed operation of facility. Suppl provides results of evaluation of approx 350 allegations & concerns re poor const practices.

* NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32976:001-32976:003.

8510010599 Draft 1 to Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4 re Allegations A-57 & A-314 concerning lack of qualifications for Mercury Const Co Level III inspectors. Insp may have been performed by unqualified personnel.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32977:067-32977:068.

8510010599 Draft 1 to Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4 re Allegations A-57 & A-314 concerning lack of qualifications for Mercury Const Co Level III inspectors. Insp may have been performed by unqualified personnel.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32977:067-32977:068.

8510010627 Draft 5 to Allegation Investigation Rept 4-83-A-88/2a & 3 of Allegations A-47 & A-51 re coverup by Ebasco QA manager.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32977:220-32977:221.

8510020033 Allegation Investigation Repts 4-84-A-06/12 & 4-84-A-06/15, Draft 6 re Allegations A-117 & A-120 concerning falsification of documents. Validity of insps questionable. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32978:262-32978:264.

8510020060 Allegation Investigation Repts 4-84-A-06/8,30 & 32, Draft 1 re Allegations A-113, A-135 & A-137 concerning need for review of concrete placement records based Ebasco Svcs, Inc 821209 memo & problems noted in nonconformance repts.

* NRC - No Detailed Affiliation Given. 84/07/17. 6pp. 32978:308-32978:313.

8510020293 Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143, Draft 6 re Allegations A-250 & A-261 concerning falsification of documentation. HARRISON, J. Office of Investigation. 84/07/17. 2pp. 32982:150-32982:151.

8510020332 Marked-up Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4, Draft 1 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel. WESTBURG, R. NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32982:280-32982:282.

8510020338 Allegation Investigation Rept 4-84-A-12-4, Draft 7 re Allegation A-57 concerning Mercury Level III examiners lack of site certifications & Level III personnel.

* NRC - No Detailed Affiliation Given. 84/07/17. 4pp. 32982:302-32982:305.

8510020341 Allegation Investigation Repts 4-84-A-06/7,26 & 51, Draft 7 re Allegations A-112, A-131 & A-269 concerning incomplete JA Jones Const Co concrete placement packages & uncertified inspectors. SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32982:319-32982:321.

8510020426 Marked-up Draft 7 to Allegation Investigation Rept 4-83-A-65/2, Allegation A-06 re QA reviewers not completing on-the-job training requirements. Investigation in progress.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32983:244-32983:245.

8510020434 Allegation Investigation Rept 4-83-A-88/3A4, Draft 7 re Allegation A-92 concerning inadequate indoctrination & training of QA reviewers. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/17. 4pp. 32983:273-32983:276.

8510020471 Allegation Investigation Rept 4-84-A-06/152, Draft 1 re Allegation A-270 concerning Ebasco Svcs, Inc QC rept on Block 2 common foundation basement. SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32984:232-32984:234.

8510020480 Allegation Investigation Repts 4-84-A-06/76 & 4-84-A-06/165, Draft 5 re Allegations A-283 & A-181 concerning process of writing nonconformance repts. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32984:296-32984:298.

8510020494 Marked-up Drafts 6 & 7 to Allegation Investigation Rept 4-83-A-48/2, Allegations A-02, A-208 & A-274 re improper certification of inspectors. Investigation of Mercury certification program underway.

* NRC - No Detailed Affiliation Given. 84/07/17. 5pp. 32985:014-32985:018.

8510030159 Draft 7 to Allegation Investigation Rept 4-83-A-65/5, Allegation A-09 re replacement of laid-off QA personnel w/ non-QA engineers.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32986:149-32986:150.

8510030379 Allegation Investigation Rept 4-84-A-06/170b, Draft 7 re Allegation A-289b concerning improper Ebasco Svcs, Inc document reviews due to unqualified reviewers. Approach to resolution listed.

* NRC - No Detailed Affiliation Given. 84/07/17. 2pp. 32987:118-32987:119.

8510010211 Marked-up Draft 8 of Allegation Investigation Rept 4-83-A-48/3 re Allegation A-03 concerning disclosure of exam answers before exam. Investigation in progress. Major areas to be investigated: Mercury certification program.

* NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32976:294-32976:295.

8510010253 Marked-up Draft 8 of Allegation Investigation Repts 4-83-A-48/2, 4-84-A-06/96 & 4-84-A-06/156 re Allegations A-208, A-208 & A-274 concerning improper certification of inspectors.

* NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32976:245-32976:246.

8510010317 Draft 4 of Allegation Investigation Repts 4-83-A-65/04 & 4-84-A-06/78b re Allegations A-08 & A-183b concerning inadequate QA records sys & failure to store records in fire safe overnight.

* NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32976:226-32976:227.

8510010336 Marked-up Rept 1 to Allegation Investigation Repts 4-83-A-65/04 & 4-84-A-06/78b re Allegations A-08 & A-183b, alleging QA documents not stored in fire safes overnight & some records stored in old file cabinets.

* NRC - No Detailed Affiliation Given. 84/07/18. 3pp. 32976:231-32976:233.

8510010520 Draft 2 to Allegation Investigation Rept 4-84-A-06-1786 re Allegation 298 concerning inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. Approach to resolution listed.

* NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32975:319-32975:320.

8510020054 Allegation Investigation Repts 4-84-A-06/8,30 & 32, Draft 2 re Allegations A-113, A-135 & A-137 concerning need for review of concrete placement records based on Ebasco Svcs, Inc 821209 memo & problems noted in nonconformance repts. SHEWMAKER NRC - No Detailed Affiliation Given. 84/07/18. 3pp. 32978:285-32978:286.

8510020323 Draft 8 of Allegation Investigation Rept 4-83-A-81(B)/2 re Allegation A-28 on use of unqualified QC inspectors to perform insps. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/18. 6pp. 32982:243-32982:248.

8510020350 Allegation Investigation Rept 4-84-A-12-4, Draft 8 re Allegation A-57 concerning uncertified Mercury Level III examiners.

* NRC - No Detailed Affiliation Given. 84/07/18. 3pp. 32983:016-32983:018.

8510020356 Allegation Investigation Rept 4-84-A-12-4, Draft 9 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners. Marked-up Draft 9 encl.

* NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32982:361-32982:362.

8510020361 Marked-up Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4, Draft 2 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel. WESTBURG, R. NRC - No Detailed Affiliation Given. 84/07/18. 4pp. 32983:037-32983:040.

8510020367 Allegation Investigation Rept 4-84-A-12-4, Draft 10 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners. Marked-up Draft 10 encl. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/18. 4pp. 32983:051-32983:054.

8510020414 Rev 0 to Allegation Investigation Rept 4-83-A-81/A6 of Allegation A-25 re CS&I QA record deficiencies on containment penetration welds. No potential violations noted. TAPIA, J. NRC - No Detailed Affiliation Given. 84/07/18. 6pp. 32983:188-32983:193.

8510020429 Allegation Investigation Rept 4-84-A-06-128, Rev 3 re Allegation A-242 concerning hydrostatic tests performed w/o use of high point vents. Violation found: hydrostatic tests not performed per 10CFR50, App B.

* NRC - No Detailed Affiliation Given. 84/07/18. 9pp. 32983:254-32983:262.

8510020431 Allegation Investigation Rept 4-83-A-88/3A4, Draft 8 re Allegation A-92 concerning inadequate indoctrination & training of QA reviewers. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/18. 2pp. 32983:267-32983:268.

8510030078 Draft 2 of Allegation Investigation Rept 4-83-A-81/4B re Allegation A-23B concerning piping installation procedures of Tompkins-Bechwith not assuring supports & hangers maintained in design-verified condition.

SHAO, L. NRC - No Detailed Affiliation Given. 84/07/18. 4pp. 32985:099-32985:102.

8510030402 Marked-up Allegation Investigation Rept 4-84-A-06-128, Rev 3 re Allegation A-242 concerning hydrostatic tests performed w/o use of high point vents. Add concerns re adequacy of instrument tubing installations cited. FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. 84/07/18. 10pp. 32987:146-32987:155.

8510040491 Draft 8 to Allegation Investigation Repts 4-84-A-06/67 & 69 re Allegations A-172 & A-174 concerning possible falsification of T-B heat numbers.

* NRC - No Detailed Affiliation Given. 84/07/18. 11pp. 32989:263-32989:273.

8510040596 Allegation Investigation Rept 4-84-A-06/152, Draft 2 re Allegation A-270 concerning Ebasco Svcs, Inc inadequate nonconformance rept on Block 2 common foundation basement.

* NRC - No Detailed Affiliation Given. 84/07/18. 3pp. 32989:201-32989:203.

8510010290 Marked-up Rev 2 to Allegation Investigation Repts 4-83-A-65/04 & 4-84-A-06/78b re Allegations A-08 & A-183b, alleging that QA documents not stored in fire safes overnight & some records stored in old file cabinets.

* NRC - No Detailed Affiliation Given. 84/07/19. 3pp. 32976:228-32976:230.

8510010576 Allegation Investigation Repts 4-84-A-06/44/46/47/48, Rev 2, re Allegations A-149, A-151, A-152 & A-153 concerning four nonconformance repts signed by uncertified QC inspectors & lack of seismic Category I stairs insp repts. CROSSMAN, W. A. NRC - No Detailed Affiliation Given. 84/07/19. 5pp. 32975:262-32975:266.

8510020136 Draft 2 to Allegation Investigation Rept 4-84-A-06-34, No violations noted. Major areas investigated: Allegation A-139 re disposition of concrete cracks identified during Summer 1983 as shrinkage cracks.

* NRC - No Detailed Affiliation Given. 84/07/19. 20pp. 32980:137-32980:156.

8510020189 Rev 2 to Allegation Investigation Repts 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.

* NRC - No Detailed Affiliation Given. 84/07/19. 9pp. 32981:064-32981:072.

8510020276 Rev 3 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. No evidence of violation found during NRC review.

* NRC - No Detailed Affiliation Given. 84/07/19. 3pp. 32982:108-32982:110.

8510020366 Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4, Draft 3 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel. WESTBURG, R. NRC - No Detailed Affiliation Given. 84/07/19. 3pp. 32983:048-32983:050.

8510020428 Allegation Investigation Rept 4-84-A-12-4, Draft 11 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners. HARRISON, J. NRC - No Detailed Affiliation Given. 84/07/19. 2pp. 32983:252-32983:253.

168 DOCKETED ITEMS

- 8510020439** Rev 0 to Allegation Investigation Rept 4-84-A-06-184e. No violations noted. Major areas inspected: Allegation A-306e re deficiencies found during review of American Bridge documentation Drafts 1 & 2 encl. SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. 84/07/19. 32pp. 32983:295-32983:326.
- 8510020457** Allegation Investigation Rept 4-83-A-88-4A, Rev 3 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance rept addressing various problems w/ stainless steel piping & tubing. SUMMERS, D.L. NRC - No Detailed Affiliation Given. 84/07/19. 4pp. 32984:103-32984:109.
- 8510030176** Rev 2 to Allegation Investigation Repts 4-84-A-06/51, 4-84-A-06/1, 4-84-A-06/3 & 4-84-A-06/28 re Allegations A-156, A-106, A-108 & A-133. Potential violation noted: daily insp rept not signed per listed procedure. Drafts 4.5 & 6 encl. YANG, L. NRC - No Detailed Affiliation Given. 84/07/19. 18pp. 32987:009-32987:026.
- 8510030274** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/1, Allegation A-01 re unverified employment records for Mercury Const Co QA personnel. Past employment not verified. * NRC - No Detailed Affiliation Given. 84/07/19. 8pp. 32986:354-32986:361.
- 8510040424** Draft 3 to Allegation Investigation Repts 4-84-A-06/112 & 116 re Allegations A-224 & A-228 concerning individual providing info on Ebasco QA comments on MCP-2170-R/7. * NRC - No Detailed Affiliation Given. 84/07/19. 8pp. 32988:088-32988:095.
- 8510040529** Rev 0 to allegation investigation rept of Allegations A-224 & A-228 re concerns about "Hydrostatic or Pneumatic Testing Procedure" (MCP-2170), used to test plant instrumentation sys. No violation noted. * NRC - No Detailed Affiliation Given. 84/07/19. 5pp. 32988:230-32988:235.
- 8510010568** Allegation Investigation Repts 4-84-A-06/44/46/47/48 Rev 3, re Allegations A-149, A-151, A-152 & A-153 concerning four nonconformance repts signed by uncertified QC inspectors & lack of seismic Category I stairs insp repts. CROSSMAN, W.A. NRC - No Detailed Affiliation Given. 84/07/20. 5pp. 32975:257-32975:261.
- 8510020023** Rev 3 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents. * NRC - No Detailed Affiliation Given. 84/07/20. 3pp. 32978:208-32978:210.
- 8510020311** Draft 2 of Allegation Investigation Rept 4-83-A-87/4 re Allegation A-43 concerning improperly calibr instruments that invalidate acceptability of safety-related sys. No violation noted. * NRC - No Detailed Affiliation Given. 84/07/20. 4pp. 32982:201-32982:204.
- 8510010527** News release announcing planned commercial operation in First Quarter 1985 & Sept fuel loading. Const costs not expected to exceed present estimates. * Louisiana Power & Light Co. 84/07/25. 2pp. 32976:007-32976:030.
- 8510030127** Urges NRC to reject util 840628 proposed plan to correct problems found by NRC Special Review Team. Independent third party to conduct review of problems outlined in NRC 840613 ltr & development of plan to resolve issues requested. BERNABEI, L. Government Accountability Project. 84/07/25. EISENHUT, D.G. Division of Licensing. 12pp. 32985:128-32986:015.
- 8510020035** Rev 3 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-18 & A-164 concerning Ebasco Svcs Intl inadequate nonconformance control. Six nonconformance repts found w/o numbers. * NRC - No Detailed Affiliation Given. 84/07/26. 2pp. 32978:266-32978:267.
- 8510040454** Press release discussing GAP suggestion that NRC require independent review of util program to correct problems at facility. JOESCH, G. Government Accountability Project. 84/07/26. 3pp. 32988:125-32988:127.
- 8510040459** News article discussing GAP suggestion that NRC require independent review of util program to correct problems at facility. CUNNINGHAM, L. Times-Picayune, La Place, LA. 84/07/27. 2pp. 32988:128-32988:129.
- 8510010383** News article re util denial of GAP & Citizens for Safe Energy claim that util cannot be trusted to ensure safety of plant & that independent review needed. * Dallas Morning News, Dallas, TX. 84/07/28. 2pp. 32976:241-32976:242.
- 8510020487** Forwards exit interview notes from Insp Rept 50-382/84-34 on 840720. MORGAN, W.M. Louisiana Power & Light Co. 84/08/01. COLLINS, J.T., CROSSMAN, W.A., PERANICH, M. NRC - No Detailed Affiliation Given. 3pp. 32985:004-32985:006.
- 8510010511** Draft of Allegation Investigation Rept 4-84-A-06 re Allegation A-296 concerning contractor failure to examine shop pipe welds during hydrostatic tests. Potential ASME Code violation noted. * NRC - No Detailed Affiliation Given. 84/08/08. 3pp. 32975:146-32975:148.
- 8510010552** Rev 3 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 concerning Ebasco Svcs, Inc. Interfrc Ltr W3-QA-23661 written to cover up problems in documentary group & unresolved welding defects. No violations found. * NRC - No Detailed Affiliation Given. 84/08/08. 11pp. 32976:146-32976:156.
- 8510010553** Marked-up Allegation Investigation Rept 4-84-A-06, Rev 2 re Allegation A-252 concerning Ebasco Svcs, Inc. Interfrc Ltr W3-QA-23611 written to cover up problems in documentary group & unresolved welding deficiencies. SHAO, L. NRC - No Detailed Affiliation Given. 84/08/08. 4pp. 32975:151-32975:154.
- 8510010573** Allegation Investigation Rept 4-84-A-06, Draft 1 re Allegation A-252 concerning contractor preparing correspondence to cover up problems in documentary review group & unresolved welding deficiencies. * NRC - No Detailed Affiliation Given. 84/08/08. 6pp. 32975:288-32975:293.
- 8510020045** Expresses appreciation for R Westberg assistance during task force effort re allegations & assessment of quality of const. HARRISON, J.J. Division of Project & Resident Programs. 84/08/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32978:277-32978:277.
- 8510020049** Expresses appreciation for assistance of Div of Reactor Safety during task force review of allegations concerning quality of const. HARRISON, J.J. Division of Project & Resident Programs. 84/08/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32978:284-32978:284.
- 8510020075** Rev 2 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 that Ebasco Svcs, Inc. Interfrc Ltr W3-QA-23661 written to cover up problems in documentary group. No potential violations found. * NRC - No Detailed Affiliation Given. 84/08/08. 6pp. 32978:335-32978:340.
- 8510030153** Commends R Mullikin participation in Waterford 3 Task Force Inquiry Team from 840402-0702. Contribution as team leader for wk of 840520 & preparation of final rept appreciated. PERANICH, M.W. Waterford 3 Task Force. 84/08/08. COLLINS, J. Region 4, Office of Director. 1p. 32986:078-32986:078.
- 8510030354** Allegation Investigation Rept 4-84-A-06, Rev 2 re Allegation A-252 concerning Ebasco Svcs, Inc. 830304 & 22 Interfrc Ltrs W3-QA-23661 & W3QAIRG-0393 respectively. No potential violations noted. SHAO, L. NRC - No Detailed Affiliation Given. 84/08/08. 4pp. 32987:071-32987:096.
- 8510020445** Rev 4 to Allegation Investigation Rept 4-84-A-06-31. No violations noted. Major areas inspected: Allegation A-136 re difficulty for Ebasco QA personnel to initiate formal nonconformance rept. Draft & Revs 0, 1, 2 & 3 encl. * NRC - No Detailed Affiliation Given. 84/08/09. 36pp. 32983:339-32984:014.
- 8510030153** Forwards Waterford 3 Task Force Inquiry Team insp rept. Section VII of rept documents insp conducted by W Belke. Commends W Belke for outstanding effort. PERANICH, M.W. Waterford 3 Task Force. PERANICH, M.W. Reactor Construction Branch. 84/08/13. ANDRUM, G.T. QA Branch. 1p. 32986:057-32986:057.
- 8510010596** Rev 2 to Allegation Investigation Rept 4-84-A-06-1786 of Allegation A-298 re inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. Violations noted. * NRC - No Detailed Affiliation Given. 84/08/15. 5pp. 32977:100-32977:104.
- 8510020172** Allegation Investigation Rept 4-84-A-06-11, Rev 2 re Allegation A-116 concerning unauthorized changes to JA Jones concrete placement records by unknown personnel. No potential violations found. * NRC - No Detailed Affiliation Given. 84/08/15. 3pp. 32980:120-32980:122.
- 8510030160** Allegation Investigation Rept 4-84-A-06-128, Rev 4 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents. Addl concerns re adequacy of instrument tubing installations cited. FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. 84/08/15. 8pp. 32986:063-32986:070.
- 8510030397** Allegation Investigation Rept 4-84-A-06-128, Rev 4 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents. Addl concerns re adequacy of instrument tubing installations cited. FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. 84/08/15. 8pp. 32987:137-32987:145.
- 8510040343** Rev 4 to Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 concerning approx 850 for 2,000 purchase orders for adapters lacking heat code markings. * NRC - No Detailed Affiliation Given. 84/08/15. 13pp. 32987:322-32987:336.
- 8510040366** Rev 2 to Allegation Investigation Rept 4-84-A-06/72 re Allegation A-177 concerning Ebasco QA inspector exercising poor judgment & improperly dispositioning nonconformance repts on American Bridge Co steel const work. * NRC - No Detailed Affiliation Given. 84/08/15. 20pp. 32987:343-32987:362.
- 8510020262** Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 6-18 & 4-84-A-31, Rev 1 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components. * NRC - No Detailed Affiliation Given. 84/08/16. 8pp. 32982:089-32982:096.
- 8510030220** Agenda for 840817 meeting w/ Louisiana Power & Light to discuss prelicensing assessment issues. Info re role of Prelicensing Issues Task Force & NUS support group & handwritten, unidentified meeting summary encl. * NRC - No Detailed Affiliation Given. 84/08/17. NRC - No Detailed Affiliation Given. 78pp. 32986:273-32986:350.
- 8510010575** Rev 3 to Allegation Investigation Repts 4-84-A-06/60, 61, 173, 174 & 178 re Allegations A-165, 166, 292, 293, 297, 299 & 300 concerning activities of Ebasco vendor QA personnel & inadequacy of vendor QA records. * NRC - No Detailed Affiliation Given. 84/08/23. 17pp. 32976:167-32976:183.
- 8510020077** Rev 3 to Allegation Investigation Repts 4-84-A-06/182, 183 & 167 re Allegations A-304, A-305 & A-285b. Rev 1 dtd 850609, Rev 2 dtd 840615 & Draft 7 dtd 840717 encl. * NRC - No Detailed Affiliation Given. 84/08/23. 7pp. 32978:341-32978:347.
- 8510020295** Allegation Investigation Repts 4-84-A-06-12 & 4-84-A-06-15, Rev 2 re Allegations A-117 & A-120 that Mercury & Thompsons-Beckwith falsified records for compliance w/ federal safety regulations. * NRC - No Detailed Affiliation Given. 84/08/23. 3pp. 32982:152-32982:154.
- 8510020465** Allegation Investigation Rept 4-84-A-06/158, Rev 4 re Allegation A-276 concerning Mercury Const Co resume fraud. Violation of 10CFR50, App B & ANSI N45.2.6 noted. Staff reviewing NRC Ofc of Investigation rept. WESTBERG, R. NRC - No Detailed Affiliation Given. 84/08/23. 3pp. 32984:174-32984:176.
- 8510020481** Allegation Investigation Rept 4-83-A-88-4A, Rev 4 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance rept addressing various problems w/ stainless steel piping & tubing. * NRC - No Detailed Affiliation Given. 84/08/23. 3pp. 32984:299-32984:301.
- 8510020499** Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76, Rev 3 re Allegations A-283 & A-181 concerning Ebasco Svcs, Inc. inadequate nonconformance repts. No potential violations noted. WHITTEMORE, J. NRC - No Detailed Affiliation Given. 84/08/23. 4pp. 32985:024-32985:027.
- 8510040005** Rev 4 to Allegation Investigation Rept 4-84-A-06/175 on Allegation A-294 re unqualified personnel used by Ebasco to perform documentation reviews. Allegation has no implications. * NRC - No Detailed Affiliation Given. 84/08/23. 2pp. 32987:165-32987:166.

8510040027 Rev 4 to Allegation Investigation Repts 4-83-A-81/B7, 4-83-A-88/7,8,13,4-84-A-06/109,185v,185w,4-84-A-12/1,2,19 & 4-84-A-06 re Allegations A-33,A-55,A-56,A-61b,c,d & e,A-67, A-68,A-69,A-70,A-71,A-73,A-74,A-221,A-306 v&w,A-309 & A-310.
* NRC - No Detailed Affiliation Given. 84/08/23. 30pp. 32987:217-32987:264.

8510040382 Rev 2 to Allegation Investigation Rept 4-84-A-06/91 re Allegation A-196 concerning qualifications of Ebasco document control supervisor.
* NRC - No Detailed Affiliation Given. 84/08/23. 2pp. 32988:014-32988:015.

8510040385 Rev 2 to Allegation Investigation Rept 4-84-A-06/95 re Allegation A-207 concerning Mercury QA personnel throwing away original documents after copies made.
* NRC - No Detailed Affiliation Given. 84/08/23. 3pp. 32988:016-32988:018.

8510040410 Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a,Rev 3 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability.No violations noted.
SUMMERS,D., ROSS,D. NRC - No Detailed Affiliation Given. 84/08/23. 3pp. 32988:065-32988:067.

8510040483 Rev 3 to Allegation Investigation Rept 4-84-A-06/102 re Allegation A-214 concerning traceability of mats lost, causing validity of installed matl containing required certification to be questionable.
* NRC - No Detailed Affiliation Given. 84/08/23. 7pp. 32989:252-32989:259.

8510010018 Marked-up Allegation Investigation Rept 4-83-A-65/1, Rev 3 re Allegation A-05 concerning Ebasco Svcs,Inc QA personnel use of speed ltrs instead of deficiency notes for listed deficiencies.
* NRC - No Detailed Affiliation Given. 84/08/24. 4pp. 32977:025-32977:028.

8510020149 Allegation Investigation Repts 4-83-A-88,4-84-A-06/21,22, 23a & c & 167,Rev 2 re Allegations A-100,A-101,A-102,A-103, A-127,A-128a,A-128c & A-285a concerning listed Mercury Const Co matl traceability problems.
SUMMERS,D.L. NRC - No Detailed Affiliation Given. 84/08/24. 4pp. 32980:162-32980:165.

8510020258 Rev 3 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59,Allegations A-18 & A-19 re inadequate nonconformance control by Ebasco Svcs Inc where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. 84/08/24. 3pp. 32982:016-32982:017.

8510020272 Rev 4 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/08/24. 5pp. 32982:103-32982:107.

8510020327 Marked-up Revs 3 & 4 to Allegation Investigation Rept 4-83-A-65/3,Allegations A-07 & A-29 re Ebasco QA reviewers grooming paperwork.Ore possible falsification of signature observed.Records review sys adequate.
* NRC - No Detailed Affiliation Given. 84/08/24. 4pp. 32982:270-32982:273.

8510020349 Allegation Investigation Repts 4-83-A-88/Ac & Ad,Rev 3 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o knowledge of authorized nuclear inspector.No potential violations found.
FARREN,J. NRC - No Detailed Affiliation Given. 84/08/24. 6pp. 32982:355-32982:360.

8510020400 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65/6,Allegation A-09 re contracted QA personnel layoffs & Ebasco engineers moving into QA positions. Reviewers laid off for financial reasons.
* NRC - No Detailed Affiliation Given. 84/08/24. 2pp. 32983:157-32983:158.

8510020416 Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12,Rev 4 re Allegations A-64 through A-66 & A-322 concerning Ebasco site ltrs which imply that Mercury insp activities unacceptable.
MORGAN,T. NRC - No Detailed Affiliation Given. 84/08/24. 3pp. 32983:196-32983:198.

8510020420 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65, Allegation A-06 re Ebasco QA reviewers not completing on-the-job training requirements.Ebasco QA training program adequate.
* NRC - No Detailed Affiliation Given. 84/08/24. 2pp. 32983:212-32983:213.

8510030361 Rev 2 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13,A-14,A-15,A-16 & A-17 re identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. 84/08/24. 3pp. 32987:101-32987:103.

8510040417 Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a,Rev 4 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability.
SUMMERS,D., ROSS,D. NRC - No Detailed Affiliation Given. 84/08/28. 5pp. 32988:068-32988:072.

8510010513 Marked-up Allegation Investigation Repts 4-84-A-06/5,25 & 43,Rev 3 re Allegations A-110,A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6, "Qualification of Insp.Exam & Testing Personnel..."
DEVERS,J.K., YANG,L. NRC - No Detailed Affiliation Given. 84/08/29. 8pp. 32977:216-32977:223.

8510010549 Allegation Investigation Repts 4-84-A-06/21 & 172,Rev 3 re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining matl traceability on supplemental steel used w/pipe hangers & supports.No potential violations noted.
* NRC - No Detailed Affiliation Given. 84/08/29. 3pp. 32975:244-32975:246.

8510010571 Rev 2 to Allegation Investigation Rept 4-84-A-06-63 re Allegation A-168 concerning poor QC by American Bndge resulting in lack of traceability of 2,300 lb of nonsafety weld rod.No safety significance re allegation.
* NRC - No Detailed Affiliation Given. 84/08/29. 3pp. 32977:041-32977:043.

8510010630 Rev 1 to Allegation Investigation Rept 4-83-A-87/4 of Allegation A-43 re improper calibr & humidity & temp control in Magnaflex Co test lab.No potential violations noted.
WESTBERG,R. NRC - No Detailed Affiliation Given. 84/08/29. 4pp. 32977:216-32977:219.

8510020125 Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 3 re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining matl traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. 84/08/29. 2pp. 32980:212-32980:217.

8510020183 Rev 3 to Allegation Investigation Repts 4-83-A-88/2c,1,3A1 & 4-84-A-06/18 re Allegations A-49,A-78,A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. 84/08/29. 7pp. 32981:057-32981:063.

8510020375 Allegation Investigation Repts 4-84-A-06/23d,4-4-A-06/100 & 4-84-A-06/157,Rev 2 re Allegations A-128d,A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
* NRC - No Detailed Affiliation Given. 84/08/29. 2pp. 32983:199-32983:100.

8510020482 Rev 4 to Allegation Investigation Repts 4-84-A-06-34 & 4-84-A-06-35.No violations noted.Major areas investigated: Allegations A-139 & A-140 re poor concrete placement practices during const.Revs 2 & 3 & Drafts 1,2 & 3 encl.
* NRC - No Detailed Affiliation Given. 84/08/29. 54pp. 32984:302-32984:355.

8510030136 Allegation Investigation Rept 4-84-A-06-66,Rev 3 re Allegation A-171 concerning Ebasco Svcs,Inc practice of using oversize cadweld sleeves to make cadweld splices.
* NRC - No Detailed Affiliation Given. 84/08/29. 4pp. 32986:016-32986:019.

8510030297 Allegation Investigation Rept 4-84-A-06/149,Rev 2 re Allegation A-267 concerning Mercury nonsafety-related pipe hangers placed in safety-related areas which resulted in falsified documentation.
* NRC - No Detailed Affiliation Given. 84/08/29. 4pp. 32987:027-32987:030.

8510040305 Rev 2 to Allegation Investigation Repts 4-84-A-06/114,184b, 184f,184c & 184p re Allegations A-226,A-306f,A-306e & A-306p on traceability requirements of matl welded to Class 1 & 2 piping pressure boundaries by Tompkins-Beckwith.
* NRC - No Detailed Affiliation Given. 84/08/29. 33pp. 32989:206-32989:238.

8510040326 Rev 1 to Allegation Investigation Rept 4-83-A-86/1 re Allegation A-36 concerning improperly calibr torque wrench utilized by Gulf Engineering for work on emergency diesel generator.
* NRC - No Detailed Affiliation Given. 84/08/29. 13pp. 32989:239-32989:251.

8510040437 Rev 3 to Allegation Investigation Rept 4-84-A-06/11 of Allegation A-223 re documentation discrepancies between field const & QC packages & missing test repts on operational control records.
* NRC - No Detailed Affiliation Given. 84/08/29. 4pp. 32988:115-32988:118.

8510040500 Rev 2 to Allegation Investigation Rept 4-83-A-81/A1 re Allegations A-20,A-21 & A-22 concerning recordkeeping problems w/Penetrations 38 (A-20) & 65 (A-21 & 22) & recordkeeping problems w/eight other penetrations.
* NRC - No Detailed Affiliation Given. 84/08/29. 13pp. 32989:274-32989:286.

8510070083 Allegation Investigation Rept 4-84-A-06-65,Rev 2 re Allegation A-170,concerning improper disposition of missing Ebasco Svcs,Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM,S.B. NRC - No Detailed Affiliation Given. 84/08/29. 7pp. 32990:299-32990:308.

8510010480 Allegation Investigation Repts 4-84-A-06/5,25 & 43,Rev 4 re Allegations A-110,A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6, "Qualification of Insp.Exam & Testing Personnel..."
DEVERS,J.K., YANG,L. NRC - No Detailed Affiliation Given. 84/08/30. 6pp. 32977:008-32977:013.

8510010555 Rev 4 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 concerning Ebasco Svcs,Inc Interloc Ltr W3-QA-23661 written to cover up problems in documentary group.No potential violations found.
* NRC - No Detailed Affiliation Given. 84/08/30. 2pp. 32976:157-32976:158.

8510020127 Allegation Investigation Rept 4-84-A-06/27,Rev 4 re Allegation A-132 concerning JA Jones Const Co use of speed ltrs to rept info that should be reported in deficiency notices & nonconformance repts.
* NRC - No Detailed Affiliation Given. 84/08/30. 3pp. 32980:218-32980:220.

8510020180 Rev 3 to Allegation Investigation Repts 4-84-A-06/120,122, 124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13, 14,15,16,17,18 & 4-84-A-31,including Allegations A-232, A-234,A-237,A-238,A-243,A-244,A-245,A-262 & A-311.
* NRC - No Detailed Affiliation Given. 84/08/30. 9pp. 32981:179-32981:187.

8510020469 Allegation Investigation Rept 4-84-A-06-128,Rev 5 re Allegation A-242 concerning hydrostatic tests performed w/o use of highpoint vents.Addl concerns re adequacy of instrument tubing installations cited.
FORD,D., THATCHER,D. NRC - No Detailed Affiliation Given. 84/08/30. 9pp. 32984:213-32984:221.

8510030264 Allegation Investigation Rept 4-84-A-06/24,Rev 2 re Allegation A-129 concerning installation,insp & acceptance of waterstop splicing activities by uncertified JA Jones Const Co personnel.
* NRC - No Detailed Affiliation Given. 84/08/30. 3pp. 32986:080-32986:062.

8510040388 Rev 2 to Allegation Investigation Repts 4-84-A-06/120,123, 124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13, 14,15,16,17 & 18,including Allegations A-232,A-234,A-237, A-238,A-243,A-244,A-245,A-262,A-311,A-312,A-313 & A-316.
* NRC - No Detailed Affiliation Given. 84/08/30. 13pp. 32988:192-32988:205.

8510040440 Rev 3 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern on piping supports not in compliance w/Reg Guide 1.29.No violations noted.
* NRC - No Detailed Affiliation Given. 84/08/30. 4pp. 32988:119-32988:122.

8510040486 Rev 4 to Allegation Investigation Rept 4-84-A-06/11 re Allegation A-223 concerning incomplete,missing & conflicting documentation that raised question re quality of installation & insp results.
* NRC - No Detailed Affiliation Given. 84/08/30. 3pp. 32989:260-32989:262.

8510010577 Allegation Investigation Rept 4-84-A-06-37 of Allegation A-142 re alleged statement on several occasions that nonconformance rept initiated had been in adequately dispositioned.
* NRC - No Detailed Affiliation Given. 84/09/04. 2pp. 32977:170-32977:171.

170 DOCKETED ITEMS

- 8510010594** Rev 1 to Allegation Investigation Rept 4-84-A-06-64 re Allegation A-169 concerning Ebasco engineer closing out nonconformance report on work done by American Bridge on steel beam connections w/o sufficient technical justification.
* NRC - No Detailed Affiliation Given. 84/09/04. 1p. 32977:114-32977:114.
- 8510010605** Rev 1 to Allegation Investigation Rept 4-84-A-06-72 re Allegation A-177 concerning Ebasco QA inspector exercising improper judgment & dispositioning nonconformance reports dishonestly for American Bridge Company steel const work.
* NRC - No Detailed Affiliation Given. 84/09/04. 1p. 32976:223-32976:223.
- 8510010614** Rev 4 to Allegation Investigation Rept 4-84-A-06-31 re Allegation A-136 concerning difficulty of Ebasco QA personnel to get approval to initiate formal nonconformance report in civil-structural area between 1975 & 1977.
* NRC - No Detailed Affiliation Given. 84/09/04. 2pp. 32977:229-32977:230.
- 8510010620** Rev 2 to Allegation Investigation Rept 4-84-A-06-65 re Allegation A-170 concerning Ebasco discrepancy notice not properly dispositioned for missing reinforcement steel in fuel handling bldg.
* NRC - No Detailed Affiliation Given. 84/09/04. 2pp. 32977:224-32977:225.
- 8510040119** Rev 1 to Allegation Investigation Rept 4-84-A-06/115 re Allegation A-227 concerning sys for identifying & dispositioning nonconformances for seismic Category 1 supports written by Ebasco worker & rejected by Ebasco mgt.
FREED,B. NRC - No Detailed Affiliation Given. 84/09/13. 7pp. 32987:306-32987:313.
- 8510010499** Marked-up portion of allegation investigation report re Allegation A-109 that Ebasco Svcs, Inc QA personnel stopped record reviewers when "wholesale" irregularities found. Specific packages not identified by 840525. Page superseded.
CHOKSHI,N.C., SHEWMAKER,R.E. NRC - No Detailed Affiliation Given. 84/09/19. 2pp. 32975:167-32975:168.
- 8510020215** Marked-up draft preliminary review of util 840929 response re QA program.
* NRC - No Detailed Affiliation Given. 84/09/29. 14pp. 32981:304-32981:319.
- 8510010611** Marked-up SSER 7 re results of NRC evaluation of 350 allegations & concerns of poor const practices.
* Office of Nuclear Reactor Regulation, Director. * Region 4, Office of Director. 84/09/30. 300pp. 32977:231-32978:161.
- 8510010500** Requests all pertinent agency records be included in package to be made publicly available by 841016 per SSER 7.
CRUTCHFIELD,D. NRC - No Detailed Affiliation Given. 84/10/05. NRC - No Detailed Affiliation Given. 5pp. 32977:002-32977:003.
- 8510040586** Requests statement explaining unauthorized procurement commitment & action taken to prevent recurrence. D Crutchfield response re svcs & equipment procured to support Waterford 3 Task Force encl.
HEWTON,J.H. Division of Contracts. 84/10/09. LAZO,L. NRC - No Detailed Affiliation Given. 4pp. 32988:236-32989:200.
- 8510010504** Discusses review of 840913 note re addl or identical allegations. Fifteen alleged items in mechanical & piping review area & status of items being addressed in SSERs listed.
HOU,S. NRC - No Detailed Affiliation Given. 84/10/11. GAGLIARDO,J.E. NRC - No Detailed Affiliation Given. 3pp. 32975:275-32975:277.
- 8510020164** Draft 3 of Allegation Investigation Rept 4-84-A-06-5 re Allegations A-110, A-130 & A-148 concerning some inspectors not meeting all requirements of ANSI N45.2.6, "Qualification of Insp, Exam & Testing Personnel."
* NRC - No Detailed Affiliation Given. 85/06/09. 9pp. 32981:153-32981:161.
- 8510020261** Draft 3 of Allegation Investigation Rept 4-84-A-06/5 re Allegations A-110, A-130 & A-148 concerning ANSI N45.2.6, "Qualification of Insp, Exam & Testing Personnel." Violation noted: contractors failed to review QA program.
* NRC - No Detailed Affiliation Given. 85/06/09. 9pp. 32982:079-32982:088.
- 8510020371** Resume of AN Fasano.
FASANO,A.N. TMI Program Office. 85/09/27. 12pp. 32983:067-32983:078.
- 8510010579** Allegation Investigation Rept 4-84-A-06, Draft 1 re Allegation A-296 concerning contractor failure to visually examine shop pipe welds during hydrostatic tests. Potential ASME Code violation noted.
* NRC - No Detailed Affiliation Given. 85/10/01. 2pp. 32975:294-32975:295.
- 8510020373** Resume of RA Feil.
FEIL,R.A. Affiliation Not Assigned. 85/10/01. 6pp. 32983:055-32983:060.
- 8510020393** Resume of CC Wilson.
WILSON,C.C. Louisiana, State of. 85/10/01. 1p. 32983:145-32983:145.
- 8510020394** Resume of WG Hubacek.
HUBACEK,W.G. Affiliation Not Assigned. 85/10/01. 3pp. 32983:146-32983:148.
- 8510020396** Resume of JD Firestone.
FIRESTONE,J.D. Martin Marietta Corp. 85/10/01. 3pp. 32983:149-32983:151.
- 8510030029** Resume of MP Mills.
MILLS,M.P. Affiliation Not Assigned. 85/10/01. 3pp. 32985:066-32985:069.
- 8510030036** Resume of KM Vadamani.
VADAMANI,K.M. Volt Technical Services. 85/10/01. 12pp. 32985:070-32985:081.
- 8510030042** Resume of WS Schum.
SCHUM,W.S. Region 4, Office of Director. 85/10/01. 4pp. 32985:082-32985:085.
- 8510040396** Resume of WM Kemp.
KEMP,W.M. Thero Special Services, Inc. 85/10/01. 4pp. 32988:021-32988:024.
- F. Security, medical, emergency & fire protection plans**
- 8510010283** Responds to FOIA request for background records of all insp repts on facility since Dec 1982 per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABE,L. Government Accountability Project. 32pp. 32884:005-32884:234.
- 8406150267** Requests that encl FEMA 840511 supplemental interim finding report on offsite plans be transmitted to util. Rept addresses four offsite planning issues specified by ASLB.
MATTHEWS,D.B. Emergency Preparedness Branch. 84/06/07. KNIGHTON,G.W. Licensing Branch 3. 3pp. 32893:319-32893:321.
- 8408210595** Forwards RW Knmm 840725 ltr forwarding report on 840208 exercise of offsite radiological emergency preparedness plans for facility Category B deficiencies identified.
MATTHEWS,D.B. Emergency Preparedness Branch. 84/08/16. BANGART,R.L. Region 4, Office of Director. 2pp. 32893:322-32893:323.
- 8510010287** Lesson Plan W3G-001-002MH-003, "General Employee Training, Station Security Plan." Related info encl.
HURSHMAN,M., LEC,T,J.J. Louisiana Power & Light Co. 84/03/02. 50pp. 32885:239-32886:107.
- 8510010326** Audit on 830119-0304 of environ monitoring program. Audit checklist for health physics program & related documentation encl.
ROBERTS,A.R., MORGAN,W.M. Louisiana Power & Light Co. 83/03/24. 169pp. 32884:037-32884:204.
- 8510010333** Vol XIII to "Plant Operating Manual," "Health Physics Procedures."
* Louisiana Power & Light Co. 83/11/21. 15pp. 32884:205-32884:222.
- 8510010343** Rev 0 to Nuclear Administrative Procedure NAP-220, "Radiation Control Section Overview." WM Morgan 840828 interofc memo re NRC review of radiation protection, Radwaste Program Insp 84-38 on 840820-24 encl.
* Louisiana Power & Light Co. 83/01/05. 8pp. 32884:223-32884:230.
- 8510010375** Forwards input from Physical Security Section for 1982-1983 facility SALP report. Related info, including Westinghouse maint manual, encl.
KELLY,J.A. Region 4, Office of Director. 83/08/29. CONSTABLE,L. Region 4, Office of Director. 150pp. 32893:153-32893:301.
- 8510010384** Advises that util has scheduled emergency exercise for score on 850208 w/ State of LA, St Charles Parish & St John the Baptist Parish. Matis will be submitted for review.
COOK,K.W. Louisiana Power & Light Co. 83/11/09. COLLINS,J.T. Region 4, Office of Director. 1p. 32893:302-32893:302.
- 8510010392** Forwards facility emergency preparedness exercise summary for review. Exercise scheduled on 830525 W/o encl.
MAURIN,L.V. Louisiana Power & Light Co. 83/04/15. COLLINS,J.T. Region 4, Office of Director. 1p. 32893:303-32893:303.
- 8510010396** Forwards facility full-scale emergency preparedness exercise objectives for review. Exercise scheduled for 830413. W/o encl.
MAURIN,L.V. Louisiana Power & Light Co. 83/02/25. COLLINS,J.T. Region 4, Office of Director. 1p. 32893:304-32893:304.
- 8510010399** Forwards description of objectives & summary of events for facility full-scale emergency preparedness exercise scheduled on 830413. W/o encl.
MAURIN,L.V. Louisiana Power & Light Co. 83/01/26. COLLINS,J.T. Region 4, Office of Director. 2pp. 32893:305-32893:318.
- 8510010423** Advises that transportation support ltrs of agreement should be withheld from public due to proprietary nature, per 10CFR2.790. FEMA 840622 memo re supplemental findings encl.
COOK,K.W. Louisiana Power & Light Co. 84/08/01. KNIGHTON,G.W. Licensing Branch 3. 4pp. 32893:324-32893:327.
- 8510010435** "Waterford 3 Steam Electric Station 1983 Annual Emergency Preparedness Exercise."
* Louisiana Power & Light Co. 83/12/31. 43pp. 32894:004-32894:052.
- 8510010442** Forwards public version of changes to facility emergency plan & procedures. Revs will be completed by 840504.
LEDDICK,R.S. Louisiana Power & Light Co. 84/02/21. Office of Nuclear Reactor Regulation, Director. 1p. 32894:053-32894:053.
- 8510010444** Public version of changes to "Waterford 3 Emergency Plan."
* Louisiana Power & Light Co. 84/02/21. 77pp. 32894:054-32894:131.
- 8510010447** Responds to Emergency Preparedness Followup Appraisal Rept 50-382/84-02. Table 5-1 of emergency plan revised re augmentation capability for supporting onshift organization, per NRC 840329 ltr.
LEDDICK,R.S. Louisiana Power & Light Co. 84/04/25. JOHNSON,E.H. Region 4, Office of Director. 25pp. 32894:283-32894:307.
- 8510010448** Informs that report of Waterford emergency exercise will not be submitted due to cancellation of exercise.
HICKEY,E.E. Battelle Memorial Institute, Pacific Northwest Laboratories. 83/06/01. HACKNEY,C.A. Region 4, Office of Director. 1p. 32894:308-32894:308.
- 8510010449** Public version of changes to emergency plan implementing procedures, including Rev 3 to EP-1-010, "Unusual Event," Rev 3 to EP-1-020, "Alert," Rev 3 to EP-1-030, "Site Area Emergency" & Rev 3 to EP-1-040, "General Emergency."
* Louisiana Power & Light Co. 84/02/21. 37pp. 32894:132-32894:173.
- 8510010454** Confirms 830406 telcon re requested one wk extension of deadline for submission of Waterford exercise scenario.
COLLINS,S.C. Louisiana, State of. 83/04/12. HACKNEY,C. Region 4, Office of Director. 75pp. 32894:318-32895:123.
- 8510010457** Forwards Safety Insp Rept 50-382/84-20. Areas examined include implementation of fire protection program & compliance w/ 10CFR50, App R. Listed open items referred to NRR for resolution. Meeting requested.
COLLINS,J.T. Region 4, Office of Director. 84/07/13. VOLLMER,R.H. Division of Engineering. 21pp. 32895:035-32895:055.
- 8510240369** Forwards objectives for emergency preparedness exercise scheduled for 850918.
COOK,K.W. Louisiana Power & Light Co. 85/07/01. MARTIN,R.D. Region 4, Office of Director. 4pp. 33151:359-33151:362.

8510250427 Forwards emergency planning annual exercise package.RMS,SPDS & qualified SPDS will be simulated.
COOK,K.W. Louisiana Power & Light Co. 85/08/03. MARTIN,R.D. Region 4, Office of Director. 425pp. 33165-074-33166-204.

8510240408 Forwards schedule of activities re 850917-19 annual emergency planning exercise.Schedule includes exercise-related meetings & general employee training schedule details.
COOK,K.W. Louisiana Power & Light Co. 85/08/26. MARTIN,R.D. Region 4, Office of Director. 3pp. 33151-325-33151-327.

8510040438 Informs that due to major computer hardware mods.completion of SPDS transient test cases must be deferred until 851018. Test cases & procedures will be available for initial review during 850925-27 SPDS audit.
COOK,K.W. Louisiana Power & Light Co. 85/09/25. KNIGHTON,G.W. Licensing Branch 3. 1p. 32857-156-32853-356.

8510020219 Revised emergency plan implementing procedures,including Rev 10 to EP-1-010, "Unusual Event," Rev 10 to EP-1-020, "Alert," Rev 3 to EP-2-090, "Core Damage Assessment" & Rev 6 to EP-2-130, "Emergency Team Assignments." W/ 850930 lt.
BARKHURST,R.P., COOK,K.W. Louisiana Power & Light Co. 85/09/30. MARTIN,R.D. Region 4, Office of Director. 319pp. 32823-138-32824-094.

8510160215 Forwards Rev 9 to physical security plan,reflecting enhancements to plan summarized in 840628 submittal.Rev withheld (ref 10CFR2.790(d)(1)).
LEDDICK,R.S. Louisiana Power & Light Co. 85/09/30. MARTIN,R.D. Region 4, Office of Director. 2pp. 33023-262-33023-263.

8510290121 Forwards addendum to FEMA findings on offsite radiological emergency response plans.Addendum resolves NUREG-0654/REP-1. Rev 1 planning elements.Approval conditional on verification of alert & notification sys.
JOHNSON,E.H. Region 4, Office of Director. 85/10/23. LEDDICK,R.S. Louisiana Power & Light Co. 2pp. 33235-261-33235-263.

8510310364 Forwards insp Rept 50-382/85-21 on 850826-29.No violation or deviation noted.
JOHNSON,E.H. Region 4, Office of Director. 85/10/28. LEDDICK,R.S. Louisiana Power & Light Co. 2pp. 33271-325-33271-333.

-8510310369 Insp Rept 50-382/85-21 on 850826-29.No violation or deviation noted.Major areas inspected:radiation protection program,including mgt controls,external radiation exposure controls & internal dosimetry.
CHANEY,H.D., SPITZBERG,D.B., MURRAY,B. Region 4, Office of Director. 85/10/10. 7pp. 33271-327-33271-333.

G. Adjudicatory correspondence

8510100176 Order extending time until 851025 for Commission to act to review ALAB-812 dtd 850711 Served on 851007.
HOYLE,J.C. Office of the Secretary of the Commission. #485 697. 85/10/04. Commissioners. 1p. 32962-201-32962-201.

8510180392 Requests that encl memo be served on all parties to proceeding to avoid ex parte problems.Served on 851016.
ALLOOT,C.S. Office of the General Counsel. #485 792. 85/10/16. CLEMENTS,W.L. Office of the Secretary of the Commission. 1p. 33062-183-33062-187.

-8510180398 Recommends against enlargement of disclosure duty to include detailed info re focus,direction & specific targets of pending investigation or preliminary conclusions of investigators.
HAYES,B.B. Office of Investigation. 85/10/11. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 4pp. 33062-184-33062-187.

8510280513 Order extending time until 851115 for Commission to act to review ALAB-812 Served on 851024.
CHILK,S.J. Office of the Secretary of the Commission. #485 945. 85/10/24. Commissioners. 1p. 33227-311-33227-311.

P. Operating license stage documents & correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982,per 841210 oral agreement. Forwards documents listed on app.Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABEIL,L. Government Accountability Project. 32pp. 32884-005-32884-234.

-8312020438 Trip rept of 831104-05 site visit & meeting to formulate final objectives,guidance & schedule for initial full-scale exercise.
PERROTTI,D.J. Emergency Preparedness Branch. 83/11/21. Emergency Preparedness Branch. 9pp. 32894-309-32894-317.

-8510010295 Rev 2 to Maint Dept Procedure MD-1-011, "Development,Control & Distribution."
* Louisiana Power & Light Co. 83/08/11. 46pp. 32886-108-32886-153.

-8510010297 Rev 2 to Calibr Procedure MI-5-118, "Calibr of Crimpers." Manual rev review forms & related documentation encl.
* Louisiana Power & Light Co. 83/10/24. 132pp. 32889-265-32890-040.

-8510010301 Rev 3 to Administrative Procedure UNT-5-002, "Condition Identification & Work Authorization."
ALLEMAN,S.A. Louisiana Power & Light Co. 84/04/20. 51pp. 32886-154-32886-204.

-8510010304 Rev 1 to Administrative Procedure MD-1-007, "Preventive Maint Task Identification."
HEREFORD,R.B. Louisiana Power & Light Co. 83/08/08. 60pp. 32890-168-32890-228.

-8510010307 Rev 1 to Surveillance Procedure ME-3-327, "4.16 kV GE Magne-Blast Breaker."
ALLEMAN,S.A. Louisiana Power & Light Co. 84/03/09. 47pp. 32886-205-32886-251.

-8510010310 Rev 0 to Procedure UNT-4-004, "Plant Correspondence Control."
* Louisiana Power & Light Co. 80/05/05. 28pp. 32890-229-32890-256.

-8510010313 Rev 2 to Maint Procedure ME-4-131, "4.16 kV GE Magne-Blast Breaker."
* Louisiana Power & Light Co. 83/05/16. 117pp. 32886-252-32887-006.

-8510010314 Rev 0 to Project Mgt Procedure PMP-004, "Control of Vendor Manuals."
* Louisiana Power & Light Co. 84/04/16. 22pp. 32890-257-32890-278.

-8510010321 Rev 1 to Administrative Procedure UNT-4-007, "Control of Plant Manuals."
* Louisiana Power & Light Co. 80/12/10. 35pp. 32890-279-32890-314.

-8510010326 Audit on 830119-0304 of environ monitoring program.Audit checklist for health physics program & related documentation encl.
ROBERTS,A.R., MORGAN,W.M. Louisiana Power & Light Co. 83/03/24. 189pp. 32884-037-32884-204.

-8510010328 Rev 1 to Plant Engineering Procedure EP-2-003, "Plant Engineering Condition Identification Work Authorization Processing."
* Louisiana Power & Light Co. 83/06/28. 19pp. 32890-314-32891-009.

-8510010332 Rev 0 to QA Plan QAP-3747, "Engineering/Technical Svcs to Perform Spare Parts Evaluation & Analysis." Related documentation encl.
* Burns & Roe Co. 82/12/31. 21pp. 32887-244-32887-264.

-8510010333 Vol XIII to "Plant Operating Manual," "Health Physics Procedures."
* Louisiana Power & Light Co. 83/11/21. 15pp. 32884-205-32884-222.

-8510010339 Rev 0 to Maint Procedure MM-6-002, "Valve Operator Repair."
ALLEMAN,S.A. Louisiana Power & Light Co. 81/08/12. 12pp. 32887-265-32887-276.

-8510010342 Rev 0 to Project Mgt Procedure PMP-002, "Document Control."
* Louisiana Power & Light Co. 84/03/01. 39pp. 32891-010-32891-022.

-8510010345 Rev 2 to Surveillance Procedure ME-3-310, "Calibr of Time Delay Relays." Related documentation encl.
ALLEMAN,S.A. Louisiana Power & Light Co. 84/04/18. 222pp. 32887-277-32888-138.

-8510010348 Rev 0 to Surveillance Procedure OP-903-106, "Plant Protection Sys Channel 'D' Functional Test." Related info, including ITT electronic transmitter manual,encl.
* Louisiana Power & Light Co. 83/12/13. 282pp. 32891-323-32892-244.

-8510010350 Rev 1 to Administrative Procedure PE-2-014, "Equipment Environ Qualification."
* Louisiana Power & Light Co. 84/01/15. 53pp. 32891-023-32891-074.

-8510010357 Rev 0 to Nuclear Administrative Procedure NAP-504, "Implementation of Operations Assessment & Info Dissemination Program."
WOLFE,R. Louisiana Power & Light Co. 82/12/26. 161pp. 32891-075-32891-236.

-8510010358 Rev 0 to Maint Procedure MM-6-012, "Structural Bolt Tensioning."
* Louisiana Power & Light Co. 82/05/26. 27pp. 32888-146-32888-172.

-8510010364 Rev 2 to Maint Procedure ME-7-001, "Insulation Resistance & Continuity Testing." Related info encl.
* Louisiana Power & Light Co. 83/06/24. 65pp. 32891-237-32891-301.

-8510010365 Rev 0 to Maint Procedure MM-6-011, "General Torquing & Detensioning." Limtorque instruction & maint manuals encl.
* Louisiana Power & Light Co. 82/03/04. 216pp. 32888-173-32889-025.

-8510010369 Rev 1 to "Plant Protection Sys Field Mod Procedure for Louisiana Power & Light."
ROBERTS,T.F., YANOSY,P.L. Louisiana Power & Light Co. 83/03/30. 21pp. 32891-302-32891-322.

-8510010371 Rev 0 to PMD-Y83-061, "Plant Lubrication Manual."
* Louisiana Power & Light Co. 85/02/27. 98pp. 32889-026-32889-122.

-8510010373 Rev 1 to Maint Procedure MM-4-001, "Lubrication Procedure."
* Louisiana Power & Light Co. 82/12/29. 23pp. 32889-123-32889-145.

-8510010376 Rev 0 to Departmental Procedure MD-01-010, "Plant Lubrication Program."
EPPERSON,W.A. Louisiana Power & Light Co. 83/04/14. 7pp. 32889-146-32889-152.

-8510010380 Rev 1 to Maint Procedure ME-13-019, "Motor Bearing Replacement & Motor Cleaning."
* Louisiana Power & Light Co. 83/04/06. 23pp. 32889-153-32889-175.

-8510010381 Rev 0 to Maint Procedure ME-4-701, "Greasing Electrical Equipment."
* Louisiana Power & Light Co. 82/11/11. 9pp. 32889-176-32889-184.

-8510010424 Rev 1 to Calibr Procedure MI-5-121, "Calibr of Burndy Hypress Crimpers."
* Louisiana Power & Light Co. 84/02/08. 18pp. 32889-185-32889-203.

-8510010427 Rev 0 to Maint Procedure ME-4-810, "Low Voltage Power Cable Terminations & Splices."
* Louisiana Power & Light Co. 83/12/31. 38pp. 32889-204-32889-241.

-8510010431 Rev 0 to Maint Procedure ME-4-811, "Medium & High Voltage Cable Terminations & Splices."
* Louisiana Power & Light Co. 82/01/25. 23pp. 32889-242-32889-264.

-8510010439 Rev 1 to Procedure TBP-18, "QA Records Control."
* Tompkins-Beckwith, Inc. 83/01/10. 21pp. 32894-208-32894-234.

-8510010441 Rev E to Procedure TBP-8, "QA Audits."
* Tompkins-Beckwith, Inc. 81/03/25. 48pp. 32894-235-32894-282.

-8510010458 Rev 1 to Administrative Procedure UNT-3-003, "General Employee Training."
ALLEMAN,S.A. Louisiana Power & Light Co. 84/02/11. 28pp. 32895-056-32895-083.

-8510010460 Rev 1 to Technical Procedure NE-1-001, "New Fuel Shipping Container Operation."
STARKEY,R.S., RYALL,R.K. Louisiana Power & Light Co. 82/11/30. 29pp. 32895-084-32895-112.

172 DOCKETED ITEMS

- 8510020199** Rev 1 to Maint Procedure ME-4-809, "Low Voltage Control Cable Termination & Splices."
* Louisiana Power & Light Co. 83/12/29. 18pp. 32890:047-32890:064.
- 8510020202** Rev 1 to Spec MC-1, "General Specs Covering Installation of Mechanical Equipment." Field change requests encl.
BENNETT, J.G. Ebasco Services, Inc. (subs. of Enserch Corp.). 76/10/29. 45pp. 32890:065-32890:109.
- 8510020229** Draft Issue C of Procedure ASP-IV-22, "Unloading &/or Handling Heavy or Specialized Equipment."
MEARKE, J. Ebasco Services, Inc. (subs. of Enserch Corp.). 82/02/09. 6pp. 32890:146-32890:151.
- 8510020236** Draft Issue H of Procedure CP-425, "Insulation Resistance Testing of Rotating Electrical Equipment & Power Cables 480-Volt & Above."
MURTHA, M. Ebasco Services, Inc. (subs. of Enserch Corp.). 80/05/13. 6pp. 32890:152-32890:157.
- 8510070354** Confirms 851002 mgt meeting in Region IV ofc to discuss general plant status, per 850920 telcon.
MARTIN, R.D. Region 4, Office of Director. 85/10/01. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 32877:246-32877:247.
- 8510090463** Notification of 851030-31 meetings w/ util, BNL & Ebasco in New York, NY to discuss confirmatory analyses for common foundation basemat.
WILSON, J.H. Licensing Branch 3. 85/10/03. KNIGHTON, G.W. Licensing Branch 3. 3pp. 32966:208-32966:210.
- 8510150244** Forwards SER re util 831104 & 840206 responses to Generic Ltr 83-28, Item 1.1, re post-trip review. Response does not meet guidelines/criteria. Corrective action on listed deficiencies should be taken by 851031.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33032:227-33032:233.
- 8510150248** SER re Generic Ltr 83-28, Item 1.1, concerning post-trip review. Criteria for determining acceptability of restart insufficient. Analysis of sys important to reactor safety should be conducted prior to restart.
* NRC - No Detailed Affiliation Given. 85/10/03. 5pp. 33032:229-33032:233.
- 8510160295** Forwards personal qualifications statements, NRC Form 398, for license renewal for listed senior operators. Hours shown are actual hours on shifts since fuel load. Completed NRC Form 396, certificate of medical history also encl w/o encls.
COOK, K.W. Louisiana Power & Light Co. 85/10/04. MARTIN, R.D. Region 4, Office of Director. 1p. 33023:350-33023:350.
- 8510150311** Requests fee for 850719 application for amend to License NPF-38 re reanalysis of C-E large break LOCA evaluation model & deviation from 10CFR50.46.
DIGGS, R.M. License Fee Management Branch. 85/10/09. LEDDICK, R.S. Louisiana Power & Light Co. 1p. 33032:309-33032:309.
- 8510150126** Submits proposed schedule for meeting reporting requirements of 10CFR50.62(c)(1) & (c)(2) re ATWS final rule (Generic Ltr 85-06). Implementation of rule requires installation of diverse scram sys & turbine trip prior to outage completion.
COOK, K.W. Louisiana Power & Light Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33010:304-33010:305.
- 8510170010** "Waterford Steam Electric Station Unit 3 Startup Rept for US NRC." W/ 851010 tr.
SMITH, J.N., BARKHURST, R.P., COOK, K.W. Louisiana Power & Light Co. 85/10/10. MARTIN, R.D. Region 4, Office of Director. 420pp. 33052:141-33053:198.
- 8510170100** Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:016-33044:027.
- 8510170202** "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.2, 'Post-Trip Review Data & Info Capabilities'..." techn. eval evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.) NRC-03-82-096. SAIC-85/1524-22. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:171-33044:185.
- 8510170233** Forwards changes to Chapter 14 to FSAR, deleting control sys steady-state operation at 100% power level & deleting movable in-core reactor responsiveness testing from power ascension test program.
COOK, K.W. Louisiana Power & Light Co. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 8pp. 33043:039-33043:046.
- 8510220205** Forwards post-trip review requirements, in response to NRC 851003 SER requesting addl info re util 840206 response to Generic Ltr 83-28, Item 1.1.
COOK, K.W. Louisiana Power & Light Co. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 14pp. 33087:249-33087:262.
- 8510220125** Further response to FOIA request for documents re EG&G rept on harassment & intimidation. Forwards App B documents. Documents also available in PDR. Portions of App C Documents 1-4 withheld (ref FOIA Exemptions 4 & 6).
FELTON, J.M. Division of Rules and Records. 85/10/16. GARDE, B., GREGORY, J.S. Government Accountability Project. 4pp. 33099:325-33100:121.
- 8510220239** Forwards project & budget proposals for NRC work for Rev 1 to, "Evaluation of Selected NRC Open Items Before Plant Fuel Load" & "Evaluation of Selected Open NRC Activities at Near-Term OL Sites Needing Action..."
WILLIAMS, S.B. Energy, Dept. of, Idaho Operations Office. FIN A-6819. 84/08/23. WILLIAMS, M. Division of Licensing. 1p. 33100:112-33100:112.
- 8510220252** Rev 1 to project & budget proposal for NRC work: "Evaluation of Selected NRC Open Items Before Plant Fuel Load."
OBENCHAIN, C.F., BARNES, B.L., WHITTEMORE, J.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6819. 85/08/15. DONOHEW, J.N., LAZO, L.M., CRUTCHFIELD, D. Office of Nuclear Reactor Regulation, Director. 9pp. 33100:113-33100:121.
- 8510280329** Forwards updated info re operating shift staffing & exams, proprietary resumes of shift advisors & synopsis of operating history since Dec 1984 fuel load. Proprietary resumes withheld (ref 10CFR2.790).
COOK, K.W. Louisiana Power & Light Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 27pp. 33194:049-33194:075.

8510310116 Forwards summary of 851002 meeting re activities authorized by License NPF-38 Meeting beneficial & provided better understanding of plant status & planned activities.
DENISE, R.P. Region 4, Office of Director. 85/10/23. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33291:001-33291:002.

-8510310124 Summary of 851002 meeting w/ util in Arlington, TX re general plant status, including recent major events & milestones achieved & recent main turbine generator outage. Attendance list & related info encl.
CONSTABLE, G.L. Region 4, Office of Director. 85/10/16. Region 4, Office of Director. 16pp. 33291:003-33291:018.

Q. Inspection reports, IE Bulletins & correspondence

8510010353 Marked-up Rev 1 to Allegation Investigation Repts 4-83-A-48/2, 4-84-A-06/96 & 4-84-A-06/156 re Allegations A-02, A-208 & A-274, alleging that Mercury Const Co QC inspectors improperly certified. Potential violations noted.
* NRC - No Detailed Affiliation Given. 84/06/06. 7pp. 32976:234-32976:240.

8510020468 Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re forged signatures & initials in JA Jones daily cadweld insp repts.
* NRC - No Detailed Affiliation Given. 84/06/14. 4pp. 32984:209-32984:212.

8510040515 Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re possibility of forged signatures & initials in JA Jones daily cadweld insp repts.
* NRC - No Detailed Affiliation Given. 84/06/14. 6pp. 32989:287-32990:298.

8510010621 Rev 2 to Allegation Investigation Repts 4-83-A-88/16, 4-83-A-88/17 & 4-83-A-88/18 re Allegations A-64, A-65 & A-66 concerning unacceptable Mercury insp activities. No violations noted.
* NRC - No Detailed Affiliation Given. 84/06/15. 2pp. 32977:222-32977:223.

8510010531 Rev 1 to Allegation Investigation Repts 4-84-A-06/110 & 119 re Allegations A-222 & A-231 re insufficiency of Mercury concrete expansion anchor installation & insp procedure. Allegation may have some safety significance.
MARINI, W.S. NRC - No Detailed Affiliation Given. 84/06/20. 5pp. 32975:233-32975:236.

8510010568 Allegation Investigation Repts 4-84-A-06/44/46/47/48, Rev 3, re Allegations A-149, A-151, A-152 & A-153 concerning four nonconformance repts signed by uncertified QC inspectors & lack of seismic Category I stairs insp repts.
CROSSMAN, W.A. NRC - No Detailed Affiliation Given. 84/07/20. 5pp. 32975:257-32975:261.

8510020487 Forwards exit interview notes from Insp Rept 50-382/84-34 on 840720.
MORGAN, W.M. Louisiana Power & Light Co. 84/08/01. COLLINS, J.T., CROSSMAN, W.A., PERANICH, M. NRC - No Detailed Affiliation Given. 3pp. 32985:004-32985:006.

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEIL, L. Government Accountability Project. 32pp. 32884:005-32884:234.

-8404050355 Summarizes 840306 telcon re insp of post-accident sampling sys per TMI Item II.B.2 Comments on 840301 memo provided.
KNIGHTON, G.W. Licensing Branch 3. 84/03/14. BANGART, R.L. Region 4, Office of Director. 45pp. 32884:235-32884:240.

-8510010320 Requests review of encl draft Insp Rept 50-382/84-24. Related documentation encl.
GAGLIARDO, J. Region 4, Office of Director. 84/08/11. CRUTCHFIELD, D. Office of Nuclear Reactor Regulation, Director. CROSSMAN, B. NRC - No Detailed Affiliation Given. 51pp. 32887:007-32887:243.

-8510010343 Rev 0 to Nuclear Administrative Procedure NAP-220, "Radiation Control Section Overview." WM Morgan 840828 interofc memo re NRC review of radiation protection, Radwaste Program Insp 84-38 on 840820-24 encl.
* Louisiana Power & Light Co. 83/01/05. 8pp. 32884:223-32884:230.

-8510010351 Rev 4 to QC Procedure WQC-50, "Equipment Hanging & Setting Insp." MCKENZIE, J.H., HEISER, L., DEAMM, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/12/09. 7pp. 32888:139-32888:145.

-8510010354 Discusses Insp Rept 50-382/84-05 open items re post-accident sampling sys design & operability. Physical layout of sys described. No leakage should be allowed at mechanical couplings in wing area of reactor auxiliary bldg.
BANGART, R.L. Division of Vendor & Technical Programs. 84/03/01. KNIGHTON, G.W. Licensing Branch 3. 4pp. 32884:231-32884:234.

-8510010360 Rev 2 to Surveillance Procedure MM-3-015, "Emergency Diesel Engine Insp." Related info encl.
HALL, B. Louisiana Power & Light Co. 84/06/04. 175pp. 32892:243-32893:065.

-8510010367 Rev 1 to Surveillance Procedure MM-3-015, "Emergency Diesel Engine Insp." encl.
HALL, B., ALLEMAN, S.A. Louisiana Power & Light Co. 84/03/19. 87pp. 32893:066-32893:152.

-8510010375 Forwards input from Physical Security Section for 1982-1983 facility SALP rept. Related info, including Westinghouse maint manual, encl.
KELLY, J.A. Region 4, Office of Director. 83/08/29. CONSTABLE, L. Region 4, Office of Director. 150pp. 32893:153-32893:301.

-8510010430 Draft ltr forwarding NRR draft SALP input for review. Comments received by 830826 will be considered in final rept.
WILSON, J.H. Licensing Branch 3. 85/02/27. EISENHUT, D.G. Division of Licensing. MATTHEWSON, R. Division of Systems Integration (post 811005). VOLLMER, R. Division of Engineering. 6pp. 32893:328-32894:003.

-8510010432 Rev P to Procedure TBP-26, "Visual Insp Procedure."
* Tompkins-Beckwith, Inc. 83/06/15. 34pp. 32893:174-32893:207.

-8510010457 Forwards Safety Insp Rept 50-382/84-20. Areas examined include implementation of fire protection program & compliance w/10CFR50, App R. Listed open items referred to: NRC for resolution. Meeting requested.
COLLINS, J.T. Region 4, Office of Director. 84/07/13. VOLLMER, R.H. Division of Engineering. 21pp. 32895-035-32895-055.

-8510010461 Rev 1 to Technical Procedure NE-1-002, "New Fuel Receipt Insp."
STARKEY, R.S. Louisiana Power & Light Co. 82/11/23. 1,451pp. 32895:113-32899:123.

-8510020207 Rev 0 to QC Procedure WQC-52, "Containment Fan Coolers - Installation Insp." Product assurance call records encl.
BERRY, R.B., STINSON, L.A. Ebasco Services, Inc. (subs. of Enserch Corp.). 79/05/23. 18pp. 32890:110-32890:125.

-8510020211 Rev 0 to QC Procedure WQC-50, "Equipment Hanging & Setting Insp."
BERRY, R., STINSON, L. Ebasco Services, Inc. (subs. of Enserch Corp.). 79/05/23. 5pp. 32890:126-32890:130.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210274 Notification of 851023-24 meeting & site visit w/Util, BNL & Ebasco Svcs, Inc. in Kilona, LA to evaluate proposed surveillance program for common foundation basement.
WILSON, J.H. Licensing Branch 3. 85/10/04. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33079:082-33079:084.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230090 Forwards Press Release 85-75 re NRC proposed fine against util for alleged violations of requirements concerning failure to take corrective action when warranted concerning QA program.
KAMMERER, C. Office of Congressional Affairs. 85/05/24. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:050-33109:051.

8510160255 Ack receipt of 850621 ltr informing NRC of steps taken to correct deviations noted in NRC 850524 ltr re Enforcement Action 85-10.
JOHNSON, E.H. Region 4, Office of Director. 85/10/08. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33022:325-33022:334.

-8510160257 Forwards response to NRC 850524 ltr re Enforcement Action 85-10 concerning failure to perform hydrostatic test per FSAR. Corrective actions: field change request initiated on 800806 to cover deletion of use of high point vents.
COOK, K.W. Louisiana Power & Light Co. 85/06/21. MARTIN, R.D. Region 4, Office of Director. 3pp. 33022:327-33022:334.

8510160098 Forwards Insp Rept 50-382/85-04 on 850211-15 & notice of violation.
JOHNSON, E.H. Region 4, Office of Director. 85/10/09. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33022:118-33022:130.

-8510160100 Notice of violation from insp on 850211-15.
* Region 4, Office of Director. 85/10/09. 2pp. 33022:120-33022:121.

-8510160109 Insp Rept 50-382/85-04 on 850211-15. Violation noted: failure to have procedures for verification of supplier acceptance of design & quality changes & review of spare parts against Ebasco as-built specs.
BOARDMAN, J.R., CONSTABLE, G.L. Region 4, Office of Director. 85/10/03. 9pp. 33022:122-33022:130.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510180392 Requests that encl memo be served on all parties to proceeding to avoid ex parte problems. Served on 851016.
ALOOT, C.S. Office of the General Counsel. #485 792. 85/10/16. CLEMENTS, W.L. Office of the Secretary of the Commission. 1p. 33062:183-33062:187.

-8510180398 Recommends against enlargement of disclosure duty to include detailed info re focus, direction & specific targets of pending investigation or preliminary conclusions of investigators.
HAYES, B.B. Office of Investigation. 85/10/11. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 4pp. 33062:184-33062:187.

8510220218 Ack receipt of 850903 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-382/85-16.
MARTIN, L.E. Region 4, Office of Director. 85/10/16. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33087:206-33087:212.

-8510220227 Responds to NRC 850802 ltr re violations noted in Insp Rept 50-382/85-16. Corrective actions: Offnormal Operating Procedure OP-901-022, "High Activity in Containment Cooling Water Sys." modified to reflect isolation at high temp.
COOK, K.W. Louisiana Power & Light Co. 85/09/03. MARTIN, R.D. Region 4, Office of Director. 5pp. 33087:208-33087:212.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510310283 Forwards Insp Rept 50-382/85-24 on 850801-0930. No violations noted.
MARTIN, L.E. Region 4, Office of Director. 85/10/25. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33272:126-33272:134.

-8510310291 Insp Rept 50-382/85-24 on 850801-0930. No violation or deviation noted. Major areas inspected: operational safety verification, monthly surveillance observation, monthly maint observation & IE bulletin followup insp.
FLIPPO, T.A., JONES, W.B., BRESLAU, B.A. Region 4, Office of Director. 85/10/23. 7pp. 33272:128-33272:134.

8510310364 Forwards Insp Rept 50-382/85-21 on 850826-29. No violation or deviation noted.
JOHNSON, E.H. Region 4, Office of Director. 85/10/28. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33271:325-33271:333.

-8510310369 Insp Rept 50-382/85-21 on 850826-29. No violation or deviation noted. Major areas inspected: radiation protection program, including mgt controls, external radiation exposure controls & internal dosimetry.
CHANEY, H.D., SPITZBERG, D.B., MURRAY, B. Region 4, Office of Director. 85/10/10. 7pp. 33271:327-33271:333.

R. Periodic operating reports & related correspondence

8510010616 Monthly operating rept for Jul 1985. W/850814 ltr.
MILLER, G., COOK, K.W. Louisiana Power & Light Co. 85/07/31. SCROGGINS, R.M. Office of Resource Management, Director. 8pp. 32830:020-32830:027.

8510150476 Monthly operating rept for Sept 1985. W/851010 ltr.
MILLER, G., COOK, K.W. Louisiana Power & Light Co. 85/09/30. SCROGGINS, R.M. Office of Resource Management, Director. 7pp. 33015:129-33015:135.

S. Reportable occurrences, LERs & related correspondence

8510040386 LER 85-034-01: on 850707, reactor trip & emergency feedwater actuation occurred. Caused by personnel error due to incorrect positioning of backwash selector switch. Mod package prepared to increase sys reliability. W/850930 ltr.
MYERS, L., COOK, K.W. Louisiana Power & Light Co. 85/09/30. 4pp. 32866:352-32866:355.

8510080281 PNO-IV 85-052: on 851003, plant outage initiated from hot standby to replace failed seal on reactor coolant pump 2B. Cause not stated.
CONSTABLE, G.L. Region 4, Office of Director. 85/10/04. 1p. 32918:358-32918:358.

8510080437 LER 85-077-00: on 850905, personnel discovered two fire seal impairments during visual insp. of fire-rated penetration seals. During addl sampling, 13 other impairments found. Cause not stated. Seals replaced. W/851004 ltr.
SMITH, T., COOK, K.W. Louisiana Power & Light Co. 85/10/04. 4pp. 32922:316-32922:319.

8510170013 LER 85-038-00: on 850910, discovered that fire wrap for conduits 315U/2C-2A & 31551R-SA did not completely cover support points. Cause not stated. Condition existed since const. Points wrapped & operability verified. W/851010 ltr.
SMITH, T., COOK, K.W. Louisiana Power & Light Co. 85/10/10. 4pp. 33053:205-33053:208.

8510210163 LER 85-039-00: on 850912, 19, 27 & 1007, spurious actuations of control room ventilation sys occurred. Caused by electrical spikes &/or spurious actuations of air intake monitors. Monitors modified. Investigation continuing. W/851011 ltr.
SMITH, T., COOK, K.W. Louisiana Power & Light Co. 85/10/11. 4pp. 33094:352-33094:355.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230090 Forwards Press Release 85-75 re NRC proposed fine against util for alleged violations of requirements concerning failure to take corrective action when warranted concerning QA program.
KAMMERER, C. Office of Congressional Affairs. 85/05/24. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:050-33109:051.

V. Operator Examinations

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510280329 Forwards updated info re operating shift staffing & exams, proprietary resumes of shift advisors & synopsis of operating history since Dec 1984 fuel load. Proprietary resumes withheld (ref 10CFR2.790).
COOK, K.W. Louisiana Power & Light Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 27pp. 33194:049-33194:075.

174 DOCKETED ITEMS

DOCKET 50-385 TAKAHAMA, UNIT 1

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8510040008 Draft 3 to Allegation Investigation Rept 4-84-A-06-36 of Allegation A-141 re whether Ebasco discrepancy notices were considered in QA review of concrete placement packages. No violation noted.
* NRC - No Detailed Affiliation Given. 84/06/18. 10pp. 32987:182-32987:191.

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510150061 Advises that 850610 Change D to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
MARTIN, T.T. Region 1, Office of Director. 85/09/24. KENYON, B.D. Pennsylvania Power & Light Co. 3pp. 33015:098-33015:100.

8510070154 Rev 3 to Emergency Plan Implementing Procedure EP-IP-102, "Surveillance Testing of Emergency Communications Equipment." Revised index & table of contents also encl. W/851002 ltr.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/02. 27pp. 32881:030-32881:056.

8510070304 Rev 6 to Emergency Plan Implementing Procedure EP-IP-045, "Post-Accident Sampling Sys 14.7-ML Gas Sample" & Rev 73 to table of contents. W/851002 ltr.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/02. 24pp. 32875:320-32875:343.

8510080410 Supplis util 850904 ltr re resolution of fire protection concerns. Listed replacement pages re sprinkler protection for control structure elevation & shutdown paths encl.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/03. BUTLER, W.R. Licensing Branch 2. 13pp. 32913:350-32913:362.

8510080034 Declines 841217 request to participate in development project for NRC emergency response data sys. No significant emergency mgt benefit anticipated to offset potential costs associated w/involvement in effort.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/04. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 32918:294-32918:294.

8510250425 Forwards Change V to physical security plan. Change withheld (ref 10CFR2.790(d)).
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/14. MURLEY, T.E. Region 1, Office of Director. 1p. 33169:332-33169:332.

8510220214 Revised emergency plan implementing procedures, including Rev 4 to EP-IP-047, "Post-Accident Sampling Sys Large Liquid/Dissolved Gas Sample" & EP-IP-043, "Post-Accident Sys Vol Liquid Sample."
* Pennsylvania Power & Light Co. 85/10/17. 5pp. 33086:353-33086:357.

8510310201 Advises that 850916 temporary change to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. Change understood to be in effect during 850925-1201, at which time security features will be returned to normal.
MARTIN, T.T. Region 1, Office of Director. 85/10/24. KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 33273:099-33273:101.

P. Operating license stage documents & correspondence

8510010165 Submits first special rept required per Tech Spec 4.12.85 re RCIC injections. Prior to 850412 Tech Spec change, 124 injections occurred. One occurred after change. Most recent injection resulted from performance of TP-150-008.
CRIMMINS, T.M. Pennsylvania Power & Light Co. 85/09/27. Record Services Branch (Document Control Desk). 1p. 32801:352-32801:352.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510150321 Forwards proposed action plan for implementing ATWS requirements delineated in 10CFR50.62(c)(3) through (c)(5). Approach consistent for both units & assures completion of ATWS mods by second refueling outage after 850416.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/09. BUTLER, W.R. Licensing Branch 2. 2pp. 33009:054-33009:055.

8510150399 Application for proposed Amend 71 to License NPF-14, changing Tech Spec Table 3.8.4.1-1 to add Entries 30 & 31 to support installation of overcurrent protection for nonsafety-related fans. Fee paid.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/10. BUTLER, W.R. Licensing Branch 2. 3pp. 33000:325-33000:327.

-8510150401 Proposed changes to Tech Spec Table 3.8.4.1-1, adding Entries 30 & 31 to support installation of overcurrent protection for nonsafety-related fans.
* Pennsylvania Power & Light Co. 85/10/10. 1p. 33000:328-33000:328.

8510170201 Requests State of PA Bureau of Solid Waste Mgt concur w/listed disposal options so State of PA Dept of Environ Resources can complete review of sewage treatment plant expansion & provide CP.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/10/10. FRITZ, D. Pennsylvania, Commonwealth of. 2pp. 33051:357-33051:358.

8510180275 Forwards "Susquehanna Steam Electric Station Unit 1 Amended Startup Rept." to replace original rept & suppl dtd 830610 & 0908, respectively.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/15. MURLEY, T.E. Region 1, Office of Director. 1p. 33059:059-33059:239.

-8510180281 "Susquehanna Steam Electric Station Unit 1 Amended Startup Rept."
SHERANKO, R.G. KEISER, H.W. Pennsylvania Power & Light Co. 85/05/09. 184pp. 33059:060-33059:239.

8510220060 Responds to 850924 telcon re update on diesel generator closed cooling sys discharges. Mail safety data sheet for Calgon Product LCS-59 encl.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/10/15. AGUSTIN, D.R. Pennsylvania, Commonwealth of. 8pp. 33095:229-33095:236.

8510280427 Forwards "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Susquehanna Steam Electric Station Unit 1." "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Susquehanna Unit 2" & safety evaluation.
BUTLER, W.R. Licensing Branch 2. 85/10/22. KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 33228:160-33228:178.

-8508230332 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Susquehanna Steam Electric Station Unit 1."
VANDERBEEK, R. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6001. 85/06/30. NRC - No Detailed Affiliation Given. 7pp. 33228:163-33228:169.

-8510280428 Safety evaluation re util response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 concerning post-maint testing (reactor trip sys components & other safety-related components). Responses acceptable.
* Licensing Branch 2. 85/10/22. 2pp. 33228:170-33228:171.

-8510150484 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 for Susquehanna Steam Electric Station Unit 2."
VANDERBEEK, R. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6002. 85/09/30. NRC - No Detailed Affiliation Given. 7pp. 33228:172-33228:178.

Q. Inspection reports, IE Bulletins & correspondence

8510020073 Forwards Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted.
KISTER, H.B. Region 1, Office of Director. 85/09/19. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32827:141-32827:170.

-8510020080 Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted. Major areas inspected: plant operations, licensee events, open items, surveillance, maint, IE bulletins & TMI action items.
JACOBS, R.H., PLISCO, L.R., STROSNIDER, J. Region 1, Office of Director. 85/09/13. 28pp. 32827:143-32827:170.

8510090186 Forwards Operator Licensing Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator exam. Written & operating exams will be administered on 851120 & 21, respectively.
STAROSTECKI, R. Region 1, Office of Director. 85/09/25. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32947:178-32947:182.

-8510090198 Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator licensing exam. Region agreed to administer one instructor certification & one senior operator exam on 851120 & 21, respectively.
LANGE, D., KELLER, R., KISTER, H. Region 1, Office of Director. 85/09/23. 3pp. 32947:180-32947:182.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230203 Forwards Press Release 84-83 re NRC proposed fine against util for loading fuel bundles & moving control rods in reactor core while sys for monitoring startup inoperable. Three other violations cited.
KAMMERER, C. Office of Congressional Affairs. 84/07/06. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109:016-33109:018.

-8510230304 Forwards Press Release 84-150 of NRC proposed fine against util for alleged inadequate control of operations.
KAMMERER, C. Office of Congressional Affairs. 84/12/19. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109:121-33109:123.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510230183 Forwards ASME Code NIS-1 form re preservice exams & GE & Nuclear Energy svcs preservice insp repts.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/17. BUTLER, W.R. Licensing Branch 2. 6pp. 33103:350-33106:325.

-8510230188 Preservice insp rept. Exams performed on Reactor Pressure Vessel 3686 described.
RECZEK, E.N., MILLER, W.F., FORSYTHE, F.F. General Electric Co. 85/10/17. 400pp. 33103:356-33105:004.

-8510230194 Rev 6 to Preservice Insp Rept 80A2804 for 1979-1983 Insp of Class 1,2 & 3 components & areas described.
MURRAY, W.F., ZENCAY, C.J. Nuclear Energy Services, Inc. 84/10/12. 650pp. 33105:005-33106:325.

8510230199 Forwards Insp Repts 50-387/85-28 & 50-388/85-23 on 850826-0929 & notice of violation. Response to violation re monthly channel functional tests not including entire channel requested.
KISTER, H.B. Region 1, Office of Director. 85/10/17. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 33101:218-33101:249.

-8510230200 Notice of violation from insp on 850826-0929.
* Region 1, Office of Director. 85/10/17. 1p. 33101:220-33101:220.

-8510230202 Insp Repts 50-387/85-26 & 50-388/85-23 on 850826-0929. Violation noted: Surveillance Procedures SI-152-203, SI-152-201, SI-152-211 & SI-180-205 failed to test entire HPCI channel.
JACOBS, R.H., PLUSCO, L.R., STROSNIDER, J. Region 1, Office of Director. 85/10/10. 29pp. 33101:221-33101:249.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510280387 Forwards Safety Insp Repts 50-387/85-27 & 50-388/85-22 on 850917-20. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/22. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 33192:149-33192:155.

-8510280388 Insp Repts 50-387/85-27 & 50-388/85-22 on 850917-20. No violations noted. Major areas inspected: measurement control & analytical procedures evaluations.
ZIBULSKY, H., PASCIAK, W.J. Region 1, Office of Director. 85/10/11. 5pp. 33192:151-33192:155.

R. Periodic operating reports & related correspondence

8510010591 Monthly operating repts for Jul 1985 W/850812 ltr.
KUCZYNSKI, L.A., KEISER, H.W. Pennsylvania Power & Light Co. 85/07/31. BEEBE, M.R. Division of Automated Information Services. 24pp. 32830:052-32830:074.

8510020139 Forwards "NPDES Discharge Monitoring Rept for Aug 1985." Info detailing data &/or noncompliances for some permitted outfalls listed.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/09/27. KOVAL, P. Pennsylvania, Commonwealth of. 2pp. 32827:089-32827:107.

-8510020141 "NPDES Discharge Monitoring Rept for Aug 1985."
* Pennsylvania Power & Light Co. 85/08/31. 17pp. 32827:091-32827:107.

S. Reportable occurrences, LERs & related correspondence

8510070007 LER 83-134/03X-1 on 830912, during diesel generator monthly operability test, generator C tripped on overexcitation. Caused by voltage perturbation on offsite grid interfacing w/site electrical sys. W/850911 ltr.
KUCZYNSKI, L.A., CRIMMINS, T.M. Pennsylvania Power & Light Co. 85/09/17. MURLEY, T.E. Region 1, Office of Director. 3pp. 32900:004-32900:006.

8510180089 LER 85-029-00 on 850910, in service insp surveillance requirements of Tech Spec 4.0.5 not performed within required time frame. Caused by plant engineering group error. Surveillance completed W/851011 ltr.
CREASY, J.N., CRIMMINS, T.M. Pennsylvania Power & Light Co. 85/10/11. 3pp. 33068:335-33068:337.

8510180148 PNO-I-85-078 on 851011, isolation valve to low pressure sys piping opened & discharge of reactor coolant to cleanup demineralizer precoat pump area occurred. Cause under investigation. Cleanup in progress.
STROSNIDER, J. Region 1, Office of Director. 85/10/11. 1p. 33055:048-33055:048.

8510210005 PNO-I-85-078A on 851011, reactor coolant spill from reactor water cleanup sys to 779 ft elevation of reactor bldg occurred. Caused by lifting of 150 psig precoat feed relief valve. Spill cleaned & access to area restored.
STROSNIDER, J., JACOBS, R. Region 1, Office of Director. 85/10/11. 1p. 33072:020-33072:020.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 84/01/01. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230203 Forwards Press Release 84-83 re NRC proposed fine against util for loading fuel bundles & moving control rods in reactor core while sys for monitoring startup inoperable. Three other violations cited.
KAMMERER, C. Office of Congressional Affairs. 84/07/06. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109:016-33109:018.

-8510230304 Forwards Press Release 84-150 of NRC proposed fine against util for alleged inadequate control of operations.
KAMMERER, C. Office of Congressional Affairs. 84/12/19. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33109:121-33109:123.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832:352-32832:353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832:354-32833:001.

8510090188 Forwards Operator Licensing Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator exam. Written & operating exams will be administered on 851120 & 21, respectively.
STAROSTECKI, R. Region 1, Office of Director. 85/09/25. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32947:178-32947:182.

-8510090198 Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator licensing exam. Region agreed to administer one instructor certification & one senior operator exam on 851120 & 21, respectively.
LANGE, D., KELLER, R., KISTER, H. Region 1, Office of Director. 85/09/23. 3pp. 32947:180-32947:182.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510220142 Advises of 851021-23 training review at facility. Tasks will include formal & continuing training, on-the-job & emergency training. Instructions/procedures & documentation listed.
BUTLER, W.R. Licensing Branch 2. 85/10/15. KEISER, H.W. Pennsylvania Power & Light Co. 4pp. 33098:166-33098:169.

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8510150061 Advises that 850610 Change D to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
MARTIN, T.T. Region 1, Office of Director. 85/09/24. KENYON, B.D. Pennsylvania Power & Light Co. 3pp. 33015:098-33015:100.

8510070154 Rev 3 to Emergency Plan Implementing Procedure EP-IP-102, "Surveillance Testing of Emergency Communications Equipment." Revised index & table of contents also encl. W/851002 ltr.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/02. 27pp. 32881:030-32881:056.

8510070304 Rev 6 to Emergency Plan Implementing Procedure EP-IP-045, "Post-Accident Sampling Sys 14.7-MI Gas Sample" & Rev 73 to table of contents. W/851002 ltr.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/02. 24pp. 32875:320-32875:343.

8510080410 Suppl util 850904 ltr re resolution of fire protection concerns. Listed replacement pages re sprinkler protection for control structure elevation & shutdown paths encl.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/03. BUTLER, W.R. Licensing Branch 2. 13pp. 32913:350-32913:362.

8510080034 Declines 841217 request to participate in development project for NRC emergency response data sys. No significant emergency mgt benefit anticipated to offset potential costs associated w/involvement in effort.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/04. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 32918:294-32918:294.

8510250425 Forwards Change V to physical security plan. Change withheld (ref 10CFR2.790(d)).
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/14. MURLEY, T.E. Region 1, Office of Director. 1p. 33169:332-33169:332.

8510220214 Revised emergency plan implementing procedures, including Rev 4 to EP-IP-047, "Post-Accident Sampling Sys Large Liquid/Dissolved Gas Sample" & EP-IP-043, "Post-Accident Sys Vol Liquid Sample."
* Pennsylvania Power & Light Co. 85/10/17. 5pp. 33086:353-33086:357.

8510310201 Advises that 850916 temporary change to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. Change understood to be in effect during 850925-1201, at which time security features will be returned to normal.
MARTIN, T.T. Region 1, Office of Director. 85/10/24. KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 33273:099-33273:101.

P. Operating license stage documents & correspondence

8510030032 Forwards application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Fee paid.
KEISER, H.W. Pennsylvania Power & Light Co. 85/09/30. BUTLER, W.R. Licensing Branch 2. 2pp. 32842:269-32842:271.

-8510030058 Application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants."
KEISER, H.W. Pennsylvania Power & Light Co. 85/09/30. 1p. 32842:271-32842:271.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510150321 Forwards proposed action plan for implementing ATWS requirements delineated in 10CFR50.62(c)(3) through (c)(5). Approach consistent for both units & assures completion of ATWS mods by second refueling outage after 850416.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/09. BUTLER, W.R. Licensing Branch 2. 2pp. 33009:054-33009:055.

8510170140 Forwards application for Amend 25 to License NPF-22, changing Tech Specs to support replacements of magnetic-only circuit breakers w/thermal-magnetic breakers. Fee paid.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/10. BUTLER, W.R. Licensing Branch 2. 4pp. 33036:237-33036:251.

176 DOCKETED ITEMS

-8510170144 Application for Amend 25 to License NPF-22, changing Tech Specs to support replacements for magnetic-only circuit breakers w/thermal-magnetic breakers. Fee paid.
KEISER, H.W. Pennsylvania Power & Light Co. 85/10/10. 1p. 33036.241-33036.241.

-8510170151 Prop. used changes to Tech Specs 3/4.8.4 re electrical equipment protective devices to support replacements of magnetic-only circuit breakers w/thermal-magnetic breakers.
* Pennsylvania Power & Light Co. 85/10/10. 10pp. 33036.242-33036.251.

8510170201 Requests State of PA, Bureau of Solid Waste Mgt concur w/listed disposal options so State of Pa Dept of Environ Resources can complete review of sewage treatment plant expansion & provide CP.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/10/10. FRITZ, D. Pennsylvania, Commonwealth of. 2pp. 33051.1-33051.358.

8510220113 Forwards Amend 19 to License NPF-22 & safety evaluation. Amend revises Tech Specs by deleting special reporting requirements per NRC 840101 rule change.
BUTLER, W.R. Licensing Branch 2. 85/10/11. CURTIS, N.W. Pennsylvania Power & Light Co. 6pp. 33098.181-33098.192.

-8510220114 Amend 18 to License NPF-22, revising Tech Specs by deleting special reporting requirements per NRC 840101 rule change.
BUTLER, W.R. Licensing Branch 2. 85/10/11. 5pp. 33098.187-33098.192.

-8510220117 Safety evaluation supporting Amend 18 to License NPF-22.
* NRC - No Detailed Affiliation Given. 85/10/11. 2pp. 33098.191-33098.192.

8510220060 Responds to 850924 telcon re update on diesel generator closed cooling sys discharges. Matl safety data sheet for Calgon Product LCS-59 encl.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/10/15. AGUSTINI, D.R. Pennsylvania, Commonwealth of. 6pp. 33095.229-33095.236.

8510280427 Forwards "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Susquehanna Steam Electric Station Unit 1," "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3, Susquehanna, Unit 2" & safety evaluation.
BUTLER, W.R. Licensing Branch 2. 85/10/22. KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 33228.160-33228.178.

-8510280428 Safety evaluation re util response to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 concerning post-maint testing (reactor trip sys components & other safety-related components). Responses acceptable.
* Licensing Branch 2. 85/10/22. 3pp. 33228.170-33228.171.

-8510150484 "Conformance to Generic Ltr 83-28, Items 3.1.3 & 3.2.3 for Susquehanna Steam Electric Station Unit 2."
VANDERBEEK, R. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN D-6002. 85/09/30. NRC - No Detailed Affiliation Given. 7pp. 33228.172-33228.178.

Q. Inspection reports, IE Bulletins & correspondence

8510020073 Forwards Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted.
KISTER, H.B. Region 1, Office of Director. 85/09/19. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32827.141-32827.170.

-8510020080 Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted. Major areas inspected: plant operations, licensee events, open items, surveillance, maint, IE bulletins & TMI action items.
JACOBS, R.H., PLISCO, L.R., STROSNIDER, J. Region 1, Office of Director. 85/09/13. 26pp. 32827.143-32827.170.

8510090188 Forwards Operator Licensing Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator exam. Written & operating exams will be administered on 851120 & 21, respectively.
STAROSTECKI, R. Region 1, Office of Director. 85/09/25. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32947.178-32947.182.

-8510090198 Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator licensing exam. Region agreed to administer one instructor certification & one senior operator exam on 851120 & 21, respectively.
LANGE, D., KELLER, R., KISTER, H. Region 1, Office of Director. 85/09/23. 3pp. 32947.180-32947.182.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230203 Forwards Press Release 84-83 re NRC proposed fine against util for loading fuel bundles & moving control rods in reactor core while sys for monitoring startup inoperable. Three other violations cited.
KAMMERER, C. Office of Congressional Affairs. 84/07/06. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109.016-33109.018.

-8510230304 Forwards Press Release 84-150 of NRC proposed fine against util for alleged inadequate control of operations.
KAMMERER, C. Office of Congressional Affairs. 84/12/19. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. HEINZ Senate. 3pp. 33109.121-33109.123.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177.001-33177.068.

8510230199 Forwards Insp Repts 50-387/85-28 & 50-388/85-23 on 850826-0929 & notice of violation. Response to violation re monthly channel functional tests not including entire channel requested.
KISTER, H.B. Region 1, Office of Director. 85/10/17. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 33101.218-33101.249.

-8510230200 Notice of violation from insp on 850826-0929.
* Region 1, Office of Director. 85/10/17. 1p. 33101.220-33101.220.

-8510230202 Insp Repts 50-387/85-28 & 50-388/85-23 on 850826-0929. Violation noted: Surveillance Procedures SI-152-203, SI-152-201, SI-152-211 & SI-180-205 failed to test entire HPCI channel.
JACOBS, R.H., PLISCO, L.R., STROSNIDER, J. Region 1, Office of Director. 85/10/10. 29pp. 33101.221-33101.249.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177.069-33177.204.

8510280387 Forwards Safety Insp Repts 50-387/85-27 & 50-388/85-22 on 850917-20. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/22. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 33192.149-33192.155.

-8510280388 Insp Repts 50-387/85-27 & 50-388/85-22 on 850917-20. No violations noted. Major areas inspected: measurement control & analytical procedures evaluations.
ZIBULSKY, H., PASCIAK, W.J. Region 1, Office of Director. 85/10/11. 5pp. 33192.151-33192.155.

R. Periodic operating reports & related correspondence

8510010591 Monthly operating repts for Jul 1985 W/850812 ltr.
KUCZYNSKI, L.A., KEISER, H.W. Pennsylvania Power & Light Co. 85/07/31. BEEBE, M.R. Division of Automated Information Services. 24pp. 32830.052-32830.074.

8510020139 Forwards "NPDES Discharge Monitoring Rept for Aug 1985." Info detailing data &/or noncompliances for some permitted outfalls listed.
FIELDS, J.S. Pennsylvania Power & Light Co. 85/09/27. KOVAL, P. Pennsylvania, Commonwealth of. 2pp. 32827.089-32827.107.

-8510020141 "NPDES Discharge Monitoring Rept for Aug 1985."
* Pennsylvania Power & Light Co. 85/08/31. 17pp. 32827.091-32827.107.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230203 Forwards Press Release 84-83 re NRC proposed fine against util for loading fuel bundles & moving control rods in reactor core while sys for monitoring startup inoperable. Three other violations cited.
KAMMERER, C. Office of Congressional Affairs. 84/07/06. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109.016-33109.018.

-8510230304 Forwards Press Release 84-150 of NRC proposed fine against util for alleged inadequate control of operations.
KAMMERER, C. Office of Congressional Affairs. 84/12/19. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109.121-33109.123.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832.352-32832.353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832.354-32833.001.

8510090188 Forwards Operator Licensing Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator exam. Written & operating exams will be administered on 851120 & 21, respectively.
STAROSTECKI, R. Region 1, Office of Director. 85/09/25. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32947.178-32947.182.

-8510090198 Meeting Repts 50-387/85-29 & 50-388/85-24 on 850828 re rescheduling of senior reactor operator licensing exam. Region agreed to administer one instructor certification & one senior operator exam on 851120 & 21, respectively.
LANGE, D. Region 1, Office of Director. 85/09/23. 3pp. 32947.180-32947.182.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510220142 Advises of 851021-23 training review at facility. Tasks will include formal & continuing training, on-the-job & emergency training, instructions/procedures & documentation listed.
BUTLER,W.R. Licensing Branch 2. 85/10/15. KEISER,H.W. Pennsylvania Power & Light Co. 4pp. 33096-166-33096-169.

DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510080279 Forwards Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20. No deviations or violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/03. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 32918-359-32918-360.

-8510080288 Physical Security Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20. No violations noted. Major areas inspected: mgt effectiveness & security program. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS,J.D. Region 2, Office of Director. 85/10/01. 1p. 32918-361-32918-361.

8510150324 Revised emergency plan implementing procedures, including 1101, "Duties of Emergency Control Officer, Offsite Emergency Organization" & 1102, "Duties of Recovery Manager, Offsite Emergency Organization." W/851004 ltr.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/04. 51pp. 33009-001-33009-051.

8510150385 Rev 5 to Emergency Plan Implementing Procedure 3100034E, "Maintaining Emergency Preparedness - Radiological Emergency Plan Training." W/851004 ltr.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/04. GRACE,J.N. Region 2, Office of Director. 9pp. 33010-156-33010-164.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/04. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33096-332-33096-335.

-8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY,W. Region 2, Office of Director. 85/09/26. 2pp. 33096-334-33096-335.

8510180426 Forwards Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violations or deviations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/09. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33056-329-33056-338.

-8510180429 Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violation or deviation noted. Major areas inspected: Tech Spec compliance, operator performance, QA practices & site security procedures.
CRLENJAK,R.V. Region 2, Office of Director. 85/10/08. 8pp. 33056-331-33056-338.

P. Operating license stage documents & correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABEI,L. Government Accountability Project. 32pp. 32884-005-32884-234.

-8510020191 Rev 0 to Procedure 753-ET-1, "Environ Test Plan for Device Qualification to IEEE 323-1971."
MARROW,R. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/09/15. 6pp. 32890-035-32890-040.

8510070265 Inform that C-E redoing facility large break LOCA analysis & results expected to be available by 860131.
WILLIAMS,J.W. Florida Power & Light Co. 85/09/30. THOMPSON,H.L. Division of Licensing. 1p. 32877-314-32877-314.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 18pp. 33091-135-33091-150.

8510180087 Forwards response to 850429 request for addl info on Generic Ltr 83-28, Item 1.1 re post-trip review. Revised procedures re post-trip review & responsibilities of shift technical advisor encl.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/11. BUTCHER,E.J. Operating Reactors Branch 3. 3pp. 33063-122-33063-155.

-8510180090 Rev 2 to Operating Procedure 0030119, "Post-Trip Review."
BARROW,J.H., SAGER,D.A. Florida Power & Light Co. 85/06/26. 13pp. 33063-125-33063-137.

-8510180096 Rev 6 to Procedure 0065725, "Duties & Responsibilities of Shift Technical Advisor."
BARROW,J.H., SAGER,D.A. Florida Power & Light Co. 85/07/03. 19pp. 33063-138-33063-155.

8510180070 Inform that util will provide NRC w/compliance schedule for ATWS rule 90 days after NRC review of C-E Owners Group approach.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/14. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33063-093-33063-093.

8510230123 Forwards addl info in response to Generic Ltr 85-02 re Category C-2 steam generator tube insps. Insp program in compliance w/expanded insp requirements of C-2. Addl tubes inspected on case-by-case basis.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/16. THOMPSON,H.L. Division of Licensing. 2pp. 33102-210-33102-211.

8510280313 Forwards Amend 11 to License NPF-16 & safety evaluation. Amend modifies surveillance requirements of pressurizer re reconnection of pressurizer heaters to respective buses.
SELLS,D.E. Operating Reactors Branch 3. 85/10/17. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33196-351-33196-358.

-8510280318 Amend 11 to License NPF-16, revising Tech Specs re surveillance requirements for pressurizer re reconnection of pressurizer heaters to respective buses.
BUTCHER,E.J. Operating Reactors Branch 3. 85/10/17. 5pp. 33196-353-33196-357.

-8510280344 Safety evaluation supporting Amend 11 to License NPF-16.
* Office of Nuclear Reactor Regulation, Director. 85/10/17. 2pp. 33196-358-33196-359.

8510240173 Advises that util will provide response to NRC 850621 & 0711 requests for info re relief & safety valve test requirements per TMI Item II.D.1 by 860315.
WILLIAMS,J.N. Florida Power & Light Co. 85/10/18. BUTCHER,E.J. Operating Reactors Branch 3. 1p. 33155-265-33155-265.

8510310523 Advises of completion of review of util 831108 response to Generic Ltr 83-28, Items 3.13 & 3.2.3. Post-maint test requirement reviews should be factored into future Tech Spec changes to assure level of safety not degraded.
BUTCHER,E.J. Operating Reactors Branch 3. 85/10/25. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33278-352-33278-353.

Q. Inspection reports, IE Bulletins & correspondence

8510180091 Forwards Insp Repts 50-335/85-23 & 50-389/85-23 on 850826-30. No violation or deviation noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/09/20. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33054-134-33054-142.

-8510180103 Insp Repts 50-335/85-23 & 50-389/85-23 on 850826-30. No violation or deviation noted. Major areas inspected: plant chemistry & inservice testing of pumps & valves.
ROSS,W.J., BLAKE,J.J. Region 2, Office of Director. 85/09/17. 7pp. 33054-136-33054-142.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080279 Forwards Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20. No deviations or violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/03. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 32918-359-32918-360.

-8510080288 Physical Security Insp Repts 50-335/85-24 & 50-389/85-24 on 850916-20. No violations noted. Major areas inspected: mgt effectiveness & security program. Details withheld (ref 10CFR2.790(d) & 73.21).
ENNIS,J.D., MCGUIRE,D.R. Region 2, Office of Director. 85/10/01. 1p. 32918-361-32918-361.

8510180178 Responds to NRC ltr re violations noted in Insp Repts 50-335/85-20 & 50-389/85-20. Corrective actions engineering requested to examine circuit changes which allow ground checks w/o effort on plant operations.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/04. GRACE,J.N. Region 2, Office of Director. 2pp. 33059-342-33059-343.

8510220387 Forwards Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/04. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33096-332-33096-335.

-8510220396 Insp Repts 50-250/85-29, 50-251/85-29, 50-335/85-22 & 50-389/85-22 on 850819-21. No violations noted. Major areas inspected: emergency preparedness, emergency response facilities & NRC Response Team coordination.
STANSBERRY,W. Region 2, Office of Director. 85/09/26. 2pp. 33096-334-33096-335.

8510180426 Forwards Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violations or deviations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/09. WILLIAMS,J.W. Florida Power & Light Co. 2pp. 33056-329-33056-338.

-8510180429 Insp Repts 50-335/85-21 & 50-389/85-21 on 850813-0923. No violation or deviation noted. Major areas inspected: Tech Spec compliance, operator performance, QA practices & site security procedures.
CRLENJAK,R.V., BIBB,H.E., ELROD,S.A. Region 2, Office of Director. 85/10/08. 8pp. 33056-331-33056-338.

8510150022 IE Info Notice 85-060, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510230123 Forwards addl info in response to Generic Ltr 85-02 re Category C-2 steam generator tube insps. Insp program in compliance w/expanded insp requirements of C-2. Addl tubes inspected on case-by-case basis.
WILLIAMS,J.W. Florida Power & Light Co. 85/10/16. THOMPSON,H.L. Division of Licensing. 2pp. 33102-210-33102-211.

8510150025 IE Info Notice 85-081, "Prob. Ins. Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

178 DOCKETED ITEMS

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 850103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510010477 Monthly operating repts for Jul 1985 W/850814 ltr.
GRANT, N.W. Florida Power & Light Co. 85/07/31. 18pp. 32809-082-32809-099.

S. Reportable occurrences, LERs & related correspondence

8510150210 LER 85-009-00 on 850910, high vibrations occurred on reactor coolant pump 2A2, causing manual trip. Caused by pump vibration permitting oil slinger ring to break free & damaged oil seal in oil reservoir W/851010 ltr.
WILLIAMS, D.M., WILLIAMS, J.W. Florida Power & Light Co. 85/10/08. 4pp. 33015-057-33015-060.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.

-8510010428 Power plant exam results summary sheets. Info deleted.
* Public Service Electric & Gas Co. of New Jersey. * Southern California Edison Co. * South Carolina Electric & Gas Co. 85/09/20. 9pp. 32832-355-32833-001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr W/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510040622 Confirms 850920 telcon w/WT Cottle concerning 850925 mgt meeting at Region II ofc to discuss TVA employee concerns re program for renewal of welder certification at facility.
WALKER, R.D. Region 2, Office of Director. 85/09/24. PARRIS, H.G. Tennessee Valley Authority. 1p. 32866-072-32866-072.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr. Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510080465 Forwards revised Apps B.C. & D re summary listing of valves, relief requests & cold shutdown justifications, respectively, for inservice testing program for pumps & valves. Summary of changes incorporated in repts provided.
SHELL, R.H. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 55pp. 32920-079-32920-132.

8510090012 Forwards description of fifth vital battery sys being installed to provide backup standby power to four vital dc channels. Sys scheduled for operation by Unit 2 fuel loading. FSAR amend will be submitted by 860115.
DOMER, J.A. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 5pp. 32934-357-32934-362.

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRR completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949-162-32949-166.

-8509030152 Informs that 850819 memo re "fects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949-167-32949-167.

8510150252 Forwards safety evaluation of util request for Tech Spec mods re reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
NOVAK, T.M. Assistant Director for Licensing. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33032-213-33032-216.

-8510150255 Safety evaluation re util request for Tech Spec mods for reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
* NRC - No Detailed Affiliation Given. 85/10/07. 2pp. 33032-215-33032-216.

8510160139 Notifies of plans to install ATWS mitigating sys actuation circuitry & await SER issuance on Westinghouse Technical Bulletin WCAP-10858, to meet 10CFR50.62(C)(1-5) requirements.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33023-230-33023-231.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

-8510170215 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities'..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-12. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044-231-33044-245.

8510310612 Summarizes 850925 mgt meeting in Region II ofc addressing employee concerns re program for renewal of welder certification at facility. Training program meets ASME Code requirements. Attendance list & transcript of meeting encl.
WALKER, R.D. Region 2, Office of Director. 85/10/15. PARRIS, H.G. Tennessee Valley Authority. 5pp. 33280-046-33280-176.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085-157-33086-052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193-185-33193-237.

8510290097 Forwards marked-up FSAR pages, including repts to Table 14.2-1 re pre-operational testing of addl diesel generator. Changes will be included in upcoming Amend 56 to FSAR.
DOMER, J.A. Tennessee Valley Authority. 85/10/21. ADENSAM, E. Licensing Branch 4. 13pp. 33235-302-33235-314.

8510300021 Proposes meeting w/NRC during wk of 851104 to discuss welding program & related employee concerns re safety issues.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/25. ADENSAM, E. Licensing Branch 4. 1p. 33247-142-33247-142.

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 58pp. 32834-229-32834-349.

8510040132 Forwards 850814, 21, 28 & 0904 & 11 PHYSI-14 surveillance instruction test results on fire protection: sys. Failure of 7-day functional test on 850821 was result of one fence sector not detecting. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32850-351-32850-351.

8510010379 Forwards addl info justifying use of saturation temp indication in auxiliary control room to infer cold leg temp. per NRC concerns discussed during 850307 meeting.
DOMER, J.A. Tennessee Valley Authority. 85/09/26. ADENSAM, E. Licensing Branch 4. 22pp. 32801-233-32801-254.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. 14pp. 33010-272-33010-284.

8510220196 Forwards Rev 2 to EQTP(84)-019, "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks," as final response to request for info re SPDS.
DOMER, J.A. Tennessee Valley Authority. 85/10/16. ADENSAM, E. Licensing Branch 4. 2pp. 33087-263-33087-283.

-8510220199 Rev 2 to "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks."
KEENER, E.L., RILING, R.W., ALBENS, C. Tennessee Valley Authority. EQTP(84)-019 R02. 85/09/26. 19pp. 33087-265-33087-283.

8510290012 Forwards 850918, 25, 1002 & 09 PHYSI-14 surveillance instruction test results on FPS-2 sys. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235-001-33235-001.

8510310164 Forwards physical security plan, including test procedures, test data & results, alarm logs, daily environ conditions, guard/sys interaction data & sensitivity changes of fence-mounted sys. Encls withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 3pp. 33273-264-33273-266.

8510310259 Advises of inability to meet requirement in 10CFR50, App. E, IV.D.2 for yearly dissemination of emergency info brochure. Delay caused by mailing during May 1984 instead of Aug 1984 & changes in evacuation routes. Revised info mailed 850920.
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 2pp. 33273-272-33273-273.

H. General correspondence

8510250318 Informs that resolution of congressional inquiry on TVA BDO Control 001048 handled by F. Combs via 851004 telcon w/ H. Myers. Myers accepted explanation that administrative error responsible for deleting encl in ltr sent to TVA.
NOVAK, T.M. Assistant Director for Licensing. 85/10/16. REHM, T. Office of the Executive Director for Operations. 4pp. 33226-131-33226-140.

8510250323 Informs that Committee on Interior & Insular Affairs requested add info re 850926 ltr to TVA.
KAMMERER, C. Office of Congressional Affairs. 85/10/01. REHM, T. Office of the Executive Director for Operations. 1p. 33226-135-33226-135.

8510250329 Requests existing info re resolution of concerns prior to low power licensing ltr forwarded to TVA on 850926 did not include Encl 2, "Concerns Issues Requiring Resolution Prior to Low Power Licensing."
MYERS, H. Affiliation Not Assigned. 85/09/27. DIRCKS, B., KAMMERER, C. NRC - No Detailed Affiliation Given. 5pp. 33226-136-33226-140.

J. Insurance & indemnity information

8510080084 Forwards Endorsements 29 & 30 to NELIA Policy NF-256.
FIELDER, J. Marsh & McLennan, Inc. 85/09/20. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 32920-250-32920-252.

G. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 66pp. 32834-229-32834-349.

8510040148 Forwards Insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29 & notice of violation identification & remedy of root cause of Violation 1 requested.
WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32867-104-32867-119.

8510040151 Notice of violation from insp on 850819-23 & 29.
* Region 2, Office of Director. 85/09/25. 2pp. 32867-106-32867-107.

8510040160 Insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29. Violation noted: failure to establish adequate measures to control storage of valves & failure to follow HVAC fabrication, installation & insp procedures.
KLEINSORGE, W.P., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 12pp. 32867-108-32867-119.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803-095-32803-125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803-099-32803-125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sucking of A9CO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510210265 Informs that actions re Insp Rept 50-390/85-32 concerning reactor protection sys P-10 permissive bistable trip setpoint & reset values meet intent of Tech Specs based on discussions w/ T. Dunning of NRR.
WALKER, R.D. Region 2, Office of Director. 85/10/01. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33094-341-33094-344.

8510180468 Ask receipt of 850911 second supplemental response informing NRC of steps taken to correct violations noted in Insp Repts 50-390/85-33 & 50-391/85-28.
VERRELLI, D.M. Region 2, Office of Director. 85/10/04. PARRIS, H.G. Tennessee Valley Authority. 1p. 33068-063-33068-063.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading w/ Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280147 Informs of 851022 mgt meeting w/ NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191-073-33191-074.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982 per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABE, L. Government Accountability Project. 32pp. 32884-005-32884-234.

8510010388 Forwards 10CFR50.55(e)/Part 21 rept from TVA re generic problem w/ hydrogen detection sys integrity. Followup on generic aspects w/ AE/vendor requested. Supporting documentation encl.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15. Region 4, Dallas, Vendor Inspection Branch. 32pp. 32884-241-32884-206.

8510010402 Advises that listed Comsip, Inc. Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl.
POTAPOVS, U. Vendor Inspection Branch. 81/07/01. LEWIS, R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885-209-32885-217.

8510030278 Third interim deficiency rept re cable insulation failing fire protection test. Initially reported on 840405. Computerized cable schedule modified to change to qualified replacement-type cable. Next rept expected by 850606.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/18. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-252-32845-253.

8510030280 Part 21 & final deficiency rept re potentially excessive indication errors in reactor vessel level instrumentation sys. Initially reported on 850823. Corrective mods will be completed for Unit 1 by 851130.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-254-32845-255.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants.
STAHL, C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078-256-33078-361.

8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078-260-33078-361.

8510310612 Summarizes 850925 mgt meeting in Region II of addressing employee concerns re program for renewal of welder certification at facility. Training program meets ASME Code requirements. Attendance list & transcript of meeting encl.
WALKER, R.D. Region 2, Office of Director. 85/10/15. PARRIS, H.G. Tennessee Valley Authority. 5pp. 33280-046-33280-176.

8510310613 Transcript of 850925 meeting w/ util in Atlanta, GA re concerns & issues arising from welding certification procedures at facility. Pp 1-126.
* Region 2, Office of Director. 85/09/25. 126pp. 33280-051-33280-176.

V. Operator Examinations

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510220008 Informs that operator & senior operator exams scheduled for wk of 851111 tentatively delayed until 860331 in order to conduct exams as close as possible to postponed fuel loading date. Applications returned under separate cover.
VERRELLI, D.M. Region 2, Office of Director. 85/09/30. PARRIS, H.G. Tennessee Valley Authority. 1p. 33095-324-33095-324.

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510150462 Forwards Tri-State Edison response to 850814 ltr re 850809 loss of feed-water event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr w/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510240622 Confirms 850920 telcon w/ WT Cottle concerning 850925 mgt meeting at Region II of discussing TVA employee concerns re program for renewal of welder certification at facility.
WALKER, R.D. Region 2, Office of Director. 85/09/24. PARRIS, H.G. Tennessee Valley Authority. 1p. 32866-072-32866-072.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

180 DOCKETED ITEMS

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr. Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919:123-32919:144.

8510080455 Forwards revised Apps B,C & D re summary listing of valves, relief requests & cold shutdown justifications, respectively, for inservice testing program for pumps & valves. Summary of changes incorporated in revs provided.
SHELL, R.H. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 55pp. 32920:079-32920:133.

8510090012 Forwards description of fifth vital battery sys being installed to provide backup standby power to four vital dc channels. Sys scheduled for operation by Unit 2 fuel loading. FSAR amend will be submitted by 860115.
DOMER, J.A. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 5pp. 32934:357-32934:362.

8510090340 Responds to 850826 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRC completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949:162-32949:166.

8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949:167-32949:167.

8510150252 Forwards safety evaluation of util request for Tech Spec mods re reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
NOVAK, T.M. Assistant Director for Licensing. 85/10/07. PARRIS, H.G. Tennessee Valley Authority. 2pp. 33032:213-33032:216.

8510150255 Safety evaluation re util request for Tech Spec mods for reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
* NRC - No Detailed Affiliation Given. 85/10/07. 2pp. 33032:215-33032:216.

8510160139 Notifies of plans to install ATWS mitigating sys actuation circuitry & await SER issuance on Westinghouse Technical Bulletin WCAP-10858 to meet 10CFR50.62(C)(1-5) requirements.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33023:230-33023:231.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

8510170215 Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), item 1.2, "Post-Trip Review Data & Info Capabilities", technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-00-82-096. SAIC-85/1523-12. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:231-33044:245.

8510160112 Summarizes 850925 mgt meeting in Region II of addressing employee concerns re program for renewal of welder certification at facility. Training program meets ASME Code requirements. Attendance list & transcript of meeting encl.
WALKER, R.D. Region 2, Office of Director. 85/10/15. PARRIS, H.G. Tennessee Valley Authority. 5pp. 33260:046-33260:176.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 8510x/ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 25pp. 33085:157-33086:052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193:185-33193:237.

8510290097 Forwards marked-up FSAR pages, including revs to Table 14.2-1 re pre-operational testing of addl diesel generator. Changes will be included in upcoming Amend 56 to FSAR.
DOMER, J.A. Tennessee Valley Authority. 85/10/21. ADENSAM, E. Licensing Branch 4. 13pp. 33235:302-33235:314.

8510300021 Proposes meeting w/NRC during wk of 851104 to discuss welding program & related employee concerns re safety issues.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/25. ADENSAM, E. Licensing Branch 4. 1p. 33247:142-33247:142.

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32634:210-32634:349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32634:229-32634:349.

8510040132 Forwards 850814, 21, 28 & 0904 & 11 PHYSI-14 surveillance instruction: test results on fire protection sys. Failure of 7-day functional test on 850821 was result of one fence sector not detecting. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32850:301-32850:351.

8510010379 Forwards addl info justifying use of saturation temp indication in auxiliary control room to infer cold leg temp, per NRC concerns discussed during 850307 meeting.
DOMER, J.A. Tennessee Valley Authority. 85/09/26. ADENSAM, E. Licensing Branch 4. 22pp. 32601:233-32601:254.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851006 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. 14pp. 33010:272-33010:284.

8510210196 Forwards Rev 2 to EQTP(84)-019, "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks," as final response to request for info re SPDS.
DOMER, J.A. Tennessee Valley Authority. 85/10/16. ADENSAM, E. Licensing Branch 4. 2pp. 33087:263-33087:263.

8510220199 Rev 2 to "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks."
KEENER, E.L., RILING, R.W., ALBENSI, C. Tennessee Valley Authority. EQTP(84)-019 R02. 85/09/26. 19pp. 33087:265-33087:283.

8510290012 Forwards 850918, 25, 1002 & 09 PHYSI-14 surveillance instruction test results on FPS-2 sys. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235:001-33235:001.

8510310184 Forwards physical security plan, including test procedures, test data & results, alarm logs, daily environ conditions, guard/sys interaction data & sensitivity changes of fence-mounted sys. Encls withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 3pp. 33273:264-33273:266.

8510310259 Advises of inability to meet requirement in 10CFR50, App E, IV.D.2 for yearly dissemination of emergency info brochure. Delay caused by mailing during May 1984 instead of Aug 1984 & changes in evacuation routes. Revised info mailed 850920.
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 2pp. 33273:272-33273:273.

H. General correspondence

8510250318 Informs that resolution of congressional inquiry on TVA BDO Control 001048 handled by F Combs via 851004 telcon w/H Myers. Myers accepted explanation that administrative error responsible for deleting encl in ltr sent to TVA.
NOVAK, T.M. Assistant Director for Licensing. 85/10/16. REHM, T. Office of the Executive Director for Operations. 4pp. 33226:131-33226:140.

8510250323 Informs that Committee on Interior & Insular Affairs requested addl info re 850926 ltr to TVA.
KAMMERER, C. Office of Congressional Affairs. 85/10/01. REHM, T. Office of the Executive Director for Operations. 1p. 33226:135-33226:135.

8510250329 Requests existing info re resolution of concerns prior to low power licensing. Ltr forwarded to TVA on 850926 did not include Encl 2, "Concerns Issues Requiring Resolution Prior to Low Power Licensing."
MYERS, H. Affiliation Not Assigned. 85/09/27. DIRCKS, B., KAMMERER, C. NRC - No Detailed Affiliation Given. 5pp. 33226:136-33226:140.

J. Insurance & indemnity information

8510080084 Forwards Endorsements 29 & 30 to NELIA Policy NF-256.
FIELDER, J. Marsh & McLennan, Inc. 85/09/20. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 32920:250-32920:252.

Q. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32634:210-32634:349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32634:229-32634:349.

8510040146 Forwards insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29 & notice of violation quantification & remedy of root cause of violation 1 requested.
WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32667:104-32667:119.

8510040151 Notice of violation from insp on 850819-23 & 29.
* Region 2, Office of Director. 85/09/25. 2pp. 32667:106-32667:107.

8510040160 Insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29. Violation noted: failure to establish adequate measures to control storage of valves & failure to follow HVAC fabrication, installation & insp procedures.
KLEINSORGE, W.P., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 12pp. 32667:108-32667:119.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 7pp. 32803:095-32803:125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

180 DOCKETED ITEMS

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr. Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919:123-32919:144.

8510080465 Forwards revised Apps B,C & D re summary listing of valves, relief requests & cold shutdown justifications, respectively, for inservice testing program for pumps & valves. Summary of changes incorporated in revs provided.
SHELL, R.H. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 55pp. 32920:079-32920:133.

8510090012 Forwards description of fifth vital battery sys being installed to provide backup standby power to four vital dc channels. Sys scheduled for operation by Unit 2 fuel loading. FSAR amend will be submitted by 860115.
DOMER, J.A. Tennessee Valley Authority. 85/10/03. ADENSAM, E. Licensing Branch 4. 5pp. 32934:357-32934:362.

8510090340 Responds to 850828 concerns that procedures in draft Manual Chapter 0514 not followed in addressing util 850604 backfit claim. NRC completed actions within stipulated 3-wk time frame. IE concurrence delayed NRC response.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. STELLO, V. Regional Operations & Generic Requirements. 5pp. 32949:162-32949:166.

8509030152 Informs that 850819 memo reflects correct determination re plant-specific backfits. Actions necessary to implement backfit controls consistent w/Manual Chapter 0514 requested.
STELLO, V. Regional Operations & Generic Requirements. 85/08/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32949:167-32949:167.

8510150252 Forwards safety evaluation of util request for Tech Spec mods re reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
NOVAK, T.M. Assistant Director for Licensing. 85/10/07. PARRIS, H.G. Tenn. see Valley Authority. 2pp. 33032:213-33032:216.

8510150255 Safety evaluation re util request for Tech Spec mods for reactor coolant sys & charging pump flow. Proposed mod involving reactor coolant sys at shutdown unacceptable. Addl info &/or commitments needed prior to approval.
* NRC - No Detailed Affiliation Given. 85/10/07. 2pp. 33032:215-33032:216.

8510160139 Notifies of plans to install ATWS mitigating sys actuation circuitry & await SER issuance on Westinghouse Technical Bulletin WCAP-10856 to meet 10CFR50.62(C)(1-5) requirements.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33023:230-33023:231.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

8510170215 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' ..., technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-12. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:231-33044:245.

8510310612 Summarizes 850925 mgt meeting in Region II ofc addressing employee concerns re program for renewal of welder certification at facility. Training program meets ASME Code requirements. Attendance list & transcript of meeting encl.
WALKER, R.D. Region 2, Office of Director. 85/10/15. PARRIS, H.G. Tennessee Valley Authority. 5pp. 33290:046-33290:176.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085:157-33086:052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193:185-33193:237.

851290097 Forwards marked-up FSAR pages, including revs to Table 14.2-1 re pre-operational testing of addl diesel generator. Changes will be included in upcoming Amend 56 to FSAR.
DOMER, J.A. Tennessee Valley Authority. 85/10/21. ADENSAM, E. Licensing Branch 4. 13pp. 33235:302-33235:314.

8510300021 Proposes meeting w/NRC during wk of 851104 to discuss welding program & related employee concerns re safety issues.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/25. ADENSAM, E. Licensing Branch 4. 1p. 33247:142-33247:142.

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834:210-32834:349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834:229-32834:349.

8510040132 Forwards 850814, 21, 28 & 0902 & 11 PHYSI-14 surveillance instruction test results on fire protection sys. Failure of 7-day functional test on 850821 was result of one fence sector not detecting. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32850:351-32850:351.

8510010379 Forwards addl info justifying use of saturation temp indication in auxiliary control room to infer cold leg temp, per NRC concerns discussed during 850307 meeting.
DOMER, J.A. Tennessee Valley Authority. 85/09/26. ADENSAM, E. Licensing Branch 4. 22pp. 32801:233-32801:254.

8510150174 Rev 3 to Central Emergency Control Ctr Implementing Procedure IP-9, incorporating Attachment 14, "Instructions for Collecting Environ Samples." W/851008 ltr.
HUFHAM, J.W. Tennessee Valley Authority. 85/10/08. 14pp. 33010:272-33010:284.

8510220196 Forwards Rev 2 to EQTP(84)-019, "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks," as final response to request for info re SPDS.
DOMER, J.A. Tennessee Valley Authority. 85/10/16. ADENSAM, E. Licensing Branch 4. 2pp. 33087:263-33087:283.

8510220199 Rev 2 to "Isolation Tests for Westinghouse Type AR Relays Used in Auxiliary Relay Racks."
KEENER, E.L., RILING, R.W., ALBENSI, C. Tennessee Valley Authority. EQTP(84)-019 R02. 85/09/26. 19pp. 33087:265-33087:233.

8510290012 Forwards 850918, 25, 1002 & 09 PHYSI-14 surveillance instruction test results on FPS-2 sys. Results withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235:001-33235:001.

8510310184 Forwards physical security plan, including test procedures, test data & results, alarm logs, daily environ conditions, guard/sys interaction data & sensitivity changes of fence-mounted sys. Encls withheld (ref 10CFR73.21).
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 3pp. 33273:264-33273:266.

8510310259 Advises of inability to meet requirement in 10CFR50, App E, IV.D.2 for yearly dissemination of emergency info brochure. Delay caused by mailing during May 1984 instead of Aug 1984 & changes in evacuation routes. Revised info mailed 850920.
DOMER, J.A. Tennessee Valley Authority. 85/10/23. ADENSAM, E. Licensing Branch 4. 2pp. 33273:272-33273:273.

H. General correspondence

8510250318 Informs that resolution of congressional inquiry on TVA BDO Control 001048 handled by F Combs via 851004 telcon w/H Myers. Myers accepted explanation that administrative error responsible for deleting encl in ltr sent to TVA.
NOVAK, T.M. Assistant Director for Licensing. 85/10/16. REHMT, T. Office of the Executive Director for Operations. 4pp. 33226:131-33226:140.

8510250323 Informs that Committee on Interior & Insular Affairs requested addl info re 850926 ltr to TVA.
KAMMERER, C. Office of Congressional Affairs. 85/10/01. REHMT, T. Office of the Executive Director for Operations. 1p. 33226:135-33226:135.

8510250329 Requests existing info re resolution of concerns prior to low power licensing ltr forwarded to TVA on 850926 did not include Encl 2, "Concerns Issues Requiring Resolution Prior to Low Power Licensing."
MYERS, H. Affiliation Not Assigned. 85/09/27. DIRCKS, B., KAMMERER, C. NRC - No Detailed Affiliation Given. 5pp. 33226:136-33226:140.

J. Insurance & indemnity information

85100804 Forwards Endorsements 29 & 30 to NELIA Policy 14F-256.
FIELDER, J. Marsh & McLennan, Inc. 85/09/20. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 32920:250-32920:252.

Q. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834:210-32834:349.

8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985. Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834:229-32834:349.

8510040146 Forwards Insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29 & notice of violation identification & remedy of root cause of violation 1 requested.
WALKER, R.D. Region 2, Office of Director. 85/09/25. PARRIS, H.G. Tennessee Valley Authority. 2pp. 32867:104-32867:119.

8510040151 Notice of violation from insp on 850819-23 & 29.
* Region 2, Office of Director. 85/09/25. 2pp. 32867:106-32867:107.

8510040160 Insp Repts 50-390/85-52 & 50-391/85-42 on 850819-23 & 29. Violation noted: failure to establish adequate measures to control storage of valves & failure to follow HVAC fabrication, installation & insp procedures.
KLEINSORGE, W.P., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 12pp. 32867:108-32867:119.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint.Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180468 Ack receipt of 850911 second supplemental response informing NRC of steps taken to correct violations noted in Insp Repts 50-390/85-33 & 50-391/85-26.
VERRELLI,D.M. Region 2, Office of Director. 85/10/04. PARRIS,H.G. Tennessee Valley Authority. 1p. 33068-063-33068-063.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Parasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510260147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action per NRC 850917 suggestion.
DEAN,C.H. Tennessee Valley Authority. 85/10/18. DIRCKS,W.J. Office of the Executive Director for Operations. 3pp. 33191-073-33191-074.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982 per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABEI,L. Government Accountability Project. 32pp. 32884-005-32884-234.

-8510010368 Forwards 10CFR50.55(e)/Part 21 rept from TVA re generic problem w/ hydrogen deflection sys integrity. Followup on generic aspects w/AE/vendor requested. Supporting documentation encl.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15. Region 4, Dallas, Vendor Inspection Branch. 327pp. 32884-241-32885-206.

-8510010402 Advises that listed Consip, Inc. Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl.
POTAPOVS,U. Vendor Inspection Branch. 81/07/01. LEWIS,R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885-209-32885-217.

8510030278 Third interim deficiency rept re cable insulation failing fire protection test. Initially reported on 840405. Computerized cable schedule modified to change to qualified replacement-type cable. Next rept expected by 860606.
HUFHAM,J.W. Tennessee Valley Authority. 85/09/18. GRACE,J.N. Region 2, Office of Director. 2pp. 32845-252-32845-253.

8510030280 Part 21 & final deficiency rept re potentially excessive indication errors in reactor vessel level instrumentation sys. Initially reported re 850823. Corrective mods wll be completed for Unit 1 by 851130.
HUFHAM,J.W. Tennessee Valley Authority. 85/09/20. GRACE,J.N. Region 2, Office of Director. 2pp. 32845-254-32845-255.

T. Hearing transcripts on non-antitrust matters

8510180495 Forwards transcript of 850916 meeting in Bethesda, MD re environ qualification at plants.
STAHLE,C. Licensing Branch 4. 85/10/09. Licensing Branch 4. 4pp. 33078-256-33078-361.

-8510180503 Transcript of 850916 meeting in Bethesda, MD re environ qualification at TVA plants. Pp 1-100.
* NRC - No Detailed Affiliation Given. 85/09/16. 103pp. 33078-260-33078-361.

8510310612 Summarizes 850925 mgt meeting in Region II of addressing employee concerns re program for renewal of welder certification at facility. Training program meets ASME Code requirements. Attendance list & transcript of meeting encl.
WALKER,R.D. Region 2, Office of Director. 85/10/15. PARRIS,H.G. Tennessee Valley Authority. 5pp. 33280-046-33280-176.

-8510310613 Transcript of 850925 meeting w/util in Atlanta, GA re concerns & issues arising from welding certification procedures at facility. Pp 1-126.
* Region 2, Office of Director. 85/09/25. 126pp. 33280-051-33280-176.

V. Operator Examinations

8509240246 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510220006 Informs that operator & senior operator exams scheduled for wk of 851111 tentatively delayed until 860331 in order to conduct exams as close as possible to postponed fuel loading date. Applications returned under separate cover.
VERRELLI,D.M. Region 2, Office of Director. 85/09/30. PARRIS,H.G. Tennessee Valley Authority. 1p. 33095-324-33095-324.

DOCKET 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510240305 Rev 5 to Emergency Plan Procedure EPP-020, "Emergency Personnel Exposure Control." W/851022 ltr.
COUNTS,M., BRADHAM,O.S., DIXON,O.W. South Carolina Electric & Gas Co. 85/10/22. GRACE,J.N. Region 2, Office of Director. 13pp. 33154-185-33154-197.

P. Operating license stage documents & correspondence

8510040416 Forwards Amend 45 to License NPF-12 & safety evaluation. Amend modifies Tech Specs to reflect 1.9% reduction in thermal design flow.
ADENSAM,E.G. Licensing Branch 4. 85/09/25. DIXON,O.W. South Carolina Electric & Gas Co. 3pp. 32860-015-32860-033.

-8510040418 Amend 45 to License NPF-12, modifying Tech Specs to reflect 1.9% reduction in thermal design flow.
ADENSAM,E.G. Licensing Branch 4. 85/09/25. 12pp. 32860-018-32860-029.

-8510040419 Safety evaluation supporting Amend 45 to License NPF-12.
* Office of Nuclear Reactor Regulation, Director. 85/09/25. 4pp. 32860-030-32860-033.

8510030041 Responds to 850802 request for addl info to support staff review of Generic Ltr 83-28, "Required Actions Based on Implications of Salem ATWS Events." Items 4.2.1 & 4.2.2. Surveillance testing procedures will be revised.
DIXON,O.W. South Carolina Electric & Gas Co. 85/10/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32842-272-32842-273.

8510160129 Submits proposed schedule for meeting requirements of 10CFR50.62 re reduction of risk from ATWS events for light water cooled nuclear power plants, per Generic Ltr 85-06, "Nonsafety-Related ATWS Equipment."
DIXON,O.W. South Carolina Electric & Gas Co. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33023-226-33023-227.

8510230141 Application for amend to License NPF-12, revising Tech Spec 3/4.4.5, "Steam Generators." Forwards proprietary WCAP 10949, nonproprietary WCAP 1050 & no significant hazards determination. Proprietary encl withheld (ref 10CFR2.790).
DIXON,O.W. South Carolina Electric & Gas Co. 85/10/16. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33103-302-33103-349.

-8510230147 Proposed Tech Spec 3/4.4.5, "Steam Generators," revising tube plugging limit definition & permitting repair of defective tubes using NRC approved method.
* South Carolina Electric & Gas Co. 85/10/16. 3pp. 33103-304-33103-306.

-8510230155 Requests withholding proprietary rept re tubesheet region plugging criterion for full depth hardroll expanded tubes, from public disclosure (ref 10CFR2.790).
WIESEMANN,R.A. Westinghouse Electric Corp. 85/10/09. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 10pp. 33103-307-33103-316.

-8510230162 Nonproprietary WCAP 10950, "Tubesheet Region Plugging Criterion for Full Depth Hardroll Expanded Tubes."
* Westinghouse Electric Corp. WCAP 10950. 85/09/30. 33pp. 33103-317-33103-349.

8510240222 Application for amend to License NPF-12, revising Tech Specs to ensure appropriate conservative requirements maintained in event of boron dilution event in Modes 3, 4 & 5.
DIXON,O.W. South Carolina Electric & Gas Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33155-248-33155-249.

-8510240234 Proposed Tech Specs re shutdown margin & boron concentration in Modes 3, 4 & 5.
* South Carolina Electric & Gas Co. 85/10/18. 3pp. 33155-250-33155-252.

8510280414 Discusses proposed amend to License NPF-12, providing flexibility for dealing w/steam generator tube imperfections besides tube plugging. Amend involves significant hazards considerations. FR notice of opportunity for hearing encl.
NOVAK,T.M. Assistant Director for Licensing. 85/10/21. DIXON,O.W. South Carolina Electric & Gas Co. 2pp. 33196-344-33196-349.

-8510280417 Notice of consideration of issuance of amend to License NPF-12 & opportunity for prior hearing. Amend revises Tech Specs to allow steam generator tube imperfections to be addressed by Westinghouse evaluation method.
HOOD,D.S. Licensing Branch 4. 85/10/21. 4pp. 33196-346-33196-349.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 85-26, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM,E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262-231-33262-231.

-85107160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.1, Post-Trip Review Program Description & Procedure" for Bellefonte Nuclear Plant.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510300008 Withdraws 850830, 0918 & 1016 requests for amend to Tech Specs re specific alternatives to tube plugging in steam generators. Results from eddy-current testing performed during present refueling outage indicate rev unnecessary.
DIXON,O.W. South Carolina Electric & Gas Co. 85/10/25. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33247-061-33247-061.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint.Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

182 DOCKETED ITEMS

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

R. Periodic operating reports & related correspondence

8510020065 Monthly operating rept for Jul 1985 W/850814 ltr.
LOIGNON,G.A., DIXON,O.W. South Carolina Electric & Gas Co. 85/07/31. BARRY,L.W. Office of Resource Management, Director. 5pp. 32827-121-32827-125.

S. Reportable occurrences, LERs & related correspondence

8510040376 Special Rept SPR 85-012 in Oct 1984, first inservice insp of steam generator tubes conducted per Tech Specs 4.4.5.2 & 4.4.5.3. Exam results encl for each tube inspected.
DIXON,O.W. South Carolina Electric & Gas Co. 85/09/20. GRACE,J.N. Region 2, Office of Director. 6pp. 32866-346-32866-351.

8510030076 Confirms 850923 telcon re enforcement conference scheduled for 851008 at Region II otc to discuss isolation of both trains of low head safety injection. Proposed agenda & meeting notification encl.
GRACE,J.N. Region 2, Office of Director. 85/09/26. DIXON,O.W. South Carolina Electric & Gas Co. 4pp. 32843-007-32843-010.

8510010212 LER 85-025-00: on 850828, nonconservative response identified for over-power delta temp setpoint following 850824 reactor trip. Caused by failure to install electrical jumper on channel cards. Jumper installed & tested W/850927 ltr.
KOON,A.R., DIXON,O.W. South Carolina Electric & Gas Co. 85/09/27. 3pp. 32809-204-32809-206.

8510100026 LER 85-026-00: on 850908, at 100% power, turbine driven emergency feedwater pump indicator read 250 rpm. Caused by seat leakage past steam supply control valve. Valve repaired & reset W/851007 ltr.
KOON,A.R., DIXON,O.W. South Carolina Electric & Gas Co. 85/10/07. 3pp. 32959-200-32959-202.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. Ltr of attendees & viewgraphs encl.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON,H.L. Division of Licensing. 23pp. 33030-243-33030-265.

8510250185 LER 85-027-00: on 850920, reactor tripped due to loss of main feedwater pumps during testing of condensate sys. Caused by improper valve lineup. Personnel instructed & training program developed W/851018 ltr.
KOON,A.R., DIXON,O.W. South Carolina Electric & Gas Co. 85/10/18. 5pp. 33190-250-33190-254.

V. Operator Examinations

8510010355 FOIA request for power plant exam results summary sheets for list'd plants.
HANAUER,S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.

8510090309 Denies 850215 application for amend to operator requalification program allowing up to three licensed individuals to be excused from taking annual exam. Proposed amend inconsistent w/need for vigorous operator training.
NOVAK,T.M. Assistant Director for Licensing. 85/09/19. DIXON,O.W. South Carolina Electric & Gas Co. 2pp. 32950-106-32950-107.

8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions delet. Summary sheets for stated plants destroyed.
FELTON,J.M. Division of Rules and Records. 85/09/20. HANAUER,S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.

-8510010428 Power plant exam results summary sheets. Info deleted.
Public Service Electric & Gas Co. of New Jersey. 85/09/20. 9pp. 32832-355-32833-001.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

F. Security, medical, emergency & fire protection plans

8510110187 Forwards Rev 1 to emergency plan & emergency plan implementing procedures, including EPIP-1 re emergency director controlling procedure & EPIP-6 re notification of emergency response personnel & support organizations.
MULDER,R.U. Virginia, Univ. of, Charlottesville, VA. 85/10/04. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32971-314-32971-352.

-8510110190 Rev 1 to emergency plan for Univ of Virginia.
Virginia, Univ. of, Charlottesville, VA. 85/09/30. 18pp. 32971-315-32971-332.

-8510110194 Emergency plan implementing procedures, including EPIP-1 re emergency director controlling procedure & EPIP-6 re notification of emergency response personnel & support organizations.
Virginia, Univ. of, Charlottesville, VA. 85/09/30. 21pp. 32971-333-32971-352.

P. Operating license stage documents & correspondence

8510250131 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE,J.C. Office of the Secretary of the Commission. 85/09/27. Virginia, Univ. of, Charlottesville, VA. 3pp. 33226-056-33226-058.

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

F. Security, medical, emergency & fire protection plans

8510290302 "WPPSS-2 Emergency Preparedness Exercise Manual for 850909-13."
Washington Public Power Supply System. 85/09/09. 350pp. 33255-083-33256-213.

8510080142 Responds to concerns & commitments in 850821 exit meeting re Insp Rept 50-397/85-29 concerning requalification training for health physics/chemistry technicians & radwaste mgt & transportation program.
SORENSEN,G.C. Washington Public Power Supply System. 85/09/18. MARTIN,J.B. Region 5, Office of Director. 3pp. 32951-025-32951-025.

8510020097 Ack receipt of 850905 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-397/85-22.
KIRSCH,D.F. Region 5, Office of Director. 85/09/25. SORESEN,G.C. Washington Public Power Supply System. 1p. 32827-310-32827-316.

-8510020104 Responds to NRC 850807 ltr re violations noted in Insp Rept 50-397/85-22. Corrective actions: two cardboard boxes containing air filters located on 525 ft elevation of radwaste bldg & small plastic bottle of acetone removed.
SORESEN,G.C. Washington Public Power Supply System. 85/09/05. MARTIN,J.B. Region 5, Office of Director. 6pp. 32827-311-32827-316.

8510040205 Discusses compliance w/10CFR50.49 & Generic Ltr 85-15 re environ qualification of electrical equipment & implementation of requirements of Rev 2 of Reg Guide 1.97. Equipment will be qualified by 851130.
SORESEN,G.C. Washington Public Power Supply System. 85/09/30. BUTLER,W.R. Licensing Branch 2. 2pp. 32851-048-32851-049.

8510150290 Forwards supplemental info re conformance to Reg Guide 1.97, Rev 2, "Emergency Response Capability," per 850809 interim rept request. No incorrect assumptions identified.
SORESEN,G.C. Washington Public Power Supply System. 85/10/08. BUTLER,W.R. Licensing Branch 2. 2pp. 33009-106-33009-109.

8510220290 Forwards Rev 5 to guard training & qualification plan, clarifying 12-month requalification criteria. Rev withheld (ref 10CFR73.21).
SORESEN,G.C. Washington Public Power Supply System. 85/10/11. MCQUEEN,A.D. Region 5, Office of Director. 2pp. 33086-358-33086-359.

8510210095 Application for amend to License NPF-21, changing License Condition 16 to implement installation or upgrade requirements of Rev 2 to Reg Guide 1.97 for flux monitoring prior to startup following second refueling outage. Fee paid.
SORESEN,G.C. Washington Public Power Supply System. 85/10/14. BUTLER,W.R. Licensing Branch 2. 4pp. 33072-275-33072-278.

P. Operating license stage documents & correspondence

8510010382 Requests 48 h temporary waiver of compliance w/Tech Spec 3.6.1.8b/4.6.1.8.2 to allow adequate time to process emergency Tech Spec change re leakage integrity tests.
SORESEN,G.C. Washington Public Power Supply System. 85/09/24. BUTLER,W.R. Licensing Branch 2. 2pp. 32801-264-32801-265.

8510030030 Application for amend to License NPF-21, modifying Surveillance Requirement 4.6.1.8.2 to allow individual valves to temporarily exceed L(a) limit on emergency basis. Fee paid.
SORESEN,G.C. Washington Public Power Supply System. 85/09/26. BUTLER,W.R. Licensing Branch 2. 4pp. 32845-116-32845-122.

-8510030038 Proposed Tech Specs, modifying Surveillance Requirement 4.6.1.8.2 to allow individual valves to temporarily exceed L(a) limit on emergency basis.
Washington Public Power Supply System. 85/09/26. 3pp. 32845-120-32845-122.

8510030377 Responds to 850913 ltr re NRC fees billed for OL reviews for WPPSS 1,2 & 3 & insp fees for WPPSS-2. Forwards documentation & "NRC Procedures for Reviewing Disputed License Fee Billings." W/o encl.
MILLER,W.O. License Fee Management Branch. 85/09/27. SORESEN,G.C. Washington Public Power Supply System. 2pp. 32848-073-32848-074.

8510040103 Application for amend to License NPF-21, modifying Tech Spec 6.4.1 & Organizational Charts 6.2.2-1a & 6.2.2-1b to authorize training coordinators to maintain retraining & replacement training program. Fee paid.
SORESEN,G.C. Washington Public Power Supply System. 85/09/27. BUTLER,W.R. Licensing Branch 2. 2pp. 32850-357-32850-362.

- * Washington Public Power Supply System. 85/09/27. 4pp. 32850-359-52650-362.

* Washington Public Power Supply System, 85/09/27, 4pp. 32850-359-52850-362

SORENSEN, G.C. Washington Public Power Supply System. 85/09/27. BUTLER, W.R. Licensing Branch 2. 2pp. 32942:342-32943:030.

85/07/31. 22pp. 32942-344-32943:003.

MARTIN, J. Washington Public Power Supply System. 85/03/20. 27pp. 32943-004-32943-030.

SORENSEN, G.C. Washington Public Power Supply System. 85/09/30. BUTLER, W.H. Licensing Branch 2. 2pp. 32851:048-32851:043.

SORENSEN, G.C. Washington Public Power Supply System. 85/09/30. BUTLER, W.H. Licensing Branch 2. 8pp. 32921:055-32921:062.

16pp. 33031:135-33031:150.

SORENSEN, G.C. Washington Public Power Supply System. 85/10/04. BUTLER, W.R. Licensing Branch 2. 3pp. 32919:049-32919:051.

* Washington Public Power Supply System, 85/10/04, 11pp, 32919:052-32919:062

SORENSEN, G.C. Washington Public Power Supply System. 85/10/04. BUTLER, W.R. Licensing Branch 2. 2pp. 33022:315-33022:316.

SORENSEN, G.C. Washington Public Power Supply System. 85/10/07. BUTLER, W.R. Licensing Branch 2. 2pp. 33022-261-33022-262.

Region 5, Office of Director, 2pp. 33081.311-33081.323.

ESCHELS, C. Washington, State of. 85/09/09. 11pp. 33081.313-33081.323.

SORENSEN, G.C. Washington Public Power Supply System. 85/10/14. BUTLER, W.R. Licensing Branch 2. 2pp. 33054-132-33054-133.

SORENSEN, G.C. Washington Public Power Supply System. 85/10/14. BUTLER, W.R. Licensing Branch 2. 4pp. 33072-275-33072-278.

SORENSEN, G.C. Washington Public Power Supply System. 85/10/17, BUTLER, W.R. Licensing Branch 2. 4pp. 33086-278-33086-282.

* Washington Public Power Supply System, 85/10/17, 1p. 33086 282:33086 282.

BOURNIA, A. Licensing Branch 2. 85/10/18. SORENSEN, G.S. Washington Public Power Supply System. 4pp. 33223-341-33223-344.

NOVAK, T.M. Assistant Director for Licensing. 85/10/18. SORESENSEN, G.C. Washington Public Power Supply System. 2pp. 33228 338-33228 339.

ESCHELS, C. Washington, State of. 85/10/24. BUTLER, W.R. Licensing Branch 2. 1p
33234 360-33234 360

Q. Inspection reports, IE Bulletins & correspondence

SORENSEN, G.C. Washington Public Power Supply System. 85/09/18. MARTIN, J.B. Region 5, Office of Director. 3pp. 32951:025-32951:025.

Public Power Supply System. 2pp. 32947:156-32947:172.

JOHNSON, P.H. Region 5, Office of Director. 85/09/20. 2pp. 32947:158-32947:159.

JOHN, A.D.; WALTER, L.S.; JOHNSON, F.H. Region 5, Office of Director. 657/04/19. 13pp. 32947:160-32947:172.

SCARANO, R.A. Region 5, Office of Director. 85/09/24. SORESENSEN, G.C. Washington Public Power Supply System. 2pp. 32946:045-32946:056.

YUHAS, G.P. Region 5, Office of Director. 85/09/24. 1p. 32946:047-32946:047.

SHERMAN, C.I., COOK, R., YUHAS, G.P. Region 5, Office of Director. 85/09/23. 9pp.
32946.048-32946.056.

KIRSCH,D.F. Region 5, Office of Director. 85/09/25. SORENSEN,G.C. Washington Public Power Supply System. 1p. 32827:310-32827:316.

SORENSEN, G.C. Wasington Public Power Supply System. 85/09/05. MARTIN, J.B. Region 5, Office of Director. 6pp. 32827:311-32827:316.

830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869.001-32869.060.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 13pp.

KIRSCH,D.F. Region 5, Office of Director. 8/5/10/01. SORESENSEN,G.C. Washington Public Power Supply System. 2pp. 33053-340-33053-350.

IVEY, K.D., YOUNG, T. Region 5, Office of Director. 85/09/30. 9pp. 33053:342-33053:350.

830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177.205-33177.341.

830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

B. Periodic operating reports & related correspondence

HUTCHISON, L.B., POWERS, C.M. Washington Public Power Supply System. 85/07/31. 5pp. 32827-305-32827-309.

S. Reportable occurrences, LERs & related correspondence

SCHREIBER, H. Louis-Allis Co. 85/09/30. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851-100-32851-107.

DAVISON, W.S., POWERS, C.M. Washington Public Power Supply System. 85/10/09
4pp. 33068-248-33068-251.

184 DOCKETED ITEMS

8510280186 LER 85-056-00 on 850930, erroneous high chlorine signal from ventilation chlorine detector started control room emergency filtration sys. Caused by breakage of chlorine sensitive paper tape. Paper tape replaced & alarms reset. W/851018 ltr. DAVISON, W.S., POWER, S.E.M. Washington Public Power Supply System. 8/10/18. 3pp. 33194.269-33194.271.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510010459 Forwards revised list of equipment included in seismic & dynamic qualification program, superseding 850211 list. More than 75% of equipment installed. Util prepared for NRC audit, tentatively scheduled for 851202.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,719pp. 32804.131-32809.045.

8510080439 Forwards draft changes to FSAR Section 14.2 re initial startup testing program. Changes concern control rod reactivity worth & pseudo rod ejection tests. Changes will be incorporated into future amend to FSAR.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 8pp. 32922.194-32922.201.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.

CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NO. AK, T.M. Assistant Director for Licensing. 3pp. 33044.010-33044.027.

-8510170205 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' ...," technical evaluation rept.

* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1520. 85/10/11. NRC No Detailed Affiliation Given. 15pp. 33044.196-33044.200.

8510180265 Submits proposed schedule for meeting requirements of 10CFR50.62 re ATWS & provides brief description of tentative design.

CUTTER, A.B. Carolina Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33062.034-33062.035.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510010041 Forwards addl info re revised pressure/temp curves in response to SER Confirmatory Item 11. Allowances for differences between RCS temp & reactor vessel flange region temp discussed.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32801.281-32801.285.

8510010204 Forwards addl info, per SER Open Item 8 re fire protection, including discussion of high/low pressure interface, double fusing & breaker coordination testing per Auxiliary Sys Branch reviewer questions.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 32800.275-32800.288.

8510010278 Submits addl info to resolve SER Open Item 10 re estimated noble gas releases through atmosphere relief valves. Design meets criteria in NUREG-0737 & Reg Guide 1.97 for monitoring effluent releases.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800.314-32800.337.

-8510010288 Rev 1 to Vol 2, Part 5 of Plant Emergency Procedure PEP-341, "Manual Dose Calculation."

MILLER, J.L. Carolina Power & Light Co. 85/08/13. 22pp. 32800.316-32800.337.

8510010302 Forwards addl info in response to SER Confirmatory Item 4 re design documentation of ASME components. Info responds to NRC concerns identified by 850618 ltr & Mechanical Engineering Branch Questions 210.80, 210.81 & 210.82.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 200pp. 32801.013-32801.207.

8510010385 Forwards revised Pages 1-10 & Sketch SK-251-006 in response to Power Sys Branch request for addl info re SER Confirmatory Item 20 concerning load sequence reliability.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 12pp. 32803.020-32803.031.

8510010419 Forwards Westinghouse Field Change Notice CQUM-10593 re mods to solid state logic protection sys necessary to eliminate potentially undetectable test circuit failure. Info completes response to SER Confirmatory Item 16.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 32804.123-32804.130.

8510180181 Forwards addl info re double fusing of control circuits for fire protection, in response to SER Open Item 8.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33059.334-33059.335.

F. Security, medical, emergency & fire protection plans

8510010204 Forwards addl info, per SER Open Item 8 re fire protection, including discussion of high/low pressure interface, double fusing & breaker coordination testing per Auxiliary Sys Branch reviewer questions.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 32800.275-32800.288.

8510010278 Submits addl info to resolve SER Open Item 10 re estimated noble gas releases through atmosphere relief valves. Design meets criteria in NUREG-0737 & Reg Guide 1.97 for monitoring effluent releases.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800.314-32800.337.

-8510010288 Rev 1 to Vol 2, Part 5 of Plant Emergency Procedure PEP-341, "Manual Dose Calculation."

MILLER, J.L. Carolina Power & Light Co. 85/08/13. 22pp. 32800.316-32800.337.

8510160228 Forwards Rev 2 to security, safeguards contingency & security personnel training & qualification plans. Changes include reflection of plant as one-unit facility & revs of vital & protected area drawings. Rev withheld (ref 10CFR73.21).

CUTTER, A.B. Carolina Power & Light Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33021.246-33021.248.

8510180153 Responds to violations noted in Insp Rept 50-400/85-09. Listing of current status of completion for improvement & incomplete items encl.

WILLIS, J.L. Carolina Power & Light Co. 85/10/02. GRACE, J.N. Region 2, Office of Director. 9pp. 33055.038-33055.046.

8510180181 Forwards addl info re double fusing of control circuits for fire protection, in response to SER Open Item 8.

ZIMMERMAN, S.R. Carolina Power & Light Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33059.334-33059.335.

8510180340 Response in opposition to W Eddleman proposed contention re emergency planning exercise. Svc list, exercise evaluation rept, operations journal & Insp Rept 50-400/85-20 encl.

RIDGWAY, D.A. Carolina Power & Light Co. RIDGWAY, D.A. Shaw, Pittman, Potts & Trowbridge. #485 823. 85/10/15. Atomic Safety and Licensing Board Panel. 120pp. 33060.001-33060.125.

8510310280 Certifies svc of encl RG Black & CS Wingo 851007 ltr & oversize drawing entitled "Revised 60 dBC Coverage Within Emergency Plan Zone of Shearon Harris Nuclear Power Plant," on 851025 Related correspondence.

HOLLARD, E. Carolina Power & Light Co. #485 966. 85/10/25. 10pp. 33273.332-33273.341.

8510310602 Requests formal confirmation that offsite emergency plans include list of medical facilities w/capabilities to provide treatment for radiation exposure & commitment to full compliance w/response to GUARD remand.

KNIGHTON, G.W. Licensing Branch 3. 85/10/25. UTLEY, E.E. Carolina Power & Light Co. 6pp. 33277.92-33277.097.

G. Adjudicatory correspondence

8510030009 Requests extension of time to file brief in appeal of 850828 partial initial decision on some safety matters. Granted for ASLAP on 851001 Certificate of Svc encl.

RUNKLE, J. Joint Intervenor - Shearon Harris. RUNKLE, J. Runkle, J.D. EDDLEMAN, W. Eddleman, W. #485 661. 85/09/30. 4pp. 32845.124-32845.128.

8510030082 Request for extension of time to file brief in appeal of 850828 partial initial decision on some safety matters. Request based on stated facts.

RUNKLE, J. Joint Intervenor - Shearon Harris. RUNKLE, J. Runkle, J.D. EDDLEMAN, W. Eddleman, W. #485 652. 85/09/30. 3pp. 32844.331-32844.333.

8510100208 Requests that listed contentions based on May 1985 emergency planning exercise be admitted as there are no other means or parties to protect or represent author interests in matters. Certificate of Svc encl.

EDDLEMAN, W. Eddleman, W. #485 699. 85/09/30. Atomic Safety and Licensing Board Panel. 7pp. 32962.074-32962.080.

8510100038 Forwards expurgated testimony of D Williams to be substituted for prefired testimony previously furnished & expunged, per J Kelley 850930 ruling. Related correspondence.

THORNBURG, L.H. North Carolina, State of. #485 686. 85/10/04. Docketing & Services Branch. 1p. 32960.245-32960.245.

-8510100047 Expurgated testimony of D Williams re undercover drug investigation at facility. Related correspondence.

WILLIAMS, D. North Carolina, State of. WILLIAMS, D. Justice, Dept. of, Drug Enforcement Administration. 85/10/04. 17pp. 32960.246-32960.262.

8510160159 Appeal from 850820 partial initial decision on mgt capabilities & safety contentions. Certificate of Svc encl.

RUNKLE, J. Conservation Council of North Carolina. RUNKLE, J. Runkle, J.D. EDDLEMAN, W. Eddleman, W. #485 774. 85/10/08. Atomic Safety and Licensing Appeal Panel. 34pp. 33022.080-33022.113.

8510150350 Notice of evidentiary hearing on Eddleman Contention 57-C-3 on 851104 in Raleigh, NC & second hearing on Conservation Council of North Carolina Contention WB-3 on 851102. Served on 851011.

KELLEY, J.L. Atomic Safety and Licensing Board Panel. #485 768. 85/10/10. 1p. 33000.340-33000.340.

8510180340 Response in opposition to W Eddleman proposed contention re emergency planning exercise. Svc list, exercise evaluation rept, operations journal & Insp Rept 50-400/85-20 encl.

RIDGWAY, D.A. Carolina Power & Light Co. RIDGWAY, D.A. Shaw, Pittman, Potts & Trowbridge. #485 823. 85/10/15. Atomic Safety and Licensing Board Panel. 120pp. 33060.001-33060.125.

8510220231 Response to W Eddleman 850930 proposed contentions based on emergency planning exercise. Certificate of Svc encl.

MOORE, J.E. Hearing Branch 1. #485 844. 85/10/15. Atomic Safety and Licensing Board Panel. 22pp. 33064.160-33064.181.

8510180308 Forwards Form 8-K, dtd 850924, filed w/Securities & Exchange Commission by util. Svc list encl. Related correspondence.

BAXTER, T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER, T.A. Carolina Power & Light Co. #485 808. 85/10/16. KELLEY, J.L., BRIGHT, G.O., CARPENTER, J.H. Atomic Safety and Licensing Board Panel. 6pp. 33062.141-33062.147.

8510230209 Forwards FEMA testimony & supplemental response to general interrogatories re Eddleman Contention 57-C-3. No other documents intended for introduction as exhibits in proceeding. Related correspondence.
MOORE, J.E. Hearing Branch 2. #485 868. 85/10/18. KELLEY, J.L., CARPENTER, J.H., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 33103:173-33103:294.

-8510230227 Supplementary response to General Interrogatories 2-3 & 12-14 re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Certificate of Svc encl. Related correspondence.
MOORE, J.E. Federal Emergency Management Agency. MOORE, J.E. Hearing Branch 2. 85/10/18. Eddleman, W. 8pp. 33103:287-33103:294.

8510240235 Forwards data sheets re home acoustic properties in emergency planning zone & listed documents concerning testimony of DN Keast, AH Joyner & DS Milet on Eddleman Contention 57-C-3. Svc list encl. Related correspondence.
RIDGWAY, D.A. Shaw, Pittman, Potts & Trowbridge. RIDGWAY, D.A. Carolina Power & Light Co. RIDGWAY, D.A. North Carolina Municipal Power Agencies. #485 878. 85/10/22. EDDLEMAN, W. Eddleman, W. 4pp. 33155:253-33155:256.

8510240671 Motion for extension until 851122 to file reply to intervenor 851008 brief due to counsel time conflict. Certificate of Svc encl. Related correspondence.
BAXTER, T.A. Carolina Power & Light Co. BAXTER, T.A. Shaw, Pittman, Potts & Trowbridge. #485 887. 85/10/23. Atomic Safety and Licensing Appeal Panel. 5pp. 33161:018-33161:022.

8510280515 Order extending time until 851122 for util to file brief. NRC brief shall be filed no later than 851202. Served on 851025.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 930. 85/10/25. Carolina Power & Light Co. 1p. 33227:308-33227:308.

8510310280 Certifies svc of encl RG Black & CS Wingo 851007 ltr & oversize drawing entitled "Revised 60 dBC Coverage Within Emergency Plan Zone of Shearon Harris Nuclear Power Plant," on 851025. Related correspondence.
HOLLAR, D.E. Carolina Power & Light Co. #485 966. 85/10/25. 10pp. 33273:332-33273:341.

H. General correspondence

8510170081 Requests that svc list for all related matls be revised to list JA Sanford as State of NC counsel of record.
SANFORD, J.A. North Carolina. State of. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 1p. 33036:228-33036:228.

Q. Inspection reports, IE Bulletins & correspondence

8509180255 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. UTLEY, E.E. Carolina Power & Light Co. 11pp. 32854:316-32854:326.

8510030047 Responds to NRC 850821 ltr re violations noted in Insp Rept 50-400/85-29. Corrective actions: defective baseplate grouts repaired & post-placement insp conducted. Grout inspector counseled & special classroom training held for personnel.
WATSON, R.A. Carolina Power & Light Co. 85/09/19. GRACE, J.N. Region 2, Office of Director. 3pp. 32842:310-32842:312.

8510070369 Responds to NRC 850827 ltr re violations noted in Insp Rept 50-400/85-29. Corrective actions: electrical connection problems corrected & Welding Procedure Spec WPS 525M1 re feed wire speed revised.
WATSON, R.A. Carolina Power & Light Co. 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32877:201-32877:202.

8510070353 Responds to NRC 850826 ltr re violations noted in Insp Rept 50-400/85-30. Corrective actions: craft personnel instructed in requirements of Work Procedure 402 re installation of ductwork & training session held for const engineers.
WATSON, R.A. Carolina Power & Light Co. 85/09/24. GRACE, J.N. Region 2, Office of Director. 3pp. 32878:244-32878:246.

8510090329 Forwards Insp Rept 50-400/85-33 on 850820-0920. No violation or deviation noted.
VERRELLI, D.M. Region 2, Office of Director. 85/09/27. UTLEY, E.E. Carolina Power & Light Co. 2pp. 32947:126-32947:137.

-8510090333 Insp Rept 50-400/85-33 on 850820-0920. No violation or deviation noted. Major areas inspected: action on previous enforcement & inspector followup items. Unresolved item re installation of safety-related equipment noted.
MAXWELL, G.F., PREVATTE, R.L., BURRIS, S.P. Region 2, Office of Director. 85/09/27. 10pp. 32947:128-32947:137.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070357 Forwards Suppl 1 to Integrated Design Insp Rept 50-400/84-48 on 850722-24 at Ebasco Svcs, Inc. Potential enforcement findings identified. Ack: corrective actions, clarifications & proposed FSAR revs documented in 850806 ltr.
GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/10/01. UTLEY, E.E. Carolina Power & Light Co. 3pp. 32901:244-32901:274.

-8510070359 Suppl 1 to Integrated Design Insp Rept 50-400/84-48 on 850722-24 at Ebasco Svcs, Inc. Potential findings: failure to detect use of incorrect assumptions in calculations that established allowable voltage drop in switchgear circuits.
ARCHITZEL, R.E., MILHOAN, J.L. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/09/25. 28pp. 32901:247-32901:274.

8510020462 Board Notification 85-083: forwards IE Info Notice 85-042 re anomaly concerning Panasonic TLD which was one of admitted contentions in facility licensing proceedings.
NOVAK, T.M. Assistant Director for Licensing. 85/10/02. MOORE, T.S., GOTCHY, R.L., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 2pp. 32878:181-32878:185.

8510180153 Responds to violations noted in Insp Rept 50-400/85-09. Listing of current status of completion for improvement & incomplete items encl.
WILLIS, J.L. Carolina Power & Light Co. 85/10/02. GRACE, J.N. Region 2, Office of Director. 9pp. 33055:038-33055:046.

8510180375 Ack receipt of 850919 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-400/85-28. Requirements of 10CFR2.201 met.
VERRELLI, D.M. Region 2, Office of Director. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 1p. 33068:279-33068:279.

8510180369 Ack receipt of 850920 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-400/85-29. Requirements of 10CFR2.201 met.
WALKER, R.D. Region 2, Office of Director. 85/10/07. UTLEY, E.E. Carolina Power & Light Co. 1p. 33068:281-33068:281.

8510180449 Ack receipt of 850924 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-400/85-30.
VERRELLI, D.M. Region 2, Office of Director. 85/10/08. UTLEY, E.E. Carolina Power & Light Co. 1p. 33067:361-33067:361.

8510310172 Responds to NRC 850911 ltr re violations noted in Insp Rept 50-400/85-32. Corrective actions: motor heater circuit breakers for charging/safety injection pumps added to auxiliary operators log for daily check.
WILLIS, J.L. Carolina Power & Light Co. 85/10/11. GRACE, J.N. Region 2, Office of Director. 3pp. 33274:053-33274:055.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510180340 Response in opposition to W Eddleman proposed contention re emergency planning exercise. Svc list, exercise evaluation rpt, operations journal & Insp Rept 50-400/85-20 encl.
RIDGWAY, D.A. Carolina Power & Light Co. RIDGWAY, D.A. Shaw, Pittman, Potts & Trowbridge. #485 823. 85/10/15. Atomic Safety and Licensing Board Panel. 120pp. 33060:001-33060:125.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510310348 Responds to questions raised during 851016 meeting re Integrated Design Insp 50-400/84-48 open items. Interdisciplinary clearance criteria will be revised to require safety & nonsafety piping review.
WATSON, R.A. Carolina Power & Light Co. 85/10/25. GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 2pp. 33272:054-33272:055.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

T. Hearing transcripts on non-antitrust matters

8510040302 Forwards revised testimony of LL Bush on Contention WB-3 re util drug prevention & detection program, replacing 850920 transmittal. Related correspondence.
BARTH, C.A. Hearing Branch 1. #485 668. 85/09/23. KELLEY, J.L., CARPENTER, J.H., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 32853:284-32853:298.

-8510040458 Revised testimony of LL Bush on Contention WB-3 re util drug prevention & detection program. Related correspondence.
BUSH, L.L. Operating Reactor Program Branch. 85/09/23. 14pp. 32853:285-32853:298.

8510080134 Transcript of 850930 evidentiary hearing in Apex, NC re drug use contention. Pp 8,283-8,540. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 85/09/30. 400pp. 32916:082-32917:151.

8510080110 Transcript of 851001 evidentiary hearing in Apex, NC. Pp 8,541-8,844. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 85/10/01. 335pp. 32951:070-32951:106.

8510080224 Transcript of 851002 evidentiary hearing in Apex, NC. Pp 8,845-9,071. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 85/10/02. 250pp. 32915:183-32916:081.

8510080261 Transcript of 851003 evidentiary hearing in Apex, NC. Pp 9,072-9,355. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 85/10/03. 285pp. 32914:001-32914:325.

186 DOCKETED ITEMS

8510230209 Forwards FEMA testimony & supplemental response to general interrogatories re Eddleman Contention 57-C-3. No other documents intended for introduction as exhibits in proceeding. Related correspondence. MOORE, J.E. Hearing Branch 2. #485 868. 85/10/18. KELLEY, J.L., CARPENTER, J.H., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 33103:173-33103:294.

-8510230211 Testimony of TF Carter re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. CARTER, T.F. International Energy Associates, Ltd. 85/10/18. 17pp. 33103:174-33103:190.

-8510230214 Testimony of VM Lee re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. LEE, V.M. Analysis & Computing. 85/10/18. 30pp. 33103:191-33103:220.

-8510230223 Testimony of KD Kryter re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. KRYTER, K.D. Stanford Research Institute. KRYTER, K.D. Acousis Co. 85/10/18. 34pp. 33103:221-33103:254.

-8510230225 Testimony of J Nehnevajsa re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. NEHNEVAJSA, J. Affiliation Not Assigned. 85/10/18. 32pp. 33103:255-33103:286.

-8510230227 Supplementary response to General Interrogatories 2-3 & 12-14 re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Certificate of Svc encl. Related correspondence. MOORE, J.E. Federal Emergency Management Agency. MOORE, J.E. Hearing Branch 2. 85/10/18. Eddleman, W. 8pp. 33103:287-33103:294.

8510240394 Transcript of testimony of DN Keast, AH Joyner & DS Milleti on Eddleman Contention 57-C-3 re night time notification. Pp 1-43. Supporting documentation & Certificate of Svc encl. Related correspondence. KEAST, D.N., JOYNER, A.H. Carolina Power & Light Co. KEAST, D.N. HMM Associates, Inc. #485 875. 85/10/18. 79pp. 33151:037-33151:116.

8510280510 Testimony of P Fredrickson & R Prevatte for NRC re Contention WB-3 on allegation concerning reinsp of work performed by persons suspected of drug abuse. Certificate of Svc encl. Related correspondence. FREDRICKSON, P. Region 2, Office of Director. PREVATTE, R. NRC - No Detailed Affiliation Given. #485 941. 85/10/24. 14pp. 33227:312-33227:325.

8510290033 Forwards testimony of RL Dupont, HR Banks, RM Parsons, GL Forehand & TW Brombach supporting util response to Conservation Council of North Carolina Contention WB-3. Certificate of Svc encl. Related correspondence. BAXTER, T.A. Shaw, Pittman, Potts & Trowbridge. BAXTER, T.A. Carolina Power & Light Co. #485 917. 85/10/25. KELLEY, J.L., BRIGHT, G.O., CARPENTER, J.H. Atomic Safety and Licensing Board Panel. 6pp. 33229:318-33230:185.

-8510290035 Testimony of HR Banks & RM Parsons re Conservation Council of North Carolina Contention WB-3 concerning const QA program. Related correspondence. BANKS, H.R., PARSONS, R.M. Carolina Power & Light Co. 85/10/25. 37pp. 33229:324-33230:001.

-8510290041 Testimony of HR Banks, RM Parsons, GL Forehand & TW Brombach re Conservation Council of North Carolina Contention WB-3 concerning evaluation & reinsp of employees implicated in possible drug activity. Related correspondence. BANKS, H.R., PARSONS, R.M., FOREHAND, G.L. Carolina Power & Light Co. 85/10/25. 27pp. 33230:002-33230:029.

-8510290046 Testimony of EF Trainor on Conservation Council of North Carolina Contention WB-3 re capabilities & performance of applicant const QA program. Related correspondence. TRAINOR, E.F. Carolina Power & Light Co. TRAINOR, E.F. CYGNA Energy Services. 85/10/25. 22pp. 33230:030-33230:052.

-8510290049 Testimony of RL Dupont on Conservation Council of North Carolina Contention WB-3 re effects of employee drug use. Related correspondence. DUPONT, R.L. Carolina Power & Light Co. DUPONT, R.L. American Psychiatric Association. DUPONT, R.L. Dupont, R.L., MD. 85/10/25. 132pp. 33230:053-33230:185.

V. Operator Examinations

8509240248 Generic Ltr 85-1 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170205 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities,'" technical evaluation rept. * Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-098, SAIC-85/1520. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:186-33044:200.

G. Adjudicatory correspondence

8510100038 Forwards expurgated testimony of D Williams to be substituted for prefired testimony previously furnished & expurgated, per J Kelley 850930 ruling. Related correspondence. THORNBURG, L.H. North Carolina, State of. #485 686. 85/10/04. Docketing & Services Branch. 1p. 32960:245-32960:245.

8510220231 Response to W Eddleman 850930 proposed contentions based on emergency planning exercise. Certificate of Svc encl. MOORE, J.E. Hearing Branch 1. #485 844. 85/10/15. Atomic Safety and Licensing Board Panel. 22pp. 33084:160-33084:181.

8510230209 Forwards FEMA testimony & supplemental response to general interrogatories re Eddleman Contention 57-C-3. No other documents intended for introduction as exhibits in proceeding. Related correspondence. MOORE, J.E. Hearing Branch 2. #485 868. 85/10/18. KELLEY, J.L. Atomic Safety and Licensing Board Panel. 1p. 33103:173-33103:294.

-8510230227 Supplementary response to General Interrogatories 2-3 & 12-14 re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Certificate of Svc encl. Related correspondence. MOORE, J.E. Federal Emergency Management Agency. MOORE, J.E. Hearing Branch 2. 85/10/18. Eddleman, W. 8pp. 33103:287-33103:294.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

T. Hearing transcripts on non-antitrust matters

8510040302 Forwards revised testimony of LL Bush on Contention WB-3 re util drug prevention & detection program, replacing 850920 transmittal. Related correspondence. BARTH, C.A. Hearing Branch 1. #485 868. 85/09/23. KELLEY, J.L., CARPENTER, J.H., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 32853:284-32853:298.

-8510040458 Revised testimony of LL Bush on Contention WB-3 re util drug prevention & detection program. Related correspondence. BUSH, L.L. Operating Reactor Program Branch. 85/09/23. 14pp. 32853:285-32853:298.

8510230209 Forwards FEMA testimony & supplemental response to general interrogatories re Eddleman Contention 57-C-3. No other documents intended for introduction as exhibits in proceeding. Related correspondence. MOORE, J.E. Hearing Branch 2. #485 868. 85/10/18. KELLEY, J.L., CARPENTER, J.H., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 33103:173-33103:294.

-8510230211 Testimony of TF Carter re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. CARTER, T.F. International Energy Associates, Ltd. 85/10/18. 17pp. 33103:174-33103:190.

-8510230214 Testimony of VM Lee re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. LEE, V.M. Analysis & Computing. 85/10/18. 30pp. 33103:191-33103:220.

-8510230223 Testimony of KD Kryter re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. KRYTER, K.D. Stanford Research Institute. KRYTER, K.D. Acousis Co. 85/10/18. 34pp. 33103:221-33103:254.

-8510230225 Testimony of J Nehnevajsa re Eddleman Contention 57-C-3 concerning nighttime emergency siren sys at facility. Related correspondence. NEHNEVAJSA, J. Affiliation Not Assigned. 85/10/18. 32pp. 33103:255-33103:286.

8510280510 Testimony of P Fredrickson & R Prevatte for NRC re Contention WB-3 on allegation concerning reinsp of work performed by persons suspected of drug abuse. Certificate of Svc encl. Related correspondence. FREDRICKSON, P. Region 2, Office of Director. PREVATTE, R. NRC - No Detailed Affiliation Given. #485 941. 85/10/24. 14pp. 33227:312-33227:325.

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

8510250202 Lists determinations based on review of 850226 response to NRC 850115 request for info re use of armed responder for compensatory duties. Although members of response force may have other duties, primary duty must be response. AXELSON, W.L. Region 3, Office of Director. 85/10/11. LINDER, F. Dairyland Power Cooperative. 2pp. 33190:259-33190:260.

8510250398 Responds to NRC 850918 ltr re violations noted in Insp Rept 50-409/85-13. Corrective actions affected carbon dioxide cylinders replaced by Halon fire extinguishers & surveillance test upgraded to preventive maint sys. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/16. KEPPLER, J.G. Region 3, Office of Director. 5pp. 33172:288-33172:292.

8510280177 Forwards Safety Insp Rept 50-409/85-12 on 850618-1015. No violations noted. CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/22. TAYLOR, J.W. Dairyland Power Cooperative. 1p. 33191:173-33191:173.

-8510280183 Insp Rept 50-409/85-12 on 850618-1015. No violations noted. Major areas inspected: licensee activities on operational safety, LERs, IE bulletins, plant trips, monthly surveillance observations & safety review committee meeting. BOYD, D.C. Region 3, Office of Director. 85/10/22. 10pp. 33191:174-33191:182.

8510290099 Forwards Safeguards Insp Rept 50-409/85-16 on 850930-1004 & notice of violation. Notice of violation withheld (ref 10CFR73.21). AXELSON, W.L. Region 3, Office of Director. 85/10/24. TAYLOR, J.W. Dairyland Power Cooperative. 2pp. 33235:298-33235:301.

-8510290115 Physical Security Insp Rept 50-409/85-16 on 850930-1004. Violations noted: failure to maintain clear isolation zone & search hardware & some alarm zones failed to perform as required. Details withheld (ref 10CFR73.21). CHRISTOFFER, G., DROUIN, B., CREED, J.R. Region 3, Office of Director. 85/10/23. 2pp. 33235-300-33235-301.

J. Insurance & Indemnity Information

8510110100 Informs that ES Murphy & Fi Smith of BNWL will visit site on 851022-23 to assist NRC in review of onsite insurance exemption request. Exemption will be issued by mid-Dec 1985. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/10. TAYLOR, J.W. Dairyland Power Cooperative. 3pp. 32974-023-32974-025.

8510230107 Ack receipt of 851010 ltr re status of request for exemption concerning onsite insurance. Indication of unfavorable outcome requested to allow for opportunity to personally discuss merits of appeal. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/14. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33102-218-33102-218.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510240266 Forwards updated FSAR for LACBWR. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/14. ZWOLINSKI, J. Operating Reactors Branch 5. 2pp. 33173-249-33176-001.

-8510240270 Updated FSAR for LACBWR.
* Dairyland Power Cooperative. 85/07/31. 800pp. 33173-251-33176-243.

P. Operating license stage documents & correspondence

8510070478 Forwards Rev 3 to QA program description. Rev eliminates assistant general manager - power & radiation protection engineering specialist & adds training specialist. TAYLOR, J.W. Dairyland Power Cooperative. 85/09/13. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32878-143-32878-170.

-8510070482 Rev 3 to QA program description.
* Dairyland Power Cooperative. 85/09/11. 42pp. 32878-146-32878-170.

8510070274 Application for amend to License DPR-45, revising Tech Specs to delete Section 2.4.7 & simplifying & making more stringent conditions for low pressure core spray. TAYLOR, J.W. Dairyland Power Cooperative. 85/09/16. ZWOLINSKI, J. Operating Reactors Branch 5. 3pp. 32877-333-32877-347.

-8510070280 Proposed Tech Specs, deleting Section 2.4.7 & simplifying & making more stringent applicable conditions for low pressure core spray.
* Dairyland Power Cooperative. 85/09/16. 12pp. 32877-336-32877-347.

8510110162 Forwards Amend 44 to License DPR-45 & safety evaluation. Amend adds new Paragraph 4.2.23 to Tech Specs requiring demineralized virgin water tank to be operable w/min water level of 1 ft. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/08. TAYLOR, J.W. Dairyland Power Cooperative. 3pp. 32972-236-32972-244.

-8510110169 Amend 44 to License DPR-45, adding Paragraph 4.2.23 to Tech Specs requiring demineralized virgin water tank to be operable w/min water level of 1 ft & surveillance requirement to verify min water level every wk. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/08. 4pp. 32972-239-32972-242.

-8510110172 Safety evaluation supporting Amend 44 to License DPR-45.
* Office of Nuclear Reactor Regulation, Director. 85/10/08. 2pp. 32972-243-32972-244.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070468 Forwards Safety Insp Rept 50-409/85-15 on 850916-20 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/02. TAYLOR, J.W. Dairyland Power Cooperative. 2pp. 32878-212-32878-223.

-8510070470 Notice of violation from insp on 850916-20. SHAFER, W.D. Region 3, Office of Director. 85/10/02. 1p. 32878-214-32878-214.

-8510070472 Insp Rept 50-409/85-15 on 850916-20. Violation noted: failure to maintain whole body dose records per NRC-5 instructions. MILLER, D.E., GREGER, L.R. Region 3, Office of Director. 85/10/02. 9pp. 32878-215-32878-223.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-086.

-8510230185 Forwards Press Release 84-69 re NRC reduction of fine for 1983 violation. Pressure sensing device capped. Fine reduced due to short duration of violation, small size of reactor & comparable enforcement actions. KAMMERER, C. Office of Congressional Affairs. 84/06/01. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109-008-33109-009.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class, Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510250398 Responds to NRC 850918 ltr re violations noted in Insp Rept 50-409/85-13. Corrective actions affected carbon dioxide cylinders replaced by Halon fire extinguishers & surveillance test upgraded to preventive maint sys. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/16. KEPPLER, J.G. Region 3, Office of Director. 5pp. 33172-288-33172-292.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 600 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510220294 Forwards Safety Insp Rept 50-409/85-14 on 850916-1004. One unresolved item re auditing maint work request sys identified. PAPERIELLO, C.J. Region 3, Office of Director. 85/10/17. TAYLOR, J.W. Dairyland Power Cooperative. 2pp. 33085-099-33085-108.

-8510220299 Insp Rept 50-409/85-14 on 850916-1004. No violation or deviation noted. Major areas inspected: licensee action on previous insp findings, maint, QA/QC administration, tests & experiments, receipts, storage, handling & procurement. WESTBERG, R.A., HAWKINS, F.C. Region 3, Office of Director. 85/10/17. 8pp. 33085-101-33085-108.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280177 Forwards Safety Insp Rept 50-409/85-12 on 850618-1015. No violations noted. CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/22. TAYLOR, J.W. Dairyland Power Cooperative. 1p. 33191-173-33191-173.

-8510280183 Insp Rept 50-409/85-12 on 850618-1015. No violations noted. Major areas inspected: licensee activities on operational safety, LERs, IE bulletins, plant trips, monthly surveillance observations & safety review committee meeting. BOYD, D.C. Region 3, Office of Director. 85/10/22. 10pp. 33191-174-33191-182.

8510290099 Forwards Safeguards Insp Rept 50-409/85-16 on 850930-1004 & notice of violation. Notice of violation withheld (ref 10CFR73.21). AXELSON, W.L. Region 3, Office of Director. 85/10/24. TAYLOR, J.W. Dairyland Power Cooperative. 2pp. 33235-298-33235-301.

-8510290115 Physical Security Insp Rept 50-409/85-16 on 850930-1004. Violations noted: failure to maintain clear isolation zone & search hardware & some alarm zones failed to perform as required. Details withheld (ref 10CFR73.21). CHRISTOFFER, G., DROUIN, B., CREED, J.R. Region 3, Office of Director. 85/10/23. 2pp. 33235-300-33235-301.

R. Periodic operating reports & related correspondence

8510020094 Monthly operating rept for Jul 1985. W/850806 ltr. MALIN, L., GOODMAN, L.S., TAYLOR, J.W. Dairyland Power Cooperative. 95/07/31. 6pp. 32827-299-32827-304.

8510070560 Forwards revised "Radioactive Effluent Rept for Jan-June 1985." Rept contains Sr-89/90 results not previously sent. TAYLOR, J.W. Dairyland Power Cooperative. 85/09/25. KEPPLER, J.G. Region 3, Office of Director. 1p. 32883-192-32883-210.

-8510070562 Revised "Radioactive Effluent Rept for Jan-June 1985."
* Dairyland Power Cooperative. 85/06/30. 18pp. 32883-193-32883-210.

S. Reportable occurrences, LERs & related correspondence

8510150329 LER 85-016-00 on 850914, fuse supplying control room instrumentation from noninterruptible bus 1B blew, causing reactor scram on high water level. Caused by technician error. Fuse replaced. W/851003 ltr. GOODMAN, L.S., TAYLOR, J.W. Dairyland Power Cooperative. 85/10/03. 3pp. 33010-360-33010-362.

8510310396 Special rept discusses circumstances which led to inaccuracies in personnel cumulative lifetime dose records. Cumulative permanent doses in radiation dosimetry rept do not agree w/records maintained in computer file. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/08. KEPPLER, J.G. Region 3, Office of Director. 3pp. 33280-284-33280-286.

8510310425 Special Rept 85-02 on 850725, 0909 & 14, reactor thermal power changed by more than 15% of rated thermal power within 1 h. Power history, fuel burnup, cleanup flow history, offgas activity levels & gross alpha activity levels discussed. TAYLOR, J.W. Dairyland Power Cooperative. 85/10/21. KEPPLER, J.G. Region 3, Office of Director. 8pp. 33280-266-33280-273.

8510280211 PNO-III-85-091 on 851022, loss of offsite power occurred due to inadvertent opening of circuit breaker in switchyard. Caused by personnel winterizing equipment. Accumulator repressurized & circuit breaker closed. BOYD, D., CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/22. 1p. 33191-009-33191-009.

8510280422 PNO-III-85-092 on 851023, reactor failed to trip automatically following high flux alarm. Cause undetermined. Reactor shut down pending results of investigation. BOYD, D., CHRISSOTIMOS, N. Region 3, Office of Director. 85/10/23. 2pp. 33194-012-33194-013.

188 DOCKETED ITEMS

8510290224 Confirmatory Action Ltr CAL-Rili-85-14 re 851023 telcon discussing improper response of reactor protection sys which resulted in alert & manual rod insertion during 851023 startup.
KEPLER,J.G. Region 3, Office of Director. 85/10/23. TAYLOR,J.W. Dairyland Power Cooperative. 2pp. 33235.002-33235.003.

8510290192 PNO-Ili-85-092A on 851023, unit shut down due to high neutron flux during startup insp team concluded that reactor sys equipment functioned acceptably. Electronic circuit cards replaced.
BOYD,D., CHRISSOTIMOS,N. Region 3, Office of Director. 85/10/24. 2pp. 33236.349-33236.350.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108.264-33109.088.

-8510230185 Forwards Press Release 84-69 re NRC reduction of fine for 1983 violation. Pressure sensing device capped. Fine reduced due to short duration of violation, small size of reactor & comparable enforcement actions.
KAMMERER,C. Office of Congressional Affairs. 84/06/01. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109.008-33109.009.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882.049-32882.075.

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510020170 Forwards supplemental info to Aug 1985 ltr re revetment ditch, including changes to previously submitted info & draft Tech Spec 3/4.7.3 concerning shore barrier protection. Visual insp & distance info discussed, per 850827 meeting request.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/09/27. BUTLER,W. Licensing Branch 2. 13pp. 32824.306-32824.318.

8510040353 Forwards integrated reactor vessel matl surveillance program for review & approval in response to request during recent meeting, due to low lead factors incorporated in facility design.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/09/30. DENTON,H. Office of Nuclear Reactor Regulation, Director. 15pp. 32854.231-32854.245.

8510080467 Forwards responses to seismic review team audit open items & schedule for responses to remaining open items W/two oversize drawings.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/09/30. BUTLER,W. Licensing Branch 2. 12pp. 32920.236-32920.247.

8510070266 Notification of 851003 meeting w/util in Bethesda, MD to discuss power sys issues.
HAUGHEY,M.F. Licensing Branch 2. 85/10/01. BUTLER,W.R. Licensing Branch 2. 4pp. 32901.211-32901.214.

8510150212 Forwards application to utilize alternative to requirements of 10CFR50.55a. Alternative involves transfer of authorized nuclear inspector functions for review of pipe supports & in certification process.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/07. DENTON,H. Office of Nuclear Reactor Regulation, Director. 5pp. 33010.327-33010.331.

8510090432 Requests listing of customers purchasing or ordering valve operators containing magnesium motor rotors. Test anomalies have raised concern re long-term availability of valve operator motors w/magnesium rotors.
BAER,R.L. Engineering & Generic Communications Branch. 85/10/08. DENHAM,F. Limitorque Corp. 1p. 33278.240-33278.240.

8510170109 Suppls 850207 ltr transmitting summary of electrical separation analyses used by GE. Applicant will evaluate 851003 suggested method of resolution for components accepted based on probability analysis.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/09. BUTLER,W. Licensing Branch 2. 1p. 33036.179-33036.179.

8510220162 Further response to FOIA request for documents re insp/ investigation of allegations on Nine Mile Point by J. Ryan, R. No man & A. Laratta. Documents listed in App A available in PDR. Search for addl documents continuing.
FELTON,J.M. Division of Rules and Records. 85/10/10. GARDE,B.P. Government Accountability Project. 2pp. 33097.300-33098.129.

-8510220176 Advises that Allegation RI-84-A-0061 re improper disposition of QA audit findings entered into NRC allegation tracking sys. Allegation reviewed & evaluated for followup actions during allegation panel 840430 meeting.
HAVERKAMP,D.R. NRC - No Detailed Affiliation Given. 84/05/03. STAROSTECKI,R. NRC - No Detailed Affiliation Given. 4pp. 33097.306-33098.129.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044.010-33044.027.

-8510170187 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review: Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-4. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044.114-33044.125.

8510180206 Notification of 851016 meeting w/util in Bethesda, MD to discuss topical rept on QA results based on NRC initial review of rept.
ANKRUM,G.T. Quality Assurance Branch. 85/10/11. GRIMES,B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 2pp. 33069.230-33069.231.

8510230149 Forwards proposed rev to FSAR, providing matl in response to Confirmatory Item 20 re isolation of circuits. Rev should result in closure of confirmatory issue & will be incorporated into future FSAR amend.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/17. BUTLER,W. Licensing Branch 2. 27pp. 33101.291-33101.317.

8510230216 Forwards response to equipment qualification questions transmitted in NRC 850723 ltr. Info will be included in FSAR Amend 22.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/17. BUTLER,W. Licensing Branch 2. 94pp. 33100.122-33100.215.

8510280179 Requests remaining outstanding responses to Generic Ltr 83-28, "Required Action Based on Generic Implications of Salem ATWS Events." Forwards draft technical evaluation rept for Item 1.2, "Post-Trip Review: Data & Info Capabilities."
BUTLER,W.R. Licensing Branch 2. 85/10/18. HOOTEN,B.G. Niagara Mohawk Power Corp. 3pp. 33228.248-33228.262.

8510290426 Summary of 851003 meeting w/util, S&W & GE re containment sys issues. Summary of responses to SER open & confirmatory items, changes to FSAR & list of attendees encl.
HAUGHEY,M.F. Licensing Branch 2. 85/10/18. Licensing Branch 2. 6pp. 33254.290-33254.295.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM,E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262.231-33262.231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review: Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262.232-33262.255.

8510310135 Clarifies 851017 ltr. Environ qualification document will not be included in FSAR Amend 22 as originally stated, since document not considered part of FSAR.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/28. BUTLER,W. Licensing Branch 2. 1p. 33273.322-33273.322.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8507050411 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION UNIT NO. 2. Docket No. 50-410. (Niagara Mohawk Power Corporation)
* Division of Licensing. NUREG-1047 S01. 85/06/30. 35pp. 31372.268-31372.301.

8510020185 Forwards proprietary figures omitted from 850916 submittal re status of various subordinate issues included in SER Confirmatory Issue 13 on pool dynamics. Affidavit requesting withholding of figures per 10CFR2.790(a)(4) encl.
LEMPGES,T.E. Niagara Mohawk Power Corp. 85/09/24. BUTLER,W. Licensing Branch 2. 4pp. 32824.231-32824.234.

8510080480 Forwards info re safety relief valve pool loads, bulk to local pool temp differences & Mark III containment, closing SER Confirmatory Items 6.13F & 13I. FSAR Pages 6A.3-17 & 17A & figures withheld (ref 10CFR2.790).
MANGAN,C.V. Niagara Mohawk Power Corp. 85/09/30. BUTLER,W. Licensing Branch 2. 23pp. 32922.168-32922.190.

8510110084 Forwards results of preliminary leak testing of MSIVs to close SER Open Issue 6. Bonnet stem leakage testing performed by pressurizing between ball valve seats. Values should be compared to acceptance criteria per 851130 ltr.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/09/30. BUTLER,W. Licensing Branch 2. 9pp. 32974.124-32974.132.

8510090013 Forwards revised FSAR Figures 9.5-40a, 9.5-40b, 9.5-40c & 9.5-42 showing certain Div I & II diesel generator interface piping. Figures provided to close SER Confirmatory Item 40 & will be included in next FSAR amend.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/04. BUTLER,W. Licensing Branch 2. 5pp. 32946.026-32946.033.

8510210056 Forwards info re fire protection program. Info reconciles differences in fire protection program described in FSAR, SRP & SER. Activities will be discussed in 851021 meeting.
LEMPGES,T.E. Niagara Mohawk Power Corp. 85/10/11. BUTLER,W. Licensing Branch 2. 5pp. 33072.303-33072.307.

8510290426 Summary of 851003 meeting w/util, S&W & GE re containment sys issues. Summary of responses to SER open & confirmatory items, changes to FSAR & list of attendees encl.
HAUGHEY,M.F. Licensing Branch 2. 85/10/18. Licensing Branch 2. 6pp. 33254.290-33254.295.

F. Security, medical, emergency & fire protection plans

8510100064 Informs of plans to conduct fire protection safe shutdown insp on 851021-25. Analyses, procedures, engineering personnel & contact requested on site for insp.
EBNETER,S.D. Region 1, Office of Director. 85/10/01. HOOTEN,B.G., SEIBERT,C.R. Niagara Mohawk Power Corp. 2pp. 32960.297-32960.298.

8510160349 Forwards draft safety evaluation for safe & alternate shutdown scheduled to be part of next SSER. Draft forwarded for info prior to 851021-25 App B audit.
BUTLER,W.R. Licensing Branch 2. 85/10/10. HOOTEN,B.G. Niagara Mohawk Power Corp. 8pp. 33028.286-33028.293.

8510210056 Forwards info re fire protection program. Info reconciles differences in fire protection program described in FSAR, SRP & SER. Activities will be discussed in 851021 meeting.
LEMPGSTE, T.E. Niagara Mohawk Power Corp. 85/10/11. BUTLER, W. Licensing Branch 2. 5pp. 33072-303-33072-307.

I. Financial Information

8510150083 Informs that financial info submitted for 1985 in 850809 ltr satisfies requirements of 10CFR140.21.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 85/10/01.
RUSHMORE, J.W. Niagara Mohawk Power Corp. 1p. 33042-204-33042-204.

Q. Inspection reports, IE Bulletins & correspondence

8510250438 Informs that 840504 commitment to update QA Category 1 const drawings per NRC Const Appraisal Team Rept 50-410/83-18, requires mod. Engineering & design coordination rept will be used to implement mod beginning on 850920.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/09/17. STAROSTECKI, R. Region 1, Office of Director. 3pp. 33169-333-33169-335.

8510160078 FOIA request for investigation Rept I-84-014.
WENNER, R. Meredith Broadcasting/WTVH Television. 85/09/26. FELTON, J. Division of Rules and Records. 1p. 33028-284-33028-284.

8510020170 Forwards supplemental info to Aug 1985 ltr re revetment ditch, including changes to previously submitted info & draft Tech Spec 3/4.7.3 concerning shore barrier protection. Visual insp & distance info discussed per 850827 meeting request.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/09/27. BUTLER, W. Licensing Branch 2. 13pp. 32824-308-32824-318.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8505260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080193 Requests schedule that indicates when each area of operational readiness listed in encl will be complete & ready for NRC insp. Schedule should be updated monthly to keep projected schedule current.
STAROSTECKI, R. Region 1, Office of Director. 85/10/01. MANGAN, C.V. Niagara Mohawk Power Corp. 5pp. 32921-042-32921-046.

8510100064 Informs of plans to conduct fire protection safe shutdown insp on 851021-25. Analyses, procedures, engineering personnel & contact requested on site for insp.
EBNETER, S.D. Region 1, Office of Director. 85/10/01. HOOTEN, B.G., SEIBERT, C.R. Niagara Mohawk Power Corp. 2pp. 32960-297-32960-298.

8510170295 Forwards Exam Rept 50-410/85-15 of exam administered during wk of 850610. Review of licensed operator training program suggested due to high failure rate of candidates.
STAROSTECKI, R. Region 1, Office of Director. 85/10/02. HOOTEN, B.G. Niagara Mohawk Power Corp. 2pp. 33051-270-33051-276.

-8510170296 Exam Rept 50-410/85-15 on 850611-19. Exam results: 13 candidates passed & 11 failed.
LANGE, D., KELLER, R., KISTER, H. Region 1, Office of Director. 85/10/02. 4pp. 33051-273-33051-276.

8510080096 Forwards Insp Rept 50-410/85-25 on 850722-0830. No violation noted.
COLLINS, S.J. Region 1, Office of Director. 85/10/03. HOOTEN, W.G. Niagara Mohawk Power Corp. 2pp. 32913-169-32913-196.

-8510080104 Insp Rept 50-410/85-25 on 850722-0830. No violation noted. Major areas inspected: work activities, procedures & records re quality performance mgmt program, instrumentation components & piping & pipe supports.
LINVILLE, J.C. Region 1, Office of Director. 85/09/27. 26pp. 32951-027-32951-069.

8510160084 Responds to FOIA request for investigation Rept I-84-014. Forwards 850912 ltr to BP Garde of GAP, provided in response to FOIA Request 85-613. W/o encl.
FELTON, J.M. Division of Rules and Records. 85/10/03. WENNER, R. Meredith Broadcasting/WTVH Television. 1p. 33028-285-33028-285.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230102 Forwards Press Release 84-36 re NRC proposed fine against util for 30 alleged violations. Util ordered to hire consultant firm to evaluate organization.
KAMMERER, C. Office of Congressional Affairs. 84/03/21. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY, E. House of Rep. MOYNIHAN, D. Senate. 2pp. 33108-341-33108-343.

8510220162 Further response to FOIA request for documents re insp/ investigation of allegations on Nine Mile Point by J. Ryan, R. Norman & A. Laratta. Documents listed in App A available in PDR. Search for addl documents continuing.
FELTON, J.M. Division of Rules and Records. 85/10/10. GARDE, B.P. Government Accountability Project. 2pp. 33097-300-33098-129.

-8510220184 Recommends closeout of Allegation 84-A-0156, "Lead Auditor Clarification," per encl insp Rept 50-410/84-15. No response to allegation required.
LINVILLE, J.C. NRC - No Detailed Affiliation Given. 85/05/15. SHROPSHIRE, A. NRC - No Detailed Affiliation Given. 60pp. 33107-109-33107-166.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510210113 Forwards Safety Insp Rept 50-410/85-30 on 850909-13. No violations noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/15. HOOTEN, B.G. Niagara Mohawk Power Corp. 2pp. 33072-215-33072-223.

-8510210117 Insp Rept 50-410/85-30 on 850909-13. No violations noted. Major areas inspected: preoperational test program, procedure review & verification, QA/QC interface w/preoperational test program & independent verification.
BRIGGS, L.E., ESELGROTH, P. Region 1, Office of Director. 85/10/09. 7pp. 33072-217-33072-223.

8510210138 Forwards updated Vol 1 of "Preservice Insp Plan," including all NDE items required by ASME Section XI for nuclear piping sys & reactor pressure vessel. Second & third parts will be submitted by 851130 & 1220, respectively.
LEMPGSTE, T.E. Niagara Mohawk Power Corp. 85/10/15. BUTLER, W. Licensing Branch 2. 2pp. 33080-011-33081-289.

-8510210139 Updated Vol 1 of "Preservice Insp Plan." Eleven oversize sketches encl.
* Niagara Mohawk Power Corp. 85/10/15. 800pp. 33080-013-33081-289.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

S. Reportable occurrences, LERs & related correspondence

8510020433 Interim Deficiency Repts (55(e)-84-10), (55(e)-84-21), (55(e)-84-40), (55(e)-84-42), (55(e)-84-46) & (55(e)-1982) re reverse/back pressure on valves furnished by Clow Corp.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/08/08. STAROSTECKI, R. Region 1, Office of Director. 3pp. 32826-275-32826-277.

8510180125 Final Deficiency Rept (55(e)-85-09) re issuance of trim design details by ITT Grinnell w/o approved design drawings. Initially reported on 850306. Planner packages recalled & reviewed by supplier.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/09/27. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33068-338-33068-339.

8510180395 Interim Deficiency Rept (55(e)-85-27) re standby diesel generator unsuccessful starting during preliminary testing. Initially reported on 850904. Investigation still in progress. Final rept will be submitted by 851104.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/09/30. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33068-051-33068-052.

8510180440 Interim Deficiency Rept (55(e)-85-26) re electrical panelboards field vs seismic test mounting configuration. Initially reported on 850830. Final rept will be submitted by 851230.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/10/01. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33068-053-33068-054.

8510180157 Interim Deficiency Rept (55(e)-85-24) re unsatisfactory soldering connections previously accepted. Initially reported on 850724. Connections reworked. Final rept will be submitted by 860131.
MANGAN, C.V. Niagara Mohawk Power Corp. 85/10/02. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33068-343-33068-344.

8510280310 PNO-I-85-082 on 851018.4 kV nonsafety-related electrical breaker exploded, injuring two const workers. Workers taken to hosp for treatment. Vendor representatives & OSHA investigating cause of event.
GRAMM, R., LINVILLE, J. Region 1, Office of Director. 85/10/24. 2pp. 33193-071-33193-072.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230102 Forwards Press Release 84-36 re NRC proposed fine against util for 30 alleged violations. Util ordered to hire consultant firm to evaluate organization.
KAMMERER, C. Office of Congressional Affairs. 84/03/21. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, A. Senate. UDALL, M. House of Rep. 2pp. 33108-341-33108-343.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510170295 Forwards Exam Rept 50-410/85-15 of exam administered during wk of 850610. Review of licensed operator training program suggested due to high failure rate of candidates.
STAROSTECKI, R. Region 1, Office of Director. 85/10/02. HOOTEN, B.G. Niagara Mohawk Power Corp. 2pp. 33051-270-33051-276.

190 DOCKETED ITEMS

—8510170296 Exam Rept 50-410/85-15 on 850611-19. Exam results: 13 candidates passed & 11 failed.
LANGED, KELLER, KISTER, H. Region 1, Office of Director. 85/10/02. 4pp. 33051:273-33051:276.

8510160067 Forwards operator licensing exam schedule, per 850927 request.
LEMPGES, T.E. Niagara Mohawk Power Corp. 85/10/11. BUTLER, W. Licensing Branch 2. 3pp. 33027:209-33027:211.

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510070255 Advises that proposed schedule for meeting requirements of 10CFR50.62, Paragraph (c), will be submitted 180 days after issuance of SER on Westinghouse ATWS mitigation sys actuation circuitry generic design package.
CAREY, J.J. Duquesne Light Co. 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 1p. 33267:085-33267:085.

8510180193 Forwards proprietary "WHIPJET Program," re improved means for determining necessity to install mechanical devices to protect equipment & structures from effects of pipe breaks. Program withheld (ref 10CFR2.790).
CAREY, J.J. Duquesne Light Co. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33054:358-33054:363.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

—8510170213 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities ...', technical evaluation repts."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-1. 85/10/11. NRC - No Detailed Affiliation Given. 16pp. 33044:215-33044:230.

8510250580 Grants 850709 request for schedular partial exemption from GDC 4 of 10CFR50, App A re need to analyze large primary loop pipe ruptures as structural design basis for facility. Exemption & related documents encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/11. CAREY, J.J. Duquesne Light Co. 5pp. 33226:316-33226:320.

—8510210159 Exemption from GDC 4 of App A to 10CFR50 to permit applicant to eliminate dynamic loading effects re postulated primary loop pipe breaks defined in FSAR & described in Part II of exemption.
THOMPSON, H.L. Division of Licensing. 85/10/11. Duquesne Light Co. 13pp. 33226:321-33226:333.

—8510250589 Topical repts evaluation of WCAP 10456, "Effects of Thermal Aging on Structural Integrity of Cast Stainless Steel Piping for Westinghouse NSSS."
* NRC - No Detailed Affiliation Given. 85/10/11. 10pp. 33226:334-33226:343.

—8510250595 Environ assessment & finding of no significant impact supporting exemption from portion of GDC 4 requirements of 10CFR50, App A re need to analyze large primary loop ruptures as structural design basis.
NOVAK, T.M. Assistant Director for Licensing. 85/09/26. 5pp. 33226:344-33226:348.

D. NRC Draft/Final Environmental Statements, supplis & correspondence

8510080129 Forwards FES for Beaver Valley Power Station, Unit 2 & FR notice of availability W/o encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. HIRSCH, A. Environmental Protection Agency. 2pp. 32925:238-32925:239.

8510090111 Forwards FES (NUREG-1094) re operation of facility.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. WOOD, J.M. Commerce, Dept. of Natl. Oceanographic & Atmospheric Administration. 4pp. 32951:341-32951:346.

8510090191 Forwards FES (NUREG-1094) for Beaver Valley Power Station, Unit 2 & FR notice of availability W/o NUREG.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. CAREY, J.J. Duquesne Light Co. 3pp. 32949:186-32949:190.

—8510090199 Notice of availability of FES (NUREG-1094) for Beaver Valley Power Station, Unit 2.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. 2pp. 32949:189-32949:190.

8510090404 Forwards FR notice of availability of FES (NUREG-1094) for Beaver Valley Power Station, Unit 2, for info.
KNIGHTON, G.W. Licensing Branch 3. 85/10/03. Citizens for a Better Environment. 2pp. 32964:335-32964:338.

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8510170341 Forwards SER re application for OL W/o encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/11. CAREY, J.J. Duquesne Light Co. 3pp. 33043:343-33043:345.

8510220030 Forwards response to final draft SER Confirmatory Issue 34 re assurance that control sys failure would not result in event more severe than design basis event described in FSAR. Confirmatory issue should be closed.
CAREY, J.J. Duquesne Light Co. 85/10/15. KNIGHTON, G.W. Licensing Branch 3. 37pp. 33090:225-33090:261.

8510300048 Forwards SER re application for OL. Eleven outstanding issues identified in Section 1.7 of SER. Resolution of open items required prior to decision on issuance of OL W/o encl.
NOVAK, T.M. Assistant Director for Licensing. 85/10/22. WARD, D. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 33261:357-33261:359.

8510310352 Forwards SER (NUREG-1057) & related notice forwarded to Ofc of FR for publication W/o SER.
KNIGHTON, G.W. Licensing Branch 3. 85/10/22. CAREY, J.J. Duquesne Light Co. 4pp. 33278:149-33278:154.

—8510310355 Notice of issuance & availability of SER (NUREG-1057).
KNIGHTON, G.W. Licensing Branch 3. 85/10/22. 2pp. 33278:153-33278:154.

8510290574 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BEAVER VALLEY POWER STATION, UNIT 2. Docket No. 50-412. (Duquesne Light Company, et al)
* Division of Licensing. NUREG-1057. 85/10/31. 639pp. 33260:001-33261:280.

F. Security, medical, emergency & fire protection plans

8510160184 Forwards comments re review of util public info brochures. Info packet reviewed against NUREG-0654 requirements & determined to meet guidelines.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33021:243-33021:245.

8510160185 Informs of three addl improvements in fire fighting re reasonable assurance of hose stream access into dense concentration of cable trays in northwest corner of cable spreading room. W/one oversize drawing.
CAREY, J.J. Duquesne Light Co. 85/10/08. THOMPSON, H.L. Division of Licensing. 4pp. 33022:248-33022:252.

8510210239 Forwards review comments re info packet, "Important Emergency Info." Info packet adequately meets requirements of NUREG-0654/FEMA REP-1, Rev 1.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33079:337-33079:339.

8510240511 Notification of 851022 meeting w/util & S&W in Bethesda, MD to discuss fire protection deviation requests.
SINGH, B.K. Licensing Branch 3. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33183:041-33183:044.

Q. Inspection reports, IE Bulletins & correspondence

8509180247 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. CAREY, J.J. Duquesne Light Co. 11pp. 32854:327-32854:337.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070159 Forwards Safety Insp Rept 50-412/85-19 on 850806-0916. No violation noted.
WENZINGER, E.C. Region 1, Office of Director. 85/10/01. CAREY, J.J. Duquesne Light Co. 2pp. 32881:017-32881:026.

—8510070166 Insp Rept 50-412/85-19 on 850806-0916. No violation or deviation noted. Major areas inspected: Part 21 repts & insp of pipe supports. Addl concerns re problems in methods used to tighten & lock nuts on pipe clamps noted.
WALTON, G.A. PRIVIDY, L.J., TRIPP, L.E. Region 1, Office of Director. 85/09/26. 8pp. 32881:019-32881:026.

8510110013 Forwards Insp Rept 50-412/85-18 on 850812-16. No violations noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/07. CAREY, J.J. Duquesne Light Co. 2pp. 32973:322-32973:332.

—8510110019 Insp Rept 50-412/85-18 on 850812-16. No violations noted. Major areas inspected: QA program for preoperational testing.
NAPUDA, G., VERNER, J., WINTERS, R. Region 1, Office of Director. 85/09/27. 9pp. 32973:324-32973:332.

8510210104 Responds to NRC 850910 ltr re violations noted in Insp Rept 50-412/85-16. Corrective actions: nonconformance & disposition repts issued, entered into Exception Work Tracking FCP-29 & assigned to applicable sys or area release.
CAREY, J.J. Duquesne Light Co. 85/10/10. WENZINGER, E.C. Region 1, Office of Director. 3pp. 33073:298-33073:300.

8510220057 Forwards Insp Rept 50-412/85-20 on 850826-30. No violation noted.
EBNETER, S.D. Region 1, Office of Director. 85/10/11. CAREY, J.J. Duquesne Light Co. 2pp. 33095:261-33095:268.

—8510220061 Insp Rept 50-412/85-20 on 850826-30. No violation noted. Major areas inspected: concrete const for closure of temporary opening in containment bldg exterior wall & response to IE Bulletin 79-02.
VARELA, A.A., WAGINS, J.T. Region 1, Office of Director. 85/10/08. 6pp. 33095:263-33095:268.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510030417 Final Significant Deficiency Rept 85-05 re insufficient thickness of insulating tape on 5 kv power cable terminations. Initially reported on 850614. Drawing 12241-RE-28A-4 revised to reflect mgt requirements.
CAREY,J.J. Duquesne Light Co. 85/09/16. MURLEY,T.E. Region 1, Office of Director. 4pp. 32846:001-32846:004.

8510240254 Potential Part 21 rept re pipe snubber brackets mfg from matts less than specified by design drawings. Brackets shipped to facility. S&W requested to return brackets. Investigation incomplete.
FISHER,R.C. Paul-Munroe Hydraulics, Inc. 85/10/09. YOUNG,T. Region 1, Office of Director. 1p. 33154:304-33154:304.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510150318 Forwards Rev 6 to training & qualification plan, clarifying fact that security personnel trained to operate detection equipment for search purposes do not have to be trained or qualified to test equipment. Rev withheld (ref 10CFR73.21).
TUCKER,H.B. Duke Power Co. 85/09/30. GRACE,J.N. Region 2, Office of Director. 3pp. 33006:360-33006:362.

8510220355 Rev 7 to emergency plan. W/851014 ltr.
HAMPTON,J.W., TUCKER,H.B. Duke Power Co. 85/10/02. 42pp. 33084:232-33084:273.

8510160145 Advises that States of SC & NC local emergency plans & preparedness adequate to protect health & safety of public pending verification of alert & notification sys.
SPECK,S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS,W.J. Office of the Executive Director for Operations. 3pp. 33002:271-33002:273.

8510210258 Advises that radiological emergency response plan in support of fixed nuclear facilities approved. W/o ltr to NRC indicating approval of alert & local plans & preparedness.
MORRIS,R.H. Federal Emergency Management Agency. 85/10/08. RILEY,R.W. South Carolina, State of. 1p. 33079:328-33079:328.

8510210263 Advises that emergency response plan approved, conditional upon verification of alert & notification sys. W/o ltr to NRC indicating approval of alert & local plans & preparedness.
MORRIS,R.H. Federal Emergency Management Agency. 85/10/08. MARTIN,J. North Carolina, State of. 1p. 33079:327-33079:327.

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER,R.D. Region 2, Office of Director. 85/10/10. TUCKER,H.B. Duke Power Co. 1p. 33026:280-33026:282.

-8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER,H.B. Duke Power Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 2pp. 33026:281-33026:282.

8510220263 Revs to emergency plan implementing procedures, including RP/O/A5000/01, "Classification of Emergency," HP/O/B/1009/01, "Health Physics Plan" & HP/O/B/1009/05, "Personnel/Vehicle Emergency Conditions." W/851014 ltr.
BOLCH,M., LEROY,P.G., TUCKER,H.B. Duke Power Co. 85/10/14. 71pp. 33087:002-33087:070.

8510180271 Responds to EG Adensam 850904 request for confirmation that offsite emergency plans include list of local or regional evaluation facilities which have capabilities to provide treatment for radiation exposure.
TUCKER,H.B. Duke Power Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33061:082-33061:083.

8510220289 Forwards Rev 9 to security plan, incorporating Unit 2 into protected area, addressing deletion of interim barrier between units used during const & super-seeding 10CFR73.67 Rev withheld (ref 10CFR73.21).
TUCKER,H.B. Duke Power Co. 85/10/16. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33084:001-33084:002.

8510250197 Forwards responses to requests for addl justification for exceptions to Reg Guide 1.97, included in 850806 draft technical evaluation rept. Narrow-range containment sump level has no intended accident monitoring function.
TUCKER,H.B. Duke Power Co. 85/10/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 8pp. 33172:131-33172:138.

G. Adjudicatory correspondence

8510040308 Order extending time until 851011 for Commission to act to review ALAB-813. Served on 851003.
CHILK,S.J. Office of the Secretary of the Commission. #485 670. 85/10/02. Commissioners. 1p. 32853:283-32853:283.

8510150343 Order extending time until 851025 for Commission to act to review ALAB-813. Served on 851011.
CHILK,S.J. Office of the Secretary of the Commission. #485 758. 85/10/11. Commissioners. 1p. 33000:351-33000:351.

8510310305 Advises that time for Commission to review ALAB-813 expired. Commission declined review. Decision became final agency action on 851025. Served on 851028.
CHILK,S.J. Office of the Secretary of the Commission. #485 969. 85/10/28. Atomic Safety and Licensing Board Panel. 1p. 33272:037-33272:037.

I. Financial Information

8510290382 Forwards "Duke Power Co. 1984 Annual Rept.," including financial forecast for 1985-1987 & interim financial statements for 850630.
TUCKER,H.B. Duke Power Co. 85/10/17. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33246:245-33246:310.

K. Utility Final Safety Analysis Report (FSAR) & amend

8510070281 Amend 35 to application for licenses, consisting of Rev 13 to FSAR Response to final rule on pressurized thermal shock encl.
OWEN,W.H. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 32879:001-32880:297.

-8510070290 Rev 13 to FSAR for Catawba Units 1 & 2.
* Duke Power Co. 85/10/01. 850pp. 32879:003-32880:297.

P. Operating license stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER,H.B. Duke Power Co. 85/03/01. GRACE,J.N. Region 2, Office of Director. 3pp. 32865:148-32865:239.

-8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-IX withheld.
* Duke Power Co. 85/03/01. 46pp. 32865:194-32865:239.

8510010260 Remits fee in response to 850918 ltr.
TUCKER,H.B. Duke Power Co. 85/09/24. NORRY,P.G. Office of Administration. DIGGS,R.M. License Fee Management Branch. 2pp. 32802:237-32802:238.

8510020158 "Catawba Nuclear Station Unit 1 Startup Rept."
* Duke Power Co. * North Carolina Electric Membership Corp. * Saluda River Electric Cooperative, Inc. 85/09/27. 431pp. 32821:001-32822:071.

8510070281 Amend 35 to application for licenses, consisting of Rev 13 to FSAR Response to final rule on pressurized thermal shock encl.
OWEN,W.H. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 32879:001-32880:297.

8510150090 Proposes schedule of proposed implementation of QA guidance provided by Generic Ltr 85-06. Implementation schedule will not occur during 1986 refueling outages.
TUCKER,H.B. Duke Power Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33008:301-33008:302.

8510170346 Final response to FOIA request for four categories of documents re notices of violation for facility. Forwards Apps L & M documents. Documents also available in PDR App M documents partially withheld (ref FOIA Exemption 7).
FELTON,J.M. Division of Rules and Records. 85/10/08. BELL,N. Nuclear Information & Resource Service. 4pp. 33051:058-33051:118.

-8510170349 Forwards marked-up affidavit of WR McAfee re concerns over quality of const at facility & ability to operate safely & w/o harm to public health.
GARDE,B.P. Government Accountability Project. 84/01/03. URYC,B. Region 2, Office of Director. SINCLAIR,J. Office of Investigation. 49pp. 33051:064-33051:112.

8510170311 Forwards seismic qualification test rept per 850624 summary description of test performed in response to Condition 1.1 of License NPF-35.
TUCKER,H.B. Duke Power Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 1p. 33040:067-33042:145.

-8510170315 "Seismic Simulation Test Program on Electrical Isolation Mounting Sys of Typical Electrical Encl."
PINKERTON,B., JORDAN,H., HIGHT,G.W. Wyle Laboratories. 47726-1. 85/06/06. 800pp. 33040:068-33042:145.

8510250190 Forwards proof & review Tech Specs. Requests review & identification of statements which do not accurately reflect FSAR SER or as-built facility. Response necessary by C.O.B. 851030 to support 851220 issuance of final draft.
ADENSAM,E. Licensing Branch 4. 85/10/10. TUCKER,H.B. Duke Power Co. 500pp. 33198:162-33199:354.

8510160300 Application for amend to License NPF-35, proposing one-time emergency amend to Tech Specs re RCS unidentified leakage. Fee paid.
PRIORY,R.B. Duke Power Co. 85/10/11. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 3pp. 33026:283-33026:288.

-8510160302 Proposed Tech Spec 3.4.6.2 re RCS unidentified leakage.
* Duke Power Co. 85/10/11. 3pp. 33026:286-33026:288.

8510180108 Requests rescission of 851011 application for emergency amend to Tech Specs, allowing hot standby (Mode 3) for addl 72 h. Application deemed necessary due to unidentified RCS leakage found on 851010. Leakage rate reduced.
TUCKER,H.B. Duke Power Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 3pp. 33063:171-33063:173.

8510230059 Application for amend to License NPF-35, authorizing temporary extension of allowed time in Mode 3 w/ unidentified RCS leakage greater than 1 gpm. Fee paid.
TUCKER,H.B. Duke Power Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 4pp. 33102:176-33102:181.

192 DOCKETED ITEMS

—8510230064 Proposed Tech Spec 3.4.6.2, authorizing temporary extension of allowed time in Mode 3 w/identified RCS leakage greater than 1 gpm.
* Duke Power Co. 85/10/18. 3pp. 33102:179-33102:181.

8510250029 Confirms 851018 telcon authorizing 72-h extension to time allowed in Mode 3 w/unidentified RCS leakage greater than 1 gpm, per 851018 request for emergency change to "h Spec 3.4.6.2."
NOVAK, T.M. Assistant Director for Licensing. 85/10/21. TUCKER, H.B. Duke Power Co. 1p. 33225:001-33225:001.

Q. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

—8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510080543 Forwards Insp Repts 50-413/85-40 & 50-414/85-38 on 850909-13. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/27. TUCKER, H.B. Duke Power Co. 1p. 32927:122-32927:131.

—8510080548 Insp Repts 50-413/85-40 & 50-414/85-38 on 850909-13. No violation or deviation noted. Major areas inspected: mat'l identification & control, housekeeping, safety-related structures & components & HVAC sys.
KLEINSORGE, W.P., BLAKE, J.J. Region 2, Office of Director. 85/09/24. 9pp. 32927:123-32927:131.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510040290 Forwards response to notice of violation & proposed imposition of civil penalty re alleged discrimination against employee for raising safety concerns, per 850813 ltr. Objection to \$64,000 civil penalty discussed.
OWEN, W.H. Duke Power Co. 85/10/01. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 76pp. 32853:105-32853:180.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

—8510230023 Forwards Press Release 85-108 re proposed fine concerning util alleged violation of NRC requirements which prohibit discrimination against employee for identifying safety concerns to mgt.
KAMMERER, C. Office of Congressional Affairs. 85/08/13. MARKEY, E. House of Rep., Energy & Commerce. HOLLINGS, THURMOND Senate. 2pp. 33109:021-33109:022.

8510170346 Final response to FOIA request for four categories of documents re notices of violation for facility. Forwards Apps L & M documents. Documents also available in PDR. App M documents partially withheld (ref FOIA Exemption 7).
FELTON, J.M. Division of Rules and Records. 85/10/08. BELL, N. Nuclear Information & Resource Service. 4pp. 3305:158-33051:118.

—8510170352 Requests nondisclosure affidavits from staff members: for access to transcripts re harassment of QC inspectors. W/o encl pages of transcripts re harassment.
O'REILLY, J.P. Region 2, Office of Director. 84/01/23. VORSE, J.Y. Office of Investigation. 1p. 33051:113-33051:113.

—8510170357 Provides addl info re 831025 interview B Garde, B Jones & B Guild attended interview. Signed sworn statement not taken due to late hour of termination of interview. Info partially withheld.
URYC, B. Region 2, Office of Director. 83/10/31. VORSE, J.Y. Office of Investigation. 2pp. 33051:114-33051:118.

8510160288 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/85-26 & 50-370/85-31.
WALKER, R.D. Region 2, Office of Director. 85/10/10. TUCKER, H.B. Duke Power Co. 1p. 33026:280-33026:282.

—8510160294 Responds to NRC 850828 ltr re violations noted in Insp Repts 50-369/85-26, 50-370/85-31 & 50-413/85-33. Corrective actions withheld.
TUCKER, H.B. Duke Power Co. 85/09/27. GRACE, J.N. Region 2, Office of Director. 2pp. 33026:281-33026:282.

8510180124 Forwards Exam Rept 50-413/OL-85-03 of exam administered on 850909-13.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/10. TUCKER, H.B. Duke Power Co. 2pp. 33058:051-33058:254.

—8510180133 Exam Rept 50-413/OL-85-03 on 850909-13. Exam results: all nine senior reactor operator candidates passed oral & written exams. All twelve reactor operator candidates passed oral exam & eleven passed written exam.
ROGERS, T., WILSON, B.A. Region 2, Office of Director. 85/10/07. 200pp. 33058:053-33058:254.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously H₂/I Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510210267 Monthly operating rept for Sept 1985. W/851015 ltr.
REAVIS, J.A., TUCKER, H.B. Duke Power Co. 85/09/30. 7pp. 33094:345-33094:351.

8510230050 Forwards fifth bimonthly rept on status of confirmatory research program of tests & analyses re containment response for main steamline break accidents.
TUCKER, H.B. Duke Power Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAME, G. Licensing Branch 4. 2pp. 33101:361-33101:362.

S. Reportable occurrences, LERs & related correspondence

8510010106 LER 85-045-01: on 850710, reactor trip occurred on lo-lo steam generator level during surveillance calibr when technician relayed incorrect transmitter mark number for isolation. Caused by personnel error W/850925 ltr.
OUELLETTE, R.W., TUCKER, H.B. Duke Power Co. 85/09/25. 5pp. 32809:193-32809:197.

8510020250 LER 85-044-01: on 850622, steam generator lo-lo level reactor trip occurred. Caused by main feedwater pump turbine speed increasing w/o proper mode due to miscommunication. Sys affected returned to normal alignment. W/850926 ltr.
OUELLETTE, R.W., TUCKER, H.B. Duke Power Co. 85/09/26. 5pp. 32827:182-32827:186.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510090466 LER 85-054-00: on 850906, 08, 11 & 17, containment noble gas & iodine radiation monitors EMF39 & EMF40 tripped. Caused by increased containment activity due to fuel rod cladding leaks. Monitor setpoints revised W/851004 ltr.
OUELLETTE, R.W., TUCKER, H.B. Duke Power Co. 85/10/04. 5pp. 32946:088-32946:092.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

8510250116 LER 85-055-00: on 850919, backup fire hose for auxiliary bldg hose station removed while permanent hose station still inoperable. Caused by procedural deficiency. Wye connection & backup hose reinstalled W/851018 ltr.
OUELLETTE, R.W., TUCKER, H.B. Duke Power Co. 85/10/18. 4pp. 33223:022-33223:025.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

—8510230023 Forwards Press Release 85-108 re proposed fine concerning util alleged violation of NRC requirements which prohibit discrimination against employee for identifying safety concerns to mgt.
KAMMERER, C. Office of Congressional Affairs. 85/08/13. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:021-33109:022.

V. Operator Examinations

8509240246 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510180124 Forwards Exam Rept 50-413/OL-85-03 of exam administered on 850909-13.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/10. TUCKER, H.B. Duke Power Co. 2pp. 33058:051-33058:254.

—8510180133 Exam Rept 50-413/OL-85-03 on 850909-13. Exam results: all nine senior reactor operator candidates passed oral & written exams. All twelve reactor operator candidates passed oral exam & eleven passed written exam.
ROGERS, T., WILSON, B.A. Region 2, Office of Director. 85/10/07. 200pp. 33058:053-33058:254.

A. Application/construction stage documents & correspondence

8503200025 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1984" & Rev 5 to "Offsite Dose Calculation Manual." No member of public received annual calculated dose in excess of 40CFR190 requirements.
TUCKER,H.B. Duke Power Co. 85/03/01. GRACE,J.N. Region 2, Office of Director. 3pp. 32865:148-32865:239.

-8510040542 Revised Vol 1 to "Process Control Program," Sections I-V. Sections VI-IX withheld.
* Duke Power Co. 85/03/01. 46pp. 32865:194-32865:239.

8510070281 Amend 35 to application for licenses,consisting of Rev 13 to FSAR,Response to final rule on pressurized thermal shock encl.
OWEN,W.H. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32879:001-32880:297.

8510180541 Forwards list of remaining const testing & insp items that require resolution prior to fuel loading,per Insp Procedure 94300B.Earliest fuel loading date projected for 860101.
WALKER,R.D. Region 2, Office of Director. 85/10/02. THOMPSON,H.L. Division of Licensing. 15pp. 33058:257-33068:271.

8510150090 Proposes schedule of proposed implementation of QA guidance provided by Generic Ltr 85-06..Implementation schedule will not occur during 1986 refueling outages.
TUCKER,H.B. Duke Power Co. 85/10/08. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33008:301-33008:302.

8510170346 Final response to FOIA request for four categories of documents re notices of violation for facility.Forwards Apps L & M documents.Documents also available in PDR.App M documents partially withheld (ref FOIA Exemption 7).
FELTON,J.M. Division of Rules and Records. 85/10/08. BELL,N. Nuclear Information & Resource Service. 4pp. 33051:058-33051:118.

-8510170349 Forwards marked-up affidavit of WR McAfee re concerns over quality of const at facility & ability to operate safely & w/o harm to public health.
GARDE,B.P. Government Accountability Project. 84/01/03. URYC.B. Region 2, Office of Director. SINCLAIR,J. Office of Investigation. 49pp. 33051:064-33051:112.

8510170311 Forwards seismic qualification test rept per 850624 summary description of test performed in response to Condition 19 of License NPF-35.
TUCKER,H.B. Duke Power Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 1p. 33040:067-33042:145.

-8510170315 "Seismic Simulation Test Program on Electrical Isolation Mounting Sys of Typical Electrical Encl."
PINKERTON,B., JORDAN,H., HIGHT,G.W. Wyle Laboratories. 47726-1. 85/06/06. 800pp. 33040:068-33042:145.

8510250190 Forwards proof & review Tech Specs,Requests review & identification of statements which do not accurately reflect FSAR,SER or as-built facility,Response necessary by C.O.B. 851030 to support 851220 issuance of final draft.
ADENSAM,E. Licensing Branch 4. 85/10/10. TUCKER,H.B. Duke Power Co. 500pp. 33198:162-33199:354.

8510300190 Forwards "Inservice Testing Program for Pumps & Valves," for incorporation into existing Unit 1 pump & valve inservice testing manual.
TUCKER,H.B. Duke Power Co. 85/10/25. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 1p. 33249:240-33250:041.

-8510300196 Rev 0 to "Inservice Testing Program for Pumps & Valves."
* Duke Power Co. 85/10/25. 140pp. 33249:241-33250:041.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510070477 Forwards Insp Rept 50-414/85-35 on 850826-30 & 0909-13.No violations or deviations noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/10/02. TUCKER,H.B. Duke Power Co. 1p. 32878:171-32878:177.

-8510070480 Insp Rept 50-414/85-35 on 850826-30 & 0909-13.No violations or deviations noted.Major areas inspected:SER item review, preoperational test procedure review & witnessing & hot functional testing.
THOMAS,J., MCELHINNEY,T.F., JAPE,F. Region 2, Office of Director. 85/09/30. 6pp. 32878:172-32878:177.

F. Security, medical, emergency & fire protection plans

8510150318 Forwards Rev 6 to training & qualification plan,clarifying fact that security personnel trained to operate detection equipment for search purposes do not have to be trained or qualified to test equipment.Rev withheld (ref 10CFR73.21).
TUCKER,H.B. Duke Power Co. 85/09/30. GRACE,J.N. Region 2, Office of Director. 3pp. 33006:360-33006:362.

8510220355 Rev 7 to emergency plan,W/851014 ltr.
HAMPTON,J.W., TUCKER,H.B. Duke Power Co. 85/10/02. 42pp. 33084:232-33084:273.

8510160145 Advises that States of SC & NC local emergency plans & preparedness adequate to protect health & safety of public pending verification of alert & notification sys.
SPECK,S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS,W.J. Office of the Executive Director for Operations. 3pp. 33022:271-33022:273.

8510210258 Advises that radiological emergency response plan in support of fixed nuclear facilities approved,W/o ltr to NRC indicating approval of state & local plans & preparedness.
MORRIS,R.H. Federal Emergency Management Agency. 85/10/08. RILEY,R.W. South Carolina, State of. 1p. 33079:328-33079:328.

8510210263 Advises that emergency response plan approved,conditional upon verification of alert & notification sys,W/o ltr to NRC indicating approval of state & local plans & preparedness.
MORRIS,R.H. Federal Emergency Management Agency. 85/10/08. MARTIN,J. North Carolina, State of. 1p. 33079:327-33079:327.

8510220263 Revs to emergency plan implementing procedures,including RP/O/A5000/01, "Classification of Emergency," HP/O/B/1009/01, "Health Physics Plan" & HP/O/B/1009/05, "Personnel/Vehicle, Emergency Conditions." W/851014 ltr.
BOLCH,M., LEROY,P.G., TUCKER,H.B. Duke Power Co. 85/10/14. 71pp. 33087:002-33087:070.

8510180271 Responds to EG Adensam 850904 request for confirmation that offsite emergency plans include list of local or regional medical facilities which have capabilities to provide treatment for radiation exposure.
TUCKER,H.B. Duke Power Co. 85/10/15. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 33061:082-33061:083.

8510220289 Forwards Rev 9 to security plan,incorporating Unit 2 into protected area,addressing deletion of interim barrier between units used during const & superseding 10CFR73.67,Rev withheld (ref 10CFR73.21).
TUCKER,H.B. Duke Power Co. 85/10/16. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33084:001-33084:002.

8510250197 Forwards responses to requests for add'l justification for exceptions to Reg Guide 1.97,including in 850806 draft technical evaluation rept.Narrow-range containment sump level has no intended accident monitoring function.
TUCKER,H.B. Duke Power Co. 85/10/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 8pp. 33172:131-33172:138.

G. Adjudicatory correspondence

8510040308 Order extending time until 851011 for Commission to act to review ALAB-813.Served on 851003.
CHILK,S.J. Office of the Secretary of the Commission. #485 670. 85/10/02. Commissioners. 1p. 32853:283-32853:283.

8510150343 Order extending time until 851025 for Commission to act to review ALAB-813.Served on 851011.
CHILK,S.J. Office of the Secretary of the Commission. #485 758. 85/10/11. Commissioners. 1p. 33000:351-33000:351.

8510310305 Advises that time for Commission to review ALAB-813 expired,Commission declined review.Decision became final agency action on 851025.Served on 851028.
CHILK,S.J. Office of the Secretary of the Commission. #485 969. 85/10/28. Atomic Safety and Licensing Board Panel. 1p. 33272:037-33272:037.

I. Financial information

8510290382 Forwards "Duke Power Co,1984 Annual Rept," including financial forecast for 1985-1987 & interim financial statements for 850630.
TUCKER,H.B. Duke Power Co. 85/10/17. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33246:245-33246:310.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510070281 Amend 35 to application for licenses,consisting of Rev 13 to FSAR,Response to final rule on pressurized thermal shock encl.
OWEN,W.H. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E.G. Licensing Branch 4. 2pp. 32879:001-32880:297.

-8510070290 Rev 13 to FSAR for Catawba Units 1 & 2.
* Duke Power Co. 85/10/01. 850pp. 32879:003-32880:297.

Q. Inspection reports, IE Bulletins & correspondence

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance.Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON,D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT,J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510060543 Forwards Insp Repts 50-413/85-40 & 50-414/85-38 on 850909-13.No violation or deviation noted.
BROWNLEE,V.L. Region 2, Office of Director. 85/09/27. TUCKER,H.B. Duke Power Co. 1p. 32927:122-32927:131.

-8510080548 Insp Repts 50-413/85-40 & 50-414/85-38 on 850909-13.No violation or deviation noted.Major areas inspected:matl identification & control,housekeeping,safety-related structures & components & HVAC sys.
KLEINSORGE,W.P., BLAKE,J.J. Region 2, Office of Director. 85/09/24. 9pp. 32927:123-32927:131.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint,Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510040290 Forwards response to notice of violation & proposed imposition of civil penalty re alleged discrimination against employee for raising safety concerns,per 850813 ltr. Objection to \$64,000 civil penalty discussed.
OWEN,W.H. Duke Power Co. 85/10/01. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 76pp. 32853:105-32853:180.

194 DOCKETED ITEMS

8510040144 Forwards Diesel Engine 2A component revalidation insps & results per insp plan submitted on 850430. Defective weld heads replaced. Diesel Engine 2B insp in progress. Insp rept will not be submitted based on prior insps.
TUCKER, H.B. Duke Power Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 32850:064-32850:187.

-8510040168 "Catawba Nuclear Station Diesel Engine 2A Component Revalidation Insp."
* Duke Power Co. 85/09/25. 122pp. 32850:066-32850:187.

8510070477 Forwards Insp Rept 50-414/85-35 on 850826-30 & 0909-13. No violations or deviations noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/02. TUCKER, H.B. Duke Power Co. 1p. 32878:171-32878:177.

-8510070480 Insp Rept 50-414/85-35 on 850826-30 & 0909-13. No violations or deviations noted. Major areas inspected: SER item review, preoperational test procedure review & witnessing & hot functional testing.
THOMAS, M., MCELHINNEY, T.F., JAPE, F. Region 2, Office of Director. 85/09/30. 6pp. 32878:172-32878:177.

8510180541 Forwards list of remaining const testing & insp items that require resolution prior to fuel loading per Insp Procedure 94300B. Earliest fuel loading date projected for 860101.
WALKER, R.D. Region 2, Office of Director. 85/10/02. THOMPSON, H.L. Division of Licensing. 15pp. 33068:257-33068:271.

8510180381 Forwards Insp Rept 50-414/85-41 on 850917-20 & notice of violation.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/04. TUCKER, H.B. Duke Power Co. 2pp. 33068:037-33068:045.

-8510180382 Notice of violation from insp on 850917-20.
* Region 2, Office of Director. 85/10/04. 1p. 33068:039-33068:039.

-8510180388 Insp Rept 50-414/85-41 on 850917-20. Violation noted: documentation of storage insp activities for safety-related cables unavailable for insp.
RUFF, A.B., CONLON, T.E. Region 2, Office of Director. 85/10/03. 6pp. 33068:040-33068:045.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230023 Forwards Press Release 85-108 re proposed fine concerning util alleged violation of NRC requirements which prohibit discrimination against employee for identifying safety concerns to mgt.
KAMMERER, C. Office of Congressional Affairs. 85/08/13. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:021-33109:022.

8510170346 Final response to FOIA request for four categories of documents re notices of violation for facility. Forwards Apps L & M documents. Documents also available in PDR. App M documents partially withheld (ref FOIA Exemption 7).
FELTON, J.M. Division of Rules and Records. 85/10/08. BELL, N. Nuclear Information & Resource Service. 4pp. 33051:058-33051:118.

-8510170352 Requests nondisclosure affidavits from staff members for access to transcripts re harassment of QC inspectors. W/o encl pages of transcripts re harassment.
O'REILLY, J.P. Region 2, Office of Director. 84/01/23. VORSE, J.Y. Office of Investigation. 1p. 33051:113-33051:113.

-8510170357 Provides addl info re 831025 interview. B Garde, B Jones & B Guild attended interview. Signed sworn statement not taken due to late hour of termination of interview. Info partially withheld.
URYC, B. Region 2, Office of Director. 83/10/31. VORSE, J.Y. Office of Investigation. 2pp. 33051:114-33051:118.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510230050 Forwards fifth bimonthly rept on status of confirmatory research program of tests & analyses re containment response for main steamline break accidents.
TUCKER, H.B. Duke Power Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 33101:361-33101:362.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAIT, J. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BEHLINGER, J. Division of Licensing. 26pp. 32824:280-32824:305.

8510150091 Summary of Operating Reactors Events Meeting 85-18 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230023 Forwards Press Release 85-108 re proposed fine concerning util alleged violation of NRC requirements which prohibit discrimination against employee for identifying safety concerns to mgt.
KAMMERER, C. Office of Congressional Affairs. 85/08/13. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:021-33109:022.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8510010462 Revised emergency plan procedures, including Rev 9 to 10-S-01-1 re activation of emergency plan & Rev 10 to 10-S-01-6 re notification of offsite agencies & plant on-call emergency personnel W/850920 ltr.
HURLEY, J., CROSS, J.C., DALE, L.F. Mississippi Power & Light Co. 85/09/20. GRACE, N. Region 2, Office of Director. 51pp. 32804:026-32804:078.

8510080532 Forwards Insp Rept 50-416/85-33 on 850817-0916 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/09/27. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 32927:159-32927:171.

-8510080538 Insp Rept 50-416/85-33 on 850817-0916. Violations noted: failure to test containment air lock test connections per 10CFR50, App J & exceeding 30-day reporting criteria per 10CFR50.73.
BUTCHER, R.C., CALDWELL, J.L., PANCIERA, V.W. Region 2, Office of Director. 85/09/26. 9pp. 32927:163-32927:171.

8510180035 Responds to violations noted in Insp Rept 50-416/85-24. Corrective actions: training given to shift health physics personnel & disciplinary action taken against supervisor & subordinate health physicists.
DALE, L.F. Mississippi Power & Light Co. 85/09/27. GRACE, J.N. Region 2, Office of Director. 4pp. 33063:052-33063:055.

8510230014 Advises that State of LA & local plans & preparedness for facility adequate to protect health & safety of public. Approval conditional on verification of alerting & notification sys per NUREG-0654/Rev 1 to FEMA REP-1, App 3.
SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33101:347-33101:347.

8510160214 Forwards Rev 6 to "Offsite Dose Calculation Manual." Current rev to manual will be submitted w/next semiannual radioactive effluent release rept.
DALE, L.F. Mississippi Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33023:045-33023:122.

-8510160216 Rev 6 to "Offsite Dose Calculation Manual."
SMITH, G.O. Mississippi Power & Light Co. 85/09/27. 74pp. 33023:047-33023:122.

8510180360 Concurs w/actions taken or underway re emergency preparedness, quality programs & administrative controls affecting quality & licensing in util 850803 response to SALP Repts 50-416/85-12 & 50-417/85-03.
GRACE, J.N. Region 2, Office of Director. 85/10/10. RICHARD, J.B. Mississippi Power & Light Co. 5pp. 33059:266-33059:275.

8510220365 Application for amend to License NPF-29, revising Tech Specs to reflect deferral of installation of automatic depressurization sys air receiver pressure indication in control room to second refueling outage. Fee paid.
KINGSLEY, O.D. Mississippi Power & Light Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33088:176-33088:182.

-8510220366 Proposed Tech Specs reflecting deferral of installation of automatic depressurization sys air receiver pressure indication in control room to second refueling outage.
* Mississippi Power & Light Co. 85/10/11. 1p. 33088:182-33088:182.

8510250264 Forwards SER re allowable control room leakage to meet control room habitability requirements. Reduction in allowable leakage rate recommended during simultaneous operation of Units 1 & 2.
NOVAK, T.M. Assistant Director for Licensing. 85/10/16. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 33226:167-33226:171.

-8510250274 SER re allowable control room leakage to meet habitability requirements. Reduction in allowable control room leakage for completed control room to 590 cfm recommended.
* NRC - No Detailed Affiliation Given. 85/10/16. 3pp. 33226:169-33226:171.

8510290038 Revised corporate emergency plan procedures, including Rev 1 to Procedure 4.1, "Organization & Position Description" & Rev 1 to Procedure 4.3, "Initial Notification & Mobilization." W/851021 ltr.
DALE, L.F. Mississippi Power & Light Co. 85/10/21. GRACE, N. Region 2, Office of Director. 200pp. 33229:001-33229:317.

8510310509 Forwards Amend 6 to License NPF-29 & safety evaluation. Amend modifies Tech Specs re unit organization, primary containment penetration conductor overcurrent protective devices & fire detection instrumentation.
ADENSAM, E.G. Licensing Branch 4. 85/10/21. RICHARD, J.B. Mississippi Power & Light Co. 3pp. 33278:327-33278:351.

—8510310516 Amend 6 to License NPF-29, modifying Tech Specs re control rod scram accumulator, fire detection instrumentation, electrical power sys, diesel generator test schedule & primary containment penetration overcurrent devices.
ADENSAM, E.G. Licensing Branch 4. 85/10/21. 19pp. 33278:329-33278:347.

I. Financial information

8510310331 Requests certification of pollution control facilities being financed by Claiborne County, MS pollution control revenue bonds in Nov 1985. Facilities financed by previous series of bonds certified in 1983 & 1984.
KNOTTS, J.B. Bishop, Liberman, Cook, Purcell & Reynolds. KNOTTS, J.B. South Mississippi Electric Power Association. 85/10/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 28pp. 33273:036-33273:076.

—8510310333 Forwards executed certificate for pollution control facilities described in Attachment 2 to 841102 request.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 84/11/13.
KNOTTS, J.B. Bishop, Liberman, Cook, Purcell & Reynolds. KNOTTS, J.B. Middle South Utilities, Inc. - Middle South Energy, Inc. 8pp. 33273:043-33273:076.

P. Operating license stage documents & correspondence

8510030259 Forwards notice of consideration of issuance of amend to License NPF-29 & proposed NSHC determination & opportunity for hearing re retracting of spent fuel pool, per 850506 submittal.
ADENSAM, E.G. Licensing Branch 4. 85/09/16. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 32849:088-32849:106.

—8510030262 Notice of consideration of issuance of amend to License NPF-29 & proposed NSHC determination & opportunity for hearing to allow increased upper containment pool capacity & spent fuel storage capacity.
STABLE, C.R. Licensing Branch 4. 85/09/10. 19pp. 32849:088-32849:106.

8510020302 Application for amend to License NPF-29, supplementing 850812, 23 & 30 submittals, to provide justification for exemption from Tech Spec 6.3.1 & 6.4.1 requirements for senior reactor operator qualifications.
KINGSLEY, O.D. Mississippi Power & Light Co. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32825:189-32825:204.

—8510020304 Proposed changes to Tech Specs 6.3.1 & 6.4.1, providing justification for exemption from requirements for senior reactor operator qualifications.
* Mississippi Power & Light Co. 85/09/25. 11pp. 32825:194-32825:204.

8510070481 Provides addl info to support proposed change to Tech Specs 4.1.3.3.b.1.b.GE info ltr dtd 850809 entitled "Hydraulic Control Unit Accumulator Pressure Switches," to support proposed change, encl.
DALE, L.F. Mississippi Power & Light Co. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32878:139-32878:142.

8510070316 Forwards response to NRC questions raised in 850815 telcon re Generic Ltr 83-28, Item 1.2, Balance-of-plant Points N30N026A, B & C added to balance-of-plant computer post-trip log will provide actual turbine bypass valve position info.
DALE, L.F. Mississippi Power & Light Co. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32880:338-32880:342.

8510070452 Forwards response to Item 3.2 of Generic Ltr 83-28 re post-maint testing of safety-related components. Response for Item 4.5.3 will be provided within 90 days of NRC issuance of evaluation of BWR Owners Group rept.
DALE, L.F. Mississippi Power & Light Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32878:341-32878:344.

8510070475 Provides update on qualification status of eq. items for which extension of environ qualification deadline until 851130 requested. Items include Rosemount transmitters & American Switch Co solenoid valves.
DALE, L.F. Mississippi Power & Light Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32878:178-32878:180.

8510080494 Forwards resumes of two individuals appointed as supervisors to organization radiation control function, per request for addl info re 850712 proposed change to Tech Spec Figure 6.2.2-1.
DALE, L.F. Mississippi Power & Light Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 32921:182-32921:188.

8510090073 Advises that 850716 request for exemption from written reporting requirements re manual & automatic actuations of ESF will be addressed on generic basis during current reevaluation of 10CFR50.72 & 73.
ADENSAM, E.G. Licensing Branch 4. 85/10/02. RICHARD, J.B. Mississippi Power & Light Co. 3pp. 32963:339-32963:341.

8510090090 Forwards calculational info to justify proposed increase in diesel fuel oil storage requirements in 850823 proposed change to Tech Specs 3.8.1.1.b.2.a & 3.8.1.2.b.2.a.
DALE, L.F. Mississippi Power & Light Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 12pp. 32941:271-32941:282.

8510150021 Notification of 851011 meeting w/Exxon Nuclear Co, Inc in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.

8510150103 Forwards "Weir Wall Overflow Probability Analysis." Because of very low probability of occurrence & lack of safety significance for worst case postulated overflow (ref AECM-85/0046), corrective actions not warranted.
DALE, L.F. Mississippi Power & Light Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33010:342-33010:346.

8510150049 Application for amend to License NPF-29, supplementing 850823 request. Amend supports design change scheduled during planned outage in Oct 1985.
KINGSLEY, O.D. Mississippi Power & Light Co. 85/10/05. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33008:357-33008:359.

—8510150054 Proposed Tech Spec 3.7.1.3, supplementing 850823 request to support design change scheduled during planned outage in Oct 1985.
* Mississippi Power & Light Co. 85/10/05. 3pp. 33008:360-33008:362.

8510150187 Responds to request for addl info re 850812 application for amend to License NPF-29. Prompt resolution of questions & approval of previously submitted Tech Specs needed for outage scheduled to start on 851012.
DALE, L.F. Mississippi Power & Light Co. 85/10/05. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 33008:269-33008:275.

8510160363 Extends thanks for cooperation during 850911/13 data gathering trip. Brief visit in Jan 1986 may be required to confirm plant design features & procedures most important to severe core damage potential.
ERNST, M.L. Division of Risk Analysis & Operations (post 840429). 85/10/07. KINGSLEY, O.D. Mississippi Power & Light Co. 2pp. 33034:291-33034:292.

8510160061 Summarizes status of Hydrogen Control Owners Group program plan tasks. Task 1 re station blackout & ATWS complete. Task 6 re hydrogen combustion testing still in progress, awaiting completion of Subtask 6.26.
DALE, L.F. Mississippi Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027:200-33027:201.

8510160073 Forwards "Grand Gulf Nuclear Station Unit 1 Post-Warranty Run, Operational Readiness Review." Rept documents full compliance w/License Condition 2.C.(4a).
DALE, L.F. Mississippi Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027:213-33027:240.

—8510160083 "Grand Gulf Nuclear Station Unit 1, Post-Warranty Run, Operational Readiness Review."
GREEN, H.J., FISCHER, S.R., HENDRIE, J.M. Mississippi Power & Light Co. 85/09/30. 26pp. 33027:215-33027:240.

8510160042 Requests NRC concurrence in withdrawal of 830817 commitment requiring IGSCC examiners to perform proficiency exams due to examiners participation in EPRI requalification program. Fee paid.
DALE, L.F. Mississippi Power & Light Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33024:168-33024:170.

8510180494 Notification of 851025 meeting w/util in Bethesda, MD to discuss schedule for completing licensing actions.
KINTNER, L.L. Licensing Branch 4. 85/10/11. ADENSAM, E.G. Licensing Branch 4. 2pp. 33077:337-33077:338.

8510220365 Application for amend to License NPF-29, revising Tech Specs to reflect deferral of installation of automatic depressurization sys air receiver pressure indication in control room to second refueling outage. Fee paid.
KINGSLEY, O.D. Mississippi Power & Light Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33088:176-33088:182.

—8510220366 Proposed Tech Specs reflecting deferral of installation of automatic depressurization sys air receiver pressure indication in control room to second refueling outage.
* Mississippi Power & Light Co. 85/10/11. 1p. 33088:182-33088:182.

8510250576 Forwards Amend 5 to License NPF-29 & safety evaluation. Amend modifies Tech Specs to increase diesel fuel storage, clarify Spec 3/4.8.1, "Electrical Power Sys - ac Sources" & modify standby svc water sys license conditions.
ADENSAM, E.G. Licensing Branch 4. 85/10/12. RICHARD, J.B. Mississippi Power & Light Co. 3pp. 33226:292-33226:312.

—8510250581 Amend 5 to License NPF-29, modifying Tech Specs to increase diesel fuel storage & clarify Spec 3/4.8.1, "Electrical Power Sys - ac Sources" & modify standby svc water sys license conditions.
THOMPSON, H.L. Division of Licensing. 85/10/12. 13pp. 33226:296-33226:308.

—8510250584 Safety evaluation supporting Amend 5 to License NPF-29.
* Office of Nuclear Reactor Regulation, Director. 85/10/12. 4pp. 33226:309-33226:312.

8510210226 Forwards simplified diagram & brief description of ATWS design, per 10CFR50.62 requirements. Implementation planned prior to startup following second refueling outage.
DALE, L.F. Mississippi Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33074:094-33074:088.

8510180008 Notification of 851024 meeting w/util in Bethesda, MD to discuss design of Exxon fuel assemblies for first refueling.
KINTNER, L.L. Licensing Branch 4. 85/10/15. ADENSAM, E.G. Licensing Branch 4. 2pp. 33075:065-33075:066.

8510310509 Forwards Amend 6 to License NPF-29 & safety evaluation. Amend modifies Tech Specs re unit organization, primary containment penetration conductor overcurrent protective devices & fire detection instrumentation.
ADENSAM, E.G. Licensing Branch 4. 85/10/21. RICHARD, J.B. Mississippi Power & Light Co. 3pp. 33278:327-33278:351.

—8510310516 Amend 6 to License NPF-29, modifying Tech Specs re control rod scram accumulator, fire detection instrumentation, electrical power sys, diesel generator test schedule & primary containment penetration overcurrent devices.
ADENSAM, E.G. Licensing Branch 4. 85/10/21. 19pp. 33278:329-33278:347.

—8510310524 Safety evaluation supporting Amend 6 to License NPF-29.
* Office of Nuclear Reactor Regulation, Director. 85/10/21. 3pp. 33278:348-33278:351.

8510280158 Forwards addl info re ECCS performance analysis which supports increase in peak cladding temp of 51 F compared to current FSAR analysis, per request FSAR changes will be made if design change implemented.
DALE, L.F. Mississippi Power & Light Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 13pp. 33191:074-33191:086.

8510300103 Forwards SER re util 850805 & 0927 responses to Generic Ltr 83-28, Position 1.2 re post-trip review data & info capabilities. Capabilities acceptable.
NOVAK, T.M. Assistant Director for Licensing. 85/10/22. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 33262:220-33262:230.

—8510300120 SER supporting util post-trip review data & info capabilities, per Item 1.2 of Generic Ltr 83-28.
* NRC - No Detailed Affiliation Given. 85/10/22. 9pp. 33262:222-33262:230.

196 DOCKETED ITEMS

8510310005 Informs that 850624 proposed schedule for meeting rule on hydrogen control sys for Mark III containment unacceptable. Schedule inconsistent w/License Condition 2.C.(33)(d). Revised schedule or application for license amend requested. NOVAK,T.M. Assistant Director for Licensing. 85/10/22. RICHARD,J.B. Mississippi Power & Light Co. 3pp. 33277-109-33277:111.

8510290445 Forwards application for amend to License NPF-29, revising Tech Spec 6.3.1 for one-time exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. Fee paid. KINGSLEY,O.D. Mississippi Power & Light Co. 85/10/24. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33240:001-33240:014.

8510290449 Application for amend to License NPF-29, revising Tech Spec 6.3.1 for one-time exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. KINGSLEY,O.D. Mississippi Power & Light Co. 85/10/23. 7pp. 33240:003-33240:009.

8510290451 Proposed Tech Spec 6.3.1 for one-time exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. * Mississippi Power & Light Co. 85/10/23. 5pp. 33240:010-33240:014.

8510310331 Requests certification of pollution control facilities being financed by Claiborne County, MS pollution control revenue bonds in Nov 1985. Facilities financed by previous series of bonds certified in 1983 & 1984. KNOTTS,J.B. Bishop, Liberman, Cook, Purcell & Reynolds. KNOTTS,J.B. South Mississippi Electric Power Association. 85/10/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 28pp. 33273:036-33273:076.

8510310333 Forwards executed certificate for pollution control facilities described in Attachment 2 to 841102 request. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 84/11/13. KNOTTS,J.B. Bishop, Liberman, Cook, Purcell & Reynolds. KNOTTS,J.B. Middle South Utilities, Inc. - Middle South Energy, Inc. 8pp. 33273:043-33273:076.

Q. Inspection reports, IE Bulletins & correspondence

8510010057 Further response to FOIA request for documents re operator qualification cards. Forwards App A & portions of App B documents. Documents also available in PDR. Portions of App B documents withheld (ref FOIA Exemptions 5.6 & 7). FELTON,J.M. Division of Rules and Records. 85/09/23. REBER,P.C. Washington Document Service. 4pp. 32832:117-32832:351.

8510010071 Forwards Ofc of Inspector & Auditor rept of investigation entitled, "Congressman Markley Ltr of 840727 re Region II Actions re Grand Gulf Nuclear Station." Two issues concern training assessment/insp. Portions deleted. CONNELLY,S.R. Office of Inspector & Auditor. 84/10/19. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 3pp. 32832:123-32832:125.

8510010091 Discusses discrepancies in documentation of operator training identified in Jan 1983 special training assessment & safety insp conducted during Aug & Sept 1983. NRC requirements violated & enforcement action should be taken. DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 84/08/23. RICHARD,J.B. Mississippi Power & Light Co. 2pp. 32832:140-32832:141.

8510080532 Forwards insp Rept 50-416/85-33 on 850817-0916 & notice of violation. WALKER,R.D. Region 2, Office of Director. 85/09/27. RICHARD,J.B. Mississippi Power & Light Co. 2pp. 32927:159-32927:171.

8510080535 Notice of violation from insp on 850817-0916. * Region 2, Office of Director. 85/09/27. 2pp. 32927:161-32927:162.

8510080538 Insp Rept 50-416/85-33 on 850817-0916. Violations noted: failure to test containment air lock test connections, per 10CFR50, App J & exceeding 30-day reporting criteria, per 10CFR50.73. BUTCHER,R.C., CALDWELL,J.L., PANCIERA,V.W. Region 2, Office of Director. 85/09/26. 9pp. 32927:163-32927:171.

8510180035 Responds to violations noted in Insp Rept 50-416/85-24. Corrective actions: training given to shift health physics personnel & disciplinary action taken against supervisor & subordinate health physicists. DALE,L.F. Mississippi Power & Light Co. 85/09/27. GRACE,J.N. Region 2, Office of Director. 4pp. 33063:052-33063:055.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510070373 Responds to deviation & violation noted in Insp Rept 50-416/85-28. Corrective actions: Surveillance Procedure 06-OP-IC61-R-0002 issued on 850830 & operations section procedures re HPCS transfer reviewed. DALE,L.F. Mississippi Power & Light Co. 85/09/30. GRACE,J.N. Region 2, Office of Director. 4pp. 32876:265-32876:268.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33108:088.

8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged matl false statements made to NRC concerning operator qualifications & training. KAMMERER,R.C. Office of Congressional Affairs. 85/06/04. MARKEY,E.J. House of Representatives, Energy & Commerce. COCHRAN, STENNIS Senate. 3pp. 33109:044-33109:046.

8510301070 Forwards Press Release 85-48 re NRC proposed fine against util concerning five alleged matl false statements in development of Tech Specs governing facility operation. KAMMERER,R.C. Office of Congressional Affairs. 85/03/22. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:068-33109:070.

8510230175 Forwards proposed enforcement action against util for violations involving matl false statements re Tech Specs. KAMMERER,R.C. Office of Congressional Affairs. 85/03/22. SIMPSON,A. Senate, Environment & Public Works. UDALL,M.K. House of Rep. COCHRAN,T. Senate. 1p. 33109:071-33109:081.

8510180445 Ack receipt of 850927 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-416/85-24. Requirements of 10CFR2.201 met. WALKER,R.D. Region 2, Office of Director. 85/10/09. RICHARD,J.B. Mississippi Power & Light Co. 1p. 33068:055-33068:055.

8510180447 Ack receipt of 850930 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-416/85-28. WALKER,R.D. Region 2, Office of Director. 85/10/09. RICHARD,J.B. Mississippi Power & Light Co. 1p. 33068:252-33068:252.

8510180360 Concurs w/actions taken or underway re emergency preparedness, quality programs & administrative controls affecting quality & licensing in util 850803 response to SALP Repts 50-416/85-12 & 50-417/85-03. GRACE,J.N. Region 2, Office of Director. 85/10/10. RICHARD,J.B. Mississippi Power & Light Co. 5pp. 33059:266-33059:275.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510250059 Forwards safety evaluation re 850825, 0511.22 & 0920 relief requests from preservice insps required by ASME Code. Imposition of identified preservice insp requirements would result in hardship or unusual difficulties. Relief granted. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/10/16. RICHARD,J.B. Mississippi Power & Light Co. 2pp. 33224:344-33224:352.

8510250066 Safety evaluation re relief requests from preservice insp requirements ASME Code Section XI preservice exams impractical. Relief granted. * NRC - No Detailed Affiliation Given. 85/10/16. 7pp. 33224:346-33224:352.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510230053 Requests authorization to incorporate ASME Code Case N-335, "Rules for Ultrasonic Exam of Similar & Dissimilar Metal Piping Welds, Section XI, Div 1," into inservice insp program. Approval requested by 851115. Fee paid. DALE,L.F. Mississippi Power & Light Co. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33090:157-33090:158.

R. Periodic operating reports & related correspondence

8510180207 Monthly operating rept for Sept 1985 W/851011 ltr. CESARE,J.G., DALE,L.F. Mississippi Power & Light Co. 85/09/30. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 8pp. 33068:296-33068:305.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 or agreement. Forwards documents listed on app Documents also available in PDR. FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABEI,L. Government Accountability Project. 32pp. 32884:005-32884:234.

8510010402 Advises that listed Comsp, Inc., Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl. POTAPOV,S.U. Vendor Inspection Branch. 81/07/01. LEWIS,R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885:209-32885:217.

8510010420 Forwards 10CFR50.55(e)/Part 21 rept received from util re failure of contaminated gas monitor sys pump. Followup of generic aspects requested. MURPHY,C.E. Region 2, Office of Director. 80/05/01. Region 4, Office of Director. 21pp. 32885:218-32885:238.

8510020221 Forwards 10CFR50.55(e)/10CFR21 rept. Problem appears to be generic. Followup requested. Record of 810211 telcon encl. MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/02/13. Region 4, Dallas, Vendor Inspection Branch. 4pp. 32890:142-32890:145.

8510010057 Further response to FOIA request for documents re operator qualification cards. Forwards App A & portions of App B documents. Documents also available in PDR. Portions of App B documents withheld (ref FOIA Exemptions 5.6 & 7). FELTON,J.M. Division of Rules and Records. 85/09/23. REBER,P.C. Washington Document Service. 4pp. 32832:117-32832:351.

8510010078 Notice of significant licensee meeting on 830923 w/util in Atlanta, GA to discuss Agastat relay failures & other topics of current interest. * Region 2, Office of Director. 83/09/21. Region 2, Office of Director. 1p. 32832:165-32832:165.

8510020018 LER 85-032-00 on 850829 discovered that on 841201 & 04, liquid effluent flow rate estimates exceeded 4 h frequency of Tech Specs requirements. Caused by late flow rate measurements. Procedural controls revised. W/850926 ltr. BYRD,R., DALE,L.F. Mississippi Power & Light Co. 85/09/26. 4pp. 32827:065-32827:068.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510080316 LER 85-03-00 on 850830, discovered standby svc water sys not under plant operational control. Caused by piping not being included in release package. Programmatic controls for addressing concerns under evaluation. W/850930 ltr. DAUGHTERY, L.F., DALE, L.F. Mississippi Power & Light Co. 85/09/30. 4pp. 32928-067-32928-070.

8510090029 Forwards response to NRC 850723 request for addl info re TDI emergency diesel generators, including info concerning TDI 10CFR21 repts, svc info memos, preventive maint program & training & trending program. DALE, L.F. Mississippi Power & Light Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 400pp. 32935-342-32936-212.

8510090361 Forwards LER 85-007-02, revising rept submitted by 850823 ltr. GE dual solenoid valve number corrected. DALE, L.F. Mississippi Power & Light Co. 85/10/02. Record Services Branch (Document Control Desk). 2pp. 32948-107-32948-116.

-8510090366 LER 85-007-02 on 850210, turbine tripped causing reactor scram & MSIV failure when condenser vacuum decreased during transfer of steam jet air ejectors. Caused by excessive valve cycling on low steam flow due to undersize piping. SHINGLETON, E.B. Mississippi Power & Light Co. 85/10/02. 8pp. 32946-109-32946-116.

8510090292 LER 85-034-00 on 850819, test canister in standby gas treatment filter Train B found to contain no charcoal. On 850906, test showed efficiency below Tech Spec requirement. Canister location in unit blanked off. W/851004 ltr. BYRD, R.W., DALE, L.F. Mississippi Power & Light Co. 85/10/04. 4pp. 32947-091-32947-094.

8510220122 LER 85-035-00 on 850911, four motor-operated valves & two drain line check valves of MSIV leakage control sys not tested per Tech Specs 4.6.1.4.6 & 4.0.5. Caused by delay in issuing/administering procedure. W/851011 ltr. BYRD, R.W., DALE, L.F. Mississippi Power & Light Co. 85/10/11. 4pp. 33095-101-33095-104.

8510240339 LER 85-036-00 on 850916, reactor scram occurred due to turbine trip on low condenser vacuum. Caused by pump trips on low tube water flow. Water level restored. Scram off-normal event procedure initiated. W/851015 ltr. BYRD, R.W., DALE, L.F. Mississippi Power & Light Co. 85/10/15. 4pp. 33160-186-33160-189.

8510290301 LER 85-037-00 on 850620, smoke detector in control bldg HVAC chase failed to announce on control room console during routine testing. Caused by erroneous zone description entry onto data base. Controls re data mod underway. W/851021 ltr. BYRD, R.W., DALE, L.F. Mississippi Power & Light Co. 85/10/21. 4pp. 33244-164-33244-167.

8510300308 LER 85-038-00 on 850925, standby gas treatment sys A & control room fresh air unit A actuated due to failed transformer powered by inverter. Cause undetermined. Corrective action incomplete. W/851022 ltr. BYRD, R.W., DALE, L.F. Mississippi Power & Light Co. 85/10/22. 3pp. 33257-356-33257-358.

U. Congressional/Executive Correspondence

8510010057 Further response to FOIA request for documents re operator qualification cards. Forwards App A & portions of App B documents. Documents also available in PDR. Portions of App B documents withheld (ref FOIA Exemptions 5.6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/23. REBER, P.C. Washington Document Service. 4pp. 32832-117-32832-351.

-8510010099 Comments on Ofc of Investigation 840305 rept "Grand Gulf Nuclear Power Plant: Possible Deliberate & Willful False Applications." Unnecessary & inappropriate that NRC shared info w/ licensee. MARKEY, E.J. House of Rep. 84/07/27. PALLADINO, N.J. Commissioners. 3pp. 32832-142-32832-144.

8510090099 Further response to FOIA request for NRC ltrs to E. Markey re facility. Forwards App B Documents 1-5. Documents also available in PDR. App C Documents 1-7 & 8-14 withheld (ref FOIA Exemptions 7 & 5, respectively). FELTON, J.M. Division of Rules and Records. 85/09/26. CUNNINGHAM, L. Times-Picayune, La Place. 4pp. 32963-296-32963-304.

-8510090108 Forwards Ofc of Investigation rept re possible falsification of operator qualifications. per 840313 request. Matter referred to DOJ for evaluation of prosecutorial merit. W/o encl. PLAINE, H.H. Office of the General Counsel. 84/06/08. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-301-32963-301.

-8510090114 Forwards SECY-84-209, per 840611 request. Paper not yet acted on by Commission. Document should be restricted to subcommittee W/o encl. DIRCKS, W.J. Office of the Executive Director for Operations. 84/06/15. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-302-32963-302.

-8510090118 Forwards Ofc of Investigation rept re possible falsification of mechanical maint training records at facility. Matter referred to DOJ for evaluation. Rept should be held in confidence. W/o encl. PLAINE, H.H. Office of the General Counsel. 84/07/23. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-303-32963-303.

-8510090124 Forwards transcript of NRC 840731 closed meeting re facility. Matters referred to DOJ for evaluation of prosecutive merit. Documents should be held in confidence. W/o encl. PALLADINO, N.J. Commissioners. 84/08/24. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-304-32963-304.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged false statements made to NRC concerning operator qualifications & training. KAMMERER, C. Office of Congressional Affairs. 85/06/04. MARKEY, E.J. House of Rep., Energy & Commerce. UDALL House of Rep. SIMPSON Senate. 3pp. 33109-044-33109-046.

-8510230170 Forwards Press Release 85-48 re NRC proposed fine against util concerning five alleged false statements in development of Tech Specs governing facility operation. KAMMERER, C. Office of Congressional Affairs. 85/03/22. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-068-33109-070.

-8510230175 Forwards proposed enforcement action against util for violations involving false statements re Tech Specs. KAMMERER, C. Office of Congressional Affairs. 85/03/22. SIMPSON, A. Senate, Environment & Public Works. UDALL, M.K. House of Rep. COCHRAN, T. Senate. 1p. 33109-071-33109-081.

-8510230253 Responds to request for all errors committed by util in application for license. Partial list of false statements should be available. COMBS, F. Office of Congressional Affairs. 84/09/25. MYERS, J. House of Rep., Interior & Insular Affairs. 1p. 33109-109-33109-109.

V. Operator Examinations

8510010057 Further response to FOIA request for documents re operator qualification cards. Forwards App A & portions of App B documents. Documents also available in PDR. Portions of App B documents withheld (ref FOIA Exemptions 5.6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/23. REBER, P.C. Washington Document Service. 4pp. 32832-117-32832-351.

-8510010071 Forwards Ofc of Inspector & Auditor rept of investigation entitled, "Congressman Markey Ltr of 840727 re Region II Actions re Grand Gulf Nuclear Station." Two issues concern training assessment/insp Portions deleted. CONNELLY, S.R. Office of Inspector & Auditor. 84/10/19. PALLADINO, ROBERTS, ASSELTINE Commissioners. 3pp. 32832-123-32832-125.

-8510010084 Rept of investigation entitled, "Congressman Markey Ltr dtd 840727 re Region II Actions re Grand Gulf Nuclear Station." Portions deleted. RESNER, M.E., BOWERS, H., CONNELLY, S.R. Office of Inspector & Auditor. 84/10/19. 14pp. 32832-126-32832-139.

-8510010091 Discusses discrepancies in documentation of operator training identified in Jan 1983 special training assessment & safety insp conducted during Aug & Sept 1983. NRC requirements violated & enforcement action should be taken. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 84/08/23. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 32832-140-32832-141.

-8510010096 Rept of interview w/JP O'Reilly re discrepancies in reactor operator training program at plant, per restart of facility on 830925 & 830923 meeting w/util at Region II. NRC response to Markey questions encl. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/10/11. 17pp. 32832-166-32832-182.

-8510010107 Rept of interview w/JM Puckett re discrepancies in licensed operator training program at facility, per Region II enforcement actions. Reactor operators not trained per FSAR commitments. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/18. 3pp. 32832-183-32832-185.

-8510010109 Rept of interview w/JP McGaughy re 830923 meeting at Region II concerning discrepancies in operator qualification cards at facility. Draft util ltr re discrepancies encl. Portions of rept deleted. RESNER, M.E. Office of Inspector & Auditor. 84/08/19. 6pp. 32832-145-32832-150.

-8510010116 Rept of interview w/Region II employee re discrepancies in reactor operator & senior reactor operator licensing program at facility. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/19. 1p. 32832-186-32832-186.

-8510010119 Rept of interview w/util employee re 830923 meeting w/util at Region II concerning discrepancies in operator qualification cards at facility. Interviewee name withheld. RESNER, M.E. Office of Inspector & Auditor. 84/08/21. 1p. 32832-151-32832-151.

-8510010125 Rept of interview w/DM Verrilli re events & circumstances of 830923 meeting w/util at Region II & language used in 831205 confirmation of action ltr to util. RESNER, M.E. Office of Inspector & Auditor. 84/09/24. 1p. 32832-152-32832-154.

-8510010130 Rept of interview w/Region II employee re reactor operator & senior reactor operator license applications & operator training deficiencies at facility. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/21. 3pp. 32832-187-32832-189.

-8510010138 Rept of interview w/DH Bekham re discrepancies in reactor operator training program at facility, per impact on facility operation. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/25. 2pp. 32832-190-32832-191.

-8510010151 "Corrective Action Plans for Operator Training Program." Related info encl. Portions deleted. Mississippi Power & Light Co. 83/11/30. 97pp. 32832-192-32832-291.

-8510010152 Rept of interview w/Ofc of Investigation, Atlanta Field Ofc employee re impact Region II 830923 meeting w/util had on Ofc of Investigation Case 2-83-037. Interviewee name withheld. RESNER, M.E. Office of Inspector & Auditor. 84/09/17. 2pp. 32832-155-32832-156.

198 DOCKETED ITEMS

- 8510010168 Rept of interview w/AF Gibson re deficiencies in reactor operator training program at facility & 830923 meeting w/util at Region II concerning util refusal to submit ltr to NRC. Portions deleted.
RESNER, M.E. Office of Inspector & Auditor. 84/09/25. 2pp. 32832:157-32832:158.
- 8510010170 Provides addl info re discrepancies discovered in operator & senior operator license applications & corrective actions, per 830930 ltr. Discrepancies identified between license applications & training records occurred prior to 1982.
MCGAUGHY, J. Mississippi Power & Light Co. 83/11/01. O'REILLY, J.P. Region 2, Office of Director. 20pp. 32832:292-32832:351.
- 8510010176 Rept of interview w/Region II employee re 830923 meeting w/util at Region II & discrepancies in reactor operator & senior reactor operator training at facility. Portions deleted.
RESNER, M.E. Office of Inspector & Auditor. 84/08/18. 6pp. 32832:159-32832:164.
- 8510020302 Application for amend to License NPF-29, supplementing 850812.23 & 30 submittals, to provide justification for exemption from Tech Spec 6.3.1 & 6.4.1 requirements for senior reactor operator qualifications.
KINGSLEY, O.D. Mississippi Power & Light Co. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32825:189-32825:204.
- 8510020304 Proposed changes to Tech Specs 6.3.1 & 6.4.1, providing justification for exemption from requirements for senior reactor operator qualifications.
* Mississippi Power & Light Co. 85/09/25. 11pp. 32825:194-32825:204.
- 8510030437 Requests encl listed ref matl necessary for administration of operator exams scheduled for wk of 851216 by 851025. All operator & senior license applications should be submitted 60 days prior to first scheduled exam date.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. RICHARD, J.B. Mississippi Power & Light Co. 5pp. 32846:006-32846:010.
- 8510090099 Further response to FOIA request for NRC ltrs to E Markey re facility. Forwards App B Documents 1-5. Documents also available in PDR. App C Documents 1-7 & 8-14 withheld (ref FOIA Exemptions 7 & 5, respectively).
FELTON, J.M. Division of Rules and Records. 85/09/25. CUNNINGHAM, L. Times-Picayune, La Place, LA. 4pp. 32963:296-32963:304.
- 8510090108 Forwards Ofc of Investigation rept re possible falsification of operator qualifications, per 840313 request. Matter referred to DOJ for evaluation of prosecutorial merit. W/o encl.
PLAINE, H.H. Office of the General Counsel. 84/06/08. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963:301-32963:301.
- 8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.
- 8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged matl false statements made to NRC concerning operator qualifications & training.
KAMMERER, C. Office of Congressional Affairs. 85/06/04. MARKEY, E.J. House of Rep., Energy & Commerce. COX/WDY House of Rep. 3pp. 33109:044-33109:046.

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 851070316 Forwards response to NRC questions raised in 850815 telcon re Generic Ltr 83-28, Item 1.2. Balance-of-plant Points N30N026A,B & C added to balance-of-plant computer post-trip log will provide actual turbine bypass valve position info.
DALE, L.F. Mississippi Power & Light Co. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32880:338-32880:342.
- 8510070452 Forwards response to Item 3.2 of Generic Ltr 83-28 re post-maint testing of safety-related components. Response for Item 4.5.3 will be provided within 90 days of NRC issuance of evaluation of BWR Owners Group rept.
DALE, L.F. Mississippi Power & Light Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32878:341-32878:344.
- 8510150021 Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues.
BLACK, S. Division of Licensing. 85/10/02. THOMPSON, H.L. Division of Licensing. 16pp. 33031:135-33031:150.
- 8510150103 Forwards "Weir Wall Overflow Probability Analysis." Because of very low probability of occurrence & leak of safety significance for worst case postulated overflow (ref AECM-85/0046), corrective actions not warranted.
DALE, L.F. Mississippi Power & Light Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33010:342-33010:346.
- 8510180363 Extends thanks for cooperation during 850911-13 data gathering trip. Brief visit in Jan 1988 may be required to confirm plant design features & procedures most important to severe core damage potential.
ERIN, M.L. Division of Risk Analysis & Operations (post 840429). 85/10/07. KINGSLEY, O.D. Mississippi Power & Light Co. 2pp. 33034:291-33034:292.
- 8510180061 Summarizes status of Hydrogen Control Owners Group program plan tasks. Task 1 re station black-out & ATWS complete. Task 6 re hydrogen combustion testing still in progress, awaiting completion of Subtask 6.26.
DALE, L.F. Mississippi Power & Light Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027:200-33027:201.
- 8510210228 Forwards simplified diagram & brief description of ATWS design, per 10CFR50.62 requirements. Implementation planned prior to startup following second refueling outage.
DALE, L.F. Mississippi Power & Light Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33074:084-33074:088.

8510300103 Forwards SER re util 850805 & 0927 responses to Generic Ltr 83-28, Position 1.2 re post-trip review data & info capabilities. Capabilities acceptable.
NOVAK, T.M. Assistant Director for Licensing. 85/10/22. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 33262:220-33262:230.

-8510300120 SER supporting util post-trip review data & info capabilities, per Item 1.2 of Generic Ltr 83-28.
* NRC - No Detailed Affiliation Given. 85/10/22. 9pp. 33262:222-33262:230.

8510300073 Ack receipt of encl 850920 ltr re State of MS PSC 850918 order directing suspension of const. Response to NRC 850822 request for addl info re util 840815 request for extension of CP should be deferred.
NOVAK, T.M. Assistant Director for Licensing. 85/10/24. CAVANAUGH, W. Mississippi Power & Light Co. 4pp. 33262:256-33262:261.

-8510300082 Discusses State of MS PSC 850918 order directing suspension of const. Util will review available alternatives & decide future of plant const during next few months.
CAVANAUGH, W. Mississippi Power & Light Co. 85/09/20. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 33262:260-33262:261.

F. Security, medical, emergency & fire protection plans

- 8510010462 Revised emergency plan procedures, including Rev 9 to 10-S-01-1 re activation of emergency plan & Rev 10 to 10-S-01-6 re notification of offsite agencies & plant on-call emergency personnel. W/850920 ltr.
HURLEY, J. CROSS, J.C., DALE, L.F. Mississippi Power & Light Co. 85/09/20. GRACE, N. Region 2, Office of Director. 51pp. 32804:026-32804:078.
 - 8510230014 Advises that State of LA & local plans & preparedness for facility adequate to protect health & safety of public. Approval conditional on verification of alerting & notification sys, per NUREG-0654/Rev 1 to FEMA REP-1, App 3.
SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33101:347-33101:347.
 - 8510180360 Concurs w/actions taken or underway re emergency preparedness, quality programs & administrative controls affecting quality & licensing in util 850803 response to SALP Repts 50-416/85-12 & 50-417/85-03.
GRACE, J.N. Region 2, Office of Director. 85/10/10. RICHARD, J.B. Mississippi Power & Light Co. 5pp. 33059:266-33059:275.
 - 8510250264 Forwards SER re allowable control room inleakage to meet control room habitability requirements. Reduction in allowable inleakage rate recommended during simultaneous operation of Units 1 & 2.
NOVAK, T.M. Assistant Director for Licensing. 85/10/16. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 33226:167-33226:171.
 - 8510250274 SER re allowable control room inleakage to meet habitability requirements. Reduction in allowable control room inleakage for completed control room to 590 cfm recommended.
* NRC - No Detailed Affiliation Given. 85/10/16. 3pp. 33226:169-33226:171.
 - 8510290038 Revised corporate emergency plan procedures, including Rev 1 to Procedure 4.1, "Organization & Position Description" & Rev 1 to Procedure 4.3, "Initial Notification & Mobilization." W/851021 ltr.
DALE, L.F. Mississippi Power & Light Co. 85/10/21. GRACE, N. Region 2, Office of Director. 200pp. 33229:001-33229:317.
- #### G. Inspection reports, IE Bulletins & correspondence
- 8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.
 - 8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
 - 8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
 - 8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged matl false statements made to NRC concerning operator qualifications & training.
KAMMERER, C. Office of Congressional Affairs. 85/06/04. MARKEY, E.J. House of Rep., Energy & Commerce. COCHRAN, STENNIS Senate. 3pp. 33109:044-33109:046.
 - 8510180360 Concurs w/actions taken or underway re emergency preparedness, quality programs & administrative controls affecting quality & licensing in util 850803 response to SALP Repts 50-416/85-12 & 50-417/85-03.
GRACE, J.N. Region 2, Office of Director. 85/10/10. RICHARD, J.B. Mississippi Power & Light Co. 5pp. 33059:266-33059:275.
 - 8510180379 Forwards Insp Rept 50-417/85-07 on 850916-20. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/10/11. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 33062:251-33062:257.
 - 8510180383 Insp Rept 50-417/85-07 on 850916-20. No violation or deviation noted. Major areas inspected: electrical components & sys work, work activities & quality records.
GIBBONS, T.D., CONLON, T.E. Region 2, Office of Director. 85/10/08. 5pp. 33062:253-33062:257.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

S. Reportable occurrences, LERs & related correspondence

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L. Government Accountability Project. 32pp. 32884-005-32884-234.

-8510010402 Advises that listed Compis, Inc. Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl. POTAPOV, S.I. Vendor Inspection Branch. 81/07/01. LEWIS, R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885-209-32885-217.

-8510010420 Forwards 10CFR50.55(e)/Part 21 rept received from util re failure of contaminated gas monitor sys pump. Followup of generic aspects requested. MURPHY, C.E. Region 2, Office of Director. 80/05/01. Region 4, Office of Director. 21pp. 32885-218-32885-238.

-8510020221 Forwards 10CFR50.55(e)/10CFR21 rept. Problem appears to be generic. Followup requested. Record of 810211 telcon encl. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/02/13. Region 4, Dallas, Vendor Inspection Branch. 4pp. 32890-142-32890-145.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BEFLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510051029 Forwards response to NRC 850723 request for addl info re TDI emergency diesel generators, including info concerning TDI 10CFR21 repts, svc info memos, preventive maint program & training & trending program. DALE, L.F. Mississippi Power & Light Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 400pp. 32935-342-32936-212.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged mal false statements made to NRC concerning operator qualifications & training. KAMMERER, C. Office of Congressional Affairs. 85/06/04. MARKEY, E.J. House of Rep., Energy & Commerce. UDALL, House of Rep. SIMPSON, Senate. 3pp. 33109-044-33109-046.

-8510230253 Responds to request for all errors committed by util in application for license. Partial list of false mal statements should be available. COMBS, F. Office of Congressional Affairs. 84/09/25. MYERS, H. House of Rep., Interior & Insular Affairs. 1p. 33109-109-33109-109.

V. Operator Examinations

8510030437 Requests encl listed ref matl necessary for administration of operator exams scheduled for wk of 851216 by 851025. All operator & senior license applications should be submitted 60 days prior to first scheduled exam date. BROWNLEE, V.L. Region 2, Office of Director. 85/09/25. RICHARD, J.B. Mississippi Power & Light Co. 5pp. 32846-006-32846-010.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged mal false statements made to NRC concerning operator qualifications & training. KAMMERER, C. Office of Congressional Affairs. 85/06/04. MARKEY, E.J. House of Rep., Energy & Commerce. DOWDY, House of Rep. 3pp. 33109-044-33109-046.

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

8510110022 Forwards addl responses to questions raised re proof & review Tech Specs. Marked-up Tech Specs encl. OPEKA, J.F. MROCKZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/20. YOUNGBLOOD, B.J. Licensing Branch 1. 34pp. 32973-233-32973-266.

8510100180 Forwards addl responses to NRC questions re proof & review Tech Specs. OPEKA, J.F., FEE, W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/23. YOUNGBLOOD, B.J. Licensing Branch 1. 52pp. 32962-142-32962-193.

8510110092 Forwards util responses to questions raised re proof & review Tech Specs. Pressurizer heatup & cooldown rates will not exceed 100 F/h & 200 F/h, respectively & Valve 3CHS-V305 will be verified closed & secured. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 30pp. 32972-001-32972-029.

8510040304 Forwards response to NRC concerns re proof & review Tech Specs. Two independent control room envelope pressurization sys ensure that breathable air supplied to control room, instrument rack & computer rooms. OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SEARS, C.F. Northeast Utilities. 85/09/25. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32854-222-32854-226.

8510030372 Advises that util failure to submit info requested by NRC re Tech Specs by 850925 will delay issuance of final draft Tech Specs. Addl delay in submitting info could result in delay of Tech Specs needed for issuance of OL. YOUNGBLOOD, B.J. Licensing Branch 1. 85/09/26. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 32848-070-32848-072.

8510070238 Forwards addl responses to NRC request for info re draft proof & review Tech Specs. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 32877-357-32877-362.

8510070444 Requests exemption from requirements of 10CFR50, App J, Section D.2.b.i Proposed Surveillance Procedure 4.6.1.3 a worded to require air door seal leak checks within 3 days of every period of air lock use. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32878-339-32878-340.

8510070264 Forwards schedule of key remaining activities for fuel loading, initial criticality & power ascension Nov 1985 fuel load on schedule. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/27. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32877-323-32877-327.

8510110226 Forwards "Seismic Interaction Review Program..." & "Application of Data to Seismic Interaction..." in response to NRC 850917 ltr. List of non-Seismic Category I equipment installed in Seismic Category I areas also encl. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/27. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 32970-058-32970-197.

-8510110227 "Seismic Interaction Review Program, Millstone 3 Nuclear Power Station." * Stone & Webster Engineering Corp. 85/09/30. 27pp. 32970-064-32970-090.

-8510110230 "Application of Experience Data to Seismic Interaction at Millstone 3 Nuclear Power Plant." * EQE, Inc. 85/01/31. 107pp. 32970-091-32970-197.

8510020257 REVIEW AND EVALUATION OF THE MILLSTONE UNIT 3 PROBABILISTIC SAFETY STUDY. Containment Failure Modes, Radiological Source-Terms And Off-site Consequences. KHATIB, RAHBAH, PRATT, W., LUDEWIG, H. Brookhaven National Laboratory. FIN A-3748. NUREG/CR-4143. 85/09/30. Division of Systems Integration (post 811005). 75pp. 32829-198-32829-272.

8510070205 Forwards addl response to Tech Spec item re justification for min secondary side steam generator water level of 10%, per NRC request for comments on proof & review draft Tech Specs. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32878-093-32878-095.

8510180245 Forwards response to NRC Question 260.59 re compliance w/ Rev 1 to Reg Guide 1.123 Revised Section 1.8 will be included in future amend to FSAR. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 33061-084-33061-088.

8510080265 Forwards Rev 1 to NUSCO-137, "Millstone Unit 3 Boron Dilution Analysis for Failures in Chemical & Vol Control Sys." Rev documents compliance w/min operator action times for boron dilution events w/o new data. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32919-350-32919-351.

-8510080270 Rev 1 to "Millstone Unit 3 Boron Dilution Analysis for Failures in Chemical & Vol Control Sys." * Northeast Nuclear Energy Co. (subs. of Northeast Utilities). NUSCO-137 R01. 85/10/01. 5pp. 32919-352-32919-356.

200 DOCKETED ITEMS

- 8510090069** Forwards util responses to NRC & EG&G Idaho comments at 850815 exit interview re 850812-16 audit of 10 files containing environ qualification info for equipment located in potentially harsh environs.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/01. YOUNGBLOOD,B.J. Licensing Branch 1. 7pp. 32941-337-32941-343.
- 8510110009** Forwards "PWR Safety Relief & Block Valve Adequacy Rept." per NUREG-0737, Item II.D.1. Response providing analysis of effect of as-built relief & safety valve discharge piping on valve operability also encl.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/01. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 32969-204-32969-246.
- 8510110014** Rev 1 to "PWR Safety Relief & Block Valve Adequacy Rept."
GRAYSON,R.M., SEPP,H.A. Westinghouse Electric Corp. 85/08/31. 40pp. 32969-207-32969-246.
- 8510110078** Forwards Rev 0 to ISI-3.0, "Millstone Point Unit 3 Inservice Testing Program for Pumps & Valves." Requests prompt review & approval in order to support fuel load schedule of Nov 1985.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/01. YOUNGBLOOD,B.J. Licensing Branch 1. 2pp. 32969-247-32970-057.
- 8510110080** Rev 0 to ISI-3.0, "Millstone Point Unit 3 Inservice Testing Program for Pumps & Valves."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/23. 200pp. 32969-249-32970-057.
- 8510150065** Forwards addl info re proof & review Tech Specs, in response to listed requests Tech Specs include Items 3/4.6.1.7 re containment ventilation sys & 3/4.3.2 re ESFAS instrumentation.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/04. YOUNGBLOOD,B.J. Licensing Branch 1. 21pp. 33010-195-33010-215.
- 8510150305** Forwards response to NRC 850910 request for addl info re containment isolation provisions.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/04. YOUNGBLOOD,B.J. Licensing Branch 1. 4pp. 33009-090-33009-093.
- 8510150351** Forwards addl info re draft proof & review Tech Specs, per NRC request Deletion of Surveillance 4.6.2.3.d re spray additive sys flow verification requested Tables 3.3-7 & 4.3-4 re seismic instrumentation consistent as issued.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/04. YOUNGBLOOD,B.J. Licensing Branch 1. 7pp. 33000-333-33000-339.
- 8510110189** Forwards "Engineering Assurance Corrective Action Status Rept, Millstone Unit 3 Project." Rept provides status of followup action re audit observations contained in 850816 engineering assurance technical audit rept.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. MILHOAN,J. Quality Assurance Branch. 2pp. 32968-128-32968-190.
- 8510110192** "Engineering Assurance Corrective Action Status Rept, Millstone Unit 3 Project."
MALONE,D.L., EIFERT,W.M. Stone & Webster Engineering Corp. EA-768. 85/09/30. 80pp. 32968-130-32968-190.
- 8510150327** Forwards responses to questions re draft Tech Specs, info provided re justification for min secondary side steam generator water level of 10% in Specs 3/4.4.1.2, 3/4.4.1.3 & 3/4.4.1.4.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33012-357-33012-359.
- 8510160019** Discusses schedule for compliance w/requirements of 10CFR50.62 re ATWS. Compliance can be achieved by end of first refueling outage, assuming staff concurrence w/Westinghouse Owners Group generic design by early 1986.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33024-099-33024-101.
- 8510170068** Forwards revised Tech Spec listing of overcurrent protective devices, per 850923 original list which repeated several device numbers. Repetition due to more than one penetration associated w/some devices.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. YOUNGBLOOD,B.J. Licensing Branch 1. 30pp. 33036-350-33037-017.
- 8510180353** Forwards description of changes to S&W QA program manual & Revs E & D to QA program for facility.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. MURLEY,T.E. Region 1, Office of Director. 14pp. 33059-245-33059-265.
- 8510180355** Rev E to QA program for facility.
KELLY,R.B., GRIFFITH,W.L. Stone & Webster Engineering Corp. 84/12/20. 4pp. 33059-259-33059-262.
- 8510180356** Rev D to QA program for facility.
KELLY,R.B. Stone & Webster Engineering Corp. 85/03/19. 3pp. 33059-263-33059-265.
- 8510240256** Forwards "Environ Qualification of Mechanical Equipment, Supplemental Rept." Rept updated to include conformance review sheets & subcompartment data sheets for remaining safety-related mechanical equipment.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. YOUNGBLOOD,B.J. Licensing Branch 1. 2pp. 33152-001-33153-046.
- 8510240262** "Environ Qualification of Mechanical Equipment, Supplemental Rept."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/30. 40pp. 33152-003-33153-046.
- 8510150009** Notification of 851009 meeting w/util in Bethesda, MD to discuss seismic interaction program.
DOOLITTLE,E.L. Licensing Branch 1. 85/10/08. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33031-178-33031-180.
- 8510150018** Summary of 8/1002 meeting w/util & Bishop, Liberman, Cook, Purcell & Reynolds re activities to be completed prior to issuance of low power license, including operating experience, fire protection & Tech Specs.
DOOLITTLE,E.L. Licensing Branch 1. 85/10/08. Licensing Branch 1. 7pp. 33031-151-33031-157.
- 8510170286** Forwards responses to SQRT audit questions during wk of 850304-08.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/08. YOUNGBLOOD,B.J. Licensing Branch 1. 18pp. 33040-046-33040-063.
- 8510290220** Forwards Administrative Control Procedure ACP 6.15, "Post-Trip & Transient Review," implementing util Nuclear Engineering & Operations Procedure NEO 8.02 w/same title, per 850910 request.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/08. YOUNGBLOOD,B.J. Licensing Branch 1. 5pp. 33239-057-33239-069.
- 8510290234** Rev 0 to Administrative Control Procedure ACP 6.15, consisting of Nuclear Engineering & Operations Procedure NEO 8.02, "Post-Trip & Transient Review."
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/06/21. 8pp. 33239-062-33239-069.
- 8510220065** Forwards addl responses to question raised re proof & review Tech Specs, Reactor coolant pump running in isolated loop inadequate method to control heatup of loop. Proposed spec & respective bases encl.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/09. YOUNGBLOOD,B.J. Licensing Branch 1. 6pp. 33081-303-33081-308.
- 8510220145** Forwards response to NRC concern re use of 90 F containment air temp for aging purpose. Heat releases from vessels, piping & equipment calculated at max operating temps using appropriate heat transfer relationships.
OPEKA,J.F. FEE,W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/10. YOUNGBLOOD,B.J. Licensing Branch 1. 9pp. 33082-101-33082-109.
- 8510220244** Responds to NRC 850910 request for addl info per Pump & Valve Operability Review Team 850304-08 audit. Svc water pumps provide adequate flow to sys w/10% margin & acceptable existing rundown times also acceptable.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/10. YOUNGBLOOD,B.J. Licensing Branch 1. 5pp. 33086-291-33086-295.
- 8510220021** Requests scheduler exemption from requirements of 10CFR50, App A, GDC 2 re seismic interaction, until issuance of full power OL. Exemption requested to allow further staff review of seismic interaction program.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/15. YOUNGBLOOD,B.J. Licensing Branch 1. 2pp. 33090-323-33090-324.
- 8510310205** Forwards "Quantitative Piping Experience Data Supporting Results of Millstone III Seismic Interaction Study," in response to request for addl info re use of historical earthquake data in evaluation of non-seismic piping sys.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/15. YOUNGBLOOD,B.J. Licensing Branch 1. 4pp. 33266-088-33266-179.
- 8510310208** "Quantitative Piping Experience Data Supporting Results of Millstone III Nuclear Power Plant Interaction Study."
* EQE, Inc. 85/10/31. 89pp. 33266-092-33266-179.
- 8510180135** Requests addl info re qualification program for safety-related mechanical equipment, including plug valves & hydraulic snubbers to continue review of application for license.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/16. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33069-272-33069-274.
- 8510220150** Discusses plans for meeting hot participation experience & shift technical advisor requirements for plant startup & operation.
OPEKA,J.F. SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/16. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33082-247-33082-249.
- 8510240062** Forwards draft NUREG-1152, "Millstone 3 Risk Evaluation Rept." Rept documents results of review of probabilistic safety study. Four improvements identified which could result in addl protection of public health & safety.
NOVAK,T.M. Assistant Director for Licensing. 85/10/17. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 200pp. 33163-160-33164-042.
- 8510250004** Forwards final draft Tech Specs for comment. Confirmation that revised draft accurately reflects plant FSAR & SER analyses requested.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/18. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33226-262-33226-263.
- 8510230034** Application for OL. Activities required for issuance of OL will be completed at time of scheduled fuel loading on 851115.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/21. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33101-356-33101-356.
- 8510290386** Notification of 851024 meeting w/util in Bethesda, MD to discuss Seismic Interaction Program.
DOOLITTLE,E.L. Licensing Branch 1. 85/10/24. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33254-268-33254-270.
- 8510310214** Forwards "Reactor Containment Bldg Integrated Leakage Rate Test, Types A,B & C." Potential changes in bypass leakage paths resulting from continuing design review identified.
OPEKA,J.F. SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/24. YOUNGBLOOD,B.J. Licensing Branch 1. 2pp. 33270-139-33270-185.

8510310219 "Reactor Containment Bldg Integrated Leakage Rate Test, Types A,B & C."

* Stone & Webster Engineering Corp. 85/07/31. 52pp. 33270:141-33270:185.

8510310048 Forwards requests for addl info re shift advisors training program & N-1 top operation, required to complete evaluation of OL application. Schedule for providing responses requested by 851101.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/25. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33277:171-33277:174.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510040433 Responds to Matis Engineering Branch SER Confirmatory Item 28 re 10CFR50, App A, GDC 51 requirements. Calculations for feedwater sys components indicate GDC 51 met.
OPEKA, J.F., FEE, W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/23. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32854:216-32854:217.

8510070059 Forwards results of revised instrument uncertainty analysis in response to Question 492.7 re RCS flow measurement capability, per 850910 telcon. SER Open Item 8 considered closed.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 9pp. 32878:025-32878:033.

8510070300 Confirms that portions of CRD mechanism do not contain any cold-worked austenitic stainless steel, including portions which are part of RCPB. Requirements of 10CFR50, App A, Criterion 26 met, per SER Confirmatory Item 16.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32877:300-32877:301.

8510040414 Forwards SSER 2 (NUREG-1031) W/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/09/27. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 32860:034-32860:036.

8510010227 SAFETY EVALUATION RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION, UNIT 3. Docket No 50-423 (Northeast Nuclear Energy Company).
* Division of Licensing. NUREG-1031 S02. 85/09/30. 100pp. 32836:195-32836:285.

8510070319 Forwards response to SER Confirmatory Item 26 re administrative control over doors in secondary containment. Encl info should resolve concerns identified in NRC 840802 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32880:298-32880:301.

8510080040 Informs that preservice insp of all piping welds in break exclusion area completed & documented as acceptable, per SER Confirmatory Item 7. Results of insps will be used in program to meet ASME Section XI requirements.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32918:298-32918:299.

8510080145 Forwards response to SER Confirmatory Item 66 re implementation of program to address item III.D.1.1 concerning integrity of sys outside containment likely to contain radioactive matl. Info should resolve item 66.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32913:200-32913:204.

8510080468 Forwards revised response to SER (NUREG-1031) Question 480.37 re asymmetric pressure loadings on structures & components due to postulated pipe ruptures, including results of evaluation of asymmetric loadings on pressurizer.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 24pp. 32921:133-32921:156.

8510110115 Forwards responses to SER Open Items 14.2 & 14.7 re qualification of fire doors & configuration of connection for primary & backup water suppression sys to fire main & use of temporary hose.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 47pp. 32972:262-32972:328.

8510110131 Forwards request for deviation from Branch Technical Position CMEB 9.5-1 in response to SER Open Item 14.3 re safe shutdown capability, per commitments identified in util 850724 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 13pp. 32973:154-32973:166.

8510110170 Forwards preliminary safety evaluation proposed for inclusion in SSER 3, to support util conclusion that single recombiner sufficient to maintain post-accident hydrogen concentration below 4% vol.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 8pp. 33012:031-33012:038.

8510220234 Forwards revised response to SER Confirmatory Item 27 re calculated containment sump approach velocity, in response to NRC questions on effect of partial sump screen submergence on velocity calculations. Item resolved.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/15. YOUNGBLOOD, B.J. Licensing Branch 1. 12pp. 33084:147-33084:158.

8510250470 Forwards Safety Insp Rept 50-423/85-55 on 850916-23. No violation noted. EBNETER, S.D. Region 1, Office of Director. 85/10/22. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33173:150-33173:167.

8510250475 Insp Rept 50-423/85-55 on 850916-23. No violation noted. Major areas inspected: plant, operating & emergency procedures & review of licensee actions on previous findings.
PRELL, J., BLUMBERG, N., DEV, M. Region 1, Office of Director. 85/10/17. 16pp. 33173:152-33173:167.

F. Security, medical, emergency & fire protection plans

8510040003 Forwards revised FSAR Section 6.2.5.3 clarifying discrepancy w/emergency operating procedures re actuation of hydrogen recombiners, per 850828 telcon. Encl rev will be included in next amend to FSAR.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32851:071-32851:075.

8510040304 Forwards response to NRC concerns re proof & review Tech Specs. Two independent control room envelope pressurization sys ensure that breathable air supplied to control room, instrument rack & computer rooms.
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/25. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32854:222-32854:226.

8510070319 Forwards response to SER Confirmatory Item 26 re administrative control over doors in secondary containment. Encl info should resolve concerns identified in NRC 840802 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32880:298-32880:301.

8510110115 Forwards responses to SER Open Items 14.2 & 14.7 re qualification of fire doors & configuration of connection for primary & backup water suppression sys to fire main & use of temporary hose.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 47pp. 32972:262-32972:328.

8510110131 Forwards request for deviation from Branch Technical Position CMEB 9.5-1 in response to SER Open Item 14.3 re safe shutdown capability, per commitments identified in util 850724 ltr.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 13pp. 32973:154-32973:166.

8510080217 Forwards Preoperational Security Program Insp Rept 50-423/85-48 on 850805-08. No noncompliance noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/03. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32922:103-32922:108.

8510080228 Preoperational Security Program Insp Rept 50-423/85-48 on 850805-08. No noncompliance noted. Major areas inspected: progress in development of site physical security program to meet requirements of 10CFR73.55 & 10CFR73.67.
MADDEN, W.J., KEIMIG, R.R. Region 1, Office of Director. 85/10/02. 4pp. 32922:105-32922:108.

8510160052 Forwards responses to NRC questions re 850819-23 fire protection audit.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/07. YOUNGBLOOD, B.J. Licensing Branch 1. 8pp. 33027:190-33027:197.

8510310093 Forwards addl request for deviations from Branch Technical Position CMEB 9.5-1 re hose stations, for approval per 850724 commitment.
OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/07. YOUNGBLOOD, B.J. Licensing Branch 1. 33pp. 33273:114-33273:149.

8510310095 "Millstone Unit 3 Fire Loop Flow Test."
WARRINER, R.S. Northeast Utilities. 84/07/09. 3pp. 33273:147-33273:149.

8510150016 Summary of 851002 meeting w/util & Bishop, Liberman, Cook, Purcell & Reynolds re activities to be completed prior to issuance of low power license, including operating experience, fire protection & Tech Specs.
DOOLITTLE, E.L. Licensing Branch 1. 85/10/08. Licensing Branch 1. 7pp. 33031:151-33031:157.

8510180411 Forwards Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/10. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33056:345-33056:352.

8510180416 Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted. Major areas inspected: organization, training, emergency facilities & equipment & emergency implementing procedures.
LAZARUS, W.J., GORDON, C., HAWKHURST, J. Region 1, Office of Director. 85/10/06. 18pp. 33056:347-33056:362.

8510180057 Forwards Safety Insp Rept 50-423/85-53 on 850819-23. No noncompliance noted. Certain activities deviate from fire protection evaluation rept commitment to provide fire detection per NFPA stds.
EBNETER, S.D. Region 1, Office of Director. 85/10/11. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33054:060-33054:079.

8510180061 Insp Rept 50-423/85-53 on 850819-23. No noncompliance or deviation noted. Major areas inspected: safe shutdown ability in event of design basis fire & insp of emergency lighting sys for safe shutdown purposes.
KRASOPOULOS, A., ANDERSON, C.J. Region 1, Office of Director. 85/10/08. 18pp. 33054:062-33054:079.

8510210170 Notification of 851017 meeting w/util in Bethesda, MD to discuss info needed to complete NRC review of DCRDR.
DOOLITTLE, E.L. Licensing Branch 1. 85/10/16. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 33094:157-33094:159.

8510290235 Forwards response to 850910 request for addl info re SPDS, including "SPDS Operator Training Program Outline for Man-In-The-Loop Validation" & "SPDS Man-In-The-Loop Validation Scenarios."
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/16. YOUNGBLOOD, B.J. Licensing Branch 1. 11pp. 33233:258-33233:281.

202 DOCKETED ITEMS

- 8510290246** "SPDS Operator Training Program Outline for Man-In-The-Loop Validation." * Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/31. 5pp. 33233:269-33233:273.
- 8510290249** "SPDS Man-In-The-Loop Validation Scenarios." * Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/10/31. 8pp. 33233:274-33233:281.
- 8510210168** Notices of potential problem w/emergency operating procedure discovered during NRC evaluation of senior operator license denial appeal. Emergency operating procedures & training programs may need improvement. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/17. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33094:207-33094:209.
- 8510230219** Forwards sections of State of CT radiological emergency response plan re medical svcs & similar sections from local plans within 10 mile emergency planning zone. KRIMM, R.W. Federal Emergency Management Agency. 85/10/18. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 150pp. 33100:216-33101:026.
- 8510280421** Forwards LLL "Audit of SPDS for Northeast Utilis. Millstone Unit 3," conducted on 850729-30. NRC concurs w/rept. Schedule to respond to unresolved items should be provided by 851108. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/23. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33228:140-33228:159.
- 8510160297** "Audit of SPDS for Northeast Utilis. Millstone Unit 3." JOHNSON, G.J. Lawrence Livermore National Laboratory. 85/09/17. 18pp. 33228:142-33228:159.
- G. Adjudicatory correspondence**
- 8510110175** Order authorizing ASLAB to exercise authority & perform review functions otherwise performed by Commission re KL Burton appeal of denial of senior operator license application. Served on 851010. CHILK, S.J. Office of the Secretary of the Commission. #485 746. 85/10/10. Atomic Safety and Licensing Appeal Panel. 3pp. 32972:250-32972:252.
- K. Utility Final Safety Analysis Report (FSAR) & amends**
- 8510070275** Forwards Amend 15 to FSAR & responses to selected requests for add info. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 7pp. 33141:171-33145:001.
- 8510070279** Amend 15 to FSAR for Millstone Unit 3. W/29 oversize encls. * Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 85/09/30. 1,700pp. 33141:175-33145:187.
- 8510310220** Forwards Amend 16 to FSAR for Millstone Nuclear Power Station, Unit 3 Responses to selected requests for add info also encl. OPEKA, J.F., FEE, W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/10/24. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 33266:180-33267:125.
- 8510310225** Amend 16 to FSAR for Millstone Nuclear Power Station, Unit 3. * Northeast Utilities. 85/10/31. 300pp. 33266:186-33267:125.
- G. Inspection reports, IE Bulletins & correspondence**
- 8510030227** Forwards Special Dosimetry Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09 Status of planning during preoperational phase for dosimetry needs reviewed. No violations noted. MARTIN, T.T. Region 1, Office of Director. 85/09/17. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32845:139-32845:150.
- 8510030235** Insp Repts 50-245/85-23, 50-336/85-28 & 50-423/85-47 on 850805-09. No violations identified. Major areas inspected: personnel selection, facilities & equipment, dose assessment, QA, documentation & recordkeeping & organization. CIOFFI, J.A., JANG, J., SHANBAKY, M. Region 1, Office of Director. 85/09/11. 10pp. 32845:141-32845:150.
- 8510040330** Forwards Safety Insp Rept 50-423/85-38 on 850715-19. No violations noted. EBNETER, S.D. Region 1, Office of Director. 85/09/17. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32866:326-32866:340.
- 8510040335** Insp Rept 50-423/85-38 on 850715-19. No violation noted. Major areas inspected: preoperational test program, including test assessing, emergency diesel generator status, ESF test status, QA & QC. VANKESSEL, H.F., ESELGROTH, P.W. Region 1, Office of Director. 85/09/12. 12pp. 32866:328-32866:340.
- 8510040455** Forwards Class 3 fee & Section II, Paragraph 2.3 of Rev 2 to preservice insp plan, per 850320 commitment. OPEKA, J.F., LEE, W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/23. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 32854:195-32854:201.
- 8510070536** Forwards Safety Insp Rept 50-423/85-43 on 850805-09. No violations observed. EBNETER, S.D. Region 1, Office of Director. 85/09/27. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32883:258-32883:275.
- 8510070538** Insp Rept 50-423/85-43 on 850805-09. No noncompliance identified. Major areas inspected: preoperational test program, including test procedure review, test witnessing, test results evaluation & emergency diesel generator test status. VANKESSEL, H.F., CHEN, U., ESELGROTH, P.W. Region 1, Office of Director. 85/09/26. 16pp. 32883:260-32883:275.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.
- 8510070211** Forwards Insp Rept 50-423/85-49 c/n 850819-23. No violations noted. EBNETER, S.D. Region 1, Office of Director. 85/09/30. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32881:202-32881:218.
- 8510070225** Insp Rept 50-423/85-49 on 850819-23. No violations identified. Major areas inspected: licensee action to address operational QA program for design changes & mods, test & experiments & safety committee activities. PRELL, J., OLIVEIRA, W., DEV, M. Region 1, Office of Director. 85/09/19. 15pp. 32881:204-32881:218.
- 8510080040** Informs that preservice insp of all piping welds in break exclusion area completed & documented as acceptable per SER Confirmatory Item 7. Results of insps will be used in program to meet ASME Section XI requirements. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32918:298-32918:299.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510080217** Forwards Preoperational Security Program Insp Rept 50-423/85-48 on 850805-08. No noncompliance noted. MARTIN, T.T. Region 1, Office of Director. 85/10/03. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32922:103-32922:108.
- 8510080228** Preoperational Security Program Insp Rept 50-423/85-48 on 850805-08. No noncompliance noted. Major areas inspected: progress in development of site physical security program to meet requirements of 10CFR73.55 & 10CFR73.67. MADDEN, W.J., KEIMIG, R.R. Region 1, Office of Director. 85/10/02. 4pp. 32922:105-32922:108.
- 8510110082** Forwards Safety Insp Rept 50-423/85-41 on 850805-09. No violation noted. EBNETER, S.D. Region 1, Office of Director. 85/10/04. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 32973:311-32973:321.
- 8510110091** Insp Rept 50-423/85-41 on 850805-09. No violation noted. Major areas inspected: procedures, quality records & work activities re insp & testing of safety-related electrical equipment, including status of previous insp findings. PAULITZ, F.P., ANDERSON, C.J. Region 1, Office of Director. 85/10/01. 9pp. 32973:313-32973:321.
- 8510170287** Forwards Insp Rept 50-423/85-50 on 850813-16. No violations noted. EBNETER, S.D. Region 1, Office of Director. 85/10/07. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33051:255-33051:262.
- 8510170288** Insp Rept 50-423/85-50 on 850813-16. No violations noted. Major areas inspected: previous insp findings & followup of allegations re electrical const activities. FINKEL, A.E., JOHNSON, J.R. Region 1, Office of Director. 85/09/16. 6pp. 33051:257-33051:262.
- 8510180411** Forwards Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted. MARTIN, T.T. Region 1, Office of Director. 85/10/10. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33056:345-33057:002.
- 8510180416** Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted. Major areas inspected: organization, training, emergency facilities & equipment & emergency implementing procedures. LAZARUS, W.J., GORDON, C., HAWKHURST, J. Region 1, Office of Director. 85/10/06. 18pp. 33056:347-33057:002.
- 8510180057** Forwards Safety Insp Rept 50-423/85-53 on 850819-23. No noncompliance noted. Certain activities deviate from fire protection evaluation rept commitment to provide fire detection per NFPA stds. EBNETER, S.D. Region 1, Office of Director. 85/10/11. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33054:060-33054:079.
- 8510180061** Insp Rept 50-423/85-53 on 850819-23. No noncompliance or deviation noted. Major areas inspected: safe shutdown ability in event of design basis fire & insp of emergency lighting sys for safe shutdown purposes. KRASOPOULOS, A., ANDERSON, C.J. Region 1, Office of Director. 85/10/08. 18pp. 33054:062-33054:079.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:091-33177:068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.
- 8510250443** Ack receipt of 850912 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-423/85-22. EBNETER, S.D. Region 1, Office of Director. 85/10/18. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33170:138-33170:143.

8510250412 Forwards Safety Insp Rept 50-423/85-51 on 850819-23,26-29, 0903-06 & 09-13. No violation noted.
EBNETER,S.D. Region 1, Office of Director. 85/10/22. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33172-302-33172-316.

-8510250417 Insp Rept 50-423/85-51 on 850819-23,26-29,0903-06 & 09-13. No violation noted. Major areas inspected: preoperational test program, including witnessing of ESF tests.
VAN KESSEL,H.F., FINKEL,A.E., EVANS,M.A. Region 1, Office of Director. 85/10/18. 13pp. 33172-304-33172-316.

8510250470 Forwards Safety Insp Rept 50-423/85-55 on 850916-23. No violation noted.
EBNETER,S.D. Region 1, Office of Director. 85/10/22. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33173:150-33173:167.

-8510250475 Insp Rept 50-423/85-55 on 850916-23. No violation noted. Major areas inspected: plant operating & emergency procedures & review of licensee actions on previous findings.
PRELL,J., BLUMBERG,N., DEV,M. Region 1, Office of Director. 85/10/17. 16pp. 33173:152-33173:167.

S. Reportable occurrences, LERs & related correspondence

8510030332 Interim Deficiency Rept SD-56 re Tubeco weld radiographs. Corrective actions include review & repair of weldments & weld radiographs. Next rept anticipated by 851101.
OPEKA,J.F., MROCKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/09/17. MURLEY,T.E. Region 1, Office of Director. 3pp. 32845:170-32845:172.

8510030426 Final Potential Significant Deficiency Rept SD-85 re seismic interaction of flux mapping sys w/ seal table/bottom mounted instrumentation. Initially reported on 850626. Support added to ensure relative displacement.
OPEKA,J.F., FEE,W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/09/18. MURLEY,T.E. Region 1, Office of Director. 2pp. 32846:011-32846:012.

8510090177 Interim Deficiency Rept (SD-81) re structural steel connections in main steam valve bldg. Initially reported on 850412. Sampling of connections in QA Category 1 bldgs completed. Final rept will be submitted by 851010.
OPEKA,J.F., LEE,W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/09/18. MURLEY,T.E. Region 1, Office of Director. 2pp. 32946:192-32946:193.

8510070253 Responds to BJ Youngblood 850910 request for addl info re Questions 220.39 220.41 on containment liner anchor stud spacing. Info should close Significant Deficiency SD-38.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/09/26. YOUNGBLOOD,B.J. Licensing Branch 1. 7pp. 32877:350-32877:356.

8510020274 PNO-I-85-071A on 850927. Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage.
STAROSTECKI,R. Region 1, Office of Director. 85/09/27. 1p. 32825:232-32825:232.

8510150233 Potential Significant Deficiency Rept SD-82 re errors in qualification testing of Westinghouse core exit thermocouples. Initially reported on 850509. Next rept will be submitted by 851030.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/09/30. MURLEY,T.E. Region 1, Office of Director. 2pp. 33015:125-33015:126.

8510300268 Final Significant Deficiency Rept SD-88 re failure of brush rigging on diesel generator B during startup testing. Initially reported on 850905. Caused by design/fabrication error. One support rod designed & installed.
OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/07. MURLEY,T.E. Region 1, Office of Director. 3pp. 33258:113-33258:115.

8510300263 Significant Deficiency Rept SD-75 re nonconforming terminations in CVI Corp equipment. Initially reported on 850213. Insp of lugs in remaining CVI panels incomplete. Next rept expected by 851108.
OPEKA,J.F., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/09. MURLEY,T.E. Region 1, Office of Director. 2pp. 33258:119-33258:120.

8510300215 Final Significant Deficiency Rept SD-81 re undersized fillet welds on clip angles for beams welded to embedded plates for structural steel installation in main steam valve bldg. Initially reported on 850412. Connections reworked.
OPEKA,J.F., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/10. MURLEY,T.E. Region 1, Office of Director. 3pp. 33257:289-33257:291.

8510300271 Final Significant Deficiency Rept SD-86 re tripping of GE Type PVD21 differential relays located in Class 1E 4,160-volt switchgear. Initially reported on 850808. Seismic qualification of relays verified on 850913, 14 & 16.
OPEKA,J.F., FEE,W.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/18. MURLEY,T.E. Region 1, Office of Director. 2pp. 33258:111-33258:112.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510150018 Summary of 851002 meeting w/ util & Bishop, Liberman, Cook, Purcell & Reynolds re activities to be completed prior to issuance of low power license, including operating experience, fire protection & Tech Specs.
DOOLITTLE,E.L. Licensing Branch 1. 85/10/08. Licensing Branch 1. 7pp. 33031:151-33031:157.

8510180411 Forwards Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted.
MARTIN,T.T. Region 1, Office of Director. 85/10/10. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33056:345-33057:002.

-8510180416 Emergency Plan Implementation Appraisal 50-423/85-39 on 850722-26. No violation noted. Major areas inspected: organization, training, emergency facilities & equipment & emergency implementing procedures.
LAZARUS,W.J., GORDON,C., HAWKHURST,J. Region 1, Office of Director. 85/10/06. 18pp. 33056:347-33057:002.

8510220150 Discusses plans for meeting hot participation experience & shift technical advisor requirements for plant startup & operation.
OPEKA,J.F., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. 85/10/16. YOUNGBLOOD,B.J. Licensing Branch 1. 3pp. 33082:247-33082:249.

8510210168 Notifies of potential problem w/ emergency operating procedure, discovered during NRC evaluation of senior operator license denial appeal. Emergency operating procedures & training programs may need improvement.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/17. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33094:207-33094:209.

8510310048 Forwards requests for addl info re shift advisors training program & N-1 loop operation, required to complete evaluation of OL application. Schedule for providing responses requested by 851101.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/25. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 33277:171-33277:174.

DOCKET 50-424 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510040054 Summary of 850911 meeting w/ util, EG&G Idaho, Inc., Houston Lighting & Power Co., Westinghouse & Bechtel in Norwalk, CA re SORT & pump & valve operability review team programs & audits. Agenda & list of meeting attendees encl.
MILLER,M.A. Licensing Branch 4. 85/09/26. Licensing Branch 4. 29pp. 32860:247-32860:276.

8510220197 Partial response to FOIA request for documents re util 850726 briefing on readiness review program, including transcript. Documents listed in Apps A & B available in PDR. App C documents withheld (ref FOIA Exemption 5).
FELTON,J.M. Division of Rules and Records. 85/10/03. GARDE,B.P. Government Accountability Project. 3pp. 33099:251-33099:324.

-8510220207 Forwards "Readiness Review Pilot Program," scheduled for 850726.
MILLER,J.H. Georgia Power Co. 85/07/17. CHILK,S. Office of the Secretary of the Commission. 4pp. 33099:272-33099:275.

-8510220211 Viewgraphs entitled, "Pilot Readiness Review Program for Vogtle Electric Generating Plant, Unit 1."
RICE,P.D. Georgia Power Co. 85/07/26. 46pp. 33099:276-33099:323.

-8510220220 Staff requirements memo re util 850726 briefing on operational readiness review pilot program in Washington, DC.
CHILK,S.J. Office of the Secretary of the Commission. 85/08/02. Office of the Secretary of the Commission. 1p. 33099:324-33099:324.

8510080503 Forwards schematic showing location of second lined startup pond in relation to other ponds & plant structures. Pond located in area previously utilized during site const. No addl clearing required for const of facility.
BAILEY,J.A. Georgia Power Co. 85/10/04. ADENSAM,E.G. Licensing Branch 4. 3pp. 32921:189-32921:191.

8510080214 Requests that util be allowed to notify NRC of plant installation schedule to comply w/ Generic Ltr 85-06, ATWS rule, within 90 days after SER on WCAP-10858 issued.
BAILEY,J.A. Georgia Power Co. 85/10/07. ADENSAM,E.G. Licensing Branch 4. 2pp. 32913:344-32913:345.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170217 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review: Data & Info Capabilities' ..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-6. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044:246-33044:257.

8510170339 Notification of 851021 meeting w/ util in Bethesda, MD to provide applicant w/ guidance re Tech Specs.
MILLER,M.A. Licensing Branch 4. 85/10/11. ADENSAM,E.G. Licensing Branch 4. 2pp. 33043:346-33043:347.

8510180004 Discusses util 851004 ltr re installation of second lined startup pond adjacent to first lined startup pond for storing addl chemical cleaning wastes. No environ action required since station discharges unchanged.
ADENSAM,E.G. Licensing Branch 4. 85/10/15. FOSTER,D.O. Georgia Power Co. 2pp. 33075:068-33075:069.

8510230073 Requests approval to use ASME Code Case N-412 as alternative to NCA-8230 re witnessing of piping sys pressure tests of Section III, Div 1, Class 1, 2 & 3 piping sys.
FOSTER,D.O. Georgia Power Co. 85/10/15. ADENSAM,E.G. Licensing Branch 4. 3pp. 33102:257-33102:259.

204 DOCKETED ITEMS

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM.E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262-231-33262-255.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant...".
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510300191 Forwards proprietary "...Resource Evaluation & Data Recovery Planning," "...Resource Inventory 1 & Resource Inventory 2" & "...Tentative Resource Treatment Plan." Encls withheld.
BAILEY,J.A. Georgia Power Co. BAILEY,J.A. Southern Co. Services, Inc. 85/10/22. DENTON Office of Nuclear Reactor Regulation, Director. ADENSAM.E.G. Licensing Branch 4. 4pp. 33250-042-33250-051.

D. NRC Draft/Final Environmental Statements, suppis & correspondence

8510040096 Ack receipt of 850724 ltr re assessment of potential impact of facility on shortnose sturgeon in Savannah River. Participation in preparation of EIS re cooling water sys at plants suggested.
ADENSAM.E.G. Licensing Branch 4. 85/09/25. ORAVETZ,C.A. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 2pp. 32860-189-32860-190.

8510040105 Ack receipt of 850515 comments on FES for facilities. Complaints re noise along high voltage transmission line & actions taken re complaints should be reported to NRC.
ADENSAM.E.G. Licensing Branch 4. 85/09/25. MOORE,S.N. Environmental Protection Agency. 1p. 32860-188-32860-188.

E. NRC Safety Evaluation Report (SER), suppis & correspondence

8510090066 Forwards marked-up procedures generation package showing deviations from emergency response guidelines, in response to SER Confirmatory Item 44.
BAILEY,J.A. Georgia Power Co. 85/09/16. ADENSAM.E.G. Licensing Branch 4. 400pp. 32935-001-32935-341.

8510070302 Forwards "Cathodic Protection for Fuel Oil Storage Tanks & Associated Pipes," per SER Open Item 10. Rept documents analysis & test performed to determine corrosion potential of soils & at site.
BAILEY,J.A. Georgia Power Co. BAILEY,J.A. Southern Co. Services, Inc. 85/10/02. ADENSAM.E.G. Licensing Branch 4. 1p. 32875-269-32875-319.

-8510070310 "Cathodic Protection for Fuel Oil Storage Tanks & Associated Pipes."
PATEL,S.G. Georgia Power Co. 85/10/02. 50pp. 32875-270-32875-319.

8510090462 Forwards request for addl info re containment purge & vent valves (SER Confirmatory Item 14) per TMI Item II.E.4.2(6).
ADENSAM.E.G. Licensing Branch 4. 85/10/04. FOSTER,D.O. Georgia Power Co. 5pp. 32966-211-32966-215.

8510050459 Discusses NRC concerns re location of unconfined aquifer recording well w/ respect to well siting criteria in SER. Addl info on Confirmatory Item 5, "Final Details of Groundwater & Settlement Monitoring Program," requested.
ADENSAM.E.G. Licensing Branch 4. 85/10/10. FOSTER,D.O. Georgia Power Co. 4pp. 33033-196-33033-199.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM.E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262-231-33262-255.

F. Security, medical, emergency & fire protection plans

8510090066 Forwards marked-up procedures generation package showing deviations from emergency response guidelines, in response to SER Confirmatory Item 44.
BAILEY,J.A. Georgia Power Co. 85/09/16. ADENSAM.E.G. Licensing Branch 4. 400pp. 32935-001-32935-341.

8510040174 Forwards "In-Progress Audit Rept of DCRDR Being Conducted by Georgia Power Co for Vogtle Electric Generating Plant, Unit 1." Present DCRDR not expected to meet requirements of Suppl 1 to NUREG-0737.
ADENSAM.E.G. Licensing Branch 4. 85/09/26. FOSTER,D.O. Georgia Power Co. 1p. 32860-137-32860-171.

-8510040182 "In-Progress Audit Rept of DCRDR Being Conducted by Georgia Power Co for Vogtle Electric Generating Plant, Unit 1."
MOORE,J.W., SAVAGE,J.W. Lawrence Livermore National Laboratory. 85/09/23. NRC - No Detailed Affiliation Given. 33pp. 32860-139-32860-171.

8510030044 Forwards Rev 0 to "SPDS SAR for Georgia Power Co, Alvin W Vogtle Nuclear Power Plant." Rept provides SPDS implementation plan & SAR, per requirements of Suppl 1 to NUREG-0737.
BAILEY,J.A. Georgia Power Co. BAILEY,J.A. Southern Co. Services, Inc. 85/09/27. ADENSAM.E.G. Licensing Branch 4. 3pp. 32843-079-32843-111.

-8510030054 Rev 0 to "SPDS SAR for Georgia Power Co, Alvin W Vogtle Nuclear Power Plant."
FELICIONE,F.S. Energy, Inc. 85/09/20. 30pp. 32843-082-32843-111.

8510030089 Advises that submittal of analysis of safe shutdown capability, alternate shutdown & associated circuits/spurious actuations delayed until Mar 1986. Change in plant design will be reflected in future FSAR amend.
BAILEY,J.A. Georgia Power Co. 85/09/30. ADENSAM.E.G. Licensing Branch 4. 2pp. 32843-190-32843-191.

8510090534 Notification of 851016 meeting w/ util & Southern Co Svcs in Bethesda, MD to discuss emergency plan.
MILLER,M.A. Licensing Branch 4. 85/09/30. ADENSAM.E.G. Licensing Branch 4. 3pp. 32965-086-32965-088.

8510100126 Forwards emergency public info/educ matls for plume exposure pathway emergency planning zone. Challenges to adequacy of matls should be submitted by Joint Intervenor within 30 days. Svc list encl. Related correspondence.
CHURCHILL,B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL,B.W. Georgia Power Co. #485 701. 85/10/04. MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. 29pp. 32961-123-32961-151.

8510180228 Provides info re fire detection design for control room. Since design provides early warning of fire, design acceptable deviation from requirements of Branch Technical Position CMEB 9.5-1, Section C.7.b.
BAILEY,J.A. Georgia Power Co. 85/10/14. ADENSAM.E.G. Licensing Branch 4. 2pp. 33061-225-33061-226.

8510290368 Forwards emergency public info/educ matls for exposure pathway emergency planning zone, including texts of signs for transients, telephone directory ad & brochure & map of emergency planning zone. W/one oversize map.
BAILEY,J.A. Georgia Power Co. 85/10/21. ADENSAM.E.G. Licensing Branch 4. 54pp. 33255-004-33255-057.

8510290425 Forwards comments & requests for addl info re emergency plan meteorological models & dose protection sys & comments on evacuation time estimates, emergency classification sys & emergency preparedness implementation appraisal.
ADENSAM.E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 3pp. 33258-282-33258-014.

-8510290429 Discusses review of 850701 submittal of addl info. Data provided substantiates reasonableness of estimates for facility. Estimates not done per NUREG-0654 guidance. Summary of evacuation time estimate review encl.
URBANIK,T. Texas Transportation Institute, Texas A&M Univ., College Station, TX. 85/08/21. WILLIAMS,E.F. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 33258-285-33258-286.

-8510290431 "Vogtle Emergency Classification Sys."
* Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/30. NRC - No Detailed Affiliation Given. 17pp. 33258-297-33258-014.

G. Adjudicatory correspondence

8510030043 Memorandum & order ruling on applicant 850905 motion for reconsideration & clarification of ASLB ruling admitting Contentions EP-6 & EP-7. Addl info needed. Served on 851002.
MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. #485 664. 85/10/01. Georgia Power Co. 9pp. 32845-085-32845-093.

8510100005 Memorandum & order granting applicant 850624 motion for summary disposition of Contention 8 re QA. Joint intervenors conclusion w/o foundation. Served on 851004.
MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. #485 705. 85/10/03. Georgia Power Co. 9pp. 32960-212-32960-220.

8510100126 Forwards emergency public info/educ matls for plume exposure pathway emergency planning zone. Challenges to adequacy of matls should be submitted by Joint Intervenor within 30 days. Svc list encl. Related correspondence.
CHURCHILL,B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL,B.W. Georgia Power Co. #485 701. 85/10/04. MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. 29pp. 32961-123-32961-151.

8510110087 Emergency planning interrogatories. Certificate of Svc encl. Related correspondence.
BORDENICK,B.M. Hearing Branch 3. #485 720. 85/10/07. Joint Intervenor - Vogtle. 13pp. 32973-293-32973-305.

8510210026 Notification that all future correspondence to Campaign for Prosperous Georgia should be forwarded to author at listed address. Phone number unchanged W/ Certificate of Svc.
JOHNSON,T. Campaign for Prosperous Georgia. #485 826. 85/10/15. Atomic Safety and Licensing Board Panel. 2pp. 33074-144-33074-145.

8510210029 First set of interrogatories & requests to produce re emergency planning. Certificate of Svc encl. Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. JOHNSON,T. Georgians Against Nuclear Energy. #485 842. 85/10/15. Georgia Power Co. 6pp. 33072-348-33072-353.

8510230010 Responds to inquiry re whether applicant would consent to 1-wk extension for Joint Intervenor to file pleading in response to Board 851003 order dismissing OA Contention 8. Svc list encl. Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. #485 867. 85/10/17. JOHNSON,T. Campaign for Prosperous Georgia. 2pp. 33101-264-33101-265.

8510220224 Order granting Campaign for Prosperous Georgia 851018 request for extension until 851028 to file request for reconsideration of 851003 memorandum & order. Served on 851021.
MARGULIES,M.B. Atomic Safety and Licensing Board Panel. #485 847. 85/10/18. Campaign for Prosperous Georgia. 1p. 33087-322-33087-322.

8510220378 Forwards emergency planning zone map. W/o map. Svc list encl. Related correspondence.
RIDGWAY,D.J. Shaw, Pittman, Potts & Trowbridge. RIDGWAY,D.A. Georgia Power Co. #485 857. 85/10/18. MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. 3pp. 33086-338-33086-340.

8510240213 Forwards affidavits verifying interrogatory replies contained in applicant first supplemental response to intervenor third set of interrogatories & request for production of documents. Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. #485 883. 85/10/18. FOWLER,L. Legal Environmental Assistance Foundation. 10pp. 33155-175-33155-184.

H. General correspondence

8510070312 Requests addition of author to svc list for docketing of NRC documents re facility & to NRR & IE docketing lists, if necessary.
GARDE,B.P. Government Accountability Project. 85/10/01. MILLER,M. NRC - No Detailed Affiliation Given. 1p. 32875-358-32875-358.

I. Financial information

8510170029 Advises that financial info submitted for 1985 in 850726 ltr satisfies requirements of 10CFR140.21.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 05/10/01.
COOK, L.A. Georgia Power Co. 1p. 33043:222-33043:222.

Q. Inspection reports, IE Bulletins & correspondence

8510030025 Suppl response to violations noted in Insp Repts 50-424/85-36 & 50-425/85-36. Corrective actions: Procedure IX-50, "Pipe Support Field Installation & Fabrication," revised & sample reinspect program completed.
FOSTER, D.O. Georgia Power Co. 85/09/20. GRACE, J.N. Region 2, Office of Director. 3pp. 32845:113-32845:115.

8510030282 Forwards Insp Rept 50-424/85-44 on 850909-13. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/24. KELLY, R.J. Georgia Power Co. 2pp. 32845:129-32845:138.

8510030284 Insp Rept 50-424/85-44 on 850909-13. No violation or deviation noted. Major areas inspected: operations, organization & administration & Module 5 readiness review.
LATTI, R.M., BELISLE, G.A. Region 2, Office of Director. 85/09/23. 8pp. 32845:131-32845:138.

8510040493 Forwards Insp Repts 50-424/85-37 & 50-425/85-29 on 850722-0830 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/09/24. KELLY, R.J. Georgia Power Co. 2pp. 32865:248-32865:271.

8510040495 Notice of violation from insp on 850722-30.
* Region 2, Office of Director. 85/09/24. 2pp. 32865:250-32865:251.

8510040496 Insp Repts 50-424/85-37 & 50-425/85-29 on 850722-0830. Violation noted: failure to prescribe appropriate procedures to control area & pump internal cleanliness.
ROGGE, J.F., SCHEPENS, R.J., SINKULE, M.V. Region 2, Office of Director. 85/09/23. 20pp. 32865:252-32865:271.

8510040526 Forwards Insp Repts 50-424/85-46 & 50-425/85-33 on 850826-30. No violation or deviation noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/24. KELLY, R.J. Georgia Power Co. 2pp. 32866:039-32866:049.

8510040531 Insp Repts 50-424/85-46 & 50-425/85-33 on 850826-30. No violation or deviation noted. Major areas inspected: preservice insp program for Unit 1 reactor vessel, procedures, work activities & data review.
NEWSOME, R.W., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 9pp. 32866:041-32866:049.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinspect of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTC, N.D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinspect of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070375 Forwards Insp Repts 50-424/85-40 & 50-425/85-31 on 850819-23 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/03. KELLY, R.J. Georgia Power Co. 3pp. 32877:184-32877:200.

8510070377 Notice of violation from insp on 850819-23.
* Region 2, Office of Director. 85/10/03. 2pp. 32877:187-32877:188.

8510070383 Insp Repts 50-424/85-40 & 50-425/85-31 on 850819-23. Violation noted: failure to follow procedures for control of welding & failure to protect permanent plant equipment.
HALLSTROM, G.A., BLAKE, J.J. Region 2, Office of Director. 85/09/23. 12pp. 32877:189-32877:200.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:311.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510040054 Summary of 850911 meeting w/util, E.G. Idaho, Inc., Houston Lighting & Power Co., Westinghouse & Bechtel in Norwalk, CA re SCRT & pump & valve operability review team programs & audits. Agenda & list of meeting attendees encl.
MILLER, M.A. Licensing Branch 4. 85/09/26. Licensing Branch 4. 29pp. 32860:247-32860:276.

8510220197 Partial response to FOIA request for documents re util 850726 briefing on readiness review program, including transcript. Documents listed in Apps A & B available in PDR. App C documents withheld (ref FOIA Exemption 5).
FELTON, J.M. Division of Rules and Records. 85/10/03. GARDE, B.P. Government Accountability Project. 5pp. 33099:251-33099:324.

8510220207 Forwards "Readiness Review Pilot Program," scheduled for 850726.
MILLER, J.H. Georgia Power Co. 85/07/17. CHILK, S. Office of the Secretary of the Commission. 4pp. 33099:272-33099:275.

8510220220 Staff requirements memo re util 850726 briefing on operational readiness review pilot program in Washington, DC.
CHILK, S.J. Office of the Secretary of the Commission. 85/08/02. Office of the Secretary of the Commission. 1p. 33099:324-33099:324.

8510080503 Forwards schematic showing location of second lined startup pond in relation to other ponds & plant structures. Pond located in area previously utilized during site const. No addl clearing required for const of facility.
BAILEY, J.A. Georgia Power Co. 85/10/04. ADENSAM, E.G. Licensing Branch 4. 3pp. 32921:189-32921:191.

8510080214 Requests that util be allowed to notify NRC of plant installation schedule to comply w/Generic Ltr 85-06, ATWS rule, within 90 days after SER on WCAP-10858 issued.
BAILEY, J.A. Georgia Power Co. 85/10/07. ADENSAM, E.G. Licensing Branch 4. 2pp. 32913:344-32913:345.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

8510170217 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review: Data & Info Capabilities'..." technical evaluation rpt.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-6. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044:246-33044:257.

8510170339 Notification of 851021 meeting w/util in Bethesda, MD to provide applicant w/guidance re Tech Specs.
MILLER, M.A. Licensing Branch 4. 85/10/11. ADENSAM, E.G. Licensing Branch 4. 2pp. 33043:346-33043:347.

8510180004 Discusses util 851004 ltr re installation of second lined startup pond adjacent to first lined startup pond for storing addl chemical cleaning wastes. No environ action required since station discharges unchanged.
ADENSAM, E.G. Licensing Branch 4. 85/10/15. FOSTER, D.O. Georgia Power Co. 2pp. 33075:068-33075:069.

8510230073 Requests approval to use ASME Code Case N-412 as alternative to NCA-8230 re witnessing of piping sys pressure tests of Section III, Div 1, Class 1, 2 & 3 piping sys.
FOSTER, D.O. Georgia Power Co. 85/10/15. ADENSAM, E.G. Licensing Branch 4. 3pp. 33102:257-33102:259.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:255.

8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review: Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

8510300191 Forwards proprietary "...Resource Evaluation & Data Recovery Planning," "...Resource Inventory 1 & Resource Inventory 2" & "...Tentative Resource Treatment Plan." Encls withheld.
BAILEY, J.A. Georgia Power Co. BAILEY, J.A. Southern Co. Services, Inc. 85/10/22. DENTON Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 4pp. 33250:042-33250:051.

206 DOCKETED ITEMS

D. NRC Draft/Final Environmental Statements, suppils & correspondence

8510040096 Ack receipt of 850724 ltr re assessment of potential impact of facility on shortnose sturgeon in Savannah River. Participation in preparation of EIS re cooling water sys at plants suggested.
ADENSAM.E.G. Licensing Branch 4. 85/09/25. ORAVETZ,C.A. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 2pp. 32860:189-32860:190.

8510040105 Ack receipt of 850515 comments on FES for facilities. Complaints re noise along high voltage transmission line & actions taken re complaints should be reported to NRC.
ADENSAM.E. Licensing Branch 4. 85/09/25. MOORE,S.N. Environmental Protection Agency. 1p. 32860:188-32860:188.

F. NRC Safety Evaluation Report (SER), suppils & correspondence

8510090066 Forwards marked-up procedures generation package showing deviations from emergency response guidelines in response to SER Confirmatory Item 44.
BAILEY,J.A. Georgia Power Co. 85/09/16. ADENSAM.E.G. Licensing Branch 4. 400pp. 32935:001-32935:341.

8510070302 Forwards "Cathodic Protection for Fuel Oil Storage Tanks & Associated Pipes," p. SER Open Item 10.Rept documents analysis & test performed to determine corrosion potential of soils & at site.
BAILEY,J.A. Georgia Power Co. BAILEY,J.A. Southern Co. Services, Inc. 85/10/02. ADENSAM.E.G. Licensing Branch 4. 1p. 32875:269-32875:319.

-8510070310 "Cathodic Protection for Fuel Oil Storage Tanks & Associated Pipes."
PATEL,S.G. Georgia Power Co. 85/10/02. 50pp. 32875:270-32875:319.

8510090462 Forwards request for addl info re containment purge & vent valves (SER Confirmatory Item 14f) per TMI Item ILE.4.2(6).
ADENSAM.E.G. Licensing Branch 4. 85/10/04. FOSTER,D.O. Georgia Power Co. 5pp. 32966:211-32966:215.

8510150459 Discusses NRC concerns re location of unconfined aquifer recording well w/respect to well siting criteria in SER. Addl info on Confirmatory Item 5, "Final Details of Groundwater & Settlement Monitoring Program," requested.
ADENSAM.E.G. Licensing Branch 4. 85/10/10. FOSTER,D.O. Georgia Power Co. 4pp. 33033:196-33033:199.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28,Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM.E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262:231-33262:231.

F. Security, medical, emergency & fire protection plans

8510090066 Forwards marked-up procedures generation package showing deviations from emergency response guidelines in response to SER Confirmatory Item 44.
BAILEY,J.A. Georgia Power Co. 85/09/16. ADENSAM.E.G. Licensing Branch 4. 400pp. 32935:001-32935:341.

8510030044 Forwards Rev 0 to "SPDS SAR for Georgia Power Co. Alvin W Vogtle Nuclear Power Plant." Rept provides SPD3 implementation plan & SAR per requirements of Suppl 1 to NUREG-0737.
BAILEY,J.A. Georgia Power Co. BAILEY,J.A. Southern Co. Services, Inc. 85/09/27. ADENSAM.E.G. Licensing Branch 4. 3pp. 32843:079-32843:111.

-8510030054 Rev 0 to "SPDS SAR for Georgia Power Co. Alvin W Vogtle Nuclear Power Plant."
FELICIONE,F.S. Energy, Inc. 85/09/20. 30pp. 32843:082-32843:111.

8510030089 Advises that submittal of analysis of safe shutdown capability,alternate shutdown & associated circuits/spurious actuations delayed until Mar 1986.Change in plant design will be reflected in future FSAR amend.
BAILEY,J.A. Georgia Power Co. 85/09/30. ADENSAM.E.G. Licensing Branch 4. 2pp. 32843:190-32843:191.

8510090534 Notification of 851016 meeting w/util & Southern Co Svcs in Bethesda,MD to discuss emergency plan.
MILLER,M.A. Licensing Branch 4. 85/09/30. ADENSAM.E.G. Licensing Branch 4. 3pp. 32965:086-32965:088.

8510100126 Forwards emergency public info/educ matls for plume exposure pathway emergency planning zone.Challenges to adequacy of matls should be submitted by Joint Intervenors within 30 days.Svc list encl.Related correspondence.
CHURCHILL,B.W. Shaw, Pittman, Potts & Trowbridge. #485 701. 85/10/04. MARGULIES,M.B. Atomic Safety and Licensing Board Panel. 29pp. 32961:123-32961:151.

8510180228 Provides info re fire detection design for control room. Since design provides early warning of fire,design acceptable deviation from requirements of Branch Technical Position CMEB 9.5-1,Section C.7.b.
BAILEY,J.A. Georgia Power Co. 85/10/14. ADENSAM.E.G. Licensing Branch 4. 2pp. 33061:225-33061:226.

8510290368 Forwards emergency public info/educ matls for exposure pathway emergency planning zone,including texts of signs for transients,telephone directory ad & brochure & map of emergency planning zone W/one oversize map.
BAILEY,J.A. Georgia Power Co. 85/10/21. ADENSAM.E.G. Licensing Branch 4. 54pp. 33255:004-33255:057.

8510290425 Forwards comments & requests for addl info re emergency plan meteorological models & dose protection sys & comments on evacuation time estimates,emergency classification sys & emergency preparedness implementation appraisal.
ADENSAM.E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 3pp. 33258:282-33258:014.

-8510290429 Discusses review of 850701 submittal of addl info.Data provided substantiates reasonableness of estimates for facility.Estimates not done per NUREG-065 guidance.Summary of evacuation time estimate review encl.
URBANIK,T. Texas Transportation Institute, Texas A&M Univ., College Station, TX. 85/08/21. WILLIAMS,E.F. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 33258:285-33258:286.

-8510290431 "Vogtle Emergency Classification Sys."

* Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/30. NRC - No Detailed Affiliation Given. 17pp. 33258:287-33259:014.

G. Adjudicatory correspondence

8510030043 Memorandum & order ruling on applicant 850905 motion for reconsideration & clarification of ASLB ruling admitting Contentions EP-6 & EP-7.Addl info needed.Served on 851002.
MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. #485 664. 85/10/01. Georgia Power Co. 9pp. 32845:085-32845:093.

8510100005 Memorandum & order granting applicant 850624 motion for summary disposition of Contention 8 re QA.Joint Intervenors conclusion w/o foundation.Served on 851004.
MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. #485 705. 85/10/03. Georgia Power Co. 9pp. 32960:212-32960:220.

8510100126 Forwards emergency public info/educ matls for plume exposure pathway emergency planning zone.Challenges to adequacy of matls should be submitted by Joint Intervenors within 30 days.Svc list encl.Related correspondence.
CHURCHILL,B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL,B.W. Georgia Power Co. #485 701. 85/10/04. MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. 29pp. 32961:123-32961:151.

8510110087 Emergency planning interrogatories.Certificate of Svc encl. Related correspondence.
BORDENICK,B.M. Hearing Branch 3. #485 720. 85/10/07. Joint Intervenors - Vogtle. 13pp. 32973:293-32973:305.

8510210026 Notification that all future correspondence to Campaign for Prosperous Georgia should be forwarded to author at listed address.Phone number unchanged.W/Certificate of Svc.
JOHNSON,T. Campaign for Prosperous Georgia. #485 826. 85/10/15. Atomic Safety and Licensing Board Panel. 2pp. 33074:144-33074:145.

8510210029 First set of interrogatories & requests to produce re emergency planning.Certificate of Svc encl.Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. JOHNSON,T. Georgians Against Nuclear Energy. #485 842. 85/10/15. Georgia Power Co. 6pp. 33072:348-33072:353.

8510230010 Responds to inquiry re whether applicant would consent to 1-wk extension for Joint Intervenors to file pleading in response to Board 851003 order dismissing QA Contention 8. Svc list encl.Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. JOHNSON,T. Georgians Against Nuclear Energy. #485 867. 85/10/17. JOHNSON,T. Campaign for Prosperous Georgia. 2pp. 33101:264-33101:265.

8510220224 Order granting Campaign for Prosperous Georgia 851018 request for extension until 851028 to file request for reconsideration of 851003 memorandum & order.Served on 851021.
MARGULIES,M.B. Atomic Safety and Licensing Board Panel. #485 847. 85/10/18. Campaign for Prosperous Georgia. 1p. 33087:322-33087:322.

8510220378 Forwards emergency planning zone map.W/o map.Svc list encl. Related correspondence.
RIDGWAY,D.A. Shaw, Pittman, Potts & Trowbridge. RIDGWAY,D.A. Georgia Power Co. #485 857. 85/10/18. MARGULIES,M.B., LINENBERGER,G., PARIS,O.H. Atomic Safety and Licensing Board Panel. 3pp. 33086:338-33086:340.

8510240213 Forwards affidavits verifying interrogatory replies contained in applicant first supplemental response to intervenor third set of interrogatories & request for production of documents.Related correspondence.
JOHNSON,T. Campaign for Prosperous Georgia. JOHNSON,T. Georgians Against Nuclear Energy. #485 883. 85/10/18. FOWLER,L. Legal Environmental Assistance Foundation. 10pp. 33155:175-33155:184.

H. General correspondence

8510070312 Requests addition of author to svc list for docketing of NRC documents re facility & to NRR & IE docketing lists,if necessary.
GARDE,B.P. Government Accountability Project. 85/10/01. MILLER,M. NRC - No Detailed Affiliation Given. 1p. 32875:358-32875:359.

I. Financial information

8510170029 Advises that financial info submitted for 1985 in 850726 ltr satisfies requirements of 10CFR140.21.
SALTZMAN,J. Assistant Director for State & Licensee Relations. 85/10/01. COOK,L.A. Georgia Power Co. 1p. 33043:222-33043:222.

Q. Inspection reports, IE Bulletins & correspondence

8510030025 Suppls response to violations noted in Insp Repts 50-424/85-36 & 50-425/85-36.Corrective actions.Procedure IX-50, "Pipe Support Field Installation & Fabrication," revised & sample reinsp program completed.
FOSTER,D.O. Georgia Power Co. 85/09/20. GRACE,J.N. Region 2, Office of Director. 3pp. 32845:113-32845:115.

8510040493 Forwards Insp Repts 50-424/85-37 & 50-425/85-29 on 850722-0830 & notice of violation.
WALKER,R.D. Region 2, Office of Director. 85/09/24. KELLY,R.J. Georgia Power Co. 2pp. 32865:248-32865:271.

-8510040498 Insp Repts 50-424/85-37 & 50-425/85-29 on 850722-0830. Violation noted/failure to prescribe appropriate procedures to control area & pump internal cleanliness.
ROGGE,J.F., SCHUPERS,R.J., SINKULE,M.V. Region 2, Office of Director. 85/09/23. 20pp. 32865:252-32865:271.

8510040526 Forwards Insp Repts 50-424/85-46 & 50-425/85-33 on 50424-30. No violation or device(s) noted.
BROWNLEE, V.L. Region 2, Office of Director. 85/09/24. KELLY, R.J. Georgia Power Co. 2pp. 32858:039-32866:049.

8510040531 Insp Repts 50-424/85-46 & 50-425/85-33 on 850826-30. No violation or deviation noted. Major areas inspected: preservice insp program for Unit 1 reactor vessel, procedures, work activities & data review.
NEWSOME, P.W., BLAKE, J.J. Region 2, Office of Director. 85/09/19. 9pp. 32866:041-32866:049.

8510010374 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds."
Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8509261122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070375 Forwards Insp Repts 50-424/85-40 & 50-425/85-31 on 850819-20 & notice of violation.
WALKER, R.D. Region 2, Office of Director. 85/10/03. KELLY, R.J. Georgia Power Co. 3pp. 32877:184-32877:200.

8510070377 Notice of violation from insp on 850819-23.
Region 2, Office of Director. 85/10/03. 27pp. 32877:187-32877:188.

8510070383 Insp Repts 50-424/85-40 & 50-425/85-31 on 850819-23. Violation noted: failure to follow procedures for control of welding & failure to protect permanent plant equipment.
HALLSTROM, G.A., BLAKE, J.J. Region 2, Office of Director. 85/09/23. 12pp. 32877:189-32877:200.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-433 UNIV. OF CALIFORNIA AT SANTA BARBARA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8510250085 Order to show cause why licensee authority to possess highly enriched U fuel should not be suspended.
HOYLE, J.C. Office of the Secretary of the Commission. 85/09/27. California, Univ. of Santa Barbara, CA. 3pp. 33226:095-33226:097.

8510220466 Responds to 850927 order to show cause re removal of spare highly enriched U to locked storage environ. Reactor scheduled to be decommissioned. i.e. then 20 g spare fuel solution exists outside reactor core.
KROES, R.J. California, Univ. of Santa Barbara, CA. 85/10/07. Office of the Secretary of the Commission. 5pp. 33099:101-33099:105.

8510170478 Forwards request for addl info re decommissioning plan. Response requested by 851121.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/11. PROFIO, A.E. California, Univ. of Santa Barbara, CA. 7pp. 33048:149-33048:155.

8510310439 Responds to 850927 order to show cause re removal of spare highly enriched U to more secure storage environ. Storage of spare fuel solution in locked cabinet in facility requested until entire fuel inventory returned to DOE.
KROES, R.J. California, Univ. of Santa Barbara, CA. 85/10/14. Office of the Secretary of the Commission. 2pp. 33278:224-33278:225.

8510300227 Informs that Commission requested Ofc of FR to publish encl notice of proposed issuance of orders authorizing disposition of component parts & terminating License R-124, per 850909 application.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/24. KROES, R.J. California, Univ. of Santa Barbara, CA. 3pp. 33261:318-33261:324.

8510300231 Notice of proposed issuance of order authorizing disposition of component parts & terminating License R-124, per licensee 850909 application.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/24. 4pp. 33261:321-33261:324.

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feedwater event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr W/O encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033:193-33033:195.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848:077-32848:081.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr. Follow up rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32519:123-32519:144.

8510150383 Forwards info in response to NPC 850926 ltr, consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts.
WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001:007-33006:171.

8510160136 Informs that response to Item 4.3 of Generic Ltr 83-28, "Required Actions Based on Generic Info of Salem ATWS Events," will be submitted by 851223.
DOMER, J.A. Tennessee Valley Authority. 85/10/10. ADENSAME, Licensing Branch 4. 1p. 33022:258-33022:258.

8510160089 Informs that ATWS equipment will be installed to provide diverse actuation circuits to initiate auxiliary feedwater sys, turbine trip & reactor trip, per 10CFR50.62 requirements. Installation date not set due to slowdown in const.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33028:001-33028:001.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085:157-33086:052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193:185-33193:237.

208 DOCKETED ITEMS

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262-231-33262-231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

G. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl. 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080348 Notices of inability to meet 851101 commitment to provide TDI emergency diesel generator in-p results & schedule due to manpower reductions.
SHELL, R.H. Tennessee Valley Authority. 85/10/01. ADENSAM, E. Licensing Branch 4. 2pp. 32922-123-32922-124.

8510110022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150060 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280147 Informs of 851022 mtg meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submit on corporate & Sequoyah portions of outage of action per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191-073-33191-074.

S. Portable occurrences, LERs & related correspondence

8510030273 First interim deficiency rept re intake pumping station electrical equipment room exhaust fans & dampers not meeting IEEE requirements. Initially reported on 850823. Next rept expected by 860131.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 3pp. 32845-245-32845-249.

8510030275 Second interim deficiency rept re containment isolation barrier defects. Initially reported on 850422. Design documents revised to comply w/code & safety requirements. Next rept expected by 860330.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-250-32845-251.

8510030300 First interim deficiency rept re undervoltage of 125-volt dc vital power distribution on sys to auxiliary feedwater turbine pump room cooling fans. Initially reported on 850808. Next rept expected by 860321.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-151-32845-152.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510150462 Forwards Toledo Edison response to 850814 ltr re 850609 loss of feedwater event at Davis-Besse. Ltr to be used as ref in response to NRC 850917 ltr w/o encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/20. PARRIS, H.G. Tennessee Valley Authority. 3pp. 33033-193-33033-195.

8510030424 Confirms 850906 agreement that util provide NRC weekly repts of potential safety-related issues generated by employee response team. Repts should also include investigation repts by nuclear safety review staff.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. WILLIS, W.F. Tennessee Valley Authority. 5pp. 32848-077-32848-081.

8510080442 Forwards first interim rept summarizing 18 reviews in which all recommendations closed by nuclear safety review staff, per commitment in util 850906 ltr Followup rept of addl summaries expected by 851031.
PARRIS, H.G. Tennessee Valley Authority. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 22pp. 32919-123-32919-144.

8510150383 Forwards info in response to NRC 850926 ltr consisting of employee concern assignment requests (K-forms), investigation repts prepared by Quality Technology Co & nuclear safety review staff & line responses to investigation repts.
WILLIS, W.F. Tennessee Valley Authority. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1,600pp. 33001-001-33006-171.

8510160136 Informs that response to Item 4.3 of Generic Ltr 83-28, "Required Actions Based on Generic Info of Salem ATWS Events," will be submitted by 851223.
DOMER, J.A. Tennessee Valley Authority. 85/10/10. ADENSAM, E. Licensing Branch 4. 1p. 33022-258-33022-258.

8510160088 Informs that ATWS equipment will be installed to provide diverse actuation circuits to initiate auxiliary feedwater system trip & reactor trip per 10CFR50.62 requirements. Installation date not set due to slowdown in const.
SHELL, R.H. Tennessee Valley Authority. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33028-001-33028-001.

8510220374 Forwards investigation repts & related documents re potentially safety-related employee concerns on util plants, per util 851007 ltr & NRC 850926 request. Encl repts cover 851001-11.
WHITT, K.W. Tennessee Valley Authority. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 250pp. 33085-157-33086-052.

8510280331 Forwards response to Quality Technology Co investigation rept. Response inadvertently omitted from 851007 response to request for investigation repts & related documents re potential safety-related employee concerns.
WILLIS, W.F. Tennessee Valley Authority. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 53pp. 33193-185-33193-237.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262-231-33262-231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

F. Security, medical, emergency & fire protection plans

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

G. Inspection reports, IE Bulletins & correspondence

8510010162 Forwards SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/17. DEAN, C. Tennessee Valley Authority. 19pp. 32834-210-32834-349.

-8510010246 SALP Repts 50-259/85-34, 50-260/85-34, 50-296/85-34, 50-327/85-22, 50-328/85-22, 50-391/85-34, 50-438/85-16 & 50-439/85-16 for Mar 1984 - May 1985 & 50-390/85-43 for Jan-Mar 1985 Overall performance marginally acceptable.
* Region 2, Office of Director. 85/09/17. 68pp. 32834-229-32834-349.

3509260122 IE Info Notice 85-078, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260389 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080348 Notices of inability to meet 851101 commitment to provide TDI emergency diesel generator insp results & schedule due to rmpower reductions.
SHELL, R.H. Tennessee Valley Authority. 85/10/01. ADENSAM, E. Licensing Branch 4. 2pp. 32922-123-32922-124.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-008.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510280147 Informs of 851022 mgt meeting w/NRC to discuss NRC concerns re util deficiencies & provide schedule for detailed submittal on corporate & Sequoyah portions of course of action per NRC 850917 suggestion.
DEAN, C.H. Tennessee Valley Authority. 85/10/18. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33191-073-33191-074.

S. Reportable occurrences, LERs & related correspondence

8510030273 First interim deficiency rept re intake pumping station electrical equipment room exhaust fans & dampers not meeting IEEE requirements. Initially reported on 850823. Next rept expected by 880131.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 3pp. 32845-248-32845-249.

8510030275 Second interim deficiency rept re containment isolation barrier defects. Initially reported on 850422. Design documents revised to comply w/code & safety requirements. Next rept expected by 860330.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-250-32845-251.

8510030300 First interim deficiency rept re undervoltage of 125-volt dc vital power distribution on sys to auxiliary feedwater turbine pump room cooling fans. Initially reported on 850806. Next rept expected by 860321.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. GRACE, J.N. Region 2, Office of Director. 2pp. 32845-151-32845-152.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Bettelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-045-32882-075.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A. Application, construction stage documents & correspondence

8510180082 Forwards response to 850808 & 14 ltrs re radwaste solidification sys. Responses incorporated into Rev 3 of process control program. Proprietary NUS Process Svcs Repts FO-013 & SS-001 withheld (ref 10CFR2.790(b)(1)).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/08/30. YOUNGBLOOD, B.J. Licensing Branch 1. 8pp. 33056-206-33056-318.

-8510180115 Rev 3 to Operations Manual OM12E-PCP, "Process Control Program."
KENSICHI, S.F. Cleveland Electric Illuminating Co. 85/08/26. 21pp. 33056-216-33056-236.

-8510180118 Rev 0 to Operations Manual PAP-1309, "Shipment of Radwaste for Disposal."
SHATMAN, R., WAHATH, B.D., SHUSTER, C.M. Cleveland Electric Illuminating Co. 85/08/05. 81pp. 33056-237-33056-318.

8510010038 Provides final update of equipment qualification issues for closing out Outstanding Issue 4 All equipment within scope of 10CFR50.49 qualified & all active safety-related pumps & valves qualified for operability. Test list encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/23. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32801-278-32801-280.

8510010465 Responds to 850529 comments re proposed resolution of TMI Action Plan Item III.D.1.1. Reactor water cleanup sys provided w/connections to post-accident sampling sys for monitoring cleanup operations.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32809-050-32809-051.

8510010374 Responds to 850716 request for confirmation from each Licensee Review Group II member to implement proposed solution for Generic Issue 9-RSB, on long-term operability of deep draft pumps. Endorses solution.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/27. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 32801-232-32801-232.

8510030003 Forwards description of procedures & programs which implement required review process for compliance w/10CFR50.59 including enhancements of existing programs & proposed changes to draft Tech Specs.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 12pp. 32842-213-32842-224.

8510080477 Forwards ltr authorizing microfiling encl NUS proprietary info re process control program for radwaste solidification, procedure change requests & revs to process control programs. Proprietary info withheld.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32922-166-32922-167.

8510070356 Confirms 851011 meeting at site to discuss status of items required for fuel load per 851001 discussion.
NORELIUS, C.E. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 1p. 32875-035-32875-035.

8510080399 Advises that traversing in-core probe piping & subsystem noted on FSAR Table 3.2-1 should have been NSC Quality Group D per 850826 request to revise safety classification. Change will be noted in next FSAR amend.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32919-302-32919-303.

8510080406 Advises that proof & review Tech Specs reviewed. Resolution of concerns w/administrative issues expected prior to issuance of final draft Tech Specs. Ltr will be submitted 30 days prior to fuel load requesting OL.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 32919-238-32919-238.

8510160210 Responds to Containment Sys Branch comments re facility Tech Specs. Valves to be water tested are at elevations below suppression pool & capable of maintaining water seal for at least 30 days following LOCA.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/09. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33021-086-33021-086.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

-8507160361 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' for Perry Nuclear Power Plant."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1522. 85/07/10. NRC - No Detailed Affiliation Given. 14pp. 33044-028-33044-041.

8510250175 Documents commitment to provide rept describing methods used to establish setpoints & allowable values for reactor protection sys & ESF trip functions assumed to operate in FSAR Chapters 6 & 15 analysis per 840723 & 1009 ltrs.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/17. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 33172-146-33172-147.

8510280008 Requests review of encl final draft Tech Specs by 851101. W/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/21. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33241-338-33241-339.

8510290628 Notification of 851107 meeting w/util in Perry, OH to determine readiness for low power OL. Simulator exercise planned for 851106. Agenda encl.
STEFANO, J.J. Licensing Branch 1. 85/10/22. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 33245-353-33245-356.

8510290011 Forwards proposed changes to FSAR Chapter 14 re startup testing program. Changes will be included in next FSAR amend.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/23. YOUNGBLOOD, B.J. Licensing Branch 1. 55pp. 33233-292-33233-346.

8510310249 Forwards application for amend to CPPR-148, extending const completion date. Fee paid.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33273-157-33273-160.

-8510310255 Application for amend to CPPR-148, extending const completion date from 851130 to 851231.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/29. 3pp. 33273-158-33273-160.

E. NRC Safety Evaluation Report (SER), suppis & correspondence

8510010077 Forwards addl info, clarifying util 820902, 830126, 840125 & 850624 submittals re Mark III containment sys issues per SER Outstanding issue 8. Commitment to provide further info will be reflected in FSAR amend, if necessary.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32801-292-32801-294.

8510010276 Provides info to clearly define cabinet/panel fire detection arrangement & to distinguish between cabinet/panel bay & console terminology. Info provided to support SER preparation. Figure encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32800-244-32800-247.

8510160029 Provides further confirmation re previous submittals on SER Outstanding Issues 8 & 9 concerning Mark III Containment Sys (Humphrey issues) & LOCA-related pool dynamic loads. Reevaluation of 10 components completed & design sufficient.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/08. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33026-337-33026-337.

210 DOCKETED ITEMS

F. Security, medical, emergency & fire protection plans

8510010276 Provides info to clearly define cabinet/panel fire detection arrangement & to distinguish between cabinet/panel bay & console terminology. Info provided to support SER preparation. Figure encl.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/09/76. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32800.244-32800.247.

8510030067 Forwards Rev 3 to security force training & qualification plan, per 850806 & 0923 discussions. Rev withheld (ref 10CFR73.21).
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/09/27. Office of Nuclear Reactor Regulation, Director. 1p. 32843.011-32843.011.

8510040474 Revised "OH State Plan for Response to Radiation Emergencies at Licensed Nuclear Facilities." W/851001 ltr.
LOCKHART, R.M. Ohio, State of. 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 415pp. 32851.240-32852.286.

8510080114 Ack receipt of 850906 ltr & scope & objectives for emergency plan exercise scheduled for 851120. Assembly, accountability & evacuation successfully demonstrated during insp on 850925 & not required for Nov exercise.
SHAFFER, W.D. Region 3, Office of Director. 85/10/02. EDELMA, M.R. Cleveland Electric Illuminating Co. 2pp. 32920.248-32920.249.

8510080446 Forwards schedule for closure of all remaining open DCRDR activities, per 850910-13 site audit. Human engineering deficiencies requiring revised responses identified in encl.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/02. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32921.237-32921.241.

8510080508 Provides info clarifying util 850612 ltr re availability of addl 125-volt dc emergency lighting in control room. Control room can be lighted by ac emergency diesel powered lighting sys. W/two oversize drawings.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/03. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 32920.043-32920.048.

8510080456 Forwards 851004 Rev 5 to security plan, updating license application & plan. Rev withheld (ref 10CFR73.21).
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/04. Record Services Branch (Document Control Desk). 1p. 32921.227-32921.227.

8510160000 Forwards Safety Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations noted. App contains two remaining emergency preparedness open items that need closing prior to fuel load.
SHAFFER, W.D. Region 3, Office of Director. 85/10/10. EDELMA, M.R. Cleveland Electric Illuminating Co. 3pp. 33023.237-33023.246.

8510170400 Responds to 850830 concerns re suggestion in author 850826 ltr to util that util should consider licensing facility control room design on preliminary design analysis, as opposed to DCRDR basis.
YOUNGBLOOD, B.J. Licensing Branch 1. 45/10/11. HIATT, S.L. Ohio Citizens for Responsible Energy. 4pp. 33045.169-33045.172.

8510220333 Forwards Suppl 1 to DCRDR summary rept, per 851002 commitment.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/14. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33086.053-33086.259.

-8510220336 Suppl 1 to DCRDR summary rept.
Cleveland Electric Illuminating Co. 85/10/14. 200pp. 33086.054-33086.259.

8510210216 Forwards status rept on remaining offsite emergency preparedness licensing conditions, per 850925 request. Conditions identified in ASLB 850903 concluding partial initial decision.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/15. JORDAN, E.J. Division of Emergency Preparedness & Engineering Response (Post 830103). 10pp. 33094.302-33094.311.

8510250422 Forwards request for exemption from Section IV.F.1 of App E to 10CFR50, requiring that full participation emergency preparedness exercise be conducted for plant within 1 yr before issuance of full power OL.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/17. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 33172.354-33172.357.

8510290340 Forwards revised Page 12 to Section 2.7, "Conclusions," to 851014 Suppl 1 to DCRDR summary rept. Section 2.6 separate task from DCRDR review & will be submitted in separate rept prior to receipt of full power OL.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/21. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 33234.334-33234.335.

8510250214 Forwards Rev 6 & Rev 5 pages to security plan, revising format to keep license application & security plan current. Rev 5 pages inadvertently omitted from 851004 submittal also encl. Encls withheld (ref 10CFR73.21).
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/22. Record Services Branch (Document Control Desk). 1p. 33169.137-33169.137.

8510280103 Forwards Preoperational Physical Security Insp Rept 50-440/85-65 on 850930-1004. No noncompliance noted.
AXELSON, W.L. Region 3, Office of Director. 85/10/22. EDELMA, M.R. Cleveland Electric Illuminating Co. 2pp. 33191.054-33191.057.

-8510280113 Preoperational Physical Security Insp Rept 50-440/85-65 on 850930-1004. No violation noted. Major areas inspected: status of implementation, installation, operability of security & testing program. Details withheld (ref 10CFR73.21).
KNICELEY, J.R., BELANGER, J.L., CREED, J.R. Region 3, Office of Director. 85/10/22. 2pp. 33191.056-33191.057.

G. Adjudicatory correspondence

8510040334 Response to applicant 850912 motion for clarification of partial initial decision re offsite emergency planning requirements. NRC has no objection to motion. Certificate of Svc encl.
WOODHEAD, C.P. Hearing Branch 4. #485 667. 85/10/02. Atomic Safety and Licensing Board Panel. 1pp. 32853.275-32853.282.

8510100014 Motion for enlargement of time until 851025 to file merit brief in pending app. J. Extension needed for addl research on emergency planning. Certificate of Svc encl.
LODGE, T.J. Sunflower Alliance. #485 707. 85/10/04. Atomic Safety and Licensing Appeal Panel. 3pp. 32961.178-32961.180.

8510100028 Memorandum & order clarifying ASLB 850903 concluding partial initial decision & Finding 55 re emergency kits. Kits should be made available at each reception area prior to issuance of low power license. Served on 851007.
GLEASON, J.P., BRIGHT, G.O., KLINE, J.R. Atomic Safety and Licensing Board Panel. #485 695. 85/10/04. 2pp. 32960.175-32960.176.

8510100145 Motion for extension until 851025 to file merit brief on appeal re emergency planning. Granted for ASLB on 851007.
LODGE, T.J. Sunflower Alliance. LODGE, T.J. Lodge, T.J. #485 676. 85/10/04. Atomic Safety and Licensing Appeal Panel. 1p. 32961.214-32961.214.

8510100029 Order extending time until 851015 for Commission to act to review Director's Decision DD-85-14. Served on 851008.
CHILK, S.J. Office of the Secretary of the Commission. #485 689. 85/10/07. Commissioners. 1p. 32960.033-32960.033.

8510110193 Withdrawal of 850916 notice of appeal from Concluding Partial Initial Decision LBP-85-35 re emergency planning.
SILBERG, J.E. Cleveland Electric Illuminating Co. SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. #485 750. 85/10/08. 4pp. 32972.341-32972.344.

8510150354 Answer opposing OCRE 850925 motion for stay pendente lite. Argument on issue 8 re hydrogen control does not constitute irreparable injury sufficient to justify stay of fuel loading.
SILBERG, J.E. Cleveland Electric Illuminating Co. SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. #485 760. 85/10/10. Atomic Safety and Licensing Appeal Panel. 10pp. 33010.107-33010.116.

-8510150359 Affidavit of LD Hamilton re assertion by intervenor that normal operation of facility will cause irreparable injury to OCRE due to exposure to routine radioactive emissions.
HAMILTON, L.D. Brookhaven National Laboratory. 85/10/09. 14pp. 33010.117-33010.130.

-8510150363 Affidavit of DA Hankins re risk to public health & safety of operation of Unit 1 before & after full operation.
HANKINS, D.A. General Electric Co. 85/10/07. 9pp. 33010.131-33010.139.

-8510150366 Affidavit of GR Leidich in response to OCRE motion for stay pendente lite re "no costs of downtime."
LEIDICH, G.R. Cleveland Electric Illuminating Co. 85/10/10. 6pp. 33010.140-33010.145.

-8510150368 Affidavit of MR Edelman summarizing util best estimates for achieving full power operation of Unit 1 & costs of delay. Certificate of Svc encl.
EDELMA, M.R. Cleveland Electric Illuminating Co. 85/10/09. 8pp. 33010.146-33010.153.

8510180351 Forwards original signature page to GR Leidich affidavit attached to applicant response to OCRE motion for stay pendente lite.
SWIGER, M.A. Shaw, Pittman, Potts & Trowbridge. SWIGER, M.A. Cleveland Electric Illuminating Co. #485 788. 85/10/11. Docketing & Services Branch. 2pp. 33061.288-33061.289.

8510180215 Forwards util 851011 ltr to HR Denton providing updated info on facility status & readiness for fuel loading & operation. Unit 1 may be ready to load fuel as early as 851108. Svc list encl. Related correspondence.
SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J.E. Cleveland Electric Illuminating Co. #485 795. 85/10/14. ROSENTHAL, S., JOHNSON, W.R., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 20pp. 33062.277-33062.296.

8510180150 Informs of Palladino 851029 site tour. One representative of each party will be permitted to join tour. Participant should notify PJ Polk or J Grobe & licensee re attendance by 851022.
POLK, P.J. NRC - No Detailed Affiliation Given. #485 786. 85/10/15. Atomic Safety and Licensing Board Panel. 1p. 33055.034-33055.034.

8510180156 extending time until 851025 for Commission to act to review Director's Decision DD-85-14. Served on 851016.
CHILK, S.J. Office of the Secretary of the Commission. #485 785. 85/10/15. Commissioners. 1p. 33055.047-33055.047.

8510220372 Motion to strike portions of applicant 851010 answer to motion for stay pendente lite on grounds of being improper & contrary to law. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. #485 858. 85/10/15. Atomic Safety and Licensing Appeal Panel. 10pp. 33086.341-33086.350.

8510210004 Informs that Commissioner Zech will tour facilities on 851113. If any party wishes to have single representative attend, notification must be made to JG Keppler by 851004. Served on 851013.
CLAUSEN, M.J. Commissioners. #485 835. 85/10/18. Office of the Executive Legal Director. 1p. 33074.127-33074.127.

8510240405 Appellate brief supporting appeal of ASLB decisions identified in 850919 notice of appeal re issues 8, 16 & 6 on hydrogen control, TDI diesel generators & ATWS/standby liquid control sys, respectively. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. #485 881. 85/10/21. Atomic Safety and Licensing Appeal Panel. 69pp. 33154.053-33154.121.

8510290009 Order denying Ohio Citizens for Responsible Energy 850925 application for stay pendente lite of ASLB 850903 partial initial decision (LBP-85-35) on emergency planning, hydrogen control & diesel generators. Served on 851025.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 932. 85/10/24. Ohio Citizens for Responsible Energy. 11pp. 33233.348-33233.358.

8510310306 Advises that time for Commission to review Director's Decision DD-85-14 expired. Commission declined review. Decision became final agency action on 851025. Served on 851028.
CHILK, S.J. Office of the Secretary of the Commission. #485 970. 85/10/28. HIATT, S.L. Ohio Citizens for Responsible Energy. 1p. 33271.313-33271.313.

8510310266 Motion for reversal of ASLB decisions & denial of OL. Applicants have not demonstrated that "reasonable assurance" of adequate protective measures exists. W/Certification of Svc.
 LODGE, T.J. Sunflower Alliance. LODGE, T.J. Lodge, T.J. #485 946. 85/10/30. Atomic Safety and Licensing Appeal Panel. 29pp. 33273-274-33273-302.

8510310272 Motion for leave to file brief on merits in appeal. Served on 851029. W/Certification of Svc.
 LODGE, T.J. Sunflower Alliance. #485 947. 85/10/30. Atomic Safety and Licensing Appeal Panel. 2pp. 33273-110-33273-111.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510090053 Forwards Amend 21 to FSAR for Perry Nuclear Power Plant, Units 1 & 2. Amend consists of miscellaneous changes to update FSAR & new App 8 entitled "License Commitments." Certificate of Svc also encl.
 EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33016-122-33019-361.

-8510090062 Amend 21 to FSAR for Perry Nuclear Power Plant, Units 1 & 2.
 * Cleveland Electric Illuminating Co. 8/39/30. 14,000pp. 33016-126-33019-361.

Q. Inspection reports, IE Bulletins & correspondence

8510020157 Forwards info on preparedness for licensing of plant in accordance w/IE Manual Chapter 94300. Items requiring insp & resolution before finding of readiness for operation can be endorsed encl.
 NORELIUS, C.E. Region 3, Office of Director. 85/09/20. THOMPSON, H.L. Division of Licensing. 53pp. 32827-216-32827-269.

8510080609 Forwards Insp Rept 50-440/85-54 on 850814-16. No violations noted.
 PAPERIELLO, C.J. Region 3, Office of Director. 85/09/27. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32927-083-32927-091.

-8510080610 Insp Rept 50-440/85-54 on 850814-16. No violations or deviations noted. Major areas inspected: allegations re electrical terminations & penetration seals.
 NEISLER, J.H., WILLIAMS, C.C. Region 3, Office of Director. 85/09/23. 8pp. 32927-085-32927-090.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070299 Forwards Safety Insp Rept 50-440/85-16 on 850318-0916 & notice of violation.
 HARRISON, J.J. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32875-344-32875-357.

-8510070301 Notice of violation from insp on 850318-0916.
 HARRISON, J.J. Region 3, Office of Director. 85/10/02. 1p. 32875-346-32875-346.

-8510070307 Safety Insp Rept 50-440/85-16 on 850318-0916. Violation noted: failure to control design of pipe supports.
 KAUFMAN, P.D., JACOBSON, J.M., DANIELSON, D.H. Region 3, Office of Director. 85/10/02. 11pp. 32875-347-32875-357.

8510080114 Ack receipt of 850906 ltr & scope & objectives for emergency plan exercise scheduled for 851120. Assembly, accountability & evacuation successfully demonstrated during insp on 850925 & not required for Nov exercise.
 SHAFER, W.D. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32920-248-32920-249.

8510080131 Forwards Safety Insp Rept 50-440/85-53 on 850803-0913 & notice of violation.
 PAPERIELLO, C.J. Region 3, Office of Director. 85/10/03. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32913-134-32913-156.

-8510080131 Notice of violation from insp on 850803-0913.
 PAPERIELLO, C.J. Region 3, Office of Director. 85/10/03. 2pp. 32913-136-32913-137.

-8510080140 Insp Rept 50-440/85-53 on 850803-0913. Violation noted: failure to provide adequate preoperational test procedures & failure to properly follow procedures re ECCS initiation reactor protection sys & feedwater leakage control.
 HILLS, D.E., O'DWYER, G.F., RING, M.A. Region 3, Office of Director. 85/10/02. 19pp. 32913-138-32913-156.

8510180018 Forwards Insp Repts 50-440/85-66 & 50-441/85-23 on 850909-13 & 16-20. No violations noted.
 WARNICK, R.F. Region 3, Office of Director. 85/10/04. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33068-319-33068-330.

-8510180019 Insp Repts 50-440/85-66 & 50-441/85-23 on 850909-13 & 16-20. No violations, deviations or safety significant issues noted. Major areas inspected: licensee actions on previous insp findings, IE bulletins & circulars.
 SCHEIBELHUT, C., KNOP, R.C. Region 3, Office of Director. 85/10/04. 10pp. 33068-321-33068-330.

8510170306 Forwards Safety Insp Rept 50-440/85-62 on 850918-20. No violations noted.
 HARRISON, J.J. Region 3, Office of Director. 85/10/07. EDELMAN, M.R. Commonwealth Edison Co. 2pp. 33051-292-33051-297.

-8510170309 Safety Insp Rept 50-440/85-62 on 850918-20. No violations or deviations noted. Major areas inspected: electric & instrument terminations, instrumentation cable installation & licensee action on previous insp findings.
 NEISLER, J.H., TANIK, F., WILLIAMS, C.C. Region 3, Office of Director. 85/10/07. 4pp. 33051-294-33051-297.

8510220005 Forwards Safety Insp Repts 50-440/85-58 & 50-441/85-21 on 850826-29. No noncompliance noted. Lack of progress toward full implementation of QA/QC program for lab & counting room noted.
 SHAFER, W.D. Region 3, Office of Director. 85/10/08. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33095-329-33095-338.

-8510220006 Insp Repts 50-440/85-58 & 50-441/85-21 on 850826-29, 0923 & 26. No violation or deviation noted. Major areas inspected: preoperational radiological environment monitoring program, including implementation & results.
 OESTMANN, M.J., HOLTZMAN, R.B., SCHUMACHER, M.C. Region 3, Office of Director. 85/10/07. 8pp. 33095-331-33095-338.

8510160232 Forwards Safety Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations noted. App contains two remaining emergency preparedness open items that need closing prior to fuel load.
 SHAFER, W.D. Region 3, Office of Director. 85/10/10. EDELMAN, M.R. Cleveland Electric Illuminating Co. 3pp. 33023-237-33023-246.

-8510160234 Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations or deviations noted. Major areas inspected: open items identified during Feb-Mar 1985 emergency preparedness implementation appraisal & insp. Two open items noted.
 SHELL, W.G., PATTERSON, J.P., WILLIAMS, N.R. Region 3, Office of Director. 85/10/10. 7pp. 33023-240-33023-246.

8510220012 Forwards Safety Insp Rept 50-440/85-64 on 850912-16. No violation noted.
 HARRISON, J.J. Region 3, Office of Director. 85/10/11. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33095-295-33095-299.

-8510220013 Insp Rept 50-440/85-64 on 850912-16. No violation or deviation noted. Major areas inspected: allegations re svc Level I coatings. Allegations unsubstantiated.
 NORTON, J.F., WILLIAMS, C.C. Region 3, Office of Director. 85/10/11. 3pp. 33095-297-33095-299.

8510220141 Submits final response to IE Bulletin 83-07 & Suppls 1 & 2 re apparently fraudulent products sold by Ray Miller, Inc. Investigation concluded that strainers do not contain any identified fraudulent matl.
 EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/14. KEPLER, J.G. Region 3, Office of Director. 2pp. 33090-087-33090-088.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510210081 Forwards Safety Insp Rept 50-440/85-56 on 850805-0923. No violation noted.
 WARNICK, R.F. Region 3, Office of Director. 85/10/17. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33072-154-33072-166.

-8510210091 Insp Rept 50-440/85-56 on 850805-0923. No violation noted. Major areas inspected: previous insp findings, potential significant const deficiencies, as-built sys walkdown & mgt meeting.
 KNOP, R.C. Region 3, Office of Director. 85/10/17. 11pp. 33072-156-33072-166.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510220238 Forwards Insp Repts 50-440/85-44 & 50-441/85-18 on 850726-0912. No violations noted.
 WARNICK, R.F. Region 3, Office of Director. 85/10/18. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33086-260-33086-266.

-8510220242 Insp Repts 50-440/85-44 & 50-441/85-18 on 850726-0912. No violations or safety concerns noted. Major areas inspected: structural as-built program, cable installations & testing & followup on three allegations.
 KNOP, R.C. Region 3, Office of Director. 85/10/18. 5pp. 33086-262-33086-266.

8510280040 Forwards Safety Insp Rept 50-440/85-67 on 851002-04. No violation noted.
 HARRISON, J.J. Region 3, Office of Director. 85/10/22. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33191-017-33191-022.

8510280103 Forwards Preoperational Physical Security Insp Rept 50-440/85-65 on 850930-1004. No noncompliance noted.
 AXELSON, W.L. Region 3, Office of Director. 85/10/22. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33191-054-33191-057.

-8510280113 Preoperational Physical Security Insp Rept 50-440/85-65 on 850930-1004. No violation noted. Major areas inspected: status of implementation, installation, operability of security & testing program. Details withheld (ref 10CFR73.21).
 KNICELEY, J.R., BELANGER, J.L., CREED, J.R. Region 3, Office of Director. 85/10/22. 2pp. 33191-056-33191-057.

8510280135 Forwards Safety Insp Rept 50-440/85-67 on 851002-04. No violations noted.
 HARRISON, J.J. Region 3, Office of Director. 85/10/22. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33191-003-33191-008.

-8510280142 Insp Rept 50-440/85-67 on 851002-04. No violations or deviations noted. Major areas inspected: licensee action on previous insp findings, const deficiency repts & instrumentation installation & records.
 NEISLER, J.H., WILLIAMS, C.C. Region 3, Office of Director. 85/10/32. 4pp. 33191-005-33191-008.

212 DOCKETED ITEMS

8510290330 Forwards Safety Insp Rept 50-440/85-61 on 850912-16. No violation noted. HARRISON, J.J. Region 3, Office of Director. 85/10/24. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33236:210-33236:219.

-8510290336 Insp Rept 50-440/85-61 on 850912-16. No violation or deviation noted. Major areas inspected: structural integrity test for drywell. NORTON, J.F., WILLIAMS, C.C. Region 3, Office of Director. 85/10/24. 8pp. 33236:212-33236:219.

S. Reportable occurrences, LERs & related correspondence

8510010478 Final Deficiency Rept [RDC 136(85)] re lack of seismic analysis on backwash assembly internals. Initially reported on 850508. Strainers seismically qualified. Condition not reportable per 10CFR50.55(e). EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/19. KEPLER, J.G. Region 3, Office of Director. 2pp. 32809:146-32809:147.

8510080019 Final Deficiency Rept [RDC 123(85)] re design defects associated w/ drywell overpressurization. Initially reported on 841213. Evaluation indicates drywell area will not be overstressed. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. KEPLER, J.G. Region 3, Office of Director. 3pp. 32927:340-32927:342.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510100009 Part 21 & final Deficiency Rept [RDC 134(85)] re potential flooding vols in turbine bldg due to circulating water sys expansion joint failure. Initially reported on 850426. Design Change Packages 85-0386 & 85-0391 issued & FSAR changed. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/03. KEPLER, J.G. Region 3, Office of Director. 3pp. 32961:002-32961:004.

8510220381 Final Deficiency Rept 243 & [RDC 139(85)] re violations of seismic support spacing criteria for tubing supports in balance-of-plant areas. Initially reported on 850711. Complete design review of all installation packages conducted. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/09. KEPLER, J.G. Region 3, Office of Director. 3pp. 33095:093-33095:095.

8510300129 Final Deficiency Rept [RDC 143(85)] re failure to provide divisional separation requirements for neutron monitoring sys. per Reg Guide 1.75. Initially reported on 850710. Condition not reportable per 10CFR50.55(e). EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/17. KEPLER, J.G. Region 3, Office of Director. 2pp. 33257:169-33257:170.

851010269 Part 21 & Final Deficiency Rept [RDC 135(85)] re load capabilities of Basic Engineers BE-419 pipe clamps. Initially reported on 850430. Clamps in use identified & reworked. Clamps in stock now on hold. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/22. KEPLER, J.G. Region 3, Office of Director. 3pp. 33292:065-33292:067.

8510310550 Final Potential Deficiency Rept [RDC 144(85)] re shop welds in containment penetration assemblies mfg by Tube Turns, Inc. Initially reported on 850731. Item not reportable per 10CFR50.55(e). EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/22. KEPLER, J.G. Region 3, Office of Director. 5pp. 33280:014-33280:018.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510070348 Forwards further clarification of response to NRC request for addl info re 850625 licensed operator requalification program. Program approval anticipated. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32877:252-32877:254.

8510250464 Responds to Generic Ltr 85-18 re scheduling of operator licensing exams. Projected needs through FY89 encl. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/21. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 33172:246-33172:248.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510180082 Forwards response to 850808 & 14 ltrs re radwaste solidification sys. Responses incorporated into Rev 3 of process control program. Proprietary NUS Process Svcs Repts FO-013 & SS-001 withheld (ref 10CFR2.790(b)(1)). EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/08/30. YOUNGBLOOD, B.J. Licensing Branch 1. 8pp. 33056:206-33056:318.

-8510180115 Rev 3 to Operations Manual OM12E-PCP, "Process Control Program." KENSICHI, S.F. Cleveland Electric Illuminating Co. 85/08/26. 21pp. 33056:216-33056:236.

-8510180118 Rev 3 to Operations Manual PAP-1309, "Shipment of Radwaste for Disposal." SHATMAN, R., WAHATH, B.D., SHUSTER, C.M. Cleveland Electric Illuminating Co. 85/08/05. 81pp. 33056:237-33056:318.

8510010038 Provides final update of equipment qualification issues for closing out Outstanding Issue 4. All equipment within scope of 10CFR50.49 qualified & all active safety-related pumps & valves qualified for operability. Test list encl. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/23. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32801:278-32801:280.

8510010465 Responds to 850529 comments re proposed resolution of TMI Action Plan Item III.D.1.1. Reactor water cleanup sys provided w/connections to post-accident sampling sys for monitoring cleanup operations. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32809:050-32809:051.

8510010374 Responds to 850716 request for confirmation from each Licensee Review Group II member to implement proposed solution for Generic Issue 9-R5B, on long-term operability of deep draft pumps. Endorses solution. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/27. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 32801:232-32801:232.

8510030003 Forwards description of procedures & programs which implement required review process for compliance w/10CFR50.59, including enhancements of existing programs & proposed changes to draft Tech Specs. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 12pp. 32842:213-32842:224.

8510080477 Forwards ltr authorizing microfiche encl NUS proprietary info re process control program for radwaste solidification, procedure change requests & revs to process control programs. Proprietary info withheld. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32922:166-32922:167.

8510070356 Confirms 851011 meeting at site to discuss status of items required for fuel load. per 851001 discussion. NOELIUS, C.E. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 1p. 32875:035-32875:035.

8510080399 Advises that traversing in-core probe piping & subsystem noted on FSAR Table 3.2-1 should have been NSC Quality Group D, per 850826 request to revise safety classification. Change will be noted in next FSAR amend. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32919:302-32919:303.

8510160210 Responds to Containment Sys Branch comments re facility Tech Specs. Valves to be water tested are at elevations below suppression pool & capable of maintaining water seal for at least 30 days following LOCA. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/09. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33021:086-33021:086.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8507160361 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' for Perry Nuclear Power Plant..." Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1522. 85/07/10. NRC - No Detailed Affiliation Given. 14pp. 33044:028-33044:041.

8512250175 Documents commitment to provide rep. describing methods used to establish setpoints & allowable values for reactor protection sys & ESF trip functions assumed to operate in FSAR Chapters 6 & 15 analysis per 840723 & 1009 ltrs. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/17. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 33172:146-33172:147.

8510290011 Forwards proposed changes to FSAR Chapter 14 re startup testing program. Changes will be included in next FSAR amend. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/23. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 33233:292-33233:346.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510010077 Forwards addl info, clarifying util 820902, 830126, 840125 & 850624 submittals re Mark III containment sys issues. per SER Outstanding Issue 8. Commitment to provide further info will be reflected in FSAR amend, if necessary. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32801:292-32801:294.

8510010276 Provides info to clearly define cabinet/panel fire detection arrangement & to distinguish between cabinet/panel bay & console terminology. Info provided to support SER preparation. Figure encl. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32800:244-32800:247.

8510160029 Provides further confirmation re previous submittals on SER Outstand. Issues 8 & 9 concerning Mark III Containment Sys (Humphrey issues) & LOCA-related pool dynamic loads. Reevaluation of 10 components completed & design sufficient. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/08. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33026:337-33026:337.

F. Security, medical, emergency & fire protection plans

8510010276 Provides info to clearly define cabinet/panel fire detection arrangement & to distinguish between cabinet/panel bay & console terminology. Info provided to support SER preparation. Figure encl. EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/26. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 32800:244-32800:247.

8510030067 Forwards Rev 3 to security force training & qualification plan. per 850806 & 0923 discussions. Rev withheld (ref 10CFR73.21). EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/27. Office of Nuclear Reactor Regulation, Director. 1p. 32843:011-32843:011.

8510040474 Revised "OH State Plan for Response to Radiation Emergencies at Licensed Nuclear Facilities." W/851001 ltr. LOCKHART, R.M. Ohio, State of. 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 415pp. 32851:240-32852:286.

8510080114 Ack receipt of 850906 ltr & scope & objectives for emergency plan exercise scheduled for 851120. Assembly, accountability & evacuation successfully demonstrated during insp on 850925 & not required for Nov exercise.
SHAFFER, W.D. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32920:248-32920:249.

8510080446 Forwards schedule for closure of all remaining open DCRDR activities, per 850910-13 site audit. Human engineering deficiencies requiring revised responses identified in encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/02. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 32921:237-32921:241.

8510080508 Provides info clarifying util 850812 ltr re availability of addl 125-volt dc emergency lighting in control room. Control room can be lighted by ac emergency diesel powered lighting sys. W/two oversize drawings.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/03. YOUNGBLOOD, B.J. Licensing Branch 1. 6pp. 32920:043-32920:048.

8510080454 Forwards 851004 Rev 5 to security plan, updating license application & plan. Rev withheld (ref 10CFR73.21).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. Record Services Branch (Document Control Desk). 1p. 32921:227-32921:227.

8510160232 Forwards Safety Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations noted. App contains two remaining emergency preparedness open items that need closing prior to fuel load.
SHAFFER, W.D. Region 3, Office of Director. 85/10/10. EDELMAN, M.R. Cleveland Electric Illuminating Co. 3pp. 33023:237-33023:246.

8510160234 Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations or deviations noted. Major areas inspected: open items identified during Feb-Mar 1985 emergency preparedness implementation appraisal & insp. Two open items noted.
SHELL, W.G., PATTERSON, J.P., WILLIAMS, N.R. Region 3, Office of Director. 85/10/10. 7pp. 33023:240-33023:246.

8510220333 Forwards Suppl 1 to DCRDR summary rept, per 851002 commitment.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/14. YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 33086:053-33086:259.

8510220336 Suppl 1 to DCRDR summary rept.
* Cleveland Electric Illuminating Co. 85/10/14. 200pp. 33086:054-33086:259.

8510210216 Forwards status rept on remaining offsite emergency preparedness licensing conditions, per 850925 request. Conditions identified in ASLB 850903 concluding partial initial decision.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/15. JORDAN, E.J. Division of Emergency Preparedness & Engineering Response (Post 850103). 10pp. 33094:302-33094:311.

8510250422 Forwards request for exemption from Section IV.F.1 of App E to 10CFR50, requiring that full participation emergency preparedness exercise be conducted for plant within 1 yr before issuance of full power OL.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/17. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 33172:354-33172:357.

8510290340 Forwards revised Page 12 to Section 2.7, "Conclusions," to 851014 Suppl 1 to DCRDR summary rept. Section 2.6 separate task from DCRDR review & will be submitted in separate rept prior to receipt of full power OL.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/21. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 33234:334-33234:335.

8510250214 Forwards Rev 6 & Rev 5 pages to security plan, revising format to keep license application & security plan current. Rev 5 pages inadvertently omitted from 851004 submittal also encl. Encls withheld (ref 10CFR73.21).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/22. Record Services Branch (Document Control Desk). 1p. 33169:137-33169:137.

G. Adjudicatory correspondence

8510040334 Response to applicant 850912 motion for clarification of partial initial decision re offsite emergency planning requirements. NRC has no objection to motion. Certificate of Svc encl.
WOODHEAD, C.P. Hearing Branch 4. #485 667. 85/10/02. Atomic Safety and Licensing Board Panel. 6pp. 32853:275-32853:282.

8510100014 Motion for enlargement of time until 851025 to file merit brief in pending appeal. Extension needed for addl research on emergency planning. Certificate of Svc encl.
LODGE, T.J. Sunflower Alliance. #485 707. 85/10/04. Atomic Safety and Licensing Appeal Panel. 3pp. 32961:178-32961:180.

8510101028 Memorandum & order clarifying ASLB 850903 concluding partial initial decision & Findings 55 re emergency kits. Kits should be made available at each reception area prior to issuance of low power license. Served on 851007.
GLEASON, J., BRIGHT, G.O., KLINE, J.R. Atomic Safety and Licensing Board Panel. #485 695. 85/10/04. 2pp. 32960:175-32960:176.

8510100145 Motion for extension until 851025 to file merit brief on appeal re emergency planning. Granted for ASLB on 851007.
LODGE, T.J. Sunflower Alliance. LODGE, T.J. Lodge, T.J. #485 676. 85/10/04. Atomic Safety and Licensing Appeal Panel. 1p. 32961:214-32961:214.

8510100029 Order extending time until 851015 for Commission to act to review Director's Decision DD-85-14. Served on 851008.
CHILK, S.J. Office of the Secretary of the Commission. #485 689. 85/10/07. Commissioners. 1p. 32960:03G-32960:033.

8510110193 Withdrawal of 850916 notice of appeal from Concluding Partial Initial Decision LBP-85-35 re emergency planning.
SILBERG, J.E. Cleveland Electric Illuminating Co. SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. #485 750. 85/10/08. 4pp. 32972:341-32972:344.

8510150354 Answer opposing OCRE 850925 motion for stay pendente lite. Argument on issue 8 re hydrogen control does not constitute irreparable injury sufficient to justify stay of fuel loading.
SILBERG, J.E. Cleveland Electric Illuminating Co. SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. #485 760. 85/10/10. Atomic Safety and Licensing Appeal Panel. 10pp. 33010:107-33010:116.

8510150359 Affidavit of LD Hamilton re assertion by intervenor that normal operation of facility will cause irreparable injury to OCRE due to exposure to routine radioactive emissions.
HAMILTON, L.D. Brookhaven National Laboratory. 85/10/09. 14pp. 33010:117-33010:130.

8510150363 Affidavit of DA Hankins re risk to public health & safety of operation of Unit 1 before & after full operation.
HANKINS, D.A. General Electric Co. 85/10/07. 9pp. 33010:131-33010:139.

8510150366 Affidavit of GR Leidich in response to OCRE motion for stay pendente lite re "no costs of downtime."
LEIDICH, G.R. Cleveland Electric Illuminating Co. 85/10/10. 6pp. 33010:140-33010:145.

8510150368 Affidavit of MR Edelman summarizing util best estimates for achieving full power operation of Unit 1 & costs of delay. Certificate of Svc encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/09. 8pp. 33010:146-33010:153.

8510180351 Forwards original signature page to GR Leidich affidavit attached to applicant response to OCRE motion for stay pendente lite.
SWIGER, M.A. Shaw, Pittman, Potts & Trowbridge. SWIGER, M.A. Cleveland Electric Illuminating Co. #485 788. 85/10/11. Docketing & Services Branch. 2pp. 33061:288-33061:289.

8510180215 Forwards util 851011 ltr to HR Denton providing updated info on facility status & readiness for fuel loading & operation. Unit 1 may be ready to load fuel as early as 851108. Svc list encl. Related correspondence.
SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J.E. Cleveland Electric Illuminating Co. #485 795. 85/10/14. ROSENTHAL, S., JOHNSON, W.R., WILBER, H.A. Atomic Safety and Licensing Appeal Panel. 20pp. 33062:277-33062:296.

8510180150 Informs of Palladino 851029 site tour. One representative of each party will be permitted to join tour. Participant should notify PJ Polk or J Grobe & licensee re attendance by 851022.
POLK, P.J. NRC - No Detailed Affiliation Given. #485 786. 85/10/15. Atomic Safety and Licensing Board Panel. 1p. 33055:034-33055:034.

8510180156 Order extending time until 851025 for Commission to act to review Director's Decision DD-85-14. Served on 851016.
CHILK, S.J. Office of the Secretary of the Commission. #485 785. 85/10/15. Commissioners. 1p. 33055:047-33055:047.

8510220372 Motion to strike portions of applicant 851010 answer to motion for stay pendente lite on grounds of being improper & contrary to law. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. #485 858. 85/10/15. Atomic Safety and Licensing Appeal Panel. 10pp. 33086:341-33086:350.

8510210004 Informs that Commissioner Zech will tour facilities on 851113. If any party wishes to have single representative attend, notification must be made to JG Keppler by 851004. Served on 851018.
CLAUSEN, M.J. Commissioners. #485 835. 85/10/18. Office of the Executive Legal Director. 1p. 33074:127-33074:127.

8510240405 Appellate brief supporting appeal of ASLB decisions identified in 850919 notice of appeal re issues 8, 16 & 6 on hydrogen control, TDI diesel generators & ATWS/standby liquid control sys, respectively. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. #485 881. 85/10/21. Atomic Safety and Licensing Appeal Panel. 69pp. 33154:053-33154:121.

8510290009 Order denying Ohio Citizens for Responsible Energy 850925 application for stay pendente lite of ASLB 850903 partial initial decision (LBP-85-35) on emergency planning, hydrogen control & diesel generators. Served on 851025.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #485 932. 85/10/24. Ohio Citizens for Responsible Energy. 11pp. 33233:348-33233:358.

8510310266 Motion for reversal of ASLB decisions & denial of OL. Applicants have not demonstrated that "reasonable assurance" of adequate protective measures exists. W/Certification of Svc.
LODGE, T.J. Sunflower Alliance. LODGE, T.J. Lodge, T.J. #485 940. 85/10/30. Atomic Safety and Licensing Appeal Panel. 29pp. 33273:274-33273:302.

8510310272 Motion for leave to file brief on merits in appeal instanter. Served on 851029. W/Certification of Svc.
LODGE, T.J. Sunflower Alliance. #485 947. 85/10/30. Atomic Safety and Licensing Appeal Panel. 2pp. 33273:110-33273:111.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510090053 Forwards Amend 21 to FSAR for Perry Nuclear Power Plant, Units 1 & 2. Amend consists of miscellaneous changes to update FSAR & new App B entitled "License Commitments." Certificate of Svc also encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33016:122-33016:136.

8510090062 Amend 21 to FSAR for Perry Nuclear Power Plant, Units 1 & 2.
* Cleveland Electric Illuminating Co. 85/09/30. 14,000pp. 33016:126-33016:361.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 35-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 05/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/11. Consolidated Edison Co. of New York, Inc. 135pp.

214 DOCKETED ITEMS

8510080114 Ack receipt of 850906 ltr & scope & objectives for emergency plan exercise scheduled for 851120. Assembly, accountability & evacuation successfully demonstrated during insp on 850925 & not required for Nov exercise.
SHAFFER, W.D. Region 3, Office of Director. 85/10/02. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32920:248-32920:249.

8510180018 Forwards Insp Repts 50-440/85-66 & 50-441/85-23 on 850909-13 & 16-20. No violations noted.
WARNICK, R.F. Region 3, Office of Director. 85/10/04. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33068:319-33068:330.

-8510180019 Insp Repts 50-440/85-66 & 50-441/85-23 on 850909-13 & 16-20. No violations, deviations or safety significant issues noted. Major areas inspected: licensee actions on previous insp findings, IE bulletins & circulars.
SCHEIBELHUT, C., KNOP, R.C. Region 3, Office of Director. 85/10/04. 10pp. 33068:321-33068:330.

8510220005 Forwards Safety Insp Repts 50-440/85-58 & 50-441/85-21 on 850826-29. No noncompliance noted. Lack of progress toward full implementation of QA/QC program for lab & counting room noted.
SHAFFER, W.D. Region 3, Office of Director. 85/10/08. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33095:329-33095:338.

-8510220006 Insp Repts 50-440/85-58 & 50-441/85-21 on 850826-29, 0923 & 26. No violation or deviation noted. Major areas inspected: preoperational radiological environment monitoring program, including implementation & results.
OESTMANN, M.J., HOLTZMAN, R.B., SCHUMACHER, M.C. Region 3, Office of Director. 85/10/07. 8pp. 33095:331-33095:338.

8510160232 Forwards Safety Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations noted. App contains two remaining emergency preparedness open items that need closing prior to fuel load.
SHAFFER, W.D. Region 3, Office of Director. 85/10/10. EDELMAN, M.R. Cleveland Electric Illuminating Co. 3pp. 33023:237-33023:246.

-8510160234 Insp Repts 50-440/85-60 & 50-441/85-22 on 850924-26. No violations or deviations noted. Major areas inspected: open items identified during Feb-Mar 1985 emergency preparedness implementation appraisal & insp. Two open items noted.
SHELL, W.G., PATTERSON, J.P., WILLIAMSEN, N.R. Region 3, Office of Director. 85/10/10. 7pp. 33023:240-33023:246.

8510220141 Submits final response to IE Bulletin 83-07 & Suppls 1 & 2 re apparently fraudulent products sold by Ray Miller, Inc. Investigation concluded that strainers do not contain any identified fraudulent matl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/14. KEPLER, J.G. Region 3, Office of Director. 2pp. 33090:087-33090:088.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-061, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510220238 Forwards Insp Repts 50-440/85-44 & 50-441/85-18 on 850726-0912. No violations noted.
WARNICK, R.F. Region 3, Office of Director. 85/10/18. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 33086:260-33086:266.

-8510220242 Insp Repts 50-440/85-44 & 50-441/85-18 on 850726-0912. No violations or safety concerns noted. Major areas inspected: structural as-built program, cable installations & testing & followup on three allegations.
KNOP, R.C. Region 3, Office of Director. 85/10/18. 5pp. 33086:262-33086:266.

S. Reportable occurrences, LERs & related correspondence

8510010478 Final Deficiency Rept [RDC 136(85)] re lack of seismic analysis on backwash assembly internals initially reported on 850508. Strainers seismically qualified. Condition not reportable per 10CFR50.55(e).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/19. KEPLER, J.G. Region 3, Office of Director. 2pp. 32809:146-32809:147.

8510080019 Final Deficiency Rept [RDC 123(85)] re design defects associated w/ drywell overpressurization initially reported on 841213. Evaluation indicates drywell area will not be overstressed.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/24. KEPLER, J.G. Region 3, Office of Director. 3pp. 32927:340-32927:342.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAF, J.W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510100009 Part 21 & final Deficiency Rept [RDC 134(85)] re potential flooding voids in turbine bldg due to circulating water sys expansion joint failure initially reported on 850426. Design Change Packages 85-0386 & 85-0391 issued & FSAR changed.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/03. KEPLER, J.G. Region 3, Office of Director. 3pp. 32961:002-32961:004.

8510220381 Final Deficiency Rept 243 & [RDC 139(85)] re violations of seismic support spacing criteria for tubing supports in balance-of-plant areas initially reported on 850711. Complete design review of all installation packages conducted.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/09. KEPLER, J.G. Region 3, Office of Director. 3pp. 33095:093-33095:095.

8510300129 Final Deficiency Rept [RDC 143(85)] re failure to provide divisional separation requirements for neutron monitoring sys. per Reg Guide 1.75. Initially reported on 850710. Condition not reportable per 10CFR50.55(e).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/17. KEPLER, J.G. Region 3, Office of Director. 2pp. 33257:169-33257:170.

8510310269 Part 21 & final Deficiency Rept [RDC 135(85)] re load capabilities of Basic Engineers BE-419 pipe clamps initially reported on 850430. Clamps in use identified & reworked. Clamps in stock now on hold.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/22. KEPLER, J.G. Region 3, Office of Director. 3pp. 33292:065-33292:067.

8510310550 Final Potential Deficiency Rept [RDC 144(85)] re shop welds in containment penetration assemblies mfg by Tube Turns, Inc. Initially reported on 850731. Item not reportable per 10CFR50.55(e).
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/22. KEPLER, J.G. Region 3, Office of Director. 5pp. 33280:014-33280:018.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510070348 Forwards further clarification of response to NRC request for add info re 850625 licensed operator requalification program. Program approval anticipated.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 32877:252-32877:254.

8510250464 Responds to Generic Ltr 85-18 re scheduling of operator licensing exams. Projected needs through FY89 encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 85/10/21. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 33172:246-33172:248.

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510150088 Notification of 850927 meeting w/util in Seabrook, NH to review current plant completion schedule, const status & licensing open items.
NERSES, V. Licensing Branch 3. 85/09/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33030:266-33030:269.

8510150047 Informs that incorporation of 1983 Edition through Winter 1983 Addenda of Section III, Div 1 of ASME Boiler & Pressure Vessel Code, per 850830 ltr, acceptable.
KNIGHTON, G. Licensing Branch 3. 85/09/24. HARRISON, R.J. Public Service Co. of New Hampshire. 3pp. 33031:293-33031:295.

8510090165 Notification of Licensee Meeting 85-99 on 851002 w/util, United Engineers & Constructors, Inc & Bechtel in King of Prussia, PA to discuss cable tray design & testing.
CERNE, J.C. Region 1, Office of Director. 85/10/01. Region 1, Office of Director. 1p. 32950:358-32950:358.

8510150121 Forwards new FSAR Section 1.9 & marked-up FSAR pages re compliance w/NUREG-0737, "Clarification of TMI Action Plan Requirements." Exception taken to item II.F.1, "Noble Gas Effluent Monitor."
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 86pp. 33007:031-33008:116.

8510150293 Addresses concerns re Mechanical Engineering Branch Request for Addl info 210.89, "Evaluations of Teas or Branch Connections in Class 1 Piping." Info discussed on 850930 ensures requirements incorporated into Class 1 stress repts.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33009:101-33009:105.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170211 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities ...' technical evaluation repts."
Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/15:5-8. 85/10/11. NRC. No Detailed Affiliation Given. 14pp. 33044:201-33044:214.

8510250001 Forwards lists of balance-of-plant & NSSS equipment selected for audit by Pump & Valve Operability Team & SQRT. Util should provide completed long forms by 851025 for audit scheduled on 851104-08.
KNIGHTON, G.W. Licensing Branch 3. 85/10/15. HARRISON, R.J. Public Service Co. of New Hampshire. 7pp. 33226:264-33226:270.

8510210062 Forwards Rev 1 to "Seismic & Dynamic Qualification Summary & Status of Safety-Related Equipment," facility sys turnover status, NSSS valve number correlation & pump listing per 850807 meeting re SQRT/PVORT site audit.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 28pp. 33091:232-33093:024.

-8510210068 Rev 1 to "Seismic & Dynamic Qualification Summary & Status of Safety-Related Equipment."
Public Service Co. of New Hampshire. 85/09/27. 250pp. 33091:261-33093:046.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, "Post-Trip Review Program Description & Procedure" for Bellefonte Nuclear Plant...
* Science Applications International Corp. (formerly Science Applications, Inc.) NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510300257 Notification of 851104-09 meetings w/utl in Seabrook, NH to review seismic qualification of safety-related equipment & operability qualification of pumps & valves.
NERSES, V. Licensing Branch 3. 85/10/23. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33259-349-33259-352.

8510310338 Forwards technical evaluation rept re utl response to Generic Ltr 83-28, "Required Action Based on Generic Implications of Salem ATWS Events."
KNIGHTON, G.W. Licensing Branch 3. 85/10/23. HARRISON, R.J. Public Service Co. of New Hampshire. 3pp. 33278-132-33278-148.

8510300138 Forwards long forms for Pump & Valve Operability Review Team & SORT site audit of balance of plant & NSSS supplied equipment, per 851015 request. W/15 oversize drawings. Six proprietary drawings withheld (ref 10CFR2.790).
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/10/25. KNIGHTON, G.W. Licensing Branch 3. 700pp. 33268-022-33270-134.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510030080 Forwards responses to unresolved Matls Engineering Branch issues re SER (NUREG-0896) Sections 4.5.1, 4.5.2, 5.2.3 & 6.1.1. Nine issues require NRC evaluation & action. Status list of active branch review items also encl.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32842-250-32842-256.

8510290027 Forwards Section 13 of SSER 3, documenting NRC review of operating procedures based on Rev 1 to Westinghouse emergency response guidelines, per 851021 results of preliminary review. Related correspondence.
PERLIS, R.G. Hearing Branch 3. #485 914. 85/10/24. WOLFE, S.J., HARBOUR, J., LUEBKE, E.A. Atomic Safety and Licensing Board Panel. 5pp. 33235-133-33235-137.

F. Security, medical, emergency & fire protection plans

8510090460 Summary of 850627 meeting w/utl in Bethesda, MD re compliance w/App R, Section III.G requirements on fire protection of safe shutdown capability. Licensee App R rept should be finished by end of 1985.
NERSES, V. Licensing Branch 3. 85/10/02. Licensing Branch 3. 5pp. 32966-216-32966-220.

8510240204 Forwards listed documents re onsite emergency planning & safety issues in response to Board 851004 order. Responses to specific questions raised by Board re environ qualification of equipment also provided. Related correspondence.
PERLIS, R.G. Hearing Branch 3. #485 884. 85/10/21. WOLFE, S.J., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 50pp. 33154-307-33155-027.

G. Adjudicatory correspondence

8510100031 Order directing staff to inform ASLB by 851021 whether listed documents submitted by applicant for evaluation & to provide submissions & evaluation to ASLB & interested parties. Served on 851004.
LUEBKE, E.A., HARBOUR, J., WOLFE, S.J. Atomic Safety and Licensing Board Panel. #485 704. 85/10/04. Office of the Executive Legal Director. 3pp. 32961-076-32961-078.

8510100016 Order instructing that submissions reflect differentiation between works onsite emergency planning & safety issues, inserted under docket numbers. Served on 851007.
WOLFE, S.J. Atomic Safety and Licensing Board Panel. #485 693. 85/10/07. Office of the Executive Legal Director. 1p. 32960-362-32960-362.

8510100138 Order to place "Offsite Emergency Planning Issues" underneath docket numbers to distinguish from onsite emergency planning & safety issue submissions. Served on 851008.
HOYT, H.F. Atomic Safety and Licensing Board Panel. #485 677. 85/10/07. Office of the Executive Legal Director. 1p. 32960-089-32960-089.

8510240204 Forwards listed documents re onsite emergency planning & safety issues in response to Board 851004 order. Responses to specific questions raised by Board re environ qualification of equipment also provided. Related correspondence.
PERLIS, R.G. Hearing Branch 3. #485 884. 85/10/21. WOLFE, S.J., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 50pp. 33154-307-33155-027.

8510290027 Forwards Section 13 of SSER 3, documenting NRC review of operating procedures based on Rev 1 to Westinghouse emergency response guidelines, per 851021 results of preliminary review. Related correspondence.
PERLIS, R.G. Hearing Branch 3. #485 914. 85/10/24. WOLFE, S.J., HARBOUR, J., LUEBKE, E.A. Atomic Safety and Licensing Board Panel. 5pp. 33235-133-33235-137.

Q. Inspection reports, IE Bulletins & correspondence

8510010188 FOIA request for 11 categories of documents re Insp Repts 50-443/84-12 & 50-444/84-06.
GROSSBERG, S. Harmon, Weiss & Jordan. 85/08/08. FELTON, J.M. Division of Rules and Records. 5pp. 32833-064-32833-068.

8510010177 Forwards Safety Insp Rept 50-443/85-9 on 850715-26. No violations observed.
EBNETER, S.D. Region 1, Office of Director. 85/09/09. HARRISON, R.J. Public Service Co. of New Hampshire. 2pp. 32802-194-32802-21.

-8510010185 Insp Rept 50-443/85-19 on 850701-26. No violations noted. Major areas inspected: safety-related piping, structural & support weldments fabricated to ASME Code, Section III, Classes 1-3 & AWS Code D1.1 requirements.
KERCH, H.W., HARRIS, R.H., CAMPBELL, R.M. Region 1, Office of Director. 85/09/03. 24pp. 32802-196-32802-219.

8510010502 Forwards Safety Insp Rept 50-443/85-20 on 850708-0827 & notice of violation. Concerns over administrative, engineering & const controls which allowed incomplete & incorrect work to be installed remain.
COLLINS, S.J. Region 1, Office of Director. 85/09/18. HARRISON, R.J. Public Service Co. of New Hampshire. 2pp. 32820-217-32820-239.

-8510010503 Notice of violation from insp on 850708-0827.
* Region 1, Office of Director. 85/09/18. 2pp. 32820-219-32820-220.

-8510010505 Insp Rept 50-443/85-20 on 850708-0827. Violations noted: lack of design change clarity, resulting in installation of matl & welds in conflict w/engineering intent & in failure to apply required QA controls.
CERNE, A.C., GALLO, R.M. Region 1, Office of Director. 85/09/12. 19pp. 32820-221-32820-239.

8510010197 Final response to FOIA requests for 11 categories of documents re Insp Repts 50-443/84-12 & 50-444/84-06. Forwards documents listed on App B. Document 2 on app withheld (ref FOIA Exemption 6).
FELTON, J.M. Division of Rules and Records. 85/09/20. GROSSBERG, S. Harmon, Weiss & Jordan. 2pp. 32833-069-32833-071.

-8510010200 Telcon w/J Assestine on 850809 re facility allegations.
* NRC - No Detailed Affiliation Given. 84/08/09. 1p. 32833-071-32833-071.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080392 Forwards Const Team Insp Rept 50-443/85-15 on 850603-14 & notice of violation.
EBNETER, S.D. Region 1, Office of Director. 85/10/03. HARRISON, R.J. Public Service Co. of New Hampshire. 2pp. 32919-145-32919-146.

-8510080395 Notice of violation from insp on 850603-14.
* Region 1, Office of Director. 85/10/03. 6pp. 32919-147-32919-152.

-8510080401 Const Team Insp Rept 50-443/85-15 on 850603-14. Violations noted: seismic installation of instrument tubes crossing seismic boundary not translated into spec & control of quality-related activities inadequate.
EAPEN, P.K., CERNE, A.C., CHEUNG, L.S. Region 1, Office of Director. 85/09/13. 81pp. 32919-153-32919-233.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510230095 Ack receipt of 850531 ltr informing NRC of steps taken to correct FSAR deviations noted in Insp Rept 50-443/85-06.
EBNETER, S.D. Region 1, Office of Director. 85/10/15. HARRISON, R.J. Public Service Co. of New Hampshire. 2pp. 33102-204-33102-209.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250489 Responds to NRC 850918 ltr re violations noted in Insp Rept 50-443/85-20. Corrective actions, design calculations revised by Westinghouse & acceptability of as-constructed condition confirmed.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/10/18. COLLINS, S.J. Region 1, Office of Director. 7pp. 33173-091-33173-097.

S. Reportable occurrences, LERs & related correspondence

8510080022 Interim Deficiency Rept (CDR 85-00-12) re error in section of GT STRUDL program that calculates frequencies using Rayleigh Quotient Method. Initially reported on 850812. Next rept will be submitted by 851115.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/16. STAROSTECKI, J. Region 1, Office of Director. 3p. 32927-337-32927-339.

8510100050 Interim Deficiency Rept CDR-85-00-13 re failure of svc water sys spool linings, piping inserts & valve liner/seals. Initially reported on 850820. Investigation & repairs underway. Next rept expected by 860115.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/18. STAROSTECKI, J. Region 1, Office of Director. 3pp. 32960-233-32960-235.

8510150223 Final Deficiency Rept CDR-85-00-08 re use of improper & mixed incompatible greases in fan motor bearings. Initially reported on 850611. Review of preventive maint prog, as performed to ensure correct spec of grease.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/30. STAROSTECKI, J. Region 1, Office of Director. 2pp. 33015-040-33015-041.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
GRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

216 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510150088 Notification of 850927 meeting w/util in Seabrook,NH to review current plant completion schedule,const status & licensing open items.
NERSES,V. Licensing Branch 3. 85/09/17. KNIGHTON,G.W. Licensing Branch 3. 4pp. 33030-266-33030-269.

8510150047 Informs that incorporation of 1983 Edition through Winter 1983 Addenda of Section III,Div 1 of ASME Boiler & Pressure Vessel Code,per 850830 ltr,acceptable.
KNIGHTON,G. Licensing Branch 3. 85/09/24. HARRISON,R.J. Public Service Co. of New Hampshire. 3pp. 33031-293-33031-295.

8510150121 Forwards new FSAR Section 1.9 & marked-up FSAR pages re compliance w/NUREG-0737, "Clarification of TMI Action Plan Requirements." Exception taken to Item II.F.1, "Noble Gas Effluent Monitor."
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/10/10. KNIGHTON,G.W. Licensing Branch 3. 86pp. 33007-031-33008-116.

8510150293 Addresses concerns re Mechanical Engineering Branch Request for Addl Info 210.89, "Evaluations of Tees or Branch Connections in Class 1 Piping." Info discussed on 850930 ensures requirements incorporated into Class 1 stress repts.
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/10/10. KNIGHTON,G.W. Licensing Branch 3. 5pp. 33009-101-33009-105.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28,Item 1.2 re Salem ATWS events.Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

8510170211 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review:Data & Info Capabilities'..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-8. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044-201-33044-214.

8510250001 Forwards lists of balance-of-plant & NSSS equipment selected for audit by Pump & Valve Operability Team & SORT. Util should provide completed long forms by 851025 for audit scheduled on 851104-08.
KNIGHTON,G.W. Licensing Branch 3. 85/10/15. HARRISON,R.J. Public Service Co. of New Hampshire. 7pp. 33226-264-33226-270.

8510210062 Forwards Rev 1 to "Seismic & Dynamic Qualification Summary & Status of Safety-Related Equipment," facility sys turnover status,NSSS valve number correlation & pump listing,per 850807 meeting re SORT/PORT site audit.
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/10/17. KNIGHTON,G.W. Licensing Branch 3. 28pp. 33091-232-33093-024.

8510210068 Rev 1 to "Seismic & Dynamic Qualification Summary & Status of Safety-Related Equipment."
* Public Service Co. of New Hampshire. 85/09/27. 250pp. 33091-261-33093-046.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28,Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSAME,E.G. Licensing Branch 4. 85/10/22. FOSTER,D.O. Georgia Power Co. 1p. 33262-231-33262-231.

8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.1, 'Post-Trip Review:Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510300257 Notification of 851104-09 meetings w/util in Seabrook,NH to review seismic qualification of safety-related equipment & operability qualification of pumps & valves.
NERSES,V. Licensing Branch 3. 85/10/23. KNIGHTON,G.W. Licensing Branch 3. 4pp. 33259-349-33259-352.

8510310338 Forwards technical evaluation rept re util response to Generic Ltr 83-28, "Required Action Based on Generic Implications of Salem ATWS Events."
KNIGHTON,G.W. Licensing Branch 3. 85/10/23. HARRISON,R.J. Public Service Co. of New Hampshire. 3pp. 33278-132-33278-148.

8510300138 Forwards long forms for Pump & Valve Operability Review Team & SORT site audit of balance of plant & NSSS supplied equipment,per 851015 request,W/15 oversize drawings.Six proprietary drawings withheld (ref 10CFR2.790).
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/10/25. KNIGHTON,G.W. Licensing Branch 3. 700pp. 33268-022-33270-134.

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8510030080 Forwards responses to unresolved Mads Engineering Branch issues re SER (NUREG-0896) Sections 4.5.1,4.5.2,5.2.3 & 6.1.1.Nine issues require NRC evaluation & action.Status list of active branch review items also encl.
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/09/30. KNIGHTON,G.W. Licensing Branch 3. 7pp. 32842-250-32842-256.

8510290027 Forwards Section 13 of SSER 3,documenting NRC review of operating procedures based on Rev 1 to Westinghouse emergency response guidelines,per 851021 results of preliminary review.Related correspondence.
PERLIS,R.G. Hearing Branch 3. #485 914. 85/10/24. WOLFE,S.J. Atomic Safety and Licensing Board Panel. 5pp. 33235-133-33235-137.

F. Security, medical, emergency & fire protection plans

8510090460 Summary of 850627 meeting w/util in Bethesda,MD re compliance w/App R,Section III.G requirements on fire protection of safe shutdown capability.Licensee App R rept should be finished by end of 1985.
NERSES,V. Licensing Branch 3. 85/10/02. Licensing Branch 3. 5pp. 32966-216-32966-220.

8510240204 Forwards listed documents re onsite emergency planning & safety issues in response to Board 851004 order.Responses to specific questions raised by Board re environ qualification of equipment also provided.Related correspondence.
PERLIS,R.G. Hearing Branch 3. #485 884. 85/10/21. WOLFE,S.J. Atomic Safety and Licensing Board Panel. 50pp. 33154-307-33155-027.

G. Adjudicatory correspondence

8510100031 Order directing staff to inform ASLB by 851021 whether listed documents submitted by applicant for evaluation & to provide submissions & evaluation to ASLB & interested parties.Served on 851004.
LUEBKE,E.A. HARBOUR,J. WOLFE,S.J. Atomic Safety and Licensing Board Panel. #485 704. 85/10/04. Office of the Executive Legal Director. 3pp. 32961-076-32961-078.

8510100016 Order instructing that submissions reflect differentiation between words onsite emergency planning & safety issues, inserted under docket numbers Served on 851007.
WOLFE,S.J. Atomic Safety and Licensing Board Panel. #485 693. 85/10/07. Office of the Executive Legal Director. 1p. 32960-362-32960-362.

8510100138 Order to place "Offsite Emergency Planning Issues" underneath docket numbers to distinguish from onsite emergency planning & safety issue submissions.Served on 851008.
HOYT,H.F. Atomic Safety and Licensing Board Panel. #485 677. 85/10/07. Office of the Executive Legal Director. 1p. 32960-089-32960-089.

8510240204 Forwards listed documents re onsite emergency planning & safety issues in response to Board 851004 order.Responses to specific questions raised by Board re environ qualification of equipment also provided.Related correspondence.
PERLIS,R.G. Hearing Branch 3. #485 884. 85/10/21. WOLFE,S.J. LUEBKE,E.A. HARBOUR,J. Atomic Safety and Licensing Board Panel. 50pp. 33154-307-33155-027.

8510290027 Forwards Section 13 of SSER 3,documenting NRC review of operating procedures based on Rev 1 to Westinghouse emergency response guidelines,per 851021 results of preliminary review.Related correspondence.
PERLIS,R.G. Hearing Branch 3. #485 914. 85/10/24. WOLFE,S.J. HARBOUR,J. LUEBKE,E.A. Atomic Safety and Licensing Board Panel. 5pp. 33235-133-33235-137.

Q. Inspection reports, IE Bulletins & correspondence

8510010188 FOIA request for 11 categories of documents re insp Repts 50-443/84-12 & 50-444/84-06.
GROSSBERG,S. Harmon, Weiss & Jordan. 85/08/08. FELTON,J.M. Division of Rules and Records. 5pp. 32833-064-32833-068.

8510010197 Final response to FOIA requests for 11 categories of documents re insp Repts 50-443/84-12 & 50-444/84-06.Forwards documents listed on App B,Document 2 on app withheld (ref FOIA Exemption 6).
FELTON,J.M. Division of Rules and Records. 85/09/20. GROSSBERG,S. Harmon, Weiss & Jordan. 2pp. 32833-069-32833-071.

8510010200 Telcon w/J Assestine on 850809 re facility allegations.
* NRC - No Detailed Affiliation Given. 94/08/09. 1p. 32833-071-32833-071.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint,Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Clars,Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

S. Reportable occurrences, LERs & related correspondence

8510080022 Interim Deficiency Rept (CDR 85-00-12) re error in section of GT STRUDL program that calculates frequencies using Rayleigh Quotient Method.Initially reported on 850812.Next rept will be submitted by 851115.
DEVINCENTIS,J. Public Service Co. of New Hampshire. 85/09/16. STAROSTEC, Region 1, Office of Director. 3pp. 32927-337-32927-339.

8510100050 Interim Deficiency Rept CDR-85-00-13 re failure of svc water sys spool linings, piping inserts & valve liner/seats. Initially reported on 850820. Investigation & repairs underway. Next rept expected by 860115.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/18. STAROSTECKI, R. Region 1, Office of Director. 3pp. 32960:233-32960:235.

8510150223 Final Deficiency Rept CDR-85-00-08 re use of improper & mixed incompatible greases in fan motor bearings. Initially reported on 850611. Review of preventive maint procedures performed to ensure correct spec of grease.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 85/09/30. STAROSTECKI, R. Region 1, Office of Director. 2pp. 33015:040-33015:041.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850916 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030:243-33030:265.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510250346 FOIA request for info re QA rept prepared by Comanche Peak Technical Review Team.
GARDE, B.P. Government Accountability Project. 85/01/09. Office of Administration. 2pp. 33191:346-33191:350.

8510150436 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 840109.
GARDE, B.P. Government Accountability Project. 85/01/11. Office of Administration. 2pp. 33110:001-33110:002.

8510150440 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850111.
GARDE, B.P. Government Accountability Project. 85/01/14. Office of Administration. 2pp. 33110:003-33110:004.

8510150443 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850114.
GARDE, B.P. Government Accountability Project. 85/01/15. Office of Administration. 2pp. 33110:005-33110:006.

8510150446 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850117.
GARDE, B.P. Government Accountability Project. 85/01/18. Office of Administration. 2pp. 33110:007-33110:008.

8510150447 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850118.
GARDE, B.P. Government Accountability Project. 85/01/21. Office of Administration. 2pp. 33110:009-33110:012.

8510030399 Notification of contract execution, Mod 1, to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs.
HAWKINS, D. Technical Assistance Contracts Branch. FIN D-1338. 85/09/09. THOMPSON, H.L. Division of Licensing. TRAMMELL, C. NRC - No Detailed Affiliation Given. 1p. 32848:075-32848:076.

-8510030404 Mod 1, extending period of performance to 850920, to "Review & Evaluation of Comanche Peak Program Plan."
MOONAN, V.S. Teledyne Engineering Services. EDGEWORTH, P.J. Division of Contracts. FIN D-1338. 85/09/09. 1p. 32848:076-32848:076.

8510170302 Forwards ASLB documents transmitted to CYGNA per 850913 ltr to util re independent assessment program, in response to 850916 request.
WILLIAMS, N.H. CYGNA Energy Services. 85/09/16. ELLIS, J. Citizens Association for Sound Energy. 47pp. 33039:234-33039:280.

8510010080 Notification of contract execution, Mod 2, to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs.
HAWKINS, D.A. Technical Assistance Contracts Branch. FIN D-1338. 85/09/24. THOMPSON, H. Division of Licensing. TRAMMELL, C. NRC - No Detailed Affiliation Given. 1p. 32833:315-32833:319.

-8510010092 Mod 2, revising statement of work to include Task D, to "Review & Evaluation of Comanche Peak Program Plan."
MOONAN, V.S. Teledyne Engineering Services. EDGEWORTH, P.J. Technical Assistance Contracts Branch. FIN D-1338. 85/09/24. 4pp. 32833:316-32833:319.

8510010059 Clarifies 850605 ltr re use of ASME Code Cases N-397 & N-411. Ltr gave generic approval provided listed items (a) through (f) implemented. Response to whether CP amend needed requested.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/25. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32833:167-32833:171.

8510030252 Notification of 851002 & 03 meetings w/util in Granbury, TX to discuss basis for establishing homogeneous hardware populations for const adequacy review & S&W piping & pipe support walkdowns.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/09/27. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 8pp. 32849:107-32849:114.

8510030214 Forwards request for addl info re revs made to FSAR by Amends 54 & 55. Info needed re revised commitment to Reg Guide 1.44 (Amend 54) & suction pipe & debris screen added to containment ventilation sys (Amend 55).
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32849:192-32849:196.

8510070494 Forwards Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns."
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 6pp. 32901:296-32902:036.

-8510070496 Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns."
* Comanche Peak Project (Technical Review Team). 85/09/30. 93pp. 32901:304-32902:036.

8510170108 Partial response to FOIA request for records re NRC determination of potential matl false statement on U-bolt sample (Board Notification 85-077), issued on 850820. Forwards App A document. Search for addl documents continuing.
FELTON, J.M. Division of Rules and Records. 85/10/01. GARDE, B.P. Government Accountability Project. 2pp. 33050:294-33050:296.

-8510170111 Forwards applicant motion for reconsideration of ASLB 841218 order re matl false statements on torquing of U-bolts. W/o encl.
MIZUNO, G. Hearing Branch 1. 84/01/08. NOONAN, V. Comanche Peak Project (Technical Review Team). 1p. 33050:296-33050:296.

8510030122 Board Notification 85-087 forwards VS Noonan 850930 ltr to util & Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns," per Commission 840706 revised notification policy.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/05. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 2pp. 32966:360-32967:098.

8510150449 First partial response to FOIA request for documentation re NRC overview, regulation & investigation of facility. Forwards records re protective coating issues. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. GARDE, B.P. Government Accountability Project. 2pp. 33110:013-33110:043.

-8510150451 Rev 7 to CPM 13.1, "General Calibr Procedure."
FRANKUM, D.C. Brown & Root, Inc. (subs. of Halliburton Co.). 81/12/09. 22pp. 33110:035-33110:043.

-8510150454 Package consisting of insp repts, calibr records & repts & Responses 3,5 & 10 to RL Bangart 840523 ltr re BNL interim rept on protective coatings.
* Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/04. 9,000pp. 33118:001-33120:362.

8510170250 Requests info from Gibbs & Hill in order to close out open issues re pipe stress analysis reviews. Encl communications rept documents initial questions asked on 851018.
WILLIAMS, N.H. CYGNA Energy Services. 85/10/09. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33040:064-33040:066.

8510180414 Further response to FOIA request for documents re NRC 840629 meeting w/util concerning investigation on illegal use of drugs at facility. Addl documents not found. Search complete.
FELTON, J.M. Division of Rules and Records. 85/10/10. GARDE, B.P. Government Accountability Project. 1p. 33077:124-33077:126.

8510210022 Forwards documents re expansion bolt data base & cable tray & conduit raceway seismic test program, in response to 851008 telcon request on independent assessment program - Phase 4.
WILLIAMS, N.H. CYGNA Energy Services. 85/10/10. PALMER, S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33072:041-33072:042.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:257.

-8510170159 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), item 1.2, 'Post-Trip Review Data & Info Capabilities ...,' technical evaluation rept."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-3. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:013-33044:027.

8510180394 Further response to FOIA request for documents re NRC review of EG&G rept on facility App B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. MILLAR, B. Fort Worth Star-Telegram, Fort Worth, TX. 3pp. 33077:346-33077:349.

8510170479 Expresses appreciation for 850815 comments on Comanche Peak Response Team program plan. Review of plan will be complete following applicant response to all NRC concerns.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/12. GARDE, B.P. Trial Lawyers for Public Justice, P.C. 1pp. 33048:143-33048:143.

-8510170480 Responds to CASE 850815 comments re Comanche Peak Response Team program plan. NRC will re-review plan following applicant response to all concerns. Meeting w/CASE to discuss findings suggested.
EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/10/12. GARDE, B.P. Trial Lawyers for Public Justice, P.C. 2pp. 33048:144-33048:148.

8510220110 Advises that implementation of ATWS mitigating sys actuation circuitry (AMSAC) per Generic Ltr 85-06, scheduled for 861201, based on NRC approval of WCAP-10858, "AMSAC Generic Design Package."
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/14. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 1p. 33090:150-33090:150.

8510210035 Forwards list of Phase 4 mechanical sys review questions & open items. Response requested.
WILLIAMS, N.H. CYGNA Energy Services. 85/10/16. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33072:043-33072:046.

218 DOCKETED ITEMS

8510210076 Forwards list of Independent Assessment Program Phase 4 electrical questions & open items, including requests for info re diesel generator short-circuit contribution & offsite grid voltage variations.
WILLIAMS, N.H. CYGNA Energy Services. 85/10/16. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 7pp. 33072-318-33072-323.

8510220125 Further response to FOIA request for documents re EG&G rept on harassment & intimidation. Forwards App B documents. Documents also available in PDR Portions of App C Documents 1-4 withheld (ref FOIA Exemptions 4 & 6).
FELTON, J.M. Division of Rules and Records. 85/10/16. GARDE, B. Government Accountability Project. 4pp. 33099-325-33100-110.

85102100470 Provides clarification on NRC position re intimidation at facility. Overall task EG&G contracted to perform defined. EG&G rept will be used as input to NRC assessment.
EISENHUT, D.G. Division of Licensing. 84/12/04. HAYES, B.B. Office of Investigation. 1p. 33100-111-33100-111.

8510220137 Forwards statements of work for FINs A-6819 (Project 2), A-6821 (Project 2) & A-0802 re evaluation of selected open NRC items at plant for review & comment.
DONOHEW, J. Division of Licensing. FIN A-6819. 84/06/15. KALTMAN, M. Planning & Program Analysis Staff. 1p. 33099-331-33099-331.

8510220154 Forwards std order for DOE work, supporting "Evaluation of Selected NRC Open Items Before Plant Fuel Load." FIN A-6819, Project 2. Proposal requested within 14 days.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/02. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 15pp. 33099-333-33099-347.

8510220161 Approves CM Rice & W Stratton as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load." FIN A-6819, Project 2, per LP Leach 840717 request.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/18. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 2pp. 33099-348-33099-349.

8510220171 Forwards project descriptive summary for FIN A-6819, "Evaluation of Selected NRC Open Items Before Plant Fuel Load (Program 1)," statement of work & NRC Form 173, for review & approval.
FUNCHES, J.L. Planning & Program Analysis Staff. FIN A-6819. 84/07/13. BECKWITH, C.A. Office of Resource Management, Director. 12pp. 33099-350-33099-362.

8510220178 Draft "Investigation & Assessment of Work Climate at Comanche Peak Electric Station."
KAPLAN, B.L., MARGUILES, N., RICE, C.M. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6429-4. 84/08/31. NRC - No Detailed Affiliation Given. 45pp. 33100-001-33100-045.

8510220202 Forwards, for concurrence, std order for DOE work, changing statement of work for "Evaluation of Selected NRC Open Items Before Plant Fuel Load." (FIN A-6819, Project 2).
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/08/24. SIMS, F.L. Energy, Dept. of. 4pp. 33100-047-33100-050.

8510220208 Forwards INEL planned staffing for Cycle 4 Comanche Peak Technical Review Team. Planned staffing for Cycle 5 will be identified as soon as possible.
WILLIAMS, M.H. Division of Licensing. 84/09/06. IPPOLITO, T.A. Comanche Peak Project (Technical Review Team). 2pp. 33100-051-33100-052.

8510220215 Forwards, for concurrence, std order for DOE work, "Evaluation of Selected NRC Open Items Before Plant Fuel Load." FIN A-6819, INEL proposal dtd Sept 1984 acceptable LP Leach 850905 & 20 ltrs to DOE encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/09/13. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 9pp. 33100-053-33100-061.

8510220225 Approves DG Bowers & H Margules as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load." FIN A-6819, Project 2, per INEL 840727 request. Related documentation encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/31. SIMS, F.L. Energy, Dept. of. 49pp. 33100-062-33100-110.

8510220239 Forwards project & budget proposals for NRC work for Rev 1 to, "Evaluation of Selected NRC Open Items Before Plant Fuel Load." & "Evaluation of Selected Open NRC Activities at Near-Term OL Sites Needing Action."
MILLAM, S.B. Energy, Dept. of, Idaho Operations Office. FIN A-6821. 84/08/23. WILLIAMS, M. Division of Licensing. 1p. 33100-112-33100-112.

8510220252 Rev 1 to project & budget proposal for NRC work: "Evaluation of Selected NRC Open Items Before Plant Fuel Load."
OBENCHAIN, C.F., NALEZNY, C.L. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6819. 85/08/15. DONOHEW, J.N. Office of Nuclear Reactor Regulation, Director. 9pp. 33100-113-33100-121.

8510250336 Responds to FOIA request for QA rept prepared by Comanche Peak Technical Review Team. Records listed on App A available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/16. GARDE, B.P. Government Accountability Project. 1p. 33191-345-33191-345.

8510240588 Grants request to withhold CAW-85-057, "Improved Thermal Design Procedures," per 850830 application, 761202 affidavit & 850905 ltr providing responses to questions on procedures per 10CFR2.790.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/17. WISEMANN, R.A. Westinghouse Electric Corp. 4pp. 33185-215-33185-218.

E. NRC Safety Evaluation Report (SER), suppl's & correspondence

85100300340 Board Notification 85-084 notifies of ACRS review of SSERs 7-11 during ACRS 30th meeting on 850912-14. NRC taking appropriate actions. DA Ward 850916 memo encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. PALLADINO, ROBERTS, ASSELTINE Commissioners. 2pp. 32853-269-32853-271.

8510040263 Forwards deferred MSIV preoperational test status rept. Initial deferred test status deficiencies reported per listed ltrs. Deferrals granted in SSER 6. Change in status result of Unit 2 heatup from Oct 1984 to Jan 1985.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 8pp. 32851-181-32851-188.

8510150239 Notification of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
COOK, A.V. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33032-217-33032-221.

8510150307 Requests transcript of 851023 public meeting between NRC & CASE in Bethesda, MD re issuance of SSERs 7-11 concerning operation.
RUSHBROOK, M.M. Licensing Branch 1. 85/10/09. WILDER, P. Atomic Safety and Licensing Board Panel. 1p. 33032-308-33032-308.

8510170337 Notification of cancellation of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 4pp. 33043-348-33043-351.

8510310003 Forwards SSER 12 (NUREG-0797) Resolution of outstanding issues re fire protection program, including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33277-103-33277-107.

F. Security, medical, emergency & fire protection plans

8510080123 Forwards FEMA finding & determination verifying State of TX & local emergency preparedness plans adequate to protect public health & can be implemented offsite per NUREG-0654. Public alert & notification sys adequate.
DENISE, R.P. Region 4, Office of Director. 85/10/03. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32914-326-32915-182.

8510220455 Forwards Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violations or deviations noted.
DENISE, R.P. Region 4, Office of Director. 85/10/11. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33096-224-33096-231.

8510220458 Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violation or deviation noted. Major areas inspected: previous emergency preparedness appraisal One App A item closed & 35 App B items closed.
TERC, N.M., BAIRD, J.B., WESTERMANT, T.F. Region 4, Office of Director. 85/08/19. 6pp. 33096-226-33096-231.

8510300005 Forwards revised emergency plan procedures, including Rev 3 to EPP-309 re offsite radiological monitoring, Rev 5 to EPP-310 re onsite & in-plant radiological surveys & Rev 5 to EPP-101 W/o stated encls.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/24. Record Services Branch (Document Control Desk). 1p. 33247-004-33247-032.

8510300011 Revised emergency plan procedures, including Rev 29 to emergency plan manual index & Rev 4 to EPP-204 re activation of technical support ctr & technical support ctr personnel duties.
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. 28pp. 33247-005-33247-032.

8510300051 Forwards list of training & drills conducted for offsite agencies over past 2 yrs, per 850919 request for exemption from regulations concerning emergency preparedness exercises.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/24. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 3pp. 33249-215-33249-217.

8510310003 Forwards SSER 12 (NUREG-0797) Resolution of outstanding issues re fire protection program, including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33277-103-33277-107.

G. Adjudicatory correspondence

8510030145 Motion for mod of ASLB 850829 memorandum re proposal for governance of case Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 643. 85/09/25. Atomic Safety and Licensing Board Panel. 4pp. 32824-323-32824-326.

8510020268 Memorandum supporting motion for mod of ASLB 850829 memorandum proposing governance of case Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 644. 85/09/25. Atomic Safety and Licensing Board Panel. 13pp. 32824-235-32824-247.

8510030034 Forwards Insp Repts 50-445/85-03 & 50-446/85-02 issued on 850917. Related correspondence.
MIZUNO, G.S. Hearing Branch 1. #485 656. 85/09/26. BLOCH, P.B., GROSSMAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 18pp. 32845-094-32845-111.

8510030024 Grants extension until 851004 for all parties to respond to ASLB 850918 memorandum re water recirculation problems caused by plant, per 850926 telcon w/ P.B. Bloch Related correspondence.
BACHMANN, R.G. Hearing Branch 1. #485 657. 85/09/27. BLOCH, P.B., JOHNSON, E.B., MCCOLLUM, K.A. Atomic Safety and Licensing Board Panel. 1p. 32842-329-32842-329.

8510040358 Notice that 851002 memorandum & order re applicant motion for mod should not be interpreted to deny any portion of intervenor motion for reconsideration of NRC 850829 memorandum & order. Served on 851002.
BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 671. 85/10/02. 1p. 32853-272-32853-272.

8510040449 Memorandum & order granting, in part, applicant 850925 motion for mod of 850829 order independence of Comanche Peak Review Team affects weight of evidence, not whether evidence would be received. Served on 851002.
BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 672. 85/10/02. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32853-340-32853-344.

8510100185 Confirms 850923 conversation re scheduling of depositions in Docket 2. Requests response within 7 days suggesting schedule for depositions of Wells, Spence & Brittain. Related correspondence.
GARDE, B.P. Trial Lawyers for Public Justice, P.C. #485 715. 85/10/02. WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Sampels). 3pp. 32962-109-32962-111.

8510100057 Confirms that all parties granted further extension of time until 851011 to file motions re ASLB 850918 memorandum concerning water recirculation problems caused by paint. per 851003 telcon w/ PB Bloch.
BACHMANN, R.G. Hearing Branch 1. #485 680. 85/10/03. BLOCH, P.B., JOHNSON, E.B., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 1p. 32960-085-32960-085.

8510160219 Forwards RP Lessy notice of appearance in proceeding. Certificate of Svc encl.
WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Sampels). #485 770. 85/10/08. Docketing & Services Branch. 5pp. 33022-243-33022-247.

8510160224 Forwards RP Lessy notice of appearance in proceeding. Certificate of Svc encl.
WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Sampels). #485 771. 85/10/08. Docketing & Services Branch. 5pp. 33022-233-33022-237.

8510110228 Response to CASE 850904 request for production of documents & motion for protective order. Applicant objects to requests for all documents as unduly broad to allow appropriate response. Certificate of Svc encl. Related correspondence.
REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 751. 85/10/09. Atomic Safety and Licensing Board Panel. 38pp. 32974-133-32974-170.

8510110238 Motion requesting ASLB reconsider & modify 850918 memorandum to reflect fact that uti not placed in special category for coatings inside containment, per SSER 9 (NUREG-0797) & consider notification of USI A-43 closed.
BACHMANN, R.G. Hearing Branch 1. #485 741. 85/10/09. Atomic Safety and Licensing Board Panel. 6pp. 32971-235-32971-252.

-8510110279 Affidavit of CE McCracken providing further explanation of background of SSER 9, App L per ASLB 850918 memorandum.
MCCRACKEN, C.E. Division of Engineering. 85/09/09. 7pp. 32971-241-32971-247.

-8510110241 Affidavit of AW Serkiz providing explanation re SSER 9, App L per ASLB 850918 memorandum. Certificate of Svc encl.
SERKIZ, A.W. Generic Issues Branch. 85/09/09. 5pp. 32971-248-32971-252.

8510150355 Response opposing CASE 850904 request for production of documents & motion for protective order re request concerning mgt qualifications & organization. Certificate of Svc encl. Related correspondence.
REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. #485 759. 85/10/09. Atomic Safety and Licensing Board Panel. 38pp. 33010-069-33010-106.

8510180346 Objects to 851002 comments & conclusions re CASE 850904 request for production of documents. Depositions should be requested formally. Prehearing conference for oral argument on unresolved issues will be sought. Related correspondence.
WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Sampels). #485 824. 85/10/14. GARDE, B.P. Trial Lawyers for Public Justice, P.C. 2pp. 33062-020-33062-021.

8510180232 Response opposing CASE 850925 motion for reconsideration of Board 850829 memorandum & order (proposal for governance of CASE) &/or motion for protective order. Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 806. 85/10/15. Atomic Safety and Licensing Board Panel. 17pp. 33061-234-33061-250.

8510180255 Forwards uti response to CASE motion for reconsideration of Board 850829 memorandum & order (proposal for governance of CASE) &/or motion for protective order, per Commission rules & regulations. W/o encl. Related correspondence.
DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 807. 85/10/15. Office of the Secretary of the Commission. 1p. 33061-127-33061-127.

8510180341 Response opposing CASE 850925 motion for reconsideration of ASLB 850829 memorandum & order &/or protective order re applicant & CASE summary disposition motions on pipe support design & design QA. Certificate of Svc encl.
MIZUNO, G.S. Hearing Branch 1. #485 790. 85/10/15. Atomic Safety and Licensing Board Panel. 12pp. 33062-005-33062-016.

8510220293 Application for issuance of encl subpoenas duces tecum for NRC witnesses V. Noonan, T. Ippolito, H. Livermore, J. Calvo, L. Shao, C. McCracken & R. Bangert. Depositions requested to be scheduled for 851029-31. Related correspondence.
ROISMAN, A.Z. Citizens Association for Sound Energy. ROISMAN, A.Z. Trial Lawyers for Public Justice, P.C. #485 862. 85/10/18. Atomic Safety and Licensing Board Panel. 30pp. 33083-298-33083-327.

8510240371 Petition for directed certification of ASLB 851002 order denying applicant motion for mod of ASLB 850829 rejection of 850628 mgt plan. Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 885. 85/10/21. 17pp. 33154-199-33154-246.

8510290004 Informs that applicants have filed answers to interrogatories served by CASE on 850827. Proposals for organizing access to applicant mats w/o need of formal discovery. No action necessary on protective order motions.
GAD, R.K. Ropes & Gray. #485 933. 85/10/21. BLOCH, P.B., MCCOLLOM, K.A., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 2pp. 33233-251-33233-252.

8510280518 Response to CASE 850827 interrogatories to applicants & requests to produce & request for protective order. Certificate of Svc encl. Related correspondence.

TYLER, T.G. Comanche Peak Project (Technical Review Team). DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 943. 85/10/22. Citizens Association for Sound Energy. 72pp. 33227-225-33227-296.

8510240677 Order requiring that NRC response to applicant 851002 petition for directed certification of licensing board be submitted by 851106. Served on 851024.
TOMPKINS, B.A. Atomic Safety and Licensing Appeal Panel. #485 886. 85/10/23. Office of the Executive Legal Director. 1p. 33161-030-33161-030.

8510290016 Forwards joir stipulation of staff & CASE (request for subpoenas) for ASLB approval.
TREBY, S.A. Hearing Branch 1. #485 942. 85/10/23. BLOCH, P.B., MCCOLLOM, K.A., JOHNSON, E.B. Atomic Safety and Licensing Board Panel. 1p. 33235-145-33235-147.

-8510290022 Joint stipulation to confirm agreement reached re CASE request for subpoenas. CASE agreed to withdraw request. Staff will produce documents requested in subpoenas.
TREBY, S.A. Hearing Branch 1. ROISMAN, A.Z. Citizens Association for Sound Energy. 85/10/23. 2pp. 33235-146-33235-147.

8510290032 Brief in response to ASLB 851015 telcon ordering parties to respond to statement concerning CASE good faith effort to coordinate discovery activities & uti provision of more specific responses to discovery. W/Certificate of Svc.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 915. 85/10/23. Atomic Safety and Licensing Board Panel. 7pp. 33235-152-33235-158.

8510290258 Forwards uti brief in response to 851015 conference call. W/o encl. Related correspondence.
DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 910. 85/10/23. Office of the Secretary of the Commission. 1p. 33233-347-33233-347.

8510290003 Discusses NRC 851009 response to ASLB 850918 memorandum re water recirculation problems caused by paint. Motion for reconsideration of listed point c & e & motion that listed point two considered resolved supported.
REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 911. 85/10/24. BLOCH, P.B., JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 3pp. 33232-360-33232-361.

8510280514 Advises of intent to file representativeness of U-bolt support configurations employed in tests & corrections to uti affidavits supporting motions for summary disposition re piping & support design.
REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 929. 85/10/25. BLOCH, P.B., JOHNSON, E.B., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 2pp. 33227-309-33227-310.

8510310200 Response to ASLB questions raised during 851015 telcon re statement concerning discovery as applied to two dockets & prehearing conference recommendations. Certificate of Svc encl.
BACHMANN, R.G. Hearing Branch 1. #485 975. 85/10/25. Commissioners. 13pp. 33273-077-33273-089.

8510280520 Response to ASLB request to address good faith effort to coordinate discovery activities & for applicant to provide more specific responses to discovery. Certificate of Svc encl. Related correspondence.
ELLIS, J. Citizens Association for Sound Energy. #485 918. 85/10/26. Atomic Safety and Licensing Board Panel. 112pp. 33227-113-33227-224.

8510310275 Response to ASLB questions re relevant dockets & discovery effort raised during 851015 conference call. Attempts to coordinate discovery efforts in two dockets made when possible. W/Certificate of Svc. Related correspondence.
ROISMAN, A.Z. Citizens Association for Sound Energy. ROISMAN, A.Z. Trial Lawyers for Public Justice, P.C. #485 958. 85/10/28. Atomic Safety and Licensing Board Panel. 20pp. 33272-135-33272-154.

8510310316 Memorandum & order granting CASE 850805 motion to reconsider 850722 order re Mgt Analysis Co rept & denying CASE 850814 motion for equipment to be preserved. Served on 851029.
BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 981. 85/10/29. Citizens Association for Sound Energy. 11pp. 33272-263-33272-273.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510170183 Amend 56 to FSAR for Comanche Peak Steam Electric Station.
COUNSIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 150pp. 33037-266-33038-096.

8510180159 Forwards table providing revised description of Amend 56 to FSAR.
COUNSIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/15. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33058-260-33058-264.

Q. Inspection reports, IE Bulletins & correspondence

8510150436 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 840109.
GARDE, B.P. Government Accountability Project. 85/01/11. Office of Administration. 2pp. 33110-001-33110-002.

8510150440 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850111.
GARDE, B.P. Government Accountability Project. 85/01/14. Office of Administration. 2pp. 33110-003-33110-004.

220 DOCKETED ITEMS

- 8510150443** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850114.
GARDE, B.P. Government Accountability Project. 85/01/15. Office of Administration. 2pp. 33110-005-33110-006.
- 8510150446** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850117.
GARDE, B.P. Government Accountability Project. 85/01/18. Office of Administration. 2pp. 33110-007-33110-008.
- 8510150447** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850118.
GARDE, B.P. Government Accountability Project. 85/01/21. Office of Administration. 2pp. 33110-009-33110-012.
- 8510080194** Ack receipt of 840817 & 1105 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 50-445/84-21. Violation 8421-01 closed in Insp Rept 50-445/84-36 & Violation 8421-02 closed in Insp Rept 50-445/84-45.
DENISE, R.P. Region 4, Office of Director. 85/09/01. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32920-260-32920-270.
- 8510080199** Responds to NRC 841011 request for addl info re violations noted in Insp Rept 50-445/84-21. Corrective actions: Startup Administrative Procedure CP-SAP-7 revised to provide instructions for instrumentation filling & venting.
CLEMENTS, B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 84/11/05. BANGART, R.L. Region 4, Office of Director. 4pp. 32920-267-32920-270.
- 8510080474** Ack receipt of 850419 ltr noting corrective actions re const appraisal team ins findings associated w/HVAC subcontractor. Bahnsen Co. More frequent Bahnsen site activities supported. Performance will be monitored.
DENISE, R.P. Region 4, Office of Director. 85/09/01. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32922-191-32922-193.
- 8510080478** Informs of current commitment status re audit frequency to be used for HVAC subcontractor, Bahnsen Co. Frequency of audit of site activities will revert to normal annual frequency due to possible inability of vendor to implement QA program.
WELLS, J.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/04/09. MARTIN, R.D. Region 4, Office of Director. 1p. 32922-193-32922-193.
- 8510080213** Ack receipt of 850319 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-445/84-31.
DENISE, R.P. Region 4, Office of Director. 85/09/06. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32921-011-32921-030.
- 8510080216** Responds to NRC 850212 ltr re violations noted in Insp Rept 50-445/84-31. Corrective actions: mechanical & electrical maint procedures identified in Tech Spec surveillance tests reclassified.
CLEMENTS, B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/03/19. HUNTER, D.R. Region 4, Office of Director. 18pp. 32921-013-32921-030.
- 8510080362** Ack receipt of 850204 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-445/84-40 & 50-446/84-15.
DENISE, R.P. Region 4, Office of Director. 85/09/06. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32922-111-32922-115.
- 8510080368** Responds to NRC 850109 ltr re violations noted in Insp Repts 50-445/84-40 & 50-446/84-15. Corrective actions: Rev 6 to Procedure CP-QP-16.1 re significant const deficiencies issued.
CLEMENTS, B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/02/04. HUNTER, D.R. Region 4, Office of Director. 3pp. 32922-113-32922-115.
- 8510100067** Forwards Insp Rept 50-445/85-06 on 850301-0430 & notice of violation.
DENISE, R.P. Region 4, Office of Director. 85/09/12. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32960-133-32960-145.
- 8510100073** Notice of violation from insp on 850301-0430 incomplete.
* Region 4, Office of Director. 85/09/12. 2pp. 32960-135-32960-136.
- 8510100079** Insp Rept 50-445/85-06 on 850301-0430. Violation noted: Procedure MDA-201 did not provide appropriate instruction for electrical & mechanical maint & failure to provide procedure for broken seal ring on reactor coolant pump.
KELLEY, D.L., SMITH, W.F., HUNNICUTT, D.M. Region 4, Office of Director. 85/05/29. 9pp. 32960-137-32960-145.
- 8510030034** Forwards Insp Repts 50-445/85-03 & 50-446/85-02 issued on 850917. Related correspondence.
MIZUNO, G.S. Hearing Branch 1. #485 656. 85/09/26. BLOCH, P.B., GROSSMAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 18pp. 32845-094-32845-111.
- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.
- 8510090206** Forwards Page 2 to notice of violation inadvertently omitted from Insp Rept 50-445/85-06.
DENISE, R.P. Region 4, Office of Director. 85/09/30. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 1p. 32947-188-32947-190.
- 8510090211** Page 2 to notice of violation. Violation noted: failure to provide adequate procedures.
* Region 4, Office of Director. 85/09/12. 2pp. 32947-189-32947-190.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510080197** Informs that ltrs re Insp Repts 50-445/83-18, 50-446/83-12, 50-445/84-31, 50-445/84-40 & 50-446/84-15 sent undated. Ltrs should be dtd 850906.
DENISE, R.P. Region 4, Office of Director. 85/10/03. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 1p. 32922-061-32922-061.
- 8510100001** Forwards Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Procedure developed per recommendations made in WV Johnston 850829 memo to VS Noonan.
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/03. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 1p. 32961-067-32961-075.
- 8510100008** Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Comanche Peak Response Team project procedure for QA/QC issue-specific Action Plans VII.6.3, VII.6.5 & VII.6.
CHRISTENSEN, J., RICH, G.W., HAUSEL, J.L. Evaluation Research Corp. 85/09/27. 8pp. 32961-068-32961-075.
- 8510150449** First partial response to FOIA request for documentation re NRC overview, regulation & investigation of facility. Forwards records re protective coating issues. Documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. GARDE, B.P. Government Accountability Project. 2pp. 33110-013-33110-043.
- 8510150454** Package consisting of insp repts, calibr records & repts & Responses 3.5 & 10 to RL Bangart 840523 ltr re BNL interim rpt on protective coatings.
* Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/04. 9,000pp. 33118-001-33118-362.
- 8510170222** Forwards questions/comments on "Comanche Peak Response Team Program Plan & Self-Initiated Actions," for all phases of independent assessment program. Insp for certain types of skewed welds in NF supports discussed.
WILLIAMS, N.H. CYGNA Energy Services. 85/10/06. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 39pp. 33039-196-33039-233.
- 8510220455** Forwards Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violations or deviations noted.
DENISE, R.P. Region 4, Office of Director. 85/10/11. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33096-224-33096-231.
- 8510220458** Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violation or deviation noted. Major areas inspected: previous emergency preparedness appraisal One App A item closed & 35 App B items closed.
TERC, N.M., BAIRD, J.B., WESTERMAN, T.F. Region 4, Office of Director. 85/08/19. 6pp. 33096-226-33096-231.
- 8510280217** Forwards Insp Rept 50-445/85-11. Const Insp Repts 50-445/85-11 & 50-446/85-06. Comanche Peak Response Team Activities Insp Repts 50-445/85-11 & 50-446/85-06 on 850622-0831 & notices of violation & deviation.
DENISE, R.P. Region 4, Office of Director. 85/10/11. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33195-115-33195-158.
- 8510280220** Notice of violation from insp on 850801-31.
* Region 4, Office of Director. 85/10/11. 1p. 33195-118-33195-118.
- 8510280223** Notice of deviation from insp on 850801-31.
* Region 4, Office of Director. 85/10/11. 2pp. 33195-119-33195-120.
- 8510280229** Insp Rept 50-445/85-11 on 850801-31. No violation or deviation noted. Major areas inspected: actions on previous insp findings, plant tours & status.
KELLEY, D.L., SMITH, W.F., BARNES, J. Region 4, Office of Director. 85/10/09. 6pp. 33195-121-33195-126.
- 8510280241** Insp Repts 50-445/85-11 & 50-446/85-06 on 850622-0822. No violation or deviation noted. Major areas inspected: const status & tour, action on potential design/const deficiency reft & concrete placement.
PHILLIPS, H.S., BUNDY, H., NORMAN, D.E. Region 4, Office of Director. 85/10/08. 6pp. 33195-127-33195-132.
- 8510280254** Insp Repts 50-445/85-11 & 50-446/85-06 on 850801-31. Violation noted: failure to reft nonconforming conditions. Deviations noted: failure to denote areas of reft in procedures & improper use of employee.
ELLERSHAW, L.E., HALE, C.J., JOHNSON, A.R. Region 4, Office of Director. 85/10/08. 26pp. 33195-133-33195-158.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.
- 8510220286** Ack receipt of 850129 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-445/84-34 & 50-446/84-13. Addl info required for item B.1 re falsification of records & corrective measures taken.
DENISE, R.P. Region 4, Office of Director. 85/10/16. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33087-284-33087-290.
- 8510220292** Responds to NRC 841231 ltr re violations noted in Insp Repts 50-445/84-34 & 50-446/84-13. Corrective actions: safety class component supports reworked & accepted & Quality Instruction QI-QAP-11.1-28A deleted.
CLEMENTS, B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/01/29. HUNTER, D.R. Region 4, Office of Director. 5pp. 33087-286-33087-290.
- 8510220303** Ack receipt of 850228 & 0730 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 50-445/84-26.
DENISE, R.P. Region 4, Office of Director. 85/10/16. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33084-003-33084-016.
- 8510220312** Responds to NRC 850118 ltr re violations noted in Insp Rept 50-445/84-26. Corrective actions: procedure for fabrication & installation/insp of safety class component supports revised. Submittal replaces util 850228 response.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/07/30. HUNTER, D.R. Region 4, Office of Director. 11pp. 33084-006-33084-016.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-066.

8510220440 Summary of 850917 meeting w/util in Bethesda, MD re visual insp of welds through paints. Transcript & viewgraphs encl.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/17. Comanche Peak Project (Technical Review Team). 5pp. 33098:357-33098:361.

-8510220445 Transcript of 850917 meeting w/util in Bethesda, MD re official insp of painted support welds. Pp 1-71.
* NRC - No Detailed Affiliation Given. 85/09/17. 87pp. 33099:001-33099:088.

-850904052 Responds to 850813 request for review of util position paper re visual insp of painted support welds. Reinsp through paint acceptable to determine presence, location & size, not quality, of structural steel weldments.
JOHNSTON, W.V. Assistant Director for Matis, Chem. & Environ Technology (Post 830201). 85/08/29. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 3pp. 33099:089-33099:091.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Schematically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510290019 Ack receipt of 851010 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-445/85-02.
DENISE, R.P. Region 4, Office of Director. 85/10/23. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 1p. 33235:140-33235:144.

-8510290021 Responds to NRC 850911 ltr re violations noted in Insp Rept 50-445/85-02. Corrective actions: Test Deficiency Rept 4254 written to document violation & sys test engineers will be reconstructed in verbatim requirements imposed by deviation.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 2pp. 33235:141-33235:144.

S. Reportable occurrences, LERs & related correspondence

8510010063 Responds to 850201 questions re reactor coolant pump motor failure & outflow: spent fuel pool liner Unit 1 reactor coolant pump Motor 4 tripped on 841028 due to phase A & B overcurrent condition caused by insulation breakdown.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/26. ELLIS, J. Citizens Association for Sound Energy. 7pp. 32833:160-32833:166.

8510010639 Deficiency Rept SDAR-199 re unsatisfactory reinsp by technical review team. Significant insp being conducted to ensure equipment will perform intended safety function. One inspector terminated.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/26. HUNTER, D.R. Region 4, Office of Director. 1p. 32820:330-32820:330.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510090336 Interim Deficiency Rept SDAR-196 re cable tray hanger design. Initially reported on 850906. Deficiency being pursued under Comanche Peak Response Team plan. Evaluation expected to be completed by 860122.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32947:142-32947:142.

8510090339 Final Deficiency Rept SDAR-183 re Posi-Seal containment isolation valves not performing safety functions. Initially reported on 850612. Investigation completed. Deficiency not reportable under 10CFR50.55(e).
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32947:146-32947:146.

8510090440 Deficiency Rept SDAR-188 re concrete debris found in seismic/separation gap between fuel & auxiliary bldgs. Initially reported on 850726. Adequacy of gap between plant structures studied. Evaluation to be complete by 851217.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32946:040-32946:040.

8510090458 Deficiency Rept SDAR-197 re indeterminant compliance w/Reg Guide 1.29 concerning installation of Train C conduit on non-nuclear safety-related dead weight supports. Initially reported on 850906. Evaluation will be completed by 860122.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32946:093-32946:093.

8510090468 Deficiency Rept SDAR-195 re inadequate conduit support sys. Initially reported on 850906. Evaluation completion anticipated by 860201.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32946:087-32946:087.

8510090430 Deficiency Rept SDAR-186 re conflict between component cooling water pump & associated HVAC sys specified by fire protection program review timeline. Initially reported on 850716. Item not reportable per 10CFR50.55(e).
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/01. DENISE, R.P. Region 4, Office of Director. 1p. 32946:159-32946:159.

8510090448 Deficiency Rept SDAR-195 re program for identifying non-seismic-to-seismic interactions of large equipment masses in 2 inch & less piping. Initially reported on 850906. Item not reportable per 10CFR50.55(e).
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/01. DENISE, R.P. Region 4, Office of Director. 1p. 32946:102-32946:102.

8510210284 Interim Deficiency Rept SDAR-206 re transformers provided by Westinghouse as part of 480-volt switchgear. Initially reported on 850920. Evaluation should be complete by 851203.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 1p. 33094:359-33094:359.

8510220058 Interim Deficiency Rept SDAR-200 re glastic matl separation barriers installed in Class 1E maint cor/rol boards & panels w/o proper design basis documentation. Initially reported on 850918. Completion by 860305 anticipated.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 1p. 33095:258-33095:258.

8510210131 Forwards update of results of util evaluation of design review/quality revalidation recommendations re maint & surveillance activities associated w/TDI diesel generators & provides clarification concerning several rept components.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/14. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 9pp. 33072:231-33072:239.

8510220403 Deficiency Rept SDAR-136 re temp envelope requirements on environ qualification of equipment outside containment for high energy line breaks. Initially reported on 840604. Completion of evaluation anticipated by 860221.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/14. DENISE, R.P. Region 4, Office of Director. 1p. 33096:345-33096:345.

8510250321 Interim Deficiency Rept SDAR-207 re use of core boring equipment during installation of shear lugs. Initially reported on 850926. Evaluation continuing. Next rept will be submitted by 851207.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33223:300-33223:300.

8510250370 Second Interim Deficiency Rept SDAR-202 re adequacy of restraints provided for flux mapping sys under seismic loads. Initially reported on 850918. Evaluation continuing. Completion expected by 851127.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33223:288-33223:288.

8510280224 Deficiency Rept SDAR-204 re possible adverse effects of thermomag on conduits & conduit support installations. Initially reported on 850920. Evaluation continuing. Completion expected by 860122.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33195:159-33195:159.

8510280484 Interim Deficiency Rept SDAR-180 re use of nonrepresentative sample in determining generic values for typical conduit span calculations. Initially reported on 850515. Evaluation continuing. Next rept anticipated by 850218.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:020-33197:020.

8510280487 Interim Deficiency Rept SDAR-192 re possible impact of previously unconsidered weight on electrical raceway support sys. Initially reported on 850827. Evaluation continuing. Next rept anticipated by 860122.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:019-33197:019.

8510280500 Final Deficiency Rept SDAR-193 re potential loss of control capability of feedwater regulating valve. Initially reported on 850827. Condition not reportable under 10CFR50.55(e).
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:018-33197:018.

8510310568 Forwards PNL-5444, "Review of Design & Quality Revalidation Rept for TDI Diesel Generators at Comanche Peak Steam Electric Station Unit 1," technical evaluation rept.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/10/17. BERLINGER, C. Division of Licensing. 1p. 33276:241-33276:001.

-8510310574 "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Comanche Peak Steam Electric Station," technical evaluation rept.
LAITY, W.W. RICHMOND, W.D. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2963. PNL-5444. 85/10/31. BERLINGER, C.H. Division of Licensing. 145pp. 33276:242-33276:036.

T. Hearing transcripts on non-antitrust matters

8504250306 Transcript of 840507 meeting in Bethesda, MD re fuel load schedule. Pp 1-103. Supporting documentation encl.
* NRC - No Detailed Affiliation Given. 84/05/07. 125pp. 30030:184-30030:308.

8510220440 Summary of 850917 meeting w/util in Bethesda, MD re visual insp of welds through paints. Transcript & viewgraphs encl.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/17. Comanche Peak Project (Technical Review Team). 5pp. 33098:357-33098:361.

-8510220445 Transcript of 850917 meeting w/util in Bethesda, MD re official insp of painted support welds. Pp 1-71.
* NRC - No Detailed Affiliation Given. 85/09/17. 87pp. 33099:001-33099:088.

8510240070 Summary of 851002-03 meetings w/util in Granbury, TX re basis for establishing homogeneous hardware populations for const adequacy review & S&W pipe & pipe support reanalysis program.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/18. Comanche Peak Project (Technical Review Team). 6pp. 33178:012-33178:199.

-8510240079 Transcript of NRC 851002 & 03 meetings w/util in Granbury, TX to discuss basis for establishing homogeneous hardware population for const adequacy review & S&W pipe & pipe support reanalysis program. Pp 1-182.
* NRC - No Detailed Affiliation Given. 85/10/02. 182pp. 33178:018-33178:199.

8510250201 Transcript of 851023 telcon w/TG Dignan, RK Gad, SA Treby, AZ Roisman & B Garde in Washington, DC re CASE 851018 motion concerning issuance of subpoenas & scheduling of prehearing conference. Pp 24,068-24,079.
* Atomic Safety and Licensing Board Panel. 85/10/23. 14pp. 33172:117-33172:130.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

222 DOCKETED ITEMS

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510250346 FOIA request for info re QA rept prepared by Comanche Peak Technical Review Team.
GARDE,B.P. Government Accountability Project. 85/01/09. Office of Administration. 2pp. 33110:346-33110:350.

8510150436 FOIA request for all documentation re overview,regulation & investigation of facility by NRC since 840109.
GARDE,B.P. Government Accountability Project. 85/01/11. Office of Administration. 2pp. 33110:001-33110:002.

8510150440 FOIA request for all documentation re overview,regulation & investigation of facility by NRC since 850111.
GARDE,B.P. Government Accountability Project. 85/01/14. Office of Administration. 2pp. 33110:003-33110:004.

8510150443 FOIA request for all documentation re overview,regulation & investigation of facility by NRC since 850114.
GARDE,B.P. Government Accountability Project. 85/01/15. Office of Administration. 2pp. 33110:005-33110:006.

8510150446 FOIA request for all documentation re overview,regulation & investigation of facility by NRC since 850117.
GARDE,B.P. Government Accountability Project. 85/01/18. Office of Administration. 2pp. 33110:007-33110:008.

8510150447 FOIA request for all documentation re overview,regulation & investigation of facility by NRC since 850118.
GARDE,B.P. Government Accountability Project. 85/01/21. Office of Administration. 2pp. 33110:009-33110:012.

8510030399 Notification of contract execution,Mod 1,to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs.
HAWKINS,D. Technical Assistance Contracts Branch. FIN D-1338. 85/09/09.
THOMPSON,H.L. Division of Licensing. TRAMMELL,C. NRC - No Detailed Affiliation Given. 1p. 32848:075-32848:076.

-8510030404 Mod 1,extending period of performance to 850920,to "Review & Evaluation of Comanche Peak Program Plan."
MOONAN,W.S. Teledyne Engineering Services. EDGEWORTH,P.J. Division of Contracts. FIN D-1338. 85/09/09. 1p. 32848:076-32848:076.

8510170302 Forwards ASLB documents transmitted to CYGNA per 850913 ltr to util re independent assessment program,in response to 850916 request.
WILLIAMS,N.H. CYGNA Energy Services. 85/09/16. ELLIS,J. Citizens Association for Sound Energy. 47pp. 33039:234-33039:280.

8510010080 Notification of contract execution,Mod 2,to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs.
HAWKINS,D.A. Technical Assistance Contracts Branch. FIN D-1338. 85/09/24.
THOMPSON,H. Division of Licensing. TRAMMELL,C. NRC - No Detailed Affiliation Given. 1p. 32833:315-32833:319.

-8510010092 Mod 2, revising statement of work to include Task D, to "Review & Evaluation of Comanche Peak Program Plan."
MOONAN,W.S. Teledyne Engineering Services. EDGEWORTH,P.J. Technical Assistance Contracts Branch. FIN D-1338. 85/09/24. 4pp. 32833:316-32833:319.

8510010059 Clarifies 850605 ltr re use of ASME Code Cases N-397 & N-411 ltr gave generic approval provided listed items (a) through (f) implemented.Response to whether CP amend needed requested.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/09/25.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32833:167-32833:171.

8510030252 Notification of 851002 & 03 meetings w/util in Granbury,TX to discuss basis for establishing homogeneous hardware populations for const adequacy review & S&W piping & pipe support walkdowns.
VIETTI-COOK,K. Comanche Peak Project (Technical Review Team). 85/09/27.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 8pp. 32849:107-32849:114.

8510030234 Forwards request for addl info re revs made to FSAR by Amends 54 & 55,info needed re revised commitment to Reg Guide 1.44 (Amend 54) & suction pipe & debris screen added to containment ventilation sys (Amend 55).
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/09/30.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32849:192-32849:196.

8510070494 Forwards Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan:Detailed Comments/Concerns."
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/09/30.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 6pp. 32901:298-32902:036.

-8510070496 Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan:Detailed Comments/Concerns."
Comanche Peak Project (Technical Review Team). 85/09/30. 93pp. 32901:304-32902:036.

8510170108 Partial response to FOIA request for records re NRC determination of potential matl false statement on U-bolt sample (Board Notification 85-077),issued on 850820.Forwards App A document,Search for addl documents continuing.
FELTON,J.M. Division of Rules and Records. 85/10/01. GARDE,B.P. Government Accountability Project. 2pp. 33050:294-33050:296.

-8510170111 Forwards applicant motion for reconsideration of ASLB 841218 order re matl false statements on torquing of U-bolts.W/o encl.
MIZUNO,G. Hearing Branch 1. 84/01/08. NOONAN,V. Comanche Peak Project (Technical Review Team). 1p. 33050:296-33050:296.

8510030122 Board Notification 85-087:forwards VS Noonan 850930 ltr to util & Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan:Detailed Comments/Concerns," per Commission 840706 revised notification policy.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/10/03. PALLADINO,ROBERTS,ASSELSTINE Commissioners. 2pp. 32966:360-32967:098.

8510150449 First partial response to FOIA request for documentation re NRC overview,regulation & investigation of facility Forwards records re protective coating issues.Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. GARDE,B.P. Government Accountability Project. 2pp. 33110:013-33110:043.

-8510150451 Rev 7 to CPM 13.1, "General Calibr Procedure."
FRANKUM,D.C. Brown & Root, Inc. (subs. of Halliburton Co.). 81/12/09. 22pp. 33110:035-33110:043.

-8510150454 Package consisting of insp repts,calibr records & repts & Responses 3,5 & 10 to RL Bangart 840523 ltr re BNL interim rept on protective coatings.
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/04. 9,000pp. 33118:001-33120:362.

8510170250 Requests info from Gibbs & Hill in order to close out open issues re pipe stress analyses reviews.Encl communications rept documents initial questions asked on 851018.
WILLIAMS,N.H. CYGNA Energy Services. 85/10/09. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33040:064-33040:066.

8510180414 Further response to FOIA request for documents re NRC 840629 meeting w/util concerning investigation on illegal use of drugs at facility.Addl documents not found,Search complete.
FELTON,J.M. Division of Rules and Records. 85/10/10. GARDE,B.P. Government Accountability Project. 1p. 33077:124-33077:126.

8510210022 Forwards documents re expansion bolt data base & cable tray & conduit raceway seismic test program,in response to 851008 telcon request on independent assessment program - Phase 4.
WILLIAMS,N.H. CYGNA Energy Services. 85/10/10. PALMER,S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33072:041-33072:042.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28,Item 1.2 re Salem ATWS events.Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:257.

-8510170159 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events),Item 1.2, 'Post-Trip Review Data & Info Capabilities'" technical evaluation rept.
Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1523-3. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:013-33044:027.

8510180394 Further response to FOIA request for documents re NRC review of EG&G rept on facility App B documents available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/11. MILLAR,B. Fort Worth Star-Telegram, Fort Worth, TX. 3pp. 33077:346-33077:349.

8510170479 Expresses appreciation for 850815 comments on Comanche Peak Response Team program plan,Review of plan will be complete following applicant response to all NRC concerns.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/10/12. GARDE,B.P. Trial Lawyers for Public Justice, P.C. 1pp. 33048:143-33048:143.

-8510170480 Responds to CASE 850815 comments re Comanche Peak Response Team program plan,NRC will re-review plan following applicant response to all concerns.Meeting w/CASE to discuss findings suggested.
EISENHUT,D.G. Office of Nuclear Reactor Regulation, Director. 85/10/12. GARDE,B.P. Trial Lawyers for Public Justice, P.C. 2pp. 33048:144-33048:148.

8510220110 Advises that implementation of ATWS mitigating sys actuation circuitry (AMSAC),per Generic Ltr 85-06,scheduled for 861201,based on NRC approval of WCAP-10858, "AMSAC Generic Design Package".
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/14. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 1p. 33090:150-33090:150.

8510210035 Forwards list of Phase 4 mechanical sys review questions & open items,Response requested.
WILLIAMS,N.H. CYGNA Energy Services. 85/10/16. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33072:043-33072:046.

8510210076 Forwards list of Independent Assessment Program Phase 4 electrical questions & open items,including requests for info re diesel generator short-circuit contribution & offsite grid voltage variations.
WILLIAMS,N.H. CYGNA Energy Services. 85/10/16. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 7pp. 33072:318-33072:323.

8510220125 Further response to FOIA request for documents re EG&G rept on harassment & intimidation,Forwards App B documents. Documents also available in PDR Portions of App C Documents 1-4 withheld (ref FOIA Exemptions 4 & 6).
FELTON,J.M. Division of Rules and Records. 85/10/16. GARDE,B. Government Accountability Project. 4pp. 33099:325-33100:110.

-8412100470 Provides clarification on NRC position re intimidation at facility,Overall task EG&G contracted to perform defined. EG&G rept will be used as input to NRC assessment.
EISENHUT,D.G. Division of Licensing. 84/12/04. HAYES,B.B. Office of investigation. 1p. 33100:111-33100:111.

-8510220137 Forwards statements of work for FINs A-6819 (Project 2), A-6821 (Project 2) & A-0802 re evaluation of selected open NRC items at plant for review & comment.
DONOHEW,J. Division of Licensing. FIN A-6821. 84/06/15. KALTMAN,M. Planning & Program Analysis Staff. 1p. 33099:331-33099:331.

-8510220154 Forwards std order for DOE work, supporting "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2. Proposal requested within 14 days.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/02. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 15pp. 33099:333-33099:347.

-8510220161 Approves CM Rice & W Stratton as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per LP Leach 840717 request.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/18. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 2pp. 33099:348-33099:349.

-8510220171 Forwards project descriptive summary for FIN A-6819, "Evaluation of Selected NRC Open Items Before Fuel Load (Program 1)," statement of work & NRC Form 173, for review & approval.
FUNCHES, J.L. Planning & Program Analysis Staff. FIN A-6819. 84/07/13. BECKWITH, C.A. Office of Resource Management, Director. 12pp. 33099:350-33099:362.

-8510220178 Draft "Investigation & Assessment of Work Climate at Comanche Peak Steam Electric Station."
KAPLAN, B.L. ANDOGNINI, G.C., STRATTON, W.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6429-4. 84/08/31. NRC - No Detailed Affiliation Given. 45pp. 33100:001-33100:045.

-8510220202 Forwards, for concurrence, std order for DOE work, changing statement of work for "Evaluation of Selected NRC Open Items Before Plant Fuel Load," (FIN A-6819, Project 2).
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/08/24. SIMS, F.L. Energy, Dept. of. 4pp. 33100:047-33100:050.

-8510220208 Forwards INEL planned staffing for Cycle 4 Comanche Peak Technical Review Team. Planned staffing for Cycle 5 will be identified as soon as possible.
WILLIAMS, M.H. Division of Licensing. 84/09/06. IPPOLITO, T.A. Comanche Peak Project (Technical Review Team). 2pp. 33100:051-33100:052.

-8510220215 Forwards, for concurrence, std order for DOE work, "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, INEL proposal dtd Sept 1984 acceptable. LP Leach 850905 & 20 ltrs to DOE encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/09/13. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 9pp. 33100:053-33100:061.

-8510220225 Approves DG Bowers & H Margulies as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per INEL 840727 request. Related documentation encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/31. SIMS, F.L. Energy, Dept. of. 4pp. 33100:062-33100:110.

-8510220239 Forwards project & budget proposals for NRC work for Rev 1 to, "Evaluation of Selected NRC Open Items Before Plant Fuel Load" & "Evaluation of Selected Open NRC Activities at Near-Term OL Sites Needing Action..."
MILLAM, S.B. Energy, Dept. of, Idaho Operations Office. FIN A-6821. 84/08/23. WILLIAMS, M. Division of Licensing. 1p. 33100:112-33100:112.

-8510220252 Rev 1 to project & budget proposal for NRC work: "Evaluation of Selected NRC Open Items Before Plant Fuel Load."
OBENCHAIN, C.F., NALEZNY, C.L. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6819. 85/08/15. DONOHEW, J.N. Office of Nuclear Reactor Regulation, Director. 9pp. 33100:113-33100:121.

8510250336 Responds to FOIA request for QA rept prepared by Comanche Peak Technical Review Team. Records listed on App A available in PDR.
FELT, J.M. Division of Rules and Records. 85/10/16. GARDE, B.P. Government Accountability Project. 1p. 33191:345-33191:345.

8510240588 Grants request to withhold CAW-85-057, "Improved Thermal Design Procedures," per 850830 application, 761202 affidavit & 850905 ltr providing responses to questions on procedures per 10CFR2.790.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/17. WIESEMANN, R.A. Westinghouse Electric Corp. 4pp. 33185:215-33185:218.

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8509300340 Board Notification 85-084 notifies of ACRS review of SSERs 7-11, during ACRS 305th meeting on 850912-14 NRC taking appropriate actions. DA Ward 850916 memo encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 2pp. 32853:269-32853:271.

8510040263 Forwards deferred MSIV preoperational test status rept. Initial deferred test status deficiencies reported per listed ltr. Deferais granted in SSER 6. Change in status result of Unit 2 heatup from Oct 1984 to Jan 1985.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. DENTON, H.H. Office of Nuclear Reactor Regulation, Director. 8pp. 32851:181-32851:188.

8510150239 Notification of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
COOK, A.V. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33032:217-33032:221.

8510150307 Requests transcript of 851023 public meeting between NRC & CASE in Bethesda, MD re issuance of SSERs 7-11 concerning operational.
RUSHBROOK, K.M. Licensing Branch 1. 85/10/09. WILDER, P. Atomic Safety and Licensing Board Panel. 1p. 33032:308-33032:308.

8510170337 Notification of cancellation of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 4pp. 33043:348-33043:351.

8510310003 Forwards SSER 12 (NUREG-0797) Resolution of outstanding issues re fire protection program, including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33277:103-33277:107.

F. Security, medical, emergency & fire protection plans

8510080122 Forwards FEMA finding & determination verifying State of TX & local emergency preparedness plans adequate to protect public health & can be implemented offsite per NUREG-0654. Public alert & notification sys adequate.
DENISE, R.P. Region 4, Office of Director. 85/10/03. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32914:326-32915:182.

8510220455 Forwards Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violations or deviations noted.
DENISE, R.P. Region 4, Office of Director. 85/10/11. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33096:224-33096:231.

-8510220458 Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07. No violation or deviation noted. Major areas inspected: previous emergency preparedness appraisal. One App A item closed & 35 App B items closed.
TERC, N.M. Region 4, Office of Director. 85/08/19. 6pp. 33096:226-33096:231.

8510300005 Forwards revised emergency plan procedures, including Rev 3 to EPP-309 re offsite radiological monitoring. Rev 5 to EPP-310 re onsite & in-plant radiological surveys & Rev 5 to EPP-101 W/o stated encls.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/24. Record Services Branch (Document Control Desk). 1p. 33247:004-33247:032.

-8510300011 Revised emergency plan procedures, including Rev 29 to emergency plan manual index & Rev 4 to EPP-204 re activation of technical support ctr & technical support ctr personnel duties.
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. 28pp. 33247:005-33247:032.

8510300051 Forwards list of training & drills conducted for offsite agencies over past 2 yrs, per 850919 request for exemption from regulations concerning emergency preparedness exercises.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/24. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 3pp. 33249:215-33249:217.

8510310003 Forwards SSER 12 (NUREG-0797) Resolution of outstanding issues re fire protection program, including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33277:103-33277:107.

G. Adjudicatory correspondence

8510020145 Motion for mod of ASLB 850829 memorandum re proposal for governance of case. Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 643. 85/09/25. Atomic Safety and Licensing Board Panel. 4pp. 32824:323-32824:326.

8510020268 Memorandum supporting motion for mod of ASLB 850829 memorandum proposing governance of case. Certificate of Svc encl.
DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 644. 85/09/25. Atomic Safety and Licensing Board Panel. 13pp. 32824:235-32824:247.

8510030034 Forwards Insp Repts 50-445/85-03 & 50-446/85-02 issued on 850917. Related correspondence.
MIZUNO, G.S. Hearing Branch 1. #485 656. 85/09/26. BLOCH, P.B., GROSSMAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 18pp. 32845:094-32845:111.

8510030024 Grants extension until 851004 for all parties to respond to ASLB 850918 memorandum re water recirculation problems caused by plant, per 850926 telcon w/ PB Bloch. Related correspondence.
BACHMANN, R.G. Hearing Branch 1. #485 657. 85/09/27. BLOCH, P.B., JOHNSON, E.B., MCCOLLUM, K.A. Atomic Safety and Licensing Board Panel. 1p. 32842:329-32842:329.

8510040358 Notice that 851002 memorandum & order re applicant motion for mod should not be interpreted to deny any portion of intervenor motion for reconsideration of NRC 850829 memorandum & order. Served on 851002.
BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 671. 85/10/02. 1p. 32853:272-32853:272.

8510040449 Memorandum & order granting, in part, applicant 850925 motion for mod of 850829 order independence of Comanche Peak Review Team affects weight of evidence, not whether evidence would be received. Served on 851002.
BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 672. 85/10/02. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32853:340-32853:344.

8510100185 Confirms 850923 conversation re scheduling of depositions in Docket 2. Requests response within 7 days suggesting schedule for depositions of Wells, Spence & Brittan. Related correspondence.
GARDE, B.P. Trial Lawyers for Public Justice, P.C. #485 715. 85/10/02. WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Wooldridge (formerly Worsham, Forsythe & Samples). 3pp. 32962:109-32962:111.

8510100057 Confirms that all parties granted further extension of time until 851011 to file motions re ASLB 850918 memorandum concerning water recirculation problems caused by plant, per 851003 telcon w/ PB Bloch.
BACHMANN, R.G. Hearing Branch 1. #485 680. 85/10/03. BLOCH, P.B., JOHNSON, E.B., MCCOLLUM, K.A. Atomic Safety and Licensing Board Panel. 1p. 32960:085-32960:085.

8510160219 Forwards RP Lessy notice of appearance in proceeding. Certificate of Svc encl.
WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Wooldridge (formerly Worsham, Forsythe & Samples). #485 770. 85/10/08. Docketing & Services Branch. 5pp. 33022:243-33022:247.

224 DOCKETED ITEMS

- 8510160224** Forwards RP Lessy notice of appearance in proceeding. Certificate of Svc encl. WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Samples). #485 771. 85/10/08. Docketing Services Branch. 5pp. 33022-233-33022-237.
- 8510110228** Response to CASE 850904 request for production of documents & motion for protective order. Applicant objects to requests for all documents as unduly broad to allow appropriate response. Certificate of Svc encl. Related correspondence. REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 751. 85/10/09. Atomic Safety and Licensing Board Panel. 38pp. 32974-133-32974-170.
- 8510110238** Motion requesting ASLB reconsider & modify 850918 memorandum to reflect fact that util not placed in special category for coatings inside containment, per SSER 9 (NUREG-0797) & consider notification of USI A-43 closed. BACHMANN, R.G. Hearing Branch 1. #485 741. 85/10/09. Atomic Safety and Licensing Board Panel. 6pp. 32971-235-32971-252.
- 8510110239** Affidavit of CE McCracken providing further explanation of background of SSER 9, App L, per ASLB 850913 memorandum. MCCracken, C.E. Division of Engineering. 85/09/09. 7pp. 32971-241-32971-247.
- 8510110241** Affidavit of AW Serkiz providing explanation re SSER 9, App L, per ASLB 850918 memorandum. Certificate of Svc encl. SERKIZ, A.W. Generic Issues Branch. 85/09/09. 5pp. 32971-248-32971-252.
- 8510150355** Response opposing CASE 850904 request for production of documents & motion for protective order re request concerning mgt qualifications & organization. Certificate of Svc encl. Related correspondence. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. #485 759. 85/10/09. Atomic Safety and Licensing Board Panel. 38pp. 33010-069-33010-106.
- 8510180346** Objects to 851002 comments & conclusions re CASE 850904 request for production of documents. Depositions should be requested formally. Prehearing conference for oral argument on unresolved issues will be sought. Related correspondence. WOOLDRIDGE, R.A. Worsham, Forsythe, Samples & Woolridge (formerly Worsham, Forsythe & Samples). #485 824. 85/10/14. GARDE, B.P. Trial Lawyers for Public Justice, P.C. 2pp. 33062-020-33062-021.
- 8510180232** Response opposing CASE 850925 motion for reconsideration of Board 850829 memorandum & order (proposal for governance of CASE) &/or motion for protective order. Certificate of Svc encl. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 806. 85/10/15. Atomic Safety and Licensing Board Panel. 17pp. 33061-234-33061-250.
- 8510180255** Forwards util response to CASE motion for reconsideration of Board 850829 memorandum & order (proposal for governance of CASE) &/or motion for protective order, per Commission rules & regulations. W/o encl. Related correspondence. DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 807. 85/10/15. Office of the Secretary of the Commission. 1p. 33061-127-33061-127.
- 8510180341** Response opposing CASE 850925 motion for reconsideration of ASLB 850829 memorandum & order &/or protective order re applicant & CASE summary disposition motions on pipe support design & design QA. Certificate of Svc encl. MIZUNO, G.S. Hearing Branch 1. #485 790. 85/10/15. Atomic Safety and Licensing Board Panel. 12pp. 33062-005-33062-016.
- 8510220293** Application for issuance of encl subpoenas duces tecum for NRC witnesses V Noonan, T Ippolito, H Livermore, J Calvo, L Shao, C McCracken & R Bangert. Depositions requested to be scheduled for 851029-31. Related correspondence. ROISMAN, A.Z. Citizens Association for Sound Energy. ROISMAN, A.Z. Trial Lawyers for Public Justice, P.C. #485 862. 85/10/18. Atomic Safety and Licensing Board Panel. 30pp. 33083-298-33083-327.
- 8510240371** Petition for directed certification of ASLB 851002 order denying applicant motion for mod of ASLB 850829 rejection of 850628 mgt plan. Certificate of Svc encl. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 885. 85/10/21. 17pp. 33111-199-33111-246.
- 8510290004** Informs that applicants have filed answers to interrogatories served by CASE on 850827. Proposals for organizing access to applicant mats w/o need of formal discovery. No action necessary on protective order motions. GAD, R.K. Ropes & Gray. #485 933. 85/10/21. BLOCH, P.B., MCCOLLUM, K.A., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 2pp. 33233-251-33233-252.
- 8510280518** Response to CASE 850827 interrogatories to applicants & requests to produce & request for protective order. Certificate of Svc encl. Related correspondence. TYLER, T.G. Comanche Peak Project (Technical Review Team). DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 943. 85/10/22. Citizens Association for Sound Energy. 72pp. 33227-225-33227-296.
- 8510240677** Order requiring that NRC response to applicant 851002 petition for directed certification of licensing board be submitted by 851106. Served on 851024. TOMPKINS, B.A. Atomic Safety and Licensing Appeal Panel. #485 886. 85/10/23. Office of the Executive Legal Director. 1p. 33161-030-33161-030.
- 8510290016** Forwards joint stipulation of staff & CASE (request for subpoenas) for ASLB approval. TREBY, S.A. Hearing Branch 1. #485 942. 85/10/23. BLOCH, P.B., MCCOLLUM, K.A., JOHNSON, E.B. Atomic Safety and Licensing Board Panel. 1p. 33235-145-33235-147.
- 8510290022** Joint stipulation to confirm agreement reached re CASE request for subpoenas. CASE agreed to withdraw request. Staff will produce documents requested in subpoenas. TREBY, S. Hearing Branch 1. ROISMAN, A.Z. Citizens Association for Sound Energy. 85/10/23. 2pp. 33235-146-33235-147.
- 8510290032** Brief in response to ASLB 851015 telcon ordering parties to respond to statement concerning CASE good faith effort to coordinate discovery activities & util provision of more specific responses to discovery. W/Certificate of Svc. DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). DIGNAN, T.G. Ropes & Gray. #485 915. 85/10/23. Atomic Safety and Licensing Board Panel. 7pp. 33235-152-33235-158.
- 8510290258** Forwards util brief in response to 851015 conference call. W/o encl. Related correspondence. DIGNAN, T.G. Ropes & Gray. DIGNAN, T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 910. 85/10/23. Office of the Secretary of the Commission. 1p. 33233-347-33233-347.
- 8510290003** Discusses NRC 851009 response to ASLB 850918 memorandum re water recirculation problems caused by paint. Motion for reconsideration of listed point one & motion that listed point two considered resolved supported. REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 911. 85/10/24. BLOCH, P.B., JORDAN, W.H., MCCOLLUM, K.A. Atomic Safety and Licensing Board Panel. 3pp. 33232-360-33232-361.
- 8510280514** Advises of intent to file representativeness of U-bolt support configurations employed in tests & corrections to util affidavits supporting motions for summary disposition re piping & support design. REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 929. 85/10/25. BLOCH, P.B., JOHNSON, E.B., MCCOLLUM, K.A. Atomic Safety and Licensing Board Panel. 2pp. 33227-309-33227-310.
- 8510310200** Response to ASLB questions raised during 851015 telcon re statement concerning discovery as applied to two dockets & prehearing conference recommendations. Certificate of Svc encl. BACHMANN, R.G. Hearing Branch 1. #485 975. 85/10/25. Commissioners. 13pp. 33273-077-33273-089.
- 8510280520** Response to ASLB request to address good faith effort to coordinate discovery activities & for applicant to provide more specific responses to discovery. Certificate of Svc encl. Related correspondence. ELLIS, J. Citizens Association for Sound Energy. #485 918. 85/10/26. Atomic Safety and Licensing Board Panel. 112pp. 33227-113-33227-224.
- 8510310276** Response to ASLB questions re relevant dockets & discovery effort raised during 851015 conference call. Attempts to coordinate discovery efforts in two dockets made when possible. W/Certificate of Svc. Related correspondence. ROISMAN, A.Z. Citizens Association for Sound Energy. ROISMAN, A.Z. Trial Lawyers for Public Justice, P.C. #485 958. 85/10/28. Atomic Safety and Licensing Board Panel. 20pp. 33272-135-33272-154.
- 8510310316** Memorandum & order granting CASE 850805 motion to reconsider 850722 order re Mgt Analysis Co rept & denying CASE 850814 motion for equipment to be preserved. Served on 851029. BLOCH, P.B. Atomic Safety and Licensing Board Panel. #485 981. 85/10/29. Citizens Association for Sound Energy. 11pp. 33272-263-33272-273.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8510170183** Amend 56 to FSAR for Comanche Peak Steam Electric Station. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 150pp. 33037-266-33038-096.
- 8510180159** Forwards table providing revised description of Amend 56 to FSAR. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/15. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33058-260-33058-264.

Q. Inspection reports, IE Bulletins & correspondence

- 8510150436** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 840109. GARDE, B.P. Government Accountability Project. 85/01/11. Office of Administration. 2pp. 33110-001-33110-002.
- 8510150440** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850111. GARDE, B.P. Government Accountability Project. 85/01/14. Office of Administration. 2pp. 33110-003-33110-004.
- 8510150443** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850114. GARDE, B.P. Government Accountability Project. 85/01/15. Office of Administration. 2pp. 33110-005-33110-006.
- 8510150446** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850117. GARDE, B.P. Government Accountability Project. 85/01/18. Office of Administration. 2pp. 33110-007-33110-008.
- 8510150447** FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850118. GARDE, B.P. Government Accountability Project. 85/01/21. Office of Administration. 2pp. 33110-009-33110-012.
- 8510080474** Ack receipt of 850419 ltr noting corrective actions re const appraisal team insp findings associated w/HVAC subcontractor, Bahnsen Co. More frequent Bahnsen site activities supported. Performance will be monitored. DENISE, R.P. Region 4, Office of Director. 85/09/01. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32922-191-32922-193.
- 8510080478** Informs of current commitment status re audit frequency to be used for HVAC subcontractor, Bahnsen Co. Frequency of audit of site activities will revert to normal annual frequency due to possible inability of vendor to implement QA program. WELLS, J.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/04/09. MARTIN, R.D. Region 4, Office of Director. 1p. 32922-193-32922-193.

8510080362 Ack receipt of 850204 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-445/84-40 & 50-446/84-15.
DENISE,R.P. Region 4, Office of Director. 85/09/06. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32922-111-32922-115.

-8510080368 Responds to NRC 850109 ltr re violations noted in Insp Repts 50-445/84-40 & 50-446/84-15. Corrective actions: Rev 6 to Procedure CP-QP-16.1 re significant const deficiencies issued.
CLEMENTS,B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/02/04. HUNTER,D.R. Region 4, Office of Director. 3pp. 32922-113-32922-115.

8510030034 Forwards Insp Repts 50-445/85-03 & 50-446/85-02 issued on 850917. Related correspondence.
MIZUNO,G.S. Hearing Branch 1. #485 656. 85/09/26. BLOCH,P.B. Atomic Safety and Licensing Board Panel. 18pp. 32845-094-32845-111.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint.Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260389 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080197 Informs that ltrs re Insp Repts 50-443/83-18,50-446/83-12, 50-445/84-31,50-445/84-40 & 50-446/84-15 sent undated.Ltrs should be dtd 850906.
DENISE,R.P. Region 4, Office of Director. 85/10/03. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 1p. 32922-061-32922-061.

8510100001 Forwards Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Procedure developed per recommendations made in WW Johnston 850829 memo to VS Noonan.
COUNCIL,W.G., MARSHALL,J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/03. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 1p. 32961-067-32961-075.

-8510100008 Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Comanche Peak Response Team project procedure for QA/QC issue-specific Action Plans VII.6.3,VII.6.5 & VII.6.
CHRISTENSEN,J., RONG,G.W., HAUSEL,J.L. Evaluation Research Corp. 85/09/27. 6pp. 32961-068-32961-075.

8510150449 First partial response to FOIA request for documentation re NRC overview,regulation & investigation of facility.Forwards records re protective coating issues.Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. GARDE,B.P. Government Accountability Project. 2pp. 33110-013-33110-043.

-8510150454 Package consisting of insp repts,calibr records & repts & Responses 3,5 & 10 to RL Bangari 840523 ltr re BNL interim rept on protective coatings.
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/04. 9,000pp. 33118-001-33120-362.

8510170222 Forwards questions/comments on "Comanche Peak Response Team Program Plan & Self-Initiated Actions," for all phases of independent assessment program Insp for certain types of skewed welds in NF supports discussed.
WILLIAMS,N.H. CYGNA Energy Services. 85/10/06. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 39pp. 33039-196-33039-233.

8510230112 Forwards Insp Rept 50-446/85-07 on 850710-18.No violations or deviations noted.
DENISE,R.P. Region 4, Office of Director. 85/10/08. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33155-346-33155-350.

-8510230115 Insp Rept 50-446/85-07 on 850710-18.No violation or deviation noted.Major areas inspected:const activities, including review of procedures & records for welding of safety-related cable tray support mods.
GILBERT,L.D., WESTERMAN,T.F. Region 4, Office of Director. 85/08/26. 3pp. 33155-348-33155-350.

8510220455 Forwards Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07.No violations or deviations noted.
DENISE,R.P. Region 4, Office of Director. 85/10/11. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33096-224-33096-231.

-8510220458 Insp Repts 50-445/85-10 & 50-446/85-10 on 850605-07.No violation or deviation noted.Major areas inspected:previous emergency preparedness appraisal:One App A item closed & 35 App B items closed.
TERC,N.M., BAIRD,J.B., WESTERMAN,T.F. Region 4, Office of Director. 85/08/19. 6pp. 33096-226-33096-231.

8510280217 Forwards Insp Rept 50-445/85-11,Const Insp Repts 50-445/85-11 & 50-446/85-06,Comanche Peak Response Team Activities Insp Repts 50-445/85-11 & 50-446/85-06 on 850622-0831 & notices of violation & deviation.
DENISE,R.P. Region 4, Office of Director. 85/10/11. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33195-115-33195-158.

-8510280241 Insp Repts 50-445/85-11 & 50-446/85-06 on 850622-0822.No violation or deviation noted.Major areas inspected:const status & tour/action on potential design/const deficiency rept & concrete placement.
PHILLIPS,H.S., BUNDY,H., NORMAN,D.E. Region 4, Office of Director. 85/10/08. 6pp. 33195-127-33195-132.

-8510280254 Insp Repts 50-445/85-11 & 50-446/85-06 on 850801-31. Violations noted:failure to rept nonconforming conditions. Deviations noted:failure to denote areas of rev in procedures & improper use of employee.
ELLERSHAW,L.E., HALE,C.J., JOHNSON,A.R. Region 4, Office of Director. 85/10/08. 26pp. 33195-133-33195-158.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510220286 Ack receipt of 850129 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-445/84-34 & 50-446/84-13.Addl info required for Item B.1 re falsification of records & corrective measures taken.
DENISE,R.P. Region 4, Office of Director. 85/10/16. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 33087-284-33087-290.

-8510220292 Responds to NRC 841231 ltr re violations noted in Insp Repts 50-445/84-34 & 50-446/84-13.Corrective actions:safety class component supports reworked & accepted & Quality Instruction QI-QAP-11.1-28A deleted.
CLEMENTS,B.R. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/01/29. HUNTER,D.R. Region 4, Office of Director. 5pp. 33087-286-33087-290.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510220440 Summary of 850917 meeting w/util in Bethesda,MD re visual insp of welds through paints.Transcript & viewgraphs encl.
VIETTI-COOK,A. Comanche Peak Project (Technical Review Team). 85/10/17. Comanche Peak Project (Technical Review Team). 5pp. 33098-357-33098-361.

-8510220445 Transcript of 850917 meeting w/util in Bethesda,MD re official insp of painted support welds.Pp 1-71.
* NRC - No Detailed Affiliation Given. 85/09/17. 87pp. 33099-001-33099-088.

-8509040052 Responds to 850813 request for review of util position paper re visual insp of painted support welds.Reinsp through paint acceptable to determine presence,location & size,not quality of structural steel weldments.
JOHNSTON,W.V. Assistant Director for Matis, Chem. & Environ Technology (Post 830201). 85/08/29. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 3pp. 33099-089-33099-091.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510290019 Ack receipt of 851010 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-445/85-02.
DENISE,R.P. Region 4, Office of Director. 85/10/23. COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 1p. 33235-140-33235-144.

-8510290021 Responds to NRC 850911 ltr re violations noted in Insp Rept 50-445/85-02.Corrective actions:Test Deficiency Rept 4254 written to document violation & sys test engineers will be retrained in verbatim requirements imposed by deviation.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE,R.P. Region 4, Office of Director. 2pp. 33235-141-33235-144.

S. Reportable occurrences, LERs & related correspondence

8510010063 Responds to 850201 questions re reactor coolant pump motor failure & cutting of spent fuel pool liner.Unit 1 reactor coolant pump Motor 4 tripped on 841028 due to Phase A & B overcurrent condition caused by insulation breakdown.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/09/26. ELLIS,J. Citizens Association for Sound Energy. 7pp. 32833-160-32833-166.

8510010639 Deficiency Rept SDAR-199 re unsatisfactory reinsp by technical review team.Significant insp being conducted to ensure equipment will perform intended safety function.One inspector terminated.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/26. HUNTER,D.R. Region 4, Office of Director. 1p. 32820-330-32820-330.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY,W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER,C. Division of Licensing. 26pp. 32824-280-32824-305.

8510090336 Interim Deficiency Rept SDAR-196 re cable tray hanger design.Initially reported on 850906.Deficiency being pursued under Comanche Peak Response Team plan.Evaluation expected to be completed by 860122.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER,D.R. Region 4, Office of Director. 1p. 32947-142-32947-142.

8510090339 Final Deficiency Rept SDAR-183 re Post-Seal containment isolation valves not performing safety functions.Initially reported on 850512.Investigation completed.Deficiency not reportable under 10CFR50.55(e).
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER,D.R. Region 4, Office of Director. 1p. 32947-146-32947-146.

8510090440 Deficiency Rept SDAR-188 re concrete debris found in seismic/separation gap between fuel & auxiliary bldgs. Initially reported on 850726.Adequacy of gap between plant structures studied.Evaluation to be complete by 851217.
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/09/30. HUNTER,D.R. Region 4, Office of Director. 1p. 32946-040-32946-040.

8510090430 Deficiency Rept SDAR-186 re conflict between component cooling water pump & associated HVAC sys specified by fire protection program review timeline.Initially reported on 850716.Item not reportable per 10CFR50.55(e).
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/01. DENISE,R.P. Region 4, Office of Director. 1p. 32946-159-32946-159.

8510090448 Deficiency Rept SDAR-195 re program for identifying non-seismic-to-seismic interactions of large equipment masses in 2 inch & less piping.Initially reported on 850906. Item not reportable per 10CFR50.55(e).
COUNCIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/01. DENISE,R.P. Region 4, Office of Director. 1p. 32946-102-32946-102.

226 DOCKETED ITEMS

8510210284 Interim Deficiency Rept SDAR-206 re transformers provided by Westinghouse as part of 480-volt switchgear. Initially reported on 850920. Evaluation should be complete by 851203.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 1p. 33094:359-33094:359.

8510220058 Interim Deficiency Rept SDAR-200 re elastic mat separation barriers installed in Class 1E main control boards & panels w/o proper design basis documentation. Initially reported on 850918. Completion by 860305 anticipated.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 1p. 33095:258-33095:258.

8510220397 Deficiency Rept SDAR-201 re installation of conduit to equipment not specified per design documents. Initially reported on 850918. Completion of evaluation anticipated by 851112.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/10. DENISE, R.P. Region 4, Office of Director. 1p. 33096:343-33096:343.

8510220403 Deficiency Rept SDAR-136 re temp envelope requirements on environ qualification of equipment outside containment for high energy line breaks. Initially reported on 840604. Completion of evaluation anticipated by 860221.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/14. DENISE, R.P. Region 4, Office of Director. 1p. 33096:345-33096:345.

8510250321 Interim Deficiency Rept SDAR-207 re use of core boring equipment during installation of shear lugs. Initially reported on 850926. Evaluation continuing. Next rept to be submitted by 851207.
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33223:300-33223:300.

8510250370 Second Interim Deficiency Rept SDAR-202 re adequacy of restraints provided for flux mapping sys under seismic loads. Initially reported on 850918. Evaluation continuing. Completion expected by 851127.
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33223:288-33223:288.

8510280484 Interim Deficiency Rept SDAR-180 re use of nonrepresentative sample in determining generic values for typical conduit span calculations. Initially reported on 850515. Evaluation continuing. Next rept anticipated by 850218.
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:020-33197:020.

8510280493 Final Deficiency Rept SDAR-191 re vendor termination crimps. Initially reported on 850815. Condition not reportable under 10CFR50.55(e).
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:017-33197:017.

8510280500 Final Deficiency Rept SDAR-193 re potential loss of control capability of feedwater regulating valve. Initially reported on 850827. Condition not reportable under 10CFR50.55(e).
COUNCIL, W.G., MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/16. DENISE, R.P. Region 4, Office of Director. 1p. 33197:018-33197:018.

T. Hearing transcripts on non-antitrust matters

8510220440 Summary of 850917 meeting w/util in Bethesda, MD re visual insp of welds through paints. Transcript & viewgraphs encl.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/17. Comanche Peak Project (Technical Review Team). 5pp. 33098:357-33099:001.

8510220445 Transcript of 850917 meeting w/util in Bethesda, MD re official insp of painted support welds. Pp 1-71.
* NRC - No Detailed Affiliation Given. 85/09/17. 87pp. 33099:001-33099:088.

8510240070 Summary of 851002-03 meetings w/util in Granbury, TX re basis for establishing homogeneous hardware populations for const adequacy review & S&W pipe & pipe support reanalysis program.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/18. Comanche Peak Project (Technical Review Team). 6pp. 33178:012-33178:199.

8510240079 Transcript of NRC 851002 & 03 meetings w/util in Granbury, TX to discuss basis for establishing homogeneous hardware population for const adequacy review & S&W pipe & pipe support reanalysis program. Pp 1-182.
* NRC - No Detailed Affiliation Given. 85/10/02. 182pp. 33178:018-33178:199.

8510250201 Transcript of 851023 telcon w/TG Dignan, RK Gad, SA Treby, AZ Roisman & B Garde in Washington, DC re CASE 851018 motion concerning issuance of subpoenas & scheduling of prehearing conference. Pp 24,068-24,079.
* Atomic Safety and Licensing Board Panel. 85/10/23. 14pp. 33172:117-33172:130.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET STN-50-447 GESSAR-238

A. Application/construction stage documents & correspondence

8510040547 Forwards SER re GESSAR II design in response to 850911 request. Review of severe accident concerns presently being considered by ACRS. Addl suppl addressing ACRS recommendation at completion of review expected. W/o encl. SCALETTI, D.C. Standardization & Special Projects Branch. 85/10/01. CHAKRABORTY, S. Switzerland, Govt. of. 2pp. 32863:160-32863:161.

8510180406 Responds to appeal re denial of FOIA request for GE PRA for GESSAR-II standardized plant design. Forwards 11 pages from PRA due to court approved stipulation of 850718 settlement. Info also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. CURRAN, D. Harmon, Weiss & Jordan. 1p. 33078:018-33078:040.

8510180410 PRA documentation for GESSAR-II standardized plant design.
* General Electric Co. 85/10/11. 11pp. 33078:019-33078:040.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510210227 Summary of ACRS Subcommittees on GESSAR II, Reliability & Probabilistic Assessment & Safeguards & Security 850327-29 combined meetings w/Sandia, GE & BNL in Albuquerque, NM re GESSAR II future final design approvals.
* ACRS - Advisory Committee on Reactor Safeguards. 85/07/11. ACRS - Advisory Committee on Reactor Safeguards. 13pp. 33094:289-33094:301.

DOCKET STN-50-454 BYRON STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppl & correspondence

8510110106 Forwards SSER supporting util 850725 proposed FSAR change incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33011:345-33011:350.

8510110114 SSER supporting util 850725 proposed FSAR change, incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
* NRC - No Detailed Affiliation Given. 85/10/07. 3pp. 33011:348-33011:350.

F. Security, medical, emergency & fire protection plans

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested.
AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33023:264-33023:345.

8510080430 Application for amend to License NPF-37, correcting typos & grammatical errors contained in Tech Spec Pages 3/4 3-15, 3/4 6-7, 3/4 7-44, 3/4 8-5, 3/4 11-8 & 6-3. Fee paid.
AINGER, K.A. Commonwealth Edison Co. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:244-32921:254.

8510080434 Proposed Tech Spec changes, correcting typos & grammatical errors contained in Pages 3/4 3-15, 3/4 6-7, 3/4 7-44, 3/4 8-5, 3/4 11-8 & 6-3 re fire hose stations. Significant hazards consideration encl.
* Commonwealth Edison Co. 85/09/27. 9pp. 32921:246-32921:254.

8510100062 Rev 5 to BZP 200-A1, "Byron Emergency Action Levels" & Rev 4 to BZP 500-1, "Operability Checks of Communication Sys (Primary Responsibility - Operations Director)."
* Commonwealth Edison Co. 85/09/28. 23pp. 32961:027-32961:050.

8510090109 Forwards Amend 1 to License NPF-37 & safety evaluation. Amend approves changes to Tech Specs re administrative controls for access to high radiation areas during emergency situations. Amend also applies to Unit 2.
YOUNGBLOOD, B.J. Licensing Branch 2. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 5pp. 32951:347-32951:359.

8510090115 Amend 1 to License NPF-37, approving changes to Tech Specs re administrative controls for access to high radiation areas during certain emergency situations. Amend also applies to Unit 2.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/01. 5pp. 32951:352-32951:356.

8510080479 Ack receipt of FEMA 850829 ltr & final exercise evaluation of 850611-12 offsite emergency preparedness exercise involving State of IL & Ogle County. No deficiencies identified.
SHAFFER, W.D. Region 3, Office of Director. 85/10/03. REED, C. Commonwealth Edison Co. 2pp. 32921:073-32921:103.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises.
BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510210008 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13 & notice of violation.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33072:022-33072:038.

8510210018 Notice of violation from insp on 850909-13.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. 1p. 33072:024-33072:024.

8510210047 Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13. Violation noted: failure to complete required quarterly inventories of emergency supplies in technical support ctr & operational support ctr between Apr & Sept 1985.
PLOSKE, T., PATTERSON, J., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 14pp. 33072:025-33072:038.

8510150078 Approves use of revised acceptance criteria for Firecode CT gypsum fire stops, per 850730 request. Gypsum & thermal fiber fire penetration seals similar in configuration to seals at LaSalle.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/08. FARRAR, D.L. Commonwealth Edison Co. 4pp. 33030:293-33030:302.

8510180339 Rev 4 to Emergency Plan Implementing Procedures BZP 500-T1, "Checklist-Communication Checks" & BZP 400-T8, "Checklist-Environ Monitoring Supplies." * Commonwealth Edison Co. 85/10/09. 15pp. 33060:252-33060:266.

8510210043 Forwards Security Insp Rept 50-454/85-40 on 850916-19. No noncompliance noted. AXELSON, W.L. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33072:310-33072:312.

8510210051 Physical Security Insp Rept 50-454/85-40 on 850916-19. No noncompliance noted. Major areas inspected: security organization performance, including security training, mgt & maint programs. Details withheld (ref 10CFR73.21). BELANGER, J.L., KNICELEY, J.R., CREED, J.R. Region 3, Office of Director. 85/10/16. 1p. 33072:312-33072:312.

8510220170 Ask receipt of encl FEMA 850917 ltr including revised schedule of corrective actions by State of IL for recommendations identified as result of 850611-12 exercise. Schedule reviewed & responses adequate. SHAFER, W.D. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33090:031-33090:036.

J. Insurance & Indemnity information

8510300064 Forwards unexecuted Amends 23.4 & 5 to Indemnity Agreements B-10, B-97 & B-84, respectively, modifying location descriptions to conform to facility forms. DINITZ, J. Office of State Programs, Director. 85/10/25. OSTER, J. Commonwealth Edison Co. 4pp. 33261:353-33261:356.

P. Operating license stage documents & correspondence

8510010111 Forwards revised FSAR Table 14.2-78, "Control Rod Reactivity Worth Measurement," in response to Violation 1a noted in 850801 ltr, to more clearly indicate testing limitations associated w/validating rod worths. AINGER, K.A. Commonwealth Edison Co. 85/09/16. KEPPLER, J.G. Region 3, Office of Director. 2pp. 32801:296-32801:297.

8510080430 Application for amend to License NPF-37, correcting typos & grammatical errors contained in Tech Spec Pages 3/4 3-15, 3/4 6-7, 3/4 7-44, 3/4 8-5, 3/4 11-8 & 6-3. Fee paid. AINGER, K.A. Commonwealth Edison Co. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:244-32921:254.

8510080434 Proposed Tech Spec changes, correcting typos & grammatical errors contained in Pages 3/4 3-15, 3/4 6-7, 3/4 7-44, 3/4 8-5, 3/4 11-8 & 6-3 re fire hose stations. Significant hazards consideration encl. * Commonwealth Edison Co. 85/09/27. 9pp. 32921:246-32921:254.

8510040301 Forwards fee for NRC review of util 850416 request for scheduler exemption from requirement to submit updated FSAR. AINGER, K.A. Commonwealth Edison Co. 85/09/30. DIGGS, R.M. License Fee Management Branch. 1p. 32853:359-32853:359.

8510090109 Forwards Amend 1 to License NPF-37 & safety evaluation. Amend approves changes to Tech Specs re administrative controls for access to high radiation areas during emergency situations. Amend also applies to Unit 2. YOUNGBLOOD, B.J. Licensing Branch 2. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 5pp. 32951:347-32951:359.

8510090115 Amend 1 to License NPF-37, approving changes to Tech Specs re administrative controls for access to high radiation area during certain emergency situations. Amend also applies to Unit 2. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/01. 5pp. 32951:352-32951:356.

8510090120 Safety evaluation supporting Amend 1 to License NPF-37. Amend also applies to Unit 2. * Office of Nuclear Reactor Regulation, Director. 85/10/01. 3pp. 32951:357-32951:359.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes. ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.

8510110058 Rev 38 to "QA Program for Nuclear Generating Stations." * Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.

8510150475 Forwards "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, Item 1.2 'Post-Trip Review Data & Info Capabilities' for Byron Station, Units 1 & 2," technical evaluation rept. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/09. FARRAR, D.L. Commonwealth Edison Co. 2pp. 33033:139-33033:154.

8510150480 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, Item 1.2 'Post-Trip Review Data & Info Capabilities' for Byron Station, Units 1 & 2," technical evaluation rept. * Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-2. 85/10/09. 14pp. 33033:141-33033:154.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested. ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010:332-33010:337.

8510290348 Determines that no adverse findings identified as result of review of amend to License NPF-37 to correct typo &/or grammatical changes. PARKER, M.C. Illinois, State of. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33234:337-33234:337.

Q. Inspection reports, IE Bulletins & correspondence

8510040246 Responds to NRC 850516 ltr re violations noted in Insp Rept 50-454/85-16. Corrective actions: technical staff memos written to stress importance of maintaining operable plant status during operating surveillances & tests. FARRAR, D.L. Commonwealth Edison Co. 85/06/14. KEPPLER, J.G. Region 3, Office of Director. 11pp. 32850:334-32850:346.

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in Insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested. AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33023:264-33023:265.

8510010111 Forwards revised FSAR Table 14.2-78, "Control Rod Reactivity Worth Measurement," in response to Violation 1a noted in 850801 ltr, to more clearly indicate testing limitations associated w/validating rod worths. AINGER, K.A. Commonwealth Edison Co. 85/09/16. KEPPLER, J.G. Region 3, Office of Director. 2pp. 32801:296-32801:297.

8510010434 Responds to NRC 850820 ltr re violations noted in Insp Rept 50-454/85-03. Corrective actions: mod made to refueling water storage tank heating pump circuitry to extend high temp heater cutoff function to manual mode. FARRAR, D.L. Commonwealth Edison Co. 85/09/18. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32804:093-32804:095.

8510030049 EN-85-068 on 851002, notice of violation & proposed imposition of civil penalties in amount of \$50,000 will be issued to licensee. Action based on events, including failure of mgt to follow radiation protection procedures. KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/26. 1p. 32843:112-32843:112.

8510040428 Forwards fee for 850831 request for emergency relief from preservice insp requirement for facility. AINGER, K.A. Commonwealth Edison Co. 85/09/27. DIGGS, R.M. License Fee Management Branch. 1p. 32853:360-32853:360.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maintenance Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070386 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-42 on 850828 & 29 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/01. REED, C. Commonwealth Edison Co. 2pp. 32878:304-32878:314.

8510070420 Notice of violation from insp on 850828-29. SHAFER, W.D. Region 3, Office of Director. 85/10/01. 2pp. 32878:306-32878:307.

8510070427 Insp Repts 50-454/85-38 & 50-455/85-42 on 850828-29. Violation noted: failure to follow liquid radwaste release procedures & to take timely action when Tech Spec release limit exceeded. HUETER, L.J., SCHUMACHER, M.C. Region 3, Office of Director. 85/09/30. 7pp. 32878:308-32878:314.

8510070362 Discusses insp on 850506-0722 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000. Three events cited re failure to follow radiation protection procedures. KEPPLER, J.G. Region 3, Office of Director. 85/10/02. O'CONNOR, J.J. Commonwealth Edison Co. 4pp. 32877:203-32877:237.

8510070368 Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violation noted: Procedure BOP-IC-03 re in-core moveable detectors did not restrict containment entry while in-core detectors withdrawn. KEPPLER, J.G. Region 3, Office of Director. 85/10/02. 4pp. 32877:207-32877:237.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises. BROWN, G.A., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510210008 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33072:022-33072:038.

8510210018 Notice of violation from insp on 850909-13. SHAFER, W.D. Region 3, Office of Director. 85/10/04. 1p. 33072:024-33072:024.

8510210047 Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13. Violation noted: failure to complete required quarterly inventories of emergency supplies in technical support ctr & operational support ctr between Apr & Sept 1985. PLOSKI, T., PATTERSON, J., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 14pp. 33072:025-33072:038.

8510220073 Forwards Safety Insp Rept 50-454/85-35 on 850805-1002. No violations noted. HARRISON, J.J. Region 3, Office of Director. 85/10/10. REED, C. Commonwealth Edison Co. 2pp. 33095:169-33095:177.

8510220077 Safety Insp Rept 50-454/85-35 on 850805-1002. No violation or deviation noted. Major areas inspected: previous insp findings & startup test results evaluation. VANDENBURGH, C., RING, M.A. Region 3, Office of Director. 85/10/10. 7pp. 33095:171-33095:177.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

228 DOCKETED ITEMS

8510210011 Forwards Safety Insp Rept 50-454/85-39 on 850904-1001 & notice of violation.
WARNICK,R.F. Region 3, Office of Director. 85/10/15. REED,C. Commonwealth Edison Co. 2pp. 33074:112-33074:126.

-8510210012 Notice of violation from insp on 850904-1001.
WARNICK,R.F. Region 3, Office of Director. 85/10/15. 2pp. 33074:114-33074:115.

-8510210013 Safety Insp Rept 50-454/85-39 on 850904-1001. Violation noted: failure to perform Tech Spec surveillances for RCS water inventory balance when required.
FORNEY,W.L. Region 3, Office of Director. 85/10/15. 11pp. 33074:116-33074:126.

8510210043 Forwards Security Insp Rept 50-454/85-40 on 850916-19. No noncompliance noted.
AXELSON,W.L. Region 3, Office of Director. 85/10/16. REED,C. Commonwealth Edison Co. 2pp. 33072:310-33072:312.

-8510210051 Physical Security Insp Rept 50-454/85-40 on 850916-19. No noncompliance noted. Major areas inspected: security organization performance, including security training, mgt & maint programs. Details withheld (ref 10CFR73.21).
BELANGER,J.L., KNICELEY,J.R., CREED,J.R. Region 3, Office of Director. 85/10/16. 1p. 33072:312-33072:312.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High P aging W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510280337 Forwards notice of violation omitted from encls to 851002 ltr re Radiation Protection Insp Repts 50-454/85-22 & 50-455/85-20 on 850506-0722.
HIND,J.A. Region 3, Office of Director. 85/10/21. REED,C. Commonwealth Edison Co. 2pp. 33193:108-33193:110.

-8510280345 Notice of violation from insp on 850506-0722. Violation noted: failure to issue permanent or temporary procedure change describing lineup through which diluted reactor coolant water transferred from recycle holdup tanks.
HIND,J.A. Region 3, Office of Director. 85/10/21. 1p. 33193:110-33193:110.

8510280347 Forwards Safety Insp Repts 50-454/85-44 & 50-455/85-43 on 851003. No violation noted.
HARRISON,J.J. Region 3, Office of Director. 85/10/22. REED,C. Commonwealth Edison Co. 2pp. 33192:355-33192:360.

-8510280351 Insp Repts 50-454/85-44 & 50-455/85-43 on 851003. No violation or deviation noted. Major areas inspected: modified Boeing steam generator snubber production tests conducted by ITT Grinnell.
YIN,T.T., DANIELSON,D.H. Region 3, Office of Director. 85/10/22. 4pp. 33192:357-33192:360.

R. Periodic operating reports & related correspondence

8510220399 "Environ Radiological Monitoring for Byron Nuclear Power Station, Commonwealth Edison Co. Annual Rept 1984."
HUEBNER,L.G. Teledyne Isotopes. 84/12/31. 68pp. 33097:132-33097:199.

S. Reportable occurrences, LERs & related correspondence

8510030335 LER 85-085-00 on 850829, determined that two ASME Code Class 2 welds in safety injection sys not examined per ASME requirements. Caused by misidentification of weld for exam. Relief from requirements granted on 850903 W/850923 ltr.
EWALD,J.J., QUERIO,R.E. Commonwealth Edison Co. 85/09/23. 5pp. 32845:173-32845:177.

8510040480 LER 85-081-01 on 850731, following completion of RHR pump operability surveillance. RHR sys declared inoperable. Caused by testing valve lineup that allowed only two of four cold legs to be available during accident. W/850923 ltr.
WURZE, K.L., BRIDE,C.A., QUERIO,R.E. Commonwealth Edison Co. 85/09/23. 3pp. 32865:243-32865:245.

8510030375 LER 85-086-00 on 850829, MSIVs declared inoperable. Caused by environmentally unqualified terminal strips located in junction boxes on MSIVs. Strips removed & wires reattached. W/850927 ltr.
ROBERT,M.M., QUERIO,R.E. Commonwealth Edison Co. 85/09/27. 3pp. 32846:063-32846:065.

8510040432 LER 85-088-00 on 850908 & 11, process radiation monitors OPR34J & OPR33J, respectively, went into interlock mode. Caused by noise spike on monitor gas channels. Train B ventilation sys transferred to ESF configuration. W/850927 ltr.
RYTTERSKI,M., QUERIO,R.E. Commonwealth Edison Co. 85/09/27. 4pp. 32866:356-32866:359.

8510090364 LER 85-087-00 on 850902, four auxiliary bldg sprinkler sys did not alarm when tested & 10 h elapsed before surveillance entered. Caused by failure of equipment attendants to inform shift engineer. W/850927 ltr.
DIAZ,C., QUERIO,R.E. Commonwealth Edison Co. 85/09/27. 3pp. 32946:117-32946:119.

8510170374 Final Deficiency Repts 85-04(BY) & 85-07(BW) re faulty tachometer readings on emergency diesel generators. Initially reported on 850905. Dc-to-dc regulator replaced w/dc-to-dc converter. All similar tachometer circuits will be revised.
MOSIAJ,D. Commonwealth Edison Co. 85/10/04. KEPLER,J. Region 3, Office of Director. 2pp. 33053:330-33053:331.

8510170386 LER 85-089-00 on 850913, both trains of control room ventilation inoperable. Caused by workers misreading HVAC ductwork drawings. Project const dept will review HVAC drawing conventions w/personnel responsible. W/851008 ltr.
TILLMANN,T., QUERIO,R.E. Commonwealth Edison Co. 85/10/08. 5pp. 33053:322-33053:326.

8510310407 LER 85-084-00 on 850924, fire watch delayed. Caused by key stuck in vital area door lock. Fire watch resumed after another security person arrived to attend door lock repaired. W/851024 ltr.
CASSIDY,R., QUERIO,R.E. Commonwealth Edison Co. 85/10/24. 2pp. 33280:313-33280:314.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030063 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI,J.A. Operating Reactors Branch 5. 85/10/01. FARRAR,D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

DOCKET STN-50-455 BYRON STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510010111 Forwards revised FSAR Table 14.2-78, "Control Rod Reactivity Worth Measurement" in response to Violation 1a noted in 850801 ltr, to more clearly indicate testing limitations. Validating rod worths.
AINGER,K.A. Commonwealth Edison Co. 85/09/16. KEPLER,J.G. Region 3, Office of Director. 2pp. 32801:296-32801:297.

8510080440 Application for amends to CPPR-131, CPPR-132 & CPPR-133, incorporating partial exemption from GDC 4 to allow implementation of leak-before-break concept on RCS primary loops. Fee paid.
AINGER,K.A. Commonwealth Edison Co. 85/09/25. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:242-32921:243.

8510040301 Forwards fee for NRC review of util 850416 request for schedular exemption from requirement to submit updated FSAR.
AINGER,K.A. Commonwealth Edison Co. 85/09/30. DIGGS,R.M. License Fee Management Branch. 1p. 32853:359-32853:359.

8510090109 Forwards Amend 1 to License NPF-37 & safety evaluation. Amend approves changes to Tech Specs re administrative controls for access to high radiation areas during emergency situations. Amend also applies to Unit 2.
YOUNGBLOOD,B.J. Licensing Branch 2. 85/10/01. FARRAR,D.L. Commonwealth Edison Co. 5pp. 32951:347-32951:359.

-8510090115 Amend 1 to License NPF-37, approving changes to Tech Specs re administrative controls for access to high radiation area during certain emergency situations. Amend also applies to Unit 2.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/01. 5pp. 32951:352-32951:356.

-8510090120 Safety evaluation supporting Amend 1 to License NPF-37. Amend also applies to Unit 2.
Office of Nuclear Reactor Regulation, Director. 85/10/01. 3pp. 32951:357-32951:359.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER,G.L. Commonwealth Edison Co. 85/10/03. KEPLER,J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.

-8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.

8510220271 Requests concurrence w/ & discusses proposed change to startup test evaluation process. Encl FSAR revs will be included in next FSAR amend.
AINGER,K.A. Commonwealth Edison Co. 85/10/07. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33087:341-33087:345.

8510150475 Forwards "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, Item 1.2 'Post-Trip Review: Data & Info Capabilities' for Byron Station Units 1 & 2," technical evaluation rept.
YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/09. FARRAR,D.L. Commonwealth Edison Co. 2pp. 33033:139-33033:154.

-8510150480 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28, Item 1.2 'Post-Trip Review: Data & Info Capabilities' for Byron Station Units 1 & 2," technical evaluation rept.
Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1525-2. 85/10/09. 14pp. 33033:141-33033:154.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER,G. Commonwealth Edison Co. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010:332-33010:337.

8510280349 Forwards 17769-1, "Electrical Cable Separation Verification Testing," in response to Power Sys Branch 850715 request for addl info. Test rept listed as Ref 1 in Sargent & Lundy Calculation 19 Q-14.
MOSIAJ,D. Commonwealth Edison Co. 85/10/22. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33193:262-33193:262.

-8510280355 "Electrical Cable Separation Verification Testing."
HENLEY,J.C., JOHNSON,F.R., HIGHT,G.W. Wyle Laboratories. 17769-1. 85/08/27. 104pp. 33193:263-33194:005.

E. MRC Safety Evaluation Report (SER), suppl & correspondence

8510110106 Forwards SSER supporting util 850725 proposed FSAR change incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33011:345-33011:350.

-8510110114 SSER supporting util 850725 proposed FSAR change, incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2. * NRC - No Detailed Affiliation Given. 85/10/07. 3pp. 33011:348-33011:350.

F. Security, medical, emergency & fire protection plans

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in Insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested. AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. App. 33023:264-33023:345.

8510100062 Rev 5 to BZP 200-A1, "Byron Emergency Action Levels" & Rev 4 to BZP 500-1, "Operability Checks of Communication Sys (Primary Responsibility - Operations Director)." * Commonwealth Edison Co. 85/09/28. 23pp. 32961:027-32961:050.

8510090109 Forwards Amend 1 to License NPF-37 & safety evaluation. Amend approves changes to Tech Specs re administrative controls for access to high radiation areas during emergency situations. Amend also applies to Unit 2. YOUNGBLOOD, B.J. Licensing Branch 2. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 5pp. 32951:347-32951:359.

-8510090115 Amend 1 to License NPF-37, approving changes to Tech Specs re administrative controls for access to high radiation area during certain emergency situations. Amend also applies to Unit 2. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/01. 5pp. 32951:352-32951:356.

8510080479 Ack receipt of FEMA 850829 ltr & final exercise evaluation of 850611-12 offsite emergency preparedness exercise involving State of IL & Ogle County. No deficiencies identified. SHAFER, W.D. Region 3, Office of Director. 85/10/03. REED, C. Commonwealth Edison Co. 2pp. 32921:073-32921:103.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises. BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510210008 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33072:022-33072:038.

-8510210018 Notice of violation from insp on 850909-13. SHAFER, W.D. Region 3, Office of Director. 85/10/04. 1p. 33072:024-33072:024.

-8510210047 Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13. Violation noted: failure to complete required quarterly inventories of emergency supplies in technical support ctr & operational support ctr between Apr & Sept 1985. PLOSKI, T. Region 3, Office of Director. 85/10/04. 14pp. 33072:025-33072:038.

8510150078 Approves use of revised acceptance criteria for Firecode CT gypsum fire stops, per 850730 request. Gypsum & thermal fiber fire penetration seals similar in configuration to seals at LaSalle. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/08. FARRAR, D.L. Commonwealth Edison Co. 4pp. 33030:293-33030:302.

8510180339 Rev 4 to Emergency Plan Implementing Procedures BZP 500-T1, "Checklist-Communication Checks" & BZP 400-T8, "Checklist-Environment Monitoring Supplies." * Commonwealth Edison Co. 85/10/09. 15pp. 33060:252-33060:266.

8510220170 Ack receipt of encl FEMA 850917 ltr including revised schedule of corrective actions by State of IL for recommendations identified as result of 850611-12 exercise. Schedule reviewed & responses adequate. SHAFER, W.D. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33090:031-33090:036.

8510280275 Informs that util must commit to full compliance w/ Commission forthcoming response to GUARD remand & confirm that emergency plans include list of local or regional medical facilities which can treat exposure cases. YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/23. FARRAR, D.L. Commonwealth Edison Co. 8pp. 33228:199-33228:206.

G. Inspection reports, IE Bulletins & correspondence

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in Insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested. AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. App. 33023:264-33023:345.

8510010409 Forwards Safety Insp Rept 50-455/85-25 on 850716-0916. No violation identified. WARNICK, R.F. Region 3, Office of Director. 85/09/26. REED, C. Commonwealth Edison Co. 2pp. 32803:257-32803:266.

-8510010416 Insp Rept 50-455/85-25 on 850716-0916. No violation or deviation noted. Major areas inspected: licensee action on IE bulletins, 10CFR21 repts, preoperational test result evaluation verification & sys flush procedure review. FORNEY, W.L. Region 3, Office of Director. 85/09/25. 8pp. 32803:259-32803:266.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070386 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-42 on 850828 & 29 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/01. REED, C. Commonwealth Edison Co. 2pp. 32878:304-32878:314.

-8510070427 Insp Repts 50-454/85-38 & 50-455/85-42 on 850828-29. Violation noted: failure to follow liquid radwaste release procedures & to take timely action when Tech Spec release limit exceeded. HUETER, L.J., SCHUMACHER, M.C. Region 3, Office of Director. 85/09/30. 7pp. 32878:308-32878:314.

8510070362 Discusses insp on 850506-0722 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000. Three events cited re failure to follow radiation protection procedures. KEPLER, J.G. Region 3, Office of Director. 85/10/02. O'CONNOR, J.J. Commonwealth Edison Co. 4pp. 32877:203-32877:237.

8510160248 Forwards Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920 re emergency preparedness. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33026:219-33026:222.

-8510160270 Mgt Meeting Repts 50-295/85-35, 50-304/85-37, 50-373/85-31, 50-374/85-32, 50-454/85-41 & 50-455/85-29 on 850920. Major areas discussed: items re exercise scheduling for FY86 exercises. BROWN, G.A. Region 3, Office of Director. 85/10/04. 2pp. 33026:221-33026:222.

8510210008 Forwards Safety Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13 & notice of violation. SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33072:022-33072:038.

-8510210018 Notice of violation from insp on 850909-13. SHAFER, W.D. Region 3, Office of Director. 85/10/04. 1p. 33072:024-33072:024.

-8510210047 Insp Repts 50-454/85-38 & 50-455/85-34 on 850909-13. Violation noted: failure to complete required quarterly inventories of emergency supplies in technical support ctr & operational support ctr between Apr & Sept 1985. PLOSKI, T., PATTERSON, J., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 14pp. 33072:025-33072:038.

8510230056 Forwards rept of analysis & disposition of ultrasonic indications identified in steam generators & pressurizer. Add repairs to steam generators or pressurizer unwarranted. Concurrence requested. AINGER, K.A. Commonwealth Edison Co. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 62pp. 33102:092-33102:175.

-8510230061 "Metallurgical Investigation of Recorded UT Indications in Steam Generator Stub Barrel to Lower Shell Welds at Byron II Station." RAO, G.V., MEYER, T.A. Westinghouse Electric Corp. MT-SMART-726. 85/07/31. 19pp. 33102:154-33102:175.

8510150022 IE Info Notice 85-C80, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510250382 Confirms NRC plan to perform independent verification insp of const on 851028-1108. Const activities & mats will be sampled through NDEs. Add info on documentation selected for insp encl. NOELIUS, C.E. Region 3, Office of Director. 85/10/18. REED, C. Commonwealth Edison Co. 8pp. 33172:152-33172:157.

8510280337 Forwards notice of violation omitted from encls to 851002 ltr re Radiation Protection Insp Repts 50-454/85-22 & 50-455/85-20 on 850506-0722. HIND, J.A. Region 3, Office of Director. 85/10/21. REED, C. Commonwealth Edison Co. 2pp. 33193:108-33193:110.

-8510280345 Notice of violation from insp on 850506-0722. Violation noted: failure to issue permanent or temporary procedure change describing lineup through which diluted reactor coolant water transferred from recycle holdup tanks. HIND, J.A. Region 3, Office of Director. 85/10/21. 1p. 33193:110-33193:110.

8510280347 Forwards Safety Insp Repts 50-454/85-44 & 50-455/85-43 on 851003. No violation noted. HARRISON, J.J. Region 3, Office of Director. 85/10/22. REED, C. Commonwealth Edison Co. 2pp. 33192:355-33192:360.

230 DOCKETED ITEMS

—8510280351 Insp Repts 50-454/85-44 & 50-455/85-43 on 851003. No violation or deviation noted. Major areas inspected: modified Boeing steam generator snubber production tests conducted by ITT Grinnell.
YIN, T.T., DANIELSON, D.H. Region 3, Office of Director. 85/10/22. 4pp. 33192:357-33192:360.

R. Periodic operating reports & related correspondence

8510220399 "Environ Radiological Monitoring for Byron Nuclear Power Station, Commonwealth Edison Co., Annual Rept 1984."
HUEBNER, L.G. Teledyne Isotopes. 84/12/31. 68pp. 33097:132-33097:199.

S. Reportable occurrences, LERs & related correspondence

8510170374 Final Deficiency Repts 85-04(BY) & 85-07(BW) re faulty tachometer readings on emergency diesel generators. Initially reported on 850905. Dc-to-dc regulator replaced w/dc-to-dc converter. All similar tachometer circuits will be revised.
MIOSI, A.D. Commonwealth Edison Co. 85/10/04. KEPPLER, J. Region 3, Office of Director. 2pp. 33053:330-33053:331.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510310111 Forwards revised FSAR Table 14.2-78, "Control Rod Reactivity Worth Measurement," in response to Violation 1a noted in 850801 ltr, to more clearly indicate testing limitations associated w/validating rod worths.
AINGER, K.A. Commonwealth Edison Co. 85/09/16. KEPPLER, J.G. Region 3, Office of Director. 2pp. 32801:296-32801:297.

8510080440 Application for amends to CPPR-131, CPPR-132 & CPPR-133, incorporating partial exemption from GDC 4 to allow implementation of leak-before-break concept on RCS primary loops. Fee paid.
AINGER, K.A. Commonwealth Edison Co. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32321:242-32921:243.

8510040301 Forwards fee for NRC review of util 850416 request for scheduler exemption from requirement to submit updated FSAR.
AINGER, K.A. Commonwealth Edison Co. 85/09/30. DIGGS, R.M. License Fee Management Branch. 1p. 32853:359-32853:359.

8510110036 Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.

—8510110058 Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.

8510150182 Requests review of encl first draft Tech Specs, based on util 850717 submittal. Proposed changes to Braidwood draft Tech Specs applicable to Byron cannot be incorporated until Byron changes approved. W/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33031:096-33031:098.

8510220271 Requests concurrence w/& discusses proposed change to startup test evaluation process. Encl FSAR revs will be included in next FSAR amend.
AINGER, K.A. Commonwealth Edison Co. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33087:341-33087:345.

8510150204 Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010:332-33010:337.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

—8510170174 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities'..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC. 03-82-096. SAIC-85/1521-1. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 3:44:057-33044:066.

8510280349 Forwards 17769-1, "Electrical Cable Separation Verification Testing," in response to Power Sys Branch 850715 request for addl info. Test rept listed as Ref 1 in Sargent & Lundy Calculation 19 Q-14.
MIOSI, A.D. Commonwealth Edison Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33193:262-33193:262.

—8510280355 "Electrical Cable Separation Verification Testing."
HENLEY, J.C., JOHNSON, F.R., HIGHT, G.W. Wyle Laboratories. 17769-1. 85/08/27. 104pp. 33193:262-33194:005.

8510310351 Forwards Science Applications Intl Corp draft technical evaluation rept re util response to Generic Ltr 83-28, Item 1.2 on Salem ATWS events. Response incomplete in five areas. Addl info requested to complete review.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/24. FARRAR, D.L. Commonwealth Edison Co. 1p. 33278:166-33278:179.

N. NRC Safety Evaluation Report (SER), supp's & correspondence

8510110106 Forwards SSER supporting util 850725 proposed FSAR change incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33011:345-33011:350.

—8510110114 SSER supporting util 850725 proposed FSAR change, incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
* NRC - No Detailed Affiliation Given. 85/10/07. 3pp. 33011:348-33011:350.

F. Security, medical, emergency & fire protection plans

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in Insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested.
AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33023:264-33023:345.

8510020370 Forwards booklet, "Emergency Info - Braidwood," referenced by LD Butterfield in testimony served on 850920. Applicant intends to submit booklet into evidence at hearings on Rorem Contention 1(a). Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 645. 85/09/27. GROSSMAN, H., BRENNER, L., COLE, R.F. Atomic Safety and Licensing Board Panel. 17pp. 32824:350-32825:004.

8510040303 Revised emergency plan procedures, including Rev 1 to BwZP 200-2A4, "Reactor Power History & Core Inventory Determinations" & Rev 1 to BwZP 200-2A7, "Example of Core Damage Assessment."
* Commonwealth Edison Co. 85/09/27. 57pp. 32853:192-32853:248.

8510080177 Revised procedures, including Rev 0 to BwZP 500-4, "Operational Support Ctr Inventory," Rev 0 to BwZP 500-5, "Technical Support Ctr Inventory" & Rev 0 to BwZP 600-3, "Station Group Directory."
* Commonwealth Edison Co. 85/10/02. 24pp. 32920:019-32920:042.

8510110079 Rev 1 to Operational Support Ctr Implementing Procedure BWZP 400-2, "Primary Responsibility - Operations Director."
* Commonwealth Edison Co. 85/10/04. 5pp. 32973:001-32973:005.

8510170330 Forwards Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No non-compliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33051:305-33051:310.

—8510170335 Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No violations or deviations noted. Major areas inspected: emergency preparedness program, including facilities & equipment training & implementing procedures.
PLOSKE, T., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 4pp. 33051:307-33051:310.

8510150078 Approves use of revised acceptance criteria for Firecode CT gypsum fire stops, per 850730 request. Gypsum & thermal fiber fire penetration seals similar in configuration to seals at LaSalle.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/08. FARRAR, D.L. Commonwealth Edison Co. 4pp. 33030:293-33030:302.

8510240354 Forwards supplemental testimony of LD Butterfield on Rorem Contention 1(a) re issues arising under requirements for news media arrangements for disseminating info during emergency. Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 877. 85/10/22. GROSSMAN, H., CALLIHAN, A.D., BRENNER, L. Atomic Safety and Licensing Board Panel. 2pp. 33153:347-33154:025.

—8510240363 Supplemental testimony of LD Butterfield on Rorem Contention 1(a) re dissemination of info to news media in event of emergency. Certificate of Svc encl. Related correspondence.
BUTTERFIELD, L. Commonwealth Edison Co. 85/10/22. 39pp. 33153:349-33154:025.

8510280275 Informs that util must commit to full compliance w/ Commission forthcoming response to GUARD remand & confirm that emergency plans include list of local or regional medical facilities which can treat exposure cases.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/23. FARRAR, D.L. Commonwealth Edison Co. 8pp. 33228:199-33228:206.

G. Adjudicatory correspondence

8510020235 Memorandum & order ruling on intervenor 850904 motion to compel discovery from applicant & NRC Motion to compel on interrogatories 1-9, 17, 19, 50-52, 57 & part of 58 granted. Interrogatories 58 & 59 denied. Served on 850930.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 649. 85/09/27. Commonwealth Edison Co. 11pp. 32824:252-32824:262.

8510020370 Forwards booklet, "Emergency Info - Braidwood," referenced by LD Butterfield in testimony served on 850920. Applicant intends to submit booklet into evidence at hearings on Rorem Contention 1(a). Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 645. 85/09/27. GROSSMAN, H., BRENNER, L., COLE, R.F. Atomic Safety and Licensing Board Panel. 17pp. 32824:350-32825:004.

8510030019 Order setting further scheduling for Oct 1985 to Feb 1986. Served on 851002.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 663. 85/10/01. 3pp. 32843:073-32843:075.

8510030065 Order confirming rulings made during 850930 telcon. ASLB will convene hearing on Rorem Contention 1(a) on 851029. Based on agreement of parties, ASLB authorizes mailing of emergency planning booklet in present form. Served on 851002. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 662. 85/10/01. Office of the Executive Legal Director. 2pp. 32843-004-32843-004.

8510040329 Provides assessment on util position re Contention 1(a) filed by NRC on 850828. Applicant stands on 850815 motion that no issue under 10CFR50.47(b)(5) should be entertained under Contention 1(a). GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. #485 669. 85/10/02. GROSSMAN, H., BRENNER, L., CALLIHAN, A.D. Atomic Safety and Licensing Board Panel. 2pp. 32653-249-32653-250.

8510100183 Order directing BL Rorem to respond by 851011 to applicant 850815 motion to particularize Rorem Contention 1(a). Served on 851004. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 716. 85/10/03. Rorem, B. 2pp. 32962-124-32962-125.

8510100091 Memorandum & order granting confidential treatment of names & otherwise identifying info re prospective witnesses on BL Rorem QA contention. Served on 851007. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 692. 85/10/04. Rorem, B. 3pp. 32961-114-32961-122.

8510100212 Notice of 851029 evidentiary hearing in Joliet, IL to discuss Rorem Contention 1(a) re dissemination of info to public on evacuation or other protective measures in event of radiological emergency. Served on 851007. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 696. 85/10/04. 2pp. 32962-081-32962-082.

8510110221 Forwards intervenors answer opposing petitions by Comm Ed for waiver of NRC regulation & for review of ASLB decision, consisting of 10-page brief w/one attachment. GUILD, R. Business & Professional People for the Public Interest. GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 728. 85/10/07. CHILK, S.L. Office of the Secretary of the Commission. 1p. 32972-253-32972-274.

-8510110222 Response opposing petitions by Comm Ed for waiver of Commission regulation & for review of ASLB decision. GUILD, R. Rorem, B. GUILD, R. Guild, R. 85/10/07. Atomic Safety and Licensing Appeal Panel. 10pp. 32972-254-32972-274.

8510110077 NRC brief in support of util 850923 motion for exemption from 10CFR2.786(b)(1) re prohibiting party from seeking review of ASLB decision on petition for directed certification. Affidavit encl. BERRY, G.A. Hearing Branch 1. #485 731. 85/10/08. Commissioners. 15pp. 32973-006-32973-027.

-8510110083 Affidavit of J.G. Keppler re 850621 util late-filed amended QA contention. Certificate of Svc encl. KEPPLER, J.G. Region 3, Office of Director. 85/10/08. 7pp. 32973-022-32973-027.

8510110085 Notice of appearance in proceeding. Certificate of Svc encl. STYLES, L.B. Commonwealth Edison Co. STYLES, L.B. Isham, Lincoln & Beale. #485 726. 85/10/08. 3pp. 32973-306-32973-308.

8510110133 Forwards affidavits of JW Gieseke, RV Seltmann & DA Hoffer supporting util sixth partial response to intervenor first set of QA interrogatories & request to produce. Related correspondence. STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 723. 85/10/08. GUILD, R. Guild, R. 2pp. 32971-253-32971-263.

-8510110136 Affidavit of JW Gieseke supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Related correspondence. GIESEKER, J.W. Commonwealth Edison Co. 85/09/19. 5pp. 32971-255-32971-259.

-8510110139 Affidavit of RV Seltmann supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Related correspondence. SELTMANN, R.V. Commonwealth Edison Co. 85/10/02. 3pp. 32971-260-32971-263.

-8510110142 Affidavit of DA Hoffer supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Certificate of Svc encl. Related correspondence. HOFFER, D.A. Commonwealth Edison Co. 85/09/06. 32pp. 32971-264-32971-295.

8510150306 Server notice that deposition of J.I. Joyce rescheduled for 851015 at author law ofcs in Chicago, IL. Uncertainty of Joyce appearing as witness (per 850930 telcon) should be resolved by 851011 file date. Related correspondence. COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 767. 85/10/08. JOYCE, J.J. Illinois, State of. ROREM, B.L. Rorem, B. 1p. 33009-089-33009-089.

8510160208 Requests that applicant motion to restrict meaning of Contention 1(a) be denied. Language of contention should be evaluated on basis of 10CFR50.47(a)(1). ROREM, B.L. Rorem, B. #485 783. 85/10/08. GROSSMAN, H., BRENNER, L., CALLIHAN, A.D. Atomic Safety and Licensing Board Panel. 2pp. 33023-124-33023-125.

8510110049 Response to Board 850927 memorandum & order compelling discovery on Rorem Interrogatories 17 & 57 from NRC. Affidavit of WS Little & Certificate of Svc encl. Related correspondence. CHAN, E.I. Hearing Branch 2. #485 719. 85/10/09. Rorem, B. 5pp. 32973-167-32973-171.

8510160172 Tenth partial response to first set of QA interrogatories & request to produce QA program complies w/criteria of 10CFR50, App B. Supporting documents & Certificate of Svc encl. Related correspondence. * Commonwealth Edison Co. #485 778. 85/10/09. Rorem, B. 235pp. 33020-139-33021-082.

8510150375 Forwards proposed testimony of G. Wenger on Rorem Contention 1(a) re public info & educ aspects of emergency planning for plant. Emergency info booklet reviewed by G. Wenger encl. CHAN, E.I. Hearing Branch 2. #485 757. 85/10/10. GROSSMAN, H., CALLIHAN, A.D., COLE, R.F. Atomic Safety and Licensing Board Panel. 31pp. 33009-336-33010-004.

8510180127 Notice of depositions of stated NRC members on 851021. Certificate of Svc encl. Related correspondence. GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 773. 85/10/10. 3pp. 33022-263-33022-265.

8510180093 Errata to ASLB 851004 memorandum & order granting protective order. Served on 851016. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 802. 85/10/15. 1p. 33054-115-33054-115.

8510180127 Notice of location change for 851029 hearing re Rorem Contention 1(a), involving dissemination of info to public. Served on 851016. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 804. 85/10/15. 1p. 33055-032-33055-032.

8510180268 Forwards AD Miosi 850909 ltr re disposition of nonconformance repts & LO DelGeorge 850925 ltr concerning Comm Ed supplemental response to insp rept, per requirements of Decision ALAB-143. Related correspondence. COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 815. 85/10/15. GROSSMAN, H., BRENNER, L., COLE, R.F. Atomic Safety and Licensing Board Panel. 7pp. 33062-027-33062-033.

8510180338 Forwards affidavits of TE Quaka & JW Gieseke supporting encl util 850828 revised response to intervenor QA Interrogatories 58 & 59 re Contention Item 3.C. Certificate of Svc encl. Related correspondence. STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 814. 85/10/15. GUILD, R. Guild, R. 24pp. 33061-291-33061-314.

8510210030 Motion for ASLB to exclude portions of G. Wenger 851010 testimony irrelevant to Contention 1(a) re emergency planning. Certificate of Svc encl. GALLO, J. Commonwealth Edison Co. GALLO, J. Isham, Lincoln & Beale. #485 830. 85/10/17. Atomic Safety and Licensing Board Panel. 6pp. 33072-342-33072-347.

8510220233 Confirms 851017 telcon re intervenors 851010 notice of deposition. L. McGregor, R.N. Gardner & RD Schultiz will be made available for deposition on 851025, 31 & 1101, respectively. Related correspondence. CHAN, E.I. Hearing Branch 2. #485 845. 85/10/17. GUILD, R. Guild, R. 1p. 33084-159-33084-159.

8510220291 Forwards revised fourth partial response to Rorem first set of QA interrogatories & request to produce. Rev corrects & updates info in Paragraph 1 & provides addl documents. Certificate of Svc encl. Related correspondence. STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 849. 85/10/18. GUILD, R. Business & Professional People for the Public Interest. 105pp. 33088-188-33088-315.

8510220343 Memorandum & order granting applicant 850816 motion to particularize Rorem Contention 1(a) re adequacy of emergency plan, subj to reconsideration. Served on 851021. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 848. 85/10/18. Commonwealth Edison Co. 7pp. 33086-319-33086-325.

8510220348 Joint motion to revise hearing schedule by extending 851028 discovery deadline to 851202. Proposed schedule & Certificate of Svc encl. GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. #485 850. 85/10/18. Atomic Safety and Licensing Board Panel. 8pp. 33089-329-33089-336.

8510220364 Application for encl subpoenas to WO Puckett & JD Seeders to appear in Chicago, IL on 851112 & 05, respectively, for deposition. Certificate of Svc encl. Related correspondence. KEZELIS, E.Z. Commonwealth Edison Co. KEZELIS, E.Z. Isham, Lincoln & Beale. #485 859. 85/10/18. Atomic Safety and Licensing Board Panel. 8pp. 33088-152-33088-159.

8510240490 Second set of QA interrogatories & requests to produce re 850621 amended QA contention. Certificate of Svc encl. Related correspondence. GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 882. 85/10/21. Commonwealth Edison Co. 12pp. 33161-001-33161-012.

8510290006 Confirms 851022 telcon re deposition of I. Yin. Suggests that Yin deposition be held on 851104 in Chicago ofc of Isham, Lincoln & Beale. Yin will also be available between 851119 & 26 in Region III ofc. Related correspondence. BERRY, G.A. Hearing Branch 1. #485 939. 85/10/22. GUILD, R. Guild, R. CASSELD, W. Cassel, D.W. 1p. 33232-102-33232-102.

8510240669 Order granting parties 851018 joint motion to revise hearing schedule due to delays in completion of certain corrective action programs. Served on 851024. GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 891. 85/10/23. Office of the Executive Legal Director. 2pp. 33161-015-33161-017.

8510310394 Responds to applicant 851017 motion to exclude portions of encl G. Wenger testimony on Rorem Contention 1(a). Related correspondence. CHAN, E.I. Hearing Branch 2. #485 973. 85/10/25. Atomic Safety and Licensing Appeal Panel. 2pp. 33272-001-33272-033.

8510310190 Order extending time until 851108 for Commission to act to review ALAB-817. Served on 851029. CHILK, S.J. Office of the Secretary of the Commission. #485 967. 85/10/26. Commissioners. 1p. 33273-173-33273-173.

J. Insurance & indemnity information

8510110052 Forwards Endorsements 1-6 to NELIA Policy NF-294. OSTER, J. Commonwealth Edison Co. 85/09/30. SALTZMAN, J. Assistant Director for State & Licensee Relations. 19pp. 32972-108-32972-126.

8510250468 Forwards executed Indemnity Agreement B-102. OSTER, J. Commonwealth Edison Co. 85/10/17. SALTZMAN, J. Assistant Director for State & Licensee Relations. 14pp. 33171-347-33171-360.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510160172 Tenth partial response to first set of QA interrogatories & request to produce QA program complies w/criteria of 10CFR50, App B. Supporting documents & Certificate of Svc encl. Related correspondence. * Commonwealth Edison Co. #485 778. 85/10/09. Rorem, B. 235pp. 33020-139-33021-082.

232 DOCKETED ITEMS

Q. Inspection reports, IE Bulletins & correspondence

- 8509260122** IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.
- 8509260369** Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.
- 8510160178** Responds to NRC 850812 ltr re violations noted in Insp Rept 50-456/85-26. Corrective action: new App C added to preoperational tests to ensure proper procedure verification.
FARRAR, D.L. Commonwealth Edison Co. 85/10/01. KEPLER, J.G. Region 3, Office of Director. 8pp. 33021:195-33021:202.
- 8510080402** Forwards Safety Insp Repts 50-456/85-32 & 50-457/85-31 on 850624-0906 & notice of violation.
LITTLE, W.S. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32919:242-32919:243.
- 8510080407** Notice of violation from insp on 850624-0906.
LITTLE, W.S. Region 3, Office of Director. 85/10/03. 2pp. 32919:244-32919:245.
- 8510080413** Insp Repts 50-456/85-32 & 50-457/85-31 on 850624-0906. Violation noted: failure to follow drawing instructions for installation of instrument flexible hoses & failure to follow procedural requirement re component pipe support.
* Region 3, Office of Director. 85/10/04. 23pp. 32919:246-32919:268.
- 8510100099** Forwards Safety Insp Repts 50-456/85-46 & 50-457/85-45 on 850912 & 15-19. No violation noted.
REYES, L.A. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32960:110-32960:115.
- 8510100105** Insp Repts 50-456/85-46 & 50-457/85-45 on 850912 & 16-19. No violations or deviations noted. Major areas inspected: licensee audits of contractor QA/QC activities.
SMEENGE, R.J., HAWKINS, F.C. Region 3, Office of Director. 85/10/04. 4pp. 32960:112-32960:115.
- 8510110029** Forwards Safety Insp Repts 50-456/85-44 & 50-457/85-43 on 850822-0905. No violation noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32974:007-32974:013.
- 8510110038** Insp Repts 50-456/85-44 & 50-457/85-43 on 850822-0905. No violation or deviation noted. Major areas inspected: allegations & licensee action on allegations.
MENDEZ, R., WILLIAMS, C.C. Region 3, Office of Director. 85/09/26. 5pp. 32974:009-32974:013.
- 8510170330** Forwards Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No non-compliance noted.
SHAFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33051:305-33051:310.
- 8510170335** Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No violations or deviations noted. Major areas inspected: emergency preparedness program, including facilities & equipment training & implementing procedures.
PLOSKI, T., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 4pp. 33051:307-33051:310.
- 8510170313** Forwards Safety Insp Repts 50-456/85-43 & 50-457/85-42 on 850912, 17-20 & 26. No violations noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/07. REED, C. Commonwealth Edison Co. 2pp. 33051:298-33051:304.
- 8510170317** Safety Insp Repts 50-456/85-43 & 50-457/85-42 on 850912, 17-20 & 26. No violations or deviations noted. Major areas inspected: licensee actions re mail traceability verification program.
MUFFETT, J.W., JACOBSON, J.M., DANIELSON, D.H. Region 3, Office of Director. 85/10/07. 5pp. 33051:300-33051:304.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

- 8510170374** Final Deficiency Repts 85-04(BY) & 85-07(BW) re faulty tachometer readings on emergency diesel generators. Initially reported on 850905. Dc-to-dc regulator replaced w/dc-to-dc converter. All similar tachometer circuits will be revised.
MIOZIA, D. Commonwealth Edison Co. 85/10/04. KEPLER, J. Region 3, Office of Director. 2pp. 33053:330-33053:331.
- 8510300107** Interim Deficiency Rept 85-06 re failure of diesel generators 1A & 1B to sustain adequate prime during testing. Initially reported on 850723. Mod of diesel engine fuel sys underway. Final rept expected upon completion of testing.
MIOZIA, D. Commonwealth Edison Co. 85/10/21. KEPLER, J.G. Region 3, Office of Director. 1p. 33256:357-33256:357.

T. Hearing transcripts on non-antitrust matters

- 8510020095** Transcript of 850930 telcon in Bethesda, MD.
* Atomic Safety and Licensing Board Panel. 85/09/30. 34pp. 32825:233-32825:267.
- 8510240354** Forwards supplemental testimony of LD Butterfield on Rorem Contention 1(a) re issues arising under requirements for news media arrangements for disseminating info during emergency related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 877. 85/10/22. GROSSMAN, H., CALLIHAN, A.D., BRENNER, L. Atomic Safety and Licensing Board Panel. 2pp. 33153:347-33154:025.
- 8510240363** Supplemental testimony of LD Butterfield on Rorem Contention 1(a) re dissemination of info to news media in event of emergency. Certificate of Svc encl. Related correspondence.
BUTTERFIELD, L. Commonwealth Edison Co. 85/10/22. 39pp. 33153:349-33154:025.
- 8510310394** Responds to applicant 851017 motion to exclude portions of encl G Wenger testimony on Rorem Contention 1(a). Related correspondence.
CHANE, E.I. Hearing Branch 2. #485 973. 85/10/25. Atomic Safety and Licensing Appeal Panel. 2pp. 33272:001-33272:033.
- 8510310399** Testimony of G Wenger re Rorem Contention 1(a). Certificate of Svc encl. Related correspondence.
WENGER, G. Federal Emergency Management Agency. 85/10/25. Atomic Safety and Licensing Board Panel. 31pp. 33272:003-33272:033.

V. Operator Examinations

- 8509240248** Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.
- 8510030083** Forwards SCR supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 8510010111** Forwards revised FSAR Table 14.2-78, "Control Rod Reactivity Worth Measurement," in response to Violation 1a noted in 850801 ltr to more clearly indicate testing limitations associated w/validating rod worths.
AINGER, K.A. Commonwealth Edison Co. 85/09/18. KEPLER, J.G. Region 3, Office of Director. 2pp. 32801:296-32801:297.
- 8510080440** Application for amends to CPPR-131, CPPR-132 & CPPR-133, incorporating partial exemption from GDC 4 to allow implementation of leak-before-break concept on RCS primary loops. Fee paid.
AINGER, K.A. Commonwealth Edison Co. 85/09/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32921:242-32921:243.
- 8510040301** Forwards fee for NRC review of util 850416 request for schedular exemption from requirement to submit updated FSAR.
AINGER, K.A. Commonwealth Edison Co. 85/09/30. DIGGS, R.M. License Fee Management Branch. 1p. 32853:359-32853:359.
- 8510110038** Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes.
ALEXANDER, G.L. Commonwealth Edison Co. 85/10/03. KEPLER, J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.
- 8510110058** Rev 38 to "QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.
- 8510150182** Requests review of encl first draft Tech Specs, based on util 850717 submittal. Proposed changes to Braidwood draft Tech Specs applicable to Byron cannot be incorporated until Byron changes approved w/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33031:096-33031:098.
- 8510220271** Requests concurrence w/& discusses proposed change to startup test evaluation process. Encl FSAR revs will be included in next FSAR amend.
AINGER, K.A. Commonwealth Edison Co. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33087:341-33087:345.
- 8510150204** Forwards projected schedule for complying w/10CFR50.62, per Generic Ltr 85-06 re QA guidance for ATWS equipment. NRC preimplementation review & approval of generic & plant-specific designs for incomplete mods requested.
ALEXANDER, G. Commonwealth Edison Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33010:332-33010:337.
- 8510170100** Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.
- 8510170174** "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on: 'Generic Implications of Salem ATWS Events'), Item 1.2, 'Post-Trip Review Data & Int. Capabilities'..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1521-1. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044:057-33044:068.

8510280349 Forwards 17769-1, "Electrical Cable Separation Verification Testing," in response to Power Sys Branch 850715 request for addl info. Test rept listed as Ref 1 in Sargent & Lundy Calculation 19 Q-14.
MIOGA, A.D. Commonwealth Edison Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33193:262-33193:262.

-8510280355 "Electrical Cable Separation Verification Testing."
HENLEY, J.C., JOHNSON, F.R., HIGHT, G.W. Wyle Laboratories. 17769-1. 85/08/27. 104pp. 33193:262-33193:005.

8510310381 Forwards Science Applications Intl Corp draft technical evaluation rept re util response to Generic Ltr 83-28, Item 1.2 on Salem ATWS events. Response incomplete in five areas. Addl info requested to complete review.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/24. FARRAR, D.L. Commonwealth Edison Co. 1p. 33278:166-33278:179.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510110106 Forwards SSER supporting util 850725 proposed FSAR change incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33011:345-33011:350.

-8510110114 SSER supporting util 850725 proposed FSAR change, incorporating Nuclear Const Issues Group Rev 2 to "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" into FSAR Table 3.8.2 & Section 3.10.3.2.2.
* NRC - No Detailed Affiliation Given. 85/10/07. 3pp. 33011:348-33011:350.

F. Security, medical, emergency & fire protection plans

8510160204 Discusses criteria for Firecode CT gypsum fire seals, identified in Insp Repts 50-454/84-76 & 50-455/84-51. Review & concurrence of criteria requested.
AINGER, K.A. Commonwealth Edison Co. 85/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33023:264-33023:345.

8510020370 Forwards booklet, "Emergency Info - Braidwood," referenced by LD Butterfield in testimony served on 850920. Applicant intends to submit booklet into evidence at hearings on Rorem Contention 1(a). Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. #485 645. 85/09/27. GROSSMAN, H. Atomic Safety and Licensing Board Panel. 17pp. 32824:350-32825:004.

8510040303 Revised emergency plan procedures, including Rev 1 to BWZP 200-2A4, "Reactor Power History & Core Inventory Determinations" & Rev 1 to BWZP 200-2A7, "Example of Core Damage Assessment."
* Commonwealth Edison Co. 85/09/27. 57pp. 32853:192-32853:246.

8510080177 Revised procedures, including Rev 0 to BWZP 500-4, "Operational Support Ctr Inventory," Rev 0 to BWZP 500-5, "Technical Support Ctr Inventory" & Rev 0 to BWZP 500-3, "Station Group Directory."
* Commonwealth Edison Co. 85/10/02. 24pp. 32920:019-32920:042.

8510110079 Rev 1 to Operational Support Ctr Implementing Procedure BWZP 400-2, "Primary Responsibility - Operations Director."
* Commonwealth Edison Co. 85/10/04. 5pp. 32973:001-32973:005.

8510170330 Forwards Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No non-compliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 3pp. 33051:305-33051:310.

-8510170335 Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No violations or deviations noted. Major areas inspected: emergency preparedness program, including facilities & equipment training & implementing procedures.
PLOSKE, T. Region 3, Office of Director. 85/10/04. 4pp. 33051:307-33051:310.

8510150078 Approves use of revised acceptance criteria for Firecode CT gypsum fire stops, per 850730 request. Gypsum & thermalbarrier fire penetration seals similar in configuration to seals at LaSalle.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/08. FARRAR, D.L. Commonwealth Edison Co. 4pp. 33030:293-33030:302.

8510240354 Forwards supplemental testimony of LD Butterfield on Rorem Contention 1(a) re issues arising under requirements for news media arrangements for disseminating info during emergency. Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. #485 877. 85/10/22. GROSSMAN, H. Atomic Safety and Licensing Board Panel. 2pp. 33153:347-33154:025.

-8510240363 Supplemental testimony of LD Butterfield on Rorem Contention 1(a) re dissemination of info to news media in event of emergency. Certificate of Svc encl. Related correspondence.
BUTTERFIELD, L. Commonwealth Edison Co. 85/10/22. 39pp. 33153:349-33154:025.

8510280275 Informs that util must commit to full compliance w/ Commission forthcoming response to GUARD remand & confirm that emergency plans include list of local or regional medical facilities which can treat exposure cases.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/23. FARRAR, D.L. Commonwealth Edison Co. 8pp. 33228:199-33228:206.

G. Adjudicatory correspondence

8510020235 Memorandum & order ruling on intervenor 850904 motion to compel discovery from applicant & NRC. Motion to compel on interrogatories 1-9, 17, 19, 50-52, 57 & part of 58 granted; Interrogatories 58 & 59 denied. Served on 850930.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 649. 85/09/27. Commonwealth Edison Co. 11pp. 32824:252-32824:262.

8510020370 Forwards booklet, "Emergency Info - Braidwood," referenced by LD Butterfield in testimony served on 850920. Applicant intends to submit booklet into evidence at hearings on Rorem Contention 1(a). Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 645. 85/09/27. GROSSMAN, H., BRENNER, L., COLE, R.F. Atomic Safety and Licensing Board Panel. 17pp. 32824:350-32825:004.

8510030019 Order setting further scheduling for Oct 1985 to Feb 1986. Served on 851002.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 663. 85/10/01. 3pp. 32843:073-32843:075.

8510030085 Order confirming rulings made during 850930 telcon. ASLB will convene hearing on Rorem Contention 1(a) on 851029. Based on agreement of parties, ASLB authorizes mailing of emergency planning booklet in present form. Served on 851002.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 662. 85/10/01. Office of the Executive Legal Director. 2pp. 32843:004-32843:004.

8510040329 Provides assessment on util position re Contention 1(a) filed by NRC on 850828. Applicant stands on 850815 motion that no issue under 10CFR50.47(b)(3) should be entertained under Contention 1(a).
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. #485 669. 85/10/02. GROSSMAN, H., BRENNER, L., CALLIHAN, A.D. Atomic Safety and Licensing Board Panel. 2pp. 32853:249-32853:250.

8510100183 Order directing BL Rorem to respond by 851011 to applicant 850815 motion to particularize Rorem Contention 1(a). Served on 851004.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 716. 85/10/03. Rorem, B. 2pp. 32962:124-32962:125.

8510100091 Memorandum & order granting confidential treatment of names & otherwise identifying info re prospective witnesses on BL Rorem QA contention. Served on 851007.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 692. 85/10/04. Rorem, B. 9pp. 32961:114-32961:122.

8510100212 Notice of 851029 evidentiary hearing in Joliet, IL to discuss Rorem Contention 1(a) re dissemination of info to public on evacuation or other protective measures in event of radiological emergency. Served on 851007.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 696. 85/10/04. 2pp. 32962:081-32962:082.

8510110221 Forwards intervenors answer opposing petitions by Comm Ed for waiver of NRC regulation & for review of ASLAP decision, consisting of 10-page brief w/one attachment.
GUILD, R. Business & Professional People for the Public Interest. GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 728. 85/10/07. CHILK, S.L. Office of the Secretary of the Commission. 1p. 32972:253-32972:274.

-8510110222 Response opposing petitions by Comm Ed for waiver of Commission regulation & for review of ASLAP decision.
GUILD, R. Rorem, B. GUILD, R. Guild, R. 85/10/07. Atomic Safety and Licensing Appeal Panel. 10pp. 32972:254-32972:274.

851010077 NRC brief in support of util 850923 motion for exemption from 10CFR2.786(b)(1) re prohibiting party from seeking review of ASLAP decision on petition for directed certification. Affidavit encl.
BERRY, G.A. Hearing Branch 1. #485 731. 85/10/08. Commissioners. 15pp. 32973:006-32973:027.

-8510110083 Affidavit of J.G. Keppler re 850621 util late-filed amended QA contention. Certificate of Svc encl.
KEPPLER, J.G. Region 3, Office of Director. 85/10/08. 7pp. 32973:022-32973:027.

8510110085 Notice of appearance in proceeding. Certificate of Svc encl.
STYLES, L.B. Commonwealth Edison Co. STYLES, L.B. Isham, Lincoln & Beale. #485 726. 85/10/08. 3pp. 32973:306-32973:308.

8510110133 Forwards affidavits of JW Gieseke, RV Seifmann & DA Hoffer supporting util sixth partial response to intervenor first set of QA interrogatories & request to produce related correspondence.
STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 723. 85/10/08. GUILD, R. Guild, R. 2pp. 32971:253-32971:263.

-8510110136 Affidavit of JW Gieseke supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Related correspondence.
GIESEKE, J.W. Commonwealth Edison Co. 85/09/19. 5pp. 32971:255-32971:259.

-8510110139 Affidavit of RV Seifmann supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Related correspondence.
SEIFMANN, R.V. Commonwealth Edison Co. 85/10/02. 3pp. 32971:260-32971:263.

-8510110142 Affidavit of DA Hoffer supporting util response to Specific Interrogatories 58 & 59 filed by intervenor as part of QA contention. Certificate of Svc encl. Related correspondence.
HOFFER, D.A. Commonwealth Edison Co. 85/09/06. 32pp. 32971:264-32971:295.

8510150306 Serves notice that deposition of J.J. Joyce rescheduled for 851015 at author law office in Chicago, IL. Uncertainty of Joyce appearing as witness (per 850930 telcon) should be resolved by 851011 file date. Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 767. 85/10/08. JOYCE, J.J. Illinois, State of. ROREM, B.L. Rorem, B. 1p. 33009:089-33009:089.

8510160208 Requests that applicant motion to restrict meaning of Contention 1(a) be denied. Language of contention should be evaluated on basis of 10CFR50.47(a)(1).
ROREM, B.L. Rorem, B. #485 783. 85/10/08. GROSSMAN, H., BRENNER, L., CALLIHAN, A.D. Atomic Safety and Licensing Board Panel. 2pp. 33023:124-33023:125.

8510110049 Response to Board 850927 memorandum & order compelling discovery on Rorem Interrogatories 17 & 57 from NRC. Affidavit of WS Little & Certificate of Svc encl. Related correspondence.
CHAN, E.I. Hearing Branch 2. #485 719. 85/10/09. Rorem, B. 5pp. 32973:167-32973:171.

8510160172 Tenth partial response to first set of QA interrogatories & request to produce QA program complies w/criteria of 10CFR50. App B. Supporting documents & Certificate of Svc encl. Related correspondence.
* Commonwealth Edison Co. #485 778. 85/10/09. Rorem, B. 235pp. 33020:139-33021:082.

234 DOCKETED ITEMS

8510150375 Forwards proposed testimony of G Wenger on Rorem Contention 1(a) re public info & educ aspects of emergency planning for plant. Emergency info booklet reviewed by G Wenger encl.
CHAN, E.I. Hearing Branch 2. #485 757. 85/10/10. GROSSMAN, H., CALLIHAN, A.D., COLE, R.F. Atomic Safety and Licensing Board Panel. 31pp. 33008:336-33010:004.

8510160127 Notice of depositions of stated NRC members on 851021. Certificate of Svc encl. Related correspondence.
GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 773. 85/10/10. 3pp. 33022:263-33022:265.

8510180093 Errata to ASLB 851004 memorandum & order granting protective order. Served on 851016.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 802. 85/10/15. 1p. 33054:115-33054:115.

8510180127 Notice of location change for 851029 hearing re Rorem Contention 1(a), involving dissemination of info to public. Served on 851016.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 804. 85/10/15. 1p. 33055:032-33055:032.

8510180268 Forwards AD Miosi 850909 ltr re disposition of nonconformance repts & LO DelGeorge 850925 ltr concerning Comm Ed supplier's ental response to insp rept, per requirements of Decision ALAB-143. Related correspondence.
COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 815. 85/10/15. GROSSMAN, H., BRENNER, L., COLE, R.F. Atomic Safety and Licensing Board Panel. 7pp. 33062:027-33062:033.

8510180338 Forwards affidavits of TE Quaka & JW Giesecker supporting encl utli 850828 revised response to intervenor QA interrogatories 58 & 59 re Contention Item 3.C. Certificate of Svc encl. Related correspondence.
STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 814. 85/10/15. GUILD, R. Guild, R. 24pp. 33061:291-33061:314.

8510210030 Motion for ASLB to exclude portions of G Wenger 851010 testimony irrelevant to Contention 1(a) re emergency planning. Certificate of Svc encl.
GALLO, J. Commonwealth Edison Co. GALLO, J. Isham, Lincoln & Beale. #485 830. 85/10/17. Atomic Safety and Licensing Board Panel. 6pp. 33072:342-33072:347.

8510220233 Confirms 851017 telcon re intervenors 851010 notice of deposition. L. McGregor, R.N. Gardner & RD Schultz will be made available for deposition on 851025, 31 & 1101, respectively. Related correspondence.
CHAN, E.I. Hearing Branch 2. #485 845. 85/10/17. GUILD, R. Guild, R. 1p. 33084:159-33084:159.

8510220291 Forwards revised fourth partial response to Rorem first set of QA interrogatories & request to produce. Rev corrects & updates info in Paragraph 1 & provides add documents. Certificate of Svc encl. Related correspondence.
STYLES, L.C. Isham, Lincoln & Beale. STYLES, L.C. Commonwealth Edison Co. #485 849. 85/10/18. GUILD, R. Business & Professional People for the Public Interest. 105pp. 33088:188-33088:315.

8510220343 Memorandum & order granting applicant 850816 motion to particularize Rorem Contention 1(a) re adequacy of emergency plan, subj to reconsideration. Served on 851021.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 848. 85/10/18. Commonwealth Edison Co. 7pp. 33086:319-33086:325.

8510220348 Joint motion to revise hearing schedule by extending 851028 discovery deadline to 851202. Proposed schedule & Certificate of Svc encl.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. #485 850. 85/10/18. Atomic Safety and Licensing Board Panel. 8pp. 33089:329-33089:336.

8510220364 Application for encl subpoenas to WO Puckett & JD Seeders to appear in Chicago, IL, on 851112 & 05, respectively, for deposition. Certificate of Svc encl. Related correspondence.
KEZELIS, E.Z. Commonwealth Edison Co. KEZELIS, E.Z. Isham, Lincoln & Beale. #485 859. 85/10/18. Atomic Safety and Licensing Board Panel. 8pp. 33088:152-33088:159.

8510240490 Second set of QA interrogatories & requests to produce re 850621 amended QA contention. Certificate of Svc encl. Related correspondence.
GUILD, R. Rorem, B. GUILD, R. Guild, R. #485 882. 85/10/21. Commonwealth Edison Co. 12pp. 33161:001-33161:012.

8510290006 Confirms 851022 telcon re deposition of I Yin. Suggests that Yin deposition be held on 851104 in Chicago ofc of Isham, Lincoln & Beale. Yin will also be available between 851119 & 26 in Region III ofc. Related correspondence.
BERRY, G.A. Hearing Branch 1. #485 939. 85/10/22. GUILD, R. Guild, R. CASSELD, W. Cassel, D.W. 1p. 33232:102-33232:102.

8510240669 Order granting parties 851018 joint motion to revise hearing schedule due to delays in completion of certain corrective action programs. Served on 851024.
GROSSMAN, H. Atomic Safety and Licensing Board Panel. #485 891. 85/10/23. Office of the Executive Legal Director. 2pp. 33161:015-33161:017.

8510310394 Responds to applicant 851017 motion to exclude portions of encl G Wenger testimony on Rorem Contention 1(a). Related correspondence.
CHAN, E.I. Hearing Branch 2. #485 973. 85/10/25. Atomic Safety and Licensing Appeal Panel. 2pp. 33272:001-33272:033.

8510310190 Order extending time until 851108 for Commission to act to review ALAB-817. Served on 851029.
CHILK, S.J. Office of the Secretary of the Commission. #485 967. 85/10/28. Commissioners. 1p. 33273:173-33273:173.

J. Insurance & Indemnity Information

8510250468 Forwards executed Indemnity Agreement B-102.
OSTER, J. Commonwealth Edison Co. 85/10/17. SALTZMAN, J. Assistant Director for State & Licensee Relations. 14pp. 33171:347-33171:360.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510180172 Tenth partial response to first set of QA interrogatories & request to produce QA program complies w/criteria of 10CFR50, App B. Supporting documents & Certificate of Svc encl. Related correspondence.
* Commonwealth Edison Co. #485 778. 85/10/09. Rorem, B. 235pp. 33020:139-33021:082.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/00. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510080402 Forwards Safety Insp Repts 50-456/85-32 & 50-457/85-31 on 850624-0906 & notice of violation.
LITTLE, W.S. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32919:242-32919:243.

8510080407 Notice of violation from insp on 850624-0906.
LITTLE, W.S. Region 3, Office of Director. 85/10/03. 2pp. 32919:244-32919:245.

8510080413 Insp Repts 50-456/85-32 & 50-457/85-31 on 850624-0906. Violation noted: failure to follow drawing instructions for installation of instrument flexible hoses & failure to follow procedural requirement re component pipe support.
* Region 3, Office of Director. 85/10/04. 23pp. 32919:246-32919:268.

8510100099 Forwards Safety Insp Repts 50-456/85-46 & 50-457/85-45 on 850912 & 16-19. No violation noted.
REYES, L.A. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32960:110-32960:115.

8510100105 Insp Repts 50-456/85-46 & 50-457/85-45 on 850912 & 16-19. No violations or deviations noted. Major areas inspected: licensee audits of contractor QA/QC activities.
SMEENGE, R.J., HAWKINS, F.C. Region 3, Office of Director. 85/10/04. 4pp. 32960:112-32960:115.

8510100229 Forwards Safety Insp Repts 50-456/85-44 & 50-457/85-43 on 850822-0905. No violation noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 32974:007-32974:013.

8510110038 Insp Repts 50-456/85-44 & 50-457/85-43 on 850822-0905. No violation or deviation noted. Major areas inspected: allegations & licensee action on allegations.
MENDEZ, R., WILLIAMS, C.C. Region 3, Office of Director. 85/09/26. 5pp. 32974:009-32974:013.

8510170330 Forwards Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No non-compliance noted.
SHAFFER, W.D. Region 3, Office of Director. 85/10/04. REED, C. Commonwealth Edison Co. 2pp. 33051:305-33051:310.

8510170335 Insp Repts 50-456/85-47 & 50-457/85-46 on 850924. No violations or deviations noted. Major areas inspected: emergency preparedness program, including facilities & equipment training & implementing procedures.
PLOSKE, T., PHILLIPS, M.P. Region 3, Office of Director. 85/10/04. 4pp. 33051:307-33051:310.

8510170313 Forwards Safety Insp Repts 50-456/85-43 & 50-457/85-42 on 850912, 17-20 & 26. No violations noted.
HARRISON, J.J. Region 3, Office of Director. 85/10/07. REED, C. Commonwealth Edison Co. 2pp. 33051:298-33051:304.

8510170317 Safety Insp Repts 50-456/85-43 & 50-457/85-42 on 850912, 17-20 & 26. No violations or deviations noted. Major areas inspected: licensee actions re matl traceability verification program.
MUFFETT, J.W., JACOBSON, J.M., DANIELSON, D.H. Region 3, Office of Director. 85/10/07. 5pp. 33051:300-33051:304.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510170374 Final Deficiency Repts 85-04(BY) & 85-07(BW) re faulty tachometer readings on emergency diesel generators. Initially reported on 850905. Dc-to-dc regulator replaced w/dc-to-dc converter. All similar tachometer circuits will be revised.
MOSI, A.D. Commonwealth Edison Co. 85/10/04. KEPPLER, J. Region 3, Office of Director. 2pp. 33053:330-33053:331.

8510300107 Interim Deficiency Rept 85-06 re failure of diesel generators 1A & 1B to sustain adequate prime during testing. Initially reported on 850723. Mod of diesel engine fuel sys underway. Final rept expected upon completion of testing. MIOSLAD, D. Commonwealth Edison Co. 85/10/21. KEPLER, J.G. Region 3, Office of Director. 1p. 33256:357-33256:357.

T. Hearing transcripts on non-antitrust matters

8510020095 Transcript of 850930 telecon in Bethesda, MD.
* Atomic Safety and Licensing Board Panel. 85/09/30. 34pp. 32825:233-32825:267.

8510240354 Forwards supplemental testimony of LD Butterfield on Rorem Contention 1(a) re issues arising under requirements for news media arrangements for disseminating info during emergency. Related correspondence. COPELAND, V.G. Isham, Lincoln & Beale. COPELAND, V.G. Commonwealth Edison Co. #485 877. 85/10/22. GROSSMAN, H., CALLIHAN, A.D., BRENNER, L. Atomic Safety and Licensing Board Panel. 2pp. 33153:347-33154:025.

-8510240363 Supplemental testimony of LD Butterfield on Rorem Contention 1(a) re dissemination of info to news media in event of emergency. Certificate of Svc encl. Related correspondence. BUTTERFIELD, L. Commonwealth Edison Co. 85/10/22. 39pp. 33153:349-33154:025.

8510310394 Responds to applicant 851017 motion to exclude portions of encl G Wenger testimony on Rorem Contention 1(a). Related correspondence. CHAN, E.I. Hearing Branch 2. #485 973. 85/10/25. Atomic Safety and Licensing Appeal Panel. 2pp. 33272:001-33272:033.

-8510310399 Testimony of G Wenger re Rorem Contention 1(a). Certificate of Svc encl. Related correspondence. WENGER, G. Federal Emergency Management Agency. 85/10/25. Atomic Safety and Licensing Board Panel. 31pp. 33272:003-33272:033.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

8510030083 Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days. ZWOLINSKI, J.A. Operating Reactors Branch 5. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.

DOCKET 50-458 RIVER BEND STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510080367 Forwards SSER 4 (NUREG-0989) for facility. BUTLER, W.R. Licensing Branch 2. 85/10/01. CAHILL, W.J., BOOKER, J.E. Gulf States Utilities Co. 4pp. 32923:040-32923:083.

8510110137 Certifies that Tech Specs on high/low pressure interface leakage accurately reflect commitments detailed in SSER 3. Affidavit encl. CAHILL, W.J. Gulf States Utilities Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32999:353-32999:355.

8510110001 Advises that recommendations for turbine maint in NUREG-0989 reviewed. Turbine sys maint program based on manufacturer calculations of missile generation probabilities & NRC guidelines will be submitted before 871101. BOOKER, J.E. Gulf States Utilities Co. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32968:362-32968:362.

8510160090 Advises that util will provide results of review & any requested info contained in update to SER (NUREG-0989), Section 13.5.2 re containment venting by 850731. BOOKER, J.E. Gulf States Utilities Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33023:356-33023:356.

F. Security, medical, emergency & fire protection plans

8510070258 Emergency implementing procedures, including EIP-2-018 re technical support ctr - activation; EIP-2-019 re technical support ctr - support functions & EIP-2-020 re emergency operations facility - activation. W/850927 ltr. BOOKER, J.E. Gulf States Utilities Co. 85/09/27. MARTIN, R.D. Region 4, Office of Director. 500pp. 32869:061-32870:239.

8510310096 Forwards Insp Rept 50-458/85-55 on 850715-19 & 29-0801. No violations or deviations noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/18. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33291:209-33291:210.

-8510310106 Insp Rept 50-458/85-55 on 850715-19 & 29-0801. No violation or deviation noted. Major areas inspected: mgt effectiveness, security organization, records & repts & lock & key controls. Details withheld (ref 10CFR73.21). CALDWELL, R.A., BAIRD, J.B. Region 4, Office of Director. 85/09/13. 1p. 33291:211-33291:211.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510030055 Amend 22 to FSAR for River Bend Station. W/850930 ltr. Five oversize figures encl. CAHILL, W.J. Gulf States Utilities Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 258pp. 32882:076-32882:333.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8510220385 Forwards comments & opinions re outstanding issues & unresolved questions concerning hydrogen control for facility. Supplemental info will be provided on request. SHEPHERD, J.E. Sandia National Laboratories. 85/09/10. SAVIO, R. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 33099:149-33099:154.

P. Operating license stage documents & correspondence

8510040145 Informs that rept describing methods used to establish GE-supplied trip setpoints & allowable values for protection sys channels assumed to operate in FSAR transient & accident analyses will be provided prior to startup. BOOKER, J.E. Gulf States Utilities Co. 85/08/13. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32851:017-32851:017.

8510010390 Provides current status of completed initial criticality & 5% license condition listed under Item 2.C of license, Subitems (1) through (18) as applicable. Initial criticality expected by 851005. BOOKER, J.E. Gulf States Utilities Co. 85/09/26. BUTLER, W. Licensing Branch 2. 1p. 32803:281-32803:281.

8510040554 Confirms NRC 850926 authorization for change in Tech Specs, as requested in util 850924 & 25 ltr. License NPF-40 amended on 850926 by increasing max transient generator voltage prescribed for HPCS diesel generator to 5,400 volts. NOVAK, T.M. Assistant Director for Licensing. 85/09/26. CAHILL, W.J. Gulf States Utilities Co. 4pp. 32863:093-32863:096.

8510050493 Approves control program for Asiatic claims submitted in 850621 & 0924 ltr, including chlorination sys to control claims prior to introducing Mississippi River water into normal & standby svc water sys. NOVAK, T.M. Assistant Director for Licensing. 85/09/27. CAHILL, W.J. Gulf States Utilities Co. 4pp. 32966:329-32966:332.

8510040267 Requests extension of environ qualification of electrical equipment per 10CFR50.49 if listed items not qualified by 851130. Remaining items include cable (Rockbestos), level elements, flow switches & solenoids. BOOKER, J.E. Gulf States Utilities Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTLER, W. Licensing Branch 4. 2pp. 32851:098-32851:099.

8510040469 Provides status of util justifications for interim operation of listed equipment for which environ qualification complete. Updated table, reflecting qualification of equipment, encl. BOOKER, J.E. Gulf States Utilities Co. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32854:184-32854:185.

8510160291 Offers no add'l comments on draft full power OL, per 850925 request. Editorial comments verbally provided to S Stern. Add'l weekly repts will be provided until issuance of full power license. BOOKER, J.E. Gulf States Utilities Co. 85/10/05. BUTLER, W.R. Licensing Branch 2. 1p. 33026:297-33026:297.

8510090492 Requests listing of customers purchasing or ordering valve operators containing magnesium motor rotors. Test anomalies have raised concern re long-term availability of valve operator motors w/magnesium rotors. BAER, R.L. Engineering & Generic Communications Branch. 85/10/08. DENHAM, F. Limitorque Corp. 1p. 33276:240-33276:240.

8510110104 Informs that two air operators requested in 850812 ltr for temporary exemption from GDC 2 installed on valves in suppression pool pumpback sys. Seismic qualification confirmation encl per request. BOOKER, J.E. Gulf States Utilities Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32974:021-32974:022.

8510110154 Submits status of justification for interim operation. Environ qualification of Air-Operated Valves 144 & 145 complete. Updated table reflecting qualification of equipment, encl. BOOKER, J.E. Gulf States Utilities Co. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32972:331-32972:332.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telecons can be arranged to resolve discrepancies. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170190 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities' - technical evaluation rept." Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-17. 85/10/11. NRC - No Detailed Affiliation Given. 12pp. 33044:126-33044:140.

8510170186 Forwards Amend 1 to License NPF-40 & safety evaluation. Amend increases max transient generator voltage prescribed for HPCS diesel generator in Item 4.8.1.1.2(f)(3) of Tech Specs from 4,784 to 5,400 volts. BUTLER, W.R. Licensing Branch 2. 85/10/11. CAHILL, W.J., BOOKER, J.E. Gulf States Utilities Co. 6pp. 33043:085-33043:097.

-8510170195 Amend 1 to License NPF-40, increasing max transient generator voltage prescribed for HPCS diesel generator in Item 4.8.1.1.2(f)(3) of Tech Specs from 4,784 to 5,400 volts. BUTLER, W.R. Licensing Branch 2. 85/10/11. 4pp. 33043:091-33043:094.

-8510170198 Safety evaluation supporting Amend 1 to License NPF-40.
* Office of Nuclear Reactor Regulation, Director. 85/10/11. 3pp. 33043:095-33043:097.

8510220345 Forwards weekly status rept consisting of cumulative list of license conditions & commitments completed since low power license issued, per NRC 850925 ltr. BOOKER, J.E. Gulf States Utilities Co. 85/10/17. BUTLER, W.R. Licensing Branch 2. 4pp. 33087:360-33087:363.

236 DOCKETED ITEMS

8510250405 Forwards updated table reflecting environ qualification summary listing of justifications for interim operation, Rev 4 to SRN 247433-1, "Flow Detecting Elements by Fluid Components, Inc.," complete. BOOKER, J.E. Gulf States Utilities Co. 85/10/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33172-293-33172-294.

8510250267 Forwards for review list of changes until requests to be included in Tech Specs re full power OL items represent corrections, clarifications & enhancements to Tech Specs. No amend to present low power license sought. BOOKER, J.E. Gulf States Utilities Co. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 34pp. 33169-336-33170-007.

8510300127 Informs that environ qualification of listed Rockbestos cable successfully completed. All outstanding justifications for interim operation completed prior to 851130, per 10CFR50.49. Final updated table re qualification encl. BOOKER, J.E. Gulf States Utilities Co. 85/10/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33250-349-33250-350.

8510300185 Confirms that 3-inch 300 lb air operated globe valves seismically qualified using static analysis, per 851010 response. Operability of valve/operator assembly established based on similarity to tested valve/operator prototype. BOOKER, J.E. Gulf States Utilities Co. 85/10/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33250-340-33250-341.

G. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510040403 Forwards Insp Rept 50-458/85-51 on 850616-0815 & notices of violation & deviation. JOHNSON, E.H. Region 4, Office of Director. 85/09/30. CAHILL, W.J. Gulf States Utilities Co. 2pp. 32853-304-32853-327.

-8510040406 Notice of violation from insp on 850616-0815.
* Region 4, Office of Director. 85/09/30. 2pp. 32853-306-32853-307.

-8510040409 Notice of deviation from insp on 850616-0815.
* Region 4, Office of Director. 85/09/30. 1p. 32853-308-32853-308.

-8510040415 Insp Rept 50-458/85-51 on 850616-0815. Violation noted: Attachments 1 & 2 for electrical & control board lineups not completed. Deviation noted: Preoperational Test Procedure 1-PT-210 did not demonstrate RHR sys will trip to vessel. CHAMBERLAIN, D., BENNETT, W.R., HARBUCK, C.C. Region 4, Office of Director. 85/09/18. 19pp. 32853-309-32853-327.

8510080585 Ack receipt of 850902 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-458/85-31. JOHNSON, E.H. Region 4, Office of Director. 85/09/30. CAHILL, W.J. Gulf States Utilities Co. 1p. 32927-051-32927-054.

-8510080589 Responds to NRC 850802 ltr re violations noted in Insp Rept 50-458/85-31. Corrective actions: valve lineup delineated in Procedure 1-PT-57-1 reverified. CAHILL, W.J. Gulf States Utilities Co. 85/09/02. MARTIN, R.D. Region 4, Office of Director. 3pp. 32927-052-32927-054.

8510090304 Ack receipt of 850821 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-458/85-29. JOHNSON, E.H. Region 4, Office of Director. 85/09/30. CAHILL, W.J. Gulf States Utilities Co. 1p. 32947-113-32947-117.

-8510090313 Responds to NRC 850802 ltr re violations noted in Insp Rept 50-458/85-29. Corrective actions: add samples of welds previously accepted by eight inspectors taken & training provided for inspectors performing visual weld insps. CAHILL, W.J. Gulf States Utilities Co. 85/08/21. MARTIN, R.D. Region 4, Office of Director. 4pp. 32947-114-32947-117.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220447 Ack receipt of 850830 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-458/85-49. JOHNSON, E.H. Region 4, Office of Director. 85/10/09. CAHILL, W.J. Gulf States Utilities Co. 1p. 33096-216-33096-221.

-8510220453 Responds to NRC 850801 ltr re violations noted in Insp Rept 50-458/85-49. Corrective actions: Test Instruction 8 revised to incorporate documenting completion of actions for disposition of test exceptions. CAHILL, W.J. Gulf States Utilities Co. 85/08/30. MARTIN, R.D. Region 4, Office of Director. 5pp. 33096-217-33096-221.

8510240107 Forwards Insp Rept 50-458/85-60 on 850909-13. No violation or deviation noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/11. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33156-274-33156-277.

-8510240112 Insp Rept 50-458/85-60 on 850909-13. No violation or deviation noted. Major areas inspected: deficiency repts, TMI action items & fuel load witnessing. BENNETT, W.R., SKOW, M.E., JAUDON, J.P. Region 4, Office of Director. 85/10/09. 3pp. 33156-275-33156-277.

8510240140 Forwards Insp Rept 50-458/85-54 on 850722-26 & 31-0802. No violation or deviation noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/11. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33157-339-33157-350.

-8510240152 Insp Rept 50-458/85-54 on 850722-26 & 31-0802. No violation or deviation noted. Major areas inspected: preoperational test results evaluation & IE bulletin followup. BENNETT, W.R., JAUDON, J.P. Region 4, Office of Director. 85/10/04. 10pp. 33157-341-33157-350.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510220358 Ack receipt of 850830 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-458/85-19. JOHNSON, E.H. Region 4, Office of Director. 85/10/15. CAHILL, W.J. Gulf States Utilities Co. 1p. 33086-331-33086-336.

-8510220359 Responds to NRC 850801 ltr re violations noted in Insp Rept 50-458/85-19. Corrective actions: all errors noted during review of EE-340 series drawings corrected via issuance of engineering & design coordination repts. CAHILL, W.J. Gulf States Utilities Co. 85/08/30. MARTIN, R.D. Region 4, Office of Director. 5pp. 33086-332-33086-336.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510240294 Forwards Insp Rept 50-458/85-62 on 850816-0915 & notice of violation. JOHNSON, E.H. Region 4, Office of Director. 85/10/18. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33154-247-33154-257.

-8510240298 Notice of violation from insp on 850816-0915.
* Region 4, Office of Director. 85/10/18. 2pp. 33154-249-33154-250.

-8510240312 Insp Rept 50-458/85-62 on 850816-0915. Violation noted: Administrative Procedure ADM-003 requirements not fully implemented for surveillance test procedures for semiannual calibr of source range monitor Channels A, B, C & D. CHAMBERLAIN, D., HARBUCK, C.C., JAUDON, J.P. Region 4, Office of Director. 85/10/09. 7pp. 33154-251-33154-257.

8510240341 Forwards Insp Rept 50-458/85-61 on 850823-25. No violation or deviation noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/18. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33153-321-33153-326.

-8510240347 Insp Rept 50-458/85-61 on 850823-25. No violations or deviations noted. Major areas inspected: allegations of improprieties on part of certain licensee contractor &/or subcontractor personnel. JOHNSON, E.H., TAYLOR, R.G., MCNEILL, W.M. Region 4, Office of Director. 85/10/15. 4pp. 33153-323-33153-326.

8510310096 Forwards Insp Rept 50-458/85-55 on 850715-19 & 29-0801. No violations or deviations noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/18. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33291-209-33291-210.

-8510310106 Insp Rept 50-458/85-55 on 850715-19 & 29-0801. No violation or deviation noted. Major areas inspected: mgt effectiveness, security organization, records & repts & lock & key controls. Details withheld (ref 10CFR73.21). CALDWELL, R.A., BAIRD, J.B. Region 4, Office of Director. 85/09/13. 1p. 33291-211-33291-211.

8510250457 Forwards Insp Rept 50-458/85-59 on 850819-23 & notice of violation. JOHNSON, E.H. Region 4, Office of Director. 85/10/21. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33172-249-33172-255.

-8510250459 Notice of violation from insp on 850819-23.
* Region 4, Office of Director. 85/10/21. 1p. 33172-251-33172-251.

-8510250462 Insp Rept 50-458/85-59 on 850819-23. Violation noted: improper disposition of nonconformance repts re test procedure criteria. BENNETT, W.R., MCNEILL, W.M., JAUDON, J.P. Region 4, Office of Director. 85/10/17. 4pp. 33172-252-33172-255.

8510310343 Forwards Insp Rept 50-458/85-63 on 850923-27. No violation or deviation noted. MARTIN, R.D. Region 4, Office of Director. 85/10/25. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33272-056-33272-063.

-8510310350 Insp Rept 50-458/85-63 on 850923-27. No violation or deviation noted. Major areas inspected: followup of various open items & license conditions. SKOW, M.E., HARBUCK, C.C., JAUDON, J.P. Region 4, Office of Director. 85/10/24. 6pp. 33272-058-33272-063.

R. Periodic operating reports & related correspondence

8510090127 Forwards weekly status rept for license conditions & other commitments completed during previous wk & since low power license issuance, per 850925 request. BOOKER, J.E. Gulf States Utilities Co. 85/10/03. BUTLER, W.R. Licensing Branch 2. 3pp. 32934-340-32934-342.

8510170196 Submits weekly status rept identifying license conditions & other commitments completed during previous wk & cumulatively since issuance of low power license. Cumulative listing & commitments encl. BOOKER, J.E. Gulf States Utilities Co. 85/10/10. BUTLER, W.R. Licensing Branch 2. 3pp. 33036-234-33036-236.

8510300132 Forwards weekly status rept identifying license conditions & other commitments completed during previous wk & cumulatively since issuance of low power license in response to 850925 ltr. BOOKER, J.E. Gulf States Utilities Co. 85/10/24. BUTLER, W.R. Licensing Branch 2. 4pp. 33250-355-33250-358.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510080067 Special rept providing details for measured structural settlement value outside limits of Tech Spec Table 3.7.10-1. Change to FSAR Table 2.5-19 & Tech Spec 3.7.10-1 will be submitted to revise predicted settlement. DEDDEN, J.C. Gulf States Utilities Co. 85/09/27. MARTIN, R.D. Region 4, Office of Director. 2pp. 32928-118-32928-119.

8510080564 Forwards LERs 85-001-00, 85-002-00, 85-003-00, 85-004-00 & 85-005-00. BOOKER, J.E. Gulf States Utilities Co. 85/09/30. Record Services Branch (Document Control Desk). 1p. 32927-037-32927-047.

-8510080578 LER 85-001-00 on 850831, reactor protection sys actuated on high source range monitor counts. Caused by core geometry change when fuel initial bundle placed in core. Four fuel loading chambers relocated to eliminate high count. WILLIAMSON, D.W. Gulf States Utilities Co. 85/09/30. 2pp. 32927-038-32927-039.

-8510080581 LER 85-002-00 on 850904, reactor protection sys actuated on high main steam line radiation & high scram discharge vol level. Caused by reactor protection sys Channel A manual trip during calibr coupled w/inadvertent noise spikes. WILLIAMSON, D.W. Gulf States Utilities Co. 85/09/30. 2pp. 32927-040-32927-041.

-8510080583 LER 85-003-00 on 850904, full reactor protection sys actuation occurred. Caused by unintentional shorting of contact while attempting to install jumper. Fuse C71-F7A replaced & jumpers moved to terminal blocks. WEST, R.C. Gulf States Utilities Co. 85/09/30. 2pp. 32927-042-32927-043.

-8510080588 LER 85-004-00 on 850906, discovered that APRM weekly reactor protection sys tests for Channels B, D, E, G & H unsatisfactory per requirements for setdown neutron trip. Caused by exclusion of steps to verify half scram. CUTCHIN, J. Gulf States Utilities Co. 85/09/30. 2pp. 32927-044-32927-045.

-8510080591 LER 85-005-00 on 850913, reactor protection sys actuation occurred. Caused by operator error when intermediate range monitor Channel E mode switch inadvertently moved from operate to standby. Switch placed in operate position. WILLIAMSON, D.W. Gulf States Utilities Co. 85/09/30. 2pp. 32927-046-32927-047.

8510310428 RO on 851012, fire occurred at Fancy Point 500 kV switchyard. Caused by apparent lightning strike. Fire extinguished. Damaged equipment to be replaced. Investigation & evaluation of emergency plan ongoing. PLUNKETT, T.F. Gulf States Utilities Co. 85/10/13. MARTIN, R.D. Region 4, Office of Director. 3pp. 33280-305-33280-307.

8510220074 Forwards LER 85-006-00 & LER 85-007-00. BOOKER, J.E. Gulf States Utilities Co. 85/10/15. Record Services Branch (Document Control Desk). 1p. 33095-164-33095-168.

-8510220078 LER 85-006-00 on 850916, reactor protection sys actuated while in non-coincident trip mode when malfunction in undervoltage printed circuit board on alternate supply breaker tripped electrical protection assembly. KOSMALA, R.J. Gulf States Utilities Co. 85/10/15. 2pp. 33095-165-33095-166.

-8510220083 LER 85-007-00 on 850919, replacement level transmitter for scram discharge vol did not meet IEEE Std 323-1974 qualifications. Caused by maint personnel not using controlled documents to specify replacement. KOSMALA, R.J. Gulf States Utilities Co. 85/10/15. 2pp. 33095-167-33095-168.

8510310075 Final Deficiency Rept DR-314 re fluid leakage from pump seals to pump drive motor in Borg-Warner electrohydraulic operators for Copes-Vulcan modulating valves. Initially reported on 850830. Actuator assemblies repaired. BOOKER, J.E. Gulf States Utilities Co. 85/10/16. MARTIN, R.D. Region 4, Office of Director. 3pp. 33291-206-33291-208.

8510290467 LER 85-008-00 on 850923, reactor protection sys actuated due to water level below Level 3 scram setpoint. Caused by procedural inadequacy combined w/operator error. Caution statement added to Test Procedure 309-0601.W/851023 ltr. OVERLID, T., BOOKER, J.E. Gulf States Utilities Co. 85/10/23. 3pp. 33242-118-33242-120.

8510250378 Special rept on 850914, during performance of monthly channel check, initial response spectrum recorder discovered inoperable due to inability to clear alarm. Caused by core activities in area. BOOKER, J.E. Gulf States Utilities Co. 85/10/24. MARTIN, R.D. Region 4, Office of Director. 2pp. 33172-150-33172-151.

V. Operations terminations

8509240248 Generic ltr 85-18 to all power licensees re "Operator Licensing Exams." Swc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 0-459 RIVER BEND STATION, UNIT 2

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

8510010281 Corrects 850906 ltr re evaluation of electrical cable tray & conduit sys seismic damping concerning statements made about Figures 8-15. Statement should read Figures 7-15 considered proprietary. SORENSEN, G.C. Washington Public Power Supply System. 85/09/25. ADENSAM, E.G. Licensing Branch 4. 1p. 32802-351-32802-351.

8510030377 Responds to 850913 ltr re NRC fees billed for OL reviews for WPPSS 1,2 & 3 & insp fees for WPPSS-2. Forwards documentation & "NRC Procedures for Reviewing Disputed License Fee Billings." W/o encl. MILLER, W.O. License Fee Management Branch. 85/09/27. SORENSEN, G.C. Washington Public Power Supply System. 2pp. 32848-073-32848-074.

8510170082 Requests approval of alternate pipe break criteria, excluding RCS primary loop. Benefit summary, technical justification & provisions for minimizing stress corrosion cracking in high energy lines encl. Fee paid. SORENSEN, G.C. Washington Public Power Supply System. 85/10/10. ADENSAM, E.G. Licensing Branch 4. 21pp. 33037-018-33037-038.

G. Adjudicatory correspondence

8510110212 Submits eighth quarterly status rept re const activities at facility. No significant safety-related const activities performed during Third Quarter 1985. Limited engineering effort continuing. Related correspondence. REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Washington Public Power Supply System. #485 748. 85/10/09. GROSSMAN, J.H., HARBOUR, J., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 32971-361-32971-361.

S. Reportable occurrences, LERs & related correspondence

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824-280-32824-305.

8510220457 Deficiency & Part 21 rept re error in Control Data GT STRUDL computer program. Initially reported on 850903. Pipe support final design will be reverified using different analysis program. Updated rept expected at const restart. ROOT, R.W. Washington Public Power Supply System. 85/10/03. MARTIN, J.B. Region 5, Office of Director. 3pp. 33096-232-33096-234.

8510290054 Forwards TDI Owners Group info re emergency diesel generators, including history, const status & "TDI Diesel Generator Design Review & Quality Revalidation Rept." Generators capable of meeting FSAR requirements. Fee paid. SORENSEN, G.C. Washington Public Power Supply System. 85/10/22. ADENSAM, E.G. Licensing Branch 4. 75pp. 33237-001-33237-056.

-8510290116 Rev 1 to "TDI Diesel Generator Design Review & Quality Revalidation Rept." DEESER, J., RAY, C.L. TDI (Transamerica Delaval, Inc.) Owners Group. 85/02/28. 1,100pp. 33237-077-33237-056.

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510020288 Forwards "High Energy Line Break/Moderate Energy Line Break, Supplementary Review for Illinois Power Co." Rept supplies independent design review. All issues satisfactorily addressed. SPANGENBERG, F. Illinois Power Co. 85/09/30. BUTLER, W.R. Licensing Branch 2. 1p. 32825-330-32825-337.

-8510020294 "High Energy Line Break/Moderate Energy Line Break, Supplementary Review for Illinois Power Co." PARKINSON, G.L., CAHN, R.S., HUGHES, E.M. Bechtel Corp. 85/09/30. 167pp. 32825-331-32825-337.

8510040140 Forwards marked-up proof & review Tech Specs per 850904 request, indicating typos & corrections to info submitted in 840928 & 840523 ltrs. SPANGENBERG, F. Illinois Power Co. 85/10/02. BUTLER, W.R. Licensing Branch 2. 85pp. 32850-188-32850-272.

8510080152 Requests results of review & disposition of allegation that safety-related HVAC control panels, installed by MCC Powers Co., mfg by Illinois Fabricators w/o benefit of QA program. NORELIUS, C.E. Region 3, Office of Director. 85/10/03. GERSTNER, W.C. Illinois Power Co. 1p. 32918-343-32918-343.

8510160323 Summary of 850926 meeting w/util & BNL in Bethesda, MD re util recovery program following unsatisfactory PVORT audit on 850826. List of meeting attendees & viewpoints encl. SIEGEL, B. Licensing Branch 2. 85/10/09. Licensing Branch 2. 20pp. 33028-329-33028-348.

8510230288 Notification of 851021 meeting w/util, BNL & Sargent & Lundy in Bethesda, MD to discuss Pump & Valve Operability Review Team overall program plan prior to resault. SIEGEL, B. Licensing Branch 2. 85/10/10. BUTLER, W.R. Licensing Branch 2. 4pp. 33108-249-33108-252.

8510160338 Forwards proposed agenda for Power Sys Branch 851029-30 site visit & drawing review audit. BUTLER, W.R. Licensing Branch 2. 85/10/11. SPANGENBERG, F. Illinois Power Co. 7pp. 33028-309-33028-315.

238 DOCKETED ITEMS

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170180 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.2, 'Post-Trip Review Data & Info Capabilities'..." technical evaluation rpt.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1517-5. 85/10/11. NRC - No Detailed Affiliation Given. 15pp. 33044:085-33044:099.

8510210028 Forwards response to 10CFR50.62 requirements re reduction of ATWS events for light water cooled power plants. Installation of ATWS sys complete. Tech Spec 3/4.1.5, "Standby Liquid Control Sys." will be revised.
SPANGENBERG, F. Illinois Power Co. 85/10/18. BUTLER, W.R. Licensing Branch 2. 9pp. 33072:354-33072:362.

8510210015 Informs that util completed compliance analysis review & identified need for list'd variance requests for NUREG-0737 Action Plan Item II.F.1 re add'l accident monitoring instrumentation. Variance requests encl.
SPANGENBERG, F. Illinois Power Co. 85/10/17. BUTLER, W.R. Licensing Branch 2. 10pp. 33074:133-33074:142.

8510210094 Submits listed clarifications in response to 850924 telcon re util 850718 & 0823 requests for exemption from N-5 certification of half-inch & smaller ASME III instrument tubing lines. Approval requested by 851025.
SPANGENBERG, F. Illinois Power Co. 85/10/18. BUTLER, W.R. Licensing Branch 2. 1p. 33072:281-33072:281.

8510280236 Forwards supplemental safety evaluation re implementation of Rev 2 to NCI01-01, "Visual Work Acceptance Criteria (VWAC) for Structural Welding..." Use of VWAC criteria acceptable. Revs should be incorporated into next FSAR amend.
BUTLER, W.R. Licensing Branch 2. 85/10/18. SPANGENBERG, F. Illinois Power Co. 3pp. 33228:215-33228:220.

-8510280240 Supplemental safety evaluation accepting use of Rev 2 to NCI01-01, "Visual Work Acceptance Criteria for Structural Welding at Nuclear Power Plants." Criteria appropriate & meet requirements of GDC 1 to App A to 10CFR50.
* NRC - No Detailed Affiliation Given. 85/10/18. 3pp. 33228:218-33228:220.

8510310250 Forwards revised FSAR pages for Chapter 13.2, "Training," reflecting changes in reactor fundamentals course & operator shift proficiency requirements. Changes effective on 851101. Changes will be incorporated into Amend 35 to FSAR.
SPANGENBERG, F. Illinois Power Co. 85/10/29. BUTLER, W.R. Licensing Branch 2. 4pp. 33272:155-33272:158.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510070321 Forwards info justifying deletion of automatic pump suction transfer feature from RCIC & HPSCs, per SER Section 7.8.
SPANGENBERG, F. Illinois Power Co. 85/09/03. BUTLER, W.R. Licensing Branch 2. 6pp. 32880:307-32880:312.

8510100054 Forwards Sept 1985 monthly update of "Seismic Qualification / Instrument Status by Sys/Equipment Number," per Generic Open Item 5, 850924 SQRT ltr & SER Outstanding Issue 7a.
SPANGENBERG, F. Illinois Power Co. 85/10/04. BUTLER, W.R. Licensing Branch 2. 150pp. 32958:338-32959:159.

8510100045 Forwards relief requests & supp's to preservice insp program sent on 820223 & 850304 per SER Confirmatory Issue 87. Justification for deviating from requirements of ASME Code provided.
SPANGENBERG, F. Illinois Power Co. 85/10/08. BUTLER, W.R. Licensing Branch 2. 14pp. 32960:052-32960:065.

8510150131 Discusses design & procedure mods undertaken by util to resolve listed SER issues. Sufficient info encl to revise License Condition 7 re diesel generator reliability in next SSER.
SPANGENBERG, F. Illinois Power Co. 85/10/11. BUTLER, W.R. Licensing Branch 2. 6pp. 33023:220-33023:225.

8510180177 Informs that containment atmosphere monitoring sys installed & turned over to util startup manager for preoperational testing on 850930, per SER Confirmatory Issue 31 & SSER 4.
SPANGENBERG, F. Illinois Power Co. 85/10/18. BUTLER, W.R. Licensing Branch 2. 1p. 33059:346-33059:346.

8510250378 Forwards Rev 00 to "Dynamic Qualification of Time Delay Relays," in response to SER Outstanding Issue 7a & unresolved items identified by SQRT during site visit during wk of 850827-30.
SPANGENBERG, F. Illinois Power Co. 85/10/23. BUTLER, W.R. Licensing Branch 2. 2pp. 33166:205-33166:300.

-8510250384 Rev 00 to "Dynamic Qualification of Time Delay Relays."
* Sargent & Lundy, Inc. CDD-023726 R00. 85/09/06. 94pp. 33166:207-33166:300.

F. Security, medical, emergency & fire protection plans

8510300018 Temporary Change Forms EPTCF 85-003 & 85-004 to Rev 4 to emergency plan, consisting of new Figures 2-2, "Nuclear Power Program Organization" & 2-8, "Headquarters Support Organization."
HALL, B. Illinois Power Co. 85/04/01. 300pp. 33251:010-33254:112.

-8510300025 Revised emergency plan implementing procedures, including Rev 1 to AP-01, "Organization & Preparation of Controlled Documents" & Rev 1 to "Document Control."
* Illinois Power Co. 85/06/28. 900pp. 33251:292-33254:112.

8510040197 Rev 10 to Procedure IP-03150 re emergency plan controlled distribution list.
* Illinois Power Co. 85/08/22. 3pp. 32851:036-32851:038.

8510080425 Forwards Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01, respectively, on 850826-0910. No violation noted.
HIND, J.A. Region 3, Office of Director. 85/10/02. GERSTNER, W.C. Illinois Power Co. 2pp. 32922:220-32922:223.

-8510080432 Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01 on 850826-0910. No violation noted. Areas inspected security program audit. Details withheld (ref. 10CFR73.21).
PIRTLE, G.L., CHRISTOFFER, G., DROUIN, B. Region 3, Office of Director. 85/10/01. 2pp. 32922:222-32922:223.

8510100132 Responds to questions re use of silicone sealant in main control room HVAC ductwork. Ductwork has in-leakage acceptance criteria less than allowed by ANSI N509.
SPANGENBERG, F. Illinois Power Co. 85/10/08. BUTLER, W.R. Licensing Branch 2. 3pp. 32960:357-32960:359.

8510110043 Forwards "Evacuation Time Estimates for Clinton Power Station Plume Exposure Pathway Emergency Planning Zone," per Rev 1 to NUREG-0654/FEMA-REP-1, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans."
SPANGENBERG, F. Illinois Power Co. 85/10/09. BUTLER, W.R. Licensing Branch 2. 2pp. 32968:191-32968:356.

-8510110048 "Evacuation Time Estimates for Clinton Power Station Plume Exposure Pathway Emergency Planning Zone."
* HMM Associates, Inc. 85/09/30. 150pp. 32968:193-32968:356.

8510160340 Forwards preliminary agenda for 851028-1101 preimplementation audit of DCDRR. Util requested to make listed arrangements, including providing documentation of DCDRR results & ensuring availability of DCDRR review team.
BUTLER, W.R. Licensing Branch 2. 85/10/11. SPANGENBERG, F. Illinois Power Co. 7pp. 33028:302-33028:308.

8510160165 Forwards "Equipment Seismic Assessment Program for Safety-Related Mechanical & Electrical Equipment," per proposed program in 820519 ltr. Sufficient assurance exists that emergency power & DHR sys can withstand SSE.
SPANGENBERG, F. Illinois Power Co. 85/10/14. BUTLER, W.R. Licensing Branch 2. 2pp. 33021:298-33022:079.

-8510160171 "Equipment Seismic Assessment Program for Safety-Related Mechanical & Electrical Equipment."
HABLE, A.J., BYAM, T.A., BELLS, S.R. Illinois Power Co. 85/10/14. 125pp. 33021:298-33022:079.

8510230301 Notification of cancellation of 851021 meeting w/util & Sargent & Lundy in Bethesda, MD to discuss open issues re fire protection due to recent fire protection audit & recently submitted revised fire protection evaluation rpt.
SIEGEL, B. Licensing Branch 2. 85/10/15. BUTLER, W.R. Licensing Branch 2. 3pp. 33108:254-33108:256.

8510210036 Informs that majority of instrument sensors & control room indicators required for compliance w/Rev 3 to Reg Guide 1.97 installed. Installation verified to be approx 90% complete.
SPANGENBERG, F. Illinois Power Co. 85/10/17. BUTLER, W.R. Licensing Branch 2. 2pp. 33072:340-33072:341.

8510280093 Discusses concerns identified as result of 850909-13 fire protection site audit. Evaluations of fire protection evaluation rpt & safe shutdown analysis submitted on 850906 to be reported. Meeting w/util suggested.
BUTLER, W.R. Licensing Branch 2. 85/10/18. SPANGENBERG, F. Illinois Power Co. 6pp. 33240:347-33240:352.

8510280393 Forwards Safety Insp Rept 50-461/85-47 on 850909-1019 & notice of violation.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/23. GERSTNER, W.C. Illinois Power Co. 2pp. 33192:190-33192:204.

-8510280395 Notice of violation from insp on 850909-1019.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/23. 1p. 33192:192-33192:192.

-8510280398 Insp Rept 50-461/85-47 on 850909-1019. Violation noted: failure to calibrate fire hose standpipe pressure restricting valve & to inspect portable fire extinguishers.
ULIE, J.M., GULDEMOND, W.G. Region 3, Office of Director. 85/10/22. 12pp. 33192:193-33192:204.

8510280288 Forwards justification for not fireproofing Div 2 switchgear ducts per safe shutdown analysis. Adequate justification provided to eliminate need for affected duct fire wrap.
SPANGENBERG, F. Illinois Power Co. 85/10/25. BUTLER, W.R. Licensing Branch 2. 8pp. 33192:069-33192:078.

J. Insurance & indemnity information

8510100035 Forwards MAELU Policy MF-121 & Endorsements 23, 24 & 25 to NELIA Policy NF-261.
TURNER, C.L. Illinois Power Co. 85/09/30. SALTZMAN, NRC - No Detailed Affiliation Given. 18pp. 32959:225-32959:242.

M. Antitrust correspondence

8510110178 Requests NRR reevaluate decision re no significant antitrust changes that would necessitate antitrust review. Util financial status discussed.
BATZ, R. Affiliation Not Assigned. 85/10/09. Office of Nuclear Reactor Regulation, Director. 13pp. 32971:298-32971:308.

Q. Inspection reports, IE Bulletins & correspondence

8510010325 Requests suspension of overinsp program for addl commodities at util risk based on 850726,0806 & 12 ltr addl data provided & responses to NRC reasons for withholding concurrence of initial requests for suspension of program. HALL,D.P. Illinois Power Co. 85/09/06. KEPLER,J.G. Region 3, Office of Director. 4pp. 32802:356-32802:359.

8510010068 Ack positions in 850827 & 0912 ltr re pending overinsp program termination requests & proposed suspension of program activities. Responses to comments encl. Approval of termination requests discussed. KEPLER,J.G. Region 3, Office of Director. 85/09/26. SAMELSON,A. Illinois, State of. 9pp. 32800:302-32800:310.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds. DUTTON,D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT,J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Reinsp of Welds." * Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

850260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510040215 Forwards Safety Insp Rept 50-461/85-49 on 850911. No violation noted. HARRISON,J.J. Region 3, Office of Director. 85/09/30. GERSTNER,W.C. Illinois Power Co. 2pp. 32851:066-32851:070.

-8510040223 Safety Insp Rept 50-461/85-49 on 850911. No violation or deviation noted. Major areas inspected: as-built condition of conduit hangers, cable tray hangers, HVAC ducts & HVAC duct supports. MUFFETT,J.W., DANIELSON,D.H. Region 3, Office of Director. 85/09/30. 3pp. 32851:068-32851:070.

8510070385 Forwards Special Safety Insp Rept 50-461/85-44 on 850823,24 & 30 & 0903-04. No violation noted. HARRISON,J.J. Region 3, Office of Director. 85/09/30. GERSTNER,W.C. Illinois Power Co. 2pp. 32877:144-32877:160.

-8510070389 Special Safety Insp Rept 50-461/85-44 on 850823,24 & 30 & 0903-04. No violation or deviation noted. Major areas inspected: licensee actions re program. MUFFETT,J.W., DANIELSON,D.H. Region 3, Office of Director. 85/09/30. 15pp. 32877:146-32877:160.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510070235 Forwards addl info & concerns from allger re Allegation RIII-85-A-0116 dealing w/ socket weld fitup. Results of review & disposition of matter should be submitted to Region III upon completion. NORELIUS,C.E. Region 3, Office of Director. 85/10/01. GERSTNER,W.C. Illinois Power Co. 2pp. 32881:226-32881:227.

8510070421 Forwards Safety Insp Rept 50-461/85-34 on 850618-0912. No violation noted. HARRISON,J.J. Region 3, Office of Director. 85/10/02. GERSTNER,W.C. Illinois Power Co. 2pp. 32877:137-32877:143.

-8510070424 Insp Rept 50-461/85-34 on 850618-0912. No violation or deviation noted. Major areas inspected: licensee action on IE bulletins, reactor coolant loop piping welds & quality records & other safety-related piping welds. JONES,D.E., DANIELSON,D.H. Region 3, Office of Director. 85/10/01. 5pp. 32877:139-32877:143.

8510080425 Forwards Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01, respectively, on 850826-0910. No violation noted. HIND,J.A. Region 3, Office of Director. 85/10/02. GERSTNER,W.C. Illinois Power Co. 2pp. 32922:220-32922:223.

-8510080432 Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01 on 850826-0910. No violation noted. Areas inspected: security program audit. Details withheld (ref 10CFR73.21). PIRTLE,G.L., CHRISTOFFER,G., DROUIN,B. Region 3, Office of Director. 85/10/01. 2pp. 32922:222-32922:223.

8510280054 Provides formal notification of Asiatic claims discovered on 850613 in response to IE Bulletin 81-03. Actions taken & planned to ensure that Corbicula will not cause significant biofouling problem provided. SPANGENBERG,F. Illinois Power Co. 85/10/02. KEPLER,J.G. Region 3, Office of Director. 2pp. 33191:023-33191:024.

8510100096 Forwards response to 850828 request for addl info re exam of corrosion resistant clad weld preservice insp. per License Condition 12.W./two oversize drawings. SPANGENBERG,F. Illinois Power Co. 85/10/04. BUTLER,W.R. Licensing Branch 2. 10pp. 32960:279-32960:289.

8510100045 Forwards relief requests & suppls to preservice insp program sent on 820223 & 850304 per SER Confirmatory Issue 67. Justification for deviating from requirements of ASME Code provided. SPANGENBERG,F. Illinois Power Co. 85/10/08. BUTLER,W.R. Licensing Branch 2. 14pp. 32960:052-32960:065.

8510280378 Forwards response to 850913 request for addl info re NRC concurrence to terminate overinsp program for electrical hangers, HVAC duct & duct supports & cable tray, conduit & cable terminations. HALL,D.P. Illinois Power Co. 85/10/11. KEPLER,J.G. Region 3, Office of Director. 28pp. 33192:116-33192:143.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLT's." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510290391 Forwards Safety Insp Rept 50-461/85-41 on 850715-0930 & notice of violation. HARRISON,J.J. Region 3, Office of Director. 85/10/22. GERSTNER,W.C. Illinois Power Co. 2pp. 33192:166-33192:188.

-8510280392 Notice of violation from insp on 850715-0930. HARRISON,J.J. Region 3, Office of Director. 85/10/22. 1p. 33192:186-33192:168.

-8510280394 Insp Rept 50-461/85-41 on 850715-0930. Violation noted: failure to verify availability & acceptability of vendor documentation. LOVE,R.S., WILLIAMS,C.C. Region 3, Office of Director. 85/10/21. 10pp. 33192:169-33192:188.

8510280354 Forwards Safety Insp Rept 50-461/85-45 on 850820-1003. No violation noted. WARNICK,R.F. Region 3, Office of Director. 85/10/23. GERSTNER,W.C. Illinois Power Co. 1p. 33192:079-33192:095.

-8510280358 Insp Rept 50-461/85-45 on 850820-1003. No violation or deviation noted. Major areas inspected: const & preoperational testing activities, including previous insp findings, 10CFR50.55(e) items & site surveillance tours. GWYNN,T.P. Region 3, Office of Director. 85/10/22. 16pp. 33192:080-33192:095.

8510280393 Forwards Safety Insp Rept 50-461/85-47 on 850909-1019 & notice of violation. PAPERIELLO,C.J. Region 3, Office of Director. 85/10/23. GERSTNER,W.C. Illinois Power Co. 2pp. 33192:190-33192:204.

-8510280395 Notice of violation from insp on 850909-1019. PAPERIELLO,C.J. Region 3, Office of Director. 85/10/23. 1p. 33192:192-33192:192.

-8510280398 Insp Rept 50-461/85-47 on 850909-1019. Violation noted: failure to calibrate fire hose standpipe pressure restricting valve & to inspect portable fire extinguishers. ULIE,J.M., GULCEMOND,W.G. Region 3, Office of Director. 85/10/22. 12pp. 33192:193-33192:204.

R. Periodic operating reports & related correspondence

8510100054 Forwards Sept 1985 monthly update of "Seismic Qualification /Instrument Status by Sys/Equipment Number," per Generic Open Item 5.850924 SQRT ltr & SER Outstanding Issue 7a. SPANGENBERG,F. Illinois Power Co. 85/10/04. BUTLER,W.R. Licensing Branch 2. 150pp. 32958:336-32959:159.

S. Reportable occurrences, LERs & related correspondence

8510010468 Final Deficiency Rept 55-85-03 re firewalls constructed w/8-inch hollow core concrete masonry units that may not meet 3 h fire resistance rating, initially reported on 850404. Item not reportable per 10CFR50.55(e). HALL,D.P. Illinois Power Co. 85/09/19. KEPLER,J.G. Region 3, Office of Director. 4pp. 32809:171-32809:174.

8510010494 Final Deficiency Rept 55-84-18 re yield & tensile strength of ASTM-A-36 plate mat less than required by mat spec. Initially reported on 840803. Item not reportable per 10CFR50.55(e). HALL,D.P. Illinois Power Co. 85/09/19. KEPLER,J.G. Region 3, Office of Director. 6pp. 32820:165-32820:170.

8510080003 Final potential Deficiency Rept 55-85-06 re inadequate design change control by Zack Co. Initially reported 850807. Field Const Procedure 3.0 addressing retro-active design changes revised. Issue not acceptable per 10CFR50.55(e). HALL,D.P. Illinois Power Co. 85/09/26. KEPLER,J.G. Region 3, Office of Director. 4pp. 32927:347-32927:350.

8510090331 Interim Potentially Reportable Deficiency Rept 55-85-09 re inadequate implementation of design document review process. Initially reported on 850818. Investigation plan to determine as-built condition of hardware implemented. HALL,D.P. Illinois Power Co. 85/09/30. KEPLER,J.G. Region 3, Office of Director. 4pp. 32947:138-32947:141.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 328P2:049-328P2:075.

8510310250 Forwards revised FSAR pages for Chapter 13.2, "Training," reflecting changes in reactor fundamentals course & operator shift proficiency requirements. Changes effective on 851101. Changes will be incorporated into Amend 35 to FSAR. SPANGENBERG,F. Illinois Power Co. 85/10/29. BUTLER,W.R. Licensing Branch 2. 4pp. 33272:155-33272:158.

240 DOCKETED ITEMS

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

F. Security, medical, emergency & fire protection plans

8510010070 Forwards Insp Rept 50-482/85-26 on 850601-0731 & notice of violation. JOHNSON,E.H. Region 4, Office of Director. 85/09/20. KOESTER,G.L. Kansas Gas & Electric Co. 2pp. 32809:217-32809:235.

-8510010082 Insp Rept 50-482/85-26 on 850601-0731: Violations noted: failure to control measuring & test equipment w/procedure & temporary changes not incorporated in procedure. CUMMINS,J.E., BARTLETT,B.L., BUNDY,H.F. Region 4, Office of Director. 85/09/13. 15pp. 32809:221-32809:235.

8510040133 Revised emergency response plan implementing procedures, including table of contents & Rev 2 to EPP 02-1.1, "Emergency Preparedness Program Maint." W/850930 ltr. KOESTER,G.L. Kansas Gas & Electric Co. 85/09/30. MARTIN,R.D. Region 4, Office of Director. 25pp. 32851:213-32851:237.

8510220044 Rev 16 to "Radiological Emergency Response Plan." W/851017 ltr. KOESTER,G.L. Kansas Gas & Electric Co. 85/10/04. MARTIN,R.D. Region 4, Office of Director. 6pp. 33081:290-33081:295.

8510150059 Revised emergency plan implementing procedures, including Rev 2 to EPP 01-5.1 re exclusion area evacuation & Rev 3 to EPP 01-6.1 re personnel accountability. Rev 3 to table of contents included. W/851011 ltr. KOESTER,G.L. Kansas Gas & Electric Co. 85/10/11. MARTIN,R.D. Region 4, Office of Director. 76pp. 33028:018-33028:093.

8510220341 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-482/85-19. JOHNSON,E.H. Region 4, Office of Director. 85/10/16. KOESTER,G.L. Kansas Gas & Electric Co. 1p. 33087:355-33087:359.

-8510220346 Responds to NRC 850726 ltr re violations noted in Insp Rept 50-482/85-19. Corrective actions: documents control clerk assigned to technical support ctr; emergency operation facility & will report to site emergency plan administrator. KOESTER,G.L. Kansas Gas & Electric Co. 85/08/23. DENISE,R.P. Region 4, Office of Director. 4pp. 33087:356-33087:359.

8510220155 Forwards Rev 16 to radiological emergency response plan. Rev will be included in first annual update of SAR. KOESTER,G.L. Kansas Gas & Electric Co. 85/10/17. MARTIN,R.D. Region 4, Office of Director. 1p. 33087:347-33087:352.

-8510220159 Rev 16 to radiological emergency response plan. KOESTER,G.L., HOYT,R.L., RATHLER,G. Kansas Gas & Electric Co. 85/10/04. 3pp. 33087:348-33087:352.

8510310156 Revised emergency plan implementing procedures, including Rev 3 to EPP 01-1.2, "Emergency Operation Organization," Rev 1 to EPP 01-1.3, "Home Ofc Emergency Organization," & Rev 2 to EPP 01-1.4, "Public Info Organization." W/851028 ltr. KOESTER,G.L. Kansas Gas & Electric Co. 85/10/28. MARTIN,R.D. Region 4, Office of Director. 800pp. 33263:055-33264:143.

P. Operating license stage documents & correspondence

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies. CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

-8510170178 Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, "Post-Trip Review Data & Info Capabilities." Technical evaluation rpt. Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1524-23. 85/10/11. NRC - No Detailed Affiliation Given. 19pp. 33044:069-33044:284.

8510180152 Submits info re implementation schedule of ATWS requirements per 10CFR50.62 w/ currently considering design mod options offered by various vendors. Mods will be completed prior to restart following second refueling. KOESTER,G.L. Kansas Gas & Electric Co. 85/10/11. DENTON,H. Office of Nuclear Reactor Regulation, Director. 2pp. 33058:258-33058:259.

8510290449 Requests addl info establishing that listed items meet NRC guidelines or that post-trip data accurately reconstructs FSAR Chapter 15 accident sequence for review of ufr response to Generic Ltr 83-28, Item 1.2. YOUNGBLOOD,B.J. Licensing Branch 1. 85/10/23. KOESTER,G.L. Kansas Gas & Electric Co. 3pp. 33259:015-33259:034.

Q. Inspection reports, IE Bulletins & correspondence

8510010070 Forwards Insp Rept 50-482/85-26 on 850601-0731 & notice of violation. JOHNSON,E.H. Region 4, Office of Director. 85/09/20. KOESTER,G.L. Kansas Gas & Electric Co. 2pp. 32809:217-32809:235.

-8510010074 Notice of violation from Insp on 850621 & 26. * Region 4, Office of Director. 85/09/20. 2pp. 32809:219-32809:220.

-8510010082 Insp Rept 50-482/85-26 on 850601-0731: Violations noted: failure to control measuring & test equipment w/procedure & temporary changes not incorporated in procedure. CUMMINS,J.E., BARTLETT,B.L., BUNDY,H.F. Region 4, Office of Director. 85/09/13. 15pp. 32809:221-32809:235.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101 Encl app documents also available in PDR. FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230106 Forwards Press Release 85-68 re NRC proposed fine against ufr for alleged noncompliance concerning improperly conducted preoperational testing program. KAMMERER,C. Office of Congressional Affairs. 85/05/09. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:054-33109:055.

-8510230261 Forwards Press Release 84-115 re NRC proposed fine against ufr for apparent violation of NRC regulations. KAMMERER,C. Office of Congressional Affairs. 84/09/28. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:110-33109:111.

8510210291 Forwards Insp Rept 50-482/85-30 on 850801-31 & notice of violation. JOHNSON,E.H. Region 4, Office of Director. 85/10/09. KOESTER,G.L. Kansas Gas & Electric Co. 2pp. 33095:018-33095:038.

-8510210293 Notice of violation from Insp on 850726 & 0805. * Region 4, Office of Director. 85/10/09. 3pp. 33095:020-33095:022.

-8510210296 Insp Rept 50-482/85-30 on 850801-31: Violations noted: test port not re-located in accordance w/procedure; inadequate procedure & flow orifices installed backwards. One open item identified re Cutler-Hammer Type E-30 switches. CUMMINS,J.E., BARTLETT,B.L., MARTIN,L.E. Region 4, Office of Director. 85/10/02. 16pp. 33095:023-33095:038.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510220298 Ack receipt of 850904 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-482/85-23. JOHNSON,E.H. Region 4, Office of Director. 85/10/15. KOESTER,G.L. Kansas Gas & Electric Co. 1p. 33086:315-33086:318.

-8510220301 Responds to NRC 850808 ltr re violations noted in Insp Rept 50-482/85-23. Corrective actions: tape removed from level indicator slide pole & drain pipe from valve & conduit relocated. KOESTER,G.L. Kansas Gas & Electric Co. 85/09/04. DENISE,R.P. Region 4, Office of Director. 3pp. 33086:316-33086:318.

8510220339 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-482/85-25. JOHNSON,E.H. Region 4, Office of Director. 85/10/15. KOESTER,G.L. Kansas Gas & Electric Co. 1p. 33084:142-33084:146.

-8510220342 Responds to NRC 850726 ltr re violations noted in Insp Rept 50-482/85-25. Corrective actions: plant mod request program reviewed. Proposed changes for KGP-1131, "Plant Mod Process," developed & in concurrent review & approval process. KOESTER,G.L. Kansas Gas & Electric Co. 85/08/23. DENISE,R.P. Region 4, Office of Director. 4pp. 33084:143-33084:146.

8510220341 Ack receipt of 850823 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-482/85-19. JOHNSON,E.H. Region 4, Office of Director. 85/10/16. KOESTER,G.L. Kansas Gas & Electric Co. 1p. 33087:355-33087:359.

-8510220346 Responds to NRC 850726 ltr re violations noted in Insp Rept 50-482/85-19. Corrective actions: documents control clerk assigned to technical support ctr; emergency operation facility & will report to site emergency plan administrator. KOESTER,G.L. Kansas Gas & Electric Co. 85/08/23. DENISE,R.P. Region 4, Office of Director. 4pp. 33087:356-33087:359.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510180212 Forwards revised pages to monthly operating repts for June & Jul 1985. Revs highlighted w/re bars. KOESTER,G.L. Kansas Gas & Electric Co. 85/09/30. Office of Resource Management, Director. DENISE,R.P. Region 4, Office of Director. 1p. 33068:306-33068:312.

-8510180217 Rev 1 to monthly operating rpt for June 1985. WILLIAMS,M. Kansas Gas & Electric Co. 85/06/30. 3pp. 33068:307-33068:309.

-8510180222 Rev 1 to monthly operating rpt for Jul 1985. WILLIAMS,M. Kansas Gas & Electric Co. 85/07/31. 3pp. 33068:310-33068:312.

8510310071 Monthly operating rpt for Sept 1985 W/851015 ltr. WILLIAMS,M., KOESTER,G.L. Kansas Gas & Electric Co. 85/09/30. DENISE,R.P. Region 4, Office of Director. 9pp. 33291:336-33291:344.

S. Reportable occurrences, LERs & related correspondence

- 8510040264** Update to Part 21 rept re insp for cracked welds discovered in generator brackets, insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.
SCHREIBER, H. Louis-Alles Co. 85/09/30. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851:100-32851:107.
- 8510070009** LER 85-064-00: on 850902, reactor trip, turbine trip, steam generator blowdown & sample isolation, feedwater isolation & auxiliary feedwater actuation occurred as result of low water level in steam generator 2.W/850930 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/09/30. DENISE, R.P. Region 4, Office of Director. 4pp. 32900:007-32900:010.
- 8510090294** LER 85-065-00: on 850905, main turbine trip caused reactor trip, feedwater isolation, auxiliary feedwater actuation, steam generator blowdown & sample isolation. Caused by faulty control pump discharge relief valve.W/851002 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/02. DENISE, R.P. Region 4, Office of Director. 3pp. 32947:095-32947:097.
- 8510090372** LER 85-066-00: on 850803, RHR ECCS degradation occurred twice during surveillance test. Caused by inappropriate procedure test method. Procedure revised to eliminate recirculation line.W/851003 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/03. DENISE, R.P. Region 4, Office of Director. 4pp. 32946:103-32946:106.
- 8510210229** LER 85-061-00: on 850914 & 1003, control room ventilation isolation occurred due to chlorine monitor signaling high levels outside air makeup to sys. Caused by paper tape breakage. Parts in paper tape drive replaced.W/851014 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/14. DENISE, R.P. Region 4, Office of Director. 3pp. 33094:325-33094:327.
- 8510210234** LER 85-057-01: on 850712, ESF actuation initiated by control room intake monitor alarm resulted in control room ventilation isolation. Caused by mismatch between software & hardware in microprocessing unit. Mod installed.W/851014 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/14. DENISE, R.P. Region 4, Office of Director. 7pp. 33094:332-33094:338.
- 8510240166** LER 85-057-01: on 850712, three control bldg dampers failed to close following unplanned ESF actuation. Caused by hardware/software mismatch & faulty switch. Switch replaced & hardware/software mod underway.W/851014 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/14. DENISE, R.P. Region 4, Office of Director. 7pp. 33156:340-33156:346.
- 851031075** LER 85-067-00: on 850923, reactor trip, turbine trip, steam generator blowdown & sample isolation, feedwater isolation & auxiliary feedwater actuation occurred. Caused by failed controller card. Card replaced.W/851023 tr.
WILLIAMS, M.G., KOESTER, G.L. Kansas Gas & Electric Co. 85/10/23. DENISE, R.P. Region 4, Office of Director. 3pp. 33291:345-33291:347.

U. Congressional/Executive Correspondence

- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230106** Forwards Press Release 85-68 re NRC proposed fine against util for alleged noncompliance concerning improperly conducted preoperational testing program.
KAMMERER, C. Office of Congressional Affairs. 85/05/09. MARKEY, E.J. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:054-33109:055.
- 8510230261** Forwards Press Release 84-115 re NRC proposed fine against util for apparent violation of NRC regulations.
KAMMERER, C. Office of Congressional Affairs. 84/09/28. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 2pp. 33109:110-33109:111.

V. Operator Examinations

- 8509240248** Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8510040075** Responds to NRC 850821 ltr re violations noted in Insp Rept 50-483/85-17 on 850716-31. Corrective actions: administrative procedures re health physics & emergency preparedness reviewed & training lessons revised.
SCHNELLD, D.F. Union Electric Co. 85/09/20. SHAFER, W.D. Region 3, Office of Director. 4pp. 32851:025-32851:028.
- 8510080068** Ack receipt of FEMA 850903 ltr & exercise evaluation of 850905 offsite emergency preparedness exercise involving State of MO & Counties of Gasconade, Callaway, Osage & Montgomery. No deficiencies identified.
SHAFER, W.D. Region 3, Office of Director. 85/09/30. SCHNELLD, D.F. Union Electric Co. 2pp. 32928:210-32928:252.
- 8510100055** Forwards Rev 6 to physical security plan. Rev withheld (ref 10CFR73.21).
FARRIS, C.J. Union Electric Co. 85/10/01. KEEPLER, J. Region 3, Office of Director. 1p. 32960:032-32960:032.
- 8510150384** Rev 2 to Emergency Plan Implementing Procedure EIP-ZZ-C0020, "Callout of Corporate Emergency Organization."
POTEAU, G.N. Union Electric Co. 85/10/08. 10pp. 33013:165-33010:174.

- 8510180035** Advises that 851001 Rev 6 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
AXELSON, W.L. Region 3, Office of Director. 85/10/08. SCHNELLD, D.F. Union Electric Co. 3pp. 33026:340-33026:342.

- 8510290111** Rev 2 to Emergency Plan Implementing Procedure EIP-ZZ-00216, "Potassium Iodide Administration."
FAULKNER, M. Union Electric Co. 85/10/22. 22pp. 33235:272-33235:293.

P. Operating license stage documents & correspondence

- 8510180485** FOIA request for four categories of documents re QC at facility. Newspaper articles re problems w/QC encl.
BELL, N. Nuclear Information & Resource Service. 85/09/23. FELTON, J.M. Division of Rules and Records. 6pp. 33068:349-33068:353.
- 8510070491** Forwards 850925 biweekly FR notice of applications & amends to OLs involving NSHC W/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/02. SCHNELLD, D.F. Union Electric Co. 3pp. 32901:295-32901:297.
- 8510150023** Forwards Amend 8 to License NPF-30 & safety evaluation. Amend changes Tech Specs to extend 18-month surveillance interval for various tests until prior to startup.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/03. SCHNELLD, D.F. Union Electric Co. 4pp. 33031:112-33031:134.
- 8510150024** Amend 8 to License NPF-30, changing Tech Specs to extend 18-month surveillance interval for various tests until prior to startup.
O'CONNOR, P.W. Licensing Branch 1. 85/10/03. 15pp. 33031:116-33031:130.
- 8510150026** Safety evaluation supporting Amend 8 to License NPF-30.
* Office of Nuclear Reactor Regulation, Director. 85/10/03. 4pp. 33031:131-33031:134.
- 8510100089** Forwards revs to operating QA manual, per 10CFR50.54(a) & 50.71(e)(1). Revs result of internal FSAR change notices & do not reduce commitments in program description previously accepted by NRC.
SCHNELLD, D.F. Union Electric Co. 85/10/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 32960:189-32960:198.
- 8510180467** Partial response to FOIA request for four categories of documents re QC at facility. Documents on App A available in PDR. Search continuing.
FELTON, J.M. Division of Rules and Records. 85/10/11. BELL, N. Nuclear Information & Resource Service. 2pp. 33068:354-33068:356.
- 8510230067** Proposes schedule for meeting requirements of 10CFR50.62 re ATWS rule, per Generic Ltr 85-06. Util concurs w/WCAP-10858, "ATWS Mitigating Sys Actuation Circuitry Generic Design Package."
SCHNELLD, D.F. Union Electric Co. 85/10/14. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33101:094-33101:096.
- 8510180051** Application for amend to License NPF-30, replacing Tech Spec Figure 3.9-1 w/curves representing criteria for storing Westinghouse optimized or std fuel & altering distance between fuel assemblies. Fee paid.
SCHNELLD, D.F. Union Electric Co. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 33063:064-33063:084.
- 8510180060** Marked-up proposed Tech Specs, replacing Figure 3.9-1 w/curves representing criteria for storing Westinghouse optimized or std fuel & revising Section 5.6.1.1 b giving ctr to ctr distance between fuel assemblies.
* Union Electric Co. 85/10/15. 7pp. 33063:078-33063:084.
- 8510230020** Application for amend to License NPF-30, revising Tech Spec Section 3/4.3.1 re specified surveillance intervals & out-of-svc times for reactor protection sys instrumentation, per Suppl 1 to WCAP-10271 Fee paid.
SCHNELLD, D.F. Union Electric Co. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 8pp. 33101:323-33101:346.
- 8510230029** Proposed Tech Spec Section 3/4.3.1, revising specified surveillance intervals & out-of-svc times for reactor protection sys instrumentation.
* Union Electric Co. 85/10/16. 16pp. 33101:331-33101:346.
- 8510300001** Requests exemption from App A to 10CFR20 to allow credit for use of radioisotope protection factor for GMF-I filter canisters. Exemption would reduce physical work effort, stress & personnel radiation exposure.
SCHNELLD, D.F. Union Electric Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 24pp. 33247:037-33247:060.
- 8510290261** Ack receipt of 851004 submittal. Based on current review schedule, more than 60 days from date of submittal may be required to complete review of Chapter 17.2 QA program description changes prescribed by 10CFR50.54(a).
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/24. SCHNELLD, D.F. Union Electric Co. 1p. 33239:360-33239:360.
- 8510310455** Notification of 851029 meeting w/util in Bethesda, MD re proposed mod to low temp overpressurization sys.
ALEXION, T.W. Licensing Branch 1. 85/10/28. YOUNGBLOOD, B.J. Licensing Branch 1. 4pp. 33278:269-33278:272.

Q. Inspection reports, IE Bulletins & correspondence

- 8510040075** Responds to NRC 850821 ltr re violations noted in Insp Rept 50-483/85-17 on 850716-31. Corrective actions: administrative procedures re health physics & emergency preparedness reviewed & training lessons revised.
SCHNELLD, D.F. Union Electric Co. 85/09/20. SHAFER, W.D. Region 3, Office of Director. 4pp. 32851:025-32851:028.
- 8510010324** Forwards Rev 0 to NRC-02 "Sampling Plan for Visual Reinsp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. DUTTON, D.E. Southern Co. Services, Inc. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

242 DOCKETED ITEMS

-8510010378 Rev 0 to NCI-02, "Sampling Plan for Visual Reinsp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510080611 Forwards Safety Insp Rept 50-483/85-16 on 850625-0903 & notice of violation.
CHRISSTIMOS,N. Region 3, Office of Director. 85/09/27. SCHNELL,D.F. Union Electric Co. 2pp. 32927:091-32927:105.

-8510080614 Notice of violation from insp on 850625-0903.
CHRISSTIMOS,N. Region 3, Office of Director. 85/09/25. 1p. 32927:093-32927:093.

-8510080616 Safety Insp Rept 50-483/85-16 on 850625-0903 Violation noted: lack of operator attention where allowable axial flux difference exceeded.
SUERMANN,J.F. Region 3, Office of Director. 85/09/24. 12pp. 32927:094-32927:105.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510280260 Forwards Safety Insp Rept 50-483/85-12 on 850310-0527 & notice of violation.
CHRISSTIMOS,N. Region 3, Office of Director. 85/10/03. SCHNELL,D.F. Union Electric Co. 2pp. 33192:004-33192:026.

-8510280264 Notice of violation from insp on 850310-0527.
CHRISSTIMOS,N. Region 3, Office of Director. 85/10/03. 2pp. 33192:006-33192:007.

-8510280268 Insp Rept 50-483/85-12 on 850310-0527 Violation noted: failure to provide adequate acceptance criteria in QC program/procedures.
SUERMANN,J.F. Region 3, Office of Director. 85/09/30. 19pp. 33192:008-33192:026.

8510150022 IE Info Notice 85-060, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510010623 Monthly operating rept for Jul 1985 W/850803 tr.
GOODENOW,R.R., MILTENBERGER,S. Union Electric Co. 85/07/31. 6pp. 32830:039-32830:044.

S. Reportable occurrences, LERs & related correspondence

8510010648 Special Rept 85-08 on 850814, during storm, true field strong motion accelerometer inoperable. Caused by voltage surge when lightning struck near power block. Instruments returned to vendor for repairs W/850923 tr.
MILTENBERGER,S. Union Electric Co. 85/09/23. KEPPLER,J.A. Region 3, Office of Director. 3pp. 32820:214-32820:216.

8510010651 Special Rept 85-07 on 850826, diesel generator failed to come up to rated voltage during surveillance test. Caused by electrician incorrectly installing relay wiring. Relay leads landed correctly. Electrician counseled W/850923 tr.
MILTENBERGER,S. Union Electric Co. 85/09/23. KEPPLER,J.G. Region 3, Office of Director. 4pp. 32820:210-32820:213.

8510020089 Special Rept 85-09 on 850823, Channel 1 of loose parts monitoring sys indicated cable fault during control room shift & surveillance. Cause not determined during investigation. Work request initiated W/850923 tr.
MILTENBERGER,S. Union Electric Co. 85/09/23. KEPPLER,J.G. Region 3, Office of Director. 4pp. 32827:322-32827:325.

8510010646 Forwards LER 85-025-01 re intermediate range high flux reactor trip caused by blown fuse in ex-core neutron monitoring channel. Expected submission date of supplemental rept amended due to continuing investigation.
MILTENBERGER,S. Union Electric Co. 85/09/27. Record Services Branch (Document Control Desk). 2pp. 32820:183-32820:186.

-8510010647 LER 85-025-01 on 850506, intermediate range high flux reactor trip occurred. Caused by blown fuse in ex-core neutron monitoring channel. Fuse replaced. Discussions w/Westinghouse indicate leak path allows currents to be superimposed.
NASLUND,G.D. Union Electric Co. 85/09/27. 2pp. 32820:185-32820:186.

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets. Insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.
SCHREIBER,H. Louis-Ailes Co. 85/09/30. NUCOR,K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851:100-32851:107.

8510170294 LER 85-040-00 on 850910, firewatch patrol covering portion of containment bldg performed late. Caused by back-to-back firewatches, causing late arrival at access area. Instructions changed to emphasize allowing ample time W/851010 tr.
DAVIS,J.E., MILTENBERGER,S. Union Electric Co. 85/10/10. 5pp. 33061:265-33061:269.

8510220052 LER 85-041-00 on 850913, sleeve to damper clearance for 12 dampers discovered below Tech Spec 3.7.11 fire rating. Caused by failure of const phase to account for thermal expansion clearance w/mtg tolerances. W/851014 tr.
MACFARLAND,T.H., MILTENBERGER,S. Union Electric Co. 85/10/14. 5pp. 33095:274-33095:278.

V. Operator Examinations

8510010406 Notifies that operator & senior operator licensing exams scheduled for wk of 851216. Util requested to provide encl approved ref mat by 851112 in order to meet schedule.
REYES,L.A. Region 3, Office of Director. 85/09/25. SCHNELL,D.F. Union Electric Co. 5pp. 32803:272-32803:275.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

8504090467 Vols 1,2 & 3 to "Design Review of Brown & Root Engineering Work for South Texas Project."
* Quadrex Corp. 81/05/31. 666pp. 29745:076-29747:021.

8510010145 Advises that ASME Code Case N-413 may be used for linear-type supports, within limitations stated in inquiry & reply sections of code case. per 850629 request. Commitment to make necessary changes to FSAR in future amend acceptable.
KNIGHTON,G.W. Licensing Branch 3. 85/09/23. GOLDBERG,J.H. Houston Lighting & Power Co. 3pp. 32833:276-32833:278.

8510010463 Forwards Miller & Lents 820831 rept, "Assessment of Potential Likelihood of Economically Producing Hydrocarbons Located Beneath South Texas Project Site" & main cooling reservoir documents, including test repts.
WISENBURG,M.R. Houston Lighting & Power Co. 85/09/24. KNIGHTON,G.W. Licensing Branch 3. 88pp. 32803:282-32804:025.

-8510010464 "Assessment of Potential Likelihood of Economically Producing Hydrocarbons Located Beneath South Texas Project Site."
VON TUNELN,P. Miller & Lents, Ltd. 82/08/31. 18pp. 32804:007-32804:025.

8510040457 Responds to 850913 concerns re General Physics Corp training program dealing w/containment integrated leak rate testing. Offensive mat removed from files.
GOLDBERG,J.H. Houston Lighting & Power Co. 85/09/30. TAYLOR,J.M. Director's Office, Office of Inspection and Enforcement. 3pp. 32854:014-32854:016.

8510090411 Ack receipt of 850826 request to issue second certificate of pollution control facilities. Based on review, certificate executed.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/09/30. GOLDBERG,J.H. Houston Lighting & Power Co. 6pp. 32964:309-32964:314.

8510080464 Provides addl info re risk mgt program to evaluate design changes in form of modified preliminary scoping study. per 850819 commitment. Positive displacement charging pump incorporated in program.
GOLDBERG,J.H. Houston Lighting & Power Co. 85/10/02. KNIGHTON,G.W. Licensing Branch 3. 7pp. 32922:027-32922:033.

8510080340 Clarifies that stainless steel piping will be used for ECCS piping in contact w/borated piping. Carbon steel piping may be used for portions of ECCS containing nonborated piping.
WISENBURG,M.R. Houston Lighting & Power Co. 85/10/03. KNIGHTON,G.W. Licensing Branch 3. 7pp. 32919:343-32919:346.

8510110274 Forwards missing sections of 850826 draft SER re current status of NRC review of FSAR.
NOVAK,T.M. Assistant Director for Licensing. 85/10/04. GOLDBERG,J.H. Houston Lighting & Power Co. 120pp. 33011:019-33011:155.

8510150081 Forwards four drawings & info to facilitate Auxiliary Sys Branch safety review. Info will be provided in future FSAR amend.
WISENBURG,M.R. Houston Lighting & Power Co. 85/10/07. KNIGHTON,G.W. Licensing Branch 3. 7pp. 33000:297-33000:304.

8510110223 Informs of schedule for implementing applicable requirements of 10CFR50.62 re reduction of risk from ATWS events. Equipment will be installed & tested in Unit 1 no later than first refueling outage.
WISENBURG,M.R. Houston Lighting & Power Co. 85/10/08. THOMPSON,H.L. Division of Licensing. 3pp. 32974:191-32974:193.

8510160076 Submits revised list of personnel directly associated w/ facilities resulting from Region IV reorganization & personnel reassignments.
JOHNSON,E.H. Region 4, Office of Director. 85/10/08. GOLDBERG,J.H. Houston Lighting & Power Co. 1p. 33028:010-33028:010.

8510150207 Forwards responses to Questions 210.02 through 210.07 per 850806 request for addl info. Info concerns piping supports & valves in cooling loops of spent fuel pool cooling & safety-related instrument tubing. Marked-up FSAR pages encl.
WISENBURG,M.R. Houston Lighting & Power Co. 85/10/09. KNIGHTON,G.W. Licensing Branch 3. 18pp. 33008:278-33008:295.

8510170100 Forwards draft technical evaluation repts for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when actions can be arranged to resolve discrepancies.
CRUTCHFIELD,D. Assistant Director for Safety Assessment. 85/10/11. NOVAK,T.M. Assistant Director for Licensing. 3pp. 33044:010-33044:027.

8510170190 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review: Data & Info Capabilities'..." technical evaluation rept.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/3092. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044:157-33044:170.

8510220309 Forwards Rev 12 to "QA Program Description," for design & const phase. Rev submitted in accordance w/requirements of 10CFR50.55(f)(3). GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/11. MARTIN, R.D. Region 4, Office of Director. 150pp. 33083:044-33083:295.

8510220311 Rev 12 to "QA Program Description."
* Ebasco Services, Inc. (subs. of Enserch Corp.). 85/10/11. 100pp. 33083:185-33083:295.

8510220179 Forwards draft FSAR Section 5.3.2.1 per NRC request for position on NRC rule concerning pressurized thermal shock. Info will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33090:056-33090:059.

8510240463 Notification of 851023-25 meetings w/utl in Bethesda, MD to discuss effects of faulting at site, auxiliary feedwater reliability analysis, long-term cooling/RHR qualification, fire protection & radiological emergency plan.
KADAMBI, N.P. Licensing Branch 3. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182:164-33182:167.

8510250453 Forwards marked-up FSAR pages to be incorporated into future amend re heaters in MSIV cubicle HVAC sys. per R. Coel request.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33170:127-33170:135.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSA, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

8507180711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review: Program Description & Procedure' for Bellefonte Nuclear Plant..."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

8510310362 Forwards safety evaluation of 850829 info on implementation of Rev 2 to NCI-01, "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" & proposed changes to FSAR. Proposed changes acceptable w/o encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/23. GOLDBERG, J.H. Houston Lighting & Power Co. 6pp. 33278:158-33278:163.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510180040 Responds to draft SER Confirmatory Item 0.0-4 re confirmatory test described in IE Bulletin 80-06. Revised response to Question 032.43 committing to testing required by Action 2 of bulletin encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33063:056-33063:058.

8510180044 Forwards response to draft SER or FSAR items. Marked-up FSAR pages, which will be incorporated in future FSAR amend, encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 27pp. 33054:018-33054:044.

8510180046 Forwards response to draft SER or FSAR items re ASHRAE, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33054:045-33054:049.

8510180047 Forwards response to draft SER or FSAR items re Chapters 3.6 & 9, including marked-up FSAR pages to be included in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided. W/one oversize drawing.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 30pp. 33055:001-33055:031.

8510180066 Forwards response to draft SER or FSAR items re MSIV closure on safety injection. Encl marked-up FSAR pages will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33063:087-33063:092.

8510180079 Forwards response to draft SER/FSAR Item F 9.4-2 (partial) re miscellaneous bldgs HVAC sys & current design info. Encl includes marked-up FSAR pages which will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33063:094-33063:117.

8510180101 Forwards response to draft SER or FSAR items.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33063:156-33063:161.

8510180116 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be included in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33063:162-33063:170.

8510180121 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 10pp. 33062:156-33062:165.

8510180122 Forwards response to draft SER/FSAR items, including TMI Item II.F.1 Encl marked-up FSAR pages will be included in future amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33059:307-33059:330.

8510180189 Forwards response to FSAR or draft SER items, including items D 4.4-3 re loose parts monitoring sys. per Rev 1 to Reg Guide 1.133 & D 12.3-4 re containment radiation monitors, per NUREG-0737, item II.F.1.3.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33062:302-33062:310.

8510180218 Forwards responses to draft SER open items re Section 9.5.1, "Fire Protection." Fire hazards analysis rept amend includes encl responses.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062:311-33062:315.

8510180241 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 64pp. 33061:161-33061:224.

8510180250 Forwards responses to draft SER & FSAR items re Chapters 5, 6 & 7 concerning RHR HX design. Marked-up FSAR pages will be included in future FSAR amend. List of item numbers correspond to list given to NIP Kadambi on 851008.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 30pp. 33061:131-33061:160.

8510180269 Forwards response to draft SER or FSAR items re feedwater line break. Mark-ups on FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 64pp. 33061:006-33061:069.

8510180331 Forwards response to open & confirmatory draft SER items. FSAR open items & open NRC questions re environ qualification detection of fuel rod failure schedule. NP Kadambi received list on 851008 from ME Powell.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33062:022-33062:025.

8510180345 Notifies that FSAR Table 7.5-1 lists all plant Category 1 & 2 post-accident monitoring equipment & qualification for Category 1 & 2 variables. In response to draft SER Open Item 3.11-3.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33062:017-33062:018.

8510180363 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33059:275-33059:281.

8510180368 Forwards response to draft SER or FSAR item 12.3-5 re typical traffic patterns, consisting of 18 oversize initial architectural drawings info will not be incorporated into radiation zone drawings.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33062:166-33062:169.

8510180386 Forwards response to draft SER or FSAR items re Sections 2.4.3.4 & 3.5, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 43pp. 33062:201-33062:243.

8510180418 Forwards response to draft SER or FSAR items concerning recirculation intake structures per Reg Guide 1.82. Encl marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33056:339-33056:344.

8510220204 Forwards revised FSAR Figures 11.4-1 & 2, per draft SER, Section 11.4. Open item 11.4-2 re process & instrumentation diagram for solid waste processing sys. Figures will be incorporated into FSAR as part of Amend 52.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062:261-33062:265.

8510180027 Forwards marked-up FSAR pages in response to draft SER Open Item 15.4-2 re dropped rod analysis. Response will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33063:026-33063:049.

8510180041 Forwards response to draft SER or FSAR items, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 19pp. 33059:288-33059:306.

8510180064 Submits response to draft SER item C 0.2-3 re LOCA break discharge coefficient. Numerous conservatisms accounted for in blowdown, refill & reflood phases of FSAR LOCA calculation. Limiting break identified.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33054:053-33054:059.

8510180262 Forwards response to draft SER & FSAR items re Chapter 7A, Item II.B.3 concerning post-accident sampling capability. Marked-up FSAR pages to be included in future FSAR amend also encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 47pp. 33061:317-33061:363.

8510180333 Forwards response to draft SER or FSAR Section 3.6 pipe break analysis, consisting of items F 3.6-1, F 3.6-2, F 3.6-5(P), F 3.6-7, F 3.6-8, F 3.6-10, F 3.6-22(P), G210.020-1(P), G210.020-2(P), G231.004-1 & G410.005-1(P).
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 164pp. 33069:032-33069:195.

8510210044 Responds to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events." Info discusses automatic shut trip mod requested in 830810 SER. Three oversize drawings encl.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/14. THOMPSON, F.L. Division of Licensing. 9pp. 33080:001-33080:010.

244 DOCKETED ITEMS

- 8510220132** Forwards response to draft SER or FSAR item re containment leak rate test pressurization sys. Marked-up FSAR page will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33090:325-33090:329.
- 8510250128** Forwards response to draft SER/FSAR item F Q430.096, Section 9.5.6 re air start sys. Marked-up pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33172:081-33172:087.
- 8510250436** Responds to draft SER/FSAR items re qualification of fire doors. Summary of engineering evaluation of special function nonfire-rated doors in App R fire barriers and.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33169:319-33169:322.
- 8510250503** Forwards responses to draft SER Open items 14.2-1, 14.2-5, 14.2-6, 14.2-7, 14.2-9, 14.2-12 & 14.2-15. Changes to FSAR Section 14.2 also encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 150pp. 33169:144-33169:308.
- 8510310230** Forwards missing sections of 850826 draft SER. Sections document NRC evaluation of indicated portions of FSAR.
NOVAK, T.M. Assistant Director for Licensing. 85/10/18. GOLDBERG, J.H. Houston Lighting & Power Co. 9pp. 33178:011-33178:106.
- 8510240442** Forwards response to draft SER or FSAR item F 10.0-1, App 10A, "Auxiliary Feeder System" description, reliability evaluation.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 56pp. 33172:036-33172:091.
- 8510240466** Forwards responses to request for add info re draft SER w/ four oversize drawings.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 17pp. 33174:026-33174:043.
- 8510250145** Forwards response to draft SER or FSAR items D 0.1-1.D 2.4-3 & C 2.3-1 re Sections 9.2.5 & 2.3.1.2.8 revs to clarify essential cooling pond (LHS) design & evaluation.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 58pp. 33172:012-33172:069.
- 8510250258** Responds to draft SER/FSAR items for Chapter 14 re startup testing. FSAR Section 14.2 no longer uses term "Phase I test." Existing test description adequate based on issuance of Amend #8.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 14pp. 33172:256-33172:269.
- 8510250295** Forwards response to draft SER & FSAR items, including testing of remote shutdown operation, insp of new fuel & central assemblies upon receipt & physical security plan. Marked-up FSAR pages will be incorporated in FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 25pp. 33171:112-33171:138.
- 8510250304** Forwards response to draft SER or FSAR items for Chapters 7 & 13 re TMI requirements & operating plant organizations, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open items provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 59pp. 33171:053-33171:111.
- 8510250356** Responds to draft SER/FSAR items re Table 3.10N-1 on Seismic Category 1 instrumentation & electrical equipment in NSSS scope. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 8pp. 33172:190-33172:197.
- 8510250381** Forwards response to draft SER & FSAR items for Chapter 12 re radiation monitoring & protection. Encl marked-up FSAR pages will be incorporated in future amend unless otherwise noted.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 16pp. 33172:163-33172:178.
- 8510250404** Forwards response to draft SER or FSAR item D 0.0-8 re methodology used to establish Tech. Spec trip setpoints & allowable values.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33172:295-33172:298.
- 8510250489** Forwards marked-up FSAR pages in response to draft SER Open item 0.0-7 & draft FSAR Open item 7.2-2 re steam generator ref leg compensation algorithm. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33171:342-33171:346.
- 8510280312** Forwards response to draft SER or FSAR item F 3.5-2 re identification of codes, strds & specs applicable to design. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33193:076-33193:084.
- 8510280321** Forwards response to draft SER or FSAR item F 11.5-21 re radiation monitoring. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 14pp. 33193:015-33193:028.
- 8510280333** Forwards response to draft SER & FSAR items D 3.10-6, D 3.10-7 & D 3.10-8 re Table 3.9-1.2 concerning check valves. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 17pp. 33193:091-33193:107.
- 8510280364** Forwards response to draft SER or FSAR items D 3.10-2 (P), D 3.10-3 (P), D 3.10-5 (P), D 3.10-11 (P), D 3.10-13 (P), D 3.10-19, D 3.10-20 & F 3.10-21 re equipment qualification (non-NSSS scope).
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 21pp. 33192:042-33192:062.
- 8510280383** Forwards response to draft SER & FSAR items re NSSS scope of equipment qualification. Marked-up encl FSAR pages will be incorporated in future amend to FSAR.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 13pp. 33192:291-33192:303.
- 8510280411** Forwards response to draft SER & FSAR open/confirmatory items, including item F 4.3-1 re const matls. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 57pp. 33192:234-33192:290.
- 8510280415** Forwards responses to draft SER & draft FSAR items re Section 3.11N on environ design of mechanical & electrical equipment. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33192:225-33192:233.

F. Security, medical, emergency & fire protection plans

- 8510250512** Notification of 850917 meeting w/utl in Bethesda, MD to discuss fire protection afforded to cable concentration areas.
KADAMBI, N.P. Licensing Branch 3. 85/09/13. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33226:109-33226:111.
- 8510010023** Summary of 850917 meeting w/utl & Ebasco re fire protection at cable concentrations. Meeting attendees list encl.
KADAMBI, N.P. Licensing Branch 3. 85/09/23. Licensing Branch 3. 6pp. 32833:181-32833:186.
- 8510250172** Inform of 851031 & 1101 emergency planning conference at facility to coordinate w/ FEMA, NRC, State of TX & Matagorda County activities. Conference agenda & map encl.
DEWEASE, J.G. Houston Lighting & Power Co. 85/09/25. MARTIN, R.D. Region 4, Office of Director. 6pp. 33172:208-33172:211.
- 8510150079** Summary of 850909 & 10 meetings w/utl re Power Sys Branch concerns on communication sys, vital areas & mod to Q40.10. Meeting agenda & list of attendees encl.
KADAMBI, N.P. Licensing Branch 3. 85/10/03. Licensing Branch 3. 8pp. 33042:187-33042:203.
- 8510080427** Forwards updated info contained in utl 850902 ltr re qualified display processing sys verification & validation program per discussions at 850815 meeting w/ NRC.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/04. KNIGHTON, G.W. Licensing Branch 3. 21pp. 32922:224-32922:244.
- 8510180218** Forwards responses to draft SER open items re Section 9.5.1, "Fire Protection." Fire hazards analysis rept amend includes and responses.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062:311-33062:315.
- 8510240463** Notification of 851023-25 meetings w/utl in Bethesda, MD to discuss effects of faulting at site, auxiliary feedwater reliability analysis, long-term cooling/RHR qualification, fire protection & radiological emergency plan.
KADAMBI, N.P. Licensing Branch 3. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182:164-33182:167.
- 8510220302** Forwards Amend 2 to fire hazards analysis rept for South Texas Project Units 1 & 2, incorporating listed changes, including addition of fixed overhead full area coverage sprinklers to cable spreading rooms & power cable vault.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33090:330-33091:231.
- 8510220305** Amend 2 to fire hazards analysis rept for South Texas Project Units 1 & 2.
Houston Lighting & Power Co. 85/09/25. 220pp. 33090:335-33091:231.
- 8510250436** Responds to draft SER/FSAR items re qualification of fire doors. Summary of engineering evaluation of special function nonfire-rated doors in App R fire barriers and.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33169:319-33169:322.
- 8510250295** Forwards response to draft SER & FSAR items, including testing of remote shutdown operation, insp of new fuel & central assemblies upon receipt & physical security plan. Marked-up FSAR pages will be incorporated in FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 25pp. 33171:112-33171:138.

G. Adjudicatory correspondence

- 8510020166** Applicants proposed findings of fact & conclusions of law, Phase II, re second partial initial decision involving application for license. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger #485 641. 85/09/30. 300pp. 32822:196-32823:135.
- 8510030028** Motion for ASLB ordered production of documents to reopen record for new contention/discovery & extension of time until 851104 for filing proposed findings & conclusions. Certificate of Svc encl. Related correspondence.
SHOEN, L.A. Citizens Concerned About Nuclear Power, Inc. #485 660. 85/09/30. Atomic Safety and Licensing Board Panel. 36pp. 32842:274-32842:309.
- 8510100023** Memorandum & order granting 2-wk extension for Citizens Concerned About Nuclear Power to file proposed findings of fact & conclusions of law on Phase II. Served on 851007.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 691. 85/10/04. Citizens Concerned About Nuclear Power, Inc. 4pp. 32960:171-32960:174.

8510100074 Response opposing Citizens Concerned About Nuclear Power, Inc. 850930 motion for extension of time to prepare proposed findings of fact & conclusions of law. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger. #485 678. 85/10/04. Atomic Safety and Licensing Board Panel. 8pp. 32960:126-32960:131.

8510110203 Informs of no intentions to suppl records for Phase II hearings re ufl 850730 supplemental response to NRC notice of violation concerning issue B/D-1, adequacy of Ebasco backfill activities. Certificate of Svc encl.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 724. 85/10/08. BECHHOEFER, C., LAMB, J.C., SHON, F.J. Atomic Safety and Licensing Board Panel. 4pp. 32974:026-32974:029.

8510160244 Response opposing Citizens Concerned About Nuclear Power, Inc. 850930 motion for ASLB ordered production of documents, reopening of record, admittance of new contention & discovery & extensions of time. Certificate of Svc encl.
GUTTERMAN, A.H. Houston Lighting & Power Co. GUTTERMAN, A.H. Newman & Holtzinger. #485 779. 85/10/10. Atomic Safety and Licensing Board Panel. 22pp. 33022:335-33022:356.

8510180277 Response opposing Citizens Concerned About Nuclear Power 850930 motion for production of documents, reopening of record, admission of new contention & discovery. Certificate of Svc encl.
PERLIS, R.G. Hearing Branch 3. #485 796. 85/10/15. Atomic Safety and Licensing Board Panel. 12pp. 33061:070-33061:081.

8510180230 Motion to establish listed schedule for Phase III of ASLB 811216 fourth prehearing conference order re issue F concerning QA for operations & Contention 3 re overpressurization. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger. #485 799. 85/10/16. Atomic Safety and Licensing Board Panel. 7pp. 33061:227-33061:233.

8510180296 Motion to reopen Phase II record to admit four encl exhibits. Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. #485 817. 85/10/16. Atomic Safety and Licensing Board Panel. 31pp. 33069:001-33069:031.

8510180374 Order ruling on Citizens Concerned About Nuclear Power 850930 motion for production of documents, to reopen record, for new contention, for discovery & for extensions of time. Jordan chronology admitted. Served on 851017.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 822. 85/10/16. Houston Lighting & Power Co. 2pp. 33059:357-33059:358.

8510180389 Motion to reopen Phase II record & extend right to discovery set forth in ASLB 850618 memorandum & order to all parties. Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. #485 818. 85/10/16. Atomic Safety and Licensing Board Panel. 13pp. 33062:188-33062:200.

8510210061 Forwards Citizens Concerned About Nuclear Power Exhibit 148 for inclusion in facility docket, per ASLB 851016 order.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 833. 85/10/17. CLEMENTS, W.L. Docketing & Services Branch. 13pp. 33072:049-33072:061.

8510210107 Order extending time until 851108 for Citizens Concerned About Nuclear Power & State of TX to respond to applicant 851014 motion to establish Phase I schedule NRC may respond by 851113. Served on 851018.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 825. 85/10/17. Citizens Concerned About Nuclear Power, Inc. 2pp. 33073:301-33073:302.

8510210210 Advises of error in applicant 851014 motion to establish schedule for Phase III indicating that NRC would not be filing response. NRC will submit response. Related correspondence.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 834. 85/10/17. BECHHOEFER, C., LAMB, J.C., SHON, F.J. Atomic Safety and Licensing Board Panel. 4pp. 33074:098-33074:101.

8510290209 Response to applicant 851004 motion to incorporate transcript corrections. Offers no objection except for listed proposed changes. Certificate of Svc encl.
PIRFO, O.R. PIRFO, O.R. Hearing Branch 3. #485 913. 85/10/24. Atomic Safety and Licensing Board Panel. 4pp. 33236:340-33236:343.

8510310286 Order granting Concerned Citizens Against Nuclear Power 851029 request for extension until 851105 to file proposed Phase II findings of fact & conclusions of law. Add extensions for parties listed. Served on 851030.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 978. 85/10/30. Office of the Executive Legal Director. 1p. 33273:240-33273:240.

M. Antitrust correspondence

8510100021 Forwards responses to Reg Guide 9.3 re antitrust OL review, including changes & updates which occurred since Sept 1980.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/08. CLEARY, D.P. Siting Analysis Branch. 72pp. 32959:243-32959:315.

G. Inspection reports, IE Bulletins & correspondence

8510010144 Forwards revised response to violations noted in Insp Repts 50-498/83-24 & 50-499/83-24, correcting plotting of location of backfill relative density tests. Locations under truck bay not under bearing foundation. Related correspondence.
GOLDBERG, J.H. Houston Lighting & Power Co. #365 061. 85/07/30. MARTIN, R.D. Region 4, Office of Director. 11pp. 32833:279-32833:289.

8509180250 Requests that listed actions be taken to counteract and misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. GOLDBERG, J.H. Houston Lighting & Power Co. 11pp. 32854:360-32855:008.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8510030057 Forwards preservice exam plan, "Eddy Current Exam Manual for Houston Lighting & Power Co., 1985." Plan is initial exam plan for steam generator tubing per 10CFR50.55a & ASME Section XI & will be revised during performance of preservice insp.
WISENBURG, M.R. Houston Lighting & Power Co. 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32843:113-32843:118.

8510030063 "Eddy Current Exam Manual for Houston Lighting & Power Co., 1985." BROOKS, W.E. Babcock & Wilcox Co. 85/08/21. 74pp. 32843:115-32843:188.

8510080592 Ack receipt of 850826 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-498/85-07 & 50-499/85-07.
JOHNSON, E.H. Region 4, Office of Director. 85/09/30. GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 32927:067-32927:077.

8510080595 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-498/85-07 & 50-499/85-07. Corrective actions. Procedure ASP-23 revised to provide enhanced details & instructions for completion of tool data base issue/record card.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/08/26. MARTIN, R.D. Region 4, Office of Director. 9pp. 32927:069-32927:077.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180040 Responds to draft SER Confirmatory item 0.0-4 re confirmatory test described in IE Bulletin 80-06. Revised response to Question 032.43 committing to testing required by Action 2 of bulletin encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33063:056-33063:058.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510220357 Ack receipt of 85/918 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-498/85-06 & 50-499/85-06.
JOHNSON, E.H. Region 4, Office of Director. 85/10/16. GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 33089:338-33089:344.

8510220360 Responds to NRC 850816 ltr re violations noted in Insp Repts 50-498/85-06 & 50-499/85-06. Corrective actions. Deficiency Rpt M-0578 issued & retorquing of bolts performed.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/09/13. MARTIN, R.D. Region 4, Office of Director. 5pp. 33089:340-33089:344.

8510150025 IE Info Notice 85-081, "Prf" is Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:089-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510010095 Second interim deficiency rept re unanalyzed seismic interactions. Initially reported on 850508. Review project continuing. Next rept will be submitted by 851115.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 32809:215-32809:216.

8510090117 Revised final deficiency rept re containment isolation valves for auxiliary feedwater sys (AFW). Initially reported on 830822. New qualified valves purchased. Table 3.9-1.2 of FSAH modified to include five AFW valves.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/03. MARTIN, R.D. Region 4, Office of Director. 2pp. 32942:136-32942:137.

8510090138 First interim deficiency rept re document control ctr personnel checking uncontrolled Bachtel std computer programs manual in violation of procedures. Initially reported on 850905. Next rept will be submitted by 851220.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/04. MARTIN, R.D. Region 4, Office of Director. 3pp. 32941:261-32941:263.

8510210301 Interim deficiency rept re valve installation process documentation. Initially reported on 850913. Review of documentation being performed to assess safety impact. Next rept will be submitted before 851221.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/11. MARTIN, R.D. Region 4, Office of Director. 2pp. 33094:357-33094:358.

8510220481 First interim deficiency rept re lack of physical separation between Class 1E & non-Class 1E electrical circuits. Initially reported on 850912. Protective barriers will be installed. Next rept expected by 851220.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/14. MARTIN, R.D. Region 4, Office of Director. 4pp. 33108:015-33108:018.

8510250309 First interim deficiency rept re mixing of greases in safety-related equipment. Initially reported on 850916. Procedures for greasing of bearings revised to mitigate possibility of over-greasing. Next rept by 851213.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/17. MARTIN, R.D. Region 4, Office of Director. 4pp. 33223:272-33223:275.

246 DOCKETED ITEMS

8510250325 Second interim deficiency report re improper consideration of prying action for pipe support anchorages. Initially reported on 850524. Design methodology for sizing of bolts modified. Next report will be submitted by 851220.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/17. MARTIN, R.D. Region 4, Office of Director. 4pp. 33223-276-33223-279.

8510310241 First interim deficiency report re in-situ of structural steel installation. Initially reported on 850920. Thorough review of in-situ documentation in progress. Next report will be submitted by 851220.

GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/18. MARTIN, R.D. Region 4, Office of Director. 4pp. 33292-032-33292-035.

T. Hearing transcripts on non-antitrust matters

8510100159 Proposed corrections to 850711 transcript for Phase II of proceeding Certificate of Service.
GUTTERMAN, A.H. Houston Lighting & Power Co. GUTTERMAN, A.H. Newman & Holtzinger. #485 685. 85/10/04. 41pp. 32962-020-32962-062.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8504090467 Vols 1, 2 & 3 to "Design Review of Brown & Root Engineering Work for South Texas Project."
* Quadrex Corp. 81/05/31. 666pp. 29745-076-29747-021.

8510010145 Advises that ASME Code Case N-413 may be used for linear-type supports, within limitations stated in inquiry & reply sections of code case; per 850829 request. Commitment to make necessary changes to FSAR in future amend acceptable.
KNIGHTON, G.W. Licensing Branch 3. 85/09/23. GOLDBERG, J.H. Houston Lighting & Power Co. 3pp. 32833-276-32833-278.

8510010463 Forwards Miller & Lents 820831 report, "Assessment of Potential Likelihood of Economically Producing Hydrocarbons Located Beneath South Texas Project Site" & main cooling reservoir documents, including test reports.
WISENBURG, M.R. Houston Lighting & Power Co. 85/09/24. KNIGHTON, G.W. Licensing Branch 3. 6pp. 32803-282-32804-025.

8510010444 "Assessment of Potential Likelihood of Economically Producing Hydrocarbons Located Beneath South Texas Project Site."
VON TUNGEN, P. Miller & Lents, Ltd. 82/08/31. 18pp. 32804-007-32804-025.

8510040457 Responds to 850913 concerns re General Physics Corp training program dealing w/containment integrated leak rate testing. Offensive mail removed from files.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/09/30. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 3pp. 32854-014-32854-016.

8510090411 Ack receipt of 850826 request to issue second certificate of pollution control facilities. Based on review, certificate executed.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/30. GOLDBERG, J.H. Houston Lighting & Power Co. 6pp. 32964-309-32964-314.

8510080464 Provides addl info re risk mgmt program to evaluate design changes in form of modified preliminary scoping study, per 850819 commitment. Positive displacement charging pump incorporated in program.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/02. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32922-027-32922-033.

8510080340 Clarifies that stainless steel piping will be used for ECCS piping in contact w/borated piping. Carbon steel piping may be used for portions of ECCS containing nonborated piping.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/03. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32919-343-32919-349.

8510110274 Forwards missing sections of 850826 draft SER re current status of NRC review of FSAR.
NOVAK, T.M. Assistant Director for Licensing. 85/10/04. GOLDBERG, J.H. Houston Lighting & Power Co. 120pp. 33011-010-33011-155.

8510150081 Forwards four drawings & info to facilitate Auxiliary Sys Branch safety review. Info will be provided in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/07. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33000-297-33000-304.

8510110223 Informs of schedule for implementing applicable requirements of 10CFR50.62 re reduction of risk from ATWS events. Equipment will be installed & tested in Unit 1 no later than first refueling outage.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/08. THOMPSON, H.L. Division of Licensing. 3pp. 32974-191-32974-193.

8510160076 Submits revised list of personnel directly associated w/ facilities resulting from Region IV reorganization & personnel reassignments.
JOHNSON, E.H. Region 4, Office of Director. 85/10/08. GOLDBERG, J.H. Houston Lighting & Power Co. 1p. 33028-010-33028-010.

8510150207 Forwards responses to Questions 210.02 through 210.07, per 850806 request for addl info. Info concerns piping, supports & valves in cooling loops of spent fuel pool cooling & safety-related instrument tubing. Marked-up FSAR pages encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/09. KNIGHTON, G.W. Licensing Branch 3. 18pp. 33008-278-33008-295.

8510170100 Forwards draft technical evaluation reports for Generic Ltr 83-28, Item 1.2 re Salem ATWS events. Project managers should advise Div of Human Factors Safety when telcons can be arranged to resolve discrepancies.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/11. NOVAK, T.M. Assistant Director for Licensing. 3pp. 33044-010-33044-027.

8510170199 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.2, 'Post-Trip Review Data & Info Capabilities'." technical evaluation report.
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/3092. 85/10/11. NRC - No Detailed Affiliation Given. 14pp. 33044-157-33044-170.

8510220309 Forwards Rev 12 to "QA Program Description," for design & const phase Rev submitted in accordance w/requirements of 10CFR50.55(f)(3).
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/11. MARTIN, R.D. Region 4, Office of Director. 150pp. 33083-044-33083-295.

8510220311 Rev 12 to "QA Program Description."
* Ebasco Services, Inc. (subs. of Enserch Corp.). 85/10/11. 100pp. 33083-185-33083-295.

8510220179 Forwards draft FSAR Section 5.3.2.1 per NRC request for position on NRC rule concerning pressurized thermal shock. Info will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33090-058-33090-059.

8510240463 Notification of 851023-25 meetings w/utl in Bethesda, MD to discuss effects of insulating at site, auxiliary feedwater reliability analysis, long-term cooling/RHR qualification, fire protection & radiological emergency plan.
KADAMBI, N.P. Licensing Branch 3. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-164-33182-167.

8510250453 Forwards marked-up FSAR pages to be incorporated into future amend re heaters in MSIV cubicle HVAC sys, per R. Coel request.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33170-127-33170-135.

8510300112 Forwards reports re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.
ADENSA, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262-231-33262-231.

8510160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events), Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262-232-33262-255.

8510310362 Forwards safety evaluation of 850829 info on implementation of Rev 2 to NCI-01, "Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants" & proposed changes to FSAR Proposed changes acceptable w/o encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/23. GOLDBERG, J.H. Houston Lighting & Power Co. 6pp. 33278-158-33278-163.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510180040 Responds to draft SER Confirmatory Item 0.0-4 re confirmatory test described in IE Bulletin 80-06. Revised response to Question 032.43 committing to testing required by Action 2 of bulletin encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33063-056-33063-058.

8510180044 Forwards response to draft SER or FSAR items. Marked-up FSAR pages which will be incorporated in future FSAR amend, encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 27pp. 33054-018-33054-044.

8510180046 Forwards response to draft SER or FSAR items re ASHRAE, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33054-045-33054-049.

8510180047 Forwards response to draft SER or FSAR items re Chapters 3.6 & 9, including marked-up FSAR pages to be included in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided w/one oversize drawing.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 30pp. 33055-001-33055-031.

8510180066 Forwards response to draft SER or FSAR items re MSIV closure on safety injection. Encl marked-up FSAR pages will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33063-087-33063-092.

8510180079 Forwards response to draft SER/FSAR Item F 9.4-2 (partial) re miscellaneous bldgs HVAC sys & current design info. Encl includes marked-up FSAR pages which will be incorporated into future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33063-094-33063-117.

8510180101 Forwards response to draft SER or FSAR items.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33063-156-33063-161.

8510180116 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be included in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33063-162-33063-170.

8510180121 Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 10pp. 33062-156-33062-165.

- 8510180122** Forwards response to draft SER/FSAR items, including TMI Item II.F.1. Encl marked-up FSAR pages will be included in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33059-307-33059-330.
- 8510180189** Forwards response to FSAR or draft SER items, including Items D 4.4-3 re loose parts monitoring sys. per Rev 1 to Reg Guide 1.133 & D 12.3-4 re containment radiation monitors, per NUREG-0737, Item II.F.1.3.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33062-302-33062-310.
- 8510180218** Forwards responses to draft SER open items re Section 9.5.1, "Fire Protection." Fire hazards analysis rept amend includes encl responses.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062-311-33062-315.
- 8510180241** Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 64pp. 33061-161-33061-224.
- 8510180250** Forwards responses to draft SER & FSAR items re Chapters 5, 6 & 7 concerning RHR HX design. Marked-up FSAR pages will be included in future FSAR amend. Listed item numbers correspond to list given to NP Kadambi on 851008.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 30pp. 33061-131-33061-160.
- 8510180269** Forwards response to draft SER or FSAR items re feedwater line break. Mark-ups on FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 64pp. 33061-006-33061-069.
- 8510180331** Forwards response to open & confirmatory draft SER items. FSAR open items & open NRC questions re environ qualification detection of fuel rod failure schedule. NP Kadambi received list on 851008 from ME Powell.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33062-022-33062-025.
- 8510180345** Notifies that FSAR Table 7.5-1 lists all plant Category 1 & 2 post-accident monitoring equipment & qualification for Category 1 & 2 variables, in response to draft SER Open Item 3.11-3.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33062-017-33062-018.
- 8510180363** Forwards response to draft SER or FSAR items. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33059-276-33059-281.
- 8510180366** Forwards response to draft SER or FSAR item 12.3-5 re typical traffic patterns, cc'-sisting of 18 oversize initial architectural drawings. Info will not be incorporated into radiation zone drawings.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33062-166-33062-169.
- 8510180386** Forwards response to draft SER or FSAR items re Sections 2.4.3.4 & 3.5, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 43pp. 33062-201-33062-243.
- 8510180418** Forwards response to draft SER or FSAR items concerning re-circulation intake structures per Reg Guide 1.82. Encl marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 6pp. 33056-339-33056-344.
- 8510220204** Forwards revised FSAR Figures 11.4-1 & 2, per draft SER, Section 11.4. Open item 11.4-2 re process & instrumentation diagram for solid waste processing sys. Figures will be incorporated into FSAR as part of Amend 52.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33082-261-33082-265.
- 8510180027** Forwards marked-up FSAR pages in response to draft SER Open Item 15.4-2 re dropped rod analysis. Response will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 24pp. 33063-026-33063-049.
- 8510180041** Forwards response to draft SER or FSAR items, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open & confirmatory items & open NRC questions provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 19pp. 33059-286-33059-306.
- 8510180064** Submits response to draft SER item C 0.2-3 re LOCA break discharge coefficient. Numerous conservatisms accounted for in blowdown, refill & reflood phases of FSAR LOCA calculation. Limiting break identified.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33054-053-33054-059.
- 8510180262** Forwards response to draft SER & FSAR items re Chapter 7A, Item II.B.3 concerning post-accident sampling capability. Marked-up FSAR pages to be included in future FSAR amend also encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 47pp. 33061-317-33061-363.
- 8510180333** Forwards response to draft SER or FSAR Section 3.6 pipe break analyses, consisting of Items F 3.6-1, F 3.6-2, F 3.6-5(P), F 3.6-7, F 3.6-8, F 3.6-10, F 3.6-22(P), G010.018-1, G210.020-1(P), G210.020-2(P), G231.004-1 & G410.005-1(P).
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 164pp. 33069-032-33069-195.
- 8510210044** Responds to Generic Ltr 85-28, "Required Actions Based on Generic Implications of Salem ATWS Events." Info discusses automatic shunt trip mod requested in 830810 SER. Three oversize drawings encl.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/14. THOMPSON, H.L. Division of Licensing. 9pp. 33080-001-33080-010.
- 8510220132** Forwards response to draft SER or FSAR item re containment leak rate test pressurization sys. Marked-up FSAR page will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33090-325-33090-329.
- 8510250128** Forwards response to draft SER/FSAR item F Q430.096, Section 9.5.6 re air start sys. Marked-up pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33172-081-33172-087.
- 8510250436** Responds to draft SER/FSAR items re qualification of fire doors. Summary of engineering evaluation of special function nonfire-rated doors in App R fire barriers encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33169-319-33169-322.
- 8510250503** Forwards responses to draft SER Open Items 14.2-1, 14.2-5, 14.2-6, 14.2-7, 14.2-9, 14.2-12 & 14.2-15. Changes to FSAR Section 14.2 also encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 150pp. 33169-144-33169-308.
- 8510310230** Forwards missing sections of 850826 draft SER Sections document NRC evaluation of indicated portions of FSAR.
NOVAK, T.M. Assistant Director for Licensing. 85/10/18. GOLDBERG, J.H. Houston Lighting & Power Co. 96pp. 33278-311-33278-106.
- 8510240442** Forwards response to draft SER or FSAR item F 10.0-1, App 10A, "Auxiliary Feedwater Sys." describing reliability evaluation.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 56pp. 33149-036-33149-091.
- 8510240466** Forwards responses to request for addl info re draft SER W/ four oversize drawings.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 17pp. 33154-026-33154-043.
- 8510250115** Forwards response to draft SER or FSAR items D 0.1-1, D 2.4-3 & C 2.3-1 re Sections 9.2.5 & 2.3.1.2.8 revs to clarify essential cooling pond (UHS) design & evaluation.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 58pp. 33172-012-33172-069.
- 8510250258** Responds to draft SER/FSAR items for Chapter 14 re startup testing. FSAR Section 14.2 no longer uses term "Phase I test." Existing test description adequate based on issuance of Amend 48.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 14pp. 33172-256-33172-269.
- 8510250295** Forwards response to draft SER & FSAR items, including testing of remote shutdown operation, insp. of new fuel & central assemblies upon receipt & physical security plan. Marked-up FSAR pages will be incorporated in FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 25pp. 33171-112-33171-136.
- 8510250304** Forwards response to draft SER or FSAR items for Chapters 7 & 13 re TMI requirements & operating plant organizations, including marked-up FSAR pages to be incorporated in future FSAR amend. List of draft SER & FSAR open items provided.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 59pp. 33171-053-33171-111.
- 8510250356** Responds to draft SER/FSAR items re Table 3.10N-1 on Seismic Category I instrumentation & electrical equipment in NSSS scope. Marked-up FSAR pages will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 8pp. 33172-190-33172-197.
- 8510250381** Forwards response to draft SER & FSAR items for Chapter 12 re radiation monitoring & protection. Encl marked-up FSAR pages will be incorporated in future FSAR amend unless otherwise noted.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 16pp. 33172-163-33172-176.
- 8510250404** Forwards response to draft SER or FSAR item D 0.0-6 re methodology used to establish Tech Spec trip setpoints & allowable values.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33172-295-33172-298.
- 8510250469** Forwards marked-up FSAR pages in response to draft SER Open Item 0.0-7 & draft FSAR Open Item 7.2-2 re steam generator ref leg compensation algorithm. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33171-342-33171-346.
- 8510280312** Forwards response to draft SER or FSAR item F 3.8-2 re identification of codes, stds & specs applicable to design. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33193-076-33193-084.
- 8510280321** Forwards response to draft SER or FSAR item F 11.5-21 re radiation monitoring. Changes will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 14pp. 33193-015-33193-028.
- 8510280333** Forwards response to draft SER & FSAR items D 3.10-6, D 3.10-7 & D 3.10-8 re Table 3.9-1.2 concerning check valves. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 17pp. 33193-091-33193-107.
- 8510280364** Forwards response to draft SER or FSAR items D 3.10-2 (P), D 3.10-3 (P), D 3.10-5 (P), D 3.10-11 (P) through D 3.10-13 (P), D 3.10-19, D 3.10-20 & F 3.10-21 re equipment qualification (non-NSSS scope).
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 21pp. 33192-042-33192-062.

248 DOCKETED ITEMS

8510280383 Forwards response to draft SER & FSAR items re NRCSS scope of equipment qualification. Marked-up and FSAR pages will be incorporated in future amend to FSAR.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 13pp. 33192-291-33192-303.

8510280411 Forwards responses to draft SER & FSAR open/confirmatory items, including Item F.4.3-1 re const matls. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 57pp. 33192-234-33192-290.

8510280415 Forwards responses to draft SER & draft FSAR items re Section 3.11N on environ design of mechanical & electrical equipment. Info will be incorporated in future FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/22. KNIGHTON, G.W. Licensing Branch 3. 9pp. 33192-225-33192-233.

F. Security, medical, emergency & fire protection plans

8510250512 Notification of 850917 meeting w/utl in Bethesda, MD to discuss fire protection afforded to cable concentration areas.
KADAMBI, N.P. Licensing Branch 3. 85/09/13. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33226-109-33226-111.

8510010023 Summary of 850917 meeting w/utl & Ebasco re fire protection at cable concentrations. Meeting attendees list encl.
KADAMBI, N.P. Licensing Branch 3. 85/09/23. Licensing Branch 3. 8pp. 32833-181-32833-186.

8510250172 Informs of 851031 & 1101 emergency planning conference at facility to coordinate utl, FEMA, NRC, State of TX & Matagorda County activities. Conference agenda & map encl.
DEWEASE, J.G. Houston Lighting & Power Co. 85/09/25. MARTIN, R.D. Region 4, Office of Director. 6pp. 33172-206-33172-211.

8510150679 Summary of 850909 & 10 meetings w/utl re Power Sys Branch concerns on communication sys, vital areas & mod to Q040.10. Meeting agenda & list of attendees encl.
KADAMBI, N.P. Licensing Branch 3. 85/10/03. Licensing Branch 3. 8pp. 33042-187-33042-203.

8510080427 Forwards updated info contained in utl 850802 re qualified display processing sys verification & validation program, per discussions at 850815 meeting w/ NRC.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/04. KNIGHTON, G.W. Licensing Branch 3. 21pp. 33022-224-33022-244.

8510180218 Forwards responses to draft SER open items re Section 9.5.1, "Fire Protection." Fire hazards analysis rept amend includes encl responses.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062-311-33062-315.

8510240463 Notification of 851023-25 meetings w/utl in Bethesda, MD to discuss effects of faulting at site, auxiliary feedwater reliability analysis, long-term cooling/IDH qualification, fire protection & radiological emergency plan.
KADAMBI, N.P. Licensing Branch 3. 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33182-164-33182-187.

8510220302 Forwards Amend 2 to fire hazards analysis rept for South Texas Project Units 1 & 2, incorporating tested changes, including addition of fixed overhead full size coverage sprinklers to cable spreading rooms & power cable vault.
GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33090-330-33091-231.

8510220305 Amend 2 to fire hazards analysis rept for South Texas Project Units 1 & 2.
Houston Lighting & Power Co. 85/09/25. 220pp. 33090-335-33091-231.

8510250436 Responds to draft SER/FSAR items re qualification of fire doors. Summary of engineering evaluation of special function non-fire-rated doors in App R fire barriers encl.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/18. KNIGHTON, G.W. Licensing Branch 3. 4pp. 33169-319-33169-322.

8510320295 Forwards response to draft SER & FSAR items, including testing of remote shutdown operation, map of new fuel & control assemblies upon receipt & physical security plan. Marked-up FSAR pages will be incorporated in FSAR amend.
WISENBURG, M.R. Houston Lighting & Power Co. 85/10/21. KNIGHTON, G.W. Licensing Branch 3. 25pp. 33171-112-33171-138.

G. Adjudicatory correspondence

8510020166 Applicants proposed findings of fact & conclusions of law, Phase II re second partial initial decision involving application for license. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger. #485 641. 85/09/30. 300pp. 32822-196-32823-135.

8510030028 Motion for ASLB ordered production of documents to reopen record for new contention, discovery & extension of time until 851104 for filing proposed findings & conclusions. Certificate of Svc encl. Related correspondence.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. #485 860. 85/09/30. Atomic Safety and Licensing Board Panel. 7pp. 32842-274-32842-309.

8510100023 Memorandum & order granting 2-wk extension for Citizens Concerned About Nuclear Power to file proposed findings of fact & conclusions of law on Phase II. Served on 851007.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 591. 85/10/04. Citizens Concerned About Nuclear Power, Inc. App. 32990-171-32990-174.

8510100074 Response opposing Citizens Concerned About Nuclear Power, Inc. 850930 motion for extension of time to prepare proposed findings of fact & conclusions of law. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger. #485 878. 85/10/04. Atomic Safety and Licensing Board Panel. 5pp. 32960-126-32960-131.

8510110203 Informs of no intentions to supply records for Phase II hearings re utl 850730 supplemental response to NRC notice of violation concerning issue B/D-1, adequacy of Ebasco backfill activities. Certificate of Svc encl.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 724. 85/10/08. BECHHOEFER, C. LAMB, J.C. SHON, F.J. Atomic Safety and Licensing Board Panel. 4pp. 32974-026-32974-029.

8510180244 Response opposing Citizens Concerned About Nuclear Power, Inc. 850930 motion for ASLB ordered production of documents, reopening of record, admission of new contention & discovery & extensions of time. Certificate of Svc encl.
GUTTERMAN, A.H. Houston Lighting & Power Co. GUTTERMAN, A.H. Newman & Holtzinger. #485 779. 85/10/10. Atomic Safety and Licensing Board Panel. 22pp. 33022-335-33022-356.

8510180277 Response opposing Citizens Concerned About Nuclear Power 850930 motion for production of documents, reopening of record, admission of new contention & discovery. Certificate of Svc encl.
PERLIS, R.G. Hearing Branch 3. #485 796. 85/10/15. Atomic Safety and Licensing Board Panel. 12pp. 33061-070-33061-081.

8510180230 Motion to establish listed schedule for Phase III of ASLB 811216 fourth prehearing conference order re issue F concerning QA for operations & Contention 3 re overpressurization. Certificate of Svc encl.
NEWMAN, J.R. Houston Lighting & Power Co. NEWMAN, J.R. Newman & Holtzinger. #485 799. 85/10/16. Atomic Safety and Licensing Board Panel. 7pp. 33061-227-33061-233.

8510180296 Motion to reopen Phase II record to admit four encl exhibits. Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. #485 817. 85/10/16. Atomic Safety and Licensing Board Panel. 31pp. 33069-001-33069-031.

8510180374 Order ruling on Citizens Concerned About Nuclear Power 850930 motion for production of documents to reopen record, for new contention, for discovery & for extensions of time. Jordan chronology admitted. Served on 851017.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 822. 85/10/16. Houston Lighting & Power Co. 2pp. 33059-357-33059-358.

8510180389 Motion to reopen Phase II record & extend right to discovery set forth in ASLB 850618 memorandum & order to all parties. Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. #485 818. 85/10/16. Atomic Safety and Licensing Board Panel. 13pp. 33062-188-33062-200.

8510210061 Forwards Citizens Concerned About Nuclear Power Exhibit 148 for inclusion in facility docket, per ASLB 851016 order.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 833. 85/10/17. CLEMENTS, V.L. Docketing & Services Branch. 13pp. 33072-049-33072-061.

8510210107 Order extending time until 851108 for Citizens Concerned About Nuclear Power & State of TX to respond to applicant 851014 motion to establish Phase III schedule NRC may respond by 851113. Served on 851018.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 825. 85/10/17. Citizens Concerned About Nuclear Power, Inc. 2pp. 33073-301-33073-302.

8510210210 Advises of error in applicant 851014 motion to establish schedule for Phase III indicating that NRC would not be filing response. NRC will submit response. Related correspondence.
NEWMAN, J.R. Newman & Holtzinger. NEWMAN, J.R. Houston Lighting & Power Co. #485 834. 85/10/17. BECHHOEFER, C. LAMB, J.C. SHON, F.J. Atomic Safety and Licensing Board Panel. 4pp. 33074-098-33074-101.

8510290209 Response to applicant 851004 motion to incorporate transcript corrections. Offers no objection except for listed proposed changes. Certificate of Svc encl.
PIRFO, O.R. PIRFO, O.R. Hearing Branch 3. #485 913. 85/10/24. Atomic Safety and Licensing Board Panel. 4pp. 33236-340-33236-343.

8510310296 Order granting Concerned Citizens Against Nuclear Power 851029 request for extension until 851105 to file proposed Phase II findings of fact & conclusions of law. Add extensions for parties listed. Served on 851030.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. #485 978. 85/10/30. Office of the Executive Legal Director. 1p. 33273-240-33273-240.

Q. Inspection reports, IE Bulletins & correspondence

8510010144 Forwards revised response to violations noted in Insp Repts 50-498/83-24 & 50-499/83-24, correcting plotting of location of backfill relative density tests. Locations under truck bay not under bearing foundation. Related correspondence.
GOLDBERG, J.H. Houston Lighting & Power Co. #385 061. 85/07/30. MARTIN, R.D. Region 4, Office of Director. 11pp. 32833-279-32833-289.

8509180250 Requests that listed actions be taken to counteract encl misleading documentation received by employees at General Physics Corp integrated containment leak rate testing course. Deceptive insp practices not condoned by industry.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/13. GOLDBERG, J.H. Houston Lighting & Power Co. 11pp. 32854-360-32855-008.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8510040067 Notifies that Insp Rept 50-499/85-09 (canceled) Insp Rept 50-498/85-09 issued on 850712. No insp rept will be issued under first rept number.
JOHNSON, E.H. Region 4, Office of Director. 85/09/30. GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 32851-189-32851-190.

8510080592 Ask receipt of 850826 re informing NRC of steps taken to correct violations noted in Insp Repts 50-498/85-07 & 50-499/85-07.
JOHNSON, E.H. Region 4, Office of Director. 85/09/30. GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 32927-067-32927-077.

—8510080595 Responds to NRC 850725 ltr re violations noted in Insp Repts 50-498/85-07 & 50-499/85-07. Corrective actions. Procedure ASP-23 revised to provide enhanced details & instructions for completion of tool data base issue/record card. GOLDBERG, J.H. Houston Lighting & Power Co. 85/08/26. MARTIN, R.D. Region 4, Office of Director. 8pp. 32927-069-32927-077.

8509250369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510180040 Responds to draft SER Confirmatory Item 0.0-4 re confirmatory test described in IE Bulletin 80-06. Revised response to Question 032.43 committing to testing required by Action 2 of bulletin encl. WISENBURG, M.R. Houston Lighting & Power Co. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33063-056-33063-058.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510220357 Ack receipt of 850918 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-498/85-06 & 50-499/85-06. JOHNSON, E.H. Region 4, Office of Director. 85/10/16. GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 33089-338-33089-344.

—8510220360 Responds to NRC 850816 ltr re violations noted in Insp Repts 50-498/85-06 & 50-499/85-06. Corrective actions. Deficiency Rept M-0576 issued & retorquing of bolts performed. GOLDBERG, J.H. Houston Lighting & Power Co. 85/09/13. MARTIN, R.D. Region 4, Office of Director. 5pp. 33089-340-33089-344.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

S. Reportable occurrences, LERs & related correspondence

8510010095 Second interim deficiency rept re unanalyzed seismic interactions initially reported on 850508. Review project continuing. Next rept will be submitted by 851115. GOLDBERG, J.H. Houston Lighting & Power Co. 85/09/20. MARTIN, R.D. Region 4, Office of Director. 2pp. 32809-215-32809-216.

8510090117 Revised final deficiency rept re containment isolation valves for auxiliary feedwater sys (AFW) initially reported on 830822. New qualified valves purchased. Table 3.9-1.2 of FSAR modified to include five AFW valves. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/03. MARTIN, R.D. Region 4, Office of Director. 2pp. 32942-136-32942-137.

8510090138 First interim deficiency rept re document control ctr personnel checking uncontrolled Bechtel std computer programs manual in violation of procedures initially reported on 850905. Next rept will be submitted by 851220. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/04. MARTIN, R.D. Region 4, Office of Director. 3pp. 32941-261-32941-263.

8510210301 Interim deficiency rept re valve installation process documentation initially reported on 850913. Review of documentation being performed to assess safety impact. Next rept will be submitted before 851221. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/11. MARTIN, R.D. Region 4, Office of Director. 2pp. 33094-357-33094-358.

8510220481 First interim deficiency rept re lack of physical separation between Class 1E & non-Class 1E electrical circuits. Initially reported on 850912. Protective barriers will be installed. Next rept expected by 851220. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/14. MARTIN, R.D. Region 4, Office of Director. 4pp. 33108-015-33108-018.

8510250309 First interim deficiency rept re mixing of greases in safety-related equipment initially reported on 850616. Procedures for greasing of bearings revised to mitigate possibility of over-greasing. Next rept by 851213. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/17. MARTIN, R.D. Region 4, Office of Director. 4pp. 33223-272-33223-275.

8510250325 Second interim deficiency rept re improper consideration of prying action for pipe support anchorages initially reported on 850524. Design methodology for sizing of bolts modified. Next rept will be submitted by 851220. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/17. MARTIN, R.D. Region 4, Office of Director. 4pp. 33223-276-33223-279.

8510310241 First interim deficiency rept re insp of structural steel installation initially reported on 850920. Thorough review of insp documentation in progress. Next rept will be submitted by 851220. GOLDBERG, J.H. Houston Lighting & Power Co. 85/10/18. MARTIN, R.D. Region 4, Office of Director. 4pp. 33292-032-33292-035.

T. Hearing transcripts on non-antitrust matters

8510100159 Proposed corrections to 850711 transcript for Phase II of proceeding. Certificate of Svc encl. GUTTERMAN, A.H. Houston Lighting & Power Co. GUTTERMAN, A.H. Newman & Hotzinger. #485 685. 85/10/04. 41pp. 32982-020-32982-082.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A. Application/construction stage documents & correspondence

8510080156 Forwards 6-month rolling schedule incorporating 850905 submittal of interim short-term schedule for readiness review program. First review Module E3-01, re piping supports in revised format. SORESEN, G.C. Washington Public Power Supply System. 85/09/23. MARTIN, J.B. Region 5, Office of Director. 4pp. 32911-217-32911-220.

8510080245 Forwards overview of readiness review program. Description of const assurance program also encl for review & approval, based on 850829 meeting at Region V. SORESEN, G.C. Washington Public Power Supply System. 85/09/25. MARTIN, J.B. Region 5, Office of Director. 13pp. 32919-096-32919-108.

8510010268 Notification of significant licensee meeting on 851029 w/utl in Elma, WA to examine readiness review const appraisal program. * Region 5, Office of Director. 85/09/27. Region 5, Office of Director. 1p. 32800-248-32800-248.

8510030377 Responds to 850913 ltr re NRC fees billed for OL reviews for WPPSS 1,2 & 3 & insp fees for WPPSS-2. Forwards documentation & "NRC Procedures for Reviewing Disputed License Fee Billings." W/o encl. MILLER, W.D. License Fee Management Branch. 85/09/27. SORESEN, G.C. Washington Public Power Supply System. 2pp. 32848-073-32848-074.

8510180087 informs that prior to issuance of full power OL facility will be in compliance w/Section 50.62 (d) requirements of ATWS rule re submittal of schedule for meeting rule requirements within 180 days after issuance of QA guidance. SORESEN, G.C. Washington Public Power Supply System. 85/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33027-357-33027-358.

8510300046 Confirms significant licensee meeting on 851029 in Elma, WA to provide info re utl involvement in readiness review & const assurance program. SORESEN, G.C. Washington Public Power Supply System. 85/10/18. MARTIN, J.B. Region 5, Office of Director. 2pp. 33247-143-33247-144.

G. Adjudicatory correspondence

8510110161 Notice of withdrawal of appearance in proceeding. Certificate of Svc encl. HASSELL, D.F. Hearing Branch 2. #485 739. 85/10/09. 3pp. 32072-181-32072-183.

Q. Inspection reports, IE Bulletins & correspondence

8510090252 Forwards Readiness Review Insp Rept 50-508/85-05 on 850528-0904. No violation noted. MARTIN, J.B. Region 5, Office of Director. 85/09/18. MAZUR, D.W. Washington Public Power Supply System. 1p. 32946-226-32946-231.

—8510090257 Readiness Review Insp Rept 50-508/85-05 on 850528-0904. No violation noted. Major areas inspected: preservation of assets & preventive maint program. DODDS, R.T., ANKRUM, G.T., KIRSCH, D.F. Region 5, Office of Director. 85/09/10. 5pp. 32946-227-32946-231.

8501280122 IE Info Notice 85-079, "Inadequate Communications Between Maint Operations & Security Personnel." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509250369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc ltr encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

S. Reportable occurrences, LERs & related correspondence

8510090285 Final Deficiency Rept D/N #59 re possible fractured or cracked welds on Louis Allis emergency standby generators. Initially reported on 850624. Item not reportable per 10CFR50.55(a). KOHLER, A.D. Washington Public Power Supply System. 85/09/27. KIRSCH, D.F. Region 5, Office of Director. 4pp. 32947-084-32947-087.

250 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

S. Reportable occurrences, LERs & related correspondence

8510220457 Deficiency & Part 21 rept re error in Control Data GT STRUDL computer program initially reported on 850903 Pipe support final designs will be reverted using different analysis program Updated rept expected at const restart.
ROOT,R.W. Washington Public Power Supply System. 85/10/03. MARTIN,J.B. Region 5, Office of Director. 3pp. 33096-232-33096-234.

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510300038 Forwards proposed cancellation plans for plants officially canceled on 840829 Requests withdrawal of CPPR-150, CPPR-152, CPPR-172 & CPPR-173 W/two oversize drawings.
HUFHAM,J.W. Tennessee Valley Authority. 85/10/24. THOMPSON,H.L. Division of Licensing. 16pp. 33250-052-33250-069.

DOCKET STN-50-526 HARTSVILLE NUCLEAR PLANT, UNIT 3

A. Application/construction stage documents & correspondence

8510300038 Forwards proposed cancellation plans for plants officially canceled on 840829 Requests withdrawal of CPPR-150, CPPR-152, CPPR-172 & CPPR-173 W/two oversize drawings.
HUFHAM,J.W. Tennessee Valley Authority. 85/10/24. THOMPSON,H.L. Division of Licensing. 16pp. 33250-052-33250-069.

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

8510090509 Concurs in rescinding Subagreements 1 & 2 re review of Skagit/Hanford Nuclear Project Units 1 & 2 in response to 850820 memo.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/09/27. ESCHELS,C. Washington, State of. 2pp. 32966-186-32966-187.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8510090509 Concurs in rescinding Subagreements 1 & 2 re review of Skagit/Hanford Nuclear Project Units 1 & 2 in response to 850820 memo.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/09/27. ESCHELS,C. Washington, State of. 2pp. 32966-186-32966-187.

Q. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), supple & correspondence

8510010046 Confirms installation & qualification of containment high range radiation monitors & primary coolant radiation monitors per 10CFR50.49 License Condition 2.C(8) & SSER (NUREG-0857).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32802-175-32802-176.

8510020009 Provides description of program to review proposed changes to plant & potential impact on Chapter 15 analyses per SSER 8 (NUREG-0857).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32824-229-32824-230.

F. Security, medical, emergency & fire protection plans

8510180335 Rev 6 to emergency plan W/851008 ltr.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/08/31. MARTIN,J.B. Region 5, Office of Director. 700pp. 33057-011-33058-050.

8510010323 Forwards Amend 8 to security plan Amend issued in preparation for issuance of Unit 2 OI Amend withheld (ref 10CFR73.21 & 2.790(d)).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32802-360-32802-361.

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V ofc Assessment will cover Apr 1984 - Sept 1985 Anticipated outline of SALP rept provided Performance analyses required by 851010.
KIRSCH,D. Region 5, Office of Director. 85/09/24. CREWS,J., HON,A., SORESENSEN,C. Region 5, Office of Director. 15pp. 32826-319-32826-333.

8510250181 Forwards public version of revised emergency plan implementing procedures including Rev 4 to EPP-02 re emergency classification & Rev 9 to EPP-03 re notification of unusual event implementing actions W/851010 release memo.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN,J.B. Region 5, Office of Director. 4pp. 33197-199-33198-161.

-8510250188 Public version of revised emergency plan implementing procedures including Rev 4 to EPP-02 re emergency classification & Rev 9 to EPP-03 re notification of unusual event implementing actions.
Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. 325pp. 33197-143-33198-161.

8510070240 Forwards FEMA rept, "Palo Verde Nuclear Generating Station Site-Specific Offsite Radiological Emergency Preparedness Alert & Notification Sys QA Verification." W/o encl.
WENSLAWSKI,F.A. Region 5, Office of Director. 85/10/01. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 32878-084-32878-084.

8510220063 Forwards Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908 & notice of violation.
KIRSCH,D.F. Region 5, Office of Director. 85/10/04. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33095-237-33095-257.

-8510220070 Notice of violation from map on 850801-0908.
MILLER,L.F. Region 5, Office of Director. 85/10/04. 2pp. 33095-239-33095-240.

-8510220075 Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908. Violations noted: failure to properly verify closure of Unit 1 doors & Tech Spec overtime limits exceeded w/o approval by plant manager or designee.
ZIMMERMAN, R., FIORELLI, G., BOSTED, C. Region 5, Office of Director. 85/09/25. 16pp. 33095-241-33095-257.

8510220193 Forwards Insp Repts 50-528/85-30 & 70-2964/85-01 on 850923-27 & notice of violation Repts & notice of violation withheld (ref 10CFR2.790).
SCARANO, R.A. Region 5, Office of Director. 85/10/17. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33087-309-33087-310.

8510220163 Discusses end evaluation of NRC public affairs activities at 1985 emergency preparedness exercise. Fifteen questions raised. Self-evaluation effective.
COOK, G.N. Region 5, Office of Director. 85/10/18. WEINSTEIN, E. Incident Response Branch. 4pp. 33090-083-33090-086.

8510300144 Forwards Mail Control & Accounting Safeguards Insp Rept 50-528/85-35 on 851007-10. No violations noted.
MONTGOMERY, J.L. Region 5, Office of Director. 85/10/24. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33248-016-33248-018.

-8510300151 Mail Control & Accounting Insp Rept 50-528/85-35 on 851007-10. No violations noted. Major areas inspected follow-up on inspector identified problem & unresolved items. Details withheld (ref 10CFR2.790).
WIEDER, A.V., SCHUSTER, M.D. Region 5, Office of Director. 85/10/23. 1pp. 33248-018-33248-018.

G. Adjudicatory correspondence

8510100177 Informs that time for Commission to act to review Director's Decision DD-85-12 expired. Commission declined review. Decision became final agency action on 851003. Served on 851007.
HOYLE, J.C. Office of the Secretary of the Commission. #485 702. 85/10/04. SCOTT, M.L. Coalition for Responsible Energy Education. 1p. 32962-200-32962-200.

8510110160 Advises that time to review Director's Decision DD-85-15 expired. NRC declined review. Decision made final agency action on 851008. Served on 851009.
CHILKIS, J. Office of the Secretary of the Commission. #485 729. 85/10/09. SCOTT, M.L. Coalition for Responsible Energy Education. 1p. 32999-350-32999-350.

I. Financial Information

8510210133 Forwards application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM & memorandum in support of application. Fee paid.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. Office of Nuclear Reactor Regulation, Director. 2pp. 33070-001-33070-002.

-8510210136 Application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/18. 150pp. 33070-003-33070-241.

-8510210137 Memorandum in support of application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/18. 200pp. 33070-242-33071-111.

K. Utility Final Safety Analysis Report (FSAR) & amendments

8510220146 Forwards revised page to FSAR Section 17.2.9 re QA during operations phase. Chemical analysis deleted as special process & cleaning changed to chemical cleaning.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. MARTIN, J.B. Region 5, Office of Director. 4pp. 33082-252-33082-255.

P. Operating license stage documents & correspondence

8510020374 Advises that solid radwaste process control program submitted w/641030 for applicable for Units 1, 2 & 3 & may be used for review & approval of Unit 2 Tech Specs now under consideration & for Unit 3 when submitted.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/09. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-349-32824-349.

8510080492 Forwards changes to FSAR Section 17.1B for review. Changes delete duplication of effort between unit & Bechtel quality organization during transition from const to operational phase.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. MARTIN, J.B. Region 5, Office of Director. 20pp. 32921-111-32921-130.

8510010123 Forwards marked-up pages of FSAR & lessons learned implementation report reflecting grab sample type post-accident sampling sys. to meet requirements of NUREG-0737, item II.B.3.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/26. KNIGHTON, G.W. Licensing Branch 3. 52pp. 32800-242-32800-349.

8510010250 Notifies that 850729 proposed changes to FSAR Section 17.1B re QA program description & 850918 add info safety 10CFR50 App 9 requirements & acceptance.
KIRSCH, D.F. Region 5, Office of Director. 35/09/26. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 32800-242-32800-243.

8510010046 Confirms installation & qualification of containment high range radiation monitors & primary coolant radiation monitors per 10CFR50.49, License Condition 2.C(8) & SSER (NUREG-0857).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32802-175-32802-175.

8510010083 Informs of reanalysis of limiting large break LOCA to confirm that impact of specific parameters do not affect results. Results demonstrated current analysis of record remains limiting for plant changes.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 1p. 32801-295-32801-295.

8510010124 Discusses methodology of large break LOCA analysis per 850829 meeting. Analysis will be submitted on 851004 for review & approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32800-200-32800-201.

8510080185 Submits rev to FSAR Section 17.2.15 re operation phase QA program. Rev provides more flexibility in disposition of nonconformances affecting preoperational test program.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN, J.B. Region 5, Office of Director. 6pp. 32918-344-32918-349.

8510020061 Forwards results of reanalysis of FSAR Chapter 15 re containment. Results presented as proposed changes to FSAR Sections 19.2.4.6.2.1 & 6.3.1.4.M. Changes will be incorporated into next FSAR amend.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 62pp. 32824-115-32824-176.

8510020101 Informs that inadvertent deboration event analysis in support of Tech Spec changes to incorporate temp dependent shutdown margin expected by Apr 1986.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-322-32824-322.

8510020190 Requests extension from implementation deadline of 851130 for justification for interim operation (JIO) re environ qualification of hydrogen recombiners. JIO end.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 5pp. 32824-332-32824-336.

8510020380 Provides add info confirming that facility small break LOCA spectrum conforms to criteria of 10CFR50.46 & bounded by limiting large break LOCA.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32824-342-32824-343.

8510020422 Forwards proposed changes to FSAR Sections 19.2.4.6.3.1.4, 15.1.5 & App 15C, incorporating results of main steam line break analysis. Changes will be incorporated into next FSAR amend per NRC approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 135pp. 32826-138-32826-272.

8510080495 Forwards util specific limiting large break LOCA reanalysis results per NRC 850830 request. Reanalysis demonstrates compliance w/10CFR50.46 Administrative limit on linear heat rate for Unit 1 will be lifted upon NRC approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/03. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32921-172-32921-175.

8510220246 Advises that unit entered Mode 2 on 850921 per 850920 meeting & confirmatory fr.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/08. MARTIN, J.B. Region 5, Office of Director. 1p. 33086-303-33086-303.

8510180036 Responds to A Han 850925 concerns re reactor cavity water seals. Seals modified by adding 3/16-in. diameter reinforcing pins in top flange. Seals not installed or located in Unit 1 containment. Seals interchangeable.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/10. MARTIN, J.B. Region 5, Office of Director. 2pp. 33024-162-33024-163.

8510180058 Advises that rev to Section 17.2.15 of FSAR re QA program description meets App B 10CFR50 requirements.
KIRSCH, D.F. Region 5, Office of Director. 85/10/10. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 33028-097-33028-097.

8510160113 Forwards Rev 1 to "Offsite Dose Calculation Manual." Changes to manual will be included in Unit 1 semiannual radioactive effluent release & waste disposal report.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/11. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33020-001-33020-082.

-8510160118 Rev 1 to "Offsite Dose Calculation Manual."
Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. 79pp. 33020-003-33020-082.

8510160049 Provides schedules for final implementation of ATWS rule requirements per Generic LR 85-06. Specific info required by Paragraph (C)(6) of rule will be submitted when preliminary design completed & approved.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33028-123-33028-124.

8510170107 Responds to request & commitments made during 851008 meeting & in 850918 fr re auxiliary pressurizer spray sys. Implementation of listed enhancements scheduled for test refueling outage for Unit 1. Concurrence requested by 851022.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/15. KNIGHTON, G.W. Office of Nuclear Reactor Regulation, Director. 53pp. 33036-047-33036-099.

8510210116 Application for amend to License NPF-41 extending 851130 date for environ qualification of hydrogen recombiners to 850331 due to testing failures at vendor facilities. Fee paid.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/16. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33072-224-33072-230.

8510210133 Forwards application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM & memorandum in support of application. Fee paid.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. Office of Nuclear Reactor Regulation, Director. 2pp. 33070-001-33070-002.

-8510210136 Application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/18. 150pp. 33070-003-33070-241.

252 DOCKETED ITEMS

-8510210137 Memorandum in support of application requesting relief by issuance of order authorizing transfer of facility through sale & leaseback financing transaction by PSC of NM.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/18. 200pp. 33070-242-33071-111.

8510220135 Requests authorization to use ASME Code N-403, permitting reassembly of component & piping supports from completed supports not in operating svc. Required documentation available.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Office of Nuclear Reactor Regulation, Director. 1p. 33062-100-33062-100.

8510300041 Confirms 851021 telcon w/ W Quinn re proposed enhancements to chemical & vol control sys. Review of events on 850912, 1003 & 07 sdr in progress. Assessment of adequacy of proposed mode premature.
KNIGHTON, G.W. Licensing Branch 3. 85/10/21. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33261-360-33261-361.

8510310537 Requests detailed explanation of how structural analysis performed on spray pond piping sys & why results of analysis demonstrate that structural integrity of sys will be maintained.
KNIGHTON, G.W. Licensing Branch 3. 85/10/24. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33277-037-33277-038.

G. Inspection reports, IE Bulletins & correspondence

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V. o/c Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP rept provided. Performance analyses required by 851010.
KIRSCH, D.F. Region 5, Office of Director. 85/09/24. CREWS, J., CHAFFEE, A., MILLER, L. Region 5, Office of Director. 15pp. 32826-319-32826-333.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220063 Forwards Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908 & notice of violation.
KIRSCH, D.F. Region 5, Office of Director. 85/10/04. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33095-237-33095-257.

-8510220070 Notice of violation from insp on 850801-0908.
MILLER, L.F. Region 5, Office of Director. 85/10/04. 2pp. 33095-239-33095-240.

-8510220075 Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908. Violations noted: failure to properly verify closure of Unit 1 doors & Tech Spec overtime limits exceeded w/o approval by plant manager or designee.
ZIMMERMAN, R., FIORELLI, G., BOSTED, C. Region 5, Office of Director. 85/09/25. 16pp. 33095-241-33095-257.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by utility. Penalty proposed for breakdown of GA program.
KAMMERER, C. Office of Congressional Affairs. 84/04/04. OTTINGER, R.L. House of Rep., Energy & Commerce. MARKEY House of Rep. DE CONCONI Senate. 3pp. 33108-344-33108-348.

8510100193 EN-85-071 on 851008, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to utility. Action based on violation re unacceptable location for obtaining post-accident containment samples.
HOLLER, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/08. 1p. 32966-359-32966-359.

8510150328 Forwards supporting preliminary data & summaries for SALP, per 850924 memo. Review & comments requested.
KIRSCH, D.F. Region 5, Office of Director. 85/10/06. CREWS, J., CHAFFEE, A., MILLER, L. Region 5, Office of Director. 25pp. 33006-327-33006-351.

8510150408 Discusses insp on 850924-0712 & 23-24 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.
MARTIN, J.B. Region 5, Office of Director. 85/10/06. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 3pp. 33010-349-33010-351.

-8510150411 Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violation noted: program not established to ensure capability to obtain & analyze post-accident containment atmosphere samples.
MARTIN, J.B. Region 5, Office of Director. 85/10/06. 2pp. 33010-352-33010-353.

8510280139 Forwards Insp Repts 50-528/85-26, 50-529/85-28 & 50-530/85-22 on 850907-0922. No violations or deviations noted.
KIRSCH, D.F. Region 5, Office of Director. 85/10/09. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33194-197-33194-213.

-8510280145 Insp Repts 50-528/85-26, 50-529/85-28 & 50-530/85-22 on 850907-0922. No violation or deviation noted. Major areas inspected: instrument components, safety-related structures & closure of Allegation RV-85-A-033.
HERNANDEZ, G.H., BALL, J.R., MILLER, L.F. Region 5, Office of Director. 85/10/08. 15pp. 33194-199-33194-213.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-205-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-066.

8510220193 Forwards Insp Repts 50-528/85-30 & 70-2984/85-01 on 850923-27 & notice of violation. Repts & notice of violation withheld (ref 10CFR2.790).
SCARANO, R.A. Region 5, Office of Director. 85/10/17. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33087-309-33087-310.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250194 Ack receipt of 850523 tr informing NRC of steps taken to correct violations noted in Insp Repts 50-528/85-01 & 50-529/85-01. Corrective actions will be examined during future insp.
KIRSCH, D.F. Region 5, Office of Director. 85/10/22. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 33172-143-33172-145.

8510300144 Forwards Maint Control & Accounting Safeguards Insp Rept 50-528/85-35 on 851007-10. No violations noted.
MONTGOMERY, J.L. Region 5, Office of Director. 85/10/24. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33248-016-33248-018.

-8510300151 Maint Control & Accounting Insp Rept 50-528/85-35 on 851007-10. No violations noted. Major areas inspected: followup on inspector identified problem & unresolved items. Details withheld (ref 10CFR2.790).
WIEDER, A.V., SCHUSTER, M.D. Region 5, Office of Director. 85/10/23. 1pp. 33248-018-33248-018.

R. Periodic operating reports & related correspondence

8510010651 Monthly operating rept for Jul 1985. W/850815 tr.
RICHARDSON, M.P., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/07/31. BARRY, L.W. Office of Resource Management, Director. 8pp. 32820-202-32820-209.

8510240083 Forwards preoperational radiological monitoring program rept for 1979-1984, previously discussed w/WW Meeks. W/o encl.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33156-258-33156-258.

8510240083 Forwards preoperational radiological monitoring program rept for 1979-1984, previously discussed w/WW Meeks.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33274-063-33274-362.

-8510310163 "Preoperational Radiological Monitoring Program Rept for 1984."
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 84/12/31. 400pp. 33275-064-33275-014.

S. Reportable occurrences, LERs & related correspondence

8510010613 Deficiency Rept DER 85-26 re containment purge sys. Initially reported on 850816. Item not reportable under 10CFR50.55(e).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/11. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32830-018-32830-019.

8510010472 Part 21 & final Deficiency Rept DER 85-24 re broken diesel generator turbocharger bolts supplied by Cooper Energy Svcs. Existing bolts will be replaced w/ longer ASTM A-193, Grade B7 full threaded studs & A-194, Grade 2H nuts.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/13. KIRSCH, D.F. Region 5, Office of Director. 7pp. 32809-175-32809-181.

8510010602 Part 21 & final Deficiency Rept DER 85-27 re slippage in Pacific Scientific pipe clamps. Initially reported on 850820. Torque value increased &/or replacement bolts & nuts installed.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 4pp. 32820-356-32820-359.

8510080353 Confirms 850917 conference call to discuss 850912 unscheduled reactor shutdown & impact on chemical & vol control sys design & operation. UAR interim resolution of NRC concerns listed.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. MARTIN, J.B. Region 5, Office of Director. 4pp. 32919-339-32919-342.

8510090419 Interim Potentially Reportable Deficiency Rept DER 85-25 re auxiliary feed-water pump turbine quick start failure. Initially reported on 850806. Final rept delayed until 851017 due to extensive investigation.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/23. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32948-034-32948-035.

8510020083 LER 85-064-00 on 850826, actuation of control room essential filtration actuation signal occurred. Caused by high radiation alarm set off by ground design mod of radiation monitoring sys. ESF maint procedures revised w/850925 tr.
QUINN, W.F., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/25. 3pp. 32827-296-32827-298.

8510020504 LER 85-008-01 on 850204, max flow delivery to steam generator following automatic actuation unclear. Results of analysis confirm as-built plant performance demonstrated to produce results conservative w/ current FSAP analysis. W/850927 tr.
QUINN, W.F., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. 3pp. 32834-184-32834-186.

8510070025 LER 85-065-00 on 850829, moisture buildup in sample line from gaseous radwaste surge tank to associated sample point prevented sampling of tank. Caused by design problem. Design mod will be installed w/850930 tr.
QUINN, W.F., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. 3pp. 32900-021-32900-023.

8510220474 Final Part 21 & Deficiency Rept DER 85-20 re Cooper Energy Svcs broken diesel generator rocker arm initially reported on 850528. Rocker arm replaced. Tapet clearances will be adjusted at 18-month intervals.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KIRSCH, D.F. Region 5, Office of Director. 6pp. 33093-047-33093-054.

8510090397 Summary of Operating Reactors Events Meeting 85-17 on 850923. List of attendees & viewgraphs encl.
CRUTCHFIELD, D.D. Assistant Director for Safety Assessment. 85/10/01. THOMPSON, H.L. Division of Licensing. 27pp. 32965-021-32965-047.

8510090522 RO on 850930, plant security computer experienced momentary interruption of power, resulting in loss of sys operability. Apparently caused by switching operation in power supply sys to computer. Security alert declared. Corrective action taken.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/01. Record Services Branch (Document Control Desk). 2pp. 32946-036-32946-037.

8510110216 Forwards request for add info re pressurizer auxiliary spray sys, based on 850912 loss of all three charging pumps during loss-of-inlet test at approx 55% power. Response requested within 20 days of its date.
THOMPSON, H.L. Division of Licensing. 85/10/02. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 5pp. 33012-018-33012-022.

8510120237 PHO-V-85-066 on 851002, while operating at 50% power, reactor trip occurred after loss of electric power. Three reactor coolant pumps restarted by resetting pump circuit breaker lockout relays. Cause under investigation.
MILLER, L. ZIMMERMAN, R. Region 5, Office of Director. 85/10/04. 1p. 33009-313-33009-313.

8510170005 Unusual event on 851003, reactor tripped, resulting from loss of power from offsite sources. Cause under investigation. Plant stabilized by natural circulation to remove decay heat via steam generators. Offsite power restored.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/04. Record Services Branch (Document Control Desk). 2pp. 33053-203-33053-204.

8510150091 Summary of Operating Reactors Events Meeting 85-16 on 850918 re briefing of director, div directors & representatives on events occurring since 850909 meeting. List of attendees & viewgraphs encl.
CRUTCHFIELD, D.D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 23pp. 33030-243-33030-265.

8510150484 RO on 851007, reactor trip occurred. Caused by loss of power from offsite sources. Plant stabilized using natural circulation to remove decay heat via steam generators. LER will be submitted within 30 days.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/08. Record Services Branch (Document Control Desk). 2pp. 33015-151-33015-152.

8510160213 PHO-V-85-069 on 851003 & 08, loss of normal electric power resulted in reactor trip. Caused by switchyard electrical distribution malfunction. Licensee proceeding w/ design change to hard-wire control for feeder breakers.
PATE, R. ZIMMERMAN, R. Region 5, Office of Director. 85/10/08. 1p. 33023-123-33023-123.

8510220452 Deficiency Rept DER 85-28 re C-E instrument rack conduit installation. Initially reported on 850821. Final rpt delayed until 851101 due to extent of investigation & evaluation.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/08. KIRSCH, D.F. Region 5, Office of Director. 2pp. 33096-222-33096-223.

8510220380 LER 85-072-00 on 850913, automatic sampling of gaseous radwaste sys not available & manual sampling not accomplished. Caused by inadequate assurance of gas stripper prior to operation. Procedures revised W/851016 tr.
QUINN, W.F., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/16. 3pp. 33095-090-33095-092.

8510240055 Forwards add info re 850912 event. Licensing basis for auxiliary pressure spray sys found in Branch Technical Position RSB 5-1. Review concluded auxiliary pressure spray sys design consistent w/NRC guidelines.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/22. KNIGHTON, G.W. Office of Nuclear Reactor Regulation, Director. 15pp. 33155-212-33155-226.

8510310168 LER 85-063-00 on 850912, when main generator breaker opened, reactor tripped due to core protection calculators sensing loss of forced coolant circulation. Reactor trip caused turbine trip. Cause not stated W/851023 tr.
QUINN, W.F., VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/23. 5pp. 33291-318-33291-322.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by (ul) Penalty proposed for breakdown of QA program.
KAMMERER, C. Office of Congressional Affairs. 84/04/04. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33108-344-33108-346.

V. Operator Examinations

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V ofc.; assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP report provided. Performance analyses required by 851010.
KIRSCH, D.F. Region 5, Office of Director. 85/09/24. CREWS, J., ZIMMERMAN, R., HERNANDEZ, G. Region 5, Office of Director. 15pp. 32826-319-32826-333.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510020374 Advises that solid radwaste process control program submitted w/841030 ltr applicable for Units 1, 2 & 3 & may be used for review & approval of Unit 2 Tech Specs now under consideration & for Unit 3 when submitted.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/09. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-349-32824-349.

8510080482 Forwards changes to FSAR Section 17.1B for review. Changes delete duplication of effort between unit & Bechtel quality organization during transition from const to operational phase.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. MARTIN, J.B. Region 5, Office of Director. 20pp. 32921-111-32921-130.

8510010123 Forwards marked-up pages of FSAR & lessons learned implementation rpt, reflecting grab sample-type post-accident sampling sys to meet requirements of NUREG-0737, item 8.B.3.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/26. KNIGHTON, G.W. Licensing Branch 3. 52pp. 32801-296-32801-349.

8510010184 Ack receipt of FSAR changes to Chapter 17.1 QA program reviewed & acceptable per 10CFR50, App B.
KIRSCH, D.F. Region 5, Office of Director. 85/09/26. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 32800-205-32800-206.

8510010250 Notifies that 850729 proposed changes to FSAR Section 17.1B re QA program description & 850918 add info satisfy 10CFR50, App B requirements & acceptable.
KIRSCH, D.F. Region 5, Office of Director. 85/09/26. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 32800-242-32800-243.

8510010083 Informs of reanalysis of limiting large break LOCA to confirm that impact of specific parameters do not affect results. Results demonstrated current analysis of record remains limiting for plant changes.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 1p. 32801-295-32801-295.

8510010124 Discusses methodology of large break LOCA analysis, per 850829 meeting. Analyses will be submitted on 851004 for review & approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32800-200-32800-201.

8510080185 Submits rev to FSAR Section 17.2.15 re operation phase QA program. Rev provides more flexibility in disposition of nonconformances affecting preoperational test program.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN, J.B. Region 5, Office of Director. 6pp. 32918-344-32918-349.

8510020061 Forwards results of reanalysis of FSAR Chapter 15 re containment. Results presented as proposed changes to FSAR Sections 1.9.2.4.6.2.1 & 6.3.1.4.M. Changes will be incorporated into next FSAR amend.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 62pp. 32824-115-32824-176.

8510020181 Informs that inadvertent deboration event analysis in support of Tech Spec changes to incorporate temp dependent shutdown margin expected by Apr 1986.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-322-32824-322.

8510020190 Requests extension from implementation deadline of 851130 for justification for interim operation (JIO) re environ qualification of hydrogen recombiners. JIO encl.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 5pp. 32824-332-32824-336.

8510020380 Provides add info confirming that facility small break LOCA spectrum conforms to criteria of 10CFR50.46 & bounded by limiting large break LOCA.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32824-342-32824-343.

8510020422 Forwards proposed changes to FSAR Sections 1.9.2.4.6.3.1.4, 15.1.5 & App 15C incorporating results of main steam line break analyses. Changes will be incorporated into next FSAR amend per NRC approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 135pp. 32826-198-32826-272.

8510080495 Forwards unit specific limiting large break LOCA reanalysis results, per NRC 850830 request. Reanalysis demonstrates compliance w/10CFR50.46 Administrative limit on linear heat rate for Unit 1 will be lifted upon NRC approval.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/03. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32921-172-32921-178.

8510180055 Requests exemption from requirements of Section III.D.2.b(6) of 10CFR50, App J re testing of air locks for periods when containment integrity not required by Tech Specs.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/07. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33059-283-33059-284.

8510180036 Responds to A Han 850925 concerns re reactor cavity water seals. Seals modified by adding 3/16-inch diameter reinforcing pins in top flange. Seals not installed or located in Unit 1 containment. Seals interchangeable.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/10. MARTIN, J.B. Region 5, Office of Director. 2pp. 33024-162-33024-163.

254 DOCKETED ITEMS

8510160058 Advises that rev to Section 17.2.15 of FSAR re QA prog... description meets App 6 10CFR50 requirements.
KIRSCH,D.F. Region 5, Office of Director. 85/10/10. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 33026:097-33026:097.

8510160113 Forwards Rev 1 to "Offsite Dose Calculation Manual." Changes to manual will be included in Unit 1 semiannual radioactive effluent release & waste disposal rept.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/11. KNIGHTON,G.W. Licensing Branch 3. 2pp. 33020:001-33020:082.

-8510160118 Rev 1 to "Offsite Dose Calculation Manual."
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. 79pp. 33020:003-33020:082.

8510160049 Provides schedules for final implementation of ATWS rule requirements, per Generic Ltr 85-06. Specific info required by Paragraph (C)(6) of rule will be submitted when preliminary design completed & approved.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/12. KNIGHTON,G.W. Licensing Branch 3. 2pp. 33026:123-33026:124.

8510170107 Responds to request & commitments made during 851008 meeting & in 850918 ltr re auxiliary pressurizer spray sys. Implementation of listed enhancements scheduled for first refueling outage for Unit 1. Concurrence requested by 851022.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/15. KNIGHTON,G.W. Office of Nuclear Reactor Regulation, Director. 53pp. 33036:047-33036:099.

8510220135 Requests authorization to use ASME Code N-403, permitting reassembly of component & piping supports, from completed supports not in operating svc. Required documentation available.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON,G.W. Office of Nuclear Reactor Regulation, Director. 1p. 33082:100-33082:100.

8510220325 Forwards, for review, change to FSAR Chapter 14, deleting position of shift test director & changing responsibilities of test program director. Safety review & evaluation complete for Unit 1.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON,G.W. Licensing Branch 3. 7pp. 33086:267-33086:273.

8510310358 Forwards final draft Tech Specs. Specs developed by utilizing C-E STS & Unit 1 Tech Specs, W/o end.
KNIGHTON,G.W. Licensing Branch 3. 85/10/18. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 3pp. 33278:155-33278:157.

8510300041 Confirms 851021 telcon w/W Quinn re proposed enhancements to chemical & vol control sys. Review of events on 850912, 1003 & 07 still in progress. Assessment of adequacy of proposed mods premature.
KNIGHTON,G.W. Licensing Branch 3. 85/10/21. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33261:360-33261:361.

8510250209 Identifies equipment required to be seismically qualified not identical to previously identified Unit 1 equipment, per 851007 ltr & SSER 5 (NUREG-0857) dtd Nov 1983. Equipment qualification summary sheets end.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/23. KNIGHTON,G.W. Licensing Branch 3. 8pp. 33169:138-33169:143.

8510290095 Forwards "Summary Rept for Regional Evaluation of Palo Verde Unit 2," summarizing readiness for issuance of low power OL.
MARTIN,J.B. Region 5, Office of Director. 85/10/23. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235:315-33235:315.

-8510290102 "Summary Rept for Regional Evaluation of Palo Verde Unit 2."
* Region 5, Office of Director. 85/10/10. 61pp. 33235:316-33235:315.

8510310537 Requests detailed explanation of how structural analysis performed on spray pond piping sys & why results of analysis demonstrate that structural integrity of sys will be maintained.
KNIGHTON,G.W. Licensing Branch 3. 85/10/24. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33277:037-33277:038.

E. NRC Safety Evaluation Report (SER), supps & correspondence

8510020009 Provides description of program to review proposed changes to plant & potential impact on Chapter 15 analyses, per SSER 6 (NUREG-0857).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32824:229-32824:230.

8510180052 Forwards equipment qualification summary sheet for equipment identified to be nonidentical to Unit 1 equipment, per SSER 5 (NUREG-0857).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/07. KNIGHTON,G.W. Licensing Branch 3. 3pp. 33059:285-33059:287.

8510250209 Identifies equipment required to be seismically qualified not identical to previously identified Unit 1 equipment, per 851007 ltr & SSER 5 (NUREG-0857) dtd Nov 1983. Equipment qualification summary sheets end.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/23. KNIGHTON,G.W. Licensing Branch 3. 8pp. 33169:138-33169:143.

F. Security, medical, emergency & fire protection plans

8510180335 Rev 6 to emergency plan W/851008 ltr.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/08/31. MARTIN,J.B. Region 5, Office of Director. 70pp. 33057:011-33058:050.

8510010323 Forwards Amend 8 to security plan. Amend issued in preparation for issuance of Unit 2 OL. Amend withdrawn (ref 10CFR73.21 & 2.79(c)(d)).
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32802:360-32802:361.

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V o/c. Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP rept provided. Performance analyses required by 851010.
KIRSCH,D.F. Region 5, Office of Director. 85/09/24. CREWS,J., HON,A., SORENS,N.C. Region 5, Office of Director. 15pp. 32826:319-32826:333.

8510250181 Forwards public version of revised emergency plan implementing procedures, including Rev 4 to EPIP-02 re emergency classification & Rev 9 to EPIP-03 re notification of unusual event implementing actions. W/851010 release memo.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN,J.B. Region 5, Office of Director. 4pp. 33197:139-33198:161.

-8510250188 Public version of revised emergency plan implementing procedures, including Rev 4 to EPIP-02 re emergency classification & Rev 9 to EPIP-03 re notification of unusual event implementing actions.
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. 325pp. 33197:143-33198:161.

8510220063 Forwards Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908 & notice of violation.
KIRSCH,D.F. Region 5, Office of Director. 85/10/04. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33095:237-33095:257.

-8510220075 Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908. Violations noted: failure to properly verify closure of Unit 1 doors & Tech Spec overtime limits exceeded w/o approval by plant manager or designee.
ZIMMERMAN,R., MILLER,L. Region 5, Office of Director. 85/09/25. 16pp. 33095:241-33095:257.

8510150135 Notification of 851009 confirmatory site visit re facility security program.
LEY,M. Licensing Branch 3. 85/10/09. KNIGHTON,G.W. Licensing Branch 3. 3pp. 33031:028-33031:030.

8510220163 Discusses end evaluation of NRC public affairs activities at 1985 emergency preparedness exercise. Fifteen questions raised. Self-evaluation effective.
COOK,G.N. Region 5, Office of Director. 85/10/18. WEINSTEIN,E. Incident Response Branch. 4pp. 33090:083-33090:086.

G. Adjudicatory correspondence

8510110160 Advises that time to review Director's Decision DD-85-15 expired. NRC declined review. Decision made final agency action on 851008. Served on 851009.
CHILK,S.J. Office of the Secretary of the Commission. #485 729. 85/10/09. SCOTT,M.L. Coalition for Responsible Energy Education. 1p. 32999:350-32999:350.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510220146 Forwards revised page to FSAR Section 17.2.9 re QA during operations phase. Chemical analysis deleted as special process & cleaning changed to chemical cleaning.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. MARTIN,J.B. Region 5, Office of Director. 4pp. 33082:252-33082:255.

Q. Inspection reports, IE Bulletins & correspondence

2510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V o/c. Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP rept provided. Performance analyses required by 851010.
KIRSCH,D.F. Region 5, Office of Director. 85/09/24. CREWS,J., CHAFFEE,A., MILLER,L. Region 5, Office of Director. 15pp. 32826:319-32826:333.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc ltr end.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc ltr end.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510220063 Forwards Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908 & notice of violation.
KIRSCH,D.F. Region 5, Office of Director. 85/10/04. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33095:237-33095:257.

-8510220075 Insp Repts 50-528/85-26 & 50-529/85-27 on 850801-0908. Violations noted: failure to properly verify closure of Unit 1 doors & Tech Spec overtime limits exceeded w/o approval by plant manager or designee.
ZIMMERMAN,R., FIORELLI,G., BOSTED,C. Region 5, Office of Director. 85/09/25. 16pp. 33095:241-33095:257.

8510230018 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. End app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108:264-33108:268.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by utility. Penalty proposed for breakdown of QA program.
KAMMERER,C. Office of Congressional Affairs. 84/04/04. OTTINGER,R.L. House of Rep. Energy & Commerce. GOLDWATER Senate. STUMP House of Rep. 3pp. 33108:344-33108:346.

8510150388 Forwards supporting preliminary data & summaries for SALP, per 850924 memo. Review & comments requested.
KIRSCH,D.F. Region 5, Office of Director. 85/10/08. CREWS,J., CHAFFEE,A., MILLER,L. Region 5, Office of Director. 25pp. 33006:327-33006:351.

8510280139 Forwards Insp Repts 50-528/85-28, 50-529/85-28 & 50-530/85-22 on 850807-0922. No violations or deviations noted.
KIRSCH,D.F. Region 5, Office of Director. 85/10/09. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33194:197-33194:213.

-8510280145 Insp Repts 50-526/85-26, 50-529/85-26 & 50-530/85-22 on 850807-0622. No violation or deviation noted. Major areas inspected: instrument components, safety-related structures & closure of Abrogation RV-85-A-033. HERNANDEZ, G.H., BALL, J.R., MILLER, L.F. Region 5, Office of Director. 85/10/08. 15pp. 33194-199-33194-213.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177-001-33177-341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177-001-33177-068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177-069-33177-204.

8510250194 Ack receipt of 850523 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-526/85-01 & 50-529/85-01. Corrective actions will be examined during future insp. KIRSCH, D.F. Region 5, Office of Director. 85/10/22. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 33172-143-33172-145.

R. Periodic operating reports & related correspondence

8510240083 Forwards preoperational radiological monitoring program rept for 1979-1984, previously discussed w/WW Meenke W/o encl. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33156-258-33156-258.

8510240083 Forwards preoperational radiological monitoring program rept for 1979-1984, previously discussed w/WW Meenke. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33274-063-33274-362.

-8510310183 "Preoperational Radiological Monitoring Program Rept for 1984." * Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 84/12/31. 400pp. 33275-064-33275-014.

S. Reportable occurrences, LERs & related correspondence

8510010613 Deficiency Rept DER 85-26 re containment purge sys. Initially reported on 850816. Item not reportable under 10CFR50.55(a). VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/11. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32830-018-32830-019.

8510010472 Part 21 & final Deficiency Rept DER 85-24 re broken diesel generator turbo-charger bolts supplied by Cooper Energy Svcs. Existing bolts will be replaced w/ longer ASTM A-193 Grade B7 full threaded studs & A-194 Grade 2H nuts. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/13. KIRSCH, D.F. Region 5, Office of Director. 7pp. 32809-175-32809-181.

8510010593 Interim Deficiency Rept DER 85-28 re C-E instrument rack flexible conduit installation. Initially reported on 850821. Bechtel evaluation incomplete. Next rept will be submitted by 851011. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 3pp. 32820-345-32820-347.

8510010602 Part 21 & final Deficiency Rept DER 85-27 re slippage in Pacific Scientific pipe clamps. Initially reported on 850820. Torque value increased &/or replacement bolts & nuts installed. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 4pp. 32820-356-32820-359.

8510090419 Interim Potentially Reportable Deficiency Rept DER 85-25 re auxiliary feed-water pump turbine quick start failure. Initially reported on 850806. Final rept delayed until 851017 due to extensive investigation. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/23. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32948-034-32948-035.

8510220474 Final Part 21 & Deficiency Rept DER 85-20 re Cooper Energy Svcs broken diesel generator rocker arm. Initially reported on 850528. Rocker arm replaced. Tappet clearances will be adjusted at 18-month intervals. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KIRSCH, D.F. Region 5, Office of Director. 6pp. 33093-047-33093-054.

8510220452 Deficiency Rept DER 85-28 re C-E instrument rack conduit installation. Initially reported on 850821. Final rept delayed until 851011 due to extent of investigation & evaluation. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/08. KIRSCH, D.F. Region 5, Office of Director. 2pp. 33096-222-33096-223.

8510310254 Interim Potentially Reportable Deficiency Rept DER 85-32 re seismic separation between bldgs. Initially reported on 850917. Due to extensive investigation, final rept delayed until 851011. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/15. KIRSCH, D.F. Region 5, Office of Director. 3pp. 33292-062-33292-064.

U. Congressional/Executive Correspondence

8510230018 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-088.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by utility. Penalty proposed for breakdown of QA program. KAMMERER, C. Office of Congressional Affairs. 84/04/04. OTTINGER, R.L. House of Rep. Energy & Commerce. SIMPSON, Senate. UDALL, House of Rep. 3pp. 33108-344-33108-346.

V. Operator Examinations

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V ofc. Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP rept provided. Performance analyses required by 851010. KIRSCH, D.F. Region 5, Office of Director. 85/09/24. CREWS, J., FIORELLI, G., BOSTED, C. Region 5, Office of Director. 15pp. 32826-319-32826-333.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl. THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

8510020374 Advises that solid radwaste process control program submitted w/841030 ltr applicable for Units 1, 2 & 3 & may be used for review & approval of Unit 2 Tech Specs now under consideration & for Unit 3 when submitted. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/09. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-349-32824-349.

8510080492 Forwards changes to FSAR Section 17.18 for review. Changes delete duplication of effort between utility & Bechtel quality organization during transition from const to operational phase. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. MARTIN, J.B. Region 5, Office of Director. 20pp. 32921-111-32921-130.

8510010123 Forwards marked-up pages of FSAR & lessons learned implementation rept reflecting grab sample-type post-accident sampling sys. to meet requirements of NUREG-0737, Item II.B.3. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/26. KNIGHTON, G.W. Licensing Branch 3. 52pp. 32801-298-32801-349.

8510010184 Ack receipt of FSAR changes to Chapter 17.1. QA program reviewed & acceptable per 10CFR50, App B. KIRSCH, D.F. Region 5, Office of Director. 85/09/26. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 32800-205-32800-206.

8510010250 Notifies that 850729 proposed changes to FSAR Section 17.18 re QA program description & 850918 add info satisfy 10CFR50, App B requirements & acceptable. KIRSCH, D.F. Region 5, Office of Director. 85/09/26. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 32800-242-32800-243.

8510010083 Informs of reanalysis of limiting large break LOCA to confirm that impact of specific parameters do not affect results. Results demonstrated current analysis of record remains limiting for plant changes. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 1p. 32801-295-32801-295.

8510010124 Discusses methodology of large break LOCA analysis per 850829 meeting. Analysis will be submitted on 851004 for review & approval. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32800-200-32800-201.

8510080185 Submits rev to FSAR Section 17.2.15 re operation phase QA program. Rev provides more flexibility in disposition of nonconformances affecting preoperational test program. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN, J.B. Region 5, Office of Director. 6pp. 32918-344-32918-349.

8510020061 Forwards results of reanalysis of FSAR Chapter 15 re containment. Results presented as proposed changes to FSAR Sections 19.2.4.6.2.1 & 6.3.1.4.M. Changes will be incorporated into next FSAR amend. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 62pp. 32824-115-32824-176.

8510020181 Informs that inadvertent deboration event analysis in support of Tech Spec changes to incorporate temp dependent shutdown margin expected by Apr 1986. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 1p. 32824-322-32824-322.

8510020380 Provides addl info confirming that facility small break LOCA spectrum conforms to criteria of 10CFR50.46 & bounded by limiting large break LOCA. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32824-342-32824-343.

8510020422 Forwards proposed changes to FSAR Sections 19.2.4.6.3.1.4, 15.1.5 & App 15C, incorporating results of main steam line break analyses. Changes will be incorporated into next FSAR amend per NRC approval. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 135pp. 32826-138-32826-272.

8510080495 Forwards utility specific limiting large break LOCA reanalysis results per NRC 850830 request. Reanalysis demonstrates compliance w/10CFR50.46 Administrative limit on linear heat rate for Unit 1 will be lifted upon NRC approval. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/03. KNIGHTON, G.W. Licensing Branch 3. 7pp. 32921-172-32921-178.

256 DOCKETED ITEMS

8510180055 Requests exemption from requirements of Section III.D.2.b(ii) of 10CFR50, App J re testing of air locks for periods when containment integrity not required by Tech Specs.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/07. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33059:283-33059:284.

8510160036 Responds to A Han 850925 concerns re reactor cavity water seals. Seals modified by adding 3/16-inch diameter reinforcing pins in top flange. Seals not installed or located in Unit 1 containment. Seals interchangeable.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/10. MARTIN, J.B. Region 5, Office of Director. 2pp. 33024:162-33024:163.

8510180058 Advises that rev to Section 17.2.15 of FSAR re QA program description meets App B 10CFR50 requirements.
KIRSCH, D.F. Region 5, Office of Director. 85/10/10. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 1p. 33028:097-33028:097.

8510160113 Forwards Rev 1 to "Offsite Dose Calculation Manual." Changes to manual will be included in Unit 1 semiannual radioactive effluent release & waste disposal report.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/11. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33020:001-33020:082.

-8510160118 Rev 1 to "Offsite Dose Calculation Manual."
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. 7pp. 33020:003-33020:082.

8510180049 Provides schedules for final implementation of ATWS rule requirements, per Generic Ltr 85-06. Specific info required by Paragraph (C)(6) of rule will be submitted when preliminary design completed & approved.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 2pp. 33028:123-33028:124.

8510170107 Responds to request & commitments made during 851008 meeting & in 850916 ltr re auxiliary pressurizer spray sys. Implementation of listed enhancements scheduled for first refueling outage for Unit 1. Concurrence requested by 851022.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/15. KNIGHTON, G.W. Office of Nuclear Reactor Regulation, Director. 53pp. 33038:047-33038:099.

8510220135 Requests authorization to use ASME Code N-403, permitting reassembly of component & piping supports from completed supports not in operating svc. Required documentation available.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Office of Nuclear Reactor Regulation, Director. 1p. 33082:100-33082:100.

8510220325 Forwards, for review, change to FSAR Chapter 14, deleting position of shift test director & changing responsibilities of test program director. Safety review & evaluation complete for Unit 1.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 7pp. 33066:267-33066:273.

8510300041 Confirms 851021 telcon w/WW Quinn re proposed enhancements to chemical & vol control sys. Review of events on 850912, 1003 & 07 still in progress. Assessment of adequacy of proposed mods pending re.
KNIGHTON, G.W. Licensing Branch 3. 85/10/21. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33261:360-33261:361.

8510310537 Requests detailed explanation of how structural analysis performed on spray pond piping sys & why results of analysis demonstrate that structural integrity of sys will be maintained.
KNIGHTON, G.W. Licensing Branch 3. 85/10/24. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33277:037-33277:038.

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8510020003 Provides description of program to review proposed changes to plant & potential impact on Chapter 15 analyses, per SSER 8 (NUREG-0857).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32824:229-32824:230.

F. Security, medical, emergency & fire protection plans

8510180335 Rev 6 to emergency plan W/851008 ltr.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/08/31. MARTIN, J.B. Region 5, Office of Director. 700pp. 33057:011-33058:050.

8510010323 Forwards Amend 8 to security plan. Amend issued in preparation for issuance of Unit 2 OLA. Amend withheld (ref 10CFR73.21 & 2.790(d)).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/20. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32802:360-32802:361.

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V o/c Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP report provided. Performance analyses required by 851010.
KIRSCH, D.F. Region 5, Office of Director. 85/09/24. CREWS, J., ZIMMERMAN, R., HERNANDEZ, G. Region 5, Office of Director. 15pp. 32826:319-32826:333.

8510250181 Forwards public version of revised emergency plan implementing procedures, including Rev 4 to EPIP-02 re emergency classification & Rev 9 to EPIP-03 re notification of unusual event implementing actions W/851010 release memo.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. MARTIN, J.B. Region 5, Office of Director. 4pp. 33197:139-33198:161.

-8510250188 Public version of revised emergency plan implementing procedures, including Rev 4 to EPIP-02 re emergency classification & Rev 9 to EPIP-03 re notification of unusual event implementing actions.
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/27. 325pp. 33197:143-33198:161.

8510220183 Discusses end evaluation of NRC public affairs activities at 1985 emergency preparedness exercise. Fifteen questions raised. Self-evaluation effective.
COOK, G.N. Region 5, Office of Director. 85/10/18. WEINSTEIN, E. Incident Response Branch. 4pp. 33090:083-33090:086.

K. Utility Final Safety Analysis Report (FSAR) & amends

8510220146 Forwards revised page to FSAR Section 17.2.9 re QA during operations phase. Chemical analysis deleted as special process & cleaning changed to chemical cleaning.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. MARTIN, J.B. Region 5, Office of Director. 4pp. 33082:252-33082:255.

Q. Inspection reports, IE Bulletins & correspondence

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V o/c Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP report provided. Performance analyses required by 851010.
KIRSCH, D.F. Region 5, Office of Director. 85/09/24. CREWS, J., CHAFFEE, A., MILLER, L. Region 5, Office of Director. 15pp. 32826:319-32826:333.

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Plant Operations & Security Personnel." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:265.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by util. Penalty proposed for breakdown of QA program.
KAMMERER, C. Office of Congressional Affairs. 84/04/04. OTTINGER, R.L. House of Rep. Energy & Commerce. GOLDWATER Senate. STUMP House of Rep. 3pp. 33108:344-33108:346.

8510150388 Forwards supporting preliminary data & summaries for SALP, par 850924 memo. Review & comments requested.
KIRSCH, D.F. Region 5, Office of Director. 85/10/08. CREWS, J., CHAFFEE, A., MILLER, L. Region 5, Office of Director. 25pp. 33006:327-33006:351.

8510280139 Forwards Insp Repts 50-528/85-28, 50-529/85-28 & 50-530/85-22 on 850807-0922. No violations or deviations noted.
KIRSCH, D.F. Region 5, Office of Director. 85/10/09. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33194:197-33194:213.

-8510280145 Insp Repts 50-528/85-28, 50-529/85-28 & 50-530/85-22 on 850807-0922. No violation or deviation noted. Major areas inspected: instrument components, safety-related structures & closure of Allegation RV-85-A-033.
HERNANDEZ, G.H., BALL, J.R., MILLER, L.F. Region 5, Office of Director. 85/10/08. 15pp. 33194:199-33194:213.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Fanasonic 800 Series TLDs." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

R. Periodic operating reports & related correspondence

8510240083 Forwards preoperational radiological monitoring program report for 1979-1984, previously discussed w/WW Meinks W/o encl.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33156:256-33156:258.

8510240083 Forwards preoperational radiological monitoring program report for 1979-1984, previously discussed w/WW Meinks.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/17. KNIGHTON, G.W. Licensing Branch 3. 1p. 33274:083-33274:382.

-8510310163 "Preoperational Radiological Monitoring Program Report for 1984."
* Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 84/12/31. 400pp. 33275:064-33275:014.

S. Reportable occurrences, LERs & related correspondence

8510010613 Deficiency Report DER 85-26 re containment purge sys initially reported on 850818. Item not reportable under 10CFR50.55(e).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/11. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32830:018-32830:019.

8510010472 Part 21 & final Deficiency Report DER 85-24 re broken diesel generator turbocharger bolts supplied by Cooper Energy Svcs. Existing bolts will be replaced w/ longer ASTM A-193, Grade B7 full threaded studs & A-194, Grade 2H nuts.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/13. KIRSCH, D.F. Region 5, Office of Director. 7pp. 32809:175-32809:181.

8510010593 Interim Deficiency Rept DER 85-28 re C-E instrument rack flexible conduit installation. Initially reported on 850821. Bechtel evaluation incomplete. Next rept will be submitted by 851011.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 3pp. 32820:345-32820:347.

8510010602 Part 21 & final Deficiency Rept DER 85-27 re slippage in Pacific Scientific pipe clamps. Initially reported on 850820. Torque value increased &/or replacement bolts & nuts installed.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 4pp. 32820:356-32820:359.

8510090419 Interim Potentially Reportable Deficiency Rept DER 85-25 re auxiliary feed-water pump turbine quick start failure. Initially reported on 850806. Final rept delayed until 851017 due to extensive investigation.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/23. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32946:034-32946:035.

8510220474 Final Part 21 & Deficiency Rept DER 85-20 re Cooper Energy Svcs broken diesel generator rocker arm. Initially reported on 850528. Rocker arm replaced. Tappet clearances will be adjusted at 18-month intervals.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/09/30. KIRSCH, D.F. Region 5, Office of Director. 6pp. 32993:047-32993:054.

8510220452 Deficiency Rept DER 85-28 re C-E instrument rack conduit installation. Initially reported on 850821. Final rept delayed until 851101 due to extent of investigation & evaluation.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/08. KIRSCH, D.F. Region 5, Office of Director. 2pp. 32996:222-32996:223.

8510310254 Interim Potentially Reportable Deficiency Rept DER 85-32 re seismic separation between bldgs. Initially reported on 850917. Due to extensive investigation, final rept delayed until 851101.

VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 85/10/15. KIRSCH, D.F. Region 5, Office of Director. 3pp. 33292:062-33292:064.

U. Congressional/Executive Correspondence

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.

FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33108:268.

-8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & extensive corrective action by util. Penalty proposed for breakdown of QA program.

KAMMERER, C. Office of Congressional Affairs. 84/04/04. OTTINGER, R.L. House of Rep. Energy & Commerce. MARKEY House of Rep. DE CONCINI Senate. 3pp. 33108:344-33108:346.

V. Operator Examinations

8510020337 Advises that regional SALP Review Board meeting scheduled on 851106 at Region V ofc. Assessment will cover Apr 1984 - Sept 1985. Anticipated outline of SALP report provided. Performance analyses required by 851010.

KIRSCH, D. Region 5, Office of Director. 85/09/24. CREWS, J., FIORELLI, G., BOSTED, C. Region 5, Office of Director. 15pp. 32826:319-32826:333.

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.

THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8510080202 Notifies that util rescinding ASME QA program. Certificate of Authorization N-2456 & Code N symbol stamp returned to ASME.

SHIELDS, S.W. Public Service Co. of Indiana, Inc. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32913:347-32913:347.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.

ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant." Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

G. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:241.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets. Insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.

SCHREIBER, H. Louis-Alles Co. 85/09/30. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851:100-32851:107.

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc list encl.

THOMPSON, H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882:049-32882:075.

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8510080202 Notifies that util rescinding ASME QA program. Certificate of Authorization N-2456 & Code N symbol stamp returned to ASME.

SHIELDS, S.W. Public Service Co. of Indiana, Inc. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32913:347-32913:347.

8510300112 Forwards repts re background & acceptance criteria for Generic Ltr 83-28, Items 1.1 & 1.2 on post-trip review. Response required for resolution of SER Open Item 5.

ADENSAM, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 1p. 33262:231-33262:231.

-8507160711 "Review of Licensee & Applicant Responses to NRC Generic Ltr 83-28 (Required Actions Based on Generic Implications of Salem ATWS Events). Item 1.1, 'Post-Trip Review Program Description & Procedure' for Bellefonte Nuclear Plant." Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. SAIC-85/1564. 85/07/10. NRC - No Detailed Affiliation Given. 12pp. 33262:232-33262:255.

G. Inspection reports, IE Bulletins & correspondence

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869:001-32869:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:241.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Seismically Qualified." Svc list encl.

JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

S. Reportable occurrences, LERs & related correspondence

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets. Insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.

SCHREIBER, H. Louis-Alles Co. 85/09/30. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 8pp. 32851:100-32851:107.

258 DOCKETED ITEMS

V. Operator Examinations

8509240248 Generic Ltr 85-18 to all power licensees re "Operator Licensing Exams." Svc ltr encl.
THOMPSON,H.L. Division of Licensing. 85/09/27. Consolidated Edison Co. of New York, Inc. 27pp. 32882-049-32882-075.

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8510300038 Forwards proposed cancellation plans for plants officially canceled on 840829 Requests withdrawal of CPPR-150, CPPR-152, CPPR-172 & CPPR-173. W/two oversize drawings.
HUFHAM,J.W. Tennessee Valley Authority. 85/10/24. THOMPSON,H.L. Division of Licensing. 16pp. 33250-052-33250-069.

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8510300038 Forwards proposed cancellation plans for plants officially canceled on 840829 Requests withdrawal of CPPR-150, CPPR-152, CPPR-172 & CPPR-173. W/two oversize drawings.
HUFHAM,J.W. Tennessee Valley Authority. 85/10/24. THOMPSON,H.L. Division of Licensing. 16pp. 33250-052-33250-069.

DOCKET 50-601 RESAR SP/90

A. Application/construction stage documents & correspondence

8510070337 Forwards questions resulting from review of Westinghouse Advanced PWR, RESAR-SP/90, Module 11.
THOMAS,C.D. Standardization & Special Projects Branch. 85/10/02. RAHE,E.P. Westinghouse Electric Corp. 7pp. 32901-237-32901-243.

DOCKET 50-602 UNIV. OF TEXAS RESEARCH REACTOR

A. Application/construction stage documents & correspondence

8510180155 Forwards revised Tech Specs for license submittal. Revs include changes in form per NRC request.
BAUER,T.L., KLEIN,D.E., FONKEN,G.J. Texas, Univ. of, Austin, TX. 85/10/09. DENTON,H. Standardization & Special Projects Branch. 1p. 33020-083-33020-134.

-8510180156 Revised Tech Specs for facility.
* Texas, Univ. of, Austin, TX. 85/09/30. 55pp. 33020-084-33020-138.

F. Security, medical, emergency & fire protection plans

8510150286 Forwards revised security plan, per 850313 & 29 telcons. Plan withheld (ref 10CFR73.21 & 2.790).
BAUER,T.L., KLEIN,D.E., FONKEN,G.J. Texas, Univ. of, Austin, TX. 85/08/14. THOMAS,C. Standardization & Special Projects Branch. 1p. 33026-230-33026-230.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA

8510220187 Partial response to FOIA request for records re AEC Sept 1967 investigation of worker exposures to enriched U during 1966 & 1967 at Atomics Intl. Forwards App A documents. Portions withheld (ref FOIA Exemption 6).
FELTON,J.M. Division of Rules and Records. 85/10/15. JALON,A. Los Angeles Times Los Angeles, CA. 3pp. 33097-205-33097-299.

-8510220175 Forwards compliance investigation rept re exposures to airborne U compounds at Atomics Intl. Investigation disclosed that procedures not followed & matters noted during meeting w/mgt as possible violations.
COOLEY,W.J. Atomic Energy Commission. 87/11/06. ROEDER,J.R. Atomic Energy Commission. 2pp. 33097-206-33097-209.

-8510220188 Compliance investigation rept on 870928-29. Noncompliance noted: exposure of individuals to concentrations of radioactive matl in restricted areas & failure to rept overexposure & excessive levels & concentrations.
COOLEY,W.J., METZGER,J.R., BOOK,H.E. Atomic Energy Commission. 87/11/06. 35pp. 33097-210-33097-245.

-8510220198 Submits rept of inhalation exposures at Atomics Intl. Japan Atomic Energy Research Inst. Air sample, inhalation exposure & internal dosimetric data for workers encl. Portions deleted.
SAXE,D. Rockwell International Corp. 87/11/13. LOW,L.D. Atomic Energy Commission. 10pp. 33097-246-33097-255.

-8510220210 Insp rept on 860402-03. No noncompliance noted. Areas inspected nuclear safety & correction of U airborne concentration problem info deleted.
COOLEY,W.J., BOOK,H.E. Atomic Energy Commission. 86/04/30. 16pp. 33097-256-33097-271.

-8510220223 Forwards notes of 860404 reinsp of License SNM-21. No noncompliance noted. Insp included tour w/emphasis on potential health & safety problems which might arise during Pu wet chemistry operations. Info deleted.
METZGER,J.R. Atomic Energy Commission. 86/04/15. COOLEY,W.J. Atomic Energy Commission. 1p. 33097-272-33097-272.

-8510220245 Insp rept of reinsp on 860404. No noncompliance noted. Major areas inspected: whole body counting of employees involved in incident, new U powder production facility & problems w/ analytical chemistry operation at Santa Susana Pu facility.
METZGER,J.R., COOLEY,W.L., BOOK,H.E. Atomic Energy Commission. 86/04/30. 27pp. 33097-273-33097-288.

-8510220257 Forwards compliance inquiry memo re Atomics Intl accident w/ARC-melt furnace. Design changes which could enhance safety include installation of water alarm sys at base of furnace. W/o memo info deleted.
* Atomic Energy Commission. 86/05/15. ROEDER,J.R. Atomic Energy Commission. 1p. 33097-289-33097-290.

-8510220272 Discusses Atomics Intl accident: w/advanced test reactor ARC-melt furnace. Info deleted.
* Atomic Energy Commission. 86/05/15. ROEDER,J.R. Atomic Energy Commission. 10pp. 33097-291-33097-299.

8510240325 Submits items of interest. On 851007-08, meetings held w/LLL re review of model study to evaluate protection against damage in severe accidents afforded by NRC performance criteria. On 851008, Comm Ed issued License SNM-1938.
CROW,W.T. Uranium Fuel Licensing Branch. 85/10/10. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 33182-272-33182-273.

DOCKET 70-0027 BABCOCK & WILCOX CO., LYNCHBURG, VA

8510030048 Responds to NRC 850701 ltr re violations noted in Insp Rept "D-0027/85-13. Corrective actions approval memo issued emphasizing need for licensing review of all new/or changed operations regardless of nuclear safety impact.
TETRAULT,R.E. Babcock & Wilcox Co. 85/07/29. GRACE,J.N. Region 2, Office of Director. 3pp. 32845-082-32845-084.

8510150122 Grants 1-wk delay to allow start of Jul-Aug 1985 physical inventory by 850906 per 850731 request. Condition re delay added to Amend MPP-1 to License SNM-42.
BROWN,W.B. Material Licensing & International Activities Branch. 85/09/03. REGAN,N.A. Babcock & Wilcox Co. 1p. 33031-090-33031-090.

8510150108 Responds to 850708 ltr transmitting revised Chapter 6 to fundamental nuclear control plan. License SNM-42 amended by revising Condition 2.1 & adding new Condition 5.5 on physical inventory schedules & Condition 5.6.
BROWN,W.B. Material Licensing & International Activities Branch. 85/09/06. REGAN,N.A. Babcock & Wilcox Co. 2pp. 33030-241-33030-242.

8510030006 Provides addl info to 850729 response to violation noted in Insp Rept 70-0027/85-13. Need for licensing review of all new or changed operations regardless of nuclear safety impact emphasized. Nuclear safety signs revised, posted & reviewed.
TETRAULT,R.E. Babcock & Wilcox Co. 85/09/11. GRACE,J.N. Region 2, Office of Director. 2pp. 32843-071-32843-072.

8510110093 Forwards 850628 officers certificates to company lenders, ensuring B&W ability to cover decommissioning costs for all plants, per GC Ziph 780313 ltr.
JORDAN,L.V. Babcock & Wilcox Co. 85/09/16. CROW,W.T. Uranium Fuel Licensing Branch. 5pp. 33011-319-33011-338.

8510150178 Accepts, w/one exception, page changes to physical protection plan submitted per 10CFR70.34 by 850705 ltr Paragraph 21.2.1 on Page 21.4 must be expanded to include measures taken when seal found broken.
BROWN,W.B. Material Licensing & International Activities Branch. 85/09/20. REGAN,N.A. Babcock & Wilcox Co. 1p. 33031-096-33031-099.

8510040126 Ack receipt of 850729 & 0911 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 70-0027/85-13.
STOHR,J.P. Region 2, Office of Director. 85/09/25. TETRAULT,R.E. Babcock & Wilcox Co. 1p. 32867-120-32867-120.

8510150496 Responds to 850710 ltr transmitting revised Chapters 4 & 9 to fundamental nuclear matl control plan & 850905 ltr License SNM-42 amended to delete existing Condition 4.9 & add new Condition 4.9 as shown in encl.
BROWN,W.B. Material Licensing & International Activities Branch. 85/10/04. REGAN,N.A. Babcock & Wilcox Co. 2pp. 33033-132-33033-133.

8510180053 Forwards Insp Rept 70-0027/85-19 on 850904-10 & notice of violation.
STOHR,J.P. Region 2, Office of Director. 85/10/04. TETRAULT,R.E. Babcock & Wilcox Co. 2pp. 33068-331-33068-334.

-8510180054 Notice of violation from Insp on 850904-10.
* Region 2, Office of Director. 85/10/04. 1p. 33068-333-33068-333.

-8510180058 Insp Rept 70-0027/85-19 on 850904-10. Violations noted: failure to follow CFR re maint of ref stds & failure to follow nuclear matl control & accounting procedures. Details withheld (ref 10CFR2.790 & 73.21).
TODO,G.A., NINH,S.Q., BATES,J.W. Region 2, Office of Director. 85/10/03. 1p. 33068-334-33068-334.

8510180454 Ack receipt of 850904 ltr informing NRC of steps taken to correct violations noted in Insp Rept 70-0027/85-14. Response to Violation 2 meets requirements of 10CFR2.201. Requests written statement for Violation 1.
STOHR,J.P. Region 2, Office of Director. 85/10/04. TETRAULT,R.E. Babcock & Wilcox Co. 2pp. 33068-056-33068-057.

8510150361 Advises that 850717 rev to physical security plan consistent w/provisions of 10CFR70.32(e) & acceptable.
STOHR,J.P. Region 2, Office of Director. 85/10/08. TETRAULT,R.E. Babcock & Wilcox Co. 1p. 33010-068-33010-068.

DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT

8510150154 Grants 850819 request for extension of time until 860131 to submit fundamental matl control plan. Listed unnumbered license condition added to Amend MPP-3 to License SNM-33.
BROWN,W.B. Material Licensing & International Activities Branch. 85/08/26. ESKRIDGE,H. Combustion Engineering, Inc. 1p. 33031-108-33031-108.

8510150084 Forwards revised chapter of fundamental nuclear matl control plan,completing revs needed to eliminate need for independent measurements for UF6 receipts.W/o encl.
ESKRIDGE,H.E. Combustion Engineering, Inc. 85/09/23. BROWN,W.B. Material Licensing & International Activities Branch. 1p. 33030-274-33030-274.

8510220278 Forwards Safeguards Insp Rept 70-0036/85-02 on 850729 & 0830 & notice of violation,insp rept & notice of violation withheld (ref 10CFR2.790(d)).
HIND,J.A. Region 3, Office of Director. 85/10/18. LICHTENBERGER Combustion Engineering, Inc. 2pp. 33087-291-33087-292.

DOCKET 70-0123 PENNSYLVANIA, UNIV. OF, PHILADELPHIA, PA

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101.Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230198 Forwards Press Release 1-84-89 re NRC proposed fine against util for six alleged violations,including overexposure of employee to I-125,failure to maintain control of matl & failure to perform thyroid bioassays.
KAMMERER,C. Office of Congressional Affairs. 84/06/25. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-013-33109-015.

DOCKET 70-0134 WISCONSIN, UNIV. OF, MADISON, WI

8510290401 Forwards matl balance repts & physical inventory listings for Types E2,E3,E4,50 & 81 for period ending on 850930.
CASHWELL,R.J. Wisconsin, Univ. of, Madison, WI. 85/10/21. Record Services Branch (Document Control Desk). 11pp. 33242-349-33242-359.

DOCKET 70-0135 BABCOCK & WILCOX CO., APOLLO, PA

8510090132 FOIA request for all repts of radioactive effluents discharged to unrestricted areas resulting from work performed under Licenses SMB-502,SNM-414,SNM-145 & 37-04456-03.
VIROSTEC,C. Kiski Valley Coalition to Save Our Children. 85/07/29. CROW,W.T. Uranium Fuel Licensing Branch. 1p. 32963-145-32963-145.

8510090143 Responds to FOIA requests for all effluent release repts for Licenses SMB-502,SNM-145,SNM-414 & 37-04456-03.Also responds to Category 6 of related FOIA Request 85-552.Forwards requested documents.Add effluent info available in PDR.
FELTON,J.M. Division of Rules and Records. 85/09/04. VIROSTEC,C. Kiski Valley Coalition to Save Our Children. 1p. 32963-145-32963-196.

-8510090155 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1977.W/770829 tr.
WILLIAMS,R.A. Babcock & Wilcox Co. 77/06/30. 3pp. 32963-147-32963-152.

-8510090169 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1977.W/780224 tr.
WILLIAMS,R.A. Babcock & Wilcox Co. 77/12/31. 3pp. 32963-153-32963-155.

-8510090178 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1978.W/780829 tr.
WILLIAMS,R.A. Babcock & Wilcox Co. 78/06/30. 3pp. 32963-156-32963-158.

-8510090186 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1978.W/790223 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 78/12/31. 3pp. 32963-159-32963-173.

-8510090197 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1981.W/810817 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 81/06/30. GRIER,B.H. Region 1, Philadelphia, Office of the Director (81/03/01). 3pp. 32963-174-32963-179.

-8510090205 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1982.W/820722 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 82/06/30. HAYNES,R.C. Region 1, Office of Director. 3pp. 32963-180-32963-182.

-8510090217 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1983.W/830126 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 82/12/31. HAYNES,R.C. Region 1, Office of Director. 3pp. 32963-183-32963-186.

-8510090225 Corrected 830725 rept of radioactive effluents discharged to unrestricted areas for Jan-June 1983.W/830727 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 83/06/30. MURLEY,T.E. Region 1, Office of Director. 2pp. 32963-187-32963-188.

-8510090277 Rept on radioactive effluents discharged to unrestricted areas for Jul-Dec 1983.W/840203 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 83/12/31. MURLEY,T.E. Region 1, Office of Director. 2pp. 32963-189-32963-190.

-8510090280 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1984.W/840814 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 84/06/30. MURLEY,T.E. Region 1, Office of Director. 2pp. 32963-191-32963-194.

-8510090282 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1985.W/850815 tr.
AUSTIN,M.A. Babcock & Wilcox Co. 85/06/30. MURLEY,T.E. Region 1, Office of Director. 2pp. 32963-195-32963-196.

8510110093 Forwards 850628 officers certificates to company lenders, assuring B&W ability to cover decommissioning costs for all plants,per GC Zaph 780313 tr.
JORDAN,L.V. Babcock & Wilcox Co. 85/09/16. CROW,W.T. Uranium Fuel Licensing Branch. 5pp. 33011-319-33011-336.

8510080071 Responds to C Virostek request for assistance to stop nuclear business in Kiskiminetas River Valley info provided to C Virostek & others explaining NRC role & answering questions re B&W.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/09/26. EDGAR,R.W. House of Rep. 2pp. 32926-179-32926-191.

-8508120712 Responds to 850613 tr forwarding V Trozzi 850613 tr re operations of nuclear fuel processing & fabrication facility in Apollo,PA.NRC EIS re 1978 renewal action,1975 environ rept & negative declaration encl.W/o encl.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/08/06. SPECTER,A. Senate. 9pp. 32926-181-32926-189.

-8510080077 Forwards C Virostek 850610 request for assistance in preventing B&W from starting radioactive incineration operation & related news article.
EDGAR,R.W. House of Rep. 85/06/27. KAMMERER,C. Office of Congressional Affairs. 4pp. 32926-190-32926-191.

8510080320 Responds to 850905 constituent tr re B&W plants.Latest EIA prepared for plants available in LPDR in Apollo,PA Response to 850729 FOIA request encl.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/09/27. EDGAR,R.W. House of Rep. 3pp. 32923-122-32923-124.

8510070568 Informs that yr of last EIS of fuel fabrication facilities at Apollo,PA was did 1978,in response to request.
CROW,W.T. Uranium Fuel Licensing Branch. 85/10/02. VIROSTEC,C. Affiliation Not Assigned. 2pp. 32900-356-32900-357.

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101.Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-088.

-8510230114 Forwards Press Release 85-63 re NRC proposed fine against Nuclear Fuel Svcs,Inc for alleged noncompliance w/requirements concerning release of radioactive matl to work area.
KAMMERER,C. Office of Congressional Affairs. 85/05/03. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-056-33109-057.

-8510230228 Forwards Press Release 85-95 re NRC proposed imposition of civil penalty in amount of \$100,000 against licensee for failure to identify & correct degradations of matl access area boundary.
KAMMERER,C. Office of Congressional Affairs. 84/07/31. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-098-33109-099.

8510250041 "Groundwater Monitoring Results,Second Quarter 1985," for Well 14.W/ 851001 tr.
GUINN,F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/06/30. 3pp. 33223-356-33223-358.

8510150128 Forwards revised conditions,effective w/start of Aug 1985 inventory,placing same inventory difference limits on plant as applied to industry,per 830511 order re joint motion to suspend proceeding.
BURNETT,R.F. Division of Safeguards. 85/08/29. TAYLOR,C.W. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 3pp. 33031-087-33031-089.

8510110064 Forwards monthly status rept re investigation findings & corrective action plan relative to accumulation of U-bearing solids in high enriched U process ventilation sys.Rept withheld (ref 10CFR2.790).
GUINN,F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/09/03. GRACE,J.N. Region 2, Office of Director. 2pp. 33011-299-33011-300.

8510160375 Advises that new License Condition 2.1.2 to Safeguards Amend SG-1 to License SNM-124 issued,in response to 850823 request for exemption from 10CFR74.31(b)(1) re fundamental nuclear matl control plan.
BROWN,W.B. Material Licensing & International Activities Branch. 85/09/06. HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1pp. 33034-288-33034-288.

8510150064 Grants 850823 request for exemptions involving vendor Aug 1985 highly enriched U physical inventory due to limited activity.Unnumbered license conditions to Amend SG-1 to License SNM-124 applicable to inventory encl.
BROWN,W.B. Material Licensing & International Activities Branch. 85/09/09. HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 33030-356-33030-357.

8510150032 Forwards add info re 850325 application for amend to License SNM-124,permitting installation of sprinkler sys in highly enriched U scrap recovery facility,per NRC 850501 request.
MAXIN,A.M. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/09/19. CROW,W.T. Uranium Fuel Licensing Branch. 7pp. 33032-012-33032-018.

8510070570 Submits list of documents withdrawn,per 850716,22 & 0906 ltrs & 10CFR2.790(c).
SCOGAN,A.L. Uranium Fuel Licensing Branch. 85/09/20. CLARK,J.R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 32900-355-32900-355.

8510240169 Forwards revs to fundamental nuclear matl control plan Section 4.0,per requirements of 10CFR70.32(c).Rev withheld (ref 10CFR2.790(d)).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/09/20. GRACE,J.N. Region 2, Office of Director. 1p. 33176-354-33176-354.

8510150033 Application for amend to License SNM-124,changing Condition 80 to allow continued operation of high enriched calsonic offgas treatment sys for add 60 days.Fee paid.
GUINN,F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/09/25. CROW,W.T. Uranium Fuel Licensing Branch. 2pp. 33032-009-33032-011.

260 DOCKETED ITEMS

8510010433 Forwards draft revised 850221 order modifying license conditions re accumulation of U-235 in 200 complex sys per NFS 850422 suggested mods, for approval. Hearing on original order may be requested.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/09/27. NEWMAN, N.J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 8pp. 32833-149-32833-156.

8510040431 Issues Amend 35 to License SNM-124, terminating operation of calciner & conversion furnace by 850928. Operations may restart when cyclone separator installed in exhaust ventilation sys.
CROW, W.T. Uranium Fuel Licensing Branch. 85/09/27. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 32859-332-32859-333.

-8510040436 Recommends approval of issuance of Amend 35 to License SNM-124 re termination of operation of calciner & conversion furnace by 850928.
SOONG, A.L., CROW, W.T. Uranium Fuel Licensing Branch. 85/09/27. Uranium Fuel Licensing Branch. 1p. 32859-333-32859-333.

8510180531 Forwards summary of 850807 meeting in Region II re activities authorized by License SNM-124. Summary documents oral commitments made by util.
STOHR, J.P. Region 2, Office of Director. 85/09/30. GUINN, J.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 33068-010-33068-016.

-8510180533 Summary of 850807 meeting w/util in Atlanta, GA re activities authorized by License SNM-124.
HOSEY, C.M. Region 2, Office of Director. 85/09/30. Region 2, Office of Director. 6pp. 33068-011-33068-016.

8510180065 Forwards Insp Rept 70-0143/85-35 on 850916-20. No noncompliance noted.
BARR, K.P. Region 2, Office of Director. 85/10/03. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 33068-313-33068-315.

-8510180071 Matl Control & Accountability Insp Rept 70-0143/85-35 on 850916-20. No violations or deviations noted. Major areas inspected: measurement control & statistics. Details withheld (ref 10CFR2.790 & 73.21).
JONES, D.W., MCALPINE, E.J. Region 2, Office of Director. 85/10/02. 1p. 33068-315-33068-315.

8510240132 Responds to NRC 850920 ltr re Oil, Chemical & Atomic Workers Intl Union concerns about plant operations. Concerns being evaluated internally. Rept of final conclusions will be submitted by 851101.
GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 85/10/04. STOHR, J.P. Region 2, Office of Director. 2pp. 33176-351-33176-351.

8510150331 Forwards Insp Rept 70-0143/85-30 on 850909-13. No violation or deviation noted.
BARR, K.P. Region 2, Office of Director. 85/10/08. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 33010-357-33010-359.

-8510150336 Insp Rept 70-0143/85-30 on 850909-13. No violations noted. Major areas inspected: security organization, audit, barriers, lighting, compensatory measures, access controls, alarms & contingency plans. Details withheld.
TOBIN, W., MCGUIRE, D.R. Region 2, Office of Director. 85/10/04. 1p. 33010-359-33010-359.

8510170011 Issues Amend 36 to License SNM-124, permitting installation of manually-operated, closed-head combination water spray/sprinkler sys in Bldg 233. SER encl.
CROW, W.T. Uranium Fuel Licensing Branch. 85/10/08. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 33043-223-33043-226.

-8510170012 SER supporting 850325 application for amend to License SNM-124, permitting installation of sprinkler sys in solvent extraction area.
BIDINGER, G.H. Uranium Fuel Licensing Branch. 85/10/08. 2pp. 33043-224-33043-225.

-8510170014 Informs of exclusion for 850325 application for amend to License SNM-124. Neither environ assessment nor EIS warranted for proposed action.
CROW, W.T. Uranium Fuel Licensing Branch. 85/10/08. Uranium Fuel Licensing Branch. 1p. 33043-226-33043-226.

8510110259 Ack receipt of 850903 ltr to Chairman Palladino presenting allegations re NFS operation & safety practices. Ltr forwarded for treatment as request for action under 10CFR2.206. Copy of FR notice encl.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/09. WAGES, R.W. Oil, Chemical & Atomic Workers International Union. 3pp. 32974-349-32974-352.

-8510110260 Notice of receipt of request for action under 10CFR2.206 to address allegations re operating & safety practices at NFS Erwin facility.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/09. 1p. 32974-352-32974-352.

8510180072 Forwards Insp Rept 70-0143/85-33 on 850923-26. No violations or deviations noted.
BARR, K.P. Region 2, Office of Director. 85/10/09. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 33054-001-33054-003.

-8510180078 Insp Rept 70-0143/85-33 on 850923-26. No violations or deviations noted. Major areas inspected: measurements & followup on previous insp findings. Details withheld (ref 10CFR2.790 & 73.21).
BATES, J.W., NINH, S.G., MCALPINE, E.J. Region 2, Office of Director. 85/10/09. 1p. 33054-003-33054-003.

8510150358 Requests order terminating NRDC proceeding involving NFS-Erwin, since requirements in Paragraph 5 of 830406 agreement of settlement entitled, "Joint Motion to Suspend Proceeding," met. Certificate of svc encl.
DICKS, W.J. Office of the Executive Director for Operations. #485 784. 85/10/10. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 8pp. 33010-179-33010-187.

8510220082 Forwards revised order modifying License SNM-124, adding new license conditions in response to violations noted in Insp Rept 70-0143/84-41, per licensee 850422 proposed changes.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/18. GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 33098-236-33098-245.

-8510220111 Revised order modifying License SNM-124, adding new license conditions in response to violations noted in Insp Rept 70-0143/84-41, based on licensee 850422 proposed changes.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/18. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 8pp. 33098-238-33098-245.

8510220104 EN-85-014A on 851018, final agreement reached w/NFS re 850422 proposed changes & clarification of license conditions concerning security/safeguards per revised order modifying License SNM-124.
ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/18. 1p. 33090-149-33090-149.

DOCKET 70-0267 NEW YORK, STATE UNIV. OF, BUFFALO, NY

8510220383 Application for renewal of License SNM-0273, authorizing possession of 9 g U-235 in any chemical or physical form in any enrichment up to 93.48% U-235, for use in R&D programs. Related documentation encl.
ADAMS, A. New York, State Univ. of, Buffalo, NY. 85/09/27. CROW, W.T. Uranium Fuel Licensing Branch. 83pp. 33099-155-33099-248.

DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA

8510090132 FOIA request for all repts of radioactive effluents discharged to unrestricted areas resulting from work performed under Licenses SMB-502, SNM-414, SNM-145 & 37-04456-03.
VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 85/07/29. CROW, W.T. Uranium Fuel Licensing Branch. 1p. 32963-145-32963-145.

8510110120 Forwards revised tables I: 841031 Vol Reduction Svcs Facility environ analysis for review. Changes include corrections to reflect computer error in C-14 pathway dose. Corrections to analysis text will be submitted on 850916.
AUSTIN, M.A. Babcock & Wilcox Co. 85/08/30. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 49pp. 33012-059-33012-108.

8510090143 Responds to FOIA requests for all effluent release repts for Licenses SMB-502, SNM-145, SNM-414 & 37-04456-03. Also responds to Category 6 of related FOIA Request 85-552. Forwards requested documents. Add effluent info available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/04. VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 1p. 32963-146-32963-196.

-8510090155 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1977 W/770829 ltr.
WILLIAMS, R.A. Babcock & Wilcox Co. 77/06/30. 3pp. 32963-147-32963-152.

-8510090169 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1977 W/780224 ltr.
WILLIAMS, R.A. Babcock & Wilcox Co. 77/12/31. 3pp. 32963-153-32963-155.

-8510090178 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1978 W/780829 ltr.
WILLIAMS, R.A. Babcock & Wilcox Co. 78/06/30. 3pp. 32963-156-32963-158.

-8510090186 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1978 W/790223 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 78/12/31. 3pp. 32963-159-32963-173.

-8510090197 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1981 W/810817 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 81/06/30. 3pp. 32963-174-32963-179.

-8510090205 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1982 W/820722 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 82/06/30. 3pp. 32963-180-32963-182.

-8510090217 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1983 W/830126 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 82/12/31. 3pp. 32963-183-32963-186.

-8510090225 Corrected 830725 rept of radioactive effluents discharged to unrestricted areas for Jan-June 1983 W/830727 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 83/06/30. 2pp. 32963-187-32963-188.

-8510090277 Rept on radioactive effluents discharged to unrestricted areas for Jul-Dec 1983 W/840203 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 83/12/31. 2pp. 32963-189-32963-190.

-8510090280 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1984 W/840814 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 84/06/30. 2pp. 32963-191-32963-194.

-8510090282 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1985 W/850815 ltr.
AUSTIN, M.A. Babcock & Wilcox Co. 85/06/30. 2pp. 32963-195-32963-196.

8510110098 Confirms that pertinent matl re application for amend to License SNM-414 on file & available at LPR & PDR to petitioners, per 850808 memorandum & order Matl will be forwarded by 850916.
FISCHER, K.P. Babcock & Wilcox Co. 85/09/05. MORRIS, P.A. Atomic Safety and Licensing Board Panel. 3pp. 33011-339-33011-341.

8510150284 Forwards recent correspondence w/NRC dtd 850830 to expedite process of providing access to matl re application for amend to License SNM-414 w/o encl.
FISCHER, K.P. Babcock & Wilcox Co. 85/09/05. WHITE, J.H. Affiliation Not Assigned. ZAWACKI, D.P. Zawacki, D.P. 2pp. 33033-029-33033-030.

8510110068 Forwards pertinent matl re amend to License SNM-414, including space & demonstration sections of license, applications for amendments & all correspondence concerning application, per 850808 memorandum & order W/o encl.
FISCHER, K.P. Babcock & Wilcox Co. 85/09/05. MORRIS, P.A. Atomic Safety and Licensing Board Panel. 4pp. 33011-296-33011-298.

8510110093 Forwards 850628 officers certificates to company lenders, assuring B&W ability to cover decommissioning costs for all plants, per GC Ziph 780313 ltr. JORDAN, L.V. Babcock & Wilcox Co. 85/09/18. CROW, W.T. Uranium Fuel Licensing Branch. 5pp. 33011:319-33011:338.

8510150034 Forwards revs to vol reduction avcs facility environ analysis. AUSTIN, M.A. Babcock & Wilcox Co. 85/09/18. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 30pp. 33031:340-33032:008.

8510210277 Forwards author 850918 ltr to LC Rouse & encls inadvertently omitted from submittal to NRC. AUSTIN, M.A. Babcock & Wilcox Co. 85/09/20. WHITE, J.H., AU, T.Y. Affiliation Not Assigned. 3pp. 33079:079-33079:081.

8510030015 Advises that NRC will not participate in proceeding re B&W vol reduction facility at Parks Township, PA. Environ assessment & safety evaluation concerning application for amend to License SNM-414 being prepared. JOHNSON, G.E. Hearing Branch 4. #485 659. 85/09/26. MORRIS, P.A. Atomic Safety and Licensing Board Panel. 2pp. 32844:337-32844:338.

8510080071 Responds to C Virostek request for assistance to stop nuclear business in Kiskiminetas River Valley info provided to C Virostek & others explaining NRC role & answering questions re B&W. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/26. EDGAR, R.W. House of Rep. 2pp. 32926:179-32926:191.

-8508120712 Responds to 850613 ltr forwarding V Trozzi 850613 ltr re operations of nuclear fuel processing & fabrication facility in Apollo, PA. NRC EIS re 1978 renewal action, 1975 environ rept & negative declaration encl. W/o encl. DIRCKS, W.J. Office of the Executive Director for Operations. 85/08/06. SPECTER, A. Senate. 9pp. 32926:181-32926:189.

-8510080077 Forwards C Virostek 850610 request for assistance in preventing B&W from starting radioactive incineration operation & related news article. EDGAR, R.W. House of Rep. 85/06/27. KAMMERER, C. Office of Congressional Affairs. 4pp. 32926:190-32926:191.

8510080320 Responds to 850905 constituent ltr re B&W plants. Latest EIA prepared for plants available in LPDR in Apollo, PA. Response to 850729 FOIA request encl. DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/27. EDGAR, R.W. House of Rep. 3pp. 32923:122-32923:124.

8510040269 Notifies that 850924 meeting w/B&W re Parks Township burial site rescheduled for 851009, due to unavailability of participant. LOYSEN, P. Uranium Fuel Licensing Branch. 85/09/30. ROUSE, L.C. Uranium Fuel Licensing Branch. 1p. 32860:113-32860:113.

8510040451 Orders granting JP Bologna & F Johnson petition to participate & denying Commonwealth of PA petition for leave to participate as interested state. Served on 851003. MORRIS, P.A. Atomic Safety and Licensing Board Panel. #485 666. 85/10/03. BOLOGNA, J.P., JOHNSON, F. Affiliation Not Assigned. 12pp. 32854:202-32854:213.

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT

8510150119 Forwards change to security plan, Section 9.1 & summary & explanation of change, per 850619 telcon w/O Smith (ref 10CFR70.32(a)). Fee paid. W/o encls. GIGLIOTTI, R.J. UNC Resources, Inc. 85/07/26. BROWN, W.B. Division of Safeguards. 3pp. 33030:220-33030:223.

-8510150123 Returns check submitted w/85/726 change to site security plan. Changes filed under 10CFR70.32(e) not subj to fee. WEISS, D. License Fee Management Branch. 85/09/23. GIGLIOTTI, R.J. UNC Resources, Inc. 1p. 33030:223-33030:223.

8510150315 Ack receipt & acceptance of changes to physical protection plan, per 850516 ltr. Changes incorporated into Safeguards Amend SG-1 of License Condition 9.1.A to License SNM-368. BROWN, W.B. Material Licensing & International Activities Branch. 85/09/17. GIGLIOTTI, R.J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 1p. 33032:310-33032:310.

8510150340 Informs that no conflict anticipated between SSNM safeguards program & proposed const projects submitted w/850628 ltr. BROWN, W.B. Material Licensing & International Activities Branch. 85/09/19. GIGLIOTTI, R.J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 1p. 33032:234-33032:235.

8510170290 Advises that portions of 850801 Rev 4 to fundamental nuclear matl control plan consistent w/provisions of 10CFR70.32(c) & acceptable. Unacceptable portions noted in encl. Revs requested within 30 days. Encl withheld (ref 10CFR2.790(d)). MARTIN, T.T. Region 1, Office of Director. 85/09/23. AMY, G.O. UNC Resources, Inc. 2pp. 33051:263-33051:264.

8510100205 Forwards Safeguards Insp Rept 70-0371/85-11 on 850722-26. No violations observed. MARTIN, T.T. Region 1, Office of Director. 85/10/03. AMY, G.O. UNC Resources, Inc. 2pp. 32962:069-32962:073.

-8510100211 Matl Control & Accounting Insp Rept 70-0371/85-11 on 850722-26. No noncompliance noted. Major areas inspected: facility organization & mgt controls, operation & internal controls & measurement sys. DELLA RATTIA, A., KEIMIG, R.R. Region 1, Office of Director. 85/09/06. 3pp. 32962:071-32962:073.

8510310210 Forwards Safeguards Insp Rept 70-0371/85-13 on 850903-06. No violation noted. MARTIN, T.T. Region 1, Office of Director. 85/10/24. AMY, G.O. United Nuclear Corp. (subs. of UNC Resources, Inc.). 2pp. 33273:102-33273:106.

-8510310217 Insp Rept 70-0371/85-13 on 850903-06. No noncompliance noted. Major areas inspected: facility operations, internal controls & physical inventory. DELLA RATTIA, A., KEIMIG, R.R. Region 1, Office of Director. 85/10/17. 3pp. 33273:104-33273:106.

DOCKET 70-0687 CINTICHEM, INC.

8510210321 Requests approval of listed route planned for shipment of 24 MTR-type fuel elements from Tuxedo, NY to Savannah River processing facility. State Motor Transit will be carrier. HART, H.C. Cintichem, Inc. 85/7/29. HILLMAN, C. Division of Safeguards. 2pp. 33079:041-33079:043.

-8510210303 Requests fee for approval of spent fuel transportation route requested in 850829 ltr. WEISS, D. License Fee Management Branch. 85/09/17. HART, H.C. Cintichem, Inc. (subs. of Medi-Physics, Inc.). 2pp. 33079:042-33079:043.

8510070019 Approves encl route from Tuxedo, NY to Aiken, SC for transport of spent reactor fuel, per 850629 request. Data re arrangements w/law enforcement agencies along route & diagrams of route encl. MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/09/30. HART, H.C. Cintichem, Inc. 13pp. 32901:056-32901:068.

8510280299 Forwards Safety Insp Repts 50-054/85-04 & 70-0687/85-07 on 850819-23 & notice of violation. MARTIN, T.T. Region 1, Office of Director. 85/10/22. MCGOVERN, J.J. Cintichem, Inc. (subs. of Medi-Physics, Inc.). 2pp. 33192:027-33192:041.

-8510280302 Notice of violation from insp on 850819-23. * NRC - No Detailed Affiliation Given. 85/10/22. 2pp. 33192:029-33192:030.

-8510280305 Insp Repts 50-054/85-04 & 70-0687/85-07 on 850819-23. Violations noted: high radiation areas not posted as required & entry to hazardous areas generated by waste drums not restricted. WEADOCK, A., MCFADDEN, J., SHANBAKY, M. Region 1, Office of Director. 85/10/21. 11pp. 33192:031-33192:041.

8510310424 Ack receipt of 850919 ltr informing NRC of steps taken to correct violations noted in Insp 70-0687/84-05. MARTIN, T.T. Region 1, Office of Director. 85/10/24. MCGOVERN, J.J. Cintichem, Inc. (subs. of Medi-Physics, Inc.). 1p. 33272:274-33272:275.

-8510310426 Responds to NRC 850731 ltr re violations noted in Insp Rept 70-0687/81-05. Corrective actions: documentation expanded to reflect full scope of audit & auditors will not audit responsible work functions. KONNERTH, C.J. Cintichem, Inc. 85/09/19. MARTIN, T.T. Region 1, Office of Director. 1p. 33272:275-33272:275.

DOCKET 70-0694 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8510210269 Forwards "Rept on Leaking Co-60 Source." Review of leak test data determined source leaking & NRC notified on 850904. GALM, D.T. Westinghouse Electric Corp. 85/09/10. MURLEY, T. Region 1, Office of Director. 1p. 33079:321-33079:326.

-8510210271 "Rept on Leaking Co-60 Source." * Westinghouse Electric Corp. 85/09/10. 5pp. 33079:322-33079:326.

DOCKET 70-0734 GA TECHNOLOGIES, INC., SAN DIEGO, CA

8510150350 Advises of intent to remove contaminated soil or vegetation until residuals meet NRC policy (SECY-81-576). Option 1 criteria. Revised plan for releasing certain portions of site to unrestricted use will be sent for NRC review. ASMUSSEN, K.E. GA Technologies, Inc./General Atomic Co. 85/09/10. CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33031:290-33031:292.

8510210273 Forwards revised Attachment 1 to 850830 response to request for add info re reorganization. Audit teams appointed to conduct annual audits of security & nuclear matl accountability & control program. WOLF, R.A. GA Technologies, Inc./General Atomic Co. 85/09/20. CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director. BROWN, W.B. Fuel Facility Safeguards Licensing Branch (Pre 850707). 5pp. 33079:085-33079:088.

8510210253 Forwards plan for obtaining approval to release portions of site for unrestricted use w/two oversize maps encl. ASMUSSEN, K.E. GA Technologies, Inc./General Atomic Co. 85/10/01. CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director. 35pp. 33093:091-33093:125.

8510160020 Forwards Safeguards Insp Rept 70-0734/85-11 on 850923-26. No noncompliance noted. Rept withheld (ref 10CFR2.790(d)). MONTGOMERY, J.L. Region 5, Office of Director. 85/10/10. COLANDREA, T.R. GA Technologies, Inc./General Atomic Co. 1p. 33042:241-33042:241.

8510220356 Forwards Safeguards Insp Rept 70-0734/85-13 on 850916-1002. No noncompliance noted. Major areas inspected: physical protection activities. Rept withheld (ref 10CFR2.790 & 73.21). MONTGOMERY, J.L. Region 5, Office of Director. 85/10/17. COLANDREA, T.R. GA Technologies, Inc./General Atomic Co. 1p. 33089:337-33089:337.

DOCKET 70-0754 GENERAL ELECTRIC CO., PLEASANTON, CA

8510150342 Forwards Insp Rept 70-0754/85-02 on 850904-19. No violations noted. MONTGOMERY, J.L. Region 5, Office of Director. 85/10/08. DARMITZEL, R.W. General Electric Co. 1p. 33000:352-33000:352.

-8510150345 Insp Rept 70-0754/85-02 on 850904-19. No violations noted. Major areas inspected: mgt organization & controls, operator training & retraining, criticality safety & operations review. BROCK, B.L., ZURAKOWSKI, P.R., THOMAS, R.D. Region 5, Office of Director. 85/10/02. 7pp. 33000:353-33000:359.

262 DOCKETED ITEMS

DOCKET 70-0820 UNITED NUCLEAR CORP., WOOD RIVER JUNCTION, RI

8510210240 Forwards "Geohydrologic Data for Low Level Radioactive Contamination Site, Wood River Junction, RI" & two articles re groundwater contamination problem at Wood River Junction plant.
JOHNSTON, H.E. Interior, Dept. of, Geological Survey. 85/09/17. CROW, W.T. NRC. No Detailed Affiliation Given. 30pp. 33093:126-33094:101.

8510210247 "Geohydrologic Data for Low Level Radioactive Contamination Site, Wood River Junction, RI" W/one oversize drawing encl.
RYAN, B.J., DESAULNIERS, R., BRISTOL, D.A. Interior, Dept. of, Geological Survey. 84-725. 85/09/17. 404pp. 33093:156-33094:101.

8510080155 Forwards Safety Insp Rept 70-0820/85-03 on 850822-23. No violation noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/03. AMY, G.O. United Nuclear Corp. (subs. of UNC Resources, Inc.). 2pp. 32922:067-32922:074.

8510080182 Insp Rept 70-0820/85-03 on 850822-23. No violation noted. Major areas inspected: water samples obtained from selected monitoring wells & exam of status of decommissioning site & bldgs.
ROTH, J., KEIMIG, R.R. Region 1, Office of Director. 85/10/02. 6pp. 32950:359-32950:360.

DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

8510180545 Application for renewal of License SNM-778.
OLSEN, A.F. Babcock & Wilcox Co. 85/06/28. Uranium Fuel Licensing Branch. 2pp. 33077:281-33077:282.

8510150030 Application for Amend 10 to License SNM-778, authorizing const & use of ground level waste storage facility due to limited available space in current facility. Fee paid.
OLSEN, A.F. Babcock & Wilcox Co. 85/09/10. Uranium Fuel Licensing Branch. 26pp. 33032:019-33032:044.

8510110093 Forwards 850628 officers certificates to company lenders, assuring B&W ability to cover decommissioning costs for all plants, per GC Ziph 780313 tr.
JORDAN, L.V. Babcock & Wilcox Co. 85/09/16. CROW, W.T. Uranium Fuel Licensing Branch. 5pp. 33011:319-33011:338.

8510220026 Forwards corrected Section A.5.2.6 of 850820 application for Amend 9 to License SNM-778 re position requirements for nuclear safety officer.
OLSEN, A.F. Babcock & Wilcox Co. 85/09/27. Uranium Fuel Licensing Branch. 4pp. 33098:277-33098:280.

8510230256 Informs of issuance of amend to License SNM-778, in response to 850820 & 0927 requests. Amend authorizes reorganization of safety & licensing staff. SER encl.
CROW, W.T. Uranium Fuel Licensing Branch. 85/10/15. OLSEN, A.F. Babcock & Wilcox Co. 1p. 33108:027-33108:030.

8510230257 Reviews 850820 application for amend to License SNM-778, authorizing reorganization of safety & licensing staff.
KETZLACH, N. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/15. Uranium Fuel Licensing Branch. 2pp. 33108:028-33108:029.

8510230258 Grants categorical exclusion for 850820 request for amend to License SNM-778. Neither environ assessment nor EIS warranted.
CROW, W.T. Uranium Fuel Licensing Branch. 85/10/15. Uranium Fuel Licensing Branch. 1p. 33108:030-33108:030.

DOCKET 70-1068 FLORIDA, UNIV. OF, GAINESVILLE, FL

8510150171 Forwards draft "Guide for Preparation of Renewal Applications for SNM Licenses for Univs & R&D Facilities," for info. W/c encl.
KODALL, K.K. Uranium Fuel Licensing Branch. 85/10/07. VERNETSON, W.G. Florida, Univ. of, Gainesville, FL. 1p. 33031:100-33031:100.

DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT

8510240326 Application for amend to License SNM-1067, deleting Pages 1.2-19, Rev 3 & 1.2-20, Rev 2 & adding Pages 1.2-19, Rev 4 & 1.2-20, Rev 3 re monthly criticality auditing of fuel mfg facility. Fee paid.
LICHTENBERGER Combustion Engineering, Inc. 85/09/23. CROWE, W.T. Uranium Fuel Licensing Branch. 5pp. 33160:348-33160:351.

8510070204 Forwards Safety Insp Repts 70-1100/85-03 & 30-03754/85-01 on 850520-24 & notices of violation & deviation. Requests written statement addressing concern re mgt controls to assure that conditions of licenses followed.
MARTIN, T.T. Region 1, Office of Director. 85/09/27. LICHTENBERGER Combustion Engineering, Inc. 2pp. 32883:320-32883:339.

8510070208 Notice of violation from insp on 850520-24.
* Region 1, Office of Director. 85/09/27. 3pp. 32883:322-32883:324.

8510070215 Notice of deviation from insp on 850520-24.
* Region 1, Office of Director. 85/09/27. 1p. 32883:325-32883:325.

8510070224 Insp Repts 70-1100/85-03 & 30-03754/85-01 on 850520-24. Violations or deviations noted: storage of SNM containers in unauthorized locations, failure to follow SNM logging procedures & failure to approve & review QA manual changes.
ROTH, J., KEIMIG, R.R. Region 1, Office of Director. 85/09/06. 14pp. 32883:326-32883:339.

8510220344 PNS-I-85-014: on 851017, licensee notified Region 1 that reconciliation of low enriched U inventory period ending Sept 1985 indicated inventory difference exceeded error limit. Cause unknown. Reconciliation continuing.
SMITH, G., KEIMIG, R. Region 1, Office of Director. 85/10/17. 1p. 33068:149-33068:149.

8510310125 Forwards Safeguards Insp Rept 70-1100/85-06 on 850916-19. No violations noted.
MARTIN, T.T. Region 1, Office of Director. 85/10/24. LICHTENBERGER Combustion Engineering, Inc. 2pp. 33273:244-33273:249.

8510310128 Matl Control & Accounting Insp Rept 70-1100/85-06 on 850916-19. No noncompliance noted. Major areas inspected: physical inventory.
DELLA RATTIA, A., KEIMIG, R.R. Region 1, Office of Director. 85/10/17. 4pp. 33273:246-33273:249.

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NC

8510150227 Grants 850808 request for extension of time until 860131 to submit fundamental nuclear matl control plan. Listed unnumbered license condition added to Amend SG-1 to License SNM-1097.
BROWN, W.B. Material Licensing & International Activities Branch. 85/08/26. VAUGHAN, C.M. General Electric Co. 1p. 33033:291-33033:291.

8510110213 Forwards portions of 40CFR referenced in Attachment 1 to 850701 application for amend to License SNM-1097, authorizing disposal of industrial waste products by burial.
VAUGHAN, C.M. General Electric Co. 85/09/10. CROW, M.T. Uranium Fuel Licensing Branch. 6pp. 33012:023-33012:028.

8510040122 Reaffirms violation noted in Insp Rept 70-1113/85-17 in response to GE 850301 & 0405 ltrs denying Violation 1 re suitability of air sampling in CHEMET Lab. Corrective actions requested within 30 days. Evaluation of denial encl.
GRACE, J.N. Region 2, Office of Director. 85/09/23. LEES, E.A. General Electric Co. 4pp. 32887:121-32887:124.

8510080225 Forwards Insp Rept 70-1113/85-14 on 850812-16. No noncompliance noted. Rept withheld (ref 10CFR2.790(d) & 73.21).
BARR, K.P. Region 2, Office of Director. 85/09/23. LEES, E.A. General Electric Co. 2pp. 32922:139-32922:140.

8510030014 PNC-3-85-092: on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown, Unit 2 shut down & Surry 1 & 2 at full power.
CUNNINGHAM, A. Region 2, Office of Director. 85/09/26. 2pp. 32844:335-32844:336.

8510240390 Rev 12 to 850701 application for amend to License SNM-1097, authorizing disposal by burial of industrial waste products containing no more than 250 pCi/g U activity. Revised Chapter 1 of Part 1 of License SNM-1097 encl.
VAUGHAN, C.M. General Electric Co. 85/10/10. CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director. 28pp. 33182:236-33182:265.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8510150074 Grants 850815 request for extension of time until 860131 to submit fundamental nuclear matl control plan. Listed unnumbered license condition added to Amend SG-2 to License SNM-1107.
BROWN, W.B. Material Licensing & International Activities Branch. 85/08/26. SANDERS, C.F. Westinghouse Electric Corp. 1p. 33030:354-33030:354.

8510150186 Notifies that licensee identified by IAEA under Article 39(b) of US/IAEA safeguards agreement for application of IAEA safeguards. Completion of encl IAEA Design Info Questionnaire Forms N-71 & 73 requested by 851018. W/c encl.
BROWN, W.B. Material Licensing & International Activities Branch. 85/09/03. D'AMORE, M. Westinghouse Electric Corp. 2pp. 33031:094-33031:095.

8510040147 Advises that 850901 rev to fundamental nuclear matl control plan consistent w/10CFR70.32(c) & acceptable.
STOHR, J.P. Region 2, Office of Director. 85/09/30. D'AMORE, M. Westinghouse Electric Corp. 1p. 32851:001-32851:001.

8510250588 Advises that 850901 Rev 5 to physical security plan consistent w/provisions of 10CFR70.32(e) & acceptable.
STOHR, J.P. Region 2, Office of Director. 85/10/11. D'AMORE, M. Westinghouse Electric Corp. 1p. 33189:303-33189:303.

DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA

8510150070 Grants 850806 request for extension of time until 860131 to submit fundamental nuclear matl control plan. Listed unnumbered license condition added to Amend MPP-3 to License SNM-1160.
BROWN, W.B. Material Licensing & International Activities Branch. 85/08/26. WATTERS, J.P. Babcock & Wilcox Co. 1p. 33030:355-33030:355.

8510110093 Forwards 850628 officers certificates to company lenders, assuring B&W ability to cover decommissioning costs for all plants, per GC Ziph 780313 tr.
JORDAN, L.V. Babcock & Wilcox Co. 85/09/16. CROW, W.T. Uranium Fuel Licensing Branch. 5pp. 33011:319-33011:338.

DOCKET 70-1257 EXXON NUCLEAR CO., INC., RICHLAND, WA

8510150130 Grants extension until 860131 for submittal of fundamental nuclear matl control plan, per 850815 request. Condition re extension added to Amend SG-1 to License SNM-1227.
BROWN, W.B. Material Licensing & International Activities Branch. 85/08/26. SCHNEIDER, R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 1p. 33031:086-33031:086.

8510110121 Forwards Rev 13 to "Exxon Nuclear Co. Richland Fuel Fabrication Plant, Emergency & Radiological Contingency Plan, Part I," reflecting Exxon Nuclear Co. current organization & names of other agency emergency plans.
MALODY, C.W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/08/27. Uranium Fuel Licensing Branch. 2pp. 33012:235-33012:236.

8510110127 Rev 13 to "Exxon Nuclear Co. Richland Fuel Fabrication Plant, Emergency & Radiological Contingency Plan, Part I."
PURCELL, R.H. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-32A R13. 85/08/31. 118pp. 33012:237-33012:356.

8510220087 Forwards addl info re application for amend to License SNM-1227, per 850805 request. Unlikely that wet conversion will be totally replaced by dry conversion because of wet process recycle capabilities. Proprietary response withheld. MALODY, C.W. Exon Nuclear Co., Inc. (subs. of Exon Corp.). 85/08/29. CROW, W.T. Uranium Fuel Licensing Branch. 10pp. 33096:221-33096:231.

8510150053 Forwards proprietary fundamental nuclear matl control plan, Rev 16 to XN-12, "Nuclear Matls Safeguards Procedures Description for Fuel Fabrication Plants" & annex. Plan & annex withheld (ref 10CFR2.790(d)). Exon Nuclear Co., Inc. (subs. of Exon Corp.). 85/09/24. BROWN, W.B. Division of Safeguards. 1p. 33030:358-33030:358.

8510180525 Advises that CW Malody has replaced R Nilson as manager of corporate licensing, effective 850831. CAUDILL, H.L. Exon Nuclear Co., Inc. (subs. of Exon Corp.). 85/09/25. CROW, W.T. Uranium Fuel Licensing Branch. 2pp. 33077:224-33077:225.

DOCKET 70-1308 GENERAL ELECTRIC CO., SAN JOSE, CA

8510010104 Request for reconsideration of 820504 decision granting GE license to store spent fuel w/o requiring federal EIS. EIS should be issued. QUIGG, C.F. Illinois Safe Energy Alliance. #485 483. 85/08/29. Office of Nuclear Material Safety & Safeguards, Director. 15pp. 32678:317-32678:330.

DOCKET 70-1489 GOODYEAR AEROSPACE CORP., AKRON, OH

8510230260 Informs of issuance of Amend 1 to License SNM-1461, per 850723 request, extending expiration date to 860401. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/15. GLEGHORN, D.E. Goodyear Aerospace Corp. (subs. of Goodyear Tire & Rubber Co.). 1p. 33106:345-33106:346.

-8510230263 Grants categorical exclusion for 850723 request for amend to License SNM-1461. Neither environ assessment nor EIS warranted. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/15. Uranium Fuel Licensing Branch. 1p. 33106:346-33106:346.

8510240156 Documents Goodyear Aerospace Corp 850723 request for extension of expiration date for License SNM-1461. Development work terminated. Facility should be decontaminated & decommissioned prior to 860401. NIXON, W.A. Uranium Fuel Licensing Branch. 85/10/15. Uranium Fuel Licensing Branch. 1p. 33176:357-33176:357.

DOCKET 70-1549 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230114 Forwards Press Release 85-53 re NRC proposed fine against Nuclear Fuel Svcs, Inc for alleged noncompliance w/requirements concerning release of radioactive matl to work area. KAMMERER, C. Office of Congressional Affairs. 85/05/03. MARKEY, E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:056-33109:057.

DOCKET 70-1784 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230114 Forwards Press Release 85-53 re NRC proposed fine against Nuclear Fuel Svcs, Inc for alleged noncompliance w/requirements concerning release of radioactive matl to work area. KAMMERER, C. Office of Congressional Affairs. 85/05/03. MARKEY, E. House of Rep., Energy & Commerce. GORE, SASSER Senate. 2pp. 33109:056-33109:057.

DOCKET 70-2322 EDLOW INTERNATIONAL CO., WASHINGTON, DC

8510070015 Approves encl route from Port of Wilmington, NC to Aiken, SC for transport of spent reactor fuel, per 850826 request. Data re arrangements w/law enforcement agencies along route & diagrams of route encl. MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/09/30. AUMULLER, J.N. Edlow International Co. 7pp. 32901:040-32901:046.

8510070018 Approves encl route from Norfolk, VA to Aiken, SC for transport of spent reactor fuel, per 850826 request. Data re arrangements w/law enforcement agencies along route & diagrams of route encl. MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/09/30. AUMULLER, J.N. Edlow International Co. 9pp. 32901:047-32901:055.

8510070557 Approves 850826 request for route from Portsmouth, VA to Aiken, SC for transport of spent reactor fuel. Request approved through 861231. Info to be incorporated into shipment plans encl. MCCORKLE, G.W. Division of Safeguards. 85/10/01. AUMULLER, J.N. Edlow International Co. 9pp. 32900:345-32900:353.

8510280436 Forwards sanitized Page 6 of encl to 851001 ltr, replacing page inadvertently left incomplete. MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/10/16. AUMULLER, J.N. Edlow International Co. 2pp. 33198:311-33198:312.

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8510090071 Issues Amend 9 to License SNM-1861, extending expiration date until 861031 or conversion of CPPR-91 to OL & authorizing personnel changes & removal of metal conversion fuel in spent fuel pool. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/03. DOMER, J.A. Tennessee Valley Authority. 1p. 32963:335-32963:336.

-8510090085 SER supporting amend to License SNM-1861, extending expiration date until 861031 or conversion of CPPR-91 to OL, authorizing personnel changes & removal of metal covers on fuel in spent fuel pool. BIDINGER, G.H., CROW, W.T. Uranium Fuel Licensing Branch. 85/10/03. 2pp. 32963:336-32963:337.

-8510090089 Advises that neither environ assessment nor EIS warranted for proposed amend to License SNM-1851. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/03. Uranium Fuel Licensing Branch. 1p. 32963:336-32963:336.

DOCKET 70-2930 FIVE FOUR THREE CO., INC., MORGANTOWN, WV

8510170468 Informs of requirements for submittal of matl transfer repts per 10CFR75.70.40 & 30 re possession & transfer of SNM. Reporting identification symbol YOH assigned to License SNM-1872. BENNINGTON, G.M. Reactor & Transportation Licensing Branch. 85/10/09. STEWART, R.F. Five Four Three Co., Inc. 1p. 33046:358-33046:358.

DOCKET 70-2947 ILLINOIS POWER CO., DECATUR, IL

8510080425 Forwards Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01, respectively, on 850826-0910. No violation noted. HIND, J.A. Region 3, Office of Director. 85/10/02. GERSTNER, W.C. Illinois Power Co. 2pp. 32922:220-32922:223.

-8510080432 Preoperational Physical Protection & SNM Control & Accountability Insp Repts 50-461/85-43 & 70-2947/85-01 on 850826-0910. No violation noted. Areas inspected security program audit. Details withheld (ref 10CFR73.21). PIRTLE, G.L., CHRISTOFFER, G., DROUIN, B. Region 3, Office of Director. 85/10/01. 2pp. 32922:222-32922:223.

DOCKET 70-2948 NIAGARA MOHAWK POWER CORP., SYRACUSE, NY

8510150164 Approves Rev 1 to security plan for SNM of low strategic significance. Full implementation of plan, including changes made per 10CFR70.32(e), requested by date of fuel receipt. BROWN, W.B. Material Licensing & International Activities Branch. 85/09/18. SUNSER, J.J. Niagara Mohawk Power Corp. 1p. 33031:101-33031:101.

85102 '0297 Application for amend to License SNM-1895, extending license to Sept 1987 or upon conversion of CPPR-112 to OL, whichever is earlier. Response to NRC 850729 request for addl info also encl. WETTERHAHN, M.J. Conner & Wetterhahn. WETTERHAHN, M.J. Niagara Mohawk Power Corp. 85/09/27. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 33pp. 33095:350-33096:022.

DOCKET 70-2953 CONNECTICUT, UNIV. OF, STORRS, CT

8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.

-8510230241 Forwards Press Release 1-84-97 re NRC proposed fine against Univ of Connecticut for six alleged violations on use & storage of radioactive matls. KAMMERER, C. Office of Congressional Affairs. 84/09/06. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:102-33109:104.

DOCKET 70-2984 ARIZONA PUBLIC SERVICE CO., PHOENIX, AZ

8510220193 Forwards Insp Repts 50-528/85-30 & 70-2984/85-01 on 850923-27 & notice of violation Repts & notice of violation withheld (ref 10CFR2.790). SCARANO, R.A. Region 5, Office of Director. 85/10/17. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 33087:309-33087:310.

DOCKET 70-2997 CAROLINA POWER & LIGHT CO., RALEIGH, NC

8510240395 Submits clarifying comments & proposed actions re application for SNM license. CUTTER, A.B. Carolina Power & Light Co. 85/10/10. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33182:232-33182:235.

DOCKET 70-3000 COMMONWEALTH EDISON CO., CHICAGO, IL

8510150120 Approves Rev 1 to "Security Plan for SNM Security for Commonwealth Edison Co. Braidwood Station," submitted by 850419 ltr. Plan meets requirements of 10CFR73.67 for fixed site & in-transit protection of SNM. BROWN, W.B. Material Licensing & International Activities Branch. 85/09/05. FARRAR, D.L. Commonwealth Edison Co. 1p. 33030:224-33030:224.

8510160163 Forwards revised License SNM-1938, Indemnity Agreement B-102, 10CFR71, finding of no significant impact, environ assessment & SER w/o indemnity agreement & 10CFR71. CROW, W.T. Uranium Fuel Licensing Branch. 85/10/08. ALEXANDER, G.L. Commonwealth Edison Co. 2pp. 33028:144-33028:167.

264 DOCKETED ITEMS

-8510160169 Revised License SNM-1938 for Comm Ed. authorizing use of 3,150 kg U-235 in U enriched to no more than 3.55 w/o 40 g U-235 at any enrichment & 2 uCi Pu-239.
CROW, W.T. Division of Fuel Cycle & Material Safety. 85/10/08. 4pp. 33028:146-33028:149.

-8510160182 Environ assessment re 850608 application for license to receive, possess, inspect & store SNM containing unirradiated nuclear fuel assemblies. Issuance of finding of no significant impact appropriate.
HORN, M., CROW, W.T. Uranium Fuel Licensing Branch. 85/05/02. 3pp. 33028:152-33028:154.

-8510160188 SER supporting 850608 application for license to receive, possess, inspect & store U enriched in U-235, contained in fuel assemblies.
KETZLACH, N., CROW, W.T. Uranium Fuel Licensing Branch. 85/10/08. 13pp. 33028:155-33028:167.

DOCKET 70-3008 DUQUESNE LIGHT CO., PITTSBURGH, PA

8510240402 Forwards corrected FSAP. Figure 4.2-1 from 850913 Rev 1 to SNM license application. Original figure contained typos. Corrected figure will be incorporated in next FSAP amend.
CAREY, J.J. Duquesne Light Co. 85/10/09. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33182:229-33182:231.

DOCKET 70-3013 COMMONWEALTH EDISON CO., CHICAGO, IL

8510150120 Approves Rev 1 to "Security Plan for SNM Security for Commonwealth Edison Co. Bradwood Station," submitted by 850419. Plan meets requirements of 10CFR73.67 for fixed site & in-transit protection of SNM.
BROWN, W.B. Material Licensing & International Activities Branch. 85/09/05. FARRAR, D.L. Commonwealth Edison Co. 1p. 33030:224-33030:224.

DOCKET 70-3016 HOUSTON LIGHTING & POWER CO., HOUSTON, TX

8510150434 Advises that review of Rev 2 to "Interim Security Plan for Fuel Storage at South Texas Project" submitted in 850719. Plan meets requirements of 10CFR73.67.
BROWN, W.B. Material Licensing & International Activities Branch. 85/09/10. DEWEASE, J.G. Houston Lighting & Power Co. 1p. 33033:205-33033:205.

DOCKET 70-3018 HOUSTON LIGHTING & POWER CO., SOUTH TEXAS PROJECT, TX

8510150434 Advises that review of Rev 2 to "Interim Security Plan for Fuel Storage at South Texas Project" submitted in 850719. Plan meets requirements of 10CFR73.67.
BROWN, W.B. Material Licensing & International Activities Branch. 85/09/10. DEWEASE, J.G. Houston Lighting & Power Co. 1p. 33033:205-33033:205.

DOCKET 70-3020 NUCLEAR ASSURANCE CORP., NORCROSS, GA

8510280457 Discusses 850820 request for approval of encl route to be used for transport of spent reactor fuel. Route meets requirements of 10CFR73.37 & is acceptable.
MCCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/10/22. DANESSE, F.L. Nuclear Assurance Corp. 8pp. 33196:251-33196:258.

DOCKET 70-3027 PUBLIC SERVICE CO. OF NEW HAMPSHIRE, SEABROOK, NH

8510040113 Forwards request for addl info required to complete safety review of 850601 application for receipt, possession & storage of fresh fuel assemblies & other SNM required for Seabrook 1. Review will continue upon receipt of info.
KODALI, K.K. Uranium Fuel Licensing Branch. 85/09/30. THOMAS, G.S. Public Service Co. of New Hampshire. 4pp. 32860:184-32860:187.

8510280416 Responds to 850930 request for addl info re application for amend to SNM license & forwards amended pages to application, including info re fuel storage facilities & physical protection.
THOMAS, G.S. Public Service Co. of New Hampshire. 85/10/24. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 26pp. 33194:023-33194:048.

-8510280418 Amended pages to application for license, authorizing receipt, possession & storage of unirradiated SNM.
* Public Service Co. of New Hampshire. 85/10/24. 23pp. 33194:026-33194:048.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0005 MAGNAFLUX CORP.

8510180529 Forwards QA program approval for radioactive matl package: 0005, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/15. BANFIELD, E.L. MOS Inspection, Inc. (formerly Magnaflux Corp.). 1p. 33077:267-33077:268.

-8510180535 QA program approval for radioactive matl package: 0005, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/15. 1p. 33077:268-33077:268.

DOCKET 71-0088 BABCOCK & WILCOX CO.

8510150027 Application for QA program approval for radioactive matl package: 0088, Rev 3 to QA program encl. Fee paid.
REGAN, N.A. Babcock & Wilcox Co. 85/09/05. MACDONALD, C.E. Transportation Certification Branch. 1p. 33032:046-33032:081.

-8510150028 Rev 3 to "QA of Shipping Containers."
TRENT, L.K. Babcock & Wilcox Co. 85/09/05. 35pp. 33032:047-33032:081.

8510180499 Forwards QA program approval for radioactive matl package: 0088, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/16. REGAN, N.A. Babcock & Wilcox Co. 1p. 33077:339-33077:340.

-8510180501 QA program approval for radioactive matl package: 0088, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/16. 1p. 33077:340-33077:340.

DOCKET 71-0121 NEUTRON PRODUCTS, INC.

8510220097 Application for renewal of QA program approval for radioactive matl package: 0121, Rev 1. Fee paid. Rev 1 to QA program will be submitted in Oct 1985. Fee paid.
COSTLEY, W.J. Neutron Products, Inc. 85/09/23. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33098:197-33098:198.

-8510220100 Requests remittance of fee for 850923 application for renewal of QA program approval for radioactive matl package: 0121, per encl 10CFR170. W/o encl.
JACKSON, G. License Fee Management Branch. 85/10/03. COSTLEY, W.J. Neutron Products, Inc. 1p. 33098:198-33098:198.

8510030317 Forwards QA program approval for radioactive matl package: 0121, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. COSTLEY, W. Neutron Products, Inc. 1p. 32849:011-32849:012.

-8510030319 QA program approval for radioactive matl package: 0121, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. 1p. 32849:012-32849:012.

DOCKET 71-0133 NAVY, DEPT. OF

8510180521 Forwards request for mod to QA program approval for radioactive matl package: 0133.
DURFEE, P.J. Navy, Dept. of Naval Sea Systems Command. 85/10/10. Transportation Certification Branch. 1p. 33077:219-33077:220.

-8510180526 Application for rev to QA program approval for radioactive matl package: 0133. Rev modifies & broadens QA program approval to permit one-time shipment & receipt of Type B quantities of encapsulated matl.
FLOR, W.J. Navy, Dept. of Pearl Harbor Naval Shipyard. 85/09/27. GORDON, L. Transportation Certification Branch. 2pp. 33077:220-33077:220.

8510220015 Forwards QA program approval for radioactive matl package: 0133, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/15. Navy, Dept. of Pearl Harbor Naval Shipyard. 1p. 33098:327-33098:328.

-8510220016 QA program approval for radioactive matl package: 0133, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/10/15. 1p. 33098:328-33098:328.

DOCKET 71-0135 BABCOCK & WILCOX CO.

8510110233 Forwards Rev 11 to "QA Policy & Procedures Manual," in response to telcon & 850815. Fee paid.
AUSTIN, M.A. Babcock & Wilcox Co. 85/08/21. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33013:169-33013:248.

-8510110234 Rev 11 to QA-72-1, "QA Policy & Procedures Manual."
* Babcock & Wilcox Co. 85/08/14. 78pp. 33013:171-33013:248.

8510030066 Forwards QA program approval for radioactive matl package: 0135, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. AUSTIN, M.A. Babcock & Wilcox Co. 1p. 32849:330-32849:330.

-8510030074 QA program approval for radioactive matl package: 0135, Rev 3. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. 1p. 32849:331-32849:331.

DOCKET 71-0139 TULSA GAMMA RAY, INC.

8510110240 Application for renewal of QA program approval for radioactive matl package: 0139. Change in safety officer noted on encl organizational chart. Fee paid.
MOSS, J.C. Tulsa Gamma Ray, Inc. 85/09/12. MACDONALD, C.E. Division of Fuel Cycle & Material Safety. 1p. 33012:183-33012:185.

-8510110242 Organizational chart indicating replacement of KL Stewart w/ PJ Moss as radiation safety officer.
* Tulsa Gamma Ray, Inc. 85/09/12. 2pp. 33012:184-33012:185.

8510030303 Forwards QA program approval for radioactive matl package: 0139, Rev 2. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. MOSS, P.J. Tulsa Gamma Ray, Inc. 1p. 32848:311-32848:312.

-8510030308 QA program approval for radioactive matl package: 0139, Rev 2. MACDONALD, C.E. Transportation Certification Branch. 85/09/30. 1p. 32848:312-32848:312.

DOCKET 71-0173 PACIFIC NORTHWEST LABORATORIES

8510210172 Expresses gratitude for timely notification re renewal of Rev 2 to QA program approval for radioactive matl package: 0173.
SIMPSON, C.L. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/26. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33094:160-33094:161.

DOCKET 71-0230 BABCOCK & WILCOX CO.

8510150037 Forwards Rev 3 to "QA Program for Radioactive Matl Packages." Fee paid.
OLSEN,A.F. Babcock & Wilcox Co. 85/09/09. MACDONALD,C.E. Transportation Certification Branch. 1p. 33042:205-33042:240.

-8510150039 Rev 3 to "QA Program for Radioactive Matl Packages."
KRAMER,J.E., BENNETT,R.L., ROBERTS,G.W. Babcock & Wilcox Co. 85/08/31. 36pp. 33042:208-33042:240.

8510090322 Forwards QA program approval for radioactive matl package: 0230,Rev 3.
MACDONALD,C.E. Transportation Certification Branch. 85/10/04. OLSEN,A.F. Babcock & Wilcox Co. 1p. 32950:235-32950:236.

-8510090325 QA program approval for radioactive matl package:0230,Rev 3.
MACDONALD,C.E. Transportation Certification Branch. 85/10/04. 1p. 32950:235-32950:236.

DOCKET 71-0240 POWER AUTHORITY OF STATE OF NEW YORK

8510090510 Requests mailing address be changed from CA McNeil to author.
CONVERSE,R.J. New York Power Authority (formerly Power Authority of the State of New York). 85/08/15. MACDONALD,C.E. Transportation Certification Branch. 2pp. 32966:184-32966:185.

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP.

8510030214 Forwards QA program approval for radioactive matl package: 0251,Rev 3.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. NARDI,A.J. Westinghouse Electric Corp. 1p. 32849:202-32849:202.

-8510030222 QA program approval for radioactive matl package:0251,Rev 3.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. 1p. 32849:203-32849:203.

DOCKET 71-0383 BALTIMORE GAS & ELECTRIC CO.

8510110275 Application for renewal of QA program approval for radioactive matl package:0383,Rev 0.Fee paid.
LUNDVALL,A.E. Baltimore Gas & Electric Co. 85/09/11. MACDONALD,C.E. Transportation Certification Branch. 2pp. 32974:358-32974:359.

8510030267 Forwards QA program approval for radioactive matl package: 0383,Rev 2.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. LUNDVALL,A.E. Baltimore Gas & Electric Co. 1p. 32849:084-32849:085.

-8510030270 QA program approval for radioactive matl package:0383,Rev 2.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. 1p. 32849:085-32849:085.

DOCKET 71-0384 NEW ENGLAND NUCLEAR CORP.

8510150297 Requests extension of QA program approval for radioactive matl package:0384,Rev 0.Fee paid.
DEMARIA,E. E.I. du Pont de Nemours & Co., Inc. 85/08/02. Transportation Certification Branch. 1p. 33032:222-33032:226.

-8510150302 Requests remittance of fee for 850802 application for renewal of QA program approval for radioactive matl package:0384,Rev 0.
JACKSON,G. License Fee Management Branch. 85/08/29. DEMARIA,E. E.I. du Pont de Nemours & Co., Inc. 1p. 33032:226-33032:226.

8510020497 Forwards QA program approval for radioactive matl package: 0384,Rev 2.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. DEMARIA,E. New England Nuclear Corp. 1p. 32836:288-32836:289.

-8510020501 QA program approval for radioactive matl package:0384,Rev 2.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. 1p. 32836:289-32836:289.

DOCKET 71-0546 VECTOR CORP.

8510150269 Forwards "QA Requirements for Transportation Package (10CFR71) as Applicable to Industrial Radiography Licensees."
HANDRAHAN,E. Vector Corp. 85/07/01. Office of Nuclear Material Safety & Safeguards,Director. 1p. 33032:300-33032:307.

-8510150276 "QA Requirements for Transportation Package (10CFR71) as Applicable to Industrial Radiography Licensees."
* Vector Corp. 85/07/01. 4pp. 33032:301-33032:307.

DOCKET 71-0551 SIEMENS MEDICAL SYS, INC.

8510150029 Informs that 850827 application for QA program approval for Siemens cobalt source shipping container Type S1747 must be resubmitted per 10CFR71,Reg Guide 7.10 & sample QA program encl as guidance in preparing application.W/o encls.
MACDONALD,C.E. Transportation Certification Branch. 85/10/03. HORNDASCH,A.F. Siemens Medical Systems, Inc. (subs. of Siemens Capital Corp.). 1p. 33032:045-33032:045.

DOCKET 71-0552 OLD DOMINION FABRICATORS

8510110243 Requests registration as user of Models A-1-G-A-2-A,A1A, 39998 & 848 Qualifications of personnel authorized to implement QA program encl.Fee paid.
MARTIN,R.M. Old Dominion Fabricators. 85/09/12. GORDON,L.L. Transportation Certification Branch. 9pp. 32974:334-32974:348.

-8510110244 Rev 2 to Certificate of Compliance 9133,for Model C-10.
MACDONALD,C.E. Transportation Certification Branch. 84/04/10. 2pp. 32974:345-32974:348.

8510110252 Forwards "QA Program,Packaging & Transporting Special Form Radioactive Matl Including Radiography Devices."
MARTIN,R.M. Old Dominion Fabricators. 85/09/18. GORDON,L.L. Transportation Certification Branch. 2pp. 32974:328-32974:333.

-8510110253 "QA Program,Packaging & Transporting Special Form Radioactive Matl Including Radiography Devices."
MARTIN,R.M. Old Dominion Fabricators. 85/09/10. 5pp. 32974:329-32974:333.

8510020508 Forwards QA program approval for radioactive matl package: 0552,Rev 0.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. MARTIN,R.W. Old Dominion Iron. 1p. 32836:286-32836:287.

-8510020510 QA program approval for radioactive matl package:0552,Rev 0.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. 1p. 32836:287-32836:287.

DOCKET 71-5088 MODEL: D34710-1, D34710-2, ROCKWELL INTERNATIONAL CORP.

8510220035 Forwards Rev 4 to Certificate of Compliance 5088 for Models D34710-1 & D34710-2.
MACDONALD,C.E. Transportation Certification Branch. 85/10/17. REGAN,N.A. Babcock & Wilcox Co. 2pp. 33098:250-33098:256.

-8510220039 Certificate of Compliance 5088,Rev 4,for Models D34710-1 & D34710-2,Approval record encl.
MACDONALD,C.E. Transportation Certification Branch. 85/10/17. 5pp. 33098:252-33098:256.

DOCKET 71-5507 MODEL: HFIR SPENT FUEL ELEMENT SHIPPING CASK, ENERGY,

8510090540 Forwards request for addl info re ORNL HFIR spent fuel element shipping package,per 780426 & 1126 requests for review.If info cannot be provided within 6 months, application should be withdrawn.
MACDONALD,C.E. Transportation Certification Branch. 85/10/03. GARRISON,R.F. Energy, Dept. of. 3pp. 32966:333-32966:335.

8510310392 Summary of 851022 meeting w/DOE & contractors in Silver Spring,MD re outstanding issues on HFIR spent fuel cask.
LAKE,W.H. Transportation Certification Branch. 85/10/24. Transportation Certification Branch. 2pp. 33278:198-33278:199.

DOCKET 71-5607 MODEL: T-2, ENERGY, DEPT. OF

8510150287 Forwards marked-up Certificate of Compliance 5607,correcting dimensions of lead shielding for Model T-2.
GARRISON,R.F. Energy, Dept. of. 85/09/20. MACDONALD,C.E. Transportation Certification Branch. 3pp. 33033:129-33033:131.

DOCKET 71-5862 MODEL: SENTINEL-100F, TELEDYNE ENERGY SYSTEMS

8510110135 Requests encl 850626 application for renewal of Certificate of Compliance 5862 w/12 oversize drawings be placed in PDR.
MACDONALD,C.E. Transportation Certification Branch. 85/10/04. SCOTT,S. Document Management Branch. 1p. 33013:051-33013:168.

-8510110140 Application for renewal of Certificate of Compliance 5862, consolidating original application into Rev 4 to INSD-3080, "Structural & Thermal Evaluation of Sentinel 100F." Redesignation of certificate withdrawn.
VOGT,J.F. Teledyne Energy Systems. 85/06/26. MACDONALD,C.E. Transportation Certification Branch. 2pp. 33013:052-33013:168.

-8510110145 Rev 4 to "Structural & Thermal Evaluation of Sentinel 100F." W/13 oversize drawings.
* Teledyne Energy Systems. INSD-3080 R04. 85/06/30. 114pp. 33013:054-33013:168.

8510110126 Application for rev to Certificate of Compliance 5862 for Model Sentinel 100F Draft Rev 5 to "Structural & Thermal Evaluation of Sentinel 100F," encl.
VOGT,J.F. Teledyne Energy Systems. 85/08/30. MACDONALD,C.E. Transportation Certification Branch. 16pp. 33012:042-33012:058.

8510030115 Forwards Rev 4 to Certificate of Compliance 5862 for Model Sentinel-100F.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. MCGREW,J.W. Teledyne Energy Systems. 1p. 32849:319-32849:319.

-8510030120 Certificate of Compliance 5862,Rev 4,for Model Sentinel-100F Approval record encl.
MACDONALD,C.E. Transportation Certification Branch. 85/09/30. 3pp. 32849:320-32849:322.

DOCKET 71-5874 MODEL: WAPD-40, ENERGY, DEPT. OF

8510110118 Application for amend to Certificate of Compliance 5874 for Model WAPD-40,allowing one-time exemption re type & form of matl in product containers to cover shipment being made from installation.Fee paid.
ANSELMO,A.A. EG&G Idaho, Inc. (subs. of EG&G, Inc.). 85/09/09. MACDONALD,C.E. Transportation Certification Branch. 13pp. 33012:120-33012:132.

266 DOCKETED ITEMS

DOCKET 71-5939 MODEL: GE-1500, GENERAL ELECTRIC CO.

8510210213 Requests registration as user of Model GE 1500.
LEMPGES, T.E. Niagara Mohawk Power Corp. 85/09/23. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 33079:360-33079:361.

-8510160371 Notification of registration as user of Model 1500, in response to 850923 request.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. GERBER, C.A. Niagara Mohawk Power Corp. 1p. 33034:290-33034:290.

DOCKET 71-5942 MODEL: GE-700, GENERAL ELECTRIC CO.

8510150261 Responds to questions contained in 850904 ltr re amend to Certificate of Compliance 5942. Separation provided by placing 0.188 inch 304 stainless steel plate between two baskets. Drawings 1 computer run encl.
CUNNINGHAM, G.E. General Electric Co. 85/09/16. MACDONALD, C.E. Transportation Certification Branch. 71pp. 33032:318-33033:028.

DOCKET 71-5994 MODEL: 5984, J.L. SHEPHERD & ASSOCIATES

8510030137 Responds to 850904 ltr re submittal of radioactive mat'l label. No record of request located. Label does not appear to comply w/requirements in 49CFR172.403, 172.310, 172.436-172.440 & 10CFR71.85(c).
MACDONALD, C.E. Transportation Certification Branch. 85/09/30. FOLK, J.L. Shepherd & Associates. 1p. 32849:316-32849:316.

8510210250 Requests registration as user of Model 5984.
CUNNINGHAM, G.E. General Electric Co. 85/09/30. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33079:335-33079:336.

8510160370 Notification of registration as user of Model 5984, in response to 850930 request.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. CUNNINGHAM, G.E. General Electric Co. 1p. 33034:289-33034:289.

DOCKET 71-6058 MODEL: B-3, U.S. ECOLOGY, INC.

8510030333 Forwards request for add info re 850331 & 0630 applications for renewal of Certificate of Compliance 6058 for Model B-3. Response requested within 30 days of ltr date.
MACDONALD, C.E. Transportation Certification Branch. 85/09/30. RUZICKA, W.G. Cinchem, Inc. 2pp. 32849:079-32849:080.

DOCKET 71-6206 MODEL: B, BABCOCK & WILCOX CO.

8510210214 Requests registration as user of Model B.
MAYHUE, D.B. General Public Utilities Corp. - GPU Service Corp. 85/09/26. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33079:356-33079:359.

8510170066 Notification of registration as user of Model B, in response to 850926 request.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. HAHN, R.E. General Public Utilities Corp. - GPU Service Corp. 1p. 33043:233-33043:233.

DOCKET 71-6574 MODEL: HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8510090543 Requests extension until 851030 to respond to NRC 850829 request for add info re application for renewal of Certificate of Compliance 6574 for Model HN-200. Time needed to reanalyze impact skirt during end drops.
LEDUC, R.J. Westinghouse Hittman Nuclear, Inc. 85/09/23. MACDONALD, C. Transportation Certification Branch. 2pp. 32965:077-32965:078.

DOCKET 71-6722 MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY

8510110155 Application for renewal of Certificate of Compliance 6722 for Model BS-33-180.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/19. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33012:040-33012:041.

8510170071 Forwards Rev 9 to Certificate of Compliance 6722 for Model BS-33-180.
MACDONALD, C.E. Transportation Certification Branch. 85/10/10. HUFHAM, J.W. Tennessee Valley Authority. 1p. 33043:227-33043:231.

-8510170072 Certificate of Compliance 6722, Rev 9, for Model BS-33-180. Approval record encl.
MACDONALD, C.E. Transportation Certification Branch. 85/10/10. 4pp. 33043:228-33043:231.

DOCKET 71-9010 MODEL: NLI 1/2, NUCLEAR ASSURANCE CORP.

8510110247 Requests encl 850830 application for amend to Certificate of Compliance 9010 w/two proprietary oversize drawings be placed in PDR.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. SCOTT, S. Document Management Branch. 1p. 33013:047-33013:050.

-8510110248 Application for amend to Certificate of Compliance 9010, incorporating revs to inner container lid of Configuration A of NLI Industries 1/2 cask per encl Rev 9 to Sheet 1 & Rev 5 to Sheet 2 of oversize Drawing /0562F Fee paid.
JOHNSON, C.R. Nuclear Assurance Corp. 85/08/30. MACDONALD, C.E. Transportation Certification Branch. 3pp. 33013:048-33013:050.

DOCKET 71-9032 MODEL: 650, TECH/OPS, INC.

8510110055 Requests registration as user of Models 650 & IR-50.
SWINEY, D.L. Bristol Steel & Iron Works, Inc. 85/09/10. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33011:001-33011:002.

DOCKET 71-9071 MODEL: AP-101, ANEFCO, INC.

8510030110 Requests add info re 850813 request for approval of supplementary shield for Model AP-101. Analysis demonstrating proposed shield remains effective under normal & accident conditions of transport needed.
MACDONALD, C.E. Transportation Certification Branch. 85/09/30. MURPHY, J.D. Anefco, Inc. 1p. 32849:325-32849:325.

DOCKET 71-9073 MODEL: OH-142 SERIES & NUS 10-135, NUCLEAR PACKAGING,

8510110059 Requests registration as user of Model OH-142 MKI.
ROWE, B.S. Westinghouse Hittman Nuclear, Inc. 85/09/24. MACDONALD, C.E. Transportation Certification Branch. 2pp. 32974:360-32974:361.

8510180546 Requests registration as user of Model OH-142 MKI.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/01. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33077:283-33077:284.

8510170063 Notification of registration as user of Models OH-142, OH-142 MKI, OH-142 MKIIB, OH-142 MKIIC & NUS 10-135, in response to 851001 request.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. CRANE, P.A. Pacific Gas & Electric Co. 1p. 33043:221-33043:221.

DOCKET 71-9079 MODEL: NUPAC 14D-2.0 & HN-100 SERIES 2 & 2A,

8510110225 Requests registration as user of Model NUPAC 14D-2.0. Future correspondence re cask should be sent to BN Leach at listed address.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/10. Transportation Certification Branch. 2pp. 33011:351-33011:352.

DOCKET 71-9080 MODEL: HN-600, NUPAC 100 & CNS 7-100,

8510090541 Requests registration as user of Model NUPAC 100.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/10. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 32965:079-32965:080.

DOCKET 71-9089 MODEL: HN-100S, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8510150045 Requests registration as user of Model HN-100s.
QUERIO, R.E. Commonwealth Edison Co. 85/09/20. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33031:296-33031:297.

8510180462 Requests registration as user of Model HN 100, Series S.
DIEDERICH, G.J. Commonwealth Edison Co. 85/09/27. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33077:152-33077:153.

8510030133 Notification of registration as user of Model HN-100S, in response to 850920 request.
MACDONALD, C.E. Transportation Certification Branch. 85/09/30. QUERIO, R.E. Commonwealth Edison Co. 1p. 32849:317-32849:317.

8510170069 Notification of registration as user of Model HN-100S, in response to 850927 request.
MACDONALD, C.E. Transportation Certification Branch. 85/10/08. DIEDERICH, G.J. Commonwealth Edison Co. 1p. 33043:232-33043:232.

DOCKET 71-9133 MODEL: C-10, GAMMA INDUSTRIES

8510110243 Requests registration as user of Models A-1-GA-2-A, A1A, 39998 & 848. Qualifications of personnel authorized to implement QA program encl. Fee paid.
MARTIN, R.M. Old Dominion Fabricators. 85/09/12. GORDON, L.L. Transportation Certification Branch. 9pp. 32974:334-32974:348.

-8510110244 Rev 2 to Certificate of Compliance 9133, for Model C-10.
MACDONALD, C.E. Transportation Certification Branch. 84/04/10. 2pp. 32974:345-32974:348.

DOCKET 71-9156 MODEL: IR-50, INDUSTRIAL NUCLEAR CO.

8510110055 Requests registration as user of Models 650 & IR-50.
SWINEY, D.L. Bristol Steel & Iron Works, Inc. 85/09/10. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33011:001-33011:002.

DOCKET 71-9159 MODEL: NUPAC 14/190L, /190M & /190H, NUCLEAR PKG., INC.

8510090317 Forwards request for add info re 841214 application for amend to package designs approved by Certificates of Compliance 9159, 9176, 9177, 9178 & 9179. Response requested within 30 days.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HIPSHER, W. NUS Corp. 2pp. 32949:168-32949:171.

DOCKET 71-9168 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC.

8510090514 Forwards Rev 0 to "Description & Safety Analysis for Optional Ratchet Binder Closure Sys for CNS 8-120B Shipping Package." Fee paid.
KINGSLEY, K.R. Chem-Nuclear Systems, Inc. 85/08/26. MACDONALD, C.E. Transportation Certification Branch. 4pp. 32965:198-32965:246.

-8510090517 Rev 0 to "Description & Safety Analysis for Optional Ratchet Binder Closure Sys for CNS 8-120B Shipping Package."
* Chem-Nuclear Systems, Inc. 85/08/26. 43pp. 32965:202-32965:246.

DOCKET 71-9176 MODEL: NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING, INC.

8510110220 Requests registration as user of Model NUPAC 14/210H. Future correspondence re cask should be sent to BN Leach at listed address.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 85/09/10. Transportation Certification Branch. 2pp. 33012:016-33012:017.

8510110208 Requests registration as user of Model CNSI 14-215H A.
KELLIE, F. Sacramento Municipal Utility District. 85/09/17. MACDONALD, C.E. Transportation Certification Branch. 2pp. 33012:029-33012:030.

8510010053 Notification of registration as user of Model NUPAC 14/210L, NUPAC 14/210H & CNSI 14-215H A in response to 850917 request.
MACDONALD, C.E. Transportation Certification Branch. 85/09/25. MILLER, R.I. Sacramento Municipal Utility District. 1p. 32833:172-32833:172.

8510090317 Forwards request for add info re 841214 application for amend to package designs approved by Certificates of Compliance 9159, 9176, 9177, 9178 & 9179. Response requested within 30 days.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HIPSHER, W. NUS Corp. 2pp. 32949:168-32949:171.

8510180050 Requests registration as user of Model CNS 14-215.
SHIFFER, J.D. Pacific Gas & Electric Co. 85/10/14. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. MACDONALD, C.E. NRC - No Detailed Affiliation Given. 1p. 33059:331-33059:331.

DOCKET 71-9177 MODEL: NUPAC 10/140, NUCLEAR PACKAGING, INC.

8510090317 Forwards request for add info re 841214 application for amend to package designs approved by Certificates of Compliance 9159, 9176, 9177, 9178 & 9179. Response requested within 30 days.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HIPSHER, W. NUS Corp. 2pp. 32949:168-32949:171.

DOCKET 71-9178 MODEL: NUPAC 7/100, NUCLEAR PACKAGING, INC.

8510090317 Forwards request for add info re 841214 application for amend to package designs approved by Certificates of Compliance 9159, 9176, 9177, 9178 & 9179. Response requested within 30 days.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HIPSHER, W. NUS Corp. 2pp. 32949:168-32949:171.

DOCKET 71-9179 MODEL: NUPAC 8/100L & 8/100H, NUCLEAR PACKAGING, INC.

8510090317 Forwards request for add info re 841214 application for amend to package designs approved by Certificates of Compliance 9159, 9176, 9177, 9178 & 9179. Response requested within 30 days.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HIPSHER, W. NUS Corp. 2pp. 32949:168-32949:171.

DOCKET 71-9192 MODEL: AP-300, ANEFCO, INC.

8510150395 Forwards revs to SAR for AP-300 shipping container submitted w/application for certificate of compliance. Revs include calculations showing that shell of cask can withstand stresses imposed by "g" loads.
MURPHY, J.D. Anefco, Inc. 85/08/23. MACDONALD, C.E. Transportation Certification Branch. 33pp. 33014:102-33014:132.

8510090505 Forwards Rev 7 to Page 2.4-141 to correct formula originally submitted on 850823. Correct number results in greater factor of safety.
MURPHY, J.D. Anefco, Inc. 85/08/27. MACDONALD, C.E. Transportation Certification Branch. 4pp. 32966:195-32966:198.

8510150292 Forwards Rev 7, replacing Rev 6, to Drawing 133-1 for Model AP-300 Type A package.
MURPHY, J.D. Anefco, Inc. 85/09/13. MACDONALD, C.E. Transportation Certification Branch. 4pp. 33014:135-33014:138.

8510010020 Forwards request for add info based on review of 840501 application requesting approval of Model AP-300, Type A package. Info should be submitted within 30 days from ltr date.
MACDONALD, C.E. Transportation Certification Branch. 85/09/24. MURPHY, J.D. Anefco, Inc. 4pp. 32833:187-32833:190.

DOCKET 71-9200 MODEL: 125-B, ENERGY, DEPT. OF

8510090459 Responds to 850809 request for add info to continue review of Nu²³⁸ 125-B package. Data in form of revised pages to SAR, will be submitted by second wk of Oct 1985.
HAELSIG, R.T. Nuclear Packaging, Inc. 85/09/09. MACDONALD, C.E. Transportation Certification Branch. 2pp. 32966:221-32966:222.

DOCKET 71-9201 MODEL: ELEKTA TIGER TYPE B(U), NUCLEAR PACKAGING, INC.

8510090302 Informs that 850830 application for approval of Model ELEKTA TIGER not accepted for detailed review. Encl listed items not provided. Withheld SAR returned under separate cover.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. TEMUS, C.J. Nuclear Packaging, Inc. 2pp. 32950:172-32950:173.

DOCKET 71-9202 MODEL: TN-BRP, TRANSNUCLEAR, INC.

8510150095 Application for certificate of compliance for TN-BRP spent fuel package.
GOLDMANN, K. Transnuclear, Inc. 85/09/13. MACDONALD, C.E. Transportation Certification Branch. 3pp. 33015:207-33015:211.

-8510150098 Requests that proprietary "TN-BRP Spent Fuel Package, SAR for Transport," be withheld from public disclosure (ref 10CFR2.790).
GOLDMANN, K. Transnuclear, Inc. 85/09/13. MACDONALD, C.E. Transportation Certification Branch. 5pp. 33015:210-33015:214.

-8510150102 Sanitized version of Vol 2 of "TN-BRP Spent Fuel Package, SAR for Transport."
* Transnuclear, Inc. 85/09/13. 200pp. 33015:215-33015:217.

8510150087 Forwards errata to SAR (E-7316) for TN-BRP spent fuel package, including handwritten symbols omitted from Chapter 3.
WILLIAMS, F.J. Transnuclear, Inc. 85/09/23. MACDONALD, C.E. Transportation Certification Branch. 4pp. 33030:270-33030:273.

8510220095 Forwards preliminary ltr rept, "Conclusions Drawn Following Review of Transnuclear, Big Rock Point SAR for Packaging." Transnuclear design acceptable.
VAN CLEVE, J.E. Oak Ridge National Laboratory. 85/10/02. MACDONALD, C.E. Transportation Certification Branch. 21pp. 33098:199-33098:220.

DOCKET 71-9203 MODEL: DHTF, BABCOCK & WILCOX CO.

8510240521 Forwards application for certificate of compliance for Model DHTF for transport of enriched U dioxide. Certification of conformance to IAEA safety stds requested. Fee paid.
WATTERS, J.P. Babcock & Wilcox Co. 85/09/30. MACDONALD, C.E. Transportation Certification Branch. 3pp. 33179:194-33180:076.

-8510240524 Application for certificate of compliance for Model DHTF.
* Babcock & Wilcox Co. 85/09/30. 200pp. 33179:197-33180:076.

DOCKET 71-9204 MODEL: CNS 10-160B, CHEM-NUCLEAR SYSTEMS, INC.

8510240546 Application for certificate of compliance for Model CNS 10-160B Proprietary & nonproprietary versions of SAR encl. Proprietary version withheld (ref 10CFR2.790). Fee paid.
ANDERSON, R.T. Chem-Nuclear Systems, Inc. 85/10/01. MACDONALD, C.E. Transportation Certification Branch. 4pp. 33183:045-33183:316.

-8510240552 Nonproprietary version of Rev 0 to "SAR for Chem-Nuclear Sys, Inc. Model CNS 10-160B Type B Radwaste Shipping Cask."
* Chem-Nuclear Systems, Inc. 85/09/30. 250pp. 33183:049-33183:316.

LICENSING OF INDEPENDENT SPENT FUEL STORAGE**DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.**

8510010104 Request for reconsideration of 820504 decision granting GE license to store spent fuel w/o requiring federal EIS. EIS should be issued.
QUIGG, C.T. Illinois Safe Energy Alliance. #485 483. 85/08/29. Office of Nuclear Material Safety & Safeguards, Director. 15pp. 32878:317-32878:330.

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO.

8510150041 Submits add info re training of personnel performing fuel handling & cask handling for dry cask ISFSI. Cask handling & fuel loading operations performed by licensed operators or under direct supervision of senior licensed personnel.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85/09/09. CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. 3pp. 33031:298-33031:300.

8510180033 Forwards topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys, Inc." Rept acceptable for referencing in licensing applications subj to encl limitations.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30. BARNHART, V.J. General Nuclear Systems, Inc. 6pp. 33074:176-33074:270.

-8510180038 Topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys, Inc."
* Office of Nuclear Material Safety & Safeguards, Director. 85/09/30. 89pp. 33074:182-33074:270.

8510180539 Requests analysis & evaluation of cause of cracking found in fuel basket of CASTOR V/21 cask used in dry spent fuel storage cooperative demonstration program. Revs necessary to topical SAR also requested.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/14. BARNHART, V.J. General Nuclear Systems, Inc. 1p. 33077:280-33077:280.

8510220028 Requests reassessment of use of CASTOR V/21 cask at ISFSI & rept of findings along w/necessary license application changes, per recent discovery of cracks in cask fuel basket.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/15. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 33098:281-33098:282.

DOCKET 72-0003 CAROLINA POWER & LIGHT CO.

8510250014 Notifies that Drawing RNT162-M-262, Sheet 1 of 2, missing from 851014 submittal. Application for withholding should be submitted for drawings identified as proprietary (ref 10CFR2.790).
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/21. UTLEY, E.E. Carolina Power & Light Co. 1p. 33191:359-33191:359.

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

- 8510020008** Staff requirements memo re 850917 affirmation/discussion & vote in Washington,DC re SECY-85-295 on review of ALAB-800 (Shoreham vital equipment) & SECY-85-178.
CHILK,S.J. Office of the Secretary of the Commission. M850917C. 85/09/30. DIRCKS,W.J. Office of the Executive Director for Operations. PLAINE,H.H. Office of the General Counsel. 1p. 32829-306-32829-306.
- 8510030088** Staff requirements memo re 850913 meeting w/ACRS in Washington,DC to discuss DOE program to handle & dispose of radwaste,NRC severe accident policy & human factor research.
CHILK,S.J. Office of the Secretary of the Commission. M850913. 85/09/25. Office of the Secretary of the Commission. 1p. 32849-329-32849-329.
- 8510030092** Staff requirements memo re 850917 meeting in Washington,DC to discuss environ qualification of electrical equipment important to safety in nuclear power plants.
CHILK,S.J. Office of the Secretary of the Commission. M850917. 85/09/25. DIRCKS,W.J. Office of the Executive Director for Operations. 1p. 32849-326-32849-326.
- 8510030229** Staff requirements memo re 850918 continued briefing in Washington,DC on 850609 event.Plant maint suggested topic of discussion for next meeting w/Nuclear Util Mgt & Human Resources Committee.
CHILK,S.J. Office of the Secretary of the Commission. M850918. 85/10/01. DIRCKS,W.J. Office of the Executive Director for Operations. 2pp. 32849-200-32849-201.
- 8510090362** Transcript of 851003 public meeting in Washington,DC re status of interpretation of App R-fire protection.Pp 1-95.
* Commissioners. 85/10/03. 98pp. 33074-273-33075-017.
- 8510090405** Transcript of 851003 affirmation/discussion & vote in Washington,DC on SECY re delegation of add rulemaking authority to EDO.Pp 1-4.
* Commissioners. 85/10/03. 8pp. 32964-327-32964-334.
- 8510110090** Transcript of 850911 meeting in Washington,DC re discussion of plant issues w/regional administrators.Pp 1-70.
* Commissioners. 85/09/11. 76pp. 33011-187-33011-262.
- 8510150278** Transcript of 851001 meeting in Washington,DC re discussion of plant issues w/regional administrators.Pp 1-81.
* Commissioners. 85/10/01. 85pp. 33033-035-33033-120.
- 8510170248** Transcript of 851010 public meeting w/ACRS in Washington,DC. Pp 1-41.Supporting documentation encl.
* Commissioners. 85/10/10. 48pp. 33045-063-33045-110.
- 8510170271** Staff requirements memo re Commission 851003 affirmation/ discussion & vote in Washington,DC approving final rule which delegates add rulemaking authority to EDO.Manual chapter revs encl.
CHILK,S.J. Office of the Secretary of the Commission. M851003B. 85/10/11. DIRCKS,W.J. Office of the Executive Director for Operations. PLAINE,H.H. Office of the General Counsel. 3pp. 33045-043-33045-045.
- 85101 0372** Transcript of Commission 851010 public meeting in Washington,DC w/util re environ qualification exemption request for facility Pp 1-88.
* Commissioners. 85/10/09. 114pp. 33048-034-33048-142.
- 8510170376** Transcript of Commission 851010 public meeting in Washington,DC re affirmation/discussion & vote.Pp 1-4.
* Commissioners. 85/10/10. 8pp. 33048-026-33048-033.
- 8510210283** Staff requirements memo re 851010 affirmation/discussion & vote in Washington,DC on SECY-85-305 re facility motions & SECY-85-324 re hearing request on denial of senior operator license.
CHILK,S.J. Office of the Secretary of the Commission. M851010B. 85/10/18. PLAINE,H.H. Office of the General Counsel. 2pp. 33079-077-33079-078.
- 8510220197** Partial response to FOIA request for documents re util 850726 briefing on readiness review program,including transcript.Documents listed in Apps A & B available in PDR. App C documents withheld (ref FOIA Exemption 5).
FELTON,J.M. Division of Rules and Records. 85/10/03. GARDE,B.P. Government Accountability Project. 5pp. 33099-251-33099-324.
- 8510220220** Staff requirements memo re util 850726 briefing on operational readiness review pilot program in Washington,DC.
CHILK,S.J. Office of the Secretary of the Commission. 850726A. 85/08/02. Office of the Secretary of the Commission. 1p. 33092-324-33099-324.
- 8510240315** Staff requirements memo re 851001 discussion of plant issues w/regional administrators in Washington,DC.Region IV requested to provide data to Commission on number of active U recovery mill licenses.
CHILK,S.J. Office of the Secretary of the Commission. M851001. 85/10/21. DIRCKS,W.J. Office of the Executive Director for Operations. 2pp. 33160-352-33160-353.
- 8510240500** Staff requirements memo re 851010 meeting w/ACRS in Washington,DC re stds proposed by EPA for disposal of high level radwaste.ACRS will submit expanded written comments on proposed EPA stds.
CHILK,S.J. Office of the Secretary of the Commission. M851010A. 85/10/21. DIRCKS,W.J. Office of the Executive Director for Operations. PLAINE,H.H. Office of the General Counsel. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 33182-158-33182-159.
- 8510240522** Staff requirements memo re 851009 meeting w/util in Washington,DC re environ qualification exemption request.
CHILK,S.J. Office of the Secretary of the Commission. M851009. 85/10/18. Office of the Secretary of the Commission. 1p. 33182-154-33182-154.
- 8510290469** Transcript of 851021 meeting w/EPA,ACRS & staff in Washington,DC on EPA stds for high level waste.Pp 1-68. Supporting documentation encl.
* Commissioners. 85/10/21. 115pp. 33259-035-33259-149.

8510300235 Transcript of Commission 851022 briefing on status of safety goal evaluation in Washington,DC.Pp 1-82.Viewgraphs encl.
* Commissioners. 85/10/22. 91pp. 33262-129-33262-219.

8510310064 Transcript of Commission 851022 meeting in Washington,DC re fitness for duty rule.Pp 1-78.Supporting documentation encl.
* Commissioners. 85/10/22. 90pp. 33277-190-33277-281.

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8509300391 Concurs w/& comments on proposed resolution for Unresolved Safety Issue A-43, "Containment Emergency Sump Performance" & Rev 1 to Reg Guide 1.82, "Water Sources..." per ACRS 305th meeting on 850912-14.
WARD,D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/09/16. DIRCKS,W.J. Office of the Executive Director for Operations. 2pp. 32777-351-32777-352.

8510010346 Transcript of ACRS Advanced Reactors Subcommittee 850925 meeting in Washington,DC.Pp 1-128.Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/09/25. 174pp. 32802-001-32802-174.

8510020309 Transcript of ACRS Class 9 Accidents Subcommittee 850927 meeting in Washington,DC.Pp 1-161.Sketches,charts,graphs & viewgraphs encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/09/27. 178pp. 32825-011-32825-188.

85100100164 Transcript of ACRS Subcommittee on Davis-Besse 851004 meeting in Oak Harbor,OH re review of course of action prior to restart of plant.Pp 1-117.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/04. 118pp. 32961-230-32961-349.

8510150092 Transcript of ACRS Subcommittee on Reliability Assurance (Valves) 851008 meeting in Washington,DC.Pp 1-300.Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/08. 400pp. 33007-001-33007-030.

8510150309 Transcript of ACRS Subcommittee on Regulatory Activities 851008 meeting in Washington,DC.Pp 1-139.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/08. 142pp. 33006-172-33006-314.

8510170089 Transcript of ACRS Subcommittees on Site Evaluation & Extreme External Phenomena 851009 meeting in Washington,DC. Pp 1-232.Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/09. 312pp. 33038-097-33039-049.

8510170248 Transcript of 851010 public meeting w/ACRS in Washington,DC. Pp 1-41.Supporting documentation encl.
* Commissioners. 85/10/10. 48pp. 33045-063-33045-110.

8510170256 Transcript of ACRS Subcommittee on Safety Philosophy, Technology & Criteria 851009 meeting in Washington,DC. Pp 1-78.Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/09. 104pp. 33039-295-33040-037.

8510180119 Transcript of ACRS 306th general meeting on 851010 in Washington,DC.Pp 1-150.Related documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. 200pp. 33054-143-33054-357.

8510180162 Transcript of ACRS 306th general meeting on 851011 in Washington,DC.Pp 1-164.Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/11. 211pp. 33055-270-33056-120.

8510180519 Summary of ACRS Subcommittee on Reactor Radiological Effects 850731 meeting in Washington,DC re INPO efforts to assure effective application of ALARA criterion in radiation protection programs.Agenda & list of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/08/02. ACRS - Advisory Committee on Reactor Safeguards. 13pp. 33077-206-33077-218.

8510180537 Proposed summary of ACRS Class 9 Accidents Subcommittee 850801 meeting in Washington,DC re NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms." List of attendees provided.
* ACRS - Advisory Committee on Reactor Safeguards. 85/08/17. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 33077-269-33077-273.

8510180538 Proposed summary of ACRS Class 9 Accidents Subcommittee 850802 meeting in Washington,DC re implementation plan for severe accident program & IDCOR plant analysis program.List of attendees provided.
* ACRS - Advisory Committee on Reactor Safeguards. 85/08/17. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 33077-274-33077-279.

8510210161 Summary of ACRS Subcommittee on Safeguards & Security 850507 meeting w/NRC,DOE & consultants in Washington,DC re sabotage protection at power & nonpower reactors.
* ACRS - Advisory Committee on Reactor Safeguards. 85/06/19. ACRS - Advisory Committee on Reactor Safeguards. 15pp. 33094-214-33094-228.

8510210164 Summary of ACRS Class 9 Accidents Subcommittee 850314 meeting w/PASNY & Risk Mgt Assoc in Washington,DC re recent source term assessment under severe accident conditions.
* ACRS - Advisory Committee on Reactor Safeguards. 85/03/31. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 33094-210-33094-213.

270 NONDOCKETED ITEMS

- 8510210198** Summary of ACRS Subcommittee on ECCS/Fluid Dynamics 850827 meeting in Washington, DC, to review status of hydrodynamic loads issue for plants w/GE Mark I-III containment & implementation proposal for resolution of USI A-43.
* ACRS - Advisory Committee on Reactor Safeguards. 85/09/06. ACRS - Advisory Committee on Reactor Safeguards. 28pp. 33094:108-33094:136.
- 8510210227** Summary of ACRS Subcommittee on GESSAR II, Reliability & Probabilistic Assessment & Safeguards & Security 850327-29 combined meetings w/Sandia, GE & BNL in Albuquerque, NM re GESSAR II future final design approvals.
* ACRS - Advisory Committee on Reactor Safeguards. 85/07/11. ACRS - Advisory Committee on Reactor Safeguards. 13pp. 33094:289-33094:301.
- 8510210246** Summary of ACRS 303rd meeting on 850711-13 in Washington, DC.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/07. ACRS - Advisory Committee on Reactor Safeguards. 200pp. 33079:089-33079:320.
- 8510220014** Summary of ACRS Subcommittee on Long Range Plan for NRC 850710-11 meetings in Washington, DC to develop info re technical issues concerning nuclear power plant safety regulation. List of attendees & meeting agenda encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/11. ACRS - Advisory Committee on Reactor Safeguards. 22pp. 33098:329-33098:352.
- 8510220020** Summary of ACRS Subcommittee on Waste Mgt & Site Evaluation 850618-19 meetings in Washington, DC re environ radiation protection stds for mgt of disposal of spent fuel & high level & transuranic radwaste.
* ACRS - Advisory Committee on Reactor Safeguards. 85/07/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098:308-33098:325.
- 8510220023** Summary of ACRS Subcommittee on Human Factors 850620 meeting in Washington, DC re problems w/operator requalification process. List of attendees & meeting agenda encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/09. ACRS - Advisory Committee on Reactor Safeguards. 25pp. 33098:283-33098:307.
- 8510220031** Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098:257-33098:274.
- 8510220385** Forwards comments & opinions re outstanding issues & unresolved questions concerning hydrogen control for facility. Supplemental info will be provided on request.
SHEPHERD, J.E. Sandia National Laboratories. 85/09/10. SAVIO, R. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 33099:149-33099:154.
- 8510220390** Summarizes ACRS ECCS Subcommittee 850827 meeting in Washington, DC re hydrodynamic loads in Mark I-III containment/resolution of USI A-43 on pump performance & feed & bleed calculations for Davis-Besse event.
TIEN, C. California, Univ. of Berkeley, CA. TIEN, C. ACRS - Advisory Committee on Reactor Safeguards. 85/09/09. BOEHNER, P.A. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 33099:147-33099:148.
- 8510240500** Staff requirements memo re 851010 meeting w/ACRS in Washington, DC re stds proposed by EPA for disposal of high level radwaste. ACRS will submit expanded written comments on proposed EPA stds.
CHILK, S.J. Office of the Secretary of the Commission. 851010A. 85/10/21. DIRCKS, W.J. Office of the Executive Director for Operations. PLAINE, H.H. Office of the General Counsel. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 33182:158-33182:159.
- 8510250242** Transcript of ACRS combined Radiological Effects & Fire Protection Subcommittees 851018 meeting in Washington, DC. Pp 1-257. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/18. 430pp. 33167:167-33168:237.
- 8510250408** Summarizes ACRS 306th meeting on 851010-12 re proposed NRC advanced reactor policy statements presented in SECY-85-279. Stated attributes in proposed policy section inconsistent. Suggested mods listed.
WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/16. PALLADINO, N.J. Commissioners. 3pp. 33172:318-33172:320.
- 8510250450** Comments on consideration of earthquakes in offsite emergency planning discussed at ACRS 306th meeting on 851010-12. Limited study of potential seismically induced effects supplied by utils would be useful.
WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/17. PALLADINO, N.J. Commissioners. 2pp. 33170:136-33170:137.
- 8510250451** Submits addl comments on EPA stds for high level radwaste repository per ACRS 306th meeting on 851010-12. Stds unreasonably restrictive. Section II, "Executive Summary" of Science Advisory Board review rept encl.
WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/16. PALLADINO, N.J. Commissioners. 10pp. 33172:343-33172:352.
- 8510250491** Submits corrected rept of ACRS 306th meeting on 851010-12 re evaluation of natural phenomena impact on offsite emergency response per NRC 850711 request. Earthquake is only event w/potential for causing severe damage.
WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/16. PALLADINO, N.J. Commissioners. 4pp. 33172:279-33172:282.
- 8510250502** Advises of proposed action on reg guides discussed at 306th meeting on 851010-12. Supports proposed Rev 2 to Reg Guide 1.105, draft reg guide, Task IC 609-5 & proposed Rev 1 to Reg Guide 1.23.
WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/15. DIRCKS, W. Office of the Executive Director for Operations. 2pp. 33171:361-33171:362.
- 8510290469** Transcript of 851021 meeting w/EPA, ACRS & staff in Washington, DC on EPA stds for high level waste. Pp 1-66. Supporting documentation encl.
* Commissioners. 85/10/21. 115pp. 33259:035-33259:149.
- 8510300022** Transcript of ACRS Subcommittees on Waste Mgt & Metal Components 851024 meeting in Washington, DC. Pp 1-246. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/24. 400pp. 33248:076-33249:214.

- 8510310288** Transcript of ACRS Subcommittees on Waste Mgt & Metal Components 851025 meeting in Washington, DC. Pp 247-488. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 85/10/25. 275pp. 33265:159-33266:087.

ADYCM NRC ADVISORY COMMITTEE

- 8510070271** Confirms appearance at Advisory Panel for Decontamination of TMI-2 851016 meeting in Lancaster, PA to present results of cancer mortality & morbidity studies. List of panel members, map & tentative agenda encl.
MASNIK, M.T. Advisory Council for Decontamination of TMI Unit 2. 85/10/03. MULLER, H.A. Pennsylvania, Commonwealth of. 5pp. 32901:215-32901:219.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108:264-33109:088.
- 8510230142** Forwards Press Release 85-52 re Ad Hoc Advisory Committee for Review of Enforcement Policy meetings on 850410-11 & 30-0501 in Bethesda, MD concerning study of effectiveness of NRC current enforcement program.
KAMMERER, C. Office of Congressional Affairs. 85/04/01. UDALL, M. House of Rep., Interior & Insular Affairs. SIMPSON, R. MARKEY House of Rep. 2pp. 33109:063-33109:064.
- 8510230346** Forwards Press Release 85-3 re NRC Ad Hoc Advisory Committee for Review of Enforcement Policy request for public comments on enforcement policy.
KAMMERER, C. Office of Congressional Affairs. 85/01/09. OTTINGER, R.L. House of Rep., Energy & Commerce. SIMPSON, R. UDALL House of Rep. 3pp. 33109:162-33109:164.
- 8510290178** Transcript of Advisory Panel on Decontamination of TMI-2 851016 meeting in Lancaster, PA. Pp 1-132.
* Advisory Council for Decontamination of TMI Unit 2. 85/10/16. 136pp. 33230:186-33230:322.

COMMISSION NRC COMMISSIONERS

- 8509170390** Forwards Final Case Study Rept AEOD/C502, "Overpressurization of ECCS in BWRs." Rept identifies & evaluates eight events involving actual or potential overpressurization of ECCS in BWRs.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/09/11. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 1p. 32646:180-32646:218.
- 8510010064** Responds to FOIA request for correspondence NRC received from Barnes, Byron, Mathias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDF. Forwards documents listed on app.
FELTON, J.M. Division of Rules and Records. 85/09/04. DEZUBE, D. Montgomery County Sentinel. 3pp. 32831:087-32831:196.
- 8504100552** Responds to 850214 ltr forwarding J Zombro ltr re periodic checks of personnel for alcohol & drug abuse at nuclear facilities. Commission considering policy statement on issue.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/03/28. BYRON, B.B. House of Rep. 1p. 32831:145-32831:179.
- 8510010172** Forwards Washington Post 840712 article entitled, "NRC Engineer Resigns From Diablo Task Force." Info requested on NRC role in safety investigations.
BARNES, M.D. House of Rep. 84/07/12. PALLADINO, N.J. Commissioners. 2pp. 32831:121-32831:122.
- 8510010334** Forwards J Zombro ltr re need for periodic checks of personnel for alcohol & drug abuse at nuclear facilities. Response requested.
BYRON, B.B. House of Rep. 85/02/14. PALLADINO, N. Commissioners. 3pp. 32831:142-32831:144.
- 8510010344** Forwards correspondence received from CF Jones re concerns about re-start of TMI-1. Response requested.
SARBANES, P.S. Senate. 85/03/25. PALLADINO, N.J. Commissioners. 2pp. 32831:180-32831:181.
- 8510010395** Informs of govt-owned bldg in Germantown, MD as possible location for office of NRC. Bldg houses 1,000 employees of DOE & has capacity to house 2,600 people.
BYRON, B.B. House of Rep. 85/05/07. PALLADINO, N.J. Commissioners. 1p. 32831:183-32831:183.
- 8510010418** Forwards VR Satern 850508 ltr re federal agency handling of requests under FOIA & GAO handling of bid protests. Review & advisement requested.
BARNES, M.D. House of Rep. 85/05/24. PALLADINO, N.J. Commissioners. 2pp. 32831:189-32831:190.
- 8510010443** Forwards V Satern ltr outlining concerns re bill received from NRC for FOIA request. Review & response to matter requested.
SARBANES, P.S. Senate. 85/06/26. PALLADINO, N.J. Commissioners. 1p. 32831:193-32831:193.
- 8510010506** Forwards insert of Page 39, Line 827 of 850417 hearing record on NRC budget insert provides addl views on estimate of crude cumulative probability of core melt accident.
KAMMERER, C. Office of Congressional Affairs. 85/09/16. MARKEY, E. House of Rep., Energy & Commerce. 7pp. 32832:060-32832:116.
- 8510010512** Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review.
PALLADINO, N.J. Commissioners. 85/09/17. MARKEY, E. House of Rep., Energy & Commerce. 3pp. 32832:067-32832:069.

-8510010525 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review. PALLADINO, N.J. Commissioners. 85/09/17. DOWNEY, T.J. House of Rep. 3pp. 32832-070-32832-072.

-8510010532 Responds to 850805 request for explanation of basis of Commission position change re conduct of emergency exercise at facility. Commission position has not changed during course of facility licensing review. PALLADINO, N.J. Commissioners. 85/09/17. MRAZEK, R.J. House of Rep. 3pp. 32832-073-32832-075.

-8510010536 Discusses NRC 850620 request that FEMA conduct emergency preparedness exercise at facility. No useful purpose served by exercise that fails to include full & active participation of state & local govts. MRAZEK, R.J., DOWNEY, T.J. House of Rep. MARKEY, E.J. House of Rep., Energy & Commerce. 85/08/05. PALLADINO, N.J. Commissioners. 3pp. 32832-076-32832-078.

-8510010538 Ack receipt of 850826 ltr re agreement w/NRC to allow State of IA to assume regulatory authority over certain sources of ionizing radiation. Assessment of proposal in progress & will be issued for comment. PALLADINO, N.J. Commissioners. 85/09/18. BRANSTAD, T.E. Iowa, State of. 1p. 32832-079-32832-079.

-8510010544 Requests agreement w/NRC to allow State of IA to assume regulatory authority for certain radioactive materials currently under NRC jurisdiction. Formal agreement signing ceremony unnecessary. BRANSTAD, T.E. Iowa, State of. 85/08/22. PALLADINO, N.J. Commissioners. 9pp. 32832-080-32832-088.

-8510010546 Urges Congress to provide necessary funding for nonpower reactors licensed by NRC to convert from high to low enriched U fuel. Commission currently considering final rule requiring conversion. PALLADINO, N.J. Commissioners. 85/09/18. HATFIELD, M.O. Senate, Appropriations. 2pp. 32832-089-32832-090.

-8510010550 Urges Congress to provide necessary funding for nonpower reactors licensed by NRC to convert from high to low enriched U fuel. Commission currently considering final rule requiring conversion. PALLADINO, N.J. Commissioners. 85/09/18. UDALL, M.K. House of Rep., Interior & Insular Affairs. 2pp. 32832-091-32832-092.

-8510010554 Urges Congress to provide necessary funding for nonpower reactors licensed by NRC to convert from high to low enriched U fuel. Commission currently considering final rule requiring conversion. PALLADINO, N.J. Commissioners. 85/09/18. MARKEY, E.J. House of Rep., Energy & Commerce. 2pp. 32832-093-32832-094.

-8510010558 Urges Congress to provide necessary funding for nonpower reactors licensed by NRC to convert from high to low enriched U fuel. Commission currently considering final rule requiring conversion. PALLADINO, N.J. Commissioners. 85/09/18. BEVILL, T. House of Rep., Appropriations. 2pp. 32832-095-32832-096.

-8510010561 Urges Congress to provide necessary funding for nonpower reactors licensed by NRC to convert from high to low enriched U fuel. Commission currently considering final rule requiring conversion. PALLADINO, N.J. Commissioners. 85/09/18. SIMPSON, A. Senate, Environment & Public Works. 2pp. 32832-097-32832-098.

-8510010566 Supports reduced enrichment for research & test reactors program. Urges NRC to process w/conversion rule to reduce risk of theft or diversion of weapons-grade materials. MARKEY, E.J. House of Rep., Energy & Commerce. SLATTERY, J., ECKART, D.E. House of Rep. 85/06/17. PALLADINO, N.J. Commissioners. 3pp. 32832-099-32832-103.

-8510010569 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32832-104-32832-104.

-8510010570 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. BOWSER, C.A. General Accounting Office. 1p. 32832-105-32832-105.

-8510010572 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. WRIGHT, J. Office of Management & Budget. 1p. 32832-106-32832-106.

-8510010578 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. UDALL, M.K. House of Rep., Interior & Insular Affairs. 1p. 32832-107-32832-107.

-8510010585 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accidents." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. SIMPSON, A. Senate, Environment & Public Works. 1p. 32832-108-32832-108.

-8510010588 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. BROOKS, J. House of Rep., Government Operations. 1p. 32832-109-32832-109.

-8510010590 Forwards responses to GAO rept, "NRC Should Rept on Progress in Implementing Lessons Learned from TMI Accident." W/o encl. ROBERTS, T.M. Commissioners. 85/09/19. ROTH, W.V. Senate, Governmental Affairs. BROOKS, J. House of Rep., Government Operations. SIMPSON, A. Senate, Environment & Public Works. 6pp. 32832-110-32832-116.

8510040063 Weekly info rept for wk ending 850927. REHM, T.A. Office of the Executive Director for Operations. 85/10/02. 51pp. 32860-191-32860-242.

8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available. ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905-053-32911-216.

-8007090278 Forwards NUREG-0667, "Transient Response of B&W-Designed Reactors." Evaluation requested. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/05/21. MATTSON, R.J. Division of Safety Technology. 2pp. 32906-184-32906-185.

-8010010843 Summarizes status of util intentions re add diverse powered auxiliary feedwater pump & recommends reserved judgment pending proposal submittal. GARNER, D. Operating Reactors Branch 4. 80/09/11. NOVAK, T.M. Assistant Director for Operating Reactors. 2pp. 32907-103-32907-108.

-8010270109 Forwards topical rept evaluation of NUREG-0677, "Transient Response of B&W Designed Reactors," in response to 800521 memo. MATTSON, R.J. Division of Safety Technology. 80/08/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 42pp. 32906-186-32906-226.

-8103190865 Forwards evaluation of IE insp program & assessment of regional implementation program. Div of Program Development & Appraisal will review concerns re insp program. MOSELEY, N.C. Division of Program Development & Appraisal. 81/03/03. STELLO, V. Director's Office, Office of Inspection and Enforcement. 14pp. 32911-152-32911-155.

-8108060119 Recommends that reliability criterion for auxiliary feedwater sys be added to SRP Section 10.4.9. MURLEY, T.E. Division of Safety Technology. 81/06/29. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 32907-158-32907-199.

-8302090513 Forwards evaluation of reliability study for auxiliary feedwater sys (AFS), based on BNL reliability analysis of upgraded AFS. THADANI, A. Reliability & Risk Assessment Branch. 83/02/04. PARR, O. Auxiliary Systems Branch. 7pp. 32907-201-32907-216.

-8308310389 Requests comments on encl draft generic requirements review package re proposed upgrading of auxiliary feedwater sys. MATTSON, R.J. Division of Systems Integration (post 811005). 83/08/22. EISENHUT, D.G. Division of Licensing. 1p. 32907-148-32907-148.

-8309060463 Forwards SER on TMI Action Item I.E.1.1, "Auxiliary Feedwater Sys Evaluation." Evaluation closes five open items identified in 820426 status rept. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. TAC 51964. 83/08/29. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32908-019-32908-043.

-8310270010 Forwards info re initiator frequency for loss of main feedwater transient/auxiliary feedwater sys unavailability & radioactive release for each plant listed in CRGR package, per 830916 meeting request. THADANI, A.C. Reliability & Risk Assessment Branch. 83/10/17. PARR, O. Auxiliary Systems Branch. 3pp. 32908-044-32908-052.

-8311040213 Forwards comments on draft CRGR package re requirements for upgrading auxiliary feedwater sys in operating plants. Proposed action should be deferred until coordination w/Unresolved Safety Issue A-45 is decided. SPEIS, T.P. Division of Safety Technology. 83/10/25. MATTSON, R.J. Division of Systems Integration (post 811005). 8pp. 32908-053-32908-068.

-8311290156 Comments on util performance & improvement program supporting util 831028 response to NRC 831017 ltr. Util safety responsive & safety conscious. RICE, C.M. LRS Consultants. 83/11/21. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 32906-227-32906-227.

-8311290219 Responds to concerns expressed in 831017 ltr re util performance & improvement program in connection w/831005 s/a visit & meeting. WILLIAMSON, J.P. Toledo Edison Co. 83/11/28. GILINSKY, V. Commissioners. 3pp. 32907-028-32907-030.

-8311290224 Expresses concern re util performance in connection w/831005 site visit & meeting. GILINSKY, V. Commissioners. 83/10/17. WILLIAMSON, J. Toledo Edison Co. 1p. 32911-214-32911-216.

-8312010439 Provides evaluation of licensee 811231 auxiliary feedwater reliability study performed by BNL. Unavailability of auxiliary feedwater sys exceeds numerical criterion presented in SRP. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 83/11/16. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32908-069-32908-076.

-8312210021 Forwards comments on draft CRGR package re auxiliary feedwater sys reliability per 830822 memo & TMI Action Plan Item I.E.1.1. EISENHUT, D.G. Division of Licensing. 83/12/07. MATTSON, R.J. Division of Systems Integration (post 811005). 3pp. 32908-077-32908-079.

-8312230206 Forwards IE Insp Rept 50-346/83-23 describing meeting re regulatory improvement program. DIRCKS, W.J. Office of the Executive Director for Operations. 83/12/12. GILINSKY, V. Commissioners. 1p. 32908-316-32909-045.

-8312230212 Forwards proposed transmittal memo & insp rept re regulatory improvement program. W/o encl. DAVIS, A.B. Region 3, Office of Director. 83/12/07. REHM, T.A. Office of the Executive Director for Operations. 2pp. 32907-020-32907-027.

-84/1270550 Forwards add info re auxiliary feedwater sys CRGR package, in response to 831017 memo. THADANI, A.C. Reliability & Risk Assessment Branch. 84/01/16. PARR, O. Auxiliary Systems Branch. 11pp. 32908-080-32908-117.

-8404170570 Encourages NRR preparation of CRGR package on safety-related electric auxiliary feedwater pump at facility interest heightened by R40302 stuck open safety valve event. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/04/09. EISENHUT, D.G. Division of Licensing. 1p. 32908-118-32908-118.

272 NONDOCKETED ITEMS

- 8405010072 Forwards comparison of emergency feedwater sys at TMI-1 & other B&W operating plants to acceptance criteria of SRP Section 10.4.9. Schedules established for implementation of necessary mods at each B&W plant.
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. GL-81-14. 84/04/17. LAINAS, G.C. Assistant Director for Operating Reactors. 13pp. 32908:119-32908:197.
- 8406250404 Provides status of third auxiliary feedwater pump & diesel generator. Util initiated PRA study of auxiliary feedwater sys (AFS). Reliability of AFS in low range does not meet SRP Section 10.4.9 criteria.
DE AGAZIO, A. Operating Reactors Branch 4. 84/06/20. LAINAS, G.C. Assistant Director for Operating Reactors. 2pp. 32909:137-32909:240.
- 8407130274 Forwards IE Mgt Meeting Rept 50-346/81-03 on 810303 re Performance Appraisal Section insp on 801027-31, 1101, 03-07 & 17-21, notices of violation & deviation & related info.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 81/05/01. MOSELEY, N.C. Division of Program Development & Appraisal. 1p. 32911:156-32911:173.
- 8407130282 Forwards IE Mgt Meeting Rept 50-346/81-03 & notices of violation & deviation re Performance Appraisal Section Insp Rept 50-346/80-03 on 801027-31, 1101, 03-07 & 17-21. App 8 withheld (ref 10CFR2.790).
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/17. CROUSE, R.P. Toledo Edison Co. 2pp. 32911:157-32911:166.
- 8407130287 Notice of violation from insp on 801027-31, 1101, 03-07 & 17-21.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/17. 5pp. 32911:159-32911:163.
- 8407130313 Notice of deviation from insp on 801027-31, 1101, 03-07 & 17-21.
* Region 3, Chicago, Office of the Director. 81/04/17. 1p. 32911:164-32911:164.
- 8407130317 IE Mgt Meeting Rept 50-346/81-03 on 810303. Major areas discussed: Performance Appraisal Section Insp Rept 50-346/80-03 on 801027-31, 1101, 03-07 & 17-21. Portions withheld (ref 10CFR2.790).
REYES, L.A., ROGERS, W.G., WARNICK, R.F. Region 3, Chicago, Office of the Director. 81/04/17. 4pp. 32911:165-32911:168.
- 8407130320 Provides info in response to 810330 memo re Performance Appraisal Section 801027-31, 801101, 03-07 & 17-21 insp.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 81/04/22. SNIEZEK, J.H. Region 3, Chicago, Office of the Director. 2pp. 32911:169-32911:173.
- 8407250135 Requests special meeting w/ util re diversity in auxiliary feedwater pump drives compliance w/ TMI Action Item I.I.E.1.1, "Auxiliary Feedwater Sys."
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 84/07/18. LAINAS, G.C. Assistant Director for Operating Reactors. 2pp. 32908:198-32908:199.
- 8410110596 Recommends closeout of Generic Issue/TMI Action Item I.I.E.5.2 re transient response of B&W designed reactors. High priority items implemented. Implementation of low priority items unnecessary. Concurrence requested. Status list encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 84/09/28. DIRCKS, W.J. Office of the Executive Director for Operations. 4pp. 32908:200-32908:203.
- 8410150611 Discusses backfit issue on several serious safety concerns re auxiliary feedwater sys design, including lack of diverse pump drive & high unreliability of sys. Addition of electric motor driven pump would improve reliability.
DE AGAZIO, A. Operating Reactors Branch 4. 84/10/09. LAINAS, G.C. Assistant Director for Operating Reactors. 3pp. 32908:204-32908:219.
- 8411210152 Forwards 22 potential enforcement findings referenced as unresolved items in Insp Rept 50-346/84-19. Requests followup on findings assigned preliminary classification. Severity Level IV violations due to potential for reclassification.
GRACE, J.N. Division of QA, Safeguards & Insp Programs (830103-850212). 84/11/15. NORELIUS, C.E. Region 3, Office of Director. 28pp. 32909:275-32909:315.
- 8411280233 Forwards response to O Parr 840718 request re CRGR package on auxiliary feedwater sys. Uncertainties of probability values noted & should be considered in regulatory analysis & decision-making process.
THADANI, A. Reliability & Risk Assessment Branch. 84/11/09. PARR, O.D. Auxiliary Systems Branch. 14pp. 32910:021-32910:034.
- 8411290581 Forwards Auxiliary Sys Branch SER input re continued operation of start-up feedwater pump until installation of new sys completed. Limited interim use of existing start-up feedwater pump acceptable. SALP evaluation also encl.
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. TAC 57023. 84/11/20. LAINAS, G.C. Assistant Director for Operating Reactors. 1p. 32910:035-32910:046.
- 8501030255 Extends response date for Insp Rept 50-346/84-15 to 850115.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. EA-84-095. 84/12/26. WILLIAMS, J.P. Toledo Edison Co. 1p. 32909:241-32909:274.
- 8502190399 Responds to 850102 memo recommending close monitoring of training program as test case of INPO accreditation program. SALP rept of 841204 indicates numerous training problems. Add review of improvements will be conducted.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/02/12. ASSELSTINE, Commissioners. 3pp. 32909:066-32909:068.
- 8502190411 Suggests that facility training program be closely monitored as test case of INPO accreditation program.
ASSELSTINE, J.K. Commissioners. 85/01/02. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 32910:019-32910:020.
- 8502190413 Informs that Commission wishes to include listed elements in policy statement on training. General course re enforcement action described.
CHILK, S.J. Office of the Secretary of the Commission. 84/11/28. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 32909:316-32909:318.
- 8503220113 Discusses licensee 851121 ltr re conceptual design for adding motor driven startup feedwater pump (SUFPP). Design mods listed. Licensee proposed Tech Specs for SUFPP sys operability requested.
PARR, O.D. Auxiliary Systems Branch. TAC 55581. 85/03/12. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32910:047-32910:181.
- 8504030276 Informs that cooperation & support provided during recent mgt visit appreciated. Discussions & facility tour very informative.
BRACH, E.W. Regional Operations & Generic Requirements. 85/03/25. ROGERS, W.G. NRC - No Detailed Affiliation Given. 1p. 32911:174-32911:175.
- 8506260560 Forwards chronology re third diverse powered auxiliary feedwater pump, per H Denton 850613 request.
RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 85/06/18. LAINAS, G.C. Assistant Director for Operating Reactors. 5pp. 32910:260-32910:264.
- 8506260595 Forwards Congressman Markey 850617 ltr re facility 850609 incident. Answers to assigned questions requested by C.O.B. 850621. Breakdown of responsibility for each question & response format also encl.
THOMPSON, H.L. Division of Licensing. 85/06/19. KEPPLER, J. Region 3, Office of Director. 2pp. 32910:265-32910:273.
- 8506260600 Expresses concern re 850609 incident at facility. Requests briefing on 850617 to subcommittee re facility incident & related matters.
MARKEY, E.J. House of Rep., Energy & Commerce. 85/06/17. PALLADINO, N.J. Commissioners. 9pp. 32910:267-32910:273.
- 8506260705 Responds to 850617 verbal request for estimate of mean annual population dose from feedwater interruptions. Core melt caused by loss-of-feedwater could result in conditional mean person-rem of 12,000 w/ range of 3,000-20,000.
HULMAN, L.G. Accident Evaluation Branch. 85/06/18. MINNERS, W. Safety Program Evaluation Branch. 1p. 32910:259-32910:259.
- 8506270129 Forwards table of B&W plants comparing selected TMI actions from NUREG-1066. Incomplete TMI items for facility listed per NUREG-0737. NUREG-0737 & Suppl 1 active items re post-implementation reviews also listed.
THOMPSON, H.L. Division of Licensing. 85/06/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32910:274-32910:279.
- 8510070099 Provides recommendation on NUREG-0611 auxiliary feedwater reliability study re addition of third, qualified, motor driven emergency feedwater pump.
ROWSOME, F.H. Division of Safety Technology. 83/03/01. PARR, O., THADANI, A., TSAO, J. NRC - No Detailed Affiliation Given. 1p. 32907:200-32907:200.
- 8510070102 Forwards revised responses to questions in Congressman Markey 850617 ltr re 850609 incident at facility. Rept of task force investigation of incident will be completed & made available by 850724.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/07/05. PALLADINO, Commissioners. 103pp. 32905:054-32905:157.
- 8510070106 Forwards info to suppl 831216 submittal, including purchase order & 1983 annual fire protection & loss prevention program insp & audit rept.
HAVERLY, J.S. Toledo Edison Co. NLL #83-013. 83/12/20. LITTLE, W.S. Region 3, Office of Director. 19pp. 32906:226-32906:246.
- 8510070108 Forwards JP Williamson 850204 ltr re SALP response. Views on meeting w/ util will be discussed during next trip.
KEPPLER, J.G. Region 3, Office of Director. 85/02/08. DIRCKS, W.J. Office of the Executive Director for Operations. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 1p. 32909:046-32909:064.
- 8510070112 Forwards Dircks 850212 memo to Commissioner Assestine suggesting that NRC closely monitor training program.
KEPPLER, J.G. Region 3, Office of Director. 85/02/19. NORELIUS, C.E. NRC - No Detailed Affiliation Given. 1p. 32909:065-32909:065.
- 8510070115 Forwards draft documents proposing civil penalty action under general policy & procedure for NRC enforcement actions, submitted for review & concurrence.
SCHULTZ, W.H. Region 3, Office of Director. 85/06/18. AXELRAD, J.A. Enforcement Staff. 11pp. 32909:319-32909:359.
- 8510070117 "Annual Fire Protection Audit of Davis-Besse Nuclear Power Station Unit 1."
* Professional Loss Control, Inc. 81/07/31. 31pp. 32906:247-32906:356.
- 8510070120 Forwards V Stello revised proposed memo to Commissioner Assestine re regulatory performance based on V Stello 850605 comments.
KEPPLER, J.G. Region 3, Office of Director. 85/06/11. DIRCKS, W.J. Office of the Executive Director for Operations. 9pp. 32909:360-32910:008.
- 8510070123 Forwards operating procedures modified re 790517 order. Matrix itemizing procedures also encl.
ROE, L.E. Toledo Edison Co. 509. 79/05/23. RIED, R.N. Operating Reactors Branch 4. 4pp. 32905:334-32905:337.
- 8510070125 Forwards requested info & documentation summary re effort put forth to meet requirements of 10CFR50.48 & App R to 10CFR50 & Kaowool wraps, committed to in 820429 component cooling water pump room exemption request.
CROUSE, R.P. Toledo Edison Co. 83/12/16. KEPPLER, J.G. Region 3, Office of Director. 22pp. 32906:357-32907:018.
- 8510070130 Forwards WJ Dircks draft memo to Commissioner Assestine, per request to provide update on status of regulatory performance.
KEPPLER, J.G. Region 3, Office of Director. 85/06/05. DIRCKS, W.J. Office of the Executive Director for Operations. 10pp. 32910:009-32910:018.
- 8510070131 Trip rept of 850207-08 site visit re status of licensee performance enhancement program & status of action plan being used to improve overall training effort.
SHAFER, W.D. Region 3, Office of Director. 85/02/26. NORELIUS, C.E. NRC - No Detailed Affiliation Given. 65pp. 32909:069-32909:133.
- 8510070133 Responds to 790508 request for info re overall reliability of auxiliary feedwater (AFW) sys w/ regard to operating history & design improvements & 790504 commitment to verify adequacy of AFW sys capacity.
ROE, L.E. Toledo Edison Co. 508. 79/05/23. RIED, R.N. Operating Reactors Branch 4. 15pp. 32905:338-32906:183.
- 8510070138 Informs of regulatory performance in connection w/ plant & NRC actions to improve performance. Special attention will be devoted to licensee effectiveness in strengthening training & improving control room behavior.
KEPPLER, J.G. Region 3, Office of Director. 85/01/09. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 32909:134-32909:135.

- 8510070142 Trip rept of 850315 site visit re presentation of licenses to senior reactor operators & reactor operators. Subs discussed during visit stated. DAVIS, A.B. Region 3, Office of Director. 85/03/15. KEPLER, J.G. Region 3, Office of Director. 1p. 32909:136-32909:136.
- 8510070155 Forwards notes & action items representing agreements w/utl based on 831104 meeting. Response requested by 831114. DAVIS, A.B. Region 3, Office of Director. 83/11/07. SHAFFER, W. NRC - No Detailed Affiliation Given. 2pp. 32907:031-32907:034.
- 8510070161 Forwards info re status of performance enhancement program. Integrated implementation schedule expected to be developed by 840901. PETERS, R.F. Toledo Edison Co. 84/07/20. SHAFFER, W.D. Region 3, Office of Director. 38pp. 32907:035-32907:072.
- 8510070167 Trip rept of 840703 site visit re training organization & programs. Program not implemented due to lack of senior mgt support. SHAFFER, W.D. Region 3, Office of Director. 84/07/05. NORELIUS, C.E. NRC - No Detailed Affiliation Given. 7pp. 32907:073-32907:102.
- 8510070181 Discusses NUREG-0667, "Transient Response of B&W Designed Reactors," implementation plan. Table of assignments & required actions encl. EISENHUT, D.G. Division of Licensing. 81/06/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32907:139-32907:148.
- 8510070184 Submits daily highlight. On 850609, reactor tripped when RCS temp & pressure increased due to Main Feedwater Pump 1 trip. Sequence of events provided. DE AGAZIO, A. Operating Reactors Branch 4. 85/06/11. DENTON, H.R. EISENHUT, D., EDISON, G. NRC - No Detailed Affiliation Given. 3pp. 32910:182-32910:258.
- 8510070192 Provides daily staff notes for 850611. Final rule amending 10CFR9 approved. Events at facilities discussed. DRICKS, W.J. Office of the Executive Director for Operations. 85/06/12. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 21pp. 32911:022-32911:081.
- 8510070198 Forwards proposed requirement for actions to be taken by operating PWR licensees to further upgrade auxiliary feedwater sys. Recommendations requested within 2 wks. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/07/17. STELLO, V. Regional Operations & Generic Requirements. 8pp. 32907:149-32907:156.
- 8510070202 Forwards updated status of ten areas of corrective actions to improve mgt controls & plant operation. TAMBUNG, T.N. Region 3, Chicago, Office of the Director. 80/02/13. HEISHMAN, R.F. Region 3, Chicago, Office of the Director. 5pp. 32911:082-32911:095.
- 8510070214 Forwards description of 800419 event. Probably caused by breaker bumped by const workers in area. Sequence of events & summary of physical security insps encl. KEPLER, J.G. Region 3, Chicago, Office of the Director. 80/04/23. MOSELEY, N.C. Division of Reactor Operations Inspections. 10pp. 32911:096-32911:131.
- 8510070220 Provides observations during recent Performance Appraisal Branch insp. KEPLER, J.G. Region 3, Chicago, Office of the Director. 80/12/08. HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 1p. 32911:132-32911:141.
- 8510070227 Discusses establishment of Region III study group due to 850609 loss of feedwater transient. Based on expanded roll of group, no time limit placed on longevity. Related info encl. NORELIUS, C.E. Region 3, Office of Director. 85/06/21. KEPLER, J.G. Region 3, Office of Director. 152pp. 32910:280-32911:021.
- 8510070262 Confirms discussion between T Tumbung, J. Smith & L. Reyes on 810706-08. As result of evaluations of inadvertent 810624 reactor trip, listed corrective action plans initiated. CROUSE, R.P. Toledo Edison Co. 1-211. 81/07/08. KEPLER, J.G. Region 3, Chicago, Office of the Director (81/03/01). 4pp. 32911:176-32911:186.
- 8510070269 Ack importance of recent insp finding of busted water storage tank over-temp condition by L. Reyes. Timely identification of safety-related concerns beneficial in reaffirming on broad level resident insp program. KEPLER, J.G. Region 3, Chicago, Office of the Director (81/03/01). 82/01/20. SPESSARD, R.L. Division of Resident & Project Inspection. 1p. 32911:187-32911:194.
- 8510070273 Discusses 850612 3, 13 telcons w/R Udell re incident on 850609. Facility only PWR which cannot be adequately protected w/HPCI alone. DAVIS, A.B. Region 3, Office of Director. 85/06/17. KEPLER, J.G. Region 3, Office of Director. 2pp. 32911:195-32911:208.
- 8510070278 Requests assistance in inspecting QA program on priority basis since QA modules more than 6 months overdue. Licensee auditing staff cannot meet audit workload. NORELIUS, C.E. Region 3, Office of Director. 83/07/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32911:209-32911:213.
- 8510070516 Forwards documents re NRC response to 850609 Davis-Besse incident, per 850920 request. IE & Region III documents will be forwarded upon receipt. Documents should be withheld from public disclosure, pending review completed on 851001. PALLADINO, N.J. Commissioners. 85/09/30. MARKEY, E. House of Rep., Energy & Commerce. 4pp. 32901:026-32901:029.
- 8510070518 Forwards documents re Representative Markey 850920 request. Region III & IE supporting documents will be forwarded upon receipt. Documents also responsive to Udell 850919 request w/exception of rept of maint insp available in late Oct. REHM, T.A. Office of the Executive Director for Operations. 85/09/26. FAY, E. Office of Congressional Affairs. 8pp. 32901:030-32901:037.
- 8510070504 Forwards matl applicable to Representative Markey 850930 request, including only documents in NRR files. Transcript of Commission 850918 & 19 briefings by utl & Chairman Palladino 850828 memo unavailable. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/09/25. REHM, T. Office of the Executive Director for Operations. 3pp. 32901:020-32901:037.
- 8510070508 Discusses Udell requests for matls in preparation for Markey Subcommittee hearing, including project manager responses re operating nuclear power plants where corrective action outstanding for extended period. DELMEDICO, J. NRC - No Detailed Affiliation Given. 85/09/19. REHM, T. NRC - No Detailed Affiliation Given. 2pp. 32901:023-32901:024.
- 8510070511 Requests listed documents in preparation for Subcommittee on Energy Conservation & Power upcoming hearing on Davis-Besse incident, including all documents generated in response to WJ Dirks 850905 memo to Commission. MARKEY, E.J. House of Rep., Energy & Commerce. 85/09/20. PALLADINO, N.J. Commissioners. 1p. 32901:025-32901:025.
- 8510070380 Responds to 850823 request for investigation into 850702 premature criticality event. Investigation expected to be completed within 60 days. Rept will be forwarded. Briefing can be arranged by request. PALLADINO, N.J. Commissioners. 85/10/01. DINGELL, J.D. House of Rep., Energy & Commerce. 1p. 33011:301-33011:304.
- 8510090385 Requests investigation of operational procedures & credentials of employees carrying out procedures at Fermi 2 on 850702. Ltr from Monroe County Commissioners, describing events, encl. DINGELL, J.D. House of Rep., Energy & Commerce. 85/08/23. PALLADINO, N.J. Commissioners. 3pp. 33011:302-33011:304.
- 8510090447 Responds to 850429 ltr re emergency preparedness at nuclear power plants. Redistribution of potassium iodide pills to public not recommended. Framework for decisionmaking or source-term considerations should be complete by end of yr. PALLADINO, N.J. Commissioners. 85/10/01. WILSON, R. Harvard Univ., Cambridge, MA. 1p. 32966:341-32966:352.
- 8507050455 Responds to 841115 request re proposed draft federal policy statement on distribution & use of potassium iodide. Commission approved 850326 version. Encl draft should be distributed to state & local govts. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/06/24. KRIMM, R.W. Federal Emergency Management Agency. 9pp. 32966:342-32966:350.
- 8510090454 Offers personal comments on emergency preparedness. Iodine pills should not be distributed. Emergency planning regulations should be reviewed. Emergency planning zone should be only 2 miles. WILSON, R. American Physical Society. 85/04/29. PALLADINO, N.J. Commissioners. 2pp. 32966:351-32966:352.
- 8510090476 Responds to questions raised re NRC views on proposed US/Peoples Republic of China agreement for cooperation, per 850830 request. Since unclassified info requested, NRC reply limited. PALLADINO, N.J. Commissioners. 85/10/02. PROXMIER, W. Senate, Banking, Housing & Urban Affairs. 5pp. 32966:201-32966:207.
- 8510090486 Requests NRC review of proposed US/Peoples Republic of China agreement for cooperation on peaceful uses of nuclear energy. PROXMIER, W. Senate, Banking, Housing & Urban Affairs. 85/08/30. PALLADINO, N.J. Commissioners. 2pp. 32966:206-32966:207.
- 8510110119 Comments on proposed legislation which would require NRC to assess & collect annual user fees from NRC licensees, per 850923 request. Ethics of NRC financially benefiting from NRC enforcement actions questioned. PALLADINO, N.J. Commissioners. 85/10/01. SIMPSON, A.K. Senate, Environment & Public Works. 2pp. 33012:109-33012:119.
- 8510110124 Requests comments on encl proposed legislation requiring NRC to assess & collect annual user fees from NRC licensees. Comments due by 850930. SIMPSON, A.K. Senate, Environment & Public Works. 85/09/23. PALLADINO, N.J. Commissioners. 9pp. 33012:111-33012:119.
- 8510150131 Weekly info rept for wk ending 851004. REHM, T.A. Office of the Executive Director for Operations. 85/10/09. 51pp. 33031:035-33031:085.
- 8510150198 Responds to 850909 ltr urging NRC to take necessary steps to improve safety & reliability at plant, based on 850609 loss of feedwater event. NRC reviewing utl submittal & wk issue SER. PALLADINO, N.J. Commissioners. 85/10/08. CELESTE, R.F. Ohio, State of. 6pp. 33030:212-33030:219.
- 8510150206 Expresses concerns re 850609 event at plant which resulted in loss of all feedwater. Deficiencies cited must be fully corrected before plant returns to operation. NRC urged to take necessary steps. CELESTE, R.F. Ohio, State of. 85/09/08. PALLADINO, N.J. Commissioners. 2pp. 33030:218-33030:219.
- 8510170425 Forwards FR notice re issued & proposed amends authorized by Public Law 97-415, allowing NRC to issue & make immediately effective any amend to OL involving NSHC, W/o encl. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/02. SIMPSON, A. Senate, Environment & Public Works. UDALL, M.K. House of Rep., Interior & Insular Affairs. MARKEY, E.J. House of Rep., Energy & Commerce. 2pp. 33047:219-33047:220.
- 8510180528 Weekly info rept for wk ending 851011. REHM, T.A. Office of the Executive Director for Operations. 85/10/17. 41pp. 33077:226-33077:266.
- 8510220432 Responds to lecture slides described in 850830 ltr. After review completed, Commission will respond to last paragraph of 850830 ltr. PALLADINO, N.J. Commissioners. 85/10/10. MARKEY, E.J. House of Rep., Energy & Commerce. 2pp. 33099:106-33099:146.
- 8510220434 Provides review of certain matls used during training course presented in Fall 1983. CLARK, P.R. General Public Utilities Corp. - GPU Service Corp. 0980K. 85/09/03. PALLADINO, N.J. Commissioners. 14pp. 33099:133-33099:146.
- 8510280463 Weekly info rept for wk ending 851018. REHM, T.A. Office of the Executive Director for Operations. 85/10/24. 41pp. 33228:060-33228:120.

274 NONDOCKETED ITEMS

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8510010004 Notification of contract execution, Mod 4, to "Technical Assistance for Support of Const Appraisal Team (CAT) Insp." Contractor: Parameter, Inc. PAGE, M. Technical Assistance Contracts Branch, FIN B-8718, NRC-05-84-152, 85/09/23. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. PHILLIPS, H. NRC - No Detailed Affiliation Given. 1p. 32833-257-32833-258.

-8510010005 Mod 4, providing addl funding, to "Technical Assistance for Support of Const Appraisal Team (CAT) Insp." LOFF, R.A. Parameter, Inc. EDGEWORTH, P.J. Division of Contracts, FIN B-8718, NRC-05-84-152, 85/09/23, 1p. 32833-258-32833-258.

8510010006 Notification of contract execution: "NRC Ofc Automation Projects Evaluation," awarded to GSA. FLYNN, M. Administrative Contracts Branch, FIN D-1219, NRC-33-85-337, 85/09/24. BASSETT, H.S. Division of Automated Information Services. PAULSEN, G. NRC - No Detailed Affiliation Given. 1p. 32833-243-32833-256.

-8510010007 Contract: "NRC Ofc Automation Projects Evaluation," awarded to GSA. * General Services Administration, HAGAN, T.F. Division of Contracts, FIN D-1219, NRC-33-85-337, 85/09/24, 13pp. 32833-244-32833-256.

8510010080 Notification of contract execution, Mod 2, to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs. HAWKINS, D. Technical Assistance Contracts Branch, FIN D-1338, NRC-03-85-067, 85/09/24. THOMPSON, H.L. Division of Licensing. TRAMMELL, C. NRC - No Detailed Affiliation Given. 1p. 32833-315-32833-319.

-8510010092 Mod 2, revising statement of work to include Task D, to "Review & Evaluation of Comanche Peak Program Plan." MOONAN, W.S. Teledyne Engineering Svcs. EDGEWORTH, P.J. Technical Assistance Contracts Branch, FIN D-1338, NRC-03-85-067, 85/09/24, 4pp. 32833-316-32833-319.

8510010137 Notification of grant execution, Mod 7, to "Thermal-Hydraulic Transients Behavior of Coolant in Simulated Reactor-Loop." Grantor: Univ of Maryland. STEWART, S.D. Division of Contracts, FIN G-1043, NRC-G-04-82-013, 85/09/24. FOREHAND, W. Office of Nuclear Regulatory Research, Director. LEE, R. NRC - No Detailed Affiliation Given. 1p. 32833-290-32833-291.

-8510010149 Mod 7, incorporating addl work & increasing funds, to "Thermal-Hydraulic Transients Behavior of Coolant in Simulated Reactor-Loop." CASHMAN, D.C. Maryland, Univ. of, College Park, MD. EDGEWORTH, P.J. Technical Assistance Contracts Branch, FIN G-1043, NRC-G-04-82-013, 85/09/24, 1p. 32833-291-32833-291.

8510010233 Notification of contract execution, Mod 12, to "Sheffield Trench Cap Study." Contractor: Univ of Illinois. LITTLE, J.M. Administrative Contracts Branch, NRC-02-80-074, 85/09/26. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. SHAFFNER, J. NRC - No Detailed Affiliation Given. 1p. 32833-326-32833-328.

-8510010240 Mod 12, revising delivery date as result of contractor failure to make timely delivery, to "Sheffield Trench Cap Study." BAZZANI, C.S. Illinois, Univ. of, Urbana, IL. WIGGINS, E. Division of Contracts, NRC-02-80-074, 85/09/26, 2pp. 32833-327-32833-328.

8510010252 Notification of contract execution, Mod 5, to "Transient Prototypical Steam Generator (MB-2) Research Testing Program." Contractor: Westinghouse/EPRI. HAWKINS, D.A. Technical Assistance Contracts Branch, FIN B-8252, NRC-04-82-020, 85/09/18. GUSTAVE, R., K. PENFELD, J. Office of Nuclear Regulatory Research, Director. 1p. 32833-323-32833-325.

-8510010258 Mod 5, extending period of performance from 850930 to 851231 & revising major milestones, to "Transient Prototypical Steam Generator (MB-2) Research Testing Program." * Westinghouse Electric Corp. FARRAR, A.O. Electric Power Research Institute. EDGEWORTH, P.J. Technical Assistance Contracts Branch, FIN B-8252, NRC-04-82-020, 85/09/18, 2pp. 32833-324-32833-325.

8510030139 Notification of contract execution, Mod 4, to "Technical Assistance in Reviewing Work of Licensee IDVP Contractor for Specific Nuclear Project." Contractor: Westec Svc, Inc. HAWKINS, D.A. Technical Assistance Contracts Branch, FIN B-8720, NRC-05-85-150, 85/09/24. HIGGINS, K. Director's Office, Office of Inspection and Enforcement. IMBRO, E. NRC - No Detailed Affiliation Given. 1p. 32849-313-32849-313.

-8510030149 Mod 4, increasing obligated funds & contract cost ceiling, to "Technical Assistance in Reviewing Work of Licensee IDVP Contractor for Specific Nuclear Project." SARGENT, J.H. WESTEC Services, Inc. EDGEWORTH, P.J. Division of Contracts, FIN B-8720, NRC-05-85-150, 85/09/24, 2pp. 32849-314-32849-315.

8510030156 Notification of contract execution, Mod 4, to "Scientific & Engineering Assistance & Svcs." Contractor: SBA, Subcontractor Engineering & Economics Research, Inc. HAWKINS, D.A. Technical Assistance Contracts Branch, FIN D-1143, NRC-04-84-120, 85/09/24. FOREHAND, W. Office of Nuclear Regulatory Research, Director. 1p. 32849-298-32849-298.

-8510030162 Mod 4 adding incremental funding & increasing contract ceiling amount, to "Scientific & Engineering Assistance & Svcs." BUTLER, J.P. Small Business Administration, * Engineering & Economics Research, Inc. EDGEWORTH, P.J. Division of Contracts, FIN D-1143, NRC-04-84-120, 85/09/24, 3pp. 32849-299-32849-301.

8510030182 Notification of grant execution: "Support of Publication Costs for Intl Topical Meeting on Fast Reactor Safety," awarded to ANS. STEWART, S. Technical Assistance Contracts Branch, FIN G-1083, NRC-G-04-85-013, 85/09/27. FOREHAND, W. Office of Nuclear Regulatory Research, Director. WALKER, T. NRC - No Detailed Affiliation Given. 1p. 32849-286-32849-286.

-8510030192 Grant: "Support of Publication Costs for Intl Topical Meeting on Fast Reactor Safety," awarded to ANS. BAERT, T.S. American Nuclear Society. EDGEWORTH, P.J. Division of Contracts, FIN G-1083, NRC-G-04-85-013, 85/09/27, 2pp. 32849-287-32849-288.

8510030327 Notification of contract execution: "Facility Sys Analysis Support," awarded to Science Applications Intl Corp. BAZIN, J.P. Administrative Contracts Branch, FIN D-1101-5, NRC-02-85-007, 85/09/25. BROWN, R.S. Office of Nuclear Material Safety & Safeguards, Director. PICKETT, D. NRC - No Detailed Affiliation Given. 1p. 32849-013-32849-078.

-8510030329 Contract: "Facility Sys Analysis Support," awarded to Science Applications Intl Corp. * Science Applications International Corp. (formerly Science Applications, Inc.). HAGAN, T.F. Division of Contracts, FIN D-1101-5, NRC-02-85-007, 85/09/25, 65pp. 32849-014-32849-078.

8510030399 Notification of contract execution, Mod 1, to "Review & Evaluation of Comanche Peak Program Plan." Contractor: Teledyne Engineering Svcs. HAWKINS, D. Technical Assistance Contracts Branch, FIN D-1338, NRC-03-85-067, 85/09/09. THOMPSON, H.L. Division of Licensing. TRAMMELL, C. NRC - No Detailed Affiliation Given. 1p. 32848-075-32848-076.

-8510030404 Mod 1, extending period of performance to 850920, to "Review & Evaluation of Comanche Peak Program Plan." MOONAN, W.S. Teledyne Engineering Svcs. EDGEWORTH, P.J. Division of Contracts, FIN D-1338, NRC-03-85-067, 85/09/09, 1p. 32848-076-32848-076.

8510030432 Notification of contract execution: "Region V Data Entry Svcs." awarded to SBA Subcontractor: Phoenix Intl. BROMBERG, B.J. Administrative Contracts Branch, FIN B-8891, NRC-33-85-133, 85/09/25. BASSETT, H.S. Division of Automated Information Services. FRIGILLANA, E. Region 5, Office of Director. 1p. 32848-126-32848-161.

-8510030434 Contract: "Region V Data Entry Svcs." awarded to SBA Subcontractor: Phoenix Intl. MIMS, R. Small Business Administration, THOMAS, B.J. Phoenix International. WIGGINS, E. Division of Contracts, FIN B-8891, NRC-33-85-133, 85/09/25, 34pp. 32848-127-32848-161.

8510040127 Notification of contract execution, Mod 12, to "Surface Boundary Conditions for Fractured Rock." Contractor: Univ of Arizona. STEWART, S. Technical Assistance Contracts Branch, FIN B-7291, NRC-04-81-224, 85/09/26. FOREHAND, B. Office of Nuclear Regulatory Research, Director. NICHOLSON, T. NRC - No Detailed Affiliation Given. 1p. 32860-178-32860-183.

-8510040129 Mod 12, providing addl FY85 funding to support unanticipated work, to "Surface Boundary Conditions for Fractured Rock." SWELSON, F.A. Arizona, Univ. of, Tucson, AZ. EDGEWORTH, P.J. Division of Contracts, FIN B-7291, NRC-04-81-224, 85/09/26, 5pp. 32860-179-32860-183.

8510040153 Notification of contract execution, Mod 2, to "Atmospheric Transport & Diffusion Models for Emergency Response Facility Appraisals." Contractor: Dept of Commerce, NOAA. WOLLETT, S. Technical Assistance Contracts Branch, FIN B-8683, NRC-03-84-066, 85/09/30. BOYD, S. Office of Nuclear Regulatory Research, Director. MARKEE, E. NRC - No Detailed Affiliation Given. 1p. 32860-172-32860-174.

-8510040157 Ltr Contract NRC-03-84-066, Mod 2, changing scope of work & adding funds, to "Atmospheric Transport & Diffusion Models for Emergency Response Facility Appraisals." EDGEWORTH, P.J. Technical Assistance Contracts Branch, FIN B-8683, NRC-03-84-066, 85/09/23. DERR, V.E. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 2pp. 32860-173-32860-174.

8510040349 Notification of contract execution: "Countercurrent Steam Water Tests," awarded to Technical Univ of Hannover. BAISDEN, L. Technical Assistance Contracts Branch, FIN D-1585, NRC-04-85-120, 85/09/30. FOREHAND, W. Office of Nuclear Regulatory Research, Director. ZUBER, N. NRC - No Detailed Affiliation Given. 1p. 32860-076-32860-101.

-8510040355 Contract: "Countercurrent Steam Water Tests," awarded to Technical Univ of Hannover. * Hannover, Technical Univ. of, Federal Republic of Germany. SMITH, P.A. Division of Contracts, FIN D-1585, NRC-04-85-120, 85/09/30, 25pp. 32860-077-32860-101.

8510040468 Notification of contract execution: "Phase II - Plant Input & Development," awarded to Sciencetech, Inc. HAGEY, H. Technical Assistance Contracts Branch, FIN D-1655, NRC-04-85-124, 85/09/26. BASSETT, O.E. Division of Accident Evaluation. TROUTMAN, C. NRC - No Detailed Affiliation Given. 1p. 32859-270-32859-307.

-8510040472 Contract: "Phase II - Plant Input & Development," awarded to Sciencetech, Inc. YBARONDO, L.J. Sciencetech, Inc. SMITH, P.A. Division of Contracts, FIN D-1655, NRC-04-85-124, 85/09/26, 37pp. 32859-271-32859-307.

8510040489 Notification of contract execution, Mod 4, to "Technical Assistance in NRC IE Operations." Contractor: Parameter, Inc. COLEMAN, R. Division of Contracts, FIN B-8745, NRC-05-85-157, 85/09/30. CORLEY, D. Director's Office, Office of Inspection and Enforcement. PHILLIPS, H. NRC - No Detailed Affiliation Given. 1p. 32863-102-32863-105.

-8510040499 Mod 4, providing incremental funding, to "Technical Assistance in NRC IE Operations." * Parameter, Inc. EDGEWORTH, P.J. Division of Contracts, FIN B-8745, NRC-05-85-157, 85/09/30, 3pp. 32863-103-32863-105.

8510040501 Notification of contract execution: "Piedmont Seismic Reflection Study," awarded to Virginia Polytechnic Inst & State Univ. HAGEY, H. Technical Assistance Contracts Branch, FIN D-1552, NRC-04-85-106, 85/09/20. GOLLER, K.G. Division of Radiation Programs & Earth Sciences (post 840429). ZURFLUEHE, NRC - No Detailed Affiliation Given. 1p. 32863-106-32863-133.

-8510040503 Contract: "Piedmont Seismic Reflection Study," awarded to Virginia Polytechnic Inst & State Univ. STEISS, A.W. Virginia Polytechnic Institute & State Univ., Blacksburg, VA. THOMPSON, R.D. Division of Contracts, FIN D-1552, NRC-04-85-106, 85/09/20, 27pp. 32863-107-32863-133.

8510040517 Notification of contract execution, Mod 5, to "Ultrasensitive Bioassay Measurements Using Sputum Initiated Resonance Ionization Spectroscopy." Contractor: Atom Sciences, Inc. HAWKINS, D. Technical Assistance Contracts Branch. FIN D-1127. NRC-04-83-180. 85/09/30. FOREHAND, W. Office of Nuclear Regulatory Research, Director. NEEL, R. NRC - No Detailed Affiliation Given. 1p. 32863:097-32863:098.

8510040571 Mod 5, extending period of performance to 850930 at no cost to govt, to "Ultrasensitive Bioassay Measurements Using Sputum Initiated Resonance Ionization Spectroscopy." SCHMITT, H.V. Atom Sciences, Inc. EDGEWORTH, P.J. Division of Contracts. FIN D-1127. NRC-04-83-180. 85/09/30. 1p. 32863:098-32863:098.

8510040559 Notification of contract execution, Mod 2, to "Stenographic Reporting Svcs Within Washington, DC Metropolitan Area." Contractor: A Riley & Assoc. Ltd. LITTLE, M. Administrative Contracts Branch. FIN D-1458. NRC-17-85-394. 85/09/30. CHILK, S.J., MCGREGOR, E.W. Office of the Secretary of the Commission. 1p. 32863:099-32863:101.

8510040564 Mod 2, extending period of performance to 851215 & providing add'l funding, to "Stenographic Reporting Svcs Within Washington, DC Metropolitan Area." RILEY, A. Ann Riley & Associates. WIGGINS, E. Administrative Contracts Branch. FIN D-1458. NRC-17-85-394. 85/09/30. 2pp. 32863:100-32863:101.

8510040576 Notification of contract execution, Mod 1, to "Technical Assistance in NRC IE Operations." Contractor: Parameter, Inc. COLEMAN, R. Division of Contracts. FIN B-8729. NRC-05-85-157. 85/09/30. CORLEY, D. Director's Office, Office of Inspection and Enforcement. BARNOLD, A. NRC - No Detailed Affiliation Given. 1p. 32861:294-32861:295.

8510040583 Mod 1, providing incremental funding, to "Technical Assistance in NRC IE Operations." Parameter, Inc. EDGEWORTH, P.J. Division of Contracts. FIN B-8729. NRC-05-85-157. 85/09/30. 1p. 32861:295-32861:295.

8510040595 Notification of contract execution, Mod 24, to "Technical Assistance in Support of NRC Reactor Licensing Action - Program 2." Contractor: Arvin/Calspan. WOLLETT, S. Division of Contracts. FIN B-6891. NRC-03-81-130. 85/09/26. THOMPSON, H.L. Division of Licensing. CARRINGTON, M. NRC - No Detailed Affiliation Given. 1p. 32861:296-32861:298.

8510040603 Mod 24, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Action - Program 2." ARVIN/CALSPAN Advanced Technology Center. EDGEWORTH, P.J. Division of Contracts. FIN B-6891. NRC-03-81-130. 85/09/26. 2pp. 32861:297-32861:298.

8510070071 Notification of contract execution, Mod 5, to "Degraded Piping Program - Phase II." Contractor: BMI. PAGE, M. Technical Assistance Contracts Branch. FIN B-8134. NRC-04-84-103. 85/09/26. FOREHAND, W. Office of Nuclear Regulatory Research, Director. VAGINS, M. NRC - No Detailed Affiliation Given. 1p. 32901:099-32901:102.

8510070078 Mod 5, providing incremental funding, to "Degraded Piping Program - Phase II." SEWELL, H.M. Battelle Memorial Institute, Columbus Laboratories. EDGEWORTH, P.J. Division of Contracts. FIN B-8134. NRC-04-84-103. 85/09/26. 3pp. 32901:100-32901:102.

8510070085 Notification of contract execution, Mod 3, to "Research Support for Rulemaking." Contractor: BMI. PAGE, M. Technical Assistance Contracts Branch. FIN D-1108. NRC-04-84-101. 85/09/27. BATSON, W. Office of Nuclear Regulatory Research, Director. MURPHY, J. NRC - No Detailed Affiliation Given. 1p. 32901:103-32901:108.

8510070089 Mod 3, providing incremental funding, to "Research Support for Rulemaking." SEWELL, H.M. Battelle Memorial Institute, Columbus Laboratories. EDGEWORTH, P.J. Division of Contracts. FIN D-1108. NRC-04-84-101. 85/09/27. 5pp. 32901:104-32901:108.

8510070124 Notification of contract execution, Mod 1, to "Technical Assistance in Support of NRC Planning Function." Contractor: SBA Subcontractor: Maxima Corp. COLEMAN, R. Administrative Contracts Branch. NRC-33-85-324. 85/09/19. BASSETT, H.S. Office of Resource Management, Director. FROST, J. NRC - No Detailed Affiliation Given. 1p. 32901:207-32901:210.

8510070129 Mod 1, changing key personnel arrangement, to "Technical Assistance in Support of NRC Planning Function." THOMAS, M. Small Business Administration. JONES, P.E. Maxima Corp. WIGGINS, E. Division of Contracts. NRC-33-85-324. 85/09/19. 3pp. 32901:208-32901:210.

8510070305 Notification of contract execution: "Sys for Generating Long Stream Flow Records for Study of Floods of Long Return Period." awarded to Linsley/Kraeger Assoc. Ltd. JESSUP, B. Technical Assistance Contracts Branch. FIN D-1663. NRC-04-85-143. 85/09/27. HAYES, M. Office of Nuclear Regulatory Research, Director. NICHOLSON, T. NRC - No Detailed Affiliation Given. 1p. 32901:220-32901:236.

8510070306 Contract: "Sys for Generating Long Stream Flow Records for Study of Floods of Long Return Period." awarded to Linsley/Kraeger Assoc. Ltd. KRAEGER, B.A. Linsley, Kraeger & Associates, Ltd. SMITH, P.A. Division of Contracts. FIN D-1663. NRC-04-85-143. 85/09/27. 16pp. 32901:221-32901:236.

8510070579 Notification of contract execution: "Time Domain Reflectometry Liquid Level Detection Concepts Assessment & Development." awarded to Mohr & Assoc. JESSUP, B. Technical Assistance Contracts Branch. FIN D-1653. NRC-04-85-140. 85/09/27. HAYES, M. Office of Nuclear Regulatory Research, Director. FEIT, R. NRC - No Detailed Affiliation Given. 1p. 32900:362-32901:019.

8510070581 Contract: "Time Domain Reflectometry Liquid Level Detection Concepts Assessment & Development." awarded to Mohr & Assoc. MOHR, L.J. Mohr & Associates. SMITH, P.A. Division of Contracts. FIN D-1653. NRC-04-85-140. 85/09/27. 19pp. 32901:001-32901:019.

8510080009 Notification of contract execution, Mod 32, Task Order 18, to "Licensing Technical Assistance." Contractor: Science Application Int'l Corp. MCLEAREN, T. Administrative Contracts Branch. FIN D-1027-5. NRC-02-83-035. 85/09/30. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. LOYSEN, P. NRC - No Detailed Affiliation Given. 1p. 32927:008-32927:012.

8510080010 Mod 32, Task Order 18, increasing funds, to "Licensing Technical Assistance." JACKSON, D.R. Science Applications International Corp. (formerly Science Applications, Inc.) WIGGINS, E. Division of Contracts. FIN D-1027-5. NRC-02-83-035. 85/09/30. 4pp. 32927:009-32927:012.

8510080012 Notification of contract execution: "Hydrogen Generation & Blanketing Assessment for Severe Accidents." awarded to Engineering Science & Analysis. MACE, M. Technical Assistance Contracts Branch. FIN D-1645. NRC-04-85-135. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. WRIGHT, R. NRC - No Detailed Affiliation Given. 1p. 32926:354-32927:007.

8510080015 Contract: "Hydrogen Generation & Blanketing Assessment for Severe Accidents." awarded to Engineering Science & Analysis. CRONENBERG, A.W. Engineering Science & Analysis. THOMPSON, R.D. Division of Contracts. FIN D-1645. NRC-04-85-135. 85/09/30. 14pp. 32926:355-32927:007.

8510080024 Notification of contract execution: "Void Fraction & Liquid Level Assessment for Perfected Fuel Bundles Under Low Reflood Rates & Boil Off Conditions." awarded to Mohr & Assoc. MACE, M. Technical Assistance Contracts Branch. FIN D-1651. NRC-04-85-136. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. VAN HOUTEN, R. NRC - No Detailed Affiliation Given. 1p. 32926:339-32926:353.

8510080027 Contract: "Void Fraction & Liquid Level Assessment for Deformed Fuel Bundles Under Low Reflood Rates & Boil Off Conditions." awarded to Mohr & Assoc. MOHR, L.J. Mohr & Associates. THOMPSON, R.D. Division of Contracts. FIN D-1651. NRC-04-85-136. 85/09/30. 14pp. 32926:340-32926:353.

8510080081 Notification of contract execution: "Technical Assistance in Hydrogeology - Project A - Testing." awarded to Williams & Assoc. Inc. FLEENOR, C. Administrative Contracts Branch. FIN D-1020-5. NRC-02-85-008. 85/09/25. BROWN, R.S. Program Support Branch. POHLE, J. NRC - No Detailed Affiliation Given. 1p. 32926:048-32926:178.

8510080087 Contract: "Technical Assistance in Hydrogeology - Project A - Testing." awarded to Williams & Assoc. Inc. Williams & Associates. HAGAN, T.F. Division of Contracts. FIN D-1020-5. NRC-02-85-008. 85/09/25. 3pp. 32926:049-32926:051.

8510080092 Solicitation, offer & award of "Technical Assistance in Hydrogeology - Project A - Testing." to Williams & Assoc. Inc. WILLIAMS, R.E. Williams & Associates. Division of Contracts. FIN D-1020-5. NRC-02-85-008. 85/05/21. 77pp. 32926:052-32926:178.

8510080118 Notification of contract execution: "On-line Plant Analyzer Utilization in Control Room for Surveillance of Plant Safety." awarded to Dynatrek, Inc. HAGEY, H. Technical Assistance Contracts Branch. FIN D-1652. NRC-04-85-139. 85/09/27. BASSETT, O.E. Division of Accident Evaluation. TOVMASSIAN, H. NRC - No Detailed Affiliation Given. 1p. 32925:299-32925:319.

8510080128 Contract: "On-line Plant Analyzer Utilization in Control Room for Surveillance of Plant Safety." awarded to Dynatrek, Inc. FABIG, C. Dynatrek, Inc. SMITH, P.A. Division of Contracts. FIN D-1652. NRC-04-85-139. 85/09/27. 20pp. 32925:300-32925:319.

8510080122 Notification of contract execution, Mod 6, to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities." Contractor: Control Data-Nuclear Assoc. Int'l. PAGE, M. Technical Assistance Contracts Branch. FIN B-7479. NRC-04-81-201. 85/09/26. FOREHAND, W. Office of Nuclear Regulatory Research, Director. SCOTT, H. NRC - No Detailed Affiliation Given. 1p. 32925:296-32925:298.

8510080130 Mod 6, revising Task D to include requirement for contractor to debug & modify as-received version of FRAPCON-2 to improve cladding irradiation growth model, to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities." KINNEY, W.H. Nuclear Associates International. EDGEWORTH, P.J. Division of Contracts. FIN B-7479. NRC-04-81-201. 85/09/26. 2pp. 32925:297-32925:298.

8510080136 Notification of contract execution: "Flow of Groundwater & Transport of Contaminants." awarded to In-Situ, Inc. JESSUP, B. Technical Assistance Contracts Branch. FIN D-1163. NRC-04-85-114. 85/09/25. HAYES, M. Office of Nuclear Regulatory Research, Director. RANDALL, J. NRC - No Detailed Affiliation Given. 1p. 32925:255-32925:277.

8510080141 Contract: "Flow of Groundwater & Transport of Contaminants." awarded to In-Situ, Inc. MCKEE, C.R. In-Situ Consulting. SMITH, P.A. Division of Contracts. FIN D-1163. NRC-04-85-114. 85/09/25. 2pp. 32925:256-32925:257.

8510080149 Solicitation, offer & award of "Flow of Groundwater & Transport of Contaminants." to In-Situ, Inc. In-Situ Consulting. Division of Contracts. FIN D-1163. NRC-04-85-114. 84/11/26. 20pp. 32925:258-32925:277.

8510080139 Notification of contract execution: "Correlation of Radioiodine Resuspension W/Tmp at TMI-2." awarded to Daniel & Assoc. Inc. MACE, M. Technical Assistance Contracts Branch. FIN D-1647. NRC-04-85-138. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. CHAN, L. NRC - No Detailed Affiliation Given. 1p. 32925:223-32925:237.

8510080146 Contract: "Correlation of Radioiodine Resuspension W/Tmp at TMI-2." awarded to Daniel & Assoc. Inc. DANIEL, J.A. Daniel & Associates, Inc. THOMPSON, R.D. Division of Contracts. FIN D-1647. NRC-04-85-138. 85/09/30. 14pp. 32925:224-32925:237.

8510080144 Notification of contract execution, Mod 8, to "Integral Sys Test Program - Once-Through Integral Sys & Multiloop Integral Sys Test Components." Contractor: B&W. WOLLETT, S. Technical Assistance Contracts Branch. FIN B-6909. NRC-04-85-168. 85/10/02. FOREHAND, B. Office of Nuclear Regulatory Research, Director. BECKNER, B. NRC - No Detailed Affiliation Given. 1p. 32925:247-32925:254.

276 NONDOCKETED ITEMS

- 8510080159** Mod 8, revising statement of work & changing project officer to W Beckner, to "Integral Sys Test Program - Cyclic-Through Integral Sys & Multiloop Integral Sys Test Components." SMITH, N. Babcock & Wilcox Co. RYTKONEN, B.B. Electric Power Research Institute. EDGEWORTH, P.J. Technical Assistance Contracts Branch. FIN B-8909. NRC-04-83-168. 85/10/02. 7pp. 32925-248-32925-254.
- 8510080182** Notification of contract execution, Mod 8, to "Severe Accident Consequences Mitigation." Contractor: R&D Assoc, Inc. PAGE, M. Technical Assistance Contracts Branch. FIN B-8625. NRC-03-83-092. 85/09/26. BERNERO, R., HARDIN, W. NRC - No Detailed Affiliation Given. 1p. 32925-242-32925-244.
- 8510080191** Mod 8, deleting Paragraph D.3, "Final Rept." in entirety from statement of work & extending period of performance to 851202, to "Severe Accident Consequences Mitigation." KELLER, D.S. R&D Associates. EDGEWORTH, P.J. Technical Assistance Contracts Branch. FIN B-8625. NRC-03-83-092. 85/09/26. 2pp. 32925-243-32925-244.
- 8510080285** Notification of contract execution: "Aging Effects of Stress Corrosion Cracking." awarded to M Fox. MACE, M. Technical Assistance Contracts Branch. FIN D-1643. NRC-04-85-131. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. TABOADA, A. NRC - No Detailed Affiliation Given. 1p. 32923-142-32923-156.
- 8510080299** Contract: "Aging Effects of Stress Corrosion Cracking." awarded to M Fox. FOX, M. Michael Fox. SMITH, P.A. Technical Assistance Contracts Branch. FIN D-1643. NRC-04-85-131. 85/09/30. 14pp. 32923-143-32923-156.
- 8510080317** Notification of contract execution: "Generalized Modeling of Condensation for Reactor Applications." awarded to Creare, Inc. MACE, M. Technical Assistance Contracts Branch. FIN D-1649. NRC-04-85-137. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. LEE, R. NRC - No Detailed Affiliation Given. 1p. 32923-125-32923-139.
- 8510080325** Contract: "Generalized Modeling of Condensation for Reactor Applications." awarded to Creare, Inc. HICKIN, R.A. Creare, Inc. THOMPSON, R.D. Division of Contracts. FIN D-1649. NRC-04-85-137. 85/09/30. 14pp. 32923-126-32923-139.
- 8510080328** Notification of contract execution: "Sys Engineering Expertise." awarded to Mitre Corp. JESSUP, B. Administrative Contracts Branch. NRC-03-85-060. 85/09/30. DIGALOMA, T. Office of Nuclear Reactor Regulation, Director. FUNCHES, J. NRC - No Detailed Affiliation Given. 1p. 32923-087-32923-118.
- 8510080334** Contract: "Sys Engineering Expertise." awarded to Mitre Corp. KONZ, J.S. Mitre Corp. SMITH, P.A. Administrative Contracts Branch. NRC-03-85-060. 85/09/30. 31pp. 32923-088-32923-118.
- 8510080347** Notification of contract execution, Mod 2, to "Development of Real-Time Residue Number Processor for Safeguards Automated Facility Evaluation Insp." Contractor: Sigma Research, Inc. PAGE, M. Administrative Contracts Branch. FIN D-1559. NRC-04-84-141. 85/09/30. BATSON, W. Office of Nuclear Regulatory Research, Director. MUSCARA, J. NRC - No Detailed Affiliation Given. 1p. 32923-084-32923-085.
- 8510080354** Mod 2, granting no-cost extension until 851226, to "Development of Real-Time Residue Number Processor for Safeguards Automated Facility Evaluation Insp." PIPKIN, Y.M. Sigma Research, Inc. EDGEWORTH, P.J. Division of Contracts. FIN D-1559. NRC-04-84-141. 85/09/30. 1p. 32923-085-32923-085.
- 8510080365** Notification of contract execution, Mod 1, to "Ref Nuclear Power Plant Simulator Assessment." Contractor: Phoenix Assoc, Inc. BAIDEN, L. Administrative Contracts Branch. FIN B-8753. NRC-05-85-168. 85/09/30. HIGGINS, K.E. Director's Office, Office of Inspection and Enforcement. GRIMES, B.K. NRC - No Detailed Affiliation Given. 1p. 32927-019-32927-021.
- 8510080376** Mod 1, amending statement of work, extending period of performance & adding funds, to "Ref Nuclear Power Plant Simulator Assessment." FENSTERSTOCK, J. Phoenix Associates, Inc. SMITH, P.A. Administrative Contracts Branch. FIN B-8753. NRC-05-85-168. 85/09/30. 2pp. 32927-020-32927-021.
- 8510080572** Notification of contract execution: "Technical Assistance in Hydrogeology - Project B - Analysis." awarded to Nuclear Waste Consultants, Inc. FLEENOR, C. Administrative Contracts Branch. FIN D-1021-5. NRC-02-85-009. 85/09/27. BROWN, R.S. Program Support Branch. POHLE, J. NRC - No Detailed Affiliation Given. 1p. 32923-158-32923-158.
- 8510080574** Contract: "Technical Assistance in Hydrogeology - Project B - Analysis." awarded to Nuclear Waste Consultants, Inc. * Nuclear Waste Consultants, Inc. HAGAN, T.F. Division of Contracts. FIN D-1021-5. NRC-02-85-009. 85/09/27. 3pp. 32923-231-32923-233.
- 8510080575** Solicitation offer & award of "Technical Assistance in Hydrogeology - Project B - Analysis." to Nuclear Waste Consultants, Inc. BROWN, A. Nuclear Waste Consultants, Inc. * Division of Contracts. FIN D-1021. NRC-02-85-009. 85/05/21. 86pp. 32923-234-32923-350.
- 8510080594** Notification of contract execution: "Containment Check Valve Leak Rate Measurement." awarded to Leak Detection Svcs, Inc. MACE, M. Technical Assistance Contracts Branch. FIN D-1650. NRC-04-85-132. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. MILLMAN, G. NRC - No Detailed Affiliation Given. 1p. 32923-215-32923-229.
- 8510080598** Contract: "Containment Check Valve Leak Rate Measurement." awarded to Leak Detection Svcs, Inc. DIMMICK, J. Leak Detection Services, Inc. THOMPSON, R.D. Division of Contracts. FIN D-1650. NRC-04-85-132. 85/09/30. 14pp. 32923-216-32923-229.
- 8510080599** Notification of contract execution: "EMAT Defect Characterization of Nuclear Reactor Piping Welds." awarded to Mattis Engineering Assoc. MACE, M. Technical Assistance Contracts Branch. FIN D-1654. NRC-04-85-133. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. MUSCARA, J. NRC - No Detailed Affiliation Given. 1p. 32923-200-32923-214.
- 8510080600** Contract: "EMAT Defect Characterization of Nuclear Reactor Piping Welds." awarded to Mattis Engineering Assoc. ANDERSON, L.W. Materials Engineering Associates, Inc. SMITH, P.A. Division of Contracts. FIN D-1654. NRC-04-85-133. 85/09/30. 14pp. 32923-201-32923-214.
- 8510090418** Notification of contract execution: "Extended Fatigue Life Evaluation Methods for Aged LWR Components." awarded to O'Donnell Consulting Engineers, Inc. MACE, M. Technical Assistance Contracts Branch. FIN D-1642. NRC-04-85-123. 85/09/19. HAYES, M. Office of Nuclear Regulatory Research, Director. WEIDENHAMER, G. NRC - No Detailed Affiliation Given. 1p. 32964-294-32964-308.
- 8510090423** Contract: "Extended Fatigue Life Evaluation Methods for Aged LWR Components." awarded to O'Donnell Consulting Engineers, Inc. O'DONNELL, W.L. O'Donnell Consulting Engineers, Inc. SMITH, P.A. Division of Contracts. FIN D-1642. NRC-04-85-123. 85/09/19. 14pp. 32964-295-32964-308.
- 8510090436** Notification of contract execution: "Use of Workstation & Expert Sys Technologies to Facilitate Development & Evaluation of Fault Trees." awarded to Expert-EASE Sys, Inc. MACE, M. Technical Assistance Contracts Branch. FIN D-1644. NRC-04-85-134. 85/09/30. HAYES, M. Office of Nuclear Regulatory Research, Director. LANCASTER, L. NRC - No Detailed Affiliation Given. 1p. 32964-249-32964-263.
- 8510090439** Contract: "Use of Workstation & Expert Sys Technologies to Facilitate Development & Evaluation of Fault Trees." awarded to Expert-EASE Sys, Inc. FROGNER, B. Expert-EASE Systems, Inc. THOMPSON, R.D. Division of Contracts. FIN D-1644. NRC-04-85-134. 85/09/30. 14pp. 32964-250-32964-263.
- 8510100099** Notification of contract execution, Mod 2, to "Technical Assistance in NRC IE Operations." Contractor: Parameter, Inc. COLEMAN, R. Division of Contracts. FIN B-8729. NRC-05-85-157. 85/09/30. CORLEY, D. Director's Office, Office of Inspection and Enforcement. BARNOLD, A. NRC - No Detailed Affiliation Given. 1p. 33011-342-33011-343.
- 8510110103** Mod 2, increasing funds, to "Technical Assistance in NRC IE Operations." * Parameter, Inc. EDGEWORTH, P.J. Division of Contracts. FIN B-8729. NRC-05-85-157. 85/09/30. 1p. 33011-343-33011-343.
- 8510150035** Notification of contract execution, Mod 1, to "Page Make-Up Svcs." Contractor: Photocraft Custom Lab, Inc. LITTLE, M. Administrative Contracts Branch. NRC-10-84-231. 85/08/07. BESAW, W.J. Division of Technical Information & Document Control. THOT-THOMPSON, NRC - No Detailed Affiliation Given. 1p. 33031-337-33031-339.
- 8510150036** Mod 1, terminating contract for convenience of govt, to "Page Make-Up Svcs." * Photocraft Custom Lab, Inc. WIGGINS, E. Division of Contracts. NRC-10-84-231. 85/08/07. 2pp. 33031-338-33031-339.
- 8510150477** Notification of contract execution: "Emergency Response Data Sys Requirements Analysis." awarded to Phoenix Assoc, Inc. BAIDEN, L. Technical Assistance Contracts Branch. FIN B-8749. NRC-05-85-163. 85/09/30. HIGGINS, K.E. Director's Office, Office of Inspection and Enforcement. HICKMAN, J.B. NRC - No Detailed Affiliation Given. 1p. 33033-135-33033-138.
- 8510150481** Contract: "Emergency Response Data Sys Requirements Analysis." awarded to Phoenix Assoc, Inc. FENSTERSTOCK, J. Phoenix Associates, Inc. SMITH, P.A. Division of Contracts. FIN B-8749. NRC-05-85-163. 85/09/30. 3pp. 33033-136-33033-138.
- 8510160322** Notification of contract execution, Mod 3, to "Review & Analysis of Selected Topics in Nuclear Safety Regulation." Contractor: Natl Academy of Sciences. HAWKINS, D. Technical Assistance Contracts Branch. FIN B-8686. NRC-03-84-069. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. SPEIS, T. NRC - No Detailed Affiliation Given. 1p. 33028-356-33028-358.
- 8510160324** Mod 3, revising Section G.6, Item B re project officer, to "Review & Analysis of Selected Topics in Nuclear Safety Regulation." * National Academy of Sciences. EDGEWORTH, P.J. Division of Contracts. FIN B-8686. NRC-03-84-069. 85/10/09. 2pp. 33028-357-33028-358.
- 8510160330** Notification of grant execution: "Peer Review of Rept Entitled, 'Shipping Container Response to Severe Highway & Railroad Accident Conditions.'" awarded to Univ of Denver. STEWART, S. Technical Assistance Contracts Branch. FIN G-1090. NRC-G-04-85-015. 85/09/30. FOREHAND, W. Office of Nuclear Regulatory Research, Director. LAH, W. NRC - No Detailed Affiliation Given. 1p. 33028-326-33028-328.
- 8510160333** Grant: "Peer Review of Rept Entitled, 'Shipping Container Response to Severe Highway & Railroad Accident Conditions.'" awarded to Univ of Denver. ROBERTS, G.L. Denver, Univ. of Denver, CO. EDGEWORTH, P.J. Division of Contracts. FIN G-1090. NRC-G-04-85-015. 85/09/30. 2pp. 33028-327-33028-328.
- 8510170115** Notification of contract execution: "Extreme Flood Probabilities." awarded to Natl Academy of Science. HAGEY, H. Technical Assistance Contracts Branch. FIN D-1333. NRC-03-85-064. 85/09/30. KNIGHT, J.P. Division of Engineering. CHERY, D. NRC - No Detailed Affiliation Given. 1p. 33043-178-33043-197.
- 8510170119** Contract: "Extreme Flood Probabilities." awarded to Natl Academy of Science. SMITH, P.M. National Academy of Sciences. SMITH, P.A. Division of Contracts. FIN D-1333. NRC-03-85-064. 85/09/30. 19pp. 33043-179-33043-197.
- 8510210191** Notification of contract execution, Mod 1, to "Career Counseling Svcs." Contractor: BEWM, Inc. LITTLE, M. Administrative Contracts Branch. NRC-10-85-214. 85/10/04. BENTSON, N. Division of Organization and Personnel. SULLIVAN, P. NRC - No Detailed Affiliation Given. 1p. 33094-137-33094-139.
- 8510210200** Mod 1, providing add'l svcs, to "Career Counseling Svcs." * BEWM, Inc. (formerly Binder, Elster, Mendelson & Wheeler, Inc.) WIGGINS, E. Division of Contracts. NRC-10-85-214. 85/10/04. 2pp. 33094-138-33094-139.

8510210202 Notification of contract execution, Mod 2, to "NRC Issuances & Indexes." Contractor: Hermer & Co. LITTLE, M. Administrative Contracts Branch. NRC-10-85-211. 85/10/09. BESAW, W.J. Division of Technical Information & Document Control. LARKINS, P.M. NRC - No Detailed Affiliation Given. 1p. 33094:102-33094:107.

-8510210204 Mod 2, providing delivery schedule for yr two, to "NRC Issuances & Indexes." HERNER, S. Hermer & Co. WIGGINS, E. Division of Contracts. NRC-10-85-211. 85/10/09. 4pp. 33094:103-33094:107.

8510240034 Notification of contract execution, Task Orders 004 & 012, Mod 31, to "Licensing Technical Assistance." Contractor: Science Applications Intl Corp. MCLEAREN, T. Administrative Contracts Branch. NRC-02-83-035. 85/10/17. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. LOYSEN, P. NRC - No Detailed Affiliation Given. 1p. 33162:334-33162:334.

-8510240036 Mod 31, Task Orders 004 & 012, extending period of performance to 860121 at no addl cost, to "Licensing Technical Assistance." LITTLE, M. Administrative Contracts Branch. FIN D-1010-5. NRC-02-84-004. 85/10/17. BROWN, R.S. Office of Nuclear Material Safety & Safeguards, Director. WIGGINS, E. Division of Contracts. NRC-02-83-035. 85/10/17. 2pp. 33162:335-33162:336.

8510250203 Notification of contract execution, Mod 4, to "Support of Continuing Activities of US Natl Committee on Tunneling Technology." Contractor: Bureau of Mines. LITTLE, M. Administrative Contracts Branch. FIN D-1010-5. NRC-02-84-004. 85/10/17. BROWN, R.S. Office of Nuclear Material Safety & Safeguards, Director. BROWN, R.S. Program Support Branch. TANIUS, N. NRC - No Detailed Affiliation Given. 1p. 33226:036-33226:037.

-8510250213 Mod 4, increasing funds, to "Support of Continuing Activities of US Natl Committee on Tunneling Technology." Interior, Dept. of, Bureau of Mines. WIGGINS, E. Division of Contracts. FIN D-1010-5. NRC-02-84-004. 85/10/17. 1p. 33226:037-33226:037.

8510250222 Notification of contract execution, Mod 10, to "Support of Continuing Activities of US Natl Committee for Rock Mechanics." Contractor: Bureau of Mines. LITTLE, M. Administrative Contracts Branch. FIN B-6932-5. NRC-02-80-038. 85/10/18. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. GUPTA, D. NRC - No Detailed Affiliation Given. 1p. 33226:202-33226:203.

-8510250225 Mod 10, increasing funds, to "Support of Continuing Activities of US Natl Committee for Rock Mechanics." Interior, Dept. of, Bureau of Mines. WIGGINS, E. Division of Contracts. FIN B-6932-5. NRC-02-80-038. 85/10/18. 1p. 33226:203-33226:203.

8510280194 Notification of contract execution, Mod 5, to "Provide Expert Technical Consulting Svcs to Document Control Sys on Task Order Basis." Contractor: GSA. BROMBERG, B.J. Administrative Contracts Branch. NRC-10-82-404. 85/10/22. NORRIS, P.G., LUNDY, J. Office of Administration. 2pp. 33226:244-33226:245.

-8510280204 Mod 5, changing name & address to reflect transfer of federal computer performance evaluation & simulation ctr to GSA, to "Provide Expert Technical Consulting Svcs to Document Control Sys on Task Order Basis." SELF, C.A. General Services Administration. WIGGINS, E. Division of Contracts. NRC-10-82-404. 85/10/22. 1p. 33226:245-33226:245.

8510310363 Notification of contract execution, Mod 17, to "Field & Theoretical Investigations of Mass Energy Transport in Subsurface Mats at Waste Disposal Sites." Contractor: Univ of Arizona. STEWART, S. Technical Assistance Contracts Branch. FIN B-5753. NRC-04-78-275. 85/10/28. FOREHAND, W. Office of Nuclear Regulatory Research, Director. RANDALL, J. NRC - No Detailed Affiliation Given. 1p. 33278:164-33278:165.

-8510310370 Mod 17, extending period of performance to 860112, to "Field & Theoretical Investigations of Mass Energy Transport in Subsurface Mats at Waste Disposal Sites." PEYTON, C.H. Arizona State Univ., Tempe, AZ. EDGEWORTH, P.J. Technical Assistance Contracts Branch. FIN B-5753. NRC-04-78-275. 85/10/28. 1p. 33278:165-33278:165.

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8510010044 FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 from June 1972 - June 1975 & Oct 1976 - Mar 1977. BARNES, C. Affiliation Not Assigned. 85/07/22. Division of Rules and Records. 1p. 32830:075-32830:075.

8510010051 FOIA request for V Stello Aug 1965 meeting minutes from CRGR Meeting 79 to be placed in PDR. GRABER, L. NUS Corp. CD-LIS-85-747. 85/09/06. Division of Rules and Records. 1p. 32833:053-32833:053.

8510010054 Responds to FOIA request for V Stello Aug 1965 meeting minutes from CRGR Meeting 79 to be placed in PDR. Documents listed on app available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/19. GRABER, L. NUS Corp. 2pp. 32833:054-32833:055.

8510010058 FOIA request for correspondence received from Congressmen M Barnes, B Byron, P Sarbanes & C Mathias during past 2 yrs. DEZUBE, D. Montgomery County Sentinel. 85/06/07. NRC - No Detailed Affiliation Given. 1p. 32831:086-32831:086.

8510010057 Further response to FOIA request for documents re operator qualification cards. Forwards App A & portions of App B documents. Documents also available in PDR. Portions of App B documents withheld (ref FOIA Exemptions 5, 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/23. REBER, P.C. Washington Document Service. 4pp. 32832:117-32832:351.

-8510010071 Forwards Ofc of Inspector & Auditor rept of investigation entitled, "Congressman Markey Ltr of 840727 re Region II Actions re Grand Gulf Nuclear Station." Two issues concern training assessment/insp. Portions deleted. CONNELLY, S.R. Office of Inspector & Auditor. 84/10/19. PALLADINO, ROBERTS, ASSELSTINE Commissioners. 3pp. 32832:123-32832:125.

-8510010078 Notice of significant licensee meeting on 830923 w/utl in Atlanta, GA to discuss Agastat relay failures & other topics of current interest. * Region 2, Office of Director. 83/09/21. Region 2, Office of Director. 1p. 32832:165-32832:165.

-8510010084 Rept of investigation entitled, "Congressman Markey Ltr dtd 840727 re Region II Actions re Grand Gulf Nuclear Station." Portions deleted. RESNER, M.E., BOWERS, H., CONNELLY, S.R. Office of Inspector & Auditor. 84/10/19. 14pp. 32832:126-32832:139.

-8510010091 Discusses discrepancies in documentation of operator training identified in Jan 1983 special training assessment & safety insp conducted during Aug & Sept 1983. NRC requirements violated & enforcement action should be taken. DEYOUNG, R.C. Director's Office. Office of Inspection and Enforcement. 84/08/23. RICHARD, J.B. Mississippi Power & Light Co. 2pp. 32832:140-32832:141.

-8510010096 Rept of interview w/JP O'Reilly re discrepancies in reactor operator training program at plant, per restart of facility on 830925 & 830923 meeting w/utl at Region II, NRC response to Markey questions encl. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/10/11. 17pp. 32832:166-32832:182.

-8510010099 Comments on Ofc of Investigation 840305 rept "Grand Gulf Nuclear Power Plant: Possible Deliberate & Willful Mistake Applications." Unnecessary & inappropriate that NRC shared info w/ licensee. MARKEY, E.J. House of Rep. 84/07/27. PALLADINO, N.J. Commissioners. 3pp. 32832:142-32832:144.

-8510010107 Rept of interview w/JM Puckett re discrepancies in licensed operator training program at facility, per Region II enforcement actions. Reactor operators not trained per FSAR commitments. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/18. 3pp. 32832:183-32832:185.

-8510010109 Rept of interview w/JP McLaughly re 830923 meeting at Region II concerning discrepancies in operator qualification cards at facility. Draft utl ltr re discrepancies encl. Portions of rept deleted. RESNER, M.E. Office of Inspector & Auditor. 84/08/19. 6pp. 32832:145-32832:150.

-8510010116 Rept of interview w/Region II employee re discrepancies in reactor operator & senior reactor operator licensing program at facility. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/19. 1p. 32832:186-32832:186.

-8510010119 Rept of interview w/utl employee re 830923 meeting w/utl at Region II concerning discrepancies in operator qualification cards at facility. Interviewee name withheld. RESNER, M.E. Office of Inspector & Auditor. 84/08/21. 1p. 32832:151-32832:151.

-8510010125 Rept of interview w/DM Verrilli re events & circumstances of 830923 meeting w/utl at Region II & language used in 831205 confirmation of action ltr to utl. RESNER, M.E. Office of Inspector & Auditor. CAL 84/09/24. 1p. 32832:152-32832:154.

-8510010130 Rept of interview w/Region II employee re reactor operator & senior reactor operator license applications & operator training deficiencies at facility. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/21. 3pp. 32832:187-32832:189.

-8510010138 Rept of interview w/DH Beckham re discrepancies in reactor operator training program at facility, per impact on facility operation. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/25. 2pp. 32832:190-32832:191.

-8510010151 "Corrective Action Plans for Operator Training Program." Related info encl. Portions deleted. * Mississippi Power & Light Co. 83/11/30. 97pp. 32832:192-32832:291.

-8510010152 Rept of interview w/Ofc of Investigation, Atlanta Field Ofc employee re impact Region II 830923 meeting w/utl had on Ofc of Investigation Case 2-83-037. Interviewee name withheld. RESNER, M.E. Office of Inspector & Auditor. 84/09/17. 2pp. 32832:155-32832:156.

-8510010168 Rept of interview w/AF Gibson re deficiencies in reactor operator training program at facility & 830923 meeting w/utl at Region II concerning utl refusal to submit ltr to NRC. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/09/25. 2pp. 32832:157-32832:158.

-8510010170 Provides addl info re discrepancies discovered in operator & senior operator license applications & corrective actions, per 830930 ltr. Discrepancies identified between license applications & training records occurred prior to 1982. MCGAUGHY, J. Mississippi Power & Light Co. AECM-83/0681. 83/11/01. O'REILLY, J.P. Region 2, Office of Director. 20pp. 32832:292-32832:351.

-8510010178 Rept of interview w/Region II employee re 830623 meeting w/utl at Region II & discrepancies in reactor operator & senior reactor operator training at facility. Portions deleted. RESNER, M.E. Office of Inspector & Auditor. 84/08/18. 6pp. 32832:159-32832:164.

8510010058 FOIA request for documents from CRGR 850723-24 meeting re integral simulation test & inservice insp pump & valve programs. SMITH, E.R. NUS Corp. CD-LIS-85-621. 85/08/01. Division of Rules and Records. 1p. 32833:056-32833:056.

8510010080 Responds to FOIA request for records under Docket 40-8006 through June 1976, Docket 40-2038 through Mar 1963 & Docket 40-8027 from June 1972 - June 1973. Forwards App A & B documents. No records available for Docket 40-2038. FELTON, J.M. Division of Rules and Records. 85/08/29. BARNES, C. Affiliation Not Assigned. 8pp. 32830:076-32830:085.

-8510010065 Forwards IE Bulletin 75-07, "Exothermic Reaction in Used HEPA Filters," requiring action re NRC licensed activities. HOWARD, E.M. Region 4, Dallas, Office of the Director. IEB-75-07. 75/11/26. Kerr-McGee Nuclear Corp. 1p. 32830:084-32830:088.

-8510010076 Rev 0 to Pu Plant Operating Procedure KM-NP-36-19, "Treatment of Wet 24-Inch by 24-Inch Acid Filters." * Kerr-McGee Nuclear Corp. 75/08/08. 2pp. 32830:089-32830:092.

278 NONDOCKETED ITEMS

- 8510010081 Forwards application for source matl license. Expedited consideration of application appreciated.
HEWLETT, J.P. Kerr-McGee Corp. 1548. 69/05/09. NUSSBAUMER, D.A. Atomic Energy Commission. 1p. 32830:093-32830:093.
- 8510010089 Application for license, authorizing use of U for calibr & standardization of instruments & in research on radiation measurements.
* Kerr-McGee Corp. 1548. 69/05/09. Spp. 32830:094-32830:098.
- 8510010103 Forwards License SUB-986. Related info encl.
HARMON, D.F. Atomic Energy Commission. 69/05/20. HEWLETT, J.P. Kerr-McGee Corp. 2pp. 32830:099-32830:100.
- 8510010117 License SUB-986 for Kerr-McGee Corp. authorizing use of U.
HARMON, D.F. Atomic Energy Commission. 69/05/20. 1p. 32830:101-32830:101.
- 8510010121 Requests interpretation of licensing category for assessment of fee. License could be classified as storage due to burial of matl & proper licensing category would be 2B rather than 2A.
HEWLETT, J.P. Kerr-McGee Corp. 71/02/12. PRICE, E. Atomic Energy Commission. 2pp. 32830:102-32830:103.
- 8510010126 Insp rept on 740604-06 No violations noted. Major areas inspected: previous insp history, organization & administration, health physics organization, radiological procedures, personnel monitoring & effluents.
MURRAY, B., BROWN, J.D. Region 4, Dallas, Office of the Director. 74/07/12. 14pp. 32830:255-32830:268.
- 8510010127 Application for amend to License SUB-986, revising Item 7 to read "800 lb U."
VALENTINE, A.M. Kerr-McGee Corp. 1838. 71/03/30. LAYFIELD, R.L. Atomic Energy Commission. 2pp. 32830:104-32830:105.
- 8510010134 Advises of reason for delay in paying invoice L-1557-71. Invoice will be paid upon receipt of opinion from Div of State & License Relations.
HEWLETT, J.P. Kerr-McGee Corp. 71/03/03. Atomic Energy Commission. 1p. 32830:106-32830:106.
- 8510010135 Forwards plan to accomplish objectives re stopping & containing present leakage & preventing occurrence of further leakage in Raffinate Pond 2 at facility per 850925 request.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 2146. 74/10/25. MILLER, J.R. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830:269-32830:275.
- 8510010140 Responds to 710212 & 0303 ltr re Invoice L-1557-71. License authorizes use of matl for instrument calibr & other investigations. Application may be filed to amend license to authorize storage only if matl no longer used.
MILLER, W.O. Atomic Energy Commission. 71/03/26. HEWLETT, J.P. Kerr-McGee Corp. 1p. 32830:107-32830:107.
- 8510010142 Forwards Suppl 3 to "Applicant Environ Rept," presenting cost benefit discussion of alternate methods of raffinate disposal applicable to process considered to be technically feasible.
SHELLEY, W.J. Kerr-McGee Corp. 5982. 73/08/01. ROUSE, L.C. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:276-32830:276.
- 8510010148 Notices of issuance of Amend 1 to License SUB-986, revising Item 7 to reflect max possession limit of 364 kg source matl.
LAYFIELD, R.L. Atomic Energy Commission. 71/04/23. VALENTINE, A.M. Kerr-McGee Corp. 2pp. 32830:108-32830:109.
- 8510010150 Suppl 3 to "Applicant Environ Rept."
* Kerr-McGee Corp. 73/08/31. 20pp. 32830:277-32830:297.
- 8510010153 Forwards Insp Findings & Licensee Ack on 720526 of License SUB-986.
HYDER, J.E. Atomic Energy Commission. 72/06/01. VALENTINE, A.M. Kerr-McGee Corp. 1p. 32830:110-32830:110.
- 8510010159 Forwards response to questions & comments re environ assessment of expansion of UF6 facility capacity. Methods contemplated include returning sludges to Kerr-McGee mill site in State of NM & solidification & burial of sludge.
SHELLEY, W.J. Kerr-McGee Corp. 77/01/03. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 5pp. 32830:298-32830:302.
- 8510010160 Insp Find: gs & Licensee Ack on 720526 of License SUB-986. No non-compliance or unsafe conditions found.
* Region 4, Dallas, Office of the Director. 72/05/26. 1p. 32830:111-32830:111.
- 8510010164 Permit OK 0000191 for NPDES authority to discharge from facility into headwaters of RS Kerr Reservoir on Arkansas River.
WHITE, J.C. Environmental Protection Agency. 76/07/31. 13pp. 32830:303-32830:315.
- 8510010166 Application for amend to License SUB-986, revising Item 6 to reflect use of U & thorium source matl.
ROBERTSON, W.J. Kerr-McGee Corp. 5122. 72/09/13. LAYFIELD, R.L. Atomic Energy Commission, Directorate of Licensing. 3pp. 32830:112-32830:114.
- 8510010173 Application for amend to License SUB-986, authorizing use of 800 lb U & thorium for development of solvent extraction process for separation & purification of thorium.
* Kerr-McGee Corp. 85/09/05. 3pp. 32830:115-32830:117.
- 8510010174 Forwards corrected 770111 ltr transmitting suppl to rept for waste retention ponds, correcting date of ltr.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 5002. 77/01/11. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 1p. 32830:316-32830:316.
- 8510010181 Notices of issuance of Amend 6 to License SUB-986, revising Items 6 & 8 to reflect use of U & thorium source matl.
LAYFIELD, R.L. Atomic Energy Commission, Directorate of Licensing. 72/09/29. ROBERTSON, W.J. Kerr-McGee Corp. 1p. 32830:118-32830:118.
- 8510010183 Responds to 761019 request for info re environ assessment of UF6 facility & forwards rept describing drilling of additional core holes, info gained & data generated from tests conducted w/new holes. W/o encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/01/11. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 3pp. 32830:317-32830:319.
- 8510010187 Requests that all communications re AEC regulations, licensing activities & insp activities be directed to WJ Shelley. Copy of insp rept may be directed to plant manager of facility. Related documents encl.
PARKS, G.B. Kerr-McGee Corp. 73/04/19. MUNTZING, L.M. Atomic Energy Commission. 9pp. 32830:119-32830:129.
- 8510010224 Forwards application for renewal of License SUB-986. Related documents encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 1125. 74/04/30. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:130-32830:132.
- 8510010229 Responds to 761012 request for info re 761006 application for renewal of License SUB-1010. Response replaces 750627 application for license renewal. Frequency in Paragraph 5.7.4 revised to read "semimonthly," in response to Question 26.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 4085. 77/01/12. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 1p. 32830:320-32830:320.
- 8510010230 Application for amend to License SUB-986, renewing license to authorize use of thorium matls in solvent extraction process for separation & purification & U matl as radiation sources for experimental work.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/04/30. 2pp. 32830:133-32830:137.
- 8510010236 Application for amend to License SUB-1010, authorizing treatment of approx 160 acres of Kerr-McGee Corp land immediately south of facility w/max concentration of ammonium nitrate from treated raffinate.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 6273. 77/03/09. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 21pp. 32830:321-32830:341.
- 8510010242 Informs that well mods made during 770328-0405 to prevent leakage of Raffinate Pond 2. Revised monitor well location & well summary table encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/05/31. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 10pp. 32830:342-32830:351.
- 8510010243 Forwards application for renewal of License SUB-986.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 74/05/09. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:138-32830:138.
- 8510010247 Confirms 770726 telcon w/GJ Sinke re 770112 application for renewal of License SUB-1010. Addl info requested, including commitment to verify design exhaust vols by actual measurements when determining stack losses.
ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 77/08/01. SHELLEY, W.J. Kerr-McGee Nuclear Corp. 5pp. 32830:352-32830:358.
- 8510010248 Application for renewal of License SUB-986, authorizing use of thorium matls in solvent extraction process & U matls as radiation sources in experimental work, design & calibr of new instruments. Related documents encl.
* Kerr-McGee Corp. 74/05/09. 5pp. 32830:139-32830:143.
- 8510010254 Insp rept of License SUB-986 on 720526. No noncompliance noted. Major areas inspected: scope of licensee program, organization, administrative control, noncompliance & safety items.
* NRC - No Detailed Affiliation Given. 72/07/12. 6pp. 32830:144-32830:153.
- 8510010256 Forwards draft revised pages to License SUB-1010, incorporating changes discussed in 770726 telcon. Exception authorizing use of GMR canister for protection against combined HF & U particulate hazards requested.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 77/08/03. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 22pp. 32830:357-32830:376.
- 8510010261 Responds to 850520 request for revised dose estimates for expanded facility. Dose estimates for 50-mile radius will be provided promptly upon receipt of info from consultant. Calculated dose estimates encl.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 07360. 77/08/13. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 9pp. 32830:017-32830:026.
- 8510010263 Health & safety evaluation insp rept of facility on 700325. No noncompliance noted. Major areas inspected: records review, interview of persons responsible for administration & radiation safety aspects of program.
PAAS, H.L., BROWN, G.D. Atomic Energy Commission. 70/04/10. 9pp. 32830:154-32830:162.
- 8510010269 Forwards corrected Page 2 to 770813 submittal re estimated facility doses, correcting erroneous distance of first location.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 07362. 77/08/16. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 2pp. 32830:027-32830:028.
- 8510010271 Confirms 720530 telcon w/CR Buchanan re Kerr-McGee Corp application for amend to License SUB-1010, authorizing disposal of liquid wastes from UF6 plant by deep-well injection. Comments & recommendations requested.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/06/02. DEBUCHANNE, G. Interior, Dept. of Geological Survey. 2pp. 32830:163-32830:164.
- 8510010273 Forwards draft "Calculation of Potential Impact of Releases From Sequoyah UF6 Facility for Year 1976 & 2000." Estimate of data results in considerably lower dose estimate than 1972 calculation.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 07672. 77/09/16. ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety. 1p. 32830:029-32830:029.
- 8510010275 Follows up Chitwood 720530 call re application for amend to License SUB-1010, authorizing deep-well disposal of wastes from Sequoyah facility. Comments & recommendations re application requested.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/06/02. WARNER, D.L. Missouri, Univ. of Rolla, MO. 2pp. 32830:165-32830:166.
- 8510010279 Draft "Calculation of Potential Impact of Releases From Sequoyah UF6 Facility for 1976 & 2000."
* Kerr-McGee Corp. 07672. 77/09/16. 31pp. 32830:030-32830:060.
- 8510010280 Responds to 720602 request for recommendations & comments re Kerr-McGee Corp application for amend to License SUB-1010, authorizing disposal of liquid waste from UF6 plant by deep-well injection. New data does not address brine displaced.
DEBUCHANNE, G. Interior, Dept. of Geological Survey. 3333. 72/06/16. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:167-32830:168.

- 8510010285** Confirms 770929 request for written notification to State of OK Dept of Health Air Quality Svc. informing of proposed expanded UF6 production & requesting authorization for airborne effluents.
ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 77/09/30. SHELLEY, W.J. Kerr-McGee Corp. 3pp. 32831:061-32831:063.
- 8510010289** Advises that time required for review of application for amend to License SUB-1010 will be lengthened due to review of State of OK geological survey work. Review should be completed by end of June.
WARNER, D.L. Missouri, Univ. of, Rolla, MO. 3465. 72/06/16. BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:169-32830:169.
- 8510010294** Forwards 1 Younghein 771001 ltr expressing Citizens Action for Safe Energy concern that EIS for UF6 facility expansion be prepared. Formal ack of concern requested. Related info encl.
SPOTTS, C.B. Environmental Protection Agency. 07958. 77/10/25. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 3pp. 32831:064-32831:066.
- 8510010296** Ack receipt of 720616 ltr re intended review of State of OK geological study of Kerr-McGee plant site. Any readily available geological info re area should be considered in proposal evaluation.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 72/07/06. WARNER, D.L. Missouri, Univ. of, Rolla, MO. 1p. 32830:170-32830:170.
- 8510010300** Forwards updated drawing of 160-acre fertilizer test plot, per 770926 request.
SINKE, G.J. Kerr-McGee Nuclear Corp. 08089. 77/10/24. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 5pp. 32831:067-32831:071.
- 8510010303** Forwards Kerr-McGee Corp revised "Applicants Environ Rept" & supplemental "Applicants Environ Rept" re UF6 plant. Review of repts & comments requested.
ROTHFLEISCH, J. Atomic Energy Commission. 72/08/24. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 1p. 32830:171-32830:171.
- 8510010308** Insp Findings & Licensee Ack on 730409-11 of License SUB-1010. No noncompliance found. Related info encl.
* Region 4, Dallas, Office of the Director. 73/04/09. 2pp. 32831:072-32831:073.
- 8510010309** Comments on Kerr-McGee Corp revised & supplemental "Applicant Environ Rept," in response to 720824 request. Environ surveillance program & four air samplers wholly inadequate for job intended.
VAN DER HOVEN Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 5315. 72/09/25. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:172-32830:173.
- 8510010315** Confirms telcon w/Parks establishing 721120 meeting in Bethesda, MD per Kerr-McGee request.
BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 72/11/07. PARKS, G.B. Kerr-McGee Corp. 1p. 32830:174-32830:174.
- 8510010318** Draft insp rept of License SUB-1010 on 730409-11. No violations noted. Major areas inspected: scope & conditions of license, organization & administration facilities & equipment & radiological safety precautions.
HYDER, J.E., BRAUN, G.D. Region 4, Dallas, Office of the Director. 73/05/15. 12pp. 32831:074-32831:085.
- 8510010322** Discusses monitoring requirements to be specified if Kerr-McGee Corp allowed to use deep well for radioactive waste water injection. Well should be drilled approx 3,000 ft north of present well.
WARNER, D.L. Missouri, Univ. of, Rolla, MO. 3531. 72/11/27. BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:175-32830:176.
- 8510010327** Discusses telcon re attendance at 721120 meeting in Bethesda, MD requested by Kerr-McGee Corp concerning proposal for deep well disposal of wastes from facility. Participation encouraged.
BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 72/11/07. DEBUCHANAN, G. Interior, Dept. of, Geological Survey. 1p. 32830:177-32830:177.
- 8510010335** Forwards modified version of comments & questions provided of meeting per 721120 discussions. Response to comments & questions requested in order to proceed on schedule w/facility DES. W/o encl.
ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 72/12/04. SHELLEY, W.J. Kerr-McGee Corp. 1p. 32830:178-32830:178.
- 8510010341** Summarizes 721120 meeting w/Kerr-McGee Corp in Bethesda, MD re proposal for deep well disposal of low level waste. Deep well disposal might be approved for limited period of 5 yrs w/appropriate restrictions & monitoring requirements.
BUCHANAN, C.R. Atomic Energy Commission, Directorate of Licensing. 72/12/07. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:179-32830:180.
- 8510010349** Comments on relative merits of subsurface injection & waste holding ponds as two possible methods of handling raffinate waste at facility. Alternative to ponds should be developed. Related correspondence encl.
WARNER, D.L. Missouri, Univ. of, Rolla, MO. 72/12/22. MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 2pp. 32830:181-32830:183.
- 8510010356** Informs that on 721215, Shelley notified Nussbaumer of unfortunate accident resulting in delay of response to 721208 ltr. Response to questions enclosed. W/o encl.
DUNN, P.S. Kerr-McGee Corp. 72/12/29. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:184-32830:184.
- 8510010363** Responds to 721208 request for addl info re revised Nov 1971 environ rept & June 1972 supplemental environ rept. Design & current plant capacity is 5,000 tons per yr.
DUNN, P.S. Kerr-McGee Corp. 1124. 73/01/18. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 27pp. 32830:185-32830:214.
- 8510010368** Forwards most current ltr sent to Kerr-McGee Corp re denial of proposal to dispose of raffinate wastes from facility by deep well. Related info encl.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 73/02/16. DEBUCHANAN, G. Interior, Dept. of, Geological Survey. 10pp. 32830:215-32830:224.
- 8510010372** Requests review of Suppl 2 to environ rept re raffinate pond seepage. Comments requested at earliest opportunity.
ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 73/03/14. EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 1p. 32830:225-32830:225.
- 8510010391** Requests review of Suppl 2 to environ rept re raffinate pond seepage. Comments requested at earliest opportunity.
ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 73/03/14. WARNER, D.L. Missouri, Univ. of, Rolla, MO. 1p. 32830:226-32830:226.
- 8510010394** Expresses gratitude for courtesy & cooperation extended during 730321-22 plant visit to facility & confirms that addl items will be provided, including proposal re solvent extraction raffinate disposal.
MALARO, J.C. Atomic Energy Commission, Directorate of Licensing. 73/03/26. SHELLEY, W.J. Kerr-McGee Corp. 2pp. 32830:227-32830:228.
- 8510010398** Discusses addl info supplied on 730314 re Kerr-McGee EIS. Review concluded that high nitrate levels shown for Monitor Wells 1, 2 & 5 was result of contamination.
WARNER, D.L. Missouri, Univ. of, Rolla, MO. 2396. 73/03/28. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 1p. 32830:229-32830:229.
- 8510010401** Responds to 730326 request for addl info resulting from Malaro 730321-22 site visit & previous submittals of environ rept. Proposal re short-term treatment & ultimate solution to solvent extraction raffinate disposal encl.
SHELLEY, W.J. Kerr-McGee Corp. 2388. 73/04/09. ROUSE, L.C. Atomic Energy Commission, Directorate of Licensing. 5pp. 32830:230-32830:234.
- 8510010404** Forwards comments on raffinate pond seepage & air sampling. Review concluded that monitoring plan adequate. Air samplers should be moved out at least 1 mile.
EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 3510. 73/04/19. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830:235-32830:238.
- 8510010408** Forwards review & comments re significance of gross alpha, gross beta, radium & U in groundwater monitoring well samples, per 730530 request. Contamination w/soluble U indicated in most seepage wells.
EVANS, N.A. Colorado State Univ., Ft. Collins, CO. 4023. 73/06/15. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 3pp. 32830:239-32830:241.
- 8510010413** Responds to request for fluoride in air & vegetation data in 1973. Revised analytical procedure for determination of fluoride in air & stack gas samples & related info encl.
SHELLEY, W.J. Kerr-McGee Corp. 5965. 73/07/16. ROTHFLEISCH, J. Atomic Energy Commission, Directorate of Licensing. 7pp. 32830:242-32830:249.
- 8510010415** Discusses retention pond leakage noted during 740604-06 routine insp of License SUB-1010. Licensee drilled 10 addl seepage wells to help identify seepage areas.
BROWN, G.D. Atomic Energy Commission. 74/06/18. THORNBURG, H.D. Atomic Energy Commission, Directorate of Regulatory Operations. 2pp. 32830:250-32830:251.
- 8510010421** Insp Findings & Licensee Ack on 740604-06 of License SUB-1010. No noncompliance or unsafe conditions found.
MURRAY, B. Region 4, Dallas, Office of the Director. 74/06/04. 3pp. 32830:252-32830:254.
- 8510010061** Responds to FOIA request for documents from CRGR 850723-24 meeting re integral simulation test & inservice insp pump & valve programs. CRGR did not meet on 850723. No transcript or handouts made for 850724 meeting. Documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/19. SMITH, E.R. NUS Corp. 3pp. 32833:057-32833:059.
- 8510010064** Responds to FOIA request for correspondence NRC received from Barnes, Byron, Mathias & Sarbanes during past 2 yrs. Ltr identified on encl app placed in PDR. Forwards documents listed on app.
FELTON, J.M. Division of Rules and Records. 85/09/04. DEZUBE, D. Montgomery County Sentinel. 3pp. 32831:087-32831:196.
- 8406210273** Responds to 840524 ltr to Chairman Palladino re constituent LW Bussert concerns on licensing delays & impact on utils. Minimized delays key in NRC decision-making process.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/06/12. SARBANES, P.S. Senate. 4pp. 32831:117-32831:117.
- 8504100552** Responds to 850214 ltr forwarding J Zombo ltr re periodic checks of personnel for alcohol & drug abuse at nuclear facilities. Commission considering policy statement on issue.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/03/28. BYRON, B.B. House of Rep. 1p. 32831:145-32831:179.
- 8510010085** Informs of acceptance of nominations for eighth presentation of Congressional Excalibur Award. Deadline for nominations & summary of nominee achievements is 830830. Fact sheet describing award encl.
BARNES, M.D. House of Rep. 83/08/01. PALLADINO, N.J. Commissioners. 4pp. 32831:090-32831:093.
- 8510010093** Informs of acceptance of nominations for eighth presentation of Congressional Excalibur Award. Deadline for nominations & summary of nominee achievements is 830830. Fact sheet describing award encl.
BARNES, M.D. House of Rep. 83/07/28. BIRD, P.E. Division of Organization and Personnel. 4pp. 32831:094-32831:097.
- 8510010105** Nominates JE Moore for Congressional Excalibur Award. Dedication & initiative exhibited by Moore characteristic of fine performance & outstanding candidate for award.
DIRCKS, W.J. Office of the Executive Director for Operations. 83/10/11. BARNES, M.D. House of Rep. 2pp. 32831:098-32831:102.
- 8510010115** Responds to 831013 ltr re aid to retirees in connection w/health benefits & "open season" changes.
DIRCKS, W.J. Office of the Executive Director for Operations. 83/11/04. BARNES, W.J. House of Rep. 1p. 32831:103-32831:106.
- 8510010122** Forwards ltr from NRC employee re concern about possible relocation of employees from Montgomery County Cto to Washington, DC location. Requests that employees concern be addressed.
BYRON, B.B. House of Rep. 84/04/13. KAMMERER, C. Office of Congressional Affairs. 4pp. 32831:107-32831:110.

280 NONDOCKETED ITEMS

- 8510010132 Responds to request for NRC consideration of issue re NRC relocation of employees from Montgomery County to District of Columbia location. No major movement of NRC expected to take place.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/05/02. BYRON, B.B. House of Rep. 1p. 32831:111-32831:116.
- 8510010143 Forwards correspondence received from JC Morris re concerns about investigations on restart of TMI-1. Review of matter & response requested.
SARBANES, P.S. Senate. 84/05/30. Office of Congressional Affairs. 2pp. 32831:118-32831:119.
- 8510010157 Ack receipt of ltr on behalf of constituent, JC Morris, inquiry as to status of Commission decision on restart of TMI-1. On 840601, Commission issued and order requesting parties comments on subj question by 840615. W/o encl.
KAMMERER, C. Office of Congressional Affairs. ALAB-772. 84/06/04. SARBANES, P. Senate. 1p. 32831:120-32831:120.
- 8510010172 Forwards Washington Post 840712 article entitled, "NRC Engineer Resigns From Diablo Task Force." Info requested on NRC role in safety investigations.
BARNES, M.D. House of Rep. 84/07/12. PALLADINO, N.J. Commissioners. 2pp. 32831:121-32831:122.
- 8510010186 Ack receipt of ltr requesting info re status of licensing for facility Forwards Chairman Palladino & H Denton statements. Results of ACRS review also encl. W/o encl.
KAMMERER, C. Office of Congressional Affairs. 84/07/20. BARNES, M.D. House of Rep. 1p. 32831:123-32831:123.
- 8510010203 Forwards 850622 ltr to GP Shultz & list of questions re recent DOE approval of France to Japan Pu shipment. Input into Secretary of State response requested by 840905.
BARNES, M.D. House of Rep., Foreign Affairs. 84/06/22. PALLADINO, N.J. Commissioners. 5pp. 32831:124-32831:130.
- 8510010210 Forwards correspondence received from J Merryman re serious concerns about delay of restart of TMI-1. Response requested.
SARBANES, P.S. Senate. 84/10/11. KAMMERER, C. Office of Congressional Affairs. 2pp. 32831:131-32831:132.
- 8510010213 Ack receipt of inquiry on behalf of J Merryman re status of restart proceeding. Commission will undertake & complete review of ALAB-772. Forwards Commission 840911 orders & Commissioner Asseltine dissenting views. W/o encl.
KAMMERER, C. Office of Congressional Affairs. ALAB-772. 84/10/18. SARBANES, P.S. Senate. 1p. 32831:133-32831:133.
- 8510010221 Responds to request for consideration of issues raised in correspondence by NRC employee re possible relocation of NRC to alternative locations in either Montgomery County, MD or District of Columbia.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/12/05. BYRON, B.B. House of Rep. 6pp. 32831:134-32831:135.
- 8510010226 Requests response to encl ltr re proposed consolidation of otc space for NRC headquarters in Montgomery County.
BYRON, B.B. House of Rep. 84/10/31. KAMMERER, C. Office of Congressional Affairs. 4pp. 32831:136-32831:140.
- 8510010235 Ack receipt of 841102 ltr. Comment on use of highly enriched U in Univ research provided to all Commissioners for consideration.
KAMMERER, C. Office of Congressional Affairs. 84/11/08. BARNES, M. House of Rep. 1p. 32831:141-32831:141.
- 8510010334 Forwards J Zombro ltr re need for periodic checks of personnel for alcohol & drug abuse at nuclear facilities. Response requested.
BYRON, B.B. House of Rep. 85/02/14. PALLADINO, N. Commissioners. 3pp. 32831:142-32831:144.
- 8510010344 Forwards correspondence received from CF Jones re concerns about restart of TMI-1. Response requested.
SARBANES, P.S. Senate. 85/03/25. PALLADINO, N.J. Commissioners. 2pp. 32831:180-32831:181.
- 8510010362 Ack receipt of ltr re status of NRC deliberations on whether to lift immediate effectiveness of orders directing that TMI-1 remain shut down pending further order of Commission. No date set for public meeting.
KAMMERER, C. Office of Congressional Affairs. 85/04/17. SARBANES, P.S. Senate. 1p. 32831:182-32831:182.
- 8510010395 Informs of govt-owned bldg in Germantown, MD as possible location for otc of NRC. Bldg houses 1,000 employees of DOE & has capacity to house 2,500 people.
BYRON, B.B. House of Rep. 85/05/07. PALLADINO, N.J. Commissioners. 1p. 32831:183-32831:183.
- 8510010400 Responds to 850507 ltr re whether NRC considered consolidating into govt-owned bldg in Germantown, MD. NRC & GSA considering housing options in Bethesda, MD along Metro Red Line near Metro stations.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/03. BYRON, B.B. House of Rep. 1p. 32831:184-32831:184.
- 8510010405 Requests consideration of encl correspondence by VR Saterm re NRC handling of requests under FOIA on federal agency & GAO handling of bid protests.
MATHIAS, C.M. Senate. 85/05/23. Office of Congressional Affairs. 2pp. 32831:185-32831:186.
- 8510010412 Responds to 850523 ltr transmitting concerns raised by constituent, V Saterm re NRC contracting process. Employment Perspectives will be added to bidders mailing list as source for performance of future NRC requirements.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/26. MATHIAS, C.M. Senate. 2pp. 32831:187-32831:188.
- 8510010418 Forwards VR Saterm 850508 ltr re federal agency handling of requests under FOIA & GAO handling of bid protests. Review & advisement requested.
BARNES, M.D. House of Rep. 85/05/24. PALLADINO, N.J. Commissioners. 2pp. 32831:189-32831:190.
- 8510010436 Responds to 850524 ltr transmitting V Saterm concerns re NRC contracting process. Employment Perspectives will be added to bidders mailing list as source for performance of future NRC requirements.
DIRCKS, W.J. Office of the Executive Director for Operations. 85/06/26. BARNES, M.D. House of Rep. 2pp. 32831:191-32831:192.
- 8510010443 Forwards V Saterm ltr outlining concerns re bill received from NRC for FOIA request. Review & response to matter requested.
SARBANES, P.S. Senate. 85/06/26. PALLADINO, N.J. Commissioners. 1p. 32831:193-32831:193.
- 8510010450 Informs that Employment Perspectives will not be responsible for reproduction costs for requested matl. under FOIA, from Commission. Matls delivered too late to have any value to bid protest.
SATERN, V. Employment Perspectives. 85/06/04. Office of Resource Management, Director. 1p. 32831:194-32831:194.
- 8510010453 Ack receipt of 850626 ltr from V Saterm of Employment Perspectives re NRC handling of FOIA request. J Felton responded directly to Saterm ltr on 850618. Response encl.
KAMMERER, C. Office of Congressional Affairs. 85/07/03. SARBANES, P. Senate. 1p. 32831:195-32831:195.
- 8510010455 Responds to 850604 ltr to J Rodriguez re payment for FOIA 85-182 request. Request closed & bill received can be disregarded.
FELTON, J.M. Division of Rules and Records. 85/06/18. SATERN, V. Employment Perspectives. 1p. 32831:196-32831:196.
- 8510010066 Further response to FOIA request for documents re NRC insp of R Guna-balan clinics in Detroit, MI. Forwards documents listed in App B & nonexempt portion of Document 1 in App C. App C documents withheld (ref FOIA Exemption 7).
FELTON, J.M. Division of Rules and Records. 85/09/20. SMITH, B.B. Stark & Gordon. 6pp. 32831:197-32831:216.
- 8510010075 Notifies that Region III investigation of allegations re unshielded generator & lack of required documentation unwarranted. Alleged info not specific enough to evaluate for wrongdoing. Related info encl.
WEIL, C.H. Region 3, Office of Director. 84/08/02. HIND, J.A. Region 3, Office of Director. 11pp. 32831:206-32831:216.
- 8510010146 FOIA request for 5 categories of gummed mailing labels, in zip code order, re general waste mgt low level mgt site repts & U recovery operations.
JARVIS, P.B. Colorado State Univ., Ft. Collins, CO. 85/09/10. PJO, L.M.J. NRC - No Detailed Affiliation Given. 1p. 32833:060-32833:060.
- 8510010158 Responds to FOIA request for five categories of gummed mailing labels re low level waste, general waste mgt policies & procedures, U recovery operations & low level waste mgt site repts. Forwards labels. W/o encl.
FELTON, J.M. Division of Rules and Records. 85/09/24. JARVIS, P.B. Colorado State Univ., Ft. Collins, CO. 1p. 32833:061-32833:061.
- 8510010171 FOIA request for documents re Mars, Inc or KaiKan application for use of air irradiation process for sterilization of pet food at new KaiKan pet food processing facility.
FISCHMAN, A. Charles E. Simon & Co. 85/08/30. FELTON, J. Division of Rules and Records. 1p. 32833:062-32833:062.
- 8510010179 Responds to FOIA request for records re Mars, Inc or KaiKan application for use of irradiation process for sterilization of pet food at new KaiKan pet food processing facility. No documents found responsive to request.
FELTON, J.M. Division of Rules and Records. 85/09/20. FISCHMAN, A. Charles E. Simon & Co. 1p. 32833:063-32833:063.
- 8510010188 FOIA request for 11 categories of documents re Insp Repts 50-443/84-12 & 50-444/84-06.
GROSSBERG, S. Harmon, Weiss & Jordan. 85/08/08. FELTON, J.M. Division of Rules and Records. 5pp. 32833:064-32833:068.
- 8510010197 Final response to FOIA requests for 11 categories of documents re Insp Repts 50-443/84-12 & 50-444/84-06. Forwards documents listed on App B. Document 2 on app withheld (ref FOIA Exemption 6).
FELTON, J.M. Division of Rules and Records. 85/09/20. GROSSBERG, S. Harmon, Weiss & Jordan. 2pp. 32833:069-32833:071.
- 8510010200 Telcon w/J Asseltine on 850809 re facility allegations.
* NRC - No Detailed Affiliation Given. 84/08/09. 1p. 32833:071-32833:071.
- 8510010205 FOIA request for documents re location of commercial & military reactors, radioactive matl storage, radwaste disposal & nuclear weapons storage facilities in US.
BARRU, H. Affiliation Not Assigned. 85/09/10. Region 4, Office of Director. 1p. 32833:072-32833:072.
- 8510010207 Responds to FOIA request for records re location of commercial & military reactors, radioactive matl storage, waste disposal & nuclear weapons storage facilities in US. Forwards NRC 1984 annual rept. W/o encl.
FELTON, J.M. Division of Rules and Records. 85/09/24. BARRU, H. Affiliation Not Assigned. 1p. 32833:073-32833:073.
- 8510010218 Final response to FOIA request for records re CE Noralius & JW Cook 850322 ltr concerning 850110 BNL rept on EE Kent allegations. Documents in PDF. App E documents withheld (ref FOIA Exemptions 6 & 7).
FELTON, J.M. Division of Rules and Records. 85/09/20. GARDE, B.P. Government Accountability Project. 1p. 32833:074-32833:076.
- 8510010225 Further response to FOIA request for eight categories of records of E Kent allegations re facilities. Forwards App D documents. Documents also available in PDF. App E documents withheld (ref FOIA Exemptions 6 & 7).
FELTON, J.M. Division of Rules and Records. 85/09/20. RILLO, C.J. Theien, Martin, Johnson & Bridges. 3pp. 32833:002-32833:052.
- 8510010237 Summary of 820915 meeting w/util in Chicago, IL re proposed util investigation into GAP allegations concerning facilities. Util agreed to delay investigation until NRC completes investigation. Related info encl.
BACI, P.E. Office of Investigation. 82/09/20. Office of Investigation. 28pp. 32833:022-32833:049.
- 8510010244 Summarizes impressions & requests presented at 830624 meeting. Meeting was good start to better working relationship between Region V, GAP & Palo Verde Intervention Fund.
BERNABEIL, Government Accountability Project. 83/09/10. MARTIN, J. Region 5, Office of Director. 3pp. 32833:050-32833:052.

- 8510010251** Appeals denial of FOIA request for portions of transcript of 840711-12 interviews w/VM English re events at Wilmington, NC facility concerning spills or alleged spills.
SMITH, B.A. General Electric Co. 85/07/16. CHILK, S.J. Office of the Secretary of the Commission. 2pp. 32833-077-32833-078.
- 8510010265** Responds to appeal re denial of FOIA request for withheld portions of transcript of 840711-12 interviews w/VM English re events at Wilmington, NC facility. Forwards portions of transcript re spills or alleged spills.
CHILK, S.J. Office of the Secretary of the Commission. 85/09/23. SMITH, B.A. General Electric Co. 1p. 32833-079-32833-110.
- 8510010272** Portions of 840711-12 transcript of interview w/VM English re events at Wilmington, NC facility concerning spills or alleged spills. Pp 173-282.
* NRC - No Detailed Affiliation Given. 84/07/11. 29pp. 32833-080-32833-110.
- 8510010266** Responds to 840712 ltr refusing to process FOIA 84-206 due to lack of specificity. Records requested documenting problems w/subcontractors work & corrective actions taken.
BERNABEI, L. Government Accountability Project. 84/06/06. FELTON, J.M. Division of Rules and Records. 2pp. 32884-001-32884-004.
- 8510010283** Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDF.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L., HENDERSON, T. Government Accountability Project. 32pp. 32884-005-32896-001.
- 8312020438** Trip rept of 831104-05 site visit & meeting to formulate final objectives, guidance & schedule for initial full-scale exercise.
PERROTTI, D.J. Emergency Preparedness Branch. 83/11/21. Emergency Preparedness Branch. 9pp. 32894-309-32894-317.
- 8404050355** Summarizes 840306 telcon re insp of post-accident sampling sys per TMI Item II.B.2. Comments on 840301 memo provided.
KNIGHTON, G.W. Licensing Branch 3. 84/03/14. BANGART, R.L. Region 4, Office of Director. 45pp. 32884-235-32884-240.
- 8406150267** Requests that encl FEMA 840511 supplemental interim finding rept on offsite plans be transmitted to util. Rept addresses four offsite planning issues specified by ASLB.
MATTHEWS, D.B. Emergency Preparedness Branch. 84/06/07. KNIGHTON, G.W. Licensing Branch 3. 3pp. 32893-319-32893-321.
- 8408210595** Forwards RW Knm 840725 ltr forwarding rept on 840208 exercise of offsite radiological emergency preparedness plans for facility. Category B deficiencies identified.
MATTHEWS, D.B. Emergency Preparedness Branch. 84/08/16. BANGART, R.L. Region 4, Office of Director. 2pp. 32893-322-32893-323.
- 8510010287** Lesson Plan W3G-001-002MH-003, "General Employee Training, Station Security Plan." Related info encl.
HURSHMAN, M., LEDIT, J.J. Louisiana Power & Light Co. 84/03/02. 50pp. 32885-239-32886-107.
- 8510010295** Rev 2 to Maint Dept Procedure MC-1-011, "Development, Control & Distribution."
* Louisiana Power & Light Co. 83/08/11. 46pp. 32886-108-32886-153.
- 8510010297** Rev 2 to Calibr Procedure MI-5-118, "Calibr of Crimpers." Manual rev review forms & related documentation encl.
* Louisiana Power & Light Co. 83/10/24. 132pp. 32889-265-32890-040.
- 8510010361** Rev 3 to Administrative Procedure UNT-5-002, "Condition Identification & Work Authorization."
ALLEMAN, S.A. Louisiana Power & Light Co. 84/04/20. 51pp. 32886-154-32886-204.
- 8510010304** Rev 1 to Administrative Procedure MD-1-007, "Preventive Maint Task Identification."
HEREFORD, R.B. Louisiana Power & Light Co. 83/08/08. 60pp. 32890-168-32890-228.
- 8510010307** Rev 1 to Surveillance Procedure ME-3-327, "4.16 kV GE Magne-Blast Breaker."
ALLEMAN, S.A. Louisiana Power & Light Co. 84/03/09. 47pp. 32886-205-32886-251.
- 8510010310** Rev 0 to Procedure UNT-4-004, "Plant Correspondence Control."
* Louisiana Power & Light Co. 80/05/05. 26pp. 32890-229-32890-256.
- 8510010313** Rev 2 to Maint Procedure ME-4-131, "4.16 kV GE Magne-Blast Breaker."
* Louisiana Power & Light Co. 83/05/16. 117pp. 32886-252-32887-006.
- 8510010314** Rev 0 to Project Mgt Procedure PMP-004, "Control of Vendor Manuals."
* Louisiana Power & Light Co. 84/04/16. 22pp. 32890-257-32890-278.
- 8510010320** Requests review of encl draft Insp Rept 50-382/84-24. Related documentation encl.
GAGLIARDO, J. Region 4, Office of Director. 84/06/11. CRUTCHFIELD, D. Office of Nuclear Reactor Regulation, Director. CROSSMAN, B. NRC - No Detailed Affiliation Given. 51pp. 32887-007-32887-243.
- 8510010321** Rev 1 to Administrative Procedure UNT-4-007, "Control of Plant Manuals."
* Louisiana Power & Light Co. 80/12/10. 35pp. 32890-279-32890-314.
- 8510010326** Audit on 830119-0304 of environ monitoring program. Audit checklist for health physics program & related documentation encl.
ROBERTS, A.R., MORGAN, W.M. Louisiana Power & Light Co. 83/03/24. 169pp. 32884-037-32884-204.
- 8510010328** Rev 1 to Plant Engineering Procedure EP-2-005, "Plant Engineering Condition Identification Work Authorization Processing."
* Louisiana Power & Light Co. 83/06/28. 19pp. 32890-314-32891-009.
- 8510010332** Rev 0 to QA Plan QAP-3747, "Engineering/Technical Svcs to Perform Spare Parts Evaluation & Analysis." Related documentation encl.
* Burns & Roe Co. 82/12/31. 21pp. 32887-244-32887-264.
- 8510010333** Vol XIII to "Plant Operating Manual," "Health Physics Procedures."
* Louisiana Power & Light Co. 83/11/21. 15pp. 32884-205-32884-222.
- 8510010339** Rev 0 to Maint Procedure MM-6-002, "Valve Operator Repair."
ALLEMAN, S.A. Louisiana Power & Light Co. 81/08/12. 12pp. 32887-265-32887-276.
- 8510010342** Rev 0 to Project Mgt Procedure PMP-002, "Document Control."
* Louisiana Power & Light Co. 84/03/01. 39pp. 32891-010-32891-022.
- 8510010343** Rev 0 to Nuclear Administrative Procedure NAP-220, "Radiation Control Section Overview." WM Morgan 840828 interofc memo re NRC review of radiation protection. Radwaste Program Insp 84-38 & 840820-24 encl.
* Louisiana Power & Light Co. 83/01/05. 8pp. 32884-223-32884-230.
- 8510010345** Rev 2 to Surveillance Procedure ME-3-310, "Calibr of Time Delay Relays." Related documentation encl.
ALLEMAN, S.A. Louisiana Power & Light Co. 84/04/16. 222pp. 32887-277-32888-138.
- 8510010348** Rev 0 to Surveillance Procedure CP-903-106, "Plant Protection Sys Channel 'D' Functional Test." Related info, including ITT electronic transmitter manual, encl.
* Louisiana Power & Light Co. 83/12/13. 282pp. 32891-323-32892-244.
- 8510010350** Rev 1 to Administrative Procedure PE-2-014, "Equipment Environ Qualification."
* Louisiana Power & Light Co. 84/01/15. 53pp. 32891-023-32891-074.
- 8510010351** Rev 4 to QC Procedure WQC-50, "Equipment Hanging & Setting Insp." MCKENZIE, J.H., HEISER, L., DEDAMM, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/12/09. 7pp. 32888-139-32888-145.
- 8510010354** Discusses Insp Rept 50-382/84-05 open items re post-accident sampling sys design & operability. Physical layout of sys described. No leakage should be allowed at mechanical couplings in wing area of reactor auxiliary bldg.
BANGART, R.L. Division of Vendor & Technical Programs. 84/03/01. KNIGHTON, G.W. Licensing Branch 3. 4pp. 32884-231-32884-234.
- 8510010357** Rev 0 to Nuclear Administrative Procedure NAP-504, "Implementation of Operations Assessment & Info Dissemination Program."
WOLFE, R. Louisiana Power & Light Co. 102/12/26. 161pp. 32891-075-32891-236.
- 8510010358** Rev 0 to Maint Procedure MM-6-012, "Structural Bolt Tensioning."
* Louisiana Power & Light Co. 82/05/26. 27pp. 32888-146-32888-172.
- 8510010360** Rev 2 to Surveillance Procedure MM-3-015, "Emergency Diesel Engine Insp." Related info encl.
HALL, B. Louisiana Power & Light Co. 84/06/04. 175pp. 32892-243-32893-065.
- 8510010364** Rev 2 to Maint Procedure ME-7-001, "Insulation Resistance & Continuity Testing." Related info encl.
* Louisiana Power & Light Co. 83/06/24. 65pp. 32891-237-32891-301.
- 8510010365** Rev 0 to Maint Procedure MM-6-011, "General Torquing & Detensioning." Limtorque instruction & maint manuals encl.
* Louisiana Power & Light Co. 82/03/04. 216pp. 32888-173-32889-025.
- 8510010367** Rev 1 to Surveillance Procedure MM-3-015, "Emergency Diesel Engine Insp." Related info encl.
HALL, B., ALLEMAN, S.A. Louisiana Power & Light Co. 84/03/19. 87pp. 32893-066-32893-152.
- 8510010369** Rev 1 to "Plant Protection Sys Field Mod Procedure for Louisiana Power & Light."
ROBERTS, T.F., YANOSY, P.L. Louisiana Power & Light Co. 83/03/30. 21pp. 32891-302-32891-322.
- 8510010371** Rev 0 to PMD-Y83-061, "Plant Lubrication Manual."
* Louisiana Power & Light Co. 85/02/27. 98pp. 32889-026-32889-122.
- 8510010373** Rev 1 to Maint Procedure MM-4-001, "Lubrication Procedure."
* Louisiana Power & Light Co. 82/12/29. 23pp. 32889-123-32889-145.
- 8510010375** Forwards input from Physical Security Section for 1982-1983 facility SAI. P rept. Related info, including Westinghouse maint manual, encl.
KELLY, J.A. Region 4, Office of Director. 83/08/29. CONSTABLE, L. Region 4, Office of Director. 150pp. 32893-153-32893-301.
- 8510010376** Rev 0 to Departmental Procedure MD-01-010, "Plant Lubrication Program."
EPPERSON, W.A. Louisiana Power & Light Co. 83/04/14. 7pp. 32889-146-32889-152.
- 8510010380** Rev 1 to Maint Procedure ME-13-019, "Motor Bearing Replacement & Motor Cleaning."
* Louisiana Power & Light Co. 83/04/06. 23pp. 32889-153-32889-175.
- 8510010381** Rev 0 to Maint Procedure ME-4-701, "Greasing Electrical Equipment."
* Louisiana Power & Light Co. 82/11/11. 9pp. 32889-176-32889-184.
- 8510010384** Advises that util has scheduled emergency exercise for score on 850208 w/State of LA, St Charles Parish & St John the Baptist Parish. Mats will be submitted for review.
COOK, K.W. Louisiana Power & Light Co. W3P83-3752. 83/11/09. COLLINS, J.T. Region 4, Office of Director. 1p. 32893-302-32893-302.
- 8510010388** Forwards 10CFR50.55(e) Part 21 rept from TVA re generic problem w/ hydrogen detection sys integrity. Followup on generic aspects w/AE/vendor requested. Supporting documentation encl.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15. Region 4, Dallas, Vendor Inspection Branch. 327pp. 32884-241-32885-206.
- 8510010392** Forwards facility emergency preparedness exercise summary for review. Exercise scheduled on 830525 W/o encl.
MAURIN, L.V. Louisiana Power & Light Co. W3F83-0206. 83/04/15. COLLINS, J.T. Region 4, Office of Director. 1p. 32893-303-32893-303.
- 8510010393** Forwards Insp Rept 99900734/82-02 on 820413-14 at Corns, Inc re extent of qualification testing of Delphi Instruments Div hydrogen analyzer, per IEEE Std 323-1974. Allegations re inadequacy unsubstantiated.
JOHNSON, E.H. Region 4, Office of Director. 82/09/01. JOHNSON, A.D. Region 5, Office of Director. 1p. 32885-207-32885-207.

282 NONDOCKETED ITEMS

- 8510010395 Forwards facility full-scale emergency preparedness exercise objectives for review. Exercise scheduled for 830413. W/o encl.
MAURIN, L.V. Louisiana Power & Light Co. W3F83-0109. 83/02/25. COLLINS, J.T. Region 4, Office of Director. 1p. 32893-304-32893-304.
- 8510010397 Confirms 810319 telcon re Insp Rept 99900734/81-01 on 810406-09. Insp will relate to QA program implementation.
POTAPOVS, U. Vendor Inspection Branch. 81/03/20. PUGH, J. Comisp, Inc. 1p. 32885-208-32885-208.
- 8510010399 Forwards description of objectives & summary of events for facility full-scale emergency preparedness exercise scheduled on 830413. W/o encls.
MAURIN, L.V. Louisiana Power & Light Co. W3F83-0032. 83/01/26. COLLINS, J.T. Region 4, Office of Director. 2pp. 32893-305-32893-318.
- 8510010402 Advises that listed Comisp, Inc. Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl.
POTAPOVS, U. Vendor Inspection Branch. 81/07/01. LEWIS, R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885-209-32885-217.
- 8510010420 Forwards 10CFR50.55(e)/Part 21 rept received from utility re failure of contaminated gas monitor sys pump. Followup of generic aspects requested.
MURPHY, C.E. Region 2, Office of Director. 80/05/01. Region 4, Office of Director. 21pp. 32885-218-32885-236.
- 8510010423 Advises that transportation support ltr of agreement should be withheld from public due to proprietary nature, per 10CFR2.790.FEMA 840622 memo re supplemental findings encl.
COOK, K.W. Louisiana Power & Light Co. W3P84-1960. 84/08/01. KNIGHTON, G.W. Licensing Branch. 3. 4pp. 32893-324-32893-327.
- 8510010424 Rev 1 to Calibr Procedure MI-5-121, "Calibr of Burndy Hypress Crimpers."
* Louisiana Power & Light Co. 84/02/08. 18pp. 32889-185-32889-203.
- 8510010427 Rev 0 to Maint Procedure ME-4-810, "Low Voltage Power Cable Terminations & Splices."
* Louisiana Power & Light Co. 83/12/31. 38pp. 32889-204-32889-241.
- 8510010430 Draft ltr forwarding NRR draft SALP input for review. Comments received by 830626 will be considered in final rept.
WILSON, J.H. Licensing Branch. 3. 85/02/27. EISENHUT, D.G. Division of Licensing. MATTSOHN, R. Division of Systems Integration (post 811005). VOLLMER, R. Division of Engineering. 6pp. 32893-328-32894-003.
- 8510010431 Rev 0 to Maint Procedure ME-4-811, "Medium & High Voltage Cable Terminations & Splices."
* Louisiana Power & Light Co. 82/01/25. 23pp. 32889-242-32889-264.
- 8510010432 Rev P to Procedure TBP-26, "Visual Insp Procedure."
* Tompkins-Beckwith, Inc. 83/06/15. 34pp. 32893-174-32893-207.
- 8510010435 "Waterford 3 Steam Electric Station 1983 Annual Emergency Preparedness Exercise."
* Louisiana Power & Light Co. 83/12/31. 43pp. 32894-004-32894-052.
- 8510010439 Rev I to Procedure TBP-18, "QA Records Control."
* Tompkins-Beckwith, Inc. 83/01/10. 21pp. 32894-208-32894-234.
- 8510010441 Rev E to Procedure TBP-8, "QA Audits."
* Tompkins-Beckwith, Inc. 81/03/25. 48pp. 32894-235-32894-282.
- 8510010442 Forwards public version of changes to facility emergency plan & procedures. Revs will be completed by 840504.
LEDDICK, R.S. Louisiana Power & Light Co. W3F84-0029. 84/02/21. Office of Nuclear Reactor Regulation, Director. 1p. 32894-053-32894-053.
- 8510010444 Public version of changes to "Waterford 3 Emergency Plan."
* Louisiana Power & Light Co. 84/02/21. 77pp. 32894-054-32894-131.
- 8510010447 Responds to Emergency Preparedness Followup Appraisal Rept 50-382/84-02 Table 5-1 of emergency plan revised re augmentation capability for supporting onshift organization, per NRC 840329 ltr.
LEDDICK, R.S. Louisiana Power & Light Co. W384-0057. 84/04/25. JOHNSON, E.H. Region 4, Office of Director. 25pp. 32894-283-32894-307.
- 8510010448 Informs that rept of Waterford emergency exercise will not be submitted due to cancellation of exercise.
HICKEY, E.E. Battelle Memorial Institute, Pacific Northwest Laboratories. 83/06/01. HACKNEY, C.A. Region 4, Office of Director. 1p. 32894-308-32894-308.
- 8510010449 Public version of changes to emergency plan implementing procedures, including Rev 3 to EP-1-010, "Unusual Event," Rev 3 to EP-1-020, "Alert," Rev 3 to EP-1-030, "Site Area Emergency" & Rev 3 to EP-1-040, "General Emergency."
* Louisiana Power & Light Co. 84/02/21. 37pp. 32894-132-32894-173.
- 8510010454 Confirms 830408 telcon re requested one wk extension of deadline for submission of Waterford exercise scenario.
COLLINS, S.C. Louisiana, State of. 83/04/12. HACKNEY, C. Region 4, Office of Director. 75pp. 32894-310-32895-123.
- 8510010457 Forwards Safety Insp Rept 50-382/84-20 Areas examined include implementation of fire protection program & compliance w/10CFR50 App R. Listed open items referred to NRR for resolution. Meeting requested.
COLLINS, J.T. Region 4, Office of Director. 84/07/13. VOLLMER, R.H. Division of Engineering. 21pp. 32895-035-32895-055.
- 8510010458 Rev 1 to Administrative Procedure UNT-3-003, "General Employee Training."
ALLEMAN, S.A. Louisiana Power & Light Co. 84/02/11. 28pp. 32895-056-32895-063.
- 8510010460 Rev 1 to Technical Procedure NE-1-001, "New Fuel Shipping Container Operation."
STARKEY, R.S., RYALL, R.K. Louisiana Power & Light Co. 82/11/30. 29pp. 32895-084-32895-112.
- 8510010461 Rev 1 to Technical Procedure NE-1-002, "New Fuel Receipt Insp."
STARKEY, R.S. Louisiana Power & Light Co. 82/11/23. 1,451pp. 32895-113-32899-123.
- 8510020191 Rev 0 to Procedure 753-ET-1, "Environ Test Plan for Device Qualification to IEEE 323-1971."
MARROW, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/09/15. 6pp. 32890-035-32890-040.
- 8510020194 Rev 0 to Reliance Test Rept 753.1, "Environ Test Program for Twenty-One Components."
MARROW, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/10/30. 6pp. 32890-041-32890-046.
- 8510020199 Rev 1 to Maint Procedure ME-4-809, "Low Voltage Control Cable Terminations & Splices."
* Louisiana Power & Light Co. 83/12/29. 18pp. 32890-047-32890-064.
- 8510020202 Rev 1 to Spec MC-1, "General Specs Covering Installation of Mechanical Equipment." Field change requests encl.
BENNETT, J.G. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/10/29. 45pp. 32890-065-32890-109.
- 8510020207 Rev 0 to QC Procedure WQC-52, "Containment Fan Covers - Installation Insp." Product assurance calibr records encl.
BERRY, R.B., STINSON, L.A. Ebasco Services, Inc. (subs. of Enserch Corp.). 79/05/23. 16pp. 32890-110-32890-125.
- 8510020211 Rev 0 to QC Procedure WQC-50, "Equipment Hanging & Setting Insp."
BERRY, R., STINSON, L. Ebasco Services, Inc. (subs. of Enserch Corp.). 79/05/23. 5pp. 32890-126-32890-130.
- 8510020216 Spec 501-76, "High-Strength Bolted Field Connections for Structural Steel."
* Ebasco Services, Inc. (subs. of Enserch Corp.). 85/02/27. 11pp. 32890-131-32890-141.
- 8510020221 Forwards 10CFR50.55(e)/10CFR21 rept. Problem appears to be generic. Followup requested. Record of 810211 telcon encl.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/02/13. Region 4, Dallas, Vendor Inspection Branch. 4pp. 32890-142-32890-145.
- 8510020229 Draft Issue C of Procedure ASP-IV-22, "Unloading &/or Handling Heavy or Specialized Equipment."
MEARKLE, J. Ebasco Services, Inc. (subs. of Enserch Corp.). 82/02/09. 6pp. 32890-146-32890-151.
- 8510020236 Draft Issue H of Procedure CP-425, "Insulation Resistance Testing of Rotating Electrical Equipment & Power Cables 480-Volt Svc & Above."
MURTHA, M. Ebasco Services, Inc. (subs. of Enserch Corp.). 80/05/13. 6pp. 32890-152-32890-157.
- 8510020245 Part 21 rept re pump diaphragm failures. Initially reported on 800403. Caused by closure of containment isolation valves w/o pump shutdown. Bypass kit available to limit pump pressure. Defects not reportable per 10CFR21.
ROBINSON, A. Comisp, Inc. 81/04/08. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 3pp. 32890-158-32890-160.
- 8510020254 Part 21 rept re broken motor shaft on Reliance Electric Co. motors supplied to Comisp. Initially reported on 800616. Corrective actions revised design included in all subsequent motors. Applicable manual & related info encl.
WHEELER, G.L. Reliance Electric Co. (subs. of Exxon Corp.). 84/05/11. BOARDMAN, J. Region 4, Dallas, Office of the Director. 7pp. 32890-161-32890-167.
- 8510010355 FOIA request for power plant exam results summary sheets for listed plants.
HANAUER, S.H. Technical Analysis Corp. 85/08/13. Office of Administration. 2pp. 32832-352-32832-353.
- 8510010387 Responds to FOIA request for power plant exam results summary sheets for 10 listed plants. Forwards summary sheets for five plants. Portions deleted. Summary sheets for stated plants destroyed.
FELTON, J.M. Division of Rules and Records. 85/09/20. HANAUER, S.H. Technical Analysis Corp. 1p. 32832-354-32833-001.
- 8510010428 Power plant exam results summary sheets info deleted.
* Public Service Electric & Gas Co. of New Jersey. * Pennsylvania Power & Light Co. * Commonwealth Edison Co. 85/09/20. 9pp. 32832-355-32833-001.
- 8510080023 Responds to FOIA request for ACRS documents re facility. Forwards App B documents App A & B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/09/30. BRUNNER, J.E. Consumers Power Co. 11pp. 32929-003-32934-092.
- 8204120124 Forwards branch SER input. Sections 2.5.5 re stability of slopes & 2.5.6 re embankment & dams, essentially complete. Section 2.5.4 re stability of subsurface mats & foundations, remains open & impacted by ASLB hearings.
LEAF, G. Hydrologic & Geotechnical Engineering Branch. 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 17pp. 32929-213-32929-229.
- 8204210531 Forwards Structural Engineering Branch SER input re FSAR Chapter 3 on design of Category I structures. Evaluation will be completed upon submittal of info re soil remedial actions & new site-specific response spectra.
KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/05. TEDESCO, R.L. Assistant Director for Licensing. 2pp. 32929-161-32929-162.
- 8204290608 Forwards geological & seismological input to SER for OL.
KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/04/06. TEDESCO, R.L. Assistant Director for Licensing. 28pp. 32929-185-32929-212.
- 8208030689 Recommends that design & const audit recommended by ACRS be performed by competitor to assure highest possible degree of objectivity & independence.
STAMIRIS, B. Stamiris, B. 82/07/28. TEDESCO, R.L. Assistant Director for Licensing. 1p. 32930-075-32930-075.
- 8209020126 Requests info on factors entering into cost of adding safety-grade high level trip on each steam generator.
FISCHER, D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/06/28. HERNAN, R. NRC - No Detailed Affiliation Given. 17pp. 32930-058-32930-074.

- 8510080033 Forwards project status rept for ACRS Subcommittee on Midland Plant 820602 meeting in Washington,DC to review application for OL Related info encl. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/28. OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 57pp. 32929-014-32929-070.
- 8510080038 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Chicago,IL to discuss radioactive matl in process steam,potential for subsidence,seismic design criteria, emergency plans & flood protection level. MCKINLEY,J.C. Atomic Energy Commission. 70/04/15. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929-073-32929-074.
- 8510080045 Forwards summary of 700312 meeting w/uttl & JT Wilson in Bethesda,MD re subsidence problem under site.General subsidence could occur,but not abrupt offset.Abrupt offset or scarping could not be tolerated. MCKINLEY,J.C. Atomic Energy Commission. 70/03/19. SQUIRES,L. Atomic Energy Commission. 11pp. 32929-075-32929-085.
- 8510080049 Submits agenda for ACRS Subcommittee on Midland Plant 700324 meeting in Washington,DC to discuss items,including emergency plans,adequacy of ESF & protection sys,control room design & ECCS initiation signals. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/03/18. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-086-32929-086.
- 8510080051 Submits agenda for ACRS Subcommittee on Midland Plant 700424 meeting in Washington,DC to discuss emergency plans,adequacy of ESF & protection sys,containment design,siting of ECCS reservoir & steam purity & monitoring. MCKINLEY,J.C. Atomic Energy Commission. 70/03/12. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-087-32929-087.
- 8510080055 Summarizes meeting w/uttl re Dow Chemical Co solution mining of salt.Calculations of stress levels at or near surface of bedrock required. WILSON,J.T. Affiliation Not Assigned. 70/03/18. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-088-32929-088.
- 8510080061 Submits schedule & agenda for ACRS Subcommittee on Midland Plant 690204 meeting to discuss meteorology,dose calculations,containment leakage rates,containment iodine removing sys & evacuation procedures.Related info encl. HARD,J.E. Atomic Energy Commission. 69/01/29. MULLER,D. Atomic Energy Commission. 22pp. 32929-089-32929-110.
- 8510080073 Summary of 700422 meeting w/uttl & Dow Chemical Co re radioactivity of process steam to be exported to Dow.FDA recommended detector to continuously monitor activity of steam Related info encl. MCKINLEY,J.C. Atomic Energy Commission. 70/04/23. SQUIRES,L. Atomic Energy Commission. 5pp. 32929-111-32929-115.
- 8510080083 Telex memorandum & order to ACRS to send "original package" (ref 761123 ltr) for in camera review & written explanation of oral explanation for determination of public availability. HEAD,D. Atomic Safety and Licensing Board Panel. 76/11/30. FRALEY,R.F., MITCHELL,P. NRC - No Detailed Affiliation Given. 1p. 32929-116-32929-116.
- 8510080088 Forwards draft FR notice re ACRS Subcommittee 820429 meeting Portions of meeting may be closed. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/04/07. HOYLE,J.C. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 32929-117-32929-119.
- 8510080094 Forwards ACRS 761118 supplemental rept & attached matl for in camera review by ASLB & parties to Midland hearing,per 761130 request. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 76/12/01. HEAD,D.M. Atomic Safety and Licensing Board Panel. 2pp. 32929-120-32929-121.
- 8510080100 Forwards 770128 request for addl info re ACRS 761201 supplemental rept on Midland.Suppemental rept encl. Discussion in 770210-12 meeting & possible action during Mar 1977 full committee meeting planned. LIBARKIN,M.W. ACRS - Advisory Committee on Reactor Safeguards. 77/02/04. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32951-026-32951-026.
- 8510080107 Forwards Special Insp Rept 50-330/77-02 on 770228 & 0301. HEISHMAN,R.F. Region 3, Office of Director. 77/03/15. HOWELL,S.H. Consumers Power Co. 2pp. 32929-124-32929-125.
- 8510080113 Const Insp Rept 50-330/77-02 on 770228-0301.Noncompliance noted:failure to rept bulge deficiency per 10CFR50.55(e)(2). Related info encl. YIN,I.T., HAYES,D.W. Region 3, Office of Director. 77/03/15. 18pp. 32929-126-32929-143.
- 8510080127 Forwards 10CFR30-36 & 150 for info in connection w/review of Midland.W/o encl. FRALEY,R.F. Atomic Energy Commission. 70/04/28. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-144-32929-144.
- 8510080132 Summary of briefing of ACRS Subcommittee Chairman L Squires on AEC requirements/plans re licensing of Midland &/or Dow Chemical Co for use of secondary steam from facility. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/05/01. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32929-145-32929-150.
- 8510080143 Forwards schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington,DC to discuss uttl remedial action re soils & structural settlement issues. FISCHER,D. NRC - No Detailed Affiliation Given. 82/04/14. SIESS,C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929-151-32929-154.
- 8510080158 Confirms conversation re 820426 meeting in Jackson,Mi to discuss SALP SALP Board finding encl. HIND,J.A. Division of Emergency Preparedness & Operational Support. 82/04/20. COOK,J.W. Consumers Power Co. 4pp. 32951-021-32951-023.
- 8510080239 Forwards,for review, seismic site-specific spectra info,per telcon & request by D Okrent.Comments will determine discussion topics at ACRS Subcommittee on Midland 820520-21 meetings. FISCHER,D.C. NRC - No Detailed Affiliation Given. 82/04/09. POMEROY,P., TRIFUNAC,M. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929-159-32929-160.
- 8510080248 SER input re design of Category 1 structures & remedial actions.Completion of SER controlled by uttl response to NRC request for info re soil remedial actions. * Structural Engineering Branch. 82/04/05. 22pp. 32929-163-32929-184.
- 8510080262 Discusses 820407 telcon re ACRS subcommittee 840429 meeting on soils matters.Discussion will focus on remedy rather than cause of soil problem. HOOD,D. Licensing Branch 4. 82/04/07. FISCHER,D. NRC - No Detailed Affiliation Given. 10pp. 32929-230-32929-239.
- 8510080272 Forwards SER input.Outstanding issues listed,including flood protection of settled structures & adequacy of dewatering sys.Related info encl. LEARG, Hydrologic & Geotechnical Engineering Branch. 85/09/30. ADENSAM,E. Licensing Branch 4. 69pp. 32929-242-32929-309.
- 8510080277 Notification of 760521 meeting w/uttl in Bethesda,MD to discuss criteria to be used for analysis of high energy line breaks.Related info encl. CROCKER,L.P. NRC - No Detailed Affiliation Given. 76/05/01. KNEELK. NRC - No Detailed Affiliation Given. 5pp. 32929-310-32929-314.
- 8510080284 Summary of 760521 meeting w/uttl in Bethesda,MD re proposed high energy line break analysis.Agenda encl. MULLER,R. ACRS - Advisory Committee on Reactor Safeguards. 76/05/24. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929-315-32929-318.
- 8510080295 Requests copies of ACRS documents re Midland be forwarded to Chairman Okrent & other ACRS members. STAMIRIS,B. Stamiris, B. 82/05/30. FISCHER ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-319-32929-319.
- 8510080302 Statement before ACRS Subcommittee on Midland Nuclear Plant re alleged QC problems.Public confidence in licensing process lost. SINCLAIR,M. Affiliation Not Assigned. 82/06/04. 21pp. 32929-320-32929-340.
- 8510080309 Advises that ACRS concurred w/proposed staff position re diverse reactor trip signal during 127th meeting. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/11/18. PRICE,H.L. Atomic Energy Commission. 2pp. 32929-341-32929-342.
- 8510080329 Forwards summary of info from Category B repts.ACRS action unwarranted. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/07/13. SQUIRES,L. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32929-343-32929-344.
- 8510080337 Notices of ACRS Subcommittee on Midland Plant 700914 meeting in Washington,DC to discuss containment design pressure change,tertiary steam sys & tertiary steam generator design.Related info encl. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/08/28. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32929-345-32929-348.
- 8510080341 Notices of ACRS Subcommittee on Midland Plant 700610 meeting in Washington,DC to discuss ATWS,design approaches, addl primary sys safety valve capacity & process steam purity & monitoring. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/14. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32929-349-32929-349.
- 8510080349 Forwards summary of info in Category B repts.ACRS action unwarranted.Related info encl. MCKINLEY,J.C. ACRS - Advisory Committee on Reactor Safeguards. 70/05/20. SQUIRES,L., BUSH,S.H. ACRS - Advisory Committee on Reactor Safeguards. 9pp. 32929-350-32929-358.
- 8510080357 Documents conclusions reached during ACRS 122nd meeting re Midland Plant Units 1 & 2 request for exemption to allow certain const & ESF instrumentation for Indian Point 2. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards. 70/06/17. MORRIS,P.A. Atomic Energy Commission. 2pp. 32929-359-32929-360.
- 8510080367 Statement of C Anderson before ACRS subcommittee 820520-21 meetings re review of application for OL.Statement addresses soil/structure interaction problems.Addenda 1 & 2 encl. ANDERSON,C. A A Engineering. 82/05/20. 3pp. 32929-361-32930-001.
- 8510080373 Forwards statement of B Stamiris before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of uttl application for OL.Statement addresses misrepresented or overlooked issues re soil settlement. STAMIRIS,B. Stamiris, B. 82/05/20. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930-002-32930-005.
- 8510080379 Statement of MP Sinclair before ACRS Subcommittee on Midland Plant 820520-21 meetings re review of application for OL. Statement addresses plant design & qualification deficiencies. SINCLAIR,M.P. Sinclair, M. 82/05/20. 3pp. 32930-006-32930-008.
- 8510080386 Forwards written statement of C Anderson,MP Sinclair & B Stamiris submitted for ACRS subcommittee 820520-21 meetings.C Anderson statement includes Addenda 1 & 2. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. ACRS - Advisory Committee on Reactor Safeguards. DENTON,H. Office of Nuclear Reactor Regulation, Director. EISENHUT,D. Division of Licensing. 1p. 32930-009-32930-009.
- 8510080391 Forwards tentative schedule for ACRS Subcommittee on Midland Plant 820602 meeting to continue review of application for OL.Topics include fire protection,control room habitability & items from 820520-21 meetings. FISCHER,D.C. ACRS - Advisory Committee on Reactor Safeguards. 82/05/25. OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930-010-32930-015.
- 8510080394 Forwards proposed summary re ACRS Subcommittee on Midland Plant 820520-21 meetings to review application for OL.List of attendees & meeting highlights,agreements & requests included. FISCHER,D. ACRS - Advisory Committee on Reactor Safeguards. 82/06/21. OKRENT,D. ACRS - Advisory Committee on Reactor Safeguards. 10pp. 32930-016-32930-025.

284 NONDOCKETED ITEMS

- 8510080397 Forwards project status rept for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL Rept summarizes ACRS review to date, open items, ACRS actions required & requests for public participation. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/17. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 16pp. 32930-026-32930-041.
- 8510080403 Forwards tentative schedule for ACRS Subcommittee on Midland 820520-21 meetings to review application for OL. Discussion topics include quality of design & const, alternate shutdown, seismic criteria & PRA mgt. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/12. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 6pp. 32930-042-32930-049.
- 8510080409 Urges serious consideration of const problems at plant site, rated one of five worst nuclear plants in country per W. Dirks May 1981 testimony before Congress. Util should be held accountable for public safety. GARDE, B.P. Government Accountability Project. 83/01/11. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. SIESS, C. Illinois, Univ. of, Urbana, IL. 8pp. 32930-050-32930-057.
- 8510080420 Forwards proposed summary of ACRS Subcommittee on Midland 820602 meeting review of application for OL for review & comment. Corrections & additions will be included in minutes of meeting. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/08/11. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 32930-076-32930-080.
- 8510080426 Forwards Midland Hearing Board request for further elaboration of 700618 committee rept re LWR problems. Comments on behalf of util arguing that other problems should be considered as items of rept encl. LIBARKIN, M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/11/10. ACRS - Advisory Committee on Reactor Safeguards. 1p. 32930-081-32930-081.
- 8510080429 Provides info re necessity of further explication of ACRS rept concerning "catch-all" paragraph on problems about LWRs. Related info encl. LIBARKIN, M.W. ACRS - Advisory Committee on Reactor Safeguards. 76/08/06. ACRS - Advisory Committee on Reactor Safeguards. 7pp. 32930-083-32930-089.
- 8510080431 Summary of ACRS Ad Hoc Subcommittee on Midland 820429 meeting w/ util & consultants in Washington, DC re foundation problems & remedial action. SIESS, C.P. ACRS - Advisory Committee on Reactor Safeguards. 85/09/30. ACRS - Advisory Committee on Reactor Safeguards. 8pp. 32930-090-32930-097.
- 8510080435 Forwards M. Sinclair statement for ACRS Subcommittee on Midland 820429 meeting. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/05/04. DENTON, H. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. Division of Licensing. MATTSO, R. Division of Systems Integration (post 811005). 2pp. 32930-098-32930-099.
- 8510080438 Forwards project status rept for ACRS Subcommittee on Midland 820429 meeting in Washington, DC to discuss util remedial action on soils & structural settlement issues. FISCHER, D. NRC - No Detailed Affiliation Given. 82/04/21. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 14pp. 32930-100-32930-119.
- 8510080441 Forwards revised schedule for ACRS Subcommittee on Midland Plant 820429 meeting in Washington, DC to discuss util remedial action re soils & structural settlement issues. Related info encl. FISCHER, D. NRC - No Detailed Affiliation Given. 82/04/26. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 32930-120-32930-123.
- 8510080444 Discusses upcoming ACRS 820429 meeting in Washington, DC to discuss soil sediment problems at facility. Related info encl. SINCLAIR, M. Sinclair, M. 82/04/26. SIESS, C. ACRS - Advisory Committee on Reactor Safeguards. 27pp. 32930-124-32930-149.
- 8510080448 Forwards proposed FR notice of ACRS Subcommittee on Midland 820520 & 21 meetings in Midland, MI. Portions of meeting may be closed for reasons stated in attachment. Requests that notice be published by 820504. Related info encl. FISCHER, D. ACRS - Advisory Committee on Reactor Safeguards. 82/04/27. HOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 29pp. 32930-150-32930-092.
- 8510080037 FOIA request for ACRS documents re facility. BRUNNER, J.E. Consumers Power Co. 85/08/23. Office of Administration. 2pp. 32929-071-32929-072.
- 8510090019 FOIA request for Contract NRC-33-85-327. LEE, C. Alcalde, Henderson, O'Bannon & Kline. 85/09/19. Division of Contracts. 1p. 32964-053-32964-053.
- 8510090023 Responds to FOIA request for Contract NRC-33-85-327. Contract available in PDR contracts file. Notice of procedures & charges for obtaining PDR records encl. W/o encl. FELTON, J.M. Division of Rules and Records. 85/09/26. LEE, C. Alcalde, Henderson, O'Bannon & Kline. 1p. 32964-058-32964-058.
- 8510090031 FOIA request for documentation re 850609 event at facility, including items 2,3 & 4 referenced in NUREG-1154, NUREG/CR-3530, NUREG-0737, Tech Specs per FSAR Chapter 16 & OL. WEBB, R.E. Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law). 85/08/29. FELTON, J.M. Division of Rules and Records. 3pp. 32964-016-32964-018.
- 8510090039 Partial response to FOIA request for specified documents re facility. App A documents available in PDR. Notice of charges & procedures for obtaining records from PDR encl. W/o encl. FELTON, J.M. Division of Rules and Records. 85/09/26. WEBB, R.E. Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law). 3pp. 32964-019-32964-021.
- 8510090044 FOIA request for mailing list of recipients of info notices issued by IE, Div of Emergency Preparedness & Engineering Response, arranged in strict zip code order & presented on gummed labels. WHITNEY, J. Keenan Corp. 85/09/13. FELTON, J. Division of Rules and Records. 1p. 32964-009-32964-009.
- 8510090049 Responds to FOIA request for gummed mailing labels in strict zip code order for info notices. Mailing labels encl. Div of Accounting & Finance will forward bill for amount cited. W/o encl. FELTON, J.M. Division of Rules and Records. 85/09/27. WHITNEY, J. Keenan Corp. 1p. 32964-010-32964-010.
- 8510090057 FOIA request for info on J. Neel &/or D. Gravely association w/ listed companies re Maxey Flats nuclear disposal area, records of permit applications, test data submissions, notices of operating violations & insp rept. PIERCE, J.F. Environmental Task Force. 85/08/30. Division of Rules and Records. 1p. 32963-313-32963-313.
- 8510090063 Responds to FOIA request for info on J. Neel & D. Gravely association w/ listed companies re Maxey Flats nuclear disposal area. Forwards App B documents. App A & B documents available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/26. PIERCE, J.F. Environmental Task Force. 3pp. 32963-314-32963-320.
- 8510090067 Authorizes use of Trench 18 for burial of radwaste subj to listed conditions, per 760903 meeting & Jul 1976 rept. L.E. Stratton 761029 ltr to J.N. Neel encl. SINGER, B. Radioisotopes Licensing Branch (Pre 790501). 76/09/21. NEEL, J. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 4pp. 32963-317-32963-320.
- 8510090075 Responds to FOIA request for meeting minutes, notes, transcript & handouts from CRGR 850724 meeting re integral simulation test/inservice insp pump & valve programs. Document 3 on App B withheld (ref FOIA Exemption 5). FELTON, J.M. Division of Rules and Records. 85/09/26. SMITH, E.R. NUS Corp. 3pp. 32963-307-32963-310.
- 8510090084 FOIA request for info re pass/fail statistics for licensing & requalification exams given to reactor & senior reactor operator candidates for time frame subsequent to issuance of SECY-84-81C. O'MEALIA, M. Doc-Search Associates. 85/09/18. FELTON, J.M. Division of Rules and Records. 1p. 32963-305-32963-305.
- 8510090091 Responds to FOIA request for records containing pass/fail statistics for licensing & requalification exams subsequent to issuance of SECY-84-81C. Next exam results rept will be sent to Commission on 851215. No records subj to request. FELTON, J.M. Division of Rules and Records. 85/09/26. O'MEALIA, M. Doc-Search Associates. 1p. 32963-306-32963-306.
- 8510090099 Further response to FOIA request for NRC ltrs to E. Markey re facility. Forwards App B Documents 1-5. Documents also available in PDR. App C Documents 1-7 & 8-14 withheld (ref FOIA Exemptions 7 & 5, respectively). FELTON, J.M. Division of Rules and Records. 85/09/26. CUNNINGHAM, L. Times-Picayune, La Place, LA. 4pp. 32963-296-32963-304.
- 8510090108 Forwards Ofc of Investigation rept re possible falsification of operator qualifications, per 840313 request. Matter referred to DOJ for evaluation of prosecutorial merit. W/o encl. PLAINE, H.H. Office of the General Counsel. 84/06/08. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-301-32963-301.
- 8510090114 Forwards SECY-84-209, per 840611 request. Paper not yet acted on by Commission. Document should be restricted to subcommittee. W/o encl. DIRCKS, W.J. Office of the Executive Director for Operations. 84/06/08. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-302-32963-302.
- 8510090118 Forwards Ofc of Investigation rept re possible falsification of mechanical training records at facility. Matter referred to DOJ for evaluation. Rept should be held in confidence. W/o encl. PLAINE, H.H. Office of the General Counsel. 84/07/23. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-303-32963-303.
- 8510090124 Forwards transcript of NRC 840731 closed meeting re facility. Matters referred to DOJ for evaluation of prosecutive merit. Documents should be held in confidence. W/o encl. PALLADINO, N.J. Commissioners. 84/08/24. MARKEY, E. House of Rep., Interior & Insular Affairs. 1p. 32963-304-32963-304.
- 8510090132 FOIA request for all rept of radioactive effluents discharged to unrestricted areas resulting from work performed under Licenses SMB-502, SNM-414, SNM-145 & 37-04456-03. VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 85/07/29. CROW, W.T. Uranium Fuel Licensing Branch. 1p. 32963-145-32963-145.
- 8510090143 Responds to FOIA requests for all effluent release rept for Licenses SMB-502, SNM-145, SNM-414 & 37-04456-03. Also responds to Category 6 of related FOIA Request 85-552. Forwards requested documents. Add effluent info available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/04. VIROSTEK, C. Kiski Valley Coalition to Save Our Children. 1p. 32963-146-32963-146.
- 8510090155 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1977 W/770829 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-147-32963-152.
- 8510090169 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1977 W/780224 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-153-32963-155.
- 8510090178 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1978 W/780829 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 78/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-156-32963-158.
- 8510090186 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1978 W/790223 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 78/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963-159-32963-173.
- 8510090197 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1981 W/810817 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 81/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director (81/06/01). 3pp. 32963-174-32963-179.

- 8510090205 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1982 W/820722 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 82/06/30. HAYNES, R.C. Region 1, Office of Director. 3pp. 32963:180-32963:182.
- 8510090217 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1983 W/830126 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 82/12/31. HAYNES, R.C. Region 1, Office of Director. 3pp. 32963:183-32963:186.
- 8510090225 Corrected 830725 rept of radioactive effluents discharged to unrestricted areas for Jan-June 1983 W/830727 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 83/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:187-32963:188.
- 8510090280 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1984 W/840814 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 84/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:191-32963:194.
- 8510090282 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1985 W/850815 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 85/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:195-32963:196.
- 8510090155 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1977 W/770829 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963:147-32963:152.
- 8510090169 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1977 W/780224 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 77/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963:153-32963:155.
- 8510090178 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1978 W/780629 ltr. WILLIAMS, R.A. Babcock & Wilcox Co. 78/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963:156-32963:158.
- 8510090186 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1978 W/790223 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 78/12/31. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 3pp. 32963:159-32963:173.
- 8510090197 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1981 W/810817 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 81/06/30. GRIER, B.H. Region 1, Philadelphia, Office of the Director (81/03/01). 3pp. 32963:174-32963:179.
- 8510090205 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1982 W/820722 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 82/06/30. HAYNES, R.C. Region 1, Office of Director. 3pp. 32963:180-32963:182.
- 8510090217 Rept of radioactive effluents discharged to unrestricted areas for Jul-Dec 1983 W/830126 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 82/12/31. HAYNES, R.C. Region 1, Office of Director. 3pp. 32963:183-32963:186.
- 8510090225 Corrected 830725 rept of radioactive effluents discharged to unrestricted areas for Jan-June 1983 W/830727 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 83/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:187-32963:188.
- 8510090277 Rept on radioactive effluents discharged to unrestricted areas for Jul-Dec 1983 W/840203 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 83/12/31. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:189-32963:190.
- 8510090280 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1984 W/840814 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 84/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:191-32963:194.
- 8510090282 Rept of radioactive effluents discharged to unrestricted areas for Jan-June 1985 W/850815 ltr. AUSTIN, M.A. Babcock & Wilcox Co. 85/06/30. MURLEY, T.E. Region 1, Office of Director. 2pp. 32963:195-32963:196.
- 8510090435 FOIA request for documents re historical background of 10CFR50.59. DAY, P. NUS Corp. CD-US-85-787. 85/09/17. Division of Rules and Records. 1p. 32965:070-32965:070.
- 8510090441 Partial response to FOIA request for documents re historical background of 10CFR50.59. Documents on encl App A & add documents available in PDR. Search for add documents continuing. FELTON, J.M. Division of Rules and Records. 85/10/02. DAY, P. NUS Corp. 3pp. 32965:071-32965:076.
- 8510090453 Comments on proposed rules 10CFR50 & 115 re NRC authorization of changes to Tech Specs for production & utilization facilities. Procedures may be unduly time consuming. VOGTLE, J.S. Alabama Power Co. 38FR22796 005. 73/10/17. Atomic Energy Commission. 1p. 32965:074-32965:074.
- 8510090464 Comments on proposed rules 10CFR50 & 115, "Licensing of Production & Utilization Facilities: Procedure for Review of Certain Nuclear Reactors Exempted From Licensing Requirements." MEYERS, S. Environmental Protection Agency. 38FR22796 004. 73/10/29. Atomic Energy Commission. 2pp. 32965:075-32965:076.
- 8510090470 FOIA request for documents re mfg or storage of radioactive nuclear substances in Maywood, NJ, including Maywood Chemical, Stephan Chemical & Manhattan Project. PONCEL, Affiliation Not Assigned. 85/09/26. NRC - No Detailed Affiliation Given. 1p. 32965:067-32965:067.
- 8510090477 Response to FOIA request for documents re mfg or storage of radioactive matters in Maywood, NJ, including records on Maywood Chemical Co & Stephan Chemical Co. List of previous FOIA requests re subj encl. FELTON, J.M. Division of Rules and Records. 85/10/02. PONCEL, Affiliation Not Assigned. 2pp. 32965:068-32965:069.
- 8510090484 Final response to FOIA request for documents re IE Info Notice 85-40, "Deficiencies in Equipment Qualification Testing & Certification Process." Search completed. No add records located. FELTON, J.M. Division of Rules and Records. IEIN-85-040. 85/10/04. GRADE, B.P. Government Accountability Project. 1p. 32965:064-32965:066.
- 8510150134 FOIA request for all documents re Licenses SUA-809 (Colorado Ventures, Inc.) & SUA-797 (Oregon Pacific Industries). BARNES, C. Affiliation Not Assigned. 85/08/09. Division of Rules and Records. 1p. 33033:292-33033:292.
- 8510150142 Response to FOIA request for documents re Licenses SUA-809 & SUA-797. Forwards documents listed in App A & portions of documents in App B. Portions of App B documents withheld (ref FOIA Exemption 6). FELTON, J.M. Division of Rules and Records. 85/09/20. BARNES, C. Affiliation Not Assigned. 8pp. 33033:293-33033:287.
- 8508280083 Followup insp rept on 600712-14. Noncompliance noted: less than adequate analytical results recorded & airborne radioactivity areas not posted. HAWLEY, C.A. Atomic Energy Commission. 60/09/16. 10pp. 33034:190-33034:199.
- 8508280100 Followup insp rept on 611011-1215 & 21. Items of noncompliance: records re liquid effluent concentrations of U reported in improper units & environ air surveys conducted improperly. HAWLEY, C.A. Atomic Energy Commission. 62/01/04. 9pp. 33034:177-33034:185.
- 8508280127 Documents B Logan & HR Keil 620416 telcon informing of forthcoming shutdown of U mill. Submittal of written notification of intentions suggested. WALKER, D.I. Atomic Energy Commission. 62/04/19. DUBINSKI, L. Atomic Energy Commission. 4pp. 33034:185-33034:189.
- 8510150153 Compliance insp rept on 580404. Noncompliance noted: survey to determine existence of hazards incident to U core processing not conducted & caution signs in areas containing U in excess of specified limits not posted. WALKER, D.I. Atomic Energy Commission. 58/07/15. 11pp. 33033:301-33033:311.
- 8510150158 Forwards photographs taken during Apr visit. WALKER, D.I. Atomic Energy Commission. 58/07/15. THORNBURG, V. Gunnison Mining Co. 1p. 33033:312-33033:312.
- 8510150163 Forwards compliance insp rept & recommends licensee furnish plans for conducting survey for determining airborne activity & radiation levels & for posting warnings. Posting regulations discussed w/ licensee. WALKER, D.I. Atomic Energy Commission. 58/07/15. MANN, M.M. Atomic Energy Commission. 2pp. 33033:313-33033:314.
- 8510150169 Forwards photographs taken during 590325 followup insp. WALKER, D.I. Atomic Energy Commission. 59/05/14. NICOU, G. Gunnison Mining Co. 1p. 33033:315-33033:315.
- 8510150170 Ack receipt of 590514 ltr & photograph taken on 590325. NICOU, G.A. Gunnison Mining Co. 59/05/29. WALKER, D.I. Atomic Energy Commission. 1p. 33033:316-33033:316.
- 8510150176 Forwards followup insp rept. Items of noncompliance include exposure of individuals in restricted areas & failure to complete survey for airborne concentrations. Licensee failure to take action noted. WALKER, D.I. Atomic Energy Commission. 59/05/14. PRICE, H.L. Atomic Energy Commission. 3pp. 33033:317-33033:319.
- 8510150201 Followup insp rept on 590325. Noncompliance noted: individuals exposed in restricted areas; surveys for airborne concentrations not made; caution signs, labels & signals not posted & records of radiation surveys not maintained. WALKER, D.I. Atomic Energy Commission. 59/05/14. 9pp. 33033:320-33033:328.
- 8510150209 Informs that radiation & dust survey calculations off by factor of 1,000 when fluorimetric results reported, per recent telcon re calculation methods. Film badge program started on 590817. Related info encl. SHREVE, R.E. Gunnison Mining Co. 59/08/25. JOHNSON, W. Atomic Energy Commission. 3pp. 33033:329-33033:360.
- 8510150214 Suggests transmittal of ltr notifying licensee of noncompliance items discovered during insp & requesting corrective action be sent. Case summary will be included in Ofc of General Manager rept. * Atomic Energy Commission. 58/08/31. Atomic Energy Commission. 1p. 33033:361-33033:361.
- 8510150220 Notifies of 600119 mill effluent meeting at Natl Reactor Testing Station, per 591208 ltr re "Determination of Ra-226 & Th-230 in Mill Effluents." Representation limited to two persons per mill. Participant names requested. WALKER, D.I. Atomic Energy Commission. 60/01/05. NICOU, G.A. Gunnison Mining Co. 1p. 33033:362-33033:362.
- 8510150226 Forwards results of effluent sampling of U mills located on Colorado River, per request. WALKER, D.I. Atomic Energy Commission. 59/12/22. MANN, M.M. Atomic Energy Commission. 2pp. 33034:001-33034:002.
- 8510150230 Forwards "Determination of Ra-226 & Th-230 in Mill Effluents." Comments requested. Meeting will be planned to discuss procedure. Film badge results will be forwarded when program completed at mill. WALKER, D.I. Atomic Energy Commission. 59/12/08. SHREVE, R.E. Gunnison Mining Co. 1p. 33034:003-33034:003.
- 8510150235 Forwards 590914-17 survey results for air samples, external radiation & liquid effluent samples & film badge results. Film badge results tabulated by profession for each month of 4-month period. WALKER, D.I. Atomic Energy Commission. 60/02/12. ROBISON, J.L. Gunnison Mining Co. 1p. 33034:004-33034:004.

286 NONDOCKETED ITEMS

- 8510150236 "Radiation & Safety Rules & Regulations."
* Gunnison Mining Co. 60/04/15. 25pp. 33034:005-33034:029.
- 8510150240 Forwards radiation exposure averages for U milling industry obtained in connection w/ mill insp program.
MANN,M.M. Atomic Energy Commission. 60/06/03. PRICE,H.L. Atomic Energy Commission. 1p. 33034:030-33034:035.
- 8510150245 Forwards photographs taken during insp & list of radiation caution sign suppliers per request. Fluorimetric analysis procedure will be forwarded when available.
HAWLEY,C.A. Atomic Energy Commission. 60/08/01. SHREVE,R.E. Gunnison Mining Co. 8pp. 33034:036-33034:043.
- 8510150251 Forwards State of ID. Licensee Compliance Div 600916 memo & rept re insp of License R-209. Citation for noncompliance re failure to conduct airborne effluent surveys suggested. Followup insp to be conducted.
LOW,L.D. Atomic Energy Commission. 60/09/23. PRICE,H.L. Atomic Energy Commission. 1p. 33034:044-33034:044.
- 8510150266 Requests that future correspondence to AD Haas be forwarded to listed address. NRC 610622 ltr to F. Jackson forwarded by AD Haas to authors.
COBB,G.H. Gunnison Mining Co. 61/06/05. WALKER,D.I. Atomic Energy Commission. 1p. 33034:045-33034:045.
- 8510150272 Informs that, according to licensee 610112 ltr re deficiencies noted during Jul 1960 insp of License R-209, corrective actions completed. No confirmation will be sent.
CUNNINGHAM,R.E. Atomic Energy Commission. 016434. 61/07/21. DUBINSKI,L. Atomic Energy Commission. 1p. 33034:046-33034:052.
- 8510150299 Forwards 620105 ltr & encl supplementing 611011 insp rept for License R-209. Film badge exposure & airborne natural U sampling of unrestricted areas discussed.
WALKER,D.I. Atomic Energy Commission. 62/03/05. DUBINSKI,L. Atomic Energy Commission. 1p. 33034:053-33034:068.
- 8510150325 Illegible memo re high exposure on film badges. Related info encl.
SHREVE,R.E. Gunnison Mining Co. 59/12/01. JOHNSON,D.B. Atomic Energy Commission. 49pp. 33034:069-33034:116.
- 8510150330 Discusses 641113 telcon w/ Davidson re Region IV survey of mill on 641201. Davidson will forward list of items exceeding release limits.
BROWN,G.D. Atomic Energy Commission. 64/11/13. Atomic Energy Commission. 2pp. 33034:117-33034:117.
- 8510150335 Outlines Div of Insp program for collection of air & liquid effluent samples to determine radioactive concentrations. Program does not replace or suppl licensee survey program per 10CFR20. Related info encl.
WALKER,D.I. Atomic Energy Commission. 59/11/05. NICLOUD,G. Gunnison Mining Co. 29pp. 33034:118-33034:153.
- 8510150344 Forwards summary rept re processes & potential exposures associated w/U ore processing. Info does not constitute evaluation of particular mill. Related info encl.
DELANEY,J.C. Atomic Energy Commission. 59/01/15. THORNBUH,G.V. Gunnison Mining Co. 23pp. 33034:154-33034:176.
- 8510150364 Notifies that ltr's confirming listed licensee responses to citations for non-compliance will not be forwarded due to time elapsed since responses were received. Related info encl.
ROGERS,L.R. Atomic Energy Commission. 59/03/11. MANN,M.M. Atomic Energy Commission. 5pp. 33034:200-33034:204.
- 8510150367 Requests listed correspondence to complete files for mills initially inspected to permit followup insp. Porter Brothers Corp. license expired on 571101. Followup insp requested. Addl initial & followup insps will be conducted.
WALKER,D.I. Atomic Energy Commission. 59/01/14. LOW,L.D. Atomic Energy Commission. 2pp. 33034:205-33034:207.
- 8510150370 Forwards Kermac Nuclear Fuels Corp 641110 ltr requesting closeout insp of Gunnison facility. Walker has contracted Davidson for purpose of scheduling insp.
HARMON,D.F. Atomic Energy Commission. 64/11/17. PAULUS,R.C. Atomic Energy Commission. 1p. 33034:208-33034:208.
- 8510150373 Requests insp of Gunnison facility required for clearance of sale of facility. List of items exceeding prescribed levels of radiation per survey results forwarded. Prior to survey, cleanup procedures included trash removal & burial.
DAVIDSON,J.M. Kerr-McGee Corp. 5221. 64/11/10. NUSSBAUMER,D.A. Atomic Energy Commission. 5pp. 33034:209-33034:213.
- 8510150374 Forwards list of items found to be over accepted levels at Gunnison facility per 641113 telcon.
DAVIDSON,J.M. Kerr-McGee Corp. 64/11/16. WALKER,D.I. Atomic Energy Commission. 1p. 33034:214-33034:214.
- 8510150378 Submits insp status rept for U & thorium ore processing mills. Status rept not submitted at end of last quarter due to SL-1 incident & subsequent problems.
WALKER,D.I. Atomic Energy Commission. 61/11/03. DUBINSKI,L. Atomic Energy Commission. 2pp. 33034:215-33034:216.
- 8510150381 Submits quarterly insp status rept for U ore processing mills 2 months following previous rept, to coincide w/ quarterly licensee insp rept submittal. No new developments transpired re Falls City TX mill operation.
WALKER,D.I. Atomic Energy Commission. 60/10/10. LOW,L.D. Atomic Energy Commission. 2pp. 33034:217-33034:218.
- 8510150386 Submits insp status rept for U ore processing mills. Corrections requested. Rept will be updated at first of each month following quarterly rept submittal. Addl mill believed to be under const in Falls City, TX.
WALKER,D.I. Atomic Energy Commission. 60/08/02. LOW,L.D. Atomic Energy Commission. 5pp. 33034:219-33034:223.
- 8510150389 Requests investigation re AEC-owned converters at Rifle Mill discovered during Dept of Labor health & safety insp.
SHERMAN,J.T. Atomic Energy Commission. 60/07/19. JONES,A.E. Atomic Energy Commission. 1p. 33034:224-33034:224.
- 8510150394 Discusses use of AEC-owned equipment at Rifle Mill discovered during Dept of Labor insp. Union Carbide Nuclear contacted re equipment. Air samplers presumably left for sample collection. Converters permit use of two prong plugs.
JONES,A.E. Atomic Energy Commission. 000832. 60/07/22. SHERMAN,J.T. Atomic Energy Commission. 3pp. 33034:225-33034:227.
- 8510150396 "AEC Radiation Control Program for U Mill Operations."
* Atomic Energy Commission. 60/05/11. 22pp. 33034:228-33034:249.
- 8510150400 Forwards draft reply & rept in response to Ramsey 600404 ltr to general manager per Finan & Main conversation w/ Toll.
NELSON,C.A. Atomic Energy Commission. 60/04/28. FINAN,W.F. Atomic Energy Commission. 20pp. 33034:250-33034:269.
- 8510150402 Illegible memo re radiation exposure averages for U mill industry.
WALKER,D.I. Atomic Energy Commission. 60/03/27. MANN,M.M. Atomic Energy Commission. 1p. 33034:270-33034:270.
- 8510150404 Forwards survey results for U ore processing mills insp status files. Files determined to be up to date. Copies of correspondence between other AEC offices & licensees requested.
WALKER,D.I. Atomic Energy Commission. 60/03/22. LOW,L.D. Atomic Energy Commission. 5pp. 33034:271-33034:275.
- 8510150406 Forwards film badge results for U mills. Film badge programs at listed mills not complete & data unavailable. Mines Development, Inc. data submitted earlier in wk.
WALKER,D.I. Atomic Energy Commission. 60/03/18. MANN,M.M. Atomic Energy Commission. 1p. 33034:276-33034:276.
- 8510150407 Forwards U mill survey program results for airborne, external radiation & effluent sampling surveys conducted during latter summer & early fall. Film badge program data will be forwarded when compilation completed.
WALKER,D.I. Atomic Energy Commission. 60/02/12. MANN,M.M. Atomic Energy Commission. 2pp. 33034:277-33034:278.
- 8510150417 Forwards correspondence between Insp. Licensing & Regulation & licensees. Complete correspondence available for Licenses R-102 & R-185. Missing correspondence requested prior to followup insps. License R-205 extended to 581031.
WALKER,D.I. Atomic Energy Commission. 58/09/30. LOW,L.D. Atomic Energy Commission. 3pp. 33034:279-33034:281.
- 8510150420 Submits results of Gunnison Mining Co mill 581217 insp. Contract processing limit would be fulfilled by 590331. Sprinkler sys installation in progress. Little progress made in survey program.
GEORGE,D.R. Atomic Energy Commission. 58/12/19. TOMRY,C.E. Atomic Energy Commission. 3pp. 33034:282-33034:284.
- 8510150423 Submits preliminary results of Kerr-McGee mill at Gunnison, CO 640803 terminal insp. per request. Release of facility not recommended. Memo confirming insp results will be forwarded when alpha counts received.
WALKER,D.I. Atomic Energy Commission. 64/08/05. DUBINSKI,L. Atomic Energy Commission. 3pp. 33034:285-33034:287.
- 8510150436 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 840106.
GARDE,B.P. Government Accountability Project. 85/01/11. Office of Administration. 2pp. 33110:001-33110:002.
- 8510150440 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850111.
GARDE,B.P. Government Accountability Project. 85/01/14. Office of Administration. 2pp. 33110:003-33110:004.
- 8510150443 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850114.
GARDE,B.P. Government Accountability Project. 85/01/15. Office of Administration. 2pp. 33110:005-33110:006.
- 8510150446 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850117.
GARDE,B.P. Government Accountability Project. 85/01/18. Office of Administration. 2pp. 33110:007-33110:008.
- 8510150447 FOIA request for all documentation re overview, regulation & investigation of facility by NRC since 850118.
GARDE,B.P. Government Accountability Project. 85/01/21. Office of Administration. 2pp. 33110:009-33110:012.
- 8510150449 First partial response to FOIA request for documentation re NRC overview, regulation & investigation of facility. Forwards records re protective coating issues. Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. GARDE,B.P. Government Accountability Project. 2pp. 33110:013-33110:043.
- 8510150451 Rev 7 to CPM 13.1, "General Calibr Procedure."
FRANKUM,D.C. Brown & Root, Inc. (subs. of Halliburton Co.). 81/12/09. 22pp. 33110:035-33110:043.
- 8510150454 Package consisting of insp repts, calibr records & repts & Responses 3.5 & 10 to RL Bangor 840523 ltr re BNL interim rept on protective coatings.
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 85/10/04. 9,000pp. 33118:001-33120:362.
- 8510160078 FOIA request for investigation Rept I-84-014.
WENNER,R. Meredith Broadcasting/WTVH Television. 85/09/26. FELTON,J. Division of Rules and Records. 1p. 33028:284-33028:284.
- 8510160084 Responds to FOIA request for investigation Rept I-84-014. Forwards 850912 ltr to BP Garde of GAP provided in response to FOIA Request 85-613.W/o encl.
FELTON,J.M. Division of Rules and Records. 85/10/03. WENNER,R. Meredith Broadcasting/WTVH Television. 1p. 33028:285-33028:285.
- 8510160089 FOIA request for documents re NRC role in high level radioactive waste program including SECY-85-197 & J Zerbe 850624 memo to Commissioners.
WAGNER,M.L. McGraw-Hill Publishers Co. 85/06/26. FELTON,J.M. Division of Rules and Records. 1p. 33042:328-33042:328.

- 8510160092** Responds to FOIA request for documents re NRC role in high level radwaste repository program. Documents listed in App A completely withheld (ref FOIA Exemption 5). FELTON, J.M. Division of Rules and Records. 85/10/09. WAGNER, M.L. McGraw-Hill Publications Co. 2pp. 33042:329-33042:330.
- 8510160099** Responds to FOIA request for info re J. Neel &/or D. Gravely association w/ listed companies concerning Maxey Flats nuclear disposal area. Forwards documents listed in App C. Documents also available in PDR. FELTON, J.M. Division of Rules and Records. 85/10/08. PIERCE, J.F. Environmental Task Force. 3pp. 33042:242-33042:247.
- 8510160105** Responds to J. Neel re burial of low level waste Mississippi River is dividing line from economic point of view. No projected vol for future. Related info encl. SIMS, R.W. Atomic Energy Commission. 62/06/01. Atomic Energy Commission. 3pp. 33042:246-33042:252.
- 8510160111** Discusses Commonwealth of KY recent visit to AEC re contemplated Nuclear Engineering Co. inc. radwaste burial site near Morehead, KY. Commonwealth of KY file survey encl. LOWENSTEIN, R. Atomic Energy Commission. 62/08/13. NEEL, J.N. Kentucky, Commonwealth of. 5pp. 33042:253-33042:257.
- 8510160117** Discusses 621102 ltr & encl documents re application & license for Nuclear Engineering Co. waste disposal activity to be conducted near Morehead, KY. Related info encl. W/o encl documents. WESTERN, F. Atomic Energy Commission. 62/11/26. NEEL, J.N. Kentucky, Commonwealth of. 10pp. 33042:258-33042:267.
- 8510160121** Informs that 621227 ltr to Commonwealth of KY Commissioner of Health provided pertinent comments re storage of low level wastes prior to burial at low level waste disposal facility. WESTERN, F. Atomic Energy Commission. 63/03/07. Kentucky, Commonwealth of. 18pp. 33042:268-33042:285.
- 8510160126** Informs of return of listed documents stamped confidential, distributed during 741118 meeting in Bethesda, MD w/ representatives of Commonwealth of KY. Related info encl. KERR, G.W. Atomic Energy Commission, Directorate of Licensing. 74/12/12. NEEL, J.N. Nuclear Engineering Co., Inc. 40pp. 33042:286-33042:325.
- 8510160130** Responds to 790927 ltr re misstatement noted in JM Herdrie 790727 ltr to J. Dingell re low level radwaste site near Sheffield, IL. Point of parenthetical statement to indicate closing of site not temporary matter for foreseeable future. GOSSICK, L.V. Office of the Executive Director for Operations. 79/10/24. NEEL, J.N. Nuclear Engineering Co., Inc. 2pp. 33042:326-33042:327.
- 8510160103** Responds to FOIA request for four categories of documents re Philippines nuclear power plant. Forwards documents listed on App D. FELTON, J.M. Division of Rules and Records. 85/10/01. SCHLEMMER, D.L. Government Accountability Project. 2pp. 33035:330-33035:034.
- 8510160115** Forwards Philippines preliminary site investigation rept. Input requested. W/o encl. DENTON, H.R. Division of Site Safety & Environmental Analysis. 77/02/16. VOLLMER, R.H. Assistant Director for Site Analysis. GAMMILL, W.P. Assistant Director for Site Technology. 1p. 33035:332-33035:332.
- 8510160122** Forwards preliminary site investigation rept for first Philippines reactor, for info. W/o encl. LAFLEUR, J.D. Office of International Programs, Director. 77/02/14. DENTON, H.R. Division of Site Safety & Environmental Analysis. 1p. 33035:333-33035:333.
- 8510160132** Submits recommendations based on initial site exam. Further analyses should be provided prior to PSAR submittal. DENTON, H.R. Division of Site Safety & Environmental Analysis. 75/02/06. GAMMILL, W.P. Assistant Director for Site Technology. GRIME, B. HELLER, L. Accident Analysis Branch. 2pp. 33035:334-33035:335.
- 8510160141** Forwards initial site exam info to minimize siting-related delays in licensing process. GIAMBUSSO, A. Atomic Energy Commission - Deputy Director for Reactor Projects. 74/08/19. FIRESTONE, L. Ohio Edison Co. 5pp. 33035:336-33035:340.
- 8510160152** Forwards comments on site investigation rept submitted by Natl Power Corp for proposed Philippine Nuclear Power Plant. VOLLMER, R.H. Assistant Director for Site Analysis. 77/03/08. MIRAGLIA, F.J. Division of Site Safety & Environmental Analysis. 9pp. 33035:341-33035:351.
- 8510160190** Advises that NRC received application from Westinghouse for license to export reactor to Philippines. FR notice encl. W/o encl. GUHIN, M.A. Assistant Director for Export/Import & International Safeguards. 76/12/29. MURPHY, G.F. Congress, Joint Committee on Atomic Energy. 1p. 33035:352-33035:352.
- 8510160207** Requests Executive Branch position re Westinghouse application for license to export power reactor to Philippines. GOSSICK, L.V. Office of the Executive Director for Operations. 76/12/20. BORG, C.A. State, Dept. of. 1p. 33035:353-33035:353.
- 8510160212** Supports Westinghouse 761118 application for license to export NSSS to Philippines. MORRISON, W.M. Reactor Systems Standards Branch. 76/12/09. GUHIN, M.A. Assistant Director for Export/Import & International Safeguards. 1p. 33035:354-33035:354.
- 8510160222** Requests assistance in determining whether equipment mentioned in encl Westinghouse 761118 application for export license constitutes utilization facility as defined in act. GUHIN, M.A. Assistant Director for Export/Import & International Safeguards. 76/12/07. MORRISON, W.M. Office of Standards Development, Director. 1p. 33035:355-33035:355.
- 8510160261** Application for license to export NSSS to Philippines. RODI, J.P. Westinghouse Electric Corp. TFG/NRC-864. 76/11/18. MOORE, N. Assistant Director for Export/Import & International Safeguards. 2pp. 33035:356-33035:357.
- 8510160268** Application for license to export mats & equipment to Philippines. RODI, J.P. Westinghouse Electric Corp. TFG/NRC-864A. 76/11/18. Assistant Director for Export/Import & International Safeguards. 3pp. 33035:358-33035:360.
- 8510160273** Extends assistance to Natl Research Council in arranging program for Philippines Atomic Energy Commission. LAFLEUR, J.D. Office of International Programs, Director. 77/10/28. IBE, L.D. Philippines, Govt. of. 1p. 33035:361-33035:361.
- 8510160277** Responds to 760503 & 07 requests for federal regulations, SRPs & reg guides. Subscription order form encl. LAFLEUR, J.D. Office of International Programs, Director. 76/07/02. PORTUGAL, A.M. Philippines, Govt. of. 2pp. 33036:001-33036:002.
- 8510160281** Advises that Philippines preliminary site investigation rept reviewed. Seismological review in progress. Geologic & foundation engineering comments of Section 2.6, "Geology & Seismology" encl. GAMMILL, W.P. Assistant Director for Site Technology. 77/03/15. MIRAGLIA, F.J. Division of Site Safety & Environmental Analysis. 8pp. 33036:003-33036:023.
- 8510160293** Forwards Geosciences Branch review of Philippines preliminary site investigation rept. per initial site exam info review procedure. W/o encl. GAMMILL, W.P. Assistant Director for Site Technology. 77/03/29. MIRAGLIA, F.J. Division of Site Safety & Environmental Analysis. 1p. 33036:024-33036:024.
- 8510160174** Further response to FOIA request for 12 categories of documents re plant. Forwards App E documents. App F documents available in PDR. Apps G & H documents withheld (ref FOIA Exemptions 7 & 8). FELTON, J.M. Division of Rules and Records. 85/09/26. ZAEKE, D. Sierra Club. 6pp. 33042:331-33042:357.
- 8510160183** Proposes course of action re legal & policy considerations concerning util proposal to restart facility. per General Counsel 841105 memo. Decision should be made promptly. ROBERTS, Commissioners. 84/11/08. PALLADINO, ASSELSTINE, BERNTHAL. Commissioners. 2pp. 33042:345-33042:346.
- 8510160187** Forwards Assestine dissenting views on order denying Sierra Club request for hearing & stay of NRC decision re facility, for inclusion w/ order prior to issuance. DAVIS, P. Commissioners. 85/02/12. BATES, A. Office of the Secretary of the Commission. 10pp. 33042:347-33042:356.
- 8510160193** Affirmation response sheet disapproving SECY-85-39, "Proposed Response to Sierra Club 'Request for Hearing & Request for Stay' re San Onofre Unit 1." Dissenting views encl. W/o encl. ASSELSTINE, Commissioners. 85/02/12. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33042:357-33042:357.
- 8510160201** FOIA request for documents re Ofc of Inspector & Auditor charges that NRC responded improperly to allegations of possible QA & safety violations by whistleblowers at plant. DEVINE, T. Government Accountability Project. 85/08/20. Office of Administration. 2pp. 33028:359-33028:360.
- 8510160205** Responds to FOIA request for documents re Ofc of Inspector & Auditor inquiry into charges that NRC responded improperly to allegation by whistleblowers. Documents withheld (ref FOIA Exemptions 5 & 7(a)). FELTON, J.M. Division of Rules and Records. 85/10/03. DEVINE, T. Government Accountability Project. 2pp. 33028:361-33028:362.
- 8510160303** FOIA request for approved operational nuclear license for Nuclear Metals, Inc. in order to evaluate depth & format of defense ordnance manufacturer licensing requirements. CROOK, M.F. Envtrotronics. 85/08/20. TILTON, J. Division of Rules and Records. 1p. 33050:028-33050:028.
- 8510160305** Responds to FOIA request for approved operational nuclear license for Nuclear Metals, Inc. Documents listed in encl App A available in PDR. FELTON, J.M. Division of Rules and Records. 85/09/12. CROOK, M.F. Envtrotronics. 2pp. 33050:029-33050:284.
- 8510160308** Amend 6 to License SMB-179 for Nuclear Metals, Inc., amending license in entirety. WANG, J.C. Materials Licensing Branch. 84/05/23. 2pp. 33050:031-33050:032.
- 8510160310** Forwards corrected Page 11 to 820930 correspondence. Original page should be discarded. VUMBACO, F.J. Nuclear Metals, Inc. 21625. 82/11/24. WANG, J.C. Materials Licensing Branch. 3pp. 33050:033-33050:035.
- 8510160313** Application for amend to License SMB-179, incorporating mfg or transfer of industrial production or device containing depleted U. Fee paid. LISCHINSKY, J. Nuclear Metals, Inc. 22634. 83/07/26. HICKEY, J. Materials Licensing Branch. 5pp. 33050:036-33050:040.
- 8510160316** Responds to 831109 request for add info re renewal of License SMB-179. Supplemental instructions for handling & disposition of depleted U. sinker bars encl. All transfers will be accompanied by NRC Form 244. VUMBACO, F.J. Nuclear Metals, Inc. 23471. 84/03/19. WANG, J.C. Materials Licensing Branch. 7pp. 33050:041-33050:164.
- 8510160317** Application for amend to License SMB-179, incorporating addition to scrap packaging procedure in accordance w/ NRC low level waste vol reduction policy & authorizing R&D for reduction of waste generated. LISCHINSKY, J. Nuclear Metals, Inc. 16684. 83/12/29. HICKEY, J. Materials Licensing Branch. 3pp. 33050:165-33050:284.
- 8510170015** FOIA request for info re AEC or NRC investigation of possible unauthorized or unlawful burials of radioactive matl by Amax, Inc. & Carborundum Co. & removal of Nigerian ore & other mats from site. KOWALSKI, K.M. Squire, Sanders & Dempsey. 85/05/16. NRC - No Detailed Affiliation Given. 2pp. 33048:182-33048:183.
- 8510170019** Responds to FOIA request for documents re investigation of possible unauthorized or unlawful burials of radioactive matl & removal of Nigerian ore & other matl from site info withheld (ref FOIA Exemptions 6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/27. KOWALSKI, K.M. Squire, Sanders & Dempsey. 6pp. 33048:184-33048:041.

288 NONDOCKETED ITEMS

- 8510170024 Discusses unauthorized burial of radioactive mail. AMAX, Inc. accepts responsibility for rectifying problem & will submit final disposal plan. ALDERSON, C.E. Enforcement & Investigation Staff. 82/01/07. GIBSON, A.F. Enforcement & Investigation Staff. 5pp. 33048:190-33048:194.
- 8510170027 Ack receipt of 780503.10 & 0821 memos of interviews conducted w/ former Carborundum & AMAX Specialty Metals, Inc. employees & list of potential witnesses re burials of various metals at site. Handwritten notes encl. ANNAST, M.V. Region 2, Atlanta, Safeguards Branch. 78/07/03. FORD, H.R. L.B. Foster Co. 4pp. 33048:195-33048:198.
- 8510170031 Forwards RG Lavesque Jr. indicating that ratio of thorium to U in soil samples taken at AMAX, Inc. property establish that contamination on site from Nigerian ore. Ore imported & processed by Carborundum Co. during early 1980. THIELKE, S.A. AMAX, Inc. 78/12/04. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 4pp. 33048:199-33048:202.
- 8510170033 Forwards ltr received by Kall from Nuclear Engineering Co., Inc. re disposal of radioactive mail from former AMAX Specialty Metals Corp. facility during 1966 & 1969. THIELKE, S.A. AMAX, Inc. 78/07/31. ANNAST, M.V. Region 2, Atlanta, Office of the Director. 4pp. 33048:203-33048:206.
- 8510170036 Responds to 780712 request for documents re activities at Washington Bottoms facility. Records transferred to AMAX, Inc. Search for addl info continuing. STINSON, T.L. Carborundum Co. 78/07/19. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 1p. 33048:207-33048:207.
- 8510170038 Forwards certificate of dissolution indicating that AMAX Specialty Metals, Inc. formally dissolved on 691204. Requests date when formal ltr of violation from NRC to Amex will be available. REID, R.L. Alston, Miller & Gaines. 78/07/07. ANNAST, M.V. Region 2, Atlanta, Office of the Director. 5pp. 33048:208-33048:212.
- 8510170041 Forwards documents re burial of mail at LB Foster Co. Parkersburg plant to assist in investigation. Sketch of areas utilized as burial site at plant encl. DOUGLAS, J.L. Alston, Miller & Gaines. 78/06/27. ANNAST, M. Region 2, Atlanta, Office of the Director. 4pp. 33048:213-33048:216.
- 8510170044 Provides preliminary summary of activities conducted re possible unauthorized burial of low level radioactive waste at site. Recorded radiation level no danger to public health & safety. Activities onsite closely monitored. ANNAST, M.V. Region 2, Atlanta, Safeguards Branch. 78/05/24. Region 2, Atlanta, Safeguards Branch. 15pp. 33048:217-33048:231.
- 8510170050 Discusses media supplied info on AMAX, Inc. problem. Reporter indicated radioactive carbon tetrachloride buried all over site. CLARK, K.M. Region 2, Atlanta, Office of the Director. 78/05/04. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 1p. 33048:232-33048:232.
- 8510170052 Requests info & records re disposal of source mail at LB Foster Co. Parkersburg, WV plant & proposed radiological survey of site to be conducted by AMAX Specialty Metals, Inc. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 78/07/12. STINSON, T.L. Carborundum Co. 2pp. 33048:233-33048:233.
- 8510170056 Confirms 780714 telcon & 780707 request for info re AMAX, Inc. issue. Receipt of notice of violation confirmed. ANNAST, M.V. Region 2, Atlanta, Safeguards Branch. 78/07/14. REID, R.L. Alston, Miller & Gaines. 3pp. 33048:234-33048:234.
- 8510170060 Informs that Carborundum Co. has adequate monitoring & bioassay program to ensure safe operations. Instrumentation adequate, but licensee should have portable alpha survey meter. Thorium metals adequately secured. ELLIS, W.P. Atomic Energy Commission. 64/04/10. Atomic Energy Commission. 117pp. 33048:235-33048:352.
- 8510170064 Forwards records of 780531 & 0601 telcons w/ various individuals re current problem at LB Foster Co. Parkersburg plant. Portions deleted. DOUGLAS, J.L. Alston, Miller & Gaines. 78/06/21. ANNAST, M. Region 2, Atlanta, Office of the Director. 50pp. 33048:353-33049:041.
- 8510170048 Final response to FOIA request for documents re restart of facility. Forwards App K documents. Documents also available in PDR. Apps L & M documents completely or partially withheld (ref FOIA Exemptions 5.6 & 7). FELTON, J.M. Division of Rules and Records. 85/09/26. BELL, N. Nuclear Information & Resource Service. 14pp. 33049:219-33050:027.
- 8510170057 Forwards Investigation Status Record Case 5-83-003 in response to requirement to inform Commission of opening of new investigation. W/o encl. HAYES, B.B. Office of Investigation. 83/09/29. PALLADINO Commissioners. 1p. 33049:235-33049:236.
- 8510170062 Forwards draft Commission paper re facility restart, including more extensive discussion of procedural issues involved than presented in SECY-84-360. Miller & Chevalier memo & State of CA PUC 840502. Interim opinion W/o encls. CUNNINGHAM, G.H. Office of the Executive Legal Director. 84/10/04. REAMER, W., CUTCHIN, J., DAVIS, P. NRC - No Detailed Affiliation Given. 1p. 33049:237-33049:237.
- 8510170067 Advises that ACRS comments re adequacy of facility seismic design features require more than single meeting & later deadline due to change in approach from context of SEP review to restart decision. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 84/11/14. PALLADINO, N.J. Commissioners. 1p. 33049:238-33049:238.
- 8510170070 Advises that Ofc of Investigation inquiry Q5-83-006 closed administratively & changed to Case 5-83-003 on 830927. per BB Hayes direction. Investigation assigned to RV Joukoff. SHACKLETON, O.C. Office of Investigation. 83/09/28. Office of Investigation. 1p. 33049:239-33049:239.
- 8510170073 Forwards memo re 830317 discussion of facility. HAYES, B.B. Office of Investigation. 83/04/28. CASE, E.J., KNIGHT, J.P., MIRAGLIA, F. Office of Nuclear Reactor Regulation, Director. 1p. 33049:240-33049:240.
- 8510170077 Notifies of 830317 meeting at NRR to discuss requested investigation of facility. Meeting attendees listed. JOUKOFF, P. Office of Investigation. 83/04/08. Office of Investigation. 2pp. 33049:241-33049:242.
- 8510170080 "Licensing Activities Schedule for Restart of San Onofre Nuclear Generating Station Unit 1." Viewgraphs re status of facility as of 841029 encl. * NRC - No Detailed Affiliation Given. 85/09/26. 11pp. 33049:243-33049:291.
- 8510170086 Advises that Commissioners Roberts & Zach do not believe ACRS technical review required prior to restart decision. No comments offered by Commissioner Barnhart. Comments encl. W/o encl. CHILK, S.J. Office of the Secretary of the Commission. 84/11/16. PALLADINO Commissioners. 1p. 33049:292-33049:292.
- 8510170093 Forwards Commissioner responses to 841107 memo re restart of facility. Meeting will be held on 841119 to discuss legal & policy issues re facility operation. CHILK, S.J. Office of the Secretary of the Commission. 84/11/15. PALLADINO Commissioners. 1p. 33049:293-33049:294.
- 8510170097 Interim decision, concluding that util achieved understanding with NRC re scope & methods of making mods required by NRC for initial restart of facility cost effective. CARLOS, M. California, State of. 84/05/02. 39pp. 33049:295-33050:027.
- 8510170085 Further response to FOIA request for eight categories of records re EE Kent allegations concerning Midland, Palisades & San Onofre nuclear power plants. Forwards App F documents. App F documents also placed in PDR. FELTON, J.M. Division of Rules and Records. 85/09/30. RILLO, C.J. Thelen, Marrin, Johnson & Bridges. 2pp. 33049:042-33049:234.
- 8510170092 Rev 7 to Spec CS-P207, "Pipe Support Field Fabrication & Installation." * Bechtel Corp. 80/04/18. 39pp. 33049:046-33049:218.
- 8510170088 FOIA request for documents re Intl Nutronics facility in Dover, NJ. SWIGER, J.L. Envirocare, Inc. 85/04/29. FELTON, J. NRC - No Detailed Affiliation Given. 1p. 33045:173-33045:173.
- 8510170095 Responds to FOIA request for documents re Intl Nutronics facility in Dover, NJ for 850115-0517. Forwards App A & portions of App B documents. Portion of Document 1 of App B withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 85/09/30. SWIGER, J.L. Envirocare, Inc. 6pp. 33045:174-33046:075.
- 8510170102 Insp Rept 30-07026/85-01 on 850108-10. No noncompliance noted. Major areas inspected: personnel exposures, airborne levels in restricted & unrestricted areas & airborne releases to environ. WINTZ, E. Region 1, Office of Director. 85/01/24. 22pp. 33045:203-33045:266.
- 8510170105 Insp Rept 30-07026/85-02 on 850114-17. Major areas inspected: personnel exposures & airborne levels in restricted & unrestricted areas. Related info encl. THOMPSON, T. Region 1, Office of Director. 85/01/17. 17pp. 33045:267-33045:283.
- 8510170112 Insp Rept 30-07026/85-05 on 850221. No noncompliance noted. FRIEDMAN, L. NRC - No Detailed Affiliation Given. GLENN, J.E. Region 1, Office of Director. 85/03/11. 2pp. 33045:284-33045:285.
- 8510170124 Requests extension of completion date to 850719 for decommissioning of facility. Listed technical problems caused delays in completion of decommissioning. PARKER, G. International Nutronics, Inc. 85/03/13. MURLEY, T. Region 1, Office of Director. 2pp. 33045:286-33045:287.
- 8510170126 Insp Rept 30-07026/85-04 on 850214. Results of wipe test encl. FRIEDMAN, L. NRC - No Detailed Affiliation Given. 85/03/13. 2pp. 33045:288-33045:291.
- 8510170130 Insp Rept 30-07026/85-06 on 850225-28. No noncompliance noted. Major areas inspected: personnel exposures, airborne levels in restricted & unrestricted areas & airborne releases to environ. FRIEDMAN, L., GLENN, J.E. NRC - No Detailed Affiliation Given. 85/03/22. 18pp. 33045:292-33045:309.
- 8510170132 Insp Rept 30-07026/85-07 on 850304-05. No noncompliance noted. Major areas inspected: personnel exposures, airborne levels in restricted & unrestricted areas & airborne releases to environ. Record of 850329 telcon encl. FRIEDMAN, L., GLENN, J.E. NRC - No Detailed Affiliation Given. 85/03/22. 11pp. 33045:310-33045:320.
- 8510170134 Forwards qualifications of NUS PSC personnel directly involved by mgt responsibilities or by actual operations performance for desludging/solidification process for old source storage pool. Procedure encl. THOMAS, B.J. International Nutronics, Inc. 85/04/02. FRIEDMAN, L. Region 1, Office of Director. 1p. 33045:321-33045:321.
- 8510170138 Procedure 62, "Procedure to Remove Pool Water from New Source Storage Pool." * International Nutronics, Inc. 85/04/02. 17pp. 33045:322-33045:338.
- 8510170142 Insp Rept 30-07026/85-08 on 850311-13. Major areas inspected: personnel exposures, airborne levels in restricted & unrestricted areas & description of daily operations. FRIEDMAN, L., GLENN, J.E. NRC - No Detailed Affiliation Given. 85/04/08. 12pp. 33045:339-33045:352.
- 8510170146 Insp Rept 30-07026/85-09 on 850319.21 & 22. No noncompliance noted. Major areas inspected: personnel exposures, airborne levels in restricted & unrestricted areas & waterborne releases to environ. WINTZ, E., GLENN, J. Region 1, Office of Director. 85/03/22. 19pp. 33045:353-33046:012.
- 8510170168 Advises that 850313 request for extension of completion date to 850719 for decontaminating & decommissioning denied. Response to listed questions should be submitted within 20 days of tr date. MURLEY, T.E. Region 1, Office of Director. 85/04/19. PARKER, G.A. International Nutronics, Inc. 25pp. 33046:013-33046:014.
- 8510170173 Insp Rept 30-07026/85-10 on 850403-04. No noncompliance noted. FRIEDMAN, L., GLENN, J.E. NRC - No Detailed Affiliation Given. 85/04/22. 2pp. 33046:015-33046:016.

-8510170186 Insp Rept 30-07026/85-11 on 850415,17,18 & 19.No noncompliance noted.Major areas inspected:personnel exposures,airborne levels in restricted & unrestricted areas & airborne releases to environ.
WINTZ,E. Region 1, Office of the Director. 85/04/19. 22pp. 33046:017-33046:041.

-8510170194 Advises that all procedures needed to resume operations submitted.Due to lack of adequate assurances of payment under contract,work will not be resumed until payment assured.
KEEFFE,J. Envirocare, Inc. 85/04/21. GLENN,J. Region 1, Office of the Director. 1p. 33046:042-33046:044.

-8510170200 Responds to NRC 850419 ltr re plans to obtain svcs of contractor to perform balance of required work at Dover,NJ facility.Contractor will be chosen by 850510 to perform work.Chem-Nuclear general outline of proposed action encl.
PARKER,G. International Nutronics, Inc. 85/05/07. MURLEY,T. Region 1, Office of the Director. 15pp. 33046:045-33046:059.

-8510170206 Discusses 850503 telcon w/J Keith & G Parker of Envirocare, Inc & Intl Nutronics,Inc, respectively, re insurance policy. Affidavit of RE Volt encl.
GUTIERREZ,J.M. Region 1, Office of the Director. 85/05/07. Region 1, Office of the Director. 4pp. 33046:060-33046:063.

-8510170210 Forwards NUSOSC Procedure 7071-07,Rev 1,for removal of suspended solids in "old" tank for review.
SWIGER,J.L. Envirocare, Inc. 85/04/01. FRIEDMAN,L. Region 1, Office of the Director. 2pp. 33046:064-33046:065.

-8510170219 Forwards,for review,Rev 1 to NUS Procedure 7071-08, "Old Storage Pool Desludging & Gross Decontamination Procedure" & Procedure 62, "Health Physics Coverage for Activities Outlined in NUSOSC Procedure 7071-08..."
SWIGER,J.L. Envirocare, Inc. 85/04/02. FRIEDMAN,L. Region 1, Office of the Director. 3pp. 33046:066-33046:068.

-8510170220 Procedure 62, "Health Physics Coverage for Activities Outlined in NUSOSC Procedure 7071-08 during De-Sludging & Solidification of Old Co-60 Source Pool."
* Envirocare, Inc. 85/04/01. 7pp. 33046:069-33046:075.

8510170096 Appeals partial denial of FOIA request for documents re Philippine nuclear power plant.
SCHLEMMER,D.L. Government Accountability Project. 85/08/25. SHEA,J.L. Office of International Programs, Director. FELTON,J.M. Division of Rules and Records. 1p. 33050:285-33050:290.

8510170099 Responds to appeal re denial of FOIA request for documents re Philippine nuclear power plant.Appeal denied.Documents withheld (ref FOIA Exemption 4).
DIRCKS,W.J. Office of the Executive Director for Operations. 85/10/01. SCHLEMMER,D.L. Government Accountability Project. 1p. 33050:291-33050:291.

8510170103 FOIA request for documents re determination of applicant potential matl false statement on U-bolt sample (Board Notification 85-077),issued on 850820.
GARDE,B.P. Government Accountability Project. 85/08/29. Office of Administration. 2pp. 33050:292-33050:293.

8510170108 Partial response to FOIA request for records re NRC determination of potential matl false statement on U-bolt sample (Board Notification 85-077),issued on 850820.Forwards App A document.Search for addl documents continuing.
FELTON,J.M. Division of Rules and Records. 85/10/01. GARDE,B.P. Government Accountability Project. 2pp. 33050:294-33050:296.

-8510170111 Forwards applicant motion for reconsideration of ASLB 841218 order re matl false statements on torquing of U-bolts.W/o encl.
MIZUNO,G. Hearing Branch 1. 84/01/08. NOONAN,V. Comanche Peak Project (Technical Review Team). 1p. 33050:296-33050:296.

8510170221 Final response to FOIA request for documents re Dow Chemical Co.Forwards Apps O & P documents.Documents also available in PDR.App Q documents withheld (ref FOIA Exemption 4).
FELTON,J.M. Division of Rules and Records. 85/10/04. KOHN,S. CONDIT,R. Government Accountability Project. 5pp. 33050:297-33051:057.

-8510170234 Notifies that reactor room & lab secured to prevent unauthorized entry in response to 780112 ltr.Updated security plan will be submitted after radiation safety committee meets to discuss reactor security.
LANGNER,R.R. Dow Chemical Co. 78/01/19. KEPLER,J.G. Region 3, Chicago, Office of the Director. 1p. 33050:303-33050:303.

-8510170242 Forwards enforcement ltr & Initial Physical Security Insp Rept 50-264/76-01 on 780115-16.Portions deleted.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/09. ROY,G.W. Office of Inspection & Enforcement, Office of the Director. 2pp. 33050:304-33050:305.

-8510170252 Forwards Physical Protection Insp Rept 50-264/76-01 on 780115-16 & notice of violation.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/10. DELINE,R.D. Dow Chemical Co. 2pp. 33050:306-33050:307.

-8510170260 Notice of violation from physical protection insp on 760115-16.Portions deleted.
* NRC - No Detailed Affiliation Given. 76/02/10. 1p. 33050:308-33050:308.

-8510170263 Physical Protection Insp Rept 50-264/76-01 on 780115-16. Noncompliance noted re communications & access control. Portions withheld (ref 10CFR2.790).
BELANGER,J.L. Region 3, Chicago, Office of the Director. HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/06. 9pp. 33050:309-33050:317.

-8510170268 Forwards comments re 760224 ltr informing NRC of steps taken to correct noncompliance noted in 760210 ltr.Comments withheld (ref 10CFR2.790).
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/04/09. DELINE,R.D. Dow Chemical Co. 18pp. 33050:318-33050:335.

-8510170270 Discusses insp on 780110-12,per 780113 telcon re positive access controls.Enforcement correspondence will be forwarded upon completion of review of insp findings.Analysis of proposed civil penalty encl.Portions deleted.
KEPLER,J.G. Region 3, Chicago, Office of the Director. 78/01/13. LANGNER,R. Dow Chemical Co. 11pp. 33050:336-33050:346.

-8510170273 PNS-III-78-004 on 780110,during physical security insp.lack of positive access controls to reactor bldg discovered. Portions deleted (ref 10CFR2.790).Related draft documents encl.
DONAHUE,J.F. HIND,J.A. Region 3, Chicago, Office of the Director. 78/01/16. 25pp. 33050:347-33051:009.

-8510170322 Discusses noncompliance from security insp.Issuance of civil penalty recommended.W/o 780113 immediate action ltr & licensee reply.Draft insp rept & notice of violation encl. Portions deleted (ref 10CFR2.790).
KEPLER,J.G. Region 3, Chicago, Office of the Director. IAL. 78/03/02. HALLER,N.M. Division of Safeguards Inspections. 24pp. 33051:010-33051:033.

-8510170327 Forwards Insp Rept 50-264/78-01 on 780110-12 & notice of violation.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 78/07/12. HANES,J.H. Dow Chemical Co. 2pp. 33051:034-33051:035.

-8510170329 Notice of violation from insp on 780110-12.Portions deleted (ref 10CFR2.790).
* NRC - No Detailed Affiliation Given. 78/07/12. 1p. 33051:036-33051:036.

-8510170334 Insp Rept 50-264/78-01 on 780110-12.Noncompliance noted re security organization & access controls.Portions deleted (ref 10CFR2.790).Written statement in reply to notice of violation encl.
MADEDA,T.J., DUNLEAVY,J.J., HIND,J.A. Region 3, Chicago, Office of the Director. 78/07/11. 14pp. 33051:037-33051:057.

-8510170234 Notifies that reactor room & lab secured to prevent unauthorized entry in response to 780112 ltr.Updated security plan will be submitted after radiation safety committee meets to discuss reactor security.
LANGNER,R.R. Dow Chemical Co. 78/01/19. KEPLER,J.G. Region 3, Chicago, Office of the Director. 1p. 33050:303-33050:303.

-8510170242 Forwards enforcement ltr & Initial Physical Security Insp Rept 50-264/76-01 on 780115-16.Portions deleted.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/09. ROY,G.W. Office of Inspection & Enforcement, Office of the Director. 2pp. 33050:304-33050:305.

-8510170252 Forwards Physical Protection Insp Rept 50-264/76-01 on 780115-16 & notice of violation.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/10. DELINE,R.D. Dow Chemical Co. 2pp. 33050:306-33050:307.

-8510170260 Notice of violation from physical protection insp on 760115-16.Portions deleted.
* NRC - No Detailed Affiliation Given. 76/02/10. 1p. 33050:308-33050:308.

-8510170263 Physical Protection Insp Rept 50-264/76-01 on 780115-16. Noncompliance noted re communications & access control. Portions withheld (ref 10CFR2.790).
BELANGER,J.L. Region 3, Chicago, Office of the Director. HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/02/06. 9pp. 33050:309-33050:317.

-8510170268 Forwards comments re 760224 ltr informing NRC of steps taken to correct noncompliance noted in 760210 ltr.Comments withheld (ref 10CFR2.790).
HIND,J.A. Region 3, Chicago, Safeguards Branch. 76/04/09. DELINE,R.D. Dow Chemical Co. 18pp. 33050:318-33050:335.

-8510170270 Discusses insp on 780110-12,per 780113 telcon re positive access controls.Enforcement correspondence will be forwarded upon completion of review of insp findings.Analysis of proposed civil penalty encl.Portions deleted.
KEPLER,J.G. Region 3, Chicago, Office of the Director. 78/01/13. LANGNER,R. Dow Chemical Co. 11pp. 33050:336-33050:346.

-8510170273 PNS-III-78-004 on 780110,during physical security insp.lack of positive access controls to reactor bldg discovered. Portions deleted (ref 10CFR2.790).Related draft documents encl.
DONAHUE,J.F. HIND,J.A. Region 3, Chicago, Office of the Director. 78/01/16. 25pp. 33050:347-33051:009.

-8510170322 Discusses noncompliance from security insp.Issuance of civil penalty recommended.W/o 780113 immediate action ltr & licensee reply.Draft insp rept & notice of violation encl. Portions deleted (ref 10CFR2.790).
KEPLER,J.G. Region 3, Chicago, Office of the Director. IAL. 78/03/02. HALLER,N.M. Division of Safeguards Inspections. 24pp. 33051:010-33051:033.

-8510170327 Forwards Insp Rept 50-264/78-01 on 780110-12 & notice of violation.
HIND,J.A. Region 3, Chicago, Safeguards Branch. 78/07/12. HANES,J.H. Dow Chemical Co. 2pp. 33051:034-33051:035.

-8510170329 Notice of violation from insp on 780110-12.Portions deleted (ref 10CFR2.790).
* NRC - No Detailed Affiliation Given. 78/07/12. 1p. 33051:036-33051:036.

-8510170334 Insp Rept 50-264/78-01 on 780110-12.Noncompliance noted re security organization & access controls.Portions deleted (ref 10CFR2.790).Written statement in reply to notice of violation encl.
MADEDA,T.J., DUNLEAVY,J.J., HIND,J.A. Region 3, Chicago, Office of the Director. 78/07/11. 14pp. 33051:037-33051:057.

8510170346 Final response to FOIA request for four categories of documents re notices of violation for facility.Forwards Apps L & M documents.Documents also available in PDR.App M documents partially withheld (ref FOIA Exemption 7).
FELTON,J.M. Division of Rules and Records. 85/10/08. BELL,N. Nuclear Information & Resource Service. 4pp. 33051:058-33051:118.

-8510170348 Forwards sealed-up affidavit of WR McAfee re concerns over quality of const at facility & stabilize operate safety & w/o harm to public health.
GARDE,B.P. Government Accountability Project. 84/01/03. URYC,B. Region 2, Office of the Director. SINGLAIR,J. Office of Investigation. 49pp. 33051:064-33051:112.

-8510170352 Requests nondisclosure affidavits from staff members for access to transcripts re harassment of QC inspectors.W/o encl pages of transcripts re harassment.
O'REILLY,J.P. Region 2, Office of the Director. 84/01/23. VORSE,J.V. Office of Investigation. 1p. 33051:113-33051:113.

290 NONDOCKETED ITEMS

- 8510170357 Provides add info re 831025 interview. B Garde, B Jones & S Guild attend interview. Signed sworn statement not taken due to late hour of termination of interview. Info partially withheld.
URRYC, B. Region 2, Office of Director. 83/10/31. VORSE, J.Y. Office of Investigation. 2pp. 33051:114-33051:118.
- 8510170399 FOIA request for SECY-85-208, all past Regulatory Requirements Review Committee meeting minutes & procedures used by Ofc of Investigations re utility employee rights.
DEANE, M.R. NUS Corp. CD-LIS-85-757. 85/09/10. Division of Rules and Records. 1p. 33064:076-33064:076.
- 8510170418 Partial response to FOIA request for SECY-85-208, all past Regulatory Requirements Review Committee meeting minutes & procedures used by Ofc of Investigations re utility employee rights. SECY-85-208 denied. Forwards App A documents.
FELTON, J.M. Division of Rules and Records. 85/10/08. DEANE, M.R. NUS Corp. 5pp. 33064:077-33064:167.
- 8510170423 Forwards summary of first meeting of Regulatory Requirements Review Committee. Future meeting summaries will be distributed by committee chairman.
MUNTZING, L.M. Atomic Energy Commission. 74/04/29. O'LEARY, J.F., KNUTH, D.F. ROGERS, L.R. Atomic Energy Commission. 1p. 33064:082-33064:098.
- 8510170432 Summarizes Meeting 12 of Regulatory Requirements Review Committee on 7/4/81. Working Paper entitled, "SRP Section 3.83-Concrete & Steel Internal Structures of Steel or Concrete Containments," discussed.
CASE, E.G. Atomic Energy Commission. 74/09/27. MUNTZING, L.M. Atomic Energy Commission. 1p. 33064:099-33064:110.
- 8510170441 Summarizes Meeting 57 of Regulatory Requirements Review Committee on 7/7/81. Rev 1 to proposed Reg Guide 1.97 reviewed & recommended for approval subj to footnotes on research & cost experience.
CASE, E.G. Regulatory Requirements Review Committee. 77/02/02. GOSSICK, L.V. Office of the Executive Director for Operations. 2pp. 33064:111-33064:112.
- 8510170443 Summarizes Meeting 58 of Regulatory Requirements Review Committee on 7/7/81. Proposed Rev 1 to Reg Guide 1.106, characterized as Category 1, recommended.
CASE, E.G. Regulatory Requirements Review Committee. 77/02/09. GOSSICK, L.V. Office of the Executive Director for Operations. 3pp. 33064:113-33064:167.
- 8510180155 FOIA request for SECY-85-056A.
O'MEALIA, M.K. Doc-Search Associates. 85/09/30. FELTON, J.M. Division of Rules and Records. 1p. 33069:204-33069:204.
- 8510180187 Responses to FOIA request for SECY-85-056A re NPRDS. Forwards rept on status of NPRDS, per 851003 telcon. Document also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. O'MEALIA, M.K. Doc-Search Associates. 2pp. 33069:205-33069:226.
- 8510180185 "Seventh Semiannual Staff Evaluation of Status of NPRDS."
* AEC/D, Director's Office. 85/07/31. 20pp. 33069:207-33069:226.
- 8510180170 Final response to FOIA request for documents re 850719 ltr from Jensen. Search for records completed & no add records re request located.
FELTON, J.M. Division of Rules and Records. 85/10/11. RATNER, M.G. Ratner, M.G. 1p. 33069:193-33069:203.
- 8510180178 FOIA request for WCAP-9964, "Iodine & Cesium Spiking Source Terms for Accident Analysis," to be placed in PDR.
PEDRO, J. NUS Corp. CD-LIS-85-756. 85/09/20. Division of Rules and Records. 1p. 33068:360-33068:390.
- 8510180182 Responds to FOIA request for WCAP-9964, "Iodine & Cesium Spiking Source Terms for Accident Analysis," to be placed in PDR. NRC does not possess document.
FELTON, J.M. Division of Rules and Records. 85/10/09. PEDRO, J. NUS Corp. 1p. 33068:361-33068:361.
- 8510180391 Further response to FOIA request for all documents re NRC interim policy of mgt allegations - proposed 840919 Manual Chapter 0517, "Mgt of Allegations." App B documents & add documents identified by NRC withheld (ref FOIA Exemption 5).
FELTON, J.M. Division of Rules and Records. 85/10/11. GARDE, B.P. Government Accountability Project. 3pp. 33077:341-33077:345.
- 8510180394 Further response to FOIA request for documents re NRC review of EG&G rept on facility App B documents available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. MILLAR, B. Fort Worth Star-Telegram, Fort Worth, TX. 3pp. 33077:346-33077:349.
- 8510180400 Further response to FOIA request for License 12-00722-06 & Rock Island Arsenal application for license. Forwards App B documents. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. FLECKENSTEIN, J. ConDiesel Mobile Equipment. 2pp. 33079:004-33079:033.
- 8510180402 Package of applications for renewal & amendments to License 12-00722-06.
* Army, Dept. of. 83/06/08. 27pp. 33079:007-33079:033.
- 8510180409 Responds to appeal re denial of FOIA request for GE PRA for GESSAR-II standardization. Plant design. Forwards 11 pages from PRA due to court approved stipulation of 850719 settlement. Info also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/10/11. CURRAN, D. Harmon, Weiss & Jordan. 1p. 33078:018-33078:040.
- 8510180410 PRA documentation for GESSAR-II standardized plant design.
* General Electric Co. 85/10/11. 11pp. 33078:019-33078:040.
- 8510180414 Further response to FOIA request for documents re NRC 840629 meeting w/utl concerning investigation on illegal use of drugs at facility. Add documents not found. Search complete.
FELTON, J.M. Division of Rules and Records. 85/10/10. GARDE, B.P. Government Accountability Project. 1p. 33077:124-33077:126.
- 8510180442 Further response to FOIA request for documents re TMI. Forwards App H documents App H & I documents available in PDR. App J & K documents withheld partially or in entirety (ref FOIA Exemptions 5 & 7).
FELTON, J.M. Division of Rules and Records. 85/10/09. BERNABE, L. Government Accountability Project. 7pp. 33077:156-33077:190.
- 8510180453 Discusses grand jury investigation of activities & persons within NRC re conspiracy to defraud US by impairing & impeding lawful functions & responsibilities & obstruction of agency proceeding, per 841031 meeting w/NRC.
GREENSPUN, J.S. Justice, Dept. of. 84/11/01. HAYES, B.B. Office of Investigation. 3pp. 33077:169-33077:171.
- 8510180452 Ack receipt of 841101 ltr re 841031 meeting. NRC pledges complete cooperation in investigation. All documents deemed pertinent will be made available w/o subpoena.
HAYES, B.B. Office of Investigation. 84/11/07. GREENSPUN, J.S. Justice, Dept. of. 1p. 33077:172-33077:172.
- 8510180455 Forwards response to inquiry re DOJ grand jury investigation of NRC employees. Press inquiries should be referred to Ofc of Public Affairs.
PALLADINO, N.J. Commissioners. 84/11/09. DIRCKS, W.J., PLAINE, H.H., ZERBE, J.E. NRC - No Detailed Affiliation Given. App. 33077:173-33077:176.
- 8510180459 Forwards NRC ltrs sent to respective oversight committees, including transmittal memo to CL Fuller, per 841114 request. No record exists of B Dircks telcon to regional administrators advising of grand jury investigation.
HAYES, B.B. Office of Investigation. 84/11/15. GREENSPUN, J.S. Justice, Dept. of. 1p. 33077:177-33077:177.
- 8510180466 Forwards ltrs sent to NRC congressional oversight committees informing of DOJ grand jury investigation of NRC employees.
PALLADINO, N.J. Commissioners. 84/11/08. FULLER, C.L. President of U.S. & Executive Offices. 1p. 33077:178-33077:178.
- 8510180468 Advises that DOJ notified NRC of grand jury investigation of alleged wrongdoing by NRC employees re actions within regulatory process. NRC pledged complete cooperation.
PALLADINO, N.J. Commissioners. 84/11/08. BEVILL, T. House of Rep., Appropriations. HATFIELD, M.O. Senate, Appropriations. SIMPSON, A.K. Senate, Environment & Public Works. 6pp. 33077:179-33077:184.
- 8510180481 Discusses role of NRC attys in advising NRC employees called to appear before grand jury re investigation of alleged misconduct by NRC employees. Attys may advise employees to cooperate fully.
CUNNINGHAM, G.H. Office of the Executive Legal Director. 84/11/20. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 33077:185-33077:185.
- 8510180496 Informs that J Greenspun will not be back at ofc until after 850101.
HAYES, B. Office of Investigation. 84/12/17. CONNELLY, S. Office of Investigation. 1p. 33077:186-33077:186.
- 8510180500 "Summary of Order Before Commission for Affirmation (SECY-84-475A)."
* NRC - No Detailed Affiliation Given. 85/02/14. 2pp. 33077:187-33077:188.
- 8510180504 Discusses whether J Greenspun 841101 ltr to author should be released to employee population. Release of ltr would assist in alleviating employee apprehension re grand jury matters.
HAYES, B.B. Office of Investigation. 84/11/14. Office of Investigation. 2pp. 33077:189-33077:190.
- 8510180450 Discusses grand jury investigation of activities & persons within NRC re conspiracy to defraud US by impairing & impeding lawful functions & responsibilities & obstruction of agency proceeding, per 841031 meeting w/NRC.
GREENSPUN, J.S. Justice, Dept. of. 84/11/01. HAYES, B.B. Office of Investigation. 3pp. 33077:169-33077:171.
- 8510180452 Ack receipt of 841101 ltr re 841031 meeting. NRC pledges complete cooperation in investigation. All documents deemed pertinent will be made available w/o subpoena.
HAYES, B.B. Office of Investigation. 84/11/07. GREENSPUN, J.S. Justice, Dept. of. 1p. 33077:172-33077:172.
- 8510180455 Forwards response to inquiry re DOJ grand jury investigation of NRC employees. Press inquiries should be referred to Ofc of Public Affairs.
PALLADINO, N.J. Commissioners. 84/11/09. DIRCKS, W.J., PLAINE, H.H., ZERBE, J.E. NRC - No Detailed Affiliation Given. App. 33077:173-33077:176.
- 8510180459 Forwards NRC ltrs sent to respective oversight committees, including transmittal memo to CL Fuller, per 841114 request. No record exists of B Dircks telcon to regional administrators advising of grand jury investigation.
HAYES, B.B. Office of Investigation. 84/11/15. GREENSPUN, J.S. Justice, Dept. of. 1p. 33077:177-33077:177.
- 8510180456 Forwards ltrs sent to NRC congressional oversight committees informing of DOJ grand jury investigation of NRC employees.
PALLADINO, N.J. Commissioners. 84/11/08. FULLER, C.L. President of U.S. & Executive Offices. 1p. 33077:178-33077:178.
- 8510180484 Advises that DOJ notified NRC of grand jury investigation of alleged wrongdoing by NRC employees re actions within regulatory process. NRC pledged complete cooperation.
PALLADINO, N.J. Commissioners. 84/11/08. BEVILL, T. House of Rep., Appropriations. HATFIELD, M.O. Senate, Appropriations. SIMPSON, A.K. Senate, Environment & Public Works. 6pp. 33077:179-33077:184.
- 8510180491 Discusses role of NRC attys in advising NRC employees called to appear before grand jury re investigation of alleged misconduct by NRC employees. Attys may advise employees to cooperate fully.
CUNNINGHAM, G.H. Office of the Executive Legal Director. 84/11/20. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 33077:185-33077:185.
- 8510180496 Informs that J Greenspun will not be back at ofc until after 850101.
HAYES, B. Office of Investigation. 84/12/17. CONNELLY, S. Office of Investigation. 1p. 33077:186-33077:186.
- 8510180500 "Summary of Order Before Commission for Affirmation (SECY-84-475A)."
* NRC - No Detailed Affiliation Given. 85/02/14. 2pp. 33077:187-33077:188.

-8510180504 Discusses whether J Greenspun 841101 ltr to author should be released to employee population. Release of ltr would assist in alleviating employee apprehension re grand jury matters.
HAYES, S.B. Office of Investigation. 84/11/14. Office of Investigation. 2pp. 33077:189-33077:190.

8510180465 FOIA request for four categories of documents re QC at facility. Newspaper articles re problems w/QC encl.
BELL, N. Nuclear Information & Resource Service. 85/09/23. FELTON, J.M. Division of Rules and Records. 6pp. 33068:349-33068:353.

8510180467 Partial response to FOIA request for four categories of documents re QC at facility. Documents on App A available in PDR. Search continuing.
FELTON, J.M. Division of Rules and Records. 85/10/11. BELL, N. Nuclear Information & Resource Service. 2pp. 33068:354-33068:356.

8510180507 FOIA request for six categories of documents re NRC contracts.
EPPS, K. Affiliation Not Assigned. 85/10/07. NRC - No Detailed Affiliation Given. 1p. 33077:191-33077:191.

8510180511 Responds to FOIA request for NRC contracts. informs that contracts routinely placed in PDR for public insp & copying.
FELTON, J.M. Division of Rules and Records. 85/10/15. EPPS, K. Affiliation Not Assigned. 1p. 33077:192-33077:192.

8510220125 Further response to FOIA request for documents re EG&G rept on harassment & intimidation. Forwards App B documents. Documents also available in PDR. Portions of App C Documents 1-4 withheld (ref FOIA Exemptions 4 & 6).
FELTON, J.M. Division of Rules and Records. 85/10/16. GARDE, B., GREGORY, J.S. Government Accountability Project. 4pp. 33099:325-33100:121.

-8412100470 Provides clarification on NRC position re intimidation at facility. Overall task EG&G contracted to perform defined. EG&G rept will be used as input to NRC assessment.
EISENHUT, D.G. Division of Licensing. 84/12/04. HAYES, S.B. Office of Investigation. 1p. 33100:111-33100:111.

-8510220137 Forwards statements of work for FINs A-6819 (Project 2), A-6821 (Project 2) & A-0802 re evaluation of selected open NRC items at plant for review & comment.
DONOHEW, J. Division of Licensing. FIN A-6819. 84/06/15. KALTMAN, M. Planning & Program Analysis Staff. 1p. 33099:331-33099:331.

-8510220148 Forwards "Evaluation of Selected NRC Open Items Before Fuel Load (Program 1)," technical assistance project, for review & concurrence. Response requested within 10 days.
KALTMAN, M. Planning & Resource Analysis Branch. FIN A-6819. 84/06/15. HAYES, M. Office of Nuclear Regulatory Research, Director. MUIR, A.P. Director's Office, Office of Inspection and Enforcement. EVANS, J. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33099:332-33099:332.

-8510220154 Forwards std order for DOE work, supporting "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2. Proposal requested within 14 days.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/02. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 15pp. 33099:333-33099:347.

-8510220161 Approves CM Rice & W Stratton as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per LP Leach 840717 request.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/18. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 2pp. 33099:348-33099:349.

-8510220171 Forwards project descriptive summary for FIN A-6819, "Evaluation of Selected NRC Open Items Before Fuel Load (Program 1)," statement of work & NRC Form 173, for review & approval.
FUNCHES, J.L. Planning & Program Analysis Staff. FIN A-6819. 84/07/13. BECKWITH, C.A. Office of Resource Management, Director. 12pp. 33099:350-33099:362.

-8510220178 Draft "Investigation & Assessment of Work Climate at Comanche Peak Electric Station."
KAPLAN, B.L., MARGUILES, N., RICE, C.M. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6429-4. 84/08/31. NRC - No Detailed Affiliation Given. 45pp. 33100:001-33100:045.

-8510220187 Notifies that FINs B-8011, "Science Applications, Inc. Contract Extension," & A-6819 & A-0802, "Near-Term OL Outstanding Action Review" for INEL & LLL, respectively, approved w/ listed qualifications.
WILLIAMS, M.H. NRC - No Detailed Affiliation Given. FIN B-8011. 84/08/07. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 1p. 33100:046-33100:046.

-8510220202 Forwards, for concurrence, std order for DOE work, changing statement of work for "Evaluation of Selected NRC Open Items Before Plant Fuel Load," (FIN A-6819, Project 2).
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/08/24. SIMS, F.L. Energy, Dept. of. 4pp. 33100:047-33100:050.

-8510220208 Forwards INEL planned staffing for Cycle 4 Comanche Peak Technical Review Team. Planned staffing for Cycle 5 will be identified as soon as possible.
WILLIAMS, M.H. Division of Licensing. 84/09/06. IPPOLITO, T.A. Comanche Peak Project (Technical Review Team). 2pp. 33100:051-33100:052.

-8510220215 Forwards, for concurrence, std order for DOE work, "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, INEL proposal dtd Sept 1984 acceptable LP Leach 850905 & 20 ltrs to DOE encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/09/13. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 9pp. 33100:053-33100:061.

-8510220225 Approves DG Bowers & H Margulies as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per INEL 840727 request. Related documentation encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/31. SIMS, F.L. Energy, Dept. of. 49pp. 33100:062-33100:110.

-8510220239 Forwards project & budget proposals for NRC work for Rev 1 to, "Evaluation of Selected NRC Open Items Before Plant Fuel Load" & "Evaluation of Selected Open NRC Activities at Near-Term OL Sites Needing Action."
MILAM, S.B. Energy, Dept. of, Idaho Operations Office. FIN A-6819. 84/08/23. WILLIAMS, M. Division of Licensing. 1p. 33100:112-33100:112.

-8510220252 Rev 1 to project & budget proposal for NRC work: "Evaluation of Selected NRC Open Items Before Plant Fuel Load."
OBENCHAIN, C.F., BARNES, B.L., WHITTEMORE, J.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6819. 85/08/15. DONOHEW, J.N., LAZO, L.M., CRUTCHFIELD, D. Office of Nuclear Reactor Regulation, Director. 9pp. 33100:113-33100:121.

-8412100470 Provides clarification on NRC position re intimidation at facility. Overall task EG&G contracted to perform defined. EG&G rept will be used as input to NRC assessment.
EISENHUT, D.G. Division of Licensing. 84/12/04. HAYES, S.B. Office of Investigation. 1p. 33100:111-33100:111.

-8510220137 Forwards statements of work for FINs A-6819 (Project 2), A-6821 (Project 2) & A-0802 re evaluation of selected open NRC items at plant for review & comment.
DONOHEW, J. Division of Licensing. FIN A-6819. 84/06/15. KALTMAN, M. Planning & Program Analysis Staff. 1p. 33099:331-33099:331.

-8510220148 Forwards "Evaluation of Selected NRC Open Items Before Fuel Load (Program 1)," technical assistance project, for review & concurrence. Response requested within 10 days.
KALTMAN, M. Planning & Resource Analysis Branch. FIN A-6819. 84/06/15. HAYES, M. Office of Nuclear Regulatory Research, Director. MUIR, A.P. Director's Office, Office of Inspection and Enforcement. EVANS, J. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33099:332-33099:332.

-8510220154 Forwards std order for DOE work, supporting "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2. Proposal requested within 14 days.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/02. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 15pp. 33099:333-33099:347.

-8510220161 Approves CM Rice & W Stratton as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per LP Leach 840717 request.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/18. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 2pp. 33099:348-33099:349.

-8510220171 Forwards project descriptive summary for FIN A-6819, "Evaluation of Selected NRC Open Items Before Fuel Load (Program 1)," statement of work & NRC Form 173, for review & approval.
FUNCHES, J.L. Planning & Program Analysis Staff. FIN A-6819. 84/07/13. BECKWITH, C.A. Office of Resource Management, Director. 12pp. 33099:350-33099:362.

-8510220178 Draft "Investigation & Assessment of Work Climate at Comanche Peak Electric Station."
KAPLAN, B.L., MARGUILES, N., RICE, C.M. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6429-4. 84/08/31. NRC - No Detailed Affiliation Given. 45pp. 33100:001-33100:045.

-8510220187 Notifies that FINs B-8011, "Science Applications, Inc. Contract Extension," & A-6819 & A-0802, "Near-Term OL Outstanding Action Review" for INEL & LLL, respectively, approved w/ listed qualifications.
WILLIAMS, M.H. NRC - No Detailed Affiliation Given. FIN B-8011. 84/08/07. CRUTCHFIELD, D. Assistant Director for Safety Assessment. 1p. 33100:046-33100:046.

-8510220202 Forwards, for concurrence, std order for DOE work, changing statement of work for "Evaluation of Selected NRC Open Items Before Plant Fuel Load," (FIN A-6819, Project 2).
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/08/24. SIMS, F.L. Energy, Dept. of. 4pp. 33100:047-33100:050.

-8510220208 Forwards INEL planned staffing for Cycle 4 Comanche Peak Technical Review Team. Planned staffing for Cycle 5 will be identified as soon as possible.
WILLIAMS, M.H. Division of Licensing. 84/09/06. IPPOLITO, T.A. Comanche Peak Project (Technical Review Team). 2pp. 33100:051-33100:052.

-8510220215 Forwards, for concurrence, std order for DOE work, "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, INEL proposal dtd Sept 1984 acceptable LP Leach 850905 & 20 ltrs to DOE encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/09/13. WADE, T.E. Energy, Dept. of, Idaho Operations Office. 9pp. 33100:053-33100:061.

-8510220225 Approves DG Bowers & H Margulies as subcontractors to assist INEL in "Evaluation of Selected NRC Open Items Before Plant Fuel Load," FIN A-6819, Project 2, per INEL 840727 request. Related documentation encl.
EISENHUT, D.G. Division of Licensing. FIN A-6819. 84/07/31. SIMS, F.L. Energy, Dept. of. 49pp. 33100:062-33100:110.

-8510220239 Forwards project & budget proposals for NRC work for Rev 1 to, "Evaluation of Selected NRC Open Items Before Plant Fuel Load" & "Evaluation of Selected Open NRC Activities at Near-Term OL Sites Needing Action."
MILAM, S.B. Energy, Dept. of, Idaho Operations Office. FIN A-6819. 84/08/23. WILLIAMS, M. Division of Licensing. 1p. 33100:112-33100:112.

-8510220252 Rev 1 to project & budget proposal for NRC work: "Evaluation of Selected NRC Open Items Before Plant Fuel Load."
OBENCHAIN, C.F., BARNES, B.L., WHITTEMORE, J.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6819. 85/08/15. DONOHEW, J.N., LAZO, L.M., CRUTCHFIELD, D. Office of Nuclear Reactor Regulation, Director. 9pp. 33100:113-33100:121.

8510220129 FOIA request for info submitted by listed manufacturers & users of "Registry of Radioactive Sealed Sources & Safety Evaluation of Sources."
URBAN, K.H. CintiChem, Inc. 85/09/23. Office of Administration. 1p. 33107:001-33107:001.

292 NONDOCKETED ITEMS

- 8510220134** Responds to FOIA request for info submitted by specified manufacturers & users of sealed sources for "Registry of Radioactive Sealed Sources & Safety Evaluation of Sources." Documents listed in app available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/16. URBAN,K. Cirtchem, Inc. 4pp. 33107-002-33107-108.
- 8510220144** Package of documents re registry of radioactive sealed sources & devices.
* NRC - No Detailed Affiliation Given. 85/10/16. 105pp. 33107-006-33107-108.
- 8510220156** FOIA request for records re AEC Sept 1967 investigation of worker exposures to enriched U during 1966 & 1967 at Atomics Int'l in Canoga Park, CA.
JALON,A. Los Angeles Times Los Angeles, CA. 85/07/18. FELTON,J. Division of Rules and Records. 1p. 33097-204-33097-204.
- 8510220162** Further response to FOIA request for documents re insp/ investigation of allegations on Nine Mile Point by J. Ryan, R. Norman & A. Laratta. Documents listed in App A available in PDR. Search for add documents continuing.
FELTON,J.M. Division of Rules and Records. 85/10/10. GARDE,B.P. Government Accountability Project. 2pp. 33097-300-33098-129.
- 8510220189** Informs that action required for closeout of Allegation 84-A-0061 completed. Documents that should be included in final file attached. W/o encl.
COLLINS,S.J. NRC - No Detailed Affiliation Given. 84/08/21. SHROPSHIRE,A. NRC - No Detailed Affiliation Given. 1p. 33097-305-33097-305.
- 8510220176** Advises that Allegation RI-84-A-0061 re improper disposition of QA audit findings entered into NRC allegation tracking sys. Allegation reviewed & evaluated for followup actions during allegation panel 840430 meeting.
HAVERKAMP,D.R. NRC - No Detailed Affiliation Given. 84/05/03. STAROSTECKI,R. NRC - No Detailed Affiliation Given. 4pp. 33097-306-33098-129.
- 8510220184** Recommends closeout of Allegation 84-A-0156, "Lead Auditor Clarification," per encl Insp Rept 50-410/84-15. No response to allegor required.
LINVILLE,J.C. NRC - No Detailed Affiliation Given. 85/05/15. SHROPSHIRE,A. NRC - No Detailed Affiliation Given. 60pp. 33107-109-33107-166.
- 8510220167** Partial response to FOIA request for records re AEC Sept 1967 investigation of worker exposures to enriched U during 1966 & 1967 at Atomics Int'l. Forwards App A documents. Portions withheld (ref FOIA Exemption 5).
FELTON,J.M. Division of Rules and Records. 85/10/15. JALON,A. Los Angeles Times Los Angeles, CA. 3pp. 33097-205-33097-299.
- 8510220175** Forwards compliance investigation rept re exposures to airborne U compounds at Atomics Int'l. Investigation disclosed that procedures not followed & matters noted during meeting w/ mgt as possible violations.
COOLEY,W.J. Atomic Energy Commission. 67/11/06. ROEDER,J.R. Atomic Energy Commission. 2pp. 33097-208-33097-209.
- 8510220188** Compliance investigation rept on 670928-29 Noncompliance noted: exposure of individuals to concentrations of radioactive mat'l in restricted areas & failure to rept overexposure & excessive levels & concentrations.
COOLEY,W.J., METZGER,J.R., BOOK,H.E. Atomic Energy Commission. 67/11/06. 35pp. 33097-210-33097-245.
- 8510220196** Submits rept of inhalation exposures at Atomics Int'l. Japan Atomic Energy Research Inst. Air sample, inhalation exposures & internal dosimetric data for workers encl. Portions deleted.
SAXE,D. Rockwell International Corp. 67AT-6308. 67/11/13. LOW,L.D. Atomic Energy Commission. 10pp. 33097-246-33097-255.
- 8510220210** Insp rept on 680402-03. No noncompliance noted. Areas inspected: nuclear safety & correction of U airborne concentration problem. Info deleted.
COOLEY,W.J., BOOK,H.E. Atomic Energy Commission. 68/04/30. 16pp. 33097-256-33097-271.
- 8510220223** Forwards notes of 680404 reinsp of License SNM-21. No noncompliance noted. Insp included tour w/ emphasis on potential health & safety problems which might arise during Pu wet chemistry operations. Info deleted.
METZGER,J.R. Atomic Energy Commission. 68/04/15. COOLEY,W.J. Atomic Energy Commission. 1p. 33097-272-33097-272.
- 8510220245** Insp rept of reinsp on 680404. No noncompliance noted. Major areas inspected: whole body counting of employees involved in incident, new U powder production facility & problems w/ analytical chemistry operation at Santa Susana Pw facility.
METZGER,S.R., COOLEY,W.L., BOOK,H.E. Atomic Energy Commission. 68/04/23. 27pp. 33097-273-33097-288.
- 8510220257** Forwards compliance inquiry memo re Atomics Int'l accident w/ ARC-melt furnace. Design changes which could enhance safety include installation of water alarm sys at base of furnace. W/o memo. Info deleted.
* Atomic Energy Commission. 68/05/15. ROEDER,J.R. Atomic Energy Commission. 1p. 33097-289-33097-290.
- 8510220272** Discusses Atomics Int'l accident w/ advanced test reactor ARC-melt furnace. Info deleted.
* Atomic Energy Commission. 68/05/15. ROEDER,J.R. Atomic Energy Commission. 10pp. 33097-291-33097-299.
- 8510220197** Partial response to FOIA request for documents re util 850726 briefing on readiness review program, including transcript. Documents listed in Apps A & B available in PDR. App C documents withheld (ref FOIA Exemption 5).
FELTON,J.M. Division of Rules and Records. 85/10/03. GARDE,B.P. Government Accountability Project. 5pp. 33099-251-33099-324.
- 8510220207** Forwards "Readiness Review Pilot Program," scheduled for 850726.
MILLER,J.H. Georgia Power Co. 85/07/17. CHILK,S. Office of the Secretary of the Commission. 4pp. 33099-272-33099-275.
- 8510220211** Viewgraphs entitled, "Pilot Readiness Review Program for Vogtle Electric Generating Plant, Unit 1."
RICE,P.D. Georgia Power Co. 85/07/26. 46pp. 33099-276-33099-323.
- 8510220220** Staff requirements memo re util 850726 briefing on operational readiness review pilot program in Washington, DC.
CHILK,S.J. Office of the Secretary of the Commission. 850726A. 85/08/02. Office of the Secretary of the Commission. 1p. 33099-324-33099-324.
- 8510220230** FOIA request for documents & transcript of readiness review program briefing on 850726.
GARDE,B.P. Government Accountability Project. 85/08/21. Office of Administration. 2pp. 33099-249-33099-250.
- 8510220425** FOIA request for documents re qualifications of senior reactor operators for listed plants.
TUCKER,H.B. Duke Power Co. 85/08/28. FELTON,J.M. Division of Rules and Records. 2pp. 33107-167-33107-168.
- 8510220426** Responds to FOIA request for documents re qualifications of senior reactor operators for 19 units listed in request. Abstracted records indicating training, educ & experience encl.
FELTON,J.M. Division of Rules and Records. 85/10/03. TUCKER,H.B. Duke Power Co. 1p. 33107-169-33108-002.
- 8510220428** Abstracted records showing educ, training & work experience data for senior reactor operators.
* NRC - No Detailed Affiliation Given. 85/10/03. 200pp. 33107-170-33107-360.
- 8510230008** FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101.
JACOBS,R. Washington Document Service. 85/07/02. FELTON,J.M. Division of Rules and Records. 1p. 33108-263-33108-263.
- 8510230016** Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/10/04. JACOBS,R. Washington Document Service. 7pp. 33108-264-33109-164.
- 8510230023** Forwards Press Release 85-108 re proposed fine concerning util alleged violation of NRC requirements which prohibit discrimination against employee for identifying safety concerns to mgt.
KAMMERER,C. Office of Congressional Affairs. 85/08/13. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-021-33109-022.
- 8510230027** Forwards Press Release 84-16 re proposed civil penalty in amount of \$40,000 against util for alleged violation of radiation protection requirements during 831014 incident.
KAMMERER,C. Office of Congressional Affairs. 84/01/02. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108-274-33108-275.
- 8510230185** Forwards Press Release 84-69 re NRC reduction of fine for 1983 violation. Pressure sensing device capped. Fine reduced due to short duration of violation, small size of reactor & comparable enforcement actions.
KAMMERER,C. Office of Congressional Affairs. 84/06/01. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-008-33109-009.
- 8510230198** Forwards Press Release I-84-69 re NRC proposed fine against util for six alleged violations, including overexposure of employee to I-125, failure to maintain control of mat'l & failure to perform thyroid bioassays.
KAMMERER,C. Office of Congressional Affairs. 84/06/25. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109-013-33109-015.
- 8408010318** Responds to 840620 ltr re investigation involving mat'l false statement. NRC policy of levying civil penalties on licensee instead of individual elucidated. Violations addressed in D Alabach 840606 ltr under consideration for enforcement.
DIRCKS,W.J. Office of the Executive Director for Operations. 84/07/17. HILLIS,E.H. House of Rep. 2pp. 33109-089-33109-093.
- 8408010320** Forwards constituent D Alabach 840606 ltr questioning fines imposed on licensee for mat'l false statements.
HILLIS,E.H. House of Rep. 84/06/20. KAMMERER,C. Office of Congressional Affairs. 3pp. 33109-091-33109-093.
- 8510230018** Forwards Press Release 84-4 re NRC proposed civil penalty in amount of \$40,000 against util for failure to post continuous firewatch while both trains of stand-by gas treatment sys fire suppression sys inoperable.
KAMMERER,C. Office of Congressional Affairs. 84/01/10. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108-271-33108-273.
- 8510230032** Forwards Press Release 85-106 re proposed fine for util alleged violation of NRC requirements concerning employee discrimination in cleanup program.
KAMMERER,C. Office of Congressional Affairs. 85/08/12. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-023-33109-024.
- 8510230041** Forwards Press Release 85-99 re NRC proposed civil penalty in amount of \$150,000 against util for violation of requirements concerning reactor vessel water level instruments.
KAMMERER,C. Office of Congressional Affairs. 85/07/23. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109-025-33109-026.
- 8510230042** Forwards response to JR Bass 840102 request for info re 831227 imposition of civil penalty in amount of \$100,000.
DIRCKS,W.J. Office of the Executive Director for Operations. 84/02/28. NUNN,S. Senate. 1p. 33108-276-33108-276.
- 8510230045** Forwards notice of violation issued to util based on 850409-0531 insp.
KAMMERER,C. Office of Congressional Affairs. 85/07/16. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 1p. 33109-027-33109-038.
- 8510230048** Forwards response to JR Bass 840102 request for info re 831227 proposed civil penalty in amount of \$100,000. Listed documentation, including NRC 831227 proposed civil penalty & computer printout describing violations, encl.
DIRCKS,W.J. Office of the Executive Director for Operations. 84/02/28. THOMAS,L. House of Rep. 4pp. 33108-277-33108-286.

- 8510230051 Forwards Press Release 85-95 re NRC proposed fine against util for alleged violations of safety requirements during Apr 1985.
KAMMERER,C. Office of Congressional Affairs. 85/07/15. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:039-33109:041.
- 8510230054 Forwards corrected Page 2 to 831227 proposed imposition of civil penalties based on violations noted in Insp Rept 50-366/83-23 re improper shutdown/Correction due to administrative oversight.
O'REILLY,J.P. Region 2, Office of Director. EA-83-086. 84/01/06. KELLY,R.J. Georgia Power Co. 3pp. 33108:287-33108:329.
- 8510230057 Forwards Press Release 1-85-68 re NRC proposed fine for Princeton Univ. alleged violations of radiation protection requirements,resulting in overexposure of lab worker.
KAMMERER,C. Office of Congressional Affairs. 85/07/05. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:042-33109:043.
- 8510230058 Requests response to encl JR Bass 840102 ltr re proposed fine against util.
THOMAS,L. House of Rep. 84/02/01. KAMMERER,C. Office of Congressional Affairs. 2pp. 33108:330-33108:331.
- 8510230060 Forwards Press Release 85-80 re NRC proposed civil penalty in amount of \$500,000 against util for alleged matl false statements made to NRC concerning operator qualifications & training.
KAMMERER,C. Office of Congressional Affairs. 85/06/04. MARKEY,E.J. House of Rep., Energy & Commerce. UDALL House of Rep. SIMPSON Senate. 3pp. 33109:044-33109:046.
- 8510230065 Forwards Press Release 84-26 re NRC proposed fine against util for 12 alleged violations of Tech Specs while performing work at facility.
KAMMERER,C. Office of Congressional Affairs. 84/02/29. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108:332-33108:334.
- 8510230069 Forwards Press Release 85-78 re NRC proposed fine against util for alleged violations of requirements concerning unplanned occupational radiation exposures & failure to control contractor work forces.
KAMMERER,C. Office of Congressional Affairs. 85/06/03. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:047-33109:049.
- 8510230077 Forwards Press Release 1-84-32 re NRC proposed fine against Pittsburgh Testing Lab for alleged violation of NRC regulations that require controlling access to high radiation areas.
KAMMERER,C. Office of Congressional Affairs. 84/03/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:335-33108:336.
- 8510230085 Forwards Press Release 84-26 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violation of security requirements during 831110 practice radiological evacuation drill.
KAMMERER,C. Office of Congressional Affairs. 84/03/07. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:337-33108:338.
- 8510230090 Forwards Press Release 85-75 re NRC proposed fine against util for alleged violations of requirements concerning failure to take corrective action when warranted concerning QA program.
KAMMERER,C. Office of Congressional Affairs. 85/05/24. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:050-33109:051.
- 8510230097 Forwards Press Release 85-70 re NRC proposed civil penalty in amount of \$50,000 against TVA for alleged violation of security requirements.
KAMMERER,C. Office of Congressional Affairs. 85/05/17. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:052-33109:053.
- 8510230098 Forwards Press Release 84-34 re NRC proposed imposition of civil penalty in amount of \$20,000 against util for alleged violation of security requirements.
KAMMERER,C. Office of Congressional Affairs. 84/03/16. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33108:339-33108:340.
- 8510230102 Forwards Press Release 84-36 re NRC proposed fine against util for 30 alleged violations.Util ordered to hire consultant firm to evaluate organization.
KAMMERER,C. Office of Congressional Affairs. 84/03/21. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON,A. Senate. UDALL,M. House of Rep. 2pp. 33108:341-33108:343.
- 8510230106 Forwards Press Release 85-68 re NRC proposed fine against util for alleged noncompliance concerning improperly conducted preoperational testing program.
KAMMERER,C. Office of Congressional Affairs. 85/05/09. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:054-33109:055.
- 8510230114 Forwards Press Release 85-83 re NRC proposed fine against Nuclear Fuel Svcs,Inc for alleged noncompliance w/requirements concerning release of radioactive matl to work area.
KAMMERER,C. Office of Congressional Affairs. 85/05/03. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:056-33109:057.
- 8510230118 Forwards Press Release 84-44 re NRC reduction of proposed civil penalty in amount of \$40,000 to \$20,000 due to prompt & enter.lvs corrective action by util.Penalty proposed for breakdown of QA program.
KAMMERER,C. Office of Congressional Affairs. 84/04/04. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108:344-33108:346.
- 8510230126 Forwards Press Release 85-66 re NRC proposed imposition of civil penalty in amount of \$112,500 against TVA for alleged noncompliance w/requirements concerning 840419 event when tube used to insert instrumentation ejected.
KAMMERER,C. Office of Congressional Affairs. 85/05/09. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:058-33109:059.
- 8510230129 Forwards NRC enforcement policy,table of 1983 proposed civil penalties,including licensees,amounts proposed & amounts imposed or paid,supplies to enforcement policy authorizing penalties & four vols of NUREG-0940 W/o NUREG-0940.
AXELRAD,J.A. Enforcement Staff. 84/04/18. GINN,N. Senate. Governmental Affairs. 12pp. 33108:347-33108:358.
- 8510230134 Forwards Press Release 84-50 re NRC proposed fine against util for failure to implement adequate radiological controls during maint.
KAMMERER,C. Office of Congressional Affairs. 84/04/18. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33108:359-33108:361.
- 8510230139 Forwards Press Release 85-53 re NRC citation on Washington,DC Veterans Admin alleged failure in six instances to comply w/requirements concerning radiation protection of workers.
KAMMERER,C. Office of Congressional Affairs. 85/04/01. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:060-33109:062.
- 8510230142 Forwards Press Release 85-52 re Ad Hoc Advisory Committee for Review of Enforcement Policy meetings on 850410-11 & 30-0501 in Bethesda,MD concerning study of effectiveness of NRC current enforcement program.
KAMMERER,C. Office of Congressional Affairs. 85/04/01. UDALL,M. House of Rep., Interior & Insular Affairs. SIMPSON Senate. MARKEY House of Rep. 2pp. 33109:063-33109:064.
- 8510230146 Forwards Press Release 84-55 re NRC proposed fine against util for alleged violations of security & radiation protection requirements on 831026 & 840114.
KAMMERER,C. Office of Congressional Affairs. 84/05/10. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:001-33109:002.
- 8510230150 Forwards Press Release 85-51 re NRC proposed fine against util for two alleged violations concerning program for dealing w/emergencies.
KAMMERER,C. Office of Congressional Affairs. 85/03/26. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:065-33109:067.
- 8510230164 Forwards Press Release V-1484 re NRC proposed fine against util for disabling facility safety sys.
KAMMERER,C. Office of Congressional Affairs. 84/05/16. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:003-33109:004.
- 8510230170 Forwards Press Release 85-48 re NRC proposed fine against util concerning five alleged matl false statements in development of Tech Specs governing facility operation.
KAMMERER,C. Office of Congressional Affairs. 85/03/22. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:068-33109:070.
- 8510230173 Forwards Press Release 84-58 re NRC proposed fine against util for alleged violation of NRC requirements during preoperational testing.
KAMMERER,C. Office of Congressional Affairs. 84/05/17. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:005-33109:007.
- 8510230175 Forwards proposed enforcement action against util for violations involving matl false statements re Tech Specs.
KAMMERER,C. Office of Congressional Affairs. EA-84-075. 85/03/22. SIMPSON,A. Senate. Environment & Public Works. UDALL,M.K. House of Rep. COCHRAN,T. Senate. 1p. 33109:071-33109:081.
- 8510230182 Forwards Press Release 85-43 re NRC proposed fine against util concerning alleged failure to maintain integrity of sys that prevents release of radioactivity into environ.
KAMMERER,C. Office of Congressional Affairs. 85/03/20. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:082-33109:084.
- 8510230189 Forwards Press Release 85-33 re NRC proposed fine against util for alleged violation of requirements concerning operation of reactor more than 5 days w/o intake CWS being operational.
KAMMERER,C. Office of Congressional Affairs. 85/03/04. MARKEY,E.J. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:085-33109:086.
- 8510230191 Forwards Press Release 84-75 re NRC proposed fine against util for five alleged violations of Tech Specs.
KAMMERER,C. Office of Congressional Affairs. 84/06/19. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:010-33109:012.
- 8510230197 Forwards Press Release 85-157 re NRC proposed civil penalty in amount of \$150,000 against util for alleged violation of requirements concerning improper startup procedures.
KAMMERER,C. Office of Congressional Affairs. 85/02/27. MARKEY,E. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:087-33109:088.
- 8510230203 Forwards Press Release 84-83 re NRC proposed fine against util for loading fuel bundles & moving control rods in reactor core while sys for monitoring startup inoperable. Three other violations cited.
KAMMERER,C. Office of Congressional Affairs. 84/07/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:016-33109:018.

294 NONDOCKETED ITEMS

- 8510230205 Forwards Press Release 84-85 re NRC proposed civil penalty in amount of \$60,000 against util for alleged violation of security requirements on 840522. KAMMERER,C. Office of Congressional Affairs. 84/07/11. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:019-33109:020.
- 8510230220 Forwards Press Release 84-90 re NRC proposed civil penalty in amount of \$120,000 against TVA for failure to identify & correct conditions adverse to quality during post-trip shutdown reviews, post-mod testing & monthly surveillance. KAMMERER,C. Office of Congressional Affairs. 84/07/20. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:094-33109:095.
- 8510230222 Forwards Press Release 84-91 re NRC proposed civil penalty in amount of \$150,000 against util for failure to identify two auxiliary feedwater pumps out of operation & failure to take compensatory action. KAMMERER,C. Office of Congressional Affairs. 84/07/20. OTTINGER,R.L. House of Rep., Energy & Commerce. 2pp. 33109:096-33109:097.
- 8510230228 Forwards Press Release 85-85 re NRC proposed imposition of civil penalty in amount of \$100,000 against licensee for failure to identify & correct degradations of main access area boundary. KAMMERER,C. Office of Congressional Affairs. 84/07/31. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:098-33109:099.
- 8510230234 Forwards Press Release 84-94 re NRC proposed imposition of civil penalty in amount of \$40,000 against util for allegedly assuming that all hydraulic snubbers rebuilt during steam generator replacement projects. KAMMERER,C. Office of Congressional Affairs. 84/07/31. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:100-33109:101.
- 8510230241 Forwards Press Release 84-97 re NRC proposed fine against Univ of Connecticut for six alleged violations on use & storage of radioactive mats. KAMMERER,C. Office of Congressional Affairs. 84/09/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:102-33109:104.
- 8510230246 Forwards Press Release 84-109 re NRC mitigation of proposed civil penalty in amount of \$30,000 against util for alleged violation of NRC radiation protection requirements due to prompt reporting. KAMMERER,C. Office of Congressional Affairs. 84/09/11. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:105-33109:106.
- 8510230250 Forwards Press Release 84-113 re NRC reduction in proposed civil penalty in amount of \$250,000 by 50% due to prompt & extensive corrective action by util. Containment spray sys subsystem inoperable on 840304-17. KAMMERER,C. Office of Congressional Affairs. 84/09/25. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:107-33109:108.
- 8510230253 Responds to request for all errors committed by util in application for license. Partial list of false mail statements should be available. COMBS,F. Office of Congressional Affairs. 84/09/25. MYERS,H. House of Rep., Interior & Insular Affairs. 1p. 33109:109-33109:109.
- 8510230261 Forwards Press Release 84-115 re NRC proposed fine against util for apparent violation of NRC regulations. KAMMERER,C. Office of Congressional Affairs. 84/09/28. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:110-33109:111.
- 8510230268 Forwards Press Release 84-134 re NRC proposed fine against util for five alleged violations, including inadvertent shutdown of control room emergency ventilation sys. KAMMERER,C. Office of Congressional Affairs. 84/11/28. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:112-33109:114.
- 8510230274 Forwards Press Release 84-52 re NRC proposed fine against util for alleged safety violations, including failure to follow approved procedures during operation of startup feedwater pump. KAMMERER,C. Office of Congressional Affairs. 84/12/03. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:115-33109:116.
- 8510230283 Forwards Press Release 84-51 re NRC proposed fine against util for violations of safety requirements, including improper control valve setting on auxiliary feedwater pump. KAMMERER,C. Office of Congressional Affairs. 84/12/03. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:117-33109:118.
- 8510230293 Forwards Press Release 84-141 of NRC mitigation of proposed civil penalty in amount of \$40,000 against util for violations of radiation protection requirements. Two workers entered locked high radiation area. KAMMERER,C. Office of Congressional Affairs. 84/12/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:119-33109:120.
- 8510230304 Forwards Press Release 84-150 of NRC proposed fine against util for alleged inadequate control of operations. KAMMERER,C. Office of Congressional Affairs. 84/12/19. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:121-33109:123.
- 8510230312 Forwards Press Release 84-140 of NRC proposed civil penalty in amount of \$50,000 against util for alleged violations of security requirements by not protecting equipment per physical security plan. KAMMERER,C. Office of Congressional Affairs. 84/12/06. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:124-33109:150.
- 8510230323 Forwards Press Release 85-28 re NRC proposed civil penalty in amount of \$50,000 against util for alleged noncompliance w/requirements concerning upper head injection accumulator sys. KAMMERER,C. Office of Congressional Affairs. 85/02/21. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:151-33109:152.
- 8510230325 Forwards Press Release 85-22 re NRC proposed fine against util for several alleged violations of regulations concerning failure to conduct surveillance tests for unit batteries. KAMMERER,C. Office of Congressional Affairs. 85/02/14. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:153-33109:154.
- 8510230327 Forwards Press Release 85-17 re NRC proposed civil penalty in amount of \$40,000 against util for alleged violations of requirements concerning failure to assure operability of reactor vessel vent sys. KAMMERER,C. Office of Congressional Affairs. 85/02/05. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:155-33109:157.
- 8510230337 Forwards Press Release 85-13 re NRC proposed civil penalty in amount of \$100,000 against util as result of 840814 incident concerning overpressurization of safety sys. KAMMERER,C. Office of Congressional Affairs. 85/01/29. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:158-33109:159.
- 8510230342 Forwards Press Release 85-4 re NRC proposed civil penalty in amount of \$50,000 against util for alleged violation of security requirements concerning protection of vital equipment. KAMMERER,C. Office of Congressional Affairs. 85/01/11. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 2pp. 33109:160-33109:161.
- 8510230346 Forwards Press Release 85-3 re NRC Ad Hoc Advisory Committee for Review of Enforcement Policy request for public comments on enforcement policy. KAMMERER,C. Office of Congressional Affairs. 85/01/09. OTTINGER,R.L. House of Rep., Energy & Commerce. SIMPSON Senate. UDALL House of Rep. 3pp. 33109:162-33109:164.
- 8510250336 Responds to FOIA request for QA rept prepared by Comanche Peak Technical Review Team. Records listed on App A available in PDR. FELTON,J.M. Division of Rules and Records. 85/10/16. GARDE,B.P. Government Accountability Project. 1p. 33191:345-33191:345.
- 8510250346 FOIA request for info re QA rept prepared by Comanche Peak Technical Review Team. GARDE,B.P. Government Accountability Project. 85/01/09. Office of Administration. 2pp. 33191:346-33191:350.
- 8510250351 FOIA request for License 37-20826-01 issued to ALARON Corp & documentation re license. TERPILAK,M.S. Nucleon Lactern Associates, Inc. 85/08/30. FELTON,J. Division of Rules and Records. 1p. 33225:208-33225:208.
- 8510250358 Responds to FOIA request for documents re license issued to ALARON Corp. App A documents available in PDR. App B documents withheld (ref FOIA Exemption 7). FELTON,J.M. Division of Rules and Records. 85/10/03. TERPILAK,M.S. Nucleon Lactern Associates, Inc. 5pp. 33225:209-33225:033.

GEN TEC IS GENERIC TECHNICAL ISSUES

- 8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR. FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABE,L. Government Accountability Project. 32pp. 32884:005-32884:234.
- 8510020229 Draft Issue C of Procedure ASP-IV-22, "Unloading &/or Handling Heavy or Specialized Equipment." MEARKLE,J. Elasco Services, Inc. (subs. of Enserch Corp.). 82/02/09. 6pp. 32890:146-32890:151.
- 8510020227 NUREG/CR-3426 V01 THERMAL AND FLUID MIXING IN 1/2-SCALE TEST FACILITY. Facility And Test Design Report. DOLAN,F.X., VALENZUELA,J.A. Creare, Inc. FIN A-4070. EPRI NP-3802. 85/09/30. Division of Accident Evaluation. 130pp. 32839:028-32839:156.
- 8510020307 NUREG/CR-4376 HEAT TRANSFER, CARRYOVER AND FALL BACK IN PWR STEAM GENERATORS DURING TRANSIENTS. LIAO,L.H., PARLOS,A., GRIFFITH,P. Massachusetts Institute of Technology, Cambridge, MA. FIN B-7229. EPRI NP-4298. 85/09/30. Division of Accident Evaluation. 212pp. 32828:124-32828:335.
- 8510030032 Forwards application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Fee paid. KEISER,H.W. Pennsylvania Power & Light Co. GL-81-07. 85/09/30. BUTLER,W.R. Licensing Branch 2. 2pp. 32842:269-32842:271.
- 8510030056 Application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." KEISER,H.W. Pennsylvania Power & Light Co. 85/09/30. 1p. 32842:271-32842:271.
- 8510040402 NUREG/CR-4304 PRESSURE VESSEL FRACTURE STUDIES PERTAINING TO THE PWR THERMAL SHOCK ISSUE. Experiment TSE-7. CHEVERTON,R.D., BALL,D.G., BOLT,S.E. Oak Ridge National Laboratory. FIN B-0119. GSCA-46. 85/09/30. Division of Engineering Technology. 152pp. 32859:050-32859:202.
- 8510070080 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available. ROBERTS,T.M. Commissioners. 85/07/17. MARKEY,E.J. House of Rep., Energy & Commerce. 1p. 32905:053-32905:157.

—8311040213 Forwards comments on draft CRGR package re requirements for upgrading auxiliary feedwater sys in operating plants. Proposed action should be deferred until coordination w/Unresolved Safety Issue A-45 is decided.
SPEIS,T.P. Division of Safety Technology. 83/10/25. MATTSON,R.J. Division of Systems Integration (post 811005). 8pp. 32908:053-32908:068.

8510070261 Advises that load drop analyses of two remaining load handling devices completed,per utli 850805 ltr addressing guidelines of NUREG-0612,Section 5.1.1.Scabbing of intervening floor may occur for certain loads.
MANGAN,C.V. Niagara Mohawk Power Corp. 85/10/01. VASSALLO,D.B. Operating Reactors Branch 2. 1p. 32877:311-32877:311.

8510070281 Amend 35 to application for licenses,consisting of Rev 13 to FSAR,Response to final rule on pressurized thermal shock encl.
OWEN,W.H. Duke Power Co. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32879:001-32880:297.

—8510070290 Rev 13 to FSAR for Catawba Units 1 & 2.
* Duke Power Co. 85/10/01. 850pp. 32879:003-32880:297.

8510090275 Modifies meeting time & agenda for CRGR Meeting 78 on 850708,Agenda includes encl proposed resolution of Unresolved Safety Issue (USI) A-46 & encl updated recommendations on fire protection.W/o USI A-46 info.
STELLO,V. Committee to Review Generic Requirements. 85/06/28. BERNERO,R. Office of Nuclear Reactor Regulation, Director. JORDAN,E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM,R.E. Office of Nuclear Material Safety & Safeguards,Director. 2pp. 32946:232-32946:233.

8510090504 Summary of CRGR Meeting 78 on 850708 re proposed resolution of Generic Issue A-46, "Seismic Qualification of Equipment in Operating Plants." Encl 3 re recommendations of fire protection policy encl W/o Encls 1,2 & 4-6.
STELLO,V. Committee to Review Generic Requirements. 85/08/20. DIRCKS,W.J. Office of the Executive Director for Operations. 4pp. 32946:060-32946:063.

8510110238 Motion requesting ASLB reconsider & modify 850918 memorandum to reflect fact that utli not placed in special category for coatings inside containment,per SSER 9 (NUREG-0797) & consider notification of USI A-43 closed.
BACHMANN,R.G. Hearing Branch 1. #485 741. OL. 85/10/09. Atomic Safety and Licensing Board Panel. 6pp. 32971:235-32971:252.

8510160014 Forwards Insp Rept 50-245/85-15 on 850617-28 & notice of violation.
EBNETER,S.D. Region 1, Office of Director. 85/10/11. OPEKA,J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33027:102-33027:161.

—8510160037 Insp Rept 50-245/85-15 on 850617-28,Violations noted: failure to provide adequate written procedures for two specific safety-related activities & failure to follow station procedure.
CHUNG,J.W., MURPHY,K.G., PETRONE,C.D. Region 1, Office of Director. IEB-80-25. 85/09/03. 48pp. 33027:114-33027:161.

8510160039 Research Info Ltr 144, "Effect of Hydrogen Gas on Downcomer Fluid Temps During TMI Accident." Forwards "Cooldown Aspects of TMI-2 Accident," based on TG Theofanis study of fluid mixing in thermally stratified flows.
MINOGUE,R.B. Office of Nuclear Regulatory Research, Director. 85/10/09. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 33028:168-33028:171.

8510160061 Summarizes status of Hydrogen Control Owners Group program plan tasks,Task 1 re station blackout & ATWS complete. Task 6 re hydrogen combustion testing still in progress, awaiting completion of Subtask 6.26.
DALE,L.F. Mississippi Power & Light Co. AECM-85/0320. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33027:200-33027:201.

8510160283 Forwards comments on NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Recommends NRC take advantage of recent studies which reflect many upgrades in industry resulting in more reliable grids & switchgear.
WELLS,R.W. C-E Operating Plants Owners Group. WELLS,R.W. Northeast Utilities. RWW-85-7. 85/10/11. KNIEL,K. Division of Safety Technology. 13pp. 33024:355-33025:005.

8510170117 Forwards "Heavy Load Analysis Rept,Phase II" & revised "Heavy Load Analysis Rept,Phase I," per 841205 request to reevaluate control of heavy loads of 1 ton or more.Action items identified from repts listed.
WAREMBOURG,D.W. Public Service Co. of Colorado. P-85361. 85/10/15. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33039:050-33039:155.

—8510170123 Revised "Heavy Load Analysis Rept,Phase I."
* Sargent & Lundy, Inc. 85/10/15. 60pp. 33039:052-33039:109.

—8510170127 "Heavy Load Analysis Rept,Phase II."
* Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 47pp. 33039:110-33039:155.

8510180034 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Draft contains errors & internal inconsistencies.Withdrawal of draft recommended until industry questions resolved.
WILLIAMS,J.W. Florida Power & Light Co. L-85-394. 85/10/15. DENTON,H. Office of Nuclear Reactor Regulation, Director. 6pp. 33054:011-33054:016.

8510180211 Comments on draft NUREG-1032, "Evaluations of Station Blackout Accidents at Nuclear Power Plants." Blackouts not an issue warranting resolution by rulemaking.Technical record indicates industry as whole presently safe enough.
WESTAFER,G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-06. 85/10/14. CHILK,S.J. Office of the Secretary of the Commission. 1p. 33062:301-33062:301.

8510210161 Summary of ACRS Subcommittee on Safeguards & Security 850507 meeting w/NRC,DOE & consultants in Washington,DC re sabotage protection at power & nonpower reactors.
* ACRS - Advisory Committee on Reactor Safeguards. 85/06/19. ACRS - Advisory Committee on Reactor Safeguards. 15pp. 33094:214-33094:228.

8510210198 Summary of ACRS Subcommittee on ECCS/Fluid Dynamics 850827 meeting in Washington,DC to review status of hydrodynamic loads issue for plants w/GE Mark I-III containment & implementation proposal for resolution of USI A-43.
* ACRS - Advisory Committee on Reactor Safeguards. 85/09/06. ACRS - Advisory Committee on Reactor Safeguards. 28pp. 33094:108-33094:136.

8510220098 Forwards comments endorsing Nuclear Util Group on Station Blackout group comments on NUREG-1032.Any rulemaking should be delayed until other power-related issues resolved.
ALEXANDER,G. Commonwealth Edison Co. 0788K. 85/10/18. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33090:151-33090:153.

8510220179 Forwards draft FSAR Section 5.3.2.1 per NRC request for position on NRC rule concerning pressurized thermal shock. Info will be incorporated into future FSAR amend.
WISEBURG,M.R. Houston Lighting & Power Co. ST-HL-AE-1423. 85/10/17. KNIGHTON,H.W. Licensing Branch 3. 4pp. 33090:056-33090:059.

8510220300 Advises that info & analysis of NUREG-1032, "Station Blackout," does not provide adequate technical basis for rulemaking.Both frequency & total number of off-site power loss events declined indicating station blackout not issue.
MITTL,R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/09. KNIEL,K. Division of Safety Technology. 1p. 33083:328-33083:328.

8510220362 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Logical basis for dividing nuclear power plants into generalized groups must be shown before any conclusions can be drawn.
HUFHAM,J.W. Tennessee Valley Authority. 85/10/11. KNIEL,K. Division of Safety Technology. 4pp. 33086:274-33086:277.

8510220351 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Conclusions in NUREG-1032 re likelihood of station blackout event & consequences overly conservative.
SCHERER,A.E. Combustion Engineering, Inc. LD-85-048. 85/10/14. KNIEL,K. Division of Safety Technology. 1p. 33086:337-33086:337.

8510220362 Submits comments on issuance & availability draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." NUREG developed w/o consideration of NRC & industry activities.
EDELMAN,M.R. Atomic Industrial Forum. 85/10/16. KNIEL,K. Division of Safety Technology. 2pp. 33084:274-33084:275.

8510220390 Summarizes ACRS ECCS Subcommittee 850827 meeting in Washington,DC re hydrodynamic loads in Mark I-III containment,resolution of USI A-43 on pump performance & feed & bleed calculations for Davis-Besse event.
TIEN,C. California, Univ. of Berkeley, CA. TIEN,C. ACRS - Advisory Committee on Reactor Safeguards. 85/09/09. BOEHNERT,P.A. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 33099:147-33099:148.

8510230031 Forwards review for integrated safety assessment program Topic 1.47, "Containment Emergency Sump Performance," per 850517 ltr USI A-43 should be resolved for facility.
OPEKA,J.F., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. B11823. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33101:352-33101:355.

8510240055 Forwards addl info re 850912 event,Licensing basis for auxiliary pressure spray sys found in Branch Technical Position RSB 5-1.Review concluded auxiliary pressure spray sys design consistent w/NRC guidelines.
VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). ANPP 33771 EEVB. 85/10/22. KNIGHTON,G.W. Office of Nuclear Reactor Regulation, Director. 15pp. 33155:212-33155:226.

8510240089 Submits integrated safety assessment program Topic 1.46, "Determination of Safety Relief Valve Pool Dynamic Loads." GDC 50,USI A-7, "Long-Term Program" & USI A-39 served as review criteria.
OPEKA,J.F., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA,J.F. Northeast Utilities. B11816. 85/10/16. GRIMES,C.I. Systematic Evaluation Program Branch. 4pp. 33155:185-33155:188.

8510240301 Forwards "Comparison of Maine Yankee Atomic Power Plant w/Seismic Qualification Util Group Seismic Experience Data Base," per 841029 request.Work will continue towards resolution of Generic Issue A-46.
WHITTIER,G.D. Maine Yankee Atomic Power Co. MN-85-181. 85/10/18. BUTCHER,E.J. Operating Reactors Branch 3. 2pp. 33151:176-33151:304.

8510250025 Requests addl info in order to complete review & evaluation & respond to utli 850911 request re Rev 2 to SER for heavy load handling inside containment,including plans for meeting keff criterion.
TRAVERS,W.D. TMI Program Office. NRC/TMI-85-078. 85/10/18. STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 1p. 33226:034-33226:034.

8510250341 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." to resolve USI A-44,NUREG does not provide sufficiently accurate analysis of station blackout situation.
EDWARDS,D.W. Yankee Atomic Electric Co. GLA 85-124. 85/10/21. KNIEL,K. Division of Safety Technology. 2pp. 33172:148-33172:149.

8510280330 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Discussion re misleading reporting of loss of offsite power & HL Wyckoff 830923 memo also encl.
HIATT,S.L. Ohio Citizens for Responsible Energy. 85/07/05. NRC - No Detailed Affiliation Given. 7pp. 33193:005-33193:011.

8510290003 Discusses NRC 851009 response to ASLB 850918 memorandum re water recirculation problems caused by paint.Motion for reconsideration of listed point one & motion that listed point two considered resolved supported.
REYNOLDS,N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS,N.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 911. OL. 85/10/24. BLOCH,P.B., JORDAN,W.H., MCCOLLUM,K.A. Atomic Safety and Licensing Board Panel. 3pp. 33232:360-33232:361.

8510290088 Discusses delay in mod schedule for fuel handling bldg crane interlocks.Delay due to vol of restart work.Mod completion rescheduled for Dec 1985.
HUKILL,H.D. General Public Utilities Corp. - GPU Service Corp. 5211-85-2175. 85/10/24. STOLZ,J.F. Operating Reactors Branch 4. 1p. 33236:016-33236:016.

8510290316 Comments on NUREG-1032, "Evaluations of Station Blackout Accidents at Nuclear Power Plants." Nuclear Util Group on Station Blackout comments that station blackout issue does not warrant rulemaking supported.
THORPE,J.R. General Public Utilities Corp. - GPU Service Corp. 85/10/15. CHILK,S.J. Office of the Secretary of the Commission. 1p. 33236:248-33236:248.

296 NONDOCKETED ITEMS

8510290352 "Fort St Vrain Nuclear Generating Station Heavy Load Analysis, Phase II." * Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 46pp. 33240:015-33240:060.

8510290360 "Fort St Vrain Nuclear Generating Station Heavy Load Analysis Phase I." * Sargent & Lundy, Inc. 85/10/15. 58pp. 33240:260-33240:317.

I&E INSPECTION AND ENFORCEMENT

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32868:282-32868:060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp. 32868:147-32868:281.

8510010062 PNO-I-85-067 on 850923, malfunction of one reactor protection sys as breaker caused small electrical fire. Operator deenergized breaker from feeder bus & fire extinguished. Spare breaker installed. CONTE, R., KANE, W. Region 1, Office of Director. 85/09/24. 1p. 32800:064-32800:064.

8510010178 PNO-III-85-086 on 850923 & 24, seven of eight main steam safety valves failed to meet criteria during testing at Wylie Labs. Four valves leaked after reseating & lift setpoints of three lower than specs. Valves will be reset. BURGESS, B., CHRISSOTIMOS, N. Region 3, Office of Director. 85/09/26. 1p. 32800:104-32800:104.

8510010190 PNO-V-85-063 on 850924, reactor tripped due to loss of main feedwater pump. Caused by work on condensate demineralizer sys resulting in flow oscillations. Reactor will be taken to Mode 5 to repair pressurizer safety valves. DODDS, R., RICHARDS, S. Region 5, Office of Director. 85/09/24. 1p. 32800:207-32800:207.

8510010234 PNO-III-85-084 on 850919, reactor scrammed due to mechanic bumping circuit board. Reactor bldg evacuated due to steam leak & high radiation alarms. Four people slightly contaminated. WRIGHT, G., CHRISSOTIMOS, N. Region 3, Office of Director. 85/09/20. 1p. 32800:187-32800:187.

8510010270 PNO-V-85-062B on 850919, reactor tripped due to failure of steam reheater dump valve to actuate resulting in main turbine overspeed. Caused by lack of lubricating oil in bearing sumps & failure of pressure switch & relay. JOHNSON, P., HUEY, R. Region 5, Office of Director. 85/09/23. 1p. 32800:185-32800:185.

8510010286 PNO-I-85-068 on 850923, chemistry technician determined to be missing & possibly drowned after being sent to obtain environ water grab sample from discharge canal. Search by uti & state police unsuccessful. JOHNSON, T., GALLO, R. Region 1, Office of Director. 85/09/24. 1p. 32802:352-32802:352.

8510010429 Responds to 850809 Itr re Info Notice 85-59, "Valve Stem Corrosion Failures." No attempt made to single out specific manufacturer. Since cracks occurred prior to hot functional testing, valves possibly defective when installed. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). IEIN-85-059. 85/09/27. VELAN, A.K. Velan Valve Co. Spp. 32833:144-32833:148.

8510020274 PNO-I-85-071A on 850927, Hurricane Gloria located at Northampton, MA moving in northeasterly direction. Status downgrade to tropical storm expected early evening on 850927. Salem Unit 1 & Millstone complex suffered damage. STAROSTECKI, R. Region 1, Office of Director. 85/09/27. 1p. 32825:232-32825:232.

8510020383 PNS-I-85-013 on 850927, bent mast on refueling bridge over spent fuel pool discovered. Cause unknown. No fuel damage apparent. Licensee conducting tests & insp to assure operability. TRIPP, L., JOYNER, J. Region 1, Office of Director. 85/09/27. 2pp. 32824:340-32824:341.

8510030014 PNO-II-85-092 on 850926, Hurricane Gloria located about 240 miles south of Cape Hatteras, NC, moving north northwest at 15 to 20 miles per hour. Brunswick Unit 1 in refueling shutdown, Unit 2 shut down & Surry 1 & 2 at full power. CUNNINGHAM, A. Region 2, Office of Director. 85/09/26. 2pp. 32844:335-32844:336.

8510030039 PNO-II-85-091 Region II dispatched emergency response specialist to plant to set up high frequency radio communications as result of Hurricane Gloria. Unit 1 in shutdown for refueling. CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/10/03. 1p. 32845:112-32845:112.

8510030049 EN-85-068 on 851002, notice of violation & proposed imposition of civil penalties in amount of \$50,000 will be issued to licensee. Action based on events, including failure of mgmt to follow radiation protection procedures. KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/26. 1p. 32843:112-32843:112.

8510030052 PNO-II-85-093 on 850926, Unit 2 shut down & on 850927, Unit 1 shut down due to Hurricane Gloria w/35-40 miles per hour winds. Unit 1 expected to restart on 850927. Unit 2 will remain shut down for 2 wks for repair of LPSI valves. CUNNINGHAM, A., COLLINS, D. Region 2, Office of Director. 85/09/27. 2pp. 32845:080-32845:081.

8510040238 PNO-IV-85-049 on 850926, cooldown commenced to replace seal on reactor coolant pump C. Seal cartridge developed crack where middle cavity seal pressure sensing line joins cartridge. Startup scheduled for 851003. MARTIN, L.E. Region 4, Office of Director. 85/09/30. 1p. 32851:058-32851:058.

8510040315 PNO-I-85-072 advising that current uti contract w/YOH Security guards expires on 851001. Contingency security guard force assembled. Strike not expected to affect plant operations. STROSNIDER, R. Region 1, Office of Director. 85/09/30. 1p. 32853:251-32853:251.

8510070055 PNO-V-85-065 on 850920, State of WA inspector discovered drum containing 19,808 mCi Sr-90, exceeding marked Class A limitations. Caused by incorrect classification. Licensee banned from use of burial site. RIEDLINGER, B.A. Region 5, Office of Director. 85/10/01. 1p. 32878:034-32878:034.

8510070195 PNO-IV-85-050 on 850930, 100 gallons slurry spilled from door frame weld failure & 20% overflowed onto bldg floor & exited through doorway. Leach tanks will be drained & examined. Welds will be repaired. PETTINGILL, H. Region 4, Office of Director. 85/10/02. 1p. 32881:133-32881:133.

8510070331 PNO-V-85-064 on 850928, reactor achieved criticality. Plant in cold shutdown since 850623 due to 1-inch diameter hot leg vent piping failure. Exams of other piping sys & supports completed. Plant at 40% power. MILLER, L., ECKHARDT, J.H. Region 5, Office of Director. 85/10/01. 1p. 32877:261-32877:261.

8510080029 PNO-I-85-074 wastes containing I-125, H-3, I-131, C-36 & P-32 lost. Untrained custodial worker entered labs & emptied wastes into normal trash compactor. Waste removed & disposed of in Saugus, MA. JOHANSEN, J., GLENN, J. Region 1, Office of Director. 85/10/02. 1p. 32913:295-32913:295.

8510080031 EN-85-066 on or about 850926, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to licensee. Action based on failure to implement & maintain installed upgrade of post-accident sampling sys. KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/23. 1p. 32918:293-32918:293.

8510080042 PNO-I-85-073 on 851001, unit placed in cold shutdown after ground fault found in reactor coolant pump motor. Pump motor will be removed to allow uti & GE to determine whether fault accessible. SHEDLOSKEY, J.T., MCCABE, E.C. Region 1, Office of Director. 85/10/02. 1p. 32913:294-32913:294.

8510080052 PNO-V-85-066 on 851002, loss of main feedwater event occurred. Plant being maintained in hot shutdown condition pending determination of exact scenario, causes & appropriate corrective action. Region evaluating response. ECKHARDT, J., MILLER, L. Region 5, Office of Director. 85/10/02. 1p. 32919:362-32919:362.

8510080160 EN-85-067: notice of violation & proposed imposition of civil penalty in amount of \$125,000 will be issued on or about 850927. Action due to three failures to ensure that mods performed on safety-related sys adequately controlled. BEACH, B., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/24. 1p. 32922:066-32922:066.

8510080183 PNS-I-85-013A on 850928, insp team conducted review on licensee investigative/followup actions & independent evaluation to determine probable cause of damaged spent fuel handling equipment. No evidence of attempted sabotage. TRIPP, L., KEIMIG, R. Region 1, Office of Director. 85/10/03. 2pp. 32921:063-32921:064.

8510080210 EN-85-064 on 850925, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee. Action based on multiple failures to maintain control over access to vital areas. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/20. 1p. 32913:349-32913:349.

8510080256 EN-85-065 on 850926, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to licensee. Action based on lack of adequate seismic supports for nitrogen supply & vent header sys. POINDEXTER, T., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/09/23. 1p. 32913:348-32913:348.

8510080258 PNO-V-85-061 on 850919, teletherapy source failed to retract after completion of teletherapy treatment on patient. Caused by contact strips which activate field limit curling up & preventing source from returning to fully shielded position. ZURAKOWSKI, P.R. Region 5, Office of Director. 85/09/19. 1p. 32913:346-32913:346.

8510080275 PNO-IV-85-053 on 850928, reactor shut down in preparation for planned refueling outage. Outage expected to last 3 months. State of NE informed. No press release planned. MARTIN, L.E. Region 4, Office of Director. 85/10/04. 1p. 32913:343-32913:343.

8510080281 PNO-IV-85-052 on 851003, plant outage initiated from hot standby to replace failed seal on reactor coolant pump 2B. Cause not stated. CONSTABLE, G.L. Region 4, Office of Director. 85/10/04. 1p. 32918:358-32918:358.

8510080482 PNO-V-85-067 on 851002, earthquake of magnitude 5.0 on Richter scale occurred. Epicenter located approx 50 miles north of site. Event minor, not felt by site personnel & did not activate recording instruments. JOHNSON, P., HUEY, R. Region 5, Office of Director. 85/10/03. 1p. 32921:164-32921:164.

8510090107 PNO-IV-85-054 on 851005, reactor manually tripped due to sudden increase in vibration of low pressure turbine elements in main turbine condensate activity. Caused by possible damage to condenser tubes. State of NE informed. JAUDON, J.P. Region 4, Office of Director. 85/10/07. 1p. 32941:264-32941:264.

8510090238 PNO-I-85-075 on 851006, plant tripped. Caused by condensation in condensers vacuum sensing line reaching sensor causing turbine trip w/automatic reactor trip. Plant in cold shutdown for maint & mod to condenser. NORRHOLM, L., KENNY, T. Region 1, Office of Director. 85/10/07. 1p. 32942:341-32942:341.

8510100187 EN-85-069 notice of violation & proposed imposition of civil penalties in amount of \$5,000 will be issued, based on violations, including unauthorized & unqualified individual performing license activities & worker overexposure. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/03. 1p. 32962:112-32962:112.

8510100193 EN-85-071 on 851008, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to uti. Action based on violation re unacceptable location for obtaining post-accident containment samples. HOLLER, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/08. 1p. 32966:359-32966:359.

8510150022 IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.

8510150025 IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:068.

8510150080 IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Satisfactorily Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.

8510150237 PNO-V-85-068: on 851003, while operating at 50% power, reactor trip occurred after loss of electric power. Three reactor coolant pumps restarted by resetting pump circuit breaker lockout relays. Cause under investigation. MILLER, L., ZIMMERMAN, R. Region 5, Office of Director. 85/10/04. 1p. 33009:313-33009:313.

8510150128 PNO-I-85-076: on 851009, reactor shut down after unsuccessful attempt to identify cause of 1.5 gpm leak from reactor coolant pump 11A controlled bleed off line. Cause by cracked weld. FOLEY, T., ELGASSER, T. Region 1, Office of Director. 85/10/10. 1p. 33022:131-33022:131.

8510160213 PNO-V-85-069: on 851003 & 08, loss of normal electric power resulted in reactor trip. Cause by switchyard electrical distribution malfunction. Licensee proceeding w/design change to hard-wire control for feeder breakers. PATER, R., ZIMMERMAN, R. Region 5, Office of Director. 85/10/08. 1p. 33023:123-33023:123.

8510160238 PNO-V-85-070: on 851008, two plant mod personnel received first & second degree burns on hands & arms due to fire in motor control ctr. Cause by short circuiting of bus bar by hand-held cordless drill. PEREIRA, D., RICHARDS, S. Region 5, Office of Director. 85/10/08. 1p. 33023:236-33023:236.

8510160240 PNO-V-85-071: on 851007, one of two auxiliary feedwater pumps declared inoperable due to failure of pump thrust bearing. Cause by disintegrated thrust bearing due to inadequate lubrication. Bearing replaced. MYERS, C., ECKHARDT, J. Region 5, Office of Director. 85/10/09. 1p. 33023:235-33023:235.

8510170221 Final response to FOIA request for documents re Dow Chemical Co. Forwards Apps O & P documents. Documents also available in PDR App O documents withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 85/10/04. KOHN, S. Government Accountability Project. 5pp. 33050:297-33051:057.

-8510170273 PNS-III-78-004: on 780110, during physical security insp, lack of positive access controls to reactor bldg discovered. Portions deleted (ref 10CFR2.790). Related draft documents encl. LONAHUE, J.F., HIND, J.A. Region 3, Chicago, Office of the Director. 78/01/18. 25pp. 33050:347-33051:009.

8510180029 PNO-I-85-077: on 851008, radiographer received whole body dose of 15.5 rem. Cause by failure to retract 100-Ci Ir-192 source to shielded position in exposure device. Radiographer removed from radiation work for remainder of quarter. COSTELLO, F., KINNEMAN, J. Region 1, Office of Director. 85/10/11. 1p. 33054:010-33054:010.

8510180086 PNO-II-85-094: on 851007, unit shut down due to steam generator tube leak. Leakage amounted to 0.15 gallon per minute & increasing. Generator isolated. Shutdown expected for 10-12 days. BURGER, C., PANCIERA, V. Region 2, Office of Director. 85/10/08. 1p. 33062:155-33062:155.

8510180148 PNO-I-85-078: on 851011, isolation valve to low pressure sys piping opened & discharge of reactor coolant to cleanup demineralizer precoat pump area occurred. Cause under investigation. Cleanup in progress. STROSNIDER, J. Region 1, Office of Director. 85/10/11. 1p. 33055:048-33055:048.

8510180372 EN-85-050A: on 851010, order imposing civil penalty in amount of \$2,000 issued. Action based on violations leading to individual receiving skin exposure of 38 rems. Licensee provided sufficient basis for mitigation. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/10. 1p. 33059:356-33059:356.

8510210005 PNO-I-85-078A: on 851011, reactor coolant spill from reactor water cleanup sys to 779 ft elevation of reactor bldg occurred. Cause by lifting of 150 psig precoat feed relief valve. Spill cleaned & access to area restored. STROSNIDER, J., JACOBS, R. Region 1, Office of Director. 85/10/11. 1p. 33072:020-33072:020.

8510210010 PNO-III-85-089: on 851004, ltr received from D Burton requesting public hearing on US Ecology application for license to store low level radwaste. Application under review. Public meeting or similar forum will be provided. MALLET, B., AXELSON, W. Region 3, Office of Director. 85/10/15. 1p. 33074:111-33074:111.

8510210080 PNO-III-85-087: on 851007, concrete finisher killed after falling 45 ft while working on interim radwaste storage facility. No contamination involved. HEHL, W., CHRISSTIMOS, N. Region 3, Office of Director. 85/10/08. 1p. 33072:285-33072:285.

8510210098 PNO-I-85-079: on 851016, steam leak identified on drain line from associated main turbine control valve header. Cause by through-wall crack in weld associated w/pipe elbow. Power reduced from 40% to make repairs. STROSNIDER, J. Region 1, Office of Director. 85/10/16. 1p. 33072:279-33072:279.

8510210101 PNO-I-85-080: on 851017, plant tripped on low level due to loss of all three turbine-driven main feed pumps. Cause unstated. Reactor vessel level recovered by HPCI & PCIC injection. GALLO, R.M., JOHNSON, T. Region 1, Office of Director. 85/10/17. 1p. 33072:280-33072:280.

8510220104 EN-85-014A: on 851018, final agreement reached w/NFS re 850422 proposed changes & clarification of license conditions concerning security/safeguards per revised order modifying License SNM-124. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/18. 1p. 33090:149-33090:149.

8510220189 EN-85-039A: adequate cause shown why License 45-09963-01 should not be revoked. Licensee improved program to comply w/license requirements & independent consultant performed audit. FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/16. 1p. 33090:052-33090:052.

8510220344 PNS-I-85-014: on 851017, licensee notified Region 1 that reconciliation of low enriched U inventory period ending Sept 1985 indicated inventory difference exceeded error limit. Cause unknown. Reconciliation continuing. SMITH, G., KEIMIG, R. Region 1, Office of Director. 85/10/17. 1p. 33088:149-33088:149.

8510240001 EN-85-073: on 851023, notice of violation & proposed imposition of civil penalties in amount of \$8,000 will be issued. Action based on unauthorized const of three U heap leach piles & failure to comply w/EPA aids. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/17. 1p. 33155:322-33155:322.

8510240406 EN-85-072: on 851021, notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued to util. Action based on multiple examples of openings in vital area barrier. ROBINSON, P., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/16. 1p. 33154:198-33154:198.

8510240413 EN-85-070: on 851021, notice of violation & proposed imposition of civil penalties in amount of \$50,000 will be issued to util. Action based on radiological incident re personnel exposure. FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/16. 1p. 33154:122-33154:122.

8510250437 PNO-I-85-081: on 851022, missing 50-mCi Cs-137 brachytherapy source reported. Source possibly removed from premises by laundry service. State of NJ informed. MCGRATH, J. Region 1, Office of Director. 85/10/23. 1p. 33172:337-33172:337.

8510250447 PNO-III-85-089: on 851015, RHR shutdown cooling suction isolation valve found leaking in excess of Tech Specs. Cause by failed valve packing. Packing & motor replaced & valve returned to svc on 851019. HEHL, W., CHRISSTIMOS, N. Region 3, Office of Director. 85/10/18. 1p. 33172:353-33172:353.

8510260211 PNO-III-85-091: on 851022, loss of offsite power occurred due to inadvertent opening of circuit breaker in switchyard. Cause by personnel winterizing equipment. Accumulator repressurized & circuit breaker closed. BOYD, D., CHRISSTIMOS, N. Region 3, Office of Director. 85/10/22. 1p. 33191:009-33191:009.

8510290310 PNO-I-85-082: on 851018, 4 kV nonsafety-related electrical breaker exploded, injuring two const workers. Workers taken to hosp for treatment. Vendor representatives & OSHA investigating cause of event. GRAMM, R., LINVILLE, J. Region 1, Office of Director. 85/10/24. 2pp. 33193:071-33193:072.

8510280422 PNO-III-85-092: on 851023, reactor failed to trip automatically following high flux alarm. Cause undetermined. Reactor shut down pending results of investigation. BOYD, D., CHRISSTIMOS, N. Region 3, Office of Director. 85/10/23. 2pp. 33194:012-33194:013.

8510290192 PNO-III-85-092A: on 851025, unit shut down due to high neutron flux during startup. Insp team concluded that reactor sys equipment functioned acceptably. Electronic circuit cards replaced. BOYD, D., CHRISSTIMOS, N. Region 3, Office of Director. CAL-RII-85-14. 85/10/24. 2pp. 33236:349-33236:350.

8510290363 EN-85-075: on 851025, order suspending license (effective immediately) issued to Inst for Medical Research of Bennington due to use of mail by unauthorized persons & possession of mail in excess of authorized limits. FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 85/10/25. 1p. 33234:361-33234:361.

8510310132 PNO-TMI-85-010: on 851028, initial phase of defueling damaged reactor core will begin. Defueling will involve manipulation of partial fuel assemblies in preparation for loading into canisters. Press release issued. MOSLAK, T., COWGILL, C., TRAVERS, W. TMI Program Office. 85/10/28. 1p. 33274:028-33274:028.

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8508010540 Details NRC policy re util review of operator & senior operator written licensing exams. Potential for compromising exam & impact on candidates outweigh benefit of concurrent review. NRC present policy should be retained. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/07/19. MURLEY, T.E. Region 1, Office of Director. 3pp. 33276:230-33276:232.

-8508010128 Forwards excerpt from NRC Examiner Std ES-201, issued to govern review of exams by facility staffs. Suggestions for enhancing security of exams & quality of reviews indicated. Std reinstated for use as modified requested. OWEN, W.H. Nuclear Utility Management & Human Resources Committee (NUMARC). 85/01/22. DIRCKS, W.J. NRC - No Detailed Affiliation Given. 2pp. 33276:233-33276:234.

298 NONDOCKETED ITEMS

- 8506010123 Responds to 850122 ltr commenting on NRR elimination of concurrent oral reviews of reactor operator & senior operator candidate written exams & answer keys. Comments appreciated.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/07/19. OWEN, W.H. Nuclear Utility Management & Human Resources Committee (NUMARC). 2pp. 33276.235-33276.236.
- 8510020007 Forwards Special Study Rept AEOD/S503, "Evaluation of Recent Valve Operator Motor Burnout Events." Recommends that rept findings be considered to expedite implementation of NRR proposed plan to address motor burnout.
HEITEMES, C.J. AEOD, Director's Office. AEOD/S503. 85/09/19. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32829:312-32829:325.
- 8510020008 Special Study Rept AEOD/S503, "Evaluation of Recent Valve Operator Motor Burnout Events."
BROWN, E.J. AEOD, Director's Office. AEOD/S503. 85/09/30. 12pp. 32829:314-32829:325.
- 8510020040 Requests that encl from WJ Dircks 850705 memo to program ofc directors & regional administrators on procedure for requesting Ofc of Investigation investigations be placed in PDR.
BRACH, B. Regional Operations & Generic Requirements. 85/09/23. NRC - No Detailed Affiliation Given. 1p. 32829:298-32829:303.
- 8510020090 Accepts 850916 invitation for participation of P. Erickson at 851112 meeting in Washington, DC re reactor decommissioning.
ZWOLINSKI, J.A. Operating Reactors Branch 5. LSO5-85-09-018. 85/09/20. HOLT, J.W. Rural Electrification Administration. 2pp. 32829:283-32829:285.
- 8510020102 Requests P. Erickson attend Committee on Joint Ownership 851112 meeting in Washington, DC to discuss problems of minority owners in shared ownership of power plants. Erickson requested to speak on decommissioning.
HOLT, J.W. Rural Electrification Administration. 85/09/16. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 32829:295-32829:295.
- 8510020112 Forwards Jul 1985 procedures established by WJ Dircks for referral of matters to Ofc of Investigations per 850920 discussion. Dircks 850705 memo also placed in PDR.
STELLO, V. Regional Operations & Generic Requirements. 85/09/23. CLARK, P.R. General Public Utilities Corp. - GPU Service Corp. 1p. 32829:277-32829:282.
- 8510020122 Forwards FR notice re Public Law 97-415, enacted on 5/30/104, amending Section 189 of Atomic Energy Act of 1954 to authorize NRC to issue & make effective any amend to OL upon determination that amend involves NSHC W/O encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/17. SIMPSON, A. Senate, Environment & Public Works. UDALL, M.K. House of Rep., Interior & Insular Affairs. MARKEY, E.J. House of Rep., Energy & Commerce. 2pp. 32829:275-32829:276.
- 8510030173 Returns marked-up manuscript, "Investigation of Stability of Backfill Mats," per Kim request for comments. Rept approved for publication. Revised manuscript requested, including clarification re rate of infiltration W/O encl.
HACKBARTH, J. Waste Management Branch (post 840429). 85/09/30. PEACOR, D.R. Affiliation Not Assigned. 6pp. 32849:289-32849:294.
- 8510070088 Forwards comments on text of encl Final Rule 10CFR50.12(a), "Specific Exemptions," which amends Commission criteria for granting exemptions from requirements of 10CFR50. Concurs w/ not invoking RES independent review procedures for change.
EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. 85/09/25. OLMSTEAD, W.J. Regulations Division. 7pp. 32901:109-32901:178.
- 8510070527 Directs recipient to take actions necessary to resolve & complete Generic Issue 87, "Failure of HPCI Steam Line W/O Isolation." Issue addressed in near-term OL cases. Resolution depends on specific plant design features.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. BERNERO, R.M. Division of Systems Integration (post 811005). 20pp. 32900:308-32900:327.
- 8510080028 Trip rept of 850904 & 06 visits to Columbia, SC & Atlanta, GA to review NRC-sponsored programs w/ contractors, including Univ of South Carolina, Law Engineering & Georgia Inst of Technology.
ZURFLUEHE, G. Earth Sciences Branch (post 840429). 85/10/01. BERATAN, L.L. Earth Sciences Branch (post 840429). 6pp. 32926:261-32926:266.
- 8510150117 Forwards summary of Operating Reactor Events Meeting 85-18 on 850930. Assignment of followup review responsibility discussed. Assignments, viewgraphs & list of attendees encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/07. THOMPSON, H.L. Division of Licensing. 16pp. 33030:225-33030:240.
- 8510150231 Informs that allocation of two direct access passwords to NRR for NPRDS insufficient & suggests allocation of six passwords. NRR reorganization will create five divs, each w/ need for access to NPRDS.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/04. HEITEMES, C.J. AEOD, Director's Office. 4pp. 33032:311-33032:317.
- 8510040098 Forwards draft statement of NRC needs re access to NPRDS. Needs will be discussed w/ INPO. Concurrence or recommendations for changes requested by 851001.
HEITEMES, C.J. AEOD, Director's Office. 85/09/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33032:315-33032:317.
- 8510150467 Comments on draft generic technical position, "Determination of Radionuclide Sorption for Assessment of High Level Waste Isolation." Discussion of sorption mechanisms suggested. Detailed comments encl.
COSTANZI, F.A. Waste Management Branch (post 840429). 85/10/04. KNAPP, M.R. Geotechnical Branch (Post 831001). 20pp. 33033:155-33033:192.
- 8510150471 Forwards draft technical position, "Determination of Radionuclide Sorption for Assessment of High Level Waste Isolation," for review by 850920.
KNAPP, M.R. Geotechnical Branch (Post 831001). 85/08/30. COSTANZI, F.A. Waste Management Branch (post 840429). GREEVE, S.J. Engineering Branch (Post 831001). BUNTING, J. Policy & Program Control Branch (Post 831001). 1p. 33033:175-33033:192.
- 8510150474 "Determination of Radionuclide Sorption for Assessment of High Level Waste Isolation," draft technical position.
* Geotechnical Branch (Post 831001). 85/08/31. 17pp. 33033:176-33033:192.

- 8510170114 Discusses archival trenches for testing performance of waste packages at specific low level waste disposal sites. Meeting requested to discuss overall exam of assurance of proper functioning at site prior to site decommissioning.
COSTANZI, F.A. Waste Management Branch (post 840429). FIN A-3171. 85/10/09. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 8pp. 33075:020-33075:030.
- 8510170121 Requests review of BNL repts re archival trenches for testing performance of waste packages at specific low level waste disposal sites. Program undertaken should be carefully planned & implemented for meaningful results.
HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. FIN A-3171. 85/08/30. COSTANZI, F.A. Waste Management Branch (post 840429). 2pp. 33075:029-33075:030.
- 8510170435 Responds to 850821 ltr to Chairman Palladino requesting explanation of estimated probabilities re likelihood of core melt accident. Probability of one short-term death lower than probability of core melt.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/07. GILLAND, B. Affiliation Not Assigned. 6pp. 33047:187-33047:193.
- 8510170436 Requests explanation of discrepancy between NRC statement in Aug 1985 issue of Harper's re chances of meltdown & 1983 Sizewell PWR inquiry re probability of reactor accident causing short-term death.
GILLAND, B. Affiliation Not Assigned. 85/08/21. PALLADINO, N. Commissioners. 2pp. 33047:193-33047:193.
- 8510180384 Responds to 850923 ltr re delay in rulemaking action for proposed human factors GDC NRC drafting proposed rule on GDC that would recognize human factor design considerations required since TMI accident.
RUSSELL, W.T. Division of Human Factors Safety. 85/10/15. SHEEHY, E.J. Affiliation Not Assigned. 6pp. 33076:296-33076:303.
- 8510210179 Forwards Div of Licensing monthly rept on plant-specific backfitting activities through 850916. Status of active issues & summary of resolved issues encl.
CRUTCHFIELD, D. Assistant Director for Safety Assessment. 85/10/15. THOMPSON, H.L. Division of Licensing. 25pp. 33094:178-33094:202.
- 8510220168 Forwards complete listing of 179 outstanding task interface agreements. Increased awareness of & attempt to reduce overall backlog recommended.
THOMPSON, H.L. Division of Licensing. 85/10/16. BERNERO, R.M. Division of Systems Integration (post 811005). KNIGHT, J.P. Division of Engineering. RUSSELL, W.R. Division of Human Factors Safety. 6pp. 33098:133-33098:138.
- 8510250599 Responds to 850819 ltr re possible rulemakings. Changes to NRC policy on mail false statements under consideration.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). HEBDON, F.J. Program Technology Branch. 85/10/21. RAY, H.B. Southern California Edison Co. 4pp. 33191:224-33191:227.
- 8510310478 Ack receipt of final case study rept "Overpressurization of ECCS in BWRs." Schedule for resolution of issue consistent w/ results of present assessment. Generic ltr should be sent to affected BWR licensees. Ltr will be prepared by Dec 1985.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/18. HEITEMES, C.J. AEOD, Director's Office. 4pp. 33278:274-33278:317.

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

- 7905290232 Forwards NUREG-0557 "Staff Safety Evaluation of Long-Term Post-Accident Cooling of TMI-2."
MATTSON, R.J. Division of Systems Safety. 79/05/09. FRALEY, R. ACRS - Advisory Committee on Reactor Safeguards. 1p. 33013:249-33013:249.
- 7905230274 NUREG-0557 "Evaluation of Long-Term Post-Accident Core Cooling of TMI-2."
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 79/04/30. 212pp. 33013:250-33013:035.
- 8406260464 Discusses encl 840602 article re review team members under intense pressure to either gloss over or forewarn of allegations. Each member should remain uninfluenced by calls, comments & pressure.
EISENHUT, D.G. Division of Licensing. 84/06/15. NRC - No Detailed Affiliation Given. 3pp. 32981:162-32981:178.
- 8407090045 Discusses receipt of FOIA requests re work performed by Watertown team at facility. Press release dtd 840208 re obligations under FOIA encl.
CRUTCHFIELD, D. NRC - No Detailed Affiliation Given. 84/06/29. NRC - No Detailed Affiliation Given. 4pp. 32975:001-32975:004.
- 8407090263 Requests listed changes be made to Contract NRC-05-82-249, increasing work requirements & extending period of performance to 840708.
CRUTCHFIELD, D. Operating Reactors Branch 5. NRC-05-82-249. 84/06/28. BLAHA, J.L. Program Support & Analysis Staff. 2pp. 32975:085-32975:086.
- 8407100662 SECY-84-239 Provides info re potentially significant safety issues at facility, including backfill soil density, cadwelds, welding instrumentation, cabinet support & insp records.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/06/18. 7pp. 32975:005-32975:084.
- 8507050411 NUREG-1047 S01 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION, UNIT NO. 2. Docket No. 50-410. (Niagara Mohawk Power Corporation)
* Division of Licensing. 85/06/30. 35pp. 31372:268-31372:301.
- 8510010010 Requests 60-day extension for response to SSER & NRC 850708 request for revised procedure for estimating extent of core damage per NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys."
GAHM, J.W. Public Service Co. of Colorado. P-85328. 85/09/20. HUNTER, D.R. Region 4, Office of Director. 2pp. 32809:211-32809:212.

8510010016 Grants 850625 request for extension of completion dates for items 2.b.3 & 4 in Commission 840612 order re Suppl 1 to NUREG-0737 implementation of upgraded emergency procedures should be completed 6 months after Cycle 12 startup.
THOMPSON, H.L. Division of Licensing. 85/09/24. MUSOLF, D.M. Northern States Power Co. 3pp. 32833:191-32833:193.

8510010018 Marked-up Allegation Investigation Rept 4-83-A-65/1, Rev 3 re Allegation A-05 concerning Ebasco Svcs, Inc. QA personnel use of speed ftrs instead of deficiency notes for identifying deficiencies.
* NRC - No Detailed Affiliation Given. A-05. 84/06/24. 4pp. 32977:025-32977:028.

8510010027 Press release re NRC receiving pressure from congressional delegation concerning facility licensing. NRC 840609 handwritten notes encl.
RIDENOUR, R. Gambit Publications, Inc., New Orleans, LA. 84/06/09. 4pp. 32977:029-32977:032.

8510010026 Forwards evaluation of J. Gagliardo & L. Shao performance on Waterford 3 team.
CRUTCHFIELD, D. NRC - No Detailed Affiliation Given. 84/06/06. EISENHUT, D. NRC - No Detailed Affiliation Given. 3pp. 32976:096-32976:098.

8510010029 Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65/1 re Ebasco QA personnel use of speed ftrs instead of deficiency notes to identify problems on sys turnover documentation packages. QA Instruction-9 acceptable.
* NRC - No Detailed Affiliation Given. A-05. 84/06/26. 6pp. 32976:099-32976:103.

8510010034 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65/1 re Ebasco QA personnel use of speed ftrs instead of deficiency notes to identify problems on sys turnover documentation packages. QA Instruction-9 acceptable.
* NRC - No Detailed Affiliation Given. A-05. 84/07/10. 4pp. 32975:104-32976:107.

8510010037 Rev 1 to Allegation Investigation Repts 4-84-A-06-106, 4-84-A-06-121 & 4-84-A-06-122 re Allegations A-220, A-233, A-235 & A-236. One nonconformance reprimand improperly closed in violation of Criterion XVI of 10CFR50, App B.
* NRC - No Detailed Affiliation Given. A-220. 84/06/11. 17pp. 32976:106-32976:124.

8510010043 Marked-up Draft 6 of Allegation Investigation Repts 4-83-A-65/2.5.4-83-A-88/3A.4.4-84/06/175 & 4-84-A-06/170b re Allegations A-06, A-09, A-92, A-294 & A-269b, alleging inadequate training & layoffs of QA personnel.
* NRC - No Detailed Affiliation Given. A-05. 84/06/09. 4pp. 32977:118-32977:121.

8510010046 Confirms installation & qualification of containment high range radiation monitors & primary coolant radiation monitors per 10CFR50.49, License Condition 2.C(6) & SSER (NUREG-0857).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). ANPP-33590-EEVB. 85/09/27. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32802:175-32802:176.

8510010048 Forwards response to NUREG-0737, Item II.K.3.30 & NRC 850701 ltr verifying utility participation in Westinghouse Owners Group & use of NOTRUMP in small-break LOCA analysis. Analysis for Item II.K.3.31 will be provided by 860602.
DOMER, J.A. Tennessee Valley Authority. 85/09/25. ADENSAME, E. Licensing Branch 4. 3pp. 32800:311-32800:313.

8510010049 Draft 3 of Allegation Investigation Repts 4-84-A-06/106, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 on use of unqualified staff on safety-related sys. Purchase, spec & orders will be reviewed for safety status.
* NRC - No Detailed Affiliation Given. A-220. 84/06/18. 12pp. 32977:122-32977:133.

8510010050 Forwards response to NRC 850826 request for addl info for 5 of 11 criteria summarized in interim safety evaluation re post-accident sampling sys (NUREG-0737, Item II.B.3).
SIMPSON, E.C. Florida Power Corp. (subs. of Florida Progress Corp.). 3F0985-25. 85/09/27. STOLZ, J.F. Operating Reactors Branch 4. 75pp. 32802:277-32802:350.

8510010069 Forwards documents re renewal of Univ of Missouri (Rolla) facility, including 850114 license, SER, environ assessment, 850416 amend extending license expiration date & Univ of Missouri (Columbia) license & SER w/o encls.
THOMAS, C.O. Standardization & Special Projects Branch. 85/09/25. DREY, L. Affiliation Not Assigned. 3pp. 32833:157-32833:159.

8510010123 Forwards marked-up pages of FSAR & lessons learned implementation rept reflecting grab sample-type post-accident sampling sys, to meet requirements of NUREG-0737, Item II.B.3.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). ANPP-33573-EEVB. 85/09/26. KNIGHTON, G.W. Licensing Branch 3. 52pp. 32801:298-32801:349.

8510010192 Marked-up Draft 3 of Allegation Investigation Rept 4-83-A-65/1 re Allegation A-05, alleging that Ebasco Svcs, Inc. QA personnel used speed ftrs instead of deficiency notices to identify sys turnover documentation package problems.
* NRC - No Detailed Affiliation Given. A-05. 84/06/08. 6pp. 32976:331-32976:336.

8510010198 Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65 re Allegation A-06, alleging that Ebasco Svcs, Inc. QA reviewers have not completed on-the-job training requirements. No potential violations identified.
* NRC - No Detailed Affiliation Given. A-06. 84/06/06. 2pp. 32976:329-32976:330.

8510010199 Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-48/1 re Allegation A-01, alleging that employment records of Mercury Const Co QA personnel not verified. Rept findings QA inspectors certified w/o verifying previous employment.
* NRC - No Detailed Affiliation Given. A-01. 84/06/14. 15pp. 32976:314-32976:328.

8510010206 Forwards NRR 840623 request to util re items resulting from task force review of SSERs. Items discussed at 840615 & 22 meetings w/ util SSERs will be signed at future meeting.
SHEWMAKER, NRC - No Detailed Affiliation Given. 84/06/28. CHOKSHIN, DEVERS, J., JOHNSON, C. NRC - No Detailed Affiliation Given. 1p. 32976:296-32976:313.

8510010209 Summarizes position re mods to containment vent & purge sys, per NUREG-0578 & NUREG-0737. Forwards Rev 1 to Technical Data Rept TDR 266, "Stress Analysis for Demonstration of Operability of Purge & Vent Valves During DBAs".
WILSON, R.F. General Public Utilities Corp. - GPU Service Corp. RFW-0620. 85/09/24. ZWOLINSKI, J.A. Operating Reactors Branch 5. 6pp. 32800:249-32800:274.

8510010211 Marked-up Draft 8 of Allegation Investigation Rept 4-83-A-48/3 re Allegation A-03 concerning disclosure of exam answers before exam. Investigation in progress. Major areas to be investigated: Mercury certification program.
* NRC - No Detailed Affiliation Given. A-03. 84/07/18. 2pp. 32976:294-32976:295.

8510010216 Rev 3 to Allegation Investigation Repts 4-84-A-06/186 & 4-84-A-06/184. No violations noted. Major areas investigated: Allegations A-308 & A-306 re inadequate piping sys documentation required to verify compliance w/ ASME Code.
* NRC - No Detailed Affiliation Given. A-308. 84/06/26. 4pp. 32976:290-32976:293.

8510010217 Marked-up Draft 7 of Allegation Investigation Rept 4-83-A-48/3 re Allegation A-03 concerning disclosure of exam answers before exam. Investigation in progress. Major areas to be investigated: Mercury certification program.
* NRC - No Detailed Affiliation Given. A-03. 84/07/17. 3pp. 32976:287-32976:289.

8510010219 NUREG/CR-4185 AN ASSESSMENT OF DOSIMETRY DATA FOR ACCIDENTAL RADIONUCLIDE RELEASES FROM NUCLEAR REACTORS.
RUNKLE, G.E., OSTMEYER, R.H. Sandia National Laboratories. FIN A-1339. SAND85-0283. 85/09/30. Division of Risk Analysis & Operations (post 840429). 61pp. 32833:329-32834:030.

8510010222 Rev 0 to Allegation Investigation Rept 4-84-A-06/145 on Allegation A-263 re Mercury Const superintendent not agreeing w/ audit findings & refusing to correct problems re tubing w/o end caps. Corrective actions taken.
* NRC - No Detailed Affiliation Given. A-263. 84/06/15. 2pp. 32976:285-32976:286.

8510010223 Rev 0 to Allegation Investigation Rept 4-84-A-06/27 on Allegation A-132 re JA Jones Const Co use of "speed ftrs" to rept info which should have been reported in deficiency notices. Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. A-132. 84/06/06. 5pp. 32976:280-32976:284.

8510010227 NUREG-1031. S02 SAFETY EVALUATION RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION, UNIT 3. Docket No 50-423 (Northeast Nuclear Energy Company).
* Division of Licensing. 85/09/30. 100pp. 32836:195-32836:285.

8510010228 Rev 1 to Allegation Investigation Rept 4-84-A-06-152(3) on Allegation A-260 re lack of traceability of matts used in nonpressure retaining components in containment vessels. Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. A-260. 84/06/14. 2pp. 32976:278-32976:279.

8510010232 Draft 2 to Allegation Investigation Rept 4-84-A-06/145 on Allegation A-263 re Mercury Const superintendent not agreeing w/ audit findings & refusing to correct problems re tubing w/o end caps. Corrective actions taken.
* NRC - No Detailed Affiliation Given. A-263. 84/06/08. 8pp. 32976:253-32976:260.

8510010238 Marked-up Draft 6 of Allegation Investigation Rept 4-83-A-48/2 on Allegation A-03 re disclosure of exam answers. Major areas to be investigated: Mercury certification program & previous Mercury inspectors.
* NRC - No Detailed Affiliation Given. A-03. 84/06/09. 1p. 32976:261-32976:261.

8510010241 Rev 1 to Allegation Investigation Rept 4-84-A-06-142(3) on Allegation A-260 re lack of traceability of matts used in nonpressure retaining components in containment vessel. Allegation has no safety significance.
* NRC - No Detailed Affiliation Given. A-260. 84/06/14. 8pp. 32976:262-32976:269.

8510010253 Marked-up Draft 8 of Allegation Investigation Repts 4-83-A-48/2.4-84-A-06/96 & 4-84-A-06/156 re Allegations A-253, A-208 & A-274 concerning improper certification of inspectors.
* NRC - No Detailed Affiliation Given. A-253. 84/07/18. 2pp. 32976:245-32976:246.

8510010255 Draft 3 to Allegation Investigation Rept 4-84-A-06/145 on Allegation A-263 re Mercury Const superintendent not agreeing w/ audit findings & refusing to correct problems identified re tubing w/o end caps. Corrective actions taken.
* NRC - No Detailed Affiliation Given. A-263. 84/06/13. 4pp. 32976:270-32976:273.

8510010264 Rev 0 to Allegation Investigation Rept 4-84-A-06-181. No potential violations noted. Major area investigated: Allegation A-303a re documentation to verify compatibility backing rings & weld base matts.
SPAULDING, W. NRC - No Detailed Affiliation Given. A-303a. 84/06/25. 4pp. 32976:274-32976:277.

8510010274 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/1 re Allegation A-01, alleging that Mercury Const Co QA personnel employment records not verified. Rept findings QA personnel certified w/o verifying previous employment.
* NRC - No Detailed Affiliation Given. A-01. 84/06/26. 4pp. 32976:247-32976:250.

8510010278 Submits addl info to resolve SER Open Item 10 re estimated noble gas releases through atmosphere relief valves. Design meets criteria in NUREG-0737 & Reg Guide 1.97 for monitoring effluent releases.
ZIMMERMAN, S.R. Carolina Power & Light Co. NLS-85-293. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800:314-32800:337.

8510010283 Responds to FOIA request for background records of all inap repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABELL, Government Accountability Project. 32pp. 32884:005-32884:234.

-8510020229 Draft Issue C of Procedure ASP-IV-22, "Unloading &/or Handling Heavy or Specialized Equipment".
MEARKLE, J. Ebasco Services, Inc. (subs. of Enserch Corp.). 82/02/09. 6pp. 32890:146-32890:151.

-8510010447 Responds to Emergency Preparedness Followup Appraisal Rept 50-382/84-02 Table 5-1 of emergency plan revised re augmentation capability for supporting onshift organization, per NRC 840329 ltr.
LEDDICK, R.S. Louisiana Power & Light Co. W384-0057. 84/04/25. JOHNSON, E.H. Region 4, Office of Director. 25pp. 32894:283-32894:307.

-8404050355 Summarizes 840306 telcon re inap of post-accident sampling sys per TMI Item II.B.2 Comments on 840301 memo provided.
KNIGHTON, G.W. Licensing Branch 3. 84/03/14. BANGART, R.L. Region 4, Office of Director. 45pp. 32884:235-32884:240.

300 NONDOCKETED ITEMS

- 8510010354 Discusses Insp Rept 50-382/84-05 open items re post-accident sampling sys design & operability. Physical layout of sys described. No leakage should be allowed at mechanical couplings in wing area of reactor auxiliary bldg.
BANGART, R.L. Division of Vendor & Technical Programs. 84/03/01. KNIGHTON, G.W. Licensing Branch 3. App. 32684.231-32684.234.
- 8510010290 Marked-up Rev 2 to Allegation Investigation Repts 4-83-A-65/04 & 4-84-A-06/78b re Allegations A-08 & A-183b, alleging that QA documents not stored in fire safes overnight & some records stored in old file cabinets.
* NRC - No Detailed Affiliation Given. A-08. 84/07/19. 3pp. 32976:228-32976:230.
- 8510010293 Marked-up Rev 1 to Allegation Investigation Rept 4-83-A-65/6 re Allegation A-09 alleging that contractor QA people conducting document reviews laid off & Ebasco Svcs, Inc. engineers moved into QA positions.
* NRC - No Detailed Affiliation Given. A-09. 84/06/06. 2pp. 32976:251-32976:252.
- 8510010317 Draft 4 of Allegation Investigation Repts 4-83-A-65-04 & 4-84-A-06/78b re Allegations A-08 & A-183b concerning inadequate QA records sys & failure to store records in fire safe overnight.
* NRC - No Detailed Affiliation Given. A-08. 84/07/18. 2pp. 32976:226-32976:227.
- 8510010336 Marked-up Rev 1 to Allegation Investigation Repts 4-83-A-65/04 & 4-84-A-06/78b re Allegations A-08 & A-183b, alleging QA documents not stored in fire safes overnight & some records stored in old file cabinets.
* NRC - No Detailed Affiliation Given. A-08. 84/07/18. 3pp. 32976:231-32976:233.
- 8510010353 Marked-up Rev 1 to Allegation Investigation Repts 4-83-A-48/2, 4-84-A-06/96 & 4-84-A-06/156 re Allegations A-02, A-208 & A-274, alleging that Mercury Const Co QC inspectors improperly certified. Potential violations noted.
* NRC - No Detailed Affiliation Given. A-02. 84/06/06. 7pp. 32976:234-32976:240.
- 8510010383 News article re util denial of GAP & Citizens for Safe Energy claim that util cannot be trusted to ensure safety of plant & that independent review needed.
* Dallas Morning News, Dallas, TX. 84/07/28. 2pp. 32976:241-32976:242.
- 8510010426 Forwards revised plans & calculations re control room habitability (NUREG-0737, Item III.D.3.4). Design verification for VA-65 ductwork in progress. Relocation expected prior to restart after Fall 1985 outage.
ANDREWS, R.L. Omaha Public Power District, LIC-85-420. 85/09/23. BUTCHER, E.J. Operating Reactors Branch 3. 24pp. 32804:099-32804:122.
- 8510010438 Rev 0 to Allegation Investigation Repts 4-84-A-06/105, 106 & 107 re Allegations A-217, A-218 & A-219 that Mercury QA manager tried to fire employee because employee alleged QA did not follow procedures. No potential violations noted.
STEARNS, J.D. NRC - No Detailed Affiliation Given. A-217. 84/06/13. 2pp. 32976:243-32976:244.
- 8510010452 Final Rev 2 to Allegation Investigation Rept 4-83-A-88-6 re Allegation A-54 on Ebasco & site subcontractor failure to implement procedures. Site procedural implementation verified as adequate. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-54. 84/06/13. 3pp. 32977:115-32977:117.
- 8510010465 Responds to 850529 comments re proposed resolution of TMI Action Plan Item III.D.1.1. Reactor water cleanup sys provided w/connections to post-accident sampling sys for monitoring cleanup operations.
EDELMAN, M.R. Cleveland Electric Illuminating Co. PY-CEI/NR-0349. 85/09/24. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 32809:050-32809:051.
- 8510010475 Rev 2 to Allegation Investigation Repts 4-84-A-06-108, 121 & 122 re Allegations A-220, A-233, A-235 & A-236 that non-safety mat used in safety-related sys & nonconformance repts improperly dispositioned.
THATCHER, D.F. NRC - No Detailed Affiliation Given. A-220. 84/06/13. 7pp. 32975:187-32975:191.
- 8510010480 Allegation Investigation Repts 4-84-A-06/5, 25 & 43. Rev 4 re Allegations A-110, A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6, "Qualification of Insp. Exam & Testing Personnel."
DEVERS, J.K., YANG, L. NRC - No Detailed Affiliation Given. A-110. 84/06/30. 6pp. 32977:008-32977:013.
- 8510010484 Marked-up Allegation Investigation Rept 4-84-A-06-4. Rev 1 re Allegation A-109 that Ebasco Svcs, Inc. QA personnel stopped record reviewers when "wholesale" irregularities found in 70 of 1,200 concrete placement packages.
DEVERS, J.K., CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-109. 84/06/27. 4pp. 32977:021-32977:024.
- 8510010486 Rev 1 to Allegation Investigation Repts 5-84-A-06/44, 4-84-A-06/46, 4-84-A-06/47 & 4-84-A-06/48 re Allegations A-149, A-151, A-152 & A-153. Violation noted re nonconformance repts. Draft Rev 1 encl.
CROSSMAN, W.A. NRC - No Detailed Affiliation Given. A-149. 84/06/21. 10pp. 32976:354-32977:001.
- 8510010489 Final Allegation Investigation Rept 4-84-A-06-4. Rev 1 re Allegation A-109 that Ebasco Svcs, Inc. QA personnel stopped record reviewers when "wholesale" irregularities found in 70 of 1,200 concrete placement packages.
DEVERS, J.K., CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-109. 84/06/27. 12pp. 32975:155-32975:166.
- 8510010497 Marked-up Allegation Investigation Rept 4-84-A-06-4. Rev 0 re Allegation A-109 that Ebasco Svcs, Inc. QA personnel stopped record reviewers when "wholesale" irregularities found in 70 of 1,200 concrete placement packages.
DEVERS, J.K., CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-109. 84/06/13. 4pp. 32977:014-32977:017.
- 8510010498 Rev 0 to Allegation Investigation Rept 4-84-A-06/170b. No violations noted. Major areas investigated: Allegation A-289b re inadequate review of QA documentation of Sys 60 (safety injection) due to unqualified reviewers.
* NRC - No Detailed Affiliation Given. A-289b. 84/06/06. 4pp. 32977:004-32977:007.
- 8510010499 Marked-up portion of allegation investigation rept re Allegation A-109 that Ebasco Svcs, Inc. QA personnel stopped record reviewers when "wholesale" irregularities found. Specific packages not identified by 840525. Page superseded.
CHOKSHI, N.C., SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-109. 84/09/19. 2pp. 32975:167-32975:168.
- 8510010500 Requests all pertinent agency records be included in package to be made publicly available by 841016 per SSER 7.
CRUTCHFIELD, D. NRC - No Detailed Affiliation Given. 84/10/05. NRC - No Detailed Affiliation Given. 5pp. 32977:002-32977:003.
- 8510010604 Discusses review of 840913 note re addl or identical allegations. Fifteen alleged items in mechanical & piping review area & status of items being addressed in SSERs listed.
HOU, S. NRC - No Detailed Affiliation Given. 84/10/11. GAGLIARDO, J.E. NRC - No Detailed Affiliation Given. 3pp. 32975:275-32975:277.
- 8510010507 Rev 2 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re unqualified Ebasco reviewers performing documentation reviews in short period given. No violation noted.
* NRC - No Detailed Affiliation Given. A-294. 84/06/27. 3pp. 32975:170-32975:172.
- 8510010508 Allegation Investigation Repts 4-84-A-06/5, 23 & 43. Rev 2 re Allegations A-110, A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6, "Qualification of Insp. Exam & Testing Personnel."
DEVERS, J.K., YANG, L. NRC - No Detailed Affiliation Given. A-110. 84/07/10. 5pp. 32975:211-32975:215.
- 8510010509 Rev 2 to Allegation Investigation Repts 4-84-A-06/83, 85, 86 & 88 re Allegations A-188, A-190, A-191 & A-193 that Mercury procedures for review of QA records & documentation packages inadequate. No violations noted.
* NRC - No Detailed Affiliation Given. A-188. 84/06/19. 10pp. 32975:137-32975:145.
- 8510010510 Draft 2 to Allegation Investigation Rept 4-84-A-06/142(3) of Allegation A-259 re Class D mat used by CB&I in fabrication of nonpressure bearing structural components not welded w/traceable weld rod. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-259. 84/06/13. 20pp. 32977:058-32977:077.
- 8510010511 Draft of Allegation Investigation Rept 4-84-A-06 re Allegation A-296 concerning contractor failure to examine shop pipe welds during hydrostatic tests. Potential ASME Code violation noted.
* NRC - No Detailed Affiliation Given. A-296. 84/06/08. 3pp. 32975:146-32975:148.
- 8510010513 Marked-up Allegation Investigation Repts 4-84-A-06/5, 25 & 43. Rev 3 re Allegations A-110, A-130 & A-148 concerning 17 inspectors failing to meet requirements of ANSI N45.2.6, "Qualification of Insp. Exam & Testing Personnel."
DEVERS, J.K., YANG, L. NRC - No Detailed Affiliation Given. A-110. 84/08/29. 8pp. 32975:216-32975:223.
- 8510010514 Rev 0 to Allegation Investigation Rept 4-84-A-06-142(1) of Allegation A-258 re CB&I not maintaining mat traceability on certain seismic Category I structural components in containment vessel. No violations noted.
* NRC - No Detailed Affiliation Given. A-258. 84/06/08. 13pp. 32975:301-32975:313.
- 8510010515 Draft 7 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re inadequate indoctrination & training & QA reviewers not completing on-the-job training requirements. Approach to resolution listed.
* NRC - No Detailed Affiliation Given. A-294. 84/07/17. 2pp. 32975:173-32975:174.
- 8510010516 Rev 1 to Allegation Investigation Rept 4-84-A-06-146 of Allegation A-264-1 re lack of accurate mat traceability on instrument tube track. No violations noted.
* NRC - No Detailed Affiliation Given. A-264-1. 84/06/11. 5pp. 32975:314-32975:318.
- 8510010517 Rev 1 to Allegation Investigation Rept 4-84-A-06/11 of Allegation A-22 re documentation discrepancies between field const & QC package. No violations noted.
* NRC - No Detailed Affiliation Given. A-223. 84/06/11. 5pp. 32976:067-32976:081.
- 8510010518 Allegation Investigation Repts 4-84-A-06/7, 26 & 151. Rev 1 re Allegations A-112, A-131 & A-269 concerning incomplete JA Jones Const Co concrete placement packages. Violation noted: failure to maintain concrete curing log.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. A-112. 84/06/27. 5pp. 32977:053-32977:057.
- 8510010520 Draft 2 to Allegation Investigation Rept 4-84-A-06-178b re Allegation 296 concerning inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. Approach to resolution listed.
* NRC - No Detailed Affiliation Given. A-296. 84/07/18. 2pp. 32975:319-32975:320.
- 8510010521 Provides executive summary of results of interview & review of individual "X" files HS Philips assigned to assist Oic of Investigation per 840601 request. Individual contacted during task force effort.
PHILLIPS, H.S. Region 4, Office of Director. 84/06/18. Region 4, Office of Director. 42pp. 32975:321-32975:362.
- 8510010522 Rev 2 to Allegation Investigation Rept 4-84-A-06/81h re Allegation A-186(b) that Ebasco records reviewer stamped off 1,600 civil records (concrete) in 8 h work day. No potential violations noted.
WENCZEL, V. NRC - No Detailed Affiliation Given. A-186(B). 84/06/19. 3pp. 32975:224-32975:226.
- 8510010523 Rev 0 to Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a, 23c & 167 re Allegations A-100-A-103, A-127, A-128a, A-128c & A-285a concerning Mercury traceability problems. Mercury weld records difficult to follow.
* NRC - No Detailed Affiliation Given. A-100. 84/06/13. 8pp. 32976:082-32976:089.
- 8510010524 Rev 1 to Allegation Investigation Rept 4-83-A-88 re Allegation A-92 on unqualified Ebasco clerks closing out document deficiency repts. No potential violations noted.
ROSS, D. NRC - No Detailed Affiliation Given. A-92. 84/06/08. 6pp. 32975:227-32975:232.
- 8510010526 Allegation Investigation Repts 4-84-A-06/7, 26 & 51. Draft 7 re Allegations A-112, A-131 & A-269 concerning incomplete JA Jones Const Co concrete placement packages. Allegation could impact assessment of concrete structure capability.
* NRC - No Detailed Affiliation Given. A-112. 84/07/17. 2pp. 32975:149-32975:150.
- 8510010527 News release announcing planned commercial operation in First Quarter 1985 & Sept fuel loading. Const costs not expected to exceed present estimates.
* Louisiana Power & Light Co. 84/07/25. 2pp. 32976:007-32976:030.
- 8510010528 Draft 3 of Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 concerning unqualified mat adaptors used on safety-related sys.
* NRC - No Detailed Affiliation Given. A-220. 84/06/18. 3pp. 32976:004-32976:006.

- 8510010529** Draft 1 of introduction to SSER 7 re proposed operation of facility. Supply provides results of evaluation of approx 350 allegations & concerns re poor const practices.
* NRC - No Detailed Affiliation Given. 84/07/17. 3pp. 32976.001-32976.003.
- 8510010530** Rev 3 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re unqualified Ebasco reviewers performing documentation reviews in short period given. No violation noted.
* NRC - No Detailed Affiliation Given. A-294. 84/07/10. 6pp. 32975.175-32975.180.
- 8510010531** Rev 1 to Allegation Investigation Repts 4-84-A-06/110 & 119 re Allegations A-222 & A-231 re insufficiency of Mercury concrete expansion anchor installation & insp procedure. Allegation may have some safety significance.
MARINI, W.S. NRC - No Detailed Affiliation Given. A-222. 84/06/20. 5pp. 32975.233-32975.236.
- 8510010533** Rev 1 to Allegation Investigation Rept 4-83-A-88/15 of Allegation A-63 re equipment improperly aligned or leveled at installation. No violations noted.
* NRC - No Detailed Affiliation Given. A-63. 84/06/07. 5pp. 32976.031-32976.035.
- 8510010534** Rev 3 to Allegation Investigation Rept 4-84-A-06/153 of Allegation A-271 re improper consideration given to upgrading process & coating interior of containment vessel. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-271. 84/07/10. 2pp. 32977.134-32977.135.
- 8510010535** Draft 3 of Allegation Investigation Repts 4-84-A-06/136 & 143 re Allegations A-250 & A-261 concerning Mercury Personnel change mat heat numbers & welder identification numbers on QA documentation w/o proper justification.
* NRC - No Detailed Affiliation Given. A-250. 84/06/21. 6pp. 32976.036-32976.041.
- 8510010537** Allegation Investigation Rept 4-83-A-88/11 re Allegation Draft 3 of A-59 concerning Ebasco failure to place hold tags on field items.
* NRC - No Detailed Affiliation Given. A-59. 84/06/13. 4pp. 32976.092-32976.095.
- 8510010539** Rev 1 to Allegation Investigation Rept 4-84-A-06/02 re Allegation A-107 that false documents generated to replace missing records concerning cadweld activities. No violations noted.
* NRC - No Detailed Affiliation Given. A-107. 84/06/15. 2pp. 32976.090-32976.091.
- 8510010540** Rev 0 to Allegation Investigation Rept 4-84-A-06-4 re Allegation A-109 on Ebasco QA personnel stopping records & reviewers when wholesale irregularities found. Potential violation noted re failure to maintain concrete records.
* NRC - No Detailed Affiliation Given. A-109. 84/06/13. 19pp. 32976.042-32976.059.
- 8510010541** Rev 2 to Allegation Investigation Rept 4-84-A-06-02 re Allegation A-107 concerning generation of false documents to replace missing cadweld activity records. No potential violations found.
DEVERS, J. NRC - No Detailed Affiliation Given. A-107. 84/06/28. 6pp. 32975.181-32975.186.
- 8510010542** Marked-up Allegation Investigation Repts 4-84-A-06/21, 172, Rev 2, re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining mat traceability on supplemental steel used w/ pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-126. 84/07/11. 3pp. 32975.237-32975.239.
- 8510010543** Rev 1 to Allegation Investigation Rept 4-83-A-88-6 re Allegation A-54 on failure by Ebasco & site contractor to implement procedures. Site procedure implementation verified as adequate. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-54. 84/06/11. 4pp. 32976.060-32976.066.
- 8510010545** Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 1, re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining mat traceability on supplemental steel. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-126. 84/07/10. 3pp. 32975.240-32975.243.
- 8510010547** Rev 1 to Allegation Investigation Rept 4-84-A-06-168 & 170a of Allegations A-286 & A-289a re falsification of heat numbers to demonstrate adequate traceability. No violations noted.
DEVERS, J. NRC - No Detailed Affiliation Given. A-286. 84/06/28. 3pp. 32977.018-32977.020.
- 8510010548** Rev 2 to Allegation Investigation Rept 4-84-A-06/81b re Allegation A-186(b) concerning Ebasco records reviewer allegedly stamping off 1,600 civil records in 8 h day in Sept 11982. Stamping was to account for & collate records.
* NRC - No Detailed Affiliation Given. A-186(B). 84/06/19. 5pp. 32976.125-32976.129.
- 8510010549** Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 3, re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining mat traceability on supplemental steel used w/ pipe hangers & supports. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-126. 84/06/29. 3pp. 32975.244-32975.246.
- 8510010551** Marked-up Draft 1 of Allegation Investigation Repts 4-84-A-06/103, 109, 126, 144 & 184 re Allegations A-215, A-175, A-240, A-239 & A-306 concerning destruction of deficiency rept. Violation noted: incomplete & incorrect records.
* NRC - No Detailed Affiliation Given. A-215. 84/06/13. 17pp. 32976.128-32976.145.
- 8510010552** Rev 3 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 concerning Ebasco Svcs, Inc Interloc Ltr W3-QA-23661 written to cover up problems in documentary group & unresolved welding defects. No violations found.
* NRC - No Detailed Affiliation Given. A-252. 84/06/08. 11pp. 32976.146-32976.156.
- 8510010553** Marked-up Allegation Investigation Rept 4-84-A-06, Rev 2 re Allegation A-252 concerning Ebasco Svcs, Inc Interloc Ltr W3-QA-23661 written to cover up problems in documentary group & unresolved welding deficiencies.
SHAO, L. NRC - No Detailed Affiliation Given. A-252. 84/08/08. 4pp. 32975.151-32975.154.
- 8510010555** Rev 4 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 concerning Ebasco Svcs, Inc Interloc Ltr W3-QA-23661 written to cover up problems in documentary group. No potential violations found.
* NRC - No Detailed Affiliation Given. A-252. 84/06/30. 2pp. 32976.157-32976.158.
- 8510010556** Rev 0 to Allegation Investigation Rept 4-84-A-06-11 re Allegation A-116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-116. 84/06/20. 6pp. 32976.159-32976.164.
- 8510010557** Rev 1 to Allegation Investigation Rept 4-84-A-06/81d re Allegation A-186(a) concerning Ebasco QA surveillance not monitoring contractor work activity. Review concluded Ebasco surveillance program meets intent of Ebasco QA program.
* NRC - No Detailed Affiliation Given. A-186(A). 84/06/08. 3pp. 32977.044-32977.046.
- 8510010559** Allegation Investigation Rept 4-84-A-06/181, Rev 1, re Allegation A-303a concerning Tompkins-Beckwith not providing documentation to verify that welding backing rings & weld base mat compatible. No potential violations noted.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-303A. 84/07/01. 6pp. 32975.247-32975.252.
- 8510010560** Rev 1 to Allegation Investigation Rept 4-8-A-06-27 of Allegation A-132 re JA Jones Const Co use of communication called "speed ltrs" to rept info that should have been reported in deficiency notices. No violation noted.
* NRC - No Detailed Affiliation Given. A-132. 84/06/19. 14pp. 32975.192-32975.205.
- 8510010562** Marked-up Allegation Investigation Rept 4-84-A-06/181, Rev 0, re Allegation A-303a concerning Tompkins-Beckwith not providing documentation to verify that welding backing rings & base mat compatible. No potential violations noted.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-303A. 84/06/25. 4pp. 32975.253-32975.256.
- 8510010563** Rev 3 to Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 that nonsafety mat used in safety-related sys & nonconformance repts improperly dispositioned.
THATCHER, D.F. NRC - No Detailed Affiliation Given. A-220. 84/06/18. 10pp. 32975.278-32975.287.
- 8510010564** Draft 2 to Allegation Investigation Rept 4-84-A-06-31 of Allegation A-136 re difficulty of Ebasco personnel to get approval to initiate formal nonconformance rept between 1975 & 1977 in civil/structural area. No violation noted.
* NRC - No Detailed Affiliation Given. A-136. 84/06/14. 5pp. 32975.206-32975.210.
- 8510010565** Draft 5 of Allegation Investigation Rept 4-84-A-06/151 re Allegations A-269, A-112, A-113, A-129, A-131, A-137, A-158 & A-272 concerning cancellation of concrete records review. Insp of issues essentially completed prior to 840402.
* NRC - No Detailed Affiliation Given. A-269. 84/05/21. 2pp. 32977.047-32977.048.
- 8510010567** Rev 1 to Allegation Investigation Repts 4-84-A-06-171 & 179 re Allegations A-290 & A-301 concerning inadequate corrective action documents & incorrectly made changes to QA records. Items potential ASME Code violation.
* NRC - No Detailed Affiliation Given. A-290. 84/06/22. 8pp. 32977.033-32977.040.
- 8510010568** Allegation Investigation Repts 4-84-A-06/44/46/47/48, Rev 3, re Allegations A-149, A-151, A-152 & A-153 concerning four nonconformance repts signed by uncertified QC inspectors & lack of seismic Category I stairs insp repts.
CROSSMAN, W.A. NRC - No Detailed Affiliation Given. A-149. 84/07/20. 5pp. 32975.257-32975.261.
- 8510010571** Rev 2 to Allegation Investigation Rept 4-84-A-06-63 re Allegation A-168 concerning poor QC by American Bridge resulting in lack of traceability of 2,300 lb of nonsafety weld rod. No safety significance re allegation.
* NRC - No Detailed Affiliation Given. A-168. 84/08/29. 3pp. 32977.041-32977.043.
- 8510010573** Allegation Investigation Rept 4-84-A-06, Draft 1 re Allegation A-252 concerning contractor preparing correspondence to cover up problems in documentary review group & unresolved welding deficiencies.
* NRC - No Detailed Affiliation Given. A-252. 84/08/08. 6pp. 32975.288-32975.293.
- 8510010574** Rev 2 to Allegation Investigation Rept 4-84-A-06-146 of Allegation A-264-1 re failures to provide accurate mat traceability on instrument tube track. No violations noted.
* NRC - No Detailed Affiliation Given. A-264-1. 84/06/13. 2pp. 32976.167-32976.166.
- 8510010575** Rev 3 to Allegation Investigation Repts 4-84-A-06/60, 61, 173, 174 & 178 re Allegations A-165, 166, 292, 293, 297, 299 & 300 concerning activities of Ebasco vendor QA personnel & inadequacy of vendor QA records.
* NRC - No Detailed Affiliation Given. A-165. 84/08/23. 17pp. 32976.167-32976.183.
- 8510010578** Allegation Investigation Repts 4-84-A-06/44/46/47/48, Rev 2, re Allegations A-149, A-151, A-152 & A-153 concerning four nonconformance repts signed by uncertified QC inspectors & lack of seismic Category I stairs insp repts.
CROSSMAN, W.A. NRC - No Detailed Affiliation Given. A-149. 84/07/19. 5pp. 32975.262-32975.266.
- 8510010577** Allegation Investigation Rept 4-84-A-06-37 of Allegation A-142 re alleged statement on several occasions that nonconformance rept inflated had been in adequately dispositioned.
* NRC - No Detailed Affiliation Given. A-142. 84/09/04. 2pp. 32977.170-32977.171.
- 8510010579** Allegation Investigation Rept 4-84-A-06, Draft 1 re Allegation A-296 concerning contractor failure to visually examine shop pipe welds during hydrostatic tests. Potential ASME Code violation noted.
* NRC - No Detailed Affiliation Given. A-296. 85/10/01. 2pp. 32975.294-32975.295.
- 8510010580** Rev 1 to Allegation Investigation Rept 4-84-A-06-1786 of Allegation A-298 re inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. No violations noted.
* NRC - No Detailed Affiliation Given. A-298. 84/06/21. 6pp. 32976.184-32976.189.
- 8510010581** Allegation Investigation Repts 4-84-A-06/177, 184a, 184k, 184l & 184m, Rev 2, re Allegations A-296, A-306a, 306k, 306l & 306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds for leaks.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-296. 84/07/11. 8pp. 32975.267-32975.274.
- 8510010582** Draft 6 to Allegation Investigation Repts 4-84-A-06/173, 174, 178, 60 & 61 re Allegations A-165, 166, 292, 293, 297, 298, 299 & 300 concerning vendor documentation possibly containing deficiencies not identified & corrected.
* NRC - No Detailed Affiliation Given. A-165. 84/07/13. 4pp. 32977.049-32977.052.
- 8510010583** Rev 1 to Allegation Investigation Repts 4-83-A-88, 6, 4-82-A-78/17, 4-83-A-88/18 & 4-84-A-12 re Allegations A-84, A-65, A-66 & A-322 concerning unacceptable Mercury insp activities. No violations noted.
* NRC - No Detailed Affiliation Given. A-64. 84/06/07. 7pp. 32976.347-32976.353.

302 NONDOCKETED ITEMS

- 8510010584** Final Allegation Investigation Repts 4-84-A-06/7,26 & 151, Rev 1 re Allegations A-112,A-131 & A-269 concerning complete JA Jones Const Co concrete placement packages. Violation noted: failure to maintain concrete curing log.
* CHOKSHI,N.C. NRC - No Detailed Affiliation Given. A-112. 84/06/27. 5pp. 32975-296-32975-300.
- 8510010586** Draft 6 of Allegation Investigation Rept 4-84-A-06/151 re Allegations A-269,A-112,A-131,A-129,A-131,A-135,A-137,A-158 & A-272 concerning concrete records canceled during partial review.
* NRC - No Detailed Affiliation Given. A-269. 84/06/06. 9pp. 32977-161-32977-169.
- 8510010587** Draft 3 to Allegation Investigation Repts 4-84-A-06/120,123, 124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13, 14,15,16,17,18,4-84-A-31,including Allegations A-232,A-234, A-237,A-238,A-243,A-244,A-245,A-311,A-312,A-313 & A-316.
* NRC - No Detailed Affiliation Given. A-232. 84/06/07. 5pp. 32677-156-32977-160.
- 8510010589** Rev 0 to Allegation Investigation Rept 4-84-A-06-27 of Allegation A-132 re JA Jones Const Co use of "speed lvs" to rept info that should have been reported in deficiency notices.No violation noted.
* NRC - No Detailed Affiliation Given. A-132. 84/06/06. 18pp. 32977-136-32977-155.
- 8510010592** Rev 1 to Allegation Investigation Rept 4-83-A-88-11 re Allegation A-59 concerning Ebasco failure to place hold tags on field items.No violations noted.
* NRC - No Detailed Affiliation Given. A-59. 84/06/13. 6pp. 32977-108-32977-113.
- 8510010594** Rev 1 to Allegation Investigation Rept 4-84-A-06-64 re Allegation A-169 concerning Ebasco engineer closing out nonconformance rept on work done by American Bridge on steel beam connections w/o sufficient technical justification.
* NRC - No Detailed Affiliation Given. A-169. 84/09/04. 1p. 32977-114-32977-114.
- 8510010595** Draft 3 of Allegation Investigation Rept 4-84-A-06-11 re Allegation A-116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel.No potential violations noted.
* NRC - No Detailed Affiliation Given. A-116. 84/06/15. 3pp. 32977-105-32977-107.
- 8510010596** Rev 2 to Allegation Investigation Rept 4-84-A-06-1786 of Allegation A-298 re inadequate Ebasco vendor reviews & failure of QC to check structural items for defects. Violations noted.
* NRC - No Detailed Affiliation Given. A-298. 84/06/15. 5pp. 32077-100-32977-104.
- 8510010597** Rev 1 to Allegation Investigation Rept A-83-A-88-10 re Allegation A-58 concerning improper maint practices of util & contractors.No violations noted.
* NRC - No Detailed Affiliation Given. A-58. 84/06/15. 10pp. 32977-090-32977-099.
- 8510010598** Marked-up Allegation Investigation Repts A-84-A-06/8,30 & 32 re Allegations A-113,A-135 & A-137 concerning need for review of concrete placement records based on Ebasco Svc,Inc 821209 memo.
* NRC - No Detailed Affiliation Given. A-113. 84/07/11. 1p. 32977-089-32977-080.
- 8510010599** Draft 1 to Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4 re Allegations A-57 & A-314 concerning lack of qualifications for Mercury Const Co Level III inspectors. Insp may have been performed by unqualified personnel.
* NRC - No Detailed Affiliation Given. A-57. 84/07/17. 2pp. 32977-087-32977-068.
- 8510010600** Draft 3 of Allegation Investigation Rept 4-84-A-06/7 re Allegations A-117, A-131 & A-269 on concrete placement packages.No evidence of significant deviations from project specs found.Some laxness in record keeping noted.
* NRC - No Detailed Affiliation Given. A-112. 84/06/07. 6pp. 32977-091-32977-097.
- 8510010604** Allegation Investigation Repts 4-84-A-06/9,39 & 49,Rev 1 re Allegations A-114,A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. A-114. 84/06/26. 3pp. 32977-078-32977-080.
- 8510010605** Rev 1 to Allegation Investigation Rept 4-84-A-06/72 re Allegation A-177 concerning Ebasco QA inspector exercising improper judgment & de-activating non-conformance repts dishonestly for American Bridge Company steel const work.
* NRC - No Detailed Affiliation Given. A-177. 84/09/04. 1p. 32976-223-32976-223.
- 8510010607** Rev 0 to Allegation Investigation Rept 4-84-A-06/7 re Allegations A-112,A-131 & A-269 concerning concrete placement packages.Potential violation noted: failure to maintain concrete curing log for Placement 593501U24FHAA.
* NRC - No Detailed Affiliation Given. A-112. 84/06/13. 5pp. 32976-208-32976-222.
- 8510010609** Rev 3 to Allegation Investigation Repts 4-84-A-06/55 & 56 re Allegations A-160 & 161 concerning fabrication of support structures for instrumentation cabinets mounted on grating inside reactor containment bldg.
* NRC - No Detailed Affiliation Given. A-160. 84/06/25. 17pp. 32976-190-32976-203.
- 8510010610** Rev 2 to Allegation Investigation Rept 4-84-A-06/118 re Allegation A-230 concerning Ebasco review of startup sys 52B RCS finding many Mercury documents incomplete & red-lined on drawings that do not match as-built plant configuration.
* NRC - No Detailed Affiliation Given. A-230. 84/06/19. 4pp. 32976-204-32976-207.
- 8510010611** Marked-up SSER 7 re results of NRC evaluation of 350 allegations & concerns of poor const practices.
* Office of Nuclear Reactor Regulation, Director. * Region 4, Office of Director. 84/09/30. 300pp. 32977-231-32978-161.
- 8510010614** Rev 4 to Allegation Investigation Rept 4-84-A-06-31 re Allegation A-136 concerning difficulty of Ebasco QA personnel to get approval to initiate formal non-conformance rept in civil-structural area between 1975 & 1977.
* NRC - No Detailed Affiliation Given. A-136. 84/09/04. 2pp. 32977-229-32977-230.
- 8510010615** Rev 1 to Allegation Investigation Repts 4-83-A-88/Ac & 4-83-A-88/Ad re Allegations A-81 & A-82 of changes made to H-5 packages w/o knowledge of authorized nuclear inspector. No violations noted.
* NRC - No Detailed Affiliation Given. A-81. 84/06/13. 3pp. 32977-226-32977-228.
- 8510010619** Rev 4 to Allegation Investigation Repts 4-84-A-06/60,61,173, 174 & 178 of Allegations A-165,A-166,A-292,A-293,A-297, A-299 & A-300 re activities of Ebasco vendor QA personnel & inadequate QA records.
* NALFEZNY,C. NRC - No Detailed Affiliation Given. A-165. 84/06/15. 10pp. 32976-337-32976-346.
- 8510010620** Rev 2 to Allegation Investigation Rept 4-84-A-06-65 re Allegation A-170 concerning Ebasco discrepancy notice not properly dispositioned for missing reinforcement steel in fuel handling bldg.
* NRC - No Detailed Affiliation Given. A-170. 84/09/04. 2pp. 32977-224-32977-225.
- 8510010621** Rev 2 to Allegation Investigation Repts 4-83-A-88/16, 4-83-A-88/17 & 4-83-A-88/18 re Allegations A-64,A-65 & A-66 concerning unacceptable Mercury insp activities.No violations noted.
* NRC - No Detailed Affiliation Given. A-64. 84/06/15. 2pp. 32977-222-32977-223.
- 8510010627** Draft 5 to Allegation Investigation Rept 4-83-A-88/2a & 3 of Allegations A-47 & A-51 re coverup by Ebasco QA manager.
* NRC - No Detailed Affiliation Given. A-47. 84/07/17. 2pp. 32977-220-32977-221.
- 8510010630** Rev 1 to Allegation Investigation Rept 4-83-A-87/4 of Allegation A-43 re improper calibr & humidity & temp control in Magnaflex Co test lab.No potential violations noted.
* WESTBERG,R. NRC - No Detailed Affiliation Given. A-43. 84/08/29. 4pp. 32977-216-32977-219.
- 8510010631** Rev 1 to Allegation Investigation Repts 4-84-A-06/83,85,86 & 86 re Allegations A-188,A-190,A-191 & A-193 concerning Mercury procedures for review of QA records & inadequate documentation packages.
* NRC - No Detailed Affiliation Given. A-188. 84/06/18. 10pp. 32977-206-32977-215.
- 8510010634** "Review of Waterford III Basemat Analysis."
* Brookhaven National Laboratory. 84/06/21. 34pp. 32977-172-32977-205.
- 8510010636** Draft 5 to Allegation Investigation Repts 4-84-A-06/175,174, 178,60 & 61 of Allegations A-292,A-293,A-297,A-296,A-299, A-300,A-165 & A-166 re problems w/ Ebasco vendor QA personnel & records.
* NRC - No Detailed Affiliation Given. A-292. 84/06/09. 2pp. 32976-224-32976-225.
- 8510020009** Provides description of program to review proposed changes to plant & potential impact on Chapter 15 analyses per SSER 8 (NUREG-0857).
* VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.) ANPP-33608-EEVB. 85/09/30. KNIGHTON,G.W. Licensing Branch 3. 2pp. 32824-229-32824-230.
- 8510020011** Rev 1 to Allegation Investigation Rept 4-84-A-06-10 re Allegations A-115 & A-155 concerning concerns on Cachewild splice tensile test failure rates exceeding 1 in 15 consecutive test samples.No potential violations noted.
* YANG,L. NRC - No Detailed Affiliation Given. A-115. 84/06/13. 8pp. 32978-162-32978-169.
- 8510020013** Rev 1 to Allegation Investigation Rept 4-84-A-06/147 re Allegation A-235 re potential violations noted:initial insp records failed to provide evidence of as-built conditions, per 10CFR50,App B,Criterion XVII.
* FORD,I. M/0025,N. NRC - No Detailed Affiliation Given. A-265. 84/06/20. 10pp. 32978-170-32978-177.
- 8510020014** Rev 2 to Allegation Investigation Repts 4-84-A-06/182,4-84-3 & 4-84-A-06/187 re Allegations A-304,A-305 & A-285b on unqualified person making changes to QA documentation which affect acceptability of safety-related piping sys.
* NRC - No Detailed Affiliation Given. A-304. 84/06/15. 10pp. 32976-178-32976-187.
- 8510020015** Rev 1 to Allegation Investigation Rept 4-84-A-06/95 re Allegation A-207 concerning Mercury QA personnel throwing away documents after copies made.No violations noted.
* NRC - No Detailed Affiliation Given. A-207. 84/06/15. 2pp. 32978-188-32978-189.
- 8510020017** Draft 3 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301 Violations noted: lack of adequate procedures for processing deficiency repts, per 10CFR50,App B,Criterion V & ASME Code.
* NRC - No Detailed Affiliation Given. A-290. 84/06/13. 5pp. 32978-190-32978-194.
- 8510020020** Rev 3 to Allegation Investigation Rept 4-84-A-06/118 re Allegation A-230 concerning disclosing incomplete Mercury documents & drawings not matching as-built plant configuration during Startup Sys 52B, "Reactor Coolant".
* NRC - No Detailed Affiliation Given. A-230. 84/05/23. 9pp. 32978-195-32978-203.
- 8510020021** Rev 1 to Allegation Investigation Rept 4-84-A-06/91 re Allegation A-196 concerning Ebasco document control supervisor being unqualified for position.No violation noted.
* NRC - No Detailed Affiliation Given. A-196. 84/06/15. 4pp. 32978-204-32978-207.
- 8510020023** Rev 3 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. A-19. 84/07/20. 3pp. 32978-208-32978-210.
- 8510020024** Rev 1 to Allegation Investigation Rept 4-84-A-06-142(1) of Allegation A-258 re CB&I not maintaining full traceability on certain seismic Category 1 structural components in containment vessel.No violation noted.
* NRC - No Detailed Affiliation Given. A-258. 84/06/19. 25pp. 32978-211-32978-237.
- 8510020025** Rev 1 to Allegation Investigation Rept 4-84-A-06/97 re Allegation A-209 concerning review of Mercury weld records identifying welds not fit-up or final-inspected.No violations noted.
* NRC - No Detailed Affiliation Given. A-209. 84/06/15. 9pp. 32985-056-32985-062.
- 8510020026** Draft 2 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301 Violations noted: lack of adequate procedures for processing deficiency repts, per 10CFR50,App B,Criterion V & ASME Code.
* NRC - No Detailed Affiliation Given. A-290. 84/06/03. 10pp. 32978-238-32978-247.
- 8510020028** Rev 1 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. A-19. 84/06/25. 4pp. 32978-248-32978-251.
- 8510020029** Rev 1 to Allegation Investigation Rept 4-84-A-06/102 re Allegation A-214 concerning 1981 Mercury QC weld data repts containing incorrect filler metal certification.No violation noted.
* NRC - No Detailed Affiliation Given. A-214. 84/06/14. 7pp. 32978-252-32978-257.
- 8510020032** Rev 2 to Allegation Investigation Rept 4-83-A-74/7 re Allegation A-19 concerning record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. A-19. 84/07/10. 4pp. 32978-258-32978-261.

- 8510020033** Allegation Investigation Repts 4-84-A-06/12 & 4-84-A-06/15, Draft 6 re Allegations A-117 & A-120 concerning falsification of documents. Validity of insps questionable.
HARRISON, J. NRC - No Detailed Affiliation Given. A-117. 84/07/17. 2pp. 32978:262-32978:264.
- 8510020035** Rev 3 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-13 & A-164 concerning Ebasco Svcs Intl inadequate nonconformance control. Six nonconformance repts found w/o numbers.
* NRC - No Detailed Affiliation Given. A-18. 84/07/26. 2pp. 32978:266-32978:267.
- 8510020038** Allegation Investigation Repts 4-84-A-06/177, 184a, 184k, 184l & 184m, Draft 4 re Allegations A-296, A-306a, A-306k, A-306l & A-306m concerning Tompkins-Beckwith violating ASME Code requirements by failing to examine pipe welds.
* NRC - No Detailed Affiliation Given. A-296. 84/07/10. 3pp. 32978:268-32978:270.
- 8510020039** Rev 2 to Allegation Investigation Rept 4-84-A-06/11 re Allegation A-223 concerning documentation discrepancies between field const & QC packages. No violations noted.
* NRC - No Detailed Affiliation Given. A-223. 84/06/13. 2pp. 32978:265-32978:265.
- 8510020042** Rev 1 to Allegation Investigation Rept 4-84-A-06/118 of Allegation A-230 re Ebasco review of Startup Sys 52B(RCS) that found Mercury documents incomplete & red-lined w/ drawings which did not match as-built plant.
* NRC - No Detailed Affiliation Given. A-230. 84/06/13. 6pp. 32978:271-32978:278.
- 8510020045** Expresses appreciation for R Westberg assistance during task force effort re allegations & assessment of quality of const.
HARRISON, J.J. Division of Project & Resident Programs. 84/08/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32978:277-32978:277.
- 8510020047** Rev 1 to Allegation Investigation Repts 4-84-A-06/82a,b & c re Allegation A-187 concerning incorrect Mercury instrumentation drawings due to unincorporated field changes.
* NRC - No Detailed Affiliation Given. A-187. 84/06/19. 7pp. 32978:278-32978:283.
- 8510020049** Expresses appreciation for assistance of Div of Reactor Safety during task force review of allegations concerning quality of const.
HARRISON, J.J. Division of Project & Resident Programs. 84/08/08. SPESSARD, R.L. Region 3, Office of Director. 1p. 32978:284-32978:284.
- 8510020051** Rev 1 to Allegation Investigation Rept 4-84-A-06-135 re Allegation A-249 concerning improperly processed Ebasco Discrepancy notices. No violation noted.
* RED, B.L. NRC - No Detailed Affiliation Given. A-249. 84/06/15. 3pp. 32985:053-32985:055.
- 8510020054** Allegation Investigation Repts 4-84-A-06/6, 30 & 31, Draft 2 re Allegations A-113, A-135 & A-137 concerning need for review of concrete placement records based on Ebasco Svcs, Inc 821209 memo & problems noted in nonconformance repts.
SHEWMAKER NRC - No Detailed Affiliation Given. A-113. 84/07/18. 3pp. 32978:285-32978:286.
- 8510020057** Rev 1 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/ protective coatings & matt traceability for inside of containment vessel. Violation noted: failure to establish QA program.
* NRC - No Detailed Affiliation Given. A-256. 84/06/06. 22pp. 32978:287-32978:307.
- 8510020060** Allegation Investigation Repts 4-84-A-06/8, 30 & 32, Draft 1 re Allegations A-113, A-135 & A-137 concerning need for review of concrete placement records based Ebasco Svcs, Inc 821209 memo & problems noted in nonconformance repts.
* NRC - No Detailed Affiliation Given. A-113. 84/07/17. 6pp. 32978:308-32978:313.
- 8510020062** Rev 2 to Allegation Investigation Rept 4-84-A-06-113 re Allegation A-225 concerning whether guidelines provided in Reg Guide 1.29 were considered during instrument air piping & tubing design.
* NRC - No Detailed Affiliation Given. A-225. 84/06/13. 13pp. 32978:314-32978:327.
- 8510020069** Rev 1 to Allegation Investigation Rept 4-83-A-88-4A re Allegation A-94-A-99 concerning improper reporting & corrective action of nonconformance rept & missing QA records. No violations noted.
* NRC - No Detailed Affiliation Given. A-94. 84/06/18. 4pp. 32990:312-32990:315.
- 8510020073** Forwards Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted.
KISTER, H.B. Region 1, Office of Director. 85/09/19. KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 32827:141-32827:170.
- 8510020080** Insp Repts 50-387/85-26 & 50-388/85-21 on 850729-0825. No violation noted. Major areas inspected: plant operations, licensee events, open items, surveillance, maint, IE bulletins & TMI action items.
JACOBS, R.H., PLUSCO, L.R., STROSNIDER, J. Region 1, Office of Director. 50-388/85-21. 85/09/13. 28pp. 32827:143-32827:170.
- 8510020075** Rev 2 to Allegation Investigation Rept 4-84-A-06 re Allegation A-252 that Ebasco Svcs, Inc Interco Ltr W3-QA-23661 written to cover up problems in documentary group. No potential violations found.
* NRC - No Detailed Affiliation Given. A-252. 84/08/08. 6pp. 32978:335-32978:340.
- 8510020077** Rev 3 to Allegation Investigation Repts 4-84-A-06/182, 183 & 187 re Allegations A-304, A-305 & A-285b. Rev 1 dtd 850609, Rev 2 dtd 840615 & Draft 7 dtd 840717 encl.
* NRC - No Detailed Affiliation Given. A-304. 84/08/23. 7pp. 32978:341-32978:347.
- 8510020078** Rev 0 to Allegation Investigation Repts 4-84-A-06-171 & 4-84-A-06-179 re Allegations A-290 & A-301. Potential violation noted: lack of adequate procedure for disposition of corrective action documents. Draft 3 encl.
* NRC - No Detailed Affiliation Given. A-290. 84/06/15. 14pp. 32978:348-32978:361.
- 8510020079** Rev 3 to Allegation Investigation Rept 4-84-A-45 re Allegation A-335. Violations noted: failure to follow Ebasco Spec LOU-1584.472, Section II re insp of concrete curing on dome. Rev 1 dtd 840609 & Rev 2 dtd 840618 encl.
DEVERS, J. NRC - No Detailed Affiliation Given. A-335. 84/06/19. 16pp. 32979:001-32979:048.
- 8510020082** Rev 2 to Allegation Investigation Rept 4-84-A-47a of Allegation A-336 re failure of Tompkins-Beckwith to account for skewed angles in weld size spec for pipe supports. No violations noted. Rev 1 dtd 840609 encl.
TAPIA, J.J. NRC - No Detailed Affiliation Given. A-336. 84/06/19. 12pp. 32979:049-32979:077.
- 8510020084** Rev 0 to Allegation Investigation Repts 4-84-A-06-139, 4-84-A-06-140A & 4-84-A-06-141 re Allegations A-253, A-254 & A-257 concerning use of unqualified vendor reviewers & poorly maintained vendor records. No violation noted.
* NRC - No Detailed Affiliation Given. A-253. 84/06/13. 8pp. 32979:078-32979:085.
- 8510020085** Forwards addl info re installation of Chicago Bridge & Iron piece Numbers 55-2 welded to 55-4 & applicable attachments to Nonconformance Rept W3-8224.
DOBSON, D.E. Louisiana Power & Light Co. W3K84-1454. 84/06/21. STROSNIDER, J. Materials Engineering Branch. 152pp. 32979:086-32979:237.
- 8510020086** Rev 1 to Allegation Investigation Repts 4-84-A-06/67 & 4-84-A-06/69 of Allegations A-172 & A-174 re falsified Tompkins-Beckwith heat number records.
* NRC - No Detailed Affiliation Given. A-172. 84/06/13. 4pp. 32979:238-32979:241.
- 8510020088** Rev 2 to Allegation Investigation Rept 4-84-A-06/158 re Allegation A-276. Violation noted: certification of unqualified inspector. Rev 1 encl.
* NRC - No Detailed Affiliation Given. A-276. 84/06/19. 9pp. 32979:242-32979:250.
- 8510020091** Rev 1 to Allegation Investigation Repts 4-84-A-06-55 & 56 of Allegations A-160 & A-161 re matt lacking heat number traceability & welds done by unqualified welder & inspected by unqualified inspectors.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. A-160. 84/06/13. 11pp. 32979:251-32979:261.
- 8510020092** Allegation Investigation Rept: 4-84-A-06/24, Draft 2 re Allegation A-129 concerning JA Jones installation, insp & acceptance of waterstop splicing activities by unqualified personnel.
SHEWMAKER NRC - No Detailed Affiliation Given. A-129. 84/07/13. 3pp. 32979:262-32979:264.
- 8510020096** Marked-up Allegation Investigation Rept 4-84-A-06/27, Rev 3 re Allegation A-132 concerning JA Jones Const Co use of speed ltrs to rept info that should be reported in deficiency notices & nonconformance repts.
* NRC - No Detailed Affiliation Given. A-132. 84/07/11. 4pp. 32979:265-32979:297.
- 8510020099** Rev 1 to Allegation Investigation Rept 4-84-A-51-2. No violation noted. Major areas investigated: Allegation A-341 re alteration of deformed cable trays in order to install cable tray covers. Rev 0 encl.
* NRC - No Detailed Affiliation Given. A-341. 84/06/22. 13pp. 32979:298-32979:310.
- 8510020107** Rev 2 to Allegation Investigation Repts 4-84-A-06/92, 93, 94, 101 & 104 re Allegations A-197 through A-206, A-213 & A-216 concerning inadequate documentation of corrective actions for problems w/ QC weld record data sheets.
* NRC - No Detailed Affiliation Given. A-197. 84/06/15. 19pp. 32979:311-32979:327.
- 8510020110** Rev 1 to Allegation Investigation Repts 4-84-A-40/1, 4-84-A-40/2 & 4-84-A-40/3. No violations noted. Major areas inspected: Allegations A-332, A-333 & A-334 re inadequate DCN-MP-920 & questionable welder certification.
BERG, V. NRC - No Detailed Affiliation Given. A-332. 84/06/19. 3pp. 32979:328-32979:330.
- 8510020111** Draft 3 to Allegation Investigation Rept 4-84-A-06-72 of Allegation A-177 re Ebasco QA inspector malfeasance in dispositioning nonconformance repts on American Bridge Co work. No violations noted.
* NRC - No Detailed Affiliation Given. A-177. 84/06/19. 13pp. 32979:331-32979:343.
- 8510020115** Allegation Investigation Repts 4-84-A-06-9, 39 & 49, Rev 1 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. A-114. 84/06/26. 3pp. 32979:344-32979:346.
- 8510020116** Rev 1 to Allegation Investigation Rept 4-84-A-12-9. No violations noted. Major areas investigated: Allegation A-319 re nonconformance repts on instrumentation weld support deficiencies. Draft Rev 0 dtd 840523 encl.
JOHNSON, C. NRC - No Detailed Affiliation Given. A-319. 84/06/09. 5pp. 32979:347-32979:352.
- 8510020117** Rev 0 to Allegation Investigation Rept 4-84-A-06-178b. No violations noted. Major areas investigated: Allegation A-298 re inadequate Ebasco QC reviews of structural items. Marked-up Rev 0 dtd 840607 encl.
* NRC - No Detailed Affiliation Given. A-298. 84/06/19. 13pp. 32979:353-32980:006.
- 8510020118** Marked-up Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167, Rev 1 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning listed Mercury Const Co matt traceability problems.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-100. 84/06/26. 3pp. 32980:007-32980:009.
- 8510020120** Rev 2 to Allegation Investigation Repts 4-84-A-06-33 & 4-84-A-06-54 re Allegations A-138 & A-159. Violation noted: validity of placement, compaction & insp of backfill matt questionable. Rev 1 & Draft 1 encl.
DEVERS, J.F. NRC - No Detailed Affiliation Given. A-138. 84/06/26. 37pp. 32980:010-32980:048.
- 8510020121** Draft 2 to Allegation Investigation Repts 4-84-A-06/103, 109, 144, 126 & 184i re Allegations A-215, A-175, A-239, A-240 & A-306i concerning destroying deficiency rept on welder qualification & questionable quality of welding.
* NRC - No Detailed Affiliation Given. A-215. 84/06/14. 38pp. 32980:049-32980:086.
- 8510020123** Rev 2 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 re Allegations A-146 & A-157. Violations noted re Procedure W-SITP-4 & Reg Guide 1.10 guidelines. Rev 1, draft Revs 1 & 2 & Drafts 1 & 2 encl.
* NRC - No Detailed Affiliation Given. A-146. 84/06/26. 26pp. 32980:087-32980:112.
- 8510020125** Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 3 re Allegations A-126 & A-291 concerning Tompkins-Beckwith not maintaining matt traceability on supplemental steel used w/ pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-126. 84/08/29. 2pp. 32980:212-32980:217.
- 8510020126** Allegation Investigation Repts 4-84-A-06-9, 39 & 49, Rev 0 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on clam shell filter blanket under nuclear plant island.
* NRC - No Detailed Affiliation Given. A-114. 84/06/21. 3pp. 32978:332-32978:334.

304 NONDOCKETED ITEMS

- 8510020127** Allegation Investigation Rept 4-84-A-06/27, Rev 4 re Allegation A-132 concerning JA Jones Const Co use of speed ltrs to rept info that should be reported in deficiency notices & nonconformance repts.
* NRC - No Detailed Affiliation Given. A-132. 84/06/30. 3pp. 32980-218-32980-220.
- 8510020129** Rev 1 to Allegation Investigation Rept 4-84-A-06-8 re Allegations A-113, A-135 & A-137 concerning concrete placement record problems that should have been identified on nonconformance repts. Allegation unsubstantiated.
* NRC - No Detailed Affiliation Given. A-113. 84/06/06. 5pp. 32980-221-32980-225.
- 8510020130** Marked-up Rev 0 to Allegation Investigation Rept 4-84-A-06-G re Allegation A-111 concerning specs & procedures used as acceptance criteria for concrete work frequently ignored by JA Jones personnel.
* NRC - No Detailed Affiliation Given. A-111. 84/06/06. 6pp. 32980-126-32980-132.
- 8510020132** Advises that written communications from GAP should be promptly provided to EDO for further action assignments & EDO should be advised if verbal communication received.
REHM, T.A. Office of the Executive Director for Operations. 84/07/03. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 32980-226-32980-228.
- 8510020134** Allegation Investigation Repts 4-84-A-06-10 & 50, Draft 2 re Allegations 115 & 155 concerning deficiencies in cadweld splice tensile testing rates as compared to Ebasco cadweld spec & inadequate closure of nonconformance rept.
SHEWMAKER NRC - No Detailed Affiliation Given. A-115. 84/07/13. 3pp. 32980-133-32980-136.
- 8510020135** Handwritten Allegation Investigation Repts 4-84-A-06-5,25 & 43 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. A-110. 84/07/12. 1p. 32980-234-32980-234.
- 8510020136** Draft 2 to Allegation Investigation Rept 4-84-A-06-34. No violations noted. Major areas investigated: Allegation A-139 re disposition of concrete cracks identified during Summer 1983 as shrinkage cracks.
* NRC - No Detailed Affiliation Given. A-139. 84/07/19. 20pp. 32980-137-32980-156.
- 8510020137** Marked-up Allegation Investigation Rept 4-84-A-06-142(3) re Allegation A-259 concerning Class D mail used by Chicago Bridge & Iron in fabrication of nonpressure bearing structural components not welded w/traceable weld rod.
* NRC - No Detailed Affiliation Given. A-259. 84/06/18. 5pp. 32980-229-32980-233.
- 8510020138** Rev 2 to Allegation Investigation Rept 4-84-A-06/77 of Allegation A-182 re failure to inspect welding done by JA Jones Const Co. No violations noted.
* NRC - No Detailed Affiliation Given. A-182. 84/06/19. 5pp. 32980-157-32980-161.
- 8510020140** Rev 3 to Allegation Investigation Rept 4-84-A-06-142(1) re Allegation A-258. Violations noted: Ebasco failed to identify deviations from design bases in CB&I design documents re mat traceability. Marked-up Rev 2 dtd 840627 encl.
* NRC - No Detailed Affiliation Given. A-258. 84/07/11. 10pp. 32980-235-32980-244.
- 8510020142** Rev 1 to Allegation Rept 4-84-A-06-63 of Allegation A-168 re poor QC by American Bridge. No violations noted.
* NRC - No Detailed Affiliation Given. A-168. 84/06/13. 7pp. 32980-245-32980-252.
- 8510020143** Allegation Investigation Repts 4-84-A-06-5,25 & 43, Draft 2 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
SHEWMAKER NRC - No Detailed Affiliation Given. A-110. 84/07/13. 2pp. 32980-253-32980-254.
- 8510020144** Rev 1 to Allegation Investigation Rept 4-84-A-06/142(3) re Allegation A-259. Violations noted: inability to produce QA records for welds in safety-related structures. Marked-up Rev 0 dtd 840622 & Draft 3 dtd 840621 encl.
* NRC - No Detailed Affiliation Given. A-259. 84/07/01. 34pp. 32980-255-32980-290.
- 8510020147** Draft 2 to Allegation Investigation Rept 4-84-A-47b of Allegation A-337 re performance of tube track welding to requirements of AWS Welding Spec D1.3 rather than Spec D1.1. No violations noted.
* NRC - No Detailed Affiliation Given. A-337. 84/06/20. 7pp. 32980-291-32980-297.
- 8510020148** Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21,22, 23a, c, & 167, Rev 2 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning tested Mercury Const Co mat traceability problems.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-100. 84/06/24. 4pp. 32980-162-32980-165.
- 8510020151** Draft 4 to Allegation Investigation Rept 4-84-A-06-181 of Allegation 303a re failure of Thompsons-Beckwith to provide documentation to verify compatibility between welding backing rings & mat. No violations noted.
SPAULDING, W. NRC - No Detailed Affiliation Given. A-303a. 84/06/20. 8pp. 32980-298-32980-305.
- 8510020152** Rev 0 to Allegation Investigation Repts A-84-A-06/117 & 184g re Allegations A-229 & A-306g concerning inadequate reviews of turnover documentation packages which affect acceptability of safety-related sys.
* NRC - No Detailed Affiliation Given. A-229. 84/06/15. 21pp. 32980-306-32980-326.
- 8510020153** Draft of Allegation Investigation Repts 4-84-A-06/120,123,124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13,14,15,16,17,18 & 4-84-A-31 re Allegations A-232, A-234, A-238, A-243, A-244, A-245, A-262, A-311, A-312, A-313, A-316 & A-317.
* NRC - No Detailed Affiliation Given. A-232. 84/06/15. 44pp. 32980-166-32980-211.
- 8510020154** Allegation Investigation Repts 4-84-A-06/5,25 & 43, Rev 2 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. A-110. 84/07/10. 6pp. 32980-327-32980-332.
- 8510020156** Rev 1 to Allegation Investigation Rept 4-84-A-06/175 of Allegation A-294 re performance of documentation reviews by unqualified Ebasco personnel. No violations noted. Marked-up Rev 1 encl.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-294. 84/06/13. 7pp. 32980-333-32980-339.
- 8510020161** Marked-up Allegation Investigation Repts 4-84-A-06/5,25 & 43, Rev 1 re Allegations A-110, A-130 & A-148 concerning 17 inspectors from Ebasco Svcs Inc, JA Jones & Fegles Power Svcs not meeting ANSI N45.2.6 requirements.
* NRC - No Detailed Affiliation Given. A-110. 84/06/27. 12pp. 32980-340-32980-351.
- 8510020162** Draft 4 to Allegation Investigation Rept 4-84-A-06-149. No violation noted. Major areas investigated: Allegation A-267 re falsification of documentation concerning nonsafety-related pipe hangers placed in safety-related areas.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-267. 84/06/20. 6pp. 32980-352-32980-357.
- 8510020164** Draft 3 of Allegation Investigation Rept 4-84-A-06-5 re Allegations A-110, A-130 & A-148 concerning some inspectors not meeting all requirements of ANSI N45.2.6. "Qualification of Insp. Exam & Testing Personnel."
* NRC - No Detailed Affiliation Given. A-110. 85/06/08. 9pp. 32981-153-32981-161.
- 8510020165** Rev 0 to Allegation Investigation Rept 4-84-A-06/115 re Allegation A-227 concerning Ebasco inadequate nonconformance sys & nonconformances not properly identified & dispositioned.
* NRC - No Detailed Affiliation Given. A-227. 84/06/15. 26pp. 32980-358-32981-021.
- 8510020167** Rev 0 to Allegation Investigation Rept 4-84-A-06-150. No violations noted. Major areas investigated: Allegation A-268 re ungrouted surface-mounted base plates. Draft 1 dtd 840631 & Draft 2 dtd 840614 encl.
* NRC - No Detailed Affiliation Given. A-268. 84/06/19. 14pp. 32981-027-32981-035.
- 8510020169** Rev 1 to Allegation Investigation Rept 4-84-A-06-152. No violations noted. Major areas investigated: Allegation A-270 re common foundation basement, Block 2 concerns in Ebasco 751215 rept. Draft Rev 1 encl.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. A-270. 84/06/19. 6pp. 32981-036-32981-041.
- 8510020171** Allegation Investigation Rept 4-84-A-06-6, Rev 2 re Allegation A-111 concerning JA Jones personnel ignoring specs & procedures used as acceptance criteria for concrete work. No potential violations found.
* NRC - No Detailed Affiliation Given. A-111. 84/06/28. 7pp. 32980-113-32980-119.
- 8510020172** Allegation Investigation Rept 4-84-A-06-11, Rev 2 re Allegation A-116 concerning unauthorized changes to JA Jones concrete placement records by unknown personnel. No potential violations found.
* NRC - No Detailed Affiliation Given. A-116. 84/08/15. 3pp. 32980-120-32980-122.
- 8510020173** Rev 2 to Allegation Investigation Rept 4-84-A-06/8 re Allegations A-113, A-135 & A-137 concerning concrete placement records. Allegation has neither safety significance nor generic implications.
* NRC - No Detailed Affiliation Given. A-113. 84/06/13. 3pp. 32980-123-32980-125.
- 8510020174** Rev 3 to Allegation Investigation Repts 4-83-A-81/6, 4-83-A-88/2d, 4-84-A-88/2A1, 4-83-A-88/2A2, 4-83-A-88/2A3, 4-83-A-88/2A4, 4-84-A-06/16, 4-84-A-06/16, 4-84-A-06/23b, 4-84-A-06/163 & 4-84-A-51/7.
* NRC - No Detailed Affiliation Given. A-32. 84/07/12. 8pp. 32981-042-32981-049.
- 8510020175** Draft 1 of Allegation Investigation Repts 4-83-A-88/2c, 1,3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that subsequent QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/05/24. 6pp. 32981-050-32981-056.
- 8510020176** Marked-up Allegation Investigation Rept 4-84-A-06-11, Rev 1 re Allegation A-116 concerning unauthorized changes to JA Jones concrete placement records by unknown personnel. No potential violations found.
* NRC - No Detailed Affiliation Given. A-116. 84/06/26. 3pp. 32981-130-32981-135.
- 8510020177** Rev 0 to Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76. No violations noted. Major areas investigated: Allegations A-283 & A-181 re nonconformance repts. Draft Rev 0 & Draft 4 dtd 840611 encl.
* NRC - No Detailed Affiliation Given. A-283. 84/06/13. 7pp. 32981-136-32981-142.
- 8510020178** Allegation investigation Repts 4-84-A-06-10 & 50, Rev 2 re Allegations A-115 & A-155 concerning deficiencies in tensile testing rates of cadweld splice when compared to Ebasco cadweld spec. No violation noted.
YANG, L. NRC - No Detailed Affiliation Given. A-115. 84/06/21. 5pp. 32981-143-32981-147.
- 8510020179** Draft 3 of Allegation Investigation Rept 4-84-A-06/39 re Allegations A-144, A-154 & A-114 concerning clam shell filter blanket record deficiencies. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. A-144. 84/06/13. 2pp. 32981-148-32981-149.
- 8510020180** Rev 3 to Allegation Investigation Repts 4-84-A-06/120,123,124,129,130,131,144,4-84-A-12/3(a),(b),(c),6,7,8,10,11,13,14,15,16,17,18 & 4-84-A-31, including Allegations A-232, A-234, A-237, A-238, A-243, A-244, A-245, A-262 & A-311.
* NRC - No Detailed Affiliation Given. A-232. 84/06/30. 9pp. 32981-179-32981-187.
- 8510020183** Rev 3 to Allegation Investigation Repts 4-83-A-88/2c, 1,3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance repts & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/08/29. 7pp. 32981-057-32981-063.
- 8510020184** Allegation Investigation Repts 4-84-A-06-10 & 50, Rev 3 re Allegations A-115 & A-155 concerning deficiencies in Cadweld splice tensile testing rates as compared to Ebasco/Cadweld spec. No violation noted.
YANG, L. NRC - No Detailed Affiliation Given. A-115. 84/06/27. 3pp. 32981-150-32981-152.
- 8510020187** Rev 2 to Allegation Investigation Repts 4-84-A-40/1, 4-84-A-40/2 & 4-84-A-40/3. No violation noted. Major areas investigated: Allegations A-332, A-333 & A-334 re Design Change DCN-MP-920 Revs 1 & 0 encl.
* NRC - No Detailed Affiliation Given. A-332. 84/06/22. 9pp. 32981-188-32981-195.
- 8510020188** Rev 1 to Allegation Investigation Repts 4-83-A-81/81, 4-84-A-06/161, 4-84-A-06/169, 4-84-A-06/162, 4-84-A-06/164 & 4-84-A-06/166 re Allegations A-279, A-280, A-282, A-284, A-288 & A-27. Violations noted re separation criteria.
SUMMERS, D.L., FARREN, J.W., WENZEL, V.L. NRC - No Detailed Affiliation Given. A-279. 84/06/18. 4pp. 32981-196-32981-199.

8510020189 Rev 2 to Allegation Investigation Repts 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance reports & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/07/19. 9pp. 32981-064-32981-072.

8510020196 Rev 1 to Allegation Investigation Rept 4-84-A-476. No violations noted. Major areas investigated: Allegation A-337 re mercury instrumentation & control tube track welding. Rev 0 & Draft 2 encl.
* NRC - No Detailed Affiliation Given. A-337. 84/07/00. 26pp. 32981-200-32981-225.

8510020204 Rev 2 to Allegation Investigation Rept 4-84-A-51-1. No violation noted. Major areas investigated: Allegation A-340 re cable tray cleanliness. Revs 0 & 1 & Drafts 1, 2 & 3 encl.
* NRC - No Detailed Affiliation Given. A-340. 84/06/26. 33pp. 32981-225-32981-258.

8510020206 Rev 3 to Allegation Investigation Rept 4-83-A-81/2 of Allegation A-28 re falsified resumes & inadequate experience of QA inspectors. Violation noted: unqualified inspectors incorrectly certified due to inadequate procedure. WESTBERG, R. NRC - No Detailed Affiliation Given. A-28. 84/06/13. 3pp. 32981-259-32981-262.

8510020210 Rev 2 to Allegation Investigation 4-84-A-06-42 re Allegation A-147. Violations noted: fabrication of Caldwell test repts to replace lost records. Revs 1 & 0 & Drafts 4 & 2 encl.
* NRC - No Detailed Affiliation Given. A-147. 84/07/11. 40pp. 32981-263-32981-303.

8510020215 Marked-up draft preliminary review of util 840929 response re QA program.
* NRC - No Detailed Affiliation Given. 84/09/29. 14pp. 32981-304-32981-319.

8510020217 NUREG/CR-3426 V02 THERMAL AND FLUID MIXING IN 1/2-SCALE TEST FACILITY. Data Report.
VALENZUELA, J.A., DOAN, F.X. Creare, Inc. FIN A-4070. EPRI NP-3802. 85/09/30. Division of Accident Evaluation. 206pp. 32629-089-32629-278.

8510020218 Draft 2 of Allegation Investigation Repts 4-84-A-06-136 & 4-84-A-06-143 re Allegations A-250 & A-261 that Mercury personnel changed mat heat & welder identification numbers w/o proper justification. No violation noted.
* NRC - No Detailed Affiliation Given. A-250. 84/06/14. 6pp. 32981-320-32981-325.

8510020223 Rev 1 to Allegation Investigation Repts 4-84-A-52 & 4-84-A-88 re Allegations A-347, A-072, A-076 & A-077. Violations noted re Procedure PCP-2030 traceability requirements. Rev 0 encl.
* NRC - No Detailed Affiliation Given. A-347. 84/07/10. 20pp. 32981-326-32981-346.

8510020224 Forwards Insp Rept 50-344/85-29 on 850826-30. No violation noted.
KIRSCH, D.F. Region 5, Office of Director. 85/09/12. WITHERS, B.D. Portland General Electric Co. 1p. 32827-108-32827-114.

8510020230 Insp Rept 50-344/85-29 on 850826-30. No violation or deviation noted. Major areas inspected: IE bulletins, notices, outstanding open items & implementation of selected TMI action items.
KANOW, L.R., YOUNG, T. Region 5, Office of Director. IEIN-85-049. 85/09/11. 6pp. 32827-109-32827-114.

8510020225 Draft 1 of Allegation Investigation Repts 4-84-A-06-136 & 4-84-A-06-143 re Allegations A-250 & A-261 that Mercury personnel changed mat heat & welder numbers w/o proper justification. No violation noted.
* NRC - No Detailed Affiliation Given. A-250. 84/06/11. 3pp. 32981-347-32981-349.

8510020227 NUREG/CR-3426 V01 THERMAL AND FLUID MIXING IN 1/2-SCALE TEST FACILITY. Facility And Test Design Report.
DOAN, F.X., VALENZUELA, J.A. Creare, Inc. FIN A-4070. EPRI NP-3802. 85/09/30. Division of Accident Evaluation. 130pp. 32629-026-32629-156.

8510020228 NUREG/CR-4379 V01 LONG-TERM PERFORMANCE OF MATERIALS USED FOR HIGH-LEVEL WASTE PACKAGING. First Quarterly Report, Year Four April-June 1985.
STAHL, D., MILLER, N.E. Battelle Memorial Institute, Columbus Laboratories. FIN B-6794. 85/09/30. Division of Radiation Programs & Earth Sciences (post 840429). 111pp. 32838-277-32839-027.

8510020231 Draft 6 to Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12-4 re Allegations A-57 & A-314 concerning Mercury Level III examiners having no site certifications.
* NRC - No Detailed Affiliation Given. A-57. 84/06/09. 1p. 32981-350-32981-350.

8510020232 NUREG-0837 V05 N02 NRC TLD DIRECT RADIATION MONITORING NETWORK. Progress Report, April-June 1985.
JANG, J., KRAMARIC, M., COHEN, L. Region 1, Office of Director. 85/09/30. 225pp. 32629-336-32629-197.

8510020234 Draft 4 of Allegation Investigation Repts 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 & 78 re Allegations A-49, A-78, A-87, A-123, A-181 & A-283 concerning personnel not free to write nonconformance reports.
* NRC - No Detailed Affiliation Given. A-49. 84/06/11. 2pp. 32981-073-32981-074.

8510020240 NUREG/CR-4355 V01 226 PU(IV) IN MONKEYS. Overview Of Metabolism. DUBBIN, P.W., JEUNG, N., SCHMIDT, C.T. Lawrence Berkeley Laboratory. B-3041. LBL-20022. 85/09/30. Division of Radiation Programs & Earth Sciences (post 840429). 96pp. 32839-157-32839-252.

8510020241 Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 5-18 & 4-84-A-31. Rev 0 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. A-232. 84/07/10. 44pp. 32982-035-32982-078.

8510020242 Forwards Safety Insp Rept 50-293/85-20 on 850718-0819 & notice of violation.
WENZINGER, E.C. Region 1, Office of Director. 85/09/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 32827-001-32827-018.

8510020260 Insp Rept 50-293/85-20 on 850718-0819. Violation noted: failure to maintain trip level settings for two main steam line high radiation monitors consistent w/ Tech Spec limits.
MCBRIDE, M., MEYER, G., CASELLA, F. Region 1, Office of Director. 85/09/12. 15pp. 32827-004-32827-018.

8510020243 Summary of 850212-14 meetings w/util in Seneca, SC re review of util response to NUREG-0737, Item III.D.3.4, "Control Room Habitability Requirements" & status of open items concerning emergency feedwater sys. Attendance list encl.
NICOLARAS, H. Operating Reactors Branch 4. 85/10/01. Operating Reactors Branch 4. 6pp. 32846-252-32846-286.

8510020246 Rev 2 to Allegation Investigation Repts 4-84-A-06-78(a) & 4-84-A-06-79 of Allegations A-183(a) & A-184 re generic deficiencies in Mercury documentation of OCP record packages. No violations noted.
* NRC - No Detailed Affiliation Given. A-183(a). 84/06/13. 15pp. 32982-001-32982-015.

8510020247 Rev 0 to Allegation Investigation Rept 4-84-A-06/170(b). No violations noted. Major areas investigated: Allegation A-289(b) re inadequate review of QA documentation of Sys 60. Draft 6 to "Waterford Open Issue." dtd 850609 encl.
* NRC - No Detailed Affiliation Given. A-289(b). 84/06/19. 12pp. 32981-351-32981-361.

8510020248 Rev 0 to Allegation Investigation Rept 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance reports & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/06/14. 10pp. 32981-075-32981-084.

8510020255 Rev 1 to Allegation Investigation Rept 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance reports & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/07/10. 14pp. 32981-085-32981-098.

8510020257 NUREG/CR-4143 REVIEW AND EVALUATION OF THE MILLSTONE UNIT 3 PROBABILISTIC SAFETY STUDY. Containment Failure Modes, Radiological Source-Terms And Offsite Consequences.
KHATIB-RAHBAR, PRATT, W., LUDEWIG, H. Brookhaven National Laboratory. FIN A-3748. BNL-NUREG-51907. 85/09/30. Division of Systems Integration (post 811005). 75pp. 32629-198-32629-272.

8510020258 Rev 3 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59. Allegations A-18 & A-19 re inadequate nonconformance control by Ebasco Svcs Inc where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. A-18. 84/08/24. 2pp. 32982-016-32982-017.

8510020259 Draft 5 of Allegation Investigation Repts 4-84-A-06/173, 174, 178, 80 & 61 re Allegations A-165, A-186, A-292, A-293, A-297, A-298, A-299 & A-300 concerning problems w/Ebasco vendor QA people & records.
* NRC - No Detailed Affiliation Given. A-165. 84/06/09. 2pp. 32982-018-32982-019.

8510020261 Draft 3 of Allegation Investigation Rept 4-84-A-06/5 re Allegations A-110, A-130 & A-148 concerning ANSI N45.2.6, "Qualification of Insp. Exam & Testing Personnel." Violation noted: contractors failed to review QA program.
* NRC - No Detailed Affiliation Given. A-110. 85/06/09. 9pp. 32982-079-32982-088.

8510020262 Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 5-18 & 4-84-A-31. Rev 1 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. A-232. 84/06/16. 8pp. 32982-089-32982-096.

8510020263 Comments RE Shewmaker effort during allegation investigations. RE Shewmaker demonstrated outstanding technical knowledge & met skills.
SHAO, L.C. Division of Engineering Technology. 84/06/26. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 32982-020-32982-020.

8510020264 Draft 3 of Allegation Investigation Rept 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance reports & that QA documentation may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/06/13. 7pp. 32981-099-32981-115.

8510020266 Draft 3 to Allegation Investigation Rept 4-84-A-06-11 re Allegation 116 concerning unauthorized changes & additions made to JA Jones concrete placement records by unknown personnel. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-116. 84/06/15. 11pp. 32982-024-32982-034.

8510020267 Marked-up Allegation Investigation Rept 4-84-A-06-135. Rev 1 re Allegation A-249 concerning Ebasco Svcs. Inc discrepancy notices falsified by subcontractors. No potential violations found.
FRED, B.L. NRC - No Detailed Affiliation Given. A-249. 84/06/15. 3pp. 32982-021-32982-023.

8510020269 Rev 0 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance notification. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-53. 84/06/09. 6pp. 32982-097-32982-102.

8510020271 Draft 2 of Allegation Investigation Rept 4-83-A-88/2c, 1.3A1 & 4-84-A-06/18 re Allegations A-49, A-78, A-87 & A-123 concerning individuals prevented from writing nonconformance reports & QA documentation that may be falsified.
* NRC - No Detailed Affiliation Given. A-49. 84/06/09. 15pp. 32981-116-32981-129.

8510020272 Rev 4 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-53. 84/06/24. 5pp. 32982-103-32982-107.

8510020273 Draft 3 to Allegation Investigation Repts 4-83-A-88/2a, 2b, 2c, 1 & 4-84-A-12-3 re Allegations A-88, A-89, A-90, A-91 & A-315 concerning failure of contractor to provide pipe hydrostatic test results & faulty test documentation.
* NRC - No Detailed Affiliation Given. A-88. 84/06/19. 4pp. 32982-126-32982-129.

8510020278 Rev 3 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. No evidence of violation found during NRC review.
* NRC - No Detailed Affiliation Given. A-53. 84/07/19. 3pp. 32982-108-32982-110.

8510020279 Draft 1 of Allegation Investigation Rept 4-83-A-88/5 re Allegations A-53 & A-93 concerning unidentified & uncorrected nonconformances. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. A-53. 84/04/11. 2pp. 32982-111-32982-112.

306 NONDOCKETED ITEMS

8510020280 Draft 2 to Allegation Investigation Rept 4-84-A-06-03 re Allegation A-252 that Ebasco Ltr W3-QA-23661 issued to cover up problems discovered by documentary review group. Allegation unsupported.
* NRC - No Detailed Affiliation Given. A-252. 84/06/20. 6pp. 32982:130-32982:135.

8510020282 Rev 2 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-53. 84/06/26. 2pp. 32982:113-32982:119.

8510020284 Rev 1 to Allegation Investigation Rept 4-83-A-88 re Allegations A-53 & A-93 concerning procedures for nonconformance identification. Missing & voided nonconformance repts violate Criterion IX of App B.
* NRC - No Detailed Affiliation Given. A-53. 84/06/15. 6pp. 32982:120-32982:125.

8510020287 Rev 2 to Allegation Investigation Rept 4-84-A-06-135 re Allegation A-249 concerning Ebasco Svcs, Inc discrepancy notices falsified by subcontractors. No potential violations found. Marked-up Rev 2 encl.
FREED, B.L. NRC - No Detailed Affiliation Given. A-249. 84/06/22. 5pp. 32982:136-32982:140.

8510020289 Marked-up Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143. Draft 1 re Allegations A-250 & A-261 concerning Mercury personnel changing mat heat numbers & welder identification numbers w/o proper justification.
* NRC - No Detailed Affiliation Given. A-250. 84/06/11. 2pp. 32982:141-32982:142.

8510020292 Draft 3 to Allegation Investigation Rept 4-84-A-06-07 re Allegations A-112, A-131 & A-279 concerning concrete placement & tampered placement packages & insp of packages. Violation noted: failure to maintain concrete curing log.
CHOKSH, N.C. NRC - No Detailed Affiliation Given. A-112. 84/06/07. 7pp. 32982:143-32982:149.

8510020293 Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143. Draft 6 re Allegations A-250 & A-261 concerning falsification of documentation.
HARRISON, J. Office of Investigation. A-250. 84/07/17. 2pp. 32982:150-32982:151.

8510020295 Allegation Investigation Repts 4-84-A-06-12 & 4-84-A-06-15. Rev 2 re Allegations A-117 & A-120 that Mercury & Thompsons-Beckwith falsified records for compliance w/ federal safety regulations.
* NRC - No Detailed Affiliation Given. A-117. 84/06/23. 3pp. 32982:152-32982:154.

8510020296 Draft 2 of Allegation Investigation Rept 4-84-A-06/39 re Allegations A-144, A-154, A-179 & A-114 concerning clam shell filter blanket record deficiencies. Approach to resolution outlined.
* NRC - No Detailed Affiliation Given. A-144. 84/04/13. 1p. 32982:155-32982:155.

8510020300 Draft 3 of Allegation Investigation Rept 4-84-A-06/177 re Allegation A-296 concerning contractor failure to provide pipe hydrostatic test results.
* NRC - No Detailed Affiliation Given. A-296. 84/06/19. 4pp. 32982:156-32982:159.

8510020301 Marked-up Allegation Investigation Repts 4-84-A-06/136 & 4-84-A-06/143. Rev 0 re Allegations A-250 & A-261 concerning Mercury personnel changing mat heat numbers & welder identification numbers on QA documentation.
* NRC - No Detailed Affiliation Given. A-250. 84/06/27. 3pp. 32982:160-32982:162.

8510020303 Rev 1 to Allegation Investigation Rept 4-84-A-06-6 re Allegation A-111 concerning specs & procedures used as acceptance criteria for concrete work frequently ignored by JA Jones personnel. No potential violations.
* NRC - No Detailed Affiliation Given. A-111. 84/06/19. 7pp. 32982:163-32982:169.

8510020305 Draft 6 to Allegation Investigation Rept 4-83-A-88/3A4 re Allegation A-92 concerning inadequate indoctrination & training. Document reviews by improperly or untrained personnel may affect acceptability of safety-related sys.
* NRC - No Detailed Affiliation Given. A-92. 84/06/09. 1p. 32982:170-32982:170.

8510020306 Draft 2 of Allegation Investigation Rept 4-84-A-06/9 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-3997 re clam shell filter blanket.
* NRC - No Detailed Affiliation Given. A-114. 84/06/09. 3pp. 32982:171-32982:173.

8510020307 NUREG/CR-4376 HEAT TRANSFER CARRYOVER AND FALL BACK IN PWR STEAM GENERATORS DURING TRANSIENTS.
LAC, L.J., PARLOS, J., GRIFFITH, P. Massachusetts Institute of Technology, Cambridge, MA. PWR D-7225. LTRI NP-4298. 85/09/30. Division of Accident Evaluation. 212pp. 32982:124-32982:335.

8510020308 Rev 0 to Allegation Investigation Rept 4-84-A-06/5 re Allegations A-110, A-130 & A-148 on 17 inspectors from Ebasco, JA Jones & Fogles Power Svcs not meeting requirements of ANSI N45.2.6. "Qualification of Insp Exam."
* NRC - No Detailed Affiliation Given. A-110. 84/06/13. 16pp. 32982:174-32982:190.

8510020310 Rev 0 to Allegation Investigation Repts 4-84-A-06-44, 46, 47 & 48 for Allegations A-149, A-151, A-152 & A-153 re nonconformance repts signed by QC inspectors performing work prior to being certified. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-149. 84/06/19. 10pp. 32982:191-32982:200.

8510020311 Draft 2 of Allegation Investigation Rept 4-83-A-87/4 re Allegation A-43 concerning improperly calibrated instruments that invalidate acceptability of safety-related sys. No violation noted.
* NRC - No Detailed Affiliation Given. A-43. 84/07/20. 4pp. 32982:201-32982:204.

8510020312 Rev 0 to Allegation Investigation Repts 4-84-A-06/184u & 4-84-A-06/184z. No violations noted. Major areas investigated: Allegations A-306u & A-306z re control of measuring & test equipment. Drafts 2 & 3 encl.
FARREN, J. NRC - No Detailed Affiliation Given. A-306U. 84/06/26. 11pp. 32982:205-32982:215.

8510020313 Rev 1 to Allegation Investigation Rept 4-84-A-06-12 re Allegations A-117 & A-120 concerning falsified Mercury & Thompsons-Beckwith records. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-117. 84/06/14. 8pp. 32982:216-32982:223.

8510020314 Draft 5 to Allegation Investigation Rept 4-84-A-06 (114) re Allegation A-226 that traceability requirements of permanent mat welded to Class 1 & 2 piping pressure boundaries not satisfactorily resolved. No violation noted.
* NRC - No Detailed Affiliation Given. A-226. 84/06/19. 8pp. 32982:224-32982:231.

8510020316 Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184o & 184p. Draft 2 re Allegations A-226, A-306u, A-306f, A-306o & A-306p concerning safety-related sys designed as nonsafety-related.
* NRC - No Detailed Affiliation Given. A-226. 84/06/27. 1p. 32982:232-32982:232.

8510020317 Rev 1 to Allegation Investigation Repts 4-84-A-06/177, 184a, 184k, 184l & 184m of Allegations A-296, A-306u, A-306k, A-306l & A-306m re Thompsons-Beckwith failing to visually examine shop pipe welds for leaks. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-296. 84/06/26. 4pp. 32982:233-32982:236.

8510020318 Draft 7 of Allegation Investigation Rept 4-84-A-06 re Allegation A-296. Potential violation noted: lack of confirmation that shop welds inspected for leaks during hydrostatic tests per ASME Code.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-296. 84/06/19. 4pp. 32982:237-32982:240.

8510020320 Rev 2 to Allegation Investigation Rept 4-83-A-81-A7 of Allegation A-26 re nonconforming conditions improperly identified & corrected by Ebasco. No potential violations noted.
MORGAN, T. NRC - No Detailed Affiliation Given. A-26. 84/06/15. 2pp. 32982:241-32982:242.

8510020321 Allegation Investigation Rept A-83-A-88-10. Rev 2 re Allegation A-56 concerning improper maint of permanent plant items by subcontractors. Ebasco Svcs inc or uti. No potential violations found.
JOHNSON, C., FARRELL, R. NRC - No Detailed Affiliation Given. A-56. 84/06/22. 10pp. 32982:249-32982:258.

8510020323 Draft 8 of Allegation Investigation Rept 4-83-A-81(B)/2 re Allegation A-28 on use of unqualified QC inspectors to perform insp.
HARRISON, J. NRC - No Detailed Affiliation Given. A-28. 84/07/18. 6pp. 32982:243-32982:248.

8510020325 Draft 2 of Allegation Investigation Rept 4-84-A-06 re Allegations A-126 & A-291 concerning failure to maintain mat traceability on supplemental steel used w/ pipe hangers & supports. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-126. 84/06/20. 8pp. 32982:259-32982:266.

8510020326 Allegation Investigation Rept 4-84-A-06-80 re Allegation A-185 concerning existence of written procedure for joint Mercury/Ebasco review of sys turnover documentation. Adequate guidance provided.
* NRC - No Detailed Affiliation Given. A-185. 84/06/09. 3pp. 32982:267-32982:269.

8510020327 Marked-up Revs 3 & 4 to Allegation Investigation Rept 4-83-A-65/3. Allegations A-07 & A-29 re Ebasco QA reviewers grooming paperwork. One possible falsification of signature observed. Records review sys adequate.
* NRC - No Detailed Affiliation Given. A-07. 84/06/24. 4pp. 32982:270-32982:273.

8510020328 Rev 2 to Allegation Investigation Rept 4-83-A-81/2 of Allegation A-26 re falsified resumes & inadequate verification of previous experience of QC inspectors. Violation noted: unqualified inspectors used to perform insp.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-26. 84/06/11. 2pp. 32982:274-32982:275.

8510020331 Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12. Draft 4 re Allegations A-64 through 66 & 322 concerning unacceptable insp work activities per Site Ltrs F6-3724E, F6-1895E & F6-1147E.
* NRC - No Detailed Affiliation Given. A-64. 84/06/26. 4pp. 32982:276-32982:279.

8510020332 Marked-up Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4. Draft 1 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-57. 84/07/17. 3pp. 32982:280-32982:282.

8510020333 Draft 2 to Allegation Investigation Rept 4-84-A-06/39 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 re clam shell filter blanket. Violation of ANSI N45.2.6 noted.
* NRC - No Detailed Affiliation Given. A-114. 84/06/09. 3pp. 32982:283-32982:285.

8510020334 Draft 6 to Allegation Investigation Rept 4-84-A-06/23D on Allegation A-126d, A-212 & A-275 re undersized welds discovered in Mercury socket weld fittings. Allegation has no safety significance or generic implications.
* NRC - No Detailed Affiliation Given. A-126D. 84/06/20. 4pp. 32982:286-32982:289.

8510020336 Allegation Investigation Rept 4-84-A-06. Rev 1 re Allegation A-252 that Ebasco Svcs, Inc Interlof Ltr W3-QA-23661 written to cover up problems in documentary review group. No potential violations found.
* NRC - No Detailed Affiliation Given. A-252. 84/07/01. 7pp. 32982:290-32982:301.

8510020338 Allegation Investigation Rept 4-84-A-12-4. Draft 7 re Allegation A-57 concerning Mercury Level III examiners lack of site certifications & Level III personnel.
* NRC - No Detailed Affiliation Given. A-57. 84/07/17. 4pp. 32982:302-32982:305.

8510020339 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-46/2. Allegations A-02, A-206 & A-274 re improper certification of Mercury Const Co QC inspectors. Twelve certifications found questionable.
* NRC - No Detailed Affiliation Given. A-02. 84/06/13. 12pp. 32982:306-32982:318.

8510020341 Allegation Investigation Repts 4-84-A-06/7.26 & 51. Draft 7 re Allegations A-112, A-131 & A-265 concerning incomplete JA Jones Const Co concrete placement packages & uncertified inspectors.
SHEWMAKER, NRC - No Detailed Affiliation Given. A-112. 84/07/17. 3pp. 32982:319-32982:321.

8510020342 Rev 2 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-18 & A-104 concerning inadequate nonconformance control by Ebasco Svcs Intl & six nonconformance repts w/o numbers.
* NRC - No Detailed Affiliation Given. A-18. 84/07/10. 2pp. 32982:322-32982:326.

8510020343 Marked-up Rev 0 to Allegation Investigation Rept 4-83-A-74/7. Allegation A-19 re record deficiencies for 186 separate Fishbach & Moore documents.
* NRC - No Detailed Affiliation Given. A-19. 84/06/19. 4pp. 32982:327-32982:330.

8510020345 Rev 4 to Allegation Investigation Repts 4-84-A-06/186 & 4-84-A-06/184. No violations noted. Major areas investigated: Allegations A-308, A-306 & A-306r re inadequate piping sys documentation. Revs 2 & 3 encl.
WENCZELV, NRC - No Detailed Affiliation Given. A-308. 84/07/10. 20pp. 32982-331-32982-350.

8510020346 Rev 0 to Allegation Investigation Rept 4-83-A-81/A1, Allegations A-20, A-21 & A-22 re recordkeeping problems including improper drawing changes, incorrect identification of heat codes & welds & improper dates for welds.
* NRC - No Detailed Affiliation Given. A-20. 84/06/27. 15pp. 32983-001-32983-015.

8510020347 Marked-up Allegation Investigation Repts 4-84-A-06/21 & 172. Rev 0 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain m/r traceability on supplemental steel used w/ pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-126. 84/06/27. 4pp. 32982-351-32982-354.

8510020348 Allegation Investigation Repts 4-83-A-88/Ac & Ad, Rev 3 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o knowledge of authorized nuclear inspector. No potential violations found.
FARREN, J. NRC - No Detailed Affiliation Given. A-81. 84/08/24. 5pp. 32982-355-32982-360.

8510020350 Allegation Investigation Rept 4-84-A-12-4, Draft 3 re Allegation A-57 concerning uncertified Mercury Level III examiners.
* NRC - No Detailed Affiliation Given. A-57. 84/07/18. 3pp. 32983-016-32983-018.

8510020353 Marked-up Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167, Rev 0 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning Mercury Const Co m/r traceability problems.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-100. 84/06/13. 4pp. 32983-019-32983-022.

8510020355 Rev 0 to Allegation Investigation Rept 4-84-A-06-6 re Allegation A-111 concerning acceptance criteria for concrete work. No potential violations noted.
* NRC - No Detailed Affiliation Given. A-111. 84/06/06. 4pp. 32983-023-32983-126.

8510020358 Allegation Investigation Rept 4-84-A-12-4, Draft 9 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners. Marked-up Draft 9 encl.
* NRC - No Detailed Affiliation Given. A-57. 84/07/18. 3pp. 32982-361-32982-362.

8510020357 Draft 4 to Allegation Investigation Repts 4-84-A-06/177, 184a, 184c, 184d & 184m for Allegations A-296, A-306a, A-306b, A-306c & A-306m re Tompkins-Beckwith failing to visually examine shop pipe welds for leaks during hydrostatic tests.
* NRC - No Detailed Affiliation Given. A-296. 84/07/10. 4pp. 32983-027-32983-030.

8510020359 Allegation Investigation Repts 4-83-A-88/16-18 & A-84-A-12/12, Rev 3 re Allegations A-64-A-06 & A-322 concerning Ethosco Svc, Inc site firs which imply Mercury insp activities unacceptable. Marked-up Rev 3 encl.
* NRC - No Detailed Affiliation Given. A-64. 84/06/26. 5pp. 32983-031-32983-035.

8510020360 Marked-up Draft 6 to Allegation Investigation Rept 4-83-A-65/5, Allegation A-09 re QA personnel lay offs & non-QA engineer replacements. Investigation of Ebasco indoctrination & training program in progress.
* NRC - No Detailed Affiliation Given. A-09. 84/06/09. 1pp. 32983-038-32983-038.

8510020361 Marked-up Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4, Draft 2 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel.
WESTBURG, R. NRC - No Detailed Affiliation Given. A-57. 84/07/18. 4pp. 32983-037-32983-040.

8510020363 Rev 0 to Allegation Investigation Rept 4-84-A-05-9 re Allegations A-114, A-144 & A-154 concerning unsatisfactory disposition of Nonconformance Rept W3-5997 on claim shell liner blank. Violation of ANSI N45.2.5 noted.
* NRC - No Detailed Affiliation Given. A-114. 84/06/13. 3pp. 32983-041-32983-043.

8510020364 Rev 0 to Allegation Investigation Rept 4-84-A-06 for Allegations A-296, A-306a, A-306b, A-306c & A-306m re Tompkins-Beckwith failing to visually examine shop pipe welds for leaks. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-296. 84/06/25. 4pp. 32983-044-32983-047.

8510020366 Allegation Investigation Repts 4-83-A-88/9 & 4-84-A-12/4, Draft 3 re Allegations A-57 & A-314 concerning uncertified Mercury Const Co Level III insp personnel.
WESTBURG, R. NRC - No Detailed Affiliation Given. A-57. 84/07/19. 3pp. 32983-048-32983-050.

8510020367 Allegation Investigation Rept 4-84-A-12-4, Draft 10 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners. Marked-up Draft 10 encl.
HARRISON, J. NRC - No Detailed Affiliation Given. A-57. 84/07/18. 4pp. 32983-051-32983-054.

8510020368 Resume of RA Feil.
FEIL, R.A. Affiliation Not Assigned. 85/10/01. 6pp. 32983-055-32983-060.

8510020369 Draft 3 to Allegation Investigation Repts 4-84-A-06/23d, 100 & 157 on Allegations A-128d, A-212 & A-275 re undersized welds in Mercury work.
* NRC - No Detailed Affiliation Given. A-128d. 84/06/19. 6pp. 32983-061-32983-066.

8510020371 Resume of AN Fasano.
FASANO, A.N. TMI Program Office. 85/09/27. 12pp. 32983-067-32983-075.

8510020373 Draft 2 to Allegation Investigation Repts 4-84-A-06-41, 50, 51, 25, 43 & 52 on Allegations A-146, A-157, A-158, A-110, A-115, A-130 & A-148 re deficiencies in cadweld splicing records improperly dispositioned. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-146. 84/06/11. 20pp. 32983-079-32983-098.

8510020375 Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157, Rev 2 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
* NRC - No Detailed Affiliation Given. A-128d. 84/08/29. 2pp. 32983-099-32983-100.

8510020377 Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157, Rev 1 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-128d. 84/07/10. 4pp. 32983-101-32983-104.

8510020381 Rev 0 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re improperly dispositioned cadweld splicing records. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-146. 84/06/19. 5pp. 32983-105-32983-118.

8510020384 Draft 3 of Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re improperly dispositioned cadweld records. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-146. 84/06/15. 8pp. 32983-119-32983-126.

8510020386 Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157, Rev 1 re Allegations A-128d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
* NRC - No Detailed Affiliation Given. A-128d. 84/07/10. 3pp. 32983-127-32983-129.

8510020390 Draft 2 to Allegation Investigation Rept 4-84-A-06-42 of Allegation A-1 cadweld test repts created to replace lost records w/ forged signatures or initials. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-147. 84/05/30. 4pp. 32983-130-32983-133.

8510020391 Draft 3 to Allegation Investigation Rept 4-84-A-06-42 of Allegation A-147 re cadweld test repts created to replace lost records w/ forged signatures or initials. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-147. 84/06/14. 8pp. 32983-134-32983-141.

8510020392 Marked-up Allegation Investigation Rept 4-84-A-06, Rev 1 re Allegation A-252 concerning Ebasco Svcs, Inc 8303c, 4 Ltr W3-QA-23661 as example of correspondence to cover up problems discovered in documentary review group.
* NRC - No Detailed Affiliation Given. A-252. 84/07/01. 3pp. 32983-142-32983-144.

8510020393 Resume of CC Wilson.
WILSON, C.C. Louisiana. State of. 85/10/01. 1p. 32983-145-32983-145.

8510020394 Resume of W.G. Hubacek.
HUBACEK, W.G. Affiliation Not Assigned. 85/10/01. 3pp. 32983-146-32983-148.

8510020396 Resume of JD Firestone.
FIRESTONE, J.D. Martin Marietta Corp. 85/10/01. 3pp. 32983-149-32983-151.

8510020398 Allegation Investigation Repts 4-84-A-06-21 & 172, Rev 0 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain m/r traceability on supplemental steel used w/ pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-126. 84/06/27. 5pp. 32983-152-32983-156.

8510020400 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65/6, Allegation A-09 re contracted QA personnel layoffs & Ebasco engineers moving into QA positions. Reviewers laid off for financial reasons.
* NRC - No Detailed Affiliation Given. A-09. 84/08/24. 2pp. 32983-157-32983-158.

8510020401 Marked-up Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 5-18 & 4-84-A-31, Rev 0 re listed allegations concerning Mercury & Ebasco Svcs, Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. A-232. 84/06/27. 26pp. 32983-159-32983-184.

8510020413 Draft 2 of Allegation Investigation Rept 4-83-A-81/A6 of Allegation A-25 re CBAI QA record deficiencies on containment penetration welds. No potential violations noted.
TAPIA, J.J. NRC - No Detailed Affiliation Given. A-25. 84/06/19. 3pp. 32983-185-32983-187.

8510020414 Rev 0 to Allegation Investigation Rept 4-83-A-81/A6 of Allegation A-25 re CBAI QA record deficiencies on containment penetration welds. No potential violations noted.
TAPIA, J.J. NRC - No Detailed Affiliation Given. A-25. 84/07/18. 6p. 32983-188-32983-193.

8510020415 Rev 1 to Allegation Investigation Rept 4-83-A-81/A7 of Allegation A-26 re nonconforming conditions improperly identified & corrected by Ebasco. No potential violations noted.
MORGAN, T. NRC - No Detailed Affiliation Given. A-26. 84/06/07. 2pp. 32983-194-32983-195.

8510020416 Allegation Investigation Repts 4-83-A-88/16-18 & 4-84-A-12/12, Rev 4 re Allegations A-64 through A-66 & A-322 concerning Ebasco site firs which imply that Mercury insp activities unacceptable.
MORGAN, T. NRC - No Detailed Affiliation Given. A-64. 84/08/24. 3pp. 32983-196-32983-198.

8510020417 Allegation Investigation Rept 4-83-A-88-13 re Allegation A-61 concerning NRC review of Ebasco Svcs, Inc Nonconformance Rept W3-4504. No potential violations found. Marked-up Rev 0 encl.
* NRC - No Detailed Affiliation Given. A-61. 84/06/27. 6pp. 32983-199-32983-204.

8510020418 Allegation Investigation Rept 4-83-A-88-4A, Rev 2 re Allegation A-94 through A-99 concerning problems w/ stainless steel piping & tubing noted in unidentified 830909 nonconformance rept.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-94. 84/06/26. 4pp. 32983-205-32983-208.

8510020419 Allegation Investigation Rept 4-83-A-88/13a, Draft 2 re Allegation A-61a concerning NRC review of Ebasco Svcs, Inc Nonconformance Rept W3-4504.
SHAO, NRC - No Detailed Affiliation Given. A-61a. 84/07/10. 3pp. 32983-209-32983-211.

8510020420 Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-65, Allegation A-06 re Ebasco QA reviewers not completing on-the-job training requirements. Ebasco QA training program adequate.
* NRC - No Detailed Affiliation Given. A-06. 84/06/24. 2pp. 32983-212-32983-213.

8510020421 Allegation Investigation Rept 4-83-A-88/13a, Rev 1 re Allegation A-61a concerning NRC review of Ebasco Svcs, Inc Nonconformance Rept W3-4504 regarding repair of threads. No potential violations found.
* NRC - No Detailed Affiliation Given. A-61a. 84/07/10. 8pp. 32983-227-32983-234.

308 NONDOCKETED ITEMS

- 8510020423** Allegation Investigation Rept 4-83-A-86-11, Rev 2 re Allegation A-59 concerning Ebasco Svcs Inc poor control over nonconforming conditions. No potential violations found.
* NRC - No Detailed Affiliation Given. A-59. 84/06/22. 8pp. 32983:235-32983:240.
- 8510020424** Final Rev 2 to Allegation Investigation Repts 4-83-A-86-16-18 & 4-84-A-12/12 re Allegations A-64-A-66 & A-322 concerning Ebasco Svcs, Inc site firs which imply that Mercury insp activities unacceptable.
MORGAN, T. NRC - No Detailed Affiliation Given. A-64. 84/06/15. 3pp. 32983:241-32983:243.
- 8510020425** Allegation Investigation Repts 4-84-A-06/120, 123, 124, 128, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 5-18 & 4-84-A-31, Draft 4 re listed allegations concerning Mercury & Ebasco Svcs Inc improperly identifying nonconforming components.
* NRC - No Detailed Affiliation Given. A-232. 84/06/21. 13pp. 32983:214-32983:226.
- 8510020426** Marked-up Draft 7 to Allegation Investigation Rept 4-83-A-65/2, Allegation A-06 re QA reviewers not completing on-the-job training requirements. Investigation in progress.
* NRC - No Detailed Affiliation Given. A-06. 84/07/17. 2pp. 32983:244-32983:245.
- 8510020427** Allegation Investigation Rept 4-83-A-58-4A, Rev 2 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance rept addressing various problems w/ stainless steel piping & tubing.
* NRC - No Detailed Affiliation Given. A-94. 84/06/26. 6pp. 32983:246-32983:251.
- 8510020428** Allegation Investigation Rept 4-84-A-12-4, Draft 11 re Allegations A-57 & A-314 concerning uncertified Mercury Level III examiners.
HARRISON, J. NRC - No Detailed Affiliation Given. A-57. 84/07/19. 2pp. 32983:252-32983:253.
- 8510020429** Allegation Investigation Rept 4-84-A-06-128, Rev 3 re Allegation A-242 concerning hydrostatic tests performed w/o use of highpoint vents. Violation found: hydrostatic tests not performed per 10CFR50, App B.
* NRC - No Detailed Affiliation Given. A-242. 84/07/16. 9pp. 32983:254-32983:262.
- 8510020430** Allegation Investigation Rept 4-84-A-06-128, Rev 2 re Allegation A-242 concerning hydrostatic tests performed w/o use of highpoint vents. Violations found: hydrostatic tests not performed per 10CFR50, App B.
* NRC - No Detailed Affiliation Given. A-242. 84/07/16. 4pp. 32983:263-32983:266.
- 8510020431** Allegation Investigation Rept 4-83-A-86/3A4, Draft 8 re Allegation A-92 concerning inadequate indoctrination & training of QA reviewers.
HARRISON, J. NRC - No Detailed Affiliation Given. A-92. 84/07/18. 2pp. 32983:267-32983:268.
- 8510020432** Allegation Investigation Rept 4-83-A-88 & 4-84-A-12, Rev 1 re Allegations A-88, A-89, A-90, A-91 & A-315 concerning hydrostatic testing for instrumentation & control tubing sys installed by Mercury Const Co.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-88. 84/07/10. 4pp. 32983:269-32983:272.
- 8510020434** Allegation Investigation Rept 4-83-A-88/3A4, Draft 7 re Allegation A-92 concerning inadequate indoctrination & training of QA reviewers.
HARRISON, J. NRC - No Detailed Affiliation Given. A-92. 84/07/17. 4pp. 32983:273-32983:276.
- 8510020436** Rev 2 to Allegation Investigation Rept 4-84-A-06-184L. No violations noted. Major areas inspected. Allegation A-306 re noncertified document reviewers making changes to QA documentation. Revs 0 & 1 & questions re items 14 & 15 encl.
ROSS, D. NRC - No Detailed Affiliation Given. A-306T. 84/07/12. 18pp. 32983:277-32983:294.
- 8510020439** Rev 0 to Allegation Investigation Rept 4-84-A-06-184e. No violations noted. Major areas inspected. Allegation A-306 re deficiencies found during review of American Bridge documentation. Drafts 1 & 2 encl.
SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-306E. 84/07/19. 32pp. 32983:295-32983:326.
- 8510020442** Rev 3 to Allegation Investigation Rept 4-84-A-06/184c. No violations noted. Major areas inspected. Allegation A-306 re lack of Ebasco documents for traceability of bolts 1-inch or less. Revs 1 & 2 encl.
SUMMERS, D. NRC - No Detailed Affiliation Given. A-306C. 84/07/11. 12pp. 32983:327-32983:338.
- 8510020445** Rev 4 to Allegation Investigation Rept 4-84-A-06-31. No violations noted. Major areas inspected. Allegation A-136 re difficulty for Ebasco QA personnel to initiate formal nonconformance rept. Draft & Revs 0, 1, 2 & 3 encl.
* NRC - No Detailed Affiliation Given. A-136. 84/08/09. 36pp. 32983:339-32984:014.
- 8510020446** Rev 1 to Allegation Investigation Rept 4-84-A-06/36. No violations noted. Major areas investigated. Allegation A-141 re consideration of Ebasco discrepancy notices in QA review. Rev 0 dtd 840622 & Draft 4 dtd 840621 encl.
* NRC - No Detailed Affiliation Given. A-141. 84/07/01. 52pp. 32984:015-32984:066.
- 8510020449** Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157, Rev 0 re Allegations A-128d, A-212 & A-275 concerning undersized welds in Mercury Const Co work.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-128D. 84/06/27. 4pp. 32984:067-32984:070.
- 8510020451** Draft 2 to Allegation Investigation Rept 4-84-A-06 re Allegation A-170 concerning improperly dispositioned Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. A-170. 84/06/21. 8pp. 32984:071-32984:078.
- 8510020454** Allegation Investigation Repts 4-84-A-06-139, 140a & 141, Rev 1 re Allegations A-253, A-254 & A-257 concerning qualified vendor records reviewers & bad vendor records, including Bergen-Paterson Pipe Support Co records.
NALEZNY, C.L. NRC - No Detailed Affiliation Given. A-253. 84/06/26. 4pp. 32984:079-32984:082.
- 8510020456** Rev 0 to Allegation Investigation Rept 4-84-A-06-34 & 4-84-A-06-35 on Allegations A-139 & A-140 re poor concrete placement practices during const of basement in violation of ACI stds leading to cracks found in 1983.
* NRC - No Detailed Affiliation Given. A-139. 84/06/07. 19pp. 32984:083-32984:102.
- 8510020457** Allegation Investigation Rept 4-83-A-88-4A, Rev 3 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance rept addressing various problems w/ stainless steel piping & tubing.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-94. 84/07/19. 4pp. 32984:103-32984:109.
- 8510020458** Rev 1 to Allegation Investigation Repts 4-84-A-06-34 & 4-84-A-06-35 on Allegations A-139 & A-140 re instances of poor concrete placement practices during const of basement in violation of spec & ACI stds.
* NRC - No Detailed Affiliation Given. A-139. 84/06/18. 14pp. 32984:110-32984:123.
- 8510020459** Allegation Investigation Rept 4-84-A-06/155, Rev 1 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted.
MARINI, W.S. NRC - No Detailed Affiliation Given. A-273. 84/07/01. 5pp. 32984:124-32984:125.
- 8510020460** Draft 2 to Allegation Investigation Rept 4-84-A-06-36 on Allegation A-141 re whether discrepancy notices written during review of 70 concrete placement packages considered in quality review. No violation noted.
* NRC - No Detailed Affiliation Given. A-141. 84/06/07. 20pp. 32984:129-32984:150.
- 8510020461** Allegation Investigation Rept 4-84-A-06/155, Draft 3 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted. Marked-up draft encl.
MARINI, W.S. NRC - No Detailed Affiliation Given. A-273. 84/06/27. 6pp. 32984:151-32984:156.
- 8510020463** Draft 1 to Allegation Investigation Rept 4-84-A-06-178b of Allegation A-298 re QC not checking structural items for defects.
* NRC - No Detailed Affiliation Given. A-298. 84/07/16. 4pp. 32984:157-32984:160.
- 8510020464** Allegation Investigation Rept 4-84-A-06-140c, Rev 3 re Allegation A-256 concerning Chicago Bridge & Iron Co problems w/ protective coating & matt traceability for inside containment vessel.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. A-256. 84/06/25. 13pp. 32984:161-32984:173.
- 8510020465** Allegation Investigation Rept 4-84-A-06/158, Rev 4 re Allegation A-276 concerning Mercury Const Co resume fraud. Violation of 10CFR50, App B & ANSI N-5.2.6 noted. Staff reviewing NRC Ofc of Investigation rept.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-276. 84/08/23. 3pp. 32984:174-32984:176.
- 8510020466** Rev 1 to Allegation Investigation Repts 4-84-A-06/180, 185, 181b & 184s of Allegations A-302, A-307, A-303b, A-306s & A-306x re lower tier corrective action documents not upgraded to nonconformance repts.
* NRC - No Detailed Affiliation Given. A-302. 84/07/10. 27pp. 32984:177-32984:203.
- 8510020467** Marked-up Allegation Investigation Rept 4-84-A-06-140c, Rev 2 re Allegation A-256 concerning Chicago Bridge & Iron Co problems w/ protective coatings & matt traceability for inside containment vessel.
JOHNSON, C.E. NRC - No Detailed Affiliation Given. A-256. 84/06/19. 5pp. 32984:204-32984:208.
- 8510020468** Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re forged signatures & initials in JA Jones daily caldweld insp repts.
* NRC - No Detailed Affiliation Given. A-156. 84/06/14. 4pp. 32984:209-32984:212.
- 8510020469** Allegation Investigation Rept 4-84-A-06-128, Rev 5 re Allegation A-242 concerning hydrostatic tests performed w/o use of highpoint vents. Addl concerns re adequacy of instrument tubing installations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. A-242. 84/08/30. 9pp. 32984:213-32984:221.
- 8510020470** Marked-up Allegation Investigation Repts 4-83-A-81/A1, A2 & A3, Rev 1 re Allegations A-20, A-21 & A-22 concerning recordkeeping problems for Penetrations 38 & 65. No potential violations found.
* NRC - No Detailed Affiliation Given. A-20. 84/07/12. 10pp. 32984:222-32984:231.
- 8510020471** Allegation Investigation Rept 4-84-A-06/152, Draft 1 re Allegation A-270 concerning Ebasco Svcs, Inc QC rept on Block 2 common foundation basement.
SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-270. 84/07/17. 3pp. 32984:232-32984:234.
- 8510020473** Allegation investigation rept, Rev 2 re Allegation A-156 concerning altered data entries made on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. A-265. 84/07/13. 3pp. 32984:235-32984:237.
- 8510020474** Rev 0 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re forged signatures & initials in JA Jones daily caldweld insp repts.
* NRC - No Detailed Affiliation Given. A-156. 84/06/07. 10pp. 32984:238-32984:249.
- 8510020475** Rev 2 to Allegation Investigation Rept 4-84-A-06-40 re Allegation A-145. Violations noted: incorrect test locations on records cast doubt on validity of backfill insp. Draft 1 dtd 840717 & Draft 2 dtd 840718 encl.
DEVERS, J. NRC - No Detailed Affiliation Given. A-145. 84/06/26. 12pp. 32984:250-32984:261.
- 8510020476** Rev 2 to Allegation Investigation Rept 4-84-A-06-66 of Allegation A-171 re quality of Ebasco caldweld splicing. No violations noted.
* NRC - No Detailed Affiliation Given. A-171. 84/06/22. 13pp. 32984:262-32984:275.
- 8510020477** Marked-up Allegation Investigation Rept 4-84-A-06-65, Rev 0 re Allegation A-170 concerning improperly disposed Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. A-170. 84/06/22. 16pp. 32984:276-32984:292.

8510020478 Allegation Investigation Rept 4-84-A-06/147, Rev 3 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. A-265. 84/07/13. 3pp. 32984-293-32984-295.

8510020480 Allegation Investigation Repts 4-84-A-06/76 & 4-84-A-06/165, Draft 5 re Allegations A-283 & A-181 concerning process of writing nonconformance repts.
HARRISON, J. NRC - No Detailed Affiliation Given. A-283. 84/07/17. 3pp. 32984-296-32984-298.

8510020481 Allegation Investigation Rept 4-83-A-88-4A, Rev 4 re Allegations A-94 through A-99 concerning 830909 unidentified nonconformance repts addressing various problems w/ stainless steel piping & tubing.
* NRC - No Detailed Affiliation Given. A-94. 84/08/23. 3pp. 32984-299-32984-301.

8510020482 Rev 4 to Allegation Investigation Repts 4-84-A-06-34 & 4-84-A-06-35. No violations noted. Major areas investigated: Allegations A-139 & A-140 re poor concrete placement practices during const. Revs 2 & 3 & Drafts 1, 2 & 3 encl.
* NRC - No Detailed Affiliation Given. A-139. 84/08/29. 54pp. 32984-302-32984-355.

8510020483 Marked-up Allegation Investigation Rept 4-84-A-06-146 re Allegation A-264-1 concerning inability to provide accurate mat'l traceability on instrument tube track. No potential violation found.
* NRC - No Detailed Affiliation Given. A-264-1. 84/07/02. 1p. 32984-356-32984-357.

8510020485 Allegation Investigation Rept 4-84-A-06/147, Rev 2 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
FORD, D., MARINI, W. NRC - No Detailed Affiliation Given. A-265. 84/07/13. 3pp. 32984-358-32984-360.

8510020486 Rev 1 to Allegation Investigation Rept 4-84-A-06/181 re Allegation A-303a concerning Tompkins-Beckwith not providing documentation necessary to verify that welding backing rings & weld base mat'l compatible.
* NRC - No Detailed Affiliation Given. A-303a. 84/07/01. 4pp. 32984-361-32985-003.

8510020487 Forwards ext interview notes from Insp Rept 50-382/84-34 on 840720.
MORGAN, W. M., Louisiana Power & Light Co. W3K84-1755. 84/08/01. COLLINS, J. T., CROSSMAN, W. A., PERANICH, M. NRC - No Detailed Affiliation Given. 3pp. 32985-004-32985-006.

8510020492 Allegation Investigation Rept 4-84-A-06-65, Rev 1 re Allegation A-170 concerning improperly disposed Ebasco Svcs, Inc discrepancy notice for missing reinforcing steel in fuel handling bldg. No potential violations found.
KIM, S. B. NRC - No Detailed Affiliation Given. A-170. 84/07/10. 7pp. 32985-007-32985-013.

8510020494 Marked-up Drafts 6 & 7 to Allegation Investigation Rept 4-83-A-48/2, Allegations A-02, A-208 & A-274 re improper certification of inspectors. Investigation of Mercury certification program underway.
* NRC - No Detailed Affiliation Given. A-02. 84/07/17. 5pp. 32985-014-32985-016.

8510020495 Allegation Investigation Rept 4-84-A-06/158, Rev 3 re Allegation A-276 concerning Mercury Const Co resume fraud. Potential violations of 10CFR50, App B & ANSI N45.2.6 noted. Marked-up Rev 3 encl.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-276. 84/06/28. 5pp. 32985-019-32985-023.

8510020499 Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06/76, Rev 3 re Allegations A-283 & A-181 concerning Ebasco Svcs, Inc inadequate nonconformance repts. No potential violations noted.
WHITTEMORE, J. NRC - No Detailed Affiliation Given. A-283. 84/06/23. 4pp. 32985-024-32985-027.

8510020500 Marked-up Allegation Investigation Rept 4-84-A-06/155, Rev 0 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance repts on seismic qualification of hanger supports. No potential violations noted.
MARINI, W. S. NRC - No Detailed Affiliation Given. A-273. 84/06/28. 6pp. 32985-028-32985-033.

8510020503 Allegation Investigation Rept 4-84-A-06/152, Rev 2 re Allegation A-270 concerning Ebasco Svcs, Inc QC repts on Block 2 common foundation base mat'l. No potential violations noted.
CHOKSHI, N. C. NRC - No Detailed Affiliation Given. A-270. 84/06/25. 3pp. 32985-034-32985-036.

8510020513 Rev 0 to Allegation Investigation Rept 4-84-A-06-9 re Allegations A-114, A-144 & A-154 concerning disposition of N nonconformance Rept W3-5997 concerning clam shell filter blanket under plant. Potential violation noted.
* NRC - No Detailed Affiliation Given. A-114. 84/06/13. 3pp. 32985-037-32985-039.

8510020523 Rev 0 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/ protective coatings & mat'l traceability for inside of containment. Violation noted: failure to establish QA program.
* NRC - No Detailed Affiliation Given. A-256. 84/06/06. 13pp. 32985-040-32985-052.

8510030008 Allegation Investigation Rept 4-84-A-06/158, Rev 2 re Allegation A-276 concerning Mercury Const Co resume fraud. Potential violations of 10CFR50, App B & ANSI N45.2.6 noted.
WESTBERG, R. NRC - No Detailed Affiliation Given. A-276. 84/06/19. 3pp. 32985-063-32985-065.

8510030022 Rev 2 to Allegation Investigation Rept 4-83-A-81-84 re Allegation A-30 concerning as-built drawings of main steamline restraint framing not reflecting actual conditions in field.
* NRC - No Detailed Affiliation Given. A-30. 84/06/19. 6pp. 32986-112-32986-124.

8510030029 Resume of MP Mills.
MILLS, M. P. Affiliation Not Assigned. 85/10/01. 3pp. 32985-066-32985-069.

8510030032 Forwards application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Fee paid.
KEISER, H. W., Pennsylvania Power & Light Co. GL-81-07. 85/09/30. BUTLER, W. R. Licensing Branch 2. 2pp. 32842-299-32842-271.

-8510030058 Application for Amend 24 to License NPF-22, deleting License Condition 2.C.(14) re implementation of mods to satisfy NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants."
KEISER, H. W., Pennsylvania Power & Light Co. 85/09/30. 1p. 32842-271-32842-271.

8510030036 Resume of KM Vadiamani.
VADLAMANI, K. M. Volt Technical Services. 85/10/01. 12pp. 32985-070-32985-081.

8510030042 Resume of WS Schum.
SCHUM, W. S. Region 4, Office of Director. 85/10/01. 4pp. 32985-082-32985-085.

8510030044 Forwards Rev 0 to "SPDS SAR for Georgia Power Co. Alvin W Vogtle Nuclear Power Plant." Rept provides SPDS implementation plan & SAR per requirements of Suppl 1 to NUREG-0737.
BAILEY, J. A., Georgia Power Co. BAILEY, J. A., Southern Co. Services, Inc. GN-709. 85/09/27. ADENSAME, E. G. Licensing Branch 4. 3pp. 32843-079-32843-111.

8510030050 Marked-up Allegation Investigation Repts 4-83-A-88/Ac & Ad, Rev 1 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o authorized nuclear inspector approval.
FARREN, J. NRC - No Detailed Affiliation Given. A-81. 84/06/13. 3pp. 32985-086-32985-088.

8510030060 Allegation Investigation Repts 4-83-A-88/Ac & Ad, Rev 2 re Allegations A-81 & A-82 concerning changes made to N-5 documentation packages for instrument lines w/o knowledge of authorized nuclear inspector. No potential violations found.
FARREN, J. NRC - No Detailed Affiliation Given. A-81. 84/06/22. 7pp. 32985-089-32985-095.

8510030069 Allegation Investigation Rept 4-84-A-06/147, Rev 1 re Allegation A-265 concerning altered data entries on instrument tubing support documentation to reflect as-built condition in field.
* NRC - No Detailed Affiliation Given. A-265. 84/06/20. 3pp. 32985-096-32985-098.

8510030078 Draft 2 of Allegation Investigation Rept 4-83-A-81/48 re Allegation A-23B concerning piping installation procedures of Tompkins-Beckwith not assuring supports & hangers maintained in design-verified condition.
SHAO, L. NRC - No Detailed Affiliation Given. A-23B. 84/07/18. 4pp. 32985-099-32985-102.

8510030080 Forwards responses to unresolved Matis Engineering Branch issues re SER (NUREG-0896) Sections 4.5.1, 4.5.2.5.2.3 & 6.1.1. Nine issues require NRC evaluation & action. Status list of active branch review items also encl.
DEVINCENTIS, J. Public Service Co. of New Hampshire. SBN-876. 85/09/30. KNIGHTON, G. W. Licensing Branch 3. 7pp. 32842-250-32842-256.

8510030083 Forwards SER supporting 830807 repts, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item I.A.2.1. Rev commitment requested within 45 days.
ZWOLINSKI, J. A., Operating Reactors Branch 5. LSOS-85-10-003. 85/10/01. FARRAR, D. L. Commonwealth Edison Co. 9pp. 32842-257-32842-265.

8510030098 Draft 3 of Allegation Investigation Rept 4-83-A-81-A4c re Allegation A-23C concerning Tompkins-Beckwith welding procedures & techniques used in ASME Code Class 1-3 piping sys inadequately installed. No potential violations noted.
HUBBARD, R. W. NRC - No Detailed Affiliation Given. A-23C. 84/06/27. 5pp. 32985-103-32985-107.

8510030102 Rev 2 to Allegation Investigation Rept 4-83-A-81-A4a re Allegation A-23A concerning problems involving Fischbach & Moore installation, removal & rework of conduit fire seals for electrical penetrations. No potential violations noted.
THATCHER, D. NRC - No Detailed Affiliation Given. A-23A. 84/07/12. 6pp. 32985-108-32985-113.

8510030104 Forwards Rev 1 to License Change Application 117, requesting amend to License NPF-1, modifying Tech Specs to revise reactor trip sys & ESFAS instrumentation requirements. Certificate of SVC encl.
WITHERS, B. D., Portland General Electric Co. 85/09/23. BUTCHER, E. J. Operating Reactors Branch 3. 2pp. 32843-012-32843-070.

-8510030112 Rev 1 to License Change Application 117, modifying Tech Specs to rectify inconsistencies w/ installed instrumentation not in agreement w/ Rev 4 to NUREG-0452 & to remove unnecessary numerals from spec numbers.
WITHERS, B. D., Portland General Electric Co. 85/09/23. 16pp. 32843-014-32843-029.

-8510030117 Proposed Tech Specs, rectifying inconsistencies w/ installed instrumentation not in agreement w/ Rev 4 to NUREG-0452 & removing unnecessary numerals from spec numbers.
* Portland General Electric Co. 85/09/23. 41pp. 32843-030-32843-070.

8510030108 Rev 1 to Allegation Investigation Rept 4-83-A-81 (A4b) re Allegation A-23B concerning piping installation procedures of Tompkins-Beckwith not assuring that supports & hangers maintained in design-verified condition.
LENARDSON, J. D. NRC - No Detailed Affiliation Given. A-23B. 84/07/16. 14pp. 32985-114-32985-127.

8510030126 NUREG-0750 V21 102 INDEXES TO NUCLEAR REGULATORY COMMISSION ISSUANCES, January-June 1985.
* Division of Technical Information & Document Control. 85/09/30. 108pp. 32985-009-32985-114.

8510030127 Urges NRC to reject until 840628 proposed plan to correct problems found by NRC Special Review Team. Independent third party to conduct review of problems outlined in NRC 840613 tr & development of plant to resolve issues requested.
BERNABEIL, J. Government Accountability Project. 84/07/25. EISENHUT, D. G. Division of Licensing. 12pp. 32985-128-32986-015.

8510030131 NUREG/CR-4396 COST ANALYSIS OF REVISIONS TO 10 CFR PART 50, APPENDIX J, LEAK TESTS FOR PRIMARY AND SECONDARY CONTAINMENTS OF LIGHT-WATER-COOLED NUCLEAR POWER PLANTS.
SCIACCA, F., NELSON, W., SIMPKINS, B. Science & Engineering Associates, Inc. FIN B-88-38. 85/09/30. Office of Resource Management, Director. 92pp. 32849-332-32850-063.

310 NONDOCKETED ITEMS

- 8510030136** Allegation Investigation Rept 4-84-A-06-66, Rev 3 re Allegation A-171 concerning Ebasco Svcs, Inc practice of using oversize cadweld sleeves to make cadweld splices.
* NRC - No Detailed Affiliation Given. A-171. 84/06/29. 4pp. 32986:016-32986:019.
- 8510030141** Rev 0 to Allegation Investigation Repts 4-84-A-06/180, 185, 184a & 184x for Allegations A-302, A-307, A-303b, A-306a & A-306x re lower tier corrective action document not upgraded to nonconformance repts.
* NRC - No Detailed Affiliation Given. A-302. 84/06/28. 14pp. 32986:020-32986:053.
- 8510030147** Allegation Investigation Rept 4-84-A-06/155, Rev 1 re Allegation A-273 concerning Ebasco Svcs, Inc inadequate nonconformance rept on seismic qualification of hanger supports. No potential violations noted.
MARINI, W.S. NRC - No Detailed Affiliation Given. A-273. 84/07/01. 3pp. 32986:054-32986:056.
- 8510030153** Forwards Waterford 3 Task Force Inquiry Team insp rept. Section VII of rept documents insp conducted by W. Bellu. Comments W. Bellu re outstanding effort.
PERANICH, M.W. Waterford 3 Task Force. PERANICH, M.W. Reactor Construction Branch. 84/08/13. ANDRUM, G.T. QA Branch. 1p. 32986:057-32986:057.
- 8510030154** Marked-up Allegation Investigation Rept 4-84-A-06-152, Rev 1 re Allegation A-270 concerning Ebasco Svcs, Inc QC rept on Block 2 common foundation base mat. No potential violations noted.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. A-270. 84/06/19. 2pp. 32986:058-32986:059.
- 8510030159** Draft 7 to Allegation Investigation Rept 4-83-A-65/5, Allegation A-09 re replacement of laid-off QA personnel w/ non-QA engineers.
* NRC - No Detailed Affiliation Given. A-09. 84/07/17. 2pp. 32986:149-32986:150.
- 8510030180** Allegation Investigation Rept 4-84-A-06-126, Rev 4 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents. Add concerns re adequacy of instrument tubing installations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. A-242. 84/08/15. 8pp. 32986:063-32986:070.
- 8510030181** Allegation Investigation Repts 4-83-A-88 & 4-84-A-12, Rev 0 re Allegations A-88 through A-91 & A-315 concerning problems w/hydrostatic testing required by ASME Code for instrumentation & control tubing sys.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-88. 84/06/27. 7pp. 32986:071-32986:077.
- 8510030183** Comments R. Mulkien participation in Waterford 3 Task Force Inquiry Team from 840402-0702. Contribution as team leader for wk of 840520 & preparation of final rept appreciated.
PERANICH, M.W. Waterford 3 Task Force. 84/7/3/08. COLLINS, J. Region 4, Office of Director. 1p. 32986:078-32986:078.
- 8510030185** Rev 1 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59 re Allegations A-18 & A-164 concerning inadequate nonconformance control by Ebasco Svcs, Inc where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. A-18. 84/06/26. 3pp. 32986:151-32986:153.
- 8510030170** Allegation Investigation Rept 4-84-A-06-126, Rev 2 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents & adequacy of instrument tubing installations. Potential violations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. A-242. 84/07/16. 5pp. 32986:079-32986:083.
- 8510030174** Rev 1 to Allegation Investigation Rept 4-83-A-74-1 re Allegations A-13, A-14, A-15, A-16 & A-17 concerning identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. A-13. 84/06/21. 3pp. 32986:154-32986:156.
- 8510030176** Rev 2 to Allegation Investigation Repts 4-84-A-06/51, 4-84-A-06/1, 4-84-A-06/3 & 4-84-A-06/28 re Allegations A-156, A-106, A-108 & A-133. Potential violation noted: daily insp rept not signed per listed procedure. Drafts 4, 5 & 6 encl.
YANG, L. NRC - No Detailed Affiliation Given. A-156. 84/07/19. 18pp. 32987:009-32987:026.
- 8510030183** Rev 3 to Allegation Investigation Repts 4-84-A-06/53 & 4-84-A-06/154 re Allegations A-158 & A-272. Potential violation noted: missing or incomplete QA/QC documentation. Rev 2 & Drafts 1 & 2 encl.
CHOKSHI, N.C. NRC - No Detailed Affiliation Given. A-158. 84/07/10. 25pp. 32986:084-32986:108.
- 8510030186** Draft 3 to Allegation Investigation Rept 4-83-A-74-1 re Allegations A-13, A-14, A-15, A-16 & A-17 concerning identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. A-13. 84/06/09. 5pp. 32986:157-32986:161.
- 8510030196** Marked-up Rev 0 to Allegation Investigation Repts 4-83-A-74/6 & 4-84-A-06/59, Allegations A-18 & A-164 re inadequate nonconformance control by Ebasco Svcs, Inc where six nonconformance repts had no numbers.
* NRC - No Detailed Affiliation Given. A-18. 84/06/14. 3pp. 32986:109-32986:111.
- 8510030198** Marked-up Allegation Investigation Rept 4-84-A-06, Rev 0 re Allegation A-252 concerning Ebasco Svcs, Inc 830301 Interfac Ltr W3-QA-23661 as example of correspondence written to cover up problems in documentary review group.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-252. 84/06/25. 3pp. 32986:125-32986:127.
- 8510030201** Handwritten memo forwarding JM Cain (Louisiana Power & Light) 840628 response to NRC 840613 ltr re resolution of precensing issues. Comments re util program plan for issue resolution due by 850706.
CRUTCHFIELD, D. NRC - No Detailed Affiliation Given. 84/07/02. HARRISON, J. Region 3, Office of Director. SHAO, L., THATCHER, D. NRC - No Detailed Affiliation Given. 1p. 32986:162-32986:267.
- 8510030205** Draft 3 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re cadweld record deficiencies, uncertified inspectors & implementation of cadweld sampling procedures.
* NRC - No Detailed Affiliation Given. A-146. 84/06/15. 7pp. 32986:128-32986:134.
- 8510030209** Rev 0 to Allegation Investigation Rept 4-83-A-81-A4c re Allegation A-23c concerning inadequate welding procedures & techniques used by Tompkins-Beckwith in ASME Code Classes 1, 2 & 3 piping sys in six specific areas.
* NRC - No Detailed Affiliation Given. A-23c. 84/07/11. 5pp. 32986:268-32986:272.
- 8510030220** Agenda for 840817 meeting w/Louisiana Power & Light to discuss precensing assessment issues. Info re role of Precensing Issues Task Force & NUS support group & handwritten, unidentified meeting summary encl.
* NRC - No Detailed Affiliation Given. 84/08/17. NRC - No Detailed Affiliation Given. 78pp. 32986:273-32986:350.
- 8510030238** Forwards comments on first draft of Second Quarter CY85 AO rept to Congress. Comments on App C write-up & updated AO write-ups also encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/09/26. HELTEMES, C.J. AEOD, Director's Office. 21pp. 32849:116-32849:136.
- 8509190637** Discusses and draft Commission paper, ltr of transmittal to Congress & Second Quarter CY85 AO rept to Congress. Comments & updated info for encls requested by 850918.
HELTEMES, C.J. AEOD, Director's Office. 85/09/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 55pp. 32849:137-32849:191.
- 8510030241** Advises that changes to emergency plan submitted by 850702, 11 & 17 ltrs compatible w/provisions of 10CFR50.47, App E to 10CFR50 & criteria of Rev 1 to NUREG-0654. Items needing adjusting discussed w/R Myers during 850924 telecon.
FISH, R.F. Region 5, Office of Director. 85/09/25. RODRIGUEZ, R.J. Sacramento Municipal Utility District. 1p. 32845:311-32845:311.
- 8510030243** Draft "Executive Summary - Instrumentation Issues."
* NRC - No Detailed Affiliation Given. 84/06/12. 11pp. 32986:135-32986:145.
- 8510030245** Allegation Investigation Rept 4-84-A-06, Rev 0 re Allegation A-252 concerning Ebasco Svcs, Inc 830301 Interfac Ltr W3-QA-23661 as example of correspondence written to cover up problems discovered in documentary review group.
HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-252. 84/06/25. 3pp. 32986:146-32986:148.
- 8510030251** Submits items of interest. License SUB-1010 renewed on 850920 for receipt, sampling & conversion of yellowcake to UF6. Canonsburg site toured. Site certification discussed w/DOE. Remedial action will be completed in Nov 1985.
CROW, W.T. Uranium Fuel Licensing Branch. 85/09/26. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 32849:115-32849:115.
- 8510030264** Allegation Investigation Rept 4-84-A-06/24, Rev 2 re Allegation A-129 concerning installation, insp & acceptance of waterstop splicing activities by uncertified JA Jones Const Co personnel.
* NRC - No Detailed Affiliation Given. A-129. 84/08/30. 3pp. 32986:060-32986:062.
- 8510030266** Allegation Investigation Rept 4-84-A-06-24 re Allegation A-129 concerning installation, insp & acceptance of waterstop splicing activities performed by unqualified JA Jones Const Co personnel.
SHEWMAKER NRC - No Detailed Affiliation Given. A-129. 84/07/12. 1p. 32986:351-32986:351.
- 8510030272** Allegation Investigation Rept 4-84-A-06-24, Draft 2 re Allegation A-129 concerning JA Jones Const Co personnel performing installation, insp & acceptance of waterstop splicing activities w/o certification.
SHEWMAKER NRC - No Detailed Affiliation Given. A-129. 84/07/13. 2pp. 32986:352-32986:353.
- 8510030274** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/1, Allegation A-01 re unverified employment records for Mercury Const Co QA personnel. Past employment not verified.
* NRC - No Detailed Affiliation Given. A-01. 84/07/19. 8pp. 32986:354-32986:361.
- 8510030277** Allegation Investigation Repts 4-84-A-06/21 & 172, Rev 2 re Allegations A-126 & A-291 concerning Tompkins-Beckwith failure to maintain mat traceability on supplemental steel used w/pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-126. 84/07/11. 1p. 32987:001-32987:003.
- 8510030288** Advises that revised procedure for estimating core damage, submitted w/850909 ltr reviewed & meets Criterion 2 of NUREG-0737, item II.B.3.
VASSALLO, D.B. Operating Reactors Branch 2. 85/09/30. HARRINGTON, W.D. Boston Edison Co. 3pp. 32849:081-32849:083.
- 8510030295** Rev 2 to Allegation Investigation Rept 4-84-A-06-140c re Allegation A-256 concerning CB&I problems w/protective coatings & mat traceability for inside of containment vessel. Violation noted: failure to establish QA program.
* NRC - No Detailed Affiliation Given. A-256. 84/06/19. 5pp. 32987:004-32987:008.
- 8510030297** Allegation Investigation Rept 4-84-A-06/149, Rev 2 re Allegation A-267 concerning Mercury non-safety-related pipe hangers placed in safety-related areas which resulted in falsified documentation.
* NRC - No Detailed Affiliation Given. A-267. 84/08/29. 4pp. 32987:027-32987:030.
- 8510030299** Rev 3 to Allegation Investigation Rept 4-84-A-06-146. No violations noted. Major area investigated. Allegation A-264-1 re accurate mat traceability on instrument tube track.
MARINI, W.S. NRC - No Detailed Affiliation Given. A-264-1. 84/07/10. 3pp. 32987:031-32987:033.
- 8510030309** NUREG/CR-2000 V04 N8 LICENSEE EVENT REPORT (LER) COMPILATION. For Month Of August 1985.
* Oak Ridge National Laboratory. FIN A-9135. ORNL/NSIC-200. 85/09/30. AEOD, Director's Office. 147pp. 32848:182-32848:310.
- 8510030312** NUREG/CR-4305 COMMENTS ON THE LEAK-BEFORE-BREAK CONCEPT FOR NUCLEAR POWER PLANT PIPING SYSTEMS.
RODABAUGH, E.C. E.C. Rodabaugh Associates, Inc. * Oak Ridge National Laboratory. FIN B-0119. 85/09/30. Division of Engineering Technology. 58pp. 32854:257-32854:315.
- 8510030316** Allegation investigation Repts 4-84-A-06/139 & 140a-141, Draft 2 re Allegations A-253, A-254 & A-257 concerning "heat treat" records of Berger-Patterson, Oreboth or Dravo & CB&I.
* NRC - No Detailed Affiliation Given. A-253. 84/07/12. 2pp. 32987:034-32987:035.
- 8510030320** Rev 1 to Allegation Investigation Repts 4-84-A-06-185 & 4-84-A-06/76 re Allegations A-283 & A-181 concerning Ebasco Svcs, Inc inadequate nonconformance repts. No potential violations noted.
WHITTEMORE, J. NRC - No Detailed Affiliation Given. A-283. 84/06/21. 8pp. 32987:036-32987:043.

8510030323 Allegation Investigation Repts 4-84-A-06-165 & 4-84-A-06-76, Rev 2 re Allegations A-283 & A-181 concerning Ebasco Svcs. inc inadequate nonconformance repts. No potential violations noted. Marked-up Rev 2 encl.
WHITTEMORE, J. NRC - No Detailed Affiliation Given. A-283. 8/1/07/10. 5pp. 32987-044-32987-048.

8510030338 Rev 1 to Allegation Investigation Rept 4-84-A-06/145. No violation noted. Major area investigated: Allegation A-263 re refusal of Mercury Const. superintendent to correct problems identified in Internal Audit 12-1-82. Rev 0 dtd 8/4/06/15 encl.
* NRC - No Detailed Affiliation Given. A-263. 8/4/06/22. 5pp. 32987-049-32987-054.

8510030341 Rev 2 to Allegation Investigation Rept 4-84-A-06-142(3). No violations noted. Major area investigated: Allegation A-260 re lack of traceability of mats used in nonpressure retaining components in containment vessel. Rev 1 encl.
* NRC - No Detailed Affiliation Given. A-260. 8/4/06/21. 4pp. 32987-055-32987-058.

8510030345 Allegation Investigation Repts 4-84-A-06/21 & 172. Rev 1 re Allegations A-128 & A-291 concerning Tompkins-Beckwith failure to maintain mat traceability on supplemental steel used w/ pipe hangers & supports.
* NRC - No Detailed Affiliation Given. A-128. 8/4/07/10. 4pp. 32987-059-32987-062.

8510030350 Rev 0 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13, A-14, A-15, A-16 & A-17 re identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. A-13. 8/4/06/15. 4pp. 32987-063-32987-066.

8510030351 Final Allegation Investigation Repts 4-83-A-88, 4-84-A-06/21, 22, 23a & c & 167. Rev 1 re Allegations A-100, A-101, A-102, A-103, A-127, A-128a, A-128c & A-285a concerning Mercury Const Co traceability problems w/ listed mats.
SUMMERS, D.L. NRC - No Detailed Affiliation Given. A-100. 8/4/06/26. 4pp. 32987-067-32987-070.

8510030354 Allegation Investigation Rept 4-84-A-06, Rev 2 re Allegation A-252 concerning Ebasco Svcs. Inc. 830304 & 22 Interfco Ltrs W3-QA-23661 & W3QAIRG-0393, respectively. No potential violations noted.
SHOALL, NRC - No Detailed Affiliation Given. A-252. 8/4/08/08. 4pp. 32987-071-32987-096.

8510030359 Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157. Rev 1 re Allegations A-129d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-129d. 8/4/07/10. 4pp. 32987-097-32987-100.

8510030361 Rev 2 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13, A-14, A-15, A-16 & A-17 re identified documentation deficiencies for seismic supports for cable trays not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. A-13. 8/4/08/24. 3pp. 32987-101-32987-103.

8510030362 Draft 2 of "Executive Summary - Civil/Structural Issues."
* NRC - No Detailed Affiliation Given. 8/4/06/12. 10pp. 32987-104-32987-113.

8510030376 Marked-up Allegation Investigation Repts 4-84-A-06/23d, 4-84-A-06/100 & 4-84-A-06/157. Rev 0 re Allegations A-129d, A-212 & A-275 concerning undersized welds in work performed by Mercury Const Co.
SPAULDING, W.H. NRC - No Detailed Affiliation Given. A-129d. 8/4/06/27. 4pp. 32987-114-32987-117.

8510030379 Allegation Investigation Rept 4-84-A-06/170b, Draft 7 re Allegation A-289b concerning improper Ebasco Svcs. Inc. document reviews due to unqualified reviewers. Approach to resolution listed.
* NRC - No Detailed Affiliation Given. A-289b. 8/4/07/17. 2pp. 32987-118-32987-119.

8510030390 Rev 0 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 on Allegations A-146 & A-157 re deficiencies in cadweld splicing records identified in Nonconformance Rept W3-6234 not properly dispositioned.
* NRC - No Detailed Affiliation Given. A-146. 8/4/06/19. 17pp. 32987-120-32987-136.

8510030397 Allegation Investigation Rept 4-84-A-06-128, Rev 4 re Allegation A-242 concerning hydrostatic tests performed w/o use of high-point vents. Add'l concerns re adequacy of instrument tubing installations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. A-242. 8/4/08/15. 8pp. 32987-137-32987-145.

8510030402 Marked-up Allegation Investigation Rept 4-84-A-06-128, Rev 3 re Allegation A-242 concerning hydrostatic tests performed w/o use of high point vents. Add'l concerns re adequacy of instrument tubing installations cited.
FORD, D., THATCHER, D. NRC - No Detailed Affiliation Given. A-242. 8/4/07/18. 10pp. 32987-146-32987-155.

8510030430 NUREG/CR-4080 DETERMINATION OF THE AVAILABILITY OF CORE EXIT THERMOCOUPLES DURING SEVERE ACCIDENT SITUATIONS.
EDSON, J.L. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6369. EGG-2366. 85/09/30. Division of Engineering Technology. 47pp. 32848-082-32848-125.

8510030433 NUREG/CR-3948 EXPERIMENTAL RESULTS OF THE OPERATIONAL TRANSIENT (OPTRAN) TESTS 1-1 AND 1-2 IN THE POWER BURST FACILITY.
MCCARDLE, R.K., PLOGER, S.A., MCCORMICK, R.D. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6305. EGG-2297. 85/09/30. Division of Accident Evaluation. 78pp. 32911-221-32911-306.

8510030435 NUREG/CR-2800 S03 GUIDELINES FOR NUCLEAR POWER PLANT SAFETY ISSUE PRIORITIZATION INFORMATION DEVELOPMENT.
ANDREWS, W.B., BICKFORD, W.E., COUNTS, C.A. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2502. 85/09/30. Division of Safety Technology. 143pp. 32847-289-32848-069.

8510030438 NUREG-0748 V05 N07 OPERATING REACTORS LICENSING ACTIONS SUMMARY. Data As Of July 31, 1985. (Orange Book)
* Management Support Branch. 85/09/30. 362pp. 32846-287-32847-288.

8510040004 Rev 1 to Allegation Investigation Rept 4-84-A-06/24 on Allegation A-129 re installation, insp & acceptance of waterstop splicing activities performed by uncertified JA Jones Const Co personnel.
* NRC - No Detailed Affiliation Given. A-129. 8/4/06/11. 9pp. 32987-156-32987-164.

8510040005 Rev 4 to Allegation Investigation Rept 4-84-A-06/175 on Allegation A-294 re unqualified personnel used by Ebasco to perform documentation reviews. Allegation has no implications.
* NRC - No Detailed Affiliation Given. A-294. 8/4/08/23. 2pp. 32987-165-32987-166.

8510040006 Rev 1 to Allegation Investigation Repts 4-84-A-06/38, 45, 57 & 58 on Allegations A-143, A-150, A-162 & A-163 re util. Ebasco & contractors not performing adequate reviews of QA records. No violation noted.
* NRC - No Detailed Affiliation Given. A-143. 8/4/06/11. 5pp. 32987-167-32987-172.

8510040007 Rev 0 to Allegation Investigation Rept 4-84-A-06-31 on Allegation A-136 re difficulty for Ebasco QA personnel to get approval to initiate formal nonconformance report between 1975 & 1977 in civil/structural area.
* NRC - No Detailed Affiliation Given. A-136. 8/4/06/15. 9pp. 32987-173-32987-181.

8510040008 Draft 3 to Allegation Investigation Rept 4-84-A-06-36 of Allegation A-141 re whether Ebasco discrepancy notices were considered in QA review of concrete placement packages. No violation noted.
* NRC - No Detailed Affiliation Given. A-141. 8/4/06/18. 10pp. 32987-182-32987-191.

8510040009 Rev 0 to Allegation Investigation Repts 4-84-A-06-33 & 54 on Allegations A-138 & A-159 re deficiencies found in Ebasco backfill operation. Corrective actions must be completed before fuel load.
* NRC - No Detailed Affiliation Given. A-138. 8/4/06/13. 14pp. 32987-192-32987-205.

8510040024 Allegation Investigation Rept 4-84-A-06-65, Rev 1 re Allegation A-170 concerning improper disposition of Ebasco Svcs. inc discrepancy notice for missing reinforcing steel in fuel handling bldg.
KIM, S.B. NRC - No Detailed Affiliation Given. A-170. 8/4/07/10. 2pp. 32987-206-32987-216.

8510040027 Rev 4 to Allegation Investigation Repts 4-83-A-81/87, 4-83-A-88/7, 8, 13, 14, 84-A-06/109, 185v, 185w, 4-84-A-12/1, 2, 19 & 4-84-A-06 re Allegations A-33, A-55, A-56, A-61b, c, d & e, A-67, A-68, A-69, A-70, A-71, A-73, A-74, A-221, A-306 v&w, A-309 & A-310.
* NRC - No Detailed Affiliation Given. A-33. 8/4/08/23. 30pp. 32987-217-32987-264.

8510040040 Draft 2 to Allegation Investigation Rept 4-83-A-74-1, Allegations A-13, A-14, A-15, A-16 & A-17 re identified electrical seismic support documentation deficiencies not being addressed by Ebasco.
* NRC - No Detailed Affiliation Given. A-13. 8/4/06/08. 5pp. 32987-265-32987-269.

8510040045 Forwards Amend 95 to License DPR-23 & safety evaluation. Amend adds requirements to Tech Specs. per NUREG-0737, Items I.A.1.3 & I.I.K.3.3 concerning shift manning overtime limits & reporting safety & relief valve failures.
REQUA, G. Operating Reactors Branch 1. GL-82-16. 85/09/12. UTLEY, E.E. Carolina Power & Light Co. 3pp. 32900-274-32900-307.

-8510040078 Amend 95 to License DPR-23, adding requirements to Tech Specs re shift manning overtime limits & reporting safety & relief valves failures, per NUREG-0737, Items I.A.1.3 & I.I.K.3.3.
VARGAS, A. Operating Reactors Branch 1. GL-82-16. 85/09/12. 6pp. 32900-277-32900-282.

-8510040100 EGG-EA-6437 "Conformance to NRR Generic Ltr 82-16, HB Robinson Steam Electric Plant, Unit 2," technical evaluation rpt.
BEAHM, D.M. Idaho National Engineering Laboratory. FIN A-6600. GL-82-16. 83/12/31. NRC - No Detailed Affiliation Given. 20pp. 32868-126-32868-146.

8510040058 Requests statement explaining unauthorized procurement commitment & action taken to prevent recurrence. D. Crutcheff response re svcs & equipment procured to support Waterford 3 Task Force and.
HAGAN, T.F. Division of Contracts. 84/05/22. FUNCHES, J.L. NRC - No Detailed Affiliation Given. 2pp. 32987-270-32987-271.

-8510070091 Forwards requisition for costs incurred from Waterford 3 Task Force effort. Costs incurred by using util. equipment justified due to cost benefit advantage over contracting svcs commercially.
FUNCHES, J.L. Planning & Program Analysis Staff. 84/05/04. REBELLO, J. Administrative Contracts Branch. 3pp. 32990-309-32990-311.

8510040064 Denies receiving pressure to alter results of Waterford 3 special review team insp conducted w/ M Good per description in 840615 ltr & R Riderhour 840602 "Gambit" article. Insp conducted per NRC procedures.
HAUGHNEY, C.J. Comex Corp. 84/07/07. EISENHUT, D.G. Division of Licensing. 2pp. 32987-272-32987-273.

8510040070 Marked-up Allegation Investigation Rept 4-84-A-06/170b, Rev 0 re Allegation A-289(b) concerning QA Sys 50 documentation inadequately reviewed due to unqualified Ebasco Svcs. Inc. reviewers. No potential violations noted.
ROSS, D. NRC - No Detailed Affiliation Given. A-289(b). 8/4/06/19. 3pp. 32987-274-32987-276.

8510040072 Discusses current Waterford 3 Task Force assignment & forthcoming Comanche Peak assignment. Training Ctr director duties to be assumed commensurate w/ Comanche Peak assignment.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 84/06/28. GAGLIARDI, J.E. Technical Training Center (830103-850212). 3pp. 32987-277-32987-279.

8510040080 Rev 1 to Allegation Investigation Rept 4-83-A-81-9 re Allegation A-35 concerning inadequate documentation & failure to verify that piping sys completed per ASME Code.
* NRC - No Detailed Affiliation Given. A-35. 8/4/06/07. 3pp. 32987-280-32987-282.

8510040086 Rev 0 to Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184g & 184p re Allegations A-226, A-306b, A-306f, A-306g & A-306p concerning traceability requirements of permanent attachment mat welded to Class 1 & 2 piping.
* NRC - No Detailed Affiliation Given. A-226. 8/4/06/25. 6pp. 32987-283-32987-288.

8510040095 Rev 2 to Allegation Investigation Repts 4-83-A-86-4 & 4-83-A-87-3 re Allegations A-39 & A-42 concerning failure to perform nitrogen purge on piping sys prior to welding.
* NRC - No Detailed Affiliation Given. A-39. 8/4/06/09. 6pp. 32987-289-32987-294.

8510040107 Allegation Investigation Rept 4-84-A-06/170b, Rev 1 re Allegation A-289(b) concerning QA Sys 60 documentation inadequately reviewed due to unqualified Ebasco Svcs. Inc. reviewers. No potential violations noted.
ROSS, D. NRC - No Detailed Affiliation Given. A-289(b). 8/4/08/25. 3pp. 32987-295-32987-297.

312 NONDOCKETED ITEMS

- 8510040108** Responds to 850812 concerns re SPOS per NUREG-0737, item ILF.2. Narrow-range water level indications available to diagnose tube rupture in steam generator.
ALEXICH, M.P. Indiana & Michigan Electric Co. AEP-NRC-0531K. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32650-347-32650-350.
- 8510040109** Rev 1 to Allegation Investigation Repts A-84-A-06/117 & 184g re Allegations A-229 & A-306g concerning turnover of operational control records packages before sys review completed.
* NRC - No Detailed Affiliation Given. A-229. 84/06/25. 7pp. 32987-298-32987-305.
- 8510040119** Rev 1 to Allegation Investigation Rept 4-84-A-06/115 re Allegation A-227 concerning sys for identifying & dispositioning nonconformances for seismic Category 1 supports written by Ebasco worker & rejected by Ebasco mgt.
FREED, B. NRC - No Detailed Affiliation Given. A-227. 84/09/13. 7pp. 32987-296-32987-313.
- 8510040130** Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a, Rev 2 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability. No violations noted.
SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. A-286. 84/06/27. 5pp. 32987-314-32987-318.
- 8510040171** Revises commitment re qualifications & duties of shift technical advisor (STA). STA training will be performed per NUREG-0737, item LA.1.1 & Tech Specs, as specified within its Refs applicable to STA issue listed.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-01. 85/10/01. THOMPSON, J.H.L. Division of Licensing. 3pp. 32851-045-32851-047.
- 8510040174** Forwards "In-Progress Audit Rept of DCRDR Being Conducted by Georgia Power Co for Vogtle Electric Generating Plant, Unit 1." Present DCRDR not expected to meet requirements of Suppl 1 to NUREG-0737.
ADENSAM, E.G. Licensing Branch 4. 85/09/26. FOSTER, D.O. Georgia Power Co. 2pp. 32860-137-32860-171.
- 8510040182** "In-Progress Audit Rept of DCRDR Being Conducted by Georgia Power Co for Vogtle Electric Generating Plant, Unit 1."
MOORE, J.W., SAVAGE, J.W. Lawrence Livermore National Laboratory. 85/09/23. NRC - No Detailed Affiliation Given. 33pp. 32860-139-32860-171.
- 8510040202** Forwards Safety Insp Rept 50-244/85-15 on 850801-31. No violations noted.
COLLINS, S.J. Region 1, Office of Director. 85/09/30. KOBERR, R.W. Rochester Gas & Electric Corp. 2pp. 32850-311-32850-328.
- 8510040209** Insp Rept 50-244/85-15 on 850801-31. No violations noted. Major areas inspected: routine plant activities, action on previous findings, surveillance testing, review of svc water leak & review of TMI action plan.
LINVILLE, J.C. Region 1, Office of Director. GL-85-12. 85/09/26. 16pp. 32850-313-32850-328.
- 8510040210** Marked-up Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a, Rev 1 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability.
SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. A-286. 84/06/13. 3pp. 32987-319-32987-321.
- 8510040243** Discusses Special Team Insp Repts 50-317/85-16, 50-318/85-14, 50-317/85-18 & 50-318/85-16 on 850824-28 & 0715-19 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.
MURLEY, T.E. Region 1, Office of Director. 85/09/26. LUNDVALL, A.E. Baltimore Gas & Electric Co. 3pp. 32860-114-32860-121.
- 8510040253** Notice of violation & proposed imposition of civil penalty in amount of \$50,000. Violation noted: failure to implement & upgrade post-accident sampling sys per NUREG-0737.
* Region 1, Office of Director. EA-85-102. 85/09/26. 5pp. 32860-117-32860-121.
- 8510040305** Rev 2 to Allegation Investigation Repts 4-84-A-06/114, 184b, 184f, 184g & 184p re Allegations A-226, A-306f, A-306g & A-306p on traceability requirements of mgt welded to Class 1 & 2 piping pressure boundaries by Thompsons-Beckwith.
* NRC - No Detailed Affiliation Given. A-226. 84/08/29. 33pp. 32989-206-32989-238.
- 8510040312** Package of two comments requesting that public comment period for NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms," be extended to 180 days, due to length & importance of document.
TOENJES, C. Democratic Women's Association of the Desert. IRWIND, Desert/Pass Action Group. 85/10/03. Docketing & Services Branch. 2pp. 32853-265-32853-266.
- 8510040318** NUREG/CR-4280 THE EFFECTS OF SUPERVISOR EXPERIENCE AND ASSISTANCE OF A SHIFT TECHNICAL ADVISOR (STA) ON CREW PERFORMANCE IN CONTROL ROOM SIMULATORS.
BEARE, A.N., DONOVAN, M.D., LASSITER, D.L. General Physics Corp. FIN B-0821. ORNL/TM-9660. 85/09/30. Division of Risk Analysis & Operations (post 840429). 202pp. 32861-049-32861-248.
- 8510040326** Rev 1 to Allegation Investigation Rept 4-83-A-86/1 re Allegation A-36 concerning improperly calibrated torque wrench utilized by Gulf Engineering for work on emergency diesel generator.
* NRC - No Detailed Affiliation Given. A-36. 84/08/29. 13pp. 32989-239-32989-251.
- 8510040332** NUREG/CR-3980 V04 LIGHT-WATER-REACTOR SAFETY FUEL SYSTEMS RESEARCH PROGRAMS. Quarterly Progress Report, October-December 1984.
CHUNG, H.M., REST, J. Argonne National Laboratory. FIN A-2016. ANL-84-61. 85/09/30. Division of Accident Evaluation. 83pp. 32856-118-32856-183.
- 8510040343** Rev 4 to Allegation Investigation Repts 4-84-A-06/108, 121, 122 & 137 re Allegations A-220, A-233, A-235, A-236 & A-251 concerning approx 850 for 2,000 purchase orders for adapters lacking heat code markings.
* NRC - No Detailed Affiliation Given. A-220. 84/08/15. 13pp. 32987-322-32987-336.
- 8510040347** NUREG/CR-4259 TAILINGS NEUTRALIZATION AND OTHER ALTERNATIVES FOR IMMOBILIZING TOXIC MATERIALS IN TAILINGS Final Report.
OPITZ, B.E., SHERWOOD, D.R., DOBSON, M.E. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2370. PNL-5467. 85/09/30. Division of Radiation Programs & Earth Sciences (post 840429). 131pp. 32857-159-32857-294.
- 8510040354** NUREG/CR-4358 APPLICATIONS OF DENSITY PROFILING TO EQUIPMENT QUALIFICATION ISSUES.
GILLEN, K.T., CLOUGH, R.L., DHOOGHE, N.J. Sandia National Laboratories. FIN A-1051. SAND85-1557. 85/09/30. Division of Engineering Technology. 38pp. 32861-012-32861-048.
- 8510040360** NUREG/CR-3613 V03 N1 EVALUATION OF WELDED AND REPAIR-WELDED STAINLESS STEEL FOR LWR SERVICE. Semiannual Report For October 1984 Through March 1985.
ATTERIDGE, D.G., CHARLOT, L.A., BRUEMMER, S.M. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2449. PNL-4941. 85/09/30. Division of Engineering Technology. 59pp. 32858-184-32858-241.
- 8510040363** Rev 2 to Allegation Investigation Rept 4-84-A-06-97 re Allegation A-209 concerning missed insps that could cause quality of installation to be in question.
* NRC - No Detailed Affiliation Given. A-209. 84/06/22. 6pp. 32987-337-32987-342.
- 8510040365** NUREG/CR-3816 V04 REACTOR SAFETY RESEARCH. Quarterly Report, October-December 1984.
* Sandia National Laboratories. FIN A-1016. SAND84-1072. 85/09/30. Division of Accident Evaluation. 242pp. 32855-238-32855-117.
- 8510040366** Rev 2 to Allegation Investigation Rept 4-84-A-06/72 re Allegation A-177 concerning Ebasco QA inspector exercising poor judgment & improperly dispositioning nonconformance reports on American Bridge Co steel cast work.
* NRC - No Detailed Affiliation Given. A-177. 84/08/15. 20pp. 32987-343-32987-362.
- 8510040370** Rev 3 to Allegation Investigation Rept 4-84-A-06/77 re Allegation A-182 concerning insp of welding performed on structural items such as pipe hangers or supports for HVAC sys.
* NRC - No Detailed Affiliation Given. A-182. 84/06/25. 11pp. 32988-001-32988-011.
- 8510040371** NUREG/CR-4325 A PARAMETRIC STUDY OF PWR PRESSURE VESSEL INTEGRITY DURING OVERCOOLING ACCIDENTS, CONSIDERING BOTH 2-D AND 3-D FLAWS.
CHEVERTON, R.D., BALL, D.G. Oak Ridge National Laboratory. FIN B-0119. ORNL/TM-9682. 85/09/30. Division of Engineering Technology. 40pp. 32860-335-32860-011.
- 8510040377** NUREG/CR-4130 ICEDFA CODE FOR AEROSOL PARTICLE CAPTURE IN ICE COMPARTMENTS.
OWCZARSKI, P.C., SCHRECK, R.J., WINEGARDNER, W. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2444. PNL-5379. 85/09/30. Division of Engineering Technology. 93pp. 32857-295-32858-028.
- 8510040378** Draft 3 to Allegation Investigation Rept 4-84-A-06-75(a) re Allegations A-183(a) & A-184 concerning Mercury documentation of generic deficiencies. Partial breakdown on HVAC program noted.
* NRC - No Detailed Affiliation Given. A-183(a). 84/07/13. 2pp. 32988-012-32988-013.
- 8510040381** NUREG/CR-4350 V02 PROBABILISTIC RISK ASSESSMENT COURSE DOCUMENTATION. Volume 2: Probability And Statistics For PRA Applications.
IMAN, R.L., PRAIRIE, R.R. Sandia National Laboratories. FIN A-1321. SAND85-1495. 85/09/30. Division of Risk Analysis & Operations (post 840429). 200pp. 32858-029-32858-313.
- 8510040382** Rev 2 to Allegation Investigation Rept 4-84-A-06/91 re Allegation A-196 concerning qualifications of Ebasco document control supervisor.
* NRC - No Detailed Affiliation Given. A-196. 84/08/23. 2pp. 32988-014-32988-015.
- 8510040385** Rev 2 to Allegation Investigation Rept 4-84-A-06/95 re Allegation A-207 concerning Mercury QA personnel throwing away original documents after copies made.
* NRC - No Detailed Affiliation Given. A-207. 84/08/23. 3pp. 32988-016-32988-018.
- 8510040386** Rev 2 to Allegation Investigation Repts 4-84-A-06/120, 123, 124, 129, 130, 131, 144, 4-84-A-12/3(a), (b), (c), 6, 7, 8, 10, 11, 13, 14, 15, 16, 17 & 18, including Allegations A-232, A-234, A-237, A-238, A-243, A-244, A-245, A-262, A-311, A-312, A-313 & A-316.
* NRC - No Detailed Affiliation Given. A-232. 84/08/30. 13pp. 32988-192-32988-205.
- 8510040389** NUREG/CP-0066 PROCEEDINGS OF AN INTERNATIONAL WORKSHOP ON HISTORIC DOSE EXPERIENCE AND DOSE REDUCTION (ALARA) AT NUCLEAR POWER PLANTS, MAY 29-JUNE 1, 1984.
HORAN, J.R., BAUM, J.W., DIONNE, B.J. Brookhaven National Laboratory. FIN A-3214. BNL NUREG-51901. 85/09/30. Division of Radiation Programs & Earth Sciences (post 840429). 279pp. 32856-242-32857-158.
- 8510040392** Rev 2 to Allegation Investigation Rept 4-84-A-06/97 re Allegation A-209 concerning review of Mercury weld records identifying welds not fit-up or final-inspected.
* NRC - No Detailed Affiliation Given. A-209. 84/06/22. 2pp. 32988-019-32988-020.
- 8510040396** Resume of WM Kemp.
KEMP, W.M. Thero Special Services, Inc. 85/10/01. 4pp. 32988-021-32988-024.
- 8510040397** NUREG/CR-4272 RESPONSE TREE EVALUATION: EXPERIMENTAL ASSESSMENT OF AN EXPERT SYSTEM FOR NUCLEAR REACTOR OPERATORS.
NELSON, W.R., BLACKMAN, H.S. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6308. EGG-2397. 85/09/30. Division of Risk Analysis & Operations (post 840429). 68pp. 32859-203-32859-269.
- 8510040401** Rev 1 to Allegation Investigation Rept 4-84-A-06/99 re Allegation A-211 concerning Mercury Const Co program for maintaining identification of instrumentation tubing hangers & supports during rework.
* NRC - No Detailed Affiliation Given. A-211. 84/07/01. 40pp. 32988-025-32988-064.
- 8510040402** NUREG/CR-4304 PRESSURE VESSEL FRACTURE STUDIES PERTAINING TO THE PWR THERMAL SHOCK ISSUE. Experiment TSE-7.
CHEVERTON, R.D., BALL, D.G., BOLT, S.E. Oak Ridge National Laboratory. FIN B-0119. GSCA-46. 85/09/30. Division of Engineering Technology. 152pp. 32859-050-32859-202.

8510040407 NUREG/CR-3633 V04 TRAC-BD1/MOD1:AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM FOR BOILING WATER REACTOR TRANSIENT ANALYSIS, Volume 4: Developmental Assessment. SHUMWAY, R.W. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6052. EGG-2294. 85/09/30. Division of Accident Evaluation. 101pp. 32858-314-32859-049.

8510040410 Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a, Rev 3 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability. No violations noted. SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. A-286. 84/08/23. 3pp. 32988-065-32988-067.

8510040411 NUREG/CR-3633 V01 S1 TRAC-BD1/MOD1:AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM FOR BOILING WATER REACTOR TRANSIENT ANALYSIS. TAYLOR, D.D., SHUMWAY, R.W., SINGER, G.L. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6052. EGG-2294. 85/09/30. Division of Accident Evaluation. 122pp. 32855-116-32855-237.

8510040414 Forwards SSER 2 (NUREG-1031) W/o encl. YOUNGBLOOD, B.J. Licensing Branch 1. 85/09/27. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 32860-034-32860-036.

8510040417 Allegation Investigation Repts 4-84-A-06-168 & 4-84-A-06-170a, Rev 4 re Allegations A-286 & A-289a concerning Tompkins-Beckwith records falsifying heat numbers to demonstrate adequate traceability. SUMMERS, D., ROSS, D. NRC - No Detailed Affiliation Given. A-286. 84/08/28. 5pp. 32988-068-32988-072.

8510040420 Allegation Investigation Rept 4-84-A-06-149, Rev 1 re Allegation A-267 concerning falsification of documents stating that Mercury nonsafety-related pipe hangers were placed in safety-related areas. No violations noted. HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-267. 84/07/01. 13pp. 32988-073-32988-067.

8510040422 Comments on NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms." Comment period should be extended by 60 days. RAMBERG, B. California, Univ. of Los Angeles, CA. 85/09/27. Docketing & Services Branch. 1p. 32854-001-32854-001.

8510040424 Draft 3 to Allegation Investigation Repts 4-84-A-06-112 & 116 re Allegations A-224 & A-226 concerning individual providing info on Ebasco QA comments on MCP-2170-R/V. * NRC - No Detailed Affiliation Given. A-224. 84/07/19. 8pp. 32988-088-32988-195.

8510040427 Rev 1 to Allegation Investigation Rept 4-84-A-06-40 of Allegation A-145 re location plots for some in-place density tests for soil backfill not falling within fill identified on test rept. Validity of insp questioned. * NRC - No Detailed Affiliation Given. A-145. 84/06/14. 8pp. 32988-096-32988-103.

8510040430 Rev 0 to Allegation Investigation Rept 4-84-A-06-40 on Allegation A-145 re location plots for some in-place density tests for soil backfill not falling within fill identified on test rept. Validity of insp of backfill questioned. * NRC - No Detailed Affiliation Given. A-145. 84/05/24. 5pp. 32988-104-32988-108.

8510040434 Rev 2 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern that piping supports not in compliance w/Reg Guide 1.29. No violations noted. * NRC - No Detailed Affiliation Given. A-225. 84/06/13. 5pp. 32988-109-32988-114.

8510040437 Rev 3 to Allegation Investigation Rept 4-84-A-06-11 of Allegation A-223 re documentation discrepancies between field const & QC packages & missing test repts on operational control records. * NRC - No Detailed Affiliation Given. A-223. 84/08/29. 4pp. 32988-115-32988-118.

8510040440 Rev 3 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern on piping supports not in compliance w/Reg Guide 1.29. No violations noted. * NRC - No Detailed Affiliation Given. A-225. 84/08/30. 4pp. 32988-119-32988-122.

8510040447 Marked-up Draft 2 to Allegation Investigation Repts 4-84-A-06-114, 184b, 184f, 184g & 184p of Allegations A-226, A-106b, A-306f, A-306g & A-306p re nonsafety instrument air piping & tubings in reactor auxiliary & fuel handling bldgs. * NRC - No Detailed Affiliation Given. A-226. 84/08/27. 2pp. 32988-123-32988-124.

8510040454 Press release discussing GAP suggestion that NRC require independent review of utility program to correct problems at facility. GROESCH, G. Government Accountability Project. 84/07/26. 3pp. 32988-125-32988-127.

8510040459 News article discussing GAP suggestion that NRC require independent review of utility program to correct problems at facility. CUNNINGHAM, L. Times-Picayune, La Place, LA. 84/07/27. 2pp. 32988-128-32988-129.

8510040461 Allegation Investigation Rept 4-84-A-06-149, Rev 0 re Allegation A-267 concerning falsification of documents stating that Mercury nonsafety-related pipe hangers placed in safety-related areas. No violations noted. HUBBARD, R.W. NRC - No Detailed Affiliation Given. A-267. 84/06/25. 6pp. 32988-130-32988-135.

8510040477 Rev 1 to Allegation Investigation Repts 4-84-A-06-103, 109, 144, 126 & 184f re Allegations A-215, A-175, A-239, A-240 & A-306 concerning unqualified welders performing welding on safety-related sys. * NRC - No Detailed Affiliation Given. A-215. 84/07/10. 56pp. 32988-136-32988-191.

8510040483 Rev 3 to Allegation Investigation Rept 4-84-A-06-103 re Allegation A-214 concerning traceability of mats lost, causing validity of installed mat containing required certification to be questionable. * NRC - No Detailed Affiliation Given. A-214. 84/08/23. 7pp. 32989-252-32989-259.

8510040486 Rev 4 to Allegation Investigation Rept 4-84-A-06-11 re Allegation A-223 concerning incomplete, missing & conflicting documentation that raised question re quality of installation & insp results. * NRC - No Detailed Affiliation Given. A-223. 84/08/30. 3pp. 32989-260-32989-262.

8510040491 Draft 6 to Allegation Investigation Repts 4-84-A-06-67 & 69 re Allegations A-172 & A-174 concerning possible falsification of T-B test numbers. * NRC - No Detailed Affiliation Given. A-172. 84/07/18. 11pp. 32989-273-32989-273.

8510040500 Rev 2 to Allegation Investigation Rept 4-83-A-81/A1 re Allegations A-20, A-21 & A-22 concerning recordkeeping problems w/ Penetrations 38 (A-20) & 65 (A-21 & 22) & recordkeeping problems w/ eight other penetrations. * NRC - No Detailed Affiliation Given. A-20. 84/08/29. 13pp. 32989-274-32989-286.

8510040515 Rev 1 to Allegation Investigation Repts 4-84-A-06-1, 4-84-A-06-3 & 4-84-A-06-28 of Allegations A-156, A-106, A-108 & A-133 re possibility of forged signatures & initials on JA Jones daily cadweld insp repts. * NRC - No Detailed Affiliation Given. A-156. 84/06/14. 6pp. 32989-287-32989-298.

8510040520 Allegation Investigation Rept 4-84-A-06-150, Rev 1 re Allegation A-268 concerning Ebasco Svcs, Inc. not placing grout under base plates for instrument stands & tubing supports. No potential violations noted. SHEWMAKER, R.E. NRC - No Detailed Affiliation Given. A-268. 84/06/22. 5pp. 32988-206-32988-210.

8510040521 Rev 2 to Allegation Investigation Rept 4-84-A-06-37 re Allegation A-142 on American Bridge failure to provide documentation for over 30% of work & documented work not reflecting true status. * NRC - No Detailed Affiliation Given. A-142. 84/06/18. 6pp. 32988-211-32988-222.

8510040525 Rev 0 to Allegation Investigation Rept 4-84-A-06-02 re Allegation A-107 concerning false document generated to replace missing records re cadweld activities. * NRC - No Detailed Affiliation Given. A-107. 84/06/08. 7pp. 32988-223-32988-229.

8510040529 Rev 0 to allegation investigation rept of Allegations A-224 & A-228 re concerns about "Hydrostatic or Pneumatic Testing Procedure" (TACP-2170), used to test plant instrumentation sys. No violation noted. * NRC - No Detailed Affiliation Given. A-224. 84/07/19. 5pp. 32988-230-32988-235.

8510040547 Forwards SER re GESSAR II design in response to 850911 request Review of severe accident concerns presently being considered by ACRS. Addl. addressing ACRS recommendation at completion of review expected W/o encl. SCALET, D.C. Standardization & Special Projects Branch. 85/10/01. CHAKRABORTY, S. Switzerland, Govt. of. 2pp. 32863-160-32863-161.

8510040553 Rev 2 to Allegation Investigation Rept 4-84-A-06-11 of Allegation A-223 re documentation discrepancies between field const & QA packages & missing test repts on operational control records. No violation noted. * NRC - No Detailed Affiliation Given. A-223. 84/06/13. 2pp. 32989-204-32989-205.

8510040578 NUREG/CR-4357 THE FEASIBILITY OF DETECTING THE IMPORT OF UNAUTHORIZED RADIOACTIVE MATERIALS INTO THE UNITED STATES. BEER, W., GORDON, J., KWAN, G. Aerospace Corp. FIN A-4168. 85/09/30. Division of Fuel Cycle & Material Safety. 235pp. 32982-213-32983-092.

8510040586 Requests statement explaining unauthorized procurement commitment & action taken to prevent recurrence. D. Crutchfield response re svcs & equipment procured to support Waterford 3 Task Force encl. NEWTON, J.H. Division of Contracts. 84/10/09. LAZO, L. NRC - No Detailed Affiliation Given. 4pp. 32988-236-32988-200.

8510040592 NUREG/CR-4397 IN-PLANT SOURCE TERM MEASUREMENTS AT PRAIRIE ISLAND NUCLEAR GENERATING STATION. MANDLER, J.W., STALKER, A.C., CRONEY, S.T. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6075. EGG-2420. 85/09/30. Division of Engineering Technology. 250pp. 32983-172-32985-016.

8510040596 Allegation Investigation Rept 4-84-A-06-152, Draft 2 re Allegation A-270 concerning Ebasco Svcs, Inc. inadequate nonconformance rept on Block 2 common foundation basement. * NRC - No Detailed Affiliation Given. A-270. 84/07/18. 3pp. 32989-201-32989-203.

8510070060 Forwards EDO preliminary responses to questions raised re 850609 incident at facility. Full staff briefing planned as soon as task force rept available. ROBERTS, T.M. Commissioners. 85/07/17. MARKEY, E.J. House of Rep., Energy & Commerce. 1p. 32905-053-32905-157.

8510070069 Provides recommendation on NUREG-0611 auxiliary feedwater reliability study re addition of third, qualified, motor driven emergency feedwater pump. ROWSOME, F.H. Division of Safety Technology. 85/03/01. PARR, C., THANDANI, A., TSAO, J. NRC - No Detailed Affiliation Given. 1p. 32907-200-32907-200.

8510070078 Forwards NUREG-0667, "Transient Response of B&W Designed Reactors." Evaluation requested. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/05/21. MATTSO, R.J. Division of Safety Technology. 2pp. 32906-184-32906-185.

8510070109 Forwards topical rept evaluation of NUREG-0677, "Transient Response of B&W Designed Reactors," in response to 800521 memo. MATTSO, R.J. Division of Safety Technology. 80/06/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 42pp. 32906-186-32906-226.

8510110596 Recommends closure of Generic Issue/TMI Action Item II E.5.2 re transient response of B&W designed reactors. High priority items implemented. Implementation of low priority items unnecessary. Concurrence requested. Status list encl. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 84/09/28. DIRCKS, W.J. Office of the Executive Director for Operations. 4pp. 32908-200-32908-203.

8510070181 Discusses NUREG-0667, "Transient Response of B&W Designed Reactors," implementation plan. Table of assignments & required actions encl. EISENHUT, D.G. Division of Licensing. 81/06/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32907-139-32907-148.

8405010072 Forwards comparison of emergency feedwater sys at TMI-1 & other B&W operating plants to acceptance criteria of SRP Section 10.4.9. Schedules established for implementation of necessary mods at each B&W plant. RUBENSTEIN, L.S. Assistant Director for Core & Plant Systems. 81-81-14. 84/04/17. LAJAS, G.C. Assistant Director for Operating Reactors. 13pp. 32908-119-32908-197.

8406250404 Provides status of third auxiliary feedwater pump & diesel generator. Utility initiated PRA study of auxiliary feedwater sys (AFS). Reliability of AFS in low range does not meet SRP Section 10.4.9 criteria. DE AGAZIO, A. Operating Reactors Branch 4. 84/06/20. LAJAS, G.C. Assistant Director for Operating Reactors. 2pp. 32909-137-32909-240.

314 NONDOCKETED ITEMS

- 8506270125** Forwards table of B&W plants comparing selected TMI actions from NUREG-1006 incomplete TMI items for facility listed per NUREG-0737 NUREG-0737 & Suppl 1 active items re post-implementation reviews also listed. THOMPSON, H.L. Division of Licensing. 85/06/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 32910:274-32910:279.
- 8510070083** Allegation investigation Rept 4-84-A-06-85, Rev 2 re Allegation A-170, concerning improper disposition of missing Ebasco Svcs, Inc. discrepancy notice for missing reinforcing steel in fuel handling bldg. KIM, S.B. NRC - No Detailed Affiliation Given. A-170. 84/08/29. 7pp. 32990:299-32990:308.
- 8510070168** Forwards plant-specific info re TMI Action Item II.K.3.5 per Section IV of SER issued w/ Generic Ltr 85-12, Reactor coolant subcooling methodology will be used to determine reactor coolant pump setpoint. ZIMMERMAN, S.R. Carolina Power & Light Co. GL-85-12. 85/09/30. THOMPSON, H.L. Division of Licensing. 6pp. 32881:196-32881:201.
- 8510070175** NUREG-0020 V08 N08 LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As of July 31, 1985. (Gray Book I)
* Division of Budget & Analysis. 85/09/30. 405pp. 32902:037-32902:116.
- 8510070182** NUREG-0540 V07 N08 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE August 1-31, 1985.
* Division of Technical Information & Document Control. 85/09/30. 610pp. 32903:117-32903:052.
- 8510070188** Responds to Generic Ltr 83-37 re containment pressure monitor Tech Specs required by NUREG-0737, Item II.F.1.4. Current Tech Specs 3.3-11.3.3-10.4.3-7 & 4.3-10 adequately meet NUREG-0737 requirements. ALLEXCH, M.P. Indiana & Michigan Electric Co. GL-83-37. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32881:135-32881:136.
- 8510070243** Responds to 850912 request for review of existing R of agreement between Region 1 & 850912, Criteria of Region 1 incident response suppt to NUREG-0845 cited as basis for activities during incidents. MURLEY, T.E. Region 1, Office of Director. 85/09/30. COONEY, M.J. Philadelphia Electric Co. App. 32878:076-32878:081.
- 8510070247** Forwards current agreement re NRC emergency response to nuclear incidents for review per NUREG-0854, Rev 1 TE Murley 850926 signature to statement that 840912 agreement shall remain in effect appended. COONEY, M.J. Philadelphia Electric Co. 85/09/12. MURLEY, T.E. Region 1, Office of Director. 2pp. 32878:080-32878:081.
- 8510070261** Advises that load drop analyses of two remaining load handling devices completed per 850805 R addressing guidelines of NUREG-0612, Section 5.1.1 Scabbing of intervening floor may occur for certain loads. MANGAN, C.V. Niagara Mohawk Power Corp. 85/10/01. VASSALLO, D.B. Operating Reactors Branch 2. 1p. 32877:311-32877:311.
- 8510070297** Requests that public comment period for NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms," be extended from 90 to 180 days. DOUGHTY, J. Seacoast Anti-Pollution League. 85/10/01. Docketing & Services Branch. 1p. 32877:299-32877:299.
- 8510070317** Forwards leakage data rept & corrective r ant performed as result of leakage per NUREG-0578, Item 2.1.6.9 & FSAR Section L.77. FREDERICH, G.J. Commonwealth Edison Co. 85/09/16. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32880:335-32880:337.
- 8510080026** Forwards results of onsite audit of DCDR, per Suppl 1 to NUREG-0737 Schedule for implementation of corrective actions satisfactory in light of required supplemental rept. VASSALLO, D.B. Operating Reactors Branch 2. 85/09/30. FARRAR, D.L. Commonwealth Edison Co. 3pp. 32926:267-32926:338.
- 8510080030** Forwards Special Team Insp Rept 50-244/85-08 on 850610-14. No violations observed. Areas of concern listed. Description of action taken or planned re possible Eberline SPN-4 sys damage requested within 25 days. MARTIN, T.T. Region 4, Office of Director. 85/09/27. KOBER, R.W. Rochester Gas & Electric Corp. 2pp. 32928:131-32928:158.
- 8510080032** Safety Insp Rept 50-244/85-08 on 850610-14. No violations identified. Major areas inspected/implementation & status of task actions identified in NUREG-0737 including increased range of noble gas radiation monitors. WHITE, J.R. PAULINO, R. DRAGOUR, T.D. Region 1, Office of Director. 85/09/25. 25pp. 32928:133-32928:158.
- 8510080035** Forwards response to Question 2 of 850719 request for add info re NUREG-0737, Item II.B.1 concerning expected blowdowns at current ring settings. Actual percent blowdown of safety valves has no adverse effect upon core cooling. WILLIAMS, J. Toledo Edison Co. 1191. 85/10/01. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 32918:295-32918:296.
- 8510080123** Forwards FEMA finding & determination verifying State of TX & local emergency preparedness plans adequate to protect public health & can be implemented (offsite per NUREG-0654, Public alert & notification sys adequate. DENHE, R.P. Region 4, Office of Director. 85/10/03. COUNSEL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32914:326-32915:182.
- 8510080203** Forwards schedule for installation of instrumentation per Reg Guide 1.97 & Suppl 1 to NUREG-0737 during Cycles 8 & 9 startup. Items include core exit temp, coolant inventory & steam generator level. ROCHON, J.E. R.J. Sacramento Municipal Utility District. RJR 85-470. 85/09/30. THOMPSON, H.L. Division of Licensing. 3pp. 32920:254-32920:259.
- 8510080307** Forwards SER 4 (NUREG-0880) for facility. BUTLER, W.R. Licensing Branch 2. 85/10/01. CAHILL, W.J. BOOKER, J.E. Gulf States Utilities Co. App. 32923:040-32923:083.
- 8510080313** Forwards response to 850701 R & supplemental safety evaluation re NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys (PASS)." Encl discusses PASS capability in post-accident water chemistry environ. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85-51. 85/10/02. VARGAS, A. Operating Reactors Branch 1. 10pp. 32919:001-32919:010.
- 8510080351** Forwards Insp Rept 50-302/85-38 on 850626-30. No violation noted. BROWNLEE, V.L. Region 2, Office of Director. 85/09/27. WILGUS, W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 32928:005-32928:016.
- 8510080353** Insp Rept 50-302/85-38 on 850626-30. No violation or deviation noted. Major areas inspected/ licensee commitment in tracking of regulatory requirements. SMITH, C.F. BELSLE, G.A. Region 2, Office of Director. GL-81-14. 85/09/28. 11pp. 32928:006-32928:016.
- 8510080390** Responds to NRC 850716 R re violations noted in Insp Rept 50-271/84-11. Existing high radiat on monitor locations meet requirements of NUREG-0737, Item II.F.1.3. Request for technical deviation from criterion will be sent by 851130. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. FVY 85-89. 85/09/26. MARTIN, T.T. Region 1, Office of Director. 2pp. 32919:313-32919:314.
- 8510080468** Forwards revised response to SER (NUREG-1031) Question 480.37 re asymmetric pressure loadings on structures & components due to postulated pipe ruptures, including results of evaluation of asymmetric loadings on pressurizer. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 811672. 85/10/01. YOUNGBLOOD, B.J. Licensing Branch 1. 24pp. 32921:133-32921:156.
- 8510090031** FOIA request for documentation re 850609 event at facility, including Items 2, 3 & 4 referenced in NUREG-1154, NUREG-CR-3530, NUREG-0737, Tech Specs per FSAR Chapter 16 & OL. WEBER, R.E. Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law). 85/08/29. FELTON, J.M. Division of Rules and Records. 3pp. 32964:016-32964:018.
- 8510090111** Forwards FES (NUREG-1094) re operation of facility. KNIGHTON, G.W. Licensing Branch 3. 85/10/03. WOOD, J.M. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 4pp. 32951:341-32951:346.
- 8510090141** Forwards nonproprietary & proprietary WCAP. (0444-NP-A & WCAP-10444-D-P, respectively, "Fuel Core Rept Vantage 5 Fuel Assembly," per NUREG-0390 Affidavit and Proprietary rept withheld (ref 10CFR2.790). RAHE, E.P. Westinghouse Electric Corp. NS-NRC-85-3066. 85/09/27. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 32956:213-32957:358.
- 8510090191** Forwards FES (NUREG-1094) for Beaver Valley Power Station, Unit 2 & FR notice of availability W/o NUREG. KNIGHTON, G.W. Licensing Branch 3. 85/10/03. CAREY, J.J. Duquesne Light Co. 3pp. 32949:186-32949:190.
- 8510090199** Notice of availability of FES (NUREG-1094) for Beaver Valley Power Station, Unit 2. KNIGHTON, G.W. Licensing Branch 3. 85/10/03. 2pp. 32949:188-32949:190.
- 8510090209** Provides add info re NUREG-0737, Item II.D.1, "Performance Testing of Relief & Safety Valves" in response to NRC 850714 w/request. MUSOLF, D. Northern States Power Co. 85/09/26. Office of Nuclear Reactor Regulation, Director. 12pp. 32942:140-32942:236.
- 8510090295** Forwards prioritization evaluation accepting Westinghouse Owners Group response to Generic issue 112 re reactor protection instrumentation sys frequencies & out-of-svc times. Evaluation will be incorporated into NUREG-0933. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/03. BERNEJO, R.M. Division of Systems Integration (post 811005). 6pp. 32950:174-32950:179.
- 8510090299** Discusses discrepancies identified in Mar 1985 edition of NUREG-0020, "Licensed Operating Reactors Status Summary Rept." Error originated in Apr 1984 edition. Excerpts from NUREG-0020 & Apr 1984 monthly operating rept encl. OTTOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/02. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. App. 32947:107-32947:112.
- 8510090316** Informs that continued shutdown not required pending action on 850910 request not to install mode associated w/ NUREG-0737, Item II.D.3.4, "Control Room Habitability" & forthcoming license amend to modify scheduler requirement. THOMPSON, H.L. Division of Licensing. 85/09/30. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 6pp. 32948:172-32948:175.
- 8510090378** Trip rept of 850925 site visit re emergency operating procedures (EOPs) still per Suppl 1 to NUREG-0737. Licensee not generating EOPs per procedures generation package & TMI Action Plan Item I.C.1. Attendance list encl. CLAYTON, H.B. Procedures & Systems Review Branch. 85/10/02. ZIEMANN, D.L. Division of Human Factors Safety. App. 32965:056-32965:061.
- 8510090404** Forwards FR notice of availability of FES (NUREG-1094) for Beaver Valley Power Station, Unit 2, for info. KNIGHTON, G.W. Licensing Branch 3. 85/10/03. Citizens for a Better Environment. 2pp. 32964:335-32964:336.
- 8510090518** Forwards final camera-ready copy of NUREG-CR-4110, SAND84-2868, "Repository Site Data Rept for Unsubstantiated TUF" & responses to NRC comments W/o NUREG-CR-4110. HUNTER, R.L. Sandia National Laboratories. FIN A-1158. 85/09/23. COLEMAN, N. Geotechnical Branch (Post 831001). 3pp. 32965:184-32965:196.
- 8510100024** Forwards description of actions, schedule & commitments for plant mode resulting from SEP open status. Rev to Table 4.1 of draft integrated plant safety assessment rept (NUREG-0829) also encl. MEDFORD, M.C. Southern California Edison Co. 85/10/04. ZWOLINSKI, J.A. Operating Reactors Branch 5. 22pp. 32959:178-32959:199.
- 8510100025** Comments on NUREG-0956 re source term rept. Reactor safety study (RSS) source term much too limiting. Deriving factors by which source terms for all radionuclides & reactors can be changed from RSS values not yet possible. Articles encl. LEWIS, M.L. Lewis, M. 85/10/06. Office of the Secretary of the Commission. App. 32960:229-32960:232.

8510100093 Forwards WT Crow 850920 ltr to JC Stauter forwarding renewed License SUB-1010 & related SER finding of no significant impact on quality of human environ & environ assessment (NUREG-1157). Related correspondence. LEWIS, S.H. Hearing Branch 2. #485 679. MLA. 85/10/03. FRYE, J.H. Atomic Safety and Licensing Board Panel. 22pp. 32957-238-32958-335.

8510100104 Forwards add response to NRC 801219 request for add info re performance testing of relief & safety valves per NUREG-0737, item 8.0.1. Pressurizer safety valve discharge piping & valve actuation time history analysis encl. MEDFORD, M.O. Southern California Edison Co. 85/10/01. ZWOLINSKI, J.A. Operating Reactors Branch 5. 8pp. 32955-092-32957-237.

8510100120 Forwards application for amend to License DPR-64, revising Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737 items. Fee paid. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). GL-83-37. 85/10/04. VARGA, S.A. Operating Reactors Branch 1. 3pp. 32961-181-32961-197.

8510100136 Application for amend to License DPR-64, revising Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737 items. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). GL-83-37. 85/10/04. 1p. 32961-184-32961-184.

8510100147 Proposed Tech Specs re RCS vents & noble gas containment water level & containment hydrogen monitors, per Generic Ltr 83-37 & NUREG-0737 items (I.B.1.B.F. 1.1.I.F. 1.5 & I.F. 1.6. Safety evaluation encl. * New York Power Authority (formerly Power Authority of the State of New York). GL-83-37. 85/10/04. 13pp. 32961-185-32961-197.

8510100124 Submits plans & schedule for providing info on NUREG-0737, item II.F.2 re inadequate core cooling instrumentation per 821210 request. Evaluation of instrumentation capabilities will be submitted by 8/30/01. MEDFORD, M.O. Southern California Edison Co. GL-82-28. 85/10/08. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 32960-351-32960-352.

8510100130 Comments on NUREG-0956, "Reassessment of Technical Basis for Estimating Source Term." Requests comment period be extended from original 90-day period to at least 180 days. WASHINGTON, M. Affiliation Not Assigned. 85/10/03. Docketing & Services Branch. 2pp. 32960-086-32960-087.

8510100155 Forwards response to NRC 850603 request for add info on NUREG-0737, item II.D.1. "Performance Testing of Relief & Safety Valves." PORV control circuit components located in cable room & not subj to harsh environ. TUCKER, J.E. Duke Power Co. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 32962-223-32962-266.

8510100001 Advises that recommendations for turbine maint in NUREG-0989 reviewed. Turbine sys maint program based on manufacturer calculations of missile generation probabilities & NRC guidelines will be submitted before 8/11/01. TUCKER, J.E. Gulf States Utilities Co. RBG-22291. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32968-362-32968-362.

8510100008 Forwards "DORDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." Most requirements of Suppl 1 to NUREG-0737 satisfied. Proposed resolutions to human engineering deficiencies necessary within 120 days of fr receipt. ZWOLINSKI, J.A. Operating Reactors Branch 5. LSOS-85-10-012. 85/10/07. FARRAR, D.L. Commonwealth Edison Co. 4pp. 32969-183-32969-251.

8509170384 "DORDR Summary Rept Evaluation for Dresden Station, Units 2 & 3." * Science Applications International Corp. (formerly Science Applications, Inc.) NRC. 85-02-096. 85/08/30. NRC - No Detailed Affiliation Given. 85pp. 32999-197-32999-251.

8510100009 Forwards "PWR Safety Relief & Block Valve Adequacy Rept." per NUREG-0737, item II.D.1. Response providing analyses of effect of as-built relief & safety valve discharge piping on valve operability also encl. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 811717. 85/10/01. YOUNGBLOOD, S.J. Licensing Branch 1. 3pp. 32969-204-32969-246.

8510100114 Rev 1 to "PWR Safety Relief & Block Valve Adequacy Rept." GRAYSON, R.M. SEPP, J.A. Westinghouse Electric Corp. 85/08/31. 40pp. 32969-207-32969-246.

8510100037 Forwards evaluations of integrated safety assessment program, Topic 2.14, Evaluation & Implementation of NUREG-0577; & Topic 2.15, "Torque Switch Evaluation for Minor Operated Valves," for review. OPEKA, J.F. SEARIS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 811717. 85/10/02. GRIMES, C.I. Systematic Evaluation Program Branch. 5pp. 32973-221-32973-225.

8510100042 Comments on draft NUREG-0956, "Reassessment of Technical Basis for Estimating Source Term." Main focus should be on how recent research data & scientific findings have impacted understanding of fission product behavior. CROENBERG, A. Engineering Science & Analysis. 85/10/02. Docketing & Services Branch. 13pp. 32974-112-32974-123.

8510100043 Forwards "Evaluation Time Estimates for Clinton Power Station Plume Exposure Pathway Emergency Planning Zone," per Rev 1 to NUREG-0654/FEMA-REP-1. "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans." SPANKENBERG, F. Birco Power Co. U-600292. 85/10/09. BUTLER, W.R. Licensing Branch 2. 2pp. 32968-191-32968-356.

8510100075 Forwards SER re 8840202 & 0316 responses to integrated safety assessment rept (NUREG-0824) sections including flooding elevation & roofs. Proposed method of safe shutdown acceptable if firehouse blockwalls can resist flood loads. ZWOLINSKI, J.A. Operating Reactors Branch 5. LSOS-85-10-011. 85/10/07. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33011-305-33011-311.

8510100086 SER supporting integrated plant safety assessment rept NUREG-0824 sections including flooding elevation & roofs, provided fire pump house blockwalls adequate to resist flood loads. * NRC - No Detailed Affiliation Given. 85/10/07. 4pp. 33011-308-33011-311.

8510101049 Provides info to close remaining open issues re NUREG-0737, item I.D.2 concerning SPDS. Complete list of radiation monitors which will be used in SPDS for monitoring radioactivity control safety provided. HARRINGTON, W.D. Boston Edison Co. BECO-85-180. 85/10/07. VASSALLO, D.B. Operating Reactors Branch 2. 4pp. 32972-127-32972-130.

851010238 Motion requesting ASLB reconsider & modify 850918 memorandum to reflect fact that unit not placed in special category for coatings inside containment, per SSER 9 (NUREG-0797) & consider notification of USI A-43 closed. BACHMANN, R.G. Hearing Branch 1. #485 741. OL. 85/10/09. Atomic Safety and Licensing Board Panel. 6pp. 32971-235-32971-252.

8510101021 Forwards new FSAR Section 1.9 & marked-up FSAR pages re compliance w/NUREG-0737. "Clarification of TMI Action Plan Requirements." Exception taken to item II.F.1. "Noble Gas Effluent Monitor." DEVINCENIS, J. Public Service Co. of New Hampshire. SEN-880. 85/10/10. KNIGHTON, G.W. Licensing Branch 3. 86pp. 33007-031-33008-16.

8510101038 Discusses history of qualification effort on pressurizer safety valve direct position indicators (refs NUREG-0578 & NUREG-0737, item II.D.3.1) per NRC 850927 telcon request. BRITT, R.W. Wisconsin Electric Power Co. VNPPO-85-489. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E. Operating Reactors Branch 3. 5pp. 33013-001-33013-005.

8510101047 Responds to 850630 request for confirmatory info re NUREG-0737, item II.K.3.30, "Small Break LOCA Methods." & use of CRAFT-2 code. URI concurs w/BAW position on NUREG-0565 concerning noncondensable gases. WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-04. 85/10/08. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 33008-355-33008-356.

85101010283 Informs that resolution of Generic Issue 30, "Potential Generator Missiles - Generator Rotor Retaining Rings," will not be pursued based on encl prioritization evaluation which will be incorporated into NUREG-0933. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/03. KNIGHT, J.P. Division of Engineering. 8pp. 33033-121-33033-128.

85101010326 Requests plans & schedule for NRC approved mods for NUREG-0737, item II.K.3.18 re automatic depressurization sys logic as specified in 830603 fr. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. HARRINGTON, W.D. Boston Edison Co. 2pp. 33033-238-33033-239.

85101010328 Requests plans & schedule for NRC approved mods for NUREG-0737, item II.K.3.18 re automatic depressurization sys logic as specified in 830603 fr. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. PARRISH, G. Tennessee Valley Authority. 3pp. 33033-240-33033-242.

85101010334 Requests plans & schedule for NRC approved mods for NUREG-0737, item II.K.3.18 re automatic depressurization sys logic as specified in 830603 fr. VASSALLO, D.B. Operating Reactors Branch 2. 85/10/07. CAPSTICK, R.W. Vermont Yankee Nuclear Power Corp. 3pp. 33033-243-33033-245.

85101010338 Forwards add info re 841120 & 850506 responses to Generic Ltr 84-23, "Reactor Water Level Instrumentation in BWRs." Plant capable of effectively compensating for reactor water level indication errors caused by drywell heatup. GUCWALL, T. Georgia Power Co. GL-84-23. 85/10/07. STOLZ, J.F. Operating Reactors Branch 4. 16pp. 33013-011-33013-026.

8510100014 Forwards Insp Rept 50-245/85-15 on 850617-28 & notice of violation. EBNETER, S.D. Region 1, Office of Director. 85/10/11. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 33027-102-33027-161.

8510100037 Insp Rept 50-245/85-15 on 850617-28. Violations noted: failure to provide adequate written procedures for two specific safety-related activities & failure to follow station procedures. CHUNG, J.W., PULLAN, S., BISSETT, P.H. Region 1, Office of Director. EB-80-25. 8/10/03. 4pp. 33027-114-33027-161.

8510100090 Advises that unit will provide results of review & any requested info contained in update to SER (NUREG-0989), Section 13.5.2 re containment venting by 850731. BOOKER, J.E. Gulf States Utilities Co. RBG-22302. 85/10/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33023-356-33023-356.

8510100179 Ack receipt of FEMA findings re evaluation of State of MN & local emergency plans. Plans adequate. SHAVER, W.D. Region 3, Office of Director. 85/10/08. LARSON, C.E. Northern States Power Co. 2pp. 33021-287-33021-289.

8510100189 Advises that state & local plans for radiological emergencies adequate sub to criteria of App 3, Rev 1 to NUREG-0654/FEMA-REP-1 & FEMA-43, "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants." SPECK, S.W. Federal Emergency Management Agency. 85/09/24. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33021-289-33021-289.

8510100184 Forwards comments re review of unit public info brochures. Info packet reviewed against NUREG-0654 requirements & determined to meet guidelines. KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33021-243-33021-245.

8510100245 Comments on draft NUREG-0956, "Reassessment of Technical Basis for Estimating Source Term." Technical differences between DORDR & NRC severe accident models should be resolved prior to regulatory application of source term. DALE, L.F. Mississippi Power & Light Co. AECM-85-0325. 85/10/07. Docketing & Services Branch. 8pp. 33022-227-33022-232.

8510100283 Forwards comments on NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Recommends NRC take advantage of recent studies which reflect many upgrades in industry resulting in more reliable grids & switchgear. WELLS, R.W. C-E Operating Plants Owners Group. WELLS, R.W. Northeast Utilities. RWW-85-71. 85/10/11. KRIEL, K. Division of Safety Technology. 13pp. 33024-355-33025-005.

316 NONDOCKETED ITEMS

- 8510180320** Summary of 850912 meeting w/utl re DCROR program plan & implementation. List of meeting attendees & agenda encl.
GRÖTEHUIS, M. Operating Reactors Branch 2. 85/10/10. Operating Reactors Branch 2. App. 33028-172-33028-260.
- 8510180325** Summary of 850925 meeting w/utl, Delian Corp. & Impell Corp at facility site re: auxiliary feedwater sys improvements & reliability analyses. Viewgraphs & list of meeting attendees encl.
MCCRACKEN, C. Operating Reactors Branch 4. 85/10/09. Operating Reactors Branch 4. 9pp. 33038-300-33038-329.
- 8510180329** Forwards "Prioritization Evaluation, Generic Issue 97, 'PWR Reactor Cavity Uncontrolled Exposures.'" Generic Issue 97 assigned resolved priority ranking. Encl. evaluation will be incorporated into NUREG-0933, "Prioritization of Generic..."
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/10/07. BERNERO, J.M. Division of Systems Integration (post 011005). 2pp. 33028-349-33028-351.
- 8510180332** "Prioritization Evaluation, Generic Issue 97, 'PWR Reactor Cavity Uncontrolled Exposures.'" * NRC - No Detailed Affiliation Given. 84/11/09. 5pp. 33028-351-33028-355.
- 8510180344** Forwards Amend 126 to License DPR-49 & safety evaluation. Amend revises Tech Specs incorporating restrictions required by NUREG-0737, Item I.A.1.3.1 re overtime for plant operators.
THADANI, M.C. Operating Reactors Branch 2. 85/10/10. ILL. Iowa Electric Light & Power Co. 2pp. 33028-204-33028-201.
- 8510180347** Safety evaluation supporting Amend 126 to License DPR-49. * Office of Nuclear Reactor Regulation, Director. GL-83-02. 85/10/10. 2pp. 33028-300-33028-301.
- 8510170055** Informs that response to 850826 request for addl info on NUREG-0737, Item I.D.1 re adequacy of relief & safety valves installed on pressurizer will be provided on or before 850115.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-07. 85/10/14. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33036-349-33036-348.
- 8510170117** Forwards "Heavy Load Analysis Rept, Phase II" & revised "Heavy Load Analysis Rept, Phase I." per 841205 request to reevaluate control of heavy loads of 1 ton or more. Action items identified from repts listed.
WARENBURG, D.W. Public Service Co. of Colorado. P-85361. 85/10/15. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33039-050-33039-155.
- 8510170123** Revised "Heavy Load Analysis Rept, Phase I." * Sargent & Lundy, Inc. 85/10/15. 80pp. 33039-052-33039-109.
- 8510170127** "Heavy Load Analysis Rept, Phase II." * Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 47pp. 33039-110-33039-156.
- 8510170129** Advises that based on review of 841210 response & info obtained in 850313 meeting re TMI Item I.K.3.25, operator action to reinstate seal cooling acceptable. NRC believes automatic reinstitution of seal cooling preferable.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/07. GRIFFIN, J.M. Arkansas Power & Light Co. 7pp. 33043-171-33043-177.
- 8510170223** Forwards proprietary Amend 13 to Rev 6 to NED-24011-P.A. "GE Std Application for Reactor Fuel." Amend completes documentation commitments per NUREG-0396. Amend withheld (ref 10CFR2.790).
CHAPIN, J.S. General Electric Co. MFN 119-85. 85/10/03. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 33039-195-33039-195.
- 8510170230** NUREG/OP-0071 TRANSACTIONS OF THE THIRTEENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING.
WEISS, A.J. Office of Nuclear Regulatory Research, Director. FIN A-5283. 85/10/31. 200pp. 33046-076-33046-351.
- 8510170291** Supplemental application for amend to License DPR-49, clarifying footnotes & correcting typos in Tech Spec Tables 3.2-H & 4.2-H re accident monitoring instrumentation per Generic Ltr 83-36, "NUREG-0737 Tech Specs."
MCGAUGHY, R.W. Iowa Electric Light & Power Co. NG-85-4408. 85/10/11. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 33043-047-33043-053.
- 8510170353** Proposed Tech Spec clarifying footnotes & correcting typos in Tech Spec Tables 3.2-H & 4.2-H re accident monitoring instrumentation per Generic Ltr 83-36, "NUREG-0737 Tech Specs." * Iowa Electric Light & Power Co. GL-83-36. 85/10/11. 8pp. 33043-048-33043-053.
- 8510170284** Forwards Rev 3 to NRC Regulations Handbook (NUREG/BR-0053). Revs reflect NRC regulations re notice & comment provisions of Administrative Procedure Act & recently implemented regulatory history procedures.
PHILIPS, J. Division of Rules and Records. 85/09/24. NRC - No Detailed Affiliation Given. 75pp. 33044-297-33044-035.
- 8510170398** Requests addl info re draft NUREG-0956 & extension of comment period to 90 working days in order to comment on urgent matters re emergency relief petitions.
REYTBLETT, Z. Illinois Institute of Technology, Chicago, IL. 85/09/23. ROSS, D.F. NRC - No Detailed Affiliation Given. 1p. 33046-352-33046-357.
- 8510170403** Requests that CRGR revert decision to allow public comment on draft reg guide independently developed draft reg guide should be submitted for public comment.
REYTBLETT, Z.V. Illinois Institute of Technology, Chicago, IL. 85/04/23. STELLO, V. Regional Operations & Generic Requirements. 3pp. 33046-353-33046-357.
- 8510180034** Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Draft contains errors & internal inconsistencies. Withdrawal of draft recommended until industry questions resolved.
WILLIAMS, J.W. Florida Power & Light Co. Ltr 85-394. 85/10/15. DENTON, H. Office of Nuclear Reactor Regulation, Director. 8pp. 33054-011-33054-016.
- 8510180052** Forwards equipment qualification summary sheet for equipment identified to be noncritical to Unit 1 equipment per SSER 5 (NUREG-0857).
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). ANPP-33671-EVB. 85/10/07. KNIGHTON, G.W. Licensing Branch 3. 3pp. 33059-285-33059-287.
- 8510180135** Requests addl info re qualification program for safety-related mechanical equipment, including plug valves & hydraulic snubbers to continue review of application for license.
YOUNGBLOOD, B.J. Licensing Branch 1. 85/10/16. CPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 33069-272-33069-274.
- 8510180171** Requests that encl documents re regulatory history on proposed revs to 10CFR73.71 for reporting requirements for safeguards events be placed in Document Control Sys.
YARDUMIAN, J. Reactor & Transportation Licensing Branch. AB46-1 01. 85/10/09. GARTNER, D. Division of Technical Information & Document Control. 1p. 33078-041-33078-253.
- 8510180177** Informs that containment atmosphere monitoring sys installed & turned over to utl startup manager for preoperational testing on 850930, per SER Confirmatory Issue 31 & SSER 4.
SPANENBERG, F. Illinois Power Co. U-600291. 85/10/16. BUTLER, W.R. Licensing Branch 2. 1p. 33059-346-33059-346.
- 8510180187** Comments on NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms." NUREG supports view that use of source terms for regulatory purposes overestimated.
LEVENSON, M. Bechtel Corp. 85/10/10. Docketing & Services Branch. 7pp. 33062-316-33062-322.
- 8510180189** Forwards response to FSAR or draft SER items, including items D 4.4-3 re loose parts monitoring sys per Rev 1 to Reg Guide 1.133 & D 12.3-4 re containment radiation monitors per NUREG-0737, Item I.F.1.3.
WISENBURG, M.R. Houston Lighting & Power Co. ST-HL-AE-1419. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 8pp. 33062-302-33062-310.
- 8510180203** Requests extension on public comment period for NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms," from 90 to at least 180 days. Extension would enable review & public comment by organization.
BUSH, B.S. Coalition for Responsible Energy Education. 85/10/05. Docketing & Services Branch. 1p. 33059-341-33059-341.
- 8510180211** Comments on draft NUREG-1022, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Blackouts not an issue warranting resolution by rulemaking. Technical record indicates industry as whole presently safe enough.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-06. 85/10/14. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33062-301-33062-301.
- 8510180262** Forwards response to draft SER & FSAR items re Chapter 7A, Item I.B.3 concerning post-accident sampling capability. Marked-up FSAR pages to be included in future FSAR amend also encl.
WISENBURG, M.R. Houston Lighting & Power Co. ST-HL-AE-1388. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 47pp. 33061-317-33061-363.
- 8510180537** Proposed summary of ACRS Class 9 Accidents Subcommittee 850601 meeting in Washington, DC re NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms." List of attendees provided.
* ACRS - Advisory Committee on Reactor Safeguards. 85/6/17. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 33077-269-33077-273.
- 8510210015** Informs that utl completed compliance analysis review & identified need for listed variance requests for NUREG-0737, Action Plan Item S.F.1 re addl accident monitoring instrumentation. Variance requests encl.
SPANENBERG, F. Illinois Power Co. U-600345. 85/10/17. BUTLER, W.R. Licensing Branch 2. 10pp. 33074-133-33074-142.
- 8510210077** Informs that licensee in final stages of PRA evaluation of emergency feedwater sys (EFS) per 841218 R-Schedule for submittal of evaluation will be provided after review of NRC generic ltr re EFS reliability for PWRs.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 3F1085-08. 85/10/16. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33072-282-33072-282.
- 8510210093** Application for amend to License DPR-3, changing Tech Specs re containment pressure monitor, containment water level monitor & instrumentation for detection of inadequate core cooling (ref NUREG-0737, Items S.F.1 & S.F.2). Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. FYR 85-108. 85/10/15. Office of Nuclear Reactor Regulation, Director. App. 33072-142-33072-153.
- 8510210099** Proposed Tech Spec changes revising Table 3.3-4, "Radiation Monitoring Instrumentation," Table 4.3-3, "Radiation Monitoring Instrumentation Surveillance Requirements," & Tech Spec 3.3.3.2, "Instrumentation-In-Core Detection Sys." * Yankee Atomic Electric Co. 85/10/15. 8pp. 33072-146-33072-153.
- 8510210119** Application for amend to License DPR-3, revising Tech Specs to accommodate mods to RCS vent sys valve power supplies. Fee paid.
HEIDER, L.H. Yankee Atomic Electric Co. FYR 85-110. 85/10/15. Office of Nuclear Reactor Regulation, Director. App. 33073-303-33073-307.
- 8510210120** Proposed Tech Specs reflecting mods to RCS vent sys valve power supplies. * Yankee Atomic Electric Co. 85/10/15. 2pp. 33073-304-33073-307.
- 8510210123** Requests extension to complete commitments for Reg Guide 1.97 & Suppl 1 to NUREG-0737 re SPDS in response to 840614 confirmatory order. Several items cannot be completed before resuming power operation.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-883. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 8pp. 33072-243-33072-248.
- 8510210149** Submits schedule for upgrades to plant instrumentation per requirements of Suppl 1 to NUREG-0737 Rev 2 to Reg Guide 1.97 & Generic Ltr 84-29. Mods will not be fully implemented until 1988 Cycle 510 refueling outage.
MCGAUGHY, R.W. Iowa Electric Light & Power Co. NG-85-4481. 85/10/16. DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 33071-142-33071-144.
- 8510210155** Forwards Insp Rept 50-247/85-23 on 850901-30 No violation observed.
COLLINS, S.J. Region 1, Office of Director. 85/10/17. SELMAN, M. Consolidated Edison Co. of New York, Inc. 8pp. 33071-128-33071-137.

- 8510210156 Insp Rept 50-247/85-23 on 850901-30. No violation identified. Major areas inspected: onsite activities, including operational safety verification, maintenance, review of monthly rept, TMI action items & security event. LIMOTH, D., NORRHO, L. Region 1, Office of Director. 85/10/07. 8pp. 33071-130-33071-137.
- 8510210239 Forwards review comments re info packet, "Important Emergency Info." Info packet adequately meets requirements of NUREG-0654/FEMA REP-1, Rev 1. KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.J. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33079-337-33079-339.
- 8510220031 Summary of ACRS Subcommittee on Human Factors 850917-18 meetings & tour re implementation & review of requirements of Suppl 1 to NUREG-0737, including emergency operating procedures. List of attendees encl. * ACRS - Advisory Committee on Reactor Safeguards. 85/10/10. ACRS - Advisory Committee on Reactor Safeguards. 18pp. 33098-257-33098-274.
- 8510220064 Forwards SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985. Meeting scheduled on 851025 to discuss assessments & plans for performance improvement. MURLEY, T.E. Region 1, Office of Director. 85/10/11. SELMAN, M. Consolidated Edison Co. of New York, Inc. 2pp. 33095-180-33095-228.
- 8510220069 SALP Rept 50-247/85-99 for Aug 1984 - Jul 1985. * Region 1, Office of Director. 85/10/11. 46pp. 33095-182-33095-228.
- 8510220098 Forwards comments endorsing Nuclear U8 Group on Station Blackout power comments on NUREG-1032. Any rulemaking should be delayed until other power-related issues resolved. ALEXANDER, G. Commonwealth Edison Co. 0788K. 85/10/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33090-151-33090-153.
- 8510220174 Forwards Rev 1 to "Progress on Selected Regulatory Projects, San Onofre Unit 1," covering long-term seismic upgrading, fire protection & Suppl 1 to NUREG-0737, per 850919 ft. MEDFORD, M.O. Southern California Edison Co. 85/10/18. ZWOLINSKI, J.A. Operating Reactors Branch 5. 3pp. 33090-060-33090-062.
- 8510220183 Forwards most significant comments from first-cut comments contained in Westinghouse Owners Group 851001 ft re Rev 5 to NUREG-0452, "STS for Westinghouse PWRs." Requests meeting w/NRC to discuss incorporation of Tech Spec improvements. BUTTERFIELD, L. Westinghouse Operating Plants Owners Group. BUTTERFIELD, L. Commonwealth Edison Co. 08161. 85/10/17. THOMPSON, H. NRC - No Detailed Affiliation Given. 15pp. 33090-037-33090-051.
- 8510220191 Forwards response to questions raised during 850905 telecon re util 851206 proposed changes to Tech Specs, per NUREG-0737. Justification of discrepancies between proposal & guidance of Generic Ltr 83-36 provided. BRONIS, J.C. New York Power Authority (formerly Power Authority of the State of New York). GL-83-36. 85/10/18. VASSALLO, D.B. Operating Reactors Branch 2. 5pp. 33087-317-33087-321.
- 8510220277 Forwards Safety Insp Rept 50-293/85-26 on 850820-0923 & notice of violation. WENZINGER, E.C. Region 1, Office of Director. 85/10/17. HARRINGTON, W.D. Boston Edison Co. 2pp. 33085-136-33085-156.
- 8510220284 Insp Rept 50-293/85-26 on 850820-0923 Violation noted: failure to take corrective action to ensure that reactor operator overtime properly authorized. MCBRIDE, M., TRIPP, L. Region 1, Office of Director. 85/10/10. 18pp. 33085-139-33085-156.
- 8510220295 Forwards review of integrated safety assessment program Topic 1.36, "Tech Specs Covered by Generic Ltr 83-36," per 850517 commitment. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. 811800. 85/10/15. GRIMES, C.I. Systematic Evaluation Program Branch. 3pp. 33086-310-33086-314.
- 8510220300 Advises that info & analysis of NUREG-1032, "Station Blackout," does not provide adequate technical basis for rulemaking. Both frequency & total number of off-site power loss events declined indicating station blackout not issue. MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 85/10/09. KNIEL, K. Division of Safety Technology. 1p. 33083-328-33083-329.
- 8510220328 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Logical basis for dividing nuclear power plants into generalized groups must be shown before any conclusions can be drawn. RUFHAM, J.W. Tennessee Valley Authority. 85/10/11. KNIEL, K. Division of Safety Technology. 4pp. 33086-274-33086-277.
- 8510220330 Forwards application for amendment to License DPR-64, extending completion date for 850318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Fee paid. BRONIS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 85-55. 85/10/17. VARGA, S.A. Operating Reactors Branch 1. 4pp. 33083-071-33083-074.
- 8510220337 Application for amendment to License DPR-64, requesting extension of completion date for 850318 confirmatory order re implementation of requirements of NUREG-0737, Item III.D.3.4, "Control Room Habitability." Safety evaluation encl. * New York Power Authority (formerly Power Authority of the State of New York). 85/10/17. 8pp. 33083-075-33083-080.
- 8510220351 Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Conclusions in NUREG-1032 re likelihood of station blackout event & consequences overly conservative. SCHERER, A.E. Combustion Engineering, Inc. LD-85-048. 85/10/14. KNIEL, K. Division of Safety Technology. 1p. 33086-337-33086-337.
- 8510220362 Submits comments on issuance & availability draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." NUREG developed w/o consideration of NRC & industry activities. EDELMAN, M.R. Atomic Industrial Forum. 85/10/18. KNIEL, K. Division of Safety Technology. 2pp. 33084-274-33084-275.

- 8510220421 Forwards SALP Rept 50-219/85-99 for May 1984 - June 1985. Meeting scheduled for 851028 to discuss assessment & plans for performance improvement. MURLEY, T.E. Region 1, Office of Director. 85/10/11. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33097-069-33097-131.
- 8510220423 SALP Rept 50-219/85-99 for May 1984 - June 1985. * Region 1, Office of Director. GL-83-28. 85/10/11. 61pp. 33097-071-33097-131.
- 8510230014 Advises that State of LA & local plans & preparedness for facility adequate to protect health & safety of public. Approval conditional on verification of alerting & notification sys, per NUREG-0654/Rev 1 to FEMA REP-1, App 3. SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33101-347-33101-347.
- 8510230016 Responds to FOIA request for all correspondence provided to & received from Congress re pending or escalated enforcement action against any reactor licensee or applicant since 840101. Encl app documents also available in FOIA. FELTON, J.M. Division of Rules and Records. 85/10/04. JACOBS, R. Washington Document Service. 7pp. 33108-264-33108-268.
- 8510230129 Forwards NRC enforcement policy table of 1983 proposed civil penalties, including licensees, amounts proposed & amounts imposed or paid, supps to enforcement policy authorizing penalties & four vols of NUREG-0940 W/c NUREG-0940. AXELRAD, J.A. Enforcement Staff. 84/04/18. GINN, N. Senate, Governmental Affairs. 12pp. 33108-347-33108-358.
- 8510240002 Requests extension for providing addl info requested in 850822 ft re NUREG-0737, Item III.D.1, "Testing of Safety Relief Valves." Response to Questions 1-6 will be provided by 851115. CAREY, J.J. Duquesne Light Co. 85/10/14. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33155-189-33155-190.
- 8510240062 Forwards draft NUREG-1152, "Milestone 3 Risk Evaluation Rept." Rept documents results of review of probabilistic safety study. Four improvements identified which could result in addl protection of public health & safety. NOVAK, T.M. Assistant Director for Licensing. 85/10/17. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 20pp. 33163-160-33163-164.
- 8510240107 Forwards Insp Rept 50-458/85-60 on 850909-13. No violation or deviation noted. JOHNSON, E.H. Region 4, Office of Director. 85/10/11. CAHILL, W.J. Gulf States Utilities Co. 2pp. 33156-274-33156-277.
- 8510240112 Insp Rept 50-458/85-60 on 850909-13. No violation or deviation noted. Major areas inspected: deficiency rept, TMI action items & fuel load witnessing. BENNETT, W.R., SKOW, M.E., JAUDON, J.P. Region 4, Office of Director. 85/10/09. 3pp. 33156-275-33156-277.
- 8510240123 Forwards draft Quarterly Rept NUREG/CR-4236 Vol 3, "Evaluation of Radiocesium Geochemical Info Developed by DOE High Level Nuclear Waste Repository Site Projects Rept for Apr-June 1985." JACOBS, G.K. Oak Ridge National Laboratory. FIN B-0290. 2472. 85/10/07. BRADBURY, J.W. Geotechnical Branch (Post 831001). 27pp. 33176-311-33176-337.
- 8510240147 "Effect of Repository Environ on Performance of Waste Package/Engineered Sys Components." monthly progress rept for Sept 1985. App D of draft Rev 1 to NUREG/CR-4134 & revised work plan being sent separately. WHATLEY, S.K. Oak Ridge National Laboratory. FIN B-0298. 2473. 85/10/07. CHANG, K.C. Engineering Branch (Post 831001). 2pp. 33180-326-33180-327.
- 8510240328 Forwards addl info re schedules for corrective actions of human engineering discrepancies noted during onsite audit of TCRDR program. Detailed justification & schedule for accepted discrepancies will be provided by 850418. ENOS, J.T. Arkansas Power & Light Co. 1CAN108510. 85/10/18. THOMPSON, H.L. Division of Licensing. 8pp. 33151-351-33151-358.
- 8510240331 Forwards objectives for 1985 emergency preparedness exercise scheduled for 851018. Objectives developed in conjunction w/States of NE & MO. Joint agency meeting scheduled for 850820. PLANT, J.M. Nebraska Public Power District. NLS8500197. 85/08/01. MARTIN, R.D. Region 4, Office of Director. 12pp. 33151-33C-33151-350.
- 8510240385 Forwards Rev 0 to Plant Emergency Procedure PEP-355, "Core Damage Assessment," per util 850624 commitment. Procedure incorporates Westinghouse Owners Group methodology re use of post-accident sampling sys, per TMI Action Item I.B.3. ZIMMERMAN, S.R. Carolina Power & Light Co. TAC 44474. 85/10/21. VARGA, S.A. Operating Reactors Branch 1. 1p. 33149-092-33149-159.
- 8510240444 Forwards addl info re 840402 submittal on Section 6 of Suppl 1 to NUREG-0737, "Reg Guide 1.97 Application to Emergency Response Facilities," requested in NRC 850613 re Existing instrumentation meets needs for post-accident monitoring. MANGAN, C.V. Niagara Mohawk Power Corp. GL-82-33. 85/10/18. VASSALLO, D.B. Operating Reactors Branch 2. 25pp. 33149-011-33149-035.
- 8510240525 Ack receipt of Aug 1985 progress rept for FIN B-0298 & draft Rev 1 to NUREG/CR-4134, "Repository Environ Parameters re Assessing Performance of High Level Waste Packages in Basalt, Tuff & Salt." Comments expected by 851031. CHANG, K.C. Engineering Branch (Post 831001). FIN B-0298. 2457. 85/09/25. WHATLEY, S.K. Oak Ridge National Laboratory. 2pp. 33177-348-33177-349.
- 8510250025 Requests addl info in order to complete review & evaluation & respond to util 850911 request re Rev 2 to SER for heavy load handling. Insite containment, including plans for meeting kelt criterion. TRAVERS, W.D. TMI Program Office. NRC/TMI-85-078. 85/10/18. STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 1p. 33226-034-33226-034.
- 8510250093 Revis to emergency plan manual (NUREG-0654) including Pages 20 & 21 of Rev 18 to AP 500 re offsite emergency organization & Rev 2 to AP 526, "Sabotage or Civil Disturbance." * Sacramento Municipal Utility District. 85/10/18. 13pp. 33226-071-33226-083.

318 NONDOCKETED ITEMS

- 8510250161** Forwards Safety Insp Rept 50-219/85-26 on 850819-0922. No violation noted.
KISTER, H.B. Region 1, Office of Director. 85/10/16. FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 2pp. 33190:028-33190:041.
- 8510250171** Insp Rept 50-219/85-26 on 850819-0922. No violation noted. Major areas inspected: plant operations, physical security, radiation control, housekeeping, chemistry. Part 21 repts & status of NUREG-0737 items.
BATEMAN, W.H., WECHSELBERGER, URBAN, J.H. Region 1, Office of Director. 85/10/16. 12pp. 33190:030-33190:041.
- 8510250209** Identifies equipment required to be intrinsically qualified not identical to previously identified Unit 1 equipment, per 851007 & SSER 5 (NUREG-0857) dtd Nov 1983. Equipment qualification summary sheets encl.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), ANPP-33799-EEVB. 85/10/23. KNIGHTON, G.W. Licensing Branch 3. 8pp. 33169:138-33169:143.
- 8510250239** Forwards responses to Questions 2-5 contained in 850424 request for add info re NUREG-0737, item I.D.1, "Performance Testing of Relief & Safety Valves."
OTOOLE, J.D. Consolidated Edison Co. of New York, Inc. 85/10/18. VARGA, S.A. Operating Reactors Branch 1. 12pp. 33172:103-33172:116.
- 8510250259** Notification of Licensee Meeting 85-105 on 851030 w/ util in King of Prussia, PA to discuss licensee action re NUREG-0737, item I.D.3.4, "Control Room Habitability."
NORRHOLM, L.J. Region 1, Office of Director. 85/10/18. Region 1, Office of Director. 1p. 33170:360-33170:360.
- 8510250341** Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants," to resolve USI A-44. NUREG does not provide sufficiently accurate analysis of station blackout situation.
EDWARDS, D.W. Yankee Atomic Electric Co. GLA 85-124. 85/10/21. KNIEL, K. Division of Safety Technology. 2pp. 33172:148-33172:149.
- 8510250354** Forwards control room emergency HVAC sys repts & test results, per 850404 meeting & 850603 ltr re NUREG-0737, item I.D.3.4, "Control Room Habitability." Results indicate control room habitability.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 5211-85-2172. 85/10/18. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33166:304-33167:166.
- 8510250364** TDR 728 R00 Rev 0 to "Evaluation of Capability of Control Bldg HVAC Sys to Maintain Post-Accident Habitable Environ in Control Room," technical data rept.
SANFORD, M. General Public Utilities Corp. - GPU Service Corp. 85/10/14. 43pp. 33167:015-33167:058.
- 8510250380** Change Sheet 2 to Rev 2 to Plant Manager Procedure PMP 2081 EPP.009, "Health Physics Mgt for Operations Staging Area," adding Step 3.3.5 to comply w/ NUREG 4937 requirements, NRC confirming order & PMI-4030 attachment.
* Indiana & Michigan Electric Co. 85/10/16. 4pp. 33172:179-33172:182.
- 8510250393** Comments opposing 851007 deadline for comment period for NUREG-0956 re reassessment of technical basis for estimating source term releases & health effects higher than NRC predictions. Extension of comment period requested.
LEWIS, M.I. Lewis, M. 85/10/21. Docketing & Services Branch. 2pp. 33172:286-33172:287.
- 8510250420** Forwards Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930. No violation noted.
WENZINGER, E.C. Region 1, Office of Director. 85/10/21. LUNDVALL, E.A. Baltimore Gas & Electric Co. 2pp. 33173:001-33173:018.
- 8510250435** Insp Repts 50-317/85-24 & 50-318/85-20 on 850815-0930. No violation noted. Major areas inspected: control room, plant structures, plant operations, radiation protection, physical security, maintenance, surveillance & emergency preparedness.
FOLEY, T. Region 1, Office of Director. IEB-80-11. 85/10/17. 16pp. 33173:003-33173:018.
- 8510250529** NUREG/CR-4382 CONCENTRATIONS OF URANIUM AND THORIUM ISOTOPES IN URANIUM MILLERS' AND MINERS' TISSUES.
WRENIN, M.E., SINGH, N.P., PASCHOA, A.S. Utah, Univ. of, Salt Lake City, UT. FIN A-2221. 85/09/30. Division of Radiation Programs & Earth Sciences (post 840429). 58pp. 33191:286-33191:344.
- 8510250531** NUREG/CR-4108 DEVELOPMENT OF MC&A ALARM RESOLUTION PROCEDURES.
SMITH, B.W. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2222. PNL-5154. 85/10/31. Division of Safeguards. 53pp. 33225:154-33225:207.
- 8510250566** Forwards SER conditionally supporting response to procedures generation package. Items re primary containment pressure limit for venting guidance & DCRDR must be addressed.
BUTLER, W.R. Licensing Branch 2. 85/10/18. FARRAR, D.L. Commonwealth Edison Co. 3pp. 33226:349-33226:358.
- 8510250574** SER conditionally supporting response to procedures generation package.
* NRC - No Detailed Affiliation Given. GL-83-05. 85/10/18. 7pp. 33226:352-33226:358.
- 8510250583** NUREG/BR-0051 V07 N2 POWER REACTOR EVENTS, MARCH-APRIL 1985.
MASSARO, S.A. AEOD, Director's Office. 85/10/31. 61pp. 33191:228-33191:285.
- 8510280060** Forwards safety evaluation & Science Applications Intl Corp technical evaluation rept re 850401, 0502 & 0615 submittals for DCRDR. DCRDR incomplete. Submittal of listed info for review & approval required within 60 days of ltr receipt.
BUTCHER, E.J. Operating Reactors Branch 3. 85/10/17. ANNE, J.E., S.R.L. Omaha Public Power District. 3pp. 33241:137-33241:196.
- 8510280069** Safety evaluation re util 850401, 0502 & 0615 submittals for DCRDR. DCRDR incomplete. Listed activities must be completed to satisfy requirements of Suppl 1 to NUREG-0737. Preimplementation audit may be necessary.
* Office of Nuclear Reactor Regulation, Director. 85/10/17. 12pp. 33241:140-33241:151.
- 8510280074** "Technical Evaluation of DCRDR for Ft Calhoun Station."
* Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-82-096. 85/08/28. Division of Human Factors Safety. 45pp. 33241:152-33241:196.
- 8510280126** Responds to NRC 850530 requests to include independent onsite safety review group & vice president of each nuclear div in inline LER review. Add reviewers unnecessary. Review exceeds Generic Ltr 84-43 & Rev 3 to NUREG-0123.
FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. GL-84-43. 85/10/21. ZWOLINSKI, J.A. Operating Reactors Branch 5. 2pp. 33191:058-33191:059.
- 8510280330** Comments on draft NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Discussion re misleading reporting of loss of offsite power & HL Wyckoff 830923 memo also encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. 85/07/05. NRC - No Detailed Affiliation Given. 7pp. 33193:005-33193:011.
- 8510280338** Forwards Safety Insp Rept 50-220/85-12 on 850701-0906 & notice of violation.
COLLINS, S.J. Region 1, Office of Director. 85/10/23. MANGAN, C.V. Niagara Mohawk Power Corp. 2pp. 33193:241-33193:253.
- 8510280348** Insp Rept 50-220/85-12 on 850701-0906. Violation noted: failure to lock open manual valve in core spray sys when sys restored to svc after maint.
LINVILLE, J.C. Region 1, Office of Director. GL-84-09. 85/10/21. 10pp. 33193:244-33193:253.
- 8510280360** Advises that review of util files indicated that actions required to closeout IE Bulletin 79-04 accomplished, contrary to NUREG/CR-4003. Weight discrepancies subsequently found acceptable as part of bulletin review.
WHITTIER, G.D. Maine Yankee Atomic Power Co. MN-85-165. 85/10/22. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33194:006-33194:007.
- 8510280439** Grants extension of completion date until Mar 1986 for compliance w/ Commission 840702 order re submittal of DCRDR summary rept & proposed implementation schedule, per 850521 request.
THOMPSON, H.L. Division of Licensing. 85/10/16. FAY, C.W. Wisconsin Electric Power Co. 3pp. 33196:303-33196:305.
- 8510280470** NUREG/CR-4146 SIMULATION OF AN EPR-NEVADA TEST SITE (NTS) HYDROGEN BURN TEST AT THE CENTRAL RECEIVER TEST FACILITY.
DANDINI, V.J., ARAGON, J.J. Sandia National Laboratories. FIN A-1270. SAND85-0205. 85/10/31. Office of Nuclear Regulatory Research, Director. 77pp. 33228:002-33228:079.
- 8510290088** Discusses delay in mod schedule for fuel handling bldg crane interlocks. Delay due to vol of restart work. Mod completion rescheduled for Dec 1985.
HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 5211-85-2175. 85/10/24. STOLZ, J.F. Operating Reactors Branch 4. 1p. 33236:016-33236:016.
- 8510290109** Requests permission to use damping values given in ASME Code Case N-411 as recommended in NUREG-1061. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-705. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 33235:294-33235:295.
- 8510290121** Forwards addendum to FEMA findings on offsite radiological emergency response plans. Addendum resolves NUREG-0654/REP-1, Rev 1 planning elements. Approval conditional on verification of alert & notification sys.
JOHNSON, E.H. Region 4, Office of Director. 85/10/23. LEDDICK, R.S. Louisiana Power & Light Co. 2pp. 33235:261-33235:263.
- 8510290197** Application for amends to Licenses NPF-4 & NPF-7, revising FSAR damping values used for seismic analysis of piping to be consistent w/ ASME Code Case N-411 damping values recommended in NUREG-1061. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-706. 85/10/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. BUTCHER, E.J. Operating Reactors Branch 3. 2pp. 33236:204-33236:205.
- 8510290235** Forwards response to 850910 request for add info re SPDS, including "SPDS Operator Training Program Outline for Man-In-The-Loop Validation" & "SPDS Man-In-The-Loop Validation Scenarios."
OPEKA, J.F., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. A02959. 85/10/16. YOUNGBLOOD, B.J. Licensing Branch 1. 11pp. 33233:258-33233:281.
- 8510290252** Forwards Rev 16 to Procedure 116, "Surveillance Test Program," in response to SEP Integrated Plant Safety Assessment Rept (NUREG-0822), Section 4.26.2, "Instrumentation for Reactor Trip Testing."
FIEDLER, P.B. General Public Utilities Corp. - GPU Service Corp. 85/10/22. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33236:284-33236:335.
- 8510290316** Comments on NUREG-1032, "Evaluation of Station Blackout Accidents at Nuclear Power Plants." Nuclear Util Group on Station Blackout comments that station blackout issue does not warrant rulemaking supported.
THORPE, J.R. General Public Utilities Corp. - GPU Service Corp. 85/10/15. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33236:248-33236:248.
- 8510290351** Forwards corrected Page 49 to evaluation of Rev 5 of LILCO transition plan for offsite emergency preparedness at facility. Error noted in section dealing w/ NUREG-0654, Element J 12.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/24. JORDAN, W.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 4pp. 33236:355-33236:358.
- 8510290352** "Fort St Vrain Nuclear Generating Station Heavy Load Analysis, Phase II."
* Sargent & Lundy, Inc. * TENERA Corp. (subs. of TERA Corp.). 85/10/15. 46pp. 33240:015-33240:060.
- 8510290366** "Fort St Vrain Nuclear Generating Station Heavy Load Analysis Phase I."
* Sargent & Lundy, Inc. 85/10/15. 58pp. 33240:260-33240:317.
- 8510290367** Forwards "Preservice Insp Summary Rept for Reactor Pressure Vessel," as partial response to NUREG-0991. Confirmatory issue 12 (Sections 5.2.4.3 & 6.6.3).
KEMPER, J.S. Philadelphia Electric Co. 85/10/22. BUTLER, W.R. Licensing Branch 2. 2pp. 33234:097-33234:333.

8510290381 Comments on NUREG-0956, "Reassessment of Technical Bases for Estimating Source Terms." Nuclear community has enough info to identify potential changes to regulations. Commission should implement process by which changes can be codified.
WILLIAMS, J.W. Florida Power & Light Co. L-85-383. 85/10/22. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33234-362-33234-362.

8510290410 NUREG/CR-4350 V04 PROBABILISTIC RISK ASSESSMENT COURSE DOCUMENTATION, Volume 4 - System Reliability And Analysis Techniques, Sessions B/C - Event Trees/Fault Trees.
HAAS, L.D. Institute of Systems Sciences. YOUNG, J. Energy, Inc. * Sandia National Laboratories. FIN A-1321. SAND85-1495. 85/10/31. Division of Risk Analysis & Operations (post 840429). 143pp. 33259-151-33259-294.

8510290415 NUREG-1046 DISPOSAL OF HIGH-LEVEL RADIOACTIVE WASTES IN UNSATURATED ZONE: TECHNICAL CONSIDERATIONS AND RESPONSE TO COMMENTS.
HACKBARTH, C.J., NICHOLSON, T.J., EVANS, D.D. Division of Radiation Programs & Earth Sciences (post 840429). 85/10/31. 49pp. 33259-295-33259-343.

8510290425 Forwards comments & requests for addl info re emergency plan meteorological models & cose protection sys & comments on evacuation time estimates, emergency classification sys & emergency preparedness implementation appraisal.
ADENSAME, E.G. Licensing Branch 4. 85/10/22. FOSTER, D.O. Georgia Power Co. 3pp. 33258-282-33259-014.

-8510290429 Discusses review of 850701 submittal of addl info. Data provided substantiates reasonableness of estimates for facility. Estimates not done per NUREG-0654 guidance. Summary of evacuation time estimate review encl.
URBANIK, T. Texas Transportation Institute, Texas A&M Univ., College Station, TX. 85/08/21. WILLIAMS, E.F. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 33258-285-33258-286.

-8510290431 "Vogtle Emergency Classification Sys."
* Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/30. NRC - No Detailed Affiliation Given. 17pp. 33258-287-33259-014.

8510290574 NUREG-1057 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BEAVER VALLEY POWER STATION, UNIT 2. Docket No. 50-412 (Duquesne Light Company et al).
* Division of Licensing. 85/10/31. 639pp. 33261-001-33261-280.

8510300235 Transcript of Commission 851022 briefing on status of safety goal evaluation in Washington, DC. Pp 1-82. Viewgraphs incl.
* Commissioners. 85/10/22. 91pp. 33262-129-33262-219.

8510310003 Forwards SSER 12 (NUREG-0797). Resolution of outstanding issues re fire protection program including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 33277-103-33277-107.

8510310019 Grants extension of completion date for submittal of NUREG-0737, Suppl 1, Item 2.b re DCRDR summary report from 851115 to 860228, per 850807 request. Extension will not impact overall completion schedule.
THOMPSON, H.L. Division of Licensing. 85/10/23. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 33277-130-33277-131.

8510310211 Forwards addl info in response to NRC 850819 request on 841030 response to Generic Ltr 82-33 re conformance to Rev 3 to Reg Guide 1.97, Suppl 1 to NUREG-0737.
MURPHY, W.P. Vermont Yankee Nuclear Power Corp. FVY-85-99. 85/10/25. VASSALLO, D.B. Operating Reactors Branch 2. 10pp. 33273-163-33273-172.

8510310248 Submits addl info re NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves." New middle ring setting for Unit 1 will be changed to .50 during end of Cycle 10 refueling outage scheduled to begin on 870920.
TUCKER, H.E. Duke Power Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33273-241-33273-241.

8510310325 Forwards Safety Insp Rept 50-346/85-34 on 851010-11. No violation noted.
SHAFER, W.D. Region 3, Office of Director. 85/10/25. WILLIAMS, J. Toledo Edison Co. 2pp. 33272-038-33272-047.

-8510310330 Insp Rept 50-346/85-34 on 851010-11. No violation or deviation noted. Major areas inspected: emergency preparedness program, licensee procedures & training program for licensed operators re reporting of events to operations ctr.
PLOSKE, T. PHILLIPS, M. Region 3, Office of Director. 85/10/24. 6pp. 33272-040-33272-047.

8510310352 Forwards SER (NUREG-1057) & related notice forwarded to Ofc of FR for publication. W/o SER.
KNIGHTON, G.W. Licensing Branch 3. 85/10/22. CAREY, J.J. Duquesne Light Co. 4pp. 33278-149-33278-154.

-8510310355 Notice of issuance & availability of SER (NUREG-1057).
KNIGHTON, G.W. Licensing Branch 3. 85/10/22. 2pp. 33278-153-33278-154.

8510310366 Responds to NUREG-0737, Item II.F.2, "Inadequate Core Cooling Instrumentation." Addl info re core exit thermocouple backup display & model reactor vessel level indication sys draft Tech Specs encl.
MUSOLF, D. Northern States Power Co. 85/10/22. Office of Nuclear Reactor Regulation, Director. 5pp. 33271-314-33271-318.

8510310448 NUREG-0946 AN EVALUATION OF RADIONUCLIDE CONCENTRATIONS IN HIGH-LEVEL RADIOACTIVE WASTES.
FEHRINGER, D.J. Division of Waste Management. 85/10/31. 34pp. 33278-231-33278-268.

8510310534 Submits implementation rpt re NUREG-0737, Item II.F.2, "Inadequate Core Cooling Instrumentation" per NRC 850906 ltr. Saturation margin meters installed before Refuel III & operational Pressure-Temp display added to SPDS.
WESTAFER, G.R. Florida Power Corp. (subs. of Florida Progress Corp.). 85/10/23. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 33280-043-33280-045.

8510310552 Forwards safety evaluation of 830812, 841228 & 850624 responses to NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys." Procedure for estimating core damage from fission measurements acceptable on interim basis.
VARGA, S.A. Operating Reactors Branch 1. TAC 44474. 85/10/04. UTLEY, E.E. Carolina Power & Light Co. 11pp. 33277-043-33277-053.

8510310595 Forwards safety evaluation identifying concerns re NUREG-0737, Item II.F.2 on final inadequate core cooling instrumentation sys. per util 840824 & 850305 responses to 840530 ltr. Further clarification required.
VARGA, S.A. Operating Reactors Branch 1. 85/10/17. FARRAR, D.L. Commonwealth Edison Co. 9pp. 33277-083-33277-091.

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8509260122 IE Info Notice 85-079, "Inadequate Communications Between Maint. Operations & Security Personnel" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/09/30. Consolidated Edison Co. of New York, Inc. 140pp. 32869-001-32869-060.

8509260369 Suppl 1 to IE Info Notice 85-017, "Possible Sticking of ASCO Solenoid Valves." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/01. Consolidated Edison Co. of New York, Inc. 135pp.

8510010060 Responds to FOIA request for records under Docket 40-8006 through June 1978, Docket 40-2038 through Mar 1963 & Docket 40-8027 for June 1972 - June 1973. Forwards App A & B documents. No records available for Docket 40-2038.
FELTON, J.M. Division of Rules and Records. 85/08/29. BARNES, C. Affiliation Not Assigned. 8pp. 32830-076-32831-085.

-8510010294 Forwards 1 Younghein 771001 ltr expressing Citizens Action for Safe Energy concern that EIS for UF6 facility expansion be prepared. Formal ack of concern requested. Related info encl.
SPOTTS, C.B. Environmental Protection Agency. 07958. 77/10/25. ROTHFLEISCH, J. Fuel Process. & Fab. Branch (Pre 790727). 3pp. 32831-064-32831-066.

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABEI, L. Government Accountability Project. 32pp. 32884-005-32884-734.

-8406150267 Requests that encl FEMA 840511 supplemental interim finding rpt on offsite plans be transmitted to util. Rept addresses four offsite planning issues specified by ASLB.
MATTHEWS, D.B. Emergency Preparedness Branch. 84/06/07. KNIGHTON, G.W. Licensing Branch 3. 3pp. 32893-319-32893-321.

-8408210595 Forwards RW Krimm 840725 ltr forwarding rpt on 840208 exercise of offsite radiological emergency preparedness plans for facility. Category B deficiencies identified.
MATTHEWS, D.B. Emergency Preparedness Branch. 84/08/16. BANGART, R.L. Region 4, Office of Director. 2pp. 32893-322-32893-323.

-8510010423 Advises that transportation support ltrs of agreement should be withheld from public due to proprietary nature, per 10CFR2.790. FEMA 840622 memo re supplemental findings encl.
COOK, K.W. Louisiana Power & Light Co. W3PB4-1960. 84/08/01. KNIGHTON, G.W. Licensing Branch 3. 4pp. 32893-324-32893-327.

8510040241 Summary of INPO/NRC 850912 quarterly coordination meeting in Atlanta, GA re licensing exams, training, radiological plan/ emergency plan activities & procedures. Tentative agenda & list of attendees encl.
JONES, D.B. Division of Human Factors Safety. 85/09/27. RUSSELL, W.T. Division of Human Factors Safety. 10pp. 32860-122-32860-136.

-8510040256 Trip rpt of INPO/NRC 850912 coordination meeting re Coordination Plan 3, "Coordination Plan for NRC/INPO Radiological Protection Activities." List of attendees provided. Summary of discussions encl.
SERBU, J.R. Radiological Assessment Branch. 85/09/17. MULLER, D.R. Assistant Director for Radiation Protection. 5pp. 32860-132-32860-136.

8510080068 Ack receipt of FEMA 850903 ltr & exercise evaluation of 850605 offsite emergency preparedness exercise involving State of MO & Counties of Gasconade, Callaway, Osage & Montgomery. No deficiencies identified.
SHAFER, W.D. Region 3, Office of Director. 85/09/30. SCHNELL, D.F. Union Electric Co. 2pp. 32928-210-32928-252.

8510080263 Forwards FEMA 850909 ltr & evaluation of 850521 offsite emergency preparedness exercise. No deficiencies affecting public health & safety identified.
SHAFER, W.D. Region 3, Office of Director. 85/10/02. DEWITT, R.B. Consumers Power Co. 2pp. 32913-226-32913-279.

8510080479 Ack receipt of FEMA 850829 ltr & final exercise evaluation of 850611-12 offsite emergency preparedness exercise involving State of IL & Ogle County. No deficiencies identified.
SHAFER, W.D. Region 3, Office of Director. 85/10/03. REED, C. Commonwealth Edison Co. 2pp. 32921-073-32921-103.

8510002447 Responds to 850429 ltr re emergency preparedness at nuclear power plants. Pre-distribution of potassium iodide pills to public not recommended. Framework for decisionmaking or source-term considerations should be complete by end of yr.
PALLADINO, N.J. Commissioners. 85/10/01. WILSON, R. Harvard Univ., Cambridge, MA. 1p. 32966-341-32966-352.

-8507050455 Responds to 841115 request re proposed draft federal policy statement on distribution & use of potassium iodide. Commission approved 850326 version. Encl draft should be distributed to state & local govts.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/06/24. KRIMM, R.W. Federal Emergency Management Agency. 9pp. 32966-342-32966-350.

320 NONDOCKETED ITEMS

- 8510100056** Forwards evaluation of "LILCO Transition Plan for Shoreham - Rev 5." Six inadequacies identified, including concerns re legal basis for plan authority & written agreements re operations concept.
SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 32959:318-32960:031.
- 8510100061** "LILCO Transition Plan for Shoreham - Rev 5." Concerns re legal authority identified during regional assistance committee review of Revs 3, 4 & 5 encl.
* Federal Emergency Management Agency. 85/09/23. 73pp. 32959:319-32960:031.
- 8510110043** Forwards "Evacuation Time Estimates for Clinton Power Station Plume Exposure Pathway Emergency Planning Zone," per Rev 1 to NUREG-0654/FEMA-REP-1, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans."
SPANGENBERG, F. Illinois Power Co. U-800292. 85/10/09. BUTLER, W.R. Licensing Branch 2. 2pp. 32968:191-32968:356.
- 8510150022** IE Info Notice 85-080, "Timely Declaration of Emergency Class Implementation of Emergency Plan & Emergency Notifications." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/15. Consolidated Edison Co. of New York, Inc. 132pp. 33177:205-33177:341.
- 8510150025** IE Info Notice 85-081, "Problems Resulting in Erroneously High Reading W/Panasonic 800 Series TLDs." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/17. Consolidated Edison Co. of New York, Inc. 70pp. 33177:001-33177:066.
- 8510150080** IE Info Notice 85-082, "Diesel Generator Differential Protection Relay Not Specially Qualified." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 85/10/18. Consolidated Edison Co. of New York, Inc. 136pp. 33177:069-33177:204.
- 8510160145** Advises that States of SC & NC local emergency plans & preparedness adequate to protect health & safety of public pending verification of alert & notification sys.
SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33022:271-33022:273.
- 8510160179** Ack receipt of FEMA findings re evaluation of State of MN & local emergency plans. Plans adequate.
SHAFFER, W.D. Region 3, Office of Director. 85/10/08. LARSON, G.E. Northern States Power Co. 2pp. 33021:287-33021:289.
- 8510160189** Advises that state & local plans for radiological emergencies adequate sub to criteria of App 3, Rev 1 to NUREG-0654/FEMA-REP-1 & FEMA-43, "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants."
SPECK, S.W. Federal Emergency Management Agency. 85/09/24. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33021:289-33021:289.
- 8510160184** Forwards comments re review of util public info brochures. Info packet reviewed against NUREG-0654 requirements & determined to meet guidelines.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33021:243-33021:245.
- 8510180483** Discusses staff interactions re geodetic measurements in northeastern US utilizing global positioning satellite (GPS) sys. Interagency agreement recommended for providing GPS receivers to Maine Geologic Survey.
BERTAN, L.L. Earth Sciences Branch (post 840429). 85/10/11. KAULA, W. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 4pp. 33077:316-33077:319.
- 8510212216** Forwards status rept on remaining offsite emergency preparedness licensing conditions, per 850925 request. Conditions identified in ASLB 850903 concluding partial initial decision.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/15. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 10pp. 33094:302-33094:311.
- 8510210239** Forwards review comments re info packet, "Important Emergency Info." Info packet adequately meets requirements of NUREG-0654/FEMA REP-1, Rev 1.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/08. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 33079:337-33079:339.
- 8510210258** Advises that radiological emergency response plan in support of fixed nuclear facilities approved. W/o ltr to NRC indicating approval of state & local plans & preparedness.
MORRIS, R.H. Federal Emergency Management Agency. 85/10/08. RILEY, R.W. South Carolina, State of. 1p. 33079:328-33079:328.
- 8510210263** Advises that emergency response plan approved, conditional upon verification of alert & notification sys. W/o ltr to NRC indicating approval of state & local plans & preparedness.
MORRIS, R.H. Federal Emergency Management Agency. 85/10/08. ARTIN, J. North Carolina, State of. 1p. 33079:327-33079:327.
- 8510230014** Advises that State of LA & local plans & preparedness for facility adequate to protect health & safety of public. Approval conditional on verification of alerting & notification sys. per NUREG-0654/Rev 1 to FEMA REP-1, App 3.
SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33101:347-33101:347.
- 8510230219** Forwards sections of State of CT radiological emergency response plan re medical svcs & similar sections from local plans within 10 mile emergency planning zone.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/18. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 150pp. 33100:216-33101:026.
- 8510290351** Forwards corrected Page 49 to evaluation of Rev 5 of LILCO transition plan for offsite emergency preparedness at facility. Error noted in section dealing w/ NUREG-0654, Element J 12.
KRIMM, R.W. Federal Emergency Management Agency. 85/10/24. JORDAN, W.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 4pp. 33236:355-33236:358.
- 8510310394** Response to applicant 851017 motion to exclude portions of encl G Wenger testimony on Rorem Contention 1(a). Related correspondence.
CHANEI, I. Hearing Branch 2. #485 973. OL 85/10/25. Atomic Safety and Licensing Appeal Panel. 2pp. 33272:001-33272:033.
- 8510310399** Testimony of G Wenger re Rorem Contention 1(a). Certificate of Svc encl. Related correspondence.
WENGER, G. Federal Emergency Management Agency. OL 85/10/25. Atomic Safety and Licensing Board Panel. 31pp. 33272:003-33272:033.

PR PROPOSED RULE

- 8510040294** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases of certain radionuclides. Criteria such as half-life, physical form & encapsulation should be considered in rule.
BANDY, T.R. Pro-Technics, Inc. 50FR23960 063. 85/09/17. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 4pp. 32854:218-32854:221.
- 8510040317** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials. Troxler moisture/density gauges should be exempt.
MAXFIELD, A.F. American Council of Independent Laboratories, Inc. 50FR23960 057. 85/09/25. Docketing & Services Branch. 2pp. 32853:263-32853:264.
- 8510040336** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases of certain radionuclides. Use of ir-192 isotopes suggested.
KRASHES, D. Massachusetts Materials Research, Inc. 50FR23960 064. 85/09/27. Docketing & Services Branch. 2pp. 32854:228-32854:229.
- 8510040352** Comments on proposed rules 10CFR30.21, 32.35 & 40 re usage of "dose" for amount of chemical administered & "dosage" for quantities of radioactivity. Use of term "absorbed dose" recommended.
ICE, R.D. Triar Enterprises. 50FR30616 010. 85/09/24. Docketing & Services Branch. 1p. 32853:273-32853:273.
- 8510040373** Package of four comments opposing proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements for cleanup of accidental or unexpected releases of radioactive materials.
CONNELL, G. X-Ray, Inc. ZANOTTI, A. White Farm Equipment Co. VAN SWEARINGEN Wake Forest Univ. Winston-Salem, NC. 50FR23960. 85/10/01. Docketing & Services Branch. 9pp. 32854:246-32854:254.
- 8510040383** Package of two comments opposing proposed rules 10CFR30.40, 61.70 & 72 re financial requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials.
HILL, W.T., BURROSS, D.C. Texas Medical Association (TMA). ENTINE, G. Radiation Monitoring Devices, Inc. 50FR23960. 85/09/30. Docketing & Services Branch. 2pp. 32853:357-32853:358.
- 8510040394** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental release of radioactive materials. Proposed rules fully endorsed. Two concerns discussed.
PETERSON, L. Adolph Coors Co. 50FR23960 065. 85/10/01. Docketing & Services Branch. 2pp. 32854:182-32854:183.
- 8510040405** Package of two comments opposing proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials.
SAVINI, R.J. Lixscope of America, Inc. SUMMERLEE, T.E. Thomas E. Summerlee & Associates, Inc. 50FR23960. 85/10/03. Docketing & Services Branch. 5pp. 32853:299-32853:303.
- 8510040442** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases. Some appropriate limits need defining to exclude low risk, low level sources from potential requirement.
THOMPSON, S.D. Central Illinois Light Co. 50FR23960 068. 85/09/26. Docketing & Services Branch. 2pp. 32854:214-32854:215.
- 8510070250** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements for cleanup of accidental & unexpected release of radioactive materials. Opposes extending financial requirements to environ restoration.
AXELROD, L.R. Kay-Ray, Inc. 50FR23960 073. 85/10/01. Docketing & Services Branch. 3pp. 32877:302-32877:306.
- 8510070292** Comments on proposed rules 10CFR30.40, 61.70 & 72 re licensee responsibility for cleanup of radioactive material releases. Rule opposed due to nature of nuclear medicine.
SCHNEIDER, P.B. Worcester Memorial Hosp., Worcester, MA. 50FR23960 074. 85/10/01. Docketing & Services Branch. 1p. 32877:298-32877:298.
- 8510090096** Forwards documents re regulatory history of final rulemaking 10CFR35, "Physicians Use of Radioactive Drugs."
MCELROY, N.L. Materials Licensing Branch. AB72-2 01. 85/10/04. Record Services Branch (Document Control Desk). 2pp. 32964:061-32964:143.
- 8510090125** Forwards draft notice of final rule re physicians use of radioactive drugs for review. Requests comment.
* Materials Licensing Branch. AB72-2 07. 85/06/03. ABEL, N.M. Affiliation Not Assigned. 2pp. 32964:075-32964:076.
- 8510090139** Forwards draft final rule to amend 10CFR35, "Human Uses of Byproduct Material," for comment. Rule would amend regulations to allow licensees to use listed FDA approved drugs.
MILLER, V.L. Materials Licensing Branch. AB72-2 08. 85/05/31. OLMSTEAD, W. Regulations Division. GOLLER, K. Division of Radiation Programs & Earth Sciences (post 840429). PHILIPS, J. Division of Rules and Records. 14pp. 32964:077-32964:090.
- 8507160166** Approves draft final rule amending 10CFR35.14(b)(7) to authorize group medical licensees to use certain radiopharmaceuticals for clinical purposes not listed in FDA-approved package inserts. Notes removal of procedures re cerebrospinal fluid.
FOULKE, J.D. Health Effects Branch. AB72-2 10. 85/06/17. MCELROY, N.L. Materials Licensing Branch. 1p. 32964:091-32964:091.

-8510090160 Forwards marked-up comments re draft final rule authorizing new uses of approved radiopharmaceuticals. Rule must contain listed info when forwarded for concurrence & EDO approval & signature. W/o encl.
PHILIPS, J. Division of Rules and Records. AB72-2 11. 85/06/06. MILLER, V.L. Materials Licensing Branch. 1p. 32964:092-32964:092.

-8510090174 Forwards final rulemaking to amend 10CFR35, "Human Uses of Byproduct Material," for concurrence. Rule amends regulations to allow licensees to use listed FDA approved drugs for clinical procedures.
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety. AB72-2 12. 85/06/21. OLIMSTEAD, W.S. Regulations Division. GOLLER, K.R. Division of Radiation Programs & Earth Sciences (post 840429). PHILIPS, J.D. Division of Rules and Records. 21pp. 32964:093-32964:113.

-8510090193 Concurs in issuance of final rule 10CFR35.14(b)(7), authorizing addl clinical procedures for approved radiopharmaceuticals.
MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. AB72-2 13. 85/07/03. CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety. 1p. 32964:114-32964:114.

-8510090203 Concurs in final rule to amend 10CFR35, authorizing new uses of approved radiopharmaceuticals. Marked-up sets of editorial corrections encl. W/o encl.
FELTON, J.M. Division of Rules and Records. AB72-2 14. 85/06/26. CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety. 1p. 32964:115-32964:115.

-8510090214 Forwards final rule to amend 10CFR35.14(b)(7), "Human Uses of Byproduct Material," for signature. Amend allows physicians to use radiopharmaceuticals for diagnostic imaging procedure not listed on package labels.
DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB72-2 15. 85/08/22. DIRCKS, W.J. Office of the Executive Director for Operations. 23pp. 32964:116-32964:138.

-8510090223 Informs that final rule entitled, "Physicians Use of Radioactive Drugs," within scope of rulemaking authority & proceeding for issuance underway.
DIRCKS, W.J. Office of the Executive Director for Operations. AB72-2 16. 85/08/26. 1p. 32964:139-32964:139.

-8510090232 Informs that EDO approved encl final rulemaking entitled, "Physicians Use of Radioactive Drugs." Requests arrangement to have rulemaking published in FR.
MCELROY, N.L. Materials Licensing Branch. AB72-2 17. 85/08/30. FELTON, J.M. Division of Rules and Records. 4pp. 32964:140-32964:143.

8510090441 Partial response to FOIA request for documents re historical background of 10CFR50.59. Documents on encl App A & addl documents available in PDR Search for addl documents continuing.
FELTON, J.M. Division of Rules and Records. 85/10/02. DAY, P. NUS Corp. 3pp. 32965:071-32965:076.

-8510090453 Comments on proposed rules 10CFR50 & 115 re NRC authorization of changes to Tech Specs for production & utilization facilities. Procedures may be unduly time consuming.
VOGTLE, J.S. Alabama Power Co. 38FR22796 005. 73/10/17. Atomic Energy Commission. 1p. 32965:074-32965:074.

-8510090464 Comments on proposed rules 10CFR50 & 115, "Licensing of Production & Utilization Facilities; Procedure for Review of Certain Nuclear Reactors Exempted From Licensing Requirements."
MEYERS, S. Environmental Protection Agency. 38FR22796 004. 73/10/29. Atomic Energy Commission. 2pp. 32965:075-32965:076.

-8510090453 Comments on proposed rules 10CFR50 & 115 re NRC authorization of changes to Tech Specs for production & utilization facilities. Procedures may be unduly time consuming.
VOGTLE, J.S. Alabama Power Co. 38FR22796 005. 73/10/17. Atomic Energy Commission. 1p. 32965:074-32965:074.

-8510090464 Comments on proposed rules 10CFR50 & 115, "Licensing of Production & Utilization Facilities; Procedure for Review of Certain Nuclear Reactors Exempted From Licensing Requirements."
MEYERS, S. Environmental Protection Agency. 38FR22796 004. 73/10/29. Atomic Energy Commission. 2pp. 32965:075-32965:076.

8510100002 Comments on proposed rule 10CFR50 re use of highly enriched U fuel at nuclear reactors on US college campuses. Rule opposed due to fuel containing more military-grade U. Deadline of 3 yrs for change to low U suggested.
DAVIS, M.B. Sierra Club. 49FR27769 158. 85/09/29. PALLADINO, N. Commissioners. 1p. 32960:360-32960:360.

8510100037 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for cleanup of accidental releases. Annual financial reporting sys should be established to indicate changes in status of licensee.
STAUTER, J.C. Ker-McGee Corp. 50FR23960 087. 85/10/04. Office of the Secretary of the Commission. 4pp. 32961:005-32961:008.

8510100010 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements of licensees for cleanup of radioactive material. Most matts licensees have adequate financial resources for cleanup.
KRAMER, H.H. Atomic Industrial Forum. 50FR23960 106. 85/10/04. Docketing & Services Branch. 2pp. 32960:210-32960:211.

8510100022 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials. Industrial devices should be exempted.
MURPHY, R.F. Aconic Systems, Inc. 50FR23960 100. 85/10/03. Docketing & Services Branch. 2pp. 32960:177-32960:178.

8510100058 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements. Recommends that operating contractors & other applicable contractors at DOE & other federal govt facilities be included.
WEST, C.P. Tennessee, State of. 50FR23960 122. 85/10/02. CHILK, S.J. Office of the Secretary of the Commission. 1p. 32961:082-32961:082.

8510100060 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility for cleanup of accidental releases. Rules should include provisions for assessment of risk of accidental releases & allow spill prevention.
MCCLUSKEY, J.P. Cottier Corp. 50FR23960 088. 85/10/04. Docketing & Services Branch. 8pp. 32961:051-32961:058.

8510100065 Package of two comments opposing proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected release of radioactive material.
SMEDIRA, C., SNYDER, T.L. Neutron Products, Inc. FISHMAN, J.B. NDC Systems. 50FR23960. 85/10/08. Docketing & Services Branch. 6pp. 32960:165-32960:170.

8510100069 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for cleanup of accidental or unexpected releases of radioactive nuclear wastes. Comments should be exempted from proposed rule.
NOEL, T.H. Hayes, Seay, Mattern & Mattern. 50FR23960 105. 85/10/02. Docketing & Services Branch. 1p. 32960:132-32960:132.

8510100070 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for cleanup of accidental or unexpected releases of radioactive materials. Commission has not shown need for action.
BRANDT, R.J. Bethlehem Steel Corp. 50FR23960 094. 85/10/07. Docketing & Services Branch. 3pp. 32960:299-32960:301.

8510100076 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for cleanup of accidental or unexpected releases of radioactive material. Proposal premature.
PRENDERGAST, W. LFE Corp. 50FR23960 096. 85/10/01. Docketing & Services Branch. 2pp. 32961:083-32961:084.

8510100077 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for NRC licensees. Unacceptable financial burden to users of low risk radioactive materials cited.
MCLELLAND, N.I. National Sanitation Foundation. 50FR23960 084. 85/09/27. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 2pp. 32960:124-32960:125.

8510100078 Package of two comments opposing proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility for cleanup of accidental releases of radioactive material. Magnitude of responsibility should correlate w/risks of matts used.
BANFIELD, E.L. MQS Insp, Inc. GRAVES, M.D. Hall, Estill, Hardwick, Gable, Collingsworth & Nelson. 50FR23960. 85/10/08. Docketing & Services Branch. 5pp. 32961:062-32961:066.

8510100094 Package of two comments opposing proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility for cleanup of accidental releases of radioactive materials. EPA experience should be considered before pursuing rulemaking further.
WISSINK, R.G. 3M Co., Minnesota Mining & Manufacturing Co. O'NEIL, M. Prairie Investors (Wireline Service). 50FR23960. 85/10/08. Docketing & Services Branch. 4pp. 32960:185-32960:188.

8510100097 Package of two comments opposing proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials.
AMLAUER, K. Isotope Products Laboratories. HUMPHRIES, H.B. Trapper Mining, Inc. 50FR23960. 85/10/07. Office of the Secretary of the Commission. 4pp. 32960:347-32960:351.

8510100100 Package of three comments supporting proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors.
ATKINS, S.J., W.R. Affiliation Not Assigned. FRISCO, D.C. Coalition for Nuclear Power Plant Postponement. AFTEI, GOOD, S. Committee to Bridge the Gap. 49FR27769. 85/10/08. PALLADINO, N. Commissioners. 5pp. 32960:116-32960:120.

8510100116 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility for cleanup from accidental radiation release. Blanket requirement for all licensees to shoulder cleanup burden opposed.
DAVIDSON, D.R. Jor-Jar Systems. 50FR23960 102. 85/10/02. BUNTING, J. Policy & Program Control Branch (Post 831001). 2pp. 32960:116-32960:101.

8510100118 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility for cleanup of accidental releases of radioactive materials w/exception of teletherapy users, potential for financial problems from releases small.
WHITE, G.A. Rocky Mountain Physics, Inc. 50FR23960 118. 85/10/04. Docketing & Services Branch. 2pp. 32960:098-32960:099.

8510100123 Comments on proposed rule 10CFR50 re use of highly enriched U fuel at nuclear reactors on US college campuses. Proliferation of bomb-grade nuclear material inducement to potential terrorist acts.
PATTON, G.A. Santa Cruz, CA. 49FR27769 159. 85/10/01. PALLADINO, N. Commissioners. 1p. 32960:356-32960:356.

8510100125 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re ruling on nuclear waste & effort to protect US from threat of theft or diversion of highly enriched U-235 or U-233.
WILLIAMS, L.G. Affiliation Not Assigned. 50FR23960 109. 85/10/03. Docketing & Services Branch. 2pp. 32960:295-32960:296.

8510100130 Comments on proposed rule 10CFR50 re use of highly enriched U fuel at nuclear reactors located on US college campuses. Concern expressed re staff disregard of Commissioners opposition to rule.
DOHERTY, J.F. Doherty, J.F. 49FR27769 157. 85/10/01. PALLADINO, N. Commissioners. 2pp. 32961:198-32961:202.

-8510100151 Withdraws 850429 petition for leave to intervene, based on Commission 850620 ruling re continuation of use of high enrichment fuel in domestic training & research reactors.
DOHERTY, J.F. Doherty, J.F. 49FR27769 155. 85/07/11. GROSSMAN, H., HILLE, F., COLE, R. Atomic Safety and Licensing Board Panel. 1p. 32960:097-32960:097.

8510100131 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re financial responsibility requirements for cleanup of accidental releases. Rules may cause burdensome liability requirements for owners of Ni-63 or tritium detectors.
MACLEAN, D.B. Association of Official Analytical Chemists. 50FR23960 104. 85/10/03. CHILK, S.J. Office of the Secretary of the Commission. 1p. 32960:097-32960:097.

8510100134 Comments on proposed rules 10CFR30, 40, 61, 70 & 72 re proposed financial responsibility for cleanup of accidental releases of radioactive material. Level of coverage should reflect type of license.
MASSEY, W.E. Chicago, Univ. of, Chicago, IL. 50FR23960 091. 85/10/03. Office of the Secretary of the Commission. 3pp. 32960:094-32960:096.

322 NONDOCKETED ITEMS

- 8510100137** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial responsibility requirements for cleanup of accidental releases of radioactive materials. Rules would impose add'l & undue hardship on small hosps for listed reasons. DUNMAN, L.E. Pulaski Community Hosp., Pulaski, VA. 50FR23960 118. 85/10/04. Docketing & Services Branch. 1p. 32960:088-32960:088.
- 8510100144** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements. Users of unsealed radioactivity should be required to provide level of assurance consistent w/ quantity & radioactivity of mat'l. STEPHENS, D.C. AccuRay Corp. 50FR23960 098. 85/10/04. Docketing & Services Branch. 2pp. 32961:211-32961:212.
- 8510100146** Package of two comments supporting proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected release of radioactive mat'l. SHERWOOD, G.G. General Electric Co. BECHTEL, D.A. Clark County, NV. 50FR23960. 85/10/08. Docketing & Services Branch. 4pp. 32961:225-32961:228.
- 8510100149** Comments on proposed rules 10CFR30.40,61,70 & 72 re proposed financial responsibility requirements. Extension of comment period until 851021 requested. HIRSCH, A. Environmental Protection Agency. 50FR23960. 85/10/04. CHILK, S.J., BATES, A. Office of the Secretary of the Commission. 1p. 32961:213-32961:213.
- 8510100154** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental releases of radioactive mat'l. Nuclear medicine facilities should be exempted. GOLDSMITH, S.J. Society of Nuclear Medicine. MCKUSICK, K.A. American College of Nuclear Physicians. 50FR23960 111. 85/10/07. Docketing & Services Branch. 3pp. 32961:353-32961:355.
- 8510100158** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibilities for cleanup of accidental releases. Test instruments have little potential to produce threat to humans or property. EVANS, C.S., GRIFFIN, D.G. Navaho Refining Co. 50FR23960 092. 85/09/30. CHILK, S.J. Office of the Secretary of the Commission. 4pp. 32961:360-32961:362.
- 8510100160** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements to guarantee cleanup of radioactive mat'l. Financial exception should be made to facilities located on state or federal property. DILLON, B.E. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 50FR23960 103. 85/10/08. Docketing & Services Branch. 5pp. 32962:015-32962:019.
- 8510100162** Comments on proposed rules 10CFR30.40,50,51,70 & 72 re decommissioning criteria for nuclear facilities. Data may not accurately reflect costs involved in full-scale commercial nuclear plant decommissioning. ALSWORTH, M.W. Oregon. State of. 50FR5600 140. 85/10/03. Docketing & Services Branch. 5pp. 32962:010-32962:014.
- 8510100168** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements for cleanup of accidental releases of radioactive mat'l. Users should be classified according to potential for contamination. PINCO, R.G., POKUSA, R.E. Finley, Kumble, Wagner, Heine, Underberg, Manley & Casey. PINCO, R.G. Nuclear Pharmacy, Inc. 50FR23960 093. 85/10/03. CHILK, S.J. Office of the Secretary of the Commission. 10pp. 32962:212-32962:221.
- 8510100169** Offers no comments on proposed rules 10CFR30.40,61,70 & 72. ANDERSON, C.C. Navy, Dept. of. 50FR23960 085. 85/09/25. Office of Nuclear Material Safety & Safeguards, Director. 1p. 32962:196-32962:196.
- 8510100172** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility for cleanup of accidental releases of radioactive mat'l. Requirement too costly for small firm & not commensurate w/ low level mat'l used. CALHOON, M. Applied Soil Mechanics, Inc. 50FR23960 097. 85/10/03. Docketing & Services Branch. 2pp. 32962:197-32962:198.
- 8510100175** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive mat'l. Insurance expected to be exorbitant. MILLER, M.S., NELSON, J.S. Geological Consulting Services, Inc. 50FR23960 121. 85/10/04. CHILK, S.J. Office of the Secretary of the Commission. 4pp. 32962:138-32962:141.
- 8510100182** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to cleanups of accidental & unexpected releases of radioactive mat'l. Responsibility should be determined on sliding scale. QUENELLE, K.H. Mallinckrodt, Inc. 50FR23960 120. 85/10/07. Docketing & Services Branch. 2pp. 32961:176-32961:177.
- 8510100188** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & expected releases of radioactive mat'l. Proposed rules unnecessary. BOHNER, H. Measurix Corp. 50FR23960 095. 85/10/04. Docketing & Services Branch. 6pp. 32966:353-32966:358.
- 8510100192** Comments on proposed rules 10CFR30.31,32,35 & 40 re medical use of byproduct mat'l. Regulation would result in poorer health care delivery & could be counterproductive to efforts of health care cost containment. HALVERSON, P., KINNEY, W. Mercy Medical Center, Coon Rapids, MN. 50FR30616 011. 85/09/27. Docketing & Services Branch. 1p. 32962:083-32962:083.
- 8510100197** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental releases of radioactive mat'l. Users of small sources should be exempt. SEAMAN, S.C. Seaman Nuclear Corp. 50FR23960 089. 85/10/04. Docketing & Services Branch. 13pp. 32962:094-32962:108.
- 8510100201** Comments on proposed rules 10CFR30.40,50,51,70 & 72 re decommissioning criteria for nuclear facilities. Fund should be established at appropriate high level to provide conservative level of funding for decommissioning. SHAFER, A. Niagara Mohawk Power Corp. 50FR5600 139. 85/10/02. CHILK, S.J. Office of the Secretary of the Commission. 2pp. 32962:113-32962:114.
- 8510100206** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive mat'l. Guidelines for cleanup suggested. CLEMMENS, C.B. Appalachian Coal Surveys. 50FR23960 099. 85/10/01. Docketing & Services Branch. 2pp. 32962:065-32962:066.
- 8510100209** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility for cleanup efforts. Requirements must be carefully considered so that small licensees will not be burdened. BROWN, R.W. Mallinckrodt, Inc. 50FR23960 086. 85/10/04. Docketing & Services Branch. 2pp. 32962:063-32962:064.
- 8510110174** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility for cleanup of accidental release of mat'l. Financial responsibility should reflect & specify differences for mat'l type & amount. Related comments encl. FORT, D. New Mexico, State of. 50FR23960 083. 85/10/02. Docketing & Services Branch. 39pp. 32972:191-32972:229.
- 8510110178** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements of licensees for cleanup of accidental releases of radioactive mat'l. Recommends that only hosps w/ broad licenses be considered. MCCALLIE, T.S. Community Hosp. of Roanoke Valley Roanoke, VA. 50FR23960 076. 85/10/01. Docketing & Services Branch. 1p. 32972:356-32972:358.
- 8510110198** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements for cleanup of accidental releases of radioactive mat'l. Opposes rule. Accidental releases rare. RUM, D.E. Brigham & Women's Hosp., Boston, MA. 50FR23960 077. 85/09/30. Docketing & Services Branch. 2pp. 32972:275-32972:277.
- 8510110200** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to licensees for cleanup of accidental & unexpected releases. Supports rule. Financial responsibility appropriate. WILLIAMS, P.A. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 50FR23960 075. 85/10/03. Docketing & Services Branch. 6pp. 32972:230-32972:235.
- 8510110211** Package of three comments opposing proposed rules 10CFR30.40,61,70 & 72 re financial responsibility for cleanup of accidental releases. HUBER, S.A. Stan A. Huber Consultants, Inc. COOK, H.L. Ohmart Corp. SHEWCHENKO, A. Atomic Energy of Canada, Ltd. 50FR23960. 85/10/04. Docketing & Services Branch. 6pp. 32974:033-32974:040.
- 8510110224** Package of two comments supporting proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive mat'l. KEILMAN, D.J. Hercules, Inc. MONTGOMERY, M.F. Smyth County Community Hosp. Marion, VA. 50FR23960. 85/10/04. Docketing & Services Branch. 2pp. 32972:278-32972:278.
- 8510150193** Comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements for cleanup of accidental releases of radioactive mat'l. Only hosps w/ NRC broad licenses should be considered for proposed rulings. MONTGOMERY, M.F. Smyth County Community Hosp. Marion, VA. 50FR23960 079. 85/09/30. Docketing & Services Branch. 1p. 33008:296-33008:296.
- 8510160070** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial responsibility requirements for cleanup of radioactive accidents. Concern re use & control of instruments & insurance expressed. BASS, C.D. Sangamo Weston, Inc. 50FR23960 125. 85/09/30. BUNTING, J.O. NRC - No Detailed Affiliation Given. 2pp. 33028:018-33028:017.
- 8510160079** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial responsibility requirements for cleanup of accidental releases of radioactive mat'l. Clarification of rule per encl referenced comments requested. BREY, H.L. Public Service Co. of Colorado. 50FR23960 128. 85/10/11. Docketing & Services Branch. 3pp. 33028:007-33028:008.
- 8510160095** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial responsibility for cleanup of accidental releases of mat'l. Financial responsibility should be developed based on listed items. LACKER, D.K. Texas, State of. 50FR23960 123. 85/10/02. Docketing & Services Branch. 2pp. 33027:361-33027:362.
- 8510160101** Offers no comment on proposed rules 10CFR30.41,61,70 & 72. RICHARDSON, W.O. South Carolina. State of. 50FR23960 127. 85/10/07. CHILK, S.J. Docketing & Services Branch. 1p. 33022:307-33022:307.
- 8510160164** Notice of extension of comment period until 851107 for proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements for cleanup of accidental & unexpected releases of radioactive mat'l. CHILK, S.J. Office of the Secretary of the Commission. 50FR23960. 85/10/09. 2pp. 33022:254-33022:255.
- 8510160271** Advises recipients of comments on proposed rules 10CFR30.40,61,70 & 72 re financial responsibility requirements. Comment 109 miscoded. Number will not be used again. Docketing & Services Branch. 50FR23960. 85/10/11. Docketing & Services Branch. 1p. 33021:290-33021:290.
- 8510160306** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial requirements for cleanup of accidental & unexpected releases of radioactive mat'l. Users of sealed sources should be waived from meeting proposed requirements. HARRIS, P.B. Blandin Paper Co. 50FR23960 124. 85/10/07. Docketing & Services Branch. 1p. 33026:251-33026:251.
- 8510160311** Comments on proposed rules 10CFR30.40,61,70 & 72 re licensee financial responsibility requirements for cleanup of accidental & unexpected releases of radioactive mat'l. Users of small amounts of mat'l should be exempt. MCCREAR, B. Grocery Manufacturers of America, Inc. 50FR23960 126. 85/10/07. Docketing & Services Branch. 1p. 33026:218-33026:218.
- 8510180171** Requests that encl documents re regulatory history on proposed revs to 10CFR73.71 for reporting requirements for safeguards events be placed in Document Control Sys. YARDUMIAN, J. Reactor & Transportation Licensing Branch. AB46-1 01. 85/10/09. GARTNER, D. Division of Technical Information & Document Control. 1p. 33078:041-33078:253.

- 8403140187** Forwards specific comments re proposed rev to 10CFR73.71, "Safeguards Reporting Requirements." Changes reducing potential for redundant reporting endorsed. LER format should be used to report safeguards events. HELTEMES, C.J. AEO, Director's Office. AB46-1 25. 84/03/01. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33078:195-33078:199.
- 8404040147** Submits comments re proposed revs to 10CFR73.71, "Safeguards Reporting Requirements." Concurs w/revs. MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. AB46-1 21. 84/03/07. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:172-33078:172.
- 8406040129** Responds to 840514 request for concurrence on proposed revs to 10CFR73.71 re safeguards reporting requirements. Div reviewed rulemaking package & concurs in proposed revs. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. AB46-1 18. 84/05/25. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:169-33078:171.
- 8406060369** Forwards comments on proposed revs to 10CFR73.71 re safeguards reporting requirements. Efforts in rev to make 10CFR73.71 consistent w/10CFR50.72 strongly supported. HELTEMES, C.J. AEO, Director's Office. AB46-1 17. 84/05/24. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33078:166-33078:168.
- 8502070362** Concurs w/proposed revs to 10CFR73.71, "Reporting Requirements for Safeguards Events." per 850118 request. HELTEMES, C.J. AEO, Director's Office. AB46-1 12. 85/01/30. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:124-33078:124.
- 8502280071** Approves continuation of proposed rev to 10CFR73, "Physical Protection of Plants & Mats," clarifying current reporting requirements. Mod to NRC Regulatory Agenda (NUREG-0936) recommended. DIRCKS, W.J. Office of the Executive Director for Operations. AB46-1 27. 85/02/15. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:127-33078:127.
- 8503040154** Discusses ongoing rulemaking, "Reporting Requirements for Safeguards Events." Repts previously nonuniform & difficult to analyze re NRC assessment needs. Rule change will improve data base re plant-specific & generic security sys. MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. AB46-1 28. 85/02/07. DIRCKS, W.J. Office of the Executive Director for Operations. 4pp. 33078:128-33078:131.
- 8503080521** Confirms previous concurrence re proposed revs to 10CFR73.71, "Reporting Requirements for Safeguards Events." per 850118 memo. MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. AB46-1 13. 85/02/28. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:125-33078:125.
- 8510180192** Proposed rules 10CFR70.72, 73 & 74, "Changes to Safeguards Reporting Requirements." Rules would clarify reporting requirements for NRC licensees & improve safeguards event data base by requiring more uniform safeguards event repts. DIRCKS, W.J. Office of the Executive Director for Operations. AB46-1 02. 85/10/09. 23pp. 33078:042-33078:064.
- 8510180198** Forwards proposed rule 10CFR73.71 re reporting requirements for safeguards events for FR publication. per EDO 850806 directive. W/o encl. BURNETT, R.F. Division of Safeguards. AB46-1 03. 85/08/16. FELTON, J.M. Division of Rules and Records. 1p. 33078:065-33078:065.
- 8510180202** Forwards, for signature, FR notice re proposed amends to 10CFR73.71 concerning reporting requirements for safeguards events. W/o encl. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB46-1 04. 85/08/01. DIRCKS, W.J. Office of the Executive Director for Operations. 2pp. 33078:066-33078:067.
- 8510180209** Notifies that proposed rule 10CFR73.71 revised to delete requirement for licensees to provide regions w/quarterly submitted log of safeguards events. Region V will be placed on internal NRC distribution. DWYER, P. NRC - No Detailed Affiliation Given. AB46-1 05. 85/02/28. NRC - No Detailed Affiliation Given. 1p. 33078:068-33078:068.
- 8510180213** Requests that any revs to 10CFR20.402 re theft or loss of licensed matl be consistent w/encl revs to 10CFR73.71 concerning licensee event reporting requirements. W/o encl. MCCORKLE, G.W. Power Reactor Safeguards Licensing Branch (Pre 850707). AB46-1 06. 85/03/07. BELOTE, J.C. Regulatory Analysis & Materials Risk Branch (post 840429). 1p. 33078:069-33078:069.
- 8510180220** Requests that any revs to 10CFR72.52 or any other applicable licensee event reporting requirement be consistent w/encl proposed rev to 10CFR73.71 & 50.73. W/o encl. MCCORKLE, G.W. Power Reactor Safeguards Licensing Branch (Pre 850707). AB46-1 07. 85/03/04. STEYER, K.G. Chemical Engineering Branch. 1p. 33078:070-33078:070.
- 8510180224** Requests assistance in implementing proposed rev to 10CFR73.71 re reporting requirements for safeguards events when promulgated. Document control desk proposed as centralized receiving point for licensee repts. BURNETT, R.F. Division of Safeguards. AB46-1 08. 85/02/25. BESAW, W.J. Division of Technical Information & Document Control. 1p. 33078:071-33078:098.
- 8510180226** Forwards draft proposed revs to 10CFR73.71, "Safeguards Reporting Requirements," for review. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB46-1 15. 84/05/14. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, G.H. Office of the Executive Legal Director. HELTEMES, C.J. AEO, Director's Office. 20pp. 33078:145-33078:164.
- 8510180229** Concurs w/encl marked-up proposed rev to 10CFR73.71 re safeguards reporting requirements. W/o encl. FELTON, J.M. Division of Rules and Records. AB46-1 16. 84/05/22. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:165-33078:165.
- 8510180233** Forwards, for review, annot. led proposed revs to 10CFR73.71 re reporting requirements for safeguards events. Concurrence or comments requested by 850201. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB46-1 10. 85/01/18. NORRIS, P.G. Office of Administration. HELTEMES, C.J. AEO, Director's Office. CUNNINGHAM, G.H. Office of the Executive Legal Director. 23pp. 33078:099-33078:121.
- 8510180237** Concurs w/proposed revs to 10CFR70 & 73 re safeguards reporting requirements based on NMSS compliance w/encl marked-up rev 12/0 encl. FELTON, J.M. Division of Rules and Records. AB46-1 11. 85/02/05. DWYER, P. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 33078:122-33078:123.
- 8510180244** Provides list of otrs offering no comments on proposed revs to 10CFR73.71. per Davis 850118 memo. DWYER, P. NRC - No Detailed Affiliation Given. AB46-1 14. 85/10/08. NRC - No Detailed Affiliation Given. 1p. 33078:126-33078:126.
- 8510180251** Informs of R Fonner 840524 concurrence w/proposed revs to 10CFR73.71. in response to Davis 840514 memo. DWYER, P. NRC - No Detailed Affiliation Given. AB46-1 22. 85/10/08. NRC - No Detailed Affiliation Given. 1p. 33078:173-33078:191.
- 8510180256** Forwards draft independent review package re rulemaking sponsored by NMSS & RES Independent Review Board consisting of voting sheets reflecting deliberations. NRC should proceed w/rulemaking. GILLESPIE, F.P. Research Independent Review Board. AB46-1 29. 84/10/12. MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. 1p. 33078:132-33078:132.
- 8510180263** Forwards revised Attachment 4 to draft rulemaking package re safeguards reporting requirements. W/o encl. INGRAM, F. Office of Public Affairs. AB46-1 20. 84/02/24. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:192-33078:192.
- 8510180264** RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Draft RES independent recommendations should be modified as listed. BASSETT, O.E. Research Independent Review Board. AB46-1 30. 84/07/17. BERNERO, R.M. Research Independent Review Board. 1p. 33078:133-33078:133.
- 8510180272** RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Draft RES independent recommendations should be modified as listed. GOLLER, K.R. Research Independent Review Board. AB46-1 31. 84/07/17. BERNERO, R.M. Research Independent Review Board. 1p. 33078:134-33078:134.
- 8510180279** Concurs w/amend to proposed rule 10CFR73.71, "Changes to Safeguards Reporting Requirements." subj to listed comments. R Fraley 830613 identification of ACRS interest & proposed rules package encl. W/o encl. FELTON, J.M. Division of Rules and Records. AB46-1 24. 84/03/13. DWYER, P. Division of Safeguards. 2pp. 33078:193-33078:194.
- 8510180280** RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Agrees w/draft RES independent review package. * Research Independent Review Board. AB46-1 32. 84/07/30. BERNERO, R.M. Research Independent Review Board. 1p. 33078:135-33078:135.
- 8510180286** RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Agrees w/draft RES independent review package. BERNERO, R.M. Research Independent Review Board. AB46-1 33. 84/07/31. 2pp. 33078:136-33078:137.
- 8510180290** Recommends continuation of action on rulemaking re reporting requirements for safeguards events. per RS Brown 840410 memo. Revised NRC regulatory agenda entry & draft Commission paper for rulemaking encl. W/o encl. BURNETT, R.F. Division of Safeguards. AB46-1 26. 84/04/30. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 33078:200-33078:200.
- 8510180291** Forwards RES review summary sheet re rulemaking, "Reporting Requirements for Safeguards Events." NRC should proceed w/rulemaking. BERNERO, R.M. Division of Risk Analysis & Operations (post 840429). AB46-1 34. 84/07/06. MALARA, J. Regulatory Analysis & Materials Risk Branch (post 840429). 4pp. 33078:138-33078:141.
- 8510180297** Forwards rulemaking review package for action. per procedures approved by EDO on 840530. Draft independent review package for rulemaking should be submitted within 5 days of memo date. BERNERO, R.M. Research Independent Review Board. AB46-1 35. 84/06/15. NORBERG, J.A. Human Factors & Safeguards Branch. 3pp. 33078:142-33078:144.
- 8510180301** Forwards Cost Analysis Group comments on regulatory impact analysis portion of revs to 10CFR73.71, "Reporting of Safeguards Events." No major changes required. TRINER, E.G. Division of Budget & Analysis. AB46-1 36. 85/03/25. WILDE, R.M. Division of Fuel Cycle & Material Safety. 3pp. 33078:201-33078:203.
- 8510180309** "Supporting Statement for Proposed Revs to 10CFR73.71: Notification Requirements for Safeguards Events & New 10CFR73.71 App G." * NRC - No Detailed Affiliation Given. AB46-1 37. 85/02/28. 6pp. 33078:204-33078:209.
- 8510180314** Forwards proposed revs to 10CFR73.71 re notification requirements for safeguards events, for review. Concurrence in exemption of amend from formal CRGR review requested. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB46-1 38. 84/08/14. STELLO, V. Regional Operations & Generic Requirements. 1p. 33078:210-33078:210.
- 8510180321** Advises that CRGR review of proposed rev to 10CFR73.71 & Reg Guide 5.62 re notification requirements for safeguards events appropriate to ensure consistent safety threshold event reporting. CRGR review will focus on listed areas. STELLO, V. Regional Operations & Generic Requirements. AB46-1 39. 84/09/25. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33078:211-33078:213.

324 NONDOCKETED ITEMS

-8519180325 Forwards revised draft rule package re proposed revs to 10CFR73.71 concerning reporting requirements for safeguards events, in response to 840925 comments.
DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. AB46-1 40. 85/03/18. STELLO, V. Regional Operations & Generic Requirements. 3pp. 33078-214-33078-236.

-8510180330 Forwards proposed clarification of examples listed in proposed guidance for events to be reported within 1 h & to be logged in proposed rev to 10CFR73.71. Related chart & survey results also encl.
BURNETT, R.F. Division of Safeguards. AB46-1 43. 85/05/08. STELLO, V. Regional Operations & Generic Requirements. 15pp. 33078-237-33078-253.

8510180253 Forwards TS LaGuardia 850902 comments on proposed rules 10CFR30.40, 50.51, 70 & 72 re decommissioning criteria for nuclear facilities. Transcript re decommissioning referenced in TS LaGuardia ltr also forwarded.
PRINS, H.R. New York. State of. 50FR5600 141. 85/10/11. CHILK, S.J. Docketing & Services Branch. 36pp. 33061-089-33061-126.

8510180282 Package of two comments opposing proposed rules 10CFR19.20, 21.30, 32.39, 40.50, 51.70, 71 & 150 re licenses & radiation safety requirements for well-logging operations.
VAUGHAN, W.A. Energy, Dept. of. 50FR13797. 85/10/17. CHILK, S.J. Commissioners. 5pp. 33062-170-33062-174.

8510180319 Comments on proposed rules 10CFR30.40, 61.70 & 72 re amend requiring certain licensees to demonstrate adequate financial ability to pay for cleanup of accidental releases of radioactive materials. Rule supported.
BATTS, M.S. Florida. State of. 50FR23960 132. 85/10/09. Docketing & Services Branch. 1p. 33062-026-33062-026.

8510180327 Comments on proposed rules 10CFR30.40, 61.70 & 72 re licensee financial responsibility for cleanup of accidental & unexpected release of radioactive materials. Cost would far exceed benefits.
SONNEMAKER, R.E. Society of Nuclear Medicine. 50FR23960 130. 85/10/07. Docketing & Services Branch. 3pp. 33060-351-33060-353.

8510180332 Comments on proposed rules 10CFR30.40, 61.70 & 72 re licensee financial responsibility for cleanup of accidental & unexpected releases of radioactive materials. Strict liability std for remedial action should be applied.
BRUCHMANN, G.W. Michigan. State of. 50FR23960 129. 85/10/07. Docketing & Services Branch. 2pp. 33062-003-33062-004.

8510180343 Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements of licensees for cleanup of accidental & unexpected releases of radioactive materials. Rule opposed for: hospo w/specific licenses.
SALYERS, R.J. Appalachian Regional Hosp. Beckley, WV. 50FR23960 133. 85/10/08. Docketing & Services Branch. 2pp. 33060-250-33060-251.

8510180349 Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases of certain materials. Responsibility for cleanup should be isolated from liability for personal injury.
COLLINS, V.P. Collins, V.P., MD. 50FR23960 134. 85/10/10. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 1p. 33062-019-33062-019.

8510180352 Requests 30-day extension of comment period until 851107 for proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements for NRC licensees.
SPAIN, W.J. Delmonte Corp. 50FR23960. 85/10/10. CHILK, S.J. Office of the Secretary of the Commission. 1p. 33060-148-33060-148.

8510180366 Comments on proposed rules 10CFR30.40, 61.70 & 72 re licensee financial responsibility requirements for cleanup of accidental releases of radioactive materials. Financial hardship would ensue due to slump in steel industry.
GAMER, G.R. Empire Steel Castings, Inc. 50FR23960 131. 85/10/03. Docketing & Services Branch. 1p. 33059-282-33059-282.

8510180412 Comments on proposed rule 10CFR50 re use of low enriched U at Georgia Inst of Technology reactor. Supports rule.
CLEMENTS, T. Affiliation Not Assigned. 49FR27769 160. 85/10/10. PALLADINO, N. Commissioners. 1p. 33062-175-33062-175.

8510250326 Package of three comments supporting proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials.
STEINER, E.J. Delaware. State of. TEDFORD, C.F. Arizona. State of. CARLINE, E. Washington. State of. 50FR23960. 85/10/21. Docketing & Services Branch. 8pp. 33172-198-33172-205.

8510250365 Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive materials. Rule should apply to broad licenses only.
LANGSTON, L.W. Kings Daughters Hosp., Staunton, VA. 50FR23960 136. 85/10/16. Docketing & Services Branch. 1p. 33172-189-33172-189.

8510250388 Comments on proposed rule 10CFR50 re removal of weapons-grade U from campus reactors. Rule supported due to security risks & unnecessary temptation. Incorporation of reasonable deadline for conversion to low enriched U fuel recommended.
FLACK, G. Affiliation Not Assigned. 49FR27769 161. 85/10/07. PALLADINO, N. Commissioners. 1p. 33169-309-33169-309.

8510250392 Comments on proposed rules 10CFR70.72, 73 & 74 re changes to safeguards reporting requirements. Change to 10CFR73.67 would produce no benefit but would result in added costs.
FOLCK, R.H. General Electric Co. 50FR34708 001. 85/10/15. Docketing & Services Branch. 2pp. 33172-335-33172-336.

8510250432 Package of two comments opposing proposed rules 10CFR30.31, 32.35 & 40 re medical use of byproduct mat.
HUBER, S.A. Stan A. Huber Consultants, Inc. HEMINGWAY, C.A. Worthington Regional Hosp. Worthington, MN. 50FR30616. 85/10/21. Docketing & Services Branch. 13pp. 33171-318-33171-330.

8510250466 Forwards State of WA 851003 ltr commenting on advanced notice of proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases of certain materials licensees.
NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 50FR23960 138. 85/10/15. SEEMAN, M.J. Policy & Program Control Branch (Post 831001). 1p. 33171-331-33171-333.

-8510251471 Comments supporting proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental releases of certain materials licensees. Superfund-like program w/govt putting up money suggested.
STRONG, T.R. Washington. State of. 85/10/03. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 2pp. 33171-332-33171-333.

8510290342 Comments on proposed rules 10CFR30.31, 32.35 & 40. Rule opposed due to need for providing adequate diagnostic expertise & on-the-job continuing education, in addition to 6 months training.
NORRIS, F.S. Army, Dept. of. Womack Army Community Hosp., Ft. Bragg, NC. 50FR30616 016. 85/10/18. Docketing & Services Branch. 1p. 33234-359-33234-359.

8510290348 Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental release of certain materials. Rule conditionally supported. Inclusion of users of gauging devices may be warranted.
RUTLEDGE, B.G. Georgia. State of. 50FR23960 140. 85/10/18. Docketing & Services Branch. 1p. 33234-336-33234-336.

8510290358 Comments on proposed rules 10CFR30.40, 50.51, 70 & 72 re decommissioning criteria for nuclear facilities. Rule opposed due to potential for introduction of contentious re decommissioning in licensing proceedings & attendant delay.
TROWBRIDGE, G.F. Shaw, Pittman, Potts & Trowbridge. TROWBRIDGE, G.F. Georgia Power Co. 50FR5600. 85/10/23. CHILK, S.J. Office of the Secretary of the Commission. 2pp. 33241-044-33241-045.

8510290362 Comments on proposed rules 10CFR30.31, 32.35 & 40 re human use of radioactive materials. NRC should seriously consider inclusion or adoption of SI units for radioactivity in final 10CFR35.
LIETO, R.P., SWANSON, D. Henry Ford Hosp., Detroit, MI. 50FR30616 014. 85/10/10. Docketing & Services Branch. 4pp. 33239-232-33239-235.

8510290383 Comments on proposed rules 10CFR30.31, 32.35 & 40 re medical use of byproduct materials. Licensees do not have expertise needed to make adequate safety review of changes proposal allows.
BLAZEK, M.L. Oregon. State of. 50FR30616 015. 85/10/22. Docketing & Services Branch. 2pp. 33236-359-33236-360.

8510290439 Proposed rule, "Policy Statement on Engineering Expertise Onshift." Rule would offer licensees two options for providing engineering expertise onshift & meeting licensed operator staffing requirements.
CHILK, S.J. Office of the Secretary of the Commission. 48FR33781. 85/10/22. 12pp. 33239-347-33239-358.

PRM PETITION FOR RULEMAKING

8510070351 Amended petition for rulemaking PRM-60-2 re EPA final stds for protection of general environ from offsite releases from radioactive mat in repositories.
SWAINSTON, H., MURPHY, M.R. Nevada. State of. OLSON, J.F. Minnesota. State of. 85/09/30. Commissioners. 15pp. 32875-020-32875-034.

8510100121 Forwards 850930 amended petition for rulemaking PRM-60-2 filed by States of NV & MN. Amend places substance of assurance requirements before Commission & proposes mechanism to ensure public health & safety.
DAVENPORT, J.H. Duryea, Houchins, Murphy & Davenport. 50FR18267. 85/10/01. PALLADINO, N.J. Commissioners. 2pp. 32960-034-32960-051.

-8510100127 Forwards amended petition for rulemaking PRM-60-2 from States of NV & MN. Petition amends petition submitted on 840722.
DAVENPORT, J.H. Duryea, Houchins, Murphy & Davenport. 85/09/30. CHILK, S. Office of the Secretary of the Commission. 1p. 32960-036-32960-036.

-8510100133 Amended petition for rulemaking PRM-60-02 placing before Commission substance of assurance requirements & providing mechanism to ensure Commission responsibility to protect health & safety of public not compromised.
SWAINSTON, H., MURPHY, M.R., DAVENPORT, J.H. Nevada. State of. 85/09/30. Commissioners. 15pp. 32960-037-32960-051.

PROJ PROJECTS - PREDOCKET LICENSING

8510010501 Summary of 850905-06 meetings w/Nuclear Structures, Inc., Mitsubishi, LLL & Lowenberg Assoc. Inc. in Livermore, CA re Mitsubishi revised rept on dry spent fuel storage cask design. Meeting attendees, agenda & viewgraphs encl.
ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/20. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 34pp. 32833-111-32833-143.

8510010625 Summary of 850910-11 meetings w/NUTECH Engineers, Inc. in Silver Spring, MD re encl NUTECH responses to NRC 850529 & 0607 comments on inservice insp procedures & estimating thermal parameters. Attendance list encl.
ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/20. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 32831-217-32832-059.

-8510010626 Forwards responses to NRC detailed comments on Topical Rept NUH-001 re horizontal modular storage sys for irradiated nuclear fuel.
MASSEY, J.V. NUTECH Engineers, Inc. JVA-85-143. 85/09/06. ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 20pp. 32831-219-32832-059.

8510070559 Supports proposed actions to resolve NRC comments & revise topical rept described in 850919 ltr. Revised topical rept expected by 851101. Each new concrete module & canister should be examined after each full yr of svc.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/01. MASSEY, J.V. NuInc, Inc. 1p. 32900-354-32900-354.

8510090307 Forwards "Info on Containment Capability of Facility Disposal Area at West Valley, NY." Rept prepared to collect & disseminate pertinent info re radiological safety of facility disposal area.
CLARK, A.T. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30.
HANNUM, W.H. Energy, Dept. of. SPAUNBURG, R., DEBOERT, New York, State of. 2pp. 32950:108-32950:167.

8510090308 "Info on Containment Capability of Facility Disposal Area at West Valley, NY."
NICHOLSON, T.J. Earth Sciences Branch (post 840429). HURT, R.D. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30. 60pp. 32950:110-32950:167.

8510110081 Forwards request for addl info re QA program. Review of "Topical SAR for Nuclear Assurance Corp. Storage/Transport Cask for Use at ISFSI" incomplete.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/01.
WOODHALL, C.B. Nuclear Assurance Corp. 3pp. 33011:312-33011:314.

8510160103 Responds to FOIA request for four categories of documents re Philippines nuclear power plant. Forwards documents listed on App D.
FELTON, J.M. Division of Rules and Records. 85/10/01. SCHLEMMER, D.L. Government Accountability Project. 2pp. 33035:330-33036:024.

8510160141 Forwards initial site exam info to minimize siting-related delays in licensing process.
GIAMBUSSO, A. Atomic Energy Commission - Deputy Director for Reactor Projects. 74/06/19. FIRESTONE, L. Ohio Edison Co. 5pp. 33035:336-33035:340.

8510170113 Forwards monitoring rept on QA program per site visit during w/o of 850729. Addl meeting suggested.
CLARK, A.T. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/08.
HANNUM, W.H. Energy, Dept. of. Idaho Operations Office. 12pp. 33043:209-33043:220.

8510180033 Forwards topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys., Inc." Rept acceptable for referencing in licensing applications subj to encl limitations.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/30.
BARNHART, V.J. General Nuclear Systems, Inc. 6pp. 33074:176-33074:270.

8510180038 Topical rept evaluation of Rev 1 to "Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask Submitted by General Nuclear Sys., Inc."
Office of Nuclear Material Safety & Safeguards, Director. 85/09/30. 89pp. 33074:182-33074:270.

8510180538 Requests analysis & evaluation of cause of cracking found in fuel basket of CASTOR V/21 cask used in dry spent fuel storage cooperative demonstration program. Revs necessary to topical SAR also requested.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/14.
BARNHART, V.J. General Nuclear Systems, Inc. 1p. 33077:280-33077:280.

8510210196 Summarizes 850910-11 meetings re review of comments concerning NUHOMS topical rept. NRC requested addl info concerning criticality analysis methods, shielding considerations & inservice visual insp program.
MASSEY, J.V. NUTECH Engineers, Inc. 25843. 85/09/19. ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 4pp. 33094:162-33094:166.

8510250083 Summary of 851003-04 meetings w/Bundesanstalt fur Mat. Prufung re final arrangements for insp of dry storage casks produced in West Germany & damaged CASTOR V/21 cask.
ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/18.
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 3pp. 33226:101-33226:103.

8510250328 Forwards Page 24 omitted from "SER re Topical SAR for CASTOR V/21 Dry Spent Fuel Storage Cask."
BROWN, F.L. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/21.
BARNHART, V.J. General Nuclear Systems, Inc. 2pp. 33226:126-33226:127.

8510250334 Forwards draft summary of 851002 meeting w/Clinch River MRS Task Force in Roane County, TN. Concept of citizen MRS environ, safety & health review board principal topic discussed. List of meeting attendees also encl.
CLARK, A.T. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/14. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. 14pp. 33226:112-33226:125.

8510310539 Forwards "Research Plan for Investigation of Radionuclide Migration at West Valley Facility Disposal Area." W/o encl.
CLARK, A.T. Advanced Fuel & Spent Fuel Licensing Branch. 85/10/21. DEBOERT, T.K. New York, State of. 2pp. 33277:039-33277:040.

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABE, L. Government Accountability Project. 32pp. 32884:005-32884:234.

8510010388 Forwards 10CFR50.55(e)/Part 21 rept from TVA re generic problem w/ hydrogen detection sys integrity. Followup on generic aspects w/AE/vendor requested. Supporting documentation encl.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15. Region 4, Dallas, Vendor Inspection Branch. 32pp. 32884:241-32885:208.

8510010420 Forwards 10CFR50.55(e)/Part 21 rept received from util re failure of contaminated gas monitor sys pump. Followup of generic aspects requested.
MURPHY, C.E. Region 2, Office of Director. 80/05/01. Region 4, Office of Director. 21pp. 32885:218-32885:238.

8510020245 Part 21 rept re pump diaphragm failures. Initially reported on 800403. Caused by closure of containment isolation valves w/o pump shutdown. Bypass kit available to limit pump pressure. Defects not reportable per 10CFR21.
ROBINSON, A. Comap, Inc. 81/04/06. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 3pp. 32890:158-32890:160.

8510020221 Forwards 10CFR50.55(e)/10CFR21 rept. Problem appears to be generic. Followup requested. Record of 810211 telcon encl.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/02/13. Region 4, Dallas, Vendor Inspection Branch. 4pp. 32890:142-32890:145.

8510020254 Part 21 rept re broken motor shaft on Reliance Electric Co. motors supplied to Comap, Inc. Initially reported on 800316. Corrective actions revised design included in all subsequent motors. Applicable manual & related info encl.
WHEELER, G.L. Reliance Electric Co. (subs. of Exxon Corp.). 84/05/11. BOARDMAN, J. Region 4, Dallas, Office of the Director. 7pp. 32890:161-32890:167.

8510010306 Preliminary Part 21 rept re 3.5-inch crack on snubber ball bearing. Vendor attempting to has a hearing returned for exam & evaluation by SKF Industries. Next rept will be submitted when significant info available.
LAURENSEN, A. ITT Grinnell Corp. (subs. of ITT Corp.). 85/09/26. Director's Office, Office of Inspection and Enforcement. 2pp. 32901:274-32901:275.

8510010472 Part 21 & final Deficiency Rept DER 85-24 re broken diesel generator turbocharger bolts supplied by Cooper Energy Svcs. Existing bolts will be replaced w/ longer ASTM A-193, Grade B7 full threaded studs & A-194, Grade 2H nuts.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). DER 85-24. 85/09/13. KIRSCH, D.F. Region 5, Office of Director. 7pp. 32809:175-32809:181.

8510010602 Part 21 & final Deficiency Rept DER 85-27 re slippage in Pacific Scientific pipe clamps. Initially reported on 850820. Torque value increased &/or replacement bolts & nuts installed.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). DER 85-27. 85/09/18. KIRSCH, D.F. Region 5, Office of Director. 4pp. 32820:356-32820:359.

8510030116 Part 21 rept re defective electronically coded vinyl key cards. Pyrotronics Model 1310 used for security electronic access control sys. Initially reported on 850913. Five defective cards destroyed. New cards will be tested.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-682. 85/09/16. GRACE, J.N. Region 7, Office of Director. 3pp. 32842:231-32842:233.

8510030280 Part 21 & final deficiency rept re potentially excessive indication errors in reactor vessel level instrumentation sys. Initially reported on 850823. Corrective mode will be completed for Unit 1 by 851130.
HUFHAM, J.W. Tennessee Valley Authority. 85/09/20. GRACE, J.N. Region 2, Office of Director. 2pp. 32845:254-32845:255.

8510040264 Update to Part 21 rept re insp for cracked welds discovered in generator brackets. Insp for Callaway Unit 1 postponed until next refueling outage (probably Apr 1986). No cracks discovered during insp at Wolf Creek.
SCHREIBER, H. Louis-Allis Co. 85/09/30. NAIJDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 1pp. 32851:100-32851:107.

8510100009 Part 21 & final Deficiency Rept [RDC 134(85)] re potential flooding voids in turbine bldg due to circulating water sys expansion joint failure. Initially reported on 850426. Design Change Packages 85-0386 & 85-0391 issued & FSAR changed.
EDELMAN, M.R. Cleveland Electric Illuminating Co. PY-CEI/OIE 0100. 85/10/03. KEPPLER, J.G. Region 3, Office of Director. 3pp. 32961:002-32961:004.

8510220062 Second preliminary Part 21 rept re hairline crack in bearing. Bearing will not be returned for exam. Bearing sent to Westinghouse.
LAURENSEN, A.S. ITT Grinnell Corp. (subs. of ITT Corp.). 85/10/15. Director's Office, Office of Inspection and Enforcement. 1p. 33090:154-33090:154.

8510220457 Deficiency & Part 21 rept re error in Control Data GT STRUDL computer program. Initially reported on 850903. Pipe support final designs will be reverified using different analysis program. Updated rept expected at const restart.
ROOT, R.W. Washington Public Power Supply System. GO1-85-0190. 85/10/03. MARTIN, J.B. Region 5, Office of Director. 3pp. 33096:232-33096:234.

8510220474 Final Part 21 & Deficiency Rept DER 85-20 re Cooper Energy Svcs broken diesel generator rocker arm. Initially reported on 850528. Rocker arm replaced. Tappet clearances will be adjusted at 18-month intervals.
VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). ANPP-33604-TDS. 85/09/30. KIRSCH, D.F. Region 5, Office of Director. 6pp. 33093:047-33093:054.

8510240254 Potential Part 21 rept re pipe snubber brackets mfg from matls less than specified by design drawings. Brackets shipped to facility. S&W requested to return brackets. Investigation incomplete.
FISHER, R.C. Paul-Munroe Hydraulics, Inc. 85/10/09. YOUNG, T. Region 1, Office of Director. 1p. 33154:304-33154:304.

8510310269 Part 21 & Final Deficiency Rept [RDC 135(85)] re load capabilities of Basic Engineers BE-419 pipe clamps. Initially reported on 850430. Clamps in use identified & reworked. Clamps in stock now on hold.
EDELMAN, M.R. Cleveland Electric Illuminating Co. [RDC 135(85)]. 85/10/22. KEPPLER, J.G. Region 3, Office of Director. 3pp. 33292:065-33292:067.

QA999 QUALITY ASSURANCE INSPECTIONS

8510010195 Ack receipt of 850806 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 89900905/85-01. Response B.(a) to Nonconformance B.2 not satisfactory. Info needed re corrective & preventive steps.
ZECH, G.G. Vendor Program Branch. 85/09/30. SADI, R.C. Wyle Laboratories. 2pp. 32800:289-32800:290.

8510010267 Confirms QA program insp at Huntsville, AL plant on 850930-1004, per 850925 telcon.
ZECH, G.G. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/09/27. HOLBROOK, W.W. Wyle Laboratories. 1p. 32800:186-32800:188.

8510010283 Responds to FOIA request for background records of all insp repts on facility since Dec 1982, per 841210 oral agreement. Forward: documents listed on app. Documents also available in PDR.
FELTON, J.M. Division of Rules and Records. 85/02/27. BERNABE, L. Government Accountability Project. 32pp. 32884:005-32884:234.

326 NONDOCKETED ITEMS

- 8510010393** Forwards Insp Rept 99900734/82-02 on 820413-14 at Comap, Inc re extent of qualification testing of Delphi Instruments Div hydrogen analyzer per IEEE Std 323-1974. Allegations re inadequacy unsubstantiated. JOHNSON, E.H. Region 4, Office of Director. 82/09/01. JOHNSON, A.D. Region 5, Office of Director. 1p. 32885-207-32885-207.
- 8510010397** Confirms 810319 telcon re Insp Rept 99900734/81-01 on 810406-09. Insp will relate to QA program implementation. POTAPOVS, U. Vendor Inspection Branch. 81/03/20. PUGH, J. Comap, Inc. 1p. 32885-206-32885-208.
- 8510010402** Advises that listed Comap, Inc. Delphi Sys Div pump failures discussed in Insp Rept 99900734/81-01 on 810406-09 closed. Related info encl. POTAPOVS, U. Vendor Inspection Branch. 81/07/01. LEWIS, R.C. Division of Resident & Reactor Project Inspection. 9pp. 32885-209-32885-217.
- 851001026:** Forwards QA Program Insp Rept 99901013/85-01 on 850528-31 & notice of nonconformance. ZECH, G.G. Vendor Program Branch. 85/09/27. SPEAR, R.W. Commonwealth Edison Co. 3pp. 32800-348-32801-003.
- 8510010292** Notice of nonconformance from insp on 850528-31.
* Vendor Program Branch. 85/09/27. 3pp. 32800-351-32800-353.
- 8510010298** QA Program Insp Rept 99901013/85-01 on 850528-31. Nonconformance noted: insps not performed on rigging & hoisting equipment used in warehouse & three RHR vertical shaft electric motors inadequately stored. OLLER, R.E., MERSCHOFF, E.W. Vendor Program Branch. 85/08/08. 12pp. 32800-354-32801-003.
- 8510030023** Confirms QA program insp at Murrysville, PA ofc on 851007-09, per 851001 telcon. ZECH, G.G. Vendor Program Branch. 85/10/02. JELOVICH, J. Westinghouse Electric Corp. 1p. 32845-123-32845-123.
- 8510070285** Forwards QA Program Insp Rept 99901007/85-01 on 850610-12 & notice of violation. ZECH, G.G. Vendor Program Branch. 85/10/03. OIKNINE, J. Fresco Corp. 2pp. 32875-259-32875-268.
- 8510070288** Notice of violation from insp on 850610-12.
* Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/10/03. 1p. 32875-261-32875-261.
- 8510070296** QA Program Insp Rept 99901007/85-01 on 850610-12. Violation noted: licensee did not develop procedure to review & evaluate deviations or inform licensee/purchaser. NAIDU, K.R. Division of QA, Vendor & Technical Training Center Programs (Post 850212). MERSCHOFF, E.W. Vendor Program Branch. 85/09/11. 7pp. 32875-262-32875-268.
- 8510070336** Forwards QA Program Insp Rept 99900827/85-01 on 850501. Corrective action plan for Insp Rept 99900827/84-01 re ferroresonant power supplies responsive to concerns. ZECH, G.G. Vendor Program Branch. 85/10/03. BENO, T.A. Elma Engineering Co. 2pp. 32878-233-32878-238.
- 8510070342** QA Program Insp Rept 99900827/85-01 on 850501. No noncompliance noted. Major areas inspected: actions re ferroresonant power supplies. PETROSINO, J.J., MERSCHOFF, E.W. Vendor Program Branch. 85/09/11. 4pp. 32878-235-32878-238.
- 8510080226** Forwards QA Program Insp Rept 99901020/85-01 on 850617-18, per allegation re fire test repts for Salem Unit 1 silicone foam fire seal barriers. No violations noted. ZECH, G.G. Vendor Program Branch. 85/10/04. BROWN, C.W. Brand Industrial Services, Inc. 2pp. 32921-065-32921-072.
- 8510080232** QA Program Insp Rept 99901020/85-01 on 850617-18. No violations noted. Major areas inspected: documentation supporting vendor technical disagreement w/ NRC conclusion re two unit fire stop test repts for Salem. OLLER, R.E., MERSCHOFF, E.W. Vendor Program Branch. 85/09/11. 6pp. 32921-067-32921-072.
- 8510080412** Forwards QA Program Insp Rept 99900282/85-01 on 850722-26. No failure to meet requirements noted. ZECH, G.G. Vendor Program Branch. 85/10/07. LAURENSEN, A. ITT Grinnell Corp. (subs. of ITT Corp.). 2pp. 32922-245-32922-258.
- 8510080417** QA Program Insp Rept 99900282/85-01 on 850722-26. No nonconformance noted. Major areas inspected: technical aspects of mfg deficiencies in hydraulic shock & sway suppressors (snubbers). OLLER, R.E., MERSCHOFF, E.W. Vendor Program Branch. 85/09/27. 12pp. 32922-247-32922-258.
- 8510100114** Forwards QA Program Insp Rept 99900003/85-01 on 850624 & notice of nonconformance. Insp conducted in response to allegations re possible deficiencies in implementation of QA program. ZECH, G.G. Division of QA, Vendor & Technical Training Center Programs (Post 850212). RII-84-A-0172. 85/10/04. STOH, R.J.P. Region 2, Office of Director. 2pp. 32961-156-32961-175.
- 8510100152** Confirms QA program insp at Lynchburg, VA facility on 851104-05, per 851007 telcon. ZECH, G.G. Vendor Program Branch. 85/10/08. MILUSZUSKY, W. Limitorque Corp. 1p. 32961-229-32961-229.
- 8510160298** Notifies that remaining open item re request for withholding proprietary info in Insp Rept 99901002/85-01 has not been addressed. Rept should not be released until request addressed. GORMLEY, J.W. Damon & Morey. 85/10/09. ZECH, G.G. Vendor Program Branch. 1p. 33023-361-33023-361.
- 8510170319** Discusses resolution of deficiencies in 3050 diaphragm globe valve as reported in unit 850618. Notice sent to customers & status of investigation encl. WATZ, J.P. Dresser Industries, Inc. 85/09/09. VAUGHAN, L. NRC - No Detailed Affiliation Given. 3pp. 33043-054-33043-056.
- 8510170321** Ack receipt of 850825 ltr informing NRC of steps taken to correct nonconformance noted in Insp Rept 99901018/85-01. Responses to items 1, 2, 4, 5, 6, 7, 14, 15 & 17 inadequate. Request for addl info encl. ZECH, G.G. Vendor Program Branch. 85/10/15. SUGAR, F. Nuclear Energy Services Manufacturing. 5pp. 33039-285-33039-289.
- 8510180405** Forwards QA Program Insp Rept 99900895/85-01 on 850520-21. Corrective actions on Part 21 items identified on electrical generators mfg by Beloit Power Sys reviewed. ZECH, G.G. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/10/16. LEUSINK, H. MagneTek, Inc. 2pp. 33062-176-33062-182.
- 8510180408** QA Program Insp Rept 99900895/85-01 on 850520-21. Major areas inspected: review of action taken on Part 21 repts & review of implementation of QA manual. NAIDU, K.R., MERSCHOFF, E.W. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 85/08/08. 5pp. 33062-178-33062-182.
- 8510210009** Ack receipt of 850823 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900510/84-02. ZECH, G.G. Vendor Program Branch. 85/10/17. BURRESS, H.P. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 1p. 33074-132-33074-132.
- 8510210023** Forwards QA Program Insp Rept 99900277/85-02 on 850422-24, 0522-24 & 0911-12. Several open items to be reviewed in future insps noted. ZECH, G.G. Vendor Program Branch. 85/10/18. THAYER, R.S. Rockbestos Co. 2pp. 33074-153-33074-175.
- 8510210027** QA Program Insp Rept 99900277/85-02 on 850422-24, 0522-24 & 0911-12. Major areas inspected: requalification program on currently mfg Class 1E cable types. ALEXANDER, S.D., POTAPOVS, U. Vendor Program Branch. 85/10/03. 21pp. 33074-155-33074-175.
- 8510210033** Forwards QA Program Insp Rept 99901029/85-01 on 850910-11. Instances of training matl possibly misleading NRC inspectors re characteristics of training courses isolated event. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/10/17. WHITNEY, J. General Physics Corp. 2pp. 33074-146-33074-152.
- 8510210037** QA Program Insp Rept 99901029/85-01 on 850910-11. Major areas inspected: training programs & matl that could be misleading to NRC inspectors. CONWAY, J.T., MERSCHOFF, E.W. Vendor Program Branch. 85/10/15. 5pp. 33074-148-33074-152.
- 8510210060** Advises of typo in second paragraph of App A to Insp Rept 99900731/85-01 on 850305-08. Error resulted in incorrect Part 21 ref. Corrected sentence given. ZECH, G.G. Vendor Program Branch. 85/10/17. CORSON, W. INRYCO, Inc. (subs. of Inland Steel Co.). 1p. 33072-062-33072-062.
- 8510210171** Confirms QA program insp on 851021-24, per 851015 telcon. Insp includes activities re Fort Calhoun flow measurement equipment. ZECH, G.G. Vendor Program Branch. 85/10/17. ANDERSON, M. Dieterich Standard Corp. 1p. 33071-273-33071-273.
- 8510290106** Forwards 850426 ltr informing of organizational change. Future correspondence should be addressed to M Pal. LEONARD, R.H. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 85/10/24. ZECH, G.G. Vendor Program Branch. 1p. 33235-296-33235-297.
- 8510290319** Forwards proposed Rev E to SWSQAP 1-74A, "Std Nuclear QA Program," consolidating changes per U Potapov 840411 ltr accepting 840210 changes. KELLY, R.B. Stone & Webster Engineering Corp. 85/10/25. ZECH, G.G. Vendor Program Branch. 6pp. 33235-041-33235-132.
- 8510290323** Proposed Rev E to SWSQAP 1-74A, "Std Nuclear QA Program."
* Stone & Webster Engineering Corp. 85/10/25. 86pp. 33235-047-33235-132.
- 8510300168** Forwards revised Qualification Test QR-5804, "Rept on Qualification Tests for Rockbestos Firewall III Chemically Cross-Linked Polyethylene Const..." & QR-5805, "...Firewall III Irradiation Cross-Linked Polyethylene Consts..." LITTLEHALES, G. Rockbestos Co. 85/10/25. ZECH, G.G. Vendor Program Branch. 1p. 33250-070-33250-339.
- 8510300172** QR-5804 R01 Rev 1 to Qualification Test QR-5804, "Rept on Qualification Tests for Rockbestos Firewall III Chemically Cross-Linked Polyethylene Const for Class 1E Svc in Nuclear Generating Stations."
* Rockbestos Co. 85/10/24. 150pp. 33250-071-33250-196.
- 8510300178** QR-5805 "Rept on Qualification Tests for Firewall III Irradiation Cross-Linked Polyethylene Consts for Class 1E Svc in Nuclear Generating Stations."
* Rockbestos Co. 85/10/08. 150pp. 33250-197-33250-339.
- 8510310274** Confirms QA program insp at Hartwood plant on 851030-31 & 1101, per 851023 telcon. ZECH, G.G. Vendor Program Branch. 85/10/30. ISON, W.J. National Technical Services. 1p. 33274-032-33274-032.
- 8510310310** Forwards QA Program Insp Rept 99900844/85-01 on 850722-23 & notice of nonconformance. ZECH, G.G. Vendor Program Branch. 85/10/30. MOTT, J.E. Technology for Energy Corp. 2pp. 33271-293-33271-311.
- 8510310322** Notice of nonconformance from insp on 850722-25.
* Vendor Program Branch. 85/10/30. 5pp. 33271-295-33271-299.
- 8510310326** QA Program Insp Rept 99900844/85-01 on 850722-25. Noncompliance noted: three vendors on qualified vendor list not audited & evaluated. MIEGEL, N.J., MERSCHOFF, E.W. Vendor Program Branch. 85/10/24. 12pp. 33271-300-33271-311.

REGGD REGULATORY GUIDES

- 8510010278** Submits addl info to resolve SER Open Item 10 re estimated noble gas releases through atmosphere relief valves. Design meets criteria in NUREG-0737 & Reg Guide 1.97 for monitoring effluent releases.
ZIMMERMAN, S.R. Carolina Power & Light Co. NLS-85-293. 85/09/26. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32800:314-32800:337.
- 8510020062** Rev 2 to Allegation Investigation Rept 4-84-A-06-113 re Allegation A-225 concerning whether guidelines provided in Reg Guide 1.29 were considered during instrument air piping & tubing design.
* NRC - No Detailed Affiliation Given. A-225. 84/06/13. 13pp. 32978:314-32978:327.
- 8510020123** Rev 2 to Allegation Investigation Repts 4-84-A-06-41 & 4-84-A-06-52 re Allegations A-146 & A-157. Violations noted re Procedure W-SITP-4 & Reg Guide 1.10 guidelines. Rev 1, draft Revs 1 & 2 & Drafts 1 & 2 encl.
YANG, L. NRC - No Detailed Affiliation Given. A-146. 84/06/26. 26pp. 32980:087-32980:112.
- 8510020339** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/2. Allegations A-02, A-208 & A-274 re improper certification of Mercury Const Co QC inspectors. Twelve certifications found questionable.
* NRC - No Detailed Affiliation Given. A-02. 84/06/13. 12pp. 32982:306-32982:318.
- 8510030083** Forwards SER supporting 830807 rept, "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," submitted in response to NUREG-0737, Item 1.A.2.1. Rev commitment requested within 45 days.
ZVOJINSKI, J.A. Operating Reactors Branch 5. LSOS-85-10-003. 85/10/01. FARRAR, D.L. Commonwealth Edison Co. 9pp. 32842:257-32842:265.
- 8510030234** Forwards request for addl info re revs made to FSAR by Amends 54 & 55. Info needed re revised commitment to Reg Guide 1.44 (Amend 54) & suction pipe & debris screen added to containment ventilation sys (Amend 55).
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. COUNSIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5p.. 32849:192-32849:196.
- 8510030274** Marked-up Rev 2 to Allegation Investigation Rept 4-83-A-48/1. Allegation A-01 re unverified employment records for Mercury Const Co QA personnel. Past employment not verified.
* NRC - No Detailed Affiliation Given. A-01. 84/07/19. 8pp. 32986:354-32986:361.
- 8510040019** Rev 4 to Reg Guide 1.147, "Inservice Insp Code Case Acceptability, ASME Section XI Div 1."
* Office of Nuclear Regulatory Research, Director. 85/09/30. 6pp. 32860:315-32860:320.
- 8510040073** Rev 23 to Reg Guide 1.85, "Mats Code Case Acceptability, ASME Section III, Div 1."
* Office of Nuclear Regulatory Research, Director. 85/09/30. 13pp. 32860:321-32860:334.
- 8510040205** Discusses compliance w/10CFR50.49 & Generic Ltr 85-15 re environ qualification of electrical equipment & implementation of requirements of Rev 2 of Reg Guide 1.97. Equipment will be qualified by 851130.
SORENSEN, G.C. Washington Public Power Supply System. GO2-85-655. 85/09/30. BUTLER, W.R. Licensing Branch 2. 2pp. 32851:048-32851:049.
- 8510040291** Comments on proposed Rev 2 to Reg Guide 10.8, "Guide for Preparation of Applications for Medical Programs." Apps listed should be amended to reflect description of required instrumentation.
LITTELL, J. Providence Hosp., Anchorage, AK. 85/09/25. Docketing & Services Branch. 2pp. 32954:017-32954:018.
- 8510040319** Comments on proposed Rev 1 to Reg Guide 3.52, Task CE 308-4, "Std Format & Content for Health & Safety Sections of License Renewal Applications for U Processing & Fuel Fabrication." Section 14.3 needs clarification.
VAUGHAN, C.M. General Electric Co. 85/09/27. Docketing & Services Branch. 4pp. 32853:259-32853:262.
- 8510040434** Rev 2 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern that piping supports not in compliance w/Reg Guide 1.29. No violations noted.
* NRC - No Detailed Affiliation Given. A-225. 84/06/13. 5pp. 32988:109-32988:114.
- 8510040440** Rev 3 to Allegation Investigation Rept 4-84-A-06-113 of Allegation A-225 re failure to resolve concern on piping supports not in compliance w/Reg Guide 1.29. No violations noted.
* NRC - No Detailed Affiliation Given. A-225. 84/08/30. 4pp. 32988:119-32988:122.
- 8510040579** "For Comment" issue of draft reg guide, Task ES 401-4, "Onsite Meteorological Measurement Program for U Recovery Facilities - Data Acquisition & Reporting."
* Office of Nuclear Regulatory Research, Director. 85/09/30. 8pp. 32862:198-32862:212.
- 8510040584** Draft value/impact statement on proposed reg guide, Task ES 401-4, "Onsite Meteorological Measurement Program for U Recovery Facilities - Data Acquisition & Reporting." Reg guide provides guidance re meteorological parameters.
* Office of Nuclear Regulatory Research, Director. 85/09/30. 7pp. 32862:206-32862:212.
- 8510070057** Forwards Reg Guide 1.97 compliance rept, providing description of requirements & method of complying w/ requirements for each post-accident variable identified in Table 1 of guide.
JENS, W.H. Detroit Edison Co. RC-LG-85-0050. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 130pp. 32875:126-32875:258.
- 8510070062** Requests addl time to complete mods to final status rept on Reg Guide 1.97 compliance. Rept expected by 851015.
ALEXICH, M.P. Indiana & Michigan Electric Co. AEP-NRC:0773P. 85/10/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32878:361-32878:361.

- 8510070479** Forwards Draft 3 of proposed Rev 1 to Reg Guide 1.23, Task ES 926-4, "Meteorological Measurement Program for Nuclear Power Plants." Draft endorses ANSI/ANS-2.5-1984 (ANS 2.5), "Std for Determining Meteorological Info..."
GOLLER, K.R. Division of Radiation Programs & Earth Sciences (post 840429). 85/09/16. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 32901:279-32901:294.
- 8510070483** Draft 3 of proposed Rev 1 to Reg Guide 1.23, Task ES 926-4, "Meteorological Measurement Program for Nuclear Power Plants."
* NRC - No Detailed Affiliation Given. 85/07/26. 5pp. 32901:281-32901:285.
- 8510070484** Draft value/impact statement of proposed Rev 1 to Reg Guide 1.23, Guide endorsing ANSI/ANS-2.5-1984, "Std for Determining Meteorological Info at Nuclear Power Sites," should be prepared to replace "Onsite Meteorological Program."
* NRC - No Detailed Affiliation Given. 85/07/26. 9pp. 32901:286-32901:294.
- 8510080131** Forwards Safety Insp Rept 50-440/85-53 on 850803-0913 & notice of violation.
PAPERIELLO, C.J. Region 3, Office of Director. 85/10/03. EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 32913:134-32913:156.
- 8510080140** Insp Rept 50-440/85-53 on 850803-0913. Violation noted: failure to provide adequate preoperational test procedures & failure to properly follow procedures re ECOS initiation reactor protection sys & feedwater leakage contrl.
HILLS, D.E., ODWYER, G.F., RING, M.A. Region 3, Office of Director. 85/10/02. 19pp. 32913:138-32913:156.
- 8510080203** Forwards schedule for installation of instrumentation per Reg Guide 1.97 & Suppl 1 to NUREG-0737 during Cycles 8 & 9 startup. Items include core exit temp, coolant inventory & steam generator level.
RODRIGUEZ, R.J. Sacramento Municipal Utility District. RJR 85-470. 85/09/30. THOMPSON, H.L. Division of Licensing. 6pp. 32920:254-32920:259.
- 8510080521** Forwards comments provided on marked-up draft "Generic Technical Position on Design Info Needs in Site Characterization Plan," per 850909 request. Reg Guide 4.17 should be cross-referenced w/o encl.
BERATAN, L.L. Earth Sciences Branch (post 840429). 85/10/01. GREEVES, J.T. Engineering Branch (Post 831001). 1p. 32950:357-32950:357.
- 8510090458** Deficiency Rept SDAR-197 re indeterminant compliance w/Reg Guide 1.29 concerning installation of Train C conduit on non-nuclear safety-related dead weight supports. Initially reported on 850906. Evaluation will be completed by 860122.
COUNSIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). SDAR-197. 85/09/30. HUNTER, D.R. Region 4, Office of Director. 1p. 32946:093-32946:093.
- 8510100021** Forwards responses to Reg Guide 9.3 re antitrust OL review, including changes & updates which occurred since Sept 1980.
WISENBURG, M. Houston Lighting & Power Co. ST-HL-AE-1377. 85/10/08. CLEARLY, D.P. Siting Analysis Branch. 72pp. 32959:243-32959:315.
- 8510100032** Forwards updated Reg Guide 10.8, App L containing radiation safety procedures for therapeutic use of radioactive mats. Current status on NRC requirements or guidelines requested.
CUDDENBAC, D.A. Prudential Insurance Co. of America. 85/10/02. Office of the Secretary of the Commission. 3pp. 32960:292-32960:294.
- 8510110066** Forwards Rev 1 to "GPU Nuclear Corp Operational QA Plan for TMI-1 & Oyster Creek." Exception to Reg Guide 1.37 re permissible particle sizes added for consistency w/requirements of ANSI N45.2.1-1980.
LONG, R.L. General Public Utilities Corp. - GPU Service Corp. 5211-85-2164. 85/10/02. MURLEY, T.E. Region 1, Office of Director. 10pp. 32969:033-32969:042.
- 8510110122** Summary of CRGR Meeting 79 on 850724 re proposed Rev 2 to Reg Guide 1.99, "Radiation Damage to Reactor Vessel" & NRR proposal for improving fire protection discussed in attached Encl 5. Encls 2 & 4 withheld.
STELLO, V. Committee to Review Generic Requirements. 85/08/21. DIRCKS, W.J. Office of the Executive Director for Operations. 13pp. 32974:194-32974:214.
- 8501280088** Responds to 841026 memo re Fire Protection Policy Steering Committee recommendations. List of questions & plan of action presented.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/12/10. STELLO, V. Regional Operations & Generic Requirements. 8pp. 32974:207-32974:214.
- 8510150029** Informs that 850827 application for QA program approval for Siemens cobalt source shipping container Type S1747 must be resubmitted per 10CFR71. Reg Guide 7.10 & sample QA program encl as guidance in preparing application. W/o encl.
MACDONALD, C.E. Transportation Certification Branch. 85/10/03. HORNDASCH, A.F. Siemens Medical Systems, Inc. (subs. of Siemens Capital Corp.). 1p. 33032:045-33032:045.
- 8510150290** Forwards supplemental info re conformance to Reg Guide 1.97, Rev 2, "Emergency Response Capability," per 850809 interim rept request. No incorrect assumptions identified.
SORENSEN, G.C. Washington Public Power Supply System. GO2-85-710. 85/10/08. BUTLER, W.R. Licensing Branch 2. 4pp. 33009:106-33009:109.
- 8510170418** Partial response to FOIA request for SECY-85-208, all past Regulatory Requirements Review Committee minutes & procedures used by Ofc of Investigations re util employee rights. SECY-85-208 denied. Forwards App A documents.
FELTON, J.M. Division of Rules and Records. 85/10/08. DEANE, M.R. NUS Corp. 5pp. 33064:077-33064:167.
- 8510170441** Summarizes Meeting 57 of Regulatory Requirements Review Committee on 770114. Rev 1 to proposed Reg Guide 1.97 reviewed & recommended for approval subj to footnote on research & const experience.
CASE, E.G. Regulatory Requirements Review Committee. 77/02/02. GOSSICK, L.V. Office of the Executive Director for Operations. 2pp. 33064:111-33064:112.
- 8510170443** Summarizes Meeting 58 of Regulatory Requirements Review Committee on 770128. Proposed Rev 1 to Reg Guide 1.106, characterized as Category 1, recommended.
CASE, E.G. Regulatory Requirements Review Committee. 77/02/09. GOSSICK, L.V. Office of the Executive Director for Operations. 3pp. 33064:113-33064:167.

328 NONDOCKETED ITEMS

8510180082 Forwards response to 850806 & 14 ltrs re radwaste solidification sys. Responses incorporated into Rev 3 of process control program. Proprietary NUS Process Svcs Repts FO-013 & SS-001 withheld (ref 10CFR2.790(b)(1)). EDELMAN, M.R. Cleveland Electric Illuminating Co. PY-CEI/NRR-0329. 85/08/30. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 33056:206-33056:318.

8510180171 Requests that encl documents re regulatory history on proposed revs to 10CFR73.71 for reporting requirements for safeguards events be placed in Document Control Sys. YARDUMIAN, J. Reactor & Transportation Licensing Branch. AB46-1 01. 85/10/09. GARTNER, D. Division of Technical Information & Document Control. 1p. 33078:041-33078:123.

8510180321 Advises that CRGR review of proposed rev to 10CFR73.71 & Reg Guide 5.62 re notification requirements for safeguards events appropriate to ensure consistent safety threshold event reporting. CRGR review will focus on listed areas. STELLO, V. Regional Operations & Generic Requirements. AB46-1 39. 84/09/25. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 33078:211-33078:213.

8510180189 Forwards response to FSAR or draft SER items, including items D 4.4-3 re loose parts monitoring sys, per Rev 1 to Reg Guide 1.133 & D 12.3-4 re containment radiation monitors, per NUREG-0737, item ILF.1.3. WISENBURG, M.R. Houston Lighting & Power Co. ST-HL-AE-1419. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33062:302-33062:310.

8510180245 Forwards response to NRC Question 260.59 re compliance w/ Rev 1 to Reg Guide 1.123. Revised Section 1.8 will be included in future amend to FSAR. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. B11762. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 5pp. 33061:084-33061:088.

8510180283 Comments on proposed Rev 2 to Reg Guide 10.8, "Guide for Preparation of Applications for Medical Programs." Rev comprehensive & thorough. MOUNT, D.K. North Dakota, State of. 85/10/11. Docketing & Services Branch. 1p. 33061:005-33061:005.

8510180438 Forwards response to draft SER or FSAR items concerning recirculation intake structures per Reg Guide 1.82. Encl marked-up FSAR pages will be incorporated in future FSAR amend. WISENBURG, M.R. Houston Lighting & Power Co. ST-HL-AE-139x. 85/10/12. KNIGHTON, G.W. Licensing Branch 3. 5pp. 33056:339-33056:344.

8510180438 Advises that licensee followup & corrective actions re bioassay results in excess of 15 micrograms/liter conform to requirements of Reg Guide 8.22. No licensing action necessary. JERREE, C.C., PETTENGILL, H.J. Uranium Recovery Field Office. 85/10/03. Uranium Recovery Field Office. 3pp. 33077:114-33077:116.

8510120036 Informs that majority of instrument sensors & control room indicators required for compliance w/ Rev 3 to Reg Guide 1.97 installed. Installation verified to be approx 90% complete. SPANGENBERG, F. Illinois Power Co. U-600287. 85/10/17. BUTLER, W.R. Licensing Branch 2. 2pp. 33072:340-33072:341.

8510120095 Application for amend to License NPF-21, changing License Condition 16 to implement installation or upgrade requirements of Rev 2 to Reg Guide 1.97 for flux monitoring prior to startup following second refueling outage. Fee paid. SORENSON, G.C. Washington Public Power Supply System. G02-85-724. 85/10/14. BUTLER, W.R. Licensing Branch 2. 4pp. 33072:275-33072:278.

8510120122 Requests extension to complete commitments for Reg Guide 1.97 & Suppl 1 to NUREG-0737 re SPDS, in response to 840614 confirmatory order. Several items cannot be completed before resuming power operation. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-683. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. THOMPSON, H.L. Division of Licensing. 6pp. 33072:243-33072:248.

8510120149 Submits schedule for upgrades to plant instrumentation per requirements of Suppl 1 to NUREG-0737, Rev 2 to Reg Guide 1.97 & Generic Ltr 84-23. Mods will not be fully implemented until 1988 Cycle 9/10 refueling outage. MCGAUGHY, R.W. Iowa Electric Light & Power Co. NG-85-4481. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 33071:142-33071:144.

8510220186 Requests schedular exemption to submit updated FSAR by 870331 for Millstone Unit 1 & by 870630 for Haddam Neck Plant (ref 10CFR50.71(e)). Complete adoption of format to Rev 3 to Reg Guide 1.70 not planned. OPEKA, J.F. Connecticut Yankee Atomic Power Co. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA, J.F. Northeast Utilities. A05282. 85/10/11. THOMPSON, H.L. Division of Licensing. 3pp. 33090:053-33090:055.

8510220249 Forwards status rept. "Implementation Plan of Reg Guide 1.97, Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," in response to 840612 licensing order. Rept reflects final plan for disposition of &/or compliance w/ reg guide. ALEXICH, M.P. Indiana & Michigan Electric Co. AEP-NRC-07730. 85/10/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33083:329-33083:359.

8510220255 "Implementation Plan of Reg Guide 1.97, Rev 3 for Donald C Cook Nuclear Plant Units 1 & 2," as rept. * Indiana & Michigan Electric Co. AEP-NRC-07730. 85/10/15. 29pp. 33083:331-33083:359.

8510220295 Forwards rev. w/ integrated safety assessment program Topic 1.36, "Tech Specs Covered by Generic Ltr 83-38," per 850517 commitment. OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). GL-83-36. 85/10/15. GRIMES, C.J. Systematic Evaluation Program Branch. 5pp. 33086:310-33086:314.

8510240444 Forwards add info re 840402 submittal on Section 6 of Suppl 1 to NUREG-0737, "Reg Guide 1.97-Application to Emergency Response Facilities," requested in NRC 850613 ltr. Existing instrumentation meets needs for post-accident monitoring. MANGAN, C.V. Niagara Mohawk Power Corp. GL-82-33. 85/10/18. VASSALLO, D.B. Operating Reactors Branch 2. 25pp. 33149:011-33149:035.

8510240521 Forwards application for certificate of compliance for Model DHTF for transport of enriched U dioxide. Certification of conformance to IAEA safety slide requested. Fee paid. WATTERS, J.P. Babcock & Wilcox Co. 25883. 85/09/30. MACDONALD, C.E. Transportation Certification Branch. 3pp. 33179:194-33180:076.

8510250164 Comments on proposed Rev 2 to Reg Guide 10.8 re preparation & maint of good radiation safety program. Supports rev. DAY, J. Hahnemann Univ., Philadelphia, PA. 85/10/16. Docketing & Services Branch. 3pp. 33166:301-33166:303.

8510250197 Forwards responses to requests for add justification for exceptions to Reg Guide 1.97, included in 850806 draft technical evaluation rept. Narrow-range containment sump level has no intended accident monitoring function. TUCKER, H.B. Duke Power Co. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 8pp. 33172:131-33172:138.

8510250385 Forwards response to WR Butler 850819 ltr re review of EG&G evaluation of implementation of Rev 2 to Reg Guide 1.97 concerning emergency response capability. LEONARD, J.D. Long Island Lighting Co. SNRC-1209. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 33172:158-33172:162.

8510250502 Advises of proposed action on reg guides discussed at 306th meeting on 851010-12. Supports proposed Rev 2 to Reg Guide 1.105, draft reg guide, Task IC 609-5 & proposed Rev 1 to Reg Guide 1.23. WARD, D.A. ACRS - Advisory Committee on Reactor Safeguards. 85/10/15. DIRCKS, W. Office of the Executive Director for Operations. 2pp. 33171:361-33171:362.

8510280175 Forwards responses to interim evaluation rept Section 4 open items re conformance to Reg Guide 1.97. Reg guide guidance superseded by 10CFR50.49. Environ qualification rept contains identified equipment. PAPANIC, G. Yankee Atomic Electric Co. FYR 85-113. 85/10/22. ZWOLINSKI, J.A. Operating Reactors Branch 5. 6pp. 33191:087-33191:092.

8510280443 Forwards safety evaluation & EG&G technical evaluation rept accepting 830415, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/ Rev 2 to Reg Guide 1.97. BUTCHER, E.J. Operating Reactors Branch 3. GL-82-33. 85/10/18. MUSOLF, D.M. Northern States Power Co. 3pp. 33196:270-33196:295.

8510280448 Safety evaluation accepting unit 830415, 0915, 850118 & 0606 responses to Generic Ltr 82-33 re conformance of post-accident monitoring instrumentation w/ Rev 2 to Reg Guide 1.97. * Office of Nuclear Reactor Regulation, Director. GL-82-33. 85/10/18. 2pp. 33196:273-33196:295.

8510280451 "Conformance to Reg Guide 1.97, Prairie Island Nuclear Generating Plant, Units 1 & 2." UDY, A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN 84-6483. GL-82-33. 85/08/31. Division of Systems Integration (post 811005). 21pp. 33196:275-33196:295.

8510290445 Forwards application for amend to License NPF-29, revising Tech Spec 6.3.1 for one-line exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. Fee paid. KINGSLEY, O.D. Mississippi Power & Light Co. AECM-85/0346. 85/10/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33240:001-33240:014.

8510290449 Application for amend to License NPF-29, revising Tech Spec 6.3.1 for one-time exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. KINGSLEY, O.D. Mississippi Power & Light Co. AECM-85/0346. 85/10/23. 7pp. 33240:003-33240:009.

8510290451 Proposed Tech Spec 6.3.1 for one-time exception of Reg Guide 1.8 re qualifications of chemistry/radiation control superintendent. * Mississippi Power & Light Co. 85/10/23. 5pp. 33240:010-33240:014.

8510300129 Final Deficiency Rept [RDC 143(85)] re failure to provide divisional separation requirements for neutron monitoring sys, per Reg Guide 1.75. Initially reported on 850710. Condition not reportable per 10CFR50.55(e). EDELMAN, M.R. Cleveland Electric Illuminating Co. [RDC 143(85)]. 85/10/17. KEPLER, J.G. Region 3, Office of Director. 2pp. 33257:169-33257:170.

8510310211 Forwards add info in response to NRC 850819 request on 841030 response to Generic Ltr 82-33 re conformance to Rev 3 to Reg Guide 1.97, Suppl 1 to NUREG-0737. MURPHY, W.P. Vermont Yankee Nuclear Power Corp. FVY-85-99. 85/10/25. VASSALLO, D.B. Operating Reactors Branch 2. 10pp. 33273:163-33273:172.

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8405240363 Research Info Ltr 140, "Handbook of Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications." Recommends handbook be used to achieve improved estimates of human error likelihood in nuclear plant operations. MINOGUE, R.B. Office of Nuclear Regulatory Research, Director. 84/05/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 33196:244-33196:250.

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8402280501 Notification of CRGR Meeting 50 on 831026, in response to request for expeditious review of draft ltr re Util Safety Classification Group concerns on NRC position on terms important to safety & safety-related. STELLO, V. Committee to Review Generic Requirements. 83/10/21. MATTON, R.J. Office of Nuclear Reactor Regulation, Director. 2pp. 32927:022-32927:023.

8403140316 Forwards final drafts of two NRC ltrs re definition of terms important to safety & safety-related. Ltrs inform permittees or licensees of responsibility to comply w/ existing NRC requirements. No CRGR review required. DENTON, H.R. NRC - No Detailed Affiliation Given. 83-095. 83/10/20. STELLO, V. NRC - No Detailed Affiliation Given. 9pp. 32927:024-32927:032.

8509300340 Board Notification 85-084: notifies of ACRS review of SSERs 7-11, during ACRS 305th meeting on 850912-14 NRC taking appropriate actions. DA Ward 850918 memo encl.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. PALLA-DINO, ROBERTS, ASSELSTINE Commissioners. 2pp. 32853:269-32853:271.

8510010059 Clarifies 850605 ltr re use of ASME Code Cases N-397 & N-411. Ltr gave generic approval provided listed items (a) through (f) implemented. Response to whether CP amend needed requested.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/25. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32833:167-32833:171.

8510010063 Responds to 850201 questions re reactor coolant pump motor failure & cutting of spent fuel pool liner. Unit 1 reactor coolant pump Motor 4 tripped on 841028 due to Phase A & B overcurrent condition caused by insulation breakdown.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/26. ELLIS, J. Citizens Association for Sound Energy. 7pp. 32833:160-32833:166.

8510010324 Forwards Rev 0 to NCIG-02 "Sampling Plan for Visual Insp of Welds" for review & acceptance. Plan provides uniform technically acceptable method of determining acceptability of given population of welds.
DUTTON, D.E. Nuclear Construction Issues Group. 85/09/27. KNIGHT, J.P. Division of Engineering. 4pp. 32803:095-32803:125.

-8510010378 Rev 0 to NCIG-02, "Sampling Plan for Visual Insp of Welds."
* Southern Co. Services, Inc. 85/09/27. 28pp. 32803:099-32803:125.

8510030122 Board Notification 85-087: forwards VS Noonan 850930 ltr to util & Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns," per Commission 840706 revised notification policy.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/03. PALLA-DINO, ROBERTS, ASSELSTINE Commissioners. 2pp. 32966:360-32967:098.

8510030234 Forwards request for addl info re revs made to FSAR by Amends 54 & 55. Info needed re revised commitment to Reg Guide 1.44 (Amend 54) & suction pipe & debris screen added to containment ventilation sys (Amend 55).
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 5pp. 32849:192-32849:196.

8510030252 Notification of 851002 & 03 meetings w/util in Granbury, TX to discuss basis for establishing homogeneous hardware populations for const adequacy review & S&W piping & pipe support walkdowns.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/09/27. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 8pp. 32849:107-32849:114.

8510040323 Forwards GE affidavit attesting to confidentiality of info supplied to NRC by Instrument Setpoint Methodology Group in response to 850813 ltr. Listed documents should be withheld (ref 10CFR2.790).
CAROLAN, J.F. IRG Instrumentation Setpoint Methodology Group. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 7pp. 32853:252-32853:258.

8510070494 Forwards Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns."
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/09/30. COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 6pp. 32901:298-32902:036.

-8510070496 Rev 2 to "Staff Evaluation of Comanche Peak Response Team Program Plan: Detailed Comments/Concerns."
* Comanche Peak Project (Technical Review Team). 85/09/30. 93pp. 32901:304-32902:036.

8510090275 Modifies meeting time & agenda for CRGR Meeting 78 on 850708. Agenda includes encl proposed resolution of Unresolved Safety Issue (USI) A-46 & encl updated recommendations on fire protection w/o USI A-46 info.
STELLO, V. Committee to Review Generic Requirements. 85/06/28. BERNERO, R. Office of Nuclear Reactor Regulation, Director. JORDAN, E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 32946:232-32946:233.

-8507110595 Forwards draft Commission paper re implementation of 10CFR50, App R fire protection requirements. Response to W Dircks 841210 memo & comments on updated steering committee report also encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 85/06/24. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 32946:234-32946:242.

-8502110622 Provides recommendations for resolution of current fire protection issues to develop policy for expediting 10CFR50, App R compliance for older plants & assuring consistent levels of fire protection safety at all plants.
GRACE, J.N. Fire Protection Policy Steering Committee. 84/10/26. DIRCKS, W.J. Office of the Executive Director for Operations. 7pp. 32946:243-32946:310.

-8407090031 Comments on S Trubatch 840529 memo on App R guidance re fire protection in response to 840608 request.
OLMSTEAD, W.J. Regulations Division. 84/06/27. VOLLMER, R.H. Division of Engineering. 26pp. 32946:311-32946:338.

-8504080378 Forwards risk perspective on fires in nuclear power plants, requested for inclusion in forthcoming Commission paper.
SPEIS, T.P. Division of Safety Technology. 85/03/20. KNIGHT, J.P. Division of Engineering. 8pp. 32946:339-32946:346.

-8503130606 Submits resource estimates for proposed expedited fire protection insps. per EDO 841210 request. Impact on IE insp program would be significant. Recommends safe shutdown insps be conducted as previously planned.
TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 85/03/06. KNIGHT, J. Division of Engineering. 3pp. 32946:347-32946:352.

-8510090290 Draft Commission paper re implementation of 10CFR50, App R concerning fire protection. Issuance of generic ltr, fire protection insps & mod of fire protection Tech Specs recommended.
DIRCKS, W.J. Office of the Executive Director for Operations. GL-83-33. 85/06/21. 15pp. 32946:353-32947:079.

8510090504 Summary of CRGR Meeting 78 on 850708 re proposed resolution of Generic Issue A-46, "Seismic Qualification of Equipment in Operating Plants." Encl 3 re recommendations of fire protection policy encl w/o Encls 1, 2 & 4-6.
STELLO, V. Committee to Review Generic Requirements. 85/06/20. DIRCKS, W.J. Office of the Executive Director for Operations. 4pp. 32946:060-32946:063.

8510100001 Forwards Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Procedure developed per recommendations made in WV Johnston 850829 memo to VS Noonan.
COUNCIL, W.G. MARSHALL, J.S. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). TXU-4580. 85/10/03. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 1p. 32961:067-32961:075.

-8510100008 Rev 0 to CPP-022, "Supplementary Evaluation of Visual Welding Insp Techniques." Comanche Peak Response Team project procedure for QA/QC issue-specific Action Plans VII.6.3, VII.6.5 & VII.c.
CHRISTENSEN, J., RONG, W., HAUSEL, J.L. Evaluation Research Corp. 85/09/27. 8pp. 32961:068-32961:075.

8510110122 Summary of CRGR Meeting 79 on 850724 re proposed Rev 2 to Reg Guide 1.99, "Radiation Damage to Reactor Vessel" & NRR proposal for improving fire protection discussed in attached Encl 5. Encls 2 & 4 withheld.
STELLO, V. Committee to Review Generic Requirements. 85/06/21. DIRCKS, W.J. Office of the Executive Director for Operations. 13pp. 32974:194-32974:214.

-8501260088 Responds to 841026 memo re Fire Protection Policy Steering Committee recommendations. List of questions & plan of action presented.
DIRCKS, W.J. Office of the Executive Director for Operations. 84/12/10. STELLO, V. Regional Operations & Generic Requirements. 8pp. 32974:207-32974:214.

8510150239 Notification of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
COOK, A.V. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33032:217-33032:221.

8510170337 Notification of cancellation of 851023 & 24 meetings w/CASE in Bethesda, MD to discuss SSERs 7-11.
VIETTI-COOK, A. Comanche Peak Project (Technical Review Team). 85/10/09. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 4pp. 33043:348-33043:351.

8510170479 Expresses appreciation for 850815 comments on Comanche Peak Response Team program plan. Review of plan will be complete following applicant response to all NRC concerns.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/12. GARDE, B.P. Trial Lawyers for Public Justice, P.C. 1pp. 33048:143-33048:143.

8510180097 Responds to 850923 ltr CRGR recommendations to issue staff proposed package of App J rule revs & reg guide for public comment reaffirmed. Comments on proposed reg guide welcomed as part of public comment process.
STELLO, V. Regional Operations & Generic Requirements. 85/10/08. REYTBLETT, Z.V. Illinois Institute of Technology, Chicago, IL. 1p. 33069:298-33069:301.

-8510180099 Requests that CRGR reverse decision to allow public comment on draft reg guide & review independently-developed draft reg guide to be submitted for public comment if meritorious.
REYTBLETT, Z.V. Illinois Institute of Technology, Chicago, IL. 85/09/23. STELLO, V. Committee to Review Generic Requirements. 3pp. 33069:299-33069:301.

8510180112 Notices of CRGR Meeting 82 on 851023 in Bethesda, MD to discuss listed agenda items, including proposed rev to 10CFR72 re licensing requirements for ISFSI & proposed final insider safeguards rules w/o stated encls.
STELLO, V. Committee to Review Generic Requirements. 85/10/11. BERNERO, R. Office of Nuclear Reactor Regulation, Director. JORDAN, E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 33069:282-33069:283.

8510180159 Forwards table providing revised description of Amend 56 to FSAR.
COUNCIL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). TXU-4587. 85/10/15. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 5pp. 33058:260-33058:264.

8510180171 Requests that encl documents re regulatory history on proposed revs to 10CFR73.71 for reporting requirements for safeguards events be placed in Document Control Sys.
YARDUMIAN, J. Reactor & Transportation Licensing Branch. AB46-1 01. 85/10/09. GARTNER, D. Division of Technical Information & Document Control. 1p. 33078:041-33078:253.

-8510180256 Forwards draft independent review package re rulemaking sponsored by NMSS & RES Independent Review Board consisting of voting sheets reflecting deliberations. NRC should proceed w/rulemaking.
GILLESPIE, F.P. Research Independent Review Board. AB46-1 29. 84/10/12. MINOQUE, R.B. Office of Nuclear Regulatory Research, Director. 1p. 33078:132-33078:132.

-8510180264 RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Draft RES independent recommendations should be modified as listed.
BASSETT, O.E. Research Independent Review Board. AB46-1 30. 84/07/17. BERNERO, R.M. Research Independent Review Board. 1p. 33078:133-33078:133.

-8510180272 RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Draft RES independent recommendations should be modified as listed.
GOLLER, K.R. Research Independent Review Board. AB46-1 31. 84/07/17. BERNERO, R.M. Research Independent Review Board. 1p. 33078:134-33078:134.

-8510180280 RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Agrees w/draft RES independent review package.
* Research Independent Review Board. AB46-1 32. 84/07/30. BERNERO, R.M. Research Independent Review Board. 1p. 33078:135-33078:135.

330 NONDOCKETED ITEMS

—**8510180286** RES Independent Review Board voting sheet re rulemaking, "Reporting Requirements for Safeguards Events." Agrees w/draft RES independent review package.
BERNERO,R.M. Research Independent Review Board. AB46-1 33. 84/07/31. 2pp. 33078:136-33078:137.

—**8510180297** Forwards rulemaking review package for action, per procedures approved by EDO on 840530. Draft independent review package for rulemaking should be submitted within 5 days of memo date.
BERNERO,R.M. Research Independent Review Board. AB46-1 35. 84/06/15. NORBERG,J.A. Human Factors & Safeguards Branch. 3pp. 33078:142-33078:144.

8510210055 Modifies agenda for CRGR Meeting 82 on 851023. Scheduled briefing on proposed rev to 10CFR72, "Licensing Requirements for Storage of Spent Fuel in ISFSI," postponed per RES request.
STELLO,V. Committee to Review Generic Requirements. 85/10/18. BERNERO,R. Office of Nuclear Reactor Regulation, Director. JORDAN,E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM,R.E. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 33073:209-33073:210.

8510210131 Forwards update of results of util evaluation of design review/quality revalidation recommendations re maint & surveillance activities associated w/TDI diesel generators & provides clarification concerning several rept components.
COUNSIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). TOX-4556. 85/10/14. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 3pp. 33072:231-33072:239.

8510220110 Advises that implementation of ATWS mitigating sys actuation circuitry (AMSAC), per Generic Ltr 85-06, scheduled for 861201, based on NRC approval of WCAP-10858, "AMSAC Generic Design Package."
COUNSIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). GL-85-06. 85/10/14. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 1p. 33090:150-33090:150.

8510220125 Further response to FOIA request for documents re EG&G rept on harassment & intimidation. Forwards App B documents. Documents also available in PDR. Portions of App C Documents 1-4 withheld (ref FOIA Exemptions 4 & 6).
FELTON,J.M. Division of Rules and Records. 85/10/16. GARDE,B. Government Accountability Project. 4pp. 33099:325-33100:110.

—**8510220206** Forwards INEL planned staffing for Cycle 4 Comanche Peak Technical Review Team. Planned staffing for Cycle 5 will be identified as soon as possible.
WILLIAMS,M.H. Division of Licensing. 84/09/06. IPPOLITO,T.A. Comanche Peak Project (Technical Review Team). 2pp. 33100:051-33100:052.

8510220440 Summary of 850917 meeting w/util in Bethesda, MD re visual insp of welds through paints. Transcript & viewgraphs encl.
VIETTI-COOK,A. Comanche Peak Project (Technical Review Team). 85/10/17. Comanche Peak Project (Technical Review Team). 5pp. 33098:357-33099:001.

—**8509040052** Responds to 850813 request for review of util position paper re visual insp of painted support welds. Reinsp through paint acceptable to determine presence, location & size, not quality of structural steel weldments.
JOHNSTON,W.V. Assistant Director for Matis, Chem. & Environ Technology (Post 830201). 85/08/29. NOONAN,V.S. Comanche Peak Project (Technical Review Team). 3pp. 33099:089-33099:091.

8510240070 Summary of 851002-03 meetings w/util in Granbury, TX re basis for establishing homogeneous hardware populations for const adequacy review & S&W pipe & pipe support reanalysis program.
VIETTI-COOK,A. Comanche Peak Project (Technical Review Team). 85/10/18. Comanche Peak Project (Technical Review Team). 6pp. 33178:012-33178:199.

8510240588 Grants request to withhold CAW-85-057, "Improved Thermal Design Procedures," per 850830 application. 761202 affidavit & 850905 ltr providing responses to questions on procedures per 10CFR2.790.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/10/17. WIESEMAN,R.A. Westinghouse Electric Corp. 4pp. 33185:215-33185:218.

8510280518 Response to CASE 850827 interrogatories to applicants & requests to produce & request for protective order. Certificate of Svc encl. Related correspondence.
TYLERT,G. Comanche Peak Project (Technical Review Team). DIGNAN,T.G. Ropes & Gray. DIGNAN,T.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). #485 943. OL 85/10/22. Citizens Association for Sound Energy. 72p. 33227:225-33227:296.

8510310003 Forwards SSER 12 (NUREG-0797). Resolution of outstanding issues re fire protection program, including alternate safe shutdown capability, noteworthy W/o encl.
NOONAN,V.S. Comanche Peak Project (Technical Review Team). 85/10/24. COUNSIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp. 33277:103-33277:107.

SECY POSITION PAPERS BEFORE THE COMMISSION

8510150157 SECY-85-306 Provides Commission w/recommendations for expediting & improving implementation of App R re fire protection. Fire protection license conditions should be removed from future licenses if fire protection plan incorporated in FSAR.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/09/17. 101pp. 33031:186-33031:289.

8510150421 Forwards comments re Incident Investigation Program improvement for future team efforts, in response to 850822 memo.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 85/10/09. HELTEMES,C.J. AEOD, Director's Office. 8pp. 33033:206-33033:237.

—**8507090487** SECY-85-208 Requests Commission approval of plans to improve existing program for investigation of significant operational events.
DIRCKS,W.J. Office of the Executive Director for Operations. 85/06/10. 8pp. 33033:227-33033:234.

STATE PROG STATE PROGRAMS

8510010068 Ack positions in 850827 & 0912 ltrs re pending overinsp program termination requests & proposed suspension of program activities. Responses to comments encl. Approval of termination requests discussed.
KEPPLER,J.G. Region 3, Office of Director. 85/09/26. SAMELSON,A. Illinois, State of. 9pp. 32800:302-32800:310.

8510010136 Forwards revised summary of 850819 meeting in Carson City, NV to clarify comments on draft environ assessment for Yucca Mountain site.
LOUX,R.F. Nevada, State of. 761. 85/08/21. BENSON,A. Energy, Dept. of. 17pp. 32833:292-32833:308.

8510010283 Responds to FOIA request for background records of all insps on facility since Dec 1982, per 841210 oral agreement. Forwards documents listed on app. Documents also available in PDR.
FELTON,J.M. Division of Rules and Records. 85/02/27. BERNABEI,L. Government Accountability Project. 32pp. 32884:005-32884:234.

—**8510010454** Confirms 830408 telcon re requested one wk extension of deadline for submission of Waterford exercise scenario.
COLLINS,S.C. Louisiana, State of. 83/04/12. HACKNEY,C. Region 4, Office of Director. 75pp. 32894:318-32895:123.

8510010506 Forwards insert of Page 39, Line 827 of 850417 hearing record on NRC budget. Insert provides addl views on estimate of crude cumulative probability of core melt accident.
KAMMERER,C. Office of Congressional Affairs. 85/09/16. MARKEY,E. House of Rep., Energy & Commerce. 7pp. 32832:060-32832:116.

—**8510010536** Ack receipt of 850826 ltr re agreement w/NRC to allow State of IA to assume regulatory authority over certain sources of ionizing radiation. Assessment of proposal in progress & will be issued for comment.
PALLADINO,N.J. Commissioners. 85/09/18. BRANSTAD,T.E. Iowa, State of. 1p. 32832:079-32832:079.

—**8510010544** Requests agreement w/NRC to allow State of IA to assume regulatory authority for certain radioactive mats currently under NRC jurisdiction. Formal agreement signing ceremony unnecessary.
BRANSTAD,T.E. Iowa, State of. 85/08/22. PALLADINO,N.J. Commissioners. 9pp. 32832:080-32832:088.

8510020524 "State of IA Radiation Control Plan & Rules." JO Lubenau 850925 transmittal memo encl.
Iowa, State of. 85/10/02. 499pp. 32836:290-32838:068.

8510030056 Discusses proposal to Commonwealth of PA, Dept of Environ Resources to use preoperational chemical cleaning basins as disposal facility for site-generated filter cake. Phase I & II submittals encl.
HUKILL,H.D. General Public Utilities Corp. - GPU Service Corp. 5211-85-2162. 85/09/27. STOLZ,J.F. Operating Reactors Branch 4. 100pp. 32844:342-32845:079.

8510040193 Forwards response to 850718 ltr re results of State of AZ radiation control program during June 1985 review. Internal procedures should be completed within 1 yr. Solution to data processing being sought.
TEDFORD,C.F. Arizona, State of. 85/08/23. MARTIN,J.B. Region 5, Office of Director. 6pp. 32851:030-32851:035.

8510040247 Advises that State of IL, Dept of Nuclear Safety, review of util emergency Tech Spec amends to Licenses NPF 11 & NPF-18 re waiver of 18-month surveillance interval, revealed no adverse findings.
PARKER,M.C. Illinois, State of. DOE-85-162. 85/09/25. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32851:078-32851:078.

8510040474 Revised "OH State Plan for Response to Radiation Emergencies at Licensed Nuclear Facilities." W/851001 ltr.
LOCKHART,R.M. Ohio, State of. AGOH-DS. 85/10/01. YOUNGBLOOD,B.J. Licensing Branch 1. 415pp. 32851:240-32852:286.

8510070323 Confirms 850828 discussion w/UT Howell & LE Jerrett following review & evaluation of State of FL radiation control program. Sys should be implemented to assure that timely enforcement ltrs issued.
GRACE,J.N. Region 2, Office of Director. 85/10/01. PINGREE,D.H. Florida, State of. 6pp. 32878:355-32878:360.

8510070351 Amended petition for rulemaking PRM-60-2 re EPA final stds for protection of general environ from offsite releases from radioactive matl in repositories.
SWAINSTON,H. MURPHY,M.R. Nevada, State of. OLSON,J.F. Minnesota, State of. 85/09/30. Commissioners. 15pp. 32875:020-32875:034.

8510080123 Forwards FEMA finding & determination verifying State of TX & local emergency preparedness plans adequate to protect public health & can be implemented offsite per NUREG-0654. Public alert & notification sys adequate.
DENISE,R.P. Region 4, Office of Director. 85/10/03. COUNSIL,W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 2pp. 32914:326-32915:182.

8510090450 Approves 850823 response to NRC review of Agreement State radiation control program w/execution of state regulations. Status of regulations comparable pending rev approval & adoption into state program.
MARTIN,J.B. NRC - No Detailed Affiliation Given. 85/10/04. TEDFORD,C.F. Arizona, State of. 1p. 32922:324-32922:324.

8510090523 Discusses status of efforts to make State of KS radiation control agreement program compatible w/NRC, in response to 850815 ltr. Div of Environ 850912 internal memo re RH5-7 insp priority sys radioactive mats.
SABOL,B.J. Kansas, State of. 85/09/25. MARTIN,R.D. Region 4, Office of Director. 4pp. 32927:145-32927:152.

8510090175 Forwards TH Bartlett ltr defining methods used to analyze selenium, arsenic & mercury in water samples from Collins Draw Project Site, per 850913 discussion.
LAUDERBACK,T.E. Cleveland-Cliffs Iron Co. 00933. 85/09/25. WASTLER,S. Uranium Recovery Field Office. HOGG,S. Wyoming, State of. 2pp. 32948:195-32948:196.

- 8510090222** Informs of approval of 850508 modified reclamation plan leaving big surface road & other mine structures for use of surface owner. F. Brown. Approval for abandonment of property pending state & NRC acceptance of wellfields restoration. MOONEY, G. Wyoming, State of. 00939. 85/09/16. LAUDERBACK, T.E. Cleveland-Cliffs Iron Co. 1p. 32949:199-32949:199.
- 8510090241** Forwards NRC 850722 ltr to Nuclear Packaging re reconstr of ENVIRALLOY family topical rpt, for info. W/o encl. SCHNEIDER, K.N. Assistant Director for State Agreements Programs. 85/07/31. ATRY, V.R. South Carolina, State of. 2pp. 32949:192-32949:193.
- 8510090267** Ack receipt of Custody Receipt 20413 for US Treasury Bill, CUSIP 912794JA3. Treasury bill accepted as replacement bonding instrument for US Treasury Bill, CUSIP 912794HZ0 which matured on 850919. BRYAN, V.J. Wyoming, State of. 00927. 85/09/19. FERGUSON, J.C. American Nuclear Corp. 3pp. 32948:246-32948:248.
- 8510090269** Discusses review of Westinghouse 850710 request for review of updated Ingray Permit 478 documents re hydrologic issues. HOGG, S. Wyoming, State of. 00924. 85/09/17. Wyoming, State of. 13pp. 32948:233-32948:245.
- 8510090310** Mod A008 to Cooperative Agreement DE-FC04-81AL16309, increasing DOE capital funds in Article VIII, "Cost Limitation & Obligation of Funds." HOYAL, J.G. Energy, Dept. of. 85/09/27. 2pp. 32950:104-32950:105.
- 8510090421** Forwards monthly update & schedule for site & near-term site characterization for site & engineered barriers dept activities. Info will be updated on regular basis. OLSON, O.L. Washington, State of. 1562. 85/09/20. HUSSEMAN, T. Washington, State of. POWER, M.S. Evergreen State College, Olympia, WA. J.M.R.R. Yakima Indian Nation. 6pp. 32964:286-32964:291.
- 8510100038** Forwards expurgated testimony of D Williams to be substituted for prefired testimony previously furnished & expurgated, per J Kelley 850930 ruling. Related correspondence. THORNBURG, L.H. North Carolina, State of. #485 686. OL. 85/10/04. Docketing & Services Branch. 1p. 32960:245-32960:245.
- 8510100047** Expurgated testimony of D Williams re undercover drug investigation at facility. Related correspondence. WILLIAMS, D. North Carolina, State of. WILLIAMS, D. Justice, Dept. of, Drug Enforcement Administration. OL. 85/10/04. 17pp. 32960:246-32960:262.
- 8510100042** Forwards State of NY Supreme Court order to show cause why Nassau County, NY county executive should not cease & desist from offering use of facilities or personnel for facility evacuation plan. Related correspondence. PALOMINO, F.G. New York, State of. #485 684. OL. 85/10/01. NRC - No Detailed Affiliation Given. 15pp. 32960:263-32960:277.
- 8510100058** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility requirements. Recommends that operating contractors & other applicable contractors at DOE & other federal govt facilities be included. WEST, C.P. Tennessee, State of. 50FR23960 122. 85/10/02. CHILK, S.J. Office of the Secretary of the Commission. 1p. 32961:082-32961:082.
- 8510100121** Forwards 850930 amended petition for rulemaking PRM-60-2 filed by States of NV & MN. Amend places substance of assurance requirements before Commission & proposes mechanism to ensure public health & safety. DAVENPORT, J.H. Duryea, Houchins, Murphy & Davenport. 50FR18267. 85/10/01. PALLADINO, N.J. Commissioners. 2pp. 32960:034-32960:051.
- 8510100127** Forwards amended petition for rulemaking PRM-60-2 from States of NV & MN. Petition amends petition submitted on 840122. DAVENPORT, J.H. Duryea, Houchins, Murphy & Davenport. 85/09/30. CHILK, S. Office of the Secretary of the Commission. 1p. 32960:036-32960:036.
- 8510100133** Amended petition for rulemaking PRM-60-02 placing before Commission substance of assurance requirements & providing mechanism to ensure Commission responsibility to protect health & safety of public not compromised. SWAINSTON, H., MURPHY, M.R., DAVENPORT, J.H. Nevada, State of. 85/09/30. Commissioners. 15pp. 32960:037-32960:051.
- 8510100162** Comments on proposed rules 10CFR30.40, 51.70 & 72 re decommissioning criteria for nuclear facilities. Data may not accurately reflect costs involved in full-scale commercial nuclear plant decommissioning. ALSWORTH, M.W. Oregon, State of. 50FR5600 140. 85/10/03. Docketing & Services Branch. 5pp. 32962:010-32962:014.
- 851010005** Forwards RB Hubbard 850927 analysis of facility IDVP, per 851001 conversation w/ GT Ankun & conversation w/ R Hubbard. Sargent & Lundy audit failed to confirm adequacy of current utility design activities. THURBER, J.P. New Jersey, State of. 85/10/01. MILHOAN, J. NRC - No Detailed Affiliation Given. 10pp. 32999:252-32999:261.
- 8510110141** Advises that no adverse findings identified based on review of proposed amendments to Licenses NPF-11 & NPF-18, changing Tech Specs re diesel generator lube oil mod. PARKER, M.C. Illinois, State of. DOE-85-156. 85/10/09. DENTON, H. Office of Nuclear Reactor Regulation, Director. 2pp. 32999:351-32999:352.
- 8510110158** Motion for leave to file instant re State of IL position concerning waiver of 10CFR51. Filing deadline missed due to inability of counsel to prepare position on time. RAPKIN, A. Illinois, State of. #485 725. ML. 85/10/07. Atomic Safety and Licensing Board Panel. 1p. 32972:184-32972:190.
- 8510110165** Position re waiver of 10CFR51 to permit hearing after supplemental DES issued. ASLB should wait completion of DuPage County trial & issuance of statement prior to decision whether to seek waiver. RAPKIN, A. Illinois, State of. ML. 85/10/07. Atomic Safety and Licensing Board Panel. 6pp. 32972:185-32972:190.
- 8510110174** Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental release of matts. Financial responsibility should reflect & specify differences for matt type & amount. Related comments encl. FORT, D. New Mexico, State of. 50FR23960 083. 85/10/02. Docketing & Services Branch. 3pp. 32972:191-32972:229.
- 8510110180** Motion for extension of time until 851023 for filing emergency planning appeal brief for 850417 decision & until 851106 for 850826 decision. Certificate of Svc encl. KELLEY, E.R. Suffolk County, NY. PALOMINO, F.G. New York, State of. #485 743. OL. 3. 85/10/08. Atomic Safety and Licensing Appeal Panel. 7pp. 32972:351-32972:357.
- 8510110255** Requests Plateau Resources Ltd application for renewal of License SUA-1371 for interim shutdown. WRIGHT, C. Utah, State of. 00940. 85/09/17. Office of the Executive Legal Director. 1pp. 32974:353-32974:353.
- 8510150271** Responds to 850829 ltr re testing of tailings cover matts. Plan describes limited sampling program that will only provide rough estimate of relative proportion of unsuitable matt in dump. Samples should be obtained from side slopes. MOXLEY, M. Wyoming, State of. 00901. 85/09/04. ANDRUS, N. American Nuclear Corp. 4pp. 33033:031-33033:034.
- 8510150286** Forwards "Cancer Mortality & Morbidity (Incidence) Around TMI" & "Assessment of Cancer Mortality Survey in Three TMI Areas..." in response to K Blouin 850709 ltr. Actions taken as result of Feb 1983 Salem ATWS events also discussed. DIRCKS, W.J. Office of the Executive Director for Operations. GL-83-28. 85/10/09. CRANSTON, A. Senate. 19pp. 33032:082-33032:211.
- 8510150291** "Cancer Mortality & Morbidity (Incidence) Around TMI." TOKUHATA, G.K. Pennsylvania, Commonwealth of. 85/09/30. 52pp. 33032:101-33032:153.
- 8510150295** "Assessment of Cancer Mortality Survey in Three TMI Areas Selected by Local Residents." Pennsylvania, Commonwealth of. 85/09/30. 22pp. 33032:154-33032:201.
- 8510160095** Comments on proposed rules 10CFR30.40, 61.70 & 72 re licensee financial responsibility for cleanup of accidental releases of matts. Financial responsibility should be developed based on listed items. LACKER, D.K. Texas, State of. 50FR23960 123. 85/10/02. Docketing & Services Branch. 2pp. 33027:361-33027:362.
- 8510160101** Offers no comment on proposed rules 10CFR30.41, 61.70 & 72. RICHARDSON, W.O. South Carolina, State of. 50FR23960 127. 85/10/07. CHILK, S.J. Docketing & Services Branch. 1p. 33022:307-33022:307.
- 8510170145** Advises that States of SC & NC local emergency plans & preparedness adequate to protect health & safety of public pending verification of alert & notification sys. SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 3pp. 33022:271-33022:273.
- 8510160309** Forwards surety contracts entered into by Atlas Corp & State of UT Board of Oil, Gas & Mining for 21 mines & for mill. Contracts still in effect as written. MAY, K. Utah, State of. 00925. 85/09/17. SMITH, R.D. Uranium Recovery Field Office. 17pp. 33028:261-33028:277.
- 8510170081** Requests that svc list for all related matts be revised to list JA Sanford as State of NC counsel of record. SANFORD, J.A. North Carolina, State of. 85/10/14. KNIGHTON, G.W. Licensing Branch 3. 1p. 33036:228-33036:228.
- 8510170201** Requests State of PA, Bureau of Solid Waste Mgt concur w/ listed disposal options so State of PA, Dept of Environ Resources can complete review of sewage treatment plant expansion & provide CP. FIELDS, J.S. Pennsylvania Power & Light Co. PLE-7667. 85/10/10. FRITZ, D. Pennsylvania, Commonwealth of. 2pp. 33051:357-33051:358.
- 8510170207** Submits summary of reasons for denial of application for permit to construct 85-315 Blue 6 reservoir. Proposed waste & wastewater disposal sys does not provide adequate protection of aquifer. GARLAND, W.L. Wyoming, State of. 00942. 85/09/10. Minerals Exploration Co. (subs. of Union Oil Co. of California). 5pp. 33043:058-33043:062.
- 8510170246** Provides summary of reasons for denial of Water Quality Div Permit 85-315. Proposed design does not adequately protect waters of state. GARLAND, W.L. Wyoming, State of. 00931. 85/09/10. Minerals Exploration Co. (subs. of Union Oil Co. of California). 5pp. 33045:127-33045:131.
- 8510170261** Summary of 850913 meeting w/ Cleveland Cliffs Iron Co & NRC in Denver, CO re present status of issues concerning in situ operation, reclamation & review of data pursuant to NRC & state sign-off on mine site. HOGG, S. Wyoming, State of. 00947. 85/09/16. SHAFFER, R. Wyoming, State of. 4pp. 33045:051-33045:054.
- 8510170272** Discusses data re stability of A & B fields, including overage water quality for B-wellfield. Further restoration & followup monitoring to ensure geochemical stability of wellfield recommended. HOGG, S. Wyoming, State of. 00946. 85/09/25. Wyoming, State of. 4pp. 33045:039-33045:042.
- 8510170336** Informs that revised monitoring plan for Collins Draw Site will be submitted for review. Number of wells monitored will be reduced & excursion indicators increased for some wells. HOGG, S. Wyoming, State of. 00948. 85/09/26. Wyoming, State of. 1p. 33043:358-33043:358.
- 8510170439** Forwards draft environ assessment supporting renewal of Plateau Resources, Ltd License SUA-1371, per request. W/o encl. JIERREE, C.C. Uranium Recovery Field Office. 85/09/27. WRIGHT, C. Utah, State of. 1p. 33047:184-33047:184.
- 8510170450** Advises that proposed monitoring plan, outlined in 850712 ltr, acceptable w/ listed exceptions. If monitoring indicates problems, expanded monitoring may again be required. SHAFFER, R. Wyoming, State of. 00684. 85/08/19. CATCHPOLE, G.J. Ogle Petroleum, Inc. of California. 1p. 33048:172-33048:173.
- 8510170474** Requests 851021 meeting to discuss reasons for requiring & denying Permit 85-315 & all areas of disagreement concerning revised tailings plans. KLEIN, T.J. Union 76 Minerals. 00956. 85/10/04. GARLAND, W.C. Wyoming, State of. 1p. 33047:223-33047:223.

332 NONDOCKETED ITEMS

- 8510180253** Forwards TS LaGuardia 850902 comments on proposed rules 10CFR30.40.50.51.70 & 72 re decommissioning criteria for nuclear facilities. Transcript re decommissioning referenced in TS LaGuardia ltr also forwarded. PRINS, H.R. New York, State of. 50FR5600 141. 85/10/11. CHILK, S.J. Docketing & Services Branch. 36pp. 33061:089-33061:126.
- 8510180283** Comments on proposed Rev 2 to Reg Guide 10.8, "Guide for Preparation of Applications for Medical Programs." Rev comprehensive & thorough. MOUNT, D.K. North Dakota, State of. 85/10/11. Docketing & Services Branch. 1p. 33061:005-33061:005.
- 8510180284** Responds to 850719 ltr re reduction of monitoring at Split Rock Mill. All concerns satisfactorily addressed w/exception of Well 14. Recommends that water quality degradation of Well 14 be investigated in more detail. GARLAND, W.L., SHAFFER, R. Wyoming, State of. 00853. 85/08/15. COLLINS, R. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 2pp. 33075:073-33075:074.
- 8510180289** Responds to Pelizza 850911 request re current restoration status of U Resources North Platte R&D project. Current restoration plan is satisfactory for pursuit of final restoration of North Platte site. SPEARS, R.G. Wyoming, State of. 00917. 85/09/13. Marsh & McLennan, Inc. 1p. 33068:358-33068:359.
- 8510180299** Summarizes 850930 telcon w/G Catchpole re confidentiality of Catchpole 850712 correspondence & 850919 meeting in Denver between Oge Petroleum, Inc. & Western Fuels. ENGELMANN, R. Wyoming, State of. 00959. 85/09/30. Wyoming, State of. 1p. 33068:357-33068:357.
- 8510180319** Comments on proposed rules 10CFR30.40.61.70 & 72 re amend requiring certain licensees to demonstrate adequate financial ability to pay for cleanup of accidental releases of radioactive waste. Financial support. BATTS, M.S. Florida, State of. 50FR23960 132. 85/10/09. Docketing & Services Branch. 1p. 33062:026-33062:026.
- 8510180332** Comments on proposed rules 10CFR30.40.61.70 & 72 re licensee financial responsibility for cleanup of accidental & unexpected releases of radioactive waste. Strict liability std for remedial action should be applied. BRUCHMANN, G.W. Michigan, State of. 50FR23960 129. 85/10/07. Docketing & Services Branch. 2pp. 33062:003-33062:004.
- 8510210258** Advises that radiological emergency response plan in support of fixed nuclear facilities approved W/o ltr to NRC indicating approval of state & local plans & preparedness. MORRIS, R.H. Federal Emergency Management Agency. 85/10/08. RILEY, R.W. South Carolina, State of. 1p. 33079:328-33079:328.
- 8510210263** Advises that emergency response plan approved, conditional upon verification of alert & notification sys. W/o ltr to NRC indicating approval of state & local plans & preparedness. MORRIS, R.H. Federal Emergency Management Agency. 85/10/08. MARTIN, J. North Carolina, State of. 1p. 33079:327-33079:327.
- 8510210288** Forwards updated corrective action plans in response to 850823 followup review of radiation control program. Proposed regulations to establish compatibility w/ 10CFR regulations & Groups 1 & 1.5 hearings complete. KIZER, K.W. California, State of. 85/10/02. MARTIN, J.B. Region 5, Office of Director. 17pp. 33095:044-33095:060.
- 8510220170** Ack receipt of encl FEMA 850917 ltr including revised schedule of corrective actions by State of IL for recommendations identified as result of 850611-12 exercise. Schedule reviewed & responses adequate. SHAFER, W.D. Region 3, Office of Director. 85/10/16. REED, C. Commonwealth Edison Co. 2pp. 33090:031-33090:036.
- 8510230014** Advises that State of LA & local plans & preparedness for facility adequate to protect health & safety of public. Approval conditional on verification of alerting & notification sys. per NUREG-0654/Rev 1 to FEMA REP-1, App 3. SPECK, S.W. Federal Emergency Management Agency. 85/10/08. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 33101:347-33101:347.
- 8510230125** Ack receipt of FEMA 850910 ltr including revised schedule of corrective actions submitted by State of IL for recommendations identified as result of 850423 exercise. FEMA & Region V determined responses adequate. SHAFER, W.D. Region 3, Office of Director. 85/10/17. REED, C. Commonwealth Edison Co. 7pp. 33101:046-33101:047.
- 8510230135** Forwards four State of CA documents supporting util SAFSTOR decommissioning environ plan. SHIFFER, J.D. Pacific Gas & Electric Co. HBL-85-047. 85/10/07. ZWOLINSKI, J.A. Operating Reactors Branch 5. 54pp. 33102:037-33102:090.
- 8510230207** Confirms 850829 discussion following review & evaluation of state radiation control program. Addl staffing required to reduce licensing & insp backlog. Description of indicators used in reporting results & addl comments encl. MURLEY, T.E. Region 1, Office of Director. 85/10/18. WILZACKA, Maryland, State of. 7pp. 33101:027-33101:033.
- 8510230219** Forwards sections of State of CT radiological emergency response plan re medical svcs & similar sections from local plans within 10 mile emergency planning zone. KRIMM, R.W. Federal Emergency Management Agency. 85/10/18. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 150pp. 33100:216-33101:026.
- 8510240517** Forwards State of SC certificate of compliance for Nuclear Packaging, Inc. for Model NUPAC FL-50/EA-50 Ferralium 225 high integrity container at Barnwell. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/04. Region 1, Office of Director. 6pp. 33182:274-33182:279.
- 8510240553** Requests commitment for interim guidance re const of repository for Lakeview cleanup project, per Tenth Circuit Court of Appeals decision against EPA ground-water stds applicable to U mill tailings cleanup projects. FRANK, L. Oregon, State of. 85/10/11. THOMAS, L. Environmental Protection Agency. 2pp. 33177:354-33177:355.
- 8510240554** Responds to 850920 ltr re NRC plans for state participation in NRC review of DOE documents. Addl 2 wks for interaction w/state & tribes on NRC milestones will allow significant state input. SPURGIN, P.D. Utah, State of. 1176. 85/09/30. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 1p. 33177:353-33177:353.
- 8510240563** Responds to Items 1, 4 & 5 raised in 850717 ltr re draft evaluation rept for NUPAC Container FL-50/EA-50. Licenses required to have data which demonstrates compliance w/10CFR61 waste classification requirements. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/02. STRONG, T.R. Washington, State of. 2pp. 33184:019-33184:020.
- 8510250326** Package of three comments supporting proposed rules 10CFR30.40.61.70 & 72 re financial responsibility requirements applicable to NRC licensees for cleanup of accidental & unexpected releases of radioactive waste. STEINER, E.J. Delaware, State of. 50FR23960. 85/10/21. Docketing & Services Branch. 6pp. 33172:198-33172:205.
- 8510250466** Forwards State of WA 851003 ltr commenting on advanced notice of proposed rules 10CFR30.40.61.70 & 72 re financial responsibility for cleanup of accidental releases of certain matl licensees. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 50FR23960 138. 85/10/15. SEEMAN, M.J. Policy & Program Control Branch (Post 831001). 1p. 33171:331-33171:333.
- 8510250471** Comments supporting proposed rules 10CFR30.40.61.70 & 72 re financial responsibility for cleanup of accidental releases of certain matl licensees. Superfund-like program, w/govt putting up money, suggested. STRONG, T.R. Washington, State of. 85/10/03. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 2pp. 33171:332-33171:333.
- 8510250556** Agenda for Nuclear Waste Board 851018 meeting in Lacey, WA to discuss status of low level compact process & public involvement rept. * Washington, State of. 1577. 85/10/18. Washington, State of. 35pp. 33225:023-33225:057.
- 8510280021** Forwards Cooperative Agreement DE-FC04-85AL20533 between DOE & State of NM re use of inactive U mill tailings site as processing site. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/03. HOYAL, J.G. Energy, Dept. of. 80pp. 33241:252-33241:331.
- 8510280067** Forwards, for concurrence, Cooperative Agreement DE-FC04-85AL20533 between State of NM & DOE re UMTRAP W/o encl. HOYAL, J.G. Energy, Dept. of. 85/09/13. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33241:124-33241:124.
- 8510280066** Requests Oct 1984 trip rept re geophysical data used to identify sub-Paradox Basin fault in immediate vicinity of proposed Davis Canyon repository site. WITTMAN, J. Utah, State of. 85/10/08. KNAPP, M.R. Geotechnical Branch (Post 831001). 1p. 33240:362-33240:362.
- 8510280110** Mod A009 to cooperative agreement between DOE & State of UT, increasing DOE obligation of funds for FY86. HOYAL, J.G. Energy, Dept. of. MAXELL, M.H. Utah, State of. 3866R. 85/10/17. 4pp. 33228:329-33228:332.
- 8510290055** Notifies that no adverse findings determined based on review of 851011 proposed Tech Spec amend re source range monitor operability. PARKER, M.C. Illinois, State of. DOE-85-183. 85/10/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33236:036-33236:135.
- 8510290061** Informs that State of IL Dept of Nuclear Safety reviewed proposed Tech Spec amend involving radiological effluent Tech Spec Section 1.0 re definitions. No adverse findings noted. PARKER, M.C. Illinois, State of. DOE-85-181. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33236:036-33236:036.
- 8510290188** Informs of review of application for amend to License NPF-11 re proposed changes to Tech Specs concerning vent & purge isolation valve mods. No adverse findings determined. PARKER, M.C. Illinois, State of. DOE-85-177. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33233:156-33233:156.
- 8510290200** Forwards NP Kimer 851003 ltr commenting on Chem-Nuclear Sys, Inc. topical rept "Fiberglass Reinforced Plastic High Integrity Containers." NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. GREEVES, J. Engineering Branch (Post 831001). HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254:222-33254:223.
- 8510290207** Comments on Chem-Nuclear Sys, Inc. CNSI-FRP-14571-01-NP, "Fiberglass Reinforced Plastic High Integrity Containers." Need for vents on packages questioned. Clarification as to whether passive vent sys will be required requested. KIRNER, N.P. Washington, State of. 85/10/03. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 1p. 33254:223-33254:223.
- 8510290231** Advises that Dept of Nuclear Safety completed review of proposed amend to Tech Specs re ECCS/RCIC testable check bypass valves. No adverse findings identified. PARKER, M.C. Illinois, State of. DOE-85-178. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33235:004-33235:004.
- 8510290279** Forwards NP Kimer 851003 ltr commenting on Chichibu Cement Co topical rept "High Integrity Container for Disposal of Low Level Radwastes." NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. GREEVES, J. Engineering Branch (Post 831001). HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254:238-33254:242.
- 8510290291** Comments on Chichibu Cement Co topical rept "High Integrity Container (HIC) for Disposal of Low Level Radwastes," per NRC 850506 request. Lack of test results addressing guidance on HIC provided in branch technical position questioned. KIRNER, N.P. Washington, State of. 85/10/03. NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 4pp. 33254:239-33254:242.

8510290296 State of GA, Radiological Emergency Plan, Annex G, U.S. TVA - Sequoyah Nuclear Plant. W/851024 ltr.
* Georgia, State of. DOMER, J.A. Tennessee Valley Authority. 85/09/18. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 56pp. 33235:159-33235:213.

8510290346 Determines that no adverse findings identified as result of review of amend to License NPF-37 to correct typo &/or grammatical changes.
PARKER, M.C. Illinois, State of. DOE-85-176. 85/10/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 33234:337-33234:337.

8510290348 Comments on proposed rules 10CFR30.40, 61.70 & 72 re financial responsibility for cleanup of accidental release of certain materials. Rule conditionally supported. Inclusion of users of gauging devices may be warranted.
RUTLEDGE, B.G. Georgia, State of. 50FR23960 140. 85/10/18. Docketing & Services Branch. 1p. 33234:336-33234:336.

8510290361 Offers no comments re proposed amendments to Tech Specs re offgas treatment monitors & administrative control for corporate nuclear safety review board.
ESCHELS, C. Washington, State of. 85/10/24. BUTLER, W.R. Licensing Branch 2. 1p. 33234:360-33234:360.

8510290383 Comments on proposed rules 10CFR30.31, 32.35 & 40 re medical use of byproduct materials. Licensees do not have expertise needed to make adequate safety review of changes proposal allows.
BLAZEK, M.L. Oregon, State of. 50FR30616 015. 85/10/22. Docketing & Services Branch. 2pp. 33236:359-33236:360.

8510290424 Forwards State of WA 851003 ltr to R Haelsig of Nuclear Packaging, Inc. extending interim approval of certain Envisalloy high integrity containers to 851231.
NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. HIGGINBOTHAM, L.L. Low-Level Waste & Uranium Recovery Projects Branch. GREEVES, J. Engineering Branch (Post 831001). 4pp. 33254:286-33254:289.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8510010155 Application for amendments to Licensees DPR-39 & DPR-48 re proposed changes to specimen capsule withdrawal schedule. Forwards WCAP-10902, "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
LEBLOND, P.C. Commonwealth Edison Co. 0590K. 85/09/13. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 32800:001-32800:063.

-8510010161 WCAP-10902 "Plant-Specific Neutron Fluence Evaluation for Zion Units 1 & 2."
ANDERSON, S.L. LAU, F.L. Westinghouse Electric Corp. 85/08/31. 55pp. 32800:010-32800:063.

8510010257 Informs that submittal of documentation re resolution of nonconservative item in large break LOCA evaluation model delayed until early Oct 1985.
SCHERER, A.E. Combustion Engineering, Inc. LD-85-041. 85/08/26. KNIGHTON, G.W. Licensing Branch 3. 2pp. 32800:240-32800:241.

8510010347 Forwards "Safety Balance Assessment for Elimination of RCS Main Loop Pipe Break Protective Devices," per 850201 request for exemption from 10CFR50, App. A, GDC 4. Meeting arranged in late Oct 1985 w/B&W to discuss NRC review.
SIMPSON, E.C. Florida Power Corp. (subs. of Florida Progress Corp.). 3F0965-26. 85/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 32803:001-32803:019.

-8510010352 51-1159048-00 "Safety Balance Assessment for Elimination of RCS Main Loop Pipe Break Protective Devices."
* Babcock & Wilcox Co. 85/09/12. 17pp. 32803:003-32803:019.

8510010440 Forwards Rev 3A to P-TOP-QA1, "Parsons QA Program for Nuclear Facilities," per 850826 acceptance ltr.
FRIAS, R. Ralph M. Parsons Co. 85/09/25. Record Services Branch (Document Control Desk). 1p. 32803:126-32803:126.

-8510010445 P-TOP-QA1 R03A Rev 3A to "Parsons QA Program for Nuclear Facilities."
* Ralph M. Parsons Co. 85/08/26. 130pp. 32803:127-32803:256.

8510010625 Summary of 850910-11 meetings w/NUTECH Engineers, Inc. in Silver Spring, MD re encl NUTECH responses to NRC 850529 & 0607 comments on inservice insp procedures & estimating thermal parameters. Attendance list encl.
ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 85/09/20. ROUSEL, C. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 32831:217-32831:217.

-8510010626 Forwards responses to NRC detailed comments on Topical Rept NUH-001 re horizontal modular storage sys for irradiated nuclear fuel.
MASSEY, J.V. NUTECH Engineers, Inc. JVM-85-143. 85/09/06. ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch. 200pp. 32831:219-32831:259.

8510020182 Forwards review of Section 4.7 of Technical Evaluation Rept PNL-5600, "Review of Resolution of Known Problems in Engine Components for TDI Emergency Diesel Generators," reflecting views re crankshafts for 16-cylinder engines.
LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/09/27. BERLINGER, C. Division of Licensing. 26pp. 32824:280-32824:305.

8510020275 Forwards FRA-QP/85 0782 NP, "Framatome QA Program (for US Applications)" & FRA-QP/85 1172, "Framatome: Resume of Resources & Scope of Activities, History & Experience & Organization" for acceptance for licensing actions.
VOIN, R. Framatome. Q/85-0288. 85/09/16. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 2pp. 32834:031-32834:088.

-8510020278 FRA-QP/85 0782 NP "Framatome QA Program (for US Applications)."
* Framatome. 85/09/16. 38pp. 32834:033-32834:070.

-8510020281 FRA-QP/85 1172 "Framatome: Resume of Resources & Scope of Activities, History & Experience & Organization."
* Framatome. 85/09/16. 18pp. 32834:071-32834:088.

8510020297 Forwards proprietary & nonproprietary version of slides presented at NRC/B&W 850215 meeting on licensing competitor reloads. Affidavit also encl. Proprietary info withheld (ref 10CFR2.790).
TAYLOR, J.H. Babcock & Wilcox Co. 85/05/29. SHERON, B. Reactor Systems Branch. 57pp. 32825:273-32825:329.

8510030072 Forwards proprietary XN-NF-85-105, "Scaling of Fuel Cooling Test Facility Based Reflood Heat Transfer Correlation for Other Bundle Designs." Affidavit also encl. Rept withheld (ref 10CFR2.790).
COPELAND, R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). RAC-076.85. 85/10/01. THOMAS, C.O. Standardization & Special Projects Branch. 5pp. 32841:151-32841:155.

8510030130 Forwards TR UR 85-225, "ASEA-Atom BWR Control Blades for US BWRs," for review & approval. Licensing of Quad Cities Unit 1 Reload 9 & Millstone Unit 1 reload dependent on approval of replot. Fee paid.
TENERZE, ASEA Atom, Inc. MB 057/85. 85/09/24. BERNARD, H. NRC - No Detailed Affiliation Given. 2pp. 32878:035-32878:075.

-8510030140 TR UR 85-225 "ASEA-Atom BWR Control Blades for US BWRs."
CHRISTIANSSON, HAMMARLUND, C.E. ASEA Atom, Inc. 85/10/01. 41pp. 32878:037-32878:075.

8510030171 Notification of 851009 meeting w/Framatome in Bethesda, MD to discuss topical replot on QA & results of NRC initial review of replot.
ANKRUM, G.T. Quality Assurance Branch. 85/10/01. GRIMES, B.K. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 3pp. 32849:295-32849:297.

8510040055 Notification of 851004 meeting w/B&W Owners Group in Bethesda, MD to discuss transient assessment committee & availability committee plans re proposed Tech Spec changes, raising reactor trip setpoints on high pressure.
VISSING, G.S. Operating Reactors Branch 4. 85/09/25. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 32860:244-32860:246.

8510040144 Forwards Diesel Engine 2A component revalidation insps & results per insp plan submitted on 850430. Defective weld heads replaced. Diesel Engine 2B insp in progress. Insp rept will not be submitted based on prior insps.
TUCKER, H.B. Duke Power Co. 85/10/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 32850:064-32850:187.

-8510040168 "Catawba Nuclear Station Diesel Engine 2A Component Revalidation Insp."
* Duke Power Co. 85/09/25. 122pp. 32850:066-32850:187.

8510040285 Forwards BAW-1882, "Analysis of Capsule TE1-A, Davis-Besse Nuclear Power Station, Unit 1, Reactor Vessel Matt Surveillance Program." Revised pressure-temp curves will be submitted prior to limit of 5 EFPPs.
WILLIAMS, J. Toledo Edison Co. 1189. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32852:287-32853:013.

-8510040289 "Analysis of Capsule TE1-A, Davis-Besse Nuclear Power Station, Unit 1, Reactor Vessel Matt Surveillance Program."
* Babcock & Wilcox Co. 85/09/30. 89pp. 32852:288-32853:013.

8510040323 Forwards GE affidavit attesting to confidentiality of info supplied to NRC by Instrument Setpoint Methodology Group in response to 850813 ltr. Listed documents should be withheld (ref 10CFR2.790).
CAROLAN, J.F. LRG Instrumentation Setpoint Methodology Group. 85/09/30. YOUNGBLOOD, B.J. Licensing Branch 1. 7pp. 32853:252-32853:258.

8510040374 Forwards WCAP-10925, "Steam Generator Girth Weld 6 Repair Rept."
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-428B. 85/09/27. THOMPSON, H.L. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch 1. 2pp. 32853:014-32853:104.

-8510040379 WCAP-10925 "Steam Generator Girth Weld 6 Repair Rept."
* Westinghouse Electric Corp. SG-85-08-045. 85/08/31. 90pp. 32853:016-32853:104.

8510040421 Discusses whether employees at WMD, rather than mgt, blameworthy for employee nonobservance of safety & health rules, per Ratner & Schiller vs GE 2:206 proceeding. Blame for noncompliance traceable to GE mgt.
RATNER, M.G. Ratner, M.G. 2:206. 85/08/21. COLLINS, J.T. Director's Office, Office of Inspection and Enforcement. 29pp. 32859:348-32860:014.

8510040423 Discusses consultation w/K Mossman re MG Ratner 850821 ltr to NRC concerning Ratner & Schiller vs GE 2:206 proceeding.
RATNER, M.G. Ratner, M.G. 2:206. 85/07/19. COLLINS, J.T. Director's Office, Office of Inspection and Enforcement. 12pp. 32859:336-32859:347.

8510070200 Forwards proprietary XN-NF-85-68(P), "DC Cook Unit 2 Limiting Break LOCA/ECCS Analysis, 10% Steam Generator Tube Plugging & K(Z) Curve." Affidavit encl. Rept withheld (ref 10CFR2.790).
COPELAND, R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). RAC-067.85. 85/10/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 5pp. 32878:228-32878:242.

8510070291 Endorses AIF rept, "Tech Spec Improvements." Short-term items identified can produce addl significant improvements in Tech Specs. Requests strong support of NRC efforts for generic improvements in Tech Specs.
WELLS, R.W. C-E Operating Plants Owners Group. WELLS, R.W. Northeast Utilities. RWW-85-68. 85/09/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 32875:359-32875:359.

8510080166 Forwards "Evaluation of Alternate Reactor Coolant Pump Trip Criteria." Rept presents criteria & setpoint methodology for reactor coolant pump trip in response to Section I of Generic Ltrs 83-10c & d.
SHEPPARD, J.J. Westinghouse Operating Plants Owners Group. SHEPPARD, J.J. Carolina Power & Light Co. OG-110. 83/12/01. MATTHEWSON, R.J. Division of Systems Integration (post 811005). 1p. 32922:327-32923:039.

-8510080178 "Evaluation of Alternate Reactor Coolant Pump Trip Criteria."
KEMPER, R.M. LEWIS, R.N. LOVE, D.S. Westinghouse Electric Corp. 83/09/30. 74pp. 32922:328-32923:039.

334 NONDOCKETED ITEMS

- 8510080247** Forwards XN-NF 85-98, "Kewaunee Limiting Break K(z) LOCA/ECCS Analysis." HINTZ,D.C. Wisconsin Public Service Corp. NRC-85-157. 85/10/03. VARGA,S.A. Operating Reactors Branch 1. 2pp. 32918:130-32918:187.
- 8510080252** XN-NF-85-98 "Kewaunee Limiting Break K(z) LOCA/ECCS Analysis." ADES,M.J., VALENTINE,P.J., HOLM,J.S. Exon Nuclear Co., Inc. (subs. of Exon Corp.). 85/09/30. 80pp. 32918:132-32918:187.
- 8510080292** Submits info re Exon Nuclear Co ECCS/LOCA analysis, per 850930 discussion w/NRC. Error found in TOODEE2 code re calculation of thermal response of hot fuel rod. Peak cladding temp underpredicted. Calculations revised. ALEXICH,M.P. Indiana & Michigan Electric Co. AEP-NRC-09400. 85/10/02. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 32919:109-32919:111.
- 8510080301** Notices of error in 10CFR50.46 LOCA analyses performed for facilities. Input error in TOODEE2 code used to calculate fuel rod heatup resulted in rod decay heat power too low & subsequent underpredicted peak cladding temp. MALODY,C. Exon Nuclear Co., Inc. (subs. of Exon Corp.). 85/09/30. MARTIN,J.B. Region 5, Office of Director. 11pp. 32919:112-32919:122.
- 8510080348** Notices of inability to meet 851101 commitment to provide TDI emergency diesel generator insp results & schedule due to manpower reductions. SHELL,R.H. Tennessee Valley Authority. 85/10/01. ADENSAM,E. Licensing Branch 4. 2pp. 32922:123-32922:124.
- 8510080514** Forwards Rev 0 to COM-83-042, "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." WOJNAROWSKI,J. Commonwealth Edison Co. 0696K. 85/09/30. THOMPSON,H.L. Division of Licensing. 2pp. 32920:134-32920:216.
- 8510080515** COM-83-042 R00 Rev 0 to "Evaluation of Containment Isolation Valves for Dresden Units 2 & 3 & Quad-Cities Units 1 & 2." ANDERSSON,O. NUTECH Engineers, Inc. COM083.0150. 85/09/23. 70pp. 32920:136-32920:216.
- 8510080561** Advises that final response to questions received in 840702 ltr (NRCS-84-59) re contents of Westinghouse Owners Group Ltrs OG-110 & OG-117 concerning reactor coolant pump trip expected by 840929. SHEPPARD,J.J. Westinghouse Operating Plants Owners Group. SHEPPARD,J.J. Carolina Power & Light Co. OG-131. 84/08/14. MILLER,J.R. Operating Reactors Branch 3. 1p. 32925:212-32925:212.
- 8510090029** Forwards response to NRC 850723 request for addl info re TDI emergency diesel generators, including info concerning TDI 10CFR21 repts, svc info memos, preventive maint program & training & trending program. DALE,L.F. Mississippi Power & Light Co. AECM-85/0301. 85/10/01. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 400pp. 32935:342-32936:212.
- 8510090045** Forwards Rev 2 to nonproprietary & proprietary ATC-8019-1-P-A, "ATCOR AVRS-80 Vol Reduction Process." Proprietary version withheld. RIES,P.A. ATCOR Engineered Systems, Inc. 85-10-04-E-02. 85/10/04. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32942:039-32942:135.
- 8510090061** ATC-8019-1-P-A R02 Nonproprietary Rev 2 to "ATCOR AVRS-80 Vol Reduction Process." * ATCOR Engineered Systems, Inc. 85/09/30. 97pp. 32942:041-32942:135.
- 8510090082** Confirms 851022 meeting w/NRC in Bethesda, MD to discuss NEDE-30996-P, "SAFER Model for Evaluation of LOCAs for Jet Pump & Non-Jet Pump Plants." Mutt presented at meeting should be withheld from public disclosure. PFEFFERLEN,H.C. General Electric Co. MFN-120-85. 85/10/04. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32934:343-32934:344.
- 8510090141** Forwards nonproprietary & proprietary WCAP-10444-NP-A & WCAP-10444-D-P, respectively, "Ref Core Rept Vantage 5 Fuel Assembly," per NUREG-0390. Affidavit encl. Proprietary rept withheld (ref 10CFR2.790). RAHE,E.P. Westinghouse Electric Corp. NS-NRC-85-3068. 85/09/27. THOMAS,C.O. Standardization & Special Projects Branch. 2pp. 32936:215-32936:228.
- 8510090147** Requests that proprietary WCAP-10444-P-A, "Ref Core Rept Vantage 5 Fuel Assembly," be withheld (ref 10CFR2.790). WISEMANN,R.A. Westinghouse Electric Corp. AW-85-065. 85/09/26. THOMAS,C.O. Standardization & Special Projects Branch. 14pp. 32936:215-32936:228.
- 8510090150** WCAP-10445-NP-A "Ref Core Rept Vantage 5 Fuel Assembly." ARLOTTI,M.G., ORR,W.L., BEVARD,D.G. Westinghouse Electric Corp. 85/09/30. 300pp. 32936:229-32937:358.
- 8510090209** Provides addl info re NUREG-0737, Item II.D.1, "Performance Testing of Relief & Safety Valves," in response to NRC 850214 request. MUSOLF,D. Northern States Power Co. 85/09/26. Office of Nuclear Reactor Regulation, Director. 12pp. 32942:140-32942:335.
- 8510090216** "Pressurizer Safety & Relief Line Evaluation Summary Rept - Prairie Island Nuclear Generating Station, Unit 1." VALASEK,L.M., ANTAKI,G.A. Westinghouse Electric Corp. 84/02/29. 78pp. 32942:153-32942:230.
- 8510090221** "Pressurizer Safety & Relief Line Evaluation Summary Rept - Prairie Island Nuclear Generating Station, Unit 2." VALASEK,L.M., ANTAKI,G.A. Westinghouse Electric Corp. 84/02/29. 78pp. 32942:231-32942:308.
- 8510090250** Forwards response to NRC 850924 questions/comments on CNSI-WF-C-01-NP, "10CFR61 Waste Form Certification - Cement." Justification for sea water leach tests on boric acid & bead resin listed. Further testing unnecessary. POPPEL,L.K., STAEHR,J.P. Chem-Nuclear Systems, Inc. 85/09/26. PERSON,L.S. NRC - No Detailed Affiliation Given. 32pp. 32950:046-32950:077.
- 8510090320** Forwards response to NRC questions, received in NRCS-84-59, re owners group program to address Generic Ltr 83-10 concerning reactor coolant pump trip. SHEPPARD,J.J. Westinghouse Operating Plants Owners Group. SHEPPARD,J.J. Carolina Power & Light Co. GL-83-10. 84/10/25. JAFFE,D. NRC - No Detailed Affiliation Given. 119pp. 32950:237-32950:356.
- 8510090409** Forwards nonproprietary Rev 1 to "Topical Rept SG-95 Solidified Boric Acid to Meet Stability Requirements of 10CFR61." Rev necessary to incorporate results of 90-day immersion biodegradation & leachability tests. BORIS,G.F. Westinghouse Hittman Nuclear, Inc. WHNI-E-326. 85/09/24. PERSON,L.S. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 32964:315-32964:323.
- 8510090414** STR-R-05-008 R01 Rev 1 to "Topical Rept SG-95 Solidified Boric Acid to Meet Stability Requirements of 10CFR61." * Westinghouse Hittman Nuclear, Inc. ECN 85-129. 85/09/24. 8pp. 32964:316-32964:323.
- 8510100003** Forwards portions of NEDC-30851-P, consisting of responses to Questions 10, 26, 29 & 31, per NRC & EG&G 850717 request re BWR Owners Group Tech Spec improvement program. Encl withheld. RASH,L. General Electric Co. OG5-371-12. 85/09/19. COLLINS,T. NRC - No Detailed Affiliation Given. 4pp. 32960:075-32960:078.
- 8510100013** Forwards Amend 14 to NEDE-24-111-P-A, "GE Std Application for Reactor Fuel," for review. Amend incorporates fuel cladding integrity safety limit. Affidavit for withholding encl. Rept withheld (ref 10CFR2.790). Fee paid. CHARNEY,L.S. General Electric Co. MFN-118-85. 85/10/02. THOMAS,C.O. Standardization & Special Projects Branch. 5pp. 32960:070-32960:074.
- 8510100036** Forwards Rev 38 to CE-1-A, "QA Program for Nuclear Generating Stations." Rev made to reflect corporate title changes. ALEXANDER,G.L. Commonwealth Edison Co. 9521Q. 85/10/03. KEPPLER,J.G. Region 3, Office of Director. 1p. 32973:333-32974:006.
- 8510100058** Rev 38 to "QA Program for Nuclear Generating Stations." * Commonwealth Edison Co. 85/10/03. 35pp. 32973:334-32974:006.
- 8510101021** Forwards Rev 13 to "Exxon Nuclear Co. Richland Fuel Fabrication Plant, Emergency & Radiological Contingency Plan, Part I," reflecting Exxon Nuclear Co current organization & names of other agency emergency plans. MALODY,C.W. Exxon Nuclear Co., Inc. (subs. of Exon Corp.). 25704. 85/08/27. Uranium Fuel Licensing Branch. 2pp. 33012:235-33012:356.
- 8510101027** XN-NF-32A R13 Rev 13 to "Exxon Nuclear Co. Richland Fuel Fabrication Plant, Emergency & Radiological Contingency Plan, Part I." PURCELL,R.H. Exxon Nuclear Co., Inc. (subs. of Exon Corp.). 25704. 85/08/31. 116pp. 33012:237-33012:356.
- 85101010210** Application for amend to License NPF-8, changing Tech Spec Table 4.4-5 re reactor vessel matl surveillance program with withdrawal schedule. Figures 3.4-2 & 3.4-3 re RCS heatup & cooldown curves & Bases 3/4.4.10. Fee paid. MACDONALD,R.P. Alabama Power Co. 85/09/30. VARGA,S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 32974:041-32974:111.
- 85101010245** Proposed Tech Specs, changing Table 4.4-5 re reactor vessel matl surveillance program with withdrawal schedule. Figures 3.4-2 & 3.4-3 re RCS heatup & cooldown curves & Bases 3/4.4.10. * Alabama Power Co. 85/09/30. 44pp. 32974:043-32974:086.
- 85101010246** WCAP-10910, "Heatup & Cooldown Limit Curves for Alabama Power Co. JM Farley Unit 2 Reactor Vessel." KAISER,W.T., CONGEDO,T.V., YANICHKO,S.E. Westinghouse Electric Corp. 85/08/31. 25pp. 32974:087-32974:111.
- 8510150021** Notification of 851011 meeting w/Exxon Nuclear Co., Inc. in Bethesda, MD to discuss recent Exxon activities toward resolving safety analysis issues. BLACK,S. Division of Licensing. 85/10/02. THOMPSON,H.L. Division of Licensing. 16pp. 33031:135-33031:150.
- 8510150337** Forwards, for review, proprietary "Preliminary Matl. Sections 5 & 7, NEDE-30996-P" on detail core heat transfer model for use in LOCA evaluation methodology for nonjet pump BWR plants. Encl withheld (ref 10CFR2.790). PFEFFERLEN,H.C. General Electric Co. MFN-122-85. 85/10/08. THOMAS,C.O. Standardization & Special Projects Branch. 7pp. 33009:314-33009:320.
- 8510160001** Discusses difficulty in implementing Action Statement 7 as applied from Item 15 re silicon controlled rectifiers. New Action Statement 11 proposed, per Generic Ltr 85-10 re Tech Specs for reactor trip breakers. ENOS,J.T. Babcock & Wilcox Operating Plants Owners Group. 1CAN108507. 85/10/09. THOMPSON,H.L. Division of Licensing. 3pp. 33026:324-33026:326.
- 8510160137** Forwards B&W Rept 47-11590s-1-00, "Design Requirements for DSS (Diverse Scram Sys) & AMSAC (ATWS Mitigation Sys Actuation Circuitry)," providing generic basis for ATWS mods required of 177 & 205FA plants by 10CFR50.62. ENOS,J.T. Babcock & Wilcox Operating Plants Owners Group. 1CAN108506. 85/10/09. THOMPSON,H.L. Division of Licensing. 1p. 33022:276-33022:304.
- 8510160140** 47-1159091-00 "Design Requirements for DSS (Diverse Scram Sys) & AMSAC (ATWS Mitigation Sys Actuation Circuitry)." * Babcock & Wilcox Co. 85/09/30. 28pp. 33022:277-33022:304.
- 8510160266** Forwards proprietary addl info on WCAP 10026 re BASH code. YOUNG,M.Y. Westinghouse Electric Corp. SED-THA-833. 85/10/11. MORAN,D.H. NRC - No Detailed Affiliation Given. 1p. 33022:253-33022:253.
- 8510160314** Forwards "Use of Steady-State Critical Heat Flux Correlations for Transient Analysis in PWRs" & responses to Questions 1-8, per 850917 request for addl info on EPRI NP-2511-CCM, Vols 1-4. BLAISDELL,J.A. Electric Power Research Institute. BLAISDELL,J.A. Northeast Utilities. NE-85-SAB-285. 85/10/10. DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 33025:006-33026:217.
- 8510160315** "Use of Steady-State Critical Heat Flux Correlations for Transient Analysis in PWRs." BLAISDELL,J., ABRAHAM,P.M. Electric Power Research Institute. BLAISDELL,J.A. Northeast Utilities Service Co. (subs. of Northeast Utilities). 85/10/07. 250pp. 33025:013-33026:217.

8510170074 Forwards VEP-NE-2. "Statistical DNBR Evaluation Methodology." Rept describes methodology for statistically treating several important uncertainties in DNBR analysis & replaces deterministic methodology. Fee paid.
STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 85-688. 85/10/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33036:252-33036:320.

-8510170079 VEP-NE-2 "Statistical DNBR Evaluation Methodology."
ANDERSON, R.C. Virginia Power (Virginia Electric & Power Co.). 85/07/31. 67pp. 33036:254-33036:320.

8510170223 Forwards proprietary Amend 13 to Rev 6 to NEDE-24011-P-A, "GE Std Application for Reactor Fuel." Amend completes documentation commitments per NUREG-0390. Amend withheld (ref 10CFR2.790).
CHARNEY, J.S. General Electric Co. MFN-119-85. 85/10/03. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 33039:195-33039:195.

8510170289 Forwards XN-NF-85-28, "DC Cook Unit 2, Cycle 6 SAR" & proprietary Suppl 1 to XN-NF-85-28(P), "DC Cook Unit 2, Cycle 6 SAR Disposition of SRP...." Proprietary suppl withheld (ref 10CFR2.790(b)).
COPELAND, R.A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). RAC-069-85. 85/10/15. DENTON, H.F. Office of Nuclear Reactor Regulation, Director. 5pp. 33039:156-33039:194.

-8510170292 XN-NF-85-28 Nonproprietary XN-NF-85-28, "DC Cook Unit 2, Cycle 6 SAR."
WIMPY, P.D., ADAMS, F.T., SKOGEN, F.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/07/31. 34pp. 33039:161-33039:194.

8510170314 Forwards topical rept evaluation of WCAP-10107(P), "CONDOR, Thermal-Hydraulic Code for BWRs." Rept acceptable for referencing in license applications.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/11. RAHE, E.P. Westinghouse Electric Corp. 3pp. 33044:284-33044:294.

-8510170320 Topical rept evaluation of WCAP-10107(P), "CONDOR, Thermal-Hydraulic Code for BWRs." Rept acceptable for referencing in licensing actions.
* Core Performance Branch. TAC 48567. 85/10/11. 8pp. 33044:287-33044:294.

8510170325 Forwards topical rept evaluation of Amend 12 to Rev 6 to NEDE-24011-P-A, "GE Std Application for Reactor Fuel." Rept acceptable for referencing in license applications.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/11. CHARNLEY, J.S. General Electric Co. 9pp. 33044:001-33044:009.

-8510170328 Topical rept evaluation of Amend 12 to Rev 6 to NEDE-24011-P-A, "GE Std Application for Reactor Fuel." Rept acceptable for referencing in license applications.
* NRC - No Detailed Affiliation Given. TAC 57908. 85/10/11. 6pp. 33044:004-33044:009.

8510170385 Summary of 851009 meeting w/BWR Owners Group on IGSCC Research/Hydrogen Installation Subcommittee in Bethesda, MD re design, const & operational guidelines for permanent hydrogen injection sys. Attendance list encl.
WITT, F.J. Chemical Engineering Branch. 85/10/11. BENAROYA, V. Chemical Engineering Branch. 3pp. 33048:018-33048:020.

8510180095 Forwards topical rept evaluation of WCAP-10125(P), "Extended Burnup Evaluation of Westinghouse Fuel." Rept acceptable for referencing in license applications.
THOMAS, C.O. Standardization & Special Projects Branch. 85/10/11. RAHE, E.P. Westinghouse Electric Corp. 2pp. 33069:302-33069:303.

-8509180210 Topical rept evaluation of WCAP-10125, "Extended Burnup Evaluation of Westinghouse Fuel." Rept acceptable for licensing Zircaloy-clad fuel designs up to requested extended burnup level.
* Core Performance Branch. * Accident Evaluation Branch. 85/05/31. 34pp. 33069:304-33069:338.

8510180132 Forwards proprietary & nonproprietary WCAP-10885, "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture... Using LOFTTR1," per 830830 request. Proprietary rept withheld.
KOBERT, R.W. Rochester Gas & Electric Corp. 85/10/09. ZWOLINSKI, J.A. Operating Reactors Branch 5. 1p. 33056:131-33056:205.

-8510180137 Requests withholding of proprietary "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture at RE Ginna Nuclear Power Plant Using LOFTTR1." Affidavit & operator action times encl.
WIESEMAN, R.A. Westinghouse Electric Corp. CAW-85-052. 85/08/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 14pp. 33056:132-33056:145.

-8510180142 WCAP-10885 "Analysis of Potential Radiological Consequences Following Steam Generator Tube Rupture at RE Ginna Nuclear Power Plant Using LOFTTR1."
BRENNAN, J., RUBIN, K. Westinghouse Electric Corp. 85/07/31. 62pp. 33056:146-33056:205.

8510180221 Notification of 851022 meeting w/GE in Bethesda, MD to discuss NEDE-30996-P.
BERNARD, H. Standardization & Special Projects Branch. 85/10/11. THOMAS, C.O. Standardization & Special Projects Branch. 3pp. 33069:227-33069:229.

8510180300 Forwards proprietary response to Request 2 for addl info re review of BAW-10156 concerning applicability of steady state critical heat flux correlations in LYNTX to transient analysis. Response withheld (ref 10CFR2.790).
TAYLOR, J.H. Babcock & Wilcox Co. 85/10/14. THOMAS, C.O. Standardization & Special Projects Branch. 8pp. 33057:003-33057:010.

8510210131 Forwards update of results of full evaluation of design review/quality revalidation recommendations re maint & surveillance activities associated w/TDI diesel generators & provides clarification concerning several rept components.
COUNSEL, W.G. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). TX-4556. 85/10/14. NOONAN, V.S. Comanche Peak Project (Technical Review Team). 9pp. 33072:231-33072:239.

8510210143 Forwards Rev 8 to XN-NF-1A, "QA Program for Nuclear Fuel Design & Fabrication," for review & acceptance. Changes reflect updating of organizational titles, clarification & improvements in QA program.
VOLMER, C.J. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/10/15. ZECH, G. Division of QA, Vendor & Technical Training Center Programs (Post 850212). 1p. 33071:263-33071:348.

-8510210145 XN-NF-1A R08 Rev 8 to "QA Program for Nuclear Fuel Design & Fabrication."
MCCULLUGH, R.W., VOLMER, C.J., PERRY, D. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/10/14. 84pp. 33071:284-33071:348.

8510220022 Forwards five sets of Rev 1 to "Emergency Response Guidelines: Low Pressure Version" & "Emergency Response Guidelines: High Pressure Version" & background & executive vols of rev per 840620 request.
BUTTERFIELD, L. Westinghouse Operating Plants Owners Group. BUTTERFIELD, L. Commonwealth Edison Co. OG-143. 85/03/12. THOMPSON, H.L. Division of Licensing. 3pp. 33200:001-33200:003.

-8510220029 Second submittal of five sets of Rev 1 to "Emergency Response Guidelines: Low Pressure Version" & Rev 1 to "Emergency Response Guidelines: High Pressure Version," executive vols & background vols.
* Westinghouse Electric Corp. 83/09/01. 7,600pp. 33200:004-33222:268.

8510220183 Forwards most significant comments from first-cut comments contained in Westinghouse Owners Group 851001 ltr re Rev 5 to NUREG-0452, "STS for Westinghouse PWRs." Requests meeting w/NRC to discuss incorporation of Tech Spec improvements.
BUTTERFIELD, L. Westinghouse Operating Plants Owners Group. BUTTERFIELD, L. Commonwealth Edison Co. OG-161. 85/10/17. THOMPSON, H. NRC - No Detailed Affiliation Given. 15pp. 33090:037-33090:051.

8510220213 Forwards proprietary & nonproprietary CEN-310-NP, "CPC & Methodology Changes for CPC Improvement Program," for review. Affidavit requesting proprietary version be withheld (ref 10CFR2.790) also encl. Fee paid.
SCHERER, A.E. Combustion Engineering, Inc. LD-85-049. 85/10/18. KNIGHTON, G. Licensing Branch 3. 7pp. 33089:267-33089:306.

-8510220216 CEN-310-NP Nonproprietary "CPC & Methodology Changes for CPC Improvement Program."
* Combustion Engineering, Inc. 85/10/31. 33pp. 33089:274-33089:306.

8510230001 Forwards proprietary Rev 1 to Suppl 3 to XN-NF-82-06(P), "Qualification of Exxon Nuclear Fuel for Extended Burnup." Rept contains addl info re analyzing end-of-life internal rod pressure. Rept withheld (ref 10CFR2.790(b)).
WARD, G.N. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). GNW-089-85. 85/10/21. THOMAS, C.O. Standardization & Special Projects Branch. 1p. 33106:326-33106:326.

8510230028 Provides plans for returning unit to power w/recirculation inlet safe-end crack indications & forwards proprietary NEDC-31086-P, "Evaluation of Crevice Cracking in Peach Bottom... Recirculation Inlet Safe-Ends." Rept withheld.
DALTROFF, S.L. Philadelphia Electric Co. GL-84-11. 85/10/11. STOLZ, J.F. Operating Reactors Branch 4. 7pp. 33103:295-33103:301.

8510230141 Application for amend to License NPF-12, revising Tech Spec 3/4.4.5, "Steam Generators." Forwards proprietary WCAP 10949, nonproprietary WCAP 1050 & no significant hazards determination. Proprietary encl withheld (ref 10CFR2.790).
DIXON, O.W. South Carolina Electric & Gas Co. 85/10/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33103:302-33103:349.

-8510230155 Requests withholding proprietary rept re tubesheet region plugging criterion for full depth hardroll expanded tubes, from public disclosure (ref 10CFR2.790).
WIESEMAN, R.A. Westinghouse Electric Corp. CAW-85-069. 85/10/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 10pp. 33103:307-33103:316.

-8510230162 WCAP 10950 Nonproprietary WCAP 10950, "Tubesheet Region Plugging Criterion for Full Depth Hardroll Expanded Tubes."
* Westinghouse Electric Corp. 85/09/30. 33pp. 33103:317-33103:349.

8510230243 Forwards proprietary Rev 7 to NEDE-24011-P-A, "GE Std Application for Reactor Fuel" & Rev 7 to NEDE-24011-P-A-US, "GE Std Application for Reactor Fuel (Suppl for US)." Repts withheld.
CHARNLEY, J.S. General Electric Co. MFN-126-85. 85/10/15. THOMAS, C.O. Standardization & Special Projects Branch. 2pp. 33103:024-33103:025.

8510240198 Requests review of encl proprietary supplemental info re Amend 11 to NEDE-24011-P-A by Jan 1986. Encl describes procedure for using GEMINI methods to derive Tech Spec MOPR limits. Affidavit for withholding (ref 10CFR2.790) encl.
CHARNLEY, J.S. General Electric Co. MFN-124-85. 85/10/09. THOMAS, C.O. Standardization & Special Projects Branch. 5pp. 33155:170-33155:174.

8510240405 Appellate brief supporting appeal of ASLB decisions identified in 850919 notice of appeal re issues 8, 16 & 6 on hydrogen control, TDI diesel generators & ATWS/standby liquid control sys, respectively. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy. #485 881. OL 85/10/21. Atomic Safety and Licensing Appeal Panel. 69pp. 33154:053-33154:121.

8510240588 Grants request to withhold CAW-85-057, "Improved Thermal Design Procedures," per 850830 application, 761202 affidavit & 850905 ltr providing responses to questions on procedures per 10CFR2.790.
NOONAN, V.S. Comanche Peak Project (Technical Review Team). 85/10/17. WIESEMAN, R.A. Westinghouse Electric Corp. 4pp. 33185:215-33185:218.

8510250580 Grants 850709 request for schedular partial exemption from GDC 4 of 10CFR50, App A re need to analyze large primary loop pipe ruptures as structural design basis for facility. Exemption & related documents encl.
KNIGHTON, G.W. Licensing Branch 3. 85/10/11. CAREY, J.J. Duquesne Light Co. 5pp. 33226:316-33226:320.

-8510250589 Topical rept evaluation of WCAP 10456, "Effects of Thermal Aging on Structural Integrity of Cast Stainless Steel Piping for Westinghouse NSSS."
* NRC - No Detailed Affiliation Given. 85/10/11. 10pp. 33226:334-33226:343.

336 NONDOCKETED ITEMS

- 8510290054** Forwards TDI Owners Group info re emergency diesel generators, including history, const status & "TDI Diesel Generator Design Review & Quality Revalidation Rept." Generators capable of meeting FSAR requirements. Fee paid. SORESEN, G.C. Westinghouse Public Power Supply System. GOI-85-0198. 85/10/22. ADENSAM, E.G. Licensing Branch 4. 75pp. 33237-001-33239-056.
- 8510290116** Rev 1 to "TDI Diesel Generator Design Review & Quality Revalidation Rept." DEESE, R.J., RAY, C.L. TDI (Transamerica Delaval, Inc.) Owners Group. 85/02/28. 1,100pp. 33237-077-33239-056.
- 8510290073** Discusses 851105 meeting w/NRC to discuss actions planned re 850609 facility transient. Topics will include description of timetable, illustration of types of actions planned & special task force action. TUCKER, H.B. Babcock & Wilcox Operating Plants Owners Group. 85/10/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. TAYLOR, J.M. Director's Office, Office of Inspection and Enforcement. 2pp. 33236-114-33236-115.
- 8510290369** Forwards proprietary & nonproprietary WCAP-8822-P-21 & WCAP-8860-S2, "Mass & Energy Releases Following Steamline Rupture..." Application for withholding proprietary info also encl. Proprietary rept withheld (ref 10CFR2.790). RAHE, E.P. Westinghouse Electric Corp. NS-NRC-85-3071. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 33239-279-33239-346.
- 8510290412** Submits application for withholding proprietary info in WCAP-8822-P-S2, "Mass & Energy Releases Following Steamline Rupture..." from public disclosure, per 10CFR2.790. A draft for withholding encl. WIESEMAN, R.A. Westinghouse Electric Corp. AW-85-067. 85/10/07. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 9pp. 33239-281-33239-289.
- 8510290413** WCAP-8860-S2 "Mass & Energy Releases Following Steamline Rupture, Suppl 2 - Impact of Steam Superheat in Mass/Energy Releases Following Steamline Rupture for Dry & Subatmospheric Containment Designs." BUTLER, J.C., LINN, P.A. Westinghouse Electric Corp. 85/09/30. 57pp. 33239-290-33239-346.
- 8510290420** Notification of 851106 proprietary meeting w/GE in Bethesda, MD to discuss info on new fuel product line & revs to GETAB/GEXL safety analysis methods. Agenda encl. PHILLIPS, L.E. Core Performance Branch. 85/10/22. BERNERO, R.M. Division of Systems Integration (post 811005). 3pp. 33254-274-33254-276.
- 8510300306** Forwards PNL-5336, "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Shoreham Nuclear Power Station Unit 1," technical evaluation rept. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/10/17. BERLINGER, C. Division of Licensing. 1p. 33262-001-33262-128.
- 8510300314** PNL-5336 "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Shoreham Nuclear Power Station Unit 1," technical evaluation rept. LAITY, W.W., RICHMOND, W.D. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2963. 85/10/31. BERLINGER, C.H. Division of Licensing. 125pp. 33262-002-33262-128.
- 8510310328** Forwards proprietary & nonproprietary BAW-10145-P-A & BAW-10145-A, respectively, "Statistical Core Design Applied to Babcock-205 Core," including SER, NRC questions & B&W responses. Proprietary rept withheld (ref 10CFR2.790). TAYLOR, J.H. Babcock & Wilcox Co. 85/09/24. THOMAS, C.C. Standardization & Special Projects Branch. 1p. 33270-186-33271-013.
- 8510310411** BAW-10145-A Nonproprietary "Statistical Core Design Applied to Babcock-205 Core." * Babcock & Wilcox Co. 85/09/30. 200pp. 33270-187-33271-013.
- 8510310568** Forwards PNL-5444, "Review of Design & Quality Revalidation Rept for TDI Diesel Generators at Comanche Peak Steam Electric Station Unit 1," technical evaluation rept. LAITY, W.W. Battelle Memorial Institute, Pacific Northwest Laboratories. 85/10/17. BERLINGER, C. Division of Licensing. 1p. 33276-241-33277-001.
- 8510310574** PNL-5444 "Review of Design Review & Quality Revalidation Rept for TDI Diesel Generators at Comanche Peak Steam Electric Station," technical evaluation rept. LAITY, W.W., RICHMOND, W.D. Battelle Memorial Institute, Pacific Northwest Laboratories. FIN B-2963. 85/10/31. BERLINGER, C.H. Division of Licensing. 145pp. 33276-242-33277-036.
- WASTE MGT NUCLEAR WASTE MANAGEMENT**
- 8504090424** Ack receipt of 850214 ltr proposing that NRC/Nevada Nuclear Waste Site Investigations mgt meeting be held on 850311 in Washington, DC. Proposal acceptable. COPLAN, S.M. Repository Projects Branch (Post 831001). 599. 85/02/27. VIETH, D.L. Energy, Dept. of. 1p. 29748-001-29748-001.
- 8510010001** Notifies of 850905-08 data review meetings w/State of TX Bureau of Economic Geology to discuss stratigraphic info in Palo Duro Basin for geology, geochemistry & hydrology. TRAPP, J. Geotechnical Branch (Post 831001). 1156. 85/07/16. KNAPP, M. Geotechnical Branch (Post 831001). GREEVES, J., MILLER, H. NRC - No Detailed Affiliation Given. 17pp. 32833-259-32833-275.
- 8510010009** Discusses meetings w/states/tribes on NRC milestones in DOE project decision schedule. States & Indian tribes indicated comments re interactions w/NRC on major milestones would be sent. RUSSELL, C.F. Policy & Program Control Branch (Post 831001). 85/08/15. Policy & Program Control Branch (Post 831001). 4pp. 32833-200-32833-242.
- 8510010011** Discusses 10CFR80 NRC/DOE policy & procedure for meetings w/ state & tribal participation. Lead responsibility for establishing meetings between NRC & DOE is chief of Repository Projects Branch. BROWNING, R.E. Division of Waste Management. 85/07/02. Division of Waste Management. 1p. 32833-242-32833-242.
- 8510010113** Ack receipt of summary of issues & comments re redox properties of basalt-groundwater sys at Hanford site. Comments on validity of redox requested. KNAPP, M.R. Geotechnical Branch (Post 831001). 1537. 85/08/12. JIM, R. Yakima Indian Nation. 2pp. 32833-313-32833-314.
- 8510010136** Forwards revised summary of 850819 meeting in Carson City, NV to clarify comments on draft environ assessment for Yucca Mountain site. LOUX, R.R. Nevada, State of. 761. 85/08/21. BENSON, A. Energy, Dept. of. 17pp. 32833-292-32833-306.
- 8510020036** Summarizes 850805-08 meetings in Austin, TX re Permian Basin core exam. Repository in San Andres formation in very impure salt probable. In situ full-scale testing will provide reasonable assurance re performance at site. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2409. 85/08/12. PEARRING, J.R. Engineering Branch (Post 831001). 2pp. 32829-304-32829-305.
- 8510020041** Submits draft review of exploratory shaft performance analysis study. Performance of review by team, including geologist, hydrologist, canister corrosion engineer &/or radionuclide release & travel specialist suggested. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2367. 85/08/13. GUPTA, D. Engineering Branch (Post 831001). 12pp. 32829-286-32829-297.
- 8510040467** Comments on Nevada Nuclear Waste Storage Investigations exploratory shaft conceptual design rept. Claim made in cover ltr re const of exploratory shafts not impacting radiological health & safety of public unacceptable. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2367. 85/08/29. GUPTA, D. Engineering Branch (Post 831001). 8pp. 32859-306-32859-314.
- 8510040597** Forwards "Radiologic & Engineering Assessment for GJ-00771-MR," "...GJ-12419-MR," "...GJ-39829-RS," "...GJ-11739-MR," "...GJ-11484-RS" & "...GJ-34151-RS." TUCKER, M.K. Energy, Dept. of. 85/09/12. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 32861-299-32862-197.
- 8510040602** "Radiologic & Engineering Assessment for GJ-00771-MR." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 38pp. 32861-300-32861-337.
- 8510040607** "Radiologic & Engineering Assessment for GJ-12419-MR." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 60pp. 32861-338-32862-035.
- 8510040615** "Radiologic & Engineering Assessment for GJ-39829-RS." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 34pp. 32862-036-32862-069.
- 8510040617** "Radiologic & Engineering Assessment for GJ-11739-MR." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 49pp. 32862-070-32862-118.
- 8510040619** "Radiologic & Engineering Assessment for GJ-11484-RS." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 49pp. 32862-112-32862-187.
- 8510040620** "Radiologic & Engineering Assessment for GJ-34151-RS." * Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/11. 30pp. 32862-168-32862-197.
- 8510080273** Advises that aeromagnetic map of State of TX transmitted prior to formal DOE Salt Repository Projects Ofc (SRPO) QA/technical review. Final map will be transmitted upon completion of formal review by SRPO. NEFF, J.O. Energy, Dept. of. 1168. 85/08/23. LINEHAN, J.J. Repository Projects Branch (Post 831001). 1p. 32925-222-32925-222.
- 8510080322** Forwards final bureau open-filed Rept OF-WTWI-1985-8, in response to 850626 telcon request W/o encl. CONDON, C. Texas, Univ. of, Austin, TX. 1169. 85/07/16. ROSS, F. Division of Waste Management. 1p. 32923-121-32923-121.
- 8510080343** Forwards listed bureau open-filed repts, in response to 850626 telcon request. Rept OF-WTWI-1985-8 will be transmitted at later date. W/o encls. CONDON, C. Texas, Univ. of, Austin, TX. 1170. 85/07/02. ROSS, F. Division of Waste Management. 1p. 32923-086-32923-086.
- 8510080570** Draft "Preliminary Data & Rept on Timing & Style Deformation Since Miocene Epoch in Yakima Fold Belt." CHUNG, D.H. Lawrence Livermore National Laboratory. FIN A-0294. SS-85-009. 85/09/26. BLACKFORD, M.E. Geotechnical Branch (Post 831001). 75pp. 32923-351-32924-063.
- 8510080605** Forwards listed bureau of economic geology open-filed repts requested by 850626 telcon. Remainder of repts will be sent at later date. CONDON, C. Texas, Univ. of, Austin, TX. 1105. 85/06/27. ROSS, F. Division of Waste Management. 16pp. 32923-184-32923-199.
- 8510080608** Forwards monthly mgt rept for Aug 1985 for FINS A-3164, "Review of DOE Waste Package Program" & A-3167, "Waste Package Verification Tests." Projections of costs by task encl for FY85. KATO, W.Y. Brookhaven National Laboratory. FIN A-3167. 2446. 85/09/24. WICK, E.A. High Level Waste Licensing Management Branch. 2pp. 32923-161-32923-183.
- 8510080612** "Review of DOE Waste Package Program," monthly mgt rept for Aug 1985. SOO, P. Brookhaven National Laboratory. FIN A-3164. 85/08/31. 14pp. 32923-163-32923-177.
- 8510080617** "Review of Waste Package Verification Tests," monthly mgt rept for Aug 1985. SOO, P. Brookhaven National Laboratory. FIN A-3167. 85/08/31. 6pp. 32923-178-32923-183.
- 8510080619** Forwards latitudes & longitudes for each UMTRAP processing site. monthly progress rept for Aug 1985. DUBOIS, D.P. Jacobs Engineering Group, Inc. 85/09/20. HAISFIELD, M. Low Level Waste Licensing Branch. 2pp. 32923-159-32923-160.
- 8510090021** "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project C," monthly progress rept for Aug 1985. WILLIAMS, R.E. Williams & Associates. FIN B-7377-2. 2432. 85/09/13. POHLE, J. Division of Waste Management. 3pp. 32964-054-32964-057.

8510090040 Forwards draft "NRC Point Paper on Exploratory Shaft Const & Testing (ES-I) BWIP, Hanford Site, WA."
MUKHERJEE, A. Engineers International, Inc. FIN D-1034. 2441. 85/09/27. BUCKLEY, J. Division of Waste Management. 1p. 32964-022-32964-052.

-8510090046 Draft "NRC Point Paper on Exploratory Shaft Const & Testing (ES-I) BWIP, Hanford Site, WA."
* Engineers International, Inc. 11085R. 85/09/30. 30pp. 32964-023-32964-052.

8510090056 "Benchmarking of Computer Codes & Licensing Assistance," monthly progress rpt for Aug 1985.
VOGT, D.K. CorSTAR Research, Inc. FIN B-6985. 2438. 85/09/18. BROOKS, P. Division of Waste Management. 5pp. 32954-011-32954-015.

8510090058 Rev 1 to Procedure OM-32, "Operating Procedure for ENVIRALLOY Disposal Containers W/ Series A (Wedge) Closures."
CLARK, G.L., HILL, S.E. Nuclear Packaging, Inc. 85/09/05. 14pp. 32963-321-32963-334.

8510090100 Forwards radiologic & engineering assessments for Vicinity Properties GJ-01014-RS, GJ-04253-RS, GJ-00050-CS, GJ-11268-RS, GJ-09769-RS & GJ-11525-MR.
TUCKER, M.K. Energy, Dept. of. 85/09/19. HIGGINBOTHAM, L. Repository Projects Branch (Post 831001). 1p. 32951-026-32951-026.

-8510090104 "Radiologic & Engineering Assessment for GJ-11525-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 43pp. 32951-027-32951-069.

-8510090110 "Radiologic & Engineering Assessment for GJ-09769-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/19. 37pp. 32951-070-32951-106.

-8510090116 "Radiologic & Engineering Assessment for GJ-11268-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/19. 43pp. 32951-107-32951-149.

-8510090119 "Radiologic & Engineering Assessment for GJ-00050-CS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/19. 44pp. 32951-150-32951-194.

-8510090126 "Radiologic & Engineering Assessment for GJ-04253-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/19. 44pp. 32951-195-32951-238.

-8510090133 "Radiologic & Engineering Assessment of GJ-01014-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/19. 63pp. 32951-239-32951-301.

8510090142 Notices of 850930 meeting w/delegates from West Germany in Silver Spring, MD to brief delegates on US site & technical criteria for disposal of high level radioactive waste in geologic repositories. Attendance suggested.
STEIN, R. Energy, Dept. of. RW-23. 85/09/26. BORGSTROM, C., MUSSLER, R., HILLEY, R. Energy, Dept. of. 1p. 32951-025-32951-025.

8510090151 Press release re DOE drilling program at Rifle, CO for disposal of 3,000,000 tons U mill tailings & related mail as part of UMRAP.
MCCARTY, B.E., HINDS, K.E. Energy, Dept. of. ALU-85-0012. 85/09/20. 1p. 32951-024-32951-024.

8510090152 Forwards marked-up draft "Annual Status Rept to Congress on U Mill Tailings Remedial Action Program." Comments requested by 851004 to meet statutory submittal to Congress.
GROELSEMA, D.H. Energy, Dept. of. 85/09/16. HIGGINBOTHAM, L. Low Level Waste Licensing Branch. 38pp. 32951-302-32951-339.

8510090158 Discusses observations, comments & recommendations for 850702-0816 re exchange of technical info, application of QA procedures to exploratory shaft design & mfg activities & analyses of radiochemical data.
COOK, F.R. NRC - No Detailed Affiliation Given. COOK, F.R. Basalt Waste Isolation Project. 1559. 85/09/09. BROWNING, R.E. Division of Waste Management. 3pp. 32951-021-32951-023.

8510090180 Requests to attend 851015-16 meetings in San Francisco, CA re 1985 subsurface drilling & seismic profiling program & field trips to Yucca Mountain & Death Valley for calcite & silica deposits study during wk of 851104.
PRESTHOLT, P.T. NRC - No Detailed Affiliation Given. 782. 85/09/25. VIETH, D.L. Energy, Dept. of. 1p. 32949-191-32949-191.

8510090202 Forwards radiologic & engineering assessments for Grand Junction, CO Properties GJ-04232-RS, GJ-02248-RS, GJ-11183-MR & GJ-05532-RS, for info per MOU between DOE & NRC.
TUCKER, M.K. Energy, Dept. of. 85/09/25. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 32949-232-32950-045.

-8510090207 "Radiologic & Engineering Assessment for GJ-04232-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/25. 44pp. 32949-233-32949-276.

-8510090210 "Radiologic & Engineering Assessment for GJ-02248-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/25. 29pp. 32949-277-32949-305.

-8510090213 "Radiologic & Engineering Assessment for GJ-11183-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/25. 58pp. 32949-306-32950-002.

-8510090218 "Radiologic & Engineering Assessment for GJ-05532-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/25. 43pp. 32950-003-32950-045.

8510090204 Forwards DOE Aug 1985 rept, "Methodology for Aiding Repository Siting Decisions," for review, per author 850829 ltr.
RUSCHE, B.C. Energy, Dept. of. 1585. 85/09/18. MYERS, P.B. National Academy of Sciences. 2pp. 32949-200-32949-231.

-8510090215 "Methodology for Aiding Repository Siting Decisions."
* Energy, Dept. of. 85/08/31. 30pp. 32949-202-32949-231.

8510090224 Monthly ltr rept for 850816-0915 for FIN D-1014.
BLAND, W.M. Management & Technical Consulting. FIN D-1014. 2445. 85/09/16. DELLIGATI, M.S. Policy & Program Control Branch (Post 831001). 2pp. 32949-197-32949-198.

8510090233 Submits trip rept on NRC/DOE 850827-28 workshop on Nevada Nuclear Waste Storage Investigation in Silver Spring, MD re exploratory shaft facility design & const.
KIM, Y.C. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2433. 85/09/05. BHATTACHARYA, S. Engineers International, Inc. 1p. 32949-196-32949-196.

8510090239 Lists objectives for NNWSI Project/NRC exploratory shaft test plan meeting. Meetings postponed from 850916-17 will be rescheduled.
VIETH, D.L. Energy, Dept. of. 781. 85/09/18. STABLEIN, N.K. Division of Waste Management. 2pp. 32949-194-32949-195.

8510090241 Forwards NRC 850722 ltr to Nuclear Packaging re reconstr of ENVIRALLOY family topical rept, for info, W/o encl.
SCHNEIDER, K.N. Assistant Director for State Agreements Programs. 85/07/31. AUTRY, V.R. South Carolina, State of. 2pp. 32949-192-32949-193.

8510090250 Forwards response to NRC 850924 questions/comments on CNSI-WF-C-01-NP, "10CFR61 Waste Form Certification - Cement." Justification for sea water leach tests on boron acid & bead resin listed. Further testing unnecessary.
POPPEL, L.K., STAHR, J.P. Chem-Nuclear Systems, Inc. 85/09/26. PERSON, L.S. NRC - No Detailed Affiliation Given. 32pp. 32950-046-32950-077.

8510090260 Forwards final draft "Statistical Evaluation of Addl Hydrochemical Data From Saddle Mountains, Wanapum & Grande Ronde Basalts, BWIP, Hanford Site."
WINTER, G.V. Williams & Associates. FIN B-7372-3. 2447. 85/09/30. GORDON, M. Division of Waste Management. 1p. 32948-088-32948-194.

-8510090268 Final draft "Statistical Evaluation of Addl Hydrochemical Data From Saddle Mountains, Wanapum & Grande Ronde Basalts, BWIP, Hanford Site."
* Williams & Associates. FIN B-7372-3. NPC-02-82-044. 85/08/23. Division of Waste Management. 106pp. 32948-090-32948-194.

8510090270 BWIP Accessions List issuance Notice MD-08/25/85 for period ending on 850825.
* NRC - No Detailed Affiliation Given. 1560. 85/09/16. 11pp. 32948-220-32948-232.

8510090272 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Geologic Repositories," monthly rept for Aug 1985.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1755. 2440. 85/09/13. NATARAJA, M.S. Engineering Branch (Post 831001). 19pp. 32948-201-32948-219.

8510090274 Thirty-eighth monthly progress rept under Contract NRC-02-82-044 for Aug 1985.
WILLIAMS, R.E. Williams & Associates. FIN B-7372-3. 2439. 85/09/09. GORDAN, M. Division of Waste Management. 9pp. 32950-180-32950-188.

8510090276 Forwards radiologic & engineering assessments for listed properties in Grand Junction, CO.
TUCKER, M.K. Energy, Dept. of. 85/09/23. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 32951-360-32951-360.

-8510090279 "Radiologic & Engineering Assessment for GJ-06591-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 34pp. 32951-361-32952-032.

-8510090284 "Radiologic & Engineering Assessment for GJ-04343-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 32pp. 32952-033-32952-064.

-8510090286 "Radiologic & Engineering Assessment for GJ-12370-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 41pp. 32952-065-32952-105.

-8510090289 "Radiologic & Engineering Assessment for GJ-02886-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 41pp. 32952-106-32952-146.

-8510090291 "Radiologic & Engineering Assessment for GJ-12523-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 35pp. 32952-147-32952-181.

-8510090293 "Radiologic & Engineering Assessment for GJ-03355-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 41pp. 32952-182-32952-222.

8510090310 Mod A008 to Cooperative Agreement DE-FC04-81AL16309, increasing DOE capital funds in Article VIII, "Cost Limitation & Obligation of Funds."
HOYAL, J.G. Energy, Dept. of. 85/09/27. 2pp. 32950-104-32950-105.

8510090311 "Technical Assistance for Design Reviews of High Level Waste Geologic Repositories," monthly progress rept for Aug 1985.
MARKHAM, J.J. ITASCA Consulting Group, Inc. FIN D-1016. 2430. 85/09/18. TIKINSKY, D. Division of Waste Management. 4pp. 32950-100-32950-103.

8510090314 Forwards water level graphs including mean monthly water levels at cluster Piezometers DC-19, 20 & 22 for Priest Rapids, Sentinel Gap, Ginkgo, Rocky Coulee, Cohasset & Umanum flows for Jan & Feb 1985.
WINTER, G. Williams & Associates. FIN B-7372-3. 2431. 85/09/20. GORDON, M. Division of Waste Management. 17pp. 32950-082-32950-098.

8510090323 Forwards four sheets on scale of 1:750,000, in response to request at 850805-09 Permian Basin Core exam for aeromagnetic map of Texas, W/o encl.
NEFF, J.O. Energy, Dept. of. 1167. 85/08/19. LIU, HAN, J.J. Repository Projects Branch (Post 831001). 1p. 32950-234-32950-234.

8510090327 Forwards preliminary draft of stratigraphic section & cartoon cross-section of Ogallala & Blackwater draw formations. Info re northeast-southwest thickness trends in eastern Deaf Smith County also encl.
GUSTAVSON, T.C. Texas, Univ. of, Austin, TX. 1171. 85/08/14. TRAPP, J. NRC - No Detailed Affiliation Given. 20pp. 32950-214-32950-233.

338 NONDOCKETED ITEMS

- 8510090330** Forwards Rev 1 to "Health Physics Procedures."
SULLIVAN,S. Morrison-Knudsen Engineers, Inc. 85/09/26. SOLLENBERGER,D. INHC
- No Detailed Affiliation Given. 2pp. 32950:201-32950:213.
- 8510090332** Rev 1 to "Health Physics Procedures."
MEYER,H.R. Chem-Nuclear Systems, Inc. 85/09/30. 11pp. 32950:203-32950:213.
- 8510090345** "Preparation of Engineering Analysis for High Level Waste Packages in
Geologic Repositories," monthly progress report for Aug 1985.
STEPHENS,K.W. Aerospace Corp. FIN A-4165-5. 2442. 85/09/13. CHANG,K.C. NRC
- No Detailed Affiliation Given. 24pp. 32949:135-32949:158.
- 8510090347** Forwards document reviews of "Experimental Characterization & Stability
of Salt & Non-Salt Containing Grouts & Mortars" & "Task V, Engineering Study 9, Under-
ground Repository Layout," for review.
RAJARAM,V. Engineers International, Inc. FIN B-7328. 2443. 85/09/20.
TIKTINSKY,D. High Level Waste Technical Development Branch. 18pp. 32949:117-
32949:134.
- 8510090349** Forwards radiologic & engineering assessments for Grand
Junction, CO, Properties GJ-03877-RS, GJ-04249-RS, GJ-03369-RM, GJ-01280-RS, GJ-
01128-RS & GJ-02826-RS.
TUCKER,M.K. Energy, Dept. of. 85/09/19. HIGGINBOTHAM,L. Low-Level Waste &
Uranium Recovery Projects Branch. 1p. 32948:249-32948:327.
- 8510090351** "Radiologic & Engineering Assessment for GJ-02826-RS."
* Bendix Field Engineering Corp. 85/09/30. 34pp. 32948:250-32948:283.
- 8510090352** "Radiologic & Engineering Assessment for GJ-01128-RS."
* Bendix Field Engineering Corp. 85/09/30. 44pp. 32948:284-32948:327.
- 8510090354** "Radiologic & Engineering Assessment for GJ-01280-RS."
* Bendix Field Engineering Corp. 85/09/30. 38pp. 32948:328-32949:003.
- 8510090357** "Radiologic & Engineering Assessment for GJ-03369-RM."
* Bendix Field Engineering Corp. 85/09/30. 43pp. 32949:004-32949:046.
- 8510090358** "Radiologic & Engineering Assessment for GJ-04249-RS."
* Bendix Field Engineering Corp. 85/09/30. 34pp. 32949:047-32949:082.
- 8510090360** "Radiologic & Engineering Assessment for GJ-03877-RS."
* Bendix Field Engineering Corp. 85/09/30. 33pp. 32949:083-32949:116.
- 8510090363** Forwards radiologic & engineering assessments for Vicinity Properties GJ-
16769-RS, GJ-00233-RS, GJ-43752-VL, GJ-31616-RS, GJ-90021-AP & GJ-13237-RS in
Grand Junction, CO.
TUCKER,M.K. Energy, Dept. of. 85/09/23. HIGGINBOTHAM,L. Repository Projects
Branch (Post 831001). 1p. 32962:267-32963:144.
- 8510090367** "Radiologic & Engineering Assessment for GJ-13237-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/23. 43pp.
32962:268-32962:310.
- 8510090373** "Radiologic & Engineering Assessment for GJ-90021-AP."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/20. 30pp.
32962:311-32962:340.
- 8510090377** "Radiologic & Engineering Assessment for GJ-31616-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/20. 59pp.
32962:341-32963:037.
- 8510090379** "Radiologic & Engineering Assessment for GJ-00233-RS & GJ-43752-
VL."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/20. 55pp.
32963:038-32963:092.
- 8510090383** "Radiologic & Engineering Assessment for GJ-16738-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/20. 52pp.
32963:093-32963:144.
- 8510090386** "Technical Assistance in Seismo-Tectonic Impacts in Repositories,"
Monthly Mgt Ltr Rept 29 for Aug 1985.
CHUNG,D.H. CUMMINGS,G.E. Lawrence Livermore National Laboratory. FIN A-0294.
L-196. 85/09/15. BLACKFORD,A.E. Geotechnical Branch (Post 831001). 2pp.
32965:062-32965:063.
- 8510090390** Forwards trip report of 850926-28 meetings in Silver Spring, MD re preparation
for NRC-DOE 850927-28 meetings on exploratory shaft design & const. List of at-
tendees for 850828 meeting encl.
RAJARAM,V. Engineers International, Inc. FIN B-7328. 2434. 85/09/13.
TIKTINSKY,D. Division of Waste Management. 10pp. 32965:048-32965:057.
- 8510090399** Summary of 850926-27 meetings w/DOE & consultants in Silver Spring, MD
re subsystem performance allocation. Attendance list, agenda & viewgraphs encl.
COPLAN,S.M. Division of Waste Management. ALEXANDER,D.H. Energy, Dept. of.
85/09/27. Division of Waste Management. 38pp. 32964:345-32965:020.
- 8510090400** Forwards trip report of 850805-08 meetings in Austin, TX re review status of
geological & geomechanical investigations of Palo Duro Basin & core exam. List of at-
tendees encl.
RAJARAM,V. Engineers International, Inc. FIN B-7328. 2435. 85/09/17.
TIKTINSKY,D. Division of Waste Management. 6pp. 32964:339-32964:344.
- 8510090409** Forwards nonproprietary Rev 1 to "Topical Rept SG-95 Solidified Boric Acid
to Meet Stability Requirements of 10CFR61." Rev necessary to incorporate re-
sults of 90-day immersion, biodegradation & leachability tests.
BORIS,G.F. Westinghouse Hittman Nuclear, Inc. WHNI-E-826. 85/09/24.
PERSON,L.S. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 32964:315-
32964:323.
- 8510090414** STR-R-05-008 R01 Rev 1 to "Topical Rept SG-95 Solidified Boric Acid to
Meet Stability Requirements of 10CFR61."
* Westinghouse Hittman Nuclear, Inc. ECN 85-129. 85/09/24. 8pp. 32964:316-
32964:323.
- 8510090420** Forwards radiological assessment coordinator responses to DOE com-
ments on REA-DU-221.
PEPIN,J. Morrison-Knudsen Engineers, Inc. 85/09/24. SENA,R. Energy, Dept. of. 2pp.
32964:292-32964:293.
- 8510090421** Forwards monthly update & schedule for site & near-term site characteriza-
tion for site & engineered barriers dept activities. Info will be updated on regular basis.
OLSON,O.L. Washington, State of. 1562. 85/09/20. HUSSEMAN,T. Washington,
State of. POWER,M.S. Evergreen State College, Olympia, WA. JIM,R.R. Yakima Indian
Nation. 6pp. 32964:286-32964:291.
- 8510090422** Forwards "Internal Guidelines for Interactions W/Communities & Local
Govts." Interest level of local groups will inevitably intensify.
RUSCHE,B.C. Energy, Dept. of. RW-1. 85/09/20. BAUER,B., PURCELL,B., HILLEY,R.
Energy, Dept. of. 22pp. 32964:264-32964:285.
- 8510090445** Forwards revised program review for 851016-17 meetings in Silver
Spring, MD re FIN B-0267, "Technical Assistance in Biochemistry" & FIN B-0290, "Lab
Evaluation of Retardation Parameters."
JACOBS,G.K. Oak Ridge National Laboratory. FIN B-0267. 2429. 85/09/23.
BROOKS,D. NRC - No Detailed Affiliation Given. 3pp. 32948:085-32948:087.
- 8510090446** Forwards response to NRC 850117 & 0304 comments on seismic hazard
evaluation of UMTRAP site, including info re insp of excavations for evidence of
faulting, definition of active fault & performance of geophysical surveys.
WILLIAMS,R.L. Jacobs Engineering Group, Inc. 85/06/07. THEMELIS,J.G. Energy,
Dept. of. 9pp. 32966:315-32966:328.
- 8510090451** Forwards DOE weekly repts for NNWSI for wks of 850822, 29, 0905 & 12.
"NNWSI Project Monthly Rept, Jul 1985" also encl.
PRESTHOLT,P.T. Policy & Program Control Branch (Post 831001). 783. 85/09/25.
BROWNING,R.E. Division of Waste Management. 19pp. 32966:223-32966:313.
- 8510090452** "Nevada Nuclear Waste Storage Investigations Project Monthly Rept, Jul
1985."
* Energy, Dept. of. 85/07/31. 72pp. 32966:242-32966:313.
- 8510090469** Forwards marked-up Section 7 of Lakeview remedial action plan, "Respon-
sibilities of Project Participants" & App B to "Remedial Action Plan & Site Conceptual
Design for Stabilization of Inactive U Mill Tailings..."
THEMELIS,J.G. Energy, Dept. of. 85/09/25. HIGGINBOTHAM,L. Division of Waste
Management. 6pp. 32965:247-32966:144.
- 8510090482** App B to Cooperative Agreement DE-FC04-84AL20534, "Remedial Action
Plan & Site Conceptual Design for Stabilization of Inactive U Mill Tailings Site at
Lakeview, OR."
* Energy, Dept. of. 85/09/30. 100pp. 32965:253-32966:144.
- 8510090400** Task Order 001, "Technical Meetings & Document Reviews on
BWIP, NNWSI & Salt Technical & Cost Proposal," under NRC-02-85-002, "Design Re-
views of High Level Nuclear Waste Geologic Repositories."
MARKHAM,J.J. ITASCA Consulting Group, Inc. FIN D-1016. 2437. 85/09/10. NRC -
No Detailed Affiliation Given. 9pp. 32966:145-32966:153.
- 8510090516** "Technical Assistance for Design Reviews," 37th monthly report for Aug
1985.
RAJARAM,V. Engineers International, Inc. FIN B-7328. 1085-37. 85/09/18.
TIKTINSKY,D. Division of Waste Management. 5pp. 32966:336-32966:340.
- 8510090518** Forwards final camera-ready copy of NUREG/CR-4110, SAND84-2668,
"Repository Site Data Rept for Unsaturated Tuff" & responses to NRC comments W/
o NUREG/CR-4110.
HUNTER,R.L. Sandia National Laboratories. FIN A-1158. 85/09/23. COLEMAN,N.
Geotechnical Branch (Post 831001). 3pp. 32965:194-32965:196.
- 8510090519** "Executive Summary on Feasibility Study of Applying Geostatics to Repository
Site Characterization." W/850914 ltr.
KIM,Y.C. Arizona, Univ. of, Tucson, AZ. FIN D-1016. 2436. 85/09/14. GREEVES,J.
NRC - No Detailed Affiliation Given. 23pp. 32965:170-32965:193.
- 8510090524** Forwards info from WPPSS-2 OL file re elastic dikes of Hanford region, per
R Lee 850912 telcon request to 1 Alterman, Partial "Task D3 Quaternary Sediments
Study of Pasco Basin & Adjacent Areas" encl.
BROCCOUM,S.J. Geosciences Branch. 1561. 85/09/20. JUSTUS,P. Geotechnical
Branch (Post 831001). 33pp. 32965:094-32965:128.
- 8510090538** Extends invitation to Ofc of Civilian Radwaste Mgt Fall info meetings on
851118-19 in Atlanta, GA to discuss program info svcs, resources & data
sys. Preliminary meeting agenda & preregistration form encl.
GALE,R.W. Energy, Dept. of. 85/09/25. NRC - No Detailed Affiliation Given. 3pp.
32965:081-32965:083.
- 8510110069** "Site Characterization Info Needs for Salt Repository Design," per Task 3
of Task Order 011.
SINGH,M.M. Engineers International, Inc. FIN B-7328. 1085-011-3. 85/09/19.
TIKTINSKY,D. NRC - No Detailed Affiliation Given. 33pp. 33011:263-33011:295.
- 8510230255** Reviews "Geochemical Sensitivity Analysis," monthly progress report for Aug
1985. Progress to date satisfactory. Trip report of attendance at 850918-20 coupled
processes symposium at LBL should be prepared.
KELLY,W.R. Geotechnical Branch (Post 831001). FIN A-1756. 2491. 85/09/30.
SIEGEL,M.D. Sandia National Laboratories. 14pp. 33106:331-33106:344.
- 8510230266** Forwards water level info for Riverton UMTRAP site, as followup to 850827
ltr.
WEBER,M.F. Geotechnical Branch (Post 831001). 85/09/05. LESTER,B.H. GeoTrans,
Inc. 4pp. 33106:327-33106:330.
- 8510230267** Forwards conclusions re status of NRC review of Shiprock radon
barrier. Barrier design remains open until NRC can approve revised design which ap-
plies more reliable diffusion coefficient.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/
05. THEMELIS,J.G. Energy, Dept. of. 2pp. 33108:240-33108:241.
- 8510230271** Forwards comments on draft certification plan for UMTRAP processing
sites. Plan should clarify & provide greater detail re NRC role in concurrence w/ certifi-
cation.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/
29. THEMELIS,J.G. Energy, Dept. of. 7pp. 33108:242-33108:248.

- 8510230290** Ack receipt of Aug 1985 Monthly Rept 17. Quality of review comments & rept satisfactory.
IBRAHIM, A.K. Geotechnical Branch (Post 831001). FIN D-1003. 2451. 85/10/01. MURPHY, V.J. Weston Geophysical Corp. 1p. 33108:253-33108:253.
- 8510230305** Comments on Aug 1985 monthly rept. Changes to hydrochemical data satisfactory.
GORDON, M. Geotechnical Branch (Post 831001). FIN B-7372. 2453. 85/09/23. WILLIAMS, R.E. Williams & Associates. 1p. 33108:257-33108:257.
- 8510230308** "Repository Site Description & Technology Transfer," monthly rept for Sept 1985.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1158. 2482. 85/10/14. COLEMAN, N.M. Geotechnical Branch (Post 831001). 4pp. 33108:258-33108:261.
- 8510230316** Comments on "Review of DOE Waste Package Program" & "Review of Waste Package Verification Tests," monthly progress repts for June 1985. Progress satisfactory. No changes to cost or delivery of products authorized.
WICK, E.A. Engineering Branch (Post 831001). FIN A-3164. 2490. 85/08/22. SOO, P. Brookhaven National Laboratory. 1p. 33108:262-33108:262.
- 8510240020** "Geochemical Sensitivity Analysis," monthly rept for Sept 1985.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1756. 2480. 85/10/14. KELLY, W. NRC - No Detailed Affiliation Given. 8pp. 33163:152-33163:159.
- 8510240027** Comments on "Technical Assistance in Geochemistry," monthly progress rept for Aug 1985. Progress satisfactory. Related repts encl.
BROOKS, D.J. Geotechnical Branch (Post 831001). FIN B-0287. 2460. 85/09/25. WHATLEY, S.K. Oak Ridge National Laboratory. 157pp. 33162:351-33162:351.
- 8510240030** "Technical Assistance in Geochemistry," monthly progress rept for Sept 1985.
JACOBS, G.K. Oak Ridge National Laboratory. FIN B-0287. 2476. 85/10/04. BROOKS, D.J. Geotechnical Branch (Post 831001). 14pp. 33162:337-33162:350.
- 8510240046** Comments on Aerospace Corp monthly rept for Aug 1985 re corrosion modeling. Workers should be encouraged to focus more on how to use mathematical tools to study consequences of realistic waste package failure.
MCNEIL, M.B. Waste Management Branch (Post 840429). FIN A-4165. 2458. 85/10/02. CHANG, K.C. Engineering Branch (Post 831001). 1p. 33162:333-33162:333.
- 8510240053** QA program for BWIP of siting & site characterization activities.
BRACKEN, G.F., OLSEN, O.L. Energy, Dept. of. 85/03/22. 350pp. 33164:043-33165:073.
- 8510240084** Trip rept of 850909-11 visit to Sandia to review recent progress in project FIN A-1756, "Geochemical Sensitivity Analysis."
KELLY, W.P. Geotechnical Branch (Post 831001). FIN A-1756. 2449. 85/10/02. JACKSON, K.C. Geotechnical Branch (Post 831001). 2pp. 33176:359-33176:360.
- 8510240086** Forwards radiologic & engineering assessments for Properties GJ-00595-MR, GJ-01245-MR, GJ-01249-RS, GJ-00995-MR, GJ-11466-RM & GJ-13040-RS in Grand Junction, CO.
TUCKER, M.K. Energy, Dept. of. 85/10/10. HIGGINBOTHAM, L. Repository Projects Branch (Post 831001). 1p. 33178:203-33179:098.
- 8510240092** "Radiologic & Engineering Assessment for GJ-00595-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 50pp. 33178:204-33178:253.
- 8510240100** "Radiologic & Engineering Assessment for GJ-01245-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 40pp. 33178:254-33178:293.
- 8510240110** "Radiologic & Engineering Assessment for GJ-01249-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 42pp. 33178:294-33178:335.
- 8510240117** "Radiologic & Engineering Assessment for GJ-00995-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 42pp. 33178:336-33179:015.
- 8510240119** "Radiologic & Engineering Assessment for GJ-11466-RM."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 55pp. 33179:016-33179:070.
- 8510240121** "Radiologic & Engineering Assessment for GJ-13040-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/31. 28pp. 33179:071-33179:098.
- 8510240111** Monthly Progress Ltr Rept 18 for Sept 1985 re geophysical data.
FANNON, M.M. Weston Geophysical Corp. FIN D-1003. 2474. 85/10/10. IBRAHIM, A. Geotechnical Branch (Post 831001). 2pp. 33176:361-33176:362.
- 8510240118** Forwards notes of NNWSI/NRC 850827-28 meetings in Silver Spring, MD re exploratory shaft design.
VIETH, D.L. Energy, Dept. of. 762. 85/10/04. LINEHAN, J.J. Repository Projects Branch (Post 831001). 30pp. 33182:302-33182:332.
- 8510240120** Forwards completed leach test results for Resin A & 66% PWR waste forms for deionized water & sea water.
NEILSEN, E.H. Chem-Nuclear Systems, Inc. 85/10/08. PERSON, L.S. NRC - No Detailed Affiliation Given. 13pp. 33176:338-33176:350.
- 8510240123** Forwards draft Quarterly Rept NUREG/CR-4236, Vol 3, "Evaluation of Radiocesium Geochemical Info Developed by DOE High Level Nuclear Waste Repository Site Projects Rept for Apr-June 1985."
JACOBS, G.K. Oak Ridge National Laboratory. FIN B-0290. 2472. 85/10/07. BRADBURY, J.W. Geotechnical Branch (Post 831001). 27pp. 33176:311-33176:337.
- 8510240128** Comments on Jul 1985 monthly progress rept for FIN B-0287, "Technical Assistance in Geochemistry." Progress to date satisfactory.
BROOKS, D.J. Geotechnical Branch (Post 831001). FIN B-0287. 2489. 85/09/05. WHATLEY, S.K. Oak Ridge National Laboratory. 43pp. 33176:266-33176:310.
- 8510240133** Forwards App D of draft, "Repository Environ Parameters Relevant to Assessing Performance of High Level Waste Packages in Basalt, Tuff & Salt."
WHATLEY, S.K. Oak Ridge National Laboratory. FIN B-0288. 2489. 85/10/07. CHANG, K.C. Engineering Branch (Post 831001). 35pp. 33180:242-33180:276.
- 8510240134** Forwards radiologic & engineering assessments for Properties GJ-12136-RS, GJ-03805-RS, GJ-01257-MR & GJ-12924-MR.
TUCKER, M.K. Energy, Dept. of. 85/10/08. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33180:077-33180:241.
- 8510240150** "Radiologic & Engineering Assessment for GJ-12136-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/08. 34pp. 33180:078-33180:112.
- 8510240155** "Radiologic & Engineering Assessment for GJ-03805-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/08. 32pp. 33180:113-33180:144.
- 8510240159** "Radiologic & Engineering Assessment for GJ-01257-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/08. 42pp. 33180:145-33180:186.
- 8510240163** "Radiologic & Engineering Assessment for GJ-12924-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/10/08. 55pp. 33180:187-33180:241.
- 8510240147** "Effect of Repository Environ on Performance of Waste Package/Engineering Sys Components," monthly progress rept for Sept 1985. App D of draft Rev 1 to NUREG/CR-4134 & revised work plan being sent separately.
WHATLEY, S.K. Oak Ridge National Laboratory. FIN B-0288. 2473. 85/10/07. CHANG, K.C. Engineering Branch (Post 831001). 2pp. 33180:326-33180:327.
- 8510240153** Summary of activities during Sept 1985 for FIN A-1165.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1165. 2479. 85/10/13. ELZEFTAWY, A. Repository Projects Branch (Post 831001). 5pp. 33180:321-33180:325.
- 8510240162** "Technical Assistance in Numerical Modeling Assessment of High Level Waste Repositories," monthly rept for Sept 1985.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1757. 2478. 85/10/13. COLEMAN, N. Geotechnical Branch (Post 831001). 2pp. 33176:355-33176:356.
- 8510240131** Forwards trip rept of 850916-18 visit to State of NV test site & status rept on erosion rates.
CHUNG, D.H. Lawrence Livermore National Laboratory. FIN A-0294. 2470. 85/10/07. BLACKFORD, M.E. Division of Waste Management. 8pp. 33180:313-33180:320.
- 8510240188** Forwards sanitized 05-1B3-WSTFO-R1, "Leachability Testing of SG-95 Samples," per 850930 request.
BORIS, G.F. Westinghouse Hittman Nuclear, Inc. WHN-E-833. 85/10/02. PERSON, L.S. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33180:277-33180:312.
- 8510240192** 85-1B3-WSTFO-R1 Sanitized "Leachability Testing of SG-95 Samples."
GRANT, D.C. Westinghouse Electric Corp. 85/03/06. 35pp. 33180:278-33180:312.
- 8510240196** Comments on Monthly Mgt Ltr 28 summarizing progress for Jul 1985 under FIN A-0294 Progress to date satisfactory.
BLACKFORD, M.E. Geotechnical Branch (Post 831001). FIN A-0294. 2493. 85/09/04. CHUNG, D. Lawrence Livermore National Laboratory. 1p. 33176:358-33176:358.
- 8510240207** Requests listed tasks be initiated under Subtask 1.1, to support analyses of repository site characterization plans to be issued in FY86. Tasks include review of DOE rept on structural analysis of Northern Palo Duro Basin.
BLACKFORD, M.E. Geotechnical Branch (Post 831001). FIN A-0294. 2492. 85/09/26. CHUNG, D. Lawrence Livermore National Laboratory. 2pp. 33182:044-33182:045.
- 8510240252** Forwards proposed agenda for DOE/NRC 851029 meeting to discuss DOE strategy for presentation of test plans, analyses & studies in Section 6.3 of site characterization plans.
ALEXANDER, D.H. Energy, Dept. of. 85/10/09. LINEHAN, J. Repository Projects Branch (Post 831001). 2pp. 33182:042-33182:043.
- 8510240263** Forwards radiologic & engineering assessments for Properties ED-00179-RS, ED-00451-OT & ED-00503-RS in Edgemont, SD.
GRANDBOUCHE, G. Energy, Dept. of. 85/10/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33181:247-33181:322.
- 8510240268** Thirty-ninth monthly progress rept for Sept 1985 for FIN B-7372.
WILLIAMS, R.E. Williams & Associates. FIN B-7372. 2462. 85/10/04. GORDON, M. Division of Waste Management. 5pp. 33182:037-33182:041.
- 8510240284** Forwards "Remedial Action Plan & Site Conceptual Design for Stabilization of Inactive U Mill Tailings Site at Shiprock, NM."
THEMELIS, J.G. Energy, Dept. of. 85/10/10. GILLEN, D. HAWKINS, E. HIGGINBOTHAM, L. NRC - No Detailed Affiliation Given. 3pp. 33180:328-33181:246.
- 8510240290** "Remedial Action Plan & Site Conceptual Design for Stabilization of Inactive U Mill Tailings Site at Shiprock, NM."
HILL, T.V., MORLEY, J.A. Energy, Dept. of. BEGAN, E.T. Navajo Nation. 85/06/30. 150pp. 33180:331-33181:246.
- 8510240296** Forwards trip rept of 850916-19 meetings w/NRC & ITASCA Consulting Group, Inc. in Las Vegas, NV re document review & Yucca Mountain site visit.
BHATTACHARYA, S. Engineers International, Inc. FIN B-7328. 2462. 85/10/02. TIKTINSKY, D. Division of Waste Management. 2pp. 33182:146-33182:147.
- 8510240303** Responds to Technical Assistance Request 85058 re review of proposed remedial action mods for Salt Lake City UMTRAP site. Analyses providing justification for mod, should be presented before branch can consider mod.
GRIEVES, J.T. Engineering Branch (Post 831001). 85/08/23. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 33pp. 33182:113-33182:145.
- 8510240311** Forwards state/tribe monthly status rept for Aug 1985. Next project coordination meeting will be held in Salt Lake City, UT on 851016-17. Draft agenda encl.
THEMELIS, J.G. Energy, Dept. of. 85/10/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 8pp. 33180:354-33180:359.
- 8510240344** "Effect of Repository Environ on Performance of Waste Package/Engineering Sys Components."
WHATLEY, S.K. Oak Ridge National Laboratory. FIN B-0288. 2485. 85/10/11. CHANG, K.C. Engineering Branch (Post 831001). 22pp. 33182:091-33182:112.

340 NONDOCKETED ITEMS

- 8510240346 Advances of data base training sessions planned for 851029-31, including technical data base (TDB), records & info sys (RIS) & catalog & records turn-over package data base (RTP).
NEFF, J.O. Energy, Dept. of. 1177. 85/10/01. LINEHAN, J.J. Repository Projects Branch (Post 831001). 1p. 33182-173-33182-173.
- 8510240352 Forwards trip repts of attendance at NNWSI 850918-18 review meeting "Las Vegas, NV & 850918-20 "Int'l Symposium on Coupled Processes Affecting Performance of Nuclear Waste Repository" at Berkeley, CA.
HART, R.D. ITASCA Consulting Group, Inc. FIN D-1016. 2483. 85/10/08. TIKTINSKY, D. Division of Waste Management. 23pp. 33182-068-33182-090.
- 8510240362 "Coupled Thermal-Hydrological-Mechanical Assessment & Site Characterization Activities for Geologic Repositories Monthly Rept for Sept 1985."
CRANWELL, R.M. Sandia National Laboratories. FIN A-1755. 2481. 85/10/15. NATARAJA, M.S. Engineering Branch (Post 831001). 20pp. 33182-048-33182-067.
- 8510240367 "Maint of Computer Programs," monthly rept for Sept 1985.
CRANWELL, R.M. Sandia National Laboratories. FIN A-1166. 2477. 85/10/13. COLEMAN, N.M. Geotechnical Branch (Post 831001). 2pp. 33182-046-33182-047.
- 8510240380 Forwards review of SAND-83-0372, "Unit Evaluation at Yucca Mountain, NV Test Site: Summary Rept & Recommendation" & SAND-84-1003, "NNWSI Exploratory Shaft Site & Const Method Recommendation Rept."
HART, R.D. ITASCA Consulting Group, Inc. FIN D-1016. 2461. 85/10/03. TIKTINSKY, D. Division of Waste Management. 31pp. 33182-174-33182-204.
- 8510240383 Forwards outline of content requirements for description of studies in Chapter 8 of site characterization plan, providing basis for discussion at 851029 meeting between DOE & NRC.
ALEXANDER, D.H. Energy, Dept. of. 85/10/15. GRACE, S. Repository Projects Branch (Post 831001). 5pp. 33182-266-33182-271.
- 8510240453 Forwards Rev B to vicinity properties mgt & implementation manual, per request. Major changes that have occurred since Apr 1985 will appear in Rev C, scheduled for release in Apr 1986. W/o encl.
WILLIAMS, R.L. Jacobs Engineering Group, Inc. 85/10/02. STILL, N. NRC - No Detailed Affiliation Given. 1p. 33182-205-33182-205.
- 8510240460 Forwards review of Olive remedial action insp plan, per Technical Assistance Request TAR 85062.
GREEVES, J.T. Engineering Branch (Post 831001). 85/09/06. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 5pp. 33182-168-33182-172.
- 8510240461 Forwards, for use & review, final Lakeview processing site characterization rept & disposal site characterization rept for Collins Ranch. Documents incorporate responses to comments received on draft repts.
THEMELIS, J.G. Energy, Dept. of. 85/10/09. HIGGINBOTHAM, L. Division of Waste Management. 1p. 33185-236-33185-172.
- 8510240467 UMTRA-DOE/AL-050123. UMTRA-DOE/AL-050123.0001, "Disposal Site Characterization Rept for Alternate U Mill Tailings Disposal Site at Collins Ranch Near Lakeview, OR." W/ four oversize maps & one oversize drawing.
* Energy, Dept. of. 85/10/31. 600pp. 33185-237-33187-172.
- 8510240471 UMTRA-DOE/AL-050106. UMTRA-DOE/AL-050106.0000, "Processing Site Characterization for U Mill Tailings Site at Lakeview, OR." W/ seven oversize maps.
* Energy, Dept. of. 85/10/31. 600pp. 33187-173-33189-172.
- 8510240505 Forwards calculations for Shiprock Site surface water hydrology analysis, per 851003 request. Add info provided to resolve conditional concurrence re rock size for Shiprock remedial action. W/o encl.
THEMELIS, J.G. Energy, Dept. of. 85/10/10. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33182-153-33182-153.
- 8510240507 Forwards monthly progress rept for Sept 1985 for FIN A-167A. Cost & labor estimates for Task 004 also encl. W/o encl.
JOHNSON, R.L. Aerospace Corp. FIN A-167A. 2468. 85/10/11. BENDER, A. Policy & Program Control Branch (Post 831001). 1p. 33182-148-33182-148.
- 8510240510 Forwards Shiprock Site backup calculations re design erosion protection for embankment & ditches, based on revised PMP & evaluation of present design in embankment & ditch protection, in response to 850517 ltr.
WATHEN, T.R. Morrison-Knudsen Engineers, Inc. 85/10/04. JOHNSON, T. NRC - No Detailed Affiliation Given. 90pp. 33225-058-33225-153.
- 8510240513 Forwards radiologic & engineering assessments for Properties GJ-03074-CS, GJ-09857-RS & GJ-31763-MR. Contamination does not exceed EPA stds. No remedial action recommended.
TUCKER, M.K. Energy, Dept. of. 85/10/02. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33182-292-33183-040.
- 8510240520 "Radiologic & Engineering Assessment for GJ-31763-MR."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 34pp. 33182-293-33182-327.
- 8510240529 "Radiologic & Engineering Assessment for GJ-09857-RS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 27pp. 33182-328-33182-353.
- 8510240537 "Radiologic & Engineering Assessment for GJ-03074-CS."
* Bendix Field Engineering Corp. TUCKER, M.K. Energy, Dept. of. 85/09/30. 49pp. 33182-354-33183-040.
- 8510240514 Forwards plans for involving states & tribes in Ofc of Geologic Repositories coordinating groups per commitment made during 850808-09 quarterly meeting in Denver, CO to transmit plan by 851008.
PURCELL, W.J. Energy, Dept. of. 85/10/07. BUNTING, J., MATTSON, D.R., REGNIER, E. NRC - No Detailed Affiliation Given. 3pp. 33182-289-33182-291.
- 8510240516 Forwards comments on draft remedial action plan & site characterization rept for mill tailings site at Durango, CO. Erosion protection proposed for drainage ditches & for prevention of gully intrusion inadequately designed.
HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/30. THEMELIS, J. Energy, Dept. of. 9pp. 33182-280-33182-288.
- 8510240517 Forwards State of SC certificate of compliance for Nuclear Packaging, Inc. for Model NUPAC FL-50/EA-50 Ferralium 225 high integrity container at Barnwell.
NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/04. Region 1, Office of Director. 6pp. 33182-274-33182-279.
- 8510240522 Submits trip rept of participation in NRC 850925-27 meetings w/ DOE in Silver Spring, MD re performance allocation & geostatistical application to NNWSI site characterization.
KIM, Y.C. Arizona, Univ. of. Tucson, AZ. FIN B-7328. 2485. 85/09/30. BHATTACHARYA, S. Engineers International, Inc. 2pp. 33177-350-33177-351.
- 8510240525 Ack receipt of Aug 1985 progress rept for FIN B-0288 & draft Rev 1 to NUREG/CR-4134, "Repository Environ Parameters re Assessing Performance of High Level Waste Packages in Basalt, Tuff & Salt." Comments expected by 851031.
CHANG, K.C. Engineering Branch (Post 831001). FIN B-0288. 2457. 85/09/25. WHITLEY, S.K. Oak Ridge National Laboratory. 2pp. 33177-348-33177-349.
- 8510240541 Requests review of listed documents under Task 2 of Task Order 001 of NRC-02-85-002, "Technical Assistance for Design Reviews of High Level Nuclear Waste Geologic Repositories."
TIKTINSKY, D.H. Engineering Branch (Post 831001). FIN D-1016. 2455. 85/08/11. HART, R. ITASCA Consulting Group, Inc. 2pp. 33177-346-33177-347.
- 8510240545 Twenty-second monthly progress rept for Sept 1985.
WINTER, G. Williams & Associates, FIN B-7389-3. 2467. 85/10/14. ROSS, F. Division of Waste Management. 4pp. 33177-342-33177-345.
- 8510240547 Trip rept of 850813 visit to Durango site & alternate sites to meet w/ U Recovery Field Ofc, TAC & State of CO re draft remedial action plan & to observe Colorado State Univ flume experiments.
HAISFIELD, M. Low-Level Waste & Uranium Recovery Projects Branch. JOHNSON, T. Geotechnical Branch (Post 831001). 85/08/26. MARTIN, D.E. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33178-009-33178-011.
- 8510240548 Monthly mgt telcon w/ J. Reuss on 850913 re work performed since inter-agency agreement (Contract NRC-02-85-004) initiated. Receipt of trip rept for kick-off meeting has completed Task Order 001.
LEER, R. NRC - No Detailed Affiliation Given. FIN D-1018. 2454. 85/09/26. 3pp. 33178-008-33178-008.
- 8510240553 Requests commitment for interim guidance re const of repository for Lakeview cleanup project, per Tenth Circuit Court of Appeals decision against EPA ground-water stds applicable to U mill tailings cleanup projects.
FRANK, L. Oregon, State of. 85/10/11. THOMAS, L. Environmental Protection Agency. 2pp. 33177-354-33177-355.
- 8510240554 Responds to 850920 ltr re NRC plans for state participation in NRC review of DOE documents. Add 2 wks for interaction w/ state & tribes on NRC milestones will allow significant state input.
SPURGIN, P.D. Utah, State of. 1176. 85/09/30. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 1p. 33177-353-33177-353.
- 8510240555 Responds to monthly progress rept for Jul 1985. Requests to be advised of problems encountered in running ADINA codes.
BROOKS, P.P. Repository Projects Branch (Post 831001). FIN B-6885. 2452. 85/10/01. VOGT, D.K. CorStar Research, Inc. 1p. 33177-352-33177-352.
- 8510240557 Forwards list of commitments made at DOE & states & Indian Tribes 850808 & 09 meetings.
PURCELL, W.J. Energy, Dept. of. RW-25. 85/10/07. BUNTING, J., REGNIER, E., RUSSELL, C. NRC - No Detailed Affiliation Given. 4pp. 33183-319-33183-322.
- 8510240561 Submits names of individuals having site responsibilities & site assignments at UMTRAP ofc.
THEMELIS, J.G. Energy, Dept. of. 85/10/01. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33183-317-33183-318.
- 8510240562 Forwards questions & comments re surface water hydrology & erosion protection aspects of Durango remedial action plan.
KNAPP, M.R. Geotechnical Branch (Post 831001). 85/08/23. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. SMITH, D. Uranium Recovery Field Office. 5pp. 33184-021-33184-025.
- 8510240563 Responds to Items 1, 4 & 5 raised in 850717 ltr re draft evaluation rept for NUPAC Container FL-50/EA-50. Licenses required to have data which demonstrates compliance w/ 10CFR61 waste classification requirements.
NUSSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/02. STRONG, T.R. Washington, State of. 2pp. 33184-019-33184-020.
- 8510240569 Forwards handset distributed at Rockwell Hanford Operations audit exit briefing & surveillance schedule & list of surveillances. Use of interim procedures discussed & will be included in final rept.
RAST, J. Energy, Dept. of. 85/10/07. HEDGES, D., MILLER, J., DELLIGATTI, M. NRC - No Detailed Affiliation Given. 38pp. 33183-339-33184-013.
- 8510240572 Rept of Salt Repository Project site visit for wks of 850819-0930.
VERMA, T.R. NRC - No Detailed Affiliation Given. 1178. 85/10/04. BROWNING, R.E. Division of Waste Management. 2pp. 33183-337-33183-338.
- 8510240576 Submits list of final std operating procedure elements under interagency Agreement NRC-02-85-004 per 850809 request for comments. Mods include addition of Element 8 re review of project-related expenses.
REUSS, J.L. Interior, Dept. of. Bureau of Mines. FIN D-1018. 2463. 85/10/04. LEER, R. Waste Management Branch (Post 840429). 2pp. 33183-334-33183-336.
- 8510240582 Clarifies response to questions at NRC 850918 meeting in Silver Spring, MD re issues tracking & info mgt sys. Promise that statutory licensing period permits 3 months for discovery in repository licensing proceeding unacceptable.
TOUSLEY, D.R. Harmon, Weiss & Jordan. TOUSLEY, D.R. Yakima Indian Nation. 85/10/09. OLMSTEAD, W.J. Regulations Division. 3pp. 33183-323-33183-325.
- 8510240583 Forwards radiologic & engineering assessments for Properties GJ-00034-RS, GJ-01139-RS, GJ-00443-MR, GJ-06208-RS, GJ-02313-MR, GJ-02273-MR, GJ-00941-RS & GJ-02311-MR.
TUCKER, M.K. Energy, Dept. of. 85/10/02. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33184-030-33185-001.

- 8510240595 "Radiologic & Engineering Assessment for GJ-02311-MR."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 33pp. 33184:031-33184:063.
- 8510240605 "Radiologic & Engineering Assessment for GJ-00941-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 40pp. 33184:064-33184:104.
- 8510240613 "Radiologic & Engineering Assessment for GJ-02273-MR."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 57pp. 33184:105-33184:161.
- 8510240621 "Radiologic & Engineering Assessment for GJ-02313-MR."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 36pp. 33184:162-33184:197.
- 8510240626 "Radiologic & Engineering Assessment for GJ-06208-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 33pp. 33184:198-33184:230.
- 8510240630 "Radiologic & Engineering Assessment for GJ-00443-MR."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 38pp. 33184:231-33184:268.
- 8510240638 "Radiologic & Engineering Assessment for GJ-01139-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/10/01. 42pp. 33184:269-33184:310.
- 8510240643 "Radiologic & Engineering Assessment for GJ-00034-RS."
* Bendix Field Engineering Corp. TUCKER,M.K. Energy, Dept. of. 85/09/30. 54pp. 33184:311-33185:003.
- 8510240586 Forwards schedule of tentative & planned meetings w/NRC on variety of topics,including environ assessment comment response,generic QA meeting,CY86 meeting,planning,BWIP geochemistry workshop & BWIP waste package.
HEAD,C.R. Energy, Dept. of. RW-23. 85/10/08. LINEHAN,J. NRC - No Detailed Affiliation Given. STEIN,R., FIORE,J. Energy, Dept. of. 4pp. 33184:026-33184:029.
- 8510240609 Forwards supporting documentation re numerical modeling of groundwater flow sys at Hanford site,for review & comment.
COLEMAN,N.M. Geotechnical Branch (Post 831001). FIN A-1757. 2486. 85/08/06. KNAPP, MILLER, LINEHAN NRC - No Detailed Affiliation Given. 90pp. 33185:119-33185:208.
- 8510240611 Forwards revised "UMTRAP Environ,Health & Safety Plan" & justification for 10 mCi criterion for controlled areas.Plan specifies federal health & safety stds & DOE requirements.
THEMELIS,J.G. Energy, Dept. of. 85/10/03. HIGGINBOTHAM,L., SOLLENBERG,D. NRC - No Detailed Affiliation Given. 3pp. 33185:049-33185:096.
- 8510240618 UMTA-DOE/AL-150224. Revised "UMTRAP Environ Health & Safety Plan." Justification for 10 mCi criterion for controlled areas encl.
* Energy, Dept. of. 85/08/30. 41pp. 33185:052-33185:096.
- 8510240622 Forwards "UMTRAP Vicinity Properties Monthly Rept for Sept 1985." "Forecasted/Actual Milestone Status Summary Rept" & production graphs also encl.
WILLIAMS,R.L. Jacobs Engineering Group, Inc. 85/10/08. THEMELIS,J.G., SENA,R. Energy, Dept. of. 15pp. 33185:034-33185:048.
- 8510240645 Advises that list of newly acquired ref documents submitted w/Aug 1985 monthly progress rept & GSA abstracts re Gulf Coast sediments satisfactory.
ROSS,F.W. Geotechnical Branch (Post 831001). FIN B-7300. 2456. 85/09/19. WILLIAMS,R.E. Williams & Associates. 1p. 33185:033-33185:033.
- 8510240650 Advises that "Lab Evaluation of DOE Radionuclide Solubility Data & Selected Retardation Parameters,Experimental Strategies Lab Techniques & Procedures," monthly progress rept for Aug 1985,satisfactory.
BRADBURY,J.W. Geotechnical Branch (Post 831001). FIN B-0290. 2450. 85/10/02. WHATLEY,S.K. Oak Ridge National Laboratory. 2pp. 33185:004-33185:005.
- 8510250015 "Preparation of Engineering Analysis for High Level Waste Packages in Geologic Repositories," monthly rept for Sept 1985.
STEPHENS,K.W. Aerospace Corp. FIN A-4165-5. 2484. 85/10/15. CHANG,K.C. NRC - No Detailed Affiliation Given. 21pp. 33226:220-33226:240.
- 8510240273 "Radiologic & Engineering Assessment for Property ED-00179-RS."
* Bendix Field Engineering Corp. 85/09/30. 25pp. 33181:249-33181:273.
- 8510240276 "Radiologic & Engineering Assessment for Property ED-00451-OT."
* Bendix Field Engineering Corp. 85/09/30. 23pp. 33181:274-33181:296.
- 8510240283 "Radiologic & Engineering Assessment for Property ED-00503-RS."
* Bendix Field Engineering Corp. 85/09/30. 26pp. 33181:297-33181:322.
- 8510250294 Submits NNWSI site rept for wk of 850826 & Sept 1985.DOE 850924 rept, "NNWSI Project Weekly Highlights for Wk Ending 850919" encl.
PRESTHOLT,P.T. NRC - No Detailed Affiliation Given. 85/10/01. BROWNING,R.E. Division of Waste Management. 6pp. 33226:154-33226:163.
- 8510250299 "Hydrogeology of Nevada Test Site,Project D," monthly progress rept for Sept 1985.
BUSS,D.R. GeoTrans, Inc. FIN B-7378-4. 2475. 85/10/11. POHLE,J.A. Division of Waste Management. 1p. 33226:154-33226:154.
- 8510250515 Advises of review of radiological & engineering assessment for Vicinity Property GJ-00447-CS in Grand Junction,CO. No concurrence possible due to lack of justification for preferred remedial action.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/27. CREW,M.E. Energy, Dept. of. 2pp. 33228:107-33228:108.
- 8510250524 "QA Mgt in DOE Ofc of Civilian Radwaste Mgt Program."
LANGSTON,M.E. Energy, Dept. of. 85/10/18. 2pp. 33191:354-33191:355.
- 8510250527 Forwards tentative schedules for progress meetings & review/ concurrence steps planned for Tuba City,Mexican Hat & Monument Valley sites.Monthly meeting to review remedial action plans requested.
THEMELIS,J.G. Energy, Dept. of. 85/09/24. HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33191:351-33191:353.
- 8510250535 Forwards notice of upcoming meetings re high level waste mgt program,per 840827 FR notice.Notice will be updated weekly.
BUNTING,J.O. Policy & Program Control Branch (Post 831001). 1581. 85/09/24. Affiliation Not Assigned. 6pp. 33223:350-33223:355.
- 8510250537 Forwards notice of upcoming meetings re high level waste mgt program,per 840827 FR notice.Notice will be updated weekly.
BUNTING,J.O. Policy & Program Control Branch (Post 831001). 1580. 85/09/30. Affiliation Not Assigned. 5pp. 33223:343-33223:349.
- 8510250556 Agenda for Nuclear Waste Board 851018 meeting in Lacey,WA to discuss status of low level compact process & public involvement rept.
* Washington, State of. 1577. 85/10/18. Washington, State of. 35pp. 33225:023-33225:057.
- 8510250590 "Lab Evaluation of DOE Radionuclide Solubility Data & Selected Retardation Parameters,Experimental Strategies,Lab Techniques & Procedures," progress rept for Sept 1985.
JACOBS,G.K. Oak Ridge National Laboratory. FIN B-0290. 2471. 85/10/07. BRADBURY,J.W. Geotechnical Branch (Post 831001). 11pp. 33191:204-33191:214.
- 8510250596 Presents comments on June 1985 monthly repts for FINs A-1158,A-1757 & A-1166.Work performed during June satisfactory.
COLEMAN,N.M. Geotechnical Branch (Post 831001). FIN A-1158. 2488. 85/07/30. CRANWELL,R.M. Sandia National Laboratories. 9pp. 33191:215-33191:223.
- 8510280021 Forwards Cooperative Agreement DE-FC04-85AL20533 between DOE & State of NM re use of inactive U mill tailings site as processing site.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/03. HOYAL,J.G. Energy, Dept. of. 80pp. 33241:252-33241:331.
- 8510280023 Forwards,for review,revised "UMTRAP - Shiprock,Remedial Action Insp Plan," to be released as final document if no response received by 851015.
THEMELIS,J.G. Energy, Dept. of. 85/10/02. HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33241:209-33241:251.
- 8510280025 "UMTRAP - Shiprock,Remedial Action Insp Plan."
* Morrison-Knudsen Engineers, Inc. 85/10/02. 42pp. 33241:211-33241:251.
- 8510280050 Forwards TAC comments & radiological assessment coordinator resolutions for Durango Site DU-023 radiological & engineering assessment (REA) Encl & initial issuance of REA constitute final approved REA.
PEPIN,J. Morrison-Knudsen Engineers, Inc. 85/10/16. SENA,R. Energy, Dept. of. 3pp. 33241:200-33241:202.
- 8510280056 Notices of listed upcoming federal agency meetings,per 830719-20 meetings,Notice will be updated weekly.Host organizations should be contacted re details & attendance.
NEFF,J.O. Energy, Dept. of. 1183. 85/10/09. LINEHAN,J. NRC - No Detailed Affiliation Given. SPURGIN,P. Utah, State of. FRISHMAN,S. Texas, State of. 3pp. 33241:197-33241:199.
- 8510280063 Trip rept of 850723 & 25 visits to Ft Collins & Denver,CO & Salt Lake City,UT re Colorado State Univ flume studies & erosion protection.
GILLEN,D.M. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/06. MARTIN,D.E. Low-Level Waste & Uranium Recovery Projects Branch. 7pp. 33241:130-33241:136.
- 8510280064 Trip rept of 850619-21 visit to Beatty,NV & site tour of low level waste disposal facility re draft closure plan. Three-phased approach for closure plan suggested by NRC.
STARMER,R.J., SHAFFNER,J.A. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/01. HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 5pp. 33241:125-33241:129.
- 8510280067 Forwards,for concurrence,Cooperative Agreement DE-FC04-85AL20533 between State of NM & DOE re UMTRAP W/o encl.
HOYAL,J.G. Energy, Dept. of. 85/09/13. HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33241:124-33241:124.
- 8510280072 Reviews & recommends listed changes in proposed mods to const specs for Olive,UT site,per request,Proposed mods acceptable.
JOHNSON,T.L. Geotechnical Branch (Post 831001). 85/09/23. GILLEN,D. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33241:122-33241:123.
- 8510280078 Confirms that BWIP exploratory shaft meeting dates changed from 851105-06 to 851203-04 & that listed info re subj meeting sent under separate cover.
OLSEN,O.L. Energy, Dept. of. 1576. 85/10/10. BUCKLEY,J. NRC - No Detailed Affiliation Given. 2pp. 33241:117-33241:118.
- 8510280082 Forwards NRC input for 1985 annual status rept to Congress on UMTRAP,per request.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/15. THEMELIS,J.G. Energy, Dept. of. 2pp. 33241:115-33241:116.
- 8510280086 Requests Oct 1984 trip rept re geophysical data used to identify sub-Paradox Basin fault in immediate vicinity of proposed Davis Canyon repository site.
WITTMAN,J. Utah, State of. 85/10/08. KNAPP,M.R. Geotechnical Branch (Post 831001). 1p. 33240:362-33240:362.
- 8510280087 Forwards criteria for preparation of technical evaluation memo re final remedial action plan (RAP).Suggests that T.L. Johnson provide direct input to project.Tentative review schedule for Lakeview RAP also encl.
HIGGINBOTHAM,L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/16. SMITH,R.D. Uranium Recovery Field Office. KNAPP,M.R. Geotechnical Branch (Post 831001). 9pp. 33241:046-33241:054.
- 8510280092 Forwards state/tribe monthly status rept for Aug 1985. Next project coordination meeting will be held in Salt Lake City,UT on 851015-17.Draft agenda also encl.
THEMELIS,J.G. Energy, Dept. of. 85/10/01. MARTIN,D. Uranium Recovery Licensing Branch. 6pp. 33240:353-33240:358.

342 NONDOCKETED ITEMS

- 8510280095** Requests add info to assist in requested review of adequacy of erosion protection design at Shiprock, NM site. Insufficient info provided to substantiate DOE claim of excessive cost. Comments & questions encl. KNAPP, M.R. Geotechnical Branch (Post 831001). TAC L04742. 85/10/07. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33240:345-33240:346.
- 8510280102** Forwards list of WTWI repts placed on open-file & submitted to DOE during Sept 1985. List consists of Topical Rept OF-WTWI-1985-13, "Erosion Rates & Processes in Subhumid & Semiarid Climates, Texas Panhandle..." CONDON, C. Texas, Univ. of, Austin, TX. 1182. 85/10/10. FOSS, F. Division of Waste Management. 2pp. 33228:340-33228:341.
- 8510280108** Forwards lists of publications resulting from BNL salt repository project & BNL repts currently under review per 850711 request. Draft rept on salt radiator damage sent under separate cover. NEFF, J.O. Energy, Dept. of. 1181. 85/10/10. LINEHAN, J.J. Repository Projects Branch (Post 831001). 5pp. 33228:333-33228:337.
- 8510280110** Mod A009 to cooperative agreement between DOE & State of UT, increasing DOE obligation of funds for FY86. HOYAL, J.G. Energy, Dept. of. MAXELL, M.H. Utah, State of. 3866R. 85/10/17. 4pp. 33228:329-33228:332.
- 8510280122** Informs of completion of review of 850709 UMTRAP environ. health & safety plan. Minor comments discussed & resolved on 850722 between J. Arthur & U. Sollenberger. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/07/24. THEMELIS, J.G. Energy, Dept. of. 1p. 33228:325-33228:325.
- 8510280127** Forwards rept of NRC review of const work at Salt Lake City Project D. Given conducted review on 850725. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/09. THEMELIS, J.G. Energy, Dept. of. 5pp. 33228:320-33228:324.
- 8510280132** Discusses review of DOE response to NRC condition of concurrence re groundwater contamination at Shiprock site, in response to Technical Assistance Request 85840. DOE should submit map showing location of monitoring wells. KNAPP, M.R. Geotechnical Branch (Post 831001). 85/10/11. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33228:318-33228:319.
- 8510280146** Forwards comments on UMTRAP vicinity property certification plan. Comments include info re purpose, responsibilities, remedial action, certification decision, notification & documentation & constraints. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/23. THEMELIS, J.G. Energy, Dept. of. 4pp. 33228:314-33228:317.
- 8510280152** Forwards results of technical review of 850710 proposed mods to remedial action plan for Salt Lake City Project. Review will be completed upon receipt of addl info pertinent to mods. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/07. THEMELIS, J.G. Energy, Dept. of. 5pp. 33228:306-33228:311.
- 8510280153** Forwards onsite const rept of Shiprock UMTRAP review performed on 851001. Rept encompasses entrance interview, site tour, testing observations, record review, resolution of outstanding issues & exit interview. GILLEN, D.M. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/10. MARTIN, D.E. Low-Level Waste & Uranium Recovery Projects Branch. 4pp. 33228:302-33228:305.
- 8510280156** Forwards summary of 850702 meeting w/DOE in Silver Spring, MD re establishment of technical discussion groups to work toward resolution of generic UMTRAP issues. Individual discussion group summaries also encl. GILLEN, D.M. Low-Level Waste & Uranium Recovery Projects Branch. 85/07/17. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 6pp. 33228:291-33228:301.
- 8510280157** Forwards memo to RD Smith detailing changes made to UMTRAP responsibilities to U Recovery Field Ofc. Ofc now responsible for site-specific casework actions while NMSS remains responsible for general program mgt & generic matters. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/10. THEMELIS, J.G. Energy, Dept. of. 2pp. 33228:289-33228:290.
- 8510280159** Forwards comments & questions re surface water hydrology & erosion protection per request to review revised remedial action plan for Lakeview site. Erosion protection design may not meet EPA 40CFR192 requirements. KNAPP, M.R. Geotechnical Branch (Post 831001). 85/10/11. SMITH, R.D. Uranium Recovery Field Office. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 4pp. 33228:285-33228:288.
- 8510280172** Provides objective for open item discussed during last quarterly meeting re interactions w/communities & local govts. Internal instructions to Ofc of Civilian Radiowaste Mgt encl. GALE, R.W. PURCELL, W.J. Energy, Dept. of. RW-42. 85/10/08. Energy, Dept. of. 1p. 33228:263-33228:264.
- 8510280178** "Internal Guidelines for Interactions W/Communities & Local Govts." * Energy, Dept. of. 85/09/20. 21pp. 33228:264-33228:284.
- 8510280226** Telcon w/D Leichel on 851009 re inquiry about DOE project surveillance & maint plan. SMYKOWSKI, S. Engineering Branch (Post 831001). 85/10/09. 1p. 33196:362-33196:362.
- 8510280227** Forwards comments on State of UT draft remedial action insp plan for Salt Lake City project. Per 850820 meeting, NRC technical position on testing & insp that provides basis for review also encl. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/18. THEMELIS, J.G. Energy, Dept. of. 5pp. 33228:221-33228:234.
- 8510280231** "Staff Technical Position on Testing & Insp Plans During Const of DOE Remedial Action at inactive U Mill Tailing Sites." * Low-Level Waste & Uranium Recovery Projects Branch. 85/09/30. 9pp. 33228:226-33228:234.
- 8510280277** Forwards notice of upcoming meetings re high level waste mgt program per 840827 FRI notice. Notice lists tentative & firmly established meetings between NRC & DOE & will be updated weekly. BUNTING, J.O. Policy & Program Control Branch (Post 831001). 1579. 85/10/07. Affiliation Not Assigned. 5pp. 33228:207-33228:211.
- 8510280430** Summarizes 850806 meeting w/Jacobs Engineering Group, Inc., DOD & Morrison-Knudsen Engineers, Inc. in San Francisco, CA re DOE UMTRAP design procedures manual & NRC Site Repository Project on geotechnical stability. JAGANNATH, B.N., BLACKFORD, M., VALDES, J. Engineering Branch (Post 831001). 85/09/06. GREEVES, J.T. Engineering Branch (Post 831001). KNAPP, M.R. Geotechnical Branch (Post 831001). 7pp. 33196:324-33196:330.
- 8510280432** Submits review of radon barrier design for Shiprock UMTRAP site. Values of diffusion coefficient D nonconservative & do not assure cover design will attenuate radon to EPA stds. Meeting requested. SMYKOWSKI, S. Engineering Branch (Post 831001). 85/07/25. GILLEN, D.M. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33196:321-33196:321.
- 8510280437** Forwards listing of tentative & planned meetings w/NRC. Steps to aid in scheduling & rescheduling meetings presented. HEAD, C.R. Energy, Dept. of. 85/10/18. LINEHAN, J. NRC - No Detailed Affiliation Given. STEIN, R., FIORE, J. Energy, Dept. of. 5pp. 33196:306-33196:310.
- 8510280442** Forwards DOE/NRC Salt Waste Package Workshop objectives, proposed agenda for SRP/NRC 851029-31 waste package meetings in Silver Spring, MD & listing of repts applicable to workshop. * Energy, Dept. of. 1180. 85/10/15. VOGELWEDE, NRC - No Detailed Affiliation Given. 7pp. 33196:296-33196:302.
- 8510280444** Forwards DOE/TAC comments & radiological assessment coordinator resolutions for Salt Lake City Vicinity Properties SL-068/205 & SL-103. PEPIN, J. Morrison-Knudsen Engineers, Inc. 85/10/08. SENAR, Energy, Dept. of. 10pp. 33196:260-33196:269.
- 8510280446** Telcon w/M Matthews on 850926 of confirmation of receipt of Lakeview remedial action plan by U Recovery Field Ofc & Div of Waste Mgt. GUGNOLI, G. NRC - No Detailed Affiliation Given. 85/09/26. 1p. 33196:258-33196:259.
- 8510280488** Forwards DOE/TAC comments & radiological assessment coordinator resolutions for Salt Lake City Property SL-069. Encl & initial issuance of radiological & engineering assessment (REA) constitute final approved REA. PEPIN, J. Morrison-Knudsen Engineers, Inc. 85/10/16. SENAR, Energy, Dept. of. 3pp. 33227:359-33227:361.
- 8510280504** Forwards summary of 850820 meeting w/DOE in Silver Spring, MD re DOE remedial action insp plans for UMTRAP sites & NRC technical position on testing & insp. GILLEN, D.M. Low-Level Waste & Uranium Recovery Projects Branch. 85/08/23. MARTIN, D.E. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33199:359-33199:361.
- 8510280506** Trip rept of attendance at 850806 meeting w/UMTRAP water resources working group in Albuquerque, NM re approach of DOE technical assistance contractor for selecting protective actions for water resources. WEBER, M.F., DAM, W.L. Geotechnical Branch (Post 831001). 85/08/29. KNAPP, M.R. Geotechnical Branch (Post 831001). 8pp. 33227:343-33227:350.
- 8510280508** Provides info re UMTRAP site refs. Available geologic data base minimal for approx 75% of sites researched. Site specific geologic studies needed to meet EPA stds. FRIEDMAN, R.M. Geotechnical Branch (Post 831001). 85/08/16. JUSTUS, P. Geotechnical Branch (Post 831001). 1p. 33199:358-33199:358.
- 8510280511** Informs that, based on results of review, radiological & engineering assessment for Central Valley Water Reclamation Facility adequately addresses NRC 811022 comments on draft & resolves concerns expressed in 850104 lt. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/09/25. THEMELIS, J.G. Energy, Dept. of. 2pp. 33199:356-33199:357.
- 8510290025** Submits progress rept on status of UMTRAP for June-Sept 1985. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/10. BROWNING, R.E. Division of Waste Management. 3pp. 33254:225-33254:227.
- 8510290031** Comments on UMTRAP draft certification plan per Technical Assistance Request TAR-85055. Plan does not specify types of data to be collected & audits to be performed during remedial actions. KNAPP, M.R. Geotechnical Branch (Post 831001). 85/08/22. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 5pp. 33254:226-33254:232.
- 8510290161** Forwards DOE news release re Ambrosia Lake. Release indicates apparent lack of coordination of DOE site characterization programs. KNAPP, M.R. Geotechnical Branch (Post 831001). 85/07/24. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 4pp. 33246:357-33246:360.
- 8510290163** Summary of 850927 meeting w/DOE re cost escalation of UMTRAP & potential cost reduction techniques. HAINFIELD, M. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/03. MARTIN, D. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33245:359-33245:361.
- 8510290167** Forwards final WM-8XXX "Draft Staff Technical Position on Testing & Insp Plans During Const of DOE Remedial Action at inactive U Mill Tailing Site." GREEVES, J.T. Engineering Branch (Post 831001). 85/06/26. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254:212-33254:221.
- 8510290171** "Draft Staff Technical Position on Testing & Insp Plans During Const of DOE Remedial Action at inactive U Mill Tailing Site." * Low-Level Waste & Uranium Recovery Projects Branch. 85/06/30. 9pp. 33254:213-33254:221.
- 8510290176** Discusses review of DOE radon barrier design calculations for Shiprock UMTRAP site. Values of all input parameters for RAECOM model acceptable w/exception of value selected for diffusion coefficient (D) of radon barrier matl. GREEVES, J.T. Engineering Branch (Post 831001). 85/08/09. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33245:357-33245:358.

8510290200 Forwards NP Kirner 851003 ltr commenting on Chem-Nuclear Sys, Inc topical rept "Fiberglass Reinforced Plastic High Integrity Containers." NUSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. GREEVES, J. Engineering Branch (Post 831001). HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254-222-33254-223.

-8510290207 Comments on Chem-Nuclear Sys, Inc CNSI-FRP-14571-01-NP. "Fiberglass Reinforced Plastic High Integrity Containers." Need for vents on packages questioned. Clarification as to whether passive vent sys will be required requested. KIRNER, N.P. Washington, State of. 85/10/03. NUSBAUMER, D.A. Assistant Director for State Agreements Programs. 1p. 33254-223-33254-223.

8510290266 Comments on UMTRAP draft certification plan for processing sites. Wording in plan should be replaced by specific detailed info to avoid miscommunication between NRC & DOE, per 850726 Technical Assistance Request 85054. GREEVES, J.T. Engineering Branch (Post 831001). 85/08/23. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 2pp. 33254-233-33254-234.

8510290271 Forwards comments on UMTRAP surveillance & maint plan. HAWKINS, E.F. Uranium Recovery Field Office. 85/10/16. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 3pp. 33254-235-33254-237.

8510290279 Forwards NP Kirner 851003 ltr commenting on Chichibu Cement Co topical rept "High Integrity Container for Disposal of Low Level Radwastes." NUSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. GREEVES, J. Engineering Branch (Post 831001). HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 33254-236-33254-242.

-8510290291 Comments on Chichibu Cement Co topical rept "High Integrity Container (HIC) for Disposal of Low Level Radwastes." per NRC 850506 request. Lack of test results addressing guidance on HIC provided in branch technical position questioned. KIRNER, N.P. Washington, State of. 85/10/03. NUSBAUMER, D.A. Assistant Director for State Agreements Programs. 4pp. 33254-239-33254-242.

8510290421 Summary of Erosion Protection Workgroup 850724 meeting in Denver, CO re resolution of generic UMTRAP issues concerning flooding & erosion protection. JOHNSON, T.L. Geotechnical Branch (Post 831001). 85/08/06. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 4pp. 33254-282-33254-285.

8510290424 Forwards State of WA 851003 ltr to R Haefsig of Nuclear Packaging, Inc. extending interim approval of certain Envrallco high integrity containers to 851231. NUSBAUMER, D.A. Assistant Director for State Agreements Programs. 85/10/17. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. GREEVES, J. Engineering Branch (Post 831001). 4pp. 33254-286-33254-289.

8510300236 Trip rept of 850917-18 visit to Canonsburg, PA for dry run certification review of completion of remedial action at UMTRAP site. List of attendees encl. GUNGNOL, G.N. Low-Level Waste & Uranium Recovery Projects Branch. 85/10/04. HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch. 14pp. 33261-296-33261-309.

WASTE RES WASTE MANAGEMENT RESEARCH REPORTS

8510020036 Summarizes 850805-08 meetings in Austin, TX re Permian Basin core exam. Repository in San Andres formation in very imp. re salt probable. In situ full-scale testing will provide reasonable assurance re performance at site. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2409. 85/08/12. PEARRING, J.R. Engineering Branch (Post 831001). 3pp. 32829-304-32829-305.

8510020041 Submits draft review of exploratory shaft performance analysis study. Performance of review by team including geologist, hydrologist, canister corrosion engineer &/or radionuclide release & travel specialist suggested. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2408. 85/08/13. GUPTA, D. Engineering Branch (Post 831001). 12pp. 32829-286-32829-297.

8510040487 Comments on Nevada Nuclear Waste Storage Investigations exploratory shaft conceptual design rept. Claim made in cover ltr re const of exploratory shafts not impacting radiological health & safety of public unacceptable. DAEMEN, J. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2367. 85/08/29. GUPTA, D. Engineering Branch (Post 831001). 8pp. 32859-308-32859-314.

8510080570 Draft "Preliminary Data & Rept on Timing & Style Deformation Since Miocene Epoch in Yakima Fold Belt." CHUNG, D.H. Lawrence Livermore National Laboratory. FIN A-0294. 55-85-009. 85/09/26. BLACKFORD, M.E. Geotechnical Branch (Post 831001). 75pp. 32923-351-32924-063.

8510080608 Forwards monthly mgt rept for Aug 1985 for FINS A-3164. "Review of DOE Waste Package Program" & A-3167, "Waste Package Verification Tests." Projections of costs by task encl for FY85. KATO, W.Y. Brookhaven National Laboratory. FIN A-3167. 2446. 85/09/24. WICK, E.A. High Level Waste Licensing Management Branch. 2pp. 32923-161-32923-183.

-8510080612 "Review of DOE Waste Package Program," monthly mgt rept for Aug 1985. SOO, P. Brookhaven National Laboratory. FIN A-3164. 85/08/31. 14pp. 32923-163-32923-177.

-8510080617 "Review of Waste Package Verification Tests," monthly mgt rept for Aug 1985. SOO, P. Brookhaven National Laboratory. FIN A-3167. 85/08/31. 8pp. 32923-178-32923-183.

8510090021 "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project C," monthly progress rept for Aug 1985. WILLIAMS, R.E. Williams & Associates. FIN B-7377-2. 2432. 85/09/13. POHLE, J. Division of Waste Management. 3pp. 32964-054-32964-057.

8510090040 Forwards draft "NRC Point Paper on Exploratory Shaft Const & Testing (ES-I) BWIP Hanford Site, WA." MUKHERJEE, A. Engineers International, Inc. FIN D-1004. 2441. 85/09/27. BUCKLEY, J. Division of Waste Management. 1p. 32964-022-32964-052.

-8510090046 Draft "NRC Point Paper on Exploratory Shaft Const & Testing (ES-I) BWIP Hanford Site, WA." Engineers International, Inc. 11085R. 85/09/30. 30pp. 32964-023-32964-052.

8510090056 "Benchmarking of Computer Codes & Licensing Assistance," monthly ltr progress rept for Aug 1985. VOGT, D.K. CorSTAR Research, Inc. FIN B-6985. 2438. 85/09/18. BROOKS, P. Division of Waste Management. 5pp. 32964-011-32964-015.

8510090224 Monthly ltr rept for 850816-0915 for FIN D-1014. BLAND, W.M. Management & Technical Consulting. FIN D-1014. 2445. 85/09/16. DELLIGATI, M.S. Policy & Program Control Branch (Post 831001). 2pp. 32949-197-32949-198.

8510090233 Submits trip rept on NRC/DOE 850827-28 workshop on Nevada Nuclear Waste Storage Investigation in Silver Spring, MD re exploratory shaft facility design & const. KIM, Y.C. Arizona, Univ. of, Tucson, AZ. FIN B-7328. 2433. 85/09/05. BHATTACHARYA, S. Engineers International, Inc. 1p. 32949-196-32949-196.

8510090260 Forwards final draft "Statistical Evaluation of Addl Hydrochemical Data From Saddle Mountains, Wanapum & Grande Ronde Basalts, BWIP Hanford Site." WINTER, G.V. Williams & Associates. FIN B-7372-3. 2447. 85/09/30. GORDON, M. Division of Waste Management. 1p. 32948-088-32948-194.

-8510090268 Final draft "Statistical Evaluation of Addl Hydrochemical Data From Saddle Mountains, Wanapum & Grande Ronde Basalts, BWIP Hanford Site." Williams & Associates. FIN B-7372-3. NRC-02-82-044. 85/08/23. Division of Waste Management. 106pp. 32948-090-32948-194.

8510090272 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Geologic Repositories," monthly rept for Aug 1985. CRANWELL, R.M. Sandia National Laboratories. FIN A-1755. 2440. 85/09/13. NATARAJA, M.S. Engineering Branch (Post 831001). 19pp. 32948-201-32948-219.

8510090274 Thirty-eighth monthly progress rept under Contract NRC-02-82-044 for Aug 1985. WILLIAMS, R.E. Williams & Associates. FIN B-7372-3. 2439. 85/09/09. GORDAN, M. Division of Waste Management. 9pp. 32950-180-32950-188.

8510090311 "Technical Assistance for Design Reviews of High Level Waste Geologic Repositories," monthly progress rept for Aug 1985. MARKHAM, J.J. ITASCA Consulting Group, Inc. FIN D-1016. 2430. 85/09/18. TIKTINSKY, D. Division of Waste Management. 4pp. 32950-100-32950-103.

8510090314 Forwards water level graphs including mean monthly water levels at cluster Piezometers DC-19, 20 & 22 for Priest Rapids, Sentinel Gap, Ginkgo, Rocky Coulee, Cohasset & Umtanum flows for Jan & Feb 1985. WINTER, G. Williams & Associates. FIN B-7372-3. 2431. 85/09/20. GORDON, M. Division of Waste Management. 17pp. 32950-082-32950-098.

8510090345 "Preparation of Engineering Analysis for High Level Waste Packages in Geologic Repositories," monthly progress rept for Aug 1985. STEPHENS, K.W. Aerospace Corp. FIN A-4165-5. 2442. 85/09/13. CHANG, K.C. NRC - No Detailed Affiliation Given. 24pp. 32949-135-32949-158.

8510090347 Forwards document reviews of "Experimental Characterization & Stability of Salt & Non-Salt Containing Grouts & Mortars" & "Task V. Engineering Study 9. Underground Repository Layout," for review. RAJARAM, V. Engineers International, Inc. FIN B-7328. 2443. 85/09/20. TIKTINSKY, D. High Level Waste Technical Development Branch. 18pp. 32949-117-32949-134.

8510090368 "Technical Assistance in Seismo-Tectonic Impacts in Repositories," Monthly Mgt Ltr Rept 29 for Aug 1985. CHUNG, D.H. CUMMINGS, G.E. Lawrence Livermore National Laboratory. FIN A-0294. 1-196. 85/09/15. BLACKFORD, M.E. Geotechnical Branch (Post 831001). 2pp. 32965-062-32965-063.

8510090390 Forwards trip rept of 850926-28 meetings in Silver Spring, MD re preparation for NRC/DOE 850927-28 meetings on exploratory shaft design & const. List of attendees for 850928 meeting encl. RAJARAM, V. Engineers International, Inc. FIN B-7328. 2434. 85/09/13. TIKTINSKY, D. Division of Waste Management. 10pp. 32965-048-32965-057.

8510090400 Forwards trip rept of 850805-08 meetings in Austin, TX re review status of geological & geomechanical investigations of Palo Duro Basin & core exam. List of attendees encl. RAJARAM, V. Engineers International, Inc. FIN B-7328. 2435. 85/09/17. TIKTINSKY, D. Division of Waste Management. 6pp. 32964-339-32964-344.

8510090445 Forwards revised program review for 851016-17 meetings in Silver Spring, MD re FIN B-0287, "Technical Assistance in Biochemistry" & FIN B-0290, "Lab Evaluation of Retardation Parameters." JACOBS, G.K. Oak Ridge National Laboratory. FIN B-0287. 2429. 85/09/23. BROOKS, D. NRC - No Detailed Affiliation Given. 3pp. 32948-085-32948-087.

8510090490 Task Order 001. "Technical Meetings & Document Reviews on BWIP, NNWSI & Salt Technical & Cost Proposal," under NRC-02-85-002, "Design Reviews of High Level Nuclear Waste Geologic Repositories." MARKHAM, J.J. ITASCA Consulting Group, Inc. FIN D-1016. 2437. 85/09/10. NRC - No Detailed Affiliation Given. 9pp. 32966-145-32966-153.

8510090518 "Technical Assistance for Design Reviews," 37th monthly rept for Aug 1985. RAJARAM, V. Engineers International, Inc. FIN B-7328. 1085-37. 85/09/18. TIKTINSKY, D. Division of Waste Management. 5pp. 32966-336-32966-340.

8510090518 Forwards final camera-ready copy of NUREG/CR-4110, SAND64-2688, "Repository Site Data Rept for Unsaturated Tuff" & responses to NRC comments W/ o NUREG/CR-4110. HUNTER, R.L. Sandia National Laboratories. FIN A-1158. 85/09/23. COLEMAN, N. Geotechnical Branch (Post 831001). 3pp. 32965-194-32965-196.

8510090519 "Executive Summary on Feasibility Study of Applying Geostatics to Repository Site Characterization," W/ 850914 ltr. KIM, Y.C. Arizona, Univ. of, Tucson, AZ. FIN D-1016. 2436. 85/09/14. GREEVES, J. NRC - No Detailed Affiliation Given. 23pp. 32965-170-32965-193.

344 NONDOCKETED ITEMS

- 8510110068** "Site Characterization Info Needs for Salt Repository Design," per Task 3 of Task Order 011.
SINGH,M.M. Engineers International, Inc. FIN B-7328. 1085-011-3. 85/09/19. TIKITSKY,D. NRC - No Detailed Affiliation Given. 33pp. 33011:263-33011:295.
- 8510230265** Reviews "Geochemical Sensitivity Analysis," monthly progress rept for Aug 1985. Progress to date satisfactory. Trip rept of attendance at 850918-20 coupled processes symposium at LBL should be prepared.
KELLY,W.R. Geotechnical Branch (Post 831001). FIN A-1756. 2491. 85/09/30. SIEGEL,M.D. Sandia National Laboratories. 14pp. 33106:331-33106:344.
- 8510230290** Ack receipt of Aug 1985 Monthly Rept 17. Quality of review comments & rept satisfactory.
IGRAHIM,A.K. Geotechnical Branch (Post 831001). FIN D-1003. 2451. 85/10/01. MURPHY,V.J. Weston Geophysical Corp. 1p. 33108:253-33108:253.
- 8510230305** Comments on Aug 1985 monthly rept. Changes to hydrochemical data satisfactory.
GORDON,M. Geotechnical Branch (Post 831001). FIN B-7372. 2453. 85/09/23. WILLIAMS,R.E. Williams & Associates. 1p. 33106:257-33106:257.
- 8510230308** "Repository Site Description & Technology Transfer," monthly rept for Sept 1985.
CRANWELL,R.M. Sandia National Laboratories. FIN A-1158. 2482. 85/10/14. COLEMAN,N.M. Geotechnical Branch (Post 831001). 4pp. 33108:258-33108:261.
- 8510230316** Comments on "Review of DOE Waste Package Program" & "Review of Waste Package Verification Tests," monthly progress repts for June 1985. Progress satisfactory. No changes to cost or delivery of products authorized.
WICK,E.A. Engineering Branch (Post 831001). FIN A-3164. 2490. 85/08/22. SCOP,P. Brookhaven National Laboratory. 1p. 33108:262-33108:262.
- 8510240020** "Geochemical Sensitivity Analysis," monthly rept for Sept 1985.
CRANWELL,R.M. Sandia National Laboratories. FIN A-1756. 2480. 85/10/14. KELLY,W. NRC - No Detailed Affiliation Given. 8pp. 33163:152-33163:159.
- 8510240027** Comments on "Technical Assistance in Geochemistry," monthly progress rept for Aug 1985. Progress satisfactory. Related repts encl.
BROOKS,D.J. Geotechnical Branch (Post 831001). FIN B-0287. 2460. 85/09/25. WHATLEY,S.K. Oak Ridge National Laboratory. 157pp. 33162:351-33163:151.
- 8510240030** "Technical Assistance in Geochemistry," monthly progress rept for Sept 1985.
JACOBS,G.K. Oak Ridge National Laboratory. FIN B-0287. 2476. 85/10/04. BROOKS,D.J. Geotechnical Branch (Post 831001). 14pp. 33162:337-33162:350.
- 8510240046** Comments on Aerospace Corp monthly rept for Aug 1985 re corrosion modeling. Workers should be encouraged to focus more on how to use mathematical tools to study consequences of realistic waste package failures.
MCNEIL,M.B. Waste Management Branch (Post 840429). FIN A-4165. 2458. 85/10/02. CHANG,K.C. Engineering Branch (Post 831001). 1p. 33162:333-33162:333.
- 8510240084** Trip rept of 850909-11 visit to Sandia to review recent progress in project FIN A-1756, "Geochemical Sensitivity Analysis."
KELLY,W.P. Geotechnical Branch (Post 831001). FIN A-1756. 2449. 85/10/02. JACKSON,K.C. Geotechnical Branch (Post 831001). 2pp. 33176:359-33176:360.
- 8510240111** Monthly Progress Ltr Rept 18 for Sept 1985 re geophysical data.
FANHCN,M.M. Weston Geophysical Corp. FIN D-1003. 2474. 85/10/10. IBRAHIM,A. Geotechnical Branch (Post 831001). 2pp. 33176:361-33176:362.
- 8510240123** Forwards draft Quarterly Rept NUREG/CR-4236, Vol 3, "Evaluation of Radiocesium Geochemical Info Developed by DOE High Level Nuclear Waste Repository Site Projects Rept for Apr-June 1985."
JACOBS,G.K. Oak Ridge National Laboratory. FIN B-0290. 2472. 85/10/07. BRADBURY,J.W. Geotechnical Branch (Post 831001). 27pp. 33176:311-33176:337.
- 8510240128** Comments on Jul 1985 monthly progress rept for FIN B-0287, "Technical Assistance in Geochemistry." Progress to date satisfactory.
BROOKS,D.J. Geotechnical Branch (Post 831001). FIN B-0287. 2489. 85/09/05. WHATLEY,S.K. Oak Ridge National Laboratory. 43pp. 33176:266-33176:310.
- 8510240133** Forwards App D of draft, "Repository Environ Parameters Relevant to Assessing Performance of High Level Waste Packages in Basalt, Tuff & Salt."
WHATLEY,S.K. Oak Ridge National Laboratory. FIN B-0288. 2469. 85/10/07. CHANG,K.C. Engineering Branch (Post 831001). 35pp. 33180:242-33180:276.
- 8510240147** "Effect of Repository Environ on Performance of Waste Package/Engineered Sys Components," monthly progress rept for Sept 1985. App D of draft Rev 1 to NUREG/CR-4134 & revised work plan being sent separately.
WHATLEY,S.K. Oak Ridge National Laboratory. FIN B-0288. 2473. 85/10/07. CHANG,K.C. Engineering Branch (Post 831001). 2pp. 33180:326-33180:327.
- 8510240153** Summary of activities during Sept 1985 for FIN A-1165.
CRANWELL,R.M. Sandia National Laboratories. FIN A-1165. 2479. 85/10/13. ELZEFTAWY,A. Repository Projects Branch (Post 831001). 5pp. 33180:321-33180:325.
- 8510240182** "Technical Assistance in Numerical Modeling Assessment of High Level Waste Repositories," monthly rept for Sept 1985.
CRANWELL,R.M. Sandia National Laboratories. FIN A-1757. 2478. 85/10/13. COLEMAN,N. Geotechnical Branch (Post 831001). 2pp. 33176:355-33176:356.
- 8510240181** Forwards trip rept of 850916-18 visit to State of NV test site & status rept on erosion rates.
CHUNG,D.H. Lawrence Livermore National Laboratory. FIN A-0294. 2470. 85/10/07. BLACKFORD,M.E. Division of Waste Management. 8pp. 33180:313-33180:320.
- 8510240196** Comments on Monthly Mgt Ltr 28 summarizing progress for Jul 1985 under FIN A-0294. Progress to date satisfactory.
BLACKFORD,M.E. Geotechnical Branch (Post 831001). FIN A-0294. 2493. 85/09/04. CHUNG,D. Lawrence Livermore National Laboratory. 1p. 331. 8:358-33176:358.
- 8510240207** Request's listed tasks be initiated under Subtask 1.1. to support analyses of repository site characterization plans to be issued in FY86. Tasks include review of DOE rept on structural analysis of Northern Palo Duro Basin.
BLACKFORD,M.E. Geotechnical Branch (Post 831001). FIN A-0294. 2492. 85/09/26. CHUNG,D. Lawrence Livermore National Laboratory. 2pp. 33182:044-33182:045.
- 8510240268** Thirty-ninth monthly progress rept for Sept 1985 for FIN B-7372.
WILLIAMS,R.E. Williams & Associates. FIN B-7372-3. 2462. 85/10/04. GORDON,M. Division of Waste Management. 5pp. 33182:037-33182:041.
- 8510240296** Forwards trip rept of 850916-19 meetings w/NRC & ITASCA Consulting Group, Inc. in Las Vegas, NV re document review & Yucca Mountain site visit.
BHATTACHARYA,S. Engineers International, Inc. FIN B-7328. 2462. 85/10/02. TIKITSKY,D. Division of Waste Management. 2pp. 33182:146-33182:147.
- 8510240344** "Effect of Repository Environ on Performance of Waste Package/Engineering Sys Components."
WHATLEY,S.K. Oak Ridge National Laboratory. FIN B-0288. 2485. 85/10/11. CHANG,K.C. Engineering Branch (Post 831001). 22pp. 33182:091-33182:112.
- 8510240352** Forwards trip repts of attendance at NNWSI 850916-18 review meeting at Las Vegas, NV & 850918-20 "Int'l Symposium on Coupled Processes Affecting Performance of Nuclear Waste Repository" at Berkeley, CA.
HART,R.D. ITASCA Consulting Group, Inc. FIN D-1016. 2483. 85/10/08. TIKITSKY,D. Division of Waste Management. 23pp. 33182:068-33182:090.
- 8510240362** "Coupled Thermal-Hydrological-Mechanical Assessment & Site Characterization Activities for Geologic Repositories Monthly Rept for Sept 1985."
CRANWELL,R.M. Sandia National Laboratories. FIN A-1755. 2481. 85/10/15. NATARAJA,M.S. Engineering Branch (Post 831001). 20pp. 33182:048-33182:067.
- 8510240367** "Maint of Computer Programs," monthly rept for Sept 1985.
CRANWELL,R.M. Sandia National Laboratories. FIN A-1166. 2477. 85/10/13. COLEMAN,N.M. Geotechnical Branch (Post 831001). 2pp. 33182:046-33182:047.
- 8510240380** Forwards review of SAND-83-0372, "Unit Evaluation at Yucca Mountain, NV Test Site: Summary Rept & Recommendation" & SAND-84-1003, "NNWSI Exploratory Shaft Site & Core Method Recommendation Rept."
HART,R.D. ITASCA Consulting Group, Inc. FIN D-1016. 2461. 85/10/03. TIKITSKY,D. Division of Waste Management. 31pp. 33182:174-33182:204.
- 8510240507** Forwards monthly progress rept for Sept 1985 for FIN A-4167A. Cost & labor estimates for Task 004 also encl. W/o encls.
JOHNSON,R.L. Aerospace Corp. FIN A-4167A. 2458. 85/10/11. BENDER,A. Policy & Program Control Branch (Post 831001). 1p. 33182:148-33182:148.
- 8510240522** Submits trip rept of participation in NRC 850925-27 meetings w/DOE in Silver Spring, MD re performance allocation & geostatistical application to NNWSI site characterization.
KIM,Y.C. Arizona, Univ. of Tucson, AZ. FIN B-7328. 2465. 85/09/30. BHATTACHARYA,S. Engineers International, Inc. 2pp. 33177:350-33177:351.
- 8510240525** Ack receipt of Aug 1985 progress rept for FIN B-0288 & draft Rev 1 to NUREG/CR-4134, "Repository Environ Parameters re Assessing Performance of High Level Waste Packages in Basalt, Tuff & Salt." Comments expected by 851031.
CHANG,K.C. Engineering Branch (Post 831001). FIN B-0288. 2457. 85/09/25. WHATLEY,S.K. Oak Ridge National Laboratory. 2pp. 33177:348-33177:349.
- 8510240541** Requests review of listed documents under Task 2 of Task Order 001 of NRC-02-85-002, "Technical Assistance for Design Reviews of High Level Nuclear Waste Geologic Repositories."
TIKITSKY,D.H. Engineering Branch (Post 831001). FIN D-1016. 2455. 85/08/11. HART,R. ITASCA Consulting Group, Inc. 2pp. 33177:346-33177:347.
- 8510240545** Twenty-second monthly progress rept for Sept 1985.
WINTER,G. Williams & Associates. FIN B-7389-3. 2467. 85/10/14. ROSS,F. Division of Waste Management. 4pp. 33177:342-33177:345.
- 8510240548** Monthly mgt telcon w/J Reuss on 850913 re work performed since interagency agreement (Contract NRC-02-85-004) initiated. Receipt of trip rept for kick-off meeting has completed Task Order 001.
LEE,R.R. NRC - No Detailed Affiliation Given. FIN D-1018. 2454. 85/09/26. 3pp. 33178:006-33178:008.
- 8510240555** Responds to monthly progress rept for Jul 1985. Requests to be advised of problems encountered in running ACINA codes.
BROOKS,D.J. Repository Projects Branch (Post 831001). FIN B-6985. 2452. 85/10/01. VOGT,D.K. CorSTAR Research, Inc. 1p. 33177:352-33177:352.
- 8510240576** Submits list of final std operating procedure elements under Interagency Agreement NRC-02-85-004 per 850809 request for comments. Made include addition of Element 8 re review of project-related expenses.
REUSS,J.L. Interior, Dept. of Bureau of Mines. FIN D-1018. 2463. 85/10/04. LEE,R. Waste Management Branch (Post 840429). 2pp. 33183:334-33183:336.
- 8510240609** Forwards supporting documentation re numerical modeling of groundwater flow sys at Hanford site, for review & comment.
COLEMAN,N.M. Geotechnical Branch (Post 831001). FIN A-1757. 2486. 85/08/08. KNAPP, MILLER, LINEHAN NRC - No Detailed Affiliation Given. 90pp. 33185:119-33185:208.
- 8510240645** Advises that list of newly acquired ref documents submitted w/Aug 1985 monthly progress rept & GSA abstracts re Gulf Coast sediments satisfactory.
ROSS,F.W. Geotechnical Branch (Post 831001). FIN B-7389. 2456. 85/09/19. WILLIAMS,R.E. Williams & Associates. 1p. 33185:033-33185:033.
- 8510240650** Advises that "Lab Evaluation of DOE Radionuclide Solubility Data & Selected Retardation Parameters, Experimental Strategies Lab Techniques & Procedures," monthly progress rept for Aug 1985, satisfactory.
BRADBURY,J.W. Geotechnical Branch (Post 831001). FIN B-0290. 2450. 85/10/02. WHATLEY,S.K. Oak Ridge National Laboratory. 2pp. 33185:004-33185:005.
- 8510250015** "Preparation of Engineering Analysis for High Level Waste Packages in Geologic Repositories," monthly rept for Sept 1985.
STEPHENS,K.W. Aerospace Corp. FIN A-4165-5. 2484. 85/10/15. CHANG,K.C. NRC - No Detailed Affiliation Given. 21pp. 33226:220-33226:240.
- 8510250299** "Hydrogeology of Nevada Test Site, Project D," monthly progress rept for Sept 1985.
BUSS,D.R. GeoTrans, Inc. FIN B-7378-4. 2475. 85/10/11. POHLE,J.A. Division of Waste Management. 1p. 33226:154-33226:154.

8510250590 "Lab Evaluation of DOE Radionuclide Solubility Data & Selected Retardation Parameters, Experimental Strategies, Lab Techniques & Procedures," progress report for Sept 1985.
JACOBS, G.K. Oak Ridge National Laboratory. FIN B-0290. 2471. 85/10/07. BRADBURY, J.W. Geotechnical Branch (Post 831001). 11pp. 33191-204-33191-214.

8510250596 Presents comments on June 1985 monthly reports for FINs A-1158, A-1757 & A-1186. Work performed during June satisfactory.
COLEMAN, M.M. Geotechnical Branch (Post 831001). FIN A-1158. 2488. 85/07/30. CRANWELL, R.M. Sandia National Laboratories. 9pp. 33191-215-33191-223.

EXPORT LIC. EXPORT AND IMPORT LICENSES

8510030113 Forwards Exxon 850920 application for amend to export license, increasing quantity of matl authorized for export to Taiwan. Ltr of assurance requested.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/09/26. BUSICK, E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 1p. 32849-323-32849-323.

-8510030119 Application to amend export license, increasing quantity to 7,160 kg U-235, contained in 173,822 kg total U & 1,938 kg U-235, contained in 50,364 kg total U to Taiwan.
MALODY, C.W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/09/20. ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 1p. 32849-324-32849-324.

8510040060 License for Parkins Int'l, Inc. to export 127,008 kg depleted U, contained in 907,195 kg spent C-21 antimony U catalyst, to France.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/09/25. 1p. 32860-243-32860-243.

8510060573 Amend to export license, increasing quantity of U to 53,753 kg, enriched to 93.3 w/o max, to France.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. TNP-449. 85/10/03. 1p. 32923-230-32923-230.

8510090028 Informs of Executive Branch position re Edlow Int'l Co application for license to export tritium to South Africa. Application should be denied.
DEVINE, J.B. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 85/09/30. SHEA, J.R. Office of International Programs, Director. 2pp. 32964-059-32964-060.

8510090335 Ltr of assurance re export of 164,000 kg U enriched to 2.83% U-235, to France.
DUBOIS, D. European Communities, Commission of. 85/09/23. THORNE, C.E. Energy, Dept. of. 1p. 32950-189-32950-189.

8510090343 Forwards application for amend to export license, increasing quantity of matl authorized for export by addl 11,536 kg U. Ltr of assurance required.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/10/02. THORNE, C.E. Energy, Dept. of. 1p. 32949-159-32949-161.

-8510090344 Application to amend license to export 246,055 kg U to Spain.
HERSCH, M.M. Westinghouse Electric Corp. MMH-706. 85/09/24. PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 1p. 32949-160-32949-161.

8510090456 Grants exemption from full 30-day waiting period to Transnuclear, Inc. in order to meet urgent shipping schedule, per request to amend License XSNM-2143 to increase quantity of U by 53 g.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/10/03. Assistant Director for Export/Import & International Safeguards. 1p. 32966-314-32966-314.

8510090515 Informs that License XSNM-2236 may be issued. No matl changed circumstances since issuance of Licenses XSNM-1212, XSNM-1232, XSNM-1238, XSNM-1241 & XSNM-1814.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/02. Assistant Director for Export/Import & International Safeguards. 1p. 32965-197-32965-197.

8510090523 License for Transnuclear, Inc. to export 4,641.2 kg U-235, contained in 164,000.0 kg U, to France.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. MIS-462. 85/10/02. 2pp. 32965-127-32965-128.

8510150075 Application to amend license to export, increasing quantity to 50.1 kg U-235, contained in 53,753 kg U.
HANNETT, B.A. Transnuclear, Inc. TNP-449. 85/10/03. MOORE, R.N. Office of International Programs, Director. 1p. 33030-352-33030-353.

8510150160 Executive Branch position re Transnuclear, Inc. application to export 9.02 kg U-233, contained in 9.2 kg U & 222.11 g U-233, contained in 223.0 g U, to Canada. Licenses should be issued.
DEVINE, J.B. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 85/10/02. SHEA, J.R. Office of International Programs, Director. 6pp. 33031-102-33031-107.

8510150189 Executive Branch position re Westinghouse application to export 7,500 kg U, enriched to max of 3.4% to France. License should be granted.
DEVINE, J.B. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 85/10/02. SHEA, J.R. Office of International Programs, Director. 3pp. 33031-091-33031-093.

8510150200 Ltr of assurance re export of 13,320 kg total U, containing 435 kg U-235, to Japan.
MALODY, C.W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 85/09/25. ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 1p. 33030-211-33030-211.

8510160103 Responds to FOIA request for four categories of documents re Philippines nuclear power plant. Forwards documents listed on App D.
FELTON, J.M. Division of Rules and Records. 85/10/01. SCHLEMMER, D.L. Government Accountability Project. 2pp. 33035-330-33035-024.

-8510160261 Application for license to export NSSS to Philippines.
RODOLPH, J.P. Westinghouse Electric Corp. TFG/NRC-864. 76/11/18. MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 2pp. 33035-356-33035-357.

-8510160268 Application for license to export matls & equipment to Philippines.
RODOLPH, J.P. Westinghouse Electric Corp. TFG/NRC-864A. 76/11/18. Assistant Director for Export/Import & International Safeguards. 3pp. 33035-358-33035-360.

8510170262 Informs that License XSNM-2228 may be issued. No matl changed circumstances since issuance of License XSNM-1435.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/09. Assistant Director for Export/Import & International Safeguards. 1p. 33045-050-33045-050.

8510170265 License for Marubeni America Corp to export 436 kg U-235, contained in 14,921 kg U, to Japan.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. ZH0389. 85/10/10. 2pp. 33045-048-33045-049.

8510170266 Ltr of assurance re export of 430 kg U-235, contained in 14,121 kg U, to Japan.
OZAWA, M. Japan, Govt. of. 85/10/03. THORNE, C.E. Energy, Dept. of. 1p. 33045-047-33045-047.

8510170269 Ltr of assurance re export of 699 kg U-235, contained in 22,958 kg U, to Japan.
OZAWA, M. Japan, Govt. of. 85/10/03. THORNE, C.E. Energy, Dept. of. 1p. 33045-046-33045-046.

8510170276 Ltr of assurance re export of 116 kg U-235, contained in 3,734 kg U, to Japan.
OZAWA, M. Japan, Govt. of. 85/10/03. THORNE, C.E. Energy, Dept. of. 1p. 33045-038-33045-038.

8510170279 Ltr of assurance re export of 436 kg U-235, contained in 14,921 kg U, to Japan.
OZAWA, M. Japan, Govt. of. 85/10/03. THORNE, C.E. Energy, Dept. of. 1p. 33045-037-33045-037.

8510170283 Ltr of assurance re export of 99 kg U-235, contained in 3,356 kg U, to Japan.
OZAWA, M. Japan, Govt. of. 85/10/03. THORNE, C.E. Energy, Dept. of. 1p. 33045-036-33045-036.

8510170481 Informs that License XSNM-2224 may be issued. No matl changed circumstances since issuance of License XSNM-1435.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/09. Assistant Director for Export/Import & International Safeguards. 1p. 33045-168-33045-168.

8510170482 License for Mitsui & Co (USA), Inc. to export 430 kg U-235, contained in 14,121 kg U enriched to 3.95 w/o max, to Japan.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. MBK-H1-R10 (A). 85/10/10. 2pp. 33045-166-33045-167.

8510170483 Informs that License XSNM-2222 may be issued. No matl changed circumstances since issuance of License XSNM-1435.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/09. Assistant Director for Export/Import & International Safeguards. 1p. 33045-165-33045-165.

8510170484 Informs that License XSNM-2226 may be issued. No matl changed circumstances since issuance of License XSNM-1435.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/09. Assistant Director for Export/Import & International Safeguards. 1p. 33048-158-33048-158.

8510180011 License for Mitsui & Co (USA), Inc. to export 116 kg U-235, contained in 3,734 kg U enriched to 3.95 w/o max, to Japan.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. MBK-H1-R-10 (B). 85/10/10. 2pp. 33075-063-33075-064.

8510180012 License for Marubeni America Corp to export 699 kg U-235, contained in 22,958 kg U enriched to 3.95 w/o max, to Japan.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. ZH038800. 85/10/10. 2pp. 33069-361-33069-362.

8510180131 Informs that License XSNM-2227 may be issued. No matl changed circumstances since issuance of License XSNM-1435.
MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 85/10/09. Assistant Director for Export/Import & International Safeguards. 1p. 33069-275-33069-275.

8510220128 Forwards revised Page 2 to reactor checklist submitted on 850610 for 850507 application.
HANNETT, B.A. Transnuclear, Inc. 85/10/10. MOORE, R.N. Office of International Programs, Director. 2pp. 33098-170-33098-171.

8510220131 Forwards revised Page 2 to reactor checklist for license to export 218,545 kg highly enriched U. Info should be considered in conjunction w/ original 850509 application.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/10/17. BUSICK, E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 3pp. 33098-172-33098-174.

8510220437 Executive Branch position re Edlow Int'l Co application to export 2,500,000 kg U to EURATOM member states. License should be granted. Ltr of assurance encl.
DEVINE, J.B. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 85/10/11. SHEA, J.R. Office of International Programs, Director. 4pp. 33098-353-33098-356.

8510220465 Application to amend license to export, deleting intermediate consignee.
HANNETT, B.A. Transnuclear, Inc. MIS-462. 85/10/16. MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 1p. 33098-100-33098-100.

8510250593 Application to amend license to export, deleting COMURHEX as intermediate consignee.
HANNETT, B.A. Transnuclear, Inc. MIS-462. 85/10/16. MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 1p. 33226-288-33226-289.

346 NONDOCKETED ITEMS

8510250597 Amend 1 to Transnuclear, Inc export license, removing COMURHEX as intermediate consignee & adding B&W.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/10/21. 1p. 33226:289-33226:289.

8510250603 Amend 1 to DISC Corp export license, increasing quantity of proportional fission counters, Model RS-P6-0805-134, from one to two & increasing total value of equipment.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. C-5336. 85/10/21. 1p. 33226:287-33226:287.

8510280005 Amend 1 to Nuclear Metals, Inc export license, extending expiration date from 851201 to 861201.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. I-201-7. 85/10/23. 1p. 33241:340-33241:340.

8510280426 Accepts requested route for transport of spent reactor fuel, per 851004 tr. Route in accordance w/requirements of 10CFR73.37 under License ISNM-79007 & approved through 861231.
McCORKLE, G.W. Reactor & Transportation Licensing Branch. 85/10/23. RAVENSCROFT, N. Edlow International Co. 9pp. 33196:335-33196:343.

8510280498 Ltr of assurance re Amend 6 to License XSNM-0844.
DOMINGUEZ, G. Spain, Govt. of. 689. 85/10/15. THORNE, C.E. Energy, Dept. of. 1p. 33227:351-33227:351.

8510290472 Application to amend license to export, extending expiration date to Dec 1988.
CONVEY, D. Nuclear Materials, Inc. 85/10/15. HEMBY, E. Office of International Programs, Director. 1p. 33259:150-33259:150.

8510290473 Application for license to export 200 Zircaloy tubes to Canada.
HERSCH, M.M. Westinghouse Electric Corp. MMH-717. 85/10/21. 1p. 33254:296-33254:296.

8510310067 Requests Executive Branch position re encl GE amended application to export one Linde 3-channel gas blender to Taiwan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 85/10/24. BUSICK, E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 1p. 33277:282-33277:283.

8510310072 Amended application for license to export one Linde 3-channel gas blender, w/three control rod modules, to Taiwan.
WILSON, B.D. General Electric Co. BDW-85-62. 85/09/01. 1p. 33277:283-33277:283.

8510310081 Forwards application to export 5.598 kg U-235, contained in 6 kg U, to West Germany.
HANNETT, B.A. Transnuclear, Inc. NUK-464. 85/10/22. MOORE, R.N. Office of International Programs, Director. 1p. 33277:291-33277:293.

8510310086 Application for license to export 5.598 kg U-235, contained in 6 kg U, to West Germany.
HANNETT, B.A. Transnuclear, Inc. NUK-464. 85/10/22. 2pp. 33277:292-33277:293.

8510310094 Amend 6 to Westinghouse export license, increasing quantity of authorized material to 7,070 kg U-235, contained in 246,055 kg U, to Spain.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. MMH-706. 85/10/24. 1p. 33277:299-33277:299.

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABRAHAM, P.M.	8510160315*	TOPREP	ALEXICH, M.P.	8510160021	50-316	ANSELMO, A.A.	8510110116	71-5874
ADAMS, A.	8510220383	70-267	ALEXICH, M.P.	8510160041	50-316	ANTAKI, G.A.	8510090216*	50-282 P
ADAMS, C.	8510310089	50-354 F	ALEXICH, M.P.	8510160047	50-316	ANTAKI, G.A.	8510090221*	50-282 P
ADAMS, F.T.	8510170292*	50-316 P	ALEXICH, M.P.	8510160160	50-316	ANTHONY, R.L.	8510020155*	50-352 G
ADENSAM, E.	8510030259	50-416 P	ALEXICH, M.P.	8510210101	50-316	ANTHONY, R.L.	8510110017	50-352 G
ADENSAM, E.	8510040105	50-424 D	ALEXICH, M.P.	8510220236	50-315 F	ANTHONY, R.L.	8510110017	50-352 G
ADENSAM, E.	8510250190	50-413 P	ALEXICH, M.P.	8510220249	50-315 F	ARAGON, J.J.	8510280470	NUREG
ADENSAM, E.G.	8510040096	50-424 D	ALEXICH, M.P.	8510250391	50-315 P	ARCHITZEL, R.E.	8510070359*	50-400 Q
ADENSAM, E.G.	8510040174	50-424 F	ALEXICH, M.P.	8510290139	50-316 P	ARCHITZEL, R.E.	8510150228*	50-250 Q
ADENSAM, E.G.	8510040416	50-395 P	ALEXICH, M.P.	8510300164	50-315 P	ARLOTTI, M.G.	8510090150*	TOPREP
ADENSAM, E.G.	8510040418*	50-395 P	ALEXION, M.P.	8510080520	50-315 F	ASHBURN, D.J.	8510090014	50-344 J
ADENSAM, E.G.	8510070534	50-369 P	ALEXION, T.W.	851010367*	50-483 P	ASMUSSEN, K.E.	8510010632	50-163 P
ADENSAM, E.G.	8510070541*	50-369 P	ALLEMAN, S.A.	8510010301*	50-382 P	ASMUSSEN, K.E.	8510150050	70-734
ADENSAM, E.G.	8510090073	50-416 P	ALLEMAN, S.A.	8510010307*	50-382 P	ASMUSSEN, K.E.	8510210253	70-734
ADENSAM, E.G.	8510090462	50-424 E	ALLEMAN, S.A.	8510010339*	50-382 P	ASSELSTINE	8510160193*	50-206 P
ADENSAM, E.G.	8510150459	50-424 E	ALLEMAN, S.A.	8510010345*	50-382 P	ASSELSTINE, J.K.	8502190411*	50-346 Q
ADENSAM, E.G.	8510180003	50-369 P	ALLEMAN, S.A.	8510010367*	50-382 P	ATEFI, B.	8510020438*	50-245 P
ADENSAM, E.G.	8510180004	50-424 A	ALLEMAN, S.A.	8510010458*	50-382 P	ATKINSON, C.G.	8510020200*	50-354 A
ADENSAM, E.G.	8510180076	50-369 P	ALLOOT, C.S.	8510180392	50-382 G	ATKINSON, W.R.	8510100102	PR
ADENSAM, E.G.	8510250576	50-416 P	ALSWORTH, M.W.	8510100162	PR	ATTERIDGE, D.G.	8510040360	NUREG
ADENSAM, E.G.	8510290425	50-424 F	AMATO, C.G.	8510160051*	50-352 Q	AU, T.Y.	8510240666	50-289 G
ADENSAM, E.G.	8510300112	50-424 A	AMATO, C.G.	8510160231*	50-272 Q	AULUCK, R.	8510170164	50-263 P
ADENSAM, E.G.	8510310509	50-416 P	AMLAUER, K.	8510100097	PR	AULUCK, R.	8510170359	50-263 P
ADENSAM, E.G.	8510310516*	50-416 P	ANDERSON, C.	8510080367*	50-329 T	AUSTIN, G.	8510100101	50-295 R
ADES, M.J.	8510060252*	50-305 P	ANDERSON, C.	8510160037*	50-245 Q	AUSTIN, M.A.	8510090186*	40-1193
AFTERGOOD, S.	8510100102	PR	ANDERSON, C.C.	8510100169	PR	AUSTIN, M.A.	8510090197*	70-135
ANGER, K.A.	8510010111	50-454 P	ANDERSON, C.J.	8510080421*	50-277 Q	AUSTIN, M.A.	8510090205*	70-135
ANGER, K.	8510040301	50-454 P	ANDERSON, C.J.	8510110091*	50-423 Q	AUSTIN, M.A.	8510090217*	70-135
ANGER, K.A.	8510040428	50-454 Q	ANDERSON, C.J.	8510180061*	50-423 Q	AUSTIN, M.A.	8510090225*	70-135
ANGER, K.A.	8510080430	50-454 P	ANDERSON, D.G.	8510080058	50-128 S	AUSTIN, M.A.	8510090277*	70-135
ANGER, K.A.	8510080440	50-455 A	ANDERSON, L.W.	8510080600*	CONTRACT	AUSTIN, M.A.	8510090280*	70-135
ANGER, K.A.	8510160204	50-454 F	ANDERSON, R.C.	8510170079*	50-280 P	AUSTIN, M.A.	8510090282*	70-135
ANGER, K.A.	8510220271	50-455 A	ANDERSON, R.T.	8510240546	71-9204	AUSTIN, M.A.	8510110120	70-364
ANGER, K.A.	8510230056	50-455 Q	ANDERSON, S.L.	8510010161*	50-295 P	AUSTIN, M.A.	8510110233	71-135
AKERS, D.W.	8510040592	50-282 P	ANDERSON, T.V.	8510290374	50-243 R	AUSTIN, M.A.	8510150034	70-364
AKSTULEWICZ, F.	8510070379	50-213 P	ANDERSSON, O.	8510080515*	50-237 P	AUSTIN, M.A.	8510210277	70-364
AKSTULEWICZ, F.	8510110025	50-213 Q	ANDOGNINI, G.C.	8510220178*	50-446 A	AXELRAD, J.	8510030049	50-454 Q
ALBENSI, C.	8510220199*	50-390 F	ANDREWS, R.L.	8510010426	50-285 F	AXELRAD, J.	8510080031	50-317 Q
ALBERT, W.G.	8510170054*	50-361 Q	ANDREWS, R.L.	8510080044	50-285 P	AXELRAD, J.	8510080160	50-373 Q
ALDEN, W.M.	8510020031	50-352 P	ANDREWS, R.L.	8510080147	50-285 P	AXELRAD, J.	8510080210	50-315 Q
ALDEN, W.M.	8510210299	50-277 R	ANDREWS, R.L.	8510100059	50-285 Q	AXELRAD, J.	8510080256	50-312 Q
ALDERSON, C.E.	8510170024*	FOIA	ANDREWS, R.L.	8510160062	50-285 P	AXELRAD, J.	8510100187	I&E
ALEXANDER, D.H.	8510090399	WASTE MGT	ANDREWS, R.L.	8510170226	50-285 F	AXELRAD, J.	8510100193	50-528 Q
ALEXANDER, D.H.	8510240252	WASTE MGT	ANDREWS, R.L.	8510230021	50-285 P	AXELRAD, J.	8510180372	I&E
ALEXANDER, D.H.	8510240383	WASTE MGT	ANDREWS, R.L.	8510230026	50-285 Q	AXELRAD, J.	8510220104	70-143
ALEXANDER, G.	8510150204	50-237 P	ANDREWS, R.L.	8510230099	50-285 F	AXELRAD, J.	8510220189	I&E
ALEXANDER, G.	8510220098	NUREG	ANDREWS, R.L.	8510230313	50-285 R	AXELRAD, J.	8510240001	40-6622
ALEXANDER, G.L.	8510110036	50-10 P	ANDREWS, R.L.	8510240403	50-285 F	AXELRAD, J.	8510240406	50-293 Q
ALEXANDER, S.D.	8510210027*	QA999	ANDREWS, R.L.	8510290208	50-285 F	AXELRAD, J.	8510240413	50-771 Q
ALEXICH, M.P.	8510040108	50-315 F	ANDREWS, R.L.	8510290240	50-285 F	AXELRAD, J.	8510290363	I&E
ALEXICH, M.P.	8510040136	50-315 Q	ANDREWS, W.B.	8510030435	NUREG	AXELRAD, J.A.	8510070572	50-285 Q
ALEXICH, M.P.	8510070062	50-315 F	ANDRUS, N.J.	8510090305	40-4492	AXELRAD, J.A.	8510080157	50-254 Q
ALEXICH, M.P.	8510070082	50-315 F	ANDRUS, N.J.	8510090312	40-4492	AXELRAD, J.A.	8510230129*	FOIA
ALEXICH, M.P.	8510070163	50-316 P	ANKRUM, G.T.	8510030171	TOPREP	AXELRAD, L.R.	8510070250	PR
ALEXICH, M.P.	8510070170*	50-316 P	ANKRUM, G.T.	8510090257*	50-508 Q	AXELSON, W.	8510210010	I&E
ALEXICH, M.P.	8510070189	50-315 P	ANKRUM, G.T.	8510180206	50-220 P	AXELSON, W.L.	8510110254	40-7604
ALEXICH, M.P.	8510070314	50-315 Q	ANNAST, M.V.	8510170027*	FOIA	AXELSON, W.L.	8510160035	50-483 F
ALEXICH, M.P.	8510080292	50-315 P	ANNAST, M.V.	8510170044*	40-8355	AXELSON, W.L.	8510160106	50-373 F
ALEXICH, M.P.	8510160009	50-316 P	ANNAST, M.V.	8510170056*	FOIA	AXELSON, W.L.	8510160168	50-254 Q

348 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AXELSON, W.L.	85102100*3	50-454 Q	BAUER, S.A.	8510300300	50-344 S	BETTENHAUSEN, L.	8510080401*	50-443 Q
AXELSON, W.L.	8510210152	50-346 Q	BAUER, T.L.	8510180155	50-602 F	BETTENHAUSEN, L.	8510160284*	50-289 G
AXELSON, W.L.	8510250202	50-409 F	BAUER, T.L.	8510160286	50-602 F	BETTENHAUSEN, L.	8510250273*	50-293 Q
AXELSON, W.L.	8510250206	50-155 F	BAUM, J.	8510080032*	50-244 Q	BEVARO, D.G.	8510090150*	TOPREP
AXELSON, W.L.	8510250210	50-331 F	BAUM, J.W.	8510040389	NUREG	BEVELACQUA, J.J.	8510150310	50-320 F
AXELSON, W.L.	8510280103	50-440 Q	BAUNACK, W.H.	8510170153*	50-219 Q	BEVELACQUA, J.J.	8510150377	50-320 F
AXELSON, W.L.	8510290099	50-409 Q	BAUNACK, W.H.	8510250171*	50-219 Q	BEVELACQUA, J.J.	8510080173	50-289 F
AXELSON, W.L.	8510310318	50-295 F	BAUSER, D.B.	8510180120	50-289 G	BHATTACHARYA, S.	8510240296	WASTE RES
BACHMANN, R.G.	8510030024	50-445 G	BAUSER, D.B.	8510160120	50-289 G	BIBB, H.E.	8510180429*	50-335 Q
BACHMANN, R.G.	8510100057	50-445 G	BAUSER, D.B.	8510180184	50-289 G	BICEHOUSE, H.	8510210090*	50-354 Q
BACHMANN, R.G.	8510110238	50-445 G	BAUSER, D.B.	8510240673	50-289 G	BICEHOUSE, H.	8510250458*	50-271 Q
BACHMANN, R.G.	8510310200	50-445 G	BAUSER, D.B.	8510180308	50-289 G	BICKFORD, W.E.	8510030435	NUREG
BACI, P.E.	8510010237*	50-329 A	BAUSER, D.B.	8510280516	50-289 G	BIDDLE, R.A.	8510290263*	50-219 P
BAER, R.L.	8510090492	50-410 A	BAUSER, D.B.	8510280516	50-289 G	BIDINGER, G.H.	8510090085*	70-2910
BAER, R.L.	8510030192*	CONTRACT	BAUSER, D.B.	8510310337	50-289 G	BIDINGER, G.H.	8510170012*	70-143
BAILEY, J.A.	8510030044	50-424 F	BAUSER, D.B.	8510310337	50-289 G	BIHL, N.K.	8510040592	50-282 P
BAILEY, J.A.	8510030044	50-424 F	BAKTER, T.A.	8510180308	50-400 G	BIRELY, W.C.	8510010215	50-277 S
BAILEY, J.A.	8510030089	50-424 F	BAKTER, T.A.	8510180308	50-400 G	BIRELY, W.C.	8510010629*	50-277 S
BAILEY, J.A.	8510070302	50-424 E	BAKTER, T.A.	8510240671	50-400 G	BIRELY, W.C.	8510010633*	50-277 S
BAILEY, J.A.	8510070302	50-424 E	BAKTER, T.A.	8510240671	50-400 G	BIRELY, W.C.	8510010742	50-277 S
BAILEY, J.A.	8510080214	50-424 A	BAKTER, T.A.	8510290033	50-400 T	BIRELY, W.C.	8510040076	50-278 S
BAILEY, J.A.	8510080503	50-424 A	BAKTER, T.A.	8510290033	50-400 T	BIRELY, W.C.	8510040087	50-277 S
BAILEY, J.A.	8510090066	50-424 E	BAZIN, J.P.	8510030327	CONTRACT	BIRELY, W.C.	8510070542	50-278 S
BAILEY, J.A.	8510180228	50-424 F	BAZZANI, C.S.	8510010240*	CONTRACT	BIRELY, W.C.	8510150250	50-277 S
BAILEY, J.A.	8510290368	50-424 F	BEACH, B.	8510080160	50-373 Q	BIRELY, W.C.	8510170416	50-277 S
BAILEY, J.A.	8510300191	50-424 A	BEAHM, D.M.	8510040100*	50-261 P	BIRELY, W.C.	8510300242	50-277 S
BAILEY, J.A.	8510300191	50-424 A	BEALS, S.	8510030131	NUREG	BIRELY, W.C.	8510300253	50-277 S
BAILEY, M.W.	8510090450	50-304 S	BEALL, J.E.	8510080080*	50-277 Q	BISSETT, P.	8510080421*	50-277 Q
BAIRD, J.B.	8510250445*	50-354 Q	BEALL, J.E.*	8510230195*	50-352 Q	BISSETT, P.	8510230208*	50-352 Q
BAIRD, J.B.	8510220458*	50-445 Q	BEARE, A.N.	8510040318	NUREG	BISSETT, P.	8510250445*	50-354 Q
BAIRD, J.B.	8510310106*	50-458 Q	BEARSE, R.C.	8510280192	50-148 P	BISSETT, P.H.	8510180037*	50-245 Q
BAISOEN, L.	8510040349	CONTRACT	BEAVER, J.R.	8510150310	50-320 F	BLACK, S.	8510150021	50-10 P
BAISOEN, L.	8510080365	CONTRACT	BECHHOEFER, C.	8510100023	50-498 G	BLACKFORD, M.	8510280430	WASTE MGT
BAISOEN, L.	8510150477	CONTRACT	BECHHOEFER, C.	8510180374	50-498 G	BLACKFORD, M.E.	8510240196	WASTE RES
BAK, W.R.	8510290174*	50-344 P	BECHHOEFER, C.	8510210107	50-498 G	BLACKFORD, M.E.	8510240207	WASTE RES
BAKER, E.T.	8510150015*	50-344 Q	BECHHOEFER, C.	8510310286	50-498 G	BLACKMAN, H.S.	8510040397	NUREG
BAKER, K.R.	8510240219	50-316 S	BECHTEL, D.A.	8510100146	PR	BLAISDELL, J.	8510160315*	TOPREP
BALL, D.G.	8510040371	NUREG	BECKHAM, J.T.	8510250250	50-321 F	BLAISDELL, J.	8510160315*	TOPREP
BALL, D.G.	8510040402	NUREG	BEE, R.W.	8510040578	NUREG	BLAISDELL, J.A.	8510160314	TOPREP
BALL, J.R.	8510280145*	50-528 Q	BEGAN, E.T.	8510240290*	WASTE MGT	BLAISDELL, J.A.	8510160314	TOPREP
BANDHAUER, W.K.	8510010640	50-302 S	BELANGER, J.L.	8510170263*	50-264 Q	BLAKE, J.J.	8510040160*	50-390 Q
BANDHAUER, W.K.	8510020193	50-302 S	BELANGER, J.L.	8510210051*	50-454 Q	BLAKE, J.J.	8510040531*	50-424 Q
BANDY, T.R.	8510040294	PR	BELANGER, J.L.	8510280113*	50-440 Q	BLAKE, J.J.	8510070042*	50-259 Q
BANFIELD, E.L.	8510100078	PR	BELISLE, G.A.	8510030284*	50-424 Q	BLAKE, J.J.	8510070383*	50-424 Q
BANGART, R.L.	8510010354*	50-382 Q	BELISLE, G.A.	8510070513*	50-268 Q	BLAKE, J.J.	8510070463*	50-324 Q
BANKS, H.R.	8510290035*	50-400 T	BELISLE, G.A.	8510080363*	50-302 Q	BLAKE, J.J.	8510070500*	50-269 Q
BANKS, H.R.	8510020041*	50-400 T	BELL, N.	8510180465	50-483 P	BLAKE, J.J.	8510080548*	50-413 Q
BARFELZ, M.E.	8510090246	50-315 S	BELLAMY, R.R.	8510230158	50-317 Q	BLAKE, J.J.	8510180103*	50-335 Q
BARKHURST, R.P.	8510020219	50-382 F	BELLS, S.R.	8510160171*	50-461 F	BLAKE, J.J.	8510220112*	50-261 Q
BARKHURST, R.P.	8510170010	50-382 P	BELMONTE, G.	8510020209	50-293 S	BLAKE, J.J.	8510220418*	50-321 Q
BARNES, B.L.	8510220252*	50-382 P	BELMONTE, G.	8510070029	50-293 S	BLAND, W.M.	8510090224	WASTE RES
BARNES, C.	8510010044	40-8006	BELMONT, C.I.	8510070283*	50-219 R	BLAZEK, M.L.	8510290383	PR
BARNES, C.	8510150134	FOIA	BENNETT, C.J.	8510080506	50-10 F	BLESS, A.	8510180522	50-295 S
BARNES, J.	8510280229*	50-445 Q	BENNETT, C.J.	8510210073*	50-10 F	BUND, A.A.	8510010120*	50-316 S
BARNES, J.	8510280241*	50-445 Q	BENNETT, D.D.	8510070185*	50-206 F	BUND, A.A.	8510010129*	50-316 S
BARNES, J.	8510280254*	50-445 Q	BENNETT, J.G.	8510020202*	50-382 P	BUND, A.A.	8510070549*	50-315 S
BARNES, M.D.	8510010085*	FOIA	BENNETT, R.L.	8510150039*	71-230 P	BUND, A.A.	8510070552*	50-315 S
BARNES, M.D.	8510010093*	FOIA	BENNETT, W.R.	8510040415*	50-458 Q	BUND, A.A.	8510090179*	50-315 S
BARNES, M.D.	8510010172*	50-323 P	BENNETT, W.R.	8510240112*	50-458 Q	BUND, A.A.	8510090184*	50-315 S
BARNES, M.D.	8510010203*	FOIA	BENNETT, W.R.	8510240152*	50-458 Q	BUND, A.A.	8510090378*	50-315 S
BARNES, M.D.	8510010418*	FOIA	BENNETT, W.R.	8510250462*	50-458 Q	BLIND, A.A.	8510170022	50-315 S
BARR, K.P.	8510080225	70-1113	BENNINGTON, G.M.	8510170468	70-2930 S	BLIND, A.A.	8510170025	50-316 S
BARR, K.P.	8510150331	70-143	BERATAN, L.L.	8510080521	REGGD	BLIND, A.A.	8510170042*	50-316 S
BARR, K.P.	8510180065	70-143	BERATAN, L.L.	8510180483	ORG	BLIND, A.A.	8510170045*	50-316 S
BARR, K.P.	8510180072	70-143	BERCZYNSKI, S.	8510240057	50-295 S	BLIND, A.A.	8510170049	50-315 S
BARRETT, R.	8510020257	50-423 A	BERG, V.	8510020110	50-382 E	BLIND, A.A.	8510170448	50-316 S
BARROW, J.H.	8510180090*	50-335 P	BERLIN, R.E.	8510170383	50-199 R	BLIND, A.A.	8510240183	50-315 S
BARROW, J.H.	8510180096*	50-335 P	BERNABELL, J.	8510010244*	FOIA	BLIND, A.A.	8510280405	50-315 S
BARRU, H.	8510010205	FOIA	BERNABELL, J.	8510010266	50-382 A	BLOCH, P.B.	8510040358	50-445 G
BARTH, C.A.	8510040302	50-400 T	BERNABELL, J.	8510030127	50-382 E	BLOCH, P.B.	8510040449	50-445 G
BARTHOLOMEW, G.	8510090227*	50-282 P	BERNARD, H.	8510180221	TOPREP	BLOCH, P.B.	8510310316	50-445 G
BARTLETT, B.L.	8510010082*	50-482 Q	BERNERO, R.M.	8510180286*	PR	BLOOMENTHAL, H.	8510180105	40-8745
BARTLETT, B.L.	8510210298*	50-482 Q	BERNERO, R.M.	8510180291*	PR	BLOOMENTHAL, H.	8510180105	40-8745
BARTON, J.J.	8510180194	50-219 F	BERNERO, R.M.	8510180297*	PR	BLOSSOM, J.N.	8510170247	40-8452
BARTON, R.W.	8510030026*	50-333 P	BERRY, G.A.	8510110077	50-456 G	BLOSSOM, J.N.	8510180329	40-8452
BASEHORE, K.L.	8510170079*	50-280 P	BERRY, G.A.	8510290006	50-456 G	BLOUGH, A.R.	8510280360*	50-354 Q
BASKIN, K.P.	8510150177*	50-206 Q	BERRY, H.	8510220042*	50-320 P	BLOUGH, A.R.	8510180105	50-354 Q
BASKIN, K.P.	8510170090	50-361 P	BERRY, J.	8510210154*	50-354 Q	BLUMBERG, N.	8510220017*	50-352 Q
BASKIN, K.P.	8510170101*	50-361 P	BERRY, K.W.	8510010319	50-155 P	BLUMBERG, N.	8510250475*	50-423 Q
BASS, C.D.	8510160070	PR	BERRY, K.W.	8510040177	50-155 P	BOARDMAN, J.R.	8510180109*	50-382 Q
BASSETT, O.E.	8510180264*	PR	BERRY, K.W.	8510220253	50-255 P	BOHNER, H.	8510100188	PR
BATEMAN, W.H.	8510170153*	50-219 Q	BERRY, K.W.	8510250444	50-255 P	BOLCH, M.	8510250445*	50-413 F
BATEMAN, W.H.	8510250171*	50-219 Q	BERRY, K.W.	8510290145	50-155 P	BOLDT, G.K.	8510040148*	50-320 P
BATES, J.W.	8510180058*	70-27	BERRY, R.B.	8510020211*	50-382 Q	BOLDT, G.K.	8510040152*	50-320 P
BATES, J.W.	8510180078*	70-143	BERRY, R.B.	8510020207*	50-382 Q	BOLDT, G.K.	8510040155*	50-320 P
BATTS, M.S.	8510180319	PR	BERRYMAN, R.M.	8510170079*	50-280 P	BOLT, S.E.	8510040402	NUREG
BATZ, R.	8510110176	50-461 M	BESS, J.E.	8510040415*	50-458 Q	BOOK, H.E.	8510220188*	70-25
BAUER, S.A.	8510070013	50-344 S	BETTENHAUSEN, L.	8510080236*	50-271 Q	BOOK, H.E.	8510220210*	70-25

PERSONAL AUTHOR INDEX 349

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BOOK, H.E.	8510220245*	70-25*	BRIDEN, D.W.	8510280408	50-346 F	BRUGGER, R.M.	8510280091	50-186 P
BOOKER, J.E.	8510010390	50-458 P	BRIGGS, L.	8510250273*	50-293 Q	BRUNET, J.R.	8510150352	50-255 F
BOOKER, J.E.	8510040145	50-458 P	BRIGGS, L.	8510250445*	50-354 Q	BRUNET, J.R.	8510150380	50-255 F
BOOKER, J.E.	8510040267	50-458 P	BRIGGS, L.E.	8510210117*	50-410 Q	BRUNET, J.R.	8510300130	50-255 F
BOOKER, J.E.	8510040469	50-458 P	BRIGHT, G.O.	8510100028	50-440 G	BRUNET, J.R.	8510300131	50-255 F
BOOKER, J.E.	8510070258	50-458 F	BRIGHT, G.O.	8510180247	50-142 G	BRUNNER, J.E.	8510080037	50-329 A
BOOKER, J.E.	8510080564	50-458 S	BRINKMAN, S.	8510170051	50-336 S	BRYAN, V.J.	8510090267	40-4492
BOOKER, J.E.	8510090127	50-458 R	BRISTOL, D.A.	8510210247*	70-820	BUCHANAN, C.R.	8510010315*	FOIA
BOOKER, J.E.	8510110001	50-458 E	BRITT, R.W.	8510150136	50-266 P	BUCHANAN, C.R.	8510010327*	40-8027
BOOKER, J.E.	8510110104	50-458 P	BRITT, R.W.	8510150165	50-266 P	BUCHANAN, C.R.	8510010341*	40-8027
BOOKER, J.E.	8510110154	50-458 P	BRITT, R.W.	8510150314	50-266 F	BUCHHOLZ, R.H.	8510090042*	50-265 Q
BOOKER, J.E.	8510160090	50-458 E	BROCK, B.L.	8510150345*	70-754	BUNDY, H.	8510280241*	50-445 Q
BOOKER, J.E.	8510160291	50-458 P	BROCK, S.J.	8510090524	WASTE MGT	BUNDY, H.F.	8510010082*	50-482 Q
BOOKER, J.E.	8510170196	50-458 R	BROMBACH, T.W.	8510290041*	50-400 T	BUNDY, H.F.	8510040415*	50-458 Q
BOOKER, J.E.	8510220074	50-458 S	BROMBERG, B.J.	8510030432	CONTRACT	BUNTING, J.O.	8510250535	WASTE MGT
BOOKER, J.E.	8510220345	50-458 P	BROMBERG, B.J.	8510280194	CONTRACT	BUNTING, J.O.	8510250537	WASTE MGT
BOOKER, J.E.	8510250267	50-458 P	BRONS, J.C.	8510030018	50-333 P	BUNTING, J.O.	8510280277	WASTE MGT
BOOKER, J.E.	8510250376	50-458 S	BRONS, J.C.	8510030071	50-286 P	BURGER, C.	8510180086	50-269 S
BOOKER, J.E.	8510250405	50-458 P	BRONS, J.C.	8510040213	50-333 P	BURGER, F.J.	8510220048	50-271 R
BOOKER, J.E.	8510290467	50-458 S	BRONS, J.C.	8510040221*	50-333 P	BURGESS, B.	8510010178	50-346 S
BOOKER, J.E.	8510300127	50-458 P	BRONS, J.C.	8510080218	50-286 P	BURNETT, P.T.	8510040539*	50-302 Q
BOOKER, J.E.	8510300132	50-458 R	BRONS, J.C.	8510080313	50-286 P	BURNETT, R.F.	8510150128	70-143
BOOKER, J.E.	8510300185	50-458 P	BRONS, J.C.	8510100033	50-333 Q	BURNETT, R.F.	8510180198*	PR
BOOKER, J.E.	8510310075	50-458 S	BRONS, J.C.	8510100120	50-286 P	BURNETT, R.F.	8510180224*	PR
BORCHARDT, R.W.	8510230163*	50-317 Q	BRONS, J.C.	8510100136*	50-286 P	BURNETT, R.F.	8510180290*	PR
BORDENICK, B.M.	8510110087	50-424 G	BRONS, J.C.	8510180059	50-286 P	BURNETT, R.F.	8510180330*	PR
BORDENICK, B.M.	8510110237	50-322 G	BRONS, J.C.	8510180310	50-333 P	BURNS, P.	8510180085*	50-320 H
BORDENICK, B.M.	8510290002	50-322 G	BRONS, J.C.	8510220191	50-333 P	BURRIS, S.P.	8510090333*	50-400 Q
BORIS, G.F.	8510090409	WASTE MGT	BRONS, J.C.	8510220330	50-286 P	BURROSS, D.C.	8510040383	PR
BORIS, G.F.	8510240188	WASTE MGT	BRONS, J.C.	8510220347	50-333 P	BUSH, B.S.	8510180203	NUREG
BOSTED, C.	8510170054*	50-361 Q	BRONS, J.C.	8510220349*	50-333 P	BUSH, L.L.	8510040458*	50-400 T
BOSTED, C.	8510220075*	50-528 P	BRONS, J.C.	8510240177	50-333 P	BUSS, D.R.	8510250299	WASTE RES
BOURNIA, A.	8510250557	50-397 P	BROOKS, D.J.	8510240027	WASTE RES	BUTCHER, E.J.	8510080102*	50-309 P
BOWEN, J.R.	8510080461*	50-139 Q	BROOKS, D.J.	8510240128	WASTE RES	BUTCHER, E.J.	8510080405*	50-317 P
BOWEN, M.A.	8510240102	27-39	BROOKS, P.P.	8510240555	WASTE RES	BUTCHER, E.J.	8510080560*	50-336 P
BOWERS, H.	8510010084*	50-416 V	BROOKS, W.E.	8510030063*	50-498 Q	BUTCHER, E.J.	8510090507	50-336 P
BOWMAKER, N.J.	8510090038	50-317 F	BROWN, A.	8510080575*	CONTRACT	BUTCHER, E.J.	8510170083*	50-266 P
BOYD, D.	8510280211	50-409 S	BROWN, E.J.	8510020008*	MISC	BUTCHER, E.J.	8510170126	50-368 P
BOYD, D.	8510280422	50-409 S	BROWN, F.L.	8510250328	PROJ	BUTCHER, E.J.	8510170133	50-309 P
BOYD, D.	8510290192	50-409 S	BROWN, G.	8510100018*	50-266 Q	BUTCHER, E.J.	8510170463	50-282 P
BOYD, D.C.	8510100051*	50-331 Q	BROWN, G.A.	8510160270*	50-295 Q	BUTCHER, E.J.	8510170466*	50-282 P
BOYD, D.C.	8510280183*	50-409 Q	BROWN, G.D.	8510010126*	40-8027	BUTCHER, E.J.	8510190102	50-344 P
BOYER, V.S.	8510070248*	50-352 K	BROWN, G.D.	8510010263*	40-8006	BUTCHER, E.J.	8510180141	50-344 P
BRACH, B.	8510020040	MISC	BROWN, G.D.	8510010415*	40-8027	BUTCHER, E.J.	8510240549*	50-344 P
BRACH, E.W.	8504030276*	50-346 S	BROWN, G.D.	8510150330*	FOIA	BUTCHER, E.J.	8510240570	50-344 P
BRACKEN, G.F.	8510240053	WASTE MGT	BROWN, K.J.	8510170458	40-8745	BUTCHER, E.J.	8510240619*	50-368 P
BRADBURY, J.W.	8510240650	WASTE RES	BROWN, R.W.	8510100209	PR	BUTCHER, E.J.	8510240648	50-317 P
BRADFORD, L.	8510240675	50-352 F	BROWN, W.B.	8510150064	70-143	BUTCHER, E.J.	851025, 2011	50-267 P
BRADHAM, O.S.	8510240305	50-395 F	BROWN, W.B.	8510150070	70-1201	BUTCHER, E.J.	8510280060	50-285 F
BRADLEY, E.J.	8510070232	50-352 K	BROWN, W.B.	8510150074	70-1151	BUTCHER, E.J.	8510280263	50-309 P
BRADLEY, E.J.	8510080268	50-352 F	BROWN, W.B.	8510150108	70-27	BUTCHER, E.J.	8510280286	50-344 P
BRADLEY, E.J.	8510180017	50-352 K	BROWN, W.B.	8510150120	70-3000	BUTCHER, E.J.	8510280297	50-266 P
BRADLEY, E.J.	8510180144	50-777 F	BROWN, W.B.	8510150122	70-27	BUTCHER, E.J.	8510280318*	50-389 P
BRADLEY, E.J.	8510210147*	50-277 P	BROWN, W.B.	8510150130	70-1257	BUTCHER, E.J.	8510280409	50-282 P
BRANDT, R.J.	8510100070	PR	BROWN, W.B.	8510150154	70-36	BUTCHER, E.J.	8510280443	50-282 F
BRANSFIELD, T.J.	8510010008	50-213 S	BROWN, W.B.	8510150164	70-2948	BUTCHER, E.J.	8510290437	50-282 P
BRANSFIELD, T.J.	8510090248	50-213 S	BROWN, W.B.	8510150178	70-27	BUTCHER, E.J.	8510290546	50-267 P
BRANSTADT, T.E.	8510010544*	COMMISSION	BROWN, W.B.	8510150186	70-1151	BUTCHER, E.J.	8510300228	50-344 F
BRAUN, G.D.	8510010318	40-8027	BROWN, W.B.	8510150227	70-1113	BUTCHER, E.J.	8510310523	50-335 P
BREGNILL, L.	8510010417	50-341 R	BROWN, W.B.	8510150315	70-371	BUTCHER, R.C.	8510080538*	50-416 Q
BREGNILL, L.P.	8510020160	50-341 S	BROWN, W.B.	8510150340	70-371	BUTLER, J.C.	8510290413*	TOPREP
BREGNILL, L.P.	8510020203	50-341 S	BROWN, W.B.	8510150434	70-3016	BUTLER, J.P.	8510030182*	CONTRACT
BREGNILL, L.P.	8510070374	50-341 S	BROWN, W.B.	8510150496	70-27	BUTLER, W.	8510010027	50-354 F
BREGNILL, L.P.	8510090083	50-341 S	BROWN, W.B.	8510160375	70-143	BUTLER, W.R.	8510080064	50-373 P
BREGNILL, L.P.	8510090182	50-341 S	BROWNING, R.E.	8510010011*	WASTE MGT	BUTLER, W.R.	8510080069*	50-373 P
BREGNILL, L.P.	8510090376	50-341 S	BROWNLEE, L.L.	8510220413	50-321 Q	BUTLER, W.R.	8510080126	50-373 P
BREGNILL, L.P.	8510240004	50-341 S	BROWNLEE, V.L.	8510020285	50-302 Q	BUTLER, W.R.	8510080133*	50-373 P
BREGNILL, L.P.	8510250289	50-341 S	BROWNLEE, V.L.	8510030282	50-424 Q	BUTLER, W.R.	8510080307	50-458 E
BREGNILL, L.P.	8510280071	50-341 S	BROWNLEE, V.L.	8510030296	50-269 Q	BUTLER, W.R.	8510080566	50-354 A
BREGNILL, L.P.	8510290057	50-341 S	BROWNLEE, V.L.	8510030437	50-416 V	BUTLER, W.R.	8510160025	50-354 E
BREGNILL, L.P.	8510310015	50-341 S	BROWNLEE, V.L.	8510040526	50-424 Q	BUTLER, W.R.	8510160032	50-354 A
BREGNILL, L.P.	8510310057	50-341 S	BROWNLEE, V.L.	8510040535	50-302 C	BUTLER, W.R.	8510160336	50-354 F
BREGNILL, L.P.	8510310404	50-341 S	BROWNLEE, V.L.	8510070477	50-414 Q	BUTLER, W.R.	8510180338	50-461 A
BRENNAN, J.	8510180142*	50-244 P	BROWNLEE, V.L.	8510070505	50-269 Q	BUTLER, W.R.	8510180340	50-461 F
BRESLAU, B.A.	8510310291*	50-382 Q	BROWNLEE, V.L.	8510080279	50-335 Q	BUTLER, W.R.	8510180349	50-410 F
BREY, H.L.	8510080001	50-267 P	BROWNLEE, V.L.	8510080351	50-302 Q	BUTLER, W.R.	8510170148	50-354 E
BREY, H.L.	8510080005	50-267 P	BROWNLEE, V.L.	8510080543	50-413 Q	BUTLER, W.R.	8510170156	50-354 A
BREY, H.L.	8510090149	50-267 P	BROWNLEE, V.L.	8510150296	50-321 Q	BUTLER, W.R.	8510170188	50-458 P
BREY, H.L.	8510090154	50-267 P	BROWNLEE, V.L.	8510180091	50-335 Q	BUTLER, W.R.	8510170195*	50-458 P
BREY, H.L.	8510160075	50-267 P	BROWNLEE, V.L.	8510180124	50-413 Q	BUTLER, W.R.	8510220113	50-388 P
BREY, H.L.	8510160079	PR	BROWNLEE, V.L.	8510180379	50-417 Q	BUTLER, W.R.	8510220114*	50-388 P
BREY, H.L.	8510160173	50-267 P	BROWNLEE, V.L.	8510180381	50-414 Q	BUTLER, W.R.	8510220142	50-387 V
BREY, H.L.	8510220237	50-267 P	BROWNLEE, V.L.	8510180426	50-335 Q	BUTLER, W.R.	8510220164	50-354 F
BREY, H.L.	8510230083	50-267 P	BROWNLEE, V.L.	8510180458	50-302 Q	BUTLER, W.R.	8510250566	50-373 F
BREY, H.L.	8510290122	50-267 Q	BROWNLEE, V.L.	8510180520	50-250 V	BUTLER, W.R.	8510280093	50-461 F
BRIDEN, D.W.	8510160301	50-446 F	BROWNLEE, V.L.	8510220387	50-250 Q	BUTLER, W.R.	8510280098	50-354 A
BRIDEN, D.W.	8510210072	50-346 F	BRUCHMANN, G.W.	8510180332	PR	BUTLER, W.R.	8510280179	50-410 A
BRIDEN, D.W.	8510280284	50-346 F	BRUEMMER, S.M.	8510040360	NUREG	BUTLER, W.R.	8510280236	50-461 A

350 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BUTLER, W.R.	8510280427	50-387 P	CHAUDHARY, S.	8510250445*	50-354 Q	CHURCHMAN, C.W.	8510080428*	50-354 A
BUTLER, W.R.	8510310413	50-354 F	CHAUDHARY, S.	8510250475*	50-423 Q	CILLIS, M.	8510030288*	50-275 Q
BUTLER, W.R.	8510310581	50-373 P	CHAUDHARY, S.K.	8510280360*	50-354 Q	CILLIS, M.	8510113304*	50-326 Q
BUTLER, W.R.	8510310586*	50-373 P	CHEU, U.	8510230143*	50-336 Q	CILLIS, M.	85101170358*	50-70 Q
BUTTERFIELD, L.	8510220022	TOPREP	CHEN, U.	8510070538*	50-423 Q	CIOFFI, J.A.	8510030235*	50-245 Q
BUTTERFIELD, L.	8510220022	TOPREP	CHEUNG, L.S.	8510080401*	50-443 Q	CIOFFI, J.A.	8510230244*	50-244 Q
BUTTERFIELD, L.	8510220183	NUREG	CHEVERTON, R.D.	8510040371	NUREG	CLARK, A.T.	8510090307	PROJ
BUTTERFIELD, L.	8510220183	NUREG	CHEVERTON, R.D.	8510040402	NUREG	CLARK, A.T.	8510170113	PROJ
BUTTERFIELD, L.	8510240363*	50-456 T	CHILES, L.	8510250030*	50-302 H	CLARK, A.T.	8510250334	PROJ
BYAM, T.A.	8510160171*	50-461 F	CHILK, S.J.	8502190413*	50-346 V	CLARK, A.T.	8510310539	PROJ
BYRD, R.	8510020018	50-416 S	CHILK, S.J.	8510010265	FOIA	CLARK, G.L.	8510090058	WASTE MGT
BYRD, R.	8510300308	50-416 S	CHILK, S.J.	8510020006	50-322 P	CLARK, K.M.	8510170050*	FOIA
BYRD, R.W.	8510090292	50-416 S	CHILK, S.J.	8510030088	10CFR	CLARK, L.	8510170165	50-20 R
BYRD, R.W.	8510220122	50-416 S	CHILK, S.J.	8510030092	10CFR	CLARK, P.R.	8510220434*	50-219 U
BYRD, R.W.	8510240339	50-416 S	CHILK, S.J.	8510030229	50-346 S	CLARK, P.R.	8510240061	50-320 Q
BYRD, R.W.	8510290301	50-416 S	CHILK, S.J.	8510040308	50-413 G	CLARK, R.E.	8510090472	50-259 P
BYRON, B.B.	8510010122*	FOIA	CHILK, S.J.	8510100029	50-440 G	CLARK, R.J.	8510230119	50-259 P
BYRON, B.B.	8510010226*	FOIA	CHILK, S.J.	8510110129	50-289 G	CLAUSEN, M.J.	8510210004	50-440 G
BYRON, B.B.	8510010334*	FOIA	CHILK, S.J.	8510110157	50-352 G	CLAYTON, H.B.	8510090375	50-272 F
BYRON, B.B.	8510010395*	FOIA	CHILK, S.J.	8510110160	50-528 G	CLEMENTS, B.R.	8510080199*	50-445 Q
CAHILL, W.J.	8510030055	50-458 K	CHILK, S.J.	8510110175	50-423 G	CLEMENTS, B.R.	8510080216*	50-445 Q
CAHILL, W.J.	8510080589*	50-458 Q	CHILK, S.J.	8510150343	50-413 G	CLEMENTS, B.R.	8510170050*	FOIA
CAHILL, W.J.	8510090313*	50-458 Q	CHILK, S.J.	8510160164	PR	CLEMENTS, B.R.	8510220292*	50-445 Q
CAHILL, W.J.	8510110137	50-458 E	CHILK, S.J.	8510170086*	50-206 P	CLEMENTS, T.	8510180412	PR
CAHILL, W.J.	8510220359*	50-458 Q	CHILK, S.J.	8510170093*	50-206 P	CLEMENTS, W.L.	8510310195	50-352 G
CAHILL, W.J.	8510220453*	50-458 Q	CHILK, S.J.	8510170271	10CFR	CLEMMENS, C.B.	8510100206	PR
CAHN, R.S.	8510020294*	50-461 A	CHILK, S.J.	8510180156	50-440 G	CLEMMONS, P.	8510230047*	50-309 Q
CALDWELL, J.L.	8510080538*	50-416 Q	CHILK, S.J.	8510210007	50-293 G	CLEMMONS, P.	8510250445*	50-354 Q
CALDWELL, R.A.	8510310106*	50-458 Q	CHILK, S.J.	8510210283	50-352 P	CLIFFORD, J.W.	8510170228	50-244 P
CALHOON, M.	8510100172	PR	CHILK, S.J.	8510220220*	50-424 A	CLIFFORD, J.W.	8510290554	50-25 P
CALLAN, L.J.	8510150228*	50-250 Q	CHILK, S.J.	8510240315	10CFR	CLIMER	8510010493	50-316 R
CAMPBELL, R.M.	8510010185*	50-443 Q	CHILK, S.J.	8510240500	10CFR	CLIMER	8510010496	50-315 R
CAPTON, D.	8510210228*	50-322 Q	CHILK, S.J.	8510240503	50-324 P	CLOUD, R.L.	8504250409	50-275 P
CAPTON, D.	8510230208*	50-352 Q	CHILK, S.J.	8510280513	50-382 G	CLOUGH, R.L.	8510040354	NUREG
CAPSTICK, R.W.	8510110097	50-271 F	CHILK, S.J.	8510290439	PR	COBB, G.H.	8510150266*	FOIA
CAPSTICK, R.W.	8510240320	50-271 P	CHILK, S.J.	8510310190	50-456 G	COHEN, I.	8510160231*	50-272 Q
CAPSTICK, R.W.	8510290399	50-271 R	CHILK, S.J.	8510310305	50-413 G	COHEN, L.	8510020232	NUREG
CAREY, J.J.	8510020239	50-334 R	CHILK, S.J.	8510310306	50-440 G	COHEN, S.	8510030131	NUREG
CAREY, J.J.	8510030417	50-412 S	CHOKSHI, N.C.	8510010464	50-382 E	COLBERT, W.F.	8510070329*	50-341 Q
CAREY, J.J.	8510070255	50-412 A	CHOKSHI, N.C.	8510010489	50-382 E	COLBURN, T.G.	8510170078	50-266 P
CAREY, J.J.	8510160185	50-412 F	CHOKSHI, N.C.	8510010497	50-382 E	COLEMAN, N.M.	8510240609	WASTE RES
CAREY, J.J.	8510180193	50-412 A	CHOKSHI, N.C.	8510010499	50-382 E	COLEMAN, N.M.	8510250596	WASTE RES
CAREY, J.J.	8510210104	50-412 Q	CHOKSHI, N.C.	8510010518	50-382 E	COLEMAN, R.	8510040489	CONTRACT
CAREY, J.J.	8510220030	50-412 E	CHOKSHI, N.C.	8510010584	50-382 E	COLEMAN, R.	8510040576	CONTRACT
CAREY, J.J.	8510230009	50-334 F	CHOKSHI, N.C.	8510020169	50-382 E	COLEMAN, R.	8510070124	CONTRACT
CAREY, J.J.	8510240002	50-334 P	CHOKSHI, N.C.	8510020292	50-382 E	COLEMAN, R.	8510110099	CONTRACT
CAREY, J.J.	8510240402	70-3008	CHOKSHI, N.C.	8510020503	50-382 E	COLLEY, J.L.	8510070463*	50-324 Q
CAREY, J.J.	8510290050	50-334 Q	CHOKSHI, N.C.	8510030154	50-382 E	COLLINS, D.	8510030039	50-324 S
CARLIN, E.	8510250326	PR	CHOKSHI, N.C.	8510030183	50-382 E	COLLINS, D.	8510030052	50-324 S
CARLOS, M.	8510170097*	50-206 P	CHRISOTIMOS, N.	8510010178	50-346 S	COLLINS, D.J.	8510170147*	50-320 Q
CAROLAN, J.F.	8510040323	REVIEW GR P	CHRISOTIMOS, N.	8510010191	50-315 Q	COLLINS, J.T.	8510010457*	50-382 Q
CARTER, T.F.	8510230211*	50-400 T	CHRISOTIMOS, N.	8510010234	50-249 S	COLLINS, S.C.	8510010454*	50-382 F
CASE, E.G.	8510170429*	FOIA	CHRISOTIMOS, N.	8510080611	50-483 Q	COLLINS, S.J.	8510010502	50-443 Q
CASE, E.G.	8510170441*	FOIA	CHRISOTIMOS, N.	8510080614*	50-483 Q	COLLINS, S.J.	8510030213	50-286 Q
CASE, E.G.	8510170443*	FOIA	CHRISOTIMOS, N.	8510100027	50-331 Q	COLLINS, S.J.	8510040149	50-333 Q
CASELLA, F.	8510020260*	50-293 Q	CHRISOTIMOS, N.	8510100039*	50-331 Q	COLLINS, S.J.	8510040202	50-244 Q
CASHMAN, D.C.	8510010149*	CONTRACT	CHRISOTIMOS, N.	8510210069	50-295 S	COLLINS, S.J.	8510070544	50-247 Q
CASHWELL, R.J.	8510250290	50-156 P	CHRISOTIMOS, N.	8510250087	50-305 Q	COLLINS, S.J.	8510080096	50-410 Q
CASHWELL, R.J.	8510250577	50-156 P	CHRISOTIMOS, N.	8510250153	50-254 Q	COLLINS, S.J.	8510210155	50-247 Q
CASHWELL, R.J.	8510290401	50-156 R	CHRISOTIMOS, N.	8510250270	50-373 Q	COLLINS, S.J.	8510220169*	FOIA
CASSIDY, R.	8510310407	50-454 S	CHRISOTIMOS, N.	8510250271	50-266 Q	COLLINS, S.J.	8510220177	50-272 Q
CATCHPOLE, G.J.	8510180001	40-8745	CHRISOTIMOS, N.	8510250276*	50-266 Q	COLLINS, S.J.	8510230192	50-352 Q
CAUDILL, L.L.	8510180525	70-1257	CHRISOTIMOS, N.	8510250447	50-255 S	COLLINS, S.J.	8510280338	50-220 Q
CAVANAU, T.W.	8510300082*	50-417 A	CHRISOTIMOS, N.	8510280177	50-409 Q	COLLINS, V.P.	8510180349	PR
CELESTE, R.F.	8510150206*	50-346 U	CHRISOTIMOS, N.	8510280211	50-409 S	COLOMBO, R.	8510280007	50-312 R
CERNE, A.C.	8510010505*	50-443 Q	CHRISOTIMOS, N.	8510280260	50-483 Q	COLOMBO, R.W.	8510020030	50-312 S
CERNE, A.C.	8510080401*	50-443 Q	CHRISOTIMOS, N.	8510280264*	50-483 Q	COLOMBO, R.W.	8510170348	50-312 S
CERNE, A.C.	8510090165	50-443 A	CHRISOTIMOS, N.	8510280422	50-409 S	COMBS, F.	8510230253*	50-416 U
CESARE, J.G.	8510180207	50-416 R	CHRISOTIMOS, N.	8510290192	50-409 S	CONDON, C.	8510080322	WASTE MGT
CHAFFEE, A.E.	8510090350*	50-323 Q	CHRISOTIMOS, N.	8510290380	50-341 Q	CONDON, C.	8510080343	WASTE MGT
CHAMBERLAIN, D.	8510040415*	50-458 Q	CHRISOTIMOS, N.	8510290384*	50-341 Q	CONDON, C.	8510080605	WASTE MGT
CHAMBERLAIN, D.	8510240312*	50-458 Q	CHRISOTIMOS, N.	8510300106	50-255 Q	CONDON, C.	8510280102	WASTE MGT
CHAMBERLAIN, D.	8510240347*	50-458 Q	CHRISTENSEN, J.	8510100008*	50-445 Q	CONGEDO, T.V.	8510110246*	50-364 P
CHAN, E.I.	8510110049	50-456 G	CHRISTIANSSON	8510030140*	50-245 P	CONLON, T.E.	8510020290*	50-302 Q
CHAN, E.I.	8510150375	50-456 G	CHRISTMAN, J.N.	8510110057	50-322 G	CONLON, T.E.	8510180383*	50-417 Q
CHAN, E.I.	8510220233	50-456 G	CHRISTMAN, J.N.	8510110057	50-322 G	CONLON, T.E.	8510180388*	50-414 Q
CHAN, E.I.	8510310384	50-456 T	CHRISTOFFER, G.	8510080432*	50-461 Q	CONNELL, G.	8510040373	PR
CHANDLER, L.J.	8510240318	50-320 G	CHRISTOFFER, G.	8510210153*	50-346 Q	CONNELLY, S.R.	8510010071*	50-416 Q
CHANDLER, L.J.	8510240323*	50-320 G	CHRISTOFFER, G.	8510290115*	50-409 Q	CONNELLY, S.R.	8510010084*	50-416 V
CHANDLER, L.J.	8510240329*	50-320 G	CHUNG, D.H.	8510080570	WASTE RES	CONNER, T.B.	8510210038	50-352 G
CHANDLER, L.J.	8510240375	50-320 G	CHUNG, D.H.	8510090366	WASTE RES	CONNER, T.B.	8510210038	50-352 G
CHANEY, H.D.	8510310369*	50-382 Q	CHUNG, D.H.	8510240181	WASTE RES	CONNER, T.B.	8510240279	50-352 G
CHANG, K.C.	8510240525	WASTE RES	CHUNG, H.M.	8510040332	NUREG	CONNER, T.B.	8510240279	50-352 G
CHARLOT, L.A.	8510040360	NUREG	CHUNG, J.W.	8510080421*	50-277 Q	CONSTABLE, G.L.	8510080281	50-382 S
CHARNLEY, J.S.	8510100013	TOPREP	CHUNG, J.W.	8510160037*	50-245 Q	CONSTABLE, G.L.	8510160109*	50-382 Q
CHARNLEY, J.S.	8510170223	TOPREP	CHURCHILL, B.W.	8510100126	50-424 G	CONSTABLE, G.L.	8510310124*	50-382 P
CHARNLEY, J.S.	8510230243	TOPREP	CHURCHILL, B.W.	8510100126	50-424 G	CONSTABLE, G.L.	8510310291*	50-382 Q
CHARNLEY, J.S.	8510240198	TOPREP	CHURCHMAN, C.W.	8510080424*	50-354 A	CONTE, R.	8510010062	50-289 S

PERSONAL AUTHOR INDEX 351

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY			
CONTE, R.	8510250193*	50-289	Q	COUNCIL, W.G.	8510220110	50-445	A	CRUTCHFIELD, D.	8510150091	50-219	S
CONVERSE, R.J.	8510010340	50-333	Q	COUNCIL, W.G.	8510220312*	50-445	Q	CRUTCHFIELD, D.	8510150117	MISC	
CONVERSE, R.J.	8510090510	71-240		COUNCIL, W.G.	8510220397	50-446	S	CRUTCHFIELD, D.	8510170100	50-322	P
CONVERSE, R.J.	8510150312	50-333	R	COUNCIL, W.G.	8510220403	50-445	S	CRUTCHFIELD, D.	8510210179	MISC	
CONVERSE, R.J.	8510280151	50-333	S	COUNCIL, W.G.	8510250321	50-445	S	CUDDENBACK, D.A.	8510100032	REGGD	
CONVERSE, R.J.	8510280403	50-333	S	COUNCIL, W.G.	8510250370	50-445	S	C'JLLEN, E.J.	8510150069	50-352	F
CONVERSE, W.E.	8510010479	50-313	R	COUNCIL, W.G.	8510280224	50-445	S	CUMMINGS, G.E.	8510090368	WASTE RES	
CONVEY, D.	8510290472	XPORTLIC		COUNCIL, W.G.	8510280484	50-445	S	CUMMINS, J.E.	8510010082*	50-482	Q
CONWAY, J.T.	8510210037*	QA999		COUNCIL, W.G.	8510280487	50-445	S	CUMMINS, J.E.	8510210298*	50-482	Q
COOK, A.V.	8510150239	50-445	E	COUNCIL, W.G.	8510280493	50-446	S	CUNNINGHAM, A.	8510030014	50-280	S
COOK, F.R.	8510090158	WASTE MGT		COUNCIL, W.G.	8510280500	50-445	S	CUNNINGHAM, A.	8510030039	50-324	S
COOK, F.R.	8510090158	WASTE MGT		COUNCIL, W.G.	8510290021*	50-445	Q	CUNNINGHAM, A.	8510030052	50-324	S
COOK, G.N.	8510220163	50-528	F	COUNCIL, W.G.	8510300005	50-445	F	CUNNINGHAM, A.L.	8510180463*	50-302	Q
COOK, H.L.	8510110211	PR		COUNCIL, W.G.	8510300051	50-445	F	CUNNINGHAM, A.L.	8510220396*	50-250	Q
COOK, J.	8510150312	50-333	R	COUNTS, C.A.	8510030043	NUREG		CUNNINGHAM, A.L.	8510220398*	50-324	Q
COOK, J.W.	8510080090	50-329	R	COUNTS, M.	8510240305	50-395	F	CUNNINGHAM, A.L.	8510220406*	50-261	Q
COOK, J.W.	8510160279	50-329	A	COWGILL, C.	8510310132	50-320	S	CUNNINGHAM, G.E.	8510070270	50-70	P
COOK, J.W.	8510220090	50-329	S	COWGILL, C.J.	8510150008	50-320	P	CUNNINGHAM, G.E.	8510150261	71-5942	
COOK, J.W.	8510220408	50-329	S	COWGILL, C.J.	8510170147*	50-320	Q	CUNNINGHAM, G.E.	8510210250	71-5984	
COOK, J.W.	8510220411	50-329	S	CRAIG, J.W.	8510310247*	50-254	Q	CUNNINGHAM, G.E.	8510300003	50-73	P
COOK, J.W.	8510230132	50-329	A	CRANE, P.A.	8510020043	50-275	K	CUNNINGHAM, G.H.	8510170062*	50-206	P
COOK, J.W.	8510290345	50-329	R	CRANE, P.A.	8510170275	50-275	J	CUNNINGHAM, G.H.	8510180491*	FOIA	
COOK, K.W.	8510010384*	50-382	F	CRANSTON, A.	8510150300*	50-272	H	CUNNINGHAM, L.	8510040459	50-382	E
COOK, K.W.	8510010423*	50-382	F	CRANWELL, R.M.	8510090272	WASTE RES		CUNNINGHAM, R.E.	8510090174*	PR	
COOK, K.W.	8510010616	50-382	R	CRANWELL, R.M.	8510230308	WASTE RES		CUNNINGHAM, R.E.	8510150272*	40-1366	
COOK, K.W.	8510020219	50-382	F	CRANWELL, R.M.	8510240020	WASTE RES		CUNNINGHAM, R.E.	8510230252	40-2061	
COOK, K.W.	8510040386	50-382	S	CRANWELL, R.M.	8510240153	WASTE RES		CUSTOM, D.B.	8510150348	50-219	S
COOK, K.W.	8510040438	50-382	F	CRANWELL, R.M.	8510240162	WASTE RES		CUTCHIN, J.	8510060568*	50-458	S
COOK, K.W.	8510080437	50-382	S	CRANWELL, R.M.	8510240362	WASTE RES		CUTTER, A.B.	8510150109	50-261	P
COOK, K.W.	8510150126	50-382	P	CRANWELL, R.M.	8510240367	WASTE RES		CUTTER, A.B.	8510150277	50-261	P
COOK, K.W.	8510150476	50-382	R	CRAWFORD, R.M.	8510080515*	50-237	P	CUTTER, A.B.	8510160057	50-324	P
COOK, K.W.	8510160257*	50-382	Q	CREASY, J.N.	8510180089	50-387	S	CUTTER, A.B.	8510160220	50-400	F
COOK, K.W.	8510167295	50-382	P	CREED, J.R.	8510080432*	50-461	Q	CUTTER, A.B.	8510180265	50-261	P
COOK, K.W.	8510170010	50-382	P	CREED, J.R.	8510160177*	50-254	Q	CUTTER, A.B.	8510230005	50-261	P
COOK, K.W.	8510170013	50-382	S	CREED, J.R.	8510210051*	50-454	Q	CUTTER, A.B.	8510240395	70-2997	
COOK, K.W.	8510170233	50-382	P	CREED, J.R.	8510210153*	50-346	Q	CUTTER, A.B.	8510300014	50-324	P
COOK, K.W.	8510210163	50-382	S	CREED, J.R.	8510280113*	50-440	Q	D'ANGELO, A.	8510170054*	50-361	Q
COOK, K.W.	8510220205	50-382	P	CREED, J.R.	8510290017*	50-341	Q	DAEMEN, J.	8510020036	WASTE RES	
COOK, K.W.	8510220227*	50-382	Q	CREED, J.R.	8510290115*	50-409	Q	DAEMEN, J.	8510020041	WASTE RES	
COOK, K.W.	8510240369	50-382	F	CREWS, J.	8510170054*	50-361	Q	DAEMEN, J.	8510040467	WASTE RES	
COOK, K.W.	8510240408	50-382	F	CREWS, J.L.	8510090350*	50-323	Q	DAHLMAN, L.C.	8510220363*	50-263	Q
COOK, K.W.	8510250427	50-382	P	CRIMMINS, T.M.	8510010185	50-387	F	DALE, L.F.	8510010462	50-416	F
COOK, K.W.	8510280329	50-382	P	CRIMMINS, T.M.	8510070007	50-387	S	DALE, L.F.	8510020018	50-416	S
COOK, R.	8510090530*	50-397	Q	CRIMMINS, T.M.	8510180089	50-387	S	DALE, L.F.	8510070316	50-416	P
COOL, D.A.	8510230254	40-3392		CRLEN, J.A.K.R.V.	8510180429*	50-335	Q	DALE, L.F.	8510070373	50-416	Q
COOL, D.A.	8510310474	40-7455		CROCKER, L.P.	8510080277*	50-329	A	DALE, L.F.	8510070452	50-416	P
COOLEY, R.A.	8510080419*	50-313	Q	CROLENBERG, A.	8510110042	NUREG		DALE, L.F.	8510070475	50-416	P
COOLEY, W.J.	8510220175*	70-25		CRONENBERG, A.W.	8510080015*	CONTRACT		DALE, L.F.	8510070481	50-416	P
COOLEY, W.J.	8510220188*	70-25		CROWN, S.T.	8510040592	50-282	P	DALE, L.F.	8510080316	50-416	S
COOLEY, W.J.	8510220210*	70-25		CROWN, M.W.	8510080489	50-288	P	DALE, L.F.	8510080494	50-416	P
COOLEY, W.L.	8510220245*	70-25		CROOK, M.F.	8510160303	FOIA		DALE, L.F.	8510090029	50-416	S
COONEY, M.J.	8510070247*	50-352	F	CROSS, J.C.	8510010462	50-416	F	DALE, L.F.	8510090090	50-416	P
COONEY, M.J.	8510150110	50-277	P	CROSSMAN, W.A.	8510010486	50-382	E	DALE, L.F.	8510090292	50-416	S
COONEY, M.J.	8510160318	50-277	F	CROSSMAN, W.A.	8510010568	50-382	E	DALE, L.F.	8510090361	50-416	S
COOPER, L.J.	8510290379	50-298	S	CROSSMAN, W.A.	8510010576	50-382	E	DALE, L.F.	8510150103	50-416	P
COPELAND, R.A.	8510030072	TOPREP		CROUSE, R.P.	8510070125*	50-346	S	DALE, L.F.	8510150187	50-416	P
COPELAND, R.A.	8510070200	50-316	P	CROUSE, R.P.	8510070262*	50-346	S	DALE, L.F.	8510160042	50-416	P
COPELAND, R.A.	8510170289	50-316	P	CROW, W.T.	8510020128	40-8027		DALE, L.F.	8510160061	50-416	P
COPELAND, V.G.	8510020370	50-456	G	CROW, W.T.	8510030251	40-6500		DALE, L.F.	8510170073	50-416	P
COPELAND, V.G.	8510020370	50-456	G	CROW, W.T.	8510040431	70-143		DALE, L.F.	8510160214	50-416	F
COPELAND, V.G.	8510150306	50-456	G	CROW, W.T.	8510040436*	70-143		DALE, L.F.	8510160245	NUREG	
COPELAND, V.G.	8510150306	50-456	G	CROW, W.T.	8510070568	70-135		DALE, L.F.	8510180035	50-416	Q
COPELAND, V.G.	8510180268	50-456	G	CROW, W.T.	8510080190	40-3392		DALE, L.F.	8510180207	50-416	R
COPELAND, V.G.	8510180268	50-456	G	CROW, W.T.	8510090071	70-2910		DALE, L.F.	8510210226	50-416	P
COPELAND, V.G.	8510240354	50-456	T	CROW, W.T.	8510090085	70-2910		DALE, L.F.	8510220053	50-416	Q
COPELAND, V.G.	8510240354	50-456	T	CROW, W.T.	8510090089*	70-2910		DALE, L.F.	8510220122	50-416	S
COPLAN, S.M.	8504090424	WASTE MGT		CROW, W.T.	8510090136	40-8027		DALE, L.F.	8510240339	50-416	S
COPLAN, S.M.	8510090399	WASTE MGT		CROW, W.T.	8510160163	70-3000		DALE, L.F.	8510280158	50-416	P
COSTANZI, F.A.	8510150467	MISC		CROW, W.T.	8510160189*	70-3000		DALE, L.F.	8510290038	50-416	F
COSTANZI, F.A.	8510170114	MISC		CROW, W.T.	8510160182*	70-3000		DALE, L.F.	8510290301	50-416	S
COSTELLO, F.	8510180029	I&E		CROW, W.T.	8510160188*	70-3000		DALE, L.F.	8510300008	50-416	S
COSTLEY, W.J.	8510220097	71-121		CROW, W.T.	8510170011	70-143		DALTROFF, S.L.	8510080274	50-277	Q
COSTNER, P.	8510020378	40-8027		CROW, W.T.	8510170014*	70-143		DALTROFF, S.L.	8510210065	50-277	F
COUNCIL, W.G.	8510010639	50-445	S	CROW, W.T.	8510230256	70-824		DALTROFF, S.L.	8510210146	50-277	P
COUNCIL, W.G.	8510040263	50-445	E	CROW, W.T.	8510230257*	70-824		DALTROFF, S.L.	8510220251	50-277	P
COUNCIL, W.G.	8510090336	50-445	S	CROW, W.T.	8510230258*	70-824		DALTROFF, S.L.	8510230028	50-278	Q
COUNCIL, W.G.	8510090339	50-445	S	CROW, W.T.	8510230260	70-1489		DALTROFF, S.L.	8510250146*	50-277	Q
COUNCIL, W.G.	8510090430	50-445	S	CROW, W.T.	8510230263*	70-1489		DALTROFF, S.L.	8510290076	50-352	F
COUNCIL, W.G.	8510090440	50-445	S	CROW, W.T.	8510240272	40-2061		DALTROFF, S.L.	8510290150	50-352	P
COUNCIL, W.G.	8510090448	50-445	S	CROW, W.T.	8510240325	40-8631		DAM, W.L.	8510280506	WASTE MGT	
COUNCIL, W.G.	8510090458	50-445	S	CROWLEY, B.R.	8510220418*	50-321	Q	DANDINI, V.J.	8510280470	NUREG	
COUNCIL, W.G.	8510090468	50-445	J	CRUTCHFIELD, D.	8407090045	50-382	E	DANIEL, J.A.	8510090146*	50-320	P
COUNCIL, W.G.	8510100001	50-445	Q	CRUTCHFIELD, D.	8407090263	50-382	E	DANIELSON, D.H.	8510040223*	50-461	Q
COUNCIL, W.G.	8510170183	50-445	K	CRUTCHFIELD, D.	8510010026	50-382	E	DANIELSON, D.H.	8510070307*	50-440	Q
COUNCIL, W.G.	8510180159	50-445	K	CRUTCHFIELD, D.	8510010500	50-382	E	DANIELSON, D.H.	8510070389*</		

352 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DANIELSON,D.H.	8510250137*	50-282 Q	DENTON,H.R.	8510150283	NUREG	DIGGS,R.M.	8510210254	50-329 Q
DANIELSON,D.H.	8510250173*	50-346 Q	DENTON,H.R.	8510150421	50-346 S	DIGGS,R.M.	8510260011	50-244 P
DANIELSON,D.H.	8510280351*	50-454 Q	DENTON,H.R.	8510150462	50-259 P	DIGNAN,T.G.	8510020145	50-445 G
DANIELSON,D.H.	8510280368*	50-306 Q	DENTON,H.R.	8510160115*	FOIA	DIGNAN,T.G.	8510020145	50-445 G
DANIELSON,D.H.	8510290066*	50-155 Q	DENTON,H.R.	8510160132*	FOIA	DIGNAN,T.G.	8510020268	50-445 G
DAUGHTERY,L.F.	8510080316	50-416 S	DENTON,H.R.	8510160329	NUREG	DIGNAN,T.G.	8510020268	50-445 G
DAVENPORT,J.H.	8510100121	PRM	DENTON,H.R.	8510170425	COMMISSION	DIGNAN,T.G.	8510180232	50-445 G
DAVENPORT,J.H.	8510100127*	PRM	DENTON,H.R.	8510170435	MISC	DIGNAN,T.G.	8510180232	50-445 G
DAVENPORT,J.H.	8510100133*	PRM	DENTON,H.R.	8510230262*	50-320 P	DIGNAN,T.G.	8510180255	50-445 G
DAVIDSON,D.R.	8510100116	PR	DENTON,H.R.	8510240589	50-306 Q	DIGNAN,T.G.	8510180255	50-445 G
DAVIDSON,J.M.	8510150373*	40-1366	DENTON,H.R.	8510250059	50-416 Q	DIGNAN,T.G.	8510240371	50-445 G
DAVIDSON,J.M.	8510150374*	40-1366	DENTON,H.R.	8510280028	50-220 P	DIGNAN,T.G.	8510240371	50-445 G
DAVIS,A.B.	8512230212*	50-346 Q	DENTON,H.R.	8510300093*	50-320 P	DIGNAN,T.G.	8510280518	50-445 G
DAVIS,A.B.	8510070142*	50-346 V	DENTON,H.R.	8510310333*	50-416 P	DIGNAN,T.G.	8510280518	50-445 G
DAVIS,A.B.	8510070155*	50-346 S	DENTON,H.R.	8510310478	MISC	DIGNAN,T.G.	8510290032	50-445 G
DAVIS,A.B.	8510070273*	50-346 S	DENTON,R.	8510070173	50-317 P	DIGNAN,T.G.	8510290032	50-445 G
DAVIS,J.	8510180226*	PR	DENTON,R.E.	8510180056	50-317 Q	DIGNAN,T.G.	8510290258	50-445 G
DAVIS,J.E.	8510170294	50-483 S	DENTON,R.E.	8510220268	50-317 F	DIGNAN,T.G.	8510290258	50-445 G
DAVIS,J.G.	8510090214*	PR	DESAULNIERS,R.	8510210247*	70-820	DIGON,E.	8510150291*	50-272 H
DAVIS,J.G.	8510180202*	PR	DEV,M.	8510070225*	50-423 Q	DILLON,B.E.	8510100160	PR
DAVIS,J.G.	8510180233*	PR	DEV,M.	8510250475*	50-423 Q	DIMMICK,J.	8510080598*	CONTRACT
DAVIS,J.G.	8510180314*	PR	DEVERS,J.	8510010541	50-382 E	DINGELL,J.D.	8510090385*	50-341 U
DAVIS,J.G.	8510180326*	PR	DEVERS,J.	8510010547	50-382 E	DINITZ,I.	8510300064	50-10 J
DAVIS,M.B.	8510100002	PR	DEVERS,J.	8510020079	50-382 E	DINITZ,I.	8510310052	50-244 J
DAVIS,P.	8510160187*	50-206 P	DEVERS,J.	8510020475	50-382 E	DONNE,B.J.	8510040399	NUREG
DAVISON,W.S.	8510180475	50-397 S	DEVERS,J.F.	8510020120	50-382 E	DIRCKS,W.J.	8312230206*	50-346 Q
DAVISON,W.S.	8510280186	50-397 S	DEVERS,J.K.	8510010480	50-382 E	DIRCKS,W.J.	8406210273*	50-289 P
DAWES,G.W.	8510220025	40-8778	DEVERS,J.K.	8510010484	50-382 E	DIRCKS,W.J.	8407100662	50-382 E
DAY,J.	8510090022	50-369 S	DEVERS,J.K.	8510010489	50-382 E	DIRCKS,W.J.	8408010318	50-315 U
DAY,J.	8510250164	REGGD	DEVERS,J.K.	8510010497	50-382 E	DIRCKS,W.J.	8501280086*	REVIEW GR P
DAY,J.	8510280397	50-369 S	DEVERS,J.K.	8510010508	50-382 E	DIRCKS,W.J.	8502190399*	50-346 V
DAY,J.	8510290464	50-369 S	DEVERS,J.K.	8510010513	50-382 E	DIRCKS,W.J.	8502280071*	PR
DAY,J.B.	8510170259	50-369 S	DEVINCENTIS,J.	8510030080	50-443 E	DIRCKS,W.J.	8504100552*	FOIA
DAY,P.	8510090435	FOIA	DEVINCENTIS,J.	8510080022	50-443 S	DIRCKS,W.J.	8507090487*	50-346 S
DE AGAZIO,A.	8406250404*	50-346 S	DEVINCENTIS,J.	8510100050	50-443 S	DIRCKS,W.J.	8508120712*	70-135
DE AGAZIO,A.	8410150611*	50-346 S	DEVINCENTIS,J.	8510150121	50-443 A	DIRCKS,W.J.	8509170390	COMMISSION
DE AGAZIO,A.	8510070184*	50-346 S	DEVINCENTIS,J.	8510150223	50-443 S	DIRCKS,W.J.	8510010105*	FOIA
DE AGAZIO,A.	8510170422	50-346 P	DEVINCENTIS,J.	8510150293	50-443 A	DIRCKS,W.J.	8510010115*	FOIA
DEAN,C.H.	8510280147	50-259 Q	DEVINCENTIS,J.	8510210062	50-443 A	DIRCKS,W.J.	8510010132*	FOIA
DEANE,M.R.	8510170399	FOIA	DEVINCENTIS,J.	8510250489	50-443 Q	DIRCKS,W.J.	8510010162	50-259 Q
DEBUCHANANNE,G.	8510010280*	40-8027	DEVINCENTIS,J.	8510300138	50-443 A	DIRCKS,W.J.	8510010221*	FOIA
DEHAMM,R.	8510010351*	50-382 Q	DEVINE,J.B.	8510090028	XPORTLIC	DIRCKS,W.J.	8510010400*	FOIA
DEIDENS,J.C.	8510080067	50-458 S	DEVINE,J.B.	8510150160	XPORTLIC	DIRCKS,W.J.	8510010412*	FOIA
DEESE,R.J.	8510290116*	50-460 S	DEVINE,J.B.	8510150189	XPORTLIC	DIRCKS,W.J.	8510010436*	FOIA
DELANEY,J.C.	8510150344*	40-1366	DEVINE,J.B.	8510220437	XPORTLIC	DIRCKS,W.J.	8510070102*	50-346 S
DELGEORGE,L.O.	8510070358	50-304 Q	DEVINE,T.	8510160201	50-275 P	DIRCKS,W.J.	8510070192*	50-346 S
DELLA RATTAA.	8510100211*	70-371	DEVOS, H.	8510010476	50-334 R	DIRCKS,W.J.	8510080071	70-135
DELLA RATTAA.	8510310128*	70-1100	DEWEA, J.J.G.	8510250172	50-496 F	DIRCKS,W.J.	8510080320	70-135
DELLA RATTAA.	8510310217*	70-371	DEWITT,R.B.	8510010329*	50-155 P	DIRCKS,W.J.	8510090114*	50-416 U
DELMEDICO,J.	8510070508*	50-346 U	DEWITT,R.B.	8510040181*	50-155 P	DIRCKS,W.J.	8510090223*	PR
DEMAREE,E.	8510150297	71-384	DEWITT,R.B.	8510220258*	50-255 P	DIRCKS,W.J.	8510090290*	REVIEW GR P
DENISE,R.P.	8510080123	50-445 F	DEWITT,R.B.	8510240067	50-255 K	DIRCKS,W.J.	8510150157	SECY
DENISE,R.P.	8510080194	50-445 Q	DEYOUNG,R.C.	8406040129*	PR	DIRCKS,W.J.	8510150286	50-272 H
DENISE,R.P.	8510080197	50-445 Q	DEYOUNG,R.C.	8510010091*	50-416 Q	DIRCKS,W.J.	8510150358	70-143
DENISE,R.P.	8510080213	50-445 Q	DEYOUNG,R.C.	8510040072	50-382 E	DIRCKS,W.J.	8510170099	FOIA
DENISE,R.P.	8510080362	50-445 Q	DEZUBE,D.	8510010056	FOIA	DIRCKS,W.J.	8510180192*	PR
DENISE,R.P.	8510080474	50-445 Q	DHOCGE,N.J.	8510040354	NUREG	DIRCKS,W.J.	8510230042*	50-321 U
DENISE,R.P.	8510090206	50-445 Q	DIAZ,C.	8510090364	50-454 S	DIRCKS,W.J.	8510230048*	50-321 U
DENISE,R.P.	8510100067	50-445 Q	DICK,G.	8510020133*	40-8027	DIRCKS,W.J.	8510250027	50-302 H
DENISE,R.P.	8510220286	50-445 Q	DICKERSON,B.	8510090227*	50-282 P	DIXON,O.W.	8510010212	50-395 S
DENISE,R.P.	8510220303	50-445 Q	DIEDERICH,G.J.	8510010638	50-373 R	DIXON,O.W.	8510020065	50-395 R
DENISE,R.P.	8510220455	50-445 Q	DIEDERICH,G.J.	8510020004	50-373 S	DIXON,O.W.	8510030041	50-395 P
DENISE,R.P.	8510230112	50-446 Q	DIEDERICH,G.J.	8510070317	50-373 P	DIXON,O.W.	8510040378	50-395 S
DENISE,R.P.	8510280217	50-445 Q	DIEDERICH,G.J.	8510080036	50-374 S	DIXON,O.W.	8510100026	50-395 S
DENISE,R.P.	8510290019	50-445 Q	DIEDERICH,G.J.	8510080171	50-373 R	DIXON,O.W.	8510160129	50-395 P
DENISE,R.P.	8510310116	50-382 P	DIEDERICH,G.J.	8510080269	50-373 S	DIXON,O.W.	8510230141	50-395 P
DENNY,I.L.	8510240175	40-2061	DIEDERICH,G.J.	8510170047	50-373 S	DIXON,O.W.	8510240222	50-395 P
DENNY,I.L.	8510240577	40-2061	DIEDERICH,G.J.	8510170166	50-373 R	DIXON,O.W.	8510240305	50-395 F
DENTON,H.R.	7905230274*	50-370 P	DIEDERICH,G.J.	8510180462	71-9089	DIXON,O.W.	8510250185	50-395 S
DENTON,H.R.	8007090278*	COMMISSION	DIETZ,C.R.	8510020068	50-325 S	DIXON,O.W.	8510300008	50-395 S
DENTON,H.R.	8403140316*	REVIEW GR P	DIETZ,C.R.	8510040540	50-325 S	DOBSON,D.E.	8510020085	50-382 E
DENTON,H.R.	8410110596*	COMMISSION	DIETZ,C.R.	8510070355	50-324 Q	DOOD,B.	8510290374	50-243 R
DENTON,H.R.	8507110595*	REVIEW GR P	DIETZ,C.R.	8510080529	50-325 S	DOODS,R.	8510010196	50-344 S
DENTON,H.R.	8508010123*	MISC	DIETZ,C.R.	8510080537	50-325 S	DOODS,R.I.	8510090245*	50-344 Q
DENTON,H.R.	8508010540	MISC	DIETZ,C.R.	8510090018	50-325 S	DOODS,R.T.	8510090257*	50-508 Q
DENTON,H.R.	8510020122	MISC	DIETZ,C.R.	8510090027	50-324 S	DOODS,R.T.	8510280159*	50-344 Q
DENTON,H.R.	8510030239	NUREG	DIETZ,C.R.	8510090342	50-324 S	DOODS,R.E.	8510010422	50-244 R
DENTON,H.R.	8510030424	50-259 P	DIETZ,C.R.	8510160321	50-324 R	DOODSON,M.E.	8510040347	NUREG
DENTON,H.R.	8510040408	50-317 Q	DIETZ,C.R.	8510250198	50-325 S	DOHERTY,J.F.	8510100130	PR
DENTON,H.R.	8510070198*	COMMISSION	DIETZ,C.R.	8510260077	50-325 S	DOHERTY,J.F.	8510100151*	PR
DENTON,H.R.	8510070361	50-338 P	DIETZ,C.R.	8510280261	50-325 S	DOLAN,F.X.	8510020217	NUREG
DENTON,H.R.	8510070527	MISC	DIETZ,C.R.	8510280440	50-325 S	DOLAN,F.X.	8510020227	NUREG
DENTON,H.R.	8510090295	NUREG	DIETZ,C.R.	8510310065	50-324 S	DOMER,J.A.	8510010048	50-327 P
DENTON,H.R.	8510090334	50-289 P	DIETZ,C.R.	8510310171	50-324 Q	DOMER,J.A.	8510010087	50-259 F
DENTON,H.R.	8510090340	50-259 P	DIGGS,R.M.	8510080551	50-309 P	DOMER,J.A.	8510100379	50-390 F
DENTON,H.R.	8510090411	50-498 A	DIGGS,R.M.	8510110159	50-315 P	DOMER,J.A.	8510040132	50-390 F
DENTON,H.R.	8510090509	50-522 A	DIGGS,R.M.	8510150311	50-382 P	DOMER,J.A.	8510070335	50-259 Q
DENTON,H.R.	8510150231	MISC	DIGGS,R.M.	8510180005	50-346 P	DOMER,J.A.	8510070336	50-259 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		
DOMER, J.A.	8510070486	50-259	Q	EBNETER, S.D.	8510010177	50-443	Q	EDGEWORTH, P.J.	8510030149*	CONTRACT
DOMER, J.A.	8510090012	50-390*	A	EBNETER, S.D.	8510020044	50-277	Q	EDGEWORTH, P.J.	8510030162*	CONTRACT
DOMER, J.A.	8510150106	50-327	P	EBNETER, S.D.	8510030037	50-309	Q	EDGEWORTH, P.J.	8510030192*	CONTRACT
DOMER, J.A.	8510160136	50-438	A	EBNETER, S.D.	8510040330	50-423	Q	EDGEWORTH, P.J.	8510030404*	50-445
DOMER, J.A.	8510160265	50-327	P	EBNETER, S.D.	8510070211	50-423	Q	EDGEWORTH, P.J.	8510040129*	CONTRACT
DOMER, J.A.	8510180048	50-327	Q	EBNETER, S.D.	8510070254	50-322	Q	EDGEWORTH, P.J.	8510040157*	CONTRACT
DOMER, J.A.	8510180069	50-259	Q	EBNETER, S.D.	8510070536	50-423	Q	EDGEWORTH, P.J.	8510040499*	CONTRACT
DOMER, J.A.	8510220196	50-390	F	EBNETER, S.D.	8510080184	50-286	Q	EDGEWORTH, P.J.	8510040571*	CONTRACT
DOMER, J.A.	8510230024	50-259	P	EBNETER, S.D.	8510080223	50-271	Q	EDGEWORTH, P.J.	8510040583*	CONTRACT
DOMER, J.A.	8510290012	50-390	F	EBNETER, S.D.	8510080392	50-443	Q	EDGEWORTH, P.J.	8510040603*	CONTRACT
DOMER, J.A.	8510290097	50-390	A	EBNETER, S.D.	8510080416	50-277	Q	EDGEWORTH, P.J.	8510070078*	CONTRACT
DOMER, J.A.	8510290159	50-327	P	EBNETER, S.D.	8510080593	50-245	Q	EDGEWORTH, P.J.	8510070089*	CONTRACT
DOMER, J.A.	8510290296	50-327	F	EBNETER, S.D.	8510100064	50-410	Q	EDGEWORTH, P.J.	8510080130*	CONTRACT
DOMER, J.A.	8510290331	50-327	F	EBNETER, S.D.	8510110013	50-412	Q	EDGEWORTH, P.J.	8510080159*	CONTRACT
DOMER, J.A.	8510310184	50-327	F	EBNETER, S.D.	8510110082	50-423	Q	EDGEWORTH, P.J.	8510080191*	CONTRACT
DOMER, J.A.	8510310233	50-327	Q	EBNETER, S.D.	8510160014	50-245	Q	EDGEWORTH, P.J.	8510080354*	CONTRACT
DOMER, J.A.	8510310259	50-390	F	EBNETER, S.D.	8510170254	50-322	Q	EDGEWORTH, P.J.	8510110103*	CONTRACT
DOMINGUEZ, G.	8510290498	XPORTLIC		EBNETER, S.D.	8510170287	50-423	Q	EDGEWORTH, P.J.	8510160324*	CONTRACT
DONAHUE, J.F.	8510170273*	FOIA		EBNETER, S.D.	8510180057	50-423	Q	EDGEWORTH, P.J.	8510160333*	CONTRACT
DONLON, W.J.	8510250418	50-220	P	EBNETER, S.D.	8510210113	50-410	Q	EDGEWORTH, P.J.	8510310370*	CONTRACT
DONLON, W.J.	8510250426*	50-220	P	EBNETER, S.D.	8510210219	50-322	Q	EDSON, J.L.	8510030430	NUREG
DONOHUE, J.	8510220137*	50-445	A	EBNETER, S.D.	8510220010	50-352	Q	EDWARDS, D.W.	8510250341	NUREG
DONOHUE, J.N.	8510020064	50-219	P	EBNETER, S.D.	8510220057	50-412	Q	EGGEBROTEN, J.	8510170457	50-267
DONOHUE, J.N.	8510290625	50-219	P	EBNETER, S.D.	8510230095	50-443	Q	EGGEBROTEN, J.	8510170462	50-267
DONOVAN, M.D.	8510040318	NUREG		EBNETER, S.D.	8510230138	50-336	Q	EGGEBROTEN, J.	8510220436	50-267
DOOITTLE, E.	8510150009	50-423	A	EBNETER, S.D.	8510230193	50-247	Q	EGGEBROTEN, J.	8510240158	50-267
DOOITTLE, E.L.	8510150010	50-423	A	EBNETER, S.D.	8510230201	50-352	Q	EGGEBROTEN, J.	8510310165	50-267
DOOITTLE, E.L.	8510210170	50-423	F	EBNETER, S.D.	8510250132	50-277	Q	EGGERT, R.R.	8510210002	40-2061
DOOITTLE, E.L.	8510290386	50-423	A	EBNETER, S.D.	8510250162	50-333	Q	EIFFERT, W.M.	8510110192*	50-423
DOROSHOW, J.	8510110156	50-289	G	EBNETER, S.D.	8510250260	50-293	Q	EISENHUT, D.G.	8312210021*	COMMISSION
DOROSHOW, J.	8510230039	50-289	G	EBNETER, S.D.	8510250412	50-423	Q	EISENHUT, D.G.	8406260464	50-382
DOUGHERTY, J.B.	8510220201	50-322	G	EBNETER, S.D.	8510250442	50-354	Q	EISENHUT, D.G.	8412100470*	50-445
DOUGHERTY, J.B.	8510220201	50-322	G	EBNETER, S.D.	8510250443	50-423	Q	EISENHUT, D.G.	8510040357*	50-320
DOUGHERTY, J.B.	8510220240	50-338	G	EBNETER, S.D.	8510250470	50-423	Q	EISENHUT, D.G.	8510070088	MISC
DOUGHERTY, J.B.	8510220240	50-338	G	EBNETER, S.D.	8510280336	50-277	Q	EISENHUT, D.G.	8510070181*	COMMISSION
DOUGHERTY, J.B.	8510220264	50-338	G	EBNETER, S.D.	8510280350	50-244	Q	EISENHUT, D.G.	8510070504*	50-346
DOUGHERTY, J.B.	8510220314	50-322	G	ECKHART, D.E.	8510010586*	COMMISSION		EISENHUT, D.G.	8510170480*	50-445
DOUGHERTY, J.B.	8510220314	50-322	G	ECKHART, J.	8510080052	50-312	S	EISENHUT, D.G.	8510220154*	50-445
DOUGHERTY, J.B.	8510220314	50-322	G	ECKHART, J.	8510160240	50-312	S	EISENHUT, D.G.	8510220161*	50-445
DOUGHERTY, T.	8510100046*	50-333	Q	ECKHART, J.H.	8510070331	50-312	S	EISENHUT, D.G.	8510220202*	50-445
DOUGHTY, J.	8510070297	NUREG		ECONOMOS, N.	8510070500*	50-269	Q	EISENHUT, D.G.	8510220215*	50-445
DOUGLAS, J.L.	8510170041*	FOIA		EDDELMAN, W.	8510030009	50-400	G	EISENHUT, D.G.	8510220225*	50-445
DOUGLAS, J.L.	8510170064*	FOIA		EDDELMAN, W.	8510030082	50-400	G	EISENHUT, D.G.	8510240379*	50-320
DOUGLAS, R.P.	8510290373	50-354	F	EDDELMAN, W.	8510100208	50-400	G	EISENHUT, D.G.	8510280088*	50-320
DOWNEY, T.J.	8510010536*	50-322	U	EDDELMAN, W.	8510160159	50-400	G	ELLERSHAW, L.E.	8510280254*	50-445
DRAGO, J.P.	8510220043	50-213	S	EDELMAN, M.	8510250175	50-440	A	ELLIS, J.	8510280520	50-445
DRAGOUN, T.	8510040172*	50-29	Q	EDELMAN, M.R.	8510010038	50-440	A	ELLIS, W.P.	8510170060*	FOIA
DRAGOUN, T.	8510250497*	50-272	Q	EDELMAN, M.R.	8510010077	50-440	E	ELLWANGER, J.R.	8510250178	50-247
DRAGOUN, T.D.	8510080032*	50-244	Q	EDELMAN, M.R.	8510010276	50-440	F	ELLWANGER, J.R.	8510290071	50-247
DRAGOUN, B.	8510080432*	50-461	Q	EDELMAN, M.R.	8510010374	50-440	A	ELLWANGER, J.R.	8510300030	50-247
DROVIN, B.	8510210153*	50-346	Q	EDELMAN, M.R.	8510010485	50-440	A	ELROD, S.A.	8510180429*	50-335
DROVIN, B.	8510290115*	50-409	Q	EDELMAN, M.R.	8510010478	50-440	S	ELSASSER, T.	8510030090	50-317
DRUGA, R.J.	8510150221	50-334	S	EDELMAN, M.R.	8510030003	50-440	A	ELSASSER, T.	8510160128	50-317
DRUGA, R.J.	8510170452	50-334	S	EDELMAN, M.R.	8510030067	50-440	F	ELSASSER, T.C.	8510080121*	50-309
DRUM, D.E.	8510110198	PR		EDELMAN, M.R.	8510070348	50-440	V	ELSASSER, T.C.	8510250435*	50-317
DUBOIS, D.	8510090335	XPORTLIC		EDELMAN, M.R.	8510080019	50-440	S	EMERSON, R.	8510290174*	50-344
DUBOIS, D.L.	8510220464*	50-298	Q	EDELMAN, M.R.	8510080399	50-440	A	EMRICH, W.J.	8510020124	50-219
DUBOIS, D.P.	8510080619	WASTE MGT		EDELMAN, M.R.	8510080406	50-440	A	ENG, P.L.	8510290089*	50-331
DUDLEY, N.F.	8510110112*	50-317	Q	EDELMAN, M.R.	8510080446	50-440	F	ENGELMANN, R.	8510170299	40-8745
DUDLEY, N.F.	8510250078*	50-57	Q	EDELMAN, M.R.	8510080454	50-440	F	ENGLE, L.B.	8510180015	50-338
DUGAN, J.S.	8510010491	50-155	R	EDELMAN, M.R.	8510080477	50-440	A	ENGLE, L.B.	8510180016*	50-338
DUGGIN, G.	8510010617	50-327	S	EDELMAN, M.R.	8510080508	50-440	F	ENGLE, L.B.	8510180076	50-338
DUGGIN, G.	8510030355	50-327	S	EDELMAN, M.R.	8510090053	50-440	K	ENNIS, J.D.	8510080284*	50-327
DUGGIN, G.	8510040102	50-327	S	EDELMAN, M.R.	8510100009	50-440	S	ENNIS, J.D.	8510080288*	50-335
DUGGIN, G.	8510150455	50-327	S	EDELMAN, M.R.	8510150388*	50-440	G	ENOS, J.T.	8510010479	50-313
DUGSTAD, D.	8510010650	50-282	R	EDELMAN, M.R.	8510160029	50-440	E	ENOS, J.T.	8510010482	50-368
DUNLAP, J.M.	8510080346*	50-219	Q	EDELMAN, M.R.	8510160210	50-440	A	ENOS, J.T.	8510010645	50-368
DUNLEAVY, J.J.	8510170334*	50-264	Q	EDELMAN, M.R.	8510180082	50-440	A	ENOS, J.T.	8510020081	50-313
DUNMAN, L.E.	8510100137	PR		EDELMAN, M.R.	8510220141	50-440	Q	ENOS, J.T.	8510070237	50-368
DUNN, P.S.	8510010356*	40-8027		EDELMAN, M.R.	8510220333	50-440	F	ENOS, J.T.	8510080356	50-313
DUNN, P.S.	8510010363*	FOIA		EDELMAN, M.R.	8510220362	NUREG		ENOS, J.T.	8510160001	TOPREP
DUPONT, R.L.	8510290049*	50-400	T	EDELMAN, M.R.	8510220381	50-440	S	ENOS, J.T.	8510160066	50-313
DUPONT, R.L.	8510290049*	50-400	T	EDELMAN, M.R.	8512250214	50-440	F	ENOS, J.T.	8510160137	TOPREP
DUPONT, R.L.	8510290049*	50-400	T	EDELMAN, M.R.	8510250422	50-440	F	ENOS, J.T.	8510160253	50-313
DURBIN, P.W.	8510020240	NUREG		EDELMAN, M.R.	8510250464	50-440	V	ENOS, J.T.	8510170034	50-313
DURFEE, P.J.	8510180521	71-133	Q	EDELMAN, M.R.	8510290011	50-440	A	ENOS, J.T.	8510170410*	50-313
DUTTON, D.E.	8510010324	50-259	Q	EDELMAN, M.R.	8510290340	50-440	F	ENOS, J.T.	8510220046	50-313
DUTTON, D.E.	8510010324	50-259	Q	EDELMAN, M.R.	8510300129	50-440	S	ENOS, J.T.	8510220056	50-368
DWYER, P.	8510180244*	PR		EDELMAN, M.R.	8510310249	50-440	A	ENOS, J.T.	8510220203	50-368
DWYER, P.	8510180251*	PR		EDELMAN, M.R.	8510310255*	50-440	A	ENOS, J.T.	8510220332*	50-313
DWYER, P.A.	8510180209*	PR		EDELMAN, M.R.	8510310269	50-440	S	ENOS, J.T.	8510240328	50-313
DYER, J.E.	8510150146*	50-267	Q	EDELMAN, M.R.	8510310550	50-440	S	ENOS, J.T.	8510250189	50-308
DYKSTRA, P.	8510090227*	50-282	P	EDGAR, B.	8510080077*	70-135		ENOS, J.T.	8510250421*	50-313
EAPEN, P.K.	8510080236*	50-271	Q	EDGAR, E.C.	8510240248	50-244	S	ENOS, J.T.	8510260218	50-368
EAPEN, P.K.	8510090401*	50-443	Q	EDGEWORTH, P.J.	8510010005*	CONTRACT		ENTINE, G.	8510040383	PR
EAPEN, P.K.	8510110019*	50-412	Q	EDGEWORTH, P.J.	8510010092*	50-445	A	EPPELSON, W.A.	8510010376*	50-382
EASLEY, P.	8510020257	50-423	A	EDGEWORTH, P.J.	8510010149*	CONTRACT		EPPELSON, W.A.	8510180507	FOIA
EBERSOLE, P.N.	8510090020	50-259	S	EDGEWORTH, P.J.	8510010258*	CONTRACT		ERNST, M.L.	8510180363	50-416

354 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY			
ESCHELS,C.	8510220080*	50-397	P	FELTON,J.M.	8510090063	27-39	FISCHER,D.	8510040533	50-311	P	
ESCHELS,C.	8510290381	50-397	P	FELTON,J.M.	8510090076	FOIA	FISCHER,D.	8510070023	50-272	P	
ESELGROTH,P.	8510070260*	50-322	Q	FELTON,J.M.	8510090091	FOIA	FISCHER,D.	8510080033*	50-329	O	
ESELGROTH,P.	8510210117*	50-410	Q	FELTON,J.M.	8510090099	50-416	FISCHER,D.	8510080088*	50-329	O	
ESELGROTH,P.	8510210228*	50-322	Q	FELTON,J.M.	8510090143	40-1193	FISCHER,D.	8510080143*	50-329	O	
ESELGROTH,P.	8510220017*	50-352	Q	FELTON,J.M.	8510090203*	PR	FISCHER,D.	8510080386*	50-330	O	
ESELGROTH,P.	8510230208*	50-352	Q	FELTON,J.M.	8510090441	FOIA	FISCHER,D.	8510080394*	50-330	O	
ESELGROTH,P.	8510250445*	50-354	Q	FELTON,J.M.	8510090477	FOIA	FISCHER,D.	8510080397*	50-330	O	
ESELGROTH,P.W.	8510040335*	50-423	Q	FELTON,J.M.	8510090484	FOIA	FISCHER,D.	8510080420*	50-330	O	
ESELGROTH,P.W.	8510070538*	50-423	Q	FELTON,J.M.	8510150142	40-1366	FISCHER,D.	8510080435*	50-329	O	
ESELGROTH,P.W.	8510230143*	50-336	Q	FELTON,J.M.	8510150440	50-445	Q	FISCHER,D.	8510080438*	50-329	A
ESELGROTH,P.W.	8510250417*	50-423	Q	FELTON,J.M.	8510160084	50-220	Q	FISCHER,D.	8510080448*	50-329	O
ESKRIDGE,H.E.	8510150084	70-36		FELTON,J.M.	8510160092	FOIA	FISCHER,D.C.	8209020126*	50-329	O	
EVANS,C.S.	8510100158	PR		FELTON,J.M.	8510160099	FOIA	FISCHER,D.C.	8510080239*	50-329	O	
EVANS,D.D.	8510290415	NUREG		FELTON,J.M.	8510160103	FOIA	FISCHER,D.C.	8510080391*	50-330	O	
EVANS,M.	8510250445*	50-354	Q	FELTON,J.M.	8510160174	50-206	P	FISCHER,D.C.	8510080403*	50-330	O
EVANS,M.A.	8510250417*	50-423	Q	FELTON,J.M.	8510160205	50-275	P	FISCHER,D.C.	8510080441*	50-329	O
EVANS,N.A.	8510010404*	40-8027		FELTON,J.M.	8510160305	40-672		FISCHER,D.C.	8510170161	50-272	F
EVANS,N.A.	8510010408*	40-8027		FELTON,J.M.	8510170019	40-8355		FISCHER,K.P.	8510110068	70-364	
EVOLA,J.H.	8510170440	50-213	S	FELTON,J.M.	8510170048	50-206	P	FISCHER,K.P.	8510110098	70-364	
EVOLA,J.H.	8510240462	50-213	S	FELTON,J.M.	8510170085	50-206	P	FISCHER,K.P.	8510150264	70-364	
EWALD,J.J.	8510030335	50-454	S	FELTON,J.M.	8510170095	FOIA		FISCHER,S.R.	8510180083*	50-416	P
FABIC,S.	8510080128*	CONTRACT		FELTON,J.M.	8510170108	50-445	A	FISCHMAN,A.	8510010171	FOIA	
FAIRFIE,M.B.	8510310034	50-305	P	FELTON,J.M.	8510170221	50-264	Q	FISH,R.F.	8510030241	50-312	F
FANNON,M.M.	8510240111	WASTE RES		FELTON,J.M.	8510170346	50-413	Q	FISH,R.F.	8510070199	50-344	F
FARRAR,A.O.	8510010258*	CONTRACT		FELTON,J.M.	8510170418	FOIA		FISH,R.F.	8510300057	50-275	F
FARRAR,D.L.	8510010434	50-454	Q	FELTON,J.M.	8510180163	FOIA		FISHER,B.O.	8510170393	40-8674	
FARRAR,D.L.	8510040246	50-454	Q	FELTON,J.M.	8510180170	FOIA		FISHER,R.C.	8510240254	50-334	S
FARRAR,D.L.	8510080222	50-373	Q	FELTON,J.M.	8510180182	FOIA		FISHMAN,J.B.	8510100065	PR	
FARRAR,D.L.	8510080408	50-373	Q	FELTON,J.M.	8510180229*	PR		FLACK,E.	8510240413	50-271	Q
FARRAR,D.L.	8510100043	50-373	F	FELTON,J.M.	8510180237*	PR		FLACK,E.	8510290363	I&E	
FARRAR,D.L.	8510110012	50-373	Q	FELTON,J.M.	8510180279*	PR		FLACK,G.	8510250368	PR	
FARRAR,D.L.	8510160178	50-456	Q	FELTON,J.M.	8510180391	FOIA		FLACK,I.E.	8510220189	I&E	
FARRAR,D.L.	8510250231	50-237	Q	FELTON,J.M.	8510180394	50-445	A	FLAHERTY,J.M.	8510090381	50-249	S
FARRAR,D.L.	8510280170	50-295	F	FELTON,J.M.	8510180400	FOIA		FLAHERTY,J.P.	8510280404*	50-333	S
FARRELL,R.	8510020321	50-382	E	FELTON,J.M.	8510180408	50-447	A	FLEENOR,C.	8510080081	CONTRACT	
FARREN,J.	8510020312	50-382	E	FELTON,J.M.	8510180414	50-445	A	FLEENOR,C.	8510080572	CONTRACT	
FARREN,J.	8510020349	50-382	E	FELTON,J.M.	8510180442	50-289	P	FLEMING,K.N.	8510090212*	50-327	P
FARREN,J.	8510030050	50-382	E	FELTON,J.M.	8510180467	50-483	P	FLEMING,K.N.	8510090220*	50-327	P
FARREN,J.	8510030060	50-382	E	FELTON,J.M.	8510180511	FOIA		FLIPPO,T.A.	8510310291*	50-382	Q
FARREN,J.W.	8510020188	50-382	E	FELTON,J.M.	8510220125	50-382	P	FLOR,W.J.	8510180526*	71-133	
FARRIS,C.J.	8510100055	50-483	F	FELTON,J.M.	8510220134	FOIA		FLOREK,D.	8510070260*	50-322	Q
FASANO,A.N.	8510020371	50-382	E	FELTON,J.M.	8510220182	50-410	A	FLOREK,D.	8510210228*	50-322	Q
FAUBER,J.R.	8510170430	40-8502	E	FELTON,J.M.	8510220167	70-25	F	FLOREK,D.	8510220017*	50-352	Q
FAULKNER,M.	8510290111	50-483	F	FELTON,J.M.	8510220197	50-424	A	FLOREK,D.	8510230208*	50-352	Q
FAW,R.E.	8510170386	50-188	R	FELTON,J.M.	8510220426	FOIA		FLYNN,M.	8510010006	CONTRACT	
FAY,C.W.	8510080389	50-266	P	FELTON,J.M.	8510230016	50-10	U	FOLECK,R.H.	8510250392	PR	
FAY,C.W.	8510100128	50-266	S	FELTON,J.M.	8510250336	50-445	A	FOLEY,T.	8510160128	50-317	S
FAY,C.W.	8510160006	50-266	P	FELTON,J.M.	8510250358	FOIA		FOLEY,T.	8510250435*	50-317	Q
FAY,C.W.	8510180502	50-266	R	FENECH,R.A.	8510080056	50-255	S	FONKEN,G.J.	8510160155	50-602	A
FAY,C.W.	8510220439	50-266	S	FENECH,R.A.	8510170016	50-255	S	FONKEN,G.J.	8510160286	50-602	F
FAY,C.W.	8510230111*	50-266	F	FENECH,R.A.	8510210294	50-255	S	FORD,D.	8510020013	50-382	E
FAY,C.W.	8510290043	50-266	P	FENSTERMACHER	8510250359*	50-289	F	FORD,D.	851020469	50-382	E
FEE,W.F.	8510030426	50-423	S	FENSTERSTOCK,J.	8510080376*	CONTRACT		FORD,D.	8510020473	50-382	E
FEE,W.F.	8510030426	50-423	S	FENSTERSTOCK,J.	8510150481*	CONTRACT		FORD,D.	8510020478	50-382	E
FEE,W.F.	8510040433	50-423	E	FERKIN,Z.G.	8510310319	50-352	G	FORD,D.	8510020485	50-382	E
FEE,W.F.	8510100180	50-423	A	FEY,F.L.	8510080505	50-263	F	FORD,D.	8510030180	50-382	E
FEE,W.F.	8510220145	50-423	A	FEY,F.L.	8510160181	50-282	F	FORD,D.	8510030170	50-382	E
FEE,W.F.	8510220158	50-213	P	FEY,F.L.	8510230121	50-282	R	FORD,D.	8510030397	50-382	E
FEE,W.F.	8510220158	50-213	P	FEY,F.L.	8510240242	50-263	F	FORD,D.	8510030402	50-382	E
FEE,W.F.	8510220158	50-213	P	FEY,F.L.	8510260055	50-263	F	FOREHAND,G.L.	8510290041*	50-400	T
FEE,W.F.	8510220313	50-245	P	FEY,F.L.	8510310304	50-282	F	FORGETTE,T.E.	8510080516	50-317	F
FEE,W.F.	8510300271	50-423	S	FIEDLER,P.	8510280126	50-219	P	FORNEY,W.L.	8510010416*	50-455	Q
FEE,W.F.	8510300271	50-423	S	FIEDLER,P.B.	8510020124	50-219	R	FORNEY,W.L.	8510210013*	50-454	Q
FEE,W.F.	8510310126	50-245	P	FIEDLER,P.B.	8510070277	50-219	R	FORSYTHE,F.F.	8510230188*	50-387	Q
FEE,W.F.	8510310220	50-423	K	FIEDLER,P.B.	8510070474	50-219	P	FORT,D.	8510110174	PR	
FEHRINGER,D.J.	8510310448	NUREG		FIEDLER,P.B.	8510110072*	50-219	P	FOSTER,D.O.	8510030025	50-424	Q
FEIL,R.A.	8510020368	50-382	E	FIEDLER,P.B.	8510150348	50-219	S	FOSTER,D.O.	8510230073	50-424	A
FELICIONE,F.S.	8510030054*	50-424	F	FIEDLER,P.B.	8510160072	50-219	P	FOULKE,J.D.	8507160166*	PR	
FELTON,J.M.	8510010054	FOIA		FIEDLER,P.B.	8510160091	50-219	F	FOX,M.	8510080299*	CONTRACT	
FELTON,J.M.	8510010057	50-416	Q	FIEDLER,P.B.	8510160073	50-219	P	FRALEY,R.F.	8510080094*	50-329	O
FELTON,J.M.	8510010060	40-8006		FIEDLER,P.B.	8510240103	50-219	P	FRALEY,R.F.	8510080127*	50-329	A
FELTON,J.M.	8510010061	FOIA		FIEDLER,P.B.	8510280126	50-219	P	FRALEY,R.F.	8510080132*	50-329	O
FELTON,J.M.	8510010064	50-289	P	FIEDLER,P.B.	8510290172	50-219	P	FRALEY,R.F.	8510080309*	50-329	O
FELTON,J.M.	8510010066	FOIA		FIEDLER,P.B.	8510290252	50-219	P	FRALEY,R.F.	8510080357*	50-237	O
FELTON,J.M.	8510010158	FOIA		FIEDLER,P.B.	8510290321	50-219	P	FRALEY,R.F.	8510170067*	50-206	O
FELTON,J.M.	8510010179	FOIA		FIELDS,J.S.	8510080084	50-390	J	FRANK,L.	8510240553	WASTE MGT	
FELTON,J.M.	8510010197	50-443	Q	FIELDS,J.S.	8510020139	50-387	R	FRANKUM,D.C.	8510150451*	50-445	A
FELTON,J.M.	8510010207	FOIA		FIELDS,J.S.	8510170201	50-387	P	FRANTZ,H.F.	8510180214	50-250	G
FELTON,J.M.	8510010218	FOIA		FIELDS,J.S.	8510220060	50-387	P	FRANTZ,H.F.	8510180214	50-250	G
FELTON,J.M.	8510010225	50-206	P	FINKEL,A.	8510250475*	50-423	Q	FRANTZ,S.P.	8510180320	50-250	G
FELTON,J.M.	8510010283	50-321	S	FINKEL,A.E.	8510060401*	50-443	Q	FRANTZ,S.P.	8510180320	50-250	G
FELTON,J.M.	8510010387	50-364	V	FINKEL,A.E.	8510170288*	50-423	Q	FRED,B.L.	8510020051	50-382	E
FELTON,J.M.	8510010455*	FOIA		FINKEL,A.E.	8510250417*	50-423	Q	FREDRICKSON,P.	8510040510*	50-324	Q
FELTON,J.M.	8510080023	50-329	A	FINKELSTEIN,L.	8510160280	50-289	G	FREDRICKSON,P.	8510090333*	50-400	Q
FELTON,J.M.	8510090023	FOIA		FIORILLI,G.	8510220075*	50-528	Q	FREDRICKSON,P.	8510180435*	50-261	Q
FELTON,J.M.	8510090039	50-346	P	FIRESTONE,J.D.	8510020396	50-382	E	FREDRICKSON,P.	8510280510	50-400	T
FELTON,J.M.	8510090049	FOIA		FISCHER,D.	8510040518	50-272	P	FREED,B.	8510040119	50-382	E

PERSONAL AUTHOR INDEX 355

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FREED,B.L.	8510020267	50-382 E	GEORGE,D.R.	8510150420*	FOIA	GRANDBOUCHE,G.	8510240263	WASTE MGT
FREED,B.L.	8510020267	50-382 E	GIAMBUSSO,A.	8510160141*	FOIA	GRANT,D.C.	8510240192*	WASTE MGT
FREEMAN,M.D.	8510170332	40-8768	GIBBONS,T.D.	8510180383*	50-417 Q	GRANT,J.M.	8510080401*	50-443 Q
FRIAS,R.	8510010440	TOPRE	GIBSON,L.S.	8510090382*	50-315 S	GRANT,N.W.	8510010477	50-250 R
FRIEDMAN,L.	8510170112*	FOIA	GIESEKER,J.W.	8510110136*	50-456 G	GRANT,W.B.	8510160125*	50-282 Q
FRIEDMAN,L.	8510170126*	FOIA	GIESLER,C.W.	8510010282	50-305 P	GRAVES,M.D.	8510100078	PR
FRIEDMAN,L.	8510170130*	FOIA	GIESLER,C.W.	8510150392	50-305 P	GRAVES,R.H.	8510010008	50-213 S
FRIEDMAN,L.	8510170132*	FOIA	GIESLER,C.W.	8510250452	50-305 P	GRAVES,R.H.	8510090248	50-213 S
FRIEDMAN,L.	8510170142*	FOIA	GIGLIOTTI,R.J.	8510150119	70-371	GRAVES,R.H.	8510170440	50-213 S
FRIEDMAN,L.	8510170173*	FOIA	GILBERT,L.D.	8510230115*	50-446 Q	GRAVES,R.H.	8510220043	50-213 S
FRIEDMAN,R.M.	8510280508	WASTE MGT	GILINSKY,V.	8311290224*	50-346 S	GRAVES,R.H.	8510104662	50-213 S
FRISCH,R.R.	8510150298	50-155 P	GILLAND,B.	8510170438*	MISC	GRAVES,R.H.	8510104663	50-213 S
FRISCH,R.R.	8510170016	50-255 S	GILLEN,D.M.	8510280063	WASTE MGT	GRAVES,R.H.	8510300296	50-213 S
FRISCH,R.R.	8510180380	50-155 P	GILLEN,D.M.	8510280153	WASTE MGT	GRAY,E.H.	8510020050*	50-277 Q
FRISCH,R.R.	8510220256	50-155 P	GILLEN,D.M.	8510280156	WASTE MGT	GRAY,L.H.	8510040318	NUREG
FRISCO,D.C.	8510100102	PR	GILLEN,D.M.	8510280504	WASTE MGT	GRAYSON,R.M.	8510110014*	50-423 A
FROENHUCH,C.H.	8510090042*	50-265 Q	GILLEN,K.T.	8510040354	NUREG	GREEN,H.J.	8510180083*	50-416 P
FROGNER,B.	8510090439*	CONTRACT	GILLESPIE,F.P.	8510180256*	PR	GREENSPUN,J.S.	8510180450*	FOIA
FROUNFELKER,R.	8510080556	50-155 J	GLEASON,J.P.	8510100028	50-440 G	GREEVES,J.T.	8510240303	WASTE MGT
FRYE,J.H.	8510180120	40-2061	GLENN,J.	8510080029	I&E	GREEVES,J.T.	8510240460	WASTE MGT
FRYE,J.H.	8510180172	40-8027	GLENN,J.	8510170146*	FOIA	GREEVES,J.T.	8510280084	27-48
FRYE,J.H.	8510180247	50-142 G	GLENN,J.E.	8510170112*	FOIA	GREEVES,J.T.	8510290167	WASTE MGT
FRYE,J.H.	8510170457	40-2061	GLENN,J.E.	8510170130*	FOIA	GREEVES,J.T.	8510290176	WASTE MGT
FUNCHES,J.L.	8510070091*	50-382 E	GLENN,J.E.	8510170132*	FOIA	GREEVES,J.T.	8510290266	WASTE MGT
FUNCHES,J.L.	8510220171*	50-445 A	GLENN,J.E.	8510170142*	FOIA	GREEVES,J.T.	8510300174	27-48
FURR,A.K.	8510280150	50-124 P	GLENN,J.E.	8510170173*	FOIA	GREGER,L.R.	8510010180*	50-266 Q
GAD,R.K.	8510290004	50-445 G	GLOVIER,H.A.	8510150038	50-333 R	GREGER,L.R.	8510070472*	50-409 Q
GAGLIARDO,J.	8510010320*	50-382 Q	GNUGNOLI,G.	8510280446	WASTE MGT	GREGER,L.R.	8510160125*	50-282 Q
GAHM,J.W.	8510010010	50-267 P	GNUGNOLI,G.N.	8510300236	40-6500	GREGER,L.R.	8510220420*	50-295 Q
GAHM,J.W.	8510080007	50-267 F	GOFFREY,D.	8510030131	NUREG	GREGER,L.R.	8510310294*	50-2 Q
GAHM,J.W.	8510080219	50-267 P	GOODWIN,S.G.	8510010231	50-269 S	GRIFFIN,D.G.	8510100158	PR
GAHM,J.W.	8510090077	50-267 Q	GOODWIN,S.G.	8510090535	50-287 S	GRIFFITH,P.	8510020307	NUREG
GAHM,J.W.	8510170457	50-267 S	GOLDBERG,J.H.	8510010095	50-498 S	GRIFFITH,W.L.	8510180355*	50-423 A
GAHM,J.W.	8510170462	50-267 S	GOLDBERG,J.H.	8510010144	50-498 Q	GRIMES,B.K.	8510070357	50-400 Q
GAHM,J.W.	8510180168	50-267 F	GOLDBERG,J.H.	8510040457	50-498 A	GRIMES,B.K.	8510310327	50-254 Q
GAHM,J.W.	8510220407	50-267 R	GOLDBERG,J.H.	8510080464	50-498 A	GRIMES,C.I.	8510020435	50-245 P
GAHM,J.W.	8510220436	50-267 S	GOLDBERG,J.H.	8510080595*	50-498 Q	GRODY,W.D.	8510100086	50-280 F
GAHM,J.W.	8510240158	50-267 S	GOLDBERG,J.H.	8510090117	50-498 S	GROELSEMA,D.H.	8510090152	WASTE MGT
GAHM,J.W.	8510310165	50-267 S	GOLDBERG,J.H.	8510090138	50-498 S	GROESCH,G.	8510040454	50-382 E
GAHM,J.W.	8510310307*	50-267 Q	GOLDBERG,J.H.	8510210044	50-498 E	GROSSBERG,S.	8510010188	50-443 Q
GAHM,J.W.	8510310532*	50-267 Q	GOLDBERG,J.H.	8510210301	50-498 S	GROSSMAN,H.	8510020235	50-456 G
GAHM,J.W.	8510090538	WASTE MGT	GOLDBERG,J.H.	8510220302	50-498 F	GROSSMAN,H.	8510030019	50-456 G
GAHM,J.W.	8510280172	WASTE MGT	GOLDBERG,J.H.	8510220309	50-498 A	GROSSMAN,H.	8510030065	50-456 G
GALLAGHER,D.	8510020438*	50-245 P	GOLDBERG,J.H.	8510220360*	50-498 Q	GROSSMAN,H.	8510100091	50-456 G
GALLO,J.	8510040329	50-456 G	GOLDBERG,J.H.	8510220481	50-498 S	GROSSMAN,H.	8510100183	50-456 G
GALLO,J.	8510040329	50-456 G	GOLDBERG,J.H.	8510250309	50-498 S	GROSSMAN,H.	8510100212	50-456 G
GALLO,J.	8510210030	50-456 G	GOLDBERG,J.H.	8510250325	50-498 S	GROSSMAN,H.	8510180093	50-456 G
GALLO,J.	8510210030	50-456 G	GOLDBERG,J.H.	8510310241	50-498 S	GROSSMAN,H.	8510180127	50-456 G
GALLO,J.	8510220348	50-456 G	GOLDEN,J.C.	8510210073	50-10 F	GROSSMAN,H.	8510220343	50-456 G
GALLO,J.	8510220348	50-456 G	GOLDEN,J.C.	8510240324	50-10 F	GROSSMAN,H.	8510240669	50-456 G
GALLO,R.	8510010286	50-277 S	GOLDIN,D.	8510030131	NUREG	GROTHENHUIS,M.	8510180320	50-324 F
GALLO,R.M.	8510010505*	50-443 Q	GOLDMANN,K.	8510150095	71-9202	GRUBB,R.L.	8510290174*	50-344 P
GALLO,R.M.	8510080080*	50-277 Q	GOLDMANN,K.	8510150098*	71-9202	GRULKEY,M.W.	8510100194	40-8027
GALLO,R.M.	8510210102	50-277 S	GOLDSMITH,S.J.	8510010154	PR	GRUNSEICH,B.	8510220007	50-322 S
GALLO,R.M.	8510230195*	50-352 Q	GOLLER,K.R.	8510070479	REGGC	GRUNSEICH,B.	8510250026	50-322 S
GALLO,R.M.	8510280306	50-277 P	GOLLER,K.R.	8510180272*	PR	GUCWALT,L.T.	8510010098	50-321 P
GALLUCCI,R.H.	8510030435	NUREG	GOLSHUN,M.	8510220340*	50-286 P	GUCWALT,L.T.	8510010277	50-321 Q
GALLM,D.T.	8510210269	70-698	GOODE,	8510240579	27-39	GUCWALT,L.T.	8510070471	50-321 Q
GAMER,G.R.	8510180366	PR	GOODENOW,R.R.	8510010623	50-483 R	GUCWALT,L.T.	8510150289	50-321 P
GAMMILL,W.P.	8510160281*	FOIA	GOODMAN,L.S.	8510020094	50-409 R	GUCWALT,L.T.	8510150338	50-321 P
GAMMILL,W.P.	8510160293*	FOIA	GOODMAN,L.S.	8510150329	50-409 S	GUCWALT,L.T.	8510180169	50-321 Q
GARCIA,P.J.	8510180238*	40-8681	GORDON,C.	8510180416*	50-423 Q	GUCWALT,L.T.	8510210142	50-366 P
GARCIA,P.J.	8510180243*	40-8681	GORDON,C.Z.	8510160331*	50-272 Q	GUCWALT,L.T.	8510280301	50-321 P
GARCIA,P.J.	8510180249*	40-8681	GORDON,D.J.	8510280284	50-346 F	GUCWALT,L.T.	8510280420	50-321 P
GARCIA,P.J.	8510180476*	40-4492	GORDON,D.J.	8510280408	50-346 F	GUERRY,J.E.	8510080249	50-238 P
GARDE,B.P.	8510070312	50-424 H	GORDON,J.	8510040578	NUREG	GUHIN,M.A.	8510160190*	FOIA
GARDE,B.P.	8510080409*	50-329 A	GORDON,J.C.	8510210064	50-10 F	GUHIN,M.A.	8510160222*	FOIA
GARDE,B.P.	8510100185	50-445 G	GORDON,M.	8510230305	WASTE RES	GUILD,R.	8510110221	50-456 G
GARDE,B.P.	8510150436	50-445 A	GORMLEY,J.W.	8510160298	QA999	GUILD,R.	8510110221	50-456 G
GARDE,B.P.	8510150440	50-445 A	GOSSICK,L.V.	8510160130*	FOIA	GUILD,R.	8510110221	50-456 G
GARDE,B.P.	8510150443	50-445 A	GOSSICK,L.V.	8510160207*	FOIA	GUILD,R.	8510110222*	50-456 G
GARDE,B.P.	8510150446	50-445 A	GRABER,L.	8510010051	FOIA	GUILD,R.	8510110222*	50-456 G
GARDE,B.P.	8510150447	50-445 A	GRACE,J.N.	8411210152*	50-346 Q	GUILD,R.	8510160127	50-456 G
GARDE,B.P.	8510170103	FOIA	GRACE,J.N.	8502110622*	REVIEW GR P	GUILD,R.	8510160127	50-456 G
GARDE,B.P.	8510170349*	50-413 P	GRACE,J.N.	8510030076	50-395 S	GUILD,R.	8510240490	50-456 G
GARDE,B.P.	8510220230	FOIA	GRACE,J.N.	8510030428	50-302 V	GUILD,R.	8510240490	50-456 G
GARDE,B.P.	8510250346	50-445 A	GRACE,J.N.	8510040122	70-1113	GUINN,F.K.	8510110064	70-143
GARLAND,W.L.	8510170207	40-8584	GRACE,J.N.	8510040122	STATE PRO G	GUINN,F.K.	8510150033	70-143
GARLAND,W.L.	8510170246	40-8584	GRACE,J.N.	8510070365	50-348 Q	GUINN,F.K.	8510240132	70-143
GARLAND,W.L.	8510180284	40-1162	GRACE,J.N.	8510160094	50-338 Q	GUINN,F.K.	8510250041	70-143
GARNER,B.	8510020071	50-338 R	GRACE,J.N.	8510180360	50-416 Q	GULDEMOND,W.G.	8510100190*	50-331 Q
GARNER,B.	8510010843	50-346 S	GRACE,J.N.	8510180456	50-369 Q	GULDEMOND,W.G.	8510160274*	50-295 Q
GARNER,L.W.	8510040510*	50-324 Q	GRACE,J.N.	8510180527	50-269 Q	GULDEMOND,W.G.	8510230154*	50-331 Q
GARRISON,R.F.	8510150287	71-5807	GRACE,J.N.	8510180542	50-250 Q	GULDEMOND,W.G.	8510230169*	50-315 Q
GAUTAM,A.S.	8510010112*	50-282 Q	GRACE,J.N.	8510240384	50-282 Q	GULDEMOND,W.G.	8510280398*	50-461 Q
GAVULA,J.A.	8510080515*	50-237 P	GRACE,J.N.	8510300214*	50-369 P	GULDEMOND,W.G.	8510290089*	50-331 Q
GEARS,G.	8510300266	50-278 P	GRAHAM,D.	8510150357*	50-302 R	GUSTAVSON,T.C.	8510090327	WASTE MGT
GEARS,G.E.	8510090437	50-278 S	GRAMM,R.	8510280310	50-410 S	GUTIERREZ,J.M.	8510170208*	FOIA

356 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GUTTERMAN, A.H.	8510100159	50-498 T	HARRINGTON, W.D.	8510180523	50-293 R	HAYES, B.B.	8510150425*	50-348 S
GUTTERMAN, A.H.	8510100159	50-498 T	HARRINGTON, W.D.	8510250232	50-293 S	HAYES, B.B.	8510170057*	FOIA
GUTTERMAN, A.H.	8510160244	50-498 G	HARRINGTON, W.D.	8510300004	50-293 R	HAYES, B.B.	8510170073*	50-206 P
GUTTERMAN, A.H.	8510160244	50-498 G	HARRINGTON, W.D.	8510310240	50-293 P	HAYES, B.B.	8510180398*	50-382 G
GWYNN, T.P.	8510280358*	50-461 Q	HARRINGTON, W.D.	8510310450	50-293 P	HAYES, B.B.	8510180452*	FOIA
HAAS, L.D.	8510290410	NUREG	HARRIS, P.B.	8510160306	PR	HAYES, B.B.	8510180459*	FOIA
HABLE, A.J.	8510160171*	50-461 F	HARRIS, R.H.	8510010185*	50-443 Q	HAYES, B.B.	8510180504*	FOIA
HACKBARTH, C.	8510030173	MISC	HARRISON, D.F.	8510010482	50-368 R	HAYES, D.W.	8510080113*	50-330 Q
HACKBARTH, C.J.	8510290415	NUREG	HARRISON, F.	8510160321	50-324 R	HAYNES, J.G.	8510010073	50-361 P
HAELSIG, R.T.	8510090459	71-9200	HARRISON, J.	8510020033	50-382 E	HEABERLIN, S.W.	8510030435	NUREG
HAGAN, T.F.	8510010007*	CONTRACT	HARRISON, J.	8510020293	50-382 E	HEAD, C.R.	8510240586	WASTE MGT
HAGAN, T.F.	8510030329*	CONTRACT	HARRISON, J.	8510020323	50-382 E	HEAD, C.R.	8510280437	WASTE MGT
HAGAN, T.F.	8510040058	50-382 E	HARRISON, J.	8510020367	50-382 E	HEAD, D.	8510080083*	FOIA
HAGAN, T.F.	8510080087*	CONTRACT	HARRISON, J.	8510020428	50-382 E	HEBDON, F.J.	8510250599	MISC
HAGAN, T.F.	8510080574*	CONTRACT	HARRISON, J.	8510020431	50-382 E	HEHL, C.W.	8510300114*	50-255 Q
HAGER, J.	8510300094	50-255 F	HARRISON, J.	8510020434	50-382 E	HEHL, W.	8510210069	50-295 S
HAGER, J.	8510300131	50-255 F	HARRISON, J.	8510020480	50-382 E	HEHL, W.	8510250447	50-255 S
HAGEY, H.	8510040468	CONTRACT	HARRISON, J.J.	8510010101	50-282 Q	HEIDER, L.H.	8510010649	50-29 R
HAGEY, H.	8510040501	CONTRACT	HARRISON, J.J.	8510020045	50-382 E	HEIDER, L.H.	8510070309	50-29 P
HAGEY, H.	8510080118	CONTRACT	HARRISON, J.J.	8510020049	50-382 E	HEIDER, L.H.	8510070430	50-29 P
HAGEY, H.	8510170115	CONTRACT	HARRISON, J.J.	8510040215	50-461 Q	HEIDER, L.H.	8510080380	50-29 P
HAISFIELD, M.	8510240547	WASTE MGT	HARRISON, J.J.	8510070299	50-440 Q	HEIDER, L.H.	8510210093	50-29 P
HAISFIELD, M.	8510290183	WASTE MGT	HARRISON, J.J.	8510070301*	50-440 Q	HEIDER, L.H.	8510210119	50-29 P
HALE, C.J.	8510280254*	50-445 Q	HARRISON, J.J.	8510070385	50-461 Q	HEIDER, L.H.	8510220024	50-29 P
HALL, B.	8510010360*	50-382 Q	HARRISON, J.J.	8510070421	50-461 Q	HEIDER, L.H.	8510220140	50-29 P
HALL, B.	8510010367*	50-382 Q	HARRISON, J.J.	8510080393	50-266 Q	HEIN, G.	8510310165	50-267 S
HALL, B.	8510300018	50-461 F	HARRISON, J.J.	8510110029	50-456 Q	HEISER, L.	8510010351*	50-382 Q
HALL, D.P.	8510010325	50-461 Q	HARRISON, J.J.	8510160004	50-331 Q	HEISHMAN, R.F.	8510080107*	50-330 Q
HALL, D.P.	8510010468	50-461 S	HARRISON, J.J.	8510160007*	50-331 Q	HELMES, C.J.	8403140187*	PR
HALL, D.P.	8510010494	50-461 S	HARRISON, J.J.	8510170218	50-316 Q	HELMES, C.J.	8406060369*	PR
HALL, D.P.	8510080003	50-461 S	HARRISON, J.J.	8510170306	50-440 Q	HELMES, C.J.	8502070362*	PR
HALL, D.P.	8510090331	50-461 S	HARRISON, J.J.	8510170313	50-456 Q	HELMES, C.J.	PR09190637*	NUREG
HALL, D.P.	8510280376	50-461 Q	HARRISON, J.J.	8510220012	50-440 Q	HELMES, C.J.	8510020007	MISC
HALLSTROM, G.A.	8510070038*	50-424 Q	HARRISON, J.J.	8510220073	50-454 Q	HELMES, C.J.	8510040098*	MISC
HALLVERSON, P.	8510100192	PR	HARRISON, J.J.	8510250129	50-282 Q	HEMINGWAY, C.A.	8510250432	PR
HAMILTON, L.D.	8510150358*	50-440 G	HARRISON, J.J.	8510250165	50-346 Q	HENDRIE, J.M.	8510160083*	50-416 P
HAMILTON, P.	8510180523	50-293 R	HARRISON, J.J.	8510250169*	50-346 Q	HENLEY, J.C.	8510280355*	50-455 A
HAMILTON, P.	8510250232	50-293 S	HARRISON, J.J.	8510280040	50-440 Q	HENSLEY, K.D.	8510240169	70-143
HAMILTON, P.J.	8510020206	50-293 S	HARRISON, J.J.	8510280135	50-440 Q	HEREFORD, R.B.	8510010304*	50-382 P
HAMILTON, P.J.	8510070034	50-293 S	HARRISON, J.J.	8510280347	50-454 Q	HERFORD, R.F.	8510250203	50-315 Q
HAMMARLUND, C.E.	8510030140*	50-245 P	HARRISON, J.J.	8510280385	50-306 Q	HERING, R.F.	8510290350	50-316 Q
HAMPTON, J.W.	8510220355	50-413 F	HARRISON, J.J.	8510280391	50-461 Q	HERMANN, R.A.	8510170417	50-278 P
HANAUER, S.H.	8510010355	50-364 V	HARRISON, J.J.	8510280392*	50-461 Q	HERNANDEZ, G.H.	8510280145*	50-528 Q
HANDRAHAN, E.	8510150269	71-546	HARRISON, J.J.	8510290051	50-155 Q	HERNER, S.	8510210204*	CONTRACT
HANKINS, D.A.	8510150363*	50-440 G	HARRISON, J.J.	8510290330	50-440 Q	HERRING, T.	8510010079*	50-361 P
HANKINS, J.L.	8510210151*	50-277 P	HART, H.C.	8510210302	70-687	HERSCH, M.M.	8510090344*	XPORTLIC
HANNETT, B.A.	8510150075	XPORTLIC	HART, R.D.	8510170104	50-250 S	HERSCH, M.M.	8510290473	XPORTLIC
HANNETT, B.A.	8510220128	XPORTLIC	HART, R.D.	8510240352	WASTE RES	HEWLETT, J.P.	8510010081*	40-8006
HANNETT, B.A.	8510220485	XPORTLIC	HART, R.D.	8510240380	WASTE RES	HEWLETT, J.P.	8510010121*	40-8006
HANNETT, B.A.	8510250593	XPORTLIC	HARTIGAN, N.F.	8510150107	40-2061	HEWLETT, J.P.	8510010134*	40-8006
HANNETT, B.A.	8510310081	XPORTLIC	HARTMAN, G.J.	8510170326*	40-8783	HIATT, S.L.	8510220372	50-440 G
HANNETT, B.A.	8510310086*	XPORTLIC	HASSETT, J.D.	8510310207	50-29 P	HIATT, S.L.	8510240405	50-440 G
HARBOUR, J.	8510100031	50-443 G	HASSELL, D.F.	8510110093	50-352 G	HIATT, S.L.	8510280330	NUREG
HARBUCK, C.C.	8510040415*	50-458 Q	HASSELL, D.F.	8510110152	50-338 G	HICKEY, E.E.	8510010448*	50-382 F
HARBUCK, C.C.	8510240312*	50-458 Q	HASSELL, D.F.	8510110161	50-508 G	HICKIN, R.A.	8510080325*	CONTRACT
HARBUCK, C.C.	8510310350*	50-458 Q	HASSELL, D.F.	8510110168	50-329 G	HICKS, T.E.	8510040510*	50-324 Q
HARD, J.E.	8510080061*	50-329 F	HASSELL, D.F.	8510110202	50-275 G	HIGGINBOTHAM, L.	8510170121*	MISC
HARE, S.M.	8510230154*	50-331 Q	HASSELL, D.F.	8510110219	50-352 G	HIGGINBOTHAM, L.	8510230267	WASTE MGT
HARE, S.M.	8510230169*	50-315 Q	HASSELL, D.V.	8510090457	50-289 S	HIGGINBOTHAM, L.	8510230271	WASTE MGT
HARMON, D.F.	8510010103*	40-8006	HAUGHEY, M.F.	8510070266	50-410 A	HIGGINBOTHAM, L.	8510240516	WASTE MGT
HARMON, D.F.	8510010117*	40-8006	HAUGHEY, M.F.	8510290426	50-410 A	HIGGINBOTHAM, L.	8510250515	WASTE MGT
HARMON, D.F.	8510150370*	40-1366	HAUGHEY, C.J.	8510040064	50-382 E	HIGGINBOTHAM, L.	8510280021	WASTE MGT
HAROLDSEN, R.O.	8509060182*	50-305 P	HAUSEL, J.L.	8510100008*	50-445 Q	HIGGINBOTHAM, L.	8510280082	WASTE MGT
HARPSTER, T.	8510180416*	50-423 Q	HAVERKAMP, D.R.	8510220176*	50-410 A	HIGGINBOTHAM, L.	8510280087	WASTE MGT
HARPSTER, T.	8510230113*	50-293 Q	HAVERLY, J.S.	8510070106*	50-346 F	HIGGINBOTHAM, L.	8510280122	WASTE MGT
HARPSTER, T.L.	8510110074	50-245 F	HAWKINS, D.	8510030399	50-445 A	HIGGINBOTHAM, L.	8510280127	WASTE MGT
HARPSTER, T.L.	8510160051*	50-352 Q	HAWKINS, D.	8510040517	CONTRACT	HIGGINBOTHAM, L.	8510280146	WASTE MGT
HARPSTER, T.L.	8510160231*	50-272 Q	HAWKINS, D.	8510160322	CONTRACT	HIGGINBOTHAM, L.	8510280152	WASTE MGT
HARPSTER, T.L.	8510220133*	50-334 Q	HAWKINS, D.A.	8510010080	50-445 A	HIGGINBOTHAM, L.	8510280157	WASTE MGT
HARPSTER, T.L.	8510230163*	50-317 Q	HAWKINS, D.A.	8510010252	CONTRACT	HIGGINBOTHAM, L.	8510280227	WASTE MGT
HARRELLE, W.	8510010603	50-338 S	HAWKINS, D.A.	8510030139	CONTRACT	HIGGINBOTHAM, L.	8510280365	27-48
HARRELLE, W.	8510090407	50-338 S	HAWKINS, P.	8510030156	CONTRACT	HIGGINBOTHAM, L.	8510280429	27-48
HARRELLE, W.	8510150166	50-338 S	HAWKINS, P.	8510180037	40-8714	HIGGINBOTHAM, L.	8510280433	27-48
HARRELLE, W.	8510240580	50-338 S	HAWKINS, E.F.	8510180257	40-8064	HIGGINBOTHAM, L.	8510280511	WASTE MGT
HARRELLE, W.	8510250182	50-338 S	HAWKINS, E.F.	8510180322*	40-8452	HIGGINBOTHAM, L.	8510290025	WASTE MGT
HARRELL, P.H.	8510170378*	50-313 Q	HAWKINS, E.F.	8510210039	40-8502	HIGHT, G.W.	8510170315*	50-413 P
HARRINGTON, P.E.	8510040114*	50-288 F	HAWKINS, E.F.	8510290271	WASTE MGT	HIGHT, G.W.	8510280355*	50-455 A
HARRINGTON, W.D.	8510020206	50-293 S	HAWKINS, F.C.	8510100105*	50-456 Q	HILAND, P.L.	8510100051*	50-331 Q
HARRINGTON, W.D.	8510020209	50-293 S	HAWKINS, F.C.	8510210186*	50-315 Q	HILDENBRAND, P.	8510180257	40-8064
HARRINGTON, W.D.	8510070029	50-293 S	HAWKINS, F.C.	8510210223*	50-237 Q	HILDENBRAND, P.	8510210039	40-8502
HARRINGTON, W.D.	8510070034	50-293 S	HAWKINS, F.C.	8510220299*	50-409 Q	HILL, C.Z.	8510180259	40-8584
HARRINGTON, W.D.	8510070193*	50-213 P	HAWKINS, P.	8510310265*	50-295 Q	HILL, C.Z.	8510220436	50-267 S
HARRINGTON, W.D.	8510080201	50-293 K	HAWLEY, C.A.	8508280083*	40-1366	HILL, S.E.	8510090058	WASTE MGT
HARRINGTON, W.D.	8510110012	50-293 P	HAWLEY, C.A.	8508280100*	40-1366	HILL, T.V.	8510240290*	WASTE MGT
HARRINGTON, W.D.	8510110149	50-293 F	HAWLEY, C.A.	8510150245*	FOIA	HILL, W.T.	8510040383	PR
HARRINGTON, W.D.	8510150100	50-293 P	HAWXHURST, J.	8510180416*	50-423 Q	HILLIS, E.H.	8408010320*	50-315 U
HARRINGTON, W.D.	8510150181	50-293 P	HAWXHURST, J.J.	8510230163*	50-317 Q	HILLMAN, R.E.	8510070283*	50-219 R
HARRINGTON, W.D.	8510180026	50-293 P	HAYES, B.	8510180496*	FOIA	HILLS, D.E.	8510080140*	50-440 Q

PERSONAL AUTHOR INDEX 357

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HIND, J.A.	8510080158*	50-329 Q	HOYLE, J.C.	8510250098	50-128 P	HUNTER, D.R.	8510090070	50-267 Q
HIND, J.A.	8510080425	50-461 Q	HOYLE, J.C.	8510250118	50-225 P	HUNTER, D.R.	8510090296	50-267 P
HIND, J.A.	8510170242*	50-264 Q	HOYLE, J.C.	8510250120	50-156 P	HUNTER, D.R.	8510280009	50-285 F
HIND, J.A.	8510170252*	50-264 Q	HOYLE, J.C.	8510250127	50-139 P	HUNTER, R.L.	8510090518	WASTE RES
HIND, J.A.	8510170263*	50-264 Q	HOYLE, J.C.	8510250131	50-396 P	HURLEY, J.	8510010462	50-416 F
HIND, J.A.	8510170268*	50-264 Q	HOYLE, J.C.	8510250138	50-62 P	HURSHMAN, M.	8510010287*	50-382 F
HIND, J.A.	8510170273*	FOIA	HOYLE, J.C.	8510250143	50-124 P	HURT, R.D.	8510090308*	PROJ
HIND, J.A.	8510170327*	50-264 Q	HOYLE, J.C.	8510250147	50-27 P	HUSTED, J.D.	8510090167*	50-397 P
HIND, J.A.	8510170334*	50-264 Q	HOYLE, J.C.	8510250150	50-150 P	HUSTON, L.	8510220040*	50-346 P
HIND, J.A.	8510220276	70-36	HOYLE, J.C.	8510250155	50-87 P	HUTCHISON, L.B.	8510020096	50-397 R
HIND, J.A.	8510280337	50-454 Q	HOYLE, J.C.	8510250160	50-83 P	HUTSEBAUT, J.	8510150444	50-304 S
HIND, J.A.	8510280345*	50-454 Q	HOYLE, J.C.	8510250297	50-182 P	HYDER, J.E.	8510010153*	40-8006
HIND, J.A.	8510290014	50-341 Q	HOYLE, J.C.	8510250302	50-5 P	HYDER, J.E.	8510010318*	40-8027
HINDS, J.R.	8510040112	50-323 S	HOYLE, J.C.	8510250306	50-243 P	IBRAHIM, A.K.	8510230290	WASTE RES
HINDS, K.E.	8510090151	WASTE MGT	HOYLE, J.C.	8510250312	50-297 P	ICE, R.D.	8510040352	PH
HINTZ, D.C.	8510040228	50-305 P	HOYLE, J.C.	8510280075	50-116 P	IGNATONIS, A.	8510070343*	50-327 Q
HINTZ, D.C.	8510080247	50-305 P	HOYT, G.W.	8510170101*	50-361 P	IKARD, J.A.	8510180337	40-8027
HINTZ, D.C.	8510150281	50-305 P	HOYT, H.F.	8510100138	50-443 G	IKARD, J.A.	8510180337	40-8027
HINTZ, D.C.	8510210292	50-305 F	HOYT, H.F.	8510100189	50-352 G	IMAN, R.L.	8510040381	NUREG
HINTZ, D.C.	8510290339	50-305 R	HOYT, H.F.	8510310359	50-352 G	INGLES, J.M.	8510080180	50-280 J
HIRSCH, A.	8510100149	PR	HOYT, R.L.	8510220159*	50-482 F	INGRAM, F.	8510180263*	PR
HODDER, M.H.	8510180133	50-250 G	HSILY	8510180347*	50-250 G	IRWIN, D.	8510040312	NUREG
HODDER, M.H.	8510180133	50-250 G	HUBACEK, W.G.	8510020394	50-382 E	IRWIN, D.P.	8510100140	50-322 G
HODDER, M.H.	8510180133	50-250 G	HUBBARD, R.W.	8510010581	50-382 E	IRWIN, D.P.	8510100140	50-322 G
HODDER, M.H.	8510180140	50-250 G	HUBBARD, R.W.	8510020162	50-382 E	IRWIN, D.P.	8510150365	50-322 G
HODDER, M.H.	8510180140	50-250 G	HUBBARD, R.W.	8510020318	50-382 E	IRWIN, D.P.	8510150365	50-322 G
HODDER, M.H.	8510310253	50-250 G	HUBBARD, R.W.	8510020432	50-382 E	ISKANDER, S.K.	8510040402	NUREG
HODDER, M.H.	8510310253	50-250 G	HUBBARD, R.W.	8510030096	50-382 E	IVEY, K.	8510170054*	50-361 Q
HODDER, M.H.	8510310257*	50-250 G	HUBBARD, R.W.	8510030161	50-382 E	IVEY, K.D.	8510170344*	50-397 Q
HODDER, M.H.	8510310323	50-250 G	HUBBARD, R.W.	8510030198	50-382 E	JACKW, J.N.	8510250095*	50-305 Q
HODDER, M.H.	8510310323	50-250 G	HUBBARD, R.W.	8510030245	50-382 E	JACKSON, D.R.	8510080010*	CONTRACT
HODDER, M.H.	8510310323	50-250 G	HUBBARD, R.W.	8510040420	50-382 E	JACKSON, D.R.	8510240036*	CONTRACT
HODGDON, A.P.	8510100066	40-2061	HUBBARD, R.W.	8510040461	50-382 E	JACKSON, G.	8510150302*	71-384
HODGDON, A.P.	8510290001	50-352 G	HUBER, S.A.	8510110211	PR	JACKSON, G.	8510220100*	71-121
HOFFER, D.A.	8510110142*	50-456 G	HUBER, S.A.	8510250432	PR	JACOBS, G.K.	8510090445	WASTE RES
HOFFMAN, D.P.	8510010491	50-155 R	HUDESPEETH, J.B.	8510040125	50-348 P	JACOBS, G.K.	8510240030	WASTE RES
HOFFMAN, J.	8510290189	50-322 J	HUDESPEETH, J.B.	8510090036	50-348 F	JACOBS, G.K.	8510240123	WASTE RES
HOGAN, R.	8510180416*	50-423 Q	HUDESPEETH, J.B.	8510150124	50-348 F	JACOBS, G.K.	8510250590	WASTE RES
HOGAN, W.T.	8510240400	50-223 P	HUDESPEETH, J.B.	8510160246	50-348 F	JACOBS, R.	8510210005	50-387 S
HOGG, S.	8510090289	40-8502	HUEBNER, L.G.	8510220399	50-454 R	JACOBS, R.	8510230006	FOIA
HOGG, S.	8510170261	40-8714	HUETER, L.J.	8510070427*	50-454 Q	JACOBS, R.H.	8510020080*	50-387 Q
HOGG, S.	8510170272	40-8714	HUETER, L.J.	8510220004*	50-282 Q	JACOBS, R.H.	8510230202*	50-387 Q
HOGG, S.	8510170336	40-8714	HUEY, R.	8510010270	50-206 S	JACOBSON, J.M.	8510070307*	50-440 Q
HOLCOMBE, J.C.	8510170101*	50-361 P	HUEY, R.	8510080482	50-206 S	JACOBSON, J.M.	8510170317*	50-456 Q
HOLDERBAUM, D.F.	8510160054*	50-206 P	HUEY, R.F.	8510090350*	50-323 Q	JAGANNATH, B.N.	8510280430	WASTE MGT
HOLLAR, D.E.	8510310280	50-400 G	HUFHAM, J.W.	8510030061	50-259 F	JALON, A.	8510220156	FOIA
HOLLER, E.	8510290193	50-528 Q	HUFHAM, J.W.	8510030273	50-438 S	JANG, J.	8510020232	NUREG
HOLLOMON, T.J.	8510020108	50-327 R	HUFHAM, J.W.	8510030275	50-438 S	JANG, J.	8510030235*	50-243 Q
HOLM, J.S.	8510080252*	50-305 P	HUFHAM, J.W.	8510030278	50-390 S	JANUSKA, A.G.	8510090171*	50-295 Q
HOLSOPPLE, K.	8510040466*	50-333 Q	HUFHAM, J.W.	8510030280	50-390 S	JANUSKA, A.C.	8510160036*	50-155 Q
HOLT, J.W.	8510020102*	MISC	HUFHAM, J.W.	8510030300	50-438 S	JAPE, F.	8510040539*	50-302 Q
HOLTZMAN, R.B.	8510220006*	50-440 Q	HUFHAM, J.W.	8510110155	71-6722	JAPE, F.	8510070780*	50-414 Q
HON, A.	8510170054*	50-361 Q	HUFHAM, J.W.	8510150060	50-327 F	JARVIS, P.B.	8510010146	FOIA
HOOD, D.	8510080282*	50-329 A	HUFHAM, J.W.	8510150174	50-259 F	JAUDON, J.P.	8510040139*	50-267 Q
HOOD, D.S.	8510180014	50-289 S	HUFHAM, J.W.	8510160242	50-259 F	JAUDON, J.P.	8510040415*	50-458 Q
HOOD, D.S.	8510280417*	50-395 P	HUFHAM, J.W.	8510220328	NUREG	JAUDON, J.P.	8510090107	50-298 S
HOOKER, C.A.	8510030268*	50-275 Q	HUFHAM, J.W.	8510300021	50-298 A	JAUDON, J.P.	8510220464*	50-390 Q
HORAN, J.R.	8510040389	NUREG	HUFHAM, J.W.	8510300038	50-518 A	JAUDON, J.P.	8510240112*	50-458 Q
HORN, M.	8510100075*	40-2061	HUGHES, E.M.	8510020294*	50-461 A	JAUDON, J.P.	8510240152*	50-458 Q
HORN, M.	8510160182*	70-3000	HUKILL, H.D.	8510030056	50-289 P	JAUDON, J.P.	8510240312*	50-458 Q
HOSEY, C.M.	8510180533*	70-143	HUKILL, H.D.	8510040445	50-289 P	JAUDON, J.P.	8510250462*	50-458 Q
HOU, S.	8510010504	50-382 E	HUKILL, H.D.	8510040448*	50-289 P	JAUDON, J.P.	8510310350*	50-458 Q
HOUGLAND, J.W.	8510210230	40-7604	HUKILL, H.D.	8510070210	50-289 P	JENISON, K.M.	8510070343*	50-327 Q
HOUGLAND, J.W.	8510210236*	40-7604	HUKILL, H.D.	8510070371	50-289 S	JENS, W.H.	8510030001	50-341 P
HOWARD, E.M.	8510010065*	40-8027	HUKILL, H.D.	8510070426	50-289 P	JENS, W.H.	8510030010	50-341 P
HOWE, P.W.	8510310227	50-324 S	HUKILL, H.D.	8510080078	50-289 P	JENS, W.H.	8510070057	50-341 F
HOWELL, T.G.	8510070185*	50-206 F	HUKILL, H.D.	8510080212	50-289 P	JENS, W.H.	8510070325	50-341 Q
HOYAL, J.G.	8510090310	WASTE MGT	HUKILL, H.D.	851009045*	50-289 S	JENS, W.H.	8510080473	50-341 Q
HOYAL, J.G.	8510280067	WASTE MGT	HUKILL, H.D.	8510110072*	50-219 P	JENS, W.H.	8510160071	50-341 P
HOYAL, J.G.	8510280110	WASTE MGT	HUKILL, H.D.	8510150376	50-289 P	JENS, W.H.	8510160119	50-341 P
HOYLE, J.C.	8510020168	50-341 G	HUKILL, H.D.	8510160080	50-289 P	JENS, W.H.	8510220243	50-341 F
HOYLE, J.C.	8510100176	50-382 G	HUKILL, H.D.	8510250226	50-289 S	JESSUP, B.	8510070305	CONTRACT
HOYLE, J.C.	8510100177	50-526 G	HUKILL, H.D.	8510250354	50-289 F	JESSUP, B.	8510070579	CONTRACT
HOYLE, J.C.	8510250009	50-184 P	HUKILL, H.D.	8510280378	50-289 P	JESSUP, B.	8510080136	CONTRACT
HOYLE, J.C.	8510250012	50-199 P	HUKILL, H.D.	8510290068	50-289 P	JESSUP, B.	8510080328	CONTRACT
HOYLE, J.C.	8510250013	50-180 P	HUKILL, H.D.	8510290160	50-289 P	JEUNG, N.	8510020240	NUREG
HOYLE, J.C.	8510250017	50-73 P	HUKILL, H.D.	8510290175*	50-289 P	JIERREE, C.C.	8510170439	40-8696
HOYLE, J.C.	8510250022	50-163 P	HUKILL, H.D.	8510310596	50-289 R	JIERREE, C.C.	8510170444	40-8696
HOYLE, J.C.	8510250032	50-20 P	HULMAN, L.G.	8506260705*	50-346 S	JIERREE, C.C.	8510180200*	40-1162
HOYLE, J.C.	8510250070	50-134 P	HUMPHRIES, H.B.	8510100097	PR	JIERREE, C.C.	8510180236*	40-8681
HOYLE, J.C.	8510250074	50-193 P	HUNNICUTT, D.M.	8510100079*	50-445 Q	JIERREE, C.C.	8510180243*	40-8681
HOYLE, J.C.	8510250075	50-2 P	HUNSTAD, A.A.	8510210276	50-282 E	JIERREE, C.C.	8510180249*	40-8681
HOYLE, J.C.	8510250079	50-223 P	HUNSTAD, A.	8510220157	50-282 I	JIERREE, C.C.	8510180438	40-2259
HOYLE, J.C.	8510250084	50-148 P	HUNT, J.	8510280435*	27-48	JIERREE, C.C.	8510180444	40-8696
HOYLE, J.C.	8510250085	50-433 P	HUNT, J.	8510280494	27-48	JIERREE, C.C.	8510180451	40-2259
HOYLE, J.C.	8510250090	50-54 P	HUNT, M.D.	8510020290*	50-302 Q	JIERREE, C.C.	8510180469*	40-299
HOYLE, J.C.	8510250091	50-123 P	HUNTER, D.	8510220055	50-29 P	JIERREE, C.C.	8510210300	40-299
HOYLE, J.C.	8510250096	50-186 P	HUNTER, D.	8510280161	50-271 P	JIERREE, C.C.	8510210305	40-299

358 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JIERREE, C.C.	8510220102	40-2259	JOINER, J. E.	8510240213	50-424 G	KAMMERER, C.	8510230261*	50-482 U
JIERREE, C.C.	8510220116	40-1162	JONES, A.E.	8510150394*	40-1366	KAMMERER, C.	8510230268*	50-346 U
JOHANSEN, J.	8510080029	I&E	JONES, D.B.	8510040241	ORG	KAMMERER, C.	8510230274*	50-346 U
JOHANSEN, R.C.	8510300221*	50-369	JONES, D.E.	8510070424*	50-461 Q	KAMMERER, C.	8510230283*	50-315 U
JOHANSEN, R.C.	8510300226*	50-369	JONES, D.E.	8510170224*	50-316 Q	KAMMERER, C.	8510230293*	50-250 U
JOHNSON, A.	8510170054*	50-361 Q	JONES, D.W.	8510180071*	70-143	KAMMERER, C.	8510230304*	50-387 U
JOHNSON, A.D.	8510090350*	50-323 Q	JONES, P.E.	8510070129*	CONTRACT	KAMMERER, C.	8510230312*	50-259 U
JOHNSON, A.R.	8510280254*	50-445 Q	JONES, V.	8510010643	50-280 R	KAMMERER, C.	8510230323*	50-369 U
JOHNSON, B.D.	8510210071	50-255 Q	JONES, W.B.	8510310291*	50-382 Q	KAMMERER, C.	8510230325*	50-298 U
JOHNSON, B.D.	8510210079	50-155 Q	JONES, W.C.	8510240398	50-285 F	KAMMERER, C.	8510230327*	50-280 U
JOHNSON, B.D.	8510210294	50-255 S	JONES, W.C.	8510250307	50-285 F	KAMMERER, C.	8510230337*	50-259 U
JOHNSON, C.	8510202116	50-382	JORDAN, E.L.	8404170570	50-346 S	KAMMERER, C.	8510230342*	50-302 U
JOHNSON, C.	8510020321	50-382	JORDAN, E.L.	8507050455*	COMMISSION	KAMMERER, C.	8510230346*	FOIA
JOHNSON, C.E.	8510020091	50-382	JORDAN, E.L.	8509260122	50-3 Q	KAMMERER, C.	8510250323*	50-390 H
JOHNSON, C.E.	8510020464	50-382	JORDAN, E.L.	8509260369	50-3 Q	KANE, W.	8510010062	50-289 S
JOHNSON, C.E.	8510020467	50-382	JORDAN, E.L.	8510010429	I&E	KANE, W.F.	8510250180	50-289 Q
JOHNSON, C.R.	85101110248*	71-9010	JORDAN, E.L.	8510150022	50-3 Q	KANICK, B.	8510010612	50-275 R
JOHNSON, D.J.	8510250189	50-368 S	JORDAN, E.L.	8510150025	50-3 Q	KANIPE, L.M.	8510180536	50-321 R
JOHNSON, E.H.	8510010070	50-482 Q	JORDAN, E.L.	8510150080	50-3 Q	KANOW, L.R.	8510020230*	50-344 Q
JOHNSON, E.H.	8510010393*	FOIA	JORDAN, E.L.	8510250599	MISC	KAPLAN, B.L.	8510220178*	50-445 A
JOHNSON, E.H.	8510040067	50-499 Q	JORDAN, H.	8510170315*	50-413 P	KASUGA, R.W.	8510240635	50-213 S
JOHNSON, E.H.	8510040134	50-267 Q	JORDAN, L.V.	8510110093	70-27	KATO, W.Y.	8510080608	WASTE RES
JOHNSON, E.H.	8510040403	50-458 Q	JOSICER, W.A.	8510290476	50-286 R	KAUFMAN, P.D.	8510070307*	50-440 Q
JOHNSON, E.H.	8510080415	50-313 Q	JOUKOFF, P.	8510170077*	50-206 P	KAY, M.A.	8510040111	50-288 F
JOHNSON, E.H.	8510080585	50-458 Q	JOYNER, A.H.	8510240394	50-400 T	KAY, M.A.	8510080489	50-288 P
JOHNSON, E.H.	8510080592	50-496 Q	JOYNER, J.	8510020383	50-293 S	KAY, M.A.	8510220228	50-288 F
JOHNSON, E.H.	8510090251	50-267 Q	KADAMBIN, P.	8510010023	50-498 F	KAZANAS, N.C.	8510110072*	50-219 P
JOHNSON, E.H.	8510090297	50-296 Q	KADAMBIN, P.	8510150079	50-498 F	KAZANAS, N.C.	8510220153*	50-320 F
JOHNSON, E.H.	8510090304	50-458 Q	KADAMBIN, P.	8510240463	50-498 A	KEAST, D.N.	8510240394	50-400 T
JOHNSON, E.H.	8510160056	50-313 Q	KADAMBIN, P.	8510250512	50-498 F	KEAST, D.N.	8510240394	50-400 T
JOHNSON, E.H.	8510160076	50-498 A	KAISER, W.T.	8510110246*	50-364 P	KEEFFE, J.	8510170194*	FOIA
JOHNSON, E.H.	8510160098	50-382 Q	KALIVANAKIS, N.	8510090388	50-265 S	KEENAN, J.S.	8510290308*	50-336 P
JOHNSON, E.H.	8510160108	50-267 Q	KALIVANAKIS, N.	8510110148*	50-254 F	KEENER, E.L.	8510220199*	50-390 F
JOHNSON, E.H.	8510160255	50-382 Q	KALIVANAKIS, N.	8510110266	50-254 S	KEILMAN, D.J.	8510110224	PR
JOHNSON, E.H.	8510170371	50-313 Q	KALIVANAKIS, N.	8510220009	50-265 S	KEIMIG, R.	8510020244*	50-293 Q
JOHNSON, E.H.	8510170402	50-313 Q	KALTMAN, M.	8510220148*	FOIA	KEIMIG, R.	8510080183	50-293 S
JOHNSON, E.H.	8510210291	50-482 Q	KAMMERER, C.	8510010157*	50-289 P	KEIMIG, R.	8510220344	70-1100
JOHNSON, E.H.	8510220298	50-482 Q	KAMMERER, C.	8510010186*	50-275 P	KEIMIG, R.R.	8510070224*	70-1100
JOHNSON, E.H.	8510220322	50-313 Q	KAMMERER, C.	8510010213*	50-289 P	KEIMIG, R.R.	8510080162*	70-820
JOHNSON, E.H.	8510220339	50-482 Q	KAMMERER, C.	8510010235*	FOIA	KEIMIG, R.R.	8510080228*	50-423 Q
JOHNSON, E.H.	8510220341	50-482 Q	KAMMERER, C.	8510010362*	50-289 P	KEIMIG, R.R.	8510080346*	50-219 Q
JOHNSON, E.H.	8510220357	50-498 Q	KAMMERER, C.	8510010453*	FOIA	KEIMIG, R.R.	8510080453*	50-322 Q
JOHNSON, E.H.	8510220358	50-458 Q	KAMMERER, C.	8510010506	50-322 U	KEIMIG, R.R.	8510100211*	70-371
JOHNSON, E.H.	8510220447	50-458 Q	KAMMERER, C.	8510230018*	50-325 U	KEIMIG, R.R.	8510310128*	70-1100
JOHNSON, E.H.	8510220460	50-298 Q	KAMMERER, C.	8510230023*	50-413 U	KEIMIG, R.R.	8510310217*	70-371
JOHNSON, E.H.	8510240107	50-458 Q	KAMMERER, C.	8510230027*	50-250 U	KEISER, H.W.	8510010591	50-387 R
JOHNSON, E.H.	8510240140	50-458 Q	KAMMERER, C.	8510230032*	50-320 U	KEISER, H.W.	8510030032	50-388 P
JOHNSON, E.H.	8510240293	50-285 Q	KAMMERER, C.	8510230041*	50-296 U	KEISER, H.W.	8510030056*	50-388 P
JOHNSON, E.H.	8510240294	50-458 Q	KAMMERER, C.	8510230045*	50-346 U	KEISER, H.W.	8510070154	50-387 F
JOHNSON, E.H.	8510240341	50-458 Q	KAMMERER, C.	8510230051*	50-346 U	KEISER, H.W.	8510070304	50-387 F
JOHNSON, E.H.	8510240347*	50-458 Q	KAMMERER, C.	8510230057*	FOIA	KEISER, H.W.	8510080034	50-387 F
JOHNSON, E.H.	8510240424	50-298 Q	KAMMERER, C.	8510230060*	50-416 U	KEISER, H.W.	8510080410	50-387 F
JOHNSON, E.H.	8510250413	50-313 Q	KAMMERER, C.	8510230065*	50-289 U	KEISER, H.W.	8510150321	50-387 P
JOHNSON, E.H.	8510250457	50-458 Q	KAMMERER, C.	8510230069*	50-277 U	KEISER, H.W.	8510150399	50-387 P
JOHNSON, E.H.	8510280012	50-298 F	KAMMERER, C.	8510230077*	FOIA	KEISER, H.W.	8510170140	50-388 P
JOHNSON, E.H.	8510290121	50-382 F	KAMMERER, C.	8510230085*	50-259 U	KEISER, H.W.	8510170144*	50-388 P
JOHNSON, E.H.	8510290194	50-298 Q	KAMMERER, C.	8510230090*	50-382 U	KEISER, H.W.	8510180275	50-387 P
JOHNSON, E.H.	8510310096	50-458 Q	KAMMERER, C.	8510230097*	50-259 U	KEISER, H.W.	8510180281*	50-387 P
JOHNSON, E.H.	8510310364	50-382 Q	KAMMERER, C.	8510230098*	50-331 U	KEISER, H.W.	8510230183	50-387 Q
JOHNSON, F.R.	8510280355*	50-455 A	KAMMERER, C.	8510230102*	50-220 U	KEISER, H.W.	8510250425	50-387 F
JOHNSON, G.E.	8510030015	70-364	KAMMERER, C.	8510230106*	50-482 U	KELLER, D.S.	8510080191*	CONTRACT
JOHNSON, G.L.	8510160297*	50-423 F	KAMMERER, C.	8510230114*	70-143	KELLER, R.	8510090198*	50-387 Q
JOHNSON, J.	8510070225*	50-423 Q	KAMMERER, C.	8510230118*	50-528 U	KELLER, R.	8510170296*	50-410 Q
JOHNSON, J.	8510170257*	50-322 Q	KAMMERER, C.	8510230126*	50-327 U	KELLER, R.M.	8510110112*	50-317 Q
JOHNSON, J.	8510250273*	50-293 Q	KAMMERER, C.	8510230134*	50-293 U	KELLER, R.M.	8510210154*	50-354 Q
JOHNSON, J.	8510250475*	50-423 Q	KAMMERER, C.	8510230139*	FOIA	KELLER, R.M.	8510250078*	50-57 Q
JOHNSON, J.R.	8510170288*	50-423 Q	KAMMERER, C.	8510230142*	FOIA	KELLEY, D.L.	8510100079*	50-445 Q
JOHNSON, P.	8510010270	50-206 S	KAMMERER, C.	8510230146*	50-10 U	KELLEY, D.L.	8510280229*	50-445 Q
JOHNSON, P.	8510080482	50-206 S	KAMMERER, C.	8510230150*	50-272 U	KELLEY, E.R.	8510110004	50-322 G
JOHNSON, P.H.	8510090358*	50-397 Q	KAMMERER, C.	8510230164*	50-382 U	KELLEY, E.R.	8510110180	50-322 G
JOHNSON, P.H.	8510090359*	50-397 Q	KAMMERER, C.	8510230170*	50-416 U	KELLEY, E.R.	8510110196	50-322 G
JOHNSON, P.H.	8510240281*	50-206 Q	KAMMERER, C.	8510230173*	50-275 U	KELLEY, E.R.	8510280519	50-322 G
JOHNSON, R.L.	8510240507	WASTE RES	KAMMERER, C.	8510230175*	50-416 U	KELLEY, J.L.	8510150350	50-400 G
JOHNSON, R.W.	8510020205*	50-354 A	KAMMERER, C.	8510230182*	50-334 U	KELLY, F.	8510110208	71-9176
JOHNSON, T.	8510010286	50-277 S	KAMMERER, C.	8510230185*	50-409 U	KELLUND, G.C.	8510090245*	50-344 Q
JOHNSON, T.	8510210026	50-424 G	KAMMERER, C.	8510230189*	50-251 U	KELLY, D.	8510020100	50-322 R
JOHNSON, T.	8510210029	50-424 G	KAMMERER, C.	8510230191*	50-277 U	KELLY, D.	8510170003	50-322 R
JOHNSON, T.	8510210029	50-424 G	KAMMERER, C.	8510230197*	50-296 U	KELLY, J.A.	8510010375*	50-382 F
JOHNSON, T.	8510210102	50-277 S	KAMMERER, C.	8510230198*	70-123	KELLY, L.	8510290476	50-286 R
JOHNSON, T.	8510240547	WASTE MGT	KAMMERER, C.	8510230203*	50-387 U	KELLY, R.B.	8510180355*	50-423 A
JOHNSON, T.L.	8510280072	WASTE MGT	KAMMERER, C.	8510230205*	50-321 U	KELLY, R.B.	8510180356*	50-423 A
JOHNSON, T.L.	8510290421	WASTE MGT	KAMMERER, C.	8510230220*	50-259 U	KELLY, R.B.	8510290319	QA999
JOHNSON, W.D.	8510170378*	50-313 Q	KAMMERER, C.	8510230222*	50-250 U	KELLY, W.P.	8510240084	WASTE RES
JOHNSRUD, J.	8510240323*	50-320 G	KAMMERER, C.	8510230228*	70-143	KELLY, W.R.	8510230265	WASTE RES
JOHNSRUD, J.	8510240329*	50-320 G	KAMMERER, C.	8510230234*	50-280 U	KEMP, W.M.	8510040396	50-382 E
JOHNSTON, H.E.	8510210240	70-820	KAMMERER, C.	8510230241*	70-2953	KEMPER, J.S.	8510290341	50-352 Q
JOHNSTON, W.V.	8509040052*	50-445 Q	KAMMERER, C.	8510230246*	50-261 U	KEMPER, J.S.	8510290367	50-352 Q
JOINER, J.E.	8510230010	50-424 G	KAMMERER, C.	8510230250*	50-362 U	KEMPER, R.M.	8510080178*	TOPREP

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KENALY, D.	8510080506	50-10	KISTER, H.	8510090198*	50-387	KODALI, K. K.	8510150171	70-1068
KENALY, D.	8510240324	50-10	KISTER, H.	8510170296*	50-410	KOERBER, G. M.	8510180536	50-321 R
KENALY, D. M.	8510210073*	50-10	KISTER, H. B.	8510020073	50-387	KOESTER, G. L.	8510040133	50-482 F
KENNY, T.	8510090238	50-272	KISTER, H. B.	8510080169	50-219	KOESTER, G. L.	8510070009	50-482 S
KENNY, T. J.	8510230163*	50-317	KISTER, H. B.	8510110112*	50-317	KOESTER, G. L.	8510090294	50-482 S
KENSICHI, S. F.	8510180115*	50-440	KISTER, H. B.	8510170149	50-219	KOESTER, G. L.	8510090372	50-482 S
KEPPLER, J. G.	8407130274*	50-346	KISTER, H. B.	8510170153*	50-219	KOESTER, G. L.	8510160059	50-482 F
KEPPLER, J. G.	8407130282*	50-346	KISTER, H. B.	8510210150	50-354	KOESTER, G. L.	8510180152	50-482 P
KEPPLER, J. G.	8407130287*	50-346	KISTER, H. B.	8510210154*	50-354	KOESTER, G. L.	8510180212	50-482 R
KEPPLER, J. G.	8407130320*	50-346	KISTER, H. B.	8510230199	50-387	KOESTER, G. L.	8510210229	50-482 S
KEPPLER, J. G.	8510010068	50-461	KISTER, H. B.	8510250078*	50-57	KOESTER, G. L.	8510210234	50-482 S
KEPPLER, J. G.	8510010175	50-373	KISTER, H. B.	8510250161	50-219	KOESTER, G. L.	8510220044	50-482 F
KEPPLER, J. G.	8510010182*	50-373	KISTER, H. B.	8510250171*	50-219	KOESTER, G. L.	8510220155	50-482 F
KEPPLER, J. G.	8510070108*	50-346	KISTER, H. B.	8510280356	50-354	KOESTER, G. L.	8510220159*	50-482 F
KEPPLER, J. G.	8510070112*	50-346	KIZER, K. W.	8510210286	STATE PRO G	KOESTER, G. L.	8510220301*	50-482 Q
KEPPLER, J. G.	8510070120*	50-346	KLEIN, D. E.	8510160155	50-602	KOESTER, G. L.	8510220342*	50-482 Q
KEPPLER, J. G.	8510070130*	50-346	KLEIN, D. E.	8510160286	50-602	KOESTER, G. L.	8510220346*	50-482 Q
KEPPLER, J. G.	8510070138*	50-346	KLEIN, T. J.	8510170474	40-8584	KOESTER, G. L.	8510220466	50-482 S
KEPPLER, J. G.	8510070214*	50-346	KLEINSORGE, W. P.	8510040160*	50-390	KOESTER, G. L.	8510310071	50-48*
KEPPLER, J. G.	8510070220*	50-346	KLEINSORGE, W. P.	8510080548*	50-413	KOESTER, G. L.	8510310156	50-482 F
KEPPLER, J. G.	8510070269*	50-346	KLINE, J. R.	8510100028	50-440	KOESTER, G. L.	8510310175	50-482 S
KEPPLER, J. G.	8510070362	50-454	KLINGLER, G.	8510030049	50-454	KOHLER, A. D.	8510090285	50-508 S
KEPPLER, J. G.	8510070368*	50-454	KLINGLER, G.	8510080031	50-317	KOLTA, P. S.	8510030225*	50-286 Q
KEPPLER, J. G.	8510110083*	50-456	KNAPP, M. R.	8510010113	WASTE MGT	KONNERTH, C. J.	8510310426*	70-687
KEPPLER, J. G.	8510170270*	50-264	KNAPP, M. R.	8510150471*	MISC	KONWINSKI, G. R.	8510180448	40-4492
KEPPLER, J. G.	8510170322*	50-264	KNAPP, M. R.	8510240562	WASTE MGT	KONWINSKI, G. R.	8510180480*	40-8584
KEPPLER, J. G.	8510220323	50-346	KNAPP, M. R.	8510280095	WASTE MGT	KONWINSKI, G. R.	8510180482*	40-8584
KEPPLER, J. G.	8510280423	50-237	KNAPP, M. R.	8510280132	WASTE MGT	KONWINSKI, G. R.	8510210053	40-6622
KEPPLER, J. G.	8510290224	50-409	KNAPP, M. R.	8510280169	WASTE MGT	KONWINSKI, G. R.	8510210082	40-1162
KERCH, H. W.	8510010185*	50-443	KNAPP, M. R.	8510290031	WASTE MGT	KONWINSKI, G. R.	8510210106	40-6659
KERR, G. W.	8510160126*	FOIA	KNAPP, M. R.	8510290161	WASTE MGT	KONWINSKI, G. R.	8510220081	40-6622
KERS, L.	8510160018*	50-255	KNICELEY, J. R.	8510210051*	50-454	KONZ, J. S.	8510080334*	CONTRACT
KERS, L. L.	8510160270*	50-295	KNICELEY, J. R.	8510280113*	50-440	KOON, A. R.	8510010212	50-395 S
KETZLACH, N.	8510160188*	70-3000	KNIGHT, J. P.	8204210531*	50-329	KOON, A. R.	8510100026	50-395 S
KETZLACH, N.	8510230257*	70-824	KNIGHT, J. P.	8204290608*	50-329	KOON, A. R.	8510250185	50-395 S
KEZELIS, E. Z.	8510220364	50-456	KNIGHTON, G.	85101500-7	50-443	KORTAS, A. J.	8510020050*	50-277 Q
KEZELIS, E. Z.	8510220364	50-456	KNIGHTON, G. W.	8404050355*	50-382	KOSMALA, R. J.	8510220078*	50-458 S
KHATIB-RAHBAR	8510020257	50-423	KNIGHTON, G. W.	8510010145	50-498	KOSMALA, R. J.	8510220083*	50-458 S
KHAZARAI, M.	8510010410	50-346	KNIGHTON, G. W.	8510070097	50-361	KOTTAN, J.	8510210090*	50-354 Q
KIDO, C.	8510030411*	50-354	KNIGHTON, G. W.	8510070104*	50-361	KOTTAN, J. J.	8510170147*	50-320 Q
KILBRIDE, C. A.	8510040480	50-454	KNIGHTON, G. W.	8510080129	50-412	KOWALSKI, K. M.	8510170015	40-8355
KIM, S. B.	8510020451	50-382	KNIGHTON, G. W.	8510090111	50-412	KRAEGER, B. A.	8510070308*	CONTRACT
KIM, S. B.	8510020477	50-382	KNIGHTON, G. W.	8510090191	50-412	KRAMERIC, M.	8510020232	NUREG
KIM, S. B.	8510020492	50-382	KNIGHTON, G. W.	8510090199*	50-412	KRAMER, H. H.	8510100010	PR
KIM, S. B.	8510040024	50-382	KNIGHTON, G. W.	8510090404	50-412	KRAMER, J. E.	8510150039*	71-230
KIM, S. B.	8510070083	50-382	KNIGHTON, G. W.	8510090408	50-323	KRASHES, D.	8510040336	PR
KIM, Y. C.	8510090233	WASTE RES	KNIGHTON, G. W.	8510110086	50-361	KRASOPOLSKA, A.	8510180061*	50-423 Q
KIM, Y. C.	8510090519	WASTE RES	KNIGHTON, G. W.	8510110094*	50-361	KRAUSE, C. W.	8510180502	50-266 R
KIM, Y. C.	8510240522	WASTE RES	KNIGHTON, G. W.	8510110232	50-361	KRAUSE, G. T.	8510220363*	50-263 Q
KINGSLEY, K. R.	8510090514	71-8168	KNIGHTON, G. W.	8510110235*	50-361	KREH, J. L.	8510220396*	50-324 Q
KINGSLEY, O. D.	8510020302	50-416	KNIGHTON, G. W.	8510150244	50-412	KRIEGER, K.	8510290627*	50-247 R
KINGSLEY, O. D.	8510150049	50-416	KNIGHTON, G. W.	8510170341	50-412	KRIEGER, K.	8510290633*	50-247 R
KINGSLEY, O. D.	8510220365	50-416	KNIGHTON, G. W.	8510240411	50-361	KRIMM, R. W.	8510160154	50-334 F
KINGSLEY, O. D.	8510290445	50-416	KNIGHTON, G. W.	8510250001	50-443	KRIMM, R. W.	8510210216	50-440 F
KINGSLEY, O. D.	8510290449*	50-416	KNIGHTON, G. W.	8510250580	50-412	KRIMM, R. W.	8510210239	50-334 F
KINNEMAN, J.	8510180029	1&E	KNIGHTON, G. W.	8510300041	50-528	KRIMM, R. W.	8510230219	50-245 F
KINNEY, W.	8510100192	PR	KNIGHTON, G. W.	8510310338	50-443	KRIMM, R. W.	8510290351	50-322 F
KINNEY, W. H.	8510080130*	CONTRACT	KNIGHTON, G. W.	8510310352	50-412	KROES, R. J.	8510220466	50-433 P
KINTNER, E. E.	8510010102*	50-320	KNIGHTON, G. W.	8510310355*	50-412	KROES, R. J.	8510310439	50-433 P
KINTNER, L. L.	8510180008	50-416	KNIGHTON, G. W.	8510310358	50-529	KRONICH, C.	8510220009	50-265 S
KINTNER, L. L.	8510180494	50-416	KNIGHTON, G. W.	8510310362	50-498	KRONICH, C. L.	8510170388	50-254 R
KIRNER, N. P.	8510290207*	WASTE MGT	KNIGHTON, G. W.	8510310537	50-528	KRUG, H. E.	8510180435*	50-261 Q
KIRNER, N. P.	8510290291*	WASTE MGT	KNIGHTON, G. W.	8510310602	50-400	KRYTER, K. D.	8510230223*	50-400 T
KIRSCH, D.	8510020337	50-528	KNOP, R. C.	8510180019*	50-440	KRYTER, K. D.	8510230223*	50-400 T
KIRSCH, D. F.	8510010139	50-344	KNOP, R. C.	8510210091*	50-440	KUCHARSKI, S.	8510070260*	50-322 Q
KIRSCH, D. F.	8510010184	50-529	KNOP, R. C.	8510220242*	50-440	KUCHARSKI, S.	8510230208*	50-352 Q
KIRSCH, D. F.	8510010250	50-528	KNOP, R. C.	8510310331	50-416	KUCZYNSKI, L. A.	8510010591	50-387 R
KIRSCH, D. F.	8510010481	50-312	KNOP, R. C.	8510310331	50-416	KUCZYNSKI, L. A.	8510070007	50-387 S
KIRSCH, D. F.	8510020097	50-397	KNOP, R. C.	8510080032*	50-244	KUECHLE, C.	8510310545	50-304 S
KIRSCH, D. F.	8510020224	50-344	KOBER, R. W.	8510010032	50-244	KUEMIN, J. L.	8510010366	50-255 Q
KIRSCH, D. F.	8510020251	50-344	KOBER, R. W.	8510040425	50-244	KUEMIN, J. L.	8510080117	50-255 P
KIRSCH, D. F.	8510070076	50-275	KOBER, R. W.	8510110231	50-244	KUEMIN, J. L.	8510080499	50-255 P
KIRSCH, D. F.	8510070157	50-312	KOBER, R. W.	8510160002	50-244	KUEMIN, J. L.	8510160202	50-255 Q
KIRSCH, D. F.	8510090235	50-344	KOBER, R. W.	8510160267	50-244	KUEMIN, J. L.	8510180032	50-255 P
KIRSCH, D. F.	8510090257*	50-508	KOBER, R. W.	8510180132	50-244	KUEMIN, J. L.	8510250134	50-255 P
KIRSCH, D. F.	8510090348	50-323	KOBER, R. W.	8510210050	50-244	KWAN, Q.	8510040578	NUREG
KIRSCH, D. F.	8510090355	50-397	KOBER, R. W.	8510210127	50-244	KWOK, C. C.	8510010414	50-133 R
KIRSCH, D. F.	8510150172	50-206	KOBER, R. W.	8510210130*	50-244	LACEY, W. S.	8510150221	50-334 S
KIRSCH, D. F.	8510150388	50-528	KOBER, R. W.	8510220092	50-244	LACEY, W. S.	8510170452	50-334 S
KIRSCH, D. F.	8510160058	50-528	KOBER, R. W.	8510220096*	50-244	LACKER, D. K.	8510160095	PR
KIRSCH, D. F.	8510170053	50-361	KOBER, R. W.	8510220274	50-244	LAFLEUR, J. D.	8510160122*	FOIA
KIRSCH, D. F.	8510170336	50-397	KOBER, R. W.	8510220278*	50-244	LAFLEUR, J. D.	8510160273*	FOIA
KIRSCH, D. F.	8510220063	50-528	KOBER, R. W.	8510220376*	50-244	LAFLEUR, J. D.	8510160277*	FOIA
KIRSCH, D. F.	8510240269	50-206	KOBER, R. W.	8510220376*	50-244	LAINAS, G. C.	8510080414*	50-317 P
KIRSCH, D. F.	8510250194	50-528	KOBER, R. W.	8510240248	50-244	LAINAS, G. C.	8510090537	50-267 P
KIRSCH, D. F.	8510280139	50-528	KOBER, R. W.	8510240644	50-244	LAINAS, G. C.	8510250018	50-346 P
KIRSCH, D. F.	8510280155	50-344	KOBER, R. W.	8510310242	50-244	LAINAS, G. C.	8510250024*	50-346 P
KISHBAUGH, T.	8510220370*	50-346	KODALI, K. K.	8510040113	70-3027	LAITY, W. W.	8510020182	50-206 S

360 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LAITY, W.W.	8510300306	50-322 S	LEVENSON, M.	8510180187	NUREG	LYON, D.	8510170047	50-373 S
LAITY, W.W.	8510300314*	50-322 S	LEVINE, J.M.	8510220120	50-313 F	LYONS, P.J.	8510170397	40-299
LAITY, W.W.	8510310568	50-445 S	LEVINE, Z.	8510000249	50-238 F	MACDONALD, C.E.	8510010020	71-9192
LAITY, W.W.	8510310574*	50-445 S	LEWIS, M.I.	8510180287	50-289 G	MACDONALD, C.E.	8510010053	71-9176
LAKE, W.H.	8510310392	71-5507	LEWIS, M.I.	8510250393	NUREG	MACDONALD, C.E.	8510020497	71-384
LAMBERT, C.W.	8510020200*	50-354 A	LEWIS, M.L.	8510100025	NUREG	MACDONALD, C.E.	8510020501*	71-384
LAMBERT, C.W.	8510020205*	50-354 A	LEWIS, R.L.	8510010487	50-259 R	MACDONALD, C.E.	8510020508	71-552
LANGE, D.	8510090198*	50-387 Q	LEWIS, R.L.	8510040479	50-296 S	MACDONALD, C.E.	8510020510*	71-552
LANGE, D.	8510170296*	50-410 Q	LEWIS, R.L.	8510070545	50-259 S	MACDONALD, C.E.	8510030086	71-135
LANGNER, R.R.	8510170234*	50-284 Q	LEWIS, R.L.	8510090020	50-259 S	MACDONALD, C.E.	8510030074*	71-135
LANGSTON, L.W.	8510250385	PR	LEWIS, R.L.	8510170370	50-259 S	MACDONALD, C.E.	8510030110	71-9071
LANGSTON, M.E.	8510250524	WASTE MGT	LEWIS, R.L.	8510180387	50-259 S	MACDONALD, C.E.	8510030115	71-5862
LARSEN, C.E.	8510310137	50-282 Q	LEWIS, R.L.	8510290470	50-259 S	MACDONALD, C.E.	8510030120*	71-5862
LASSITER, D.L.	8510040318	NUREG	LEWIS, R.N.	8510080178*	TOPREP	MACDONALD, C.E.	8510030133	71-9069
LATHAM, S.	8510100087	50-322 G	LEWIS, S.H.	8510100093	40-8027	MACDONALD, C.E.	8510030137	71-5884
LATHAM, S.	8510100087	50-322 G	LEWIS, S.H.	8510310388	40-8027	MACDONALD, C.E.	8510030214	71-251
LATHAM, S.B.	8510280519	50-322 G	LEY, M.	8510150135	50-529 F	MACDONALD, C.E.	8510030222*	71-251
LATHAM, S.B.	8510280519	50-322 G	LIAO, L.H.	8510020307	NUREG	MACDONALD, C.E.	8510030267	71-383
LATTA, R.M.	8510030284*	50-424 Q	LIBARKIN, M.W.	8510080100*	50-329 Q	MACDONALD, C.E.	8510030270*	71-383
LAU, F.L.	8510010181*	50-295 P	LIBARKIN, M.W.	8510080426*	50-330 O	MACDONALD, C.E.	8510030303	71-139
LAUDERBACK, T.E.	8510090175	40-8714	LIBARKIN, M.W.	8510080429*	50-330 O	MACDONALD, C.E.	8510030308*	71-139
LAUDERBACK, T.E.	8510110282	40-8714	LICARI, K.	8510220186	50-10 F	MACDONALD, C.E.	8510030317	71-121
LAURENSEN, A.	8510010306	50-282 S	LICHTENBERGER	8510240326	70-1100	MACDONALD, C.E.	8510030319*	71-121
LAURENSEN, A.S.	8510220062	50-282 S	LIDEN, E.A.	8510180471	50-272 R	MACDONALD, C.E.	8510030333	71-6058
LAUTON, M.D.	8510090512	40-8084	LIETO, R.P.	8510290382	PR	MACDONALD, C.E.	8510090302	71-9201
LAWYER, S.	8510030298*	50-289 Q	LIMROTH, D.	8510070590*	50-247 Q	MACDONALD, C.E.	8510090317	71-9159
LAYFIELD, R.L.	8510010148*	40-8006	LIMROTH, D.	8510210158*	50-247 Q	MACDONALD, C.E.	8510090322	71-230
LAYFIELD, R.L.	8510010181*	40-8006	LIMROTH, D.F.	8510110171*	50-272 Q	MACDONALD, C.E.	8510090325*	71-230
LAZARUS, W.	8510230113*	50-293 Q	LIMROTH, D.F.	8510220192*	50-272 Q	MACDONALD, C.E.	8510090540	71-5507
LAZARUS, W.J.	8510180416*	50-423 Q	LINENBERGER, G.	8510030043	50-424 G	MACDONALD, C.E.	8510110135	71-5862
LAZOL, L.	8510240536	50-344 P	LINENBERGER, G.	8510100005	50-424 G	MACDONALD, C.E.	8510110244*	71-552
LEAR, P.T.	8510020438*	50-245 P	LINENBERGER, G.	8510180185	50-289 G	MACDONALD, C.E.	8510110247	71-9010
LEAR, G.	851004120124*	50-329 E	LIN, N.P.A.	8510290413*	TOPREP	MACDONALD, C.E.	8510150029	71-551
LEAR, G.	8510080272*	50-329 E	LINVILLE, J.	8510280310	50-410 S	MACDONALD, C.E.	8510160370	71-5884
LEAVITT, J.B.	8510180194	50-219 F	LINVILLE, J.C.	8510040181*	50-333 Q	MACDONALD, C.E.	85101700371	71-5939
LEBLOND, P.C.	8510010155	50-295 P	LINVILLE, J.C.	8510040209*	50-244 Q	MACDONALD, C.E.	8510170063	71-9073
LEBLOND, P.C.	8510220304	50-245 P	LINVILLE, J.C.	8510080104*	50-410 Q	MACDONALD, C.E.	8510170066	71-6206
LEBLOND, P.C.	8510230055	50-304 Q	LINVILLE, J.C.	8510220184*	50-410 Q	MACDONALD, C.E.	8510170069	71-9088
LEDDICK, R.S.	8510010442*	50-382 F	LINVILLE, J.C.	8510280348*	50-220 Q	MACDONALD, C.E.	8510170071	71-6722
LEDDICK, R.S.	8510010447*	50-382 F	LISCHINSKY, J.	8510250313*	40-672	MACDONALD, C.E.	8510170072*	71-6722
LEDDICK, R.S.	8510160215	50-382 F	LISCHINSKY, J.	8510160317*	40-672	MACDONALD, C.E.	8510180499	71-88
LEDDIT, J.J.	8510010287*	50-382 F	LITTELL, A.	8510100184	40-8027	MACDONALD, C.E.	8510180501*	71-88
LEDDUC, R.J.	8510090543	71-6574	LITTELL, J.	8510040291	REGGD	MACDONALD, C.E.	8510180529	71-5
LEE, C.	8510090019	FOIA	LITTLE, M.	8510010293	CONTRACT	MACDONALD, C.E.	8510180535*	71-5
LEE, G.R.	8510170171	50-267 F	LITTLE, M.	8510040559	CONTRACT	MACDONALD, C.E.	8510220015	71-133
LEE, G.R.	8510230052	50-267 P	LITTLE, M.	8510150035	CONTRACT	MACDONALD, C.E.	8510220016*	71-133
LEE, R.	8510240610	50-388 P	LITTLE, M.	8510210151	CONTRACT	MACDONALD, C.E.	8510220035	71-5088
LEE, R.	8510280097	27-39	LITTLE, M.	8510210102	CONTRACT	MACDONALD, C.E.	8510220039*	71-5088
LEE, R.	8510290219	27-48	LITTLE, M.	8510250103	CONTRACT	MACDONALD, R.P.	8510110210	50-364 P
LEE, R.	8510240548	WASTE RES	LITTLE, M.	8510250222	CONTRACT	MACE, M.	8510080012	CONTRACT
LEE, V.M.	8510230214*	50-400 T	LITTLE, W.S.	8510080402	50-456 Q	MACE, M.	8510080024	CONTRACT
LEE, W.F.	8510040455	50-423 Q	LITTLE, W.S.	8510080407*	50-456 Q	MACE, M.	8510080139	50-320 P
LEE, W.F.	8510090177	50-423 S	LITTLEHALES, G.	8510300186	QA999	MACE, M.	8510080285	CONTRACT
LEEDCH, P.H.	8510170249	50-293 P	LIU, W.C.	8510070042*	50-259 Q	MACE, M.	8510080317	CONTRACT
LEIDICH, G.R.	8510150366*	50-440 G	LOYD, R.D.	8510250529	NUREG	MACE, M.	8510080594	CONTRACT
LEMKE, J.A.	8510290392*	50-245 P	LOCKER, F.	8510160282	50-133 G	MACE, M.	8510080599	CONTRACT
LEMPGES, T.E.	8510020185	50-410 E	LOCKHART, R.M.	8510040474	50-440 F	MACE, M.	8510090418	CONTRACT
LEMPGES, T.E.	8510030348	50-220 S	LODGE, T.J.	8510100014	50-440 G	MACE, M.	8510090436	CONTRACT
LEMPGES, T.E.	8510160067	50-410 V	LODGE, T.J.	8510100145	50-440 G	MACE, M.	8510220052	50-483 S
LEMPGES, T.E.	8510160218	50-220 P	LODGE, T.J.	8510100145	50-440 G	MACE, M.	8510100131	PR
LEMPGES, T.E.	8510170110	50-220 S	LODGE, T.J.	8510310266	50-440 G	MADDEN, W.J.	8510080228*	50-423 Q
LEMPGES, T.E.	8510180236	50-220 R	LODGE, T.J.	8510310266	50-440 G	MADEDA, T.J.	8510170334*	50-264 Q
LEMPGES, T.E.	8510210056	50-410 F	LODGE, T.J.	8510310272	50-440 G	MADEDA, T.J.	8510210153*	71-346 Q
LEMPGES, T.E.	8510210138	50-410 Q	LODY, R.A.	8510010005*	CONTRACT	MADEDA, T.J.	8510290017*	50-341 Q
LEMPGES, T.E.	8510210213	71-5939	LODY, R.A.	8510160254	50-29 Q	MAISEL, R.J.	8510020114*	50-361 R
LEMPGES, T.E.	8510220011	50-220 S	LOGUE, R.H.	8510210299	50-277 R	MAISEL, R.J.	8510020119*	50-361 R
LEONARDSON, J.D.	8510030108	50-382 E	LONG, N.G.A.	8510020065	50-395 R	MALARO, J.C.	8510010271*	40-8027
LEONART, R.S.	8510010417	50-341 R	LONG, R.L.	8510110066	50-219 P	MALARO, J.C.	8510010275*	40-8027
LEONART, R.S.	8510020180	50-341 S	LOPEZ, D.	8510220139	50-315 F	MALARO, J.C.	8510010296*	40-8027
LEONART, R.S.	8510020203	50-341 S	LORET, L.S.	8510040592	50-282 P	MALARO, J.C.	8510010368*	40-8027
LEONART, R.S.	8510070374	50-341 S	LOUX, R.R.	8510010136	WASTE MGT	MALARO, J.C.	8510010394*	40-8027
LEONART, R.S.	8510090083	50-341 S	LOVE, D.S.	8510080178*	TOPREP	MALIN, L.	8510020094	50-409 R
LEONART, R.S.	8510090182	50-341 S	LOVE, R.S.	8510280394*	50-461 Q	MALLET, B.	8510210010	40-8027
LEONART, R.S.	8510090376	50-341 S	LOWENDALE, P.C.	8510220420*	50-295 Q	MALLODY, C.	8510080301*	50-315 P
LEONART, R.S.	8510240004	50-341 S	LOW, L.D.	8510150251*	40-1386	MALLODY, C.W.	8510030119*	XPORTLIC
LEONART, R.S.	8510250289	50-341 S	LOWENSTEIN, R.	8510160111*	FOIA	MALLODY, C.W.	8510110121	70-1257
LEONART, R.S.	8510260071	50-341 S	LOYSEN, P.	8510040269	70-364	MALLODY, C.W.	8510150200	XPORTLIC
LEONART, R.S.	8510290067	50-341 S	LUDEWIG, H.	8510020257	50-423 A	MALLODY, C.W.	8510220067	70-1257
LEONART, R.S.	8510310015	50-341 S	LUEBKE, E.A.	8510100031	50-443 G	MALONE, D.L.	8510110192*	50-423 A
LEONART, R.S.	8510310057	50-341 S	LUEBKE, E.A.	8510180247	50-142 G	MANDEL, J.W.	8510040592	50-282 P
LEONART, R.S.	8510310404	50-341 S	LUNDVALL, A.E.	8510110275	71-383	MANEATIS, G.A.	8510290267	50-275 P
LEONARD, J.D.	8510020019*	50-322 Q	LUNDVALL, A.E.	8510150469*	50-317 P	MANEATIS, G.A.	8510290276*	50-275 P
LEONARD, J.D.	8510150372	50-322 P	LUNDVALL, A.E.	8510210140	50-317 Q	MANGAN, C.V.	8510020170	50-410 A
LEONARD, J.D.	8510230074	50-322 P	LUNDVALL, A.E.	8510280339	50-317 P	MANGAN, C.V.	8510020433	50-410 S
LEONARD, J.D.	8510290082*	50-322 P	LUNDVALL, A.E.	8510310044	50-317 P	MANGAN, C.V.	8510040143	50-220 P
LEONARD, J.D.	8510250385	50-322 F	LYASH, J.	8510250445*	50-354 Q	MANGAN, C.V.	8510040353	50-410 A
LEONARD, R.H.	8510290108	QA999	LYASH, J.J.	8510280360*	50-354 Q	MANGAN, C.V.	8510070261	50-220 P
LEROY, P.G.	8510220263	50-413 F	LYNCH, T.	8510230183*	50-317 Q	MANGAN, C.V.	8510080467	50-410 A

PERSONAL AUTHOR INDEX 361

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MANGAN, C.V.	8510080480	50-416 E	MARTIN, T.J.	8510300126	50-354 S	MAYS, R.L.	8510040152*	50-320 P
MANGAN, C.V.	8510090013	50-410 E	MARTIN, T.O.	8510150228*	50-250 Q	MAYS, R.L.	8510040155*	50-320 P
MANGAN, C.V.	8510110084	50-410 E	MARTIN, T.T.	8510020016	50-322 Q	MCALPINE, E.J.	8510180058*	70-27
MANGAN, C.V.	8510150212	50-410 A	MARTIN, T.T.	8510020192	50-293 Q	MCALPINE, E.J.	8510180071*	70-143
MANGAN, C.V.	8510170109	50-410 A	MARTIN, T.T.	8510030227	50-245 Q	MCALPINE, E.J.	8510180078*	70-143
MANGAN, C.V.	8510180125	50-410 S	MARTIN, T.T.	8510040163	50-29 Q	MCCBREARY, R.A.	8510020050*	50-277 Q
MANGAN, C.V.	8510180157	50-410 S	MARTIN, T.T.	8510040464	50-333 Q	MCCBREARY, R.A.	8510030053*	50-309 Q
MANGAN, C.V.	8510180395	50-410 S	MARTIN, T.T.	8510070068	50-309 Q	MCCBREARY, R.A.	8510080189*	50-286 Q
MANGAN, C.V.	8510180440	50-410 S	MARTIN, T.T.	8510070204	70-1100 Q	MCCBRIDE, M.	8510020244*	50-293 Q
MANGAN, C.V.	8510230149	50-410 A	MARTIN, T.T.	8510080030	50-244 Q	MCCBRIDE, M.	8510020260*	50-293 Q
MANGAN, C.V.	8510230216	50-410 A	MARTIN, T.T.	8510080155	70-820 Q	MCCBRIDE, M.	8510220284*	50-293 Q
MANGAN, C.V.	8510240444	50-220 F	MARTIN, T.T.	8510080217	50-423 Q	MCCABE, B.	8510240174	50-249 S
MANGAN, C.V.	8510250438	50-410 Q	MARTIN, T.T.	8510080238	50-3 Q	MCCABE, E.C.	8510080042	50-336 S
MANGAN, C.V.	8510310135	50-410 A	MARTIN, T.T.	8510080339	50-219 Q	MCCABE, E.C.	8510080604*	50-184 Q
MANN, M.M.	8510150240*	FOIA	MARTIN, T.T.	8510080451	50-322 Q	MCCABE, E.C.	8510230213*	50-97 Q
MANNING, T.G.	8510010214*	50-219 P	MARTIN, T.T.	8510100205	70-371 Q	MCCABE, E.C.	8510310167*	50-213 Q
MANOLY, K.A.	8510080401*	50-443 Q	MARTIN, T.T.	8510110040	50-297 Q	MCCALLIE, T.S.	8510110178	NUREG
MARGULIES, N.B.	8510220178*	50-445 A	MARTIN, T.T.	8510150061	50-387 F	MCCARDOLL, R.K.	8510030433	WASTE MGT
MARGULIES, M.B.	8510030043	50-424 G	MARTIN, T.T.	8510150111	50-29 F	MCCARDOLL, R.K.	8510090151	PR
MARGULIES, M.B.	8510100005	50-424 G	MARTIN, T.T.	8510150113	50-213 F	MCCLELLAND, N.I.	8510100077	PR
MARGULIES, M.B.	8510220224	50-424 G	MARTIN, T.T.	8510160010	50-333 Q	MCCLOSKEY, J.P.	8510100060	PR
MARINI, W.	8510020013	50-382 E	MARTIN, T.T.	8510160048	50-352 Q	MCCORKLE, G.W.	8510070015	70-2322
MARINI, W.	8510020473	50-382 E	MARTIN, T.T.	8510160226	50-272 Q	MCCORKLE, G.W.	8510070018	70-2322
MARINI, W.	8510020478	50-382 E	MARTIN, T.T.	8510170007	50-352 F	MCCORKLE, G.W.	8510070019	70-687
MARINI, W.S.	8510010557	50-382 E	MARTIN, T.T.	8510170143	50-320 Q	MCCORKLE, G.W.	8510070022	50-186 F
MARINI, W.S.	8510020459	50-382 E	MARTIN, T.T.	8510170290	70-371 Q	MCCORKLE, G.W.	8510070557	70-2322
MARINI, W.S.	8510020461	50-382 E	MARTIN, T.T.	8510180411	50-423 Q	MCCORKLE, G.W.	8510180213*	PR
MARINI, W.S.	8510020465	50-382 E	MARTIN, T.T.	8510210086	50-354 Q	MCCORKLE, G.W.	8510180220*	PR
MARINI, W.S.	8510020500	50-382 E	MARTIN, T.T.	8510220103	50-244 Q	MCCORKLE, G.W.	8510280426	XPORTLIC
MARINI, W.S.	8510030147	50-382 E	MARTIN, T.T.	8510220124	50-334 Q	MCCORKLE, G.W.	8510280436	70-2322
MARINI, W.S.	8510030299	50-382 E	MARTIN, T.T.	8510230038	50-309 Q	MCCORMICK, R.D.	8510280457	70-3020
MARKEY, E.J.	8506260600*	50-346 S	MARTIN, T.T.	8510230109	50-293 Q	MCCORMICK, R.D.	8510030433	NUREG
MARKEY, E.J.	8510010099*	50-416 U	MARTIN, T.T.	8510230233	50-244 Q	MCCORMICK, R.D.	8510080398*	50-266 Q
MARKEY, E.J.	8510010536*	50-322 U	MARTIN, T.T.	8510250215	50-271 Q	MCCRACKEN, C.	8510060325	50-346 P
MARKEY, E.J.	8510010566*	COMMISSION	MARTIN, T.T.	8510250219	50-320 Q	MCCRACKEN, C.E.	8510110239*	50-445 G
MARKEY, E.J.	8510070511*	50-346 U	MARTIN, T.T.	8510250454	50-334 Q	MCCULLUGH, R.W.	8510210145*	TOPREP
MARKHAM, J.J.	8510090311	WASTE RES	MARTIN, T.T.	8510250456	50-271 Q	MCDONALD, D.G.	8510030231	50-250 P
MARKHAM, J.J.	8510090490	WASTE RES	MARTIN, T.T.	8510250493	50-272 Q	MCDONALD, D.R.P.	8509110513	50-348 R
MARKS, B.K.	8510160242	50-259 F	MARTIN, T.T.	8510260299	50-54 Q	MCDONALD, D.R.P.	8510010495	50-364 R
MARKS, M.	8510160018*	50-255 Q	MARTIN, T.T.	8510260387	50-387 Q	MCDONALD, D.R.P.	8510010635	50-348 R
MARROW, R.	8510020191*	50-335 P	MARTIN, T.T.	8510310125	70-1100 Q	MCDONALD, D.R.P.	8510020001	50-348 S
MARROW, R.	8510020194*	FOIA	MARTIN, T.T.	8510310178	50-286 Q	MCDONALD, D.R.P.	8510030146	50-364 P
MARSHALL, B.M.	8510040367	50-280 S	MARTIN, T.T.	8510310201	50-387 F	MCDONALD, D.R.P.	8510070349	50-348 Q
MARSHALL, B.M.	8510150173	50-280 S	MARTIN, T.T.	8510310210	70-371 Q	MCDONALD, D.R.P.	8510070490	50-348 Q
MARSHALL, J.S.	8510100001	50-445 Q	MARTIN, T.T.	8510310424	70-687 Q	MCDONALD, D.R.P.	8510150188	50-348 H
MARSHALL, J.S.	8510250321	50-445 S	MARTIN, W.G.	8510080453*	50-322 Q	MCDONALD, D.R.P.	8510150285	50-348 P
MARSHALL, J.S.	8510250370	50-445 S	MARTINEZ, E.D.	8510080308	27-48 Q	MCDONALD, D.R.P.	8510160081	50-348 P
MARSHALL, J.S.	8510260224	50-445 S	MARTINEZ, E.D.	8510250183	27-48 Q	MCDONALD, D.R.P.	8510170401	50-348 S
MARSHALL, J.S.	8510280484	50-445 S	MARTINEZ, E.D.	8510250314	27-48 Q	MCDONALD, D.R.P.	8510180134	50-348 P
MARSHALL, J.S.	8510280487	50-445 S	MASNIK, M.T.	8510070271	50-320 P	MCDONALD, D.R.P.	8510180359	50-348 Q
MARSHALL, J.S.	8510280493	50-446 S	MASNIK, M.T.	8510180084	50-320 H	MCDONALD, D.R.P.	8510220054	50-364 R
MARSHALL, J.S.	8510280500	50-445 S	MASNYK, O.M.	8510150304*	50-321 Q	MCDONALD, D.R.P.	8510220101	50-348 R
MARSTON, R.R.	8510220406*	50-261 Q	MASNYK, O.M.	8510220229*	50-302 Q	MCDONALD, D.R.P.	8510250236	50-348 F
MARTIN, J.	851009187*	50-397 P	MASNYK, O.M.	8510240392*	50-269 Q	MCDONALD, D.R.P.	8510250428	50-348 F
MARTIN, J.B.	8510070177	50-344 F	MASSA, S.A.	8510250583	NUREG	MCDONALD, D.R.P.	8510280034	50-348 F
MARTIN, J.B.	8510080305	50-312 Q	MASSEY, J.V.	8510010626*	PROJ	MCDONALD, D.R.P.	8510280294	50-348 V
MARTIN, J.B.	8510080450	STATE PROJ	MASSEY, J.V.	8510210196	PROJ	MCDONALD, D.R.P.	8510300248	50-348 S
MARTIN, J.B.	8510090252	50-508 Q	MASSEY, W.E.	8510100134	PR	MCDONALD, D.R.P.	8510300307	50-348 S
MARTIN, J.B.	8510090324	50-312 Q	MASSIN, H.L.	8510010052	50-373 P	MCDONALD, D.R.P.	8510300313	50-348 S
MARTIN, J.B.	8510090328*	50-312 Q	MASSIN, H.L.	8510010067	50-373 Q	MCDONALD, D.R.P.	8510090417	50-309 S
MARTIN, J.B.	8510150243	50-312 S	MASSIN, H.L.	8510080404	50-374 P	MCELHINNEY, T.F.	8510020290*	50-302 Q
MARTIN, J.B.	8510150408	50-526 Q	MASSIN, H.L.	8510080484	50-373 Q	MCELHINNEY, T.F.	8510070480*	50-414 Q
MARTIN, J.B.	8510150411*	50-526 Q	MASSIN, H.L.	8510080490	50-373 F	MCELROY, N.L.	8510090096	PR
MARTIN, J.B.	8510290095	50-529 A	MASSIN, H.L.	8510090002	50-373 F	MCELROY, N.L.	8510090232*	PR
MARTIN, L.E.	8510010582*	50-482 Q	MASSIN, H.L.	8510100082	50-373 P	MCFADDEN, J.	8510040172*	50-29 Q
MARTIN, L.E.	8510040238	50-368 S	MASSIN, H.L.	8510230036	50-373 F	MCFADDEN, J.	8510250465*	50-334 Q
MARTIN, L.E.	8510040275	50-285 S	MASSIN, H.L.	8510230053	50-373 P	MCFADDEN, J.	8510280305*	50-54 Q
MARTIN, L.E.	8510170378*	50-313 Q	MASSIN, H.L.	8510230238	50-373 P	MCFADDEN, J.	8510310182*	50-286 Q
MARTIN, L.E.	8510210288*	50-482 Q	MATTHIAS, C.M.	8510010405*	FOIA	MCGAUGHY, J.	8510010170*	50-418 V
MARTIN, L.E.	8510220218	50-382 Q	MATTHEWS, D.B.	8406150267*	50-382 F	MCGAUGHY, R.W.	8510040255	50-331 Q
MARTIN, L.E.	8510240343*	50-285 Q	MATTHEWS, D.B.	8408210595*	50-382 F	MCGAUGHY, R.W.	8510150332	50-331 P
MARTIN, L.E.	8510310283	50-382 Q	MATTHEWS, T.P.	8510230313	50-285 R	MCGAUGHY, R.W.	8510170281	50-331 P
MARTIN, L.E.	8510310296	50-267 Q	MATTSON, R.J.	7905290232	50-320 P	MCGAUGHY, R.W.	8510210020	50-331 P
MARTIN, L.E.	8510310343	50-458 Q	MATTSON, R.J.	8510270109*	COMMISSION	MCGAUGHY, R.W.	8510210149	50-331 F
MARTIN, L.E.	8510310444	50-267 Q	MATTSON, R.J.	8308310389*	COMMISSION	MCGAUGHY, R.W.	8510250394	50-331 F
MARTIN, R.D.	8510040460	50-267 P	MAUPIN, M.W.	8510210093	50-289 G	MCGAUGHY, R.W.	8510280001	50-331 Q
MARTIN, R.D.	8510070354	50-382 P	MAURA, F.	8510160274*	50-205 Q	MCGAUGHY, R.W.	8510280353	50-331 F
MARTIN, R.D.	8510290117	40-6022	MAURIN, L.V.	8510010392*	50-382 F	MCGAUGHY, R.W.	8510280384	50-331 Q
MARTIN, R.D.	8510290127*	40-6022	MAURIN, L.V.	8510010398*	50-382 F	MCGRATH, J.	8510250437	I&E
MARTIN, R.D.	8510290136*	40-6022	MAURIN, L.V.	8510010399*	50-382 F	MCGRATH, R.S.	8510240840	50-309 S
MARTIN, R.M.	8510110243	71-552	MAUWS, L.L.	8510090187*	50-397 P	MCGUIRE, D.R.	8510080284*	50-327 Q
MARTIN, R.M.	8510110252	71-552	MAXELL, M.H.	8510280110	WASTE MGT	MCGUIRE, D.R.	8510080288*	50-335 Q
MARTIN, R.M.	8510110253*	71-552	MAXFIELD, A.F.	8510040317	PR	MCGUIRE, D.R.	8510150304*	50-321 Q
MARTIN, T.J.	8510030422	50-354 S	MAXIN, A.M.	8510150032	70-143	MCGUIRE, D.R.	8510150336*	70-143
MARTIN, T.J.	8510170236	50-354 S	MAXWELL, D.C.	8510180472	50-237 R	MCGUIRE, D.R.	8510180082*	50-259 Q
MARTIN, T.J.	8510210108	50-354 Q	MAYKELL, G.F.	8510090333*	50-400 Q	MCGUIRE, D.R.	8510220229*	50-302 Q
MARTIN, T.J.	8510250446	50-354 A	MAYKELL, G.F.	8510160309	40-3453	MCGUIRE, D.R.	8510240392*	50-269 Q
MARTIN, T.J.	8510300101	50-354 S	MAYHUE, D.B.	8510210214	71-6206	MCGURRIN, H.J.	8510030005	50-352 G

362 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCGURRIN,H.J.	8510110063	50-352 Q	METZGER,J.R.	8510220223*	70-25	MOHR,L.J.	8510070581*	CONTRACT
MCINTYRE,R.P.	8510150015*	50-344 Q	METZGER,S.R.	8510220245*	70-25	MOHR,L.J.	8510080027*	CONTRACT
MCINTYRE,R.P.	8510310247*	50-254 Q	MEYER,G.	8510020260*	50-290 Q	MOISIDIS,N.	8510220040*	50-346 P
MCKEE,C.R.	8510080141*	CONTRACT	MEYER,G.W.	8510230213*	50-97 Q	MONTGOMERY,J.L.	8510080507	50-312 Q
MCKEE,P.F.	8510150146*	50-267 Q	MEYER,H.R.	8510090332*	WASTE MGT	MONTGOMERY,J.L.	8510150076	50-27 Q
MCKEE,P.F.	8510150228*	50-250 Q	MEYER,T.A.	8510010032	50-244 S	MONTGOMERY,J.L.	8510150342	70-754
MCKENZIE,J.H.	8510010351*	50-382 Q	MEYER,T.A.	8510230061*	50-455 Q	MONTGOMERY,J.L.	8510160020	70-734
MCKINLEY,J.C.	8510080049*	50-329 O	MEYERS,S.	85-0090464*	FOIA	MONTGOMERY,J.L.	8510220091	50-344 Q
MCKINLEY,J.C.	8510080038*	50-329 O	MICHAELIS,J.	8510090006	50-346 S	MONTGOMERY,J.L.	8510220356	70-734
MCKINLEY,J.C.	8510080045*	50-329 A	MIEGEL,N.J.	8510310247*	50-254 Q	MONTGOMERY,J.L.	8510300144	50-528 Q
MCKINLEY,J.C.	8510080051*	50-329 F	MIEGEL,N.J.	8510310326*	QA999	MONTGOMERY,M.F.	8510110224	PR
MCKINLEY,J.C.	8510080073*	50-329 O	MILAM,S.B.	8510220239*	50-382 P	MONTGOMERY,M.F.	8510150193	PR
MCKINLEY,J.C.	8510080329*	50-330 O	MILBROT,W.E.	8510100051*	50-331 Q	MOONAN,W.S.	8510010092*	50-445 A
MCKINLEY,J.C.	8510080337*	50-329 O	MILHOAN,J.L.	8510070359*	50-400 Q	MOONAN,W.S.	8510030404*	50-445 A
MCKINLEY,J.C.	8510080341*	50-329 O	MILLER,A.	8510150310	50-320 F	MOONEY,G.	8510090222	40-8714
MCLEAREN,T.	8510080349*	50-329 O	MILLER,D.E.	8510070472*	50-409 Q	MOORE,A.B.	8510160311	PR
MCLEAREN,T.	8510100154	PR	MILLER,G.	8510010616	50-382 R	MOORE,J.E.	8510220231	50-400 G
MCLEAREN,T.	8510080009	CONTRACT	MILLER,G.	8510150476	50-382 R	MOORE,J.E.	8510230209	50-400 T
MCNATT,E.M.	8510240034	CONTRACT	MILLER,H.L.	8510100066	50-280 F	MOORE,J.E.	8510230227*	50-400 T
MCNATT,E.M.	8510310402	50-336 S	MILLER,J.H.	8510220207*	50-424 A	MOORE,J.E.	8510230227*	50-400 T
MCNEIL,M.B.	8510240046	WASTE RES	MILLER,J.L.	8510010286*	50-400 E	MOORE,J.W.	8510040182*	50-424 F
MCNEILL,C.A.	8510020226*	50-272 F	MILLER,L.	8510070331	50-312 S	MOORE,R.C.	8510110218	50-312 F
MCNEILL,C.A.	8510030087	50-272 F	MILLER,L.	8510080052	50-312 S	MOORE,R.D.	8510240324	50-10 F
MCNEILL,C.A.	8510080106	50-272 P	MILLER,L.	8510150237	50-528 S	MOORE,R.N.	8510090515	XPORTLIC
MCNEILL,C.A.	8510170382	50-272 P	MILLER,L.	8510220075*	50-528 Q	MOORE,R.N.	8510170262	XPORTLIC
MCNEILL,C.A.	8510220050	50-272 P	MILLER,L.F.	8510220070*	50-528 Q	MOORE,R.N.	8510170265	XPORTLIC
MCNEILL,C.A.	8510220068	50-272 P	MILLER,L.F.	8510280145*	50-528 Q	MOORE,R.N.	8510170481	XPORTLIC
MCNEILL,C.A.	8510220262	50-272 P	MILLER,M.A.	8510210090*	50-354 Q	MOORE,R.N.	8510170482	XPORTLIC
MCNEILL,C.A.	8510220270	50-272 P	MILLER,M.A.	8510040054	50-424 A	MOORE,R.N.	8510170483	XPORTLIC
MCNEILL,C.A.	8510220315	50-272 R	MILLER,M.A.	8510090534	50-424 F	MOORE,R.N.	8510170484	XPORTLIC
MCNEILL,C.A.	8510220316	50-272 F	MILLER,M.A.	8510170339	50-424 A	MOORE,R.N.	8510180011	XPORTLIC
MCNEILL,C.A.	8510220320	50-272 P	MILLER,M.I.	8510110217	50-329 G	MOORE,R.N.	8510180012	XPORTLIC
MCNEILL,C.A.	8510220353	50-272 P	MILLER,M.S.	8510010075	PR	MOORE,R.N.	8510180131	XPORTLIC
MCNEILL,C.A.	8510240649	50-272 P	MILLER,M.T.	8510040466*	50-333 Q	MOORMAN,J.H.	8510070513*	50-269 Q
MCNEILL,C.A.	8510250081	50-272 P	MILLER,N.E.	8510020228	NUREG	MORGAN,H.E.	8510010628	50-206 S
MCNEILL,W.M.	8510040415*	50-458 Q	MILLER,V.L.	8510090139*	PR	MORGAN,H.E.	8510010641	50-206 R
MCNEILL,W.M.	8510240312*	50-458 Q	MILLER,W.F.	8510230188*	50-387 Q	MORGAN,H.E.	8510201113	50-361 R
MCNEILL,W.M.	8510240347*	50-458 Q	MILLER,W.H.	8510020290*	50-302 Q	MORGAN,H.E.	8510020212	50-361 S
MCNEILL,W.M.	8510250482*	50-458 Q	MILLER,W.O.	8510010140*	FOIA	MORGAN,H.E.	8510090183	50-361 S
MEARKE,J.	8510020229*	50-382 P	MILLER,W.O.	8510030377	50-397 P	MORGAN,H.E.	8510170385	50-361 S
MEDFORD,M.O.	8510040287	50-381 P	MILLER,W.O.	8510150258	50-244 P	MORGAN,H.E.	8510170455	50-361 S
MEDFORD,M.O.	8510090007	50-206 F	MILLS,M.P.	8510030029	50-382 E	MORGAN,H.E.	8510180358	50-362 S
MEDFORD,M.O.	8510100024	50-206 P	MILTENBERGER,S.	8510010623	50-483 R	MORGAN,H.E.	8510210290	50-361 S
MEDFORD,M.O.	8510100034	50-206 P	MILTENBERGER,S.	8510010646	50-483 S	MORGAN,H.E.	8510220127	50-361 S
MEDFORD,M.O.	8510100036	50-206 P	MILTENBERGER,S.	8510010648	50-483 S	MORGAN,H.E.	8510220152	50-206 S
MEDFORD,M.O.	8510100080	50-206 Q	MILTENBERGER,S.	8510010652	50-483 S	MORGAN,H.E.	8510250568	50-362 S
MEDFORD,M.O.	8510100083	50-206 P	MILTENBERGER,S.	8510020089	50-483 S	MORGAN,H.E.	8510290133	50-206 S
MEDFORD,M.O.	8510100092	50-206 F	MILTENBERGER,S.	8510170294	50-483 S	MORGAN,H.E.	8510290355	50-362 S
MEDFORD,M.O.	8510100104	50-206 P	MILTENBERGER,S.	8510220052	50-483 S	MORGAN,H.E.	8510300165	50-362 S
MEDFORD,M.O.	8510100124	50-206 P	MIMS,R.	8510030434*	CONTRACT	MORGAN,H.E.	8510300724	50-206 S
MEDFORD,M.O.	8510110105	50-361 P	MINECK,D.L.	8510090283	50-331 S	MORGAN,H.E.	8510310549	50-361 S
MEDFORD,M.O.	8510150141	50-361 P	MINECK,D.L.	8510100019	50-331 P	MORGAN,H.E.	8510310591	50-362 S
MEDFORD,M.O.	8510150199	50-361 P	MINECK,D.L.	8510150432	50-331 S	MORGAN,H.E.	8510310596	50-362 S
MEDFORD,M.O.	8510160046	50-206 P	MINECK,D.L.	8510210289	50-331 R	MORGAN,H.E.	8510070341	50-261 Q
MEDFORD,M.O.	8510170179	50-206 P	MINECK,D.L.	8510280396	50-331 S	MORGAN,H.E.	8510080065	50-261 S
MEDFORD,M.O.	8510170267	50-361 P	MINECK,D.L.	8510290405	50-331 S	MORGAN,H.E.	8510090055	50-261 S
MEDFORD,M.O.	8510180167	50-361 P	MINECK,D.L.	8510310140	50-331 P	MORGAN,H.E.	8510180239	50-261 R
MEDFORD,M.O.	8510180328	50-361 P	MINECK,D.L.	8510310513	50-331 R	MORGAN,H.E.	8510180532	50-261 S
MEDFORD,M.O.	8510210024	50-206 P	MINER,S.	8510080112	50-312 P	MORGAN,H.E.	8510220248	50-261 F
MEDFORD,M.O.	8510220174	50-206 P	MINOGUE,R.B.	8404040147*	PR	MORGAN,H.E.	8510300153	50-261 S
MEDFORD,M.O.	8510280285	50-361 Q	MINOGUE,R.B.	8405240363	RES	MORGAN,T.	8510020320	50-382 E
MEDFORD,M.O.	8510280296	50-361 R	MINOGUE,R.B.	8503040154*	PR	MORGAN,T.	8510020415	50-382 E
MEDFORD,M.O.	8510280419	50-361 P	MINOGUE,R.B.	8503080521*	PR	MORGAN,T.	8510020416	50-382 E
MEDLOCK,R.L.	8510110111	40-8452	MINOGUE,R.B.	8510090193*	PR	MORGAN,T.	8510020424	50-382 E
MEDLOCK,R.L.	8510110123	40-8452	MINOGUE,R.B.	8510160039	50-320 P	MORGAN,W.M.	8510010326*	50-382 P
MEDULAN,K.	8510090388	50-265 S	MIOSA,D.	8510170374	50-454 S	MORGAN,W.M.	8510020487	50-382 E
MELLEN,L.S.	8510020290*	50-302 Q	MIOSA,D.	8510280349	50-455 A	MORLEY,J.A.	8510240290*	WASTE MGT
MENDEZ,R.	8510110038*	50-456 Q	MIOSA,D.	8510300107	50-456 S	MORRELL,M.P.	8510160247	50-289 I
MENGER,C.	8510220067	50-315 S	MITTLER,L.	8509250119	50-354 K	MORRIS,G.W.	8510150228*	50-250 Q
MERSCHOFF,E.W.	8510010298*	QA999	MITTLER,L.	8510020195	50-354 A	MORRIS,P.A.	8510040451	70-364
MERSCHOFF,E.W.	8510070296*	QA999	MITTLER,L.	8510030031	50-354 F	MORRIS,R.H.	8510210258	50-413 F
MERSCHOFF,E.W.	8510070342*	QA999	MITTLER,L.	8510030040	50-354 A	MORRIS,R.H.	8510210263	50-413 F
MERSCHOFF,E.W.	8510080232*	QA999	MITTLER,L.	8510030103	50-354 E	MORRISON,W.M.	8510160212*	FOIA
MERSCHOFF,E.W.	8510080417*	QA999	MITTLER,L.	8510030148	50-354 A	MORROW,M.	8510240389*	50-261 F
MERSCHOFF,E.W.	8510150015*	50-344 Q	MITTLER,L.	8510080422	50-354 A	MORZENTIS,P.	8510170447	40-8064
MERSCHOFF,E.W.	8510180408*	QA999	MITTLER,L.	8510150222	50-354 A	MOSELEY,N.C.	8510310865*	50-346 Q
MERSCHOFF,E.W.	8510210342*	QA999	MITTLER,L.	8510180292	50-354 Q	MOSKOWITZ,J.	8510250401	50-277 Q
MERSCHOFF,E.W.	8510310326*	QA999	MITTLER,L.	8510220209	50-354 F	MOSLAK,T.	8510310132	50-320 S
MESERVE,R.A.	8510100170	40-2061	MITTLER,L.	8510220300	NUREG	MOSS,J.C.	8510110240	71-139
MESERVE,R.A.	8510100170	40-2061	MITTLER,L.	8510220329	50-354 E	MOUNT,D.K.	8510180283	REGGO
MESERVE,R.A.	8510240355	40-2061	MITTLER,L.	8510270481	50-354 A	MOXLEY,M.	8510150271	40-4492
MESERVE,R.A.	8510240355	40-2061	MITTLER,L.	8510263295	50-354 E	MOY,M.	8510300279	50-249 S
MESERVE,R.A.	8510310284	40-2061	MITTLER,L.	8510290373	50-354 F	MRAZEK,R.J.	8510010536*	50-322 U
MESERVE,R.A.	8510310284	40-2061	MITTLER,L.	8510300179	50-354 F	MROCKA,E.J.	8510030332	50-423 S
MESERVE,R.A.	8510310336	40-8027	MIZUNO,G.	8510170111*	50-445 A	MROCKA,E.J.	8510110022	50-423 A
MESERVE,R.A.	8510310341	40-2061	MIZUNO,G.S.	8510030034	50-445 G	MROCKA,E.J.	8510220033	50-245 P
MESERVE,R.A.	8510310341	40-2061	MIZUNO,G.S.	8510180341	50-445 G	MUFFETT,J.W.	8510040223*	50-461 Q
METZGER,J.R.	8510220188*	70-25	MOHR,C.M.	8510040411	NUREG	MUFFETT,J.W.	8510070389*	50-461 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MUFFETT, J.W.	8510170317*	50-456 Q	NEFF, J.O.	8510280056	WASTE MGT	NORRHOLM, L.	8510090238	50-272 S
MUKHERJEE, A.	8510090040	WASTE RES	NEFF, J.O.	8510280108	WASTE MGT	NORRHOLM, L.	8510210156*	50-247 Q
MULCAHEY, E.	8510220105	50-353 F	NEHNEVA, J.A.	8510230225*	50-400 T	NORRHOLM, L.J.	8510110117*	50-272 Q
MULDER, R.U.	8510110187	50-62 F	NEIGHBORS, J.D.	8510310174	50-247 P	NORRHOLM, L.J.	8510220182*	50-272 Q
MULLEN, R.	8510080284*	50-329 O	NEILSEN, E.H.	8510240120	WASTE MGT	NORRHOLM, L.J.	8510250259	50-286 F
MUNTZING, L.M.	8510170423*	FOIA	NEISLER, J.H.	8510080610*	50-440 Q	NORRIS, F.S.	8510290342	PR
MURAT, A.	8510090261	50-272 J	NEISLER, J.H.	8510170309*	50-440 Q	NORRIS, J.A.	8510310542	50-295 P
MURAT, A.	8510160199	50-272 J	NEISLER, J.H.	8510280142*	50-440 Q	NORTON, J.F.	8510220013*	50-440 Q
MURLEY, T.E.	8108060119*	COMMISSION	NELSON, C.A.	8510150400*	FOIA	NORTON, J.F.	8510290336*	50-440 Q
MURLEY, T.E.	8510020214	50-272 F	NELSON, J.S.	8510100175	PR	NOVACHEK, F.	8510220407	50-267 R
MURLEY, T.E.	8510040243	50-317 Q	NELSON, W.	8510030131	NUREG	NOVAK, T.M.	8510020462	50-400 Q
MURLEY, T.E.	8510070243	50-352 F	NELSON, W.R.	8510040397	NUREG	NOVAK, T.M.	8510040554	50-458 P
MURLEY, T.E.	8510170168*	FOIA	NERON, G.	8510020076	50-336 R	NOVAK, T.M.	8510090309	50-395 V
MURLEY, T.E.	8510220064	50-247 Q	NERSES, V.	8510090480	50-443 F	NOVAK, T.M.	8510090493	50-458 P
MURLEY, T.E.	8510220421	50-219 Q	NERSES, V.	8510150088	50-443 A	NOVAK, T.M.	8510110011	50-329 A
MURLEY, T.E.	8510230207	STATE PRO G	NERSES, V.	8510300257	50-443 A	NOVAK, T.M.	8510110274	50-498 A
MURLEY, T.E.	8510280292	50-247 P	NEUMANN, M.R.	8510090173	40-8452	NOVAK, T.M.	8510150252	50-390 A
MURLEY, T.E.	8510310166	50-271 Q	NEWBURGH, G.	8510020074	50-245 R	NOVAK, T.M.	8510240062	50-423 A
MURLEY, T.E.	8510310170*	50-271 Q	NEWMAN, J.R.	8510020166	50-498 G	NOVAK, T.M.	8510250029	50-413 P
MURPHY, C.E.	8510010388*	50-328 S	NEWMAN, J.R.	8510020166	50-498 G	NOVAK, T.M.	8510250264	50-416 F
MURPHY, C.E.	8510010420*	50-416 S	NEWMAN, J.R.	8510100074	50-498 G	NOVAK, T.M.	8510250318	50-390 H
MURPHY, C.E.	8510020221*	50-416 S	NEWMAN, J.R.	8510100074	50-498 G	NOVAK, T.M.	8510250595*	50-412 A
MURPHY, J.D.	8510090505	71-9192	NEWMAN, J.H.	8510110203	50-498 G	NOVAK, T.M.	8510280106	50-397 P
MURPHY, J.D.	8510150292	71-9192	NEWMAN, J.H.	8510110203	50-498 G	NOVAK, T.M.	8510280414	50-395 P
MURPHY, J.D.	8510150395	71-9192	NEWMAN, J.R.	851018,230	50-498 G	NOVAK, T.M.	8510300048	50-412 E
MURPHY, J.J.	8510280476	50-77 P	NEWMAN, J.R.	8510180230	50-498 G	NOVAK, T.M.	8510300073	50-417 A
MURPHY, K.G.	8510160037*	50-245 Q	NEWMAN, J.R.	8510210081	50-498 G	NOVAK, T.M.	8510300103	50-416 P
MURPHY, M.R.	8510070351	PRM	NEWMAN, J.R.	8510210081	50-498 G	NOVAK, T.M.	8510310005	50-416 P
MURPHY, M.R.	8510100133*	PRM	NEWMAN, J.R.	8510210210	50-498 G	NOVAK, T.M.	8510310230	50-498 E
MURPHY, R.F.	8510100022	PR	NEWMAN, J.R.	8510210210	50-498 G	NUSSBAUMER, D.A.	8510240517	WASTE MGT
MURPHY, W.P.	8510080198	50-271 F	NEWSOME, R.W.	8510040531*	50-424 Q	NUSSBAUMER, D.A.	8510240563	WASTE MGT
MURPHY, W.P.	8510080352	50-271 F	NEWTON, J.H.	8510040586	50-382 E	NUSSBAUMER, D.A.	8510250486	PR
MURPHY, W.P.	8510080390	50-271 Q	NICHOLSON, N.A.	8510100051*	50-331 Q	NUSSBAUMER, D.A.	8510790200	WASTE MGT
MURPHY, W.P.	8510090541	71-9080	NICHOLSON, N.A.	8510220420*	50-295 Q	NUSSBAUMER, D.A.	8510290279	WASTE MGT
MURPHY, W.P.	8510110220	71-9176	NICHOLSON, N.A.	8510310294*	50-2 Q	NUSSBAUMER, D.A.	8510290424	WASTE MGT
MURPHY, W.P.	8510110225	71-9079	NICHOLSON, T.J.	8510090308*	PROJ	O'CONNOR, P.W.	8510150024*	50-483 P
MURPHY, W.P.	8510180068	50-271 P	NICHOLSON, T.J.	8510290415	NUREG	O'DONNELL, W.L.	8510090423*	CONTRACT
MURPHY, W.P.	8510220048	50-271 R	NICKLES, P.J.	8510310284	40-2061	O'DWYER, G.F.	8510080140*	50-440 Q
MURPHY, W.P.	8510220212	50-271 P	NICKLES, P.J.	8510310284	40-2061	O'MEALIA, M.	8510090084	FOIA
MURPHY, W.P.	8510310211	50-271 F	NICOLARAS, H.	8510020243	50-269 F	O'MEALIA, M.K.	8510180155	FOIA
MURRAY, B.	8510010126*	40-8027	NICOLARAS, H.	8510040565	50-269 P	O'NEIL, M.	8510100094	PR
MURRAY, B.	8510010421*	40-8027	NICOLARAS, H.	8510090075	50-269 P	O'REILLY, J.P.	8510170052*	FOIA
MURRAY, B.	8510310369*	50-382 Q	NICOLARAS, H.	8510210189	50-269 P	O'REILLY, J.P.	8510170352*	50-413 Q
MURRAY, T.D.	8510150393	50-346 F	NICOLARAS, H.	8510300188	50-269 P	O'REILLY, J.P.	8510230054*	50-366 Q
MURRAY, W.F.	8510230194*	50-387 Q	NICOD, G.A.	8510150170*	FOIA	O'TOOLE, J.	8510300030	50-247 S
MURTHA, M.	8510020236*	50-382 P	NIMITZ, R.L.	8510110047*	50-293 Q	O'TOOLE, J.D.	8510090299	50-247 P
MUSOLF, D.	8510010299	50-282 P	NINH, S.Q.	8510180058*	70-27	O'TOOLE, J.D.	8510180220	50-247 P
MUSOLF, D.	8510010650	50-282 R	NINH, S.Q.	8510180078*	70-143	O'TOOLE, J.D.	8510180249	50-247 Q
MUSOLF, D.	8510020103	50-263 R	NISHIMURA, J.	8510290151	50-312 G	O'TOOLE, J.D.	8510180039	50-247 P
MUSOLF, D.	8510030017	50-263 P	NIX, H.C.	8510010220	50-321 S	O'TOOLE, J.D.	8510220118	50-247 P
MUSOLF, D.	8510070449	50-282 P	NIX, H.C.	8510080085	50-366 S	O'TOOLE, J.D.	8510220226	50-247 P
MUSOLF, D.	8510080101	50-282 Q	NIX, H.C.	8510180377	50-366 S	O'TOOLE, J.D.	8510250066	50-247 P
MUSOLF, D.	8510090209	50-282 P	NIX, H.C.	8510180510	50-321 R	O'TOOLE, J.D.	8510250178	50-247 S
MUSOLF, D.	851100037	50-263 F	NIX, H.C.	8510180536	50-321 S	O'TOOLE, J.D.	8510250192	50-247 P
MUSOLF, D.	8510160252	50-263 P	NIX, H.C.	8510250061	50-321 S	O'TOOLE, J.D.	8510250239	50-247 P
MUSOLF, D.	8510180063	50-282 P	NIX, H.C.	8510250564	50-366 S	O'TOOLE, J.D.	8510290071	50-247 S
MUSOLF, D.	8510210276	50-282 S	NIXON, W.A.	8510240156	70-1489	O'TOOLE, J.D.	8510290196	50-247 P
MUSOLF, D.	8510220157	50-282 S	NOEL, T.H.	8510100089	PR	O'TOOLE, J.D.	8510290372	50-3 J
MUSOLF, D.	8510220361	50-263 Q	NOONAN, V.S.	8509300340	50-445 E	O'TOOLE, J.D.	8510290622	50-247 R
MUSOLF, D.	8510290371	50-203 P	NOONAN, V.S.	8510010059	50-445 A	O'BENCHAIN, C.F.	8510220252*	50-372 P
MUSOLF, D.	8510290375*	50-263 P	NOONAN, V.S.	8510010063	50-445 S	OESTMANN, M.J.	8510220004*	50-282 Q
MUSOLF, D.	8510310365	50-282 P	NOONAN, V.S.	8510030122	50-445 A	OESTMANN, M.J.	8510220008*	50-440 Q
MUSOLF, D.	8510250484*	50-354 A	NOONAN, V.S.	8510030234	50-445 A	OKRENT, D.	8510250179	50-3 O
MYERS, C.	8510160240	50-312 S	NOONAN, V.S.	8510070494	50-445 A	OLIVEIRA, W.	8510070225*	50-423 Q
MYERS, D.M.	8510090167*	50-397 P	NOONAN, V.S.	8510170479	50-445 A	OLLER, R.E.	8510010298*	QA999
MYERS, H.	8510250329*	50-390 H	NOONAN, V.S.	8510240588	50-445 A	OLLER, R.E.	8510080232*	QA999
MYERS, L.	8510040386	50-382 S	NOONAN, V.S.	8510310033	50-445 E	OLLER, R.E.	8510080417*	QA999
MYRABO, A.L.	8510020103	50-263 R	NORELIUS, C.E.	8510020157	50-440 Q	OLMSTEAD, W.J.	8407090031*	REVIEW GR P
NAGLE, J.C.	8510010606	50-352 S	NORELIUS, C.E.	8510070227*	50-446 S	OLSEN, A.F.	8510150030	70-824
NAGLE, J.C.	8510150241	50-352 S	NORELIUS, C.E.	8510070235	50-446 Q	OLSEN, A.F.	8510150037	71-230
NAGLE, J.C.	8510170407	50-352 S	NORELIUS, C.E.	8510070278*	50-40 Q	OLSEN, A.F.	8510180545	70-824
NAGLE, J.C.	8510280434	50-352 S	NORELIUS, C.E.	8510070356	50-40 A	OLSEN, A.F.	8510220028	70-824
NAGLE, J.C.	8510300244	50-352 S	NORELIUS, C.E.	8510080152	461 A	OLSEN, O.L.	8510240053	WASTE MGT
NAGLE, J.C.	8510310161	50-352 S	NORELIUS, C.E.	8510080517	50-10 Q	OLSEN, O.L.	8510280078	WASTE MGT
NAIDU, K.R.	8510070296*	QA999	NORELIUS, C.E.	8510080596	50-315 S	OLSON, J.F.	8510070351	PRM
NAIDU, K.R.	8510150015*	50-344 Q	NORELIUS, C.E.	8510090494	50-373 Q	OLSON, J.F.	8510100133*	PRM
NAIDU, K.R.	8510180408*	QA999	NORELIUS, C.E.	8510090499*	50-373 Q	OLSON, O.L.	8510090421	WASTE MGT
NALEZNY, C.	8510010619	50-382 E	NORELIUS, C.E.	8510100015	50-331 Q	OPASL, P.O.	8510080424*	50-354 A
NALEZNY, C.L.	8510020454	50-382 E	NORELIUS, C.E.	8510100150	50-331 Q	OPASL, P.O.	8510080428*	50-354 A
NALEZNY, C.L.	8510220252*	50-445 A	NORELIUS, C.E.	8510220275	50-255 P	OPEKA, J.F.	8510020055	50-245 P
NANSTAD, R.K.	8510040402	NUREG	NORELIUS, C.E.	8510250382	50-455 Q	OPEKA, J.F.	8510020055	50-245 P
NAPUDA, G.	8510080236*	50-271 Q	NORELIUS, C.E.	8510250410	50-315 Q	OPEKA, J.F.	8510030332	50-423 S
NAPUDA, G.	8510110019*	50-412 Q	NORELIUS, C.E.	8510280181	50-150 Q	OPEKA, J.F.	8510030332	50-423 S
NARBU, P.P.	8510240281*	50-206 Q	NORELIUS, C.E.	8510280187*	50-150 Q	OPEKA, J.F.	8510030426	50-423 S
NASLUND, C.D.	8510010647*	50-483 S	NORELIUS, C.E.	8510310198	50-373 S	OPEKA, J.F.	8510030426	50-423 S
NEFF, J.O.	8510080273	WASTE MGT	NORMAN, D.E.	8510280241*	50-445 Q	OPEKA, J.F.	8510040003	50-423 F
NEFF, J.O.	8510090323	WASTE MGT	NORRHOLM, L.	8510030225*	50-286 Q	OPEKA, J.F.	8510040003	50-423 F
NEFF, J.O.	8510240348	WASTE MGT	NORRHOLM, L.	8510070550*	50-247 Q	OPEKA, J.F.	8510040304	50-423 A

364 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY			
OPEKA,J.F.	8510040433	50-423	E	OPEKA,J.F.	8510160052	50-423	F	OPEKA,J.F.	8510300268	50-423	S
OPEKA,J.F.	8510040433	50-423	E	OPEKA,J.F.	8510160052	50-423	F	OPEKA,J.F.	8510300268	50-423	S
OPEKA,J.F.	8510040455	50-423	Q	OPEKA,J.F.	8510170068	50-423	A	OPEKA,J.F.	8510300271	50-423	S
OPEKA,J.F.	8510040455	50-423	Q	OPEKA,J.F.	8510170068	50-423	A	OPEKA,J.F.	8510300271	50-423	S
OPEKA,J.F.	8510070059	50-423	E	OPEKA,J.F.	8510170098	50-213	P	OPEKA,J.F.	8510310093	50-423	F
OPEKA,J.F.	8510070059	50-423	E	OPEKA,J.F.	8510170098	50-213	P	OPEKA,J.F.	8510310093	50-423	F
OPEKA,J.F.	8510070205	50-423	A	OPEKA,J.F.	8510170098	50-213	P	OPEKA,J.F.	8510310126	50-245	P
OPEKA,J.F.	8510070205	50-423	A	OPEKA,J.F.	8510170286	50-423	A	OPEKA,J.F.	8510310126	50-245	P
OPEKA,J.F.	8510070238	50-423	A	OPEKA,J.F.	8510170286	50-423	A	OPEKA,J.F.	8510310205	50-423	A
OPEKA,J.F.	8510070238	50-423	A	OPEKA,J.F.	8510180245	50-423	A	OPEKA,J.F.	8510310205	50-423	A
OPEKA,J.F.	8510070253	50-423	F	OPEKA,J.F.	8510180245	50-423	A	OPEKA,J.F.	8510310214	50-423	A
OPEKA,J.F.	8510070253	50-423	F	OPEKA,J.F.	8510180353	50-423	A	OPEKA,J.F.	8510310214	50-423	A
OPEKA,J.F.	8510070264	50-423	A	OPEKA,J.F.	8510180353	50-423	A	OPEKA,J.F.	8510310220	50-423	A
OPEKA,J.F.	8510070264	50-423	A	OPEKA,J.F.	8510220021	50-423	A	OPEKA,J.F.	8510310220	50-423	A
OPEKA,J.F.	8510070275	50-423	K	OPEKA,J.F.	8510220021	50-423	A	OPITZ,B.E.	8510040347	NUREG	
OPEKA,J.F.	8510070275	50-423	K	OPEKA,J.F.	8510220033	50-245	P	ORMSBY,D.P.	8510020220	50-327	S
OPEKA,J.F.	8510070300	50-423	E	OPEKA,J.F.	8510220033	50-245	P	ORR,W.L.	8510090150*	TOPREP	
OPEKA,J.F.	8510070303	50-245	P	OPEKA,J.F.	8510220065	50-423	A	ORSER,W.S.	8510010601	50-344	R
OPEKA,J.F.	8510070303	50-245	P	OPEKA,J.F.	8510220065	50-423	A	ORSER,W.S.	8510070013	50-344	S
OPEKA,J.F.	8510070319	50-423	E	OPEKA,J.F.	8510220145	50-423	A	ORSER,W.S.	8510280214	50-344	S
OPEKA,J.F.	8510070319	50-423	E	OPEKA,J.F.	8510220145	50-423	A	ORSER,W.S.	8510300300	50-344	S
OPEKA,J.F.	8510070441	50-245	P	OPEKA,J.F.	8510220150	50-423	A	OSBORNE,D.B.	8510080558	50-336	P
OPEKA,J.F.	8510070441	50-245	P	OPEKA,J.F.	8510220150	50-423	A	OSTER,J.	8510080148	50-295	J
OPEKA,J.F.	8510070444	50-423	A	OPEKA,J.F.	8510220158	50-213	P	OSTER,J.	8510110052	50-456	J
OPEKA,J.F.	8510070444	50-423	A	OPEKA,J.F.	8510220158	50-213	P	OSTER,J.	8510170308	50-373	J
OPEKA,J.F.	8510080040	50-423	E	OPEKA,J.F.	8510220158	50-213	P	OSTER,J.	8510250468	50-456	J
OPEKA,J.F.	8510080040	50-423	E	OPEKA,J.F.	8510220186	50-213	P	OSTMEYER,R.H.	8510010219	NUREG	
OPEKA,J.F.	8510080145	50-423	E	OPEKA,J.F.	8510220186	50-213	P	QUELLETTE,R.W.	8510010106	50-413	S
OPEKA,J.F.	8510080145	50-423	E	OPEKA,J.F.	8510220186	50-213	P	QUELLETTE,R.W.	8510020250	50-413	S
OPEKA,J.F.	8510080265	50-423	A	OPEKA,J.F.	8510220234	50-423	E	QUELLETTE,R.W.	8510090466	50-413	S
OPEKA,J.F.	8510080265	50-423	A	OPEKA,J.F.	8510220234	50-423	E	QUELLETTE,R.W.	8510250116	50-413	S
OPEKA,J.F.	8510080385	50-245	P	OPEKA,J.F.	8510220244	50-423	A	OVERBECK,G.J.	8510150228*	50-250	Q
OPEKA,J.F.	8510080385	50-245	P	OPEKA,J.F.	8510220244	50-423	A	OVERLID,T.	8510290467	50-458	S
OPEKA,J.F.	8510080468	50-423	E	OPEKA,J.F.	8510220247	50-245	P	OWCZARSKI,P.C.	8510040377	NUREG	
OPEKA,J.F.	8510080468	50-423	E	OPEKA,J.F.	8510220247	50-245	P	OWEN,W.H.	8508010128*	MISC	
OPEKA,J.F.	8510080470	50-245	P	OPEKA,J.F.	8510220295	50-245	P	OWEN,W.H.	8510040290	50-413	Q
OPEKA,J.F.	8510080470	50-245	P	OPEKA,J.F.	8510220295	50-245	P	OWEN,W.H.	8510070281	50-413	K
OPEKA,J.F.	8510090069	50-423	A	OPEKA,J.F.	8510220313	50-245	P	OZAWA,M.	8510170266	XPORTLIC	
OPEKA,J.F.	8510090069	50-423	A	OPEKA,J.F.	8510220313	50-245	P	OZAWA,M.	8510170269	XPORTLIC	
OPEKA,J.F.	8510090177	50-423	S	OPEKA,J.F.	8510230031	50-245	P	OZAWA,M.	8510170276	XPORTLIC	
OPEKA,J.F.	8510090177	50-423	S	OPEKA,J.F.	8510230031	50-245	P	OZAWA,M.	8510170279	XPORTLIC	
OPEKA,J.F.	8510100004	50-213	F	OPEKA,J.F.	8510230034	50-423	A	OZAWA,M.	8510170283	XPORTLIC	
OPEKA,J.F.	8510100135	50-245	P	OPEKA,J.F.	8510230034	50-423	A	PAAS,H.L.	8510010263*	40-8006	
OPEKA,J.F.	8510100135	50-245	P	OPEKA,J.F.	8510230131	50-213	F	PADOVAN,M.	8510170054*	50-361	Q
OPEKA,J.F.	8510100163	50-336	P	OPEKA,J.F.	8510240003	50-245	P	PAGE,M.	8510010004	CONTRACT	
OPEKA,J.F.	8510100163	50-336	P	OPEKA,J.F.	8510240003	50-245	P	PAGE,M.	8510010004	CONTRACT	
OPEKA,J.F.	8510100166	50-336	P	OPEKA,J.F.	8510240078	50-245	P	PAGE,M.	8510010071	CONTRACT	
OPEKA,J.F.	8510100166	50-336	P	OPEKA,J.F.	8510240078	50-245	P	PAGE,M.	8510010085	CONTRACT	
OPEKA,J.F.	8510100180	50-423	A	OPEKA,J.F.	8510240078	50-245	P	PAGE,M.	8510080122	CONTRACT	
OPEKA,J.F.	8510100180	50-423	A	OPEKA,J.F.	8510240089	50-245	P	PAGE,M.	8510080182	CONTRACT	
OPEKA,J.F.	8510100180	50-423	A	OPEKA,J.F.	8510240089	50-245	P	PAGE,M.	8510080347	CONTRACT	
OPEKA,J.F.	8510110009	50-423	A	OPEKA,J.F.	8510240256	50-423	A	PAGE,R.E.	8510040360	NUREG	
OPEKA,J.F.	8510110009	50-423	A	OPEKA,J.F.	8510240256	50-423	A	PAGE,R.E.	8510040360	NUREG	
OPEKA,J.F.	8510110022	50-423	A	OPEKA,J.F.	8510240287	50-245	F	PALLADINO,N.J.	8510010512*	50-322	U
OPEKA,J.F.	8510110022	50-423	A	OPEKA,J.F.	8510240287	50-245	F	PALLADINO,N.J.	8510010525*	50-322	U
OPEKA,J.F.	8510110037	50-245	P	OPEKA,J.F.	8510240287	50-245	F	PALLADINO,N.J.	8510010532*	50-322	U
OPEKA,J.F.	8510110037	50-245	P	OPEKA,J.F.	8510240335	50-245	P	PALLADINO,N.J.	8510010538*	COMMISSION	
OPEKA,J.F.	8510110037	50-245	P	OPEKA,J.F.	8510240335	50-245	P	PALLADINO,N.J.	8510010538*	COMMISSION	
OPEKA,J.F.	8510110078	50-423	A	OPEKA,J.F.	8510240373	50-245	P	PALLADINO,N.J.	8510010546*	COMMISSION	
OPEKA,J.F.	8510110078	50-423	A	OPEKA,J.F.	8510240373	50-245	P	PALLADINO,N.J.	8510010550*	COMMISSION	
OPEKA,J.F.	8510110092	50-423	A	OPEKA,J.F.	8510240373	50-245	P	PALLADINO,N.J.	8510010554*	COMMISSION	
OPEKA,J.F.	8510110092	50-423	A	OPEKA,J.F.	8510240382	50-245	P	PALLADINO,N.J.	8510010554*	COMMISSION	
OPEKA,J.F.	8510110092	50-423	A	OPEKA,J.F.	8510240382	50-245	P	PALLADINO,N.J.	8510010558*	COMMISSION	
OPEKA,J.F.	8510110115	50-423	E	OPEKA,J.F.	8510240410	50-245	P	PALLADINO,N.J.	8510010561*	COMMISSION	
OPEKA,J.F.	8510110115	50-423	E	OPEKA,J.F.	8510240410	50-245	P	PALLADINO,N.J.	8510070516	50-346	U
OPEKA,J.F.	8510110131	50-423	E	OPEKA,J.F.	8510240459	50-245	P	PALLADINO,N.J.	8510090124*	50-416	U
OPEKA,J.F.	8510110131	50-423	E	OPEKA,J.F.	8510240459	50-245	P	PALLADINO,N.J.	8510090380	50-341	U
OPEKA,J.F.	8510110131	50-423	E	OPEKA,J.F.	8510240459	50-245	P	PALLADINO,N.J.	8510090447	COMMISSION	
OPEKA,J.F.	8510110189	50-423	A	OPEKA,J.F.	8510250101	50-213	P	PALLADINO,N.J.	8510090476	COMMISSION	
OPEKA,J.F.	8510110189	50-423	A	OPEKA,J.F.	8510250101	50-213	P	PALLADINO,N.J.	8510090476	COMMISSION	
OPEKA,J.F.	8510110226	50-423	A	OPEKA,J.F.	8510280203	50-245	F	PALLADINO,N.J.	8510110119	COMMISSION	
OPEKA,J.F.	8510110226	50-423	A	OPEKA,J.F.	8510280203	50-245	F	PALLADINO,N.J.	8510150198	50-346	U
OPEKA,J.F.	8510110226	50-423	A	OPEKA,J.F.	8510280370	50-336	P	PALLADINO,N.J.	8510180455*	FOIA	
OPEKA,J.F.	8510150065	50-423	A	OPEKA,J.F.	8510280370	50-336	P	PALLADINO,N.J.	8510180466*	FOIA	
OPEKA,J.F.	8510150065	50-423	A	OPEKA,J.F.	8510290220	50-423	A	PALLADINO,N.J.	8510180484*	FOIA	
OPEKA,J.F.	8510150065	50-423	A	OPEKA,J.F.	8510290220	50-423	A	PALLADINO,N.J.	8510180484*	FOIA	
OPEKA,J.F.	8510150067	50-245	P	OPEKA,J.F.	8510290220	50-423	A	PALLADINO,N.J.	8510220432	50-219	U
OPEKA,J.F.	8510150067	50-245	P	OPEKA,J.F.	8510290234*	50-423	A	PALLADINO,N.J.	8510220432	50-219	U
OPEKA,J.F.	8510150233	50-423	S	OPEKA,J.F.	8510290234*	50-423	A	PALOMINO,F.G.	8510100042	50-322	G
OPEKA,J.F.	8510150233	50-423	S	OPEKA,J.F.	8510290235	50-423	F	PALOMINO,F.G.	8510110180	50-322	G
OPEKA,J.F.	8510150284	50-213	F	OPEKA,J.F.	8510290235	50-423	F	PALOMINO,F.G.	8510110180	50-322	G
OPEKA,J.F.	8510150284	50-213	F	OPEKA,J.F.	8510290300	50-336	P	PALOMINO,F.G.	8510110196	50-322	G
OPEKA,J.F.	8510150284	50-213	F	OPEKA,J.F.	8510290300	50-336	P	PALOMINO,F.G.	8510280519	50-322	G
OPEKA,J.F.	8510150284	50-213	F	OPEKA,J.F.	8510290300	50-336	P	PALOMINO,F.G.	8510280519	50-322	G
OPEKA,J.F.	8510150305	50-423	A	OPEKA,J.F.	8510290320	50-245	P	PANCIERA,V.	8510180066	50-269	S
OPEKA,J.F.	8510150305	50-423	A	OPEKA,J.F.	8510290320	50-245	P	PANCIERA,V.V.	8510080538*	50-416	Q
OPEKA,J.F.	8510150305	50-423	A	OPEKA,J.F.	8510290333	50-24*	P	PANGBURN,G.C.	8510180322*	40-6452	
OPEKA,J.F.	8510150327	50-423	A	OPEKA,J.F.	8510290333	50-24*	P	PAPANIC,G.	8510030033	50-29	F
OPEKA,J.F.	8510150327	50-423	A	OPEKA,J.F.	8510290333	50-24*	P	PAPANIC,G.	8510030073	50-29	F
OPEKA,J.F.	8510150327	50-423	A	OPEKA,J.F.	8510290388	50-245	P	PAPANIC,G.	8510030073	50-29	F
OPEKA,J.F.	8510150346	50-213	P	OPEKA,J.F.	8510290388	50-245	P	PAPANIC,G.	8510280061	50-29	V
OPEKA,J.F.	8510150351	50-423	A	OPEKA,J.F.	8510290388	50-245	P	PAPANIC,G.	8510280175	50-29	F
OPEKA,J.F.	8510150351	50-423	A	OPEKA,J.F.	8510300123	50-245	P	PAPERIELLO,C.J.	8510040178	50-305	P
OPEKA,J.F.	8510150351	50-423	A	OPEKA,J.F.	8510300123	50-245	P	PAPERIELLO,C.J.	8510040250	50-346	P
OPEKA,J.F.	8510150369	50-245	P	OPEKA,J.F.	8510300215	50-423	S	PAPERIELLO,C.J.	8510040251	50-266	P
OPEKA,J.F.	8510150369	50-245	P	OPEKA,J.F.	8510300215	50-423	S	PAPERIELLO,C.J.	8510080131	50-440	Q
OPEKA,J.F.	8510150369	50-245	P	OPEKA,J.F.	8510300263	50-423	S	PAPERIELLO,C.J.	8510080135*	50-440	Q
OPEKA,J.F.	8510150369	50-245	P	OPEKA,J.F.	8510300263	50-423	S	PAPERIELLO,C.J.	8510080609	50-440	Q
OPEKA,J.F.	8510150369	50-245	P	OPEKA,J.F.	8510300263	50-423	S	PAPERIELLO,C.J.	8510080609	50-440	Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAPERIELLO, C.J.	8510210173	50-315	PETERSON, M.R.	8510030113	XPORTLIC	PINCO, R.G.	8510100168	PR
PAPERIELLO, C.J.	8510210180*	50-315	PETERSON, M.R.	8510040060	XPORTLIC	PINCO, R.G.	8510100168	PR
PAPERIELLO, C.J.	8510220294	50-409	PETERSON, M.R.	8510080573	XPORTLIC	PINKERTON, B.	8510170315*	50-413 P
PAPERIELLO, C.J.	8510230144	50-331	PETERSON, M.R.	8510090343	XPORTLIC	PIPKIN, Y.M.	8510080354*	CONTRACT
PAPERIELLO, C.J.	8510230148*	50-331	PETERSON, M.R.	8510090456	XPORTLIC	PIRFO, O.R.	8510290209	50-498 G
PAPERIELLO, C.J.	8510230160	50-315	PETERSON, M.R.	8510090523	XPORTLIC	PIRTLE, G.L.	8510080432*	50-461 Q
PAPERIELLO, C.J.	8510230165*	50-315	PETERSON, M.R.	8510220131	XPORTLIC	PIRTLE, G.L.	8510160177*	50-254 Q
PAPERIELLO, C.J.	8510280393	50-461	PETERSON, M.R.	8510250597*	XPORTLIC	PIRTLE, G.L.	8510290017*	50-341 Q
PAPERIELLO, C.J.	8510280395*	50-461	PETERSON, M.R.	8510250603	XPORTLIC	PLAINE, H.H.	8510090108*	50-416 U
PAPERIELLO, C.J.	8510290078	50-331	PETERSON, M.R.	8510280005	XPORTLIC	PLAINE, H.H.	8510090118*	50-416 U
PAPERIELLO, C.J.	8510290082*	50-331	PETERSON, M.R.	8510310067	XPORTLIC	PLIML, G.J.	8510090450	50-304 S
PAPERIELLO, C.J.	8510290261	50-463	PETERSON, M.R.	8510310094	XPORTLIC	PLIML, G.J.	8510100101	50-295 R
PARIS, O.H.	8510030043	50-424	PETRONE, C.	8510170257*	50-322 Q	PLIML, G.J.	8510150444	50-304 S
PARIS, O.H.	8510100005	50-424	PETRONE, C.	8510210228*	50-322 Q	PLIML, G.J.	8510150499	50-295 S
PARIS, O.H.	8510190258	50-320	PETRONE, C.D.	8510180037*	50-245 Q	PLIML, G.J.	8510160259*	50-295 F
PARKER, G.	8510170124*	FOIA	PETROSINO, J.J.	8510070342*	QA999	PLIML, G.J.	8510180266	50-304 S
PARKER, G.	8510170200*	FOIA	PETROSINO, J.J.	8510310247*	50-254 Q	PLIML, G.J.	8510180522	50-295 S
PARKER, M.C.	8510040247	50-373	PETROWSKI, K.	8510180243*	50-304 S	PLIML, G.J.	8510170335*	50-295 S
PARKER, M.C.	8510110141	50-373	PETTENGILL, H.J.	8510070195	40-8681	PLIML, G.J.	8510310545	50-304 S
PARKER, M.C.	8510290055	50-373	PETTENGILL, H.J.	8510170436	40-6659	PLISCO, L.R.	8510020080*	50-387 Q
PARKER, M.C.	8510290081	50-295	PETTENGILL, H.J.	8510180200*	40-1162	PLISCO, L.R.	8510230202*	50-387 Q
PARKER, M.C.	8510290188	50-373	PETTENGILL, H.J.	8510180238*	40-8681	PLISGER, S.A.	8510030433	NUREG
PARKER, M.C.	8510290231	50-373	PETTENGILL, H.J.	8510180243*	40-8681	PLOSKE, T.	8510170335*	50-456 Q
PARKER, M.C.	8510290346	50-454	PETTENGILL, H.J.	8510180249*	40-8681	PLOSKE, T.	8510210047*	50-454 Q
PARKINSON, G.L.	8510020294*	50-461	PETTENGILL, H.J.	8510180252	40-8584	PLOSKE, T.	8510310330*	50-346 Q
PARKS, G.B.	8510010187*	FOIA	PETTENGILL, H.J.	8510180438	40-2259	PLUNKETT, T.F.	8510310428	50-458 S
PARLO, S.A.	8510020307	NUREG	PETTENGILL, H.J.	8510180444	40-8698	POINDEXTER, C.H.	8510070193*	50-213 P
PARR, O.D.	8503220113*	50-346	PETTENGILL, H.J.	8510180448	40-4492	POINDEXTER, T.	8510080256	50-312 Q
PARRIS, H.G.	8510030045	50-327	PETTENGILL, H.J.	8510180451	40-2259	POKUSA, R.E.	8510100168	PR
PARRIS, H.G.	8510080442	50-759	PETTENGILL, H.J.	8510180469*	40-299	POKUSA, R.E.	8510130168	PR
PARSONS, C.H.	8510080175	50-270	PETTENGILL, H.J.	8510180476*	40-4492	POLICH, T.J.	8510090350*	50-323 Q
PARSONS, R.M.	8510290035*	50-400	PETTENGILL, H.J.	8510180480*	40-8584	POLK, P.J.	8510180150	50-440 Q
PARSONS, R.M.	8510290041*	50-400	PETTENGILL, H.J.	8510180482*	40-8584	PONCE, L.	8510090470	FOIA
PARTLOW, J.G.	8510150139	50-267	PETTENGILL, H.J.	8510180489*	40-8084	POPPE, L.K.	8510090250	WASTE MGT
PASCHOA, A.S.	8510250529	NUREG	PETTENGILL, H.J.	8510210048	40-3453	PORTER, R.J.	8510220089	50-317 R
PASCIAK, W.	8510040466*	50-333	PETTENGILL, H.J.	8510210053	40-6622	POTAPOV, S.U.	8510010397*	FOIA
PASCIAK, W.	8510110047*	50-293	PETTENGILL, H.J.	8510210070	40-8084	POTAPOV, S.U.	8510010402*	50-390 S
PASCIAK, W.	8510210096*	50-354	PETTENGILL, H.J.	8510210082	40-1162	POTAPOV, S.U.	8510210027*	QA999
PASCIAK, W.	8510250458*	50-271	PETTENGILL, H.J.	8510210106	40-6659	POTEAT, G.N.	8510150384	50-483 F
PASCIAK, W.J.	8510160016*	50-333	PETTENGILL, H.J.	8510210118	40-8681	POULTON, B.R.	8510220482	50-297 P
PASCIAK, W.J.	8510170147*	50-320	PETTENGILL, H.J.	8510210125*	40-8681	POWERS, C.M.	8510020096	50-397 R
PASCIAK, W.J.	8510220106*	50-244	PETTENGILL, H.J.	8510210132	40-8698	POWERS, C.M.	8510180475	50-397 S
PASCIAK, W.J.	8510280308*	50-387	PETTENGILL, H.J.	8510210135*	40-8698	POWERS, E.M.	8510280196	50-397 S
PASTVA, M.J.	8510020066	50-325	PETTENGILL, H.J.	8510210169	40-3453	POWERS, T.B.	8510030435	NUREG
PASTVA, M.J.	8510080529	50-325	PETTENGILL, H.J.	8510210176	40-8084	PRAIRIE, R.R.	8510040381	NUREG
PASTVA, M.J.	8510080537	50-325	PETTENGILL, H.J.	8510210300	40-299	PRATT, D.S.	8510290374	50-243 R
PASTVA, M.J.	8510090018	50-325	PETTENGILL, H.J.	8510210305	40-299	PRATT, W.	8510020257	50-423 A
PASTVA, M.J.	8510090027	50-324	PETTENGILL, H.J.	8510220081	40-6622	PRELL, J.	8510070225*	50-423 Q
PASTVA, M.J.	8510090342	50-324	PETTENGILL, H.J.	8510220084	40-8084	PRELL, J.	8510080236*	50-271 Q
PASTVA, M.J.	8510250198	50-325	PETTENGILL, H.J.	8510220102	40-2259	PRELL, J.	8510250475*	50-423 Q
PASTVA, M.J.	8510280077	50-325	PETTENGILL, H.J.	8510220116	40-1162	PRENDERGAST, W.	8510100076	PR
PASTVA, M.J.	8511280261	50-325	PETTENGILL, H.J.	8510040394	PR	PRESTHOLT, P.T.	8510090180	WASTE MGT
PASTVA, M.J.	8510280440	50-325	PETTENGILL, H.J.	8510310247*	50-254 Q	PRESTHOLT, P.T.	8510090451	WASTE MGT
PASTVA, M.J.	8510310065	50-324	PETTENGILL, H.J.	8510310370*	CONTRACT	PRESTHOLT, P.T.	8510250294	WASTE MGT
PATE, R.	8510160213	50-528	PETTENGILL, H.J.	8510170331	40-6659	PREVATTE, R.	8510280510	50-400 T
PATEL, S.G.	8510070310*	50-424	PFAFF, S.J.	8510180432	40-6659	PREVATTE, R.L.	8510090333*	50-400 Q
PATTERSON, J.	8510160018*	50-255	PFAFF, S.J.	8510180437*	40-6659	PRINS, H.R.	8510180253	PR
PATTERSON, J.	8510210047*	50-454	PFAFF, S.J.	8510090082	TOPREP	PRIORITY, R.B.	8510160300	50-413 P
PATTERSON, J.P.	8510010141*	50-255	PFAFF, S.J.	8510150337	TOPREP	PRIVIDY, L.J.	8510070166*	50-412 Q
PATTERSON, J.P.	8510160234*	50-440	PFAFF, S.J.	8510080421*	50-277 Q	PROBST, J.	8510090283	50-331 S
PATTON, G.A.	8510100123	PR	PHILLIPS, J.	8510090160*	PR	PROBST, J.R.	8510290405	50-331 S
PATTON, J.D.	8510170409	40-8102	PHILLIPS, J.	8510170284	NUREG	PROXIMIRE, W.	8510090486*	COMMISSION
PAUL, R.A.	8510010180*	50-266	PHILLIPS, H.S.	8510010521	50-382	PULLANI, S.	8510160037*	50-245 Q
PAULINO, R.	8510080032*	50-244	PHILLIPS, H.S.	8510280421	50-445	PURCELL, R.H.	8510110127*	70-1257
PAULTZ, F.P.	8510110091*	50-423	PHILLIPS, L.E.	8510290420	TOPREP	PURCELL, W.J.	8510240514	WASTE MGT
PEDRO, J.	8510180176	FOIA	PHILLIPS, M.	8510100018*	50-266	PURCELL, W.J.	8510240557	WASTE MGT
PELIZZA, M.S.	8510170471	40-8786	PHILLIPS, M.	8510280359*	50-341 Q	PURCELL, W.J.	8510280172	WASTE MGT
PELLET, J.L.	8510080419*	50-313	PHILLIPS, M.P.	8510310330*	50-346 Q	QUENELLE, K.H.	8510100182	PR
PEPIN, J.	8510090420	WASTE MGT	PHILLIPS, M.P.	8510010141*	50-255 Q	QUERIO, R.E.	8510030335	50-454 S
PEPIN, J.	8510280050	WASTE MGT	PHILLIPS, M.P.	8510180018*	50-255 Q	QUERIO, R.E.	8510030375	50-454 S
PEPIN, J.	8510280444	WASTE MGT	PHILLIPS, M.P.	8510180018*	50-440 Q	QUERIO, R.E.	8510040432	50-454 S
PERANICH, M.W.	8510280488	WASTE MGT	PHILLIPS, M.P.	8510180027*	50-295 Q	QUERIO, R.E.	8510040480	50-454 S
PERANICH, M.W.	8510030153	50-382	PHILLIPS, M.P.	8510170335*	50-156 Q	QUERIO, R.E.	8510090364	50-454 S
PERANICH, M.W.	8510030153	50-382	PHILLIPS, M.P.	8510210047*	50-154 Q	QUERIO, R.E.	8510150045	71-8089
PERANICH, M.W.	8510030163	50-382	PHILLIPS, M.P.	8510010079*	50-81 P	QUERIO, R.E.	8510170366	50-454 S
PEREIRA, D.	8510160238	50-344	PIERCE, J.F.	8510090057	FOIA	QUERIO, R.E.	8510310407	50-454 S
PEREIRA, D.B.	8510280159*	50-344	PILANT, J.M.	8510020034	50-298	QUIGG, C.T.	8510010104	70-1308
PERKINS, C.	8510150377	50-320	PILANT, J.M.	8510040001	50-298	QUINN, W.F.	8510020083	50-528 S
PERLIS, R.G.	8510180277	50-498	PILANT, J.M.	8510070244	50-298	QUINN, W.F.	8510020504	50-528 S
PERLIS, R.G.	8510240204	50-443	PILANT, J.M.	8510080166	50-298	QUINN, W.F.	8510070025	50-528 S
PERLIS, R.G.	8510290027	50-443	PILANT, J.M.	8510090300*	50-298	QUINN, W.F.	8510220380	50-528 S
PERNY, C.D.	851024032*	50-269	PILANT, J.M.	8510180040	50-298	QUINN, W.F.	8510310188	50-528 S
PERROTTI, D.J.	8510200438*	50-382	PILANT, J.M.	8510180043	50-298	RAABE, P.H.	8510090212*	50-327 P
PERRY, D.	8510210145*	TOPREP	PILANT, J.M.	8510240247	50-298	RAABE, P.H.	8510090220*	50-327 P
PERRY, D.	8510100046*	50-333	PILANT, J.M.	8510240331	50-298	RADER, R.M.	8510030011	50-352 G
PETERS, B.	8510150393	50-346	PILANT, J.M.	8510240414	50-298	RADER, R.M.	8510030011	50-352 G
PETERS, J.P.	8510070186	50-373	PILANT, J.M.	8510240426*	50-298	RADER, R.M.	8510180240	50-352 T
PETERS, J.P.	8510070181*	50-346	PILANT, J.M.	8510290202*	50-298	RADER, R.M.	8510180240	50-352 T

366 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RAHE,E.P.	8510090141	TOPREF	REYNOLDS,N.S.	8510290003	50-445 G	ROCHINO,A.P.	8510010214*	50-219 P
RAHE,E.P.	8510290369	TOPREF	REYNOLDS,N.S.	8510290003	50-445 G	ROCKEFELLER,J.	8510180282	PR
RAJARAM,V.	8510090347	WASTE RES	REYNOLDS,S.D.	8510080401*	50-443 Q	RODABAUGH,E.C.	8510030312	NUREG
RAJARAM,V.	8510090390	WASTE RES	REYNOLDS,S.D.	8510170153*	50-219 Q	RODI,J.P.	8510180261*	FOIA
RAJARAM,V.	8510090400	WASTE RES	REYTBATT,Z.V.	8510170398	NUREG	RODI,J.P.	8510180268*	FOIA
RAJARAM,V.	8510090516	WASTE RLS	REYTBATT,Z.V.	8510170403*	NUREG	RODRIGUEZ,R.J.	8510020030	50-312 S
RAMBERG,B.	8510040422	NUREG	REYTBATT,Z.V.	8510180099*	REVIEW GR P	RODRIGUEZ,R.J.	8510040002	50-312 P
RAMSETT,L.	8510220370*	50-346 S	RHOADS,G.G.	8510010013	50-322 S	RODRIGUEZ,R.J.	8510040240	50-312 F
RANDALL,R.	8510170110	50-220 S	RHOADS,G.G.	8510030378	50-322 S	RODRIGUEZ,R.J.	8510070276	50-312 P
RANDALL,R.G.	8510220011	50-220 S	RHOADS,G.G.	8510030412	50-322 S	RODRIGUEZ,R.J.	8510080039	50-312 P
RANDAZZA,J.B.	8510070268	50-309 P	RHOADS,G.G.	8510090101	50-322 S	RODRIGUEZ,R.J.	8510080047	50-312 P
RANDAZZA,J.B.	8510110031	50-309 P	RHOADS,G.G.	8510090287	50-322 S	RODRIGUEZ,R.J.	8510080125	50-312 J
RANDAZZA,J.B.	8510220160	50-309 P	RHOADS,G.G.	8510170363	50-322 S	RODRIGUEZ,R.J.	8510080203	50-312 F
RANGE,D.M.	8510180487	40-8102	RHOADS,G.G.	8510170368	50-322 S	RODRIGUEZ,R.J.	8510090208	50-312 F
RAO,G.V.	8510230061*	50-455 Q	RHOADS,G.G.	8510180154	50-322 S	RODRIGUEZ,R.J.	8510080221	50-312 S
RAPKIN,A.	8510110158	40-2061	RHOADS,G.G.	8510180179	50-322 S	RODRIGUEZ,R.J.	8510080501	50-312 S
RAPKIN,A.	8510110165*	40-2061	RHOADS,G.G.	8510040373	PR	RODRIGUEZ,R.J.	8510090266	50-312 R
RASH,L.	8510100003	TOPREF	RHOADS,G.G.	8311290156*	50-346 S	RODRIGUEZ,R.J.	8510170348	50-312 S
RAST,J.	8510240589	WASTE MGT	RICE,C.M.	8510220178*	50-445 A	RODRIGUEZ,R.J.	8510210019	50-312 P
RATHLER,G.	8510220159*	50-482 F	RICE,C.M.	8510220211*	50-424 A	RODRIGUEZ,R.J.	8510210059	50-312 P
RATNER,M.G.	8510040421	TOPREF	RICHARDS,S.	8510010190	50-344 S	RODRIGUEZ,R.J.	8510220172	50-312 S
RATNER,M.G.	8510040422	TOPREF	RICHARDS,S.	8510180238	50-344 S	RODRIGUEZ,R.J.	8510220266	50-312 S
RAY,C.L.	8510290118*	50-460 S	RICHARDS,S.	8510170054*	50-361 Q	RODRIGUEZ,R.J.	8510230116	50-312 P
REAVEAU,Z.K.	8510170433	40-8674	RICHARDS,S.A.	8510090245*	50-344 Q	RODRIGUEZ,R.J.	8510240127	50-312 F
REAVIS,J.A.	8510210267	50-413 R	RICHARDSON,H.H.	8510310435	50-59 H	RODRIGUEZ,R.J.	8510240378	50-312 S
REAVIS,J.A.	8510210285	50-369 R	RICHARDSON,J.	8510300230*	50-369 P	RODRIGUEZ,R.J.	8510280007	50-312 R
REAVIS,J.A.	8510220094	50-269 R	RICHARDSON,M.P.	8510010651	50-528 R	RODRIGUEZ,R.J.	8510280121	50-312 P
RECZEK,E.N.	8510230188*	50-387 Q	RICHARDSON,W.O.	8510160101	PR	RODRIGUEZ,R.J.	8510290138	50-312 R
REDMOND,R.F.	8510290253	50-150 Q	RICHLEY,E.A.	8510230017	50-30 H	RODRIGUEZ,R.J.	8510290289	50-312 Q
REED,G.J.	8510150391	50-346 F	RICHMOND,W.D.	8510300314*	50-322 S	RODRIGUEZ,R.J.	8510290356	50-312 R
REED,G.J.	8510280317	50-346 F	RICHMOND,W.D.	8510310574*	50-445 S	RODRIGUEZ,R.J.	8510080255	50-312 P
REED,G.J.	8510110266	50-254 S	RIDENHOUR,R.	8510010021	50-382 E	ROE,L.E.	8510070123*	50-346 S
REGAN,N.A.	8510150027	71-48	RIDER,R.L.	8510040152*	50-320 P	ROE,L.E.	8510070133*	50-346 S
REHM,T.A.	8510020132	50-382 E	RIDER,R.L.	8510040155*	50-320 P	ROGERS,D.W.	8510150380	50-255 F
REHM,T.A.	8510040063	COMMISSION	RIDGWAY,D.A.	8510020265	50-320 G	ROGERS,L.R.	8510150364*	40-1368
REHM,T.A.	8510310513*	COMMISSION	RIDGWAY,D.A.	8510020265	50-320 G	ROGERS,P.C.	8510010645	50-368 S
REHM,T.A.	8510180528	COMMISSION	RIDGWAY,D.A.	8510180340	50-400 G	ROGERS,P.C.	8510020081	50-313 S
REHM,T.A.	8510280463	COMMISSION	RIDGWAY,D.A.	8510180340	50-400 G	ROGERS,P.C.	8510170034	50-313 S
REID,R.L.	8510170038*	FOIA	RIDGWAY,D.A.	8510220378	50-424 G	ROGERS,P.C.	8510220056	50-368 S
REIS,H.F.	8510310281	50-250 G	RIDGWAY,D.A.	8510220378	50-424 G	ROGERS,T.	8510180133*	50-413 Q
REIS,H.F.	8510310281	50-250 G	RIDGWAY,D.A.	8510240235	50-400 G	ROGERS,W.G.	8407130317*	50-346 Q
REIS,H.F.	8510310365	50-250 G	RIDGWAY,D.A.	8510240235	50-400 G	ROGGE,J.F.	8510040498*	50-424 Q
REIS,H.F.	8510310365	50-250 G	RIDGWAY,D.A.	8510240235	50-400 G	ROHDE,J.E.	8510150499	50-295 S
REIS,H.F.	8510310365	50-250 G	RIDGWAY,D.A.	8510240323*	50-320 G	ROHRE,R.J.	8510010638	50-373 R
REIS,H.F.	8510310434	50-250 G	RIDGWAY,D.A.	8510240329*	50-320 G	ROISMAN,A.Z.	8510220293	50-445 G
REIS,H.F.	8510310434	50-250 G	RIDGWAY,K.R.	8510280195*	50-150 Q	ROISMAN,A.Z.	8510220293	50-445 G
RENY,D.A.	8510090212*	50-327 P	RIEDLINGER,B.A.	P510070055	I&E	ROISMAN,A.Z.	8510290022*	50-445 G
RENY,D.A.	8510090220*	50-327 P	RIES,R.A.	8510090045	TOPREF	ROISMAN,A.Z.	8510310276	50-445 G
REQUA,G.	8510040045	50-261 P	RILEY,A.	8510040564*	CONTRACT	ROISMAN,A.Z.	8510310276	50-445 G
RESCHESKE,P.R.	8510160011*	50-331 Q	RILING,R.W.	8510220199*	50-390 F	ROMAN,T.W.	8510180236	50-220 R
RESNER,M.E.	8510010084*	50-416 V	RING,M.A.	8510080140*	50-440 Q	ROMANO,F.R.	8510100106	50-352 G
RESNER,M.E.	8510010084*	50-416 V	RING,M.A.	8510080398*	50-266 Q	ROMANO,F.R.	8510100202*	50-352 G
RESNER,M.E.	8510010107*	50-416 V	RING,M.A.	8510160011*	50-331 Q	ROMBERG,W.D.	8510020074	50-245 R
RESNER,M.E.	8510010109*	50-416 V	RING,M.A.	8510220077*	50-454 Q	ROMBERG,W.D.	8510020074	50-245 R
RESNER,M.E.	8510010116*	50-416 V	RJORDAN,B.	8510030131	NUREG	ROMBERG,W.D.	8510020076	50-336 R
RESNER,M.E.	8510010119*	50-416 V	RITTENBERG,R.B.	8510250204	27-48	ROMBERG,W.D.	8510020076	50-336 R
RESNER,M.E.	8510010125*	50-416 V	RIVENBARK,G.W.	8510300217	50-221 P	ROMBERG,W.D.	8510170051	50-336 S
RESNER,M.E.	8510010130*	50-416 V	RIVERS,M.E.	8510240043	50-327 R	ROMBERG,W.D.	8510170051	50-336 S
RESNER,M.E.	8510010138*	50-416 V	RIVERS,M.E.	8510250293	50-259 R	ROMBERG,W.D.	8510170245	50-245 S
RESNER,M.E.	8510010152*	50-416 V	RIVERS,M.E.	8510250440*	50-259 R	ROMBERG,W.D.	8510170245	50-245 S
RESNER,M.E.	8510010168*	50-416 V	ROBERSON,P.W.	8510300221*	50-369 P	ROMBERG,W.D.	8510240415	50-245 S
RESNER,M.E.	8510010176*	50-416 V	ROBERSON,P.W.	8510300226*	50-369 P	ROMBERG,W.D.	8510240415	50-245 S
REST,J.	8510040332	NUREG	ROBERT,M.M.	8510030375	50-454 S	ROMBERG,W.D.	8510310100	50-245 S
REUSS,J.L.	8510240576	WASTE RES	ROBERTS	8510160183*	50-206 P	ROMBERG,W.D.	8510310100	50-245 S
REYES,L.A.	8407130317*	50-346 Q	ROBERTS,A.R.	8510010326*	50-382 P	ROMBERG,W.D.	8510310402	50-336 S
REYES,L.A.	8510010406	50-483 V	ROBERTS,G.L.	8510160333*	CONTRACT	ROMBERG,W.D.	8510310402	50-336 S
REYES,L.A.	8510070295	50-305 V	ROBERTS,G.W.	8510150039	71-230	ROMBERG,W.D.	8510310502	50-245 S
REYES,L.A.	8510100099	50-456 Q	ROBERTS,J.P.	8510010501	PROJ	ROMBERG,W.D.	8510310502	50-245 S
REYES,L.A.	8510100181	50-331 Q	ROBERTS,J.P.	8510010625	PROJ	RON,G.W.	8510100008*	50-445 Q
REYES,L.A.	8510100186*	50-331 Q	ROBERTS,J.P.	8510250083	PROJ	RONAFALVY,J.	8510240396	50-272 R
REYES,L.A.	8510100190*	50-331 Q	ROBERTS,T.F.	8510010369*	50-382 P	RONAFALVY,J.P.	8510080209*	50-311 R
REYES,L.A.	8510160272	50-295 Q	ROBERTS,T.M.	8510010569*	COMMISSION	RONAFALVY,J.P.	8510080280*	50-311 R
REYES,L.A.	8510210014	50-373 V	ROBERTS,T.M.	8510010570*	COMMISSION	RONAFALVY,J.P.	8510090190*	50-272 R
REYES,L.A.	8510210041	50-10 V	ROBERTS,T.M.	8510010572*	COMMISSION	RONAFALVY,J.P.	8510090192*	50-272 R
REYES,L.A.	8510210042	50-331 V	ROBERTS,T.M.	8510010578*	COMMISSION	RONAFALVY,J.P.	8510240387	50-311 R
REYES,L.A.	8510210218	50-237 Q	ROBERTS,T.M.	8510010585*	COMMISSION	ROOT,R.W.	8510220457	50-460 S
REYES,L.A.	8510210220*	50-237 Q	ROBERTS,T.M.	8510010588*	COMMISSION	ROEM,B.L.	8510180208	50-456 G
REYES,L.A.	8510220279	50-331 V	ROBERTS,T.M.	8510010590*	50-320 U	ROSS,D.	8510010524	50-382 E
REYES,L.A.	8510240647	50-87 V	ROBERTS,T.M.	8510070080	50-346 S	ROSS,D.	8510020436	50-382 E
REYES,L.A.	8510310262	50-295 Q	ROBERTSON,W.J.	8510010165*	40-8006	ROSS,D.	8510040070	50-382 E
REYNOLDS,N.S.	8510110212	50-460 G	ROBINSON,A.	8510020245*	50-321 S	ROSS,D.	8510040107	50-382 E
REYNOLDS,N.S.	8510110212	50-460 G	ROBINSON,P.	8510080210	50-315 Q	ROSS,D.	8510040130	50-382 E
REYNOLDS,N.S.	8510110228	50-445 G	ROBINSON,P.	8510100187	I&E	ROSS,D.	8510040217	50-382 E
REYNOLDS,N.S.	8510110228	50-445 G	ROBINSON,P.	8510180372	I&E	ROSS,D.	8510040410	50-382 E
REYNOLDS,N.S.	8510150355	50-445 G	ROBINSON,P.	8510220104	70-143	ROSS,D.	8510040417	50-382 E
REYNOLDS,N.S.	8510150355	50-445 G	ROBINSON,P.	8510240001	40-6622	ROSS,F.W.	8510240645	WASTE RES
REYNOLDS,N.S.	8510280514	50-445 G	ROBINSON,P.	8510240406	50-293 Q	ROSS,S.W.J.	8510180103*	50-335 Q
REYNOLDS,N.S.	8510280514	50-445 G	ROBINSON,P.	8510250582	50-139 P	ROSS,W.J.	8510220112*	50-261 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROTH,J.	8510070224*	70-1100	SCARANO,R.A.	8510080472	50-27	SEARS,P.M.	8510080097	50-309 P
ROTH,J.	8510080162*	70-820	SCARANO,R.A.	8510090525	50-397 Q	SELF,C.A.	8510280204*	CONTRACT
ROTHFLEISCH,J.	8510010247*	40-8027	SCARANO,R.A.	8510150379	50-70 Q	SELLS,D.E.	8510280313	50-389 P
ROTHFLEISCH,J.	8510010285*	40-8027	SCARANO,R.A.	8510170298	50-326 Q	SELMAN,M.	8510040123	50-247 Q
ROTHFLEISCH,J.	8510010303*	40-8027	SCARANO,R.A.	8510170301*	50-326 Q	SELMAN,M.	8510160225	50-3 F
ROTHFLEISCH,J.	8510010335*	40-8027	SCARANO,R.A.	8510170354	50-70 Q	SELMAN,M.	8510240585	50-3 F
ROTHFLEISCH,J.	8510010372*	40-8027	SCARANO,R.A.	8510170355*	50-70 Q	SELTSMANN,R.V.	8510110139*	50-456 G
ROTHFLEISCH,J.	8510010391*	40-8027	SCARANO,R.A.	8510220193	50-528 Q	SEPP,H.A.	8510110014*	50-423 A
ROUSE,L.C.	8510070559	PROJ	SCHEIBELHUT,C.	8510180019*	50-440 Q	SERBU,R.J.	8510040256*	ORG
ROUSE,L.C.	8510110081	PROJ	SCHEPENS,R.J.	8510040498*	50-424 Q	SERKIZ,A.W.	8510110241*	50-445 G
ROUSE,L.C.	8510180033	50-280 Y	SCHERER,A.E.	8510010257	TOPREP	SERNE,R.J.	8510040347	NUREG
ROUSE,L.C.	8510180536	50-280 Y	SCHERER,A.E.	8510220213	TOPREP	SERRANO,W.	8506050540*	50-266 P
ROUSE,L.C.	8510220028	50-280 Y	SCHERER,A.E.	8510220351	NUREG	SEWELL,W.D.	8510070078*	CONTRACT
ROUSE,L.C.	8510250064	50-261 Y	SCHIERLING,H.	8510180506	50-275 P	SEWELL,W.D.	8510070089*	CONTRACT
ROWE,B.S.	8510110059	71-9073	SCHIERLING,H.	8510240497	50-275 F	SHACKLETON,O.C.	8510170070*	50-206 P
ROWSOME,F.H.	8510070099*	50-346 S	SCHIERLING,H.	8510240506	50-275 Q	SHAFFER,W.D.	8510010128	50-255 Q
ROZAK,S.	8510160038*	50-155 Q	SCHIERMAN,S.L.	8510170408	40-8681	SHAFFER,W.D.	8510010154	50-266 Q
RUBENSTEIN,L.S.	8309060463*	50-346 S	SCHLEMMER,D.L.	8510170096	FOIA	SHAFFER,W.D.	8510070131*	50-346 Q
RUBENSTEIN,L.S.	8312010439	50-346 S	SCHMIDT,C.T.	8510020240	NUREG	SHAFFER,W.D.	8510070167*	50-346 S
RUBENSTEIN,L.S.	8405010072*	50-289 P	SCHMIDT,H.W.	8510040571*	CONTRACT	SHAFFER,W.D.	8510070223	50-266 F
RUBENSTEIN,L.S.	8407250135*	50-346 S	SCHNEIDER,K.N.	8510090241	WASTE MGT	SHAFFER,W.D.	8510070386	50-454 Q
RUBENSTEIN,L.S.	8411290581*	50-346 S	SCHNEIDER,P.B.	8510070292	PR	SHAFFER,W.D.	8510070420*	50-454 Q
RUBENSTEIN,L.S.	8506260505*	50-346 S	SCHNELL,D.F.	8510040075	50-483 Q	SHAFFER,W.D.	8510070468	50-409 Q
RUBIN,K.	8510180142*	50-244 P	SCHNELL,D.F.	8510100089	50-483 P	SHAFFER,W.D.	8510070470*	50-409 Q
RUFF,A.B.	8510180388*	50-414 Q	SCHNELL,D.F.	8510180051	50-483 P	SHAFFER,W.D.	8510080050	50-331 F
RUITER,G.H.	8510210292	50-305 R	SCHNELL,D.F.	8510230020	50-483 P	SHAFFER,W.D.	8510080068	50-483 F
RUNKLE,G.E.	8510010219	NUREG	SCHNELL,D.F.	8510230067	50-483 P	SHAFFER,W.D.	8510080114	50-440 F
RUNKLE,J.	8510030009	50-400 G	SCHNELL,D.F.	8510300001	50-483 P	SHAFFER,W.D.	8510080263	50-155 F
RUNKLE,J.	8510030009	50-400 G	SCHRECK,R.I.	8510040377	NUREG	SHAFFER,W.D.	8510080345	50-263 F
RUNKLE,J.	8510030082	50-400 G	SCHREIBER,H.	8510040264	50-322 S	SHAFFER,W.D.	8510080389	50-263 F
RUNKLE,J.	8510030082	50-400 G	SCHULTZ,S.P.	8510310215*	50-29 P	SHAFFER,W.D.	8510080479	50-454 F
RUNKLE,J.	8510160159	50-400 G	SCHULTZ,W.H.	8510070115*	50-346 Q	SHAFFER,W.D.	8510090156	50-295 Q
RUNKLE,J.	8510160159	50-400 G	SCHUM,W.S.	8510030042	50-382 E	SHAFFER,W.D.	8510090161*	50-295 Q
RUNYAN,M.F.	8510070513*	50-269 Q	SCHUMACHER,M.C.	8510070427*	50-454 Q	SHAFFER,W.D.	8510100006	50-266 Q
RUPP,J.	8510220119	50-272 S	SCHUMACHER,M.C.	8510090171*	50-295 Q	SHAFFER,W.D.	8510110146	50-254 F
RUPP,J.L.	8510010606	50-311 S	SCHUMACHER,M.C.	8510160038*	50-155 Q	SHAFFER,W.D.	8510160015	50-255 Q
RUPP,J.L.	8510080074	50-311 S	SCHUMACHER,M.C.	8510220004*	50-282 Q	SHAFFER,W.D.	8510160031	50-155 Q
RUPP,J.L.	8510240050	50-272 S	SCHUMACHER,M.C.	8510220006*	50-440 Q	SHAFFER,W.D.	8510160114	50-282 Q
RUPP,J.L.	8510240185	50-311 S	SCHUSTER,M.D.	8510300151*	50-528 Q	SHAFFER,W.D.	8510160179	50-282 Q
RUPP,J.L.	8510290527	50-272 S	SCHUSTER,M.D.	8510310285	50-206 F	SHAFFER,W.D.	8510160232	50-440 Q
RUSCHE,B.C.	8510090204	WASTE MGT	SCHWEIBINZ,E.R.	8510280195*	50-150 Q	SHAFFER,W.D.	8510160248	50-295 Q
RUSCHE,B.C.	8510090422	WASTE MGT	SCHWENCER,A.	8510070400*	50-213 P	SHAFFER,W.D.	8510160256	50-295 F
RUSHBROOK,M.M.	8510150307	50-445 E	SCIACCA,F.	8510030131	NUREG	SHAFFER,W.D.	8510170330	50-456 Q
RUSSELL,C.F.	8510010009	WASTE MGT	SCOTT,A.E.	8510180242*	50-261 R	SHAFFER,W.D.	8510210008	50-454 Q
RUSSELL,J.B.	8510080544	50-317 F	SCOTT,A.E.	8510180246*	50-261 R	SHAFFER,W.D.	8510210018*	50-454 Q
RUSSELL,J.B.	8510160146	50-317 F	SCOTT,D.J.	8510010208	50-249 S	SHAFFER,W.D.	8510220002	50-282 Q
RUSSELL,J.B.	8510220089	50-317 R	SCOTT,D.J.	8510040142	50-237 S	SHAFFER,W.D.	8510220003	50-282 Q
RUSSELL,W.T.	8510180384	MISC	SCOTT,D.J.	8510090381	50-249 S	SHAFFER,W.D.	8510220005	50-440 Q
RUTLEDGE,B.G.	8510290348	PR	SCOTT,D.J.	8510180472	50-237 R	SHAFFER,W.D.	8510220170	50-454 F
RUTLEDGE,C.	8510030143	40-8502	SCOTT,D.J.	8510240174	50-249 S	SHAFFER,W.D.	8510220282	50-263 Q
RUTLEDGE,C.	8510170394	40-8502	SCOTT,D.J.	8510300279	50-249 S	SHAFFER,W.D.	8510220414	50-295 Q
RYALL,R.K.	8510010460*	50-382 P	SCOTT,D.J.	8510300304	50-249 S	SHAFFER,W.D.	8510220417*	50-295 Q
RYAN,B.J.	8510210247*	70-820	SCOTT,D.J.	8510310133	50-249 P	SHAFFER,W.D.	8510230105	50-266 F
RYAN,H.A.	8510210002	40-2061	SCOTT,E.Y.	8510090529	40-8452 F	SHAFFER,W.D.	8510230125	50-237 F
RYTERS,K.M.	8510040432	50-454 S	SCOTT,R.	8510160301	50-346 F	SHAFFER,W.D.	8510230184	50-155 F
RYTKONEN,B.B.	8510080159*	CONTRACT	SCOTT-WASLIK,J.	8510280408	50-346 F	SHAFFER,W.D.	8510280298	50-282 Q
SABOL,B.J.	8510080523	STATE PRO G	SEAMAN,S.C.	8510100197	PR	SHAFFER,W.D.	8510280307	50-315 Q
SACCOMANNO,G.	8510250529	NUREG	SEARS,C.F.	8510040304	50-423 A	SHAFFER,W.D.	8510280352	50-341 Q
SAGER,D.A.	8510180090*	50-335 P	SEARS,C.F.	8510040304	50-423 A	SHAFFER,W.D.	8510280368	50-346 F
SAGER,D.A.	8510180096*	50-335 P	SEARS,C.F.	8510110037	50-245 P	SHAFFER,W.D.	8510310267	50-373 Q
SALISBURY,J.K.	8510010492	50-298 R	SEARS,C.F.	8510220150	50-423 A	SHAFFER,W.D.	8510310292	50-2 Q
SALTZMAN,J.	8510110269	50-259 I	SEARS,C.F.	8510220247	50-245 P	SHAFFER,W.D.	8510310293*	50-2 Q
SALTZMAN,J.	8510150083	50-220 I	SEARS,C.F.	8510230031	50-245 P	SHAFFER,W.D.	8510310325	50-346 Q
SALTZMAN,J.	8510150495	50-285 I	SEARS,C.F.	8510240003	50-245 P	SHAFFER,W.D.	8510100201	PR
SALTZMAN,J.	8510170029	50-321 I	SEARS,C.F.	8510240079	50-245 P	SHAFFER,R.	8510170450	40-8745
SALTZMAN,J.	8510290440	50-302 I	SEARS,C.F.	8510240089	50-245 P	SHAFFER,R.	8510180284	40-1162
SALTZMAN,J.	8510310004	50-263 I	SEARS,C.F.	8510240089	50-245 P	SHAFFNER,J.	8510280090	27-48
SALVESEN,R.S.	8510310089	50-354 F	SEARS,C.F.	8510240287	50-245 P	SHAFFNER,J.	8510280431	27-48
SALYERS,R.J.	8510180343	PR	SEARS,C.F.	8510240335	50-245 P	SHAFFNER,J.	8510280435*	27-48
SANCIG,D.	8510100046*	50-333 Q	SEARS,C.F.	8510240373	50-245 P	SHAFFNER,J.	8510280481	27-39
SANFORD,J.A.	8510170081	50-400 H	SEARS,C.F.	8510240382	50-245 P	SHAFFNER,J.	8510280494	27-48
SANFORD,M.	8510250364*	50-289 F	SEARS,C.F.	8510240410	50-245 P	SHAFFNER,J.A.	8510280064	WASTE MGT
SANTER,L.G.	8510010102*	50-320 P	SEARS,C.F.	8510240459	50-245 P	SHAFFNER,J.A.	8510280512	27-39
SARBANES,P.S.	8510010143*	50-289 P	SEARS,C.F.	8510250101	50-213 F	SHAFFNER,J.A.	8510290559	27-39
SARBANES,P.S.	8510010210*	50-289 P	SEARS,C.F.	8510280203	50-245 F	SHAH,V.N.	8510030433	NUREG
SARBANES,P.S.	8510010344*	50-289 P	SEARS,C.F.	8510280203	50-245 F	SHANBAKY,M.	8510030235*	50-245 Q
SARBANES,P.S.	8510010443*	FOIA	SEARS,C.F.	8510290235	50-423 F	SHANBAKY,M.	8510040172*	50-29 P
SARGENT,L.H.	8510030149*	CONTRACT	SEARS,C.F.	8510290235	50-423 F	SHANBAKY,M.	8510230047*	50-309 Q
SATERN,V.	8510010450*	FOIA	SEARS,C.F.	8510290300	50-336 P	SHANBAKY,M.	8510250465*	50-334 Q
SAUER,G.	8510290390*	50-245 P	SEARS,C.F.	8510290320	50-245 P	SHANBAKY,M.	8510250497*	50-272 Q
SAUER,G.	8510290393*	50-245 P	SEARS,C.F.	8510290333	50-245 P	SHANBAKY,M.	8510280305*	50-54 Q
SAUNDERS,R.F.	8510170442	50-281 S	SEARS,C.F.	8510290388	50-245 P	SHANBAKY,M.	8510310182*	50-266 Q
SAUNDERS,R.F.	8510280032	50-280 S	SEARS,C.F.	8510300123	50-245 P	SHANBAKY,M.M.	8510070073*	50-309 Q
SAVAGIL,J.W.	8510040182*	50-424 F	SEARS,C.F.	8510300215	50-423 S	SHANBAKY,M.M.	8510080032*	50-244 Q
SAVINI,R.J.	8510040405	PR	SEARS,C.F.	8510300215	50-423 S	SHANBAKY,M.M.	8510230244*	50-244 Q
SAXE,D.	8510220198*	70-25	SEARS,C.F.	8510300263	50-423 S	SHAO	8510020419	50-382 E
SCALETTO,D.C.	8510040547	50-447 A	SEARS,C.F.	8510300263	50-423 S	SHAO,L.	8510010553	50-382 E
SCARANO,R.A.	8510080459	50-139 Q	SEARS,C.F.	8510310214	50-423 A	SHAO,L.	8510030078	50-382 E

368 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY			
SHAO, L.C.	8510020263	50-382	E	SHOEMAKER, C.J.	8510100081	50-322	G	SMITH, G.	8510220344	70-1100	
SHAPAKER, J.W.	8510070519	50-295	P	SHOEMAKER, C.J.	8510110028	50-338	G	SMITH, G.	8510250273*	50-293	Q
SHATMAN, R.	8510180118*	50-440	A	SHOEMAKER, C.J.	8510210040	50-322	G	SMITH, G.	8510250445*	50-354	Q
SHEDLOSKEY, J.T.	8510080042	50-336	S	SHOEMAKER, C.J.	8510230087	50-289	G	SMITH, G.O.	8510180216*	50-416	F
SHEFFEL, B.J.	8510070329*	50-341	Q	SHOEMAKER, C.J.	8510230128	50-289	G	SMITH, H.A.	8510300230*	50-369	P
SHELL, R.H.	8510030068	50-259	Q	SHOEMAKER, C.J.	8510230255	50-352	G	SMITH, I.W.	8510180185	50-289	G
SHELL, R.H.	8510080348	50-438	Q	SHOEMAKER, C.J.	8510280515	50-400	G	SMITH, J.D.	8510150228*	50-250	Q
SHELL, R.H.	8510080465	50-390	A	SHOEMAKER, C.J.	8510280517	50-289	G	SMITH, J.N.	8510170010	50-382	Q
SHELL, R.H.	8510090130	50-327	P	SHOEMAKER, C.J.	8510290008	50-352	G	SMITH, M.J.	8510180270*	50-295	Q
SHELL, R.H.	8510090200	50-327	P	SHOEMAKER, C.J.	8510290009	50-440	G	SMITH, M.O.	8510220042*	50-320	Q
SHELL, R.H.	8510160088	50-438	A	SHON, F.J.	8510180258	50-320	G	SMITH, N.	8510080159*	CONTRACT	
SHELL, R.H.	8510160139	50-390	A	SHOPENN, N.M.	8510180489*	40-8084		SMITH, P.A.	8510020239	50-334	P
SHELL, R.H.	8510160153	50-259	P	SHOPENN, N.M.	8510210048	40-3453		SMITH, P.A.	8510040355*	CONTRACT	
SHELL, R.H.	8510160200	50-327	P	SHOPENN, N.M.	8510210070	40-8084		SMITH, P.A.	8510040472*	CONTRACT	
SHELL, R.H.	8510180021	50-259	Q	SHOPENN, N.M.	8510210169	40-3453		SMITH, P.A.	8510070308*	CONTRACT	
SHELL, R.H.	8510180030	50-259	Q	SHOPENN, N.M.	8510210176	40-8084		SMITH, P.A.	8510070581*	CONTRACT	
SHELL, W.G.	8510180234*	50-440	Q	SHOPENN, N.M.	8510220084	40-8084		SMITH, P.A.	8510080128*	CONTRACT	
SHELLEY, W.J.	8510010135*	40-8027		SHOUY, A.A.	8510070329*	50-341	Q	SMITH, P.A.	8510080141*	CONTRACT	
SHELLEY, W.J.	8510010142*	40-8027		SHREVE, R.E.	8510150209*	FOIA		SMITH, P.A.	8510080299*	CONTRACT	
SHELLEY, W.J.	8510010159*	40-8027		SHREVE, R.E.	8510150325*	FOIA		SMITH, P.A.	8510080334*	CONTRACT	
SHELLEY, W.J.	8510010174*	40-8027		SHUMWAY, R.W.	8510040407	NUREG		SMITH, P.A.	8510080376*	CONTRACT	
SHELLEY, W.J.	8510010183*	40-8027		SHUMWAY, R.W.	8510040411	NUREG		SMITH, P.A.	8510080600*	CONTRACT	
SHELLEY, W.J.	8510010224*	40-8006		SHUSTER, C.M.	8510150118*	50-440	A	SMITH, P.A.	8510090423*	CONTRACT	
SHELLEY, W.J.	8510010229*	40-8027		SHYMLOCK, M.B.	8510150228*	50-250	Q	SMITH, P.A.	8510150438	50-255	R
SHELLEY, W.J.	8510010230*	40-8006		SIACOR, E.R.	8510010641	50-206	R	SMITH, P.A.	8510150481*	CONTRACT	
SHELLEY, W.J.	8510010236*	40-8027		SIEBER, J.D.	8510020105	50-334	F	SMITH, P.M.	8510170119*	CONTRACT	
SHELLEY, W.J.	8510010242*	40-8027		SIEGEL, B.	8510180323	50-461	A	SMITH, P.M.	8510170119*	CONTRACT	
SHELLEY, W.J.	8510010243*	40-8006		SIEGEL, B.	8510230286	50-461	A	SMITH, R.D.	8510180191	40-1162	
SHELLEY, W.J.	8510010256*	40-8027		SIEGEL, B.	8510230301	50-461	F	SMITH, R.D.	8510180195*	40-1162	
SHELLEY, W.J.	8510010261*	40-8027		SISS, C.P.	8510080431*	50-330	Q	SMITH, R.D.	8510180227	40-8681	
SHELLEY, W.J.	8510010269*	40-8027		SILBERG, J.E.	8510110193	50-440	G	SMITH, R.D.	8510180234*	40-8681	
SHELLEY, W.J.	8510010273*	40-8027		SILBERG, J.E.	8510110193	50-440	G	SMITH, R.D.	8510180305	40-8452	
SHELLEY, W.J.	8510010401*	40-8027		SILBERG, J.E.	8510150354	50-440	G	SMITH, R.D.	8510180313*	40-8452	
SHELLEY, W.J.	8510010413*	40-8027		SILBERG, J.E.	8510150354	50-440	G	SMITH, R.D.	8510180460	40-299	
SHEPHERD, J.E.	8510220385	50-458	Q	SILBERG, J.E.	8510180215	50-440	G	SMITH, R.D.	8510180464*	40-299	
SHEPPARD, J.J.	8510080186	TOPREP		SILBERG, J.E.	8510180215	50-440	G	SMITH, R.D.	8510180470	40-4492	
SHEPPARD, J.J.	8510080186	TOPREP		SILVER, H.	8510040327	50-302	P	SMITH, R.D.	8510180473*	40-4492	
SHEPPARD, J.J.	8510080561	TOPREP		SILVER, H.	8510040350	50-302	P	SMITH, R.D.	8510180477	40-8584	
SHEPPARD, J.J.	8510080561	TOPREP		SILVER, H.	8510090162	50-302	P	SMITH, R.D.	8510180479*	40-8584	
SHEPPARD, J.J.	8510090320	TOPREP		SILVER, H.	8510150133	50-302	F	SMITH, R.D.	8510180485	40-8084	
SHEPPARD, J.J.	8510090320	TOPREP		SILVER, H.	8510150149	50-302	P	SMITH, R.D.	8510180486*	40-8084	
SHERANKO, R.G.	8510180281*	50-387	P	SILVER, H.	8510150316	50-302	P	SMITH, R.H.	8510220133*	50-334	Q
SHERMAN, C.I.	8510090530*	50-397	Q	SIMON, S.	8510220340*	50-286	P	SMITH, S.H.	8510040338	50-324	G
SHERMAN, C.I.	8510150465*	50-133	Q	SIMPSON, B.	8510030131	NUREG		SMITH, S.N.	8510040391	50-324	P
SHERMAN, J.T.	8510150389*	FOIA		SIMPSON, A.K.	8510110124*	COMMISSION		SMITH, T.	8510080437	50-382	S
SHERWOOD, D.R.	8510040347	NUREG		SIMPSON, C.L.	8510210172	71-173		SMITH, T.	8510170013	50-382	S
SHERWOOD, G.G.	8510100146	PR		SIMPSON, E.C.	8510010050	50-302	P	SMITH, T.	8510210163	50-382	S
SHEU, J.	8510010214*	50-219	P	SIMPSON, E.C.	8510010347	50-302	P	SMITH, W.F.	8510100079*	50-445	Q
SHEWCHENKO, A.	8510110211	PR		SIMS, R.W.	8510160105*	FOIA		SMITH, W.F.	8510280229*	50-445	Q
SHEWMAKER	8510010206	50-382	E	SINCLAIR, M.	8510080302*	50-329	Q	SMITH, W.F.	8510280254*	50-445	Q
SHEWMAKER	8510020054	50-382	E	SINCLAIR, M.	8510060444*	50-329	Q	SMITH, W.G.	8510010110	50-316	S
SHEWMAKER	8510020092	50-382	E	SINCLAIR, M.P.	8510080379*	50-329	T	SMITH, W.G.	8510010493	50-316	R
SHEWMAKER	8510020134	50-382	E	SINGER, B.	8510090067*	27-39		SMITH, W.G.	8510010496	50-315	R
SHEWMAKER	8510020143	50-382	E	SINGER, G.L.	8510040411	NUREG		SMITH, W.G.	8510070548	50-315	S
SHEWMAKER	8510020341	50-382	E	SINGH, B.K.	8510240511	50-412	F	SMITH, W.G.	8510080577	50-315	S
SHEWMAKER	8510020471	50-382	E	SINGH, M.M.	8510110069	WASTE RES		SMITH, W.G.	8510090176	50-315	S
SHEWMAKER	8510030266	50-382	E	SINGH, N.P.	8510250529	NUREG		SMITH, W.G.	8510090246	50-315	S
SHEWMAKER	8510030272	50-382	E	SINGH, S.	8510080424*	50-354	A	SMITH, W.G.	8510090370	50-315	S
SHEWMAKER, R.E.	8510010484	50-382	E	SINGH, S.	8510080428*	50-354	A	SMITH, W.G.	8510090374	50-315	S
SHEWMAKER, R.E.	8510010489	50-382	E	SINKE, G.J.	8510010300*	40-8027		SMITH, W.G.	8510090520	50-315	S
SHEWMAKER, R.E.	8510010497	50-382	E	SINKIN, L.	8510180296	50-498	G	SMITH, W.G.	8510170022	50-315	S
SHEWMAKER, R.E.	8510010499	50-382	E	SINKIN, L.	8510180389	50-498	G	SMITH, W.G.	8510170025	50-316	S
SHEWMAKER, R.E.	8510020439	50-382	E	SINKIN, L.A.	8510030028	50-498	G	SMITH, W.G.	8510170040	50-316	S
SHEWMAKER, R.E.	8510040520	50-382	E	SINKULE, M.V.	8510040498*	50-424	Q	SMITH, W.G.	8510170049	50-315	S
SHIELDS, S.W.	8510080202	50-546	A	SISK, D.P.	8510010644	50-275	S	SMITH, W.G.	8510170445	50-316	S
SHIFFER, J.D.	8510010239	50-275	F	SISK, D.P.	8510080396	50-323	S	SMITH, W.G.	8510170448	50-316	S
SHIFFER, J.D.	8510010644	50-275	S	SISK, D.P.	8510210286	50-275	S	SMITH, W.G.	8510240183	50-315	S
SHIFFER, J.D.	8510020043	50-275	K	SKOGEN, F.B.	8510170292*	50-316	P	SMITH, W.G.	8510240219	50-316	S
SHIFFER, J.D.	8510040112	50-323	S	SKOW, M.E.	8510040139*	50-267	Q	SMITH, W.G.	8510280405	50-315	S
SHIFFER, J.D.	8510080396	50-323	S	SKOW, M.E.	8510240112*	50-458	Q	SMITH, W.J.	8510180194	50-219	F
SHIFFER, J.D.	8510150185	50-275	S	SKOW, M.E.	8510310350*	50-458	Q	SMITH, W.J.	8510290263*	50-219	P
SHIFFER, J.D.	8510160043	50-133	P	SLATTERY, J.	8510010586*	COMMISSION		SMYKOWSKI, S.	8510280226	WASTE MGT	
SHIFFER, J.D.	8510160151	50-275	E	SLIFER, B.C.	8510310215*	50-29	P	SMYKOWSKI, S.	8510280432	WASTE MGT	
SHIFFER, J.D.	8510180020	50-275	P	BLOSSON, M.M.	8510180498	50-247	Q	SMYTH, C.W.	8510310596	50-289	R
SHIFFER, J.D.	8510180050	71-9176		SMEDIRA, C.	8510100065	PR		SNELL, W.	8510100018*	50-266	Q
SHIFFER, J.D.	8510180139	50-275	F	SMEENGER, R.J.	8510100105*	50-456	Q	SNELL, W.	8510280359*	50-341	Q
SHIFFER, J.D.	8510180546	71-9073		SMITH, B.A.	8510010251	FOIA		SNOW, B.A.	8510010422	50-244	R
SHIFFER, J.D.	8510210286	50-275	S	SMITH, B.W.	8510250531	NUREG		SNYDER, B.J.	8510040351	50-320	P
SHIFFER, J.D.	8510230135	50-133	P	SMITH, C.F.	8510080363*	50-302	Q	SNYDER, B.J.	8510070105	50-320	P
SHIFFER, J.D.	8510280362	50-275	P	SMITH, C.V.	8510280115	50-243	P	SNYDER, B.J.	8510230259	50-320	P
SHIFFER, J.D.	8510280400	50-133	F	SMITH, C.V.	8510290586	50-243	R	SNYDER, B.J.	8510230264*	50-320	P
SHIFFER, J.D.	8510290059	50-275	P	SMITH, D.L.	8510040479	50-296	S	SNYDER, B.J.	8510250565	50-320	P
SHIFFER, J.D.	8510290062*	50-275	P	SMITH, D.L.	8510070545	50-259	S	SNYDER, B.J.	8510250591*	50-320	P
SHIFFER, J.D.	8510300065	50-275	P	SMITH, D.L.	8510170370	50-259	S	SNYDER, B.J.	8510280083	50-320	P
SHINGLETON, E.B.	8510090366*	50-416	S	SMITH, D.L.	8510290470	50-259	S	SNYDER, B.J.	8510300017	50-320	P
SHOALL	8510030354	50-382	E	SMITH, E.P.	8510010058	FOIA		SNYDER, B.J.	8510300088	50-320	P
SHOEMAKER, C.J.	8510020150	50-352	G	SMITH							

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SOMERVILLE, K.G.	8510170323	40-8793	STANDERFER, F.R.	8510180160	50-320 P	STEWART, W.L.	8510180151	50-280 P
SOMERVILLE, K.G.	8510170326*	40-8793	STANDERFER, F.R.	8510220037	50-320 P	STEWART, W.L.	8510210122	50-338 F
SONNEMAKER, R.E.	8510180327	PR	STANDERFER, F.R.	8510220149	50-320 P	STEWART, W.L.	8510280118	50-338 P
SOO, P.	8510080612	WASTE RES	STANDERFER, F.R.	8510250463	50-320 Q	STEWART, W.L.	8510280324	50-338 P
SOO, P.	8510080617*	WASTE RES	STANDERFER, F.R.	8510290212	50-320 P	STEWART, W.L.	8510280326	50-338 P
SOONG, A.L.	8510040436*	70-143	STANDERFER, F.R.	8510290218	50-320 P	STEWART, W.L.	8510280372	50-338 F
SOONG, A.L.	8510070170	70-143	STANLEY, J.E.	8510150468	50-317 P	STEWART, W.L.	8510290047	50-280 P
SORENSEN, G.C.	8510010281	50-480 A	STANSBERRY, W.	8510220396*	50-250 Q	STEWART, W.L.	8510290086	50-280 F
SORENSEN, G.C.	8510010382	50-397 P	STANSBERRY, W.W.	8510180463*	50-302 Q	STEWART, W.L.	8510290109	50-280 P
SORENSEN, G.C.	8510020104*	50-397 Q	STARKEY, R.S.	8510010460*	50-382 P	STEWART, W.L.	8510290197	50-338 P
SORENSEN, G.C.	8510030030	50-397 P	STARKEY, R.S.	8510010461*	50-382 Q	STEWART, W.L.	8510290253	50-338 P
SORENSEN, G.C.	8510040103	50-397 P	STARMER, R.J.	8510290064	WASTE MGT	STEWART, W.L.	8510310353	50-280 P
SORENSEN, G.C.	8510040205	50-397 P	STARMER, R.J.	8510280435*	27-48	STIETZEL, J.F.	8510090370	50-315 S
SORENSEN, G.C.	8510080142	50-397 Q	STARMER, R.J.	8510280494	27-48	STIETZEL, J.F.	8510170445	50-316 S
SORENSEN, G.C.	8510080156	50-508 A	STAROSTECKI, R.	8510020238	50-293 Q	STILLE, T.	8510220241*	40-8027
SORENSEN, G.C.	8510080205	50-397 P	STAROSTECKI, R.	8510020274	50-29 S	STINSON, L.	8510020211*	50-382 Q
SORENSEN, G.C.	8510080242	50-397 P	STAROSTECKI, R.	8510030260	50-293 Q	STINSON, L.A.	8510020207*	50-382 Q
SORENSEN, G.C.	8510080245	50-508 A	STAROSTECKI, R.	8510080072	50-277 Q	STINSON, T.L.	8510170036*	FOIA
SORENSEN, G.C.	8510090163	50-397 P	STAROSTECKI, R.	8510080119	50-309 Q	STOETZEL, G.	8510230163*	50-317 Q
SORENSEN, G.C.	8510150290	50-397 F	STAROSTECKI, R.	8510080193	50-410 Q	STOHR, J.P.	8510040126	70-27
SORENSEN, G.C.	8510180087	50-508 A	STAROSTECKI, R.	8510090188	50-387 Q	STOHR, J.P.	8510040147	70-1151
SORENSEN, G.C.	8510180097	50-397 P	STAROSTECKI, R.	8510090219	50-354 Q	STOHR, J.P.	8510150361	70-27
SORENSEN, G.C.	8510180260	50-397 P	STAROSTECKI, R.	8510110166	50-272 Q	STOHR, J.P.	8510180053	70-27
SORENSEN, G.C.	8510170082	50-480 A	STAROSTECKI, R.	8510170295	50-410 Q	STOHR, J.P.	8510180454	70-27
SORENSEN, G.C.	8510180114	50-397 P	STAROSTECKI, R.	8510310164	50-213 Q	STOHR, J.P.	8510180531	70-143
SORENSEN, G.C.	8510220071	50-397 P	STAUTER, J.C.	8510100007	PR	STOHR, J.P.	8510250588	70-1151
SORENSEN, G.C.	8510220290	50-397 F	STAUTER, J.C.	8510150071	40-8027	STOLZ, J.F.	8508270323	50-312 P
SORENSEN, G.C.	8510220318	50-397 F	STAUTER, J.C.	8510180304	40-8027	STOLZ, J.F.	8510010118	50-289 P
SORENSEN, G.C.	8510290054	50-460 S	STAUTER, J.C.	8510180481	40-8758	STOLZ, J.F.	8510010386	50-277 F
SORENSEN, G.C.	8510300046	50-508 A	STAUTER, J.C.	8510220194	40-2061	STOLZ, J.F.	8510040339*	50-302 P
SORENSEN, G.C.	8510210095	50-397 P	STAUTER, J.C.	8510220235	40-8027	STOLZ, J.F.	8510040356*	50-302 P
SORRELLE, E.C.	8510250448	50-321 F	STEARN, J.D.	8510010438	50-382 E	STOLZ, J.F.	8510080116*	50-312 P
SPAIN, W.J.	8510180352	PR	STEELE, R.C.	8510180387	50-259 S	STOLZ, J.F.	8510090080*	50-269 P
SPANGENBERG, F.	8510020288	50-461 A	STEFANO, J.J.	8510290628	50-440 A	STOLZ, J.F.	8510090196*	50-302 P
SPANGENBERG, F.	8510040140	50-461 A	STEIGER, W.E.	8510010013	50-322 S	STOLZ, J.F.	8510090315	50-289 P
SPANGENBERG, F.	8510070321	50-461 E	STEIGER, W.E.	8510020100	50-322 R	STOLZ, J.F.	8510090319	50-289 P
SPANGENBERG, F.	8510100045	50-461 E	STEIGER, W.E.	8510030378	50-322 S	STOLZ, J.F.	8510090521	50-277 P
SPANGENBERG, F.	8510100054	50-461 E	STEIGER, W.E.	8510030412	50-322 S	STOLZ, J.F.	8510090528*	50-277 P
SPANGENBERG, F.	8510100096	50-461 F	STEIGER, W.E.	8510090101	50-322 S	STOLZ, J.F.	8510150317*	50-302 P
SPANGENBERG, F.	8510100132	50-461 F	STEIGER, W.E.	8510090287	50-322 S	STOLZ, J.F.	8510180512	50-269 P
SPANGENBERG, F.	8510110043	50-461 F	STEIGER, W.E.	8510170003	50-322 R	STOLZ, J.F.	8510180524	50-312 F
SPANGENBERG, F.	8510180131	50-461 E	STEIGER, W.E.	8510170363	50-322 S	STOLZ, J.F.	8510210194*	50-260 P
SPANGENBERG, F.	8510180165	50-461 E	STEIGER, W.E.	8510170368	50-322 S	STOLZ, J.F.	8510290418	50-278 Q
SPANGENBERG, F.	8510180177	50-461 E	STEIGER, W.E.	8510180154	50-322 S	STOLZ, J.F.	8510300193*	50-269 P
SPANGENBERG, F.	8510210015	50-461 A	STEIGER, W.E.	8510180179	50-322 S	STOLZ, J.F.	8510300222*	50-321 P
SPANGENBERG, F.	8510210028	50-461 A	STEIGER, W.E.	8510220007	50-322 S	STOLZ, J.F.	8510300294	50-346 P
SPANGENBERG, F.	8510210036	50-461 A	STEIGER, W.E.	8510250026	50-322 S	STOLZ, J.F.	8510310387	50-277 P
SPANGENBERG, F.	8510210094	50-461 A	STEIN, R.	8510090142	WASTE MGT	STOLZ, J.F.	8510310420	50-346 P
SPANGENBERG, F.	8510250378	50-461 E	STEINER, E.J.	8510250326	PR	STORZ, L.F.	8510010410	50-346 R
SPANGENBERG, F.	8510280054	50-461 Q	STEISS, A.W.	8510040503*	CONTRACT	STORZ, L.F.	8510090008	50-346 S
SPANGENBERG, F.	8510280288	50-461 F	STELLO, V.	8402280501	REVIEW GR P	STORZ, L.F.	8510240023	50-346 R
SPANGENBERG, F.	8510310250	50-461 A	STELLO, V.	8509030152*	50-259 P	STORZ, L.F.	8510240039	50-346 R
SPAULDING, W.	8510010264	50-382 E	STELLO, V.	8510020112	MISC	STORZ, L.F.	8510240040*	50-346 R
SPAULDING, W.	8510020151	50-382 E	STELLO, V.	8510090275	REVIEW GR P	STRATTON, W.E.	8510220178*	50-446 A
SPAULDING, W.H.	8510010559	50-382 E	STELLO, V.	8510090504	REVIEW GR P	STRONG, T.H.	8510250471*	PR
SPAULDING, W.H.	8510010562	50-382 E	STELLO, V.	8510110122	REVIEW GR P	STROSNIER, J.	8510040315	50-322 S
SPAULDING, W.H.	8510020377	50-382 E	STELLO, V.	8510180097	REVIEW GR P	STROSNIER, J.	8510020080*	50-387 Q
SPAULDING, W.H.	8510020449	50-382 E	STELLO, V.	8510180112	REVIEW GR P	STROSNIER, J.	8510210005	50-387 S
SPAULDING, W.H.	8510030359	50-382 E	STELLO, V.	8510180321*	PR	STROSNIER, J.	8510210098	50-289 S
SPAULDING, W.H.	8510030375	50-382 E	STELLO, V.	8510210055	REVIEW GR P	STROSNIER, J.	8510230202*	50-387 Q
SPEARS, R.G.	8510180289	40-8786	STEPHENS, D.C.	8510100144	PR	STROSNIER, J.	8510280360*	50-354 Q
SPECK, S.W.	8510100056	50-322 F	STEPHENS, K.W.	8510090345	WASTE RES	STROSNIER, J.	8510180148	50-387 S
SPECK, S.W.	8510180145	50-413 F	STEPHENS, K.W.	8510250015	WASTE RES	STRUCKMEYER, R.	8510070073*	50-309 Q
SPECK, S.W.	8510180189*	50-282 F	STEWART, S.	8510030182	CONTRACT	STRUCKMEYER, R.	8510310182*	50-286 Q
SPECK, S.W.	8510230014	50-416 F	STEWART, S.	8510040127	CONTRACT	STYLES, L.B.	8510110085	50-456 Q
SPEIS, T.P.	8311040213*	COMMISSION	STEWART, S.	8510160330	CONTRACT	STYLES, L.B.	8510110085	50-456 Q
SPEIS, T.P.	8504080378*	REVIEW GR P	STEWART, S.	8510310363	CONTRACT	STYLES, L.C.	8510110133	50-456 Q
SPITZBERG, D.B.	8510310389*	50-382 Q	STEWART, S.A.	8510150356*	50-302 R	STYLES, L.C.	8510110133	50-456 Q
SPOTTS, C.B.	8510010294*	40-8027	STEWART, S.A.	8510150357*	50-302 R	STYLES, L.C.	8510180338	50-456 Q
SPURGIN, P.D.	8510240554	WASTE MGT	STEWART, S.D.	8510010137	CONTRACT	STYLES, L.C.	8510180338	50-456 Q
ST LAURENT, N.N.	8510070370	50-29 S	STEWART, W.L.	8510010451	50-338 P	STYLES, L.C.	8510220291	50-456 Q
STABLE, C.R.	8510030282*	50-416 P	STEWART, W.L.	8510010643	50-280 R	STYLES, L.C.	8510220291	50-456 Q
STAHR, J.P.	8510090250	WASTE MGT	STEWART, W.L.	8510020071	50-338 R	SUERMANN, J.F.	8510010201*	50-315 Q
STAHL, D.	8510020228	NUREG	STEWART, W.L.	8510030013	50-339 P	SUERMANN, J.F.	8510080616*	50-483 Q
STAHL, C.	8510180495	50-259 Y	STEWART, W.L.	8510030116	50-338 S	SUERMANN, J.F.	8510280268*	50-483 Q
STALKER, A.C.	8510040592	50-282 P	STEWART, W.L.	8510040082	50-338 F	SULLIVAN, S.	8510090330	WASTE MGT
STAMIRIS, B.	8208030689*	50-329 A	STEWART, W.L.	8510040137	50-280 F	SUMMA, J.A.	8510170245	50-245 S
STAMIRIS, B.	8510060295*	50-329 Q	STEWART, W.L.	8510040348	50-280 F	SUMMER, T.E.	8510040405	PR
STAMIRIS, B.	8510080373*	50-329 A	STEWART, W.L.	8510040374	50-281 P	SUMMERS, D.	8510020442	50-382 E
STANDERFER, F.R.	8510010094	50-320 P	STEWART, W.L.	8510070328	50-338 Q	SUMMERS, D.	8510040130	50-382 E
STANDERFER, F.R.	8510010102*	50-320 P	STEWART, W.L.	8510070360	50-280 F	SUMMERS, D.	8510040217	50-382 E
STANDERFER, F.R.	8510040141	50-320 P	STEWART, W.L.	8510070378	50-338 Q	SUMMERS, D.	8510040410	50-382 E
STANDERFER, F.R.	8510040293	50-320 P	STEWART, W.L.	8510080153	50-338 P	SUMMERS, D.L.	8510040417	50-382 E
STANDERFER, F.R.	8510040299	50-320 P	STEWART, W.L.	8510080380	50-280 P	SUMMERS, D.L.	8510020116	50-382 E
STANDERFER, F.R.	8510040309	50-320 P	STEWART, W.L.	8510100113	50-280 P	SUMMERS, D.L.	8510020149	50-382 E
STANDERFER, F.R.	8510080457	50-320 P	STEWART, W.L.	8510150041	50-280 V	SUMMERS, D.L.	8510020188	50-382 E
STANDERFER, F.R.	8510180096	50-320 P	STEWART, W.L.	8510160104*	50-338 Q	SUMMERS, D.L.	8510020383	50-382 E
STANDERFER, F.R.	8510180074	50-320 P	STEWART, W.L.	8510170074	50-280 P	SUMMERS, D.L.	8510020418	50-382 E

370 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SUMMERS,D.L.	8510020457	50-382 E	THEOFANOUS,T.G.	8510090412*	50-320 P	TOTH,A.D.	8510090359*	50-397 Q
SUMMERS,D.L.	8510030351	50-382 E	THIELKE,S.A.	8510170031*	FOIA	TOUSLEY,D.R.	8510240582	WASTE MGT
SUTPHIN,R.N.	8510310265*	50-295 Q	THIELKE,S.A.	8510170033*	FOIA	TOUSLEY,D.R.	8510240582	WASTE MGT
SWAINSTON,H.	8510070351	PRM	THOM,T.	8510010487	50-259 R	TOWNSEND,M.	8510180478	40-8781
SWAINSTON,H.	8510100133*	PRM	THOMAS,J.	8510310445	50-289 P	TRAINOR,E.F.	8510290046*	50-400 T
SWANSON,D.	8510290362	PR	THOMAS,B.	8510150432	50-331 S	TRAINOR,E.F.	8510290046*	50-400 T
SWENSON,F.A.	8510040129*	CONTRACT	THOMAS,B.	8510210289	50-331 R	TRAMMELL,J.W.	8510170212	40-299
SWETLAND,P.D.	8510310167*	50-213 Q	THOMAS,B.	8510280396	50-331 S	TRAMMELL,J.W.	8510170426	40-299
SWIGER,J.L.	8510170088	FOIA	THOMAS,B.J.	8510030434*	CONTRACT	TRAPP,J.	8510010001	WASTE MGT
SWIGER,J.L.	8510170210*	FOIA	THOMAS,B.J.	8510170134*	FOIA	TRAVERS,W.D.	8510310132	50-320 S
SWIGER,J.L.	8510170219*	FOIA	THOMAS,C.O.	8510010089	50-123 H	TRAVERS,W.D.	8510020005	50-320 R
SWIGER,M.A.	8510180351	50-440 G	THOMAS,C.O.	8510070337	50-601 A	TRAVERS,W.D.	8510040041	50-320 R
SWIGER,M.A.	8510180351	50-440 G	THOMAS,C.O.	8510150005	50-59 F	TRAVERS,W.D.	8510070575	50-320 F
SWINEY,D.L.	8510110055	71-9032	THOMAS,C.O.	8510170314	TOPREP	TRAVERS,W.D.	8510150439	50-320 R
TAMBLING,T.N.	8510070202*	50-346 S	THOMAS,C.O.	8510170325	TOPREP	TRAVERS,W.D.	8510170381	50-320 R
TAMLYN,T.K.	8510170094	50-254 P	THOMAS,C.O.	8510170478	50-433 P	TRAVERS,W.D.	8510250008	50-320 P
TAMLYN,T.K.	8510170388	50-254 R	THOMAS,C.O.	8510180095	TOPREP	TRAVERS,W.D.	8510250025	50-320 P
TANI,K.	8510310112*	50-282 Q	THOMAS,C.O.	8510210181	50-163 P	TRAVERS,W.D.	8510280013	50-320 R
TANI,K.	8510170309*	50-440 Q	THOMAS,C.O.	8510210183*	50-163 P	TREB,S.	8510290022*	50-445 G
TAPIA,J.I.	8510020082	50-382 E	THOMAS,C.O.	8510210183*	50-77 P	TREB,S.A.	8510290016	50-445 G
TAPIA,J.I.	8510020413	50-392 E	THOMAS,C.O.	8510300227	50-433 P	TREJO,J.	8510080086	50-272 R
TAPIA,J.I.	8510020414	50-382 E	THOMAS,C.O.	8510300231*	50-433 P	TREJO,J.	8510240106	50-272 R
TAPLEY,J.	8510180301	50-346 F	THOMAS,G.S.	8510280416	70-3027	TRENT,L.K.	8510150028*	71-88
TAYLOR,D.D.	8510040411	NUREG	THOMAS,L.	8510230058*	50-321 U	TRIMBLE,D.	8510230163*	50-317 Q
TAYLOR,H.	8510020297	TOPREP	THOMAS,M.	8510070129*	CONTRACT	TRIMBLE,D.C.	8510080604*	50-184 Q
TAYLOR,J.H.	8510070263	50-269 P	THOMAS,M.	8510070480*	50-414 Q	TRIMBLE,D.C.	8510250425*	50-317 Q
TAYLOR,J.H.	8510180300	TOPREP	THOMAS,R.D.	8510150345*	70-754	TRINER,E.G.	8510180301*	PR
TAYLOR,J.H.	8510103328	TOPREP	THOMAS,P.V.	8510010492	50-296 R	TRIPP,L.	8510020244*	50-293 Q
TAYLOR,J.M.	8510303255*	50-346 Q	THOMPSON,A.J.	8510180302	40-8681	TRIPP,L.	8510020260*	50-293 Q
TAYLOR,J.M.	8503130606*	REVIEW GR P	THOMPSON,A.J.	8510180307*	40-8681	TRIPP,L.	8510020383	50-293 S
TAYLOR,J.M.	8509180247	50-334 Q	THOMPSON,H.L.	8506260595*	50-346 S	TRIPP,L.	8510080183	50-293 S
TAYLOR,J.M.	8509180248	50-317 Q	THOMPSON,H.L.	8506270129*	50-346 F	TRIPP,L.	8510220284*	50-293 Q
TAYLOR,J.M.	8509180250	50-496 Q	THOMPSON,H.L.	8509240248	50-3 V	TRIPP,L.	8510290587	50-271 Q
TAYLOR,J.M.	8509180255	50-261 Q	THOMPSON,H.L.	8510010014	50-333 F	TRIPP,L.E.	8510070166*	50-412 Q
TAYLOR,J.M.	8509180313	50-280 Q	THOMPSON,H.L.	8510010016	50-263 F	TROWBRIDGE,G.F.	8510100048	50-289 G
TAYLOR,J.M.	8510010433	70-143	THOMPSON,H.L.	8510020101	50-213 P	TROWBRIDGE,G.F.	8510100048	50-289 G
TAYLOR,J.M.	8510010637	50-309 R	THOMPSON,H.L.	8510030105	50-213 P	TROWBRIDGE,G.F.	8510290358	PR
TAYLOR,J.M.	8510110259	70-143	THOMPSON,H.L.	8510040138	50-321 P	TROWBRIDGE,G.F.	8510290358	PR
TAYLOR,J.M.	8510110260*	70-143	THOMPSON,H.L.	8510090316	50-286 F	TUCCINARDI,T.E.	8510070073*	50-309 Q
TAYLOR,J.M.	8510150224*	50-250 Q	THOMPSON,H.L.	8510110089	50-267 P	TUCCINARDI,T.E.	8503200025	50-269 P
TAYLOR,J.M.	8510210033	QA999	THOMPSON,H.L.	8510110113	50-267 P	TUCKER,H.B.	8510010106	50-413 S
TAYLOR,J.M.	8510220082	70-143	THOMPSON,H.L.	8510110216	50-528 S	TUCKER,H.B.	8510010231	50-269 S
TAYLOR,J.M.	8510220111*	70-143	THOMPSON,H.L.	8510110229	50-247 P	TUCKER,H.B.	8510010259	50-269 P
TAYLOR,J.M.	8510250322	50-289 Q	THOMPSON,H.L.	8510150249	50-338 P	TUCKER,H.B.	8510010280	50-413 P
TAYLOR,J.W.	8510020094	50-409 R	THOMPSON,H.L.	8510170464	50-267 P	TUCKER,H.B.	8510010389	50-369 P
TAYLOR,J.W.	8510070274	50-409 P	THOMPSON,H.L.	8510180183	50-281 Q	TUCKER,H.B.	8510020250	50-413 S
TAYLOR,J.W.	8510070478	50-409 R	THOMPSON,H.L.	8510210159*	50-412 A	TUCKER,H.B.	8510040144	50-414 Q
TAYLOR,J.W.	8510070560	50-409 P	THOMPSON,H.L.	8510220138	50-213 P	TUCKER,H.B.	8510070437	50-369 Q
TAYLOR,J.W.	8510150329	50-409 S	THOMPSON,H.L.	8510220168	MISC	TUCKER,H.B.	8510070466	50-269 Q
TAYLOR,J.W.	8510230107	50-409 J	THOMPSON,H.L.	8510240417*	50-361 P	TUCKER,H.B.	8510080165	50-269 F
TAYLOR,J.W.	8510240266	50-409 K	THOMPSON,H.L.	8510250581*	50-416 P	TUCKER,H.B.	8510080175	50-270 P
TAYLOR,J.W.	8510250396	50-409 Q	THOMPSON,H.L.	8510280439	50-266 F	TUCKER,H.B.	8510080335	50-269 F
TAYLOR,J.W.	8510310396	50-409 S	THOMPSON,H.L.	8510310019	50-333 F	TUCKER,H.B.	8510080359	50-369 P
TAYLOR,J.W.	8510310423	50-409 S	THOMPSON,H.L.	8510310222	50-348 P	TUCKER,H.B.	8510090022	50-369 S
TAYLOR,R.G.	8510240347*	50-458 Q	THOMPSON,R.D.	8510040503*	CONTRACT	TUCKER,H.B.	8510090466	50-413 S
TAYLOR,T.E.	8510210223*	50-237 Q	THOMPSON,R.D.	8510080015*	CONTRACT	TUCKER,H.B.	8510090535	50-287 S
TEDFORD,C.F.	8510040193	STATE PRO G	THOMPSON,R.D.	8510080027*	CONTRACT	TUCKER,H.B.	8510100155	50-269 P
TEDFORD,C.F.	8510250326	PR	THOMPSON,R.D.	8510080146*	50-320 P	TUCKER,H.B.	8510150090	50-369 P
TENERZ,E.	8510030130	50-245 P	THOMPSON,R.D.	8510080325*	CONTRACT	TUCKER,H.B.	8510150318	50-413 F
TERC,N.M.	8510220456*	50-445 Q	THOMPSON,R.D.	8510080598*	CONTRACT	TUCKER,H.B.	8510160017	50-269 Q
TERPILAK,M.S.	8510250351	FOIA	THOMPSON,R.D.	8510090439*	CONTRACT	TUCKER,H.B.	8510160278	50-269 P
TETRAULT,R.E.	8510030006	70-27	THOMPSON,S.D.	8510040442	PR	TUCKER,H.B.	8510160294*	50-369 Q
TETRAULT,R.E.	8510030048	70-27	THOMPSON,T.	8510170105*	FOIA	TUCKER,H.B.	8510170185	50-269 R
TEUTBERG,R.L.	8510080333	50-250 S	THORNBERY,R.C.	8510010612	50-275 R	TUCKER,H.B.	8510170259	50-369 S
TEUTBERG,R.L.	8510280003	7-250 S	THORNBERG,L.H.	8510100038	50-400 G	TUCKER,H.B.	8510170311	50-413 P
THADANI,A.	8302090513*	50-346 S	THORPE,J.R.	8510290315	NUREG	TUCKER,H.B.	8510180108	50-413 P
THADANI,A.	84111280233*	COMMISSION	THURBER,J.P.	8510110005	50-354 A	TUCKER,H.B.	8510180271	50-413 F
THADANI,A.C.	8310270010*	COMMISSION	TIEN,C.	8510220390	50-346 O	TUCKER,H.B.	8510210067	50-269 F
THADANI,A.C.	8401270550*	COMMISSION	TIEN,C.	8510220390	50-346 O	TUCKER,H.B.	8510210074	50-269 P
THADANI,M.C.	8510160344	50-331 P	TIERNAN,J.A.	8510250414	50-317 Q	TUCKER,H.B.	8510210075	50-269 F
THATCHER,D.	8510020469	50-382 E	TIKINSKY,D.H.	8510240351	WASTE RES	TUCKER,H.B.	8510210267	50-413 R
THATCHER,D.	8510030102	50-382 E	TILLMAN,A.	8510220229*	50-302 Q	TUCKER,H.B.	8510210285	50-369 R
THATCHER,D.	8510030160	50-382 E	TILLMAN,T.	8510170366*	50-454 S	TUCKER,H.B.	8510220094	50-269 R
THATCHER,D.	8510030170	50-382 E	TIPPS,S.B.	8510010220	50-321 S	TUCKER,H.B.	8510220263	50-413 F
THATCHER,D.	8510030397	50-382 E	TIPPS,S.B.	8510080085	50-366 S	TUCKER,H.B.	8510220289	50-413 F
THATCHER,D.	8510030402	50-382 E	TIPPS,S.B.	8510180377	50-366 S	TUCKER,H.B.	8510220355	50-413 F
THATCHER,D.F.	8510010475	50-382 E	TIPPS,S.B.	8510180510	50-321 S	TUCKER,H.B.	8510220425	FOIA
THEMELIS,J.G.	8510010563	50-382 E	TIPPS,S.B.	8510250081	50-321 S	TUCKER,H.B.	8510230050	50-413 R
THEMELIS,J.G.	8510090469	WASTE MGT	TIPPS,S.B.	8510250564	50-366 S	TUCKER,H.B.	8510230059	50-413 P
THEMELIS,J.G.	8510240284	WASTE MGT	TOBIN,W.	8510150336*	70-143	TUCKER,H.B.	8510230070	50-369 F
THEMELIS,J.G.	8510240311	WASTE MGT	TOBIN,W.	8510160082*	50-259 Q	TUCKER,H.B.	8510230153	50-369 P
THEMELIS,J.G.	8510240461	WASTE MGT	TODD,G.A.	8510180058*	70-27	TUCKER,H.B.	8510250116	50-413 S
THEMELIS,J.G.	8510240505	WASTE MGT	TOENJES,C.	8510040312	NUREG	TUCKER,H.B.	8510250197	50-413 F
THEMELIS,J.G.	8510240561	WASTE MGT	TOKUHATA,G.K.	8510150291*	50-272 H	TUCKER,H.B.	8510250218	50-369 P
THEMELIS,J.G.	8510240611	WASTE MGT	TOMPKINS,B.A.	8510240677	50-445 G	TUCKER,H.B.	8510280397	50-369 S
THEMELIS,J.G.	8510250527	WASTE MGT	TONG,V.	8510180478	40-8781	TUCKER,H.B.	8510290073	50-346 S
THEMELIS,J.G.	8510280023	WASTE MGT	TOOLE,R.J.	8510250375*	50-289 F	TUCKER,H.B.	8510290382	50-269 I
THEMELIS,J.G.	8510280082	WASTE MGT	TORIN,H.	8510040191	50-254 F	TUCKER,H.B.	8510290464	50-369 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TUCKER,H.B.	8510300190	50-414 A	URBAN,R.J.	8510250171*	50-219 Q	VARGA,S.A.	8510310022	50-280 P
TUCKER,H.B.	8510300209	50-389 P	URBANIK,T.	8510290429*	50-424 F	VARGA,S.A.	8510310023	50-305 P
TUCKER,H.B.	8510310039	50-389 F	URYC,B.	8510170357*	50-413 Q	VARGA,S.A.	8510310028	50-315 P
TUCKER,H.B.	8510310248	50-289 P	VADLAMANI,K.M.	8510030036	50-382 E	VARGA,S.A.	8510310037*	50-305 P
TUCKER,M.	8510090218*	WASTE MGT	VALASEK,L.M.	8510090216*	50-282 P	VARGA,S.A.	8510310056	50-305 F
TUCKER,M.K.	8510040597	WASTE MGT	VALASEK,L.M.	8510090221*	50-282 P	VARGA,S.A.	8510310059	50-311 P
TUCKER,M.K.	8510040602*	WASTE MGT	VALDES,J.	8510280430	WASTE MGT	VARGA,S.A.	8510310068	50-334 P
TUCKER,M.K.	8510040607*	WASTE MGT	VALENTINE,A.M.	8510010127*	40-8006	VARGA,S.A.	8510310083	50-334 P
TUCKER,M.K.	8510040615*	WASTE MGT	VALENTINE,P.J.	8510080252*	50-305 P	VARGA,S.A.	8510310179*	50-247 P
TUCKER,M.K.	8510040617*	WASTE MGT	VALENZUELA,J.A.	8510020217	NURCG	VARGA,S.A.	8510310552	50-261 P
TUCKER,M.K.	8510040619*	WASTE MGT	VALENZUELA,J.A.	8510020227	NURCG	VARGA,S.A.	8510310561	50-295 P
TUCKER,M.K.	8510040620*	WASTE MGT	VAN BRUNT,E.E.	8510010046	50-526 P	VARGA,S.A.	8510310595	50-295 P
TUCKER,M.K.	8510090100	WASTE MGT	VAN BRUNT,E.E.	8510010083	50-526 P	VASSALLO,D.B.	8510010012	50-333 P
TUCKER,M.K.	8510090104*	WASTE MGT	VAN BRUNT,E.E.	8510010123	50-526 P	VASSALLO,D.B.	8510030288	50-293 P
TUCKER,M.K.	8510090110*	WASTE MGT	VAN BRUNT,E.E.	8510010124	50-526 P	VASSALLO,D.B.	8510040429	50-220 P
TUCKER,M.K.	8510090116*	WASTE MGT	VAN BRUNT,E.E.	8510010323	50-526 F	VASSALLO,D.B.	8510070024	50-263 F
TUCKER,M.K.	8510090119*	WASTE MGT	VAN BRUNT,E.E.	8510010472	50-526 S	VASSALLO,D.B.	8510080026	50-254 F
TUCKER,M.K.	8510090126*	WASTE MGT	VAN BRUNT,E.E.	8510010593	50-529 S	VASSALLO,D.B.	8510150326	50-293 P
TUCKER,M.K.	8510090133*	WASTE MGT	VAN BRUNT,E.E.	8510010602	50-526 S	VASSALLO,D.B.	8510150328	50-259 P
TUCKER,M.K.	8510090202	WASTE MGT	VAN BRUNT,E.E.	8510010613	50-526 S	VASSALLO,D.B.	8510150334	50-271 P
TUCKER,M.K.	8510090207*	WASTE MGT	VAN BRUNT,E.E.	8510010651	50-526 R	VASSALLO,D.B.	8510160345*	50-331 P
TUCKER,M.K.	8510090210*	WASTE MGT	VAN BRUNT,E.E.	8510020009	50-526 E	VASSALLO,D.B.	8510170170*	50-263 P
TUCKER,M.K.	8510090213*	WASTE MGT	VAN BRUNT,E.E.	8510020061	50-526 P	VASSALLO,D.B.	8510170253*	50-293 P
TUCKER,M.K.	8510090276	WASTE MGT	VAN BRUNT,E.E.	8510020083	50-526 S	VASSALLO,D.B.	8510170793	50-325 Q
TUCKER,M.K.	8510090279*	WASTE MGT	VAN BRUNT,E.E.	8510020181	50-526 P	VASSALLO,D.B.	8510170361*	50-263 P
TUCKER,M.K.	8510090284*	WASTE MGT	VAN BRUNT,E.E.	8510020190	50-526 P	VASSALLO,D.B.	8510220185	50-259 P
TUCKER,M.K.	8510090296*	WASTE MGT	VAN BRUNT,E.E.	8510020374	50-526 P	VASSALLO,D.B.	8510250610	50-271 P
TUCKER,M.K.	8510090299*	WASTE MGT	VAN BRUNT,E.E.	8510020380	50-526 P	VASSALLO,D.B.	8510280274	50-298 P
TUCKER,M.K.	8510090291*	WASTE MGT	VAN BRUNT,E.E.	8510020422	50-526 P	VASSALLO,D.B.	8510280361*	50-298 P
TUCKER,M.K.	8510090293*	WASTE MGT	VAN BRUNT,E.E.	8510020504	50-526 S	VASSALLO,D.B.	8510290423	50-324 P
TUCKER,M.K.	8510090349	WASTE MGT	VAN BRUNT,E.E.	8510070025	50-526 S	VASSALLO,J.V.	8510240058	50-334 Q
TUCKER,M.K.	8510090383	WASTE MGT	VAN BRUNT,E.E.	8510080185	50-526 P	VAUGHAN,C.M.	8510040319	REGGD
TUCKER,M.K.	8510090387*	WASTE MGT	VAN BRUNT,E.E.	8510080353	50-526 S	VAUGHAN,C.M.	8510110213	70-1113
TUCKER,M.K.	8510090373*	WASTE MGT	VAN BRUNT,E.E.	8510080492	50-526 P	VAUGHAN,C.M.	8510240380	70-1113
TUCKER,M.K.	8510090377*	WASTE MGT	VAN BRUNT,E.E.	8510080495	50-526 P	VAUGHAN,W.A.	8510180282	PR
TUCKER,M.K.	8510090379*	WASTE MGT	VAN BRUNT,E.E.	8510090419	50-526 S	VERMA,T.R.	8510240572	WASTE MGT
TUCKER,M.K.	8510090383*	WASTE MGT	VAN BRUNT,E.E.	8510090522	50-526 S	VERNER,J.	8510170019*	50-412 Q
TUCKER,M.K.	8510240086	WASTE MGT	VAN BRUNT,E.E.	8510150464	50-526 S	VERNETSON,W.G.	8510300070	50-83 P
TUCKER,M.K.	8510240092*	WASTE MGT	VAN BRUNT,E.E.	8510160036	50-526 P	VERRELL,D.M.	8510040505	50-324 Q
TUCKER,M.K.	8510240100*	WASTE MGT	VAN BRUNT,E.E.	8510160049	50-526 P	VERRELL,D.M.	8510040618	50-324 Q
TUCKER,M.K.	8510240110*	WASTE MGT	VAN BRUNT,E.E.	8510160113	50-526 P	VERRELL,D.M.	8510070460	50-324 Q
TUCKER,M.K.	8510240117*	WASTE MGT	VAN BRUNT,E.E.	8510170005	50-526 S	VERRELL,D.M.	8510080243	50-327 Q
TUCKER,M.K.	8510240119*	WASTE MGT	VAN BRUNT,E.E.	8510170107	50-526 P	VERRELL,D.M.	8510090329	50-400 Q
TUCKER,M.K.	8510240121*	WASTE MGT	VAN BRUNT,E.E.	8510180052	50-529 E	VERRELL,D.M.	8510160066	50-259 Q
TUCKER,M.K.	8510240134	WASTE MGT	VAN BRUNT,E.E.	8510180055	50-529 A	VERRELL,D.M.	8510180375	50-400 Q
TUCKER,M.K.	8510240150*	WASTE MGT	VAN BRUNT,E.E.	8510180335	50-526 F	VERRELL,D.M.	8510180431	50-261 Q
TUCKER,M.K.	8510240155*	WASTE MGT	VAN BRUNT,E.E.	8510210116	50-526 P	VERRELL,D.M.	8510180449	50-400 Q
TUCKER,M.K.	8510240159*	WASTE MGT	VAN BRUNT,E.E.	8510210133	50-526 P	VERRELL,D.M.	8510180466	50-390 Q
TUCKER,M.K.	8510240163*	WASTE MGT	VAN BRUNT,E.E.	8510210136*	50-526 P	VERRELL,D.M.	8510210260	50-259 F
TUCKER,M.K.	8510240513	WASTE MGT	VAN BRUNT,E.E.	8510210137*	50-526 P	VERRELL,D.M.	8510220006	50-390 V
TUCKER,M.K.	8510240520*	WASTE MGT	VAN BRUNT,E.E.	8510220135	50-526 P	VERRELL,D.M.	8510220107	50-261 Q
TUCKER,M.K.	8510240529*	WASTE MGT	VAN BRUNT,E.E.	8510220146	50-526 K	VERRELL,D.M.	8510220404	50-261 Q
TUCKER,M.K.	8510240537*	WASTE MGT	VAN BRUNT,E.E.	8510220246	50-526 P	VERRELL,D.M.	8510040578	NURCG
TUCKER,M.K.	8510240583	WASTE MGT	VAN BRUNT,E.E.	8510220325	50-529 A	VIETH,D.L.	8510090239	WASTE MGT
TUCKER,M.K.	8510240595*	WASTE MGT	VAN BRUNT,E.E.	8510220380	50-526 S	VIETH,D.L.	8510240118	WASTE MGT
TUCKER,M.K.	8510240605*	WASTE MGT	VAN BRUNT,E.E.	8510220452	50-526 S	VIETTI-COOK,A.	8510030252	50-445 A
TUCKER,M.K.	8510240613*	WASTE MGT	VAN BRUNT,E.E.	8510220474	50-526 S	VIETTI-COOK,A.	8510170337	50-445 E
TUCKER,M.K.	8510240621*	WASTE MGT	VAN BRUNT,E.E.	8510240055	50-526 S	VIETTI-COOK,A.	8510220440	50-445 Q
TUCKER,M.K.	8510240626*	WASTE MGT	VAN BRUNT,E.E.	8510240083	50-526 R	VIETTI-COOK,A.	8510240070	50-445 T
TUCKER,M.K.	8510240639*	WASTE MGT	VAN BRUNT,E.E.	8510250181	50-526 F	VIROSTOK,C.	8510090132	40-1193
TUCKER,M.K.	8510240638*	WASTE MGT	VAN BRUNT,E.E.	8510250209	50-529 A	VISSING,G.S.	8510040053	TOPREP
TUCKER,M.K.	8510240643*	WASTE MGT	VAN BRUNT,E.E.	8510070190	50-526 S	VITO,D.	8510230163*	50-317 Q
TUCKMAN,M.S.	8510080165	50-289 F	VAN BRUNT,E.E.	8510310254	50-529 S	VITO,D.J.	8510160051*	50-352 Q
TUCKMAN,M.S.	8510210067	50-289 F	VAN CLEVE,J.E.	8510220095	71-9202	VITO,D.J.	8510160251*	50-272 Q
TUCKMAN,M.S.	8510210075	50-289 F	VAN DER HOVEN	8510010309*	40-8027	VITO,D.J.	8510220133*	50-334 Q
TURNER,C.L.	8510100035	50-461 J	VAN KESSEL,H.F.	8510250417*	50-423 Q	VOGT,D.K.	8510090056	WASTE RES
TYLER,T.G.	8510280518	50-445 G	VAN STAVAREN,D.	8510220334*	50-354 E	VOGT,J.F.	8510110126	71-5862
TYLINSKI,G.H.	8510300296	50-213 S	VAN SWERINGEN	8510040373	PR	VOGT,J.F.	8510110140*	71-5862
UDY,A.C.	8510280451*	50-282 F	VANDENBERG,D.	8510150438	50-255 R	VOGT,J.F.	8510090453*	FOIA
ULIE,J.M.	8510280368*	50-461 Q	VANDEBURGH,G.	8510220077*	50-454 Q	VOIN,R.	8510020275	TOPREP
ULLRICH,W.T.	8510010215	50-277 S	VANDENBURGH,D.	8510070190	50-213 P	VOLLMER,R.H.	8510160152*	FOIA
ULLRICH,W.T.	8510010906	50-352 S	VANDENBURGH,D.	8510070538*	50-213 P	VOLLMER,C.J.	8510210143	TOPREP
ULLRICH,W.T.	8510010818	50-277 S	VANDERBEEK,R.	8508230332*	50-387 P	VOLLMER,C.J.	8510210145*	TOPREP
ULLRICH,W.T.	8510010842	50-277 S	VANDERBEEK,R.	8510150484*	50-387 P	VON TUNGEN,P.	8510010464*	50-498 A
ULLRICH,W.T.	8510040078	50-278 S	VANDEWALLE,D.J.	8510040184	50-255 Q	VUMBACO,F.J.	8510160310*	40-872
ULLRICH,W.T.	8510040088*	50-277 S	VANKESSEL,H.F.	8510040335*	50-423 Q	VUMBACO,F.J.	8510160318*	40-872
ULLRICH,W.T.	8510070542	50-278 S	VANKESSEL,H.F.	8510070538*	50-423 Q	WAGNER,M.E.	8510110020	50-289 G
ULLRICH,W.T.	8510150241	50-352 S	VARELA,A.A.	8510220061*	50-412 Q	WAGNER,M.L.	8510160089	FOIA
ULLRICH,W.T.	8510150250	50-277 S	VARELA,A.A.	8510230196*	50-247 Q	WAHATH,B.D.	8510180118*	50-440 A
ULLRICH,W.T.	8510170407	50-352 S	VARGA,S.A.	8510040078*	50-261 P	WAHL,H.W.	8510180161*	50-329 A
ULLRICH,W.T.	8510170416	50-277 S	VARGA,S.A.	8510040444	50-305 P	WAHL,H.W.	8510180175*	50-129 A
ULLRICH,W.T.	8510280434	50-352 S	VARGA,S.A.	8510040522*	50-272 P	WAITE,R.S.	8510080350*	50-323 Q
ULLRICH,W.T.	8510300242	50-277 S	VARGA,S.A.	8510040537*	50-311 P	WAITE,R.S.	8510080359*	50-393 Q
ULLRICH,W.T.	8510300244	50-352 S	VARGA,S.A.	8510040544	50-247 P	WALENGA,C.G.	8510150228*	50-250 Q
ULLRICH,W.T.	8510300253	50-277 S	VARGA,S.A.	8510070027*	50-272 P	WALKER,D.I.	8508280127*	40-1366
ULLRICH,W.T.	8510310181	50-352 S	VARGA,S.A.	8510180274	50-261 P	WALKER,D.I.	8510150153*	40-1366
ULMER,F.J.	8510010801	50-344 R	VARGA,S.A.	8510300033	50-247 P	WALKER,D.I.	8510150158*	FOIA
URBAN,K.H.	8510220129	FOIA	VARGA,S.A.	8510310007	50-334 P	WALKER,D.I.	8510150183*	40-1366

372 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WALKER, D.I.	8510150189*	FOIA	WARRICK, R.F.	8510260354	50-461 Q	WESTERMAN, T.F.	8510280241*	50-445 Q
WALKER, D.I.	8510150176*	40-1366	WARRINER, R.S.	8510310095*	50-423 F	WESTERMAN, T.F.	8510280254*	50-445 Q
WALKER, D.I.	8510150201*	40-1366	WASHINGTON, M.	8510100139	NUREG	WESTERN, F.	8510160117*	FOIA
WALKER, D.I.	8510150220*	FOIA	WASILK, J.S.	8510280284	50-346 F	WESTERN, F.	8510160121*	FOIA
WALKER, D.I.	8510150226*	FOIA	WASTLER, S.L.	8510180042*	40-8714	WETTERHAHN, M.J.	8510210297	70-2948
WALKER, D.I.	8510150230*	FOIA	WATHEN, T.R.	8510240510	WASTE MGT	WETTERHAHN, M.J.	8510210297	70-2948
WALKER, D.I.	8510150235*	FOIA	WATSON, L.J.	8510070343*	50-327 Q	WHARTON, M.A.	8510070185*	50-206 F
WALKER, D.I.	8510150299*	40-1366	WATSON, R.A.	8510030047	50-400 Q	WHATLEY, S.K.	8510240133	WASTE RES
WALKER, D.I.	8510150335*	FOIA	WATSON, R.A.	8510070353	50-400 Q	WHATLEY, S.K.	8510240147	WASTE RES
WALKER, D.I.	8510150367*	40-1366	WATSON, R.A.	8510070369	50-400 Q	WHATLEY, S.K.	8510240344	WASTE RES
WALKER, D.I.	8510150378*	40-1366	WATSON, R.A.	8510310348	50-400 Q	WHEELER, G.L.	8510020254*	FOIA
WALKER, D.I.	8510150381*	40-1366	WATTS, J.P.	8510240521	71-9203	WHEELER, L.L.	8510150146*	50-267 Q
WALKER, D.I.	8510150386*	40-1366	WATZ, J.P.	8510170319	QA999	WHIPPLE, S.	8510010649	50-29 R
WALKER, D.I.	8510150402*	FOIA	WEADOCK, A.	8510280305*	50-54 Q	WHITCOMB, H.C.	8510180435*	50-261 Q
WALKER, D.I.	8510150404*	40-1366	WEADOCK, A.A.	8510080032*	50-244 Q	WHITE, G.A.	8510100118	PR
WALKER, D.I.	8510150406*	FOIA	WEAKLEY, S.A.	8510030435	NUREG	WHITE, J.C.	8510010164*	40-8027
WALKER, D.I.	8510150407*	FOIA	WEBB, R.E.	8510090031	50-346 S	WHITE, J.R.	8510080037*	50-244 Q
WALKER, D.I.	8510150417*	40-1366	WEBER, M.F.	8510230266	WASTE MGT	WHITE, P.	8510240378	50-311 R
WALKER, D.I.	8510150423*	FOIA	WEBER, M.F.	8510280506	WASTE MGT	WHITE, P.	8510240386	50-272 R
WALKER, H.A.	8510210186*	50-315 Q	WECHSELBERGER	8510170153*	50-219 Q	WHITNEY, J.	8510090044	FOIA
WALKER, R.D.	8510020270	50-327 Q	WECHSELBERGER	8510250171*	50-219 Q	WHITNEY, J.E.	8510150146*	50-267 Q
WALKER, R.D.	8510020351	50-327 Q	WEEKS, E.D.	8510010414	50-133 R	WHITT, K.W.	8510220374	50-259 P
WALKER, R.D.	8510040118	50-327 Q	WEEKS, E.D.	8510030271	50-133 P	WHITTEMORE, J.	8510020499	50-382 E
WALKER, R.D.	8510040146	50-390 Q	WEGST, W.F.	8510020197	50-142 P	WHITTEMORE, J.	8510030320	50-382 E
WALKER, R.D.	8510040493	50-424 Q	WEGST, W.F.	8510150219	50-142 P	WHITTEMORE, J.	8510030323	50-382 E
WALKER, R.D.	8510040622	50-390 A	WEIDLER, R.R.	8510300230*	50-389 P	WHITTEMORE, J.E.	8510220253*	50-382 P
WALKER, R.D.	8510070037	50-259 Q	WEIL, C.H.	8510010075*	FOIA	WHITTIER, G.D.	8510010637	50-309 R
WALKER, R.D.	8510070063	50-302 Q	WEISE, S.P.	8510070343*	50-327 Q	WHITTIER, G.D.	8510030095	50-309 Q
WALKER, R.D.	8510070069	50-280 Q	WEISS, A.J.	8510170230	NUREG	WHITTIER, G.D.	8510080179	50-309 Q
WALKER, R.D.	8510070326	50-327 Q	WEISS, D.	8510150123*	70-371	WHITTIER, G.D.	8510080417	50-309 S
WALKER, R.D.	8510070375	50-424 Q	WEISS, D.	8510210303*	70-687	WHITTIER, G.D.	8510150387	50-309 P
WALKER, R.D.	8510070492	50-369 Q	WEISS, R.R.	8510150347	50-289 G	WHITTIER, G.D.	8510170061	50-309 F
WALKER, R.D.	8510070495	50-289 Q	WEISS, R.R.	8510150347	50-289 G	WHITTIER, G.D.	8510240301	50-309 P
WALKER, R.D.	8510080043	50-83 F	WELLS, C.E.	8510150391	50-346 F	WHITTIER, G.D.	8510240418	50-309 V
WALKER, R.D.	8510080532	50-416 Q	WELLS, C.E.	8510280317	50-346 F	WHITTIER, G.D.	8510240640	50-309 S
WALKER, R.D.	8510180268	50-369 Q	WELLS, J.R.	8510080478*	50-445 Q	WHITTIER, G.D.	8510280369	50-309 Q
WALKER, R.D.	8510180208	50-160 Q	WELLS, R.W.	8510070291	TOPREP	WICKERS, D.L.	8510170191	40-8502
WALKER, R.D.	8510180342	50-348 Q	WELLS, R.W.	8510070291	TOPREP	WICK, E.A.	8510230316	WASTE RES
WALKER, R.D.	8510180367	50-259 Q	WELLS, R.W.	8510180283	NUREG	WIDAY, J.A.	8510240644	50-244 S
WALKER, R.D.	8510180389	50-400 Q	WELLS, R.W.	8510160283	NUREG	WIEBE, J.S.	8510100051*	50-331 Q
WALKER, R.D.	8510180373	50-321 Q	WEN, P.C.	8510230143*	50-336 Q	WIEDER, A.V.	8510300151*	50-528 Q
WALKER, R.D.	8510180378	50-321 Q	WENCZEL, V.	8510230143*	50-382 E	WIESEMANN, R.A.	8510090147*	TOPREP
WALKER, R.D.	8510180445	50-416 Q	WENCZEL, V.	8510020345	50-382 E	WIESEMANN, R.A.	8510160137*	50-244 P
WALKER, R.D.	8510180447	50-416 Q	WENCZEL, V.L.	8510020188	50-382 E	WIESEMANN, R.A.	8510230155*	50-335 P
WALKER, R.D.	8510180518	50-261 F	WENGER, G.	8510310399*	50-456 T	WIESEMANN, R.A.	8510290412*	TOPREP
WALKER, R.D.	8510180540	50-280 P	WENNER, R.	8510160078	50-226 Q	WIGGINS, E.	8510010240*	CONTRACT
WALKER, R.D.	8510180541	50-414 A	WENNER, T.J.	8510090042*	50-265 Q	WIGGINS, E.	8510050434*	CONTRACT
WALKER, R.D.	8510180543	50-250 Q	WENSLAWSKI, F.A.	8510030285	50-275 Q	WIGGINS, E.	8510040564*	CONTRACT
WALKER, R.D.	8510210265	50-390 Q	WENSLAWSKI, F.A.	8510070240	50-528 F	WIGGINS, E.	8510070129*	CONTRACT
WALKER, R.D.	8510220219	50-302 Q	WENSLAWSKI, F.A.	8510070524	50-275 R	WIGGINS, E.	8510080010*	CONTRACT
WALKER, R.D.	8510220394	50-324 Q	WENSLAWSKI, F.A.	8510150461	50-133 Q	WIGGINS, E.	8510150036*	CONTRACT
WALKER, R.D.	8510210612	50-330 T	WENZINGER, E.C.	8510200242	50-293 Q	WIGGINS, E.	8510210200*	CONTRACT
WALLACE, P.R.	8510010617	50-327 S	WENZINGER, E.C.	8510070159	50-412 Q	WIGGINS, E.	8510210204*	CONTRACT
WALLACE, P.R.	8510020108	50-327 R	WENZINGER, E.C.	8510080121*	50-309 Q	WIGGINS, E.	8510240036*	CONTRACT
WALLACE, P.R.	8510020220	50-327 S	WENZINGER, E.C.	8510080602	50-184 Q	WIGGINS, E.	8510250213*	CONTRACT
WALLACE, P.R.	8510030355	50-327 S	WENZINGER, E.C.	8510110110	50-317 Q	WIGGINS, E.	8510250225*	CONTRACT
WALLACE, P.R.	8510040102	50-327 S	WENZINGER, E.C.	8510220277	50-293 Q	WIGGINS, E.	8510280204*	CONTRACT
WALLACE, P.R.	8510150455	50-327 S	WENZINGER, E.C.	8510230190	50-97 Q	WIGGINS, J.T.	8510010185*	50-443 Q
WALLACE, T.J.	8510240400	50-223 P	WENZINGER, E.C.	8510250062	50-57 Q	WIGGINS, J.T.	8510020050*	50-277 Q
WALLO, A.	8510040578	NUREG	WENZINGER, E.C.	8510250420	50-317 Q	WIGGINS, J.T.	8510030053*	50-309 Q
WALTON, G.A.	8510070166*	50-412 Q	WEST, C.P.	8510100058	PR	WIGGINS, J.T.	8510080189*	50-286 Q
WALZ, V.M.	8510280151	50-333 S	WEST, R.C.	8510080583*	50-458 S	WIGGINS, J.T.	8510220061*	50-412 Q
WANG, J.C.	8510160308*	40-872	WESTAFER, G.R.	8510010100	50-302 P	WIGGINS, J.T.	8510230196*	50-247 Q
WARD, D.A.	8509030391	ACRS	WESTAFER, G.R.	8510010640	50-302 S	WILBOURN, G.H.	8510020108	50-327 R
WARD, D.A.	8510250408	ACRS	WESTAFER, G.R.	8510020193	50-302 S	WILBUR, L.C.	8510230152	50-134 P
WARD, D.A.	8510250450	ACRS	WESTAFER, G.R.	8510040171	50-302 P	WILCOX, J.G.	8510230044	40-8027
WARD, D.A.	8510250451	ACRS	WESTAFER, G.R.	8510040257	50-302 P	WILGUS, W.S.	8510070320	50-302 Q
WARD, D.A.	8510250491	ACRS	WESTAFER, G.R.	8510150147	50-302 P	WILGUS, W.S.	8510070372	50-302 Q
WARD, D.A.	8510250502	ACRS	WESTAFER, G.R.	8510150353	50-302 R	WILGUS, W.S.	8510310191	50-302 P
WARD, G.N.	8510230001	TOPREP	WESTAFER, G.R.	8510160085	50-302 P	WILGUS, W.S.	8510310197*	50-302 P
WARD, K.D.	8510280386*	50-306 Q	WESTAFER, G.R.	8510170055	50-302 P	WILLIAMS, C.C.	8510010112*	50-282 Q
WARD, K.D.	8510290066*	50-155 Q	WESTAFER, G.R.	8510180211	NUREG	WILLIAMS, C.C.	8510080610*	50-440 Q
WAREMBOURG, D.W.	8510090201	50-267 P	WESTAFER, G.R.	8510210077	50-302 P	WILLIAMS, C.C.	8510110038*	50-456 U
WAREMBOURG, D.W.	8510090280*	50-267 P	WESTAFER, J.R.	8510310534	50-302 F	WILLIAMS, C.C.	8510170309*	50-440 Q
WAREMBOURG, D.W.	8510090353	50-267 P	WESTBERG, R.	8510010630	50-382 E	WILLIAMS, C.C.	8510220013*	50-440 Q
WAREMBOURG, D.W.	8510170117	50-267 P	WESTBERG, R.	8510020156	50-382 E	WILLIAMS, C.C.	8510280142*	50-440 Q
WAREMBOURG, D.W.	8510310566	50-267 F	WESTBERG, R.	8510020206	50-382 E	WILLIAMS, C.C.	8510280394*	50-481 Q
WARNER, D.L.	8510010289*	40-8027	WESTBERG, R.	8510020328	50-382 E	WILLIAMS, C.C.	8510290336*	50-440 Q
WARNER, D.L.	8510010322*	FOIA	WESTBERG, R.	8510020332	50-382 E	WILLIAMS, D.	8510100047*	50-400 Q
WARNER, D.L.	8510010349*	40-8027	WESTBERG, R.	8510020465	50-382 E	WILLIAMS, D.	8510100047*	50-400 Q
WARNER, D.L.	8510010398*	40-8027	WESTBERG, R.	8510020495	50-382 E	WILLIAMS, D.M.	8510150210	50-389 S
WARRICK, R.F.	FW07130317*	50-346 Q	WESTBERG, R.	8510030008	50-382 E	WILLIAMS, F.J.	8510150087	71-9202
WARRICK, R.F.	8510010409	50-456 Q	WESTBERG, R.A.	8510220299*	50-400 Q	WILLIAMS, J.	8510010086	50-346 P
WARRICK, R.F.	8510180018	50-440 Q	WESTBURG, R.	8510020381	50-382 E	WILLIAMS, J.	8510010196	50-346 P
WARRICK, R.F.	8510210011	50-454 Q	WESTBURG, R.	8510020386	50-382 E	WILLIAMS, J.	8510010331	50-346 F
WARRICK, R.F.	8510210012*	50-454 Q	WESTERMAN, T.F.	8510220456*	50-445 Q	WILLIAMS, J.	8510040285	50-346 P
WARRICK, R.F.	8510210081	50-440 Q	WESTERMAN, T.F.	8510230115*	50-446 Q	WILLIAMS, J.	8510080035	50-346 P
WARRICK, R.F.	8510220238	50-440 Q	WESTERMAN, T.F.	8510280229*	50-445 Q	WILLIAMS, J.	8510090009	50-346 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WILLIAMS, J.	8510110143	50-346 S	WILLIS, W. F.	8510280331	50-259 P	WITHERS, B. D.	8510030112*	50-344 P
WILLIAMS, J.	8510160085	50-346 P	WILSON, B. A.	8510030298*	50-269 Q	WITHERS, B. D.	8510080041	50-344 Q
WILLIAMS, J.	8510160112	50-346 Q	WILSON, B. A.	8510180133*	50-413 Q	WITHERS, B. D.	8510080095	50-344 F
WILLIAMS, J.	8510160203	50-346 P	WILSON, B. D.	8510310072*	XPORTLIC	WITHERS, B. D.	8510080188	50-344 Q
WILLIAMS, J.	8510160209	50-346 P	WILSON, C. C.	8510020393	50-382 E	WITHERS, B. D.	8510150192	50-344 P
WILLIAMS, J.	8510220036	50-346 P	WILSON, D. L.	8510070286	50-331 F	WITHERS, B. D.	8510160053	50-344 P
WILLIAMS, J.	8510220368	50-346 S	WILSON, J. H.	8510010430*	50-382 Q	WITHERS, B. D.	8510160060*	50-344 P
WILLIAMS, J.	8510230013	50-346 S	WILSON, J. H.	8510090463	50-382 P	WITHERS, B. D.	8510160299	50-344 P
WILLIAMS, J.	8510230025	50-346 P	WILSON, J. H.	8510210274	50-382 Q	WITHERS, B. D.	8510220151	50-344 P
WILLIAMS, J.	8510230117	50-346 P	WILSON, J. T.	8510080055*	50-329 A	WITHERS, B. D.	8510280342	50-344 Q
WILLIAMS, J.	8510230120*	50-346 P	WILSON, R.	8510090454*	COMMISSION	WITHERS, B. D.	8510290169	50-344 P
WILLIAMS, J.	8510240023	50-346 R	WILSON, R. F.	8510010209	50-219 P	WITHERS, E. D.	8510310228	50-344 Q
WILLIAMS, J.	8510250371	50-346 Q	WILSON, R. F.	8510110214	50-219 P	WITT, F. J.	8510170385	TOPREP
WILLIAMS, J.	8510280343	50-346 P	WILSON, R. F.	8510150398	50-289 P	WITTMAN, J.	8510280086	WASTE MGT
WILLIAMS, J.	8510280406	50-346 F	WILSON, R. F.	8510250220	50-219 P	WITTMAN, R.	8510080423	50-302 F
WILLIAMS, J.	8510290217	50-346 P	WILSON, W. E.	8510080475*	50-27 Q	WOJNAROWSKI, J.	8510080445	50-237 P
WILLIAMS, J.	8510290357	50-346 S	WILSON, W. E.	8510150082*	50-27 Q	WOJNAROWSKI, J.	8510080452	50-237 P
WILLIAMS, J.	8510310234	50-346 F	WILSON, W. E.	8510150086*	50-27 Q	WOJNAROWSKI, J.	8510080466	50-249 P
WILLIAMS, J.	8510310313	50-346 Q	WIMPY, P. D.	8510170292*	50-316 P	WOJNAROWSKI, J.	8510080514	50-237 P
WILLIAMS, J. N.	8510240173	50-335 P	WINEGARDNER, W.	8510040377	NUREG	WOJNAROWSKI, J.	8510090037	50-265 Q
WILLIAMS, J. W.	8510010381	50-250 P	WINTER, G.	8510090314	WASTE RES	WOJNAROWSKI, J.	8510230049	50-237 F
WILLIAMS, J. W.	8510010477	50-250 R	WINTER, G.	8510240545	WASTE RES	WOJNAROWSKI, J.	8510010208	50-249 S
WILLIAMS, J. W.	8510040088	50-250 F	WINTER, G. V.	8510090260	WASTE RES	WOJNAROWSKI, J.	8510300304	50-249 S
WILLIAMS, J. W.	8510080333	50-250 S	WINTERS, R.	8510110019	50-412 Q	WOLF, R. A.	8510210273	70-734
WILLIAMS, J. W.	8510100108	50-335 Q	WINTZ, E.	8510170102*	FOIA	WOLFE, R.	8510010357*	50-382 P
WILLIAMS, J. W.	8510150324	50-250 F	WINTZ, E.	8510170146*	FOIA	WOLFE, S. J.	8510100016	50-443 G
WILLIAMS, J. W.	8510150385	50-335 F	WINTZ, E.	8510170186*	FOIA	WOLFE, S. J.	8510100031	50-443 G
WILLIAMS, J. W.	8510160023	50-250 F	WISEMAN, G. R.	8510020290*	50-302 Q	WOLFE, S. J.	8510180185	50-289 G
WILLIAMS, J. W.	8510170076	50-250 F	WISENBURG, M. R.	8510010463	50-498 A	WOLFE, S. J.	8510180258	50-320 G
WILLIAMS, J. W.	8510170091	50-250 P	WISENBURG, M. R.	8510030057	50-498 Q	WOLLETT, S.	8510040153	CONTRACT
WILLIAMS, J. W.	8510170104	50-250 S	WISENBURG, M. R.	8510080340	50-498 A	WOLLETT, S.	8510040595	CONTRACT
WILLIAMS, J. W.	8510180023	50-250 P	WISENBURG, M. R.	8510080427	50-498 F	WOLLETT, S.	8510080144	CONTRACT
WILLIAMS, J. W.	8510180034	NUREG	WISENBURG, M. R.	8510100021	50-498 M	WOOD, J.	8510160146	50-317 F
WILLIAMS, J. W.	8510180070	50-335 P	WISENBURG, M. R.	8510110223	50-498 A	WOODALL, D. M.	8510170197	50-252 F
WILLIAMS, J. W.	8510180081	50-2 P	WISENBURG, M. R.	8510150087	50-498 A	WOODARD, J. D.	8510010495	50-364 R
WILLIAMS, J. W.	8510180087	50-335 P	WISENBURG, M. R.	8510150207	50-498 A	WOODARD, J. D.	8510010635	50-348 R
WILLIAMS, J. W.	8510180178	50-335 Q	WISENBURG, M. R.	8510180027	50-498 A	WOODARD, J. D.	8510020001	50-348 S
WILLIAMS, J. W.	8510210046	50-250 Q	WISENBURG, M. R.	8510180040	50-498 A	WOODARD, J. D.	8510180276*	50-348 F
WILLIAMS, J. W.	8510230019	50-335 P	WISENBURG, M. R.	8510180041	50-498 A	WOODARD, J. D.	8510170401	50-348 S
WILLIAMS, J. W.	8510230078	50-250 P	WISENBURG, M. R.	8510180044	50-498 E	WOODARD, J. D.	8510220054	50-364 R
WILLIAMS, J. W.	8510230123	50-335 P	WISENBURG, M. R.	8510180046	50-498 E	WOODARD, J. D.	8510220101	50-346 R
WILLIAMS, J. W.	8510250386	50-250 F	WISENBURG, M. R.	8510180047	50-498 E	WOODARD, J. D.	8510300248	50-348 S
WILLIAMS, J. W.	8510280003	50-250 S	WISENBURG, M. R.	8510180064	50-498 E	WOODARD, J. D.	8510300307	50-348 S
WILLIAMS, J. W.	8510290307	50-335 P	WISENBURG, M. R.	8510180066	50-498 E	WOODARD, J. D.	8510300313	50-348 S
WILLIAMS, J. W.	8510290381	NUREG	WISENBURG, M. R.	8510180079	50-498 E	WOODHEAD, C. P.	8510040334	50-440 G
WILLIAMS, J. W.	8510310203	50-250 Q	WISENBURG, M. R.	8510180101	50-498 E	WOODHEAD, C. P.	8510150308	50-142 G
WILLIAMS, L. G.	8510100125	PR	WISENBURG, M. R.	8510180116	50-498 E	WOODHEAD, C. P.	8510290007	50-142 G
WILLIAMS, M.	8510180217*	50-482 R	WISENBURG, M. R.	8510180121	50-498 E	WOODHEAD, C. P.	8510310298	50-142 G
WILLIAMS, M.	8510180222*	50-482 R	WISENBURG, M. R.	8510180122	50-498 E	WOOLDRIDGE, R. A.	8510160219	50-445 G
WILLIAMS, M.	8510310071	50-482 R	WISENBURG, M. R.	8510180189	50-498 E	WOOLDRIDGE, R. A.	8510160224	50-445 G
WILLIAMS, M. G.	8510070009	50-482 S	WISENBURG, M. R.	8510180218	50-498 E	WOOLDRIDGE, R. A.	8510180348	50-445 G
WILLIAMS, M. G.	8510090294	50-482 S	WISENBURG, M. R.	8510180241	50-498 E	WRENN, M. E.	8510250529	NUREG
WILLIAMS, M. G.	8510090372	50-482 S	WISENBURG, M. R.	8510180250	50-498 E	WRIGHT, C.	8510110255	40-8698
WILLIAMS, M. G.	8510210229	50-482 S	WISENBURG, M. R.	8510180262	50-498 E	WRIGHT, C. L.	8510080065	50-261 S
WILLIAMS, M. G.	8510210234	50-482 S	WISENBURG, M. R.	8510180269	50-498 E	WRIGHT, C. L.	8510090055	50-261 S
WILLIAMS, M. G.	8510240166	50-482 S	WISENBURG, M. R.	8510180331	50-498 E	WRIGHT, C. L.	8510180532	50-261 S
WILLIAMS, M. G.	8510310175	50-482 S	WISENBURG, M. R.	8510180333	50-498 E	WRIGHT, C. L.	8510300153	50-261 S
WILLIAMS, M. H.	8510220187*	FOIA	WISENBURG, M. R.	8510180345	50-498 E	WRIGHT, G.	8510010234	50-249 S
WILLIAMS, M. H.	8510220208*	50-445 A	WISENBURG, M. R.	8510180363	50-498 E	WRIGHT, G. C.	8510080518*	50-10 Q
WILLIAMS, N. H.	8510170222	50-445 Q	WISENBURG, M. R.	8510180368	50-498 E	WRIGHT, G. C.	8510090501*	50-373 Q
WILLIAMS, N. H.	8510170250	50-445 A	WISENBURG, M. R.	8510180386	50-498 E	WRIGHT, G. C.	8510250158*	50-254 Q
WILLIAMS, N. H.	8510170302	50-445 A	WISENBURG, M. R.	8510180418	50-498 E	WRIGHT, G. C.	8510250283*	50-373 Q
WILLIAMS, N. H.	8510210022	50-445 A	WISENBURG, M. R.	8510220132	50-498 A	WRIGHT, G. C.	8510290387*	50-341 Q
WILLIAMS, N. H.	8510210035	50-445 A	WISENBURG, M. R.	8510220179	50-498 A	WRIGHT, J. A.	8510010079*	50-361 P
WILLIAMS, N. H.	8510210076	50-445 A	WISENBURG, M. R.	8510220204	50-498 E	WURZ, E.	8510140480	50-454 S
WILLIAMS, P. A.	8510110200	PR	WISENBURG, M. R.	8510240442	50-498 E	YANDELL, L. A.	8510240543*	50-285 Q
WILLIAMS, R. A.	8510090155*	40-1193	WISENBURG, M. R.	8510240466	50-498 E	YANDELL, L. A.	8510280241*	50-445 Q
WILLIAMS, R. A.	8510090189*	40-1193	WISENBURG, M. R.	8510250128	50-498 E	YANG, L.	8510010480	50-382 E
WILLIAMS, R. A.	8510090178*	40-1193	WISENBURG, M. R.	8510250145	50-498 E	YANG, L.	8510010508	50-382 E
WILLIAMS, R. E.	8510080092*	CONTRACT	WISENBURG, M. R.	8510250258	50-498 E	YANG, L.	8510010513	50-382 E
WILLIAMS, R. E.	8510090021	WASTE RES	WISENBURG, M. R.	8510250295	50-498 E	YANG, L.	8510020011	50-382 E
WILLIAMS, R. E.	8510090274	WASTE RES	WISENBURG, M. R.	8510250304	50-498 E	YANG, L.	8510020123	50-382 E
WILLIAMS, R. E.	8510240266	WASTE RES	WISENBURG, M. R.	8510250356	50-498 E	YANG, L.	8510020178	50-382 E
WILLIAMS, R. L.	8510090446	WASTE MGT	WISENBURG, M. R.	8510250381	50-498 E	YANG, L.	8510020184	50-382 E
WILLIAMS, R. L.	8510240453	WASTE MGT	WISENBURG, M. R.	8510250404	50-498 E	YANG, L.	8510030176	50-382 E
WILLIAMS, R. L.	8510240622	WASTE MGT	WISENBURG, M. R.	8510250436	50-498 E	YANICHKO, S. E.	8510110246*	50-364 P
WILLIAMS, T. W.	8510070285	50-389 P	WISENBURG, M. R.	8510250453	50-498 A	YANOSY, P. L.	8510010369*	50-382 P
WILLIAMSEN, N.	8510100018*	50-266 Q	WISENBURG, M. R.	8510250469	50-498 E	YAPCHANYK, D.	8510310113	50-245 S
WILLIAMSEN, N.	8510180018	50-255 Q	WISENBURG, M. R.	8510250503	50-498 E	YAPCHANYK, D. J.	8510240415	50-245 S
WILLIAMSEN, N.	8510280359*	50-341 Q	WISENBURG, M. R.	8510280312	50-498 E	YAPCHANYK, D. J.	8510310502	50-245 S
WILLIAMSEN, N. R.	8510180234*	50-440 Q	WISENBURG, M. R.	8510280321	50-498 E	YARDUMIAN, J.	8510180171	PR
WILLIAMSON, D. W.	8510080578*	50-458 S	WISENBURG, M. R.	8510280333	50-498 E	YBARRONDO, L. J.	8510040472*	CONTRACT
WILLIAMSON, D. W.	8510080581*	50-458 S	WISENBURG, M. R.	8510280364	50-498 E	YIN, J. T.	8510080113*	50-330 Q
WILLIAMSON, D. W.	8510080591*	50-458 S	WISENBURG, M. R.	8510280383	50-498 E	YIN, J. T.	8510250137*	50-282 Q
WILLIAMSON, J. P.	8311290219*	50-346 S	WISENBURG, M. R.	8510280411	50-498 E	YIN, J. T.	8510250173*	50-346 Q
WILLIS, J. L.	8510180153	50-400 Q	WISENBURG, M. R.	8510280415	50-498 E	YIN, T. T.	8510280351*	50-454 Q
WILLIS, J. L.	8510310172	50-400 Q	WISSINK, R. G.	8510100094	PR	YOUNG, H. T.	8510250396	50-250 F
WILLIS, W. F.	8510150383	50-259 P	WITHERS, B. D.	8510030104	50-344 P	YOUNG, J.	8510290410	NUREG

374 PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
YOUNG, M.A.	8510160287	50-133	ZECH, G.G.	8510080412	QA999	ZUPKO, J. M.	8510240050	50-272
YOUNG, M.A.	8510180344	50-250	ZECH, G.G.	8510100114	QA999	ZUPKO, J. M.	8510240185	50-311
YOUNG, M.Y.	8510160266	TOPREP	ZECH, G.G.	8510100152	QA999	ZUPKO, J. M.	8510240387	50-311
YOUNG, T.	8510020230*	50-344	ZECH, G.G.	8510150012	50-344	ZUPKO, J. M.	8510240396	50-272
YOUNG, T.	8510170054*	50-361	ZECH, G.G.	8510150015*	50-344	ZUPKO, J. M.	8510290527	50-272
YOUNG, T.	8510170344*	50-397	ZECH, G.G.	8510170321	QA999	ZURAKOWSKI, P. R.	8510080258	I&E
YOUNG, T. E.	8510040592	50-282	ZECH, G.G.	8510180405	QA999	ZURAKOWSKI, P. R.	8510150345*	70-754
YOUNGBLOOD, B. J.	8510030372	50-423	ZECH, G.G.	8510210009	QA999	ZURFLUEH, E. G.	8510080028	MISC
YOUNGBLOOD, B. J.	8510040414	50-423	ZECH, G.G.	8510210023	QA999	ZWETZIG, G.	8510170054*	50-361
YOUNGBLOOD, B. J.	8510070491	50-483	ZECH, G.G.	8510210060	QA999	ZWOLINSKI, J. A.	8510080460	50-245
YOUNGBLOOD, B. J.	8510090109	50-454	ZECH, G.G.	8510210171	QA999	ZWOLINSKI, J. A.	8510020090	MISC
YOUNGBLOOD, B. J.	8510090115*	50-454	ZECH, G.G.	8510310243	50-254	ZWOLINSKI, J. A.	8510020253	50-155
YOUNGBLOOD, B. J.	8510110106	50-454	ZECH, G.G.	8510310274	QA999	ZWOLINSKI, J. A.	8510020256*	50-155
YOUNGBLOOD, B. J.	8510110170	50-423	ZECH, G.G.	8510310310	QA999	ZWOLINSKI, J. A.	8510030002	50-244
YOUNGBLOOD, B. J.	8510150023	50-483	ZENCAY, C. J.	8510230194*	50-387	ZWOLINSKI, J. A.	8510030083	50-237
YOUNGBLOOD, B. J.	8510150078	50-454	ZIBULSKY, H.	8510160016*	50-333	ZWOLINSKI, J. A.	8510030203	50-213
YOUNGBLOOD, B. J.	8510150182	50-456	ZIBULSKY, H.	8510220106*	50-244	ZWOLINSKI, J. A.	8510040260	50-29
YOUNGBLOOD, B. J.	8510150475	50-454	ZIBULSKY, H.	8510280388*	50-387	ZWOLINSKI, J. A.	8510040265*	50-29
YOUNGBLOOD, B. J.	8510170477	50-440	ZIMMERMAN, R.	8510150237	50-528	ZWOLINSKI, J. A.	8510040274	50-155
YOUNGBLOOD, B. J.	8510180135	50-423	ZIMMERMAN, R.	8510160213	50-528	ZWOLINSKI, J. A.	8510040277*	50-155
YOUNGBLOOD, B. J.	8510210168	50-423	ZIMMERMAN, R.	8510220075*	50-528	ZWOLINSKI, J. A.	8510080447	50-213
YOUNGBLOOD, B. J.	8510250004	50-423	ZIMMERMAN, S. R.	8510010041	50-400	ZWOLINSKI, J. A.	8510080449*	50-213
YOUNGBLOOD, B. J.	8510280008	50-440	ZIMMERMAN, S. R.	8510010204	50-400	ZWOLINSKI, J. A.	8510100143	50-219
YOUNGBLOOD, B. J.	8510280275	50-455	ZIMMERMAN, S. R.	8510010278	50-400	ZWOLINSKI, J. A.	8510100167	50-244
YOUNGBLOOD, B. J.	8510280421	50-423	ZIMMERMAN, S. R.	8510010302	50-400	ZWOLINSKI, J. A.	8510110008	50-237
YOUNGBLOOD, B. J.	8510290448	50-482	ZIMMERMAN, S. R.	8510010385	50-400	ZWOLINSKI, J. A.	8510110075	50-245
YOUNGBLOOD, B. J.	8510310046	50-423	ZIMMERMAN, S. R.	8510010419	50-400	ZWOLINSKI, J. A.	8510110100	50-409
YOUNGBLOOD, B. J.	8510310381	50-456	ZIMMERMAN, S. R.	8510010459	50-400	ZWOLINSKI, J. A.	8510110162	50-409
YOUNGBLOOD, B. J.	8510030296*	50-275	ZIMMERMAN, S. R.	8510070109	50-261	ZWOLINSKI, J. A.	8510110169*	50-409
YOUNGBLOOD, B. J.	8510090527*	50-397	ZIMMERMAN, S. R.	8510080433	50-400	ZWOLINSKI, J. A.	8510110333	50-29
YUHAS, G. P.	8510090530*	50-397	ZIMMERMAN, S. R.	8510150116	50-261	ZWOLINSKI, J. A.	8510150403	50-29
YUHAS, G. P.	8510150465*	50-133	ZIMMERMAN, S. R.	8510160050	50-325	ZWOLINSKI, J. A.	8510160296	50-155
YUHAS, G. P.	8510170304*	50-326	ZIMMERMAN, S. R.	8510180181	50-400	ZWOLINSKI, J. A.	8510180104	50-213
YUHAS, G. P.	8510170358*	50-70	ZIMMERMAN, S. R.	8510180348	50-261	ZWOLINSKI, J. A.	8510180109*	50-213
ZANOTTI, A.	8510040373	PR	ZIMMERMAN, S. R.	8510240337	50-261	ZWOLINSKI, J. A.	8510180315	50-206
ZAVADOSKI, R. W.	8510250448	50-321	ZIMMERMAN, S. R.	8510240385	50-261	ZWOLINSKI, J. A.	8510180318*	50-206
ZECH, G. G.	8510010090	50-280	ZINTL, W. G.	8510070179	50-206	ZWOLINSKI, J. A.	8510180365	50-213
ZECH, G. G.	8510010195	QA999	ZINTL, W. G.	8510310277	50-206	ZWOLINSKI, J. A.	8510180493	50-206
ZECH, G. G.	8510010267	QA999	ZITZER, P.	8510150349	50-352	ZWOLINSKI, J. A.	8510220190	50-213
ZECH, G. G.	8510010284	QA999	ZUPKO, J. M.	8510010608	50-311	ZWOLINSKI, J. A.	8510220195*	50-213
ZECH, G. G.	8510030023	QA999	ZUPKO, J. M.	8510080074	50-311	ZWOLINSKI, J. A.	8510250045	50-219
ZECH, G. G.	8510070285	QA999	ZUPKO, J. M.	8510080206	50-311	ZWOLINSKI, J. A.	8510250049*	50-219
ZECH, G. G.	8510070338	QA999	ZUPKO, J. M.	8510090185	50-272	ZWOLINSKI, J. A.	8510280201	50-213
ZECH, G. G.	8510080226	QA999	ZUPKO, J. M.	8510220119	50-272	ZWOLINSKI, J. A.	8510290360	50-155
						ZWOLINSKI, J. A.	8510310001	50-245
						ZWOLINSKI, J. A.	8510310385	50-219
						ZWOLINSKI, J. A.	8510310485	50-29
						ZWOLINSKI, J. A.	8510310493*	50-29

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-232 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
3M Co., Minnesota Mining & Manufacturing Co.	8510100094	PR	Alcaide, Henderson, O'Bannon & Kline	8510090019	FOIA
A A Engineering	8510080367*	50-329 T	Aiston, Miller & Gaines	8510170038*	FOIA
AMAX, Inc.	8510170031*	FOIA		8510170041*	FOIA
	8510170033*	FOIA	American College of Nuclear Physicians	8510170064*	FOIA
ARVIN/CALSPAN Advanced Technology Center	8510040603*	CONTRACT		8510100154	PR
ASEA Atom, Inc.	8510030130	50-245 P	American Council of Independent Laboratories, Inc.	8510040317	PR
ATCOR Engineered Systems, Inc.	8510030140*	50-245 P	American Electric Power Service Corp.	8510070086*	50-315 F
	8510090045	TOPREP	American Nuclear Corp.	8510090305	40-4492
	8510090081*	TOPREP		8510090306*	40-4492
AccuRay Corp.	8510100144	PR		8510090312	40-4492
Acousis Co.	8510230223*	50-400 T	American Nuclear Society	8510030192*	CONTRACT
Adolph Coors Co.	8510040394	PR	American Physical Society	8510090454*	COMMISSIO
Aeronic Systems, Inc.	8510100022	PR	American Psychiatric Association	8510290049*	50-400 T
Aerospace Corp.	8510040578	NUREG	Anaheim, CA	8510170101*	50-361 P
	8510090345	WASTE RES	Analysis & Computing	8510230214*	50-400 T
	8510240507	WASTE RES	Anefco, Inc.	8510090505	71-9192
Air and Water Pollution Patrol	8510250015	WASTE RES		8510150292	71-9192
	8510100106	50-352 G	Ann Riley & Associates	8510150395	71-9192
	8510100106	50-352 G		8510040564*	CONTRACT
	8510100202*	50-352 G	Anthony, R.L.	8510020155*	50-352 G
Alabama Power Co.	8510100202*	50-352 G		8510110017	50-352 G
	8509110513	50-348 R	Appalachian Coal Surveys	8510100206	PR
	8510010495	50-364 R	Appalachian Regional Hosp. Beckley, WV	8510180343	PR
	8510010635	50-348 R	Applied Soil Mechanics, Inc.	8510100172	PR
	8510020001	50-348 S	Argonne National Laboratory	8510040332	NUREG
	8510020081	50-313 S	Arizona Nuclear Power Project (formerly	8510010046	50-528 P
	8510030146	50-364 P	Arizona Public Service Co.)	8510010083	50-528 P
	8510030152*	50-364 P		8510010083	50-528 P
	8510040125	50-348 P		8510010083	50-528 P
	8510070349	50-348 Q		8510010123	50-528 P
	8510070349	50-348 Q		8510010124	50-528 P
	8510070490	50-348 Q		8510010124	50-528 P
	8510070490	50-348 Q		8510010124	50-528 P
	8510090036	50-348 F		8510010124	50-528 P
	8510090453*	FOIA		8510010323	50-528 F
	8510110210	50-364 P		8510010323	50-528 F
	8510110245*	50-364 P		8510010323	50-528 F
	8510150124	50-348 F		8510010472	50-528 S
	8510150124	50-348 F		8510010593	50-529 S
	8510150188	50-348 H		8510010593	50-529 S
	8510150188	50-348 H		8510010602	50-528 S
	8510150285	50-348 P		8510010602	50-528 S
	8510150285	50-348 P		8510010602	50-528 S
	8510160081	50-348 P		8510010613	50-528 S
	8510160081	50-348 P		8510010651	50-528 R
	8510160195*	50-348 R		8510020009	50-528 F
	8510160246	50-348 F		8510020009	50-528 F
	8510160246	50-348 F		8510020009	50-528 F
	8510160276*	50-348 F		8510020061	50-528 P
	8510160276*	50-348 F		8510020061	50-528 P
	8510170401	50-348 S		8510020061	50-528 P
	8510180134	50-348 P		8510020083	50-528 S
	8510180134	50-348 P		8510020181	50-528 P
	8510180334	50-348 Q		8510020181	50-528 P
	8510180359	50-348 Q		8510020181	50-528 P
	8510180359	50-348 Q		8510020190	50-528 P
	8510220054	50-364 R		8510020190	50-528 P
	8510220101	50-348 R		8510020374	50-528 P
	8510250236	50-348 F		8510020380	50-528 P
	8510250236	50-348 F		8510020380	50-528 P
	8510250428	50-348 F		8510020380	50-528 P
	8510280034	50-348 F		8510020422	50-528 P
	8510280294	50-348 V		8510020422	50-528 P
	8510280294	50-348 V		8510020422	50-528 P
	8510300248	50-348 S		8510020504	50-528 S
	8510300307	50-348 S		8510070025	50-528 S
	8510300313	50-348 S		8510080185	50-528 P

376 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510080185	50-528	Hosp., Ft. Bragg, NC	8510100131	PR
	8510080185	50-528	Association of Official Analytical Chemists	8510110211	PR
	8510080353	50-528	Atom Sciences, Inc.	8510040571*	CONTRACT
	8510080492	50-528	Atomic Energy of Canada, Ltd.	8510110211	PR
	8510080492	50-528	Atomic Industrial Forum	8510100010	PR
	8510080495	50-528	BEMW, Inc. (formerly Binder, Elster, Mendelson & Wheeler, Inc.)	8510220362	NUREG
	8510090419	50-528	Babcock & Wilcox Co.	8510210200*	CONTRACT
	8510090522	50-528		8510010352*	50-302
	8510110200	PR		8510020297	TOPREP
	8510150464	50-528		8510030006	70-27
	8510160036	50-528		8510030045	70-27
	8510160049	50-528		8510030060*	50-498
	8510160113	50-528		8510040289*	50-346
	8510160118*	50-528		8510070263	50-269
	8510160118*	50-528		8510080159*	CONTRACT
	8510170005	50-528		8510090155*	40-1193
	8510170107	50-528		8510090169*	40-1193
	8510170107	50-528		8510090178*	40-1193
	8510180052	50-529		8510090186*	40-1193
	8510180055	50-529		8510090197*	70-135
	8510180335	50-528		8510090205*	70-135
	8510210116	50-528		8510090217*	70-135
	8510210133	50-528		8510090225*	70-135
	8510210136*	50-528		8510090277*	70-135
	8510210137*	50-528		8510090280*	70-135
	8510220135	50-528		8510090282*	70-135
	8510220135	50-528		8510110068	70-364
	8510220135	50-528		8510110093	70-27
	8510220146	50-528		8510110098	70-364
	8510220146	50-528		8510110120	70-364
	8510220146	50-528		8510110233	71-135
	8510220246	50-528		8510110234*	71-135
	8510220325	50-529		8510150027	71-88
	8510220325	50-529		8510150028*	71-88
	8510220380	50-528		8510150030	70-824
	8510220452	50-528		8510150034	70-364
	8510220474	50-528		8510150037	71-230
	8510220474	50-528		8510150039*	71-230
	8510220474	50-528		8510150264	70-364
	8510240055	50-528		8510160140*	TOPREP
	8510240083	50-528		8510160300	TOPREP
	8510240083	50-528		8510180545	70-824
	8510240083	50-528		8510210277	70-364
	8510250181	50-528		8510220026	70-824
	8510250181	50-528		8510240521	71-9203
	8510250181	50-528		8510240524*	71-9203
	8510250188*	50-528		8510310326	TOPREP
	8510250188*	50-528		8510310411*	TOPREP
	8510250188*	50-528	Babcock & Wilcox Operating Plants Owners Group	8510160001	TOPREP
	8510250209	50-529		8510160137	TOPREP
	8510310163*	50-528		8510290073	50-346
	8510310168	50-528	Baltimore Gas & Electric Co.	8510070173	50-317
	8510310254	50-529		8510070173	50-317
	8510310254	50-529		8510070173	50-317
Arizona State Univ., Tempe, AZ	8510310370*	CONTRACT		8510070173	50-317
Arizona, State of	8510040193	STATE PRO		8510070193*	50-213
	8510250326	PR		8510080400	50-317
Arizona, Univ. of, Tucson, AZ	8510020036	WASTE RES		8510080400	50-317
	8510020041	WASTE RES		8510080418	50-317
	8510040129*	CONTRACT		8510080418	50-317
	8510040467	WASTE RES		8510080476	50-317
	8510090233	WASTE RES		8510080476	50-317
	8510090519	WASTE RES		8510080516	50-317
	8510240522	WASTE RES		8510080516	50-317
Arkansas Power & Light Co.	8510010479	50-313		8510080544	50-317
	8510010482	50-368		8510090038	50-317
	8510010645	50-368		8510110275	71-363
	8510070237	50-368		8510150498	50-317
	8510080356	50-313		8510150469*	50-317
	8510160066	50-313		8510150473*	50-317
	8510160066	50-313		8510160146	50-317
	8510160253	50-313		8510180056	50-317
	8510170034	50-313		8510210140	50-317
	8510170410*	50-313		8510210140	50-317
	8510180294	50-313		8510220089	50-317
	8510220046	50-313		8510220089	50-317
	8510220056	50-368		8510220268	50-317
	8510220120	50-313		8510220268	50-317
	8510220203	50-368		8510220307	50-317
	8510220332*	50-313		8510250414	50-317
	8510220332*	50-313		8510250429	50-317
	8510240328	50-313		8510250429	50-317
	8510250189	50-368		8510250474	50-317
	8510250421*	50-313		8510280339	50-317
Army, Dept. of	8510280218	50-368		8510310044	50-317
Army, Dept. of, Womack Army Community	8510180402*	FOIA	Basalt Waste Isolation Project	8510090158	WASTE MGT
	8510290342	PR	Basic Energy Technology Associates	8510220373*	50-346
			Battelle Memorial Institute, Columbus	8510020228	NUREG

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Laboratories	8510070078*	CONTRACT			8510240638*	WASTE MGT
	8510070089*	CONTRACT			8510240643*	WASTE MGT
Battelle Memorial Institute, Pacific Northwest Laboratories	8510010448*	50-382	F	Bethlehem Steel Corp. Bishop, Liberman, Cook, Purcell & Reynolds	8510100070 8510110212	PR 50-460
	8510020182	50-206	S		8510110228	50-445
	8510030435	NUREG			8510110228	50-445
	8510040347	NUREG			8510150355	50-445
	8510040360	NUREG			8510150355	50-445
	8510040377	NUREG			8510280514	50-445
	8510210172	71-173			8510290003	50-445
	8510250531	NUREG			8510310331	50-416
	8510290431*	50-424	F	Blandin Paper Co. Boston Edison Co.	8510160306 8510020208	PR 50-293
	8510300306	50-322	S		8510020209	50-293
	8510300314*	50-322	S		8510070029	50-293
	8510310568	50-445	S		8510070034	50-293
Battelle New England Marine Research Laboratory	8510310574*	50-445	S		8510070193*	50-213
Bear Creek Uranium Co.	8510070283*	50-219	R		8510080201	50-293
	8510090529	40-8452			8510080215*	50-293
	8510110111	40-8452			8510100112	50-293
	8510110123	40-8452			8510110149	50-293
	8510110132*	40-8452			8510150100	50-293
	8510170247	40-8452			8510150181	50-293
	8510180329	40-8452			8510180026	50-293
Bechtel Corp.	8510020294*	50-461	A		8510180523	50-293
	8510100040*	50-206	P		8510250232	50-293
	8510150077	40-8631			8510300004	50-293
	8510170092*	50-361	P		8510310240	50-293
	8510180161*	50-329	A		8510310450	50-293
	8510180175*	50-329	A		8510310453*	50-293
	8510180187	NUREG		Brigham & Womens Hosp., Boston, MA	8510110198	PR
	8510290344*	50-352	Q	Bristol Steel & Iron Works, Inc.	8510110055	71-9032
	8510290347*	50-352	Q	Brookhaven National Laboratory	8510010634	50-382
Bendix Field Engineering Corp.	8510040602*	WASTE MGT			8510020257	50-423
	8510040607*	WASTE MGT			8510040389	NUREG
	8510040615*	WASTE MGT			8510080608	WASTE RES
	8510040617*	WASTE MGT			8510080612*	WASTE RES
	8510040619*	WASTE MGT			8510080617*	WASTE RES
	8510040620*	WASTE MGT			8510150359*	50-440
	8510090104*	WASTE MGT		Brown & Root, Inc. (subs. of Halliburton Co.)	8510150451*	50-445
	8510090110*	WASTE MGT		Burns & Roe Co.	8510010332*	50-382
	8510090116*	WASTE MGT		Business & Professional People for the Public Interest	8510110221	50-456
	8510090119*	WASTE MGT			8510070291	TOPREP
	8510090126*	WASTE MGT		C-E Operating Plants Owners Group	8510160283	NUREG
	8510090133*	WASTE MGT			8510220370*	50-346
	8510090207*	WASTE MGT		CER Corp.	8510170222	50-445
	8510090210*	WASTE MGT		CYGNA Energy Services	8510170250	50-445
	8510090213*	WASTE MGT			8510170302	50-445
	8510090218*	WASTE MGT			8510210022	50-445
	8510090279*	WASTE MGT			8510210035	50-445
	8510090284*	WASTE MGT			8510210035	50-445
	8510090286*	WASTE MGT			8510210035	50-445
	8510090289*	WASTE MGT			8510210076	50-445
	8510090291*	WASTE MGT			8510210076	50-445
	8510090293*	WASTE MGT			8510210076	50-445
	8510090351*	WASTE MGT			8510220040*	50-346
	8510090352*	WASTE MGT			8510290046*	50-400
	8510090354*	WASTE MGT		California, State of	8510170097*	50-206
	8510090357*	WASTE MGT			8510210288	STATE PRO
	8510090358*	WASTE MGT			8510220390	50-346
	8510090360*	WASTE MGT		California, Univ. of, Berkeley, CA	8510020197	50-142
	8510090367*	WASTE MGT		California, Univ. of, Los Angeles, CA	8510020201*	50-142
	8510090373*	WASTE MGT			8510040422	NUREG
	8510090377*	WASTE MGT			8510150219	50-142
	8510090379*	WASTE MGT			8510220486	50-433
	8510090383*	WASTE MGT			8510310439	50-433
	8510240092*	WASTE MGT		California, Univ. of, Santa Barbara, CA	8510210026	50-424
	8510240100*	WASTE MGT		Campaign for Prosperous Georgia	8510210026	50-424
	8510240110*	WASTE MGT			8510210029	50-424
	8510240117*	WASTE MGT			8510210029	50-424
	8510240119*	WASTE MGT			8510210029	50-424
	8510240121*	WASTE MGT			8510170036*	FOIA
	8510240150*	WASTE MGT		Carborundum Co.	8510040373	PR
	8510240155*	WASTE MGT		Cardiovascular Consultants of Nevada, Las Vegas, NV	8510010041	50-400
	8510240159*	WASTE MGT		Carolina Power & Light Co.	8510010204	50-400
	8510240163*	WASTE MGT			8510010278	50-400
	8510240273*	WASTE MGT			8510010288*	50-400
	8510240276*	WASTE MGT			8510010302	50-400
	8510240283*	WASTE MGT			8510010385	50-400
	8510240520*	WASTE MGT			8510010419	50-400
	8510240529*	WASTE MGT			8510010459	50-400
	8510240537*	WASTE MGT			8510020066	50-325
	8510240595*	WASTE MGT			8510030047	50-400
	8510240605*	WASTE MGT			8510040338	50-324
	8510240613*	WASTE MGT			8510040391	50-324
	8510240621*	WASTE MGT			8510040540	50-325
	8510240626*	WASTE MGT			8510070189	50-261
	8510240630*	WASTE MGT			8510070341	50-261

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510070353	50-400	Q	Clintchem, Inc.	8510210302	70-687
	8510070355	50-324	Q		8510220129	FOIA
	8510070355	50-324	Q		8510310426*	70-687
	8510070369	50-400	Q	Citizens Association for Sound Energy	8510220293	50-445
	8510080065	50-261	S		8510280520	50-445
	8510080166	TOPREP			8510290022*	50-445
	8510080439	50-400	A		8510310276	50-445
	8510080529	50-325	S	Citizens Concerned About Nuclear Power, Inc.	8510030028	50-498
	8510080537	50-325	S		8510180296	50-498
	8510080561	TOPREP			8510180296	50-498
	8510090018	50-325	S		8510180389	50-498
	8510090027	50-324	S		8510180389	50-498
	8510090055	50-261	S		8510100146	PR
	8510090320	TOPREP		Clark County, NV	8510010038	50-440
	8510090342	50-324	S	Cleveland Electric Illuminating Co.		
	8510150109	50-261	P		8510010077	50-440
	8510150112*	50-261	P		8510010077	50-440
	8510150116	50-261	F		8510010276	50-440
	8510150277	50-261	P		8510010374	50-440
	8510160050	50-325	Q		8510010374	50-440
	8510160057	50-324	P		8510010465	50-440
	8510160057	50-324	P		8510010465	50-440
	8510160228	50-400	F		8510010478	50-440
	8510160321	50-324	R		8510030003	50-440
	8510160321	50-324	R		8510030003	50-440
	8510180153	50-400	Q		8510030067	50-440
	8510180181	50-400	E		8510030067	50-440
	8510180239	50-261	R		8510070348	50-440
	8510180242*	50-261	R		8510070348	50-440
	8510180246*	50-261	R		8510080019	50-440
	8510180265	50-261	P		8510080019	50-440
	8510180265	50-261	P		8510080399	50-440
	8510180308	50-400	G		8510080399	50-440
	8510180340	50-400	G		8510080406	50-440
	8510180348	50-261	Q		8510080446	50-440
	8510180350*	50-261	Q		8510080454	50-440
	8510180532	50-261	F		8510080454	50-440
	8510220248	50-261	F		8510080477	50-440
	8510230005	50-261	P		8510080477	50-440
	8510240235	50-400	G		8510080508	50-440
	8510240337	50-261	P		8510080508	50-440
	8510240385	50-261	F		8510090053	50-440
	8510240389*	50-261	F		8510090053	50-440
	8510240394	50-400	T		8510090062*	50-440
	8510240395	70-2997			8510090062*	50-440
	8510240671	50-400	G		8510100009	50-440
	8510250196	50-325	S		8510100009	50-440
	8510280077	50-325	S		8510110193	50-440
	8510280261	50-325	S		8510110193	50-440
	8510280440	50-325	S		8510150354	50-440
	8510290033	50-400	T		8510150354	50-440
	8510290035*	50-400	T		8510150366*	50-440
	8510290041*	50-400	T		8510150366*	50-440
	8510290046*	50-400	T		8510150366*	50-440
	8510290049*	50-400	T		8510150366*	50-440
	8510300014	50-324	P		8510160029	50-440
	8510300153	50-261	S		8510160029	50-440
	8510310065	50-324	S		8510160210	50-440
	8510310171	50-324	S		8510160210	50-440
	8510310171	50-324	Q		8510180082	50-440
	8510310171	50-324	Q		8510180082	50-440
	8510310171	50-324	Q		8510180115*	50-440
	8510310171	50-324	Q		8510180115*	50-440
	8510310171	50-324	Q		8510180215	50-440
	8510310171	50-324	Q		8510180215	50-440
	8510310171	50-324	Q		8510180215	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	8510310171	50-324	Q		8510180351	50-440
	851031					

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510310269	50-440		8510080490	50-373
	8510310550	50-440		8510080506	50-10
	8510310550	50-440		8510080514	50-237
Cleveland-Cliffs Iron Co.	8510090175	40-8714		8510080514	50-237
	8510110262	40-8714		8510080514	50-237
Coalition for Nuclear Power Plant Postponement	8510100102	PR		8510080514	50-237
Coalition for Responsible Energy Education	8510180203	NUREG		8510080514	50-237
Collins, V.P., MD	8510180349	PR		8510090002	50-373
Colorado State Univ., Ft. Collins, CO	8510010146	FOIA		8510090002	50-265
	8510010404*	40-8027		8510090364	50-454
	8510010408*	40-8027		8510090381	50-249
Combustion Engineering, Inc.	8510010257	TOPREP		8510090388	50-265
	8510150084	70-36		8510090450	50-304
	8510220213	TOPREP		8510100043	50-373
	8510220216*	TOPREP		8510100062	50-454
	8510220351	NUREG		8510100082	50-373
	8510240326	70-1100		8510100101	50-295
Comex Corp.	8510040064	50-382		8510100119*	50-373
Commerce, Dept. of, Natl. Oceanographic Atmospheric Administration	8510010309*	40-8027		8510110012	50-373
Committee to Bridge the Gap	8510100102	FR		8510110012	50-373
Commonwealth Edison Co.	8510010052	50-373		8510110036	50-10
	8510010052	50-373		8510110036	50-10
	8510010055*	50-373		8510110036	50-10
	8510010055*	50-373		8510110036	50-10
	8510010067	50-373		8510110036	50-10
	8510010111	50-454		8510110036	50-10
	8510010111	50-454		8510110036	50-10
	8510010155	50-295		8510110036	50-10
	8510010208	50-249		8510110036	50-10
	8510010428*	50-272		8510110036	50-10
	8510010428*	50-272		8510110036	50-10
	8510010428*	50-272		8510110036	50-10
	8510010434	50-454		8510110036	50-10
	8510010638	50-373		8510110052	50-456
	8510020004	50-373		8510110058*	50-10
	8510020370	50-456		8510110058*	50-10
	8510020370	50-456		8510110058*	50-10
	8510030335	50-454		8510110058*	50-10
	8510030375	50-454		8510110058*	50-10
	8510040142	50-237		8510110058*	50-10
	8510040191	50-254		8510110058*	50-10
	8510040246	50-454		8510110058*	50-10
	8510040301	50-454		8510110058*	50-10
	8510040301	50-454		8510110058*	50-10
	8510040301	50-454		8510110058*	50-10
	8510040303	50-456		8510110058*	50-10
	8510040303	50-456		8510110058*	50-10
	8510040329	50-456		8510110058*	50-10
	8510040329	50-456		8510110079	50-456
	8510040428	50-454		8510110079	50-456
	8510040432	50-454		8510110085	50-456
	8510040480	50-454		8510110085	50-456
	8510070317	50-373		8510110133	50-456
	8510070358	50-304		8510110133	50-456
	8510080036	50-374		8510110136*	50-456
	8510080148	50-295		8510110139*	50-456
	8510080171	50-373		8510110139*	50-456
	8510080174*	50-373		8510110142*	50-456
	8510080177	50-456		8510110148*	50-254
	8510080177	50-456		8510110266	50-254
	8510080222	50-373		8510150045	71-9089
	8510080269	50-373		8510150204	50-237
	8510080269	50-373		8510150204	50-237
	8510080375	50-254		8510150306	50-456
	8510080375	50-254		8510150306	50-456
	8510080404	50-374		8510150444	50-304
	8510080406	50-373		8510150499	50-295
	8510080430	50-454		8510160172	50-456
	8510080434*	50-454		8510160178	50-456
	8510080440	50-455		8510160204	50-454
	8510080440	50-455		8510160259*	50-295
	8510080445	50-217		8510170047	50-373
	8510080445	50-237		8510170094	50-254
	8510080452	50-237		8510170166	50-373
	8510080452	50-237		8510170308	50-373
	8510080452	50-237		8510170366	50-454
	8510080452	50-237		8510170374	50-454
	8510080452	50-237		8510170374	50-454
	8510080452*	50-237		8510170374	50-454
	8510080456*	50-237		8510170374	50-454
	8510080456*	50-237		8510170388	50-254
	8510080456*	50-237		8510170388	50-254
	8510080456*	50-237		8510180266	50-304
	8510080456*	50-237		8510180268	50-456
	8510080466	50-249		8510180268	50-456
	8510080484	50-373		8510180268	50-456
	8510080490	50-373		8510180338	50-456

380 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510180338	50-456		8510170440	50-213
	8510180339	50-454		8510220043	50-213
	8510180462	71-9089		8510220158	50-213
	8510180472	50-237		8510220158	50-213
	8510180522	50-295		8510220158	50-213
	8510210030	50-456		8510220158	50-213
	8510210030	50-456		8510220186	50-213
	8510210064	50-10		8510220186	50-213
	8510210064	50-10		8510220186	50-213
	8510210064	50-10		8510230131	50-213
	8510210064	50-10		8510240462	50-213
	8510210064	50-10		8510240635	50-213
	8510210064	50-10		8510250101	50-213
	8510210064	50-10		8510300296	50-213
	8510210064	50-10	Conner & Wetterhahn	8510030011	50-352
	8510210073*	50-10		8510180240	50-352
	8510210073*	50-10		8510210038	50-352
	8510210073*	50-10		8510210297	70-2948
	8510210073*	50-10		8510240279	50-352
	8510210073*	50-10	Conservation Council of North Carolina	8510180159	50-400
	8510210073*	50-10		8510040123	50-247
	8510210073*	50-10	Consolidated Edison Co. of New York, Inc	8510090299	50-247
	8510210073*	50-10		8510160220	50-247
	8510220009	50-265		8510160225	50-3
	8510220022	TOPREF		8510160249	50-247
	8510220098	NUREG		8510160251*	50-247
	8510220166	50-10		8510180039	50-247
	8510220183	NUREG		8510220118	50-247
	8510220250	50-373		8510220226	50-247
	8510220250	50-373		8510240585	50-3
	8510220271	50-455		8510240592*	50-3
	8510220271	50-455		8510240592*	50-3
	8510220291	50-456		8510250068	50-247
	8510220291	50-456		8510250178	50-247
	8510220304	50-295		8510250192	50-247
	8510220304	50-295		8510250239	50-247
	8510220308*	50-295		8510290071	50-247
	8510220308*	50-295		8510290196	50-247
	8510220348	50-456		8510290372	50-3
	8510220348	50-456		8510290622	50-247
	8510220364	50-456		8510290627*	50-247
	8510220364	50-456		8510290633*	50-247
	8510230036	50-373		8510300030	50-247
	8510230043*	50-373		8510010316	50-255
	8510230049	50-237	Consumers Power Co.	8510010319	50-155
	8510230053	50-373		8510010329*	50-155
	8510230055	70-304		8510010338*	50-155
	8510230056	50-455		8510010366	50-255
	8510230238	50-373		8510010370*	50-255
	8510230238	50-373		8510010407	50-255
	8510230242*	50-373		8510010491	50-155
	8510230242*	50-373		8510040177	50-155
	8510240057	50-295		8510040181*	50-155
	8510240174	50-249		8510040184	50-255
	8510240324	50-10		8510040187*	50-155
	8510240354	50-456		8510080037	50-329
	8510240354	50-456		8510080046	50-155
	8510240363*	50-456		8510080056	50-255
	8510240363*	50-456		8510080090	50-329
	8510250231	50-237		8510080117	50-255
	8510250231	50-237		8510080499	50-255
	8510250468	50-456		8510080556	50-155
	8510250468	50-456		8510150298	50-155
	8510280170	50-295		8510150303*	50-155
	8510280349	50-455		8510150323	50-255
	8510280349	50-455		8510150352	50-255
	8510280349	50-455		8510150380	50-255
	8510280349	50-455		8510150438	50-255
	8510300107	50-456		8510160202	50-255
	8510300279	50-249		8510160279	50-329
	8510300304	50-249		8510170016	50-255
	8510310133	50-249		8510180032	50-255
	8510310407	50-454		8510180235	50-255
	8510310545	50-304		8510180380	50-155
Community Hosp. of Roanoke Valley	8510110178	PR		8510210071	50-255
Roanoke, VA				8510210079	50-155
Consip, Inc.	8510020245*	50-321		8510210294	50-255
Concerned Citizens of Louisa County	8510220240	50-338		8510220090	50-329
	8510220240	50-338		8510220253	50-255
	8510220264	50-338		8510220256	50-155
	8510220264	50-338		8510220258*	50-255
Connecticut Yankee Atomic Power Co.	8510010006	50-213		8510220261*	50-255
	8510090248	50-213		8510220408	50-329
	8510100004	50-213		8510220408	50-329
	8510150247	50-213		8510220411	50-329
	8510150284	50-213		8510220411	50-329
	8510150284	50-213		8510230132	50-329
	8510150346	50-213		8510240067	50-255
	8510170098	50-213		8510240074*	50-255

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510250134	50-255	P		8503200025	50-269	P
	8510250251	50-255	F		8503200025	50-269	P
	8510250444	50-255	P		8503200025	50-269	P
	8510250449*	50-255	P		8503200025	50-269	P
	8510290145	50-155	P		8503200025	50-269	P
	8510290145	50-155	P		8503200025	50-269	P
	8510290145	50-155	P		8510010106	50-413	S
	8510290152*	50-155	P		8510010231	50-269	S
	8510290152*	50-155	P		8510010259	50-269	P
	8510290152*	50-155	P		8510010259	50-269	P
	8510290345	50-329	R		8510010259	50-269	P
	8510300002	50-255	F		8510010260	50-413	P
	8510300009	50-255	F		8510010262*	50-269	P
	8510300015	50-155	F		8510010262*	50-269	P
	8510300016	50-255	F		8510010262*	50-269	P
	8510300052	50-255	F		8510010389	50-369	P
	8510300094	50-255	F		8510010389	50-369	P
	8510300130	50-255	F		8510020158	50-413	P
	8510300131	50-255	F		8510020250	50-413	Q
	8510300183	50-255	F		8510040144	50-414	Q
CorSTAR Research, Inc.	8510090056	WASTE RES			8510040168*	50-414	Q
Cottler Corp.	8510100060	PR			8510040290	50-413	Q
Covington & Burling	8510100170	40-2061			8510040290	50-413	Q
	8510240355	40-2061			8510040542*	50-269	P
	8510310284	40-2061			8510040542*	50-269	P
	8510310336	40-8027			8510040542*	50-269	P
Creare, Inc.	8510310341	40-2061			8510040542*	50-269	P
	8510020217	NUREG			8510040542*	50-269	P
	8510020227	NUREG			8510040542*	50-269	P
	8510080325*	CONTRACT			8510040542*	50-269	P
Dairyland Power Cooperative	8510020094	50-409	R		8510040542*	50-269	P
	8510070274	50-409	P		8510070261	50-413	K
	8510070280*	50-409	P		8510070281	50-413	K
	8510070478	50-409	P		8510070290*	50-413	K
	8510070482*	50-409	P		8510070290*	50-413	K
	8510070560	50-409	R		8510070437	50-369	Q
	8510070562*	50-409	R		8510070437	50-369	Q
	8510150329	50-409	J		8510070466	50-269	Q
	8510230107	50-409	J		8510080165	50-269	F
	8510240266	50-409	K		8510080165	50-269	F
	8510240270*	50-409	K		8510080165	50-269	F
	8510250398	50-409	Q		8510080175	50-270	P
	8510310396	50-409	S		8510080335	50-269	F
	8510310423	50-409	S		8510080335	50-269	F
Dallas Morning News, Dallas, TX	8510010383	50-382	E		8510080335	50-269	F
Damon & Morey	8510160298	QA999			8510080359	50-369	P
Daniel & Associates, Inc.	8510080146*	50-320	P		8510080364*	50-369	P
Delaware, State of	8510250326	PR			8510080364*	50-369	P
Delmonte Corp.	8510180352	PR			8510090022	50-369	S
Democratic Women's Association of the	8510040312	NUREG			8510090466	50-413	S
Desert					8510090535	50-287	S
Denver, Univ. of, Denver, CO	8510160333*	CONTRACT			8510100155	50-269	P
Desert/Pass Action Group	8510040312	NUREG			8510100155	50-269	P
Detroit Edison Co.	8510010417	50-341	R		8510100155	50-269	P
	8510020160	50-341	S		8510150090	50-369	P
	8510020203	50-341	S		8510150090	50-369	P
	8510030001	50-341	P		8510150318	50-413	F
	8510030007*	50-341	P		8510150318	50-413	F
	8510030010	50-341	P		8510160017	50-269	Q
	8510070057	50-341	F		8510160278	50-269	P
	8510070325	50-341	Q		8510160278	50-269	P
	8510070329*	50-341	Q		8510160278	50-269	P
	8510070374	50-341	S		8510160294*	50-369	Q
	8510080473	50-341	Q		8510160294*	50-369	Q
	8510090083	50-341	S		8510160294*	50-369	Q
	8510090182	50-341	S		8510160300	50-413	P
	8510090376	50-341	S		8510160302*	50-413	P
	8510160071	50-341	P		8510170185	50-269	R
	8510160119	50-341	P		8510170259	50-369	S
	8510160123*	50-341	P		8510170311	50-413	P
	8510220243	50-341	F		8510180108	50-413	P
	8510240004	50-341	S		8510180271	50-413	F
	8510250289	50-341	S		8510210067	50-269	F
	8510260071	50-341	S		8510210067	50-269	F
	8510290067	50-341	S		8510210067	50-269	F
	8510310015	50-341	S		8510210074	50-269	P
	8510310057	50-341	S		8510210074	50-269	P
	8510310404	50-341	S		8510210074	50-269	P
Doc-Search Associates	8510090084	FOIA			8510210075	50-269	F
	8510180155	FOIA			8510210075	50-269	F
Doherty, J.F.	8510100130	PR			8510210075	50-269	F
	8510100151*	PR			8510210267	50-413	R
Donna L. Wickers	8510170191	40-8502			8510210285	50-369	R
Dougherty, J.B.	8510220240	50-338	G		8510210285	50-369	R
	8510220314	50-322	G		8510220094	50-269	R
Dow Chemical Co.	8510170234*	50-264	Q		8510220094	50-269	R
Dresser Industries, Inc.	8510170319	QA999			8510220094	50-269	R
Duke Power Co.	8503200025	50-269	P		8510220263	50-413	F
	8503200025	50-269	P		8510220280	50-413	F

382 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510220355	50-413		8510160314	TOPREP
	8510220355	50-413		8510160315*	TOPREP
	8510220425	FOIA		8510180366	PR
	8510230050	50-413	Empire Steel Castings, Inc.	8510010450*	FOIA
	8510230059	50-413	Employment Perspectives	8510040597	WASTE MGT
			Energy, Dept. of		
	8510230064*	50-413		8510040602*	WASTE MGT
	8510230070	50-369		8510040607*	WASTE MGT
	8510230070	50-369		8510040615*	WASTE MGT
	8510230153	50-369		8510040617*	WASTE MGT
	8510230153	50-369		8510040619*	WASTE MGT
	8510230157*	50-369		8510040620*	WASTE MGT
	8510230157*	50-369		8510080273	WASTE MGT
	8510250116	50-413		8510090100	WASTE MGT
	8510250197	50-413		8510090104*	WASTE MGT
	8510250218	50-369		8510090110*	WASTE MGT
	8510280397	50-369		8510090116*	WASTE MGT
	8510290382	50-269		8510090119*	WASTE MGT
	8510290464	50-369		8510090126*	WASTE MGT
	8510300190	50-414		8510090133*	WASTE MGT
	8510300196*	50-414		8510090142	WASTE MGT
	8510300209	50-369		8510090151	WASTE MGT
	8510300221*	50-369		8510090152	WASTE MGT
	8510300221*	50-369		8510090202	WASTE MGT
	8510300226*	50-369		8510090204	WASTE MGT
	8510300226*	50-369		8510090207*	WASTE MGT
	8510300230*	50-369		8510090210*	WASTE MGT
	8510300230*	50-369		8510090213*	WASTE MGT
	8510310039	50-369		8510090215*	WASTE MGT
	8510310248	50-269		8510090218*	WASTE MGT
Dupont, R.L., MD	8510290049*	50-400		8510090239	WASTE MGT
Duquesne Light Co.	8510010476	50-334		8510090276	WASTE MGT
	8510020105	50-334		8510090279*	WASTE MGT
	8510020239	50-334		8510090284*	WASTE MGT
	8510030417	50-412		8510090286*	WASTE MGT
	8510070255	50-412		8510090289*	WASTE MGT
	8510150221	50-334		8510090291*	WASTE MGT
	8510160185	50-412		8510090293*	WASTE MGT
	8510170452	50-334		8510090310	WASTE MGT
	8510180193	50-412		8510090323	WASTE MGT
	8510210104	50-412		8510090349	WASTE MGT
	8510220030	50-412		8510090363	WASTE MGT
	8510230009	50-334		8510090367*	WASTE MGT
	8510230011*	50-334		8510090373*	WASTE MGT
	8510240002	50-334		8510090377*	WASTE MGT
	8510240058	50-334		8510090379*	WASTE MGT
	8510240402	70-3008		8510090383*	WASTE MGT
	8510290050	50-334		8510090399	WASTE MGT
Duryea, Houchins, Murphy & Davenport	8510100121	PRM		8510090422	WASTE MGT
	8510100127*	PRM		8510090452*	WASTE MGT
Dynatrek, Inc.	8510080128*	CONTRACT		8510090489	WASTE MGT
E.C. Rodabaugh Associates, Inc.	8510030312	NUREG		8510090482*	WASTE MGT
E.I. du Pont de Nemours & Co., Inc.	8510150297	71-384		8510090538	WASTE MGT
EG&G Idaho, Inc. (subs. of EG&G, Inc.)	8508050540*	50-266		8510150287	71-5607
	8508230332*	50-387		8510180282	PR
	8509060182*	50-305		8510240053	WASTE MGT
	8510030411*	50-354		8510240086	WASTE MGT
	8510030430	NUREG		8510240092*	WASTE MGT
	8510030433	NUREG		8510240100*	WASTE MGT
	8510040397	NUREG		8510240110*	WASTE MGT
	8510040407	NUREG		8510240117*	WASTE MGT
	8510040411	NUREG		8510240118	WASTE MGT
	8510040592	50-282		8510240119*	WASTE MGT
	8510110116	71-5874		8510240121*	WASTE MGT
	8510150484*	50-387		8510240134	WASTE MGT
	8510270178*	50-445		8510240150*	WASTE MGT
	8510220252*	50-382		8510240155*	WASTE MGT
	8510280451*	50-282		8510240159*	WASTE MGT
	8510110230*	50-423		8510240163*	WASTE MGT
EOE, Inc.	8510240310*	50-309		8510240252	WASTE MGT
	8510310208*	50-423		8510240263	WASTE MGT
	8510010351*	50-382		8510240284	WASTE MGT
Ebasco Services, Inc. (subs. of Enserch Corp.)	8510020191*	50-335		8510240290*	WASTE MGT
	8510020194*	FOIA		8510240311	WASTE MGT
	8510020202*	50-382		8510240348	WASTE MGT
				8510240383	WASTE MGT
	8510020207*	50-382		8510240481	WASTE MGT
	8510020207*	50-382		8510240467*	WASTE MGT
	8510020211*	50-382		8510240471*	WASTE MGT
	8510020211*	50-382		8510240505	WASTE MGT
	8510020216*	FOIA		8510240513	WASTE MGT
	8510020229*	50-382		8510240514	WASTE MGT
	8510020236*	50-382		8510240520*	WASTE MGT
	8510220311*	50-498		8510240529*	WASTE MGT
Eddleman, W.	8510030009	50-400		8510240537*	WASTE MGT
	8510030082	50-400		8510240557	WASTE MGT
	8510100208	50-400		8510240581	WASTE MGT
	8510160159	50-400		8510240589	WASTE MGT
Electric Power Research Institute	8510010258*	CONTRACT		8510240583	WASTE MGT
	8510080159*	CONTRACT		8510240586	WASTE MGT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510240595*	WASTE MGT		851021025e	50-413 F
	8510240605*	WASTE MGT		8510210263	50-413 F
	8510240611*	WASTE MGT		8510210263	50-413 F
	8510240613*	WASTE MGT		8510230014	50-416 F
	8510240618*	WASTE MGT		8510230219	50-245 F
	8510240621*	WASTE MGT		8510230219	50-245 F
	8510240626*	WASTE MGT		8510230227*	50-400 T
	8510240630*	WASTE MGT		8510290351	50-322 F
	8510240638*	WASTE MGT		8510310399*	50-456 T
	8510240643*	WASTE MGT	Finley, Kumble, Wagner, Heine, Underberg	8510100168	PR
	8510250524	WASTE MGT	Manley & Casey		
	8510250527	WASTE MGT	Florida Power & Light Co.	8510010361	50-250 P
	8510280023	WASTE MGT		8510010477	50-250 R
	8510280056	WASTE MGT		8510040088	50-250 F
	8510280067	WASTE MGT		8510070265	50-389 P
	8510280078	WASTE MGT		8510080333	50-250 S
	8510280092	WASTE MGT		8510100108	50-335 Q
	8510280106	WASTE MGT		8510150210	50-389 S
	8510280110	WASTE MGT		8510150324	50-250 F
	8510280172	WASTE MGT		8510150324	50-250 F
	8510280176*	WASTE MGT		8510150324	50-250 F
	8510280437	WASTE MGT		8510150385	50-335 F
Energy, Dept. of, Idaho Operations Office	8510280442	WASTE MGT		8510150385	50-335 F
Energy, Inc.	8510220239*	50-382		8510160023	50-250 F
	8510030054*	50-424		8510160023	50-250 F
	8510290410	NUREG		8510170076	50-250 F
Engineering & Economics Research, Inc.	8510030162*	CONTRACT		8510170076	50-250 F
Engineering Science & Analysis	8510080015*	CONTRACT		8510170091	50-250 P
	8510110042	NUREG		8510170091	50-250 P
Engineers International, Inc.	8510080040	WASTE RES		8510170104	50-250 S
	8510090046*	WASTE RES		8510180023	50-250 P
	8510090347	WASTE RES		8510180034	NUREG
	8510090390	WASTE RES		8510180070	50-335 P
	8510090400	WASTE RES		8510180081	50-250 P
	8510090516	WASTE RES		8510180081	50-250 P
	8510110069	WASTE RES		8510180087	50-335 P
Envirocare, Inc.	8510240296	WASTE RES		8510180090*	50-335 P
	8510170088	FOIA		8510180096*	50-335 P
	8510170194*	FOIA		8510180178	50-335 Q
	8510170210*	FOIA		8510180178	50-335 Q
	8510170219*	FOIA		8510180214	50-250 G
Environmental Coalition on Nuclear Power	8510170220*	FOIA		8510180214	50-250 G
	8510240323*	50-320	G	8510180320	50-250 G
Environmental Protection Agency	8510240329*	50-320	G	8510180320	50-250 G
	8510010164*	40-8027		8510210046	50-250 Q
	8510010294*	40-8027		8510210058*	50-250 Q
	8510090464*	FOIA		8510230019	50-335 P
Environmental Task Force	8510100149	PR		8510230022*	50-335 P
Envirotronics	8510090057	FOIA		8510230078	50-250 P
	8510160303	FOIA		8510230123	50-335 P
	8510090335	XPORTLIC		8510240173	50-335 P
European Communities, Commission of	8510100008*	50-445	Q	8510250396	50-250 F
Evaluation Research Corp.	8510170447	40-8064		8510280003	50-250 S
Everest Minerals Corp.	8510170453*	40-8064		8510290307	50-335 P
Expert-EASE Systems, Inc.	8510090439*	CONTRACT		8510290314*	50-335 P
	8510170413*	40-8102		8510290381	NUREG
Exxon Corp.	8510180487	40-8102		8510310203	50-250 Q
	8510180490*	40-8102		8510310203	50-250 Q
	8510180492*	40-8102		8510310281	50-250 G
Exxon Nuclear Co., Inc. (subs. of Exxon	8510030072	TOPREP		8510310281	50-250 G
Corp.)	8510030119*	XPORTLIC		8510310365	50-250 G
	8510070200	50-31F	P	8510310365	50-250 G
	8510080252*	70-305	P	8510310434	50-250 G
	8510080301*	50-315	P	8510310434	50-250 G
	8510080301*	50-315	P	8510010050	50-302 P
	8510110121	70-1257	P	8510010100	50-302 P
	8510110127*	70-1257		8510010347	50-302 P
	8510150053	70-1257		8510010640	50-302 S
	8510150200	XPORTLIC		8510020193	50-302 S
	8510170289	50-316	P	8510040171	50-302 P
	8510170292*	50-316	P	8510040257	50-302 P
	8510170409	40-8102		8510070320	50-302 Q
	8510180525	70-1257		8510070372	50-302 Q
	8510210143	TOPREP		8510080423	50-302 F
	8510210145*	TOPREP		8510150147	50-302 P
	8510220087	70-1257		8510150353	50-302 R
Federal Emergency Management Agency	8510230001	TOPREP		8510150356*	50-302 R
	8510100056	50-322	F	8510150357*	50-302 R
	8510100061*	50-322	F	8510160085	50-302 P
	8510160145	50-413	F	8510170055	50-302 P
	8510160145	50-413	F	8510180211	NUREG
	8510160184	50-334	F	8510210077	50-302 P
	8510160184	50-334	F	8510290206	50-302 F
	8510160189*	50-282	F	8510310191	50-302 P
	8510210216	50-440	F	8510310197*	50-302 P
	8510210239	50-334	F	8510310216	50-302 F
	8510210239	50-334	F	8510310534	50-302 F
	8510210258	50-413	F	8510180319	PR
			Florida, State of		

384 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Florida, Univ. of, Gainesville, FL	8510300070	50-83		8510180077*	50-219
	8510300076*	50-83		8510180180	50-320
Fluor Corp.	8510070227*	50-282		8510180194	50-219
Framatome	8510020275	TOPREP		8510210214	71-6206
	8510020278*	TOPREP		8510220037	50-320
Friends of the Earth	8510020281*	TOPREP		8510220042*	50-320
GA Technologies, Inc./General Atomic Co.	8510110017	50-352		8510220149	50-320
	8510010632	50-183		8510220153*	50-320
	8510150050	70-734		8510220434*	50-219
	8510210253	70-734		8510230136	50-219
Gambit Publications, Inc., New Orleans, LA	8510210273	70-734		8510240061	50-320
General Electric Co.	8510010021	50-382		8510240103	50-219
	8510010251	FOIA		8510240108*	50-219
	8510040019	REGGD		8510240323*	50-320
				8510240329*	50-320
	8510070270	50-70		8510240673	50-289
	8510070272*	50-70		8510250220	50-219
	8510090082	TOPREP		8510250226	50-289
	8510100003	TOPREP		8510250354	50-289
	8510100013	TOPREP		8510250364*	50-289
	8510100146	PR		8510250375*	50-289
	8510110213	70-1113		8510250463	50-320
	8510150261	71-5942		8510280126	50-219
	8510150337	TOPREP		8510280174	50-320
	8510150363*	50-440		8510280378	50-289
	8510170223	TOPREP		8510280516	50-289
	8510180410*	50-447		8510290088	50-289
	8510210250	71-5984		8510290160	50-289
	8510230186*	50-387		8510290172	50-219
	8510230243	TOPREP		8510290175*	50-289
	8510240198	TOPREP		8510290182*	50-289
	8510240390	70-1113		8510290212	50-320
	8510250392	PR		8510290218	50-320
	8510300003	50-73		8510290252	50-219
	8510300006*	50-73		8510290263*	50-219
General Physics Corp.	8510310072*	XPORTLIC		8510290316	NUREG
General Public Utilities Corp. - GPU	8510040318	NUREG		8510290321	50-219
Service Corp.	8510010094	50-320		8510290327*	50-219
				8510310337	50-289
	8510010102*	50-320		8510310596	50-289
	8510010209	50-219	General Services Administration	8510010007*	CONTRACT
	8510010214*	50-219		8510280204*	CONTRACT
	8510020124	50-219	GeoTrans, Inc.	8510250299	WASTE RES
	8510020265	50-320	Geological Consulting Services, Inc.	8510100175	PR
	8510030056	50-289	Georgia Power Co.	8510010098	50-321
	8510040141	50-320		8510010114*	50-321
	8510040148*	50-320		8510010220	50-321
	8510040152*	50-320		8510010277	50-321
	8510040155*	50-320		8510010277	50-321
	8510040293	50-320		8510030025	50-424
	8510040296*	50-320		8510030044	50-424
	8510040299	50-320		8510030089	50-424
	8510040309	50-320		8510070302	50-424
	8510040445	50-289		8510070302	50-424
	8510040448*	50-289		8510070310*	50-424
	8510040450*	50-289		8510070310*	50-424
	8510070210	50-289		8510070471	50-321
	8510070218*	50-289		8510070471	50-321
	8510070277	50-219		8510080085	50-366
	8510070371	50-289		8510080214	50-424
	8510070426	50-289		8510080503	50-424
	8510070432*	50-289		8510080503	50-424
	8510070474	50-219		8510090066	50-424
	8510070476*	50-219		8510100126	50-424
	8510080078	50-289		8510100126	50-424
	8510080173	50-289		8510150289	50-321
	8510080212	50-289		8510150338	50-321
	8510080457	50-320		8510180169	50-321
	8510090457	50-289		8510180169	50-321
	8510100048	50-289		8510180228	50-424
	8510110066	50-219		8510180377	50-366
	8510110066	50-219		8510180510	50-321
	8510110072*	50-219		8510180536	50-321
	8510110214	50-219		8510180536	50-321
	8510150310	50-320		8510210142	50-366
	8510150348	50-219		8510220207*	50-424
	8510150362	50-289		8510220211*	50-424
	8510150376	50-289		8510220378	50-424
	8510150377	50-320		8510230073	50-424
	8510150396	50-289		8510250061	50-321
	8510180072	50-219		8510250250	50-321
	8510180080	50-289		8510250448	50-321
	8510180091	50-219		8510250564	50-366
	8510180096	50-320		8510280301	50-321
	8510180102*	50-320		8510280420	50-321
	8510180120	50-289		8510290358	PR
	8510180247	50-289		8510290368	50-424
	8510180073	50-219		8510300191	50-424
	8510180074	50-320		8510290296	50-327
			Georgia, State of		

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Georgians Against Nuclear Energy Government Accountability Project	8510290348	PR	House of Rep.	8408010320*	50-315 U
	8510210029	50-424 G		8510010085*	FOIA
	8510010244*	FOIA		8510010093*	FOIA
	8510010266	50-382 A		8510010099*	50-416 U
	8510030127	50-382 E		8510010122*	FOIA
	8510040454	50-382		8510010172*	50-323 P
	8510070312	50-424 H		8510010226*	FOIA
	8510080409*	50-329 A		8510010334*	FOIA
	8510150436	50-445 A		8510010395*	FOIA
	8510150440	50-445 A		8510010418*	FOIA
	8510150443	50-445 A	House of Rep., Energy & Commerce	8510010536*	50-322 U
	8510150446	50-445 A		8510010566*	COMMISSIO N
	8510150447	50-445 A		8510080077*	70-135
	8510160201	50-275 P		8510230058*	50-321 U
	8510170096	FOIA		8506260600*	50-346 S
Grocery Manufacturers of America, Inc.	8510170103	FOIA	House of Rep., Foreign Affairs	8510010536*	50-322 U
	8510170349*	50-413 P		8510010566*	COMMISSIO N
	8510220230	FOIA		8510070511*	50-346 U
	8510250346	50-445 A		8510090385*	50-341 U
	8510160311	PR		8510010203*	FOIA
Guild, R.	8510110221	50-456 G	Houston Lighting & Power Co.	8510010095	50-498 S
	8510110221	50-456 G		8510010144	50-498 O
	8510110222*	50-456 G		8510010463	50-498 A
	8510110222*	50-456 G		8510020166	50-498 G
	8510160127	50-456 G		8510020166	50-498 G
Gulf States Utilities Co.	8510240490	50-456 G		8510030057	50-498 Q
	8510010390	50-458 P		8510040457	50-498 A
	8510030055	50-458 K		8510040457	50-498 A
	8510040145	50-458 P		8510080340	50-498 A
	8510040267	50-458 P		8510080340	50-498 A
	8510040469	50-458 P		8510080427	50-498 F
	8510070258	50-458 F		8510080427	50-498 F
	8510080067	50-458 S		8510080464	50-498 A
	8510080564	50-458 S		8510080595*	50-498 O
	8510080578*	50-456 S		8510090117	50-498 S
	8510080581*	50-458 S		8510090117	50-498 S
	8510080583*	50-458 S		8510090138	50-498 S
	8510080588*	50-458 S		8510090138	50-498 S
	8510080589*	50-458 Q		8510100021	50-498 M
	8510080591*	50-458 S		8510100074	50-498 G
	8510090127	50-458 R		8510100074	50-498 G
	8510090313*	50-458 O		8510100159	50-498 T
	8510110001	50-458 E		8510100159	50-498 T
	8510110104	50-458 P		8510110203	50-498 G
	8510110137	50-458 E		8510110203	50-498 G
	8510110154	50-458 P		8510110223	50-498 A
	8510160090	50-458 P		8510110223	50-498 A
	8510160291	50-458 P		8510150081	50-498 A
	8510170196	50-458 R		8510150207	50-498 A
	8510220074	50-458 S		8510160244	50-498 G
	8510220078*	50-458 S		8510180027	50-498 mmmmm
	8510220083*	50-458 S		8510180027	50-498 mmmmm
	8510220345	50-458 P		8510180040	50-498 mmmmm
	8510220359*	50-458 Q		8510180040	50-498 mmmmm
	8510220453*	50-458 Q		8510180041	50-498 mmmmm
	8510250267	50-458 P		8510180041	50-498 mmmmm
	8510250376	50-458 S		8510180044	50-498 mmmmm
	8510250405	50-458 P		8510180044	50-498 mmmmm
	8510290467	50-458 S		8510180046	50-498 mmmmm
	8510300127	50-458 P		8510180046	50-498 mmmmm
	8510300132	50-458 R		8510180047	50-498 mmmmm
	8510300185	50-458 P		8510180047	50-498 mmmmm
	8510310075	50-458 S		8510180064	50-498 mmmmm
	8510310428	50-458 S		8510180064	50-498 mmmmm
	8510150170*	FOIA		8510180066	50-498 mmmmm
Gunnison Mining Co.	8510150209*	FOIA		8510180066	50-498 mmmmm
	8510150236*	FOIA		8510180079	50-498 mmmmm
	8510150266*	FOIA		8510180079	50-498 mmmmm
	8510150325*	FOIA		8510180101	50-498 mmmmm
	8510110048*	50-461 F		8510180101	50-498 mmmmm
HMM Associates, Inc.	8510240394	50-400 T		8510180116	50-498 mmmmm
Hahnemann Univ., Philadelphia, PA	8510250164	REGGD		8510180116	50-498 mmmmm
Hall, Estill, Hardwick, Gable, Collingsworth & Nelson	8510100078	PR		8510180121	50-498 mmmmm
Hamel, Park, McCabe & Saunders	8510180302	40-8681		8510180121	50-498 mmmmm
	8510180307*	40-8681		8510180122	50-498 mmmmm
Hannover, Technical Univ. of, Federal Republic of Germany	8510040355*	CONTRACT		8510180199	50-498 mmmmm
Harmon, Weiss & Jordan	8510010188	50-443 Q		8510180199	50-498 mmmmm
	8510150347	50-289 G		8510180218	50-498 mmmmm
	8510240582	WASTE MGT		8510180218	50-498 mmmmm
Hayes, Seay, Mattern & Mattern	8510100069	PR		8510180230	50-498 mmmmm
Henry Ford Hosp., Detroit, MI	8510290362	PR		8510180241	50-498 mmmmm
Hercules, Inc.	8510110224	PR		8510180241	50-498 mmmmm
Herner & Co.	8510210204*	CONTRACT		8510180250	50-498 mmmmm
	8510180133	50-250 G		8510180250	50-498 mmmmm
Hodder, M.H.	8510180140	50-250 G		8510180262	50-498 mmmmm
	8510310253	50-250 G		8510180262	50-498 mmmmm
	8510310323	50-250 G		8510180269	50-498 mmmmm

386 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510180331	50-498		8510150365	50-322
	8510180331	50-498		8510210003	50-289
	8510180333	50-498	ITASCA Consulting Group, Inc.	8510090311	WASTE RES
	8510180333	50-498		8510090490	WASTE RES
	8510180345	50-498		8510240352	WASTE RES
	8510180345	50-498		8510240380	WASTE RES
	8510180363	50-498	ITT Grinnell Corp. (subs. of ITT Corp.)	8510010306	50-282
	8510180363	50-498		8510220062	50-282
	8510180368	50-498	Idaho National Engineering Laboratory	8510040100*	50-261
	8510180368	50-498	Ikard, J.	851180337	40-8027
	8510180386	50-498	Illinois Institute of Technology,	8510170398	NUREG
	8510180386	50-498	Chicago, IL	8510170403*	NUREG
	8510180418	50-498		8510180099*	REVIEW GR
	8510180418	50-498	Illinois Power Co.	8510010325	50-461
	8510210044	50-498		8510010468	50-461
	8510210044	50-498		8510010494	50-461
	8510210061	50-498		8510020288	50-461
	8510210061	50-498		8510040140	50-461
	8510210210	50-498		8510040197	50-461
	8510210210	50-498		8510070321	50-461
	8510210301	50-498		8510080003	50-461
	8510210301	50-498		8510090331	50-461
	8510220132	50-498		8510110035	50-461
	8510220132	50-498		8511110045	50-461
	8510220179	50-498		8510100054	50-461
	8510220179	50-498		8510100096	50-461
	8510220204	50-498		8510100132	50-461
	8510220204	50-498		8510110043	50-461
	8510220302	50-498		8510160131	50-461
	8510220302	50-498		8510160165	50-461
	8510220305*	50-498		8510160171*	50-461
	8510220305*	50-498		8510160177	50-461
	8510220309	50-498		8510210015	50-461
	8510220309	50-498		8510210028	50-461
	8510220360*	50-498		8510210036	50-461
	8510220481	50-498		8510210094	50-461
	8510220481	50-498		8510250378	50-461
	8510240442	50-498		8510280054	50-461
	8510240442	50-498		8510280288	50-461
	8510240466	50-498		8510280376	50-461
	8510250128	50-498		8510300018	50-461
	8510250128	50-498		8510300025*	50-461
	8510250145	50-498		8510310250	50-461
	8510250145	50-498	Illinois Safe Energy Alliance	8510010104	70-1305
	8510250172	50-498		8510040247	50-373
	8510250172	50-498	Illinois, State of	8510110141	50-373
	8510250258	50-498		8510110158	40-2061
	8510250258	50-498		8510110165*	40-2061
	8510250295	50-498		8510150107	40-2061
	8510250295	50-498		8510210002	40-2061
	8510250304	50-498		8510290055	50-373
	8510250304	50-498		8510290081	50-295
	8510250309	50-498		8510290188	50-373
	8510250309	50-498		8510290231	50-373
	8510250325	50-498		8510290346	50-454
	8510250325	50-498	Illinois, Univ. of, Urbana, IL	8510010240*	CONTRACT
	8510250356	50-498	Impell Corp.	8510090333*	50-206
	8510250356	50-498		8510290174*	50-344
	8510250381	50-498	In-Situ Consulting	8510080141*	CONTRACT
	8510250381	50-498		8510080149*	CONTRACT
	8510250404	50-498		8510010110	50-316
	8510250404	50-498	Indiana & Michigan Electric Co.	8510010120*	50-316
	8510250436	50-498		8510010129*	50-316
	8510250436	50-498		8510010493	50-316
	8510250453	50-498		8510010496	50-315
	8510250453	50-498		8510040108	50-315
	8510250469	50-498		8510040136	50-315
	8510250469	50-498		8510070062	50-315
	8510250503	50-498		8510070062	50-315
	8510250503	50-498		8510070082	50-315
	8510280312	50-498		8510070082	50-315
	8510280312	50-498		8510070086*	50-315
	8510280321	50-498		8510070086*	50-315
	8510280321	50-498		8510070163	50-316
	8510280333	50-498		8510070170*	50-316
	8510280333	50-498		8510070189	50-315
	8510280364	50-498		8510070189	50-315
	8510280364	50-498		8510070314	50-315
	8510280383	50-498		8510070548	50-315
	8510280383	50-498		8510070549*	50-315
	8510280411	50-498		8510070552*	50-315
	8510280411	50-498		8510080292	50-315
	8510280415	50-498		8510080520	50-315
	8510280415	50-498		8510080520	50-315
	8510310241	50-498		8510080577	50-315
	8510310241	50-498		8510090176	50-315
	8510100140	50-322		8510090179*	50-315
	8510110057	50-322		8510090184*	50-315

CORPORATE SOURCE INDEX 387

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510090246	50-315		8510180268	50-456
	8510090370	50-315		8510180268	50-456
	8510090374	50-315		8510180338	50-456
	8510090378*	50-315		8510180338	50-456
	8510090382*	50-315		8510210030	50-456
	8510090520	50-315		8510220291	50-456
	8510160009	50-316		8510220291	50-456
	8510160021	50-316		8510220348	50-456
	8510160041	50-315		8510220348	50-456
	8510160047	50-315		8510220364	50-456
	8510160047	50-315		8510220364	50-456
	8510160160	50-315		8510240354	50-456
	8510160160	50-315	Isotope Products Laboratories	8510100097	PR
	8510160167*	50-315	Jacobs Engineering Group, Inc.	8510080619	WASTE MGT
	8510160167*	50-315		8510090446	WASTE MGT
	8510160227	50-315		8510240453	WASTE MGT
	8510170022	50-315		8510240622	WASTE MGT
	8510170025	50-316	Japan, Govt. of	8510170266	XPORTLIC
	8510170040	50-316		8510170269	XPORTLIC
	8510170042*	50-316		8510170276	XPORTLIC
	8510170045*	50-316		8510170279	XPORTLIC
	8510170049	50-315		8510170283	XPORTLIC
	8510170445	50-316	Joint Intervenor - Shearon Harris	8510030009	50-400
	8510170448	50-316		8510030082	50-400
	8510180180	50-315	Jomar Systems	8510100116	PR
	8510180180	50-315		8510180450*	FOIA
	8510210101	50-315	Justice, Dept. of	8510100047*	50-400
	8510220067	50-315	Justice, Dept. of, Drug Enforcement		
	8510220133	50-315	Administration		
	8510220236	50-315	Kansas Gas & Electric Co.	8510040133	50-482
	8510220236	50-315		8510070009	50-482
	8510220236	50-315		8510090294	50-482
	8510220249	50-315		8510090372	50-482
	8510220249	50-315		8510160059	50-482
	8510220255*	50-315		8510180152	50-482
	8510220255*	50-315		8510180212	50-482
	8510240183	50-315		8510180217*	50-482
	8510240219	50-316		8510180222*	50-482
	8510250380	50-315		8510210229	50-482
	8510250391	50-315		8510210234	50-482
	8510250391	50-315		8510220044	50-482
	8510280405	50-315		8510220155	50-482
	8510290023	50-315		8510220159*	50-482
	8510290139	50-316		8510220301*	50-482
	8510290350	50-316		8510220342*	50-482
	8510300164	50-315		8510220346*	50-482
Indiana & Michigan Power Co.	8510160227	50-315		8510240166	50-482
Institute of Systems Sciences	8510290410	NUREG		8510310071	50-482
Interior, Dept. of, Bureau of Mines	8510240576	WASTE RES		8510310156	50-482
	8510250213*	CONTRACT		8510310175	50-482
	8510250225*	CONTRACT	Kansas State Univ., Manhattan, KS	8510170386	50-188
Interior, Dept. of, Geological Survey	8510010280*	40-8027		8510080523	STATE PRO
	8510210240	70-820	Kansas, State of	8510280192	50-148
	8510210247*	70-820	Kansas, Univ. of, Lawrence, KS	8510070250	PR
International Energy Associates, Ltd.	8510230211*	50-400	Kay-Ray, Inc.	8510090044	FOIA
International Nutronics, Inc.	8510170124*	FOIA	Kerr-McGee Chemical Corp. (subs. of	8510100170	40-2061
	8510170134*	FOIA			
	8510170138*	FOIA	Kerr-McGee Corp.)		
	8510170200*	FOIA		8510240355	40-2061
Iowa Electric Light & Power Co.	8510040255	50-331		8510240577	40-2061
	8510070286	50-331		8510110284	40-2061
	8510090283	50-331		8510310341	40-2061
	8510100019	50-331		8510010081*	40-8006
	8510150332	50-331	Kerr-McGee Corp.	8510010089*	40-8006
	8510150432	50-331		8510010121*	40-8006
	8510170281	50-331		8510010127*	40-8006
	8510170353*	50-331		8510010134*	40-8006
	8510210020	50-331		8510010142*	40-8027
	8510210149	50-331		8510010150*	40-8027
	8510210289	50-331		8510010159*	40-8027
	8510250394	50-331		8510010166*	40-8006
	8510280001	50-331		8510010173*	40-8006
	8510280353	50-331		8510010187*	FOIA
	8510280384	50-331		8510010188*	40-8006
	8510280396	50-331		8510010191*	40-8027
	8510290405	50-331		8510010193*	40-8027
	8510310140	50-331		8510010356*	FOIA
	8510310513	50-331		8510010401*	40-8027
	8510310519*	50-331		8510010413*	40-8027
Iowa, State of	8510010544*	COMMISSIO		8510100007	PR
	8510020524	STATE PRO		8510150071	40-8027
	8510020524	STATE PRO		8510150073*	40-8027
Isham, Lincoln & Beale	8510020370	50-456		8510150373*	40-1366
	8510040329	50-456		8510150374*	40-1366
	8510110085	50-456		8510160304	40-8027
	8510110085	50-456		8510160307*	40-8027
	8510110133	50-456		8510180381	40-8768
	8510110133	50-456		8510220194	40-2061
	8510110217	50-329		8510220235	40-8027
	8510150306	50-456		8510240175	40-2061
	8510150306	50-456	Kerr-McGee Nuclear Corp.	8510010076*	FOIA

388 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510010135*	40-8027		8510010373*	50-382	
	8510010174*	40-8027		8510010376*	50-382	
	8510010183*	40-8027		8510010380*	50-382	
	8510010224*	40-8006		8510010381*	50-382	
	8510010229*	40-8027		8510010384*	50-382	
	8510010230*	40-8006		8510010392*	50-382	
	8510010236*	40-8027		8510010396*	50-382	
	8510010242*	40-8027		8510010399*	50-382	
	8510010243*	40-8006		8510010423*	50-382	
	8510010256*	40-8027		8510010424*	50-382	
	8510010261*	40-8027		8510010427*	50-382	
	8510010269*	40-8027		8510010427*	50-382	
	8510010273*	40-8027		8510010431*	50-382	
	8510010300*	40-8027		8510010435*	50-382	
Kings Daughters Hosp., Staunton, VA	8510250365	PR		8510010435*	50-382	
Kiski Valley Coalition to Save Our Children	8510090132	40-1193		8510010442*	50-382	
LFE Corp.	8510100076	PR		8510010442*	50-382	
LRG Instrumentation Setpoint Methodology Group	8510040323	REVIEW GR	P	8510010444*	50-382	
				8510010447*	50-382	
LRS Consultants	8311290156*	50-346	S	8510010449*	50-382	
Lawrence Berkeley Laboratory	8510020240	NUREG		8510010449*	50-382	
Lawrence Livermore National Laboratory	8510040182*	50-424	F	8510010458*	50-382	
	8510080570	WASTE RES		8510010460*	50-382	
	8510090366	WASTE RES		8510010461*	50-382	
	8510160297*	50-423	F	8510010527	50-382	
	8510240181	WASTE RES		8510010616	50-382	
Leak Detection Services, Inc.	8510080598*	CONTRACT		8510020085	50-382	
Lewis, M.	8510100025	NUREG		8510020199*	50-382	
	8510180287	50-289	G	8510020219	50-382	
	8510250393	NUREG		8510020487	50-382	
Limerick Ecology Action	8510150349	50-352	G	8510040386	50-382	
Linsley, Krueger & Associates, Ltd.	8510070308*	CONTRACT		8510040438	50-382	
Lidscope of America, Inc.	8510040405	PR		8510080437	50-382	
Lodge, T.J.	8510100145	50-440	G	8510150126	50-382	
	8510310266	50-440	G	8510150476	50-382	
Long Island Lighting Co.	8510010013	50-322		8510160215	50-382	
	8510020019*	50-322	Q	8510160257*	50-382	
	8510020100	50-322	R	8510160296	50-382	
	8510030378	50-322	S	8510170010	50-382	
	8510030412	50-322	S	8510170013	50-382	
	8510090101	50-322	S	8510170233	50-382	
	8510090287	50-322	S	8510210163	50-382	
	8510100140	50-322	G	8510220205	50-382	
	8510110057	50-322	G	8510220227*	50-382	
	8510150365	50-322	G	8510240369	50-382	
	8510150372	50-322	P	8510240408	50-382	
	8510170003	50-322	R	8510250427	50-382	
	8510170363	50-322	S	8510280329	50-382	
	8510170368	50-322	S	Louisiana, State of	8510010454*	50-382
	8510180154	50-322	S	8510020393	50-382	
	8510180179	50-322	S	8510240400	50-223	
	8510220007	50-322	S	8510030131	NUREG	
	8510230074	50-322	P	8510100078	PR	
	8510230082*	50-322	P	Maine Yankee Atomic Power Co.	8510010637	50-309
	8510230086*	50-322	P	8510030095	50-309	
	8510250026	50-322	S	8510070268	50-309	
	8510250385	50-322	F	8510070282*	50-309	
	8510180133	50-250	G	8510080179	50-309	
	8510310323	50-250	G	8510090417	50-309	
Lorton, J.						
Los Angeles Times Los Angeles, CA	8510220156	FOIA		8510110031	50-309	
Louis-Allis Co.	8510040264	50-322	S	8510110035*	50-309	
Louisiana Power & Light Co.	8510010287*	50-382	F	8510150387	50-309	
	8510010295*	50-382	P	8510170061	50-309	
	8510010297*	50-382	P	8510170075*	50-309	
	8510010301*	50-382	P	8510220160	50-309	
	8510010304*	50-382	P	8510220165*	50-309	
	8510010307*	50-382	P	8510240301	50-309	
	8510010310*	50-382	P	8510240418	50-309	
	8510010313*	50-382	P	8510240640	50-309	
	8510010314*	50-382	P	8510250229	50-309	
	8510010321*	50-382	P	8510250244	50-309	
	8510010326*	50-382	P	8510280369	50-309	
	8510010328*	50-382	P	8510100182	PR	
	8510010333*	50-382	P	8510100209	PR	
	8510010339*	50-382	P	8510090224	WASTE RES	
	8510010342*	50-382	P	8510170383	50-199	
	8510010343*	50-382	F	8510080084	50-390	
	8510010345*	50-382	F	8510080180	50-280	
	8510010348*	50-382	P	8510090014	50-344	
	8510010350*	50-382	P	8510090261	50-272	
	8510010357*	50-382	P	8510160199	50-272	
	8510010358*	50-382	P	8510290189	50-322	
	8510010360*	50-382	Q	8510020396	50-382	
	8510010364*	50-382	P	Martin Marietta Corp.	8510010149*	CONTRACT
			Maryland, Univ. of, College Park, MD			
	8510010365*	50-382	P	Massachusetts Institute of Technology,	8510020307	NUREG
	8510010367*	50-382	Q	Cambridge, MA		
	8510010369*	50-382	P	Massachusetts Materials Research, Inc.	8510040336	PR
	8510010371*	50-382	P	Materials Engineering Associates, Inc.	8510080600*	CONTRACT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Maxima Corp.	8510070129*	CONTRACT	National Aeronautics & Space Admin.	8510230017	50-30 H
McGraw-Hill Publications Co.	8510160089	FOIA	National Sanitation Foundation	8510100077	PR
Measurix Corp.	8510100188	PR	National Water Center	8510020378	40-8027
Mercy Medical Center, Coon Rapids, MN	8510100192	PR	Navajo Refining Co.	8510100158	PR
Meredith Broadcasting/WTVH Television	8510160078	50-220 Q	Navajo Nation	8510240290*	WASTE MGT
Michael Fox	8510080299*	CONTRACT	Navy, Dept. of	8510100169	PR
Michigan, State of	8510180332	PR	Navy, Dept. of, Naval Sea Systems Command	8510180521	71-133
Miller & Lents, L'd.	8510010464*	50-498 A	Navy, Dept. of, Pearl Harbor Naval Shipyard	8510180526*	71-133
Minnesota, State of	8510070301	PRM	Nebraska Public Power District	8510010492	50-298 R
	8510100133*	PRM			
Mississippi Power & Light Co.	8510010151*	50-416 V		8510020034	50-298 P
	8510010170*	50-416 V		8510020037*	50-298 P
	8510010462	50-416 S		8510040001	50-298 F
	8510020018	50-416 S		8510070244	50-298 F
	8510020302	50-416 P		8510080168	50-298 F
	8510020304*	50-416 P		8510090300*	50-298 Q
	8510070316	50-416 P		8510160040	50-298 F
	8510070316	50-416 P		8510180043	50-298 F
	8510070373	50-416 Q		8510240247	50-298 F
	8510070452	50-416 P		8510240331	50-298 F
	8510070452	50-416 P		8510240414	50-298 F
	8510070475	50-416 P		8510240426*	50-298 Q
	8510070481	50-416 S		8510290202*	50-298 S
	8510080316	50-416 S	Neutron Products, Inc.	8510290379	50-298 S
	8510080494	50-416 P		8510100065	PR
	8510090029	50-416 S			
	8510090090	50-416 P	Nevada, State of	8510220097	71-121
	8510090292	50-416 S		8510010136	WASTE MGT
	8510090361	50-416 S		8510070351	PRM
	8510090368*	50-416 S		8510100133*	PRM
	8510150049	50-416 P	New Jersey, State of	8510110005	50-354 A
	8510150054*	50-416 P			
	8510150103	50-416 P	New Mexico, State of	8510110174	PR
	8510150187	50-416 P	New Mexico, Univ. of, Albuquerque, NM	8510170197	50-252 F
	8510160042	50-416 P	New York Power Authority (formerly Power Authority of the State of New York)	8510010340	50-333 Q
	8510160061	50-416 P		8510030018	50-333 P
	8510160061	50-416 P		8510030071	50-286 P
	8510160073	50-416 P		8510040213	50-333 P
	8510160083*	50-416 P		8510040221*	50-333 P
	8510160214	50-416 F		8510040225*	50-333 P
	8510160216*	50-416 F		8510080218	50-286 P
	8510160245	NUREG		8510080313	50-286 P
	8510180035	50-416 Q		8510090510	71-240
	8510180207	50-416 R		8510100033	50-333 Q
	8510210226	50-416 P		8510100048*	50-333 Q
	8510220053	50-416 Q		8510100120	50-286 P
	8510220122	50-416 S		8510100136*	50-286 P
	8510220365	50-416 P		8510100147*	50-286 P
	8510220366*	50-416 P		8510150038	50-333 R
	8510240339	50-416 S		8510150312	50-333 R
	8510280158	50-416 P		8510180059	50-286 P
	8510290038	50-416 F		8510180310	50-333 P
	8510290038	50-416 F		8510220001	50-286 F
	8510290301	50-416 S		8510220105	50-333 F
	8510290445	50-416 P		8510220191	50-333 P
	8510290449*	50-416 P		8510220330	50-286 P
	8510290451*	50-416 P		8510220337*	50-286 P
	8510300082*	50-417 A		8510220347	50-333 P
Missouri, Univ. of, Columbia, MO	8510300308	50-418 S		8510220349*	50-333 P
	8510280091	50-186 P		8510220352*	50-333 P
Missouri, Univ. of, Rolla, MO	8510010289*	40-8027		8510240177	50-333 P
	8510010322*	FOIA			
	8510010349*	40-8027		8510280151	50-333 S
Mitre Corp.	8510080334*	CONTRACT		8510280403	50-333 S
Mohr & Associates	8510070581*	CONTRACT	New York, State Univ. of, Buffalo, NY	8510280404*	50-333 S
MolyCorp, Inc. (subs. of Union Oil of California)	8510080027*	CONTRACT		8510290476	50-286 R
Montgomery County Sentinel	8510220025	40-8778		8510220383	70-267
Morrison-Knudsen Engineers, Inc.	8510010056	FOIA			
	8510090330	WASTE MGT		8510100042	50-322 G
	8510090420	WASTE MGT		8510110180	50-322 G
	8510240510	WASTE MGT		8510110196	50-322 G
	8510280025*	WASTE MGT		8510180253	PR
	8510280050	WASTE MGT		8510280519	50-322 G
	8510280444	WASTE MGT			
NDC Systems	8510280468	WASTE MGT		8510020166	50-498 G
NUS Corp.	8510100065	PR		8510100074	50-498 G
	8510010051	FOIA		8510100074	50-498 G
	8510010058	FOIA		8510100159	50-498 T
	8510090435	FOIA		8510100159	50-498 T
	8510170399	FOIA		8510110203	50-498 G
	8510180176	FOIA		8510160244	50-498 G
NUTECH Engineers, Inc.	8510010826*	PRQJ		8510180214	50-250 G
	8510080515*	50-237 P		8510180214	50-250 G
	8510090042*	50-265 Q		8510180230	50-498 G
National Academy of Sciences	8510210196	PRQJ		8510180320	50-250 G
	8510180324*	CONTRACT		8510180320	50-250 G
	8510170119*	CONTRACT		8510210061	50-498 G
				8510210061	50-498 G
				8510210210	50-498 G
				8510210210	50-498 G
				8510310281	50-250 G
				8510310281	50-250 G
				8510310365	50-250 G

390 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Niagara Mohawk Power Corp.	8510310365	50-250	G	8510110037	50-245	P
	8510310434	50-250	G	8510110078	50-423	A
	8510310434	50-250	G	8510110080*	50-423	A
	8510020170	50-410	A	8510110092	50-423	A
	8510020185	50-410	E	8510110115	50-423	E
	8510020433	50-410	S	8510110131	50-423	E
	8510030346	50-220	S	8510110189	50-423	A
	8510040143	50-220	P	8510110226	50-423	A
	8510040353	50-410	A	8510150065	50-423	A
	8510070261	50-220	P	8510150067	50-245	P
8510080467	50-410	A	8510150233	50-423	S	
8510080480	50-410	E	8510150284	50-213	F	
8510090013	50-410	E	8510150284	50-213	F	
8510100201	PR		8510150305	50-423	A	
8510110084	50-410	E	8510150327	50-423	A	
8510150212	50-410	A	8510150351	50-423	A	
8510160067	50-410	V	8510150369	50-245	P	
8510160218	50-220	P	8510150371*	50-245	P	
8510170109	50-410	A	8510160019	50-423	A	
8510170110	50-220	S	8510160052	50-423	F	
8510180125	50-410	S	8510170051	50-336	S	
8510180157	50-410	S	8510170068	50-423	A	
8510180236	50-220	R	8510170098	50-213	P	
8510180395	50-410	S	8510170098	50-213	P	
8510180440	50-410	S	8510170245	50-245	S	
8510210056	50-410	F	8510170286	50-423	A	
8510210138	50-410	Q	8510180245	50-423	A	
8510210139*	50-410	Q	8510180353	50-423	A	
8510210213	71-5939		8510220021	50-423	A	
8510210297	70-2948		8510220033	50-245	P	
8510220011	50-220	S	8510220065	50-423	A	
8510230149	50-410	A	8510220145	50-423	A	
8510230216	50-410	A	8510220150	50-423	A	
8510240444	50-220	F	8510220158	50-213	P	
8510250418	50-220	P	8510220158	50-213	P	
8510250426*	50-220	P	8510220158	50-213	P	
8510250431*	50-220	P	8510220158	50-213	P	
8510250438	50-410	Q	8510220186	50-213	P	
8510310135	50-410	A	8510220186	50-213	P	
8510020158	50-413	P	8510220186	50-213	P	
North Carolina Electric Membership Corp.						
North Carolina Municipal Power Agencies	8510240235	50-400	G	8510220234	50-423	E
North Carolina State Univ., Raleigh, NC	8510220462	50-297	P	8510220244	50-423	A
North Carolina, State of	8510100038	50-400	G	8510220247	50-245	P
	8510100038	50-400	G	8510220295	50-245	P
	8510100047*	50-400	G	8510220313	50-245	P
8510170081	50-400	H	8510230031	50-245	P	
8510180283	REGGD		8510230034	50-423	A	
8510220201	50-322	G	8510240003	50-245	P	
			8510240078	50-245	P	
8510220314	50-322	G	8510240089	50-245	P	
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	8510020055	50-245	P	8510240256	50-423	A
				8510240262*	50-423	A
8510020074	50-245	R	8510240287	50-245	F	
8510020076	50-336	R	8510240335	50-245	P	
8510030332	50-423	S	8510240373	50-245	P	
8510030426	50-423	S	8510240382	50-245	P	
8510040003	50-423	F	8510240410	50-245	P	
8510040304	50-423	A	8510240415	50-245	S	
8510040433	50-423	E	8510240459	50-245	P	
8510040455	50-423	Q	8510280203	50-245	F	
8510070059	50-423	E	8510280370	50-336	P	
8510070205	50-423	A	8510280375*	50-336	P	
8510070238	50-423	A	8510290220	50-423	A	
8510070253	50-423	S	8510290234*	50-423	A	
8510070264	50-423	A	8510290235	50-423	F	
8510070275	50-423	K	8510290246*	50-423	F	
8510070279*	50-423	K	8510290249*	50-423	F	
8510070300	50-423	E	8510290300	50-336	P	
8510070303	50-245	P	8510290308*	50-336	P	
8510070319	50-423	E	8510290320	50-245	P	
8510070441	50-245	P	8510290324*	50-245	P	
8510070444	50-423	A	8510290333	50-245	P	
8510070447*	50-245	P	8510290343*	50-245	P	
8510080040	50-423	E	8510290368	50-245	P	
8510080145	50-423	E	8510290390*	50-245	P	
8510080265	50-423	A	8510290392*	50-245	P	
8510080270*	50-423	A	8510290393*	50-245	P	
8510080385	50-245	P	8510300123	50-245	P	
8510080468	50-423	E	8510300215	50-423	S	
8510080470	50-245	P	8510300263	50-423	S	
8510090069	50-423	A	8510300268	50-423	S	
8510090177	50-423	S	8510300271	50-423	S	
8510100135	50-245	P	8510310093	50-423	F	
8510100163	50-336	P	8510310100	50-245	S	
8510100166	50-336	P	8510310126	50-245	P	
8510100174*	50-336	P	8510310205	50-423	A	
8510100180	50-423	A	8510310214	50-423	A	
8510110009	50-423	A	8510310220	50-423	K	
8510110022	50-423	A	8510310402	50-336	S	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		
Northeast Utilities	8510310502	50-245	S	8510240415	50-245	S	
	8510020055	50-245	P	8510240459	50-245	P	
	8510020074	50-245	R	8510280203	50-245	F	
	8510020076	50-336	R	8510280370	50-336	P	
	8510030332	50-423	S	8510290220	50-423	A	
	8510030426	50-423	S	8510290235	50-423	F	
	8510040003	50-423	F	8510290300	50-336	P	
	8510040304	50-423	A	8510290320	50-245	P	
	8510040433	50-423	E	8510290333	50-245	P	
	8510040455	50-423	Q	8510290388	50-245	P	
	8510070059	50-423	E	8510300123	50-245	P	
	8510070205	50-423	A	8510300215	50-423	S	
	8510070238	50-423	A	8510300263	50-423	S	
	8510070253	50-423	S	8510300268	50-423	S	
	8510070264	50-423	A	8510300271	50-423	S	
	8510070275	50-423	K	8510310093	50-423	F	
	8510070291	TOPREP		8510310095*	50-423	F	
	8510070303	50-245	P	8510310100	50-245	S	
	8510070319	50-423	E	8510310126	50-245	P	
	8510070441	50-245	P	8510310205	50-423	A	
	8510070444	50-423	A	8510310214	50-423	A	
	8510080040	50-423	E	8510310220	50-423	K	
	8510080145	50-423	E	8510310225*	50-423	K	
	8510080265	50-423	A	8510310402	50-336	S	
	8510080385	50-245	P	8510310502	50-245	S	
	8510080468	50-423	E	Northeast Utilities Service Co. (subs. o	8510160315*	TOPREP	
	8510080470	50-245	P	Northeast Utilities)			
	8510090069	50-423	A	Northern States Power Co.	8510010299	50-282	P
	8510090177	50-423	S		8510010650	50-282	R
	8510100135	50-245	P		8510020103	50-263	R
	8510100163	50-336	P		8510030017	50-263	P
	8510100186	50-336	P		8510070449	50-282	P
	8510100180	50-423	A		8510070449	50-282	P
	8510110009	50-423	A		8510080101	50-282	Q
	8510110022	50-423	A		8510080505	50-263	F
	8510110037	50-245	P		8510090209	50-282	P
	8510110078	50-423	A		8510100037	50-263	F
	8510110092	50-423	A		8510160181	50-282	F
	8510110115	50-423	E		8510160252	50-263	P
	8510110131	50-423	E		8510180063	50-282	P
	8510110189	50-423	A		8510210276	50-282	S
	8510110226	50-423	A		8510220157	50-282	S
	8510150065	50-423	A		8510220361	50-263	Q
	8510150067	50-245	P		8510220363*	50-263	Q
	8510150233	50-423	S		8510230121	50-282	R
	8510150284	50-213	F		8510230121	50-282	R
	8510150305	50-423	A		8510230124*	50-282	R
	8510150327	50-423	A		8510240242	50-263	F
	8510150351	50-423	A		8510280055	50-263	F
	8510150369	50-245	P		8510290371	50-263	P
	8510160019	50-423	A		8510290375*	50-263	P
	8510160052	50-423	F		8510290378*	50-263	P
	8510160283	NUREG			8510310137	50-282	Q
	8510160314	TOPREP			8510310304	50-282	F
	8510170051	50-336	S		8510310366	50-282	P
	8510170068	50-423	A	Nuclear Associates International	8510080130*	CONTRACT	
	8510170098	50-213	P	Nuclear Assurance Corp.	8510110248*	71-9010	
	8510170098	50-213	P	Nuclear Construction Issues Group	8510010324	50-259	Q
	8510170245	50-245	S	Nuclear Energy Services, Inc.	8510230194*	50-367	Q
	8510170286	50-423	A	Nuclear Fuel Services, Inc. (subs. of	8510110064	70-143	
	8510180245	50-423	A	Getty Oil Co.)			
	8510180353	50-423	A		8510150032	70-143	
	8510220021	50-423	A		8510150033	70-143	
	8510220033	50-245	P		8510240132	70-143	
	8510220065	50-423	A		8510240169	70-143	
	8510220145	50-423	A		8510250041	70-143	
	8510220150	50-423	A	Nuclear Information & Resource Service	8510180465	50-483	P
	8510220158	50-213	P	Nuclear Materials, Inc.	8510290472	XPORTLIC	
	8510220158	50-213	P	Nuclear Metals, Inc.	8510160310*	40-672	
	8510220158	50-213	P		8510160313*	40-672	
	8510220186	50-213	P		8510160316*	40-672	
	8510220186	50-213	P		8510160317*	40-672	
	8510220186	50-213	P	Nuclear Packaging, Inc.	8510090058	WASTE MGT	
	8510220234	50-423	E		8510090459	71-9200	
	8510220244	50-423	A	Nuclear Pharmacy, Inc.	8510100168	PR	
	8510220247	50-245	P	Nuclear Reactor Laboratory	8510170165	50-20	R
	8510220295	50-245	P	Nuclear Utility Management & Human	8508010128*	MISC	
	8510220313	50-245	P	Resources Committee (NUMARC)			
	8510230031	50-245	P	Nuclear Waste Consultants, Inc.	8510080574*	CONTRACT	
	8510230034	50-423	A		8510080575*	CONTRACT	
	8510240003	50-245	P	Nucleon Lectern Associates, Inc.	8510250351	FOIA	
	8510240078	50-245	P	O'Donnell Consulting Engineers, Inc.	8510090423*	CONTRACT	
	8510240089	50-245	P	Oak Ridge National Laboratory	8510030309	NUREG	
	8510240256	50-423	A		8510030312	NUREG	
	8510240287	50-245	F		8510040318	NUREG	
	8510240335	50-245	P		8510040371	NUREG	
	8510240373	50-245	P		8510040402	NUREG	
	8510240382	50-245	P		8510090445	WASTE RES	
	8510240410	50-245	P		8510150203*	50-361	P

392 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510220095	71-9202		8510010428*	50-272	V
	8510240030	WASTE RES		8510010591	50-387	R
	8510240123	WASTE RES		8510020139	50-387	R
	8510240133	WASTE RES		8510020141*	50-387	R
	8510240147	WASTE RES		8510030032	50-388	P
	8510240344	WASTE RES		8510030058*	50-388	P
	8510250590	WASTE RES		8510070007	50-387	S
Ogle Petroleum, Inc. of California	8510170458	40-8745		8510070154	50-387	F
	8510180001	40-8745		8510070154	50-387	F
Ohio Citizens for Responsible Energy	8510220372	50-440	G	8510070304	50-387	F
	8510240405	50-440	G	8510070304	50-387	F
	8510280330	NUREG		8510080034	50-387	F
Ohio State Univ., Columbus, OH	8510280253	50-150	Q	8510080410	50-387	F
Ohio, State of	8510040474	50-440	F	8510150321	50-387	P
	8510150206*	50-346	U	8510150399	50-387	P
Ohmart Corp.	8510110211	PR		8510150401*	50-387	P
Old Dominion Fabricators	8510110243	71-552		8510170140	50-388	P
	8510110252	71-552		8510170144*	50-388	P
	8510110253*	71-552		8510170151*	50-388	P
Omaha Public Power District	8510010426	50-285	F	8510170201	50-387	P
	8510080044	50-285	P	8510170201	50-387	P
	8510080147	50-285	P	8510180089	50-387	S
	8510100059	50-285	Q	8510180275	50-387	P
	8510160062	50-285	P	8510180281*	50-387	P
	8510170226	50-285	F	8510220060	50-387	P
	8510230021	50-285	P	8510220214	50-387	F
	8510230026	50-285	Q	8510220214	50-387	F
	8510230099	50-285	F	8510230183	50-387	Q
	8510230313	50-285	R	8510250425	50-387	F
	8510240398	50-285	F	8510150291*	50-272	H
	8510240403	50-285	F	8510150291*	50-272	H
	8510250307	50-285	F	8510150291*	50-272	H
	8510290208	50-285	F	8510150295*	50-272	H
	8510290240	50-285	F	8510150295*	50-272	H
Oregon State Univ., Corvallis, OR	8510290115	50-243	P	8510150295*	50-272	H
	8510290374	50-243	R	8510240666	50-289	G
	8510290586	50-243	R	8510310319	50-352	G
Oregon, State of	8510100162	PR		8510100184	40-8027	
	8510240553	WASTE MGT		8510170331	40-6659	
	8510290383	PR				
PSE&G Research Corp.	8510180474*	50-272	R	8510180432	40-6659	
Pacific Gas & Electric Co.	8510010239	50-275	F	8510180437*	40-6659	
	8510010239	50-275	F	8510180439*	40-6659	
	8510010414	50-133	R	8510180441*	40-6659	
	8510010612	50-275	R	8510010215	50-277	S
	8510010644	50-275	S	8510010606	50-352	S
	8510020043	50-275	K	8510010618	50-277	S
	8510020046*	50-275	K	8510010629*	50-277	S
	8510030271	50-133	P	8510010633*	50-277	S
	8510040112	50-323	S	8510010642	50-277	S
	8510060396	50-323	S	8510020031	50-352	P
	8510150185	50-275	S	8510030011	50-352	G
	8510160043	50-133	P	8510040076	50-278	S
	8510160151	50-275	E	8510040087	50-277	S
	8510160282	50-133	G	8510070232	50-352	K
	8510170275	50-275	J	8510070232	50-352	K
	8510180020	50-275	P	8510070247*	50-352	F
	8510180020	50-275	P	8510070248*	50-352	K
	8510180050	71-9176		8510070248*	50-352	K
	8510180139	50-275	F	8510070257*	50-352	K
	8510180139	50-275	F	8510070257*	50-352	K
	8510180143*	50-275	F	8510070257*	50-352	K
	8510180143*	50-275	F	8510070542	50-278	S
	8510180546	71-9073		8510080268	50-352	F
	8510210286	50-275	S	8510080274	50-277	Q
				8510150069	50-352	F
	8510230135	50-133	P	8510150110	50-277	P
	8510280362	50-275	P	8510150241	50-352	S
	8510280362	50-275	P	8510150250	50-277	S
	8510280400	50-133	F	8510160318	50-277	F
	8510290059	50-275	P	8510160319*	50-277	F
	8510290059	50-275	P	8510170407	50-352	S
	8510290062*	50-275	P	8510170416	50-277	S
	8510290062*	50-275	P	8510163017	50-352	K
	8510290069*	50-275	P	8510180144	50-277	F
	8510290069*	50-275	P	8510180240	50-352	T
	8510290267	50-275	P	8510210038	50-352	G
	8510290267	50-275	P	8510210065	50-277	F
	8510290276*	50-275	P	8510210065	50-277	F
	8510290276*	50-275	P	8510210148	50-277	P
	8510290285*	50-275	P	8510210147*	50-277	P
	8510290285*	50-275	P	8510210147*	50-277	P
	8510290285*	50-275	P	8510210151*	50-277	P
	8510300065	50-275	P	8510210299	50-277	R
Parameter, Inc.	8510010005*	CONTRACT		8510220251	50-277	P
	8510040499*	CONTRACT		8510220251	50-277	P
	8510040583*	CONTRACT		8510220251	50-277	P
				8510230028	50-278	Q
	8510110103*	CONTRACT		8510240279	50-352	G
	8510160264	50-29	Q	8510240279	50-352	G
Paul-Munroe Hydraulics, Inc.	8510240254	50-334	S	8510250146*	50-277	Q
Pennsylvania Power & Light Co.	8510010165	50-387	P	8510250401	50-277	Q

CORPORATE SOURCE INDEX 393

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510280434	50-352		8510210068*	50-443
	8510290076	50-352		8510250489	50-443
	8510290076	50-352		8510280416	70-3027
	8510290150	50-352		8510280419*	70-3027
	8510290341	50-352		8510300138	50-443
	8510290367	50-352	Public Service Electric & Gas Co. of New Jersey	8509250119	50-354
	8510290376*	50-352		8509250123*	50-354
	8510300242	50-277		8510010428*	50-361
	8510300244	50-352		8510010428*	50-272
	8510300253	50-277		8510010608	50-311
	8510310161	50-352		8510020195	50-354
Phoenix Associates, Inc.	8510080376*	CONTRACT		8510020200*	50-354
	8510150481*	CONTRACT		8510020205*	50-354
Phoenix International Photocraft Custom Lab, Inc.	8510030434*	CONTRACT		8510020226*	50-272
	8510150036*	CONTRACT		8510030031	50-354
Pickard, Lowe & Garrick, Inc.	8510090212*	50-327		8510030040	50-354
	8510090212*	50-327		8510030087	50-272
	8510090220*	50-327		8510030103	50-354
	8510090220*	50-327		8510030148	50-354
	8510250359*	50-289		8510030422	50-354
Plateau Resources, Ltd.	8510170393	40-8674		8510080074	50-311
	8510170433	40-8674		8510080086	50-272
Portland General Electric Co.	8510010601	50-344		8510080091*	50-272
	8510030104	50-344		8510080091*	50-272
	8510030112*	50-344		8510080108	50-272
	8510030117*	50-344		8510080206	50-311
	8510070013	50-344		8510080209*	50-311
	8510080041	50-344		8510080260*	50-311
	8510080095	50-344		8510080422	50-354
	8510080188	50-344		8510080424*	50-354
	8510090230	50-344		8510080428*	50-354
	8510150192	50-344		8510090185	50-272
	8510160053	50-344		8510090190*	50-272
	8510160060*	50-344		8510090192*	50-272
	8510160064*	50-344		8510150222	50-354
	8510160299	50-344		8510170236	50-354
	8510220151	50-344		8510170382	50-272
	8510290214	50-344		8510170387*	50-272
	8510290342	50-344		8510180292	50-354
	8510290169	50-344		8510180471	50-272
	8510300300	50-344		8510210108	50-354
Prairie Investors (Wireline Service)	8510310228	50-344		8510220050	50-272
Pro-Technics, Inc.	8510100094	PR		8510220050	50-272
Professional Loss Control, Inc.	8510040294	PR		8510220050	50-272
	8510070117*	50-346		8510220068	50-272
Providence Hosp., Anchorage, AK	8510040291	REGGD		8510220068	50-272
Prudential Insurance Co. of America	8510100032	REGGD		8510220119	50-272
Public Service Co. of Colorado	8510010010	50-267		8510220209	50-354
	8510080001	50-267		8510220262	50-272
	8510080005	50-267		8510220262	50-272
	8510080007	50-267		8510220265*	50-272
	8510080219	50-267		8510220265*	50-272
	8510090077	50-267		8510220270	50-272
	8510090149	50-267		8510220300	NUREG
	8510090154	50-267		8510220315	50-272
	8510090201	50-267		8510220315	50-272
	8510090263*	50-267		8510220316	50-272
	8510090353	50-267		8510220319*	50-272
	8510160075	50-267		8510220320	50-272
	8510160079	PR		8510220326*	50-272
	8510160173	50-267		8510220329	50-354
	8510170117	50-267		8510220334*	50-354
	8510170171	50-267		8510220353	50-272
	8510170457	50-267		8510220354*	50-272
	8510170462	50-267		8510240050	50-272
	8510180168	50-267		8510240106	50-272
	8510220237	50-267		8510240106	50-272
	8510220407	50-267		8510240116*	50-272
	8510220436	50-267		8510240116*	50-272
	8510230052	50-267		8510240185	50-311
	8510230093	50-267		8510240387	50-311
	8510240158	50-267		8510240396	50-272
	8510290122	50-267		8510240649	50-272
	8510310165	50-267		8510250081	50-272
	8510310317*	50-267		8510250081	50-272
	8510310532*	50-267		8510250092*	50-272
	8510310566	50-267		8510250092*	50-272
Public Service Co. of Indiana, Inc.	8510080202	50-546		8510250446	50-354
Public Service Co. of New Hampshire	8510030080	50-443		8510250481	50-354
	8510030080	50-443		8510250482*	50-354
	8510080022	50-443		8510250483*	50-354
	8510100050	50-443		8510250484*	50-354
	8510150121	50-443		8510250486*	50-354
	8510150121	50-443		8510250487*	50-354
	8510150223	50-443		8510250488*	50-354
	8510150223	50-443		8510250490*	50-354
	8510150293	50-443		8510250492*	50-354
	8510150293	50-443		8510280295	50-354
	8510210062	50-443		8510290373	50-354

394 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510290377*	50-354	F	S. Cohen & Associates, Inc.	8510030131	NUREG
	8510290527	50-272	S	Sacramento Municipal Utility District	8510020030	50-312
	8510300101	50-354	S		8510040002	50-312
	8510300126	50-354	S		8510040240	50-312
	8510300179	50-354	F		8510070180	50-312
	8510310089	50-354	F		8510070276	50-312
	8510310176	50-354	F		8510080039	50-312
	8510310180	50-354	F		8510080047	50-312
Pulaski Community Hosp., Pulaski, VA	8510100137	PR			8510080048*	50-312
Purdue Univ., West Lafayette, IN	8510090412*	50-320	P		8510080125	50-312
	8504090467	50-498	A		8510080203	50-312
Quadrax Corp.	8510080191*	CONTRACT			8510080208	50-312
R&D Associates	8510210157	40-8724			8510080221	50-312
Radiation Management Corp.	8510220200*	40-2061			8510080255	50-312
	8510040383	PR			8510080501	50-312
Radiation Monitoring Devices, Inc.						
Ralph M. Parsons Co.	8510010440	TOPREP			8510090266	50-312
	8510010445*	TOPREP			8510110208	71-9176
Ratner, M.G.	8510040421	TOPREP			8510110218	50-312
	8510040423	TOPREP			8510170348	50-312
Reed College, Portland, OR	8510040111	50-288	F		8510210019	50-312
	8510040114*	50-288	F		8510210059	50-312
	8510080489	50-288	P		8510210066*	50-312
	8510080491*	50-288	P		8510220172	50-312
	8510220228	50-288	F		8510220266	50-312
	8510220232*	50-288	F		8510230116	50-312
Reliance Electric Co. (subs. of Exon Corp.)	8510020254*	FOIA			8510240127	50-312
Rio Algom Corp.	8510090512	40-8084			8510240378	50-312
	8510090513*	40-8084			8510250093	50-312
Roath & Brega, P.C.	8510180105	40-8745			8510280007	50-312
					8510280121	50-312
Robert L. Cloud Associates, Inc.	8504250409	50-275	P		8510280128*	50-312
	8504250410*	50-275	P		8510290138	50-312
Rochester Gas & Electric Corp.	8510010032	50-244	S		8510290146*	50-312
	8510010422	50-244	R		8510290151	50-312
	8510040425	50-244	Q		8510290289	50-312
	8510110231	50-244	F		8510290356	50-312
	8510180002	50-244	Q	Saluda River Electric Cooperative, Inc.	8510020158	50-413
	8510180267	50-244	P	San Diego Gas & Electric Co.	8510170101*	50-361
	8510180132	50-244	P	Sandia National Laboratories	8510010219	NUREG
	8510210050	50-244	P		8510040354	NUREG
	8510210127	50-244	P		8510040365	NUREG
	8510210130*	50-244	P		8510040381	NUREG
	8510210134*	50-244	P		8510090272	WASTE RES
	8510220092	50-244	P		8510090518	WASTE RES
	8510220096*	50-244	P		8510220385	50-458
	8510220099*	50-244	P		8510230308	WASTE RES
	8510220274	50-244	P		8510240020	WASTE RES
	8510220278*	50-244	P		8510240153	WASTE RES
	8510220283*	50-244	P		8510240162	WASTE RES
	8510220371	50-244	P		8510240362	WASTE RES
	8510220376*	50-244	P		8510240367	WASTE RES
	8510220379*	50-244	P		8510280470	NUREG
	8510240248	50-244	S		8510290410	NUREG
	8510240644	50-244	S	Sangamo Weston, Inc.	8510160070	PR
	8510310242	50-244	F	San Jose, CA	8510100123	PR
Rockbestos Co.	8510300168	QA999		Sargent & Lundy, Inc.	8510170123*	50-267
	8510300172*	QA999			8510170127*	50-267
	8510300178*	QA999			8510250384*	50-461
Rockwell International Corp.	8510220196*	70-25			8510290352	50-267
Rocky Mountain Energy Co.	8510090173	40-8452			8510290366	50-267
Rocky Mountain Physics, Inc.	8510100118	PR		Science & Engineering Associates, Inc.	8510030131	NUREG
Ropes & Gray	8510020145	50-445	G	Science Applications International Corp.	8507160361*	50-322
	8510020145	50-445	G	(formerly Science Applications, Inc.)	8507160361*	50-322
	8510020268	50-445	G		8507160711*	50-424
	8510020268	50-445	G		8507160711*	50-424
	8510180232	50-445	G		8507160711*	50-424
	8510180232	50-445	G		8509170394*	50-237
	8510180255	50-445	G		8510020438*	50-245
	8510180255	50-445	G		8510030329*	CONTRACT
	8510240371	50-445	G		8510080010*	CONTRACT
	8510240371	50-445	G		8510150480*	50-454
	8510280518	50-445	G		8510170159*	50-322
	8510290004	50-445	G		8510170159*	50-322
	8510290004	50-445	G		8510170159*	50-322
	8510290032	50-445	G		8510170169*	50-322
	8510290032	50-445	G		8510170169*	50-322
	8510290258	50-445	G		8510170174*	50-322
	8510290258	50-445	G		8510170174*	50-322
Roem, B.	8510110221	50-456	G		8510170178*	50-322
	8510110221	50-456	G		8510170178*	50-322
	8510110222*	50-456	G		8510170180*	50-322
	8510110222*	50-456	G		8510170180*	50-322
	8510160127	50-456	G		8510170184*	50-322
	8510160208	50-456	G		8510170184*	50-322
	8510240490	50-456	G		8510170187*	50-322
Runkle, J.D.	8510030009	50-400	G		8510170187*	50-322
	8510030082	50-400	G		8510170190*	50-322
	8510180159	50-400	G		8510170190*	50-322
Rural Electrification Administration	8510020102*	MISC			8510170193*	50-322

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510170193*	50-322		8510160101	PR
	8510170199*	50-322		8510310331	50-416
	8510170199*	50-322	South Mississippi Electric Power Association		P
	8510170202*	50-322	Southampton, NY	8510100087	50-322
	8510170202*	50-322		8510280519	50-322
					G
	8510170205*	50-322		8510010073	50-361
	8510170205*	50-322	Southern California Edison Co.	8510010079*	50-361
	8510170211*	50-322		8510010428*	50-389
	8510170211*	50-322		8510010428*	50-389
	8510170213*	50-322		8510010628	50-206
					S
	8510170213*	50-322		8510010641	50-206
	8510170215*	50-322		8510020113	50-361
	8510170215*	50-322		8510020114*	50-361
	8510170217*	50-322		8510020119*	50-361
	8510170217*	50-322		8510020212	50-361
					S
	8510240036*	CONTRACT		8510040287	50-361
	8510250613*	50-271		8510070179	50-206
	8510280074*	50-285		8510070179	50-206
	8510310011*	50-334		8510070179	50-206
	8510310032*	50-315		8510070185*	50-206
					F
	8510310390*	50-219		8510070185*	50-206
	8510040472*	CONTRACT		8510070185*	50-206
Sciencetech, Inc.	8510070297	NUREG		8510090007	50-206
Seacoast Anti-Pollution League	85100100197	PR		8510090011*	50-206
Seaman Nuclear Corp.	8510010143*	50-289		8510090016*	50-206
Senate					F
	8510010210*	50-289		8510090025*	50-203
	8510010344*	50-289		8510090183	50-361
	8510010405*	FOIA		8510100024	50-206
	8510010443*	FOIA		8510100034	50-206
	8510150300*	50-272		8510100036	50-206
					P
	8510180282	PR		8510100080	50-206
	8510250030*	50-302		8510100083	50-206
Senate, Banking, Housing & Urban Affairs	8510090486*	COMMISSIO		8510100092	50-206
Senate, Environment & Public Works	8510110124*	COMMISSIO		8510100104	50-206
Sequoyah Fuels Corp. (subs. of Kerr-McGee)	8510170332	40-8768		8510100124	50-206
					P
Nuclear Corp.)				8510110105	50-361
	8510220241*	40-8027		8510110105	50-361
Shaw, Pittman, Potts & Trowbridge	8510020265	50-320		8510110108*	50-361
	8510100048	50-289		8510150141	50-361
	8510100126	50-424		8510150141	50-361
					P
	8510110193	50-440		8510150177*	50-206
	8510150354	50-440		8510150199	50-361
	8510160120	50-289		8510150199	50-361
	8510180164	50-289		8510160046	50-206
	8510180215	50-440		8510170090	50-361
					P
	8510180308	50-400		8510170090	50-361
	8510180340	50-400		8510170101*	50-361
	8510180351	50-440		8510170101*	50-361
	8510220378	50-424		8510170106*	50-361
	8510240235	50-400		8510170106*	50-361
					P
	8510240671	50-400		8510170179	50-206
	8510240673	50-289		8510170267	50-361
	8510280516	50-289		8510170267	50-361
	8510290053	50-400		8510170365	50-361
	8510290358	PR		8510170455	50-361
					S
	8510310337	50-289		8510180167	50-361
Shoreham Opponents Coalition	8510220201	50-322		8510180167	50-361
	8510220314	50-322		8510180173*	50-361
Sierra Club	8510100002	PR		8510180173*	50-361
Sigma Research, Inc.	8510080354*	CONTRACT		8510180328	50-361
					P
Sinclair, M.	8510080379*	50-329		8510180328	50-361
	8510080444*	50-329		8510180336*	50-361
Small Business Administration	8510030162*	CONTRACT		8510180336*	50-361
	8510030434*	CONTRACT		8510180358	50-362
	8510070129*	CONTRACT		8510210024	50-206
					P
Smyth County Community Hosp. Marion, VA	8510110224	PR		8510210290	50-361
	8510150193	PR		8510220127	50-361
Society of Nuclear Medicine	8510100154	PR		8510220127	50-361
	8510180327	PR		8510220152	50-206
Sohio Chemical Co. (subs. of Standard Oil Co., Ohio)	8510210230	40-7604		8510220174	50-206
					P
	8510210236*	40-7604		8510250568	50-362
South Carolina Electric & Gas Co.	8510010212	50-395		8510280285	50-361
	8510010428*	50-389		8510280285	50-361
	8510020065	50-395		8510280296	50-361
				8510280296	50-361
					R
	8510030041	50-395		8510280419	50-361
	8510040376	50-395		8510280419	50-361
	8510100026	50-395		8510290133	50-206
	8510160129	50-395		8510290306	50-206
	8510230141	50-395		8510290355	50-362
					S
	8510230147*	50-395		8510300165	50-362
	8510240222	50-395		8510300224	50-206
	8510240234*	50-395		8510310277	50-206
	8510240305	50-395		8510310277	50-206
	8510250185	50-395		8510310277	50-206
					F
	8510300008	50-395		8510310549	50-361
South Carolina, State of	8510080249	50-238		8510310591	50-362
	8510080254*	50-238		8510310598	50-362
	8510080257*	50-238		8510010324	50-259
			Southern Co. Services, Inc.		Q

396 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510010324	50-259	Q	8510070340*	50-259	P
	8510010324	50-259	Q	8510070340*	50-259	P
	8510010378*	50-259	Q	8510070486	50-259	Q
	8510010378*	50-259	Q	8510070545	50-259	S
	8510010378*	50-259	Q	8510070553	50-259	R
	8510010378*	50-259	Q			
	8510010378*	50-259	Q	8510070553	50-259	R
	8510010378*	50-259	Q	8510070553	50-259	R
	8510030044	50-424	F	8510080348	50-438	Q
	8510030044	50-424	F	8510080442	50-259	P
	8510070302	50-424	E	8510080442	50-259	P
	8510300191	50-424	A	8510080442	50-259	P
Spain, Govt. of	8510280498	XPORTLIC		8510080442	50-259	P
Squire, Sanders & Dempsey	8510170015	40-8355		8510080442	50-259	P
Stamiris, B.	8208030689*	50-329	A	8510080442	50-259	P
	8510080295*	50-329	O	8510080442	50-259	P
	8510080373*	50-329	A	8510080465	50-390	A
Stan A. Huber Consultants, Inc.	8510110211	PR		8510080465	50-390	A
	8510250432	PR		8510090012	50-390	A
Stanford Research Institute	8510230223*	50-400	T	8510090012	50-390	A
State, Dept. of, Bureau of Oceans & Intl	8510090028	XPORTLIC		8510090020	50-259	S
Environ. & Scientific Affairs	8510150180	XPORTLIC		8510090130	50-327	P
	8510150189	XPORTLIC		8510090130	50-327	P
	8510220437	XPORTLIC		8510090134*	50-327	P
Stone & Webster Engineering Corp.	8510110192*	50-423	A	8510090134*	50-327	P
				8510090200	50-327	P
	8510110227*	50-423	A	8510110155	71-6722	
	8510180355*	50-423	A	8510150060	50-327	F
	8510180356*	50-423	A	8510150106	50-327	P
	8510290319	QA999		8510150106	50-327	P
	8510290323*	QA999		8510150174	50-259	F
	8510310219*	50-423	A	8510150174	50-259	F
Suffolk County, NY	8510110004	50-322	G	8510150383	50-259	P
	8510110180	50-322	G	8510150383	50-259	P
	8510110 96	50-322	G	8510150455	50-327	S
	8510280514	50-322	G	8510160088	50-438	A
Sunflower Alliance	8510100014	50-440	G	8510160136	50-438	A
	8510100014	50-440	G	8510160139	50-390	A
	8510100145	50-440	G	8510160153	50-259	P
	8510100145	50-440	G	8510160153	50-259	P
	8510310266	50-440	G	8510160153	50-259	P
	8510310266	50-440	G	8510160200	50-327	P
	8510310272	50-440	G	8510160200	50-327	P
	8510310272	50-440	G	8510160242	50-259	F
TDI (Transamerica Delaval, Inc.) Owners Group	8510290116*	50-460	S	8510160242	50-259	F
				8510160242	50-259	F
TENERA Corp. (subs. of TERA Corp.)	8510170127*	50-267	P	8510160265	50-327	P
	8510260352	50-267	P	8510160265	50-327	P
Technical Analysis Corp.	8510010355	50-364	V	8510170370	50-259	S
Teledyne Energy Systems	8510110126	71-5862		8510180021	50-259	Q
	8510110140*	71-5862		8510180021	50-259	Q
	8510110145*	71-5862		8510180021	50-259	Q
Teledyne Engineering Services	8510010092*	50-445	A	8510180030	50-259	Q
	8510030404*	50-445	A	8510180048	50-327	Q
	8510310244*	50-293	P	8510180048	50-327	Q
Teledyne Isotopes	8510220399	50-454	R	8510180069	50-259	Q
Tennessee Valley Authority	8510010048	50-327	P	8510180387	50-259	S
	8510010048	50-327	P	8510220196	50-390	F
	8510010087	50-259	F	8510220196	50-390	F
	8510010087	50-259	F	8510220199*	50-390	F
	8510010087	50-259	F	8510220199*	50-390	F
	8510010379	50-390	F	8510220328	NUREG	
	8510010379	50-390	F	8510220374	50-259	P
	8510010487	50-259	R	8510220374	50-259	P
	8510010617	50-327	S	8510220374	50-259	P
	8510020108	50-327	R	8510220374	50-259	P
	8510020220	50-327	S	8510230024	50-259	P
	8510030045	50-327	P	8510240043	50-327	R
	8510030045	50-327	P	8510240043	50-327	R
	8510030061	50-259	F	8510240045*	50-327	R
	8510030068	50-259	Q	8510250293	50-254	R
	8510030273	50-438	S	8510250293	50-259	R
	8510030273	50-438	S	8510250293	50-259	R
	8510030275	50-438	S	8510250440*	50-259	R
	8510030275	50-438	S	8510250440*	50-259	R
	8510030278	50-390	S	8510250440*	50-259	R
	8510030280	50-390	S	8510280147	50-259	Q
	8510030300	50-438	S	8510280147	50-259	Q
	8510030300	50-438	S	8510280147	50-259	Q
	8510030355	50-327	S	8510280147	50-259	Q
	8510040102	50-327	S	8510280147	50-259	Q
	8510040132	50-390	F	8510280147	50-259	Q
	8510040479	50-296	S	8510280331	50-259	P
	8510070335	50-259	Q	8510280331	50-259	P
	8510070335	50-259	Q	8510280331	50-259	P
	8510070335	50-259	Q	8510290012	50-390	F
	8510070336	50-259	P	8510290012	50-390	F
	8510070336	50-259	P	8510290097	50-390	A
	8510070336	50-259	P	8510290097	50-390	A
	8510070340*	50-259	P	8510290159	50-327	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510290159	50-327		8510290003	50-445
	8510290166*	50-327		8510290003	50-445
	8510290166*	50-327		8510290021*	50-445
	8510290296	50-327		8510290021*	50-445
	8510290331	50-327		8510290032	50-445
	8510290331	50-327		8510290032	50-445
	8510290470	50-259		8510290258	50-445
	8510300021	50-390		8510290258	50-445
	8510300038	50-518		8510300005	50-445
	8510310184	50-327		8510300005	50-445
	8510310184	50-327		8510300011*	50-445
	8510310184	50-327		8510300011*	50-445
	8510310184	50-327		8510300051	50-445
	8510310184	50-327		8510300051	50-445
	8510310233	50-327	Texas, State of	8510160095	FR
	8510310259	50-390		8510080322	WASTE MGT
	8510310259	50-390	Texas, Univ. of, Austin, TX	8510080343	WASTE MGT
	8510100058	PR		8510080605	WASTE MGT
	8510180478	40-878*		8510090327	WASTE MGT
Tennessee, State of				8510160155	50-602
Teton Exploration Drilling Co., Inc.					A
(subs. of UNC Resources, Inc.)					
Texas A&M Univ., College Station, TX	8510080058	50-128		8510160158*	50-602
	8510310435	50-59		8510160286	50-602
Texas Medical Association (TMA)	8510040383	PR		8510280102	WASTE MGT
Texas Transportation Institute, Texas A&M Univ., College Station, TX	8510290429*	50-424	Thero Special Services, Inc.	8510040396	50-382
			Thomas E. Summerlee & Associates, Inc.	8510040405	PR
Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.)	8510010639	50-445	Three Mile Island Alert	8510110156	50-289
	8510020145	50-445		8510230039	50-289
	8510020145	50-445		8510240675	50-289
	8510020268	50-445	Times-Picayune, La Place, LA	8510040459	50-382
	8510020268	50-445	Toledo Edison Co.	8311290219*	50-346
	8510020268	50-445		8510010086	50-346
	8510040263	50-445		8510010086*	50-346
	8510040263	50-445		8510010196	50-346
	8510080199*	50-445		8510010331	50-346
	8510080216*	50-445		8510010410	50-346
	8510080368*	50-445		8510040285	50-346
	8510080478*	50-445		8510040453	50-346
	8510090336	50-445		8510070106*	50-346
	8510090336	50-445		8510070123*	50-346
	8510090339	50-445		8510070123*	50-346
	8510090339	50-445		8510070125*	50-346
	8510090430	50-445		8510070133*	50-346
	8510090430	50-445		8510070133*	50-346
	8510090440	50-445		8510070161*	50-346
	8510090440	50-445		8510070262*	50-346
	8510090448	50-445		8510080035	50-346
	8510090448	50-445		8510090008	50-346
	8510090458	50-445		8510090009	50-346
	8510090468	50-445		8510110143	50-346
	8510100001	50-445		8510110144*	50-346
	8510110228	50-445		8510150391	50-346
	8510110228	50-445		8510150393	50-346
	8510150355	50-445		8510160055	50-346
	8510150355	50-445		8510160065	50-346
	8510150454*	50-445		8510160112	50-346
	8510170183	50-445		8510160203	50-346
	8510170183	50-445		8510160209	50-346
	8510180159	50-445		8510160301	50-346
	8510180159	50-445		8510210072	50-346
	8510180232	50-445		8510220036	50-346
	8510180232	50-445		8510220040*	50-346
	8510180255	50-445		8510220368	50-346
	8510180255	50-445		8510230013	50-346
	8510210131	50-445		8510230025	50-346
	8510210284	50-445		8510230117	50-346
	8510210284	50-445		8510230120*	50-346
	8510220058	50-445		8510230122*	50-346
	8510220058	50-445		8510240023	50-346
	8510220110	50-445		8510240039	50-346
	8510220110	50-445		8510240040*	50-346
	8510220292*	50-445		8510250371	50-346
	8510220312*	50-445		8510280284	50-346
	8510220397	50-445		8510280317	50-346
	8510220403	50-445		8510280343	50-346
	8510220403	50-445		8510280346*	50-346
	8510240371	50-445		8510280406	50-346
	8510250321	50-445		8510280408	50-346
	8510250321	50-445		8510290217	50-346
	8510250370	50-445		8510290357	50-346
	8510250370	50-445		8510290359*	50-346
	8510280224	50-445		8510310234	50-346
	8510280484	50-445		8510310313	50-346
	8510280484	50-445	Tompkins-Beckwith, Inc.	8510010432*	50-382
	8510280487	50-445		8510010439*	50-382
	8510280493	50-446		8510010441*	50-382
	8510280500	50-445		8510150075	XPORTLIC
	8510280500	50-445	Transnuclear, Inc.	8510150087	71-9202
	8510280514	50-445		8510150095	71-9202
	8510280518	50-445		8510150098*	71-9202

398 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8510150102*	71-9202	Co.)	8510010451	50-338
	8510220128	XPORTLIC		8510010456*	50-338
	8510220465	XPORTLIC		8510010456*	50-338
	8510250593	XPORTLIC		8510010603	50-338
	8510310081	XPORTLIC			
	8510310086*	XPORTLIC		8510010643	50-280
Traupper Mining, Inc.	8510100097	PR		8510010643	50-280
Tril Lawyers for Public Justice, P.C.	8510100185	50-445	G	8510020071	50-338
	8510220293	50-445	G	8510020071	50-338
	8510310276	50-445	G	8510030013	50-339
Triar Enterprises	8510040352	PR		8510030020*	50-339
Troutman, Sanders, Lockman & Ashmore	8510230010	50-424	G	8510030116	50-338
	8510240213	50-424	G	8510040082	50-338
Tulsa Gamma Ray, Inc.	8510110240	71-139		8510040082	50-338
	8510110242*	71-139		8510040137	50-280
Twomey, Latham & Shea	8510100087	50-322	G	8510040137	50-280
U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.)	8510280519	50-322	G	8510040137	50-280
	8510080308	27-48		8510040348	50-280
				8510040348	50-280
	8510100180	PR			
	8510240102	27-39		8510040367	50-280
	8510250183	27-48		8510040374	50-281
	8510250204	27-48		8510070328	50-338
	8510250314	27-48		8510070360	50-280
UMETCO Minerals Corp. (subs. of Union Carbide Corp.)	8510170212	40-299		8510070378	50-338
	8510170397	40-299		8510080153	50-338
	8510170406*	40-299		8510080153	50-338
	8510170408	40-8681		8510080360	50-280
	8510170426	40-299		8510090407	50-338
				8510100086	50-280
UNC Resources, Inc.	8510150119	70-371		8510100086	50-280
Union 76 Minerals	8510170474	40-8584		8510100113	50-280
Union 76 Minerals Exploration Co.	8510180259	40-8584		8510100113	50-280
Union Electric Co.	8510010623	50-483	R	8510100122*	50-280
	8510010646	50-483	S	8510100122*	50-280
	8510010647*	50-483	S	8510150041	50-280
	8510010648	50-483	S	8510150166	50-338
	8510010652	50-483	S	8510150173	50-280
	8510020089	50-483	S	8510160104*	50-338
	8510040075	50-483	Q	8510160104*	50-338
	8510100055	50-483	F	8510170074	50-280
	8510100089	50-483	P	8510170079*	50-280
	8510150384	50-483	F	8510170079*	50-280
	8510170294	50-483	S	8510170079*	50-280
	8510180051	50-483	P	8510170079*	50-280
	8510180060*	50-483	P	8510170079*	50-280
	8510220052	50-483	S	8510170442	50-281
	8510230020	50-483	P	8510180151	50-280
	8510230029*	50-483	P	8510180151	50-280
	8510230067	50-483	P	8510210122	50-338
	8510290111	50-483	F	8510240560	50-338
	8510300001	50-483	P	8510250182	50-338
Union of Concerned Scientists	8510150347	50-289	G	8510280032	50-280
United Engineers & Constructors, Inc. (subs. of Raytheon Co.)	8510030026*	50-333	P	8510280118	50-338
				8510280324	50-338
	8510220340*	50-286	P	8510280326	50-338
	8510290106	QA999		8510280326	50-338
Uranerz USA, Inc.	8510170323	40-8783		8510280372	50-338
	8510170326*	40-8783		8510290047	50-280
Uranium Resources, Inc.	8510170471	40-8786		8510290047	50-280
Utah, State of	8510110255	40-8698		8510290086	50-280
	8510160309	40-3453		8510290086	50-280
	8510240554	WASTE MGT		8510290109	50-280
	8510280086	WASTE MGT		8510290109	50-280
	8510280110	WASTE MGT		8510290197	50-338
Utah, Univ. of, Salt Lake City, UT	8510250529	NUREG		8510290197	50-338
Vector Corp.	8510150269	71-546		8510290253	50-338
	8510150269	71-546		8510290253	50-338
	8510150276*	71-546		8510310353	50-280
	8510150276*	71-546		8510310353	50-280
Vermont Yankee Nuclear Power Corp.	8510080198	50-271	F	8510310357*	50-280
	8510080352	50-271	F	8510310357*	50-280
	8510080390	50-271	Q	8510110187	50-62
	8510090541	71-9080		8510110190*	50-62
	8510110097	50-271	F	8510110190*	50-62
	8510110220	71-9176		8510110194*	50-62
	8510110225	71-9079		8510110194*	50-62
	8510180068	50-271	P	8510030036	50-382
	8510220048	50-271	R	8510030149*	CONTRACT
	8510220212	50-271	P	8510040373	PR
	8510220217*	50-271	P	8510230008	FOIA
	8510240320	50-271	P	8510010291	50-460
	8510280161	50-271	P	8510010382	50-397
	8510290199	50-271	R	8510020096	50-397
	8510310211	50-271	F	8510020104*	50-397
Virginia Polytechnic Institute & State Univ., Blacksburg, VA	8510040503*	CONTRACT		8510030030	50-397
				8510030038*	50-397
Virginia Power (Virginia Electric & Power)	8510280150	50-124	P	8510040103	50-397
	8510010451	50-338	P	8510040104*	50-397

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8510040205	50-397	P		8510220022	TOPREP	
	8510080142	50-397	Q		8510220183	NUREG	
	8510080156	50-508	A	Weston Geophysical Corp.	8510240111	WASTE RES	
	8510080205	50-397	P	White Farm Equipment Co.	8510040373	PR	
	8510080207*	50-397	P	Williams & Associates	8510080087*	CONTRACT	
	8510080242	50-397	P		8510080092*	CONTRACT	
	8510080245	50-508	A		8510090021	WASTE RES	
	8510090163	50-397	P		8510090260	WASTE RES	
	8510090167*	50-397	P		8510090268*	WASTE RES	
	8510090187*	50-397	P		8510090274	WASTE RES	
	8510090285	50-508	S		8510090314	WASTE RES	
	8510110212	50-460	G		8510240268	WASTE RES	
	8510150290	50-397	F		8510240545	WASTE RES	
	8510160067	50-508	A	Wisconsin Electric Power Co.	8510080369	50-266	P
	8510160097	50-397	P		8510080369	50-266	P
	8510160260	50-397	P		8510100128	50-266	S
	8510170082	50-460	A		8510150138	50-266	P
	8510180114	50-397	P		8510150165	50-266	P
	8510180475	50-397	S		8510150165	50-266	P
	8510210095	50-397	P		8510150314	50-266	F
	8510220071	50-397	P		8510160006	50-266	P
	8510220290	50-397	F		8510160006	50-266	P
	8510220318	50-397	P		8510180502	50-266	R
	8510220324*	50-397	P		8510180502	50-266	R
	8510220457	50-460	S		8510220439	50-266	S
	8510280186	50-397	S		8510230111*	50-266	F
	8510290054	50-460	S		8510230111*	50-266	F
	8510290302	50-397	F		8510290043	50-266	P
Washington State Univ., Pullman, WA	8510300046	50-508	A	Wisconsin Public Service Corp.	8510010282	50-305	P
	8510080475*	50-27	Q		8510010291*	50-305	P
	8510150082*	50-27	Q		8510040228	50-305	P
Washington, State of	8510150086*	50-27	Q		8510040232*	50-305	P
	8510090421	WASTE MGT			8510080247	50-305	P
	8510220080*	50-397	P		8510150281	50-305	P
	8510250326	PR			8510150392	50-305	P
	8510250471*	PR			8510150397*	50-305	P
	8510250556	WASTE MGT			8510210292	50-305	R
	8510290207*	WASTE MGT			8510250452	50-305	P
	8510290291*	WASTE MGT			8510250455*	50-305	P
	8510290361	50-397	F		8510290399	50-305	F
Washington, Univ. of, Seattle, WA	8510080461*	50-139	Q	Wisconsin, Univ. of, Madison, WI	8510250290	50-156	P
Webb, R.E. (Studies of Nuclear Hazards & Constitutional Law)	8510250582	50-139	P		8510250577	50-156	P
Westec Services, Inc.	8510090031	50-346	S		8510290401	50-156	R
	8510150228*	50-250	Q	Worcester Memorial Hosp., Worcester, MA	8510070292	PR	
Western Environmental Services & Testing	8510180443*	40-6659		Worcester Polytechnic Institute,	8510230152	50-134	P
	8510180446*	40-6659		Worcester, MA			
Western Fuel, Inc.	8510180105	40-8745		Worsham, Forsythe, Sampels & Woolridge	8510160219	50-445	G
Westinghouse Electric Corp.	8510010161*	50-295	P	(formerly Worsham, Forsythe & Sampels)	8510160219	50-445	G
	8510010258*	CONTRACT			8510160224	50-445	G
	8510030143	40-8502			8510160224	50-445	G
	8510040379*	50-281	P		8510180346	50-445	G
	8510080178*	TOPREP		Worthington Regional Hosp. Worthington, M	8510250432	PR	
	8510090141	TOPREP		Wyle Laboratories	8510170315*	50-413	P
	8510090147*	TOPREP			8510280355*	50-455	A
	8510090150*	TOPREP		Wyoming, State of	8510090222	40-8714	
	8510090216*	50-282	P		8510090267	40-4492	
	8510090221*	50-282	P		8510090269	40-8502	
	8510090344*	XPORTLIC			8510150271	40-4492	
	8510110014*	50-423	A		8510170207	40-8584	
	8510110246*	50-364	P		8510170246	40-8584	
	8510160054*	50-206	P		8510170261	40-8714	
	8510160261*	FOIA			8510170272	40-8714	
	8510160266	TOPREP			8510170336	40-8714	
	8510160268*	FOIA			8510170450	40-8745	
	8510170394	40-8502			8510180284	40-1162	
	8510170430	40-8502			8510180289	40-8786	
	8510180137*	50-244	P		8510180299	40-8745	
	8510180142*	50-244	P	X-Ray, Inc.	8510040373	PR	
	8510210269	70-698		Yakima Indian Nation	8510240582	WASTE MGT	
	8510210271*	70-698		Yankee Atomic Electric Co.	8510010649	50-29	R
	8510220029*	TOPREP			8510030033	50-29	P
	8510230061*	50-455	Q		8510030073	50-29	F
	8510230155*	50-395	P		8510070190	50-213	P
	8510230162*	50-395	P		8510070193*	50-213	P
	8510240192*	WASTE MGT			8510070309	50-29	P
	8510230369	TOPREP			8510070315*	50-29	P
	8510290412*	TOPREP			8510070370	50-29	S
	8510290413*	TOPREP			8510070430	50-29	P
	8510290473	XPORTLIC			8510070433*	50-29	P
Westinghouse Hittman Nuclear, Inc.	8510090409	WASTE MGT			8510080380	50-29	P
	8510090414*	WASTE MGT			8510210093	50-29	P
	8510090543	71-6574			8510210099*	50-29	P
	8510110059	71-9073			8510210119	50-29	P
	8510240188	WASTE MGT			8510210120*	50-29	P
Westinghouse Operating Plants Owners Group	8510080166	TOPREP			8510220024	50-29	P
	8510080561	TOPREP			8510220027*	50-29	P
	8510090320	TOPREP			8510220055	50-29	P
					8510220059*	50-29	P

400 CORPORATE SOURCE INDEX

AUTHOR AFFILIATION

ACCESSION
NUMBER

SUBJECT
CATEGORY

8510220140	50-29	P
8510250341	NUREG	
8510280061	50-29	V

AUTHOR AFFILIATION

ACCESSION
NUMBER

SUBJECT
CATEGORY

8510280175	50-29	F
8510310207	50-29	P
8510310215*	50-29	P

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-233 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
01-0300-1395 R00	8510290174*	50-344	P	NUREG/CR-4272	8510040397	NUREG	EGG-2397
01-0310-1435 R00	8510090033*	50-206	F	NUREG/CR-4280	8510040318	NUREG	ORNL/TM-9660
15298	8510070283*	50-219	R	NUREG/CR-4304	8510040402	NUREG	GSCA-46
15737-2-G03-106 R07	8510040148*	50-320	P	NUREG/CR-4305	8510030312	NUREG	
15737-2-G07-108 R04	8510160102*	50-320	P	NUREG/CR-4325	8510040371	NUREG	ORNL/TM-9682
17769-1	8510280355*	50-455	A	NUREG/CR-4350 V02	8510040381	NUREG	SAND85-1495
4340-3100-85-0156 R0	8510220042*	50-320	P	NUREG/CR-4350 V04	8510290410	NUREG	SAND85-1495
4430-84-007R R02	8510040296*	50-320	P	NUREG/CR-4355 V01	8510020240	NUREG	LBL-20022
47-1159091-00	8510160140*	TOPREP		NUREG/CR-4357	8510040578	NUREG	
47726-1	8510170315*	50-413	P	NUREG/CR-4358	8510040354	NUREG	SAND85-1557
51-1159048-00	8510010352*	50-302	P	NUREG/CR-4376	8510020307	NUREG	EPRI NP-4298
54-725	8510210247*	70-820	25860	NUREG/CR-4379 V01	8510020228	NUREG	
840-240363	8405240363	REJ		NUREG/CR-4382	8510250529	NUREG	
85-183-WSTFO-R1	8510240192*	WASTE MGT		NUREG/CR-4397	8510040592	50-282	P EGG-2420
ATC-8019-1-P-A R02	8510090061*	TOPREP		NUREG/CR-4398	8510030131	NUREG	
BAW-10145-A	8510310411*	TOPREP		NUSCO-137 R01	8510080270*	50-423	A
CCC-450	8510150203*	50-361	P	P-TOP-QA1 R03A	8510010445*	TOPREP	
CEC-20-013 R01	8510090042*	50-285	Q 0397K	PLG-0433	8510250359*	50-289	F
CEN-310-NP	8510220216*	TOPREP		PNL-5336	8510300314*	50-322	S
COM-83-042 R00	8510080515*	50-237	P COM83.0150	PNL-5444	8510310574*	50-445	S
COO-023726 R00	8510250384*	50-461	E	PSE-SE-Z-007	8510250482*	50-354	A
DOE/OR/20722-58	8510150077*	40-8631	25773	PSE-SE-Z-014	8510020205*	50-354	A
EA-7000	8509060182*	50-305	P GL-83-28	PSE-SE-Z-015	8510250483*	50-354	A
EA-768	8510110192*	50-423	A	PSE-SE-Z-016	8510250488*	50-354	A
EGG-EA-6437	8510040100*	50-261	P GL-82-16	PSE-SE-Z-018	8510250484*	50-354	A
EGG-EA-6901	8510030411*	50-354	A	PSE-SE-Z-019	8510080428*	50-354	A
EGG-PBS-6863	8506050540*	50-266	P	PSE-SE-Z-020	8510020200*	50-354	A
EPRI NP-4128 V01	8510090212*	50-327	P	PSE-SE-Z-021	8510250492*	50-354	A
EPRI NP-4128 V02	8510090220*	50-327	P	PSE-SE-Z-022	8510250487*	50-354	A
EQTP(84)-019 R02	8510220199*	50-390	F 1ES-654	PSE-SE-Z-023	8510250490*	50-354	A
FRA-QP/85 0782 NP	8510020278*	TOPREP		PSE-SE-Z-025	8510250486*	50-354	A
FRA-QP/85 1172	8510020281*	TOPREP		QR-5804 R01	8510300172*	QA999	
INSO-3080 R04	8510110145*	71-5862	25454	QR-5805	8510300178*	Q/999	
MCI-PTP-85-300-1	8510210058*	50-250	Q	RTL-ENV-85-01	8510180474*	50-272	R
MT-SMAP7-726	8510230061*	50-455	Q	SAIC-85/1517-1	8510170189*	50-322	P GL-83-28
NUREG-0020 V09 N08	8510070175	NUREG		SAIC-85/1517-3	8510170184*	50-322	P GL-83-28
NUREG-0540 V07 N08	8510070182	NUREG		SAIC-85/1517-5	8510170180*	50-322	P GL-83-28
NUREG-0557	7905230274*	50-320	P	SAIC-85/1520	8510170205*	50-322	P GL-83-28
NUREG-0748 V05 N07	8510030438	NUREG		SAIC-85/1521-1	8510170174*	50-322	P GL-83-28
NUREG-0750 V21 I02	8510030126	NUREG		SAIC-85/1521-4	8510170187*	50-322	P GL-83-28
NUREG-0837 V05 N02	8510020232	NUREG		SAIC-85/1521-6	8510170217*	50-322	P GL-83-28
NUREG-0946	8510310448	NUREG		SAIC-85/1522	8507160361*	50-322	P GL-83-28
NUREG-1031 S02	8510010227	50-423	E	SAIC-85/1523-12	8510170215*	50-322	P GL-83-28
NUREG-1046	8510290413	NUREG		SAIC-85/1523-3	8510170159*	50-322	P GL-83-28
NUREG-1047 S01	8507050411	50-410	E	SAIC-85/1524-1 DRFT	8510310011*	50-334	P GL-83-28
NUREG-1057	8510290574	50-412	E	SAIC-85/1524-17	8510170190*	50-322	P GL-83-28
NUREG/BR-0051 V07 N2	8510250583	NUREG		SAIC-85/1524-21 DRFT	8510250613*	50-271	P GL-83-28
NUREG/CP-0066	8510040389	NUREG	BNL-NUREG-51901	SAIC-85/1524-22	8510170202*	50-322	P GL-83-28
NUREG/CP-0071	8510170230	NUREG		SAIC-85/1524-23	8510170178*	50-322	P GL-83-28
NUREG/CR-2000 V04 N8	8510030309	NUREG	ORNL/NSIC-200	SAIC-85/1524-4	8510310032*	50-315	P GL-83-28
NUREG/CR-2800 S03	8510030435	NUREG		SAIC-85/1525-1	8510170213*	50-322	P GL-83-28
NUREG/CR-3428 V01	8510020227	NUREG	EPRI NP-3802	SAIC-85/1525-2	8510150480*	50-454	P GL-83-28
NUREG/CR-3428 V02	8510020217	NUREG	EPRI NP-3802	SAIC-85/1525-4	8510170193*	50-322	P GL-83-28
NUREG/CR-3613 V03 N1	8510040360	NUREG	PNL-4941	SAIC-85/1525-8	8510170211*	50-322	P GL-83-28
NUREG/CR-3633 V01 S1	8510040411	NUREG	EGG-2294	SAIC-85/1526 DRFT	8510310390*	50-219	P GL-83-28
NUREG/CR-3633 V04	8510040407	NUREG	EGG-2294	SAIC-85/1564	8507160711*	50-424	A GL-83-28
NUREG/CR-3616 V04	8510040365	NUREG	SAND84-1072	SAIC-85/3092	8510170199*	50-322	P GL-83-28
NUREG/CR-3948	8510030433	NUREG	EGG-2297	SECY-84-239	8407100662	50-382	E
NUREG/CR-3980 V04	8510040332	NUREG	ANL-84-61	SECY-85-208	8507080487*	50-346	S
NUREG/CR-4080	8510030430	NUREG	EGG-2386	SECY-85-306	8510150157	SECY	
NUREG/CR-4108	8510250531	NUREG	PNL-8154	SON-REP R22	8510150960	50-327	F
NUREG/CR-4130	8510040377	NUREG	PNL-5379	STP 141/13 R00	8510250375*	50-289	F MTX 52.5.2.9
NUREG/CR-4143	8510020257	50-423	A BNL-NUREG-51907	STR-R-05-008 R01	8510090414*	WASTE MGT	ECN 85-129
NUREG/CR-4146	8510280470	NUREG	SAND85-0205	TDR 266 R01	8510010214*	50-219	P
NUREG/CR-4185	8510010219	NUREG	SAND85-0283	TDR 728 R00	8510250364*	50-289	F
NUREG/CR-4259	8510040347	NUREG	PNL-5467	TR UR 85-225	8510030140*	50-245	P

402 REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
TR-6121-4 R02	8510310244*	50-293	P	WCAP-10902	8510010161*	50-295	P
UMTRA-DOE/AL-050106	8510240471*	WASTE MGT		WCAP-10910	8510110246*	50-364	P
UMTRA-DOE/AL-050123	8510240467*	WASTE MGT		WCAP-10925	8510040379*	50-281	P SG-85-08-045
UMTRA-DOE/AL-150224	8510240618*	WASTE MGT		WCAP-8860-S2	8510290413*	TOPREP	
VEP-NE-2	8510170079*	50-280	P	XN-NF-1A R08	8510210145*	TOPREP	
WCAP 10950	8510230162*	50-395	P	XN-NF-32A R13	8510110127*	70-1257	25704
WCAP-10445-NP-A	8510090150*	TOPREP		XN-NF-85-28	8510170292*	50-316	P
WCAP-10885	8510180142*	50-244	P	XN-NF-85-98	8510080252*	50-305	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENT

Item listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7905230274	7905290232	79/05/09	50-320 P	8502280071	8510180171	85/10/09	PR
8007090278	8510070080	85/07/17	COMMISSIO N	8503040154	8510180171	85/10/09	PR
8010010843	8510070080	85/07/17	50-346 S	8503080521	8510180171	85/10/09	PR
8010270109	8510070080	85/07/17	COMMISSIO N	8503130606	8510090275	85/06/28	REVIEW GR P
8103190865	8510070080	85/07/17	50-346 Q	8503220113	8510070080	85/07/17	50-346 S
8108060119	8510070080	85/07/17	COMMISSIO N	8504030276	8510070080	85/07/17	50-346 S
8204120124	8510080023	85/09/30	50-329 E	8504080378	8510090275	85/06/28	REVIEW GR P
8204210531	8510080023	85/09/30	50-329 E	8504100552	8510010064	85/09/04	FOIA
8204290608	8510080023	85/09/30	50-329 E	8504250410	8504250409	81/10/21	50-275 P
8208030689	8510080023	85/09/30	50-329 A	8506050540	8510170078	85/10/03	50-266 P
8209020126	8510080023	85/09/30	50-329 Q	8506260560	8510070080	85/07/17	50-346 S
8302090513	8510070080	85/07/17	50-346 S	8506260595	8510070080	85/07/17	50-346 S
8308310389	8510070080	85/07/17	COMMISSIO N	8506260600	8510070080	85/07/17	50-346 S
8309060463	8510070080	85/07/17	50-346 S	8506260705	8510070080	85/07/17	50-346 S
8310270010	8510070080	85/07/17	COMMISSIO N	8506270129	8510070080	85/07/17	50-346 F
8311040213	8510070080	85/07/17	COMMISSIO N	8507050455	8510090447	85/10/01	COMMISSIO N
83111290156	8510070080	85/07/17	50-346 S	8507090487	8510150421	85/10/09	50-346 S
8311290219	8510070080	85/07/17	50-346 S	8507110595	8510090275	85/06/28	REVIEW GR P
8311290224	8510070080	85/07/17	50-346 S	8507160166	8510090096	85/10/04	PR
8312010439	8510070080	85/07/17	50-346 S	8507160361	8510170100	85/10/11	50-322 P
8312020438	8510010283	85/02/27	50-382 P	8507160711	8510300112	85/10/22	50-424 A
8312210021	8510070080	85/07/17	COMMISSIO N	8508010123	8508010540	85/07/19	MISC
8312230206	8510070080	85/07/17	50-346 Q	8508010128	8508010540	85/07/19	MISC
8312230212	8510070080	85/07/17	50-346 Q	8508120712	8510080071	85/09/26	70-135
8401270550	8510070080	85/07/17	COMMISSIO N	8508230332	8510280427	85/10/22	50-387 P
8403140187	8510180171	85/10/09	PR	8508280083	8510150142	85/09/20	40-1366
8403140316	8402280501	83/10/21	REVIEW GR P	8508280100	8510150142	85/09/20	40-1366
8404040147	8510180171	85/10/09	PR	8508280127	8510150142	85/09/20	40-1366
8404050355	8510010283	85/02/27	92 Q	8509030152	8510090340	85/10/04	50-259 P
8404170570	8510070080	85/07/17	46 S	8509040052	8510220440	85/10/17	50-445 Q
8405010072	8510070080	85/07/17	50-289 P	8509040194	8508270323	85/08/19	50-312 P
8406040129	8510180171	85/10/09	PR	8509060182	8510040444	85/09/19	50-305 P
8406060369	8510180171	85/10/09	PR	8509170394	8510110006	85/10/07	50-237 F
8406150267	8510010283	85/02/27	50-382 F	8509180210	8510180095	85/10/11	TOPREP
8406210273	8510010064	85/09/04	50-209 P	8509190637	8510030239	85/09/26	NUREG
8406250404	8510070080	85/07/17	50-346 S	8509250119	8509250119	85/09/20	50-354 K
8407090031	8510090275	85/06/28	REVIEW GR P	8510010005	8510010004	85/09/23	CONTRACT
8407130274	8510070080	85/07/17	50-346 Q	8510010007	8510010006	85/09/24	CONTRACT
8407130282	8510070080	85/07/17	50-346 Q	8510010011	8510010009	85/08/15	WASTE MGT
8407130287	8510070080	85/07/17	50-346 Q	8510010014	8510010012	85/09/18	50-333 P
8407130313	8510070080	85/07/17	50-346 Q	8510010055	8510010052	85/09/23	50-373 P
8407130317	8510070080	85/07/17	50-346 Q	8510010065	8510010060	85/08/29	40-8027
8407130320	8510070080	85/07/17	50-346 Q	8510010071	8510010057	85/09/23	50-416 Q
8407250135	8510070080	85/07/17	50-346 S	8510010074	8510010070	85/09/20	50-482 Q
8408010318	8510230016	85/10/04	50-315 U	8510010075	8510010066	85/09/20	FOIA
8408010320	8510230016	85/10/04	50-315 U	8510010076	8510010060	85/08/29	FOIA
8408210595	8510010283	85/02/27	50-382 F	8510010078	8510010057	85/09/23	50-416 S
8410110596	8510070080	85/07/17	COMMISSIO N	8510010079	8510010073	83/10/21	50-361 P
8410150611	8510070080	85/07/17	50-346 S	8510010081	8510010060	85/08/29	40-8006
8411210152	8510070080	85/07/17	50-346 Q	8510010082	8510010070	85/09/20	50-482 Q
8411280233	8510070080	85/07/17	COMMISSIO N	8510010084	8510010057	85/09/23	50-416 V
8411290581	8510070080	85/07/17	50-346 S	8510010085	8510010064	85/09/04	FOIA
8412100470	8510220125	85/10/16	50-445 A	8510010088	8510010086	85/09/20	50-346 P
8501030255	8510070080	85/07/17	50-346 Q	8510010089	8510010060	85/08/29	40-8006
8501280088	8510110122	85/08/21	REVIEW GR P	8510010091	8510010057	85/09/23	50-416 Q
8502070362	8510180171	85/10/09	PR	8510010092	8510010080	85/09/24	50-445 A
8502110822	8510090275	85/06/28	REVIEW GR P	8510010093	8510010064	85/09/04	FOIA
8502190399	8510070080	85/07/17	50-346 V	8510010096	8510010057	85/09/23	50-416 V
8502190411	8510070080	85/07/17	50-346 Q	8510010099	8510010057	85/09/23	50-416 U
8502190413	8510070080	85/07/17	50-346 V	8510010102	8510010094	85/09/23	50-320 P

404 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510010103	8510010060	85/08/29	40-8006	8510010288	8510010278	85/09/26	50-400 E
8510010105	8510010064	85/09/04	FOIA	8510010289	8510010060	85/08/29	40-8027
8510010107	8510010057	85/09/23	50-416 V	8510010291	8510010282	85/09/24	50-305 P
8510010109	8510010057	85/08/23	50-416 V	8510010292	8510010284	85/09/27	QA999
8510010112	8510010101	85/09/25	50-282 Q	8510010294	8510010060	85/08/29	40-8027
8510010114	8510010098	85/09/23	50-321 P	8510010295	8510010283	85/02/27	50-382 P
8510010115	8510010064	85/09/04	FOIA	8510010296	8510010060	85/08/29	40-8027
8510010116	8510010057	85/09/23	50-416 V	8510010297	8510010283	85/02/27	50-382 P
8510010117	8510010060	85/08/29	40-8006	8510010298	8510010284	85/09/27	QA999
8510010119	8510010057	85/09/23	50-416 V	8510010300	8510010060	85/08/29	40-8027
8510010120	8510010110	85/09/24	50-316 S	8510010301	8510010283	85/02/27	50-382 P
8510010121	8510010060	85/08/29	40-8006	8510010303	8510010060	85/08/29	40-8027
8510010122	8510010064	85/09/04	FOIA	8510010304	8510010283	85/02/27	50-382 P
8510010125	8510010057	85/09/23	50-416 V	8510010307	8510010283	85/02/27	50-382 P
8510010126	8510010060	85/08/29	40-8027	8510010308	8510010060	85/08/29	40-8027
8510010127	8510010060	85/08/29	40-8006	8510010309	8510010060	85/08/29	40-8027
8510010129	8510010110	85/09/24	50-316 S	8510010310	8510010283	85/02/27	50-382 P
8510010130	8510010057	85/09/23	50-416 V	8510010313	8510010283	85/02/27	50-382 P
8510010132	8510010064	85/09/04	FOIA	8510010314	8510010283	85/02/27	50-382 P
8510010134	8510010060	85/08/29	40-8006	8510010315	8510010060	85/08/29	FOIA
8510010135	8510010060	85/08/29	40-8027	8510010318	8510010060	85/08/29	40-8027
8510010138	8510010057	85/09/23	50-416 V	8510010320	8510010283	85/02/27	50-382 Q
8510010140	8510010060	85/08/29	FOIA	8510010321	8510010283	85/02/27	50-382 P
8510010141	8510010128	85/09/23	50-255 Q	8510010322	8510010060	85/08/29	FOIA
8510010142	8510010060	85/08/29	40-8027	8510010326	8510010283	85/02/27	50-382 P
8510010143	8510010064	85/09/04	50-289 P	8510010327	8510010060	85/08/29	40-8027
8510010148	8510010060	85/08/29	40-8006	8510010328	8510010283	85/02/27	50-382 P
8510010149	8510010137	85/09/24	CONTRACT	8510010329	8510010319	85/09/24	50-155 P
8510010150	8510010060	85/08/29	40-8027	8510010332	8510010283	85/02/27	50-382 P
8510010151	8510010057	85/09/23	50-416 V	8510010333	8510010283	85/02/27	50-382 P
8510010152	8510010057	85/09/23	50-416 V	8510010334	8510010064	85/09/04	FOIA
8510010153	8510010060	85/08/29	40-8006	8510010335	8510010060	85/08/29	40-8027
8510010157	8510010064	85/09/04	50-289 P	8510010338	8510010319	85/09/24	50-155 P
8510010159	8510010060	85/08/29	40-8027	8510010339	8510010283	85/02/27	50-382 P
8510010160	8510010060	85/08/29	40-8006	8510010341	8510010060	85/08/29	40-8027
8510010161	8510010155	85/09/13	50-295 P	8510010342	8510010283	85/02/27	50-382 P
8510010164	8510010060	85/08/29	40-8027	8510010343	8510010283	85/02/27	50-382 F
8510010166	8510010060	85/08/29	40-8006	8510010344	8510010064	85/09/04	50-289 P
8510010168	8510010057	85/09/23	50-416 V	8510010345	8510010283	85/02/27	50-382 P
8510010170	8510010057	85/09/23	50-416 V	8510010348	8510010283	85/02/27	50-382 P
8510010172	8510010064	85/09/04	50-323 P	8510010349	8510010060	85/08/29	40-8027
8510010173	8510010060	85/08/29	40-8006	8510010350	8510010283	85/02/27	50-382 P
8510010174	8510010060	85/08/29	40-8027	8510010351	8510010283	85/02/27	50-382 Q
8510010176	8510010057	85/09/23	50-416 V	8510010352	8510010347	85/09/27	50-302 P
8510010180	8510010154	85/09/25	50-266 Q	8510010354	8510010283	85/02/27	50-382 Q
8510010181	8510010060	85/08/29	40-8006	8510010356	8510010060	85/08/29	40-8027
8510010182	8510010175	85/09/27	50-373 Q	8510010357	8510010283	85/02/27	50-382 P
8510010183	8510010060	85/08/29	40-8027	8510010358	8510010283	85/02/27	50-382 P
8510010185	8510010177	85/09/09	50-443 Q	8510010360	8510010283	85/02/27	50-382 Q
8510010186	8510010064	85/09/04	50-275 P	8510010362	8510010064	85/09/04	50-289 P
8510010187	8510010060	85/08/29	FOIA	8510010363	8510010060	85/08/29	FOIA
8510010200	8510010197	85/09/20	50-443 Q	8510010364	8510010283	85/02/27	50-382 P
8510010201	8510010191	85/09/24	50-315 Q	8510010365	8510010283	85/02/27	50-382 P
8510010203	8510010064	85/09/04	FOIA	8510010367	8510010283	85/02/27	50-382 Q
8510010210	8510010064	85/09/04	50-289 P	8510010368	8510010060	85/08/29	40-8027
8510010213	8510010064	85/09/04	50-289 P	8510010369	8510010283	85/02/27	50-382 P
8510010214	8510010209	85/09/24	50-219 P	8510010370	8510010366	85/09/27	50-255 Q
8510010221	8510010064	85/09/04	FOIA	8510010371	8510010283	85/02/27	50-382 P
8510010224	8510010060	85/08/29	40-8006	8510010372	8510010060	85/08/29	40-8027
8510010226	8510010064	85/09/04	FOIA	8510010373	8510010283	85/02/27	50-382 P
8510010229	8510010060	85/08/29	40-8027	8510010375	8510010283	85/02/27	50-382 F
8510010230	8510010060	85/08/29	40-8006	8510010376	8510010283	85/02/27	50-382 P
8510010235	8510010064	85/09/04	FOIA	8510010378	8510010324	85/09/27	50-259 Q
8510010236	8510010060	85/08/29	40-8027	8510010380	8510010283	85/02/27	50-382 P
8510010237	8510010225	85/09/20	50-329 A	8510010381	8510010283	85/02/27	50-382 P
8510010240	8510010233	85/09/26	CONTRACT	8510010384	8510010283	85/02/27	50-382 F
8510010242	8510010060	85/08/29	40-8027	8510010388	8510010283	85/02/27	50-328 S
8510010243	8510010060	85/08/29	40-8006	8510010391	8510010060	85/08/29	40-8027
8510010244	8510010225	85/09/20	FOIA	8510010392	8510010283	85/02/27	50-382 F
8510010246	8510010182	85/09/17	50-259 Q	8510010393	8510010283	85/02/27	FOIA
8510010247	8510010060	85/08/29	40-8027	8510010394	8510010060	85/08/29	40-8027
8510010248	8510010060	85/08/29	40-8006	8510010395	8510010064	85/09/04	FOIA
8510010254	8510010060	85/08/29	40-8006	8510010396	8510010283	85/02/27	50-382 F
8510010256	8510010060	85/08/29	40-8027	8510010397	8510010283	85/02/27	FOIA
8510010258	8510010252	85/09/18	CONTRACT	8510010398	8510010060	85/08/29	40-8027
8510010261	8510010060	85/08/29	40-8027	8510010399	8510010283	85/02/27	50-382 F
8510010262	8510010259	85/09/24	50-269 P	8510010400	8510010064	85/09/04	FOIA
8510010263	8510010060	85/08/29	40-8006	8510010401	8510010060	85/08/29	40-8027
8510010269	8510010060	85/08/29	40-8027	8510010402	8510010283	85/02/27	50-390 S
8510010271	8510010060	85/08/29	40-8027	8510010404	8510010060	85/08/29	40-8027
8510010272	8510010265	85/09/23	FOIA	8510010405	8510010064	85/09/04	FOIA
8510010273	8510010060	85/08/29	40-8027	8510010408	8510010060	85/08/29	40-8027
8510010275	8510010060	85/08/29	40-8027	8510010412	8510010064	85/09/04	FOIA
8510010279	8510010060	85/08/29	40-8027	8510010413	8510010060	85/08/29	40-8027
8510010280	8510010060	85/08/29	40-8027	8510010415	8510010060	85/08/29	40-8027
8510010285	8510010060	85/08/29	40-8027	8510010416	8510010409	85/09/26	50-455 Q
8510010287	8510010233	85/02/27	50-382 F	8510010418	8510010064	85/09/04	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 405

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510010420	8510010283	85/02/27	50-416	8510020254	8510010283	85/02/27	FOIA
8510010421	8510010060	85/08/29	40-8027	8510020256	8510020253	85/09/26	50-155
8510010423	8510010283	85/02/27	50-382	8510020260	8510020242	85/09/17	50-293
8510010424	8510010283	85/02/27	50-382	8510020278	8510020275	85/09/16	TOPREP
8510010427	8510010283	85/02/27	50-382	8510020281	8510020275	85/09/16	TOPREP
8510010428	8510010367	85/09/20	50-272	8510020290	8510020285	85/09/25	50-302
8510010430	8510010283	85/02/27	50-382	8510020294	8510020288	85/09/30	50-461
8510010431	8510010283	85/02/27	50-382	8510020304	8510020302	85/09/25	50-416
8510010432	8510010283	85/02/27	50-382	8510020438	8510020435	85/09/23	50-245
8510010435	8510010283	85/02/27	50-382	8510020501	8510020497	85/09/30	71-384
8510010436	8510010064	85/09/04	FOIA	8510020510	8510020508	85/09/30	71-552
8510010439	8510010283	85/02/27	50-382	8510030007	8510030001	85/09/27	50-341
8510010441	8510010283	85/02/27	50-382	8510030016	8510030002	85/10/01	50-244
8510010442	8510010283	85/02/27	50-382	8510030020	8510030013	85/09/26	50-339
8510010443	8510010064	85/09/04	FOIA	8510030026	8510030018	85/10/01	50-333
8510010444	8510010283	85/02/27	50-382	8510030038	8510030030	85/09/26	50-397
8510010445	8510010440	85/09/25	TOPREP	8510030053	8510030037	85/09/18	50-309
8510010447	8510010283	85/02/27	50-382	8510030054	8510030044	85/09/27	50-424
8510010448	8510010283	85/02/27	50-382	8510030058	8510030032	85/09/30	50-386
8510010449	8510010283	85/02/27	50-382	8510030063	8510030057	85/09/30	50-498
8510010450	8510010064	85/09/04	FOIA	8510030074	8510030066	85/09/30	71-135
8510010453	8510010064	85/09/04	FOIA	8510030112	8510030104	85/09/23	50-344
8510010454	8510010283	85/02/27	50-382	8510030117	8510030104	85/09/23	50-344
8510010455	8510010064	85/09/04	FOIA	8510030119	8510030113	85/09/26	XPORLIC
8510010456	8510010451	85/09/24	50-338	8510030120	8510030115	85/09/30	71-5862
8510010457	8510010283	85/02/27	50-382	8510030140	8510030130	85/09/24	50-245
8510010458	8510010283	85/02/27	50-382	8510030149	8510030139	85/09/24	CONTRACT
8510010460	8510010283	85/02/27	50-382	8510030152	8510030146	85/09/16	50-364
8510010461	8510010283	85/02/27	50-382	8510030162	8510030156	85/09/24	CONTRACT
8510010464	8510010463	85/09/24	50-498	8510030192	8510030182	85/09/27	CONTRACT
8510010483	8510010481	85/09/25	50-312	8510030211	8510030203	85/09/24	50-213
8510010503	8510010502	85/09/18	50-443	8510030222	8510030214	85/09/30	71-251
8510010505	8510010502	85/09/18	50-443	8510030225	8510030213	85/09/18	50-286
8510010512	8510010506	85/09/16	50-322	8510030235	8510030227	85/09/17	50-245
8510010525	8510010506	85/09/16	50-322	8510030261	8510030260	85/09/20	50-293
8510010532	8510010506	85/09/16	50-322	8510030262	8510030259	85/09/16	50-416
8510010536	8510010506	85/09/16	50-322	8510030268	8510030265	85/09/16	50-275
8510010538	8510010506	85/09/16	COMMISSIO	8510030270	8510030267	85/09/30	71-383
8510010544	8510010506	85/09/16	COMMISSIO	8510030284	8510030282	85/09/24	50-424
8510010546	8510010506	85/09/16	COMMISSIO	8510030298	8510030296	85/09/25	50-269
8510010550	8510010506	85/09/16	COMMISSIO	8510030308	8510030303	85/09/30	71-139
8510010554	8510010506	85/09/16	COMMISSIO	8510030319	8510030317	85/09/30	71-121
8510010558	8510010506	85/09/16	COMMISSIO	8510030329	8510030327	85/09/25	CONTRACT
8510010561	8510010506	85/09/16	COMMISSIO	8510030404	8510030399	85/09/09	50-445
8510010568	8510010506	85/09/16	COMMISSIO	8510030411	8510170156	85/10/02	50-354
8510010569	8510010506	85/09/16	COMMISSIO	8510030434	8510030432	85/09/25	CONTRACT
8510010570	8510010506	85/09/16	COMMISSIO	8510040078	8510040045	85/09/12	50-261
8510010572	8510010506	85/09/16	COMMISSIO	8510040089	8510040045	85/09/12	50-261
8510010578	8510010506	85/09/16	COMMISSIO	8510040098	8510150231	85/10/04	MISC
8510010585	8510010506	85/09/16	COMMISSIO	8510040100	8510040045	85/09/12	50-261
8510010588	8510010506	85/09/16	COMMISSIO	8510040104	8510040103	85/09/27	50-397
8510010590	8510010506	85/09/16	50-320	8510040114	8510040111	85/09/24	50-288
8510010626	8510010625	85/09/20	PROJ	8510040129	8510040127	85/09/26	CONTRACT
8510010629	8510010618	85/09/20	50-277	8510040139	8510040134	85/09/30	50-267
8510010633	8510010618	85/09/20	50-277	8510040148	8510040141	85/03/27	50-320
8510010647	8510010646	85/09/27	50-483	8510040151	8510040146	85/09/25	50-390
8510020008	8510020007	85/09/19	MISC	8510040152	8510040141	85/09/27	50-320
8510020019	8510020016	85/09/25	50-322	8510040155	8510040141	85/09/27	50-320
8510020037	8510020034	85/09/23	50-298	8510040157	8510040153	85/09/30	CONTRACT
8510020046	8510020043	85/09/20	50-275	8510040160	8510040146	85/09/25	50-390
8510020050	8510020044	85/09/17	50-277	8510040161	8510040149	85/09/30	50-333
8510020060	8510020073	85/09/19	50-387	8510040168	8510040144	85/10/02	50-414
8510020102	8510020090	85/09/20	MISC	8510040172	8510040163	85/09/30	50-29
8510020104	8510020097	85/09/25	50-397	8510040181	8510040177	85/09/30	50-155
8510020114	8510020113	85/08/15	50-361	8510040182	8510040174	85/09/26	50-424
8510020119	8510020113	85/08/15	50-361	8510040187	8510040177	85/09/30	50-155
8510020133	8510020128	85/09/27	40-8027	8510040209	8510040202	85/09/30	50-244
8510020141	8510020139	85/09/27	50-387	8510040221	8510040213	85/10/01	50-333
8510020155	8510020150	85/09/30	50-352	8510040223	8510040215	85/09/30	50-461
8510020191	8510010283	85/02/27	50-335	8510040226	8510040213	85/10/01	50-333
8510020194	8510010283	85/02/27	FOIA	8510040232	8510040228	85/09/20	50-305
8510020199	8510010283	85/02/27	50-382	8510040253	8510040243	85/09/26	50-317
8510020200	8510020195	85/09/30	50-354	8510040256	8510040241	85/09/27	ORG
8510020201	8510020197	85/09/25	50-142	8510040265	8510040260	85/10/01	50-29
8510020202	8510010283	85/02/27	50-382	8510040270	8510040260	85/10/01	50-29
8510020205	8510020195	85/09/30	50-354	8510040277	8510040274	85/10/02	50-155
8510020207	8510010283	85/02/27	50-382	8510040279	8510040274	85/10/02	50-155
8510020211	8510010283	85/02/27	50-382	8510040289	8510040285	85/09/30	50-346
8510020216	8510010283	85/02/27	FOIA	8510040296	8510040293	85/09/27	50-320
8510020221	8510010283	85/02/27	50-416	8510040335	8510040330	85/09/17	50-423
8510020226	8510020214	85/09/18	50-272	8510040339	8510040327	85/09/18	50-302
8510020229	8510010283	85/02/27	50-382	8510040344	8510040327	85/09/18	50-302
8510020230	8510020224	85/09/12	50-344	8510040355	8510040349	85/09/30	CONTRACT
8510020236	8510010283	85/02/27	50-382	8510040356	8510040350	85/09/23	50-302
8510020244	8510020238	85/09/18	50-293	8510040357	8510040351	85/09/20	50-320
8510020245	8510010283	85/02/27	50-321	8510040362	8510040350	85/09/23	50-302
8510020249	8510020242	85/09/17	50-243	8510040379	8510040374	85/09/27	50-281

406 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510040406	8510040403	85/09/30	50-458 Q	8510070256	8510070254	85/09/26	50-322 Q
8510040409	8510040403	85/09/30	50-458 Q	8510070257	8510070232	85/10/03	50-352 K
8510040412	8510040408	85/09/18	50-317 Q	8510070258	8510070254	85/09/26	50-322 Q
8510040415	8510040403	85/09/30	50-458 Q	8510070259	8510070080	85/07/17	50-346 S
8510040418	8510040416	85/09/25	50-395 P	8510070269	8510070080	85/07/17	50-346 Q
8510040419	8510040416	85/09/25	50-395 P	8510070272	8510070270	85/09/30	50-70 P
8510040436	8510040431	85/09/27	70-143	8510070273	8510070080	85/07/17	50-346 S
8510040448	8510040445	85/09/30	50-289 P	8510070278	8510070080	85/07/17	50-346 Q
8510040450	8510040445	85/09/30	50-289 P	8510070279	8510070275	85/09/26	50-423 K
8510040458	8510040302	85/09/23	50-400 T	8510070280	8510070274	85/09/16	50-409 P
8510040463	8510040460	85/09/30	50-267 P	8510070282	8510070268	85/10/03	50-309 P
8510040466	8510040464	85/09/30	50-333 Q	8510070283	8510070277	85/09/27	50-219 R
8510040472	8510040468	85/09/26	CONTRACT	8510070288	8510070285	85/10/03	QA999
8510040495	8510040493	85/09/24	50-424 Q	8510070290	8510070281	85/10/01	50-413 K
8510040498	8510040493	85/09/24	50-424 Q	8510070296	8510070265	85/10/03	QA999
8510040499	8510040489	85/09/30	CONTRACT	8510070301	8510070299	85/10/02	50-440 Q
8510040503	8510040501	85/09/20	CONTRACT	8510070307	8510070299	85/10/02	50-440 Q
8510040506	8510040505	85/09/23	50-324 Q	8510070308	8510070305	85/09/27	CONTRACT
8510040510	8510040505	85/09/23	50-324 Q	8510070310	8510070302	85/10/02	50-29 E
8510040522	8510040518	85/09/16	50-272 P	8510070315	8510070309	85/09/30	50-29 P
8510040528	8510040518	85/09/16	50-272 P	8510070329	8510070325	85/09/30	50-341 Q
8510040531	8510040526	85/09/24	50-424 Q	8510070333	8510070326	85/10/01	50-327 Q
8510040537	8510040533	85/09/16	50-311 P	8510070340	8510070336	85/10/01	50-259 P
8510040539	8510040535	85/09/25	50-302 Q	8510070342	8510070338	85/10/03	QA999
8510040541	8510040533	85/09/16	50-311 P	8510070343	8510070326	85/10/01	50-327 Q
8510040542	8503200025	85/03/01	50-269 P	8510070359	8510070357	85/10/01	50-400 Q
8510040564	8510040559	85/09/30	CONTRACT	8510070368	8510070362	85/10/02	50-454 Q
8510040571	8510040517	85/09/30	CONTRACT	8510070377	8510070375	85/10/03	50-424 Q
8510040583	8510040576	85/09/30	CONTRACT	8510070383	8510070375	85/10/03	50-424 Q
8510040584	8510040579	85/09/30	REGGD	8510070389	8510070385	85/09/30	50-461 Q
8510040602	8510040597	85/09/12	WASTE MGT	8510070391	8510070379	85/10/04	50-213 P
8510040603	8510040595	85/09/26	CONTRACT	8510070400	8510070379	85/10/04	50-213 P
8510040607	8510040597	85/09/12	WASTE MGT	8510070416	8510070379	85/10/04	50-213 P
8510040615	8510040597	85/09/12	WASTE MGT	8510070420	8510070386	85/10/01	50-454 Q
8510040617	8510040597	85/09/12	WASTE MGT	8510070424	8510070421	85/10/02	50-461 Q
8510040619	8510040597	85/09/12	WASTE MGT	8510070427	8510070386	85/10/01	50-454 Q
8510040620	8510040597	85/09/12	WASTE MGT	8510070432	8510070426	85/10/02	50-289 P
8510070026	8510070024	85/10/02	50-263 F	8510070433	8510070430	85/09/30	50-29 P
8510070027	8510070023	85/09/16	50-272 P	8510070447	8510070441	85/09/26	50-245 P
8510070032	8510070023	85/09/16	50-272 P	8510070463	8510070460	85/10/01	50-324 Q
8510070042	8510070037	85/09/24	50-259 Q	8510070470	8510070468	85/10/02	50-409 Q
8510070073	8510070068	85/10/01	50-309 Q	8510070472	8510070468	85/10/02	50-409 Q
8510070078	8510070071	85/09/26	CONTRACT	8510070476	8510070474	85/09/30	50-219 P
8510070086	8510070082	85/09/30	50-315 F	8510070480	8510070477	85/10/02	50-414 Q
8510070089	8510070085	85/09/27	CONTRACT	8510070482	8510070482	85/09/13	50-409 P
8510070091	8510040058	84/05/22	50-382 E	8510070483	8510070479	85/09/16	REGGD
8510070099	8510070080	85/07/17	50-346 S	8510070484	8510070479	85/09/16	REGGD
8510070102	8510070080	85/07/17	50-346 S	8510070496	8510070494	85/09/30	50-445 A
8510070104	8510070097	85/09/24	50-361 P	8510070497	8510070495	85/10/01	50-269 Q
8510070106	8510070080	85/07/17	50-346 F	8510070500	8510070495	85/10/01	50-269 Q
8510070108	8510070090	85/07/17	50-346 Q	8510070504	8510070516	85/09/30	50-346 U
8510070109	8510070105	85/09/25	50-320 P	8510070506	8510070516	85/09/30	50-346 U
8510070111	8510070097	85/09/24	50-361 P	8510070511	8510070516	85/09/30	50-346 U
8510070112	8510070080	85/07/17	50-346 V	8510070513	8510070505	85/10/01	50-269 Q
8510070115	8510070080	85/07/17	50-346 Q	8510070518	8510070516	85/09/30	50-346 U
8510070117	8510070080	85/07/17	50-346 F	8510070538	8510070536	85/09/27	50-423 Q
8510070120	8510070080	85/07/17	50-346 Q	8510070541	8510070534	85/09/30	50-369 P
8510070123	8510070080	85/07/17	50-346 S	8510070547	8510070534	85/09/30	50-369 P
8510070125	8510070080	85/07/17	50-346 S	8510070549	8510070548	85/10/01	50-315 S
8510070129	8510070124	85/09/19	CONTRACT	8510070550	8510070544	85/09/27	50-247 Q
8510070130	8510070080	85/07/17	50-346 Q	8510070552	8510070548	85/10/01	50-315 S
8510070131	8510070080	85/07/17	50-346 Q	8510070562	8510070560	85/09/25	50-409 R
8510070133	8510070080	85/07/17	50-346 S	8510070581	8510070579	85/09/27	CONTRACT
8510070138	8510070080	85/07/17	50-346 Q	8510080010	8510080009	85/09/30	CONTRACT
8510070142	8510070080	85/07/17	50-346 V	8510080015	8510080012	85/09/30	CONTRACT
8510070155	8510070080	85/07/17	50-346 S	8510080027	8510080024	85/09/30	CONTRACT
8510070161	8510070080	85/07/17	50-346 Q	8510080032	8510080030	85/09/27	50-244 Q
8510070166	8510070159	85/10/01	50-412 Q	8510080033	8510080023	85/09/30	50-329 O
8510070167	8510070080	85/07/17	50-346 S	8510080038	8510080023	85/09/30	50-329 O
8510070170	8510070163	85/09/30	50-316 P	8510080045	8510080023	85/09/30	50-329 A
8510070181	8510070080	85/07/17	COMMISSIO N	8510080048	8510080047	85/09/24	50-312 P
8510070184	8510070080	85/07/17	50-346 S	8510080049	8510080023	85/09/30	50-329 O
8510070185	8510070179	85/09/27	50-206 F	8510080051	8510080023	85/09/30	50-329 F
8510070192	8510070080	85/07/17	50-346 S	8510080055	8510080023	85/09/30	50-329 A
8510070193	8510070190	85/09/06	50-213 P	8510080061	8510080023	85/09/30	50-329 F
8510070198	8510070080	85/07/17	COMMISSIO N	8510080069	8510080064	85/10/02	50-373 P
8510070202	8510070080	85/07/17	50-346 S	8510080073	8510080023	85/09/30	50-329 O
8510070206	8510070204	85/09/27	70-1100	8510080076	8510080064	85/10/02	50-373 P
8510070214	8510070080	85/07/17	50-346 S	8510080077	8510080071	85/09/26	70-135
8510070215	8510070204	85/09/27	70-1100	8510080080	8510080072	85/10/03	50-277 Q
8510070218	8510070210	85/09/30	50-289 P	8510080083	8510080023	85/09/30	FOIA
8510070220	8510070080	85/07/17	50-346 Q	8510080087	8510080081	85/09/25	CONTRACT
8510070224	8510070204	85/09/27	70-1100	8510080088	8510080023	85/09/30	50-329 O
8510070225	8510070211	85/09/30	50-423 Q	8510080091	8510080086	85/09/17	50-272 R
8510070227	8510070080	85/07/17	50-346 S	8510080092	8510080081	85/09/25	CONTRACT
8510070247	8510070243	85/09/30	50-352 F	8510080094	8510080023	85/09/30	50-329 O
8510070248	8510070232	85/10/03	50-352 K	8510080100	8510080023	85/09/30	50-329 O

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 407

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510080102	8510080097	85/09/30	50-309 P	8510080426	8510080023	85/09/30	50-330 O
8510080104	8510080096	85/10/03	50-410 Q	8510080428	8510080422	85/10/04	50-354 A
8510080106	8510080097	85/09/30	50-309 P	8510080429	8510080023	85/09/30	50-330 O
8510080107	8510080023	85/09/30	50-330 Q	8510080431	8510080023	85/09/30	50-330 O
8510080113	8510080023	85/09/30	50-330 Q	8510080432	8510080425	85/10/02	50-461 Q
8510080116	8510080112	85/09/30	50-312 P	8510080434	8510080430	85/09/27	50-454 P
8510080120	8510080112	85/09/30	50-312 P	8510080435	8510080023	85/09/30	50-329 O
8510080121	8510080119	85/10/03	50-300 Q	8510080438	8510080023	85/09/30	50-329 A
8510080127	8510080023	85/09/30	50-329 A	8510080441	8510080023	85/09/30	50-329 O
8510080128	8510080118	85/09/27	CONTRACT	8510080444	8510080023	85/09/30	50-329 O
8510080130	8510080122	85/09/26	CONTRACT	8510080448	8510080023	85/09/30	50-329 O
8510080132	8510080023	85/09/30	50-329 O	8510080449	8510080447	85/10/04	50-329 P
8510080133	8510080126	85/10/01	50-373 P	8510080453	8510080451	85/10/03	50-322 P
8510080135	8510080131	85/10/03	50-440 P	8510080456	8510080452	85/09/30	50-327 Q
8510080138	8510080126	85/10/01	50-373 P	8510080461	8510080459	85/10/04	50-139 Q
8510080140	8510080131	85/10/03	50-440 Q	8510080462	8510080460	85/10/02	50-245 F
8510080141	8510080136	85/09/25	CONTRACT	8510080475	8510080472	85/10/04	50-27 Q
8510080143	8510080023	85/09/30	50-329 O	8510080478	8510080474	85/09/01	50-445 Q
8510080146	8510080139	85/09/30	50-320 P	8510080489	8510080489	85/09/30	50-288 P
8510080149	8510080136	85/09/25	CONTRACT	8510080515	8510080514	85/09/30	50-237 P
8510080158	8510080023	85/09/30	50-329 Q	8510080518	8510080517	85/09/27	50-10 Q
8510080159	8510080144	85/10/02	CONTRACT	8510080535	8510080532	85/09/27	50-416 Q
8510080162	8510080155	85/10/03	70-820 R	8510080538	8510080532	85/09/27	50-416 Q
8510080174	8510080171	85/09/24	50-373 R	8510080548	8510080543	85/09/27	50-413 Q
8510080178	8510080186	83/12/01	TOPREP	8510080560	8510080558	85/10/03	50-336 P
8510080189	8510080184	85/10/02	50-286 Q	8510080562	8510080558	85/10/03	50-336 P
8510080191	8510080182	85/09/26	CONTRACT	8510080574	8510080572	85/09/27	CONTRACT
8510080199	8510080194	85/09/01	50-445 Q	8510080575	8510080572	85/09/27	CONTRACT
8510080207	8510080205	85/10/04	50-397 P	8510080578	8510080584	85/09/27	50-458 S
8510080209	8510080206	85/09/23	50-311 R	8510080581	8510080584	85/09/30	50-458 S
8510080215	8510080201	85/10/08	50-293 K	8510080583	8510080584	85/09/30	50-458 S
8510080216	8510080213	85/09/06	50-445 Q	8510080588	8510080584	85/09/30	50-458 S
8510080228	8510080217	85/10/03	50-423 Q	8510080589	8510080585	85/09/30	50-458 Q
8510080232	8510080226	85/10/04	QA999	8510080591	8510080584	85/09/27	50-458 S
8510080236	8510080223	85/10/01	50-271 Q	8510080595	8510080592	85/09/30	50-498 Q
8510080239	8510080023	85/09/30	50-329 O	8510080598	8510080594	85/09/30	CONTRACT
8510080248	8510080023	85/09/30	50-329 E	8510080600	8510080599	85/09/30	CONTRACT
8510080252	8510080247	85/10/03	50-305 P	8510080604	8510080602	85/09/25	50-184 Q
8510080254	8510080249	85/09/20	50-238 P	8510080610	8510080609	85/09/27	50-440 Q
8510080257	8510080249	85/08/20	50-238 P	8510080612	8510080608	85/09/24	WASTE RES
8510080260	8510080206	85/09/23	50-311 R	8510080614	8510080611	85/09/27	50-483 Q
8510080262	8510080023	85/09/30	50-329 A	8510080616	8510080611	85/09/27	50-483 Q
8510080264	8510080243	85/10/01	50-327 Q	8510080617	8510080608	85/09/24	WASTE RES
8510080270	8510080265	85/10/01	50-423 A	8510090011	8510090007	85/10/04	50-206 F
8510080272	8510080023	85/09/30	50-329 E	8510090016	8510090007	85/10/04	50-206 F
8510080277	8510080023	85/09/30	50-329 A	8510090025	8510090007	85/10/04	50-206 F
8510080284	8510080023	85/09/30	50-329 O	8510090033	8510090007	85/10/04	50-206 F
8510080288	8510080279	85/10/03	50-335 Q	8510090042	8510090037	85/07/22	50-265 Q
8510080295	8510080023	85/09/30	50-329 O	8510090046	8510090040	85/09/27	WASTE RES
8510080299	8510080285	85/09/30	CONTRACT	8510090061	8510090045	85/10/04	TOPREP
8510080301	8510080292	85/10/02	50-315 P	8510090062	8510090053	85/10/04	50-440 K
8510080302	8510080023	85/09/30	50-329 O	8510090067	8510090063	85/09/26	27-39 Q
8510080309	8510080023	85/09/30	50-329 O	8510090074	8510090070	85/10/03	50-267 Q
8510080325	8510080317	85/09/30	CONTRACT	8510090080	8510090075	85/09/19	50-269 P
8510080329	8510080023	85/09/30	50-330 O	8510090085	8510090071	85/10/03	70-2910
8510080334	8510080328	85/09/30	CONTRACT	8510090088	8510090075	85/09/19	50-269 P
8510080337	8510080023	85/09/30	50-329 O	8510090089	8510090071	85/10/03	70-2910 U
8510080341	8510080023	85/09/30	50-329 O	8510090104	8510090100	85/09/19	WASTE MGT
8510080346	8510080339	85/10/03	50-219 Q	8510090106	8510090099	85/09/26	50-416 U
8510080349	8510080023	85/09/30	50-329 O	8510090110	8510090100	85/09/19	WASTE MGT
8510080354	8510080347	85/09/30	CONTRACT	8510090114	8510090099	85/09/26	50-416 U
8510080357	8510080023	85/09/30	50-237 O	8510090115	8510090109	85/10/01	50-454 P
8510080363	8510080351	85/09/27	50-302 Q	8510090116	8510090100	85/09/19	WASTE MGT
8510080364	8510080359	85/10/02	50-369 P	8510090118	8510090099	85/09/26	50-416 U
8510080367	8510080023	85/09/30	50-329 T	8510090119	8510090100	85/09/19	WASTE MGT
8510080368	8510080362	85/09/06	50-445 Q	8510090120	8510090109	85/10/01	50-454 P
8510080373	8510080023	85/09/30	50-329 A	8510090124	8510090099	85/09/26	50-416 U
8510080376	8510080365	85/09/30	CONTRACT	8510090125	8510090096	85/10/04	PR
8510080379	8510080023	85/09/30	50-329 T	8510090126	8510090100	85/09/19	WASTE MGT
8510080386	8510080023	85/09/30	50-330 O	8510090133	8510090100	85/09/19	WASTE MGT
8510080391	8510080023	85/09/30	50-330 O	8510090134	8510090130	85/09/27	50-327 P
8510080394	8510080023	85/09/30	50-330 O	8510090139	8510090096	85/10/04	PR
8510080395	8510080392	85/10/03	50-443 Q	8510090147	8510090141	85/09/27	TOPREP
8510080397	8510080023	85/09/30	50-330 O	8510090150	8510090141	85/09/27	TOPREP
8510080398	8510080393	85/10/02	50-266 Q	8510090155	8510090143	85/09/04	40-1193
8510080401	8510080392	85/10/03	50-443 Q	8510090160	8510090096	85/10/04	PR
8510080403	8510080023	85/09/30	50-330 O	8510090161	8510090156	85/09/27	50-295 Q
8510080405	8510080388	85/09/26	50-317 P	8510090166	8510090162	85/09/30	50-302 P
8510080407	8510080402	85/10/04	50-456 Q	8510090167	8510090163	85/09/27	50-397 P
8510080409	8510080023	85/09/30	50-329 A	8510090169	8510090143	85/09/04	40-1193
8510080413	8510080402	85/10/04	50-456 Q	8510090171	8510090156	85/09/27	50-295 Q
8510080414	8510080388	85/09/26	50-317 P	8510090172	8510090162	85/09/30	50-302 P
8510080417	8510080412	85/10/07	QA999	8510090174	8510090096	85/10/04	PR
8510080419	8510080415	85/10/01	50-313 Q	8510090178	8510090143	85/09/04	40-1193
8510080420	8510080023	85/09/30	50-330 O	8510090179	8510090176	85/10/02	50-315 S
8510080421	8510080416	85/10/01	50-277 Q	8510090184	8510090176	85/10/02	50-315 S
8510080424	8510080422	85/10/04	50-354 A	8510090186	8510090143	85/09/04	40-1193

408 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510090187	8510090163	85/09/27	50-397 P	8510100039	8510100027	85/10/07	50-331 Q
8510090190	8510090185	85/09/23	50-272 R	8510100040	8510100034	85/10/04	50-206 P
8510090192	8510090185	85/09/23	50-272 R	8510100046	8510100033	85/09/30	50-333 Q
8510090193	8510090096	85/10/04	PR	8510100047	8510100038	85/10/04	50-400 G
8510090197	8510090143	85/09/04	70-135	8510100051	8510100027	85/10/07	50-331 Q
8510090198	8510090188	85/09/25	50-367 Q	8510100061	8510100056	85/10/08	50-322 F
8510090199	8510090191	85/10/03	50-412 D	8510100073	8510100067	85/09/12	50-445 Q
8510090203	8510090096	85/10/04	PR	8510100075	8510100068	85/10/04	40-2061
8510090205	8510050143	85/09/04	70-135	8510100079	8510100067	85/09/12	50-445 Q
8510090207	8510090202	85/09/25	WASTE MGT	8510100105	8510100099	85/10/04	50-456 Q
8510090210	8510090202	85/09/25	WASTE MGT	8510100119	8510100082	85/10/02	50-373 P
8510090211	8510090206	85/09/30	50-445 Q	8510100122	8510100113	85/10/07	50-280 P
8510090212	8510090200	85/10/02	50-327 P	8510100127	8510100121	85/10/01	PRM
8510090213	8510090202	85/09/25	WASTE MGT	8510100133	8510100121	85/10/01	PRM
8510090214	8510090096	85/10/04	PR	8510100136	8510100120	85/10/04	50-286 P
8510090215	8510090204	85/09/16	WASTE MGT	8510100147	8510100120	85/10/04	50-286 P
8510090216	8510090209	85/09/26	50-282 P	8510100151	8510100130	85/10/01	PR
8510090217	8510090143	85/09/04	70-135	8510100157	8510100150	85/10/04	50-341 Q
8510090218	8510090202	85/09/25	WASTE MGT	8510100174	8510100183	85/10/01	50-336 P
8510090220	8510090200	85/10/02	50-327 P	8510100186	8510100181	85/10/04	50-331 Q
8510090221	8510090209	85/09/26	50-282 P	8510100190	8510100181	85/10/04	50-331 Q
8510090223	8510090096	85/10/04	PR	8510100202	8510100189	85/10/04	50-352 Q
8510090225	8510090143	85/09/04	70-135	8510100211	8510100205	85/10/03	70-371
8510090227	8510090209	85/09/26	50-282 P	8510100214	8510100009	85/10/01	50-423 A
8510090232	8510090096	85/10/04	PR	8510100119	8510100113	85/10/07	50-412 Q
8510090245	8510090235	85/09/18	50-344 Q	851010035	851010031	85/10/07	50-309 P
8510090257	8510090137	85/09/18	50-508 Q	851010038	851010029	85/10/01	50-456 Q
8510090263	8510090251	85/09/30	50-267 Q	851010047	851010040	85/10/07	50-293 Q
8510090268	8510090260	85/09/30	WASTE RES	851010048	851010043	85/10/09	50-461 P
8510090277	8510090143	85/09/04	70-135	851010058	851010036	85/10/03	50-10 P
8510090279	8510090276	85/09/23	WASTE MGT	851010072	851010066	85/10/02	50-219 P
8510090280	8510090143	85/09/04	70-135	851010080	851010078	85/10/01	50-423 A
8510090282	8510090143	85/09/04	70-135	851010083	851010077	85/10/06	50-456 G
8510090284	8510090276	85/09/23	WASTE MGT	851010086	851010075	85/10/07	50-245 F
8510090286	8510090276	85/09/23	WASTE MGT	851010091	851010082	85/10/04	50-423 Q
8510090289	8510090276	85/09/23	WASTE MGT	851010094	851010088	85/09/24	50-361 P
8510090290	8510090275	85/06/28	REVIEW GR	851010103	851010099	85/09/30	CONTRACT
8510090291	8510090276	85/09/23	WASTE MGT	851010108	851010105	85/10/09	50-361 P
8510090293	8510090276	85/09/23	WASTE MGT	851010109	851010089	85/07/02	50-267 P
8510090300	8510090297	85/09/30	50-298 Q	851010112	851010110	85/09/25	50-317 Q
8510090306	8510090305	85/08/06	40-4492	851010114	851010106	85/10/07	50-454 E
8510090308	8510090307	85/09/30	PROJ	851010124	851010119	85/10/01	COMMISSIO N
8510090313	8510090304	85/09/30	50-458 Q	851010127	851010121	85/08/27	70-1257
8510090321	8510090319	85/10/01	50-269 P	851010132	851010123	85/08/30	40-8452
8510090325	8510090322	85/10/04	71-230	851010136	851010133	85/10/06	50-456 G
8510090328	8510090324	85/09/26	50-312 Q	851010139	851010133	85/10/08	50-456 G
8510090332	8510090330	85/09/26	WASTE MGT	851010140	851010135	85/10/04	71-5862
8510090333	8510090329	85/09/27	50-400 Q	851010142	851010133	85/10/08	50-456 G
8510090344	8510090343	85/10/02	XPORTLIC	851010144	851010143	85/09/26	50-346 S
8510090350	8510090348	85/09/19	50-323 Q	851010145	851010135	85/10/04	71-5862
8510090351	8510090349	85/09/19	WASTE MGT	851010148	851010146	85/10/08	50-254 F
8510090352	8510090349	85/09/19	WASTE MGT	851010165	851010158	85/10/07	40-2061
8510090354	8510090349	85/09/19	WASTE MGT	851010169	851010162	85/10/06	50-409 P
8510090356	8510090355	85/09/20	50-397 Q	851010171	851010166	85/10/07	50-272 Q
8510090357	8510090349	85/09/19	WASTE MGT	851010172	851010162	85/10/08	50-409 P
8510090358	8510090349	85/09/19	WASTE MGT	851010190	851010187	85/10/04	50-62 F
8510090359	8510090355	85/09/20	50-397 Q	851010192	851010189	85/10/07	50-423 A
8510090360	8510090349	85/09/19	WASTE MGT	851010194	851010187	85/10/04	50-62 F
8510090366	8510090361	85/10/02	50-416 S	851010222	851010221	85/10/07	50-456 G
8510090367	8510090363	85/09/23	WASTE MGT	851010227	851010226	85/09/27	50-423 A
8510090373	8510090363	85/09/23	WASTE MGT	851010230	851010226	85/09/27	50-423 A
8510090377	8510090363	85/09/23	WASTE MGT	851010234	851010233	85/08/21	71-135
8510090378	8510090374	85/09/30	50-315 S	851010235	851010232	85/09/30	50-361 P
8510090379	8510090353	85/09/23	WASTE MGT	851010236	851010232	85/09/30	50-361 P
8510090382	8510090374	85/09/30	50-315 S	851010239	851010238	85/10/09	50-445 G
8510090383	8510090363	85/09/23	WASTE MGT	851010241	851010238	85/10/09	50-445 G
8510090385	8510090380	85/10/01	50-341 U	851010242	851010240	85/09/12	71-139
8510090412	8510160039	85/10/09	50-320 P	851010244	851010243	85/09/12	71-552
8510090414	8510090409	85/09/24	WASTE MGT	851010245	851010210	85/09/30	50-364 P
8510090423	8510090418	85/09/19	CONTRACT	851010246	851010210	85/09/30	50-364 P
8510090439	8510090436	85/09/30	CONTRACT	851010248	851010247	85/10/08	71-9010
8510090452	8510090451	85/09/25	WASTE MGT	851010253	851010252	85/09/18	71-552
8510090453	8510090441	85/10/02	FOIA	851010260	851010259	85/10/09	70-143
8510090454	8510090447	85/10/01	COMMISSIO N	851010268	851010088	85/09/24	50-361 P
8510090464	8510090441	85/10/02	FOIA	8510150015	8510150012	85/09/26	50-344 Q
8510090482	8510090469	85/09/25	WASTE MGT	8510150024	8510150023	85/10/03	50-483 P
8510090486	8510090476	85/10/02	COMMISSIO N	8510150026	8510150023	85/10/03	50-483 P
8510090499	8510090494	85/09/27	50-373 Q	8510150028	8510150027	85/09/05	1-88
8510090501	8510090494	85/09/27	50-373 Q	8510150036	8510150035	85/08/07	CONTRACT
8510090513	8510090512	85/09/25	40-8084	8510150039	8510150037	85/09/09	71-230
8510090517	8510090514	85/08/26	71-9188	8510150054	8510150049	85/10/05	50-416 P
8510090527	8510090525	85/09/24	50-397 Q	8510150073	8510150071	85/03/13	40-8027
8510090528	8510090521	85/10/02	50-277 P	8510150082	8510150076	85/10/07	50-27 Q
8510090530	8510090525	85/09/24	50-397 Q	8510150086	8510150076	85/10/07	50-27 Q
8510090533	8510090521	85/10/02	50-277 F	8510150098	8510150095	85/09/13	71-9202
8510100008	8510100001	85/10/03	50-445 Q	8510150102	8510150095	85/09/13	71-9202
8510100018	8510100006	85/10/04	50-268 Q	8510150112	8510150109	85/10/09	50-261 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 409

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510150123	8510150119	85/07/26	70-371	8510160016	8510160010	85/10/11	50-333 Q
8510150146	8510150139	85/10/08	50-267 Q	8510160018	8510160015	85/10/08	50-255 Q
8510150153	8510150142	85/09/20	40-1366	8510160024	8510160014	85/10/11	50-245 Q
8510150158	8510150142	85/09/20	FOIA	8510160037	8510160014	85/10/11	50-245 Q
8510150163	8510150142	85/09/20	40-1366	8510160038	8510160031	85/10/08	50-155 Q
8510150169	8510150142	85/09/20	FOIA	8510160051	8510160048	85/10/08	50-352 Q
8510150170	8510150142	85/09/20	FOIA	8510160054	8510160046	85/10/10	50-206 P
8510150176	8510150142	85/09/20	40-1366	8510160060	8510160053	85/10/11	50-344 P
8510150177	8510150172	85/10/07	50-206 Q	8510160064	8510160053	85/10/11	50-344 P
8510150201	8510150142	85/09/20	40-1366	8510160082	8510160068	85/10/10	50-259 Q
8510150203	8510150199	85/10/10	50-361 P	8510160083	8510160073	85/10/10	50-416 P
8510150206	8510150198	85/10/08	50-346 U	8510160100	8510160098	85/10/09	50-382 Q
8510150209	8510150142	85/09/20	FOIA	8510160102	8510160096	85/10/10	50-320 P
8510150214	8510150142	85/09/20	40-1366	8510160104	8510160094	85/10/11	50-338 Q
8510150220	8510150142	85/09/20	FOIA	8510160105	8510160099	85/10/08	FOIA
8510150226	8510150142	85/09/20	FOIA	8510160109	8510160098	85/10/09	50-382 Q
8510150228	8510150224	85/10/07	50-250 Q	8510160111	8510160099	85/10/08	FOIA
8510150230	8510150142	85/09/20	FOIA	8510160115	8510160103	85/10/01	FOIA
8510150235	8510150142	85/09/20	FOIA	8510160117	8510160099	85/10/08	FOIA
8510150236	8510150142	85/09/20	FOIA	8510160118	8510160113	85/10/11	50-526 P
8510150240	8510150142	85/09/20	FOIA	8510160121	8510160099	85/10/08	FOIA
8510150245	8510150142	85/09/20	FOIA	8510160122	8510160103	85/10/01	FOIA
8510150248	8510150244	85/10/03	50-382 P	8510160123	8510160119	85/10/09	50-341 P
8510150251	8510150142	85/09/20	40-1366	8510160125	8510160114	85/10/10	50-282 Q
8510150255	8510150252	85/10/07	50-390 A	8510160126	8510160099	85/10/08	FOIA
8510150266	8510150142	85/09/20	FOIA	8510160130	8510160099	85/10/08	FOIA
8510150272	8510150142	85/09/20	40-1366	8510160132	8510160103	85/10/01	FOIA
8510150276	8510150269	85/07/01	71-546	8510160140	8510160137	85/10/09	TOPREP
8510150291	8510150286	85/10/09	50-272 H	8510160141	8510160103	85/10/01	FOIA
8510150295	8510150286	35/10/09	50-272 H	8510160152	8510160103	85/10/01	FOIA
8510150299	8510150142	85/09/20	40-1366	8510160158	8510160155	85/10/08	50-602 A
8510150300	8510150286	85/10/09	50-272 H	8510160167	8510160160	85/10/11	50-315 P
8510150302	8510150297	85/08/02	71-384	8510160169	8510160163	85/10/08	70-3000
8510150303	8510150296	85/10/09	50-155 P	8510160171	8510160165	85/10/14	50-461 F
8510150304	8510150296	85/10/08	50-321 Q	8510160177	8510160168	85/10/09	50-254 Q
8510150317	8510150316	85/09/30	50-302 P	8510160182	8510160163	85/10/08	70-3000
8510150319	8510150316	85/09/30	50-302 P	8510160183	8510160174	85/09/26	50-206 P
8510150325	8510150142	85/09/20	FOIA	8510160187	8510160174	85/09/26	50-206 P
8510150330	8510150142	85/09/20	FOIA	8510160188	8510160163	85/10/08	70-3000
8510150335	8510150142	85/09/20	FOIA	8510160189	8510160179	85/10/08	50-282 F
8510150336	8510150331	85/10/08	70-143	8510160190	8510160103	85/10/01	FOIA
8510150339	8510150333	85/10/10	50-29 P	8510160193	8510160174	85/09/26	50-206 P
8510150344	8510150142	85/09/20	40-1366	8510160195	8509110513	85/07/15	50-348 R
8510150345	8510150342	85/10/08	70-754	8510160207	8510160103	85/10/01	FOIA
8510150356	8510150353	85/10/08	50-302 R	8510160212	8510160103	85/10/01	FOIA
8510150357	8510150353	85/10/08	50-302 R	8510160216	8510160214	85/10/10	50-416 F
8510150359	8510150354	85/10/10	50-440 G	8510160222	8510160103	85/10/01	FOIA
8510150363	8510150354	85/10/10	50-440 G	8510160231	8510160226	85/10/09	50-272 Q
8510150364	8510150142	85/09/20	40-1366	8510160234	8510160232	85/10/10	50-440 Q
8510150366	8510150354	85/10/10	50-440 G	8510160251	8510160249	85/09/30	50-247 Q
8510150367	8510150142	85/09/20	40-1366	8510160257	8510160255	85/10/08	50-382 Q
8510150368	8510150354	85/10/10	50-440 G	8510160259	8510160256	85/10/09	50-295 F
8510150370	8510150142	85/09/20	40-1366	8510160261	8510160103	85/10/01	FOIA
8510150371	8510150369	85/10/07	50-245 P	8510160266	8510160103	85/10/01	FOIA
8510150373	8510150142	85/09/20	40-1366	8510160270	8510160248	85/10/04	50-295 Q
8510150374	8510150142	85/09/20	40-1366	8510160273	8510160103	85/10/01	FOIA
8510150378	8510150142	85/09/20	40-1366	8510160274	8510160272	85/10/10	50-295 Q
8510150381	8510150142	85/09/20	40-1366	8510160276	8510160246	85/10/11	50-348 F
8510150382	8510150379	85/10/08	50-70 Q	8510160277	8510160103	85/10/01	FOIA
8510150386	8510150142	85/09/20	40-1366	8510160281	8510160103	85/10/01	FOIA
8510150389	8510150142	85/09/20	FOIA	8510160284	8510160280	85/10/09	50-289 G
8510150394	8510150142	85/09/20	40-1366	8510160293	8510160103	85/10/01	FOIA
8510150396	8510150142	85/08/20	FOIA	8510160294	8510160286	85/10/10	50-369 Q
8510150397	8510150392	85/10/09	50-305 P	8510160297	8510280421	85/10/23	50-423 F
8510150400	8510150142	85/09/20	FOIA	8510160302	8510160300	85/10/11	50-413 P
8510150401	8510150399	85/10/10	50-387 P	8510160307	8510160304	85/09/13	40-8027
8510150402	8510150142	85/09/20	FOIA	8510160308	8510160305	85/09/12	40-672
8510150404	8510150142	85/09/20	40-1366	8510160310	8510160305	85/09/12	40-672
8510150406	8510150142	85/09/20	FOIA	8510160313	8510160305	85/09/12	40-672
8510150407	8510150142	85/09/20	FOIA	8510160315	8510160314	85/10/10	TOPREP
8510150411	8510150406	85/10/08	50-528 Q	8510160316	8510160305	85/09/12	40-672
8510150417	8510150142	85/09/20	40-1366	8510160317	8510160305	85/09/12	40-672
8510150420	8510150142	85/09/20	FOIA	8510160319	8510160318	85/09/26	50-277 F
8510150423	8510150142	85/08/20	FOIA	8510160324	8510160322	85/10/09	CONTRACT
8510150425	8510150421	85/10/09	50-346 S	8510160332	8510160329	85/10/07	NUREG
8510150451	8510150449	85/10/04	50-445 A	8510160333	8510160330	85/09/30	CONTRACT
8510150454	8510150449	85/10/04	50-445 A	8510160345	8510160344	85/10/10	50-331 P
8510150465	8510150461	85/09/27	50-133 Q	8510160347	8510160344	85/10/10	50-331 P
8510150469	8510150466	85/10/09	50-317 P	8510160348	8510170011	85/10/08	70-143
8510150471	8510150467	85/10/04	MISC	8510170014	8510170011	85/10/08	70-143
8510150473	8510150468	85/10/09	50-317 P	8510170024	8510170019	85/09/27	FOIA
8510150474	8510150467	85/10/04	MISC	8510170027	8510170019	85/09/27	FOIA
8510150480	8510150475	85/10/09	50-454 P	8510170031	8510170019	85/09/27	FOIA
8510150481	8510150477	85/09/30	CONTRACT	8510170033	8510170019	85/09/27	FOIA
8510150484	8510280427	85/10/22	50-387 P	8510170036	8510170019	85/09/27	FOIA
8510160007	8510160004	85/10/09	50-331 Q	8510170038	8510170019	85/09/27	FOIA
8510160011	8510160004	85/10/09	50-331 Q	8510170041	8510170019	85/09/27	FOIA

410 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510170042	8510170040	85/10/07	50-316 S	8510170268	8510170221	85/10/04	50-264 Q
8510170044	8510170019	85/09/27	40-8355 S	8510170270	8510170221	85/10/04	50-264 Q
8510170045	8510170040	85/10/07	50-316 S	8510170273	8510170221	85/10/04	FOIA Q
8510170050	8510170019	85/09/27	FOIA	8510170286	8510170287	85/10/07	50-423 Q
8510170052	8510170019	85/09/27	FOIA	8510170287	8510170289	85/10/15	50-316 P
8510170054	8510170053	85/09/25	50-361 Q	8510170296	8510170295	85/10/02	50-410 Q
8510170056	8510170019	85/09/27	FOIA	8510170301	8510170298	85/09/30	50-326 Q
8510170057	8510170048	85/10/07	FOIA	8510170304	8510170298	85/09/30	50-326 Q
8510170060	8510170019	85/09/27	FOIA	8510170309	8510170306	85/10/07	50-440 Q
8510170062	8510170048	85/09/26	50-206 P	8510170315	8510170311	85/10/10	50-413 P
8510170064	8510170019	85/09/27	FOIA	8510170317	8510170313	85/10/07	50-456 Q
8510170067	8510170048	85/09/26	50-206 Q	8510170320	8510170314	85/10/11	TOPREP
8510170070	8510170048	85/09/26	50-206 P	8510170322	8510170221	85/10/04	50-264 Q
8510170072	8510170071	85/10/10	71-6722	8510170326	8510170323	85/09/16	40-8783
8510170073	8510170048	85/09/26	50-206 P	8510170327	8510170221	85/10/04	50-264 Q
8510170075	8510170061	85/10/15	50-309 F	8510170328	8510170325	85/10/11	TOPREP
8510170077	8510170048	85/09/26	50-206 P	8510170329	8510170221	85/10/04	50-264 Q
8510170079	8510170074	85/10/08	50-280 P	8510170334	8510170221	85/10/04	50-264 Q
8510170080	8510170048	85/09/26	50-206 P	8510170335	8510170330	85/10/04	50-456 Q
8510170083	8510170078	85/10/03	50-266 P	8510170344	8510170338	85/10/01	50-397 Q
8510170086	8510170048	85/09/26	50-206 P	8510170349	8510170346	85/10/08	50-413 P
8510170087	8510170078	85/10/03	50-266 P	8510170352	8510170346	85/10/08	50-413 Q
8510170092	8510170085	85/09/30	50-361 P	8510170353	8510170281	85/10/11	50-331 P
8510170093	8510170048	85/09/26	50-206 P	8510170355	8510170354	85/10/01	50-70 Q
8510170097	8510170048	85/09/26	50-206 P	8510170357	8510170346	85/10/08	50-413 Q
8510170101	8510170090	85/10/09	50-361 P	8510170358	8510170354	85/10/01	50-70 Q
8510170102	8510170095	85/09/30	FOIA	8510170361	8510170359	85/10/08	50-263 P
8510170105	8510170095	85/09/30	FOIA	8510170362	8510170359	85/10/08	50-263 P
8510170106	8510170090	85/10/09	50-361 P	8510170375	8510170371	85/10/03	50-313 Q
8510170111	8510170108	85/10/01	50-445 A	8510170378	8510170371	85/10/03	50-313 Q
8510170112	8510170095	85/09/30	FOIA	8510170387	8510170382	85/07/03	50-272 P
8510170119	8510170115	85/09/30	CONTRACT	8510170403	8510170398	85/09/23	NUREG
8510170121	8510170114	85/10/09	MISC	8510170406	8510170397	85/08/28	40-299
8510170123	8510170117	85/10/15	50-267 P	8510170410	8510170402	85/10/03	50-313 Q
8510170124	8510170095	85/09/30	FOIA	8510170413	8510170409	85/09/05	40-8102
8510170126	8510170095	85/09/30	FOIA	8510170423	8510170418	85/10/08	FOIA
8510170127	8510170117	85/10/15	50-267 P	8510170429	8510170418	85/10/08	FOIA
8510170130	8510170095	85/09/30	FOIA	8510170438	8510170435	85/10/07	MISC
8510170132	8510170095	85/09/30	FOIA	8510170441	8510170418	85/10/08	FOIA
8510170134	8510170095	85/09/30	FOIA	8510170443	8510170418	85/10/08	FOIA
8510170137	8510170133	85/10/02	50-309 P	8510170447	8510170447	85/09/10	40-8064
8510170138	8510170095	85/09/30	FOIA	8510170463	8510170463	85/10/11	50-282 P
8510170142	8510170095	85/09/30	FOIA	8510170467	8510170463	85/10/11	50-282 P
8510170144	8510170140	85/10/10	50-388 P	8510170480	8510170479	85/10/12	50-445 A
8510170146	8510170095	85/09/30	FOIA	8510180016	8510180015	85/10/04	50-338 A
8510170147	8510170143	85/10/07	50-320 Q	8510180019	8510180018	85/10/04	50-440 Q
8510170150	8510170149	85/10/07	50-219 Q	8510180038	8510180033	85/09/30	50-280 Y
8510170151	8510170140	85/10/10	50-388 P	8510180042	8510180037	85/10/02	40-8714
8510170153	8510170149	85/10/07	50-219 Q	8510180054	8510180053	85/10/04	70-27
8510170159	8510170100	85/10/11	50-322 P	8510180058	8510180053	85/10/04	70-27
8510170166	8510170095	85/09/30	FOIA	8510180060	8510180051	85/10/15	50-463 P
8510170169	8510170100	85/10/11	50-322 P	8510180061	8510180057	85/10/11	50-423 Q
8510170170	8510170164	85/10/07	50-263 P	8510180071	8510180065	85/10/03	70-143
8510170173	8510170095	85/09/30	FOIA	8510180077	8510180073	85/10/11	50-219 P
8510170174	8510170100	85/10/11	50-322 P	8510180078	8510180072	85/10/09	70-143
8510170176	8510170164	85/10/07	50-263 P	8510180085	8510180084	85/10/10	50-320 H
8510170178	8510170100	85/10/11	50-322 P	8510180090	8510180087	85/10/11	50-335 P
8510170180	8510170100	85/10/11	50-322 P	8510180096	8510180087	85/10/11	50-335 P
8510170184	8510170100	85/10/11	50-322 P	8510180099	8510180097	85/10/08	REVIEW GR
8510170186	8510170095	85/09/30	FOIA	8510180103	8510180091	85/09/20	50-335 Q
8510170187	8510170100	85/10/11	50-322 P	8510180107	8510180102	85/10/10	50-344 P
8510170190	8510170100	85/10/11	50-322 P	8510180109	8510180104	85/10/16	50-213 P
8510170193	8510170100	85/10/11	50-322 P	8510180110	8510180104	85/10/16	50-213 P
8510170194	8510170095	85/09/30	FOIA	8510180115	8510180082	85/08/30	50-440 A
8510170195	8510170188	85/10/11	50-458 P	8510180118	8510180082	85/08/30	50-440 A
8510170198	8510170188	85/10/11	50-458 P	8510180133	8510180124	85/10/10	50-413 Q
8510170199	8510170100	85/10/11	50-322 P	8510180137	8510180132	85/10/01	50-244 P
8510170200	8510170095	85/09/30	FOIA	8510180142	8510180132	85/10/09	50-244 P
8510170202	8510170100	85/10/11	50-322 P	8510180143	8510180139	85/10/04	50-275 F
8510170205	8510170100	85/10/11	50-322 P	8510180145	8510180141	85/10/11	50-344 P
8510170206	8510170095	85/09/30	FOIA	8510180161	8510110011	85/10/07	50-329 A
8510170210	8510170095	85/09/30	FOIA	8510180165	8510180163	85/10/11	FOIA
8510170211	8510170100	85/10/11	50-322 P	8510180173	8510180167	85/10/18	50-361 P
8510170213	8510170100	85/10/11	50-322 P	8510180175	8510110011	85/10/07	50-329 A
8510170215	8510170100	85/10/11	50-322 P	8510180192	8510180171	85/10/09	PR
8510170217	8510170100	85/10/11	50-322 P	8510180195	8510180191	85/10/02	40-1162
8510170219	8510170095	85/09/30	FOIA	8510180198	8510180171	85/10/09	PR
8510170220	8510170095	85/09/30	FOIA	8510180200	8510180191	85/10/02	40-1162
8510170224	8510170218	85/10/08	50-316 Q	8510180202	8510180171	85/10/09	PR
8510170234	8510170221	85/10/04	50-264 Q	8510180209	8510180171	85/10/09	PR
8510170242	8510170221	85/10/04	50-264 Q	8510180213	8510180171	85/10/09	PR
8510170252	8510170221	85/10/04	50-264 Q	8510180217	8510180212	85/09/30	50-482 R
8510170253	8510170249	85/10/09	50-293 P	8510180220	8510180171	85/10/09	PR
8510170255	8510170249	85/10/09	50-293 P	8510180222	8510180212	85/09/30	50-482 R
8510170257	8510170254	85/10/07	50-322 Q	8510180224	8510180171	85/10/09	PR
8510170260	8510170221	85/10/04	50-264 Q	8510180226	8510180171	85/10/09	PR
8510170263	8510170221	85/10/04	50-264 Q	8510180229	8510180171	85/10/09	PR

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 411

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510180233	8510180171	85/10/09	PR	8510210047	8510210008	85/10/04	50-454 Q
8510180234	8510180227	85/09/26	40-8681	8510210051	8510210043	85/10/16	50-454 Q
8510180237	8510180171	85/10/09	PR	8510210058	8510210046	85/10/16	50-250 Q
8510180238	8510180227	85/09/26	40-8681	8510210066	8510210059	85/10/14	50-312 P
8510180242	8510180239	85/10/09	50-261 R	8510210068	8510210062	85/10/17	50-443 A
8510180243	8510180227	85/09/26	40-8681	8510210073	8510210064	85/10/15	50-10 F
8510180244	8510180171	85/10/09	PR	8510210090	8510210086	85/10/17	50-354 Q
8510180246	8510180239	85/10/09	50-261 R	8510210091	8510210081	85/10/17	50-440 Q
8510180249	8510180227	85/09/26	40-8681	8510210099	8510210093	85/10/15	50-29 P
8510180251	8510180171	85/10/09	PR	8510210117	8510210113	85/10/15	50-410 Q
8510180256	8510180171	85/10/09	PR	8510210120	8510210119	85/10/15	50-29 P
8510180263	8510180171	85/10/09	PR	8510210125	8510210118	85/09/18	40-8681
8510180264	8510180239	85/10/09	PR	8510210130	8510210127	85/10/16	50-440 P
8510180272	8510180171	85/10/09	PR	8510210134	8510210127	85/10/16	50-244 P
8510180279	8510180171	85/10/09	PR	8510210135	8510210132	85/10/08	40-8688
8510180280	8510180171	85/10/09	PR	8510210136	8510210133	85/10/17	50-528 P
8510180281	8510180275	85/10/15	50-387 P	8510210137	8510210133	85/10/17	50-528 P
8510180286	8510180171	85/10/09	PR	8510210139	8510210138	85/10/15	50-410 Q
8510180290	8510180171	85/10/09	PR	8510210145	8510210143	85/10/15	TOPREP
8510180291	8510180171	85/10/09	PR	8510210147	8510210146	85/10/17	50-277 P
8510180297	8510180171	85/10/09	PR	8510210151	8510210146	85/10/17	50-277 P
8510180301	8510180171	85/10/09	PR	8510210153	8510210152	85/10/16	50-346 Q
8510180307	8510180302	85/10/16	40-8681	8510210154	8510210150	85/10/15	50-354 Q
8510180309	8510180171	85/10/09	PR	8510210155	8510210155	85/10/17	50-247 Q
8510180313	8510180305	85/10/02	40-8452	8510210159	8510250580	85/10/11	50-412 A
8510180314	8510180171	85/10/09	PR	8510210180	8510210173	85/10/16	50-315 Q
8510180318	8510180315	85/10/15	50-206 P	8510210183	8510210181	85/10/17	50-163 Q
8510180321	8510180171	85/10/09	PR	8510210186	8510210173	85/10/16	50-315 Q
8510180322	8510180305	85/10/02	40-8452	8510210187	8510210181	85/10/17	50-163 P
8510180323	8510180315	85/10/15	50-206 P	8510210194	8510210189	85/10/09	50-269 P
8510180326	8510180171	85/10/09	PR	8510210197	8510210189	85/10/09	50-269 P
8510180330	8510180171	85/10/09	PR	8510210200	8510210191	85/10/04	CONTRACT
8510180336	8510180328	85/10/16	50-361 P	8510210204	8510210202	85/10/09	CONTRACT
8510180347	8510180344	85/10/15	50-250 G	8510210220	8510210218	85/10/16	50-237 Q
8510180350	8510180348	85/10/15	50-261 Q	8510210223	8510210218	85/10/16	50-237 Q
8510180355	8510180353	85/10/07	50-423 A	8510210228	8510210219	85/10/10	50-322 Q
8510180356	8510180353	85/10/07	50-423 A	8510210236	8510210230	85/09/23	40-7604
8510180370	8510180365	85/10/16	50-213 P	8510210247	8510210240	85/09/17	70-820
8510180382	8510180381	85/10/04	50-414 Q	8510210271	8510210269	85/09/10	70-698
8510180383	8510180379	85/10/11	50-417 Q	8510210293	8510210291	85/10/09	50-482 Q
8510180388	8510180381	85/10/04	50-114 Q	8510210298	8510210291	85/10/09	50-482 Q
8510180396	8510180392	85/10/16	50-382 G	8510210303	8510210302	85/08/29	70-137
8510180402	8510180400	85/10/11	FOIA	8510220003	8510220002	85/10/10	50-282 Q
8510180406	8510180405	85/10/16	QA999	8510220004	8510220002	85/10/10	50-282 Q
8510180410	8510180406	85/10/11	50-447 A	8510220006	8510220005	85/10/08	50-440 Q
8510180416	8510180411	85/10/10	50-423 Q	8510220013	8510220012	85/10/11	50-440 Q
8510180429	8510180426	85/10/09	50-335 Q	8510220016	8510220015	85/10/15	71-133
8510180435	8510180431	85/10/10	50-261 Q	8510220017	8510220010	85/10/11	50-352 Q
8510180437	8510180432	85/08/29	40-6659	8510220027	8510220024	85/10/15	50-29 P
8510180439	8510180432	85/08/29	40-6659	8510220029	8510220022	85/03/12	TOPREP
8510180441	8510180432	85/08/29	40-6659	8510220039	8510220035	85/10/17	71-5088
8510180443	8510180432	85/08/29	40-6659	8510220040	8510220036	85/10/16	50-346 P
8510180446	8510180432	85/08/29	40-6659	8510220042	8510220037	85/10/17	50-320 P
8510180450	8510180442	85/10/09	FOIA	8510220059	8510220055	85/10/16	50-29 P
8510180452	8510180442	85/10/09	FOIA	8510220061	8510220057	85/10/11	50-412 Q
8510180455	8510180442	85/10/09	FOIA	8510220069	8510220064	85/10/11	50-247 Q
8510180459	8510180442	85/10/09	FOIA	8510220070	8510220063	85/10/04	50-528 Q
8510180463	8510180458	85/10/01	50-302 Q	8510220075	8510220063	85/10/04	50-528 Q
8510180464	8510180460	85/10/02	40-299	8510220077	8510220073	85/10/10	50-454 Q
8510180466	8510180442	85/10/09	FOIA	8510220078	8510220074	85/10/15	50-458 S
8510180469	8510180460	85/10/02	40-299	8510220080	8510220071	85/10/08	50-397 P
8510180473	8510180470	85/10/02	40-4492	8510220083	8510220074	85/10/15	50-458 P
8510180474	8510180471	85/03/26	50-272	8510220096	8510220092	85/10/16	50-244 P
8510180476	8510180470	85/10/02	40-4492	8510220099	8510220092	85/10/16	50-244 P
8510180479	8510180477	85/10/02	40-8584	8510220100	8510220097	85/09/23	71-121
8510180480	8510180477	85/10/02	40-8584	8510220106	8510220103	85/10/11	50-244 Q
8510180482	8510180477	85/10/02	40-8584	8510220111	8510220082	85/10/18	70-143
8510180484	8510180442	85/10/09	FOIA	8510220112	8510220107	85/10/04	50-261 Q
8510180486	8510180485	85/10/01	40-8084	8510220114	8510220113	85/10/11	50-388 P
8510180489	8510180485	85/10/01	40-8084	8510220117	8510220113	85/10/11	50-388 P
8510180490	8510180487	85/09/24	40-8102	8510220133	8510220124	85/10/18	50-334 Q
8510180491	8510180442	85/10/09	FOIA	8510220137	8510220125	85/10/16	50-445 A
8510180492	8510180487	85/09/24	40-8102	8510220144	8510220134	85/10/16	FOIA
8510180496	8510180442	85/10/09	FOIA	8510220148	8510220125	85/10/16	FOIA
8510180500	8510180442	85/10/09	50-289 P	8510220153	8510220149	85/10/14	50-320 P
8510180501	8510180499	85/10/16	71-88	8510220154	8510220125	85/10/16	50-445 A
8510180503	8510180495	85/10/09	50-259 T	8510220159	8510220155	85/10/17	50-482 F
8510180504	8510180442	85/10/09	FOIA	8510220161	8510220125	85/10/16	50-445 A
8510180517	8510180512	85/10/11	50-269 P	8510220165	8510220180	85/10/16	50-309 P
8510180526	8510180521	85/10/10	71-133	8510220169	8510220162	85/10/10	FOIA
8510180533	8510180531	85/09/30	70-143	8510220171	8510220125	85/10/16	50-445 A
8510180535	8510180529	85/10/15	71-E	8510220175	8510220167	85/10/15	70-25
8510210012	8510210011	85/10/15	50-454 Q	8510220176	8510220162	85/10/10	50-410 A
8510210013	8510210011	85/10/15	50-454 Q	8510220178	8510220125	85/10/16	50-445 A
8510210018	8510210008	85/10/04	50-454 Q	8510220181	8510220177	85/10/17	50-272 Q
8510210027	8510210023	85/10/18	QA999	8510220184	8510220162	85/10/10	50-410 Q
8510210037	8510210033	85/10/17	QA999	8510220187	8510220125	85/10/16	FOIA

412 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510220188	8510220167	85/10/15	70-25	8510230042	8510230016	85/10/04	50-321 U
8510220192	8510220177	85/10/17	50-272 Q	8510230043	8510230036	85/10/11	50-373 F
8510220193	8510220190	85/10/16	50-213 P	8510230045	8510230016	85/10/04	50-346 U
8510220198	8510220167	85/10/15	70-25	8510230047	8510230038	85/10/18	50-309 Q
8510220199	8510220196	85/10/16	50-390 F	8510230048	8510230016	85/10/04	50-321 U
8510220200	8510220194	85/07/19	40-2061	8510230051	8510230016	85/10/04	50-348 U
8510220202	8510220125	85/10/16	50-445 A	8510230054	8510230016	85/10/04	50-366 Q
8510220206	8510220190	85/10/16	50-213 P	8510230057	8510230016	85/10/04	FOIA
8510220207	8510220197	85/10/03	50-424 A	8510230058	8510230016	85/10/04	50-321 U
8510220208	8510220125	85/10/16	50-445 A	8510230060	8510230016	85/10/04	50-418 U
8510220210	8510220167	85/10/15	70-25	8510230061	8510230056	85/10/11	50-455 Q
8510220211	8510220197	85/10/03	50-424 A	8510230064	8510230059	85/10/18	50-413 P
8510220215	8510220125	85/10/13	50-445 A	8510230065	8510230016	85/10/04	50-289 U
8510220216	8510220213	85/10/18	TOPREP	8510230069	8510230016	85/10/04	50-277 U
8510220217	8510220212	85/10/09	50-271 P	8510230077	8510230016	85/10/04	FOIA
8510220220	8510220197	85/10/03	50-424 A	8510230082	8510230074	85/10/21	50-322 P
8510220223	8510220167	85/10/15	70-25	8510230085	8510230016	85/10/04	50-259 U
8510220225	8510220125	85/10/16	50-445 A	8510230086	8510230016	85/10/21	50-322 P
8510220227	8510220218	85/10/16	50-362 Q	8510230090	8510230016	85/10/04	50-382 U
8510220229	8510220219	85/10/03	50-302 Q	8510230097	8510230016	85/10/04	50-259 U
8510220232	8510220228	85/10/18	50-288 F	8510230098	8510230016	85/10/04	50-331 U
8510220239	8510220125	85/10/16	50-382 P	8510230102	8510230016	85/10/04	50-220 U
8510220241	8510220235	85/10/18	40-8027	8510230106	8510230016	85/10/04	50-482 U
8510220242	8510220238	85/10/18	50-440 Q	8510230111	8510230105	85/10/18	50-266 F
8510220245	8510220167	85/10/15	70-25	8510230113	8510230109	85/10/18	50-293 Q
8510220252	8510220125	85/10/16	50-382 P	8510230114	8510230016	85/10/04	70-143
8510220255	8510220249	85/10/15	50-315 F	8510230115	8510230112	85/10/06	50-446 Q
8510220257	8510220167	85/10/15	70-25	8510230118	8510230016	85/10/04	50-528 U
8510220258	8510220253	85/10/15	50-255 P	8510230120	8510230117	85/08/29	50-346 P
8510220261	8510220253	85/10/15	50-255 P	8510230122	8510230117	85/08/29	50-346 P
8510220265	8510220262	85/10/16	50-272 P	8510230124	8510230121	85/10/01	50-282 R
8510220272	8510220167	85/10/15	70-25	8510230126	8510230016	85/10/04	50-327 U
8510220278	8510220274	85/10/09	50-244 P	8510230129	8510230016	85/10/04	FOIA
8510220281	8510220277	85/10/17	50-293 Q	8510230134	8510230016	85/10/04	50-293 U
8510220283	8510220274	85/10/09	50-244 P	8510230139	8510230016	85/10/04	FOIA
8510220284	8510220277	85/10/17	50-293 Q	8510230142	8510230016	85/10/04	FOIA
8510220285	8510220282	85/10/15	50-263 Q	8510230143	8510230138	85/10/18	50-336 Q
8510220292	8510220286	85/10/16	50-445 Q	8510230146	8510230016	85/10/04	50-10 U
8510220299	8510220294	85/10/17	50-409 Q	8510230147	8510230141	85/10/16	50-395 P
8510220301	8510220298	85/10/15	50-482 Q	8510230148	8510230144	85/10/18	50-331 Q
8510220305	8510220302	85/10/18	50-498 F	8510230150	8510230016	85/10/04	50-272 U
8510220308	8510220304	85/10/07	50-295 P	8510230154	8510230144	85/10/18	50-331 Q
8510220311	8510220309	85/10/11	50-498 A	8510230155	8510230141	85/10/16	50-395 F
8510220312	8510220303	85/10/16	50-445 Q	8510230157	8510230153	85/10/14	50-369 P
8510220319	8510220315	85/10/16	50-272 R	8510230162	8510230141	85/10/16	50-395 P
8510220324	8510220318	85/10/17	50-397 P	8510230163	8510230158	85/10/18	50-317 Q
8510220326	8510220320	85/10/16	50-272 P	8510230164	8510230016	85/10/04	50-382 U
8510220332	8510220322	85/10/11	50-313 Q	8510230165	8510230160	85/10/18	50-315 Q
8510220334	8510220329	85/10/17	50-354 E	8510230169	8510230160	85/10/18	50-315 Q
8510220336	8510220333	85/10/14	50-440 F	8510230170	8510230016	85/10/04	50-416 U
8510220337	8510220330	85/10/17	50-286 P	8510230173	8510230016	85/10/04	50-275 U
8510220340	8510220330	85/10/17	50-286 P	8510230175	8510230016	85/10/04	50-416 U
8510220342	8510220339	85/10/15	50-482 Q	8510230182	8510230016	85/10/04	50-334 U
8510220346	8510220341	85/10/16	50-482 Q	8510230185	8510230016	85/10/04	50-409 U
8510220349	8510220347	85/10/11	50-333 P	8510230188	8510230183	85/10/17	50-387 Q
8510220352	8510220347	85/10/11	50-333 P	8510230189	8510230016	85/10/04	50-251 U
8510220354	8510220353	85/10/16	50-272 P	8510230191	8510230016	85/10/04	50-277 U
8510220359	8510220358	85/10/15	50-458 Q	8510230194	8510230183	85/10/17	50-387 Q
8510220360	8510220357	85/10/16	50-498 Q	8510230195	8510230192	85/10/21	50-352 Q
8510220363	8510220361	85/10/18	50-263 Q	8510230196	8510230193	85/10/18	50-247 Q
8510220366	8510220365	85/10/11	50-416 P	8510230197	8510230016	85/10/04	50-296 U
8510220370	8510220368	85/10/15	50-346 S	8510230198	8510230016	85/10/04	70-123 Q
8510220373	8510220368	85/10/15	50-346 S	8510230200	8510230199	85/10/17	50-387 Q
8510220376	8510220371	85/10/22	50-244 P	8510230202	8510230199	85/10/17	50-387 Q
8510220379	8510220371	85/10/22	50-244 P	8510230203	8510230016	85/10/04	50-387 U
8510220396	8510220387	85/10/04	50-250 Q	8510230205	8510230016	85/10/04	50-321 U
8510220398	8510220394	85/10/04	50-324 Q	8510230208	8510230201	85/10/18	50-352 Q
8510220406	8510220404	85/10/04	50-261 Q	8510230210	8510230190	85/09/18	50-97 Q
8510220415	8510220413	85/10/03	50-321 Q	8510230211	8510230209	85/10/18	50-400 T
8510220417	8510220414	85/10/08	50-295 Q	8510230213	8510230190	85/09/18	50-97 Q
8510220418	8510220413	85/10/03	50-321 Q	8510230214	8510230209	85/10/18	50-400 T
8510220420	8510220414	85/10/08	50-295 Q	8510230220	8510230016	85/10/04	50-259 U
8510220423	8510220421	85/10/11	50-219 Q	8510230222	8510230016	85/10/04	50-250 U
8510220426	8510220426	85/10/03	FOIA	8510230223	8510230209	85/10/18	50-400 T
8510220434	8510220432	85/10/10	50-219 U	8510230225	8510230209	85/10/18	50-400 T
8510220445	8510220440	85/10/17	50-445 Q	8510230227	8510230209	85/10/18	50-400 T
8510220453	8510220447	85/10/09	50-458 Q	8510230228	8510230016	85/10/04	70-143 Q
8510220458	8510220455	85/10/11	50-445 Q	8510230234	8510230016	85/10/04	50-280 U
8510220464	8510220460	85/10/11	50-298 Q	8510230236	8510230233	85/10/18	50-244 Q
8510230011	8510230009	85/10/16	50-334 F	8510230241	8510230016	85/10/04	70-2953
8510230018	8510230016	85/10/04	50-325 U	8510230242	8510230238	85/10/11	50-373 F
8510230022	8510230019	85/10/17	50-335 P	8510230244	8510230233	85/10/18	50-244 Q
8510230023	8510230016	85/10/04	50-413 U	8510230246	8510230016	85/10/04	50-261 U
8510230027	8510230016	85/10/04	50-250 U	8510230250	8510230016	85/10/04	50-362 U
8510230029	8510230020	85/10/16	50-483 P	8510230253	8510230016	85/10/04	50-416 U
8510230032	8510230016	85/10/04	50-320 U	8510230257	8510230256	85/10/15	70-824
8510230041	8510230016	85/10/04	50-296 U	8510230258	8510230256	85/10/15	70-824

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 413

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510230261	8510230016	85/10/04	50-482 U	8510250066	8510250059	85/10/16	50-416 Q
8510230262	8510230259	85/10/17	50-320 P	8510250078	8510250062	85/10/17	50-57 Q
8510230263	8510230260	85/10/15	70-1489	8510250092	8510250081	85/10/17	50-272 Q
8510230264	8510230259	85/10/17	50-320 P	8510250095	8510250087	85/10/21	50-305 Q
8510230266	8510230016	85/10/04	50-346 U	8510250137	8510250129	85/10/21	50-282 Q
8510230274	8510230016	85/10/04	50-346 U	8510250146	8510250132	85/10/15	50-277 Q
8510230283	8510230016	85/10/04	50-315 U	8510250158	8510250153	85/10/21	50-254 Q
8510230293	8510230016	85/10/04	50-250 U	8510250169	8510250165	85/10/18	50-346 Q
8510230304	8510230016	85/10/04	50-387 U	8510250171	8510250161	85/10/16	50-219 Q
8510230312	8510230016	85/10/04	50-259 U	8510250173	8510250165	85/10/18	50-346 Q
8510230323	8510230016	85/10/04	50-369 L	8510250186	8510250180	85/10/15	50-289 Q
8510230325	8510230016	85/10/04	50-298 U	8510250188	8510250181	85/09/27	50-528 F
8510230327	8510230016	85/10/04	50-280 U	8510250193	8510250180	85/10/15	50-289 Q
8510230337	8510230016	85/10/04	50-259 U	8510250213	8510250203	85/10/17	CONTRACT
8510230342	8510230016	85/10/04	50-302 U	8510250225	8510250222	85/10/18	CONTRACT
8510230346	8510230016	85/10/04	FOIA	8510250273	8510250260	85/10/18	50-293 Q
8510240036	8510240034	85/10/17	CONTRACT	8510250274	8510250264	85/10/16	50-416 F
8510240040	8510240039	85/10/16	50-346 R	8510250276	8510250271	85/10/10	50-266 Q
8510240045	8510240043	85/10/18	50-327 R	8510250282	8510250271	85/10/10	50-266 Q
8510240074	8510240067	85/10/17	50-255 K	8510250283	8510250270	85/10/21	50-373 Q
8510240079	8510240070	85/10/18	50-445 T	8510250323	8510250318	85/10/16	50-390 H
8510240092	8510240086	85/10/10	WASTE MGT	8510250329	8510250318	85/10/16	50-390 H
8510240100	8510240086	85/10/10	WASTE MGT	8510250359	8510250354	85/10/18	50-229 F
8510240108	8510240103	85/10/18	50-219 P	8510250364	8510250354	85/10/18	50-289 F
8510240110	8510240086	85/10/10	WASTE MGT	8510250375	8510250354	85/10/18	50-289 F
8510240112	8510240107	85/10/11	50-458 Q	8510250384	8510250378	85/10/23	50-461 E
8510240116	8510240106	85/10/11	50-272 R	8510250417	8510250412	85/10/22	50-423 Q
8510240117	8510240086	85/10/10	WASTE MGT	8510250421	8510250413	85/10/18	50-313 Q
8510240119	8510240086	85/10/10	WASTE MGT	8510250426	8510250418	85/10/17	50-220 P
8510240121	8510240086	85/10/10	WASTE MGT	8510250431	8510250418	85/10/17	50-220 P
8510240150	8510240134	85/10/08	WASTE MGT	8510250435	8510250420	85/10/21	50-317 Q
8510240152	8510240140	85/10/11	50-458 Q	8510250440	8510250293	85/10/18	50-259 R
8510240155	8510240134	85/10/08	WASTE MGT	8510250445	8510250442	85/10/22	50-354 Q
8510240159	8510240134	85/10/08	WASTE MGT	8510250449	8510250444	85/10/22	50-255 P
8510240163	8510240134	85/10/08	WASTE MGT	8510250455	8510250452	85/10/23	50-305 P
8510240192	8510240188	85/10/02	WASTE MGT	8510250458	8510250456	85/10/18	50-271 Q
8510240234	8510240222	85/10/18	50-395 P	8510250459	8510250457	85/10/21	50-458 Q
8510240262	8510240256	85/10/07	50-423 A	8510250462	8510250457	85/10/21	50-458 Q
8510240270	8510240266	85/10/14	50-409 K	8510250465	8510250454	85/10/18	50-334 Q
8510240273	8510250263	85/10/01	WASTE MGT	8510250471	8510250466	85/10/15	PR
8510240276	8510250263	85/10/01	WASTE MGT	8510250475	8510250470	85/10/22	50-423 Q
8510240281	8510240269	85/10/04	50-206 Q	8510250482	8510250481	85/10/17	50-354 A
8510240283	8510250263	85/10/01	WASTE MGT	8510250483	8510250481	85/10/17	50-354 A
8510240290	8510240284	85/10/10	WASTE MGT	8510250484	8510250481	85/10/17	50-354 A
8510240298	8510240294	85/10/18	50-458 Q	8510250486	8510250481	85/10/17	50-354 A
8510240310	8510240301	85/10/18	50-309 P	8510250487	8510250481	85/10/17	50-354 A
8510240312	8510240294	85/10/18	50-458 Q	8510250488	8510250481	85/10/17	50-354 A
8510240323	8510240318	85/10/22	50-320 G	8510250490	8510250481	85/10/17	50-354 A
8510240329	8510240318	85/10/22	50-320 G	8510250492	8510250481	85/10/17	50-354 A
8510240334	8510240293	85/10/18	50-285 Q	8510250497	8510250493	85/10/21	50-272 Q
8510240343	8510240293	85/10/18	50-285 Q	8510250574	8510250566	85/10/18	50-373 F
8510240347	8510240341	85/10/18	50-458 Q	8510250576	8510250576	85/10/12	50-416 P
8510240363	8510240354	85/10/22	50-456 T	8510250584	8510250576	85/10/12	50-416 P
8510240379	8510240375	85/10/22	50-320 G	8510250589	8510250580	85/10/11	50-412 A
8510240389	8510240385	85/10/21	50-261 F	8510250591	8510250565	85/10/21	50-320 P
8510240392	8510240384	85/10/17	50-269 Q	8510250594	8510250565	85/10/21	50-320 P
8510240417	8510240411	85/10/11	50-361 P	8510250595	8510250580	85/10/11	50-412 A
8510240420	8510240411	85/10/11	50-361 P	8510250597	8510250593	85/10/16	XPORTLIC
8510240426	8510240424	85/10/11	50-298 Q	8510250613	8510250610	85/10/15	50-271 P
8510240467	8510240461	85/10/09	WASTE MGT	8510280025	8510280023	85/10/02	WASTE MGT
8510240471	8510240461	85/10/09	WASTE MGT	8510280069	8510280060	85/10/17	50-285 F
8510240520	8510240513	85/10/02	WASTE MGT	8510280074	8510280060	85/10/17	50-285 F
8510240524	8510240521	85/09/30	71-9203	8510280088	8510280083	85/10/18	50-320 P
8510240529	8510240513	85/10/02	WASTE MGT	8510280096	8510280083	85/10/18	50-320 P
8510240537	8510240513	85/10/02	WASTE MGT	8510280113	8510280103	85/10/22	50-440 Q
8510240549	8510240536	85/10/04	50-344 P	8510280128	8510280121	85/10/18	50-312 P
8510240552	8510240546	85/10/01	71-9204	8510280142	8510250135	85/10/22	50-440 Q
8510240558	8510240536	85/10/04	50-344 P	8510280145	8510280139	85/10/09	50-528 Q
8510240578	8510240570	85/10/10	50-344 P	8510280159	8510280155	85/10/10	50-344 Q
8510240592	8510240585	85/10/11	50-3 F	8510280176	8510280172	85/10/08	WASTE MGT
8510240595	8510240583	85/10/02	WASTE MGT	8510280183	8510280177	85/10/22	50-409 Q
8510240601	8510240589	85/10/11	50-306 Q	8510280187	8510280181	85/09/18	50-150 Q
8510240605	8510240583	85/10/02	WASTE MGT	8510280191	8510280181	85/09/18	50-150 Q
8510240613	8510240583	85/10/02	WASTE MGT	8510280195	8510280181	85/09/18	50-150 Q
8510240618	8510240611	85/10/03	WASTE MGT	8510280204	8510280194	85/10/22	CONTRACT
8510240619	8510240610	85/10/11	50-368 P	8510280219	8510280201	85/10/21	50-213 P
8510240621	8510240583	85/10/02	WASTE MGT	8510280220	8510280217	85/10/11	50-445 Q
8510240626	8510240583	85/10/02	WASTE MGT	8510280223	8510280217	85/10/11	50-445 Q
8510240627	8510240610	85/10/11	50-368 P	8510280229	8510280217	85/10/11	50-445 Q
8510240630	8510240583	85/10/02	WASTE MGT	8510280231	8510280227	85/09/18	WASTE MGT
8510240638	8510240583	85/10/02	WASTE MGT	8510280240	8510280236	85/10/18	50-461 A
8510240643	8510240583	85/10/02	WASTE MGT	8510280241	8510280211	85/10/11	50-445 Q
8510240652	8510240648	85/10/10	50-317 P	8510280254	8510280217	85/10/11	50-445 Q
8510250024	8510250018	85/10/15	50-346 P	8510280264	8510280260	85/10/03	50-483 Q
8510250030	8510250027	85/10/18	50-302 H	8510280266	8510280260	85/10/03	50-483 Q
8510250049	8510250045	85/10/18	50-219 P	8510280290	8510280286	85/10/18	50-344 P
8510250050	8510250045	85/10/18	50-219 P	8510280300	8510280297	85/10/18	50-266 P

414 CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510280302	8510280299	85/10/22	50-54 Q	8510290412	8510290389	85/10/07	TOPREP
8510280304	8510280298	85/10/22	50-282 Q	8510290413	8510290388	85/10/07	TOPREP
8510280305	8510280299	85/10/22	50-54 Q	8510290427	8510290423	85/10/23	50-324 P
8510280316	8510280307	85/10/22	50-315 Q	8510290429	8510290425	85/10/22	50-424 F
8510280318	8510280313	85/10/17	50-389 P	8510290431	8510290425	85/10/22	50-424 F
8510280341	8510280338	85/10/23	50-220 Q	8510290449	8510290445	85/10/24	50-416 P
8510280344	8510280313	85/10/17	50-389 P	8510290451	8510290445	85/10/24	50-416 P
8510280345	8510280337	85/10/21	50-454 Q	8510290622	8510290622	85/10/18	50-247 R
8510280346	8510280343	85/10/11	50-346 P	8510290633	8510290622	85/10/18	50-247 R
8510280348	8510280338	85/10/23	50-220 Q	8510300006	8510300003	85/10/24	50-73 P
8510280351	8510280347	85/10/22	50-454 Q	8510300011	8510300005	85/10/24	50-445 F
8510280355	8510280349	85/10/22	50-455 A	8510300025	8510300018	85/10/24	50-461 F
8510280357	8510280356	85/10/21	50-354 Q	8510300027	8510300017	85/10/21	50-320 P
8510280358	8510280354	85/10/23	50-461 Q	8510300076	8510300070	85/10/17	50-83 P
8510280359	8510280352	85/10/22	50-341 Q	8510300082	8510300073	85/10/24	50-417 A
8510280360	8510280356	85/10/21	50-354 Q	8510300093	8510300088	85/10/24	50-320 P
8510280361	8510280274	85/10/18	50-298 P	8510300098	8510300088	85/10/24	50-320 P
8510280375	8510280370	85/10/34	50-336 P	8510300114	8510300106	85/10/24	50-255 Q
8510280386	8510280385	85/10/22	50-306 Q	8510300120	8510300103	85/10/22	50-416 P
8510280388	8510280387	85/10/22	50-387 Q	8510300151	8510300144	85/10/24	50-528 Q
8510280392	8510280391	85/10/22	50-461 Q	8510300172	8510300168	85/10/25	QA999
8510280394	8510280391	85/10/22	50-461 Q	8510300178	8510300168	85/10/25	QA999
8510280395	8510280393	85/10/23	50-461 Q	8510300193	8510300188	85/10/21	50-269 P
8510280396	8510280393	85/10/23	50-461 Q	8510300196	8510300190	85/10/25	50-414 A
8510280404	8510280403	85/10/15	50-333 S	8510300211	8510300188	85/10/21	50-269 P
8510280412	8510280409	85/10/18	50-282 P	8510300214	8510300209	85/10/28	50-369 P
8510280417	8510280414	85/10/21	50-395 P	8510300221	8510300209	85/10/28	50-369 P
8510280418	8510280416	85/10/24	70-3027 P	8510300222	8510300217	85/10/15	50-321 P
8510280428	8510280427	85/10/22	50-387 P	8510300223	8510300217	85/10/15	50-321 P
8510280435	8510280433	85/08/09	27-48	8510300226	8510300209	85/10/28	50-369 P
8510280448	8510280443	85/10/18	50-282 F	8510300230	8510300209	85/10/28	50-369 P
8510280451	8510280443	85/10/18	50-282 F	8510300231	8510300227	85/10/24	50-433 P
8510280478	8510280476	85/10/22	50-77 P	8510300233	8510300228	85/10/15	50-344 F
8510290017	8510290014	85/10/24	50-341 Q	8510300314	8510300306	85/10/17	50-322 S
8510290021	8510290019	85/10/23	50-445 Q	8510310002	8510310001	85/10/24	50-245 P
8510290022	8510290016	85/10/23	50-445 G	8510310011	8510310007	85/10/17	50-334 P
8510290035	8510290033	85/10/25	50-400 T	8510310025	8510310023	85/10/09	50-305 P
8510290041	8510290033	85/10/25	50-400 T	8510310032	8510310028	85/10/17	50-315 P
8510290046	8510290033	85/10/25	50-400 T	8510310037	8510310034	85/10/15	50-305 P
8510290049	8510290033	85/10/25	50-400 T	8510310038	8510310034	85/10/15	50-305 P
8510290062	8510290059	85/10/24	50-275 P	8510310062	8510310059	85/10/11	50-315 P
8510290066	8510290051	85/10/24	50-155 Q	8510310072	8510310067	85/10/24	XPORTLIC
8510290069	8510290059	85/10/24	50-275 P	8510310086	8510310081	85/10/22	XPORTLIC
8510290082	8510290078	85/10/24	50-331 Q	8510310087	8510310068	85/10/09	50-334 P
8510290089	8510290078	85/10/24	50-331 Q	8510310092	8510310083	85/10/08	50-334 P
8510290102	8510290095	85/10/23	50-529 A	8510310095	8510310093	85/10/07	50-423 F
8510290115	8510290099	85/10/24	50-409 Q	8510310106	8510310096	85/10/18	50-458 Q
8510290116	8510290054	85/10/22	50-460 S	8510310124	8510310116	85/10/23	50-382 P
8510290127	8510290117	85/10/24	40-6622	8510310128	8510310125	85/10/24	70-1100
8510290136	8510290117	85/10/24	40-6622	8510310163	8510240083	85/10/17	50-528 R
8510290146	8510290138	85/10/07	50-312 R	8510310167	8510310164	85/10/25	50-213 Q
8510290152	8510290145	85/10/18	50-155 P	8510310170	8510310166	85/10/22	50-271 Q
8510290166	8510290159	85/10/22	50-327 P	8510310179	8510310174	85/09/30	50-247 P
8510290171	8510290167	85/06/26	WASTE MGT	8510310182	8510310178	85/10/25	50-286 Q
8510290174	8510290169	85/10/25	50-344 P	8510310183	8510310174	85/09/30	50-247 P
8510290175	8510290160	85/10/24	50-289 P	8510310197	8510310191	85/10/29	50-302 P
8510290182	8510290160	85/10/24	50-289 P	8510310208	8510310205	85/10/15	50-423 A
8510290202	8510290194	85/10/23	50-298 Q	8510310215	8510310207	85/10/24	50-29 P
8510290207	8510290200	85/10/17	WASTE MGT	8510310217	8510310210	85/10/24	70-371
8510290234	8510290220	85/10/08	50-423 A	8510310219	8510310214	85/10/24	50-423 A
8510290246	8510290235	85/10/16	50-423 F	8510310225	8510310220	85/10/24	50-423 K
8510290249	8510290235	85/10/16	50-423 F	8510310244	8510310240	85/10/23	50-293 P
8510290263	8510290252	85/10/22	50-219 P	8510310247	8510310243	85/10/25	50-254 Q
8510290276	8510290267	85/10/25	50-275 P	8510310255	8510310249	85/10/29	50-440 A
8510290285	8510290267	85/10/25	50-275 P	8510310257	8510310253	85/10/26	50-250 G
8510290291	8510290279	85/10/17	WASTE MGT	8510310265	8510310262	85/10/25	50-295 Q
8510290308	8510290300	85/10/16	50-336 P	8510310278	8510310267	85/10/24	50-373 Q
8510290314	8510290307	85/10/22	50-335 P	8510310291	8510310283	85/10/25	50-382 Q
8510290323	8510290319	85/10/25	QA999	8510310293	8510310292	85/10/25	50-2 Q
8510290324	8510290320	85/10/16	50-245 P	8510310294	8510310292	85/10/25	50-2 Q
8510290327	8510290321	85/10/22	50-219 P	8510310307	8510310296	85/10/25	50-267 Q
8510290336	8510290330	85/10/24	50-440 Q	8510310322	8510310310	85/10/30	QA999
8510290343	8510290333	85/10/16	50-245 P	8510310326	8510310310	85/10/30	QA999
8510290344	8510290341	85/10/23	50-352 Q	8510310330	8510310325	85/10/25	50-346 Q
8510290347	8510290341	85/10/23	50-352 Q	8510310333	8510310331	85/10/30	50-416 P
8510290359	8510290357	85/10/21	50-346 S	8510310350	8510310343	85/10/25	50-458 Q
8510290365	8510290360	85/10/22	50-155 P	8510310355	8510310352	85/10/22	50-412 E
8510290370	8510290360	85/10/22	50-155 P	8510310357	8510310353	85/10/28	50-280 P
8510290375	8510290371	85/10/16	50-263 P	8510310369	8510310364	85/10/28	50-382 Q
8510290376	8510290367	85/10/22	50-352 Q	8510310370	8510310363	85/10/25	CONTRACT
8510290377	8510290373	85/10/25	50-354 F	8510310390	8510310385	85/10/24	50-219 P
8510290378	8510290371	85/10/16	50-263 P	8510310399	8510310394	85/10/25	50-456 T
8510290384	8510290380	85/10/25	50-341 Q	8510310411	8510310328	85/09/24	TOPREP
8510290387	8510290380	85/10/25	50-341 Q	8510310426	8510310424	85/10/24	70-687
8510290390	8510290388	85/10/09	50-245 P	8510310453	8510310450	85/10/24	50-293 P
8510290392	8510290388	85/10/09	50-245 P	8510310499	8510310485	85/10/25	50-29 P
8510290393	8510290388	85/10/09	50-245 P	8510310516	8510310509	85/10/21	50-416 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS 415

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8510310519	8510310513	85/09/27	50-331 R	8510310574	8510310566	85/10/17	50-445 S
8510310524	8510310509	85/10/21	50-116 P	8510310586	8510310581	85/10/22	50-373 P
8510310532	8510310444	85/10/25	50-267 Q	8510310590	8510310581	85/10/22	50-373 P
8510310573	8510310561	85/10/03	50-295 P	8510310613	8510310612	85/10/15	50-390 T

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.
4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR).
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual operating reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:
Logbooks on Environmental Data
Logbooks on Radiological Data
Operations Log on Plant Systems Core
Plant Status Summary Sheets.
5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNSs).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plant, formerly filed in category P.

X. NSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3. Meeting announcements; description of meeting agendas.
4. Committee generated reports, memoranda, and correspondence that are publicly available.
5. Committee related correspondence.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS -- Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E -- Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC -- Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG -- NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG -- Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR -- Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM -- Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ -- Projects--Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

WASTE RES — Waste Management Research Reports

Contains interim and final reports, and correspondence submitted to NRC by its contractors doing research on topics related to the storage of high-level radioactive waste.

1. Periodic progress reports on the status of research.
2. Trip reports of travel by NRC and contractor personnel.
3. Draft, partial or related reports submitted for NRC review or information.
4. Correspondence between NRC staff and contractors relating to technical questions or issues to be resolved.

XPORTLIC — Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

BIBLIOGRAPHIC DATA SHEET

NUREG-0540
Vol. 7, No. 10

SEE INSTRUCTIONS ON THE REVERSE

2. TITLE AND SUBTITLE

Title List of Documents Made Publicly Available
October 1-31, 1985

3. LEAVE BLANK

4. DATE REPORT COMPLETED

MONTH

YEAR

6. DATE REPORT ISSUED

MONTH

YEAR

December

1985

5. AUTHOR(S)

7. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8. PROJECT/TASK/WORK UNIT NUMBER

9. FIN OR GRANT NUMBER

10. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Same as 7, above.

11a. TYPE OF REPORT

Monthly

b. PERIOD COVERED (Inclusive dates)

October 1-31, 1985

12. SUPPLEMENTARY NOTES

13. ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

14. DOCUMENT ANALYSIS - a. KEYWORDS/DESCRIPTORS

b. IDENTIFIERS/OPEN-ENDED TERMS

15. AVAILABILITY STATEMENT

Unlimited

16. SECURITY CLASSIFICATION

(This page)

Unclassified

(This report)

Unclassified

17. NUMBER OF PAGES

18. PRICE

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, \$300

FOURTH CLASS MAIL
POSTAGE & FEES PAID
USNRC
WASH D.C.
PERMIT No. G 87

120555078877 1 1AM1A5
US NRC
ADM-DIV OF TIDC
POLICY & PUB MGT BR-PDR NUREG
W-501
WASHINGTON DC 20555