

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) LaSalle County Station										DOCKET NUMBER (2) 0 5 0 0 0 3 7 4 1 OF 0 2										PAGE 12	
TITLE (4) Drywell Vacuum Breaker Open																					
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)							
10	10	85	85	043	00	11	07	85						0 5 0 0 0							
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following): (11)																			
1		20.402(b)				20.408(a)				X 80.73(a)(2)(iv)				73.71(b)							
POWER LEVEL (10)		20.408(a)(1)(i)				80.38(a)(1)				80.73(a)(2)(v)				73.71(a)							
100		20.408(a)(1)(ii)				80.38(a)(2)				80.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 306A)							
		20.408(a)(1)(iii)				80.73(a)(2)(i)				80.73(a)(2)(vii)(A)											
		20.408(a)(1)(iv)				80.73(a)(2)(ii)				80.73(a)(2)(vii)(B)											
		20.408(a)(1)(v)				80.73(a)(2)(iii)				80.73(a)(2)(v)											
LICENSEE CONTACT FOR THIS LER (12)																					
NAME Anne M. Lucietto, extension 640										TELEPHONE NUMBER 8 1 5 3 5 7 - 6 7 6 1											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS											
X	B	F V I A C B	G 12 0 12	N																	
SUPPLEMENTAL REPORT EXPECTED (14)																					
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO											
										EXPECTED SUBMISSION DATE (15)											
										MONTH DAY YEAR											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On October 10, 1985, the Unit 2 "A" Vacuum Breaker opened and closed at 1933 hours. The cause of this event is unknown. At the time of this event Unit 2 was at 100% power.

8511180262 851107
PDR ADOCK 05000374
S PDR

U

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMR NO. 3150-0104
EXT. REG. 8/31/85

FACILITY NAME (1): LaSalle County Station	DOCKET NUMBER (2): 0 6 0 0 0 3 7 4	LER NUMBER (3)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	0 4 3	0 0	0 2	OF	0 2

TEXT (if more space is required, use additional NRC Form 3604's) (17)

I. EVENT DESCRIPTION

On October 10, 1985, at 1933 hours with Unit 2 at 100% power in Mode 1, vacuum breaker (BF) 2PC001A opened and closed equalizing a pressure difference between the Primary Containment Drywell and the Suppression Pool.

II. CAUSE

The cause of the differential pressure which caused the opening and closing of the vacuum breaker is unknown. There were no plant evolutions in progress which might have contributed to this event.

III. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The Primary Containment vacuum breaker operated per design to maintain pressure equalization between the Primary Containment and the Suppression Pool. The plant was maintained in a safe condition throughout the event.

IV. CORRECTIVE ACTION

The vacuum breaker operated as designed. No further action is required.

V. PREVIOUS OCCURRENCES

This exact event has not previously occurred, but similar events are documented in (Unit 1) LER 85-014-00, 85-015-00, 85-025-00, (Unit 2) LER 84-077-00, 84-080-00, 84-081-00, 84-083-00, 84-088-00, 84-090-00, 84-091-00, 84-092-00.

VI. NAME AND TELEPHONE NUMBER OF PREPARER

Anne M. Lucietto, 815/357-6761, extension 640.



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

November 7, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Dear Sir:

Reportable Occurrence Report #85-043-00, Docket #050-374 is being submitted to your office in accordance with 10CFR 50.73.

for R.D. B...
G. J. Diederich
Station Manager
LaSalle County Station

GJD/DRR/kg

Enclosure

cc: NRC, Regional Director
INPO-Records Center
File/NRC

TE22
1/1